# Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

# Title List of Documents Made Publicly Available

July 1-31, 1983

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555





# CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	1
Docketed Items	
Low Level Radwaste Disposal — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	4
Domestic Licensing of Special Nuclear Material — Docket 70	337
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	346
Licensing of Independent Spent Fuel Storage — Docket 72	352
Nondocketed Items	
10 CFR — Commission Meeting Records	353
ACRS — Advisory Committee on Reactor Safeguards	354
	356
COMMISSION — NRC Commissioners	356
CONTRACT — NRC Contracts and Modifications	357
FOIA - Freedom of Information Act Requests and Releases	362
GEN TECH IS — Generic Technical Issues	367
I&E — Inspection and Enforcement	370
	373
	373
0.10	389
	391
Trion Trojens Triumini management December 1997	394
PT 21 — Noncompliance Reports and Related Correspondence	394
Q18333 Quantil 12000100000 20000000000000000000000000	396
REGGD — Regulatory Guides	400
RES — Research and Technical Assistance Reports	400
	401
OZOI IOMIONI AMPINI ZITOTO MIO TOMININOSTITO INTERNATIONALI INTERN	402
Dillian I I I I I I I I I I I I I I I I I I I	402
· · · · · · · · · · · · · · · · · · ·	403
	407
The same of the sa	417
1 VIDORAL FRANCIS AND ALL PROPERTY OF THE PROP	423
	453
###### * · · · · · · · · · · · · · · · ·	481
**************************************	483
	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

#### **PREFACE**

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

#### DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence

2 3
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. 5 Tennessee Valley Authority. 6 82/03/04. 7 VASSALLO, D.B. Operating Reactors Branch 2. 8 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H. St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

# NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E — Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG -- Correspondence with Other Organizations

PR - Proposed Rule

PRM - Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

QA999 - Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG - State Programs

TOPREP - Vendor Reports and Related Correspondence


WASH - Regulatory Publications-Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

#### NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27			40-8724	Chemetron Corp., Chicago, IL	3
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8743	Conoco, Inc., Denver, CO	3
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	3
Domestic Lice	ensing of Source Material — Docket 40		40-8829	Wyoming Fuel Co., Lakewood, CO	3
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1			
40-0299	Union Carbide Corp., Grand Junction, CO	1	Domestic Lice Docket 50	nsing of Production and Utilization Facilities—	
40-0672	Nuclear Metals, Inc., Concord, MA	1	50-2	Univ. of Michigan Research Reactor	4
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	50-3	Indian Point Station, Unit 1	4
40-2061	Kerr-McGee Chemical Corp. Oklahoma City, OK	•	50-5	Pennsylvania State Univ. Research Reactor	4
40-2259	Pathfinder Mines Corp., Riverton, WY	2	50-8	North Carolina State Univ. Research Reactor	4
40-4492	Federal-American Partners, Riverton, WY	2	50-10	Dresden Nuclear Power Station, Unit 1	4
40-6264	Michigan Chemical Corp., St. Louis, MI	2	50-13	Babcock & Wilcox Co. Critical Facility	5
40-6500	Energy, Dept. of, Canonsburg, PA	2	50-16	Enrico Fermi Atomic Power Plant, Unit 1	5
40-6659	Getty Oil Co Petrotomics Co.,	2	50-20	Massachusetts Institute of Technology	
40-0009	Shirley Basin, WY	2		Research Reactor	5
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA		50-25	Dow Chemical Co. TRIGA Reactor	5
40-8027		2	50-27	Washington State Univ. Research Reactor	5
40-6027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	2	50-29	Yankee-Rowe Nuclear Power Station	6
40-8035	Cotter Corp., Roswell, NM	2	50-54	Union Carbide Research Reactor	7
40-8064	Exxon Minerals Co., USA, Houston, TX	2	50-57	State Univ. of New York Research Reactor	7
40-8331	African Metals Corp., New York, NY	3	50-59	Texas A&M Univ. Research Reactor	8
40-8380	Rocky Mountain Energy Co., Broomfield, CO	3	50-62	Univ. of Virginia Research Reactor	8
40-8452	Bear Creek Uranium Co., Casper, WY	3	50-70	General Electric Test Reactor	8
40-8550	Holmes & Narver, Inc., Anaheim, CA	3	50-72	Univ. of Utah Research Reactor	8
40-8584	Minerals Exploration Co., Los Angeles, CA	3	50-73	General Electric Nuclear Test Reactor	8
40-8585	Wyoming Mineral Corp., Lakewood, CO	3	50-77	Catholic Univ. of America Research Reactor	9
40-8681	Energy Fuels Nuclear, Inc., Denver, CO	3	50-83	Univ. of Florida Training Reactor	9
40-8698	Plateau Resources, Ltd., Grand Junction, CO	3	50-87	Westinghouse Critical Experiment	9
40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	3	50-89	General Atomic Co.	9
40-8722	Brush Wellman, Inc., Cleveland, OH	3	50-97	Cornell Univ. Zero Power Reactor	9
			50-99	Babcock & Wilcox Test Reactor	9

Docke	et	Name	Page	Docket	Name	Page
50	0-103	Aerojet General Nucleonics	9	50-208	Columbia Univ. Research Reactor	18
51	0-111	North Carolina State Univ. Research Reactor	9	50-213	Haddam Neck Plant	18
5	0-112	Univ. of Oklahoma Research Reactor	10	50-219	Oyster Creek Nuclear Power Plant	19
5	0-113	Univ. of Arizona Research Reactor	10	50-220	Nine Mile Point Nuclear Station, Unit 1	21
5	0-116	Iowa State Univ. Research Reactor	10	50-223	Univ. of Lowell Research Reactor	23
5	0-118	Aerojet General Nucleonics	10	50-224	Univ. of California Research Reactor	23
5	0-123	Univ. of Missouri Research Reactor	10	50-225	RPI Critical Experiment	23
5	0-124	Virginia Polytechnic Institute	10	50-228	Aerotest Radiography & Research Reactor	24
	0.120	Training Reactor	10	50-237	Dresden Nuclear Power Station, Unit 2	24
	0-128	Texas A&M Univ. Research Reactor	10	50-243	Oregon State Univ. Research Reactor	27
31	0-131	Omaha Veterans Administration Hospital Research Reactor	10	50-244	Robert Emmet Ginna Nuclear Plant, Unit I	27
50	0-133	Humboldt Bay Power Plant, Unit 3	10	50-245	Millstone Nuclear Power Station, Unit 1	29
5	0-134	Worcester Polytechnic Institute Research Reactor	11	50-247	Indian Point Station, Unit 2	31
5	0-139	Univ. of Washington Research Reactor	11	50-249	Dresden Nuclear Power Station, Unit 3	34
	0-139	Stanford Univ. Research Reactor	11	50-250	Turkey Point Plant, Unit 3	37
	0-142	UCLA Training Reactor		50-251	Turkey Point Plant, Unit 4	38
	0-142	Univ. of Kansas Research Reactor	1 i 1 2	50-252	Univ. of New Mexico Research Reactor	40
	0-150	Ohio State Univ. Research Reactor	12	50-254	Quad-Cities Station, Unit 1	40
	0-150	Univ. of Illinois Research Reactor	13	50-255	Palisades Nuclear Plant	42
	0-155	Big Rock Point Nuclear Plant	13	50-259	Browns Ferry Nuclear Power Station, Unit 1	44
	0-156	Univ. of Wisconsin Research Reactor	15	50-260	Browns Ferry Nuclear Power Station, Unit 2	47
	0-157	Cornell Univ. Research Reactor	15	50-261	H. B. Robinson Plant, Unit 2	49
	0-160	Georgia Institute of Technology Research Reactor		50-262	Brigham Young Univ. Research Reactor	52
	0-163	General Atomic Co.		50-263	Monticello Nuclear Generating Plant	52
	0-166	Univ. of Maryland Research Reactor	15 16	50-264	Dow Chemical Co.	54
	0-170	National Naval Medical Center	16	50-265	Quad-Cities Station, Unit 2	54
	0-182	Purdue Univ. Research Reactor	16	50-266	Point Beach Nuclear Plant, Unit 1	56
	0-184	National Bureau of Standards Reactor	16	50-267	Fort St. Vrain Nuclear Generating Station	58
	0-186	Univ. of Missouri Research Reactor	16	50-269	Oconce Nuclear Station, Unit 1	60
	0-187	Space Radiation Research Reactor	16	50-270	Oconee Nuclear Station, Unit 2	61
	0-192	Univ. of Texas Research Reactor	16	50-271	Vermont Yankee Nuclear Power Station	63
	0-193	Rhode Island & Providence Plantations AEC	16	50-272	Salem Nuclear Generating Station, Unit 1	65
	0-199	Manhattan College Research Reactor	16	50-274	U. S. Geological Survey Research Reactor	. 67
	60-201	West Valley Reprocessing Plant	17	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	68
	0-206	San Onofre Nuclear Station, Unit 1	17	50-276	Georgia Technology Research Reactor	73
_		Zana canada Canton, Cim I	4 /			

Docket	Name	Page	Docket	Name	Page
50-277	Peach Bottom Atomic Power Station, Unit 2	73	50-325	Brunswick Steam Electric Plant, Unit 1	146
50-278	Peach Bottom Atomic Power Station, Unit 3	75	50-326	Univ. of California at Irvine Research Reactor	148
50-280	Surry Power Station, Unit 1	77	50-327	Sequoyah Nuclear Plant, Unit 1	149
50-281	Surry Power Station, Unit 2	79	50-328	Sequoyah Nuclear Plant, Unit 2	151
50-282	Prairie Island Nuclear Station, Unit 1	80	50-329	Midland Plant, Unit 1	153
50-284	Idaho State Univ. Research Reactor	82	50-330	Midland Plant, Unit 2	158
50-285	Fort Calhoun Station, Unit 1	82	50-331	Duane Arnold Energy Center	164
50-286	Indian Point Station, Unit 3	85	50-333	James A. Fitzpatrick Nuclear Power Plant	166
50-287	Oconee Nuclear Station, Unit 3	88	50-334	Beaver Valley Power Station, Unit 1	168
50-288	Reed College Research Reactor	89	50-335	St. Lucie Plant, Unit 1	170
50-289	Three Mile Island Nuclear Station, Unit 1	90	50-336	Millstone Nuclear Power Station, Unit 2	172
50-293	Pilgrim Nuclear Power Station, Unit 1	95	50-338	North Anna Power Station, Unit 1	174
50-294	Michigan State Univ. Research Reactor	97	50-339	North Anna Power Station, Unit 2	177
50-295	Zion Nuclear Power Station, Unit 1	98	50-341	Enrico Fermi Atomic Power Plant, Unit 2	179
50-296	Browns Ferry Nuclear Power Station, Unit 3	99	50-344	Trojan Nuclear Plant	181
50-297	North Carolina State Univ. PULSTAR Reactor	101	50-346	Davis-Besse Nuclear Power Station, Unit 1	182
50-298	Cooper Nuclear Station	101	50-348	Joseph M. Farley Nuclear Plant, Unit 1	185
50-301	Point Beach Nuclear Plant, Unit 2	103	50-352	Limerick Generating Station, Unit 1	187
50-302	Crystal River Nuclear Plant, Unit 3	105	50-353	Limerick Generating Station, Unit 2	192
50-304	Zion Nuclear Power Station, Unit 2	107	50-354	Hope Creek Nuclear Station, Unit 1	197
50-305	Kewaunee Nuclear Power Plant	109	50-355	Hope Creek Nuclear Station, Unit 2	198
50-306	Prairie Island Nuclear Station, Unit 2	110	50-356	Univ. of Illinois LOPRA Research Reactor	198
50-309	Maine Yankee Atomic Power Plant	111	50-358	William H. Zimmer Nuclear Station, Unit 1	198
50-311	Salem Nuclear Generating Station, Unit 2	114	50-361	San Onofre Nuclear Station, Unit 2	201
50-312	Rancho Seco Nuclear Generating Station	116	50-362	San Onofre Nuclear Station, Unit 3	203
50-313	Arkansas Nuclear One, Unit 1	119	50-364	Joseph M. Farley Nuclear Plant, Unit 2	205
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	121	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	207
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	123	50-367	Bailly Generating Station	210
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	124	50-368	Arkansas Nuclear One, Unit 2	210
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	127	50-369	William B. McGuire Nuclear Station, Unit 1	212
50-320	Three Mile Island Nuclear Station, Unit 2	129	50-370	William B. McGuire Nuclear Station, Unit 2	215
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	132	50-373	LaSalle County Station, Unit 1	217
50-322	Shoreham Nuclear Power Station	134	50-374	LaSalle County Station, Unit 2	221
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	141	50-382	Waterford Generating Station, Unit 3	223
50-324	Brunswick Steam Electric Plant, Unit 2	144	50-387	Susquehanna Steam Electric Station, Unit 1	227

Docket	Name	Page	Docket	Name	Page
50-388	Susquehanna Steam Electric Station, Unit 2	229	STN-50-457	Braidwood Station, Unit 2	304
50-389	St. Lucie Plant, Unit 2	<b>2</b> 31	50-458	River Bend Station, Unit 1	306
50-390	Watts Bar Nuclear Plant, Unit 1	234	50-459	River Bend Station, Unit 2	308
50-391	Watts Bar Nuclear Plant, Unit 2	236	50-460	WPPSS Nuclear Project, Unit 1	308
50-395	Virgil C. Summer Nuclear Station, Unit 1	238	50-461	Clinton Power Station, Unit 1	309
50-396	Univ. of Virginia Cavalier Reactor	241	50-462	Clinton Power Station, Unit 2	311
50-397	WPPSS Nuclear Project, Unit 2	241	50-466	Allens Creek Nuclear Station, Unit 1	311
50-400	Shearon Harris Nuclear Power Plant, Unit 1	244	50-467	Allens Creek Nuclear Station, Unit 2	311
50-401	Shearon Harris Nuclear Power Plant, Unit 2	249	STN-50-470	CESSAR System 80	311
50-406	Tuskegee Institute Research Reactor	253	STN-50-482	Wolf Creek Generating Station	312
50-407	Univ. of Utah Research Reactor	253	STN-50-483	Callaway Plant, Unit 1	314
50-409	La Crosse Boiling Water Reactor	253	50-496	Montague Nuclear Power Station, Unit 1	316
50-410	Nine Mile Point Nuclear Station, Unit 2	255	50-497	Montague Nuclear Power Station, Unit 2	317
50-412	Beaver Valley Power Station, Unit 2	256	STN-50-498	South Texas Project, Unit 1	317
50-413	Catawba Nuclear Station, Unit 1	257	STN-50-499	South Texas Project, Unit 2	318
50-414	Catawba Nuclear Station, Unit 2	260	STN-50-508	WPPSS Nuclear Project, Unit 3	319
50-416	Grand Gulf Nuclear Station, Unit 1	263	STN-50-509	WPPSS Nuclear Project, Unit 5	320
50-417	Grand Gulf Nuclear Station, Unit 2	267	50-513	WPPSS Nuclear Project, Unit 4	321
50-423	Millstone Nuclear Power Station, Unit 3	268	50-514	Pebble Springs Nuclear Plant, Unit 1	321
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	269	50-515	Pebble Springs Nuclear Plant, Unit 2	321
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	271	STN-50-518	Hartsville Nuclear Plant, Unit 1	321
50-433	UC-Santa Barbara Research Reactor	273	STN-50-520	Hartsville Nuclear Plant, Unit 3	321
STN-50-437	Floating Nuclear Plant	273	50-522	Skagit Nuclear Power Project, Unit 1	322
50-438	Bellefonte Nuclear Plant, Unit 1	273	50-523	Skagit Nuclear Power Project, Unit 2	322
50-439	Bellefonte Nuclear Plant, Unit 2	275	STN-50-528	Palo Verde Nuclear Station, Unit 1	323
50-440	Perry Nuclear Power Plant, Unit 1	276	STN-50-529	Palo Verde Nuclear Station, Unit 2	325
50-441	Perry Nuclear Power Plant, Unit 2	279	STN-50-530	Palo Verde Nuclear Station, Unit 3	328
50-443	Seabrook Nuclear Station, Unit 1	281	50-537	Clinch River Breeder Reactor	331
50-444	Seabrook Nuclear Station, Unit 2	285	50-538	Memphis State Univ. Research Reactor	333
50-445	Comanche Peak Steam Electric Station, Unit 1	288	STN-50-546	Marble Hill Nuclear Station, Unit 1	333
50-446	Comanche Peak Steam Electric Station, Unit 2	291	STN-50-547	Marble Hill Nuclear Station, Unit 2	334
STN-50-447	GESSAR-238	294	STN-50-553	Phipps Bend Nuclear Station, Unit 1	336
STN-50-454	Byron Station, Unit 1	294	STN-50-554	Phipps Bend Nuclear Station, Unit 2	336
STN-50-455	Byron Station, Unit 2	299	STN-50-556	Black Fox Station, Unit 1	336
STN-50-456	Braidwood Station, Unit 1	303	STN-50-557	Black Fox Station, Unit 2	336

Docket	Name	Page	Docket	Name	Page
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	337	70-1308	General Electric Co., San Jose, CA	344
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	337	70-1353	Deaconess Hospital, Milwaukee, WI	344
Damastia Ligar	nsing of Special Nuclear Material — Docket 70		70-1359	IRT Corp., San Diego, CA	344
70-0025	Rockwell International Corp.,		70-1406	Veterans Administration Hospital, New Orleans, LA	345
70 0022	Canoga Park, CA	337	70-1486	Butterworth Hospital, Grand Rapids, MI	345
70-0027	Babcock & Wilcox Co., Lynchburg, VA	337	70-1703	Eastman Kodak Co., Rochester, NY	345
70-0036	Combustion Engineering, Inc., Windsor, CT	337	70-1779	American Steel Foundries, East Chicago, IN	345
70-0064	Stanford Univ., Stanford, CA	337	70-2204	Blodgett Memorial Medical Center,	345
70-0115	Washington, Univ. of, Seattle, WA	337	70-2204	Grand Rapids, MI	345
70-0135	Babcock & Wilcox Co., Apollo, PA	337	70-2319	Our Lady of Lourdes Hospital, Camden, NJ	345
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	338	70-2609	Commonwealth Edison Co., Chicago, IL	345
70-0168	Nuclide Corp., State College, PA	340	70-2885	Commonwealth Edison Co., Chicago, IL	345
70-0223	California, Univ. of, Los Angeles, CA	340	70-2926	Detroit Edison Co., Detroit, MI	345
70-0364	Babcock & Wilcox Co., Apollo, PA	340	70-2945	Union Electric Co., St. Louis, MO	345
70-0371	UNC Naval Products, Inc., Uncasville, CT	340	70-2946	Louisiana Power & Light Co., New Orleans, LA	345
70-0378	Army, Dept. of, Adelphi, MD	341	70-2947	·	
70-0398	Commerce, Dept. of, Washington, DC	341		Illinois Power & Light Co., Decatur, IL	345
70-0572	Monsanto Research Corp., Dayton, OH	341	70-2950	Washington Public Power Supply System, Richland, WA	345
70-0687	Union Carbide Corp., Tuxedo, NY	341	70-2957	Florida Power & Light Co., Miami, FL	346
70-0698	Westinghouse Electric Corp., Pittsburgh, PA	341	70-2960	Kansas Gas & Electric Co., Wichita, KS	346
70-0734	GA Technologies, Inc., San Diego, CA	341	70-2973	Commonwealth Edison Co., Chicago, IL	346
70-0754	General Electric Co., Pleasanton, CA	342	70-2974	North Kansas City Memorial Hospital, North Kansas City, MO	346
70-0801	Ohio State Univ., Columbus, OH	342	70-2982	Rochester, Univ. of, Rochester, NY	346
70-0820	United Nuclear Corp., Wood River Junction, RI	342	70-2983	Pennsylvania Power & Light Co.,	
70-0824	Babcock & Wilcox Co., Lynchburg, VA	342	70.0000	Allentown, PA	346
70-0966	Ohio State Univ., Columbus, OH	342	70-2988	Philadelphia Electric Co., Philadelphia, PA	346
70-1007	General Electric Co., San Jose, CA	342		adioactive Material for Transport and Transport Material Under Certain Conditions — Docket 7	
70-1100	Combustion Engineering, Inc., Windsor, CT	342	71-0004	General Electric Co.	346
70-1113	General Electric Co., Wilmington, NC	343			
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	343	71-0037	Navy, Dept. of	346
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	343	71-0210	Gulf Nuclear, Inc.	346
70-1193	Kerr-McGee Nuclear Corp. Oklahoma City, OK	343	71-0231 71-0318	Chem-Nuclear Systems, Inc.  Marathon Oil Co.	346 346
70-1201	Babcock & Wilcox Co., Lynchburg, VA	344	71-0496	NUS Corp.	346
70-1257	Exxon Nuclear Co., Inc., Richland, WA	344	71-0499	Kokomo Tube Co.	347
10"1201	egaza Harion Con mon Memmin, 111	≥1°1	11-0422	MONOTING 1800 CO.	WT /

Docke	t	Name	Page	Docket	Name	Page
71-0	0500	E. I. Du Pont de Nemours & Co., Inc.	347	71-9035	Model: 680 & 680E, Technical Operations,	350
71-0	0501	Scientific Inspection Technology, Inc.	347	71-9039	Inc.  Model: 715, Technical Operations, Inc.	350
71-0	0502	Vermont Yankee Nuclear Power Corp.	347	71-9039	Model: GE-1600, General Electric Co.	350
71~	4909	Model: GE 21PF-1, General Electric Co.	347		Model: GE-500, General Electric Co.	350
71-	5026	Model: CNS 14-190, Chem-Nuclear Systems, Inc.	347	71-9049 71-9070	Model: N-55, Energy, Dept. of	350
71-:	5450	Model: RCC -1, -2, -3, -4, Westingthouse	247	71-9071	Model: AP-101, ANEFCO, Inc.	350
71-	5552	Electric Corp.  Model: Gas Cylinder Fire Impact Shield,	347 347	71-9079	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	350
		Energy, Dept. of		71-9080	Model: 9080, Hittman Nuclear & Development	250
	5641	Model: UNC-2500, United Nuclear Corp.	348		Corp.	350
	578 <b>7</b>	Model: D-28, Energy, Dept. of	348	71-9088	Model: NLS-RF, Schlumberger Well Services	350
	5805	Model: CNS-3-55, Chem-Nuclear Systems, Inc.	348	71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	t 350
	5828	Model: TREAT, Energy, Dept. of	348	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc	350
	5874	Model: WAPD-40, Energy, Dept. of	348	71-9098	Model: UCC-20WC-2 & 2A, Union Carbide	
	5957	Model: BMI-1, Battelle Columbus Laboratory	348		Corp.	350
	5971	Model: GE-200, General Electric Co.	348	71-9107	Model: 771, Technical Operations, Inc.	351
71-	6078	Model: 927A1 & 927C1, Combustion Engineering, Inc.	348	71-9108	Model: CNS 6-75, Chem-Nuclear Systems, Inc.	351
71-	6272	Model: 6272, U.S. Ecology, Inc.	348	71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	351
71-	6286	Model: CMB-11, Energy, Dept. of	348	71-9127	Model: 100, 100A, 200, 200A Gamma Industries	351
71-	6346	Model: FSV-1, General Atomic Co.	348	71-9128	Model: C-8, Gamma Industries	351
71-	6400	Model: 6400, Westinghouse Electric Corp.	348	71-9132	Model: T-3, Energy, Dept. of	351
	6406	Model: None, Energy, Dept. of	349	71-9135	Model: Century S & SA, Cen. Univ. S & Sa, Gamma Industries	351
. 71-	6495	Model: PADUCAH Demonstration Cask, Energy, Dept. of	349	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corporation	351
71-	6550	Model: 6-GS-1, Energy, Dept. of	349	71-9156	Model: IR-50, Industrial Nuclear Co.	351
71-	6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	349	71-9157	Model: IR-100, Industrial Nuclear Co.	351
71-	6679	Model: 6679, U.S. Ecology, Inc.	349		Model: GNM-20, Gulf Nuclear, Inc.	351
74-	6698	Model: NFS-4, Nuclear Fuel Services, Inc.	349	71-9162	,	351
71-	6708	Model: C-6, Energy, Dept. of	349	71-9163	Model: GNG-20, Gulf Nuclear, Inc.	221
71-	6771	Model: SN-1, Metropolitan Edison Co.	349	71-9176	Model: NUPAC 14/210L & 14/210H, Nuclear Packaging, Inc.	352
71-	9006	Model: 500-SU, Automation Industries, Inc.	349	71-9180	Model: 500-SU, Automation Industries, Inc.	352
71-	9010	Model: NLI-1/2, NL Industries, Inc.	349	71-9505	Model: HPG MOD-3, RTG, Energy, Dept. of	352
71-	9029	Model: 676 & 676E, Technical Operations, Inc.	349			
71-	9032	Model: 650, Technical Operations, Inc.	350	Ü	dependent Spent Fuel Storage — Docket 72	
71-	9033	Model: 660 & 660E, Technical Operations, Inc.	350	72-0001	Morris Operations, General Electric Co.	352

# ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27			Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Union Carbide Corp., Grand Junction, CO	40-0299	1
Richland, WA, U.S. Ecology, Inc.	27-048	1	W. R. Grace & Co., Pompton Plains, NJ	40-0086	ı
Domestic Licensing of Source Material — Docket 40			Wyoming Fuel Co., Lakewood, CO	40-8829	3
African Metals Corp., New York, NY	40-8331	3	Wyoming Mineral Corp., Lakewood, CO	40-8585	3
Bear Creek Uranium Co., Casper, WY	40-8452	3	Domestic Licensing of Production and Utilizatio	n Facilities —	
Brush Wellman, Inc., Cleveland, OH	40-8722	3	Docket 50		
Chemetron Corp., Chicago, IL	40-8724	3	Aerojet General Nucleonics	50-103	9
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	3	Aerojet General Nucleonics	50-118	10
Conoco, Inc., Denver, CO	40-8743	3	Aerotest Radiography & Research Reactor	50-228	24
Cotter Corp, Roswell, NM	40-8035	2	Allens Creek Nuclear Station, Unit 1	50-466	311
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	3	Allens Creek Nuclear Station, Unit 2	50-467	311
			Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	269
Energy, Dept. of, Canonsburg, PA	40-6500	2	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	271
Exxon Minerals Co., USA, Houston, TX	40-8064	2	Arkansas Nuclear One, Unit 1	50-31 <b>3</b>	119
Federal-American Partners, Riverton, WY	40-4492	2	Arkansas Nuclear One, Unit 2	50-368	210
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	2	Babcock & Wilcox Co. Critical Facility	50-13	5
Holmes & Narver, Inc., Anaheim, CA	40-8550	3	Babcock & Wilcox Test Reactor	50-99	9
Kawecki Berylco Industries, Inc.,	10 (010		Bailly Generating Station	50-367	210
Boyertown, PA	40-6940	2	Beaver Valley Power Station, Unit 1	50-334	168
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Beaver Valley Power Station, Unit 2	50-412	256
Kerr-McGee Nuclear Corp.,	40.0007	2	Bellefonte Nuclear Plant, Unit 1	50-438	273
Oklahoma City, OK	40-8027	2	Bellefonte Nuclear Plant, Unit 2	50-439	275
Kerr-McGee Nuclear Corp., Okiahoma City, OK	40-8768	3	Big Rock Point Nuclear Plant	50-155	13
Michigan Chemical Corp., St. Louis, MI	40-6264	2	Black Fox Station, Unit 1	STN-50-556	336
Minerals Exploration Co., Los Angeles, CA	40-8584	3	Black Fox Station, Unit 2	STN-50-557	336
Nuclear Metals, Inc., Concord, MA	40-0672	1	Braidwood Station, Unit 1	STN-50-456	303
Pathfinder Mines Corp., Riverton, WY	40-2259	2	Braidwood Station, Unit 2	STN-50-457	304
Plateau Resources, Ltd., Grand Junction, CO	40-8698	3	Brigham Young Univ. Research Reactor	50-262	52
Rocky Mountain Energy Co., Broomfield, CO	40-8380	3	Browns Ferry Nuclear Power Station, Unit 1	50-259	44

Name	Docket	Page	Name	Docket	Page
Browns Ferry Nuclear Power Station, Unit 2	50-260	47	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	207
Browns Ferry Nuclear Power Station, Unit 3	50-296	99	Enrico Fermi Atomic Power Plant, Unit 1	50-16	5
Brunswick Steam Electric Plant, Unit 1	50-325	146	Enrico Fermi Atomic Power Plant, Unit 2	50-341	179
Brunswick Steam Electric Plant, Unit 2	50-324	144	Floating Nuclear Plant	STN-50-437	273
Byron Station, Unit 1	STN-50-454	294	Fort Calhoun Station, Unit 1	50-285	82
Byron Station, Unit 2	STN-50-455	299	Fort St. Vrain Nuclear Generating Station	50-267	58
Callaway Plant, Unit 1	STN-50-483	314	General Atomic Co.	50-89	9
Caivert Cliffs Nuclear Power Plant, Unit 1	50-317	124	General Atomic Co.	50-163	15
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	127	General Electric Nuclear Test Reactor	50-73	8
Catawba Nuclear Station, Unit 1	50-413	257	General Electric Test Reactor	50-70	8
Catawba Nuclear Station, Unit 2	50-414	260	Georgia Institute of Technology Research Reactor	r 50-160	15
Catholic Univ. of America Research Reactor	50-77	9	Georgia Technology Research Reactor	50-276	73
CESSAR System 80	STN-50-470	311	GESSAR-238	STN-50-447	294
Clinch River Breeder Reactor	50-537	331	Grand Gulf Nuclear Station, Unit 1	50-416	263
Clinton Power Station, Unit 1	50-461	309	Grand Gulf Nuclear Station, Unit 2	50-417	267
Clinton Power Station, Unit 2	50-462	311	H. B. Robinson Plant, Unit 2	50-261	49
Columbia Univ. Research Reactor	50-208	18	Haddam Neck Plant	50-213	18
Comanche Peak Steam Electric Station, Unit 1	50-445	288	Hartsville Nuclear Plant, Unit 1	STN-50-518	321
Comanche Peak Steam Electric Station, Unit 2	50-446	291	Hartsville Nuclear Plant, Unit 3	STN-50-520	321
Cooper Nuclear Station	50-298	101	Hope Creek Nuclear Station, Unit 1	50-354	197
Cornell Univ. Research Reactor	50-157	15	Hope Creek Nuclear Station, Unit 2	50-355	198
Cornell Univ. Zero Power Reactor	50-97	9	Humboldt Bay Power Plant, Unit 3	50-133	10
Crystal River Nuclear Plant, Unit 3	50-302	105	Idaho State Univ. Research Reactor	50-284	82
Davis-Besse Nuclear Power Station, Unit 1	50-346	182	Indian Point Station, Unit 1	50-3	4
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	68	Indian Point Station, Unit 2	50-247	31
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	<b>1</b> 41	Indian Point Station, Unit 3	50-286	85
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	121	Iowa State Univ. Research Reactor	50-116	10
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	123	James A. Fitzpatrick Nuclear Power Plant	50-333	166
Dow Chemical Co.	50-264	54	Joseph M. Farley Nuclear Plant, Unit 1	50-348	185
Dow Chemical Co. TRIGA Reactor	50-25	5	Joseph M. Parley Nuclear Plant, Unit 2	50-364	205
Dresden Nuclear Power Station, Unit 1	50-10	4	Kewaunee Nuclear Power Plant	50-305	109
Dresden Nuclear Power Station, Unit 2	. 50-237	24	La Crosse Boiling Water Reactor	50-409	253
Dresden Nuclear Power Station, Unit 3	50-249	34	La Crosse Boiling Water Reactor  LaSalle County Station, Unit 1	50-373	217
Duane Arnold Energy Center	50-331	1 <b>64</b>	LaSalle County Station, Unit 2	50-374	221
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	132	Labane county diation, out 2	<b>42 2. 1</b>	

Name	Docket	Page	Name	Docket	Page
Limerick Generating Station, Unit 1	50-352	187	Palo Verde Nuclear Station, Unit 1	STN-50-528	323
Limerick Generating Station, Unit 2	50-353	192	Palo Verde Nuclear Station, Unit 2	STN-50-529	325
Maine Yankee Atomic Power Plant	50-309	111	Palo Verde Nuclear Station, Unit 3	STN-50-530	328
Manhattan College Research Reactor	50-199	16	Peach Bottom Atomic Power Station, Unit 2	50-277	73
Marble Hill Nuclear Station, Unit 1	STN-50-546	333	Peach Bottom Atomic Power Station, Unit 3	50-278	75
Marble Hill Nuclear Station, Unit 2	STN-50-547	334	Pebble Springs Nuclear Plant, Unit 1	50-514	321
Massachusetts Institute of Technology Research Reactor	50-20	5	Pebble Springs Nuclear Plant, Unit 2	50-515	321
Memphis State Univ. Research Reactor	50-538	333	Pennsylvania State Univ. Research Reactor	50-5	4
Michigan State Univ. Research Reactor	50-294	97	Perry Nuclear Power Plant, Unit I	50-440	276
Midland Plant, Unit 1	50-329	153	Perry Nuclear Power Plant, Unit 2	50-441	279
Midland Plant, Unit 2	50-330	158	Phipps Bend Nuclear Station, Unit 1	STN-50-553	336
Millstone Nuclear Power Station, Unit 1	50-245	29	Phipps Bend Nuclear Station, Unit 2	STN-50-554	336
Millstone Nuclear Power Station, Unit 2	50-336	172	Pilgrim Nuclear Power Station, Unit 1	50-293	95
Millstone Nuclear Power Station, Unit 3	50-423	268	Point Beach Nuclear Plant, Unit 1	50-266	56
Montague Nuclear Power Station, Unit 1	50-496	316	Point Beach Nuclear Plant, Unit 2	50-301	103
Montague Nuclear Power Station, Unit 2	50-497	317	Prairie Island Nuclear Station, Unit 1	50-282	80
Monticello Nuclear Generating Plant	50-263	52	Prairie Island Nuclear Station, Unit 2	50-306	110
National Bureau of Standards Reactor	50-184	16	Purdue Univ. Research Reactor	50-182	16
National Naval Medical Center	50-170	16	Quad-Cities Station, Unit 1	50-254	40
Nine Mile Point Nuclear Station, Unit 1	50-220	21	Quad-Cities Station, Unit 2	50-265	54
Nine Mile Point Nuclear Station, Unit 2	50-410	255	Rancho Seco Nuclear Generating Station	50-312	116
North Anna Power Station, Unit 1	50-338	174	Reed College Research Reactor	50-288	89
North Anna Power Station, Unit 2	50-339	177	Rhode Island & Providence Plantations AEC	50-193	16
North Carolina State Univ. PULSTAR Reactor	50-297	101	River Bend Station, Unit 1	50-458	306
North Carolina State Univ. Research Reactor	50-8	4	River Bend Station, Unit 2	50-459	308
North Carolina State Univ. Research Reactor	50-111	9	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	27
Oconee Nuclear Station, Unit 1	50-269	60	RPI Critical Experiment	50-225	23
Oconee Nuclear Station, Unit 2	50-270	61	Salem Nuclear Generating Station, Unit 1	50-272	65
Oconee Nuclear Station, Unit 3	50-287	88	Salem Nuclear Generating Station, Unit 2	50-311	114
Ohio State Univ. Research Reactor	50-150	12	San Onofre Nuclear Station, Unit 1	50-206	17
Omaha Veterans Administration Hospital Research Reactor	50-131	IU	San Onofre Nuclear Station, Unit 2	50-361	201
Oregon State Univ. Research Reactor		10	San Onofre Nuclear Station, Unit 3	50-362	203
Oyster Creek Nuclear Power Plant	50-243 50-219	27	Seabrook Nuclear Station, Unit 1	50-443	281
Palisades Nuclear Plant		19	Seabrook Nuclear Station, Unit 2	50-444	285
a monde indicat fight	50-255	42	Sequoyah Nuclear Plant, Unit 1	50-327	149

Name	Docket	Page	Name	Docket	Page
Sequoyah Nuclear Plant, Unit 2	50-328	151	Univ. of Kansas Research Reactor	50-148	12
Shearon Harris Nuclear Power Plant, Unit 1	50-400	244	Univ. of Lowell Research Reactor	50-223	23
Shearon Harris Nuclear Power Plant, Unit 2	50-401	249	Univ. of Maryland Research Reactor	50-166	16
Shoreham Nuclear Power Station	50-322	134	Univ. of Michigan Research Reactor	50-2	4
Skagit Nuclear Power Project, Unit 1	50-522	322	Univ. of Missouri Research Reactor	50-123	10
Skagit Nuclear Power Project, Unit 2	50-523	322	Univ. of Missouri Research Reactor	50-186	16
South Texas Project, Unit 1	STN-50-498	317	Univ. of New Mexico Research Reactor	50-252	40
South Texas Project, Unit 2	STN-50-499	318	Univ. of Okłahoma Research Reactor	50-112	10
Space Radiation Research Reactor	50-187	16	Univ. of Texas Research Reactor	50-192	16
St. Lucie Plant, Unit 1	50-335	170	Univ. of Utah Research Reactor	50-72	8
St. Lucie Plant, Unit 2	50-389	231	Univ. of Utah Research Reactor	50-407	253
Stanford Univ. Research Reactor	50-141	11	Univ. of Virginia Cavalier Reactor	50-396	241
State Univ. of New York Research Reactor	50-57	7	Univ. of Virginia Research Reactor	50-62	8
Surry Power Station, Unit !	50-280	77	Univ. of Washington Research Reactor	50-139	11
Surry Power Station, Unit 2	50-281	79	Univ. of Wisconsin Research Reactor	50-156	15
Susquehanna Steam Electric Station, Unit 1	50-387	227	Vermont Yankee Nuclear Power Station	50-271	63
Susquehanna Steam Electric Station, Unit 2	50-388	229	Virgil C. Summer Nuclear Station, Unit 1	50-395	238
Texas A&M Univ. Research Reactor	50-59	8	Virginia Polytechnic Institute Training Reactor	50-124	10
Texas A&M Univ. Research Reactor	50-128	10	Washington State Univ. Research Reactor	50-27	5
Three Mile Island Nuclear Station, Unit 1	50-289	90	Waterford Generating Station, Unit 3	50-382	223
Three Mile Island Nuclear Station, Unit 2	50-320	129	Watts Bar Nuclear Plant, Unit 1	50-390	234
Trojan Nuclear Plant	50-344	181	Watts Bar Nuclear Plant, Unit 2	50-391	236
Turkey Point Plant, Unit 3	50-250	37	West Valley Reprocessing Plant	50-201	17
Turkey Point Plant, Unit 4	50-251	38	Westinghouse Critical Experiment	50-87	9
Tuskegee Institute Research Reactor	50-406	253	William B. McGuire Nuclear Station, Unit 1	50-369	212
U. S. Geological Survey Research Reactor	50-274	67	William B. McGuire Nuclear Station, Unit 2	50-370	215
UC-Santa Barbara Research Reactor	50-433	273	William H. Zimmer Nuclear Station, Unit 1	50-358	198
UCLA Training Reactor	50-142	11	Wolf Creek Generating Station	STN-50-482	312
Union Carbide Research Reactor	50-54	7	Worcester Polytechnic Institute		
Univ. of Arizona Research Reactor	50-113	10	Research Reactor	50-134	11
Univ. of California at Irvine Research Reactor	50-326	148	WPPSS Nuclear Project, Unit 1	50-460	308
Univ. of California Research Reactor	50-224	23	WPPSS Nuclear Project, Unit 2	50-397	241
Univ. of Florida Training Reactor	50-83	9	WPPSS Nuclear Project, Unit 3	STN-50-508	319
Univ. of Illinois LOPRA Research Reactor	50-356	198	WPPSS Nuclear Project, Unit 4	50-513	321
Univ. of Illinois Research Reactor	50-151	13	WPPSS Nuclear Project, Unit 5	STN-50-509	320

Name	Docket	Page	Name	Docket	Page
Yankee-Rowe Nuclear Power Station	50-29	6	Kansas Gas & Electric Co., Wichita, KS	70-2960	346
Yellow Creek Nuclear Plant, Unit I	STN-50-566	337	Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	343
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	337	Louisiana Power & Light Co,		
Zion Nuclear Power Station, Unit 1	50-295	98	New Orleans, LA	70-2946	345
Zion Nuclear Power Station, Unit 2	50-304	107	Monsanto Research Corp., Dayton, OH	70-0572	341
Domestic Licensing of Special Nuclear Material	- Docket 70		North Kansas City Memorial Hospital, North Kansas City, MO	70-2974	346
American Steel Foundries, East Chicago, IN	70-1779	345	Nuclear Fuel Services, Inc., Erwin, TN	70-0143	338
Army, Dept. of, Adelphi, MD	70-0378	341	Nuclide Corp., State College, PA	70-0168	340
Babcock & Wilcox Co., Apollo, PA	70-0135	337	Ohio State Univ., Columbus, OH	70-0966	342
Babcock & Wilcox Co., Apollo, PA	70-0364	340	Ohio State Univ., Columbus, OH	70-0801	342
Babcock & Wilcox Co., Lynchburg, VA	70-0027	337	Our Lady of Lourdes Hospital, Camden, NJ	70-2319	345
Babcock & Wilcox Co., Lynchburg, VA	70-0824	342	Pennsylvania Power & Light Co., Allentown, PA	70-2983	346
Babcock & Wilcox Co., Lynchburg, VA	70-1201	344	Philadelphia Electric Co., Philadelphia, PA	70-2988	346
Blodgett Memorial Medical Center, Grand Rapids, MI	70-2204	345	Rochester, Univ. of, Rochester, NY	70-2982	346
Butterworth Hospital, Grand Rapids, MI	70-1486	345	Rockwell International Corp., Canoga Park, CA	70-0025	337
California, Univ. of, Los Angeles, CA	70-0223	340	Stanford Univ., Stanford, CA	70-0064	337
Combustion Engineering, Inc., Windsor, CT	70-1100	342	UNC Naval Products, Inc., Uncasville, CT	70-0371	340
Combustion Engineering, Inc., Windsor, CT	70-0036	337	Union Carbide Corp., Tuxedo, NY	70-0687	341
Commerce, Dept. of, Washington, DC	70-0398	341	Union Electric Co., St. Louis, MO	70-2945	345
Commonwealth Edison Co., Chicago, IL	70-2973	346	United Nuclear Corp., Wood River Junction, RI	70-0820	342
Commonwealth Edison Co., Chicago, IL	70-2609	345	Veterans Administration Hospital, New Orleans, LA	70-1406	345
Commonwealth Edison Co., Chicago, IL	70-2885	345	Washington Public Power Supply System,		
Deaconess Hospital, Milwaukee, WI	70-1353	344	Richland, WA	70-2950	345
Detroit Edison Co., Detroit, MI	70-2926	345	Washington, Univ. of, Seattle, WA	70-0115	337
Eastman Kodak Co., Rochester, NY	70-1703	345	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	343
Exxon Nuclear Co., Inc., Richland, WA	70-1257	344	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	343
Florida Power & Light Co., Miami, FL	70-2957	346	Westinghouse Electric Corp., Pittsburgh, PA	70-0698	341
GA Technologies, Inc., San Diego, CA	70-0734	341	Packaging of Radioactive Material for Transport ar	ıd Transport:	ation
General Electric Co., Pleasanton, CA	70-0754	342	of Radioactive Material Under Certain Conditions	- Docket 7	1 .
General Electric Co., San Jose, CA	70-1007	342	Chem-Nuclear Systems, Inc.	71-0231	346
General Electric Co., San Jose, CA	70-1308	344	E. I. Du Pont de Nemours & Co., Inc.	71-0500	347
General Electric Co., Wilmington, NC	70-1113	343	General Electric Co.	71-0004	346
Illinois Power & Light Co., Decatur, IL	70-2947	345	Gulf Nuclear, Inc.	71-0210	346
IRT Corp., San Diego, CA	70-1359	344	Kokomo Tube Co.	71-0499	347

	Docket	Page	Name	Docket	Page
Name		346	Model: GE-200, General Electric Co.	71-5971	348
Marathon Oil Co.	71-0318	351		71-9049	350
Model: 100, 100A, 200, 200A, Gamma Industries	71-9127		Model: GE-500, General Electric Co.		
Model: 500-SU, Automation Industries, Inc.	71-9180	352	Model: GNG-20, Gulf Nuclear, Inc.	71-9163	351
Model: 500-SU, Automation Industries, Inc.	71-9006	349	Model: GNM-20, Gulf Nuclear, Inc.	71-9162	351
Model: 6-GS-1, Energy, Dept. of	71-6550	349	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	71-9079	350
Model: 6272, U. S. Ecology, Inc.	71-6272	348	Model: HN-100, Series 3, Hittman Nuclear &		
Model: 6400, Westinghouse Electric Corp.	71-6400	348	Development Corp.	71-9151	351
Model: 650, Technical Operations, Inc.	71-9032	350	Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	350
Model: 660 & 660E, Technical Operations, Inc.	71-9033	350	Model: HPG MOD-3 RTG, Energy, Dept. of	71-9505	352
Model: 6679, U. S. Ecology, Inc.	71-6679	349	Model: IR-100, Industrial Nuclear Co.	71-9157	351
Model: 676 & 676E, Technical Operations, Inc.	71-9029	349	Model: IR-50, Industrial Nuclear Co.	71-9156	351
Model: 680 & 680E, Technical Operations, Inc.	71-9035	350	Model: N-55, Energy, Dept. of	71-9070	350
Model: 715, Technical Operations, Inc.	71-9039	350	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	349
Model: 771, Technical Operations, Inc.	7 <b>1-</b> 9107	351	Model: NLI-1/2, NL Industries, Inc.	71-9010	349
Model: 9080, Hittman Nuclear & Development Corp.	71-9080	350	Model: NLS-RF, Schlumberger Well Services	71-9088	350
Model: 927A1 & 927C1, Combustion Engineering,	71-6078	348	Model: None, Energy, Dept. of	71-6406	349
Inc.	71-9071	350	Model: NUPAC 14/210L & 14/210H, Nuclear Packaging, Inc.	71-9176	352
Model: AP-101, ANEFCO, Inc.	71-5957	348	Model: PADUCAH Demonstration Cask, Energy,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Model: BMI-1, Battelle Columbus Laboratory	71-6708	349	Dept. of	71-6495	349
Model: C-6, Energy, Dept. of	71-9128	351	Model: RCC, -1, -2, -3, -4, Westinghouse Electric	71-5450	347
Model: C-8, Gamma Industries	71-3120	331	Corp.	71-6771	349
Model: Century S & SA, Cen. Univ. S & SA, Gamma Industries	71-9135	<b>35</b> 1	Model: SN-1, Metropolitan Edison Co.	71-9132	351
Model: CMB-11, Energy, Dept. of	71-6286	348	Model: T-3, Energy, Dept. of		348
Model: CNS 14-190, Chem-Nuclear Systems, Inc.	71-5026	347	Model: TREAT, Energy, Dept. of	71-5828	
Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	350	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	71-9098	350
Model: CNS 6-75, Chem-Nuclear Systems, Inc.	71-9108	351	Model: UNC-2500, United Nuclear Corp.	71-5641	348
Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	351	Model: WAPD-40, Energy, Dept. of	71-5874	348
Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	349	Navy, Dept. of	71-0037	346
Model: CNS-3-55, Chem-Nuclear Systems, Inc.	71-5805	348	NUS Corp.	71-0496	346
Model: D-28, Energy, Dept. of	71-5787	348	Scientific Inspection Technology, Inc.	71-0501	347
Model: FSV-1, General Atomic Co.	71-6346	348	Vermont Yankee Nuclear Power Corp.	71-0502	347
Model: Gas Cylinder Fire Impact Shield,	00 .0		Licensing of Independent Spent Fuel Storage — Do	cket 72	
Energy, Dept. of	71-5552	347	Morris Operations, General Electric Co.	72-0001	352
Model: GE 21PF-1, General Electric Co.	71-4909	347	N.		
Model: GE-1600, General Electric Co.	71-9044	350			

# **DOCKETED ITEMS**

#### LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-047 BARNWELL, SC. CHEM-NUCLEAR SYSTEMS, INC.

8307180310 Forwards clarification of License Condition 24 re standing water requirements in dry solid waste. Use of absorbent matl not intended as substitute for solidification media. PURNIS.J. Chem-Nuclear Systems, Inc. 83/07/06. WIDMEYER, D. NRC -No Detailed Affiliation Given. 2pp. 19566:114.

DOCKET 27-048 RICHLAND, WA. U.S. ECOLOGY, INC.

- 8307200160 Trip rept of 830503-05 site visit to Richland, WA to discuss closure & stabilization plan for low level waste disposal facility w/State of WA.

  8HAFFNER.J. A. Low Level Waste Licensing Branch. 83/06/23,
  HIGGINBOTHAM, L. Low Level Waste Licensing Branch. 3pp. 19670:330.
- 8307060401 Forwards IE Waste Packaging Insp Rept 15000046/83-05 conducted by State of WA on 830517.

  BOOK, H. E.: Region 5, Office of Director. B3/06/30. ORELLA, A. Bafeguards & Materials Program Branch. 1p. 19234: 298.
- --8307060407 IE Waste Packaging Insp Rept 15000046/83-05 on 830517.
  Noncompliance noted: violation of DUT/NRC regulations re
  Drum 205 w/open rim & lack of strong tight container.
  THOMAS.R.D.: 800K.H.E. Region 5. Office of Director. FOUTE.A.M.
  Washington, State of. 83/06/29. 3pp. 19234:299.
- 8307060052 PND-V-83-027: on 830627. State of WA notified that shipment of low level waste received from Palisades power plant w/one drum leaking due to hole caused by corrosion. Util banned from using site & burial permit suspended, effective 830621. THOMAS.R.D. Region 5, Office of Director. 83/07/01. 1p. 19251: 330.
- 8307270144 Forwards monthly SNM receipt & burial rept for June 1983 & rept of isotopic activity. W/o encis.
  WRIGHT, S. V. US Ecology, Inc. (formerly Nuclear Engineering).
  83/07/11. HAWKINS, E. Low Level Haste Licensing Branch. ip.
  19811: 136.
- B307260452 Forwards Waste Packaging Insp Rept 15000046/83-06 on 830621. Noncompliance noted. BOOK, H. E. Region 5. Office of Director. 83/07/19. GRELLA, A. Bafeguards & Materials Program Branch. 1p. 19734:185.
- --8307260436 Waste Packaging Insp Rept 15000046/83-06 on B30621.
  Noncompliance noted: failure to provide strong, tight package for Drum BI-II-4 & failure to prevent presence of loose radioactive matl on trailer floor.
  ELBEN.M.J., THOMAS,R.D., BOOK,H.E. Region 5, Office of Director.
  83/07/19. 18pp. 19734:186.

# DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0086 W.R. GRACE & CO., POMPTON PLAINS, NJ

- 8307250440 Responds to 83040B ltr forwarding Mar 1983 "Radiological Survey of Former Thorium/Rare Earths Processing Facility (MR Grace Property Wayne, NJ). " NRC studies conclude no immediate hazard from thorium concentration.

  MARTIN, T. T. Division of Engineering & Technical Programs. 83/07/19. KUHRTZ, S. Q. New Jersey, State of. 1p. 19701:103.
- --8307250443 Forwards "Rediological Survey of Former Thorium/Rare Earths Processing Facility (WR Grace Property Wayne, NJ)."
  Evaluation of area should be based on more stringent environ stds.due to possible change in property use.
  KUHRTZ.S.Q. New Jersey, State of. 83/04/08. Region 1, Office of Director, 2pp. 19701:104.

--B307250444 "Radiological Survey of Former Thorium/Rare Earths Processing Facility (MR Grace Property Wayne,NJ)." W/two oversize figures. Aperture cards are available in PDR. \* New Jersey, State of. 83/03/31. 60pp. 19701:106.

DOCKET 40-0299 UNION CARBIDE CORP. . GRAND JUNCTION, CO

8307180395 Atk receipt of 830615 ltr re 830527 const of new pumpback well. Guardwell 38. Well can be incorporated in current application for A-9 pit collection sys.provided listed info submitted in triplicate.

LABARGE.F. Hyoming. State of. 83/06/20. LYONS.P.J. Union Carbide Corp. 2pp. 19366:361.

DDCKET 40-0672 NUCLEAR METALS, INC., CONCORD, MA

- 8307280164 Forwards IE Insp Rept 40-0672/83-01 on 830525-27 & 0608-10. Violations identified during insp will be discussed during 830727 enforcement conference at Region I ofc.per 830629 telcon.
  - vercon. MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/11. TUFFIN.W.B. Nuclear Metals. Inc. 2pp. 19792:079.
- --8307280170 IE insp Rept 40-0672/83-01 on 830525-27 & 0608-10.
  Noncompliance noted: failure to evaluate & rept apparent 110 rem extremity exposure & exposure to extremities of foundry workers.
  RDWG.C., COSTELLO.F., KINNEMAN, J. Region 1, Office of Director. 83/07/01. 11pp. 19792:081.
- B307190087 Ack receipt of B20921 ltr re monthly Gi film badge exposures in response to NRC 620721 ltr.
  MARTIN.T. T. Division of Engineering & Technical Programs. B3/07/13. VUMBACO, F. Nuclear Metals, Inc. ip. 19635:150.
- --8307190091 Forwards corrected 820909 response to NRC 820721 ltr. Several handwritten items re exposures vs reported doses inadverteetily omitted during final preparation. ALLARD. D. J. Nuclear Metals. Inc. 82/09/21. MARTIN. T. T. Division of Engineering & Technical Programs. Ip. 19635:151.
- --B307190095 Corrected response to B20721 request for add1 info. Equation used to correct gamma dose based on averaging of bast fit lines for monthly 01 film badge exposures (90 RVp X-rays) vs reported doses.

  ALLARD.D. J., VUMBACD.F. J. Nuclear Hetals, Inc. B2/09/09. MARTIN.T.T. Division of Engineering & Technical Programs. 9pp. 19635:152.
- --8307190097 "Personnel Dosimetry Performance Testing,Pilot Study, Results of Test 3." PLATO,P., MIKICS, J. Michigan, Univ. of. 82/06/10. 12pp. 19635:161.
- B307280123 Ack receipt of B30304 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0472/81-02.
  MARTIN.T.T. Division of Engineering & Technical Programs. TUFFIN.W.B. Nuclear Metals, Inc. 10. 19794:300.
- --8307280129 Responds to NRC 830117 ltr re violations noted in IE Insp. Rept 40-0672/81-02. Corrective actions: health physics program revised & bioassay program modified.
  GILMANIA.R. Nuclear Metals. Inc. 83/03/04. MARTIN, T. T. Division of Engineering & Technical Programs. 15pp. 19796:301.
- 8307250349 Ack receipt of 830602 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 40-0672/81-03: 40-0672/82-01 & 40-0672/82-02. MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/19. TUFFIN.W.B. Nuclear Metals: Inc. 1p. 19703:246.

- --B307250354 Responds to NRC 830523 ltr re violations noted in IE Insp. Repts 40-0672/83-03. 40-0672/82-01 & 40-0672/82-02 Corrective actions:self-grapping nails used in Fabrication of all wooden shipping crates BARBOUR.D.A. VUMBACO.F.J. Nuclear Metals, Inc. 83/06/02. MARTIM.T.T. Division of Engineering & Technical Programs. Bpp. 19703:247.
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY. CHATTANDOGA. IN
- 8307110723 Forwards environ assessment & action description memo for remedial action activities planned for 100 vicinity properties in Edgemont, SD. Implementation of remedial action critical. Energy, Dept. of. 83/06/06. BAUBLITZ, J. E. Energy. pp. 19391: 248. TUCKER M.K. Ens Dept. of 2pp.
- ---8307110726 Action description memo. "Cleanup Activities at Vicinity Properties in Edgement.SD." Bendix Corp. 83/06/01. Spp. 19391:250.
- --8307110727 "Environ Assessment of Cleanup Activities at Vicinity Properties in Edgemont, SD." \* Bendix Corp. 9J-06(83). 83/06/30. 43pp. 19391:258.
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP. DKLAHOMA CITY. OK
- B307070216 Requests extension until B30801 to file petitions for hearing Add1 time needed to review FES. Certificate of Svc enci. RENNELS, A. E. Wast Chicago, IL. 83/07/01. Docketing & Services Branch. 3pp. 19269: 318.
- 8307110304 Petition for hearing & for leave to intervene.EIS must be prepared re application to decommission thorium milling site.Certificate of Svc enci.

  HARTIGAN.N.F. 11linois, State of. 83/07/07. Commissioners.
  12pp. 19374:345.
- 8307280020 Forwards comments on FES re decommissioning of Rare Earths Facility. West Chicago, IL (NUREG-0904). FES deficient & unresponsive to EPA DES concerns. Rept does not substantiate that onsite waste disposal will be accomplished acceptably. ALBERICO, P. A. Environmental Protection Agency. 83/07/15. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17824:022.
- 8307260305 Answer supporting State of IL 830707 petition to intervene & motion for scheduling order Notices of appearance & Certificate of Svc encl.
  RHINELANDER.J Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.) RHINELANDER.J. Shaw, Pittman, Potts & Trowbridge.
  83/07/22. Commissioners. 10pp. 19726:282.
- DOCKET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY
- 8307130442 Forwards request for add1 info re 830324 request for approval of waste disposal program required by Amend 16 to License SUA-672. Info requested within 15 days. PETTENGILL.H.J. Uranium Recovery Licensing Branch. 83/06/29. Pathfinder Mines Corp. 4pp. 19510:035.
- DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY
- 8307150452 Forwards plan for windblown tailings contamination cleanup in conjunction w/reroute of Willow Springs Draw Project. Three oversize maps encl. Aperture cards are available in OFFICE OVERSIZE MAPS THE MAPS OF THE MAPS
- DOCKET 40-6264 MICHIGAN CHEMICAL CORP., ST. LOUIS, MI
- 8307080467 Confirms 830601 telcon re radioactive contamination at facility. Implementation of site stabilization plan imposed by consent judgment filed 821227 adequate. Proposed land use restrictions acceptable. Site evaluation memo encl. PAGE.R.O. Uranium Fuel Licensing Branch. 83/06/09. RADEMACHER.J.W. Velsicol Chemical Corp. 1p. 19383:135.

- --8307080474 Site evaluation memo concluding that encl consent judgment requirements & proposed notations on granite marker adequate to protect public from radioactive contaminants at site. Site. CROW.W.T., PAGE.R.G. Uranium Fuel Licensing Branch. 83/06/09. Uranium Fuel Licensing Branch. 3pp. 19363:136.
- --B307080480 Forwards draft proposed granite marker legend & proposed restrictions on use to be recorded against title of site.

  Draft consent decree encl.

  RADEMACHER.J. M. Veisical Chemical Corp. 82/09/29, PAGE, R. 0.

  Uranium Fuel Licensing Branch. 107pp. 19383:139.
- --B307080484 "Comprehensive Radiological Survey." W/nine oversize figures.Aperture cards are available in PDR.

  \* Dames & Moore. B1/07/23. 216pp. 19383:247.
- DOCKET 40-4500 ENERGY, DEPT. OF, CANONSSURG, PA
- 8307150026 Forwards review team initial comments on review draft of remedial action plan for Canonsburg PA site. Response to comments required. quired. Uranium Fuel Licensing Branch. 83/06/29. BALL.D.M. t. of. 5pp. 19562:324. nergy, Dept. of. Spp.
- 8307280027 Forwards final responses to NRC comments on "Remedial Action Plan & Site Conceptual Design for Stabilization of Inactive U Mill Tailings Site at Canonsburg, PA. "Meeting on 830726 suggested. BALL.D.M. Energy, Dept. of. 83/07/15. NIXON,W.A. Nuclear Material Bafety & Bafeguards,Director. 30pp.
- DOCKET 40-6659 GETTY DIL CO. PETROTOMICS CO., SHIRLEY BABIN, WY
- 8307250299 Responds to 830624 notice of deviation. Quarterly spot check for personnel contamination conducted & documented on 830519 & contamination monitor alarm setpoint reset. Implementation dates to be adhered to unless extended by written approval. #HITMAN.J.H. Getty/Petrotomics Co. 83/06/30. BROWN.G.D. Region 4. Office of Director. 2pp. 19701:352. Region 4.
- DOCKET 40-4940 KAWECKI BERYLCO IND., INC., BOYERTOWN, PA
- 8307060493 Ack cooperation extended during 830607-08 site visit. Trip rept re insp & discussions held encl. Action re release of facility for unrestricted use cannot be taken until survey results submitted. results submitted. COOL.D.A. Uranium Fuel Licensing Branch. 83/06/23. COYCLE.F.T. KBI Corp. 1p. 19299:206.
- --8307060497 Trip rept of 830607-08 sits visits in Boyertown, Revere & Reading, PA to accompany Region I inspector on safety insp of bioassay program & groundwater conditions. CCOL. D. A. Uranium Fuel Licensing Branch. 83/06/22. Uranium Fuel Licensing Branch. 83/06/22.
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., DKLAHOMA CITY, OK
- 8307080548 Requests extension of Amend 17 to License SUB-1010 until 840901 to exempt treated raffinate storage pands from spare ponding requirements of Condition 13. Amend 22 approving deep well injection issued 6 months late. SHELLEY, W. J. Kerr-McGee Corp. 83/06/21. PAGE, R. G. Uranium Fuel Licensing Branch. 1p. 19365:039.
- DOCKET 40-8035 COTTER CORP., ROSWELL, NM
- 8307280165 Provides update of activities re design of containment bldg to store radwaste temporarily. JARBOE.E.D. Futura Coetings, Inc. 83/07/05, RIFAKES.G. Commonwealth Edison Co. 2pp. 19826:273.
- DOCKET 40-8064 EXXON MINERALS CO., USA, HOUSTON, TX
- B307200167 Confirms 830523 & 24 telcon agreements to incorporate listed items pertaining to expanded R&D pilot in situ U mine, into B20917 submittal List of target restoration values encl.
  OILCHRIST, J. E. Exxon Corp. 83
  Field Office. 5pp. 19670; 323. 83/05/24. ROSS.F. Uranium Recovery

DOCKET 40-8331 AFRICAN METALS CORP., NEW YORK, NY

8307190331 Confirms contract of agreement  $t_{\rm c}$  settlement under which DOE agrees to take title of residues stored at site. DOE agrees to take title of residues stored at site, effective 830701. SMICK. V. Afrimet Indussa, Inc. 83/06/27. CROW.W.T. Division of Fuel Cycle & Material Safety. 1p. 19654:044.

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CD., BROOMETEIN, CD.

8307220009 Forwards "Nine Mile Lake Pattern 4 Restoration Rept." Authorization of well abandonment for carbonate pattern requested.

NEUMANN.M.R. Rocky Mountain Energy Co. 83/06/06. SMITH.R.D. Uranium Recovery Licensing Branch. SUNDIN.R. Wyoming, State 2pp. 19692:169.

Wyoming, State of.

8307180254 Forwards "Nine Mile Lake Pattern 4 Restoration Rept." Authorization of well abandonment for carbonate pattern

AUCUMANN.M.R. Rocky Mountain Energy Co. 83/0 Uranium Recovery Licensing Branch. SUNDIN.R. 2pp. 19566:219. 83/06/17. SMITH, R. D. Wyoming, State of.

--8307180256 "Nine Mile Lake Pattern 4 Restoration Rept." \* Rocky Mountain Energy Co. 83/05/31. 93pp. 19366:221.

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

8307180394 Informs of installation of clay liner in remaining incremental areas of tailings basin commencing 830705 Rept will be submitted upon completion of installation for

MEDLOCK.R.L. Bear Creek Uranium Co. 83/06/27. SMITH.R.D. Uranium Recovery Field Office. 1p. 19567:362.

DOCKET 40-8550 HOLMES & NARVER, INC., ANAHEIM, CA

8307260318 Forwards IE Insp Rept 40-8550/83-01 on 820518-830422.No noncompliance noted. BROWN 9.D. Region 4, Office of Director. 83/06/03. ALVY, R. R. Holmes & Narver, Inc. 2pp. 19726:082.

--8307260329 IE Insp Rept 40-8550/83-01 on 820518-830422 No noncompliance noted Major areas inspected: review of transfer & disposal of licensed matls, decontamination activities, surveys &

independent measurements.

SPITZBURG, D. B., EVERETT, R. J. Region 4, Office of Director.
83/05/24. 3pp. 19726:084.

DOCKET 40-8584 MINERALS EXPLORATION CO. , LOS ANGELES, CA

8307110762 Forwards corrected Table 1 to 830412 submittal re Sweetwater U Project describing requested changes to contamination surveys & radiation protection training. KLEIN.T.J. Union Minerals. 83/06/10. SMITH.R.D. Uranium Recovery Field Office. 2pp. 19391:246.

DOCKET 40-8585 WYOMING MINERAL CORP., LAKEWOOD, CO

8307080838 Requests approval to use proposed disposal procedures for disposal of waste ion exchange resins containing low levels of U & trace quantities of Ra-226 & Th-230 at Kennecott Copper Mine.

RUTLEDGE, C. Wyoming Mineral Corp. B3/05/10. SMITH, R.D. Uranium
Recovery Licensing Branch. 3pp. 19365:047.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC., DENVER, CO

B307210015 Forwards IE Insp Rept 40-8681/83-01 on B30511-12.No noncompliance noted.
BROWN, G. D. Region 4, Office of Director. B3/06/10. SPARLIN Energy Fuels Nuclear, Inc. 2pp. 17667:213. 83/06/10. SPARLING, D. K.

--8307210020 IE Insp Rept 40-8681/83-01 on 830511-12 No noncompliance noted Major areas inspected: U milling operations & radiation safety program, including organization mgt & training & independent measurements.

CAIN.C.L. EVERETT.R.J. Region 4, Office of Director. B3/06/07, 6pp. 19669:215.

DOCKET 40-869B PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8307130345 Forwards application to amend License SUA-1371, reducing environ & radiological safety monitoring programs on interim basis to reflect temporary suspension of processing operations. QERDEMAN.F.W. Plateau Resources, Ltd. 83/06/20. SMITH.R.D. Uranium Recovery Field Office. 2pp. 19509: 284.

-8307130367 Application for amend of License 8UA-1371, reducing environ & radiological safety monitoring programs on interim basis to reflect temporary suspension of operations.

\* Plateau Resources, i.td. 83/06/20. 38pp. 19309:286.

8307180370 Forwards revised Page 4 to "Interim Surety Estimates for Decommissioning & Reclamation," correcting inflation factor. GERDEMAN.F.W. Plateau Resources, Ltd. 83/06/20. SMITH,R.D. Urenium Recovery Field Office. 3pp. 17441:274.

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

8307090105 Summarises Cleveland-Cliffs perceptions from 830511 discussions & agreements concerning fulfillment of obligations to State of WY re efforts to effect water quality restoration.
SUNDANL, J. A. Godfrey & Sundahl. 83/06/14. FREUDENTHAL, N. Wyoming, Btate of. 4pp. 19366;319.

8307180372 Forwards Guideline 8 results for 6-month sampling of 10 stability wells in B well field, supplementing partial 830615

MUDDECK, D. J. Cleveland-Cliffs Iron Co. 83/06/21, FREUDENTHAL, N. Wyoming, State of. Spp. 19641; 287.

DOCKET 40-8722 BRUSH WELLMAN, INC., CLEVELAND, OH

8307260490 Forwards fuel cycle & matls LER summary for June 1983. BROWN, G. D. Region 4, Office of Director. 83/07/19. DAVIS, J. G. Office of Nuclear Material Safety & Bafeguards, Director. 2pp. 19734:183.

DOCKET 40-8724 CHEMETRON CORP., CHICAGO, IL

8307280227 Application for renewal of License BUB-1357, extending expiration date until 840731. DESMAN.R.J. Chemtron Corp. 83/06/28. PAGE.R.G. Uranium Fuel Licensing Branch. 3pp. 19826:074.

DOCKET 40-8743 CONDCO, INC., DENVER, CO

8307130043 Relinquishes 800731 application for source matl license HARVEY,R.C. CONDCO,Inc. (Continental Dil Co.). 83/06/10. BMIT Uranium Recovery Field Office. 2pp. 19511;303.

DOCKET 40-8748 KERR-MCGEE NUCLEAR CORP. . OKLAHOMA CITY, DK

8307200219 Third semiannual rept covering ALARA audit performed on 830923 & 24.5ep License Condition 27.W/830403 ltr. SINKE, G. J. Kerr-McGee Corp. 83/06/03. Uranium Recovery Licensing Branch. 5pp. 19670:295.

8307130086 Forwards addendum to semiannual ALARA review rept ¢td B30603. BINKE, G. J. Kerr-McGee Corp. 83/06/15. Brench. 3pp. 19511:289. Uranium Recovery Licensing

9307200209 Addendum to 830403 semiannual ALARA review rept for 1982 & First Quarter 1983 required by License SUA-1387, W/830415 197. BINKE,G.J. Kerr-McGee Corp. 83/06/15. Branch. 4pp. 19670:300. Uranium Recovery Licensing

DOCKET 40-8829 WYGMING FUEL CO., LAKEWOOD, CO

8307230302 Forwards revised "Aquifer Testing at Crow Butte U Project, Wyoming Fuel Co." Rev based on discussions during 830331 & OAO1 trip to Lincoln.NE. WILLIAMS.R.E. R.E. Williams & Associates, Inc. 83/06/13, WABILER.S. Uranium Recovery Field Office. 1p. 19721:067.

---8307250506 "Aquifer Testing at Crow Butte U Project, Myoming Fuel Co." \* R.E. Williams & Associates, Inc. 83/05/20. 33pp. 19721:068.

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8307080532 Summary of 830512 meeting w/univ in Ann Arbor,MI re licensee safeguards program & other proprietary info.
ROBSOMONDO. C. Fuel Facility Safeguards Licensing Branch. 83/05/16.
BROWN.W.B. Fuel Facility Safeguards Licensing Branch. 1p.
19365:050. 24X Fiche:50-002,83/05/16.8307080532.

8307060413 Forwards review & evaluation of emergency plan against App E to 10CFR50 requirements & Rev 1 to Reg Ouide 2.6. Plan acceptable & should be implemented within 120 days. THOMAS.C.O. Standardization & Special Projects Branch. 83/06/24. KERR.W.F. Michigan. Univ. of. 4pp. 19299:351. 24X Ficha: 50-002.83/06/24.8307060413.

#### Q. Inspection reports, IE Bulletins & correspondence

B307200257 Clarifies Page 4.Section 9.a of B30516-18 routine safety insp.per NRC B30610 ltm. Section me beam port floor extracted from facility investigative rept under consideration but not implemented as procedure.

KERR.W. Michigan, Univ. of. B3/07/12. PAPERIELLO.C. J. Region 3, D#ficc of Director. ip. 19648:136. 24X Fiche:50-002.B3/07/12. B307200257.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 378, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. Ø. Division of Licensing. 83/07/11, Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

#### DOCKET 50-3 INDIAN POINT STATION, UNIT 1

# P. Operating license stage documents & correspondence

8306270397 Generic Ltr 83-26 to 411 applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Byc list encl. EISENHUT. D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000.83/07/05.8306270397.

8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 818.8vc list enci. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.

8307080167 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENMUT. D. @. Division of Licensing. 83/07/08. Cansolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000,83/07/08,8307080167.

# Q. Inspection reports. IE Bulletins & correspondence

B306270401 |E Info Notice B3-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Cansolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.

8305270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid," Svc list enct. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17553:153. 24X Fiche: 50-000, 83/07/12, 8306270404.

8306270406 IE info Notice 83-48, "Gaseous Efficient Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Byc list encl. TAYLOR, J. M. Division of GA. Befeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406. DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR
V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B. "Personal Qualifications 8tatement - Licensee." Svc list encl. EISENUUT.D.O. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche:50-000.83/07/11.8307080427.

DOCKET 50-8 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

J. Insurance & indemnity information

8307080005 Executed Amend 17 to Indemnity Agreement E-7, effective 830613. Accepted by univ on 830627.

8ALIZMAN J. Assistant Director for State & Licenses Relations. 83/06/27. ip. 19351:246. 24X Fiche: 50-008, 83/06/27, 8307080005.

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8307050249 Forwards IE Safeguards Insp Repts 50-010/83-10,50-237/83-15 & 50-249/83-24 on 830523-27. HIND, J.A. Region 3. Office of Director. 83/06/23. REED.C. Commonwealth Edison Co. 2pp. 19198:354. 24X Fiche: 50-010,83/06/23,8307050249.

---8307050262 IE Bafeguards Insp Repts 50-010/83-10 50-237/83-14 & 50-249/83-14 on 830523-27. Noncompliance noted: security violations not reported in required manner or format. Details withheld (ref 10CFR73. 21). PIRTLE.9. L. Region 3, Office of Director. 83/06/23. 2pp. 19178: 356. 24X Fiche: 50-010, 83/06/23, 8307080249.

8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan.Plan deficiencies marked. Flow chart for general emergency offsite protective decisions enci. PAPERIELLO.C.J. Region 3, Office of Director. 83/07/26. REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 50-000, 83/07/26.8307280347.

#### G. Adjudicatory correspondence

8307120595 Advises that time for Commission to review Director's Decision DD-83-8 expired Commission declined review. Decision became final agency action on 830705. CHILK-S.J. Office of the Secretary of the Commission. 83/07/11. 0UIGG.C. Pollution & Environmental Problems, Inc. ip. 19433:076. 24% Fiche: 50-000.83/07/11,8307120595.

# J. Insurance & indemnity information

8307260430 Forwards Endorsements 146 & 147 to NELIA Policy NF-43 & Endorsements 123 & 124 to MAELU Policy MF-22, OSTERIJ. Commanuralth Edison Co. 83/07/19. SALTZMAN, J. Assistant Director for State & Licensee Relations. Spp. 19734:178. 24X Fiche: 50-010, 83/07/19, 8307260430.

# P. Operating license stage documents & correspondence

8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 30-000, 83/07/05, 8306270397.

8307060329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in ST8.8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche: 50-000, 83/07/06. 8307060327.

8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York: Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.

# Q. Inspection reports, IE Bulletins & correspondence

- 8307050249 Forwards IE Bafeguards Insp Repts 50-010/83-10.50-237/83-15 \$ 50-249/83-24 on 830523-27. 
  HIND J.A. Region 3, Office of Director. 83/06/23. REED.C. Commonwealth Edison Co. 2pp. 19198.354. 24X Fiche: 50-010.83/06/23, B307050249.
- --8307050262 IE Safeguards Inap Repts 30-010/83-10 50-237/83-14 & 50-249/83-14 on 830523-27. Noncompliance noted: security violations not reported in required manner or format. Details withheld (ref iOCFR73, 21).
  PIRTLE, G. L., KNICELEY, J. R., CREED, J. R. Region 3, Office of Director. 83/06/23, 2pp. 19198: 356. 24X Fithe: 50-010, 83/06/23, 8307050249.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Ficha: 50-000, B3/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JCRDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 14ipp. 17963:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 830627040& IE Info Notice 83-4B, "Oaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307280287 Forwards IE Insp Repts 50-010/83-11,50-237/83-19 & 50-249/83-17 on 930606-10 & 17. No noncompliance noted. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. B3/07/14. REED. C. Commonwealth Edison Co. 2pp. 19770: 209. 24X Fiche: 50-010, B3/07/14, 8307280287.
- --8307280293 IE Insp Repts 50-010/83-11, 50-237/83-19 & 50-249/83-17 on 830606-10 & 17. No noncompliance noted. Major areas inspected: records & repts of effluents.effluent control instrumentation & procedure for controlling releases. PAUL.R. A., OREGER.L. R. Region 3, Office of Director. 83/07/13, 7ρp. 19790: 211. 24X Fiche: 50-010, 83/07/14, 8307280287.
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util, per 830715 discussion.

  NORELIUS.C.E. Division of Project & Resident Programs.

  REED.C. Commonwealth Edison Co. 2pp. 19791:167. 24X Fiche: 50-000, 83/07/22, 8307280084.
- --8307280102 Confirms request for NRC & util senior mgt meeting on 830726 in Chicago, it to discuss licensee regulatory performance & relationship w/NRC.

  REED.C. Commonwealth Edison Co. 83/07/11, DAVIS, B.A. Region 3, Office of Director. 1p. 19791:171, 24X Fiche: 50-000, 83/07/22, 8307280084.
- 8307280446 Forwards SALP Repts 50-010/83-13,50-237/83-18 & 50-249/83-16 for Jan-Dec 1982 Endorses that assessments are indicative of util efforts to improve performance at facilities.

  KEPPLER J. G. Region 3, Office of Director. 83/07/25, REED, C. Commonwealth Edison Co. 2pp. 19797:206, 24X Fiche: 50-010,83/07/25,8307280446.
- --8307280450 SALP Repts 50-010/B3-13,50-237/B3-18 & 50-249/B3-16 for Jan-Dec 1982.

  \* Region 3, Office of Director. 83/07/25, 27pp. 19797:208. 24X Fichs:50-010,83/07/25,8307280446,
- ---8307280454 Discusses upcoming 830512 meeting in Glen Ellyn, IL to discuss SALP rept for Jan-Dec 1782.

  HIND: J. A. Division of Radiological & Materials Safety Programs, 83704/22. REED. C. Commonwealth Edison Co. 2pp. 19797: 236. 24) Fiche: 50-010,83/07/25,8307280444.
- --B307280457 Forwards comments on SALP repts based on 830512 meeting. Practice of issuing reduced rating to all five operating plant sites for same alleged corporate weakness tends to overamphasize significance of alleged deficiency. REED.C. Commonwealth Edison Co. B3/05/31. KEPPLER.J.O. Region G. G. Office of Director. Δpp. 19797:23B. 24X Fiche: 30-010, 83/07/25, 8307280446.

#### S. Reportable occurrences, LERs & related correspondence

8307220446 Part 21 rept re-possible discrepancy in variable springs in turnbuckle & top plate assemblies bult interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.

LITKA: T. J. Elicen Metal Products Co. 83/07/15. KEPPLER: J. G. Region 3, Office of Director. 26pp. 19686:086. 24X Fiche: 50-000,83/07/15,8307220446.

DUCKET 50-13 BABCOCK & WILCOX CO. CRITICAL FACILITY
V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 39B, "Personal Qualifications Statement - Licenses." Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000, 83/07/11.8307080427.

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

R. Periodic operating reports & related correspondence

B307260455 "Annual Rept for Decommissioned License DPR-9, May 1982 - June 1983. W/B30711 ltr.
MAVEAL.W. T., ORIFFINO.E. P., ALEXANDERSON.E. Detroit Edison Co.
B3/07/12. STOLZ.V. Operating Reactors Branch 4. 13pp. 19733:241.
24X Fiche: 30-016.83/07/12,8307260455.

DOCKET 50-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR
F. Security, medical, emergency & fire protection plans

8307070515 Forwards evaluation of emergency plan per requirements of App E to 10CFR50 & Rev 1 to Reg Quide 2.6.Plan acceptable. Implementation should be accomplished within 120 days.

THOMAS. C. O. Standardization & Special Projects Branch. 83/06/24. CLARK.L. Massachusetts Institute of Technology. 5pp. 19300: 339. 24X Fiche: 50-020:83/06/24,8307070515.

P. Operating license stage documents & correspondence

8307280441 Submits rept on remeasurement of MITR-II temp coefficient & analysis of results. Core temp coefficient of reactivity negative in normal operating range & existence of positive uniform temp coefficent not safety hazard. CLARK.L. Messachusetts Institute of Technology. 83/07/22. ALLAN.J.M. Region 1, Office of Director. 3pp. 19797:114. 24X Fiche: 50-020, 83/07/22, 8307280441.

V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Syc list encl. EISENHUTD, O. Division of Licensing, 83/07/11, Michigan, Univ. of, 14pp. 19343:138, 24X Fiche: 50-000,83/07/11,8307080427.

DOCKET 50-25 DOW CHEMICAL CO. TRIGA REACTOR
V. Operator Examinations

B3070B0427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 398, "Personal Qualifications Btatement - Licenses." Syc list encl. EISENAUT.D.O. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR
C. Utility Environmental Report (ER), amends & correspondence

B307i1062l Clarifies safeguards licensing policy re inventory requirements of BMN contained in liquid & solid waste matts stored at site. Request for exception from 10CFR70. 31 should be submitted for storage of holding account waste discards. BHITH.C.N. Fuel Facility Safeguards Licensing Branch. B3/01/13. REGAN.N. Dabcock & Hilcox Co. 2pp. 19434:113. 24X Fiche: 30-027, B3/01/13, B307110621.

- F. Security, medical, emergency & fire protection plans
- 8307110603 Releases public version of licensee 830614 request for 90-day extension to submit addl emergency plan info.NRC 830610 request for addl info also released. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19391:127. 24X Fiche: 50-027, 83/06/24, 6307110603.
- B307210343 Grants extension until B30915 to respond to NRC questions on emergency plan.per B30614 request.

  THOMAS.C.D. Standardization & Special Projects Branch. 83/07/13.

  HILSON.M.E. Hashington State Univ. 1p. 19672:326. 24X

  Fiche: 50-027, B3/07/13, B307210343.

# V. Operator Examinations

- B3070B0427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 378, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 17563:138. 24X Fiche:50-000,83/07/11.8307080427.
- DOCKET 50-29 YANKEE-ROHE NUCLEAR POWER STATION
  F. Becurity, medical, emergency & fire protection plans
- 8307010130 Forwards add1 corrections to security plan. Corrections withheld (ref 100F873, 21).
  RAYLJA. Yankon Atomic Electric Co. 83/06/14. HAYNES.R.C. Region 1: Office of Director. 1p. 19175:336. 24% Fiche: 50-029:83/06/14. 8307010150.
- 8307140238 Forwards IE Safeguards Insp Rept 50-029/83-09 on 830613-17. No noncompliance noted.

  MARTIN.T.T. Region in Office of Director. 83/06/30. HEIDER.L.H. Yankee Atomic Electric Co. 2pp. 19523:106. 24X

  Fiche: 50-029, 83/06/30, 8307140238.
- --8307140242 IE Bafeguards Insp Rept 50-027/83-07 on 830613-17. No noncompliance noted Major areas inspected physical barriers (protected & vital areas), security sys power supply, assessment aids, access control & contingency plan.

  SMITH.G.C., SDDY.A.T. Region I, Office of Director. 83/06/28.

  3pp. 19523:108. 24X Fiche: 50-029.83/06/30.8307140238.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8307090095 Bummarizes 276th ACRB meetings on 830414-16 w/utils to review request for OL Agenda for 830512-14 meetings entl. EBERSOLE, J. ACRB Advisory Committee on Reactor Safeguards. 83/04/29, PALLADINO, N.J. Commissioners. 3pp. 19366:058. 24X Fiche:80-000,83/04/29,830709095.
- P. Operating license stage documents & correspondence
- 8305050070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Syc list encl.

  EISENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Elschric Co. 10pp. 17563:116. 24X Fiche: 50-000, 83/06/03.
- 8307080259 Forwards backfit cost figures for addl seven utils per original 830808 request Cost figures for 20 utils transmitted 830411.
  TOURTELLOTTE, J. Regulatory Reform Task Force. 83/06/22.
  PALLADINO, N., OILINSKY, V., AHEARNE, J. Commissioners. 2pp. 19363; 313. 24X Fiche: 50-000, 83/06/22, 8307080259.
- --B3070B0366 Forwards summary of backfitting costs for facility.per NRC request.
  EDMARDS.D.H. Yankee Atomic Electric Co. 83/05/11.
  TAURTELLOTTE.J. Regulatory Reform Task Force. 2pp. 19364:014.
  24X Fiche: 30-000,83/06/22,83070B0259.
- 8304270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of survaillance requirements for diesel fuel impurity. Svc list encl. EIBENHUT, D. O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05.8306270397.

- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:294. 24X Ficha: 50-000, 83/07/06, 8307060329.
- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269. 24X Fiche: 50-000. 83/07/08. B307030169.
- 8307280416 Application to amend License DPR-3, consisting of Proposed Tech Spec Change 180 to modify surveillance testing of electrical penetrations & personnel hatch & to revise containment valve isolation valve listing, Table 3.6-1.
  HEIDER, L. H. Yankee Atomic Electric Co. 83/07/19. Office of Nuclear Reactor Regulation, Director. 26pp. 19795:313. 24x
  Fiche: 50-029.83/07/19.8307280416.
- --8307280423 Proposed Tech Spacs 3/4.6. "Containment Sys" & 3/4/6/1. "Primary Containment" re containment integrity limiting condition for operation.

  \* Yankee Atomic Electric Co. 83/07/19. 14pp. 19795:331. 24X Fiche: 50-029.83/07/19.8307280416.
- B307280462 Application for amend to License DPR-3, consisting of Suppl to Proposed Change 177, changing Tech Specs re cycle dependent variables revising specific values w/symbols or blank figures to be generated for each reload core.
  HEIDER, L. H. Yankee Atomic Electric Co. 83/07/19. Office of Nuclear Reactor Regulation. Director. Spp. 19797:165. 24X Fiche: 50-029, B3/07/19, 8307280462.
- --B307280464 Proposed Tech Specs re routine change in core operating limits due to cycle dependent variables. \* Yankee Atomic Electric Co. B3/07/19. 36pp. 19797:170. 24X Fiche: 50-027, B3/07/19, B307280462.
- G. Inspection reports, IE Bullatins & correspondence
- B30714023B Forwards IE Safaguards Insp Rept 50-029/83-09 on 830613-17. No noncompliance noted.

  MRRTIN.T. T. Region i, Office of Director. 83/06/30. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 19523:106. 24X
  Fiche: 50-029, 83/06/30, 830714023B.
- --8307140242 IE Safeguards Insp Rept 50-029/83-09 on 830613-17. No noncompliance noted Major areas inspected:physical barriers (protected & vital areas), security sys power supply, assessment aids, access control & contingency plan. SMITH. O. C., GDDY. A. T. Region I, Office of Director. 83/06/28. 3pp. 19323:108. 24X Fiche: 50-029, 83/06/30, 8307140238.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Bubsystem." Svc list encl. JORDAN.E. L. Division of Emergency Preparagness & Engineering Response (Post 830103). 83/07/11. Consolidated Edjeon Co. of New York, Inc. 154pp. 19563: 293. 24X Fiche: 50-000, 83/07/11, 8306270401
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Syc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 90-000, 83/07/12, 8306270404
- 8306270406 IE Info Notice 83-48, "Qaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 30-000, 83/07/14, 8306270406.
- B307270344 Advises that no further action required re 800508 analysis of main steam line b/continued feedwater addition.per IE Bulletin 80-04. NRC review contained in B30523 safety evaluation of SEP Topics VI-2.D & VI-3. CRUTCHFIELD.D. Operating Reactors Branch 9. 83/07/26. KAY, J. A. Yankee Atomic Electric Co. 2pp. 19767: 295. 24X Fiche: 50-029, 83/07/26, 8307270344.
- R. Periodic operating reports & related correspondence
- 8307220039 Monthly operating rept for May 1983.W/830607 ltr. BATTERSON.S., HEIDER.L.H. Yankee Atomic Electric Co. 83/06/07. Office of Resource Management, Director. 6pp. 19674:075, 24X Fiche:30-029.83/06/07.8307220039.

# **DOCKETED ITEMS**

- S. Reportable occurrences, LERs & related correspondence
- B307010114 LER B3-018/03L-0: on B30318, body-to-bonnet leak found on Pacific Valve, Inc valve 5A-V-603, causing 5 h valve & steam generator blowdown monitor 3 isolation. Caused by failure of bady-to-bonnet joint gasket. W/830617 ltr.

  MAY. E. L. , AUTIO, H. A. Yankee Atomic Electric Co. B3/06/17.

  ALLANJ. M. Region 1, Office of Director. 2pp. 19169: 241. 24X Fiche: 50-029, 83/06/17, 8307010114.
- 8307010024 LER 83-019/03L-0: on 830523, lightning strike causes Z-126
  115 kV transmission line at Harriman Hydro Station
  switchyard to open & lock out, resulting in loss of
  continuity of circuit. W/830622 ltr.
  RICE, D.A., AUTIO, H.A. Yankee Atomic Electric Co. 83/06/22.
  ALLAN, JM. Region 1, Office of Director. 2pp. 19169: 085. 24X
  Fiche: 50-029, 83/06/22, 8307010024.
- B307010037 LER B3-020/03L-0: on B30524, during performance of safety injection, setpoint of time delay relay 4 found out of Tech Spec limits. Caused by setpoint drift: Setpoint readjusted. W/B30623 ltr.
  AUTIO.H.A.: FRENCH.L.D. Yankee Atomic Electric Co. 83/06/23. ALLAN.J.M. Region 1, Dffice of Director. 2pp. 19167:194. 24X Fiche: 50-027, B3/06/23, B307010037.
- 8307010127 Supplemental LER. 83-012/01T-1: on 830405, bonnet stud found to have failed on PR-MGV-191. Caused by slight leakage from valve. Valve replaced w/1 1/2-inch Pacific Model 5-31552-12-X gate valve. W/830623 ltr.
  FRENCH.L. D. , AUTIO.H. A. Yankee Atomic Electric Go. 83/06/23.
  ALLAN.J. M. Region 1. Office of Director. 3pp. 19175:323. 24X Fiche: S0-029,83/06/23,8307010127.
- B307150130 LER B3-021/03L-0: on B30531, valve SA-V-603 had body bonnet leak. Caused by failure of valve body-to-bonnet joint gasket & steam cutting of seating surface. Gasket replaced W/B30630 ltr.
  MAY. E. L. , AUTIO, H. A. Yankee Atomic Electric Co. B3/06/30. ALLAN, J. M. Region 1. Office of Director. 2pp. 17535: 264. 24X Fiche: 50-029, 83/06/30, 8307150130.
- 8307150319 LER 83-024:on 830629, error discovered in power level calculation. Caused by false boiler feedwater temp input used to determine reactor thermal power due to failure of resistance temp detector cable.

  AUTIO.H.A. Yankee Atomic Electric Co. 83/06/30. ALLAN, J. M. Region 1, Office of Director, 1p. 19533:018. 24X Fiche: 50-027, 83/06/30, 8307150319.
- B307220327 LER B3-024/01T-0: on B30629, while performing OP-7302 to determine unexplained 2 F increase in reactor power, increased feedwater temp noted Caused by failure of 12-inch RTD jumper cable M/830713 itr.
  MAY.E.L., LAURENT, N. Vankee Atomic Electric Co. B3/07/13.
  MURLEY, T. E. Region 1, Office of Director. 3pp. 17675:126. 24X Fiche: 50-029, B3/07/13, B307220327.
- 8307220295 LER 83-022/03L-0: on 830614, lightning induced electrical disturbance on Z-126 115 kV transmission line resulted in plant trip. Caused by lightning strike on transmission line. Busses & equipment returned to svc.W/830714 ltr. FRENCH, L. D., ST LAURENT, N. N. Yankee Atomic Electric Cq. 83/07/14. WMRLY, T. E. Region J. Office of Director. 3pp. 17684:137. 24% Fiche: 50-027,83/07/14,8307220295.

# DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 8307010013 Forwards physical security plan for facility.updated through Rev 3.Plan withheld.

  VDTH.M.H. Union Carbide Corp. 89/04/21. CARLSON, D. Office of Nuclear Material Safety & Safeguards, Director. ip. 17124:362. 24X Fiche: 30-054, 83/04/21, 8307010013.
- B307010113 Forwards Rev 4 to physical security plan. Rev withheld. VDTH.M.H. Union Carbide Corp. B3/05/17. Office of Nuclear Reactor Regulation, Director. 1p. 19167: 236, 24X Fiche: 50-054, 83/05/19, 8307010113.
- 8307070527 Forwards review of emergency plan per App E to 10CFR50 requirements & Rev I to Reg Guide 2.6. Plan unacceptable. Addl info identified in encl must be provided by 830615. THCMAS.C.O. Standardization & Special Projects Branch. 83/06/23. MCGQVERN.J. Union Carbide Corp. Spp. 19300:351. 24X Fiche: 50-054, 83/06/23, 8307070527.

- 8307210336 Forwards Amend 20 to License R-81 identifying currently approved physical security plan submitted w/830421 ltr. Physical security plan should be implemented within 30 days. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/12. MCGOVERN.J. Union Carbide Corp. 3pp. 19672:327. 24X Fiche: 50-054, 83/07/12, 8307210336.
- --8307210338 Amend 20 to License R-B1, incorporating approved physical security plan.
  THOMAS, C. D. Standardization & Special Projects Branch. 83/07/12, 2pp. 19672: 330. 24X Fiche: 50-054, 83/07/12, 8307210336.
- P. Operating license stage documents & correspondence
- 8307080493 Responds to Ryzicka 830602 ltr advising NRC that fuel element cladding math being changed from Series 1100 to Series 6061 aluminum. Agrees w/conclusions. Change must be reported in annual rept.
  THOMAS.C.O. Standardization & Special Projects Branch. 83/06/29. McGOVERN.J. Union Carbide Corp. 1p. 19365:068. 24X Fichs: 50-054, 83/06/29, 8307080493.
- 8307210336 Forwards Amend 20 to License R-81 identifying currently approved physical security plan submitted w/830421 ltr. Physical security plan should be implemented within 30 days. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/12. MCGOVERN.J. Union Carbida Corp. 3pp. 19672:327. 24X Fiche: 50-054.83/07/12,8307210336.
- --B307210338 Amend 20 to License R-B1.incorporating approved physical security plan.
  THOMAS.C.D. Standardization & Special Projects Branch. 83/07/12.
  Rpp. 19672:330. 24X Fiche:30-054.83/07/12.8307210336.
- V. Operator Examinations
- B307080427 Generic Ltr B3~12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Qualifications Btatement - Licensee." By: list encl. EIBENRUT.D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fichs:50-000.83/07/11,8307080427.
- DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR
  F. Becurity, medical, emergency & fire protection plans
- 8307140079 Forwards IE Safeguards Insp Rept 50-057/83-02 on 830601 No noncompliance noted.

  MARTINIT.T. Division of Engineering & Technical Programs. 83/06/29.

  HENRYLL 9. New York, State Univ. of, Buffelo. 2pp. 19514:179.

  24X Fiche: 50-057,83/06/29,8307140079.
- --B307140086 IE Safeguards Insp Rept 50-057/83-02 on B30601. No noncompliance noted. Major areas inspected: physical protection measures for protecting SNM of low strategic significance.
  SMITH.O.C., GGDY.A.T. Region 1, Office of Director. 83/06/27.
  2pp. 19514:181, 24X Fiche: 50-057, 83/06/29, 8307140079.
- 8307200505 Forwards Amend 18 to License R-77.notice of issuance & negative declaration. Tech Specs. SER & EIA. M/o SER. Amend renews license for 20 yrs & incorporates physical sacurity plan. W/o SER. EISENHUT. D. Q. Division of Licensing. 83/07/11. HENRY, L. Q. New York, State Univ. of, Buffalo. 3pp. 19672: 027. 24X
- --8307200510 Amend iB to License 8-77, renewing license for 20 yrs & incorporating physical security plan.
  EISEMULT.D. Q. Division of Licensing. 83/07/12. 4pg. 19672:030.
  24X Fiche: 50-057,83/07/11,8307200505.
- --8307200511 Notice of renewal of License R-77 for 20 yrs & negative declaration.
  THOMAS.C.O. Standardization & Special Projects Branch. 83/07/11.
  41pp. 17672:034. 24X Fiche:50-057,83/07/11.8307200505.
- --B307200515 EIA supporting Amend 18 to License R-77. # NRC - No Detailed Affiliation Given. 83/07/11. 7pp. 19472:075. 24X Fiche: 50-057.83/07/11,8307200505.

#### P. Operating license stage documents & correspondence

8307200305 Porwards Amend 18 to License R-77.notice of issuance & negative declaration.Tech Specs.BER & E1A.W/o SER. Amend remaws license for 20 yrs & incorporates physical security plan.W/o SER.
EIBENHUT.D. 9. Division of Licensing. 83/07/11. HENRY.L.O. New York, State Univ. of, Buffalo. 3pp. 19472:027. 24X Fiche: 50-057.83/07/11,8307200505.

--8307200510 Amend 18 to License 8-77, renewing license for 20 yrs & incorporating physical security plan.
EISENUT.D.O. Division of Licensing. 83/07/12. 4pp. 19672:030.
24% Fiche: 50-057, 83/07/11.8307200505.

--B3072005ii Notice of renewal of License R-77 for 20 yrs & negative declaration, THOMAS,C.O. Standardization & Special Projects Branch. 83/07/11. 41pp. 19672:034, 24X Fiche:50-057,B3/07/11.8307200505.

--8307200515 EIA supporting Amend 18 to License R-77. \* NRC - No Detailed Affiliation Given. 83/07/11. 7pp. 19672:075. 24X Fiche: 50-057.83/07/11.8307200505.

# G. Inspection reports, IE Bulletins & carrespondence

8307140077 Forwards IE Bafeguards Insp Rept 50-057/83-02 on 830801. No noncompliance noted.

MARTIN,T.T. Division of Engineering & Technical Programs. 83/06/29.

HENRY,L.G. New York, State Univ. of, Buffaio. 2pp. 19514:179.
24X Fiche: 50-057, 83/06/29, 8307140079.

--8307140086 IE Safeguards Insp Rept 50-057/83-02 on 830601. No noncompliance noted Major areas inspected physical protection measures for protecting SNM of low strategic significance.

BMITH. O. C., GDDY, A. T. Region 1, Office of Director. 83/06/27.

2pp. 19514: 181. 24X Fiche: 50-057, 83/06/29, 8307140079.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 39B. "Personal Qualifications Statement - Licenses." Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/11. Michigan. Univ. of. 14pp. 19563:138. 24X Fiche: 50-000.83/07/11.8307080427.

DOCKET 50-59 TEXAS ALM UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8307070230 Forwards review of smargency plan per requirements of App E to 100FRSO & Rev 1 to Reg Ouide 2.6.Plan acceptable. Implementation should be acceptished within 120 days of 1tr receipt.

THOMAS.C. G. Standardization & Special Projects Branch. 83/06/24. ERDMAN.C. A. Texas A&M Univ. College Station, TX. 4pp. 19344: 954. 24X Fiche: 50-059, 83/06/24, 8307070230.

# H. General correspondence

8307260566 Informs that B Willits will join staff-effective 830601, in order to strengthen technical & mgt personnel Author will serve as acting reactor supervisor until replacement for B Willits hired & licensed.

SCHLAPPER.O.A. Texas A&M Univ., College Station, TX. 83/05/31.
COLLINS.J.T. Region 4, Office of Director. 1p. 19731:144. 24X Fiche:50-059,83/05/31,8307260566.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Gualifications Statement - Licensee." Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche:50-000.83/07/11.8307080427.

DOCKET 50-62 UNIV. OF VIRGINIA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8307210344 Grants extension until 830915 to respond to NRC questions on amergency plan.per 830624 request.

THOMAS.C.G. Standardization & Special Projects Branch.
BRENIZER.J.S. Virginis. Univ. of. Charlottesville, VA. 1p.
19672:325. 24X Fiche: 50-062,83/07/13.8307210344.

8307250514 Releases public version of licensee request for extension for responding to emergency plan review. FELTON, M. Division of Rules and Records. 83/07/19. Document Management Branch. ip. 19725:361. 24X Fiche: 50-062,83/07/19,8307250514.

--8307250521 Forwards public version of request for 60-day extension for responding to emergency plan review. Extension needed to allow rewriting, review & approval of SOPs to improve reactor operations.

BRENIZER.J.S. Virginia, Univ. of, Charlottesville, VA. 83/06/24.

THOMAB.C.O. Standardization & Special Projects Branch. 1p. 19720: 341. 24X Fiche: 50-062, 83/07/19, 8307250514.

# S. Reportable occurrences, LERs & related correspondence

B307120206 Updated RO re B30525 low shutdown margin during criticality. Initially reported on B30609. Caused by change in control rod reactivity worth curves due to fuel burnup. Procedures for shutdown margin & reactivity worth determination rewritten. RERNIZER. J. S. Virginia. Univ. of. Charlottesville, VA. B3/06/30. 0/REILLY.J.P. Region 2. Office of Director. 3pp. 19423:289. 24X Fiche: 50-062.83/06/30, 8307120206.

# V. Operator Examinations

B307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Hichigan, Univ. of. 14pp. 19543:138. 24X Fiche:50-000.83/07/11.8307080427.

DOCKET 30-70 GENERAL ELECTRIC TEST REACTOR

G. Adjudicatory correspondence

8307050130 Order extending time until 830718 for Commission to act to review ALAB-720.
CHILK,S. J. Office of the Secretary of the Commission. 83/06/30.
Commissioners. 1p. 19197:311. 24X Fiche: 50-070,83/06/30.

8307210301 Order extending time until 830725 for Commission to act to review ALAB-720.

CHILK, B. J. Office of the Secretary of the Commission. 83/07/18.

Commissioners. 1p. 19664:286. 24X Fiche: 50-070.83/07/18.

# V. Operator Examinations

B3070B0427 Generic Ltr B3-12A to all nonpower reactor licensess re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EIGENRUIT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.63/07/11.8307080427.

DOCKET 50-72 UNIV. OF UTAH REGEARCH REACTOR
V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 378, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/fi. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/fi.8307080427.

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR
F. Security, medical, emergency & fire protection plans

B307200027 Forwards Amend 16 to License R-33, identifying currently approved physical security plan.

THOMAS, C. D. Standardization & Special Projects Branch. B3/07/11.

DARMITZEL, R. W. Geneval Electric Co. 3pp. 19670: 349. 24X

Fiche: 30-073, B3/07/11, B307200027.

--8307200035 Amend 16 to License R-33 identifying currently approved physical security plan.
THOMAS.C.O. Standardization & Special Projects Dranch. 83/07/11.
2pp. 19670:352. 24% Fiche:50-073.83/07/11.8307200027.

#### P. Operating license stage documents & correspondence

B307200027 Forwards Amend 16 to License R-33.identifying currently approved physical security plan.
THOMAS.C.O. Standardization & Special Projects Branch. B3/07/11.
DARMITZEL.R.W. General Electric Co. 3pp. 19670: 349. 24X
Fiche: 50-073.83/07/11.8307200027.

--8307200035 Amend 16 to License R-33, identifying currently approved physical security plan.
THOMAS.C.D. Standardization & Special Projects Branch.
2pp. 19670:352. 24X Fiche:50-073.83/07/11.8307200027.

## V. Operator Examinations

B307080427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENVUT.O. G. Division of Licensing. B3/07/II. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000,83/07/II.8307080427.

# DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR

#### V. Operator Examinations

8307080427 Qameric Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee," Svc list encl. EIBENHUT. D. Q. Division of Licensing, 89/07/11, Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000,83/07/11,8307080427.

#### DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR

# F. Security, medical, emergency & fire protection plans

8307070523 Forwards review of emergency plan per requirements of App E to 100FR50 & Rev 1 to Reg Guide 2.6.Plan unacceptable. Addl info identified in encl must be provided by 830815. THOMAS.C.O. Standardization & Special Projects Branch. 83/06/23. DIAZ.N.J. Florida. Univ. of. Gainesville. 5pp. 19300:346, 24X Fiche:50-083,83/06/23,8307070523.

### V. Operator Examinations

B307080427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 37B, "Personal Qualifications Statement - Licensee." Byc list encl. EISENHUTLD.9. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000,83/07/11,8307080427.

#### DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees reissuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. 815ENHUT.D.O. Division of Licensing. 83/07/11, Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

# DOCKET 50-89 GENERAL ATOMIC CO.

# F. Security, medical, emergency & fire protection plans

B307140288 Requests extension for submittal of any new info re radiological contingency plan, per B30610 request. Extension to allow for receipt & response to addl questions from NMBS re fuel cycle portions of plan requested.

HOWRY, W. R. GA Technologies: Inc./General Atomic Co. B3/07/06. THOMAS.C.C. Btandardization & Special Projects Branch. 1p. 19525:098. 24X Fichs: 50-089, 83/07/06, 8307140288.

# G. Adjudicatory correspondence

B307140450 Response to UCLA B30630 motion to reopen record to take official notice of class of NRC license held by GA
Technologies. NRC does not appose motion, but motion unnecessary since record not closed.
MODDHEAD, C. P. Hearing Branch 4. B3/07/12. Atomic Safety and Licensing Board Panel. 2pp. 19521:185. 24X Fiche:50-000,83/07/12,8307140450.

--8307140457 Amend 21 to License R-38. SKOVHOLT.D.J. NRC - No Detailed Affiliation Given. 72/01/21. 3pp. 19521:187. 24X Fiche: 50-000,83/07/12,8307140450. --8307140462 Amend 21 to License R-67. Certificate of Svc encl. SKOVHOLT, D. J. Atomic Energy Commission. 6B/09/27. 6pp. 19521: 190. 24X Fiche: 50-000, 83/07/12, 8307140450.

# V. Operator Examinations

B3070B0427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHVI.D.G. Division of Licenseing. 83/07/11. Hichigan, Univ. of. 14pp. 19563:13B. 24X Fiche:50-000.83/07/11.8307080427.

#### DOCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR

# F. Security, medical, emergency & fire protection plans

8307110369 Forwards 1E Bafaguards Insp Repts 50-097/B3-02 & 50-157/B3-02 on 830602-03. No noncompliance noted.
MARTIN, T. Division of Engineering & Technical Programs. 83/06/22.
STREETT, W. B. Cornell Univ. 2pp. 19380:261. 24X
Fiche: 50-097, 83/06/22, 8307110369.

--8307110372 IE Safeguards Insp Repts 50-097/83-02 & 50-157/83-02 on 830602-03. No noncompliance noted Major areas inspected: physical protection measures for protecting SNM of low strategic significance.

EMITH Q. C. CODY, A. T. Region 1, Office of Director, 83/06/21, 3pp. 19380: 263. 24X Fiche: 50-097, 83/06/22, 8307110369.

# G. Inspection reports, IE Bulletins & correspondence

8307110369 Forwards IE Bafeguards Insp Repts 50-097/83-02 & 50-157/83-02 on 830602-03.No noncompliance noted.
MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/22.
STREETI.W.B. Cornell Univ. 2pp. 19380:241. 24%
Fichs: 50-097, 83/06/22, 8307110369.

--8307110372 IE Safeguards Insp Repts 50-097/83-02 & 50-157/83-02 on 830602-03. No noncompliance noted Major areas inspected: physical protection measures for protecting SNM of low strategic significance.
SMITH, G. C. : GODY, A. T. Region 1, Office of Director. 83/06/21, 3pp. 19380: 263. 24X Fiche: 50-097, 83/06/22, 8307110369.

#### V. Operator Examinations

B3070B0427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee," Svc list encl. E18ENH-UT.D. G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:13B, 24X Fiche: 50-000, 83/07/11, B3070B0427.

# DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees relissuance of NRC Form 378, "Personal Qualifications Btatement - Licensee." Svc list encl. EISEM-NUT.D. 0. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138, 24X Fiche: 50-000,83/07/11,8307080427.

DOCKET 50-103 AEROJET GENERAL NUCLEONICE

P. Operating license stage documents & correspondence

B307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STB.Svc list encl. EISEN-HUT.D. Q. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fichs: 50-000, 83/07/06, 8307060329.

# DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

# J. Insurance & indemnity information

8307080005 Executed Amend 17 to Indomnity Agreement E-7, effective 830613. Accepted by univ on 830627.

BALTZMAN.J. Assistant Director for State & Licensee Relations. 83/06/27. 1p. 17351:246. 24X Fiche: 50-008.83/06/27.8307080005.

DOCKET 30-112 UNIV. OF OXLAHOMA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8307280104 Extends submittal date to 830701 for addit emergency plan info.per 830701 request. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/15. JENSEN.C. Oklahoma, Univ. of. 2pp. 19812:353. 24X Fiche:50-112,83/07/15,8307280104.

# 0. Inspection reports, IE Bulletins & correspondence

8307130183 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-112/83-01.

MADSEM, G.L. Region 4, Office of Birector, 83/07/11. EQLE.D.M. Gklahoma, Univ. of. ip. 19531:054. 24K Fiche:50-112,83/07/11.

--8307150192 Responds to NRC 830517 ltr ve violations noted in IE Insp. Rept 50-112/83-01. Corrective actions: check of flow rate for water gurification sys procedure reviewed for relevance & implementation.

JENSEN: C. . EGLE, D. M. Oklahoma, Univ. of. 83/05/27. MADSEN: G. L. Region 4. Office of 91/rector. 12pp. 19531:055. 24X Fiche: 50-112,83/07/11,8307150185.

#### V. Operator Examinations

8307260374 Advises that univ operating under approved rev to reactor operator requalification programmer NRC B30223 ltr.
TERRELL.C.M. Oblahoma: Univ. of. 83/06/17. MADSEN.G.L. Region 4, Office of Director. ip. 19733:166. 24% Fiche: 30-112,83/06/17, B307260374.

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B. "Personal Qualifications Blatement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Hichigan, Univ of. 14pp. 19563:13B. 24X Fiche:50-000.83/07/11.8307080427.

# DOCKET 50-113 UNIV. OF ARTIGNA RESEARCH REACTOR

## V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list enci. EISEN-UT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138, 24X Fiche:50-000,83/07/11,8307080427.

DOCKET 50-116 IOWA STATE UNIV. RESEARCH REACTOR
F. Security, medical, emergency & fire protection plans

8307270293 Grants 830704 request for extension of time until 830915 to respond to questions on emergency plan.
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13.
HENDRICKSON.R. I lows 8tate Univ. 2pp. 19812:043. 24X
Fiche:50-116.83/07/13.8307270293.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Suc list encl. EISENMUT.D.Q. Division of Licensing. 83/07/EI. Michigan, Univ. of. 14pp. 17543:138. 24X Fiche: 50-000,83/07/II,8307080427.

DOCKET 30-118 AEROJET GENERAL NUCLEONICS

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Qualifications Statement - Licensee." Svc list encl. EISEMBUT, D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000.83/07/11.8307080427. DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR
V. Operator Examinations

8307080427 Generic Ltr 83-12A to all hompower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

DOCKET 50-124 VIRGINIA POLYTECH INST. TRAINING REACTOR
V. Operator Examinations

9307080427 Opneric Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000,83/07/11,8307080427.

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR
P. Operating license stage documents & correspondence

B307260300 Advises of scheduled transfer of irradiated TRIGA fuel to ANL Hest TRIGA facility in Idaho Falls. ID during wk of 830822 Description of fuel loading for each shipping package submitted.
FELT2.D.E. Teras AbM Univ. College Station. TX. 83/07/20.
BERNARD.H. Standardization & Special Projects Branch. 3pp. 19731: 337. 24X Fiche: 50-128,83/07/20,8307260500.

8307260223 Describes procedure change for shipment of irradiated TRIGA fuel from facility to ANL/West.Responsibility for fuel & inventory transfer will occur when fuel is in cask & cask is ready for closure.

FELTZ.D.E. Texas A&M Univ., College Station, TX. 83/07/22.

BERNARD, H. Standardization & Special Projects Branch. 2pp 19727:359. 24X Fiche:50-128,83/07/22,8307260223.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee: "Svc list encl. EISENMITT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

DOCKET 50-131 OMAHA VET. ADMIN. HOSP. RESEARCH REACTOR
F. Security, medical, emergency & fire protection plans

8307270232 Responds to 830624 request for extension to respond to questions on emergency plan. Extension until 830810 granted. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13. TURCOTTO.R.L. Vet. Admin. Hosp. Omaba.NE. 1p. 19811:176. 24X Fiche: 50-131:83/07/13.8307270252.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENMUT.D. 9. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3
G. Adjudicatory correspondence

8307120573 Commits to submittal of decommissioning plan. Updated 1983 economic analysis reveals returning plant to operation would not be cost beneficial. Final safety goals & implementation policy will not be available for 2 yrs. CRANE.P.A. Pacific Gas & Electric Co. 83/07/07. LAZD,R.M., SCHINK, D.R., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 2pp. 19433:176. 24X Fiche: 50-133,83/07/07,8307120573.

# P. Operating license stage documents & correspondence

- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fichs: 50-900. B3/07/05. 8306270397.
- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000. 83/07/08. 8307080169.
- B307190115 Discusses util decision to decommission facility.Reactor core will be stored in spent fuel pool until DDE repository operational.OL to be amended for "possession only" license. Aug 1983 meeting requested to discuss decommissioning plans. SCHUYLER.J.O. Pacific Oas & Electric Co. B3/07/15. EISENHUT.D.G. Division of Licensing. 1p. 19635:006. 24X Fiche: 50-133,83/07/15,8307190115.
- 0. Inspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Dagrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JCRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307220492 Monthly operating ropt for May 1783 W/830608 ltr.
  DERKS.P. S., WEEKS.E.D. Pacific Gas & Electric Co. 83/06/08.
  Office of Resource Management, Director. Spp. 17685:220. 24X
  Fiche: 50-133,83/06/08,8307220492.
- S. Reportable occurrences, LERs & related correspondence
- 8307060007 PNO-V-83-026: on 830627, util notified Region V of intention to decommission facility. Decision based on restart costs. Licensee expected to apply for "possession only" license. Facility shut down since Jul 1976. KIRSCH. D. F. MURRILL, P. J. Region 5, Office of Director. 83/06/27. 1p. 1925i: 014. 24X Fiche: 50-133, 83/06/27, 8307060007.

# DGCKET 50-134 WORCESTER POLYTECH INST. RESEARCH REACTOR V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing, 83/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

# DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19543:138. 24X Fiche:50-000.83/07/11.8307080427.

# DOCKET 50-141 STANFORD UNIV. RESEARCH REACTOR

- J. Insurance & indemnity information
- 8307080679 Amend ii to Indemnity Agreement E-19, terminating agreement effective 830621.

  SALTZMAN, J. Assistant Director for State & Licensee Relations.

  B3/06/21. 1p. 19364:105. 24X Fiche: 50-141,83/06/21,8307080679.
- 8307040273 Requests change in annual indemnity fee for License R-60, per issuance of Amend ii un 830421. Amend terminates license. DINITZ.I. Assistant Director for State & Licensee Relations. B3/06/28. PUGLISE:A.S. Division of Accounting. ip. 19299:267. 24X Fiche: 50-141.83/06/28.8307060273.

# DOCKET 50~142 UCLA TRAINING REACTOR

- G. Adjudicatory correspondence
- 8307110133 Forwards proposed findings of fact & conclusions of law re special proceeding on Contention II re univ application for wrong class of license. CORMIER.W.H. California. Univ. of, Los Angeles. 83/06/23. LAURENBON, J. A. Atomic Safety and Licensing Board Panel. ip. 19373:097. 24X Fiche: 50-142,83/06/23.8307110133.
- --B30711013B Proposed findings of fact & conclusions of law re hearings on Contention II re univ application for wrong class of license. Certificate of Bvc encl. CORMIER.W.H. California, Univ. of, Los Angeles. 83/06/23. 27pp. 19375:098. 24X Fiche: 30-142, 83/06/23, 8307110133.
- 8307010121 Reply to Committee to Bridge the Gap 830623 proposed findings of fact & conclusions of law. Certain arguments, proposed findings & erroneous transcript refs oppused. Certificate of Svc encl. WOODHEAD.C.P. Hearing Branch 4, 83/06/30, 12pp. 19168:338, 24% Fiche: 50-142,83/06/30,8307010121.
- B307050153 Fowards NRC B30621 corrected proposed findings of fact & conclusions of law. H/o enci.
  WOUDHEAD.C.P. Hearing Branch 4. B3/06/30. FRYE.J.H., LUEBKE.E.A., BRIGHT.O.O. Atomic Safety and Licensing Board Panel. 1p.
  19199:164. 24X Fiche: 50-142,83/06/30,8307050153.
- B307040363 Forwards response & objections to NRC & util proposed findings of fact & conclusions of law.
  HIRBCH.D. Committee to Bridge the Gap. B3/06/30. LAURENSON, J. A. Atomic Safety and Licensing Board Panel. 1p. 19234:004. 24x Fiche: 50-142: B3/06/30. B307060363.
- ---8307060369 Responses & objections to proposed findings of fact & conclusions of law Declaration of Svc encl.
  HIRBCH, D. Committee to Bridge the Gap. 83/06/30. 32pp.
  19234:005. 24X Fichs: 50-142, 83/06/30, 8307060363.
- 8307060412 Forwards proposed findings of fact & conclusions of law re special proceeding on Contention II & motion to reopen record to take official notice that GA Technologies, inc licensed as Class 104c R&D facility.

  CORMIER. W. H. California, Univ. of, Los Angeles. 83/06/30.

  LAURENBON, J. A. Atomic Bafety and Licensing Board Panel. ip. 19236:349. 24X Ficho:50-142,83/06/30,8307060412.
- --8307060417 Mution to reopen special proceedings on Contention II.to take official notice of Commission licensing records re GA Technologies. Inc. license class.
  CORMIER.W. H. California, Univ. of. Los Angeles. 83/06/30. Atomic 8afety and Licensing Board Panel. 3pp. 19236:330. 24X Fiche: 50-142,83/06/30.8307060412.
- --B307060417 Reply to Committee to Bridge the Cap proposed findings of fact & conclusions of law re Contention II. Certificate of Svc encl.)
  CORMIER.W. H. California, Univ. of, Los Angeles. 83/06/30, 17pp. 19236: 353. 24X Fiche: 50-142,83/06/30,8307060412.
- B307060193 Notice of B30719 evidentiary hearing in Los Angeles.CA reproposed renewal of license.
  FRYE.J.H. Atomic Safety and Licensing Board Panel. B3/07/01. 2pp. 19249:312. 24X Fiche:50-142,83/07/01,8307060193.
- 8307060390 Memorandum & order confirming 830630 telcon w/City of Banta Monica,UCLA,Committee to Bridge the Gap & NRC re schedule for 830719 hearings & outstanding pending procedural matters. FRYE, J. H. Atomic Bafety and Licensing Board Panel. 83/07/01. 3pp. 19236:080. 24X Fiche:50-142.83/07/01,8307060390.

- 8307120355 Reply opposing util 830630 mution to reopen Contention II proceedings Motion untimely w/o proper foundation & unnecessary. Proferred matter irrelevant Declaration of Svc encl.

  HRRSCH, D. Committee to Bridge the Cap. 83/07/06. Atomic Safety and Licensing Board Panel. 8pp. 19432:067. 24% Fiche: 50~142,83/07/06,8307120555.
- 8307120054 Advises of schedule to appear as NRC witness on 830801-06. WOBBHEAD, C. P. Hearing Branch 4. 83/07/11. NEOGY, P. Brookhaven National Laboratory. 1p. 19423:151. 24X Fiche: 50-142, 83/07/11, 8307120054.
- B307120057 Advises of schedule to appear as NRC witness on B30801-06. HddDMEAD.C.P. Hearing Branch 4. 83/07/11. CCRT.E. Los Alamos Scientific Laboratory. ip. 19423:114. 24x Fiche: 50-142.83/07/11. 8307120057.
- 8307120041 Advises of schedule to appear as NRC witness on 830801-06. MODDMEAD.C.P. Hearing Branch 4. 83/07/11. HAMLEY.S. Battelle Memorial Institute, Pacific Northwest Laboratory. 1p. 19423:148. 24X Fiche: 50-142. 83/07/11. 8307120061.
- 8307140450 Response to UCLA 830630 motion to reopen record to take official notice of class of NRC license held by GA Tachnologies. NRC does not appose motion, but motion unnecessary since record not closed.

  MODDHEAD, C.P. Hearing Branch 4. 83/07/12. Atomic Safety and Licensing Board Panel. 290. 19321:185. 24X Fiche: 50-000,83/07/12.
- --8307140457 Amend 21 to License R-3B.
  SKOVHOLT.D. J. NRC No Detailed Affiliation Given. 72/01/21.
  3pp. 19521;187. 24X Fiche: 50-000/83/07/12/8307140450.
- 8307140452 Forwards Region V 830708 ltr to GELD re physical inventory of strategic BSNM at facility.

  WOODHEAD.C.P. Hearing Branch 4. 83/07/12. FRYE.J.H., BRIGHT.G.G., LUERKE.A. Atomic Safety and Licensing Board Panel. 2pp. 19321:244. 24% Fiche:30-142.83/07/12.8307140452.
- ~-8307140455 Forwards into rept per 830531 request for SNM inventory into Current inventory of 4921.13 g U~235 & 32 g Pu available from nuclear energy lab.

  MARTIN,J.B. Region 5, Office of Director. 83/07/08.

  CKRISTENBURY.E. Hearings Division. 2pp. 19521:246. 24X

  Fiche: 50~142,83/07/12,8307140452.
- 8307140468 Recommended decision re contention on use of reactor for commercial educational & research purposes. If license granted commercial use should not exceed 50% of annual reactor use.

  LAURENSON, JA. Atomic Safety and Licensing Board Panel. 83/07/12.
  37pp. 19520:283. 24% Fiche: 50-142.83/07/12.8307140468.
- B307290134 Forwards IE Insp Repts 50-142/83-02 & 70-0223/83-01 re recent SNM inventory. WDDDMEAD.C.P. Hearing Branch 4. 83/07/28. FRYE.J.H., BRIGHT.G.D., LUEBKE.A. Actomic Safety and Litensing Board Panel. 6pp. 19822:134. 24X Fiche: 50-142, 83/07/28,8307290134.

# 0. Inspection reports: IE Bulletins & correspondence

- 8307260521 Forwards IE insp Repts 50-142/83-02 & 70-0223/83-01 on 830628.No noncompliance noted.
  NORDERHAUG.L.R. Region 5. Office of Director. 83/07/08. O'NEIL.R. Calleornia. Univ. of. Los Angeles. 2pp. 19734:156. 24X
  -Fiche:50-142,83/07/08.8307260521.
- --8307260328 IE Insp Repts 50-142/83-02 & 70-0223/83-01 on 830628.

  No noncompliance moted Major areas inspected: SSNM inventory,
  NELSON, G. B., NORDERHAUGLL. R. Region 5, Office of Director.
  83/07/08. 3pg. 19734:158. 24X Fiche: 50-142,83/07/08. 8307260521.
- 8307260442 Forwards modified Page 2 to IE Insp Repts 50-142/83-02 & 70-0223/83-01 summartizing SNN physical inventory.
  NGRDERHAUG.L.R. Region 5. Office of Director. 83/07/20. O'NEIL.R. California, Univ. of. Los Angeles. 1p. 19731: 284. 24X
  Fiche: 50-142,83/07/20.8307260442.
- --9307260444 Modified Page 2 to 1E Insp Repts 50-142/83-02 & 70-0223/83-01 on 830628.

  Region 5, Office of Director. 83/07/20. ip. 19731:285. 24X Fichs:50-142,83/07/20,8307260442.
- 8307290134 Forwards IE Insp Repts 50-142/83-02 % 70-0223/83-01 re recent SNM inventory. WOODHEAD.C.P. Hearing Branch 4. 83/07/28. FRYE.J.H., BRIGHT, 0.0., LUEBKE.E.A. Atomic Safety and Licensing Board Panel. 6pp. 19822:134. 24X Fiche:50-142,83/07/28.8307290134.

#### T. Hearing transcripts on non-antitrust matters

- B306170403 Testimony of L Wayne, D DuPont, B Norton, M Kaku, M Pulido, R Kohn, D Hirsch, S Plotkin, S Aftergood, as Panel II rethemical reactions. Reactor not inherently protected against severe core damage from fire.

  MAYNE, L. DUPONT, D. , NORTON, B. Committee to Bridge the Gap.

  83/06/14. 42pp. 18879: 176. 24X Fiche: 50-142,83/06/14,8306170403.
- 8307250417 Transcript of 830719 hearing in Los Angeles.CA.Pp 991-1.169 \* Atomic Safety and Licensing Board Panel. 83/07/19. 179pp. 19704:051. 24X Fiche:50-142.83/07/19.8307250417.
- B307250414 Transcript of B30720 hearing in Los Angeles, CA. Pp. 1,170-1,339.

  \* Atomic Safety and Licensing Board Panel. 83/07/20. 190pp. 19702:177. 24X Fiche: 50-142,83/07/20,8307250414.
- 8307270015 Transcript of 830721 hearing in Los Angeles, CA. Pp. 1, 360-1, 377.

  4 Atomic Bafety and Licensing Board Panel. 83/07/21. 220pp. 19786: 185. 24X Fiche: 50-142, 83/07/21. 8307270015.
- B307270007 Transcript of B30722 hearing in Los Angeles.CA.Pp i.578-1.816.Supporting documentation encl. \* Atomic Safety and Litensing Board Panel 83/07/22. 250pp. 19746:161. 24X Fiche:50-142.83/07/22.8307270007.
- B307270010 Transcript of B30723 hearing in Los Angeles, CA Pp 1,817-2,000. Supporting documentation encl. # Atomic Safety and Licensing Board Panel. 83/07/23. 200pp 19765: 334. 24% Fiche: 50-142,83/07/23. B307270010
- 8307280215 Transcript of 830725 hearing in Los Angeles.CA Pp 2:001-2:115.

  \* Atomic Safety and Licensing Board Panel. 83/07/25. 129pp. 19794:010. 24% Fiche:50-142.83/07/25.8307280215.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 378, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000,83/07/11.8307080427.

DOCKET 50-148 UNIV. OF KANSAG RESEARCH REACTOR
F. Security, medical, emergency & fire protection plans

8307270235 Grants 830701 request for extension of time until 830930 to respond to questions on emergency plan.
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13.
MESLER.R. Kansas. Univ. of. 2pp. 19811:199. 24X
Fiche: 50-148.83/07/13,8307270235.

# Q. Inspection reports. IE Bulletins & correspondence

8307120553 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-148/83-01 Corrective actions:nuclear engineer will be appointed member of committee on radiation sources by 830501. KRAFT.D.C. Kansas, Univ. of. 83/04/14. MADSEN.G.L. Region 4, Office of Director. 1p. 19432:127. 24X Fiche: 50-148, 83/04/14, 8307120553.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement ~ Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 17563:138. 24X Fiche:50-000.83/07/11.8307080427.

DOCKET 50-150 OHIO STATE UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8307280452 Forwards IE Safeguards Insp. Repts 50-150/83-01.70-0801/83-01 & 70-0966/83-01 on 830412-13 & notice of violation Encls withheld (ref 10CFR2.790).

MILLER. J. R. Region 3, Office of Director. 83/05/09. REDMOND, R. F. Ohio State Univ. 2pp. 19797:258. 24X Fiche: 50-150, 83/05/09, 8307280452.

# Q. Inspection reports, IE Bulletins & correspondence

8307280452 Forwards IE Safeguards Insp Repts 50-150/83-01,70-0801/83-01 & 70-0966/83-01 on 830412-13 & notice of violation Encls withheld (ref 10CFR2.790).

MILLER, J. R. Region 3. Office of Director. 83/05/09, REDMOND, R. F. Ohio State Univ. 2pp. 19797:258. 24X Fiche: 50-150, 83/05/09, 8307280452

B307060085 Ack receipt of B30607 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-150/B3-01, 70-0801/B3-01 & 70-0966/B3-01. Response withheld (ref 10CFR2.790).
MILLER.J.R. Region 3, Office of Director. B3/06/30, CRAMBLETT, H. G. Ohio State Univ. 1p. 19237:240. 24X Fiche: 50-150, B3/06/30, B307060085.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENNUT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000,83/07/11,8307080427.

# DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

# V. Operator Examinations

B3070B0427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Blatement - Licensee." Svc list encl. EISENNUT.D G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche:50-000.B3/07/11.83070B0427.

### DOCKET 50-195 BIG ROCK POINT NUCLEAR PLANT

# F. Security, modical, emergency & fire protection plans

8307150167 Forwards memo supplementing 830322 findings on adequacy of remedial actions taken by util resulting from 820914 order. Order required applicant to demonstrate that six deficient areas in offsite emergency planning & preparedness remedied. KRIMM.R.W. Federal Emergency Management Agency. 83/06/17. JORDÁN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 19530:246. 24X Fiche:50-155.83/06/17.8307130167.

8307180402 Releases public version of revised emergency plan implementing procedure. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 17641:268. 24X Fiche:30-155,83/06/24, 8307180402.

--8307180404 Public version of Rev 24 to Emergency Plan Implementing Procedure EPIP 6J, "Communications Tests." W/830411 ltr & receipt form. \* Consumers Power Co. 83/04/06. 13pp. 17641:269. 24X Fiche:50-155,83/06/24,8307180402.

B307060102 Ack receipt of B30613 ltr describing exercise scenario & sequence of events for B30725-24 emergency exercise. Bcenario adequate. Complete package requested at least 20 days prior to evercise.

PAPERIELLO.C.J. Region 3, Office of Director. B3/06/29.

DEWITT.R.B. Consumers Power Co. ip. 19291: 361. 24X

Fiche: 50-155, 83/06/29, 8307060102.

B307220186 Forwards complete controller/prompter packages for emergency plan exercise scheduled for 830725 & 26. Exercise will involve both state & local agencies. Encl scenario not considered credible sequence of events W/O encl.
BORDINE: T.C. Consumers Power Co. 83/07/01. KEPPLER, J.C. Region 3, Office of Director. 2pp. 19683:347. 24% Fiche: 50-155,83/07/01, 8307220186.

830720010B Forwards FEMA 830617 comments on intervenor comments re licensee response to deficiencies identified in ABLB 820914 emergency preparedness order. FEMA original position that licensee comments adequate unchanged. GODDARD.R.J. Hearing Branch 3. B3/07/15. BLOCH.P.B., SHON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel. 18pp. 19646:030. 24X Fichs: 50-155,83/07/15,8307200108.

#### Adjudicatory correspondence

8307030150 Order extending time until 830805 for Commission to act to review ALAB-725.
CMILK.S. J. Office of the Secretary of the Commission. 83/07/01.
Commissioners. 1p. 19199:165. 24X Fiche: 50-155,83/07/01,8307050150.

8307070250 Advises that time for Commission to review Director's Decision DD-83-07 expired Commission declined review. Decision became final agency action on 830630.
CHILKS J. Office of the Secretary of the Commission. 83/07/06.
BIER.J. Affiliation Unknown. ip. 19269:312. 24X
Fiche: 50-155, 83/07/06, 8307070250.

8307070252 Advises that time for Commission to review Director's Decision DD-83-07 expired. Commission declined review. Becision became final agency action on 830630.

CHILM.S. J. Office of the Secretary of the Commission. 83/07/06.

CHRISTA-MARIA Christa-Maria. ip. 19293:361. 24X

Fiche: 30-155, B3/07/06, 8307070252.

8307080432 Order extending time until 830722 for Commission to act to review Director's Decision DD-83-09.
CHILK.S. J. Office of the Secretary of the Commission. 83/07/06.
Commissioners. ip. 19346:362 24X Fiche:50-155,83/07/06,8307080432.

B307120591 Forwards util 830623 memo re sighting of military aircraft over plant. Dates of incident & identity of aircraft unknown.

GALLO.J. Isham. Lincoln & Beale. GALLO.J. Consumers Power Co. 83/07/08. BLOCH, P.B., PARIS.O.H., SHON, F.J. Atomic Safety and Licensing Board Panel. 2pp. 19432:146. 24X Fiche: 50-155, 83/07/08, 8307120571.

8307200108 Forwards FEMA 830617 comments on intervenor comments re licensee response to deficiencies identified in ASLB 820914 emergency preparedness order.FEMA original position that licensee comments adequate unchanged. GDDDARD.R.J. Hearing Branch 3. 83/07/15. BLOCH.P.B., SHON.F.J., PARIS.D.H. Atomic Safety and Licensing Board Panel. 18pp. 19646:030. 24X Fiche: 50-155, 83/07/15, 8307200108.

8307260344 Application for subpoons directing WP Hickey & JV Lyczkowski to testify re plant safety from hazards due to flyovers from military aircraft & small planes. Proposed subpoense & Certificate of Svc encl.
COPELAND, V. G. Consumers Power Co. COPELAND, V. G. Isham, Lincoln & Beale. 83/07/19. Atomic Safety and Licensing Board Panel. 12pp. 19726:334. 24X Fiche: 50-155, 83/07/19, 8307260344.

8307230326 Forwards util analysis of structural adequacy of overhead crane to withstand ground motion resulting from seismic event to serve as testimony re O'Neill Contention IIC. GALLO.J. Isham. Lincoln & Beals. GALLO.J. Consumers Power Co. 83/07/21. BLOCH.P.B., PARIS.O.H., GHON.F.J. Atomic Safety and Licensing Board Panel. 70pp. 19703:043. 24X Fiche: 50-155, 83/07/21, 830/250326.

# P. Operating license stage documents & correspondence

#307010086 Notification of #30706 meeting w/util & engineering consultant in Bethesda. MD to discuss thermal analysis of spent fuel pool.

EMCH.R.L. Operating Reactors Branch 5. #83/06/29, CRUTCHFIELD. D. Operating Reactors Branch 5. 3pp. 19124:350. 24X
Fiche: 50-155. #83/06/29, #8307010086.

8307050007 Forwards FR notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing neutron source strength procedure. CRUTCHFIELD. D. Operating Reactors Branch 5. 83/06/29, VANDEWALLE, D. J. Consumers Power Co. 3pp. 19192; 103. 24X Fiche: 50-155, 83/06/29, 8307050007.

--B307050012 Notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing re neutron source strength procedure.

CRUTCHFIELD.D. Operating Reactors Branch 5. 83/06/29. 7pp. 19192: 106. 24X Fiche: 50-155,83/06/29,8307050007.

8307060175 Forwards FR notice of consideration of issuance of amend to License DRR-6 & proposed no significant hazards consideration determination & opportunity for hearing re-min critical power ratio, in response to 821220 application. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/27. VANDEWALLE, D. J. Consumers Power Co. 3pp. 19238: 286. 24X Fiche: 30-135.83/06/29, 8307060175.

- --8307060274 Notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing re min critical power ratio. CRUTCHFIELD.D. Operating Reactors Branch 5. 83/06/29. 8pp. 19238.289. 24x Fiche: 50-155.83/06/29.8307060175.
- 8307050248 Notification of B30630 meeting w/NUS Corp in Germantown.MD to discuss thermal analysis of facility spent fuel pool. EMCH.R.L. Dperating Reactors Branch 5. 83706/30. CRUTCHFIELD.D. Dperating Reactors Branch 5. 30p. 19198:351. 24X Fiche: 50-135,83706/30.8307050248.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307120485 Forwards PRA evaluations for SEP Topics III-2, "Wind % Tornado Loadings," & III-4.A. "Tornado Missiles." per B30601 commitments.Cost/benefit analysis on proposed mod to install portable pumps performed.
  TONER.K.A. Consumers Pawer Co. 83/07/05. CRUTCHFIELD.D. Operating Reactors Branch 5. 52pp. 19424:233. 24x Fiche: 50-155/83/07/05, B307120485.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveitlance intervals in STS. Svc list encl. BISENHUT. D. 0. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307110030 Summary of 830706 meeting w/util. NUS Corp & Isham.Lincoln & Beals in Bethes6a. HD re thermal/structural analysis of spent fuel pool.
  EMCH.R.L. Operating Reactors Branch 5. 83/07/07. Operating Reactors Branch 5. 24X Fiche: 50-155. 83/07/07, 8307110030.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24% Fiche: 50-000, 83/07/08, 8307080169.
- B307180302 Discusses supplemental evaluation in response to NRC concerns re Amend III to "Spent Fuel Rack Addition Consolidated Application."

  BORDINE, T. C. Consumers Power Co. B3/07/12. CRUTCHFIELD. D. Operating Reactors Branch 5. 3pp. 19556:056. 24X Fiche: 50-155,83/07/12,8307180302.
- --B307180307 "Seismit Safety Evaluation of Reactor Bldg Crane, Big Rock Point Plant: Charlevois, MI." BANDN. H., CAMPBELL.R.D., WESLEY, D. A. Structural Mechanics Associates. SMA 13703. 01R003 R03. 83/07/31. 46pp. 19556:060. 24X Fiche: 50-155, 83/07/12, 8307180302.
- --8307180311 "Assessment of Annual Frequency of Occurrence of Reactor Blig Crane Over Spent Fuel Storage Pool." BEACHUN.S.B. Consumbrs Power Co. 83/06/30. 16pp. 19356:105. 24X Fiche: 50-153,83/07/12,8307180302.
- ---8307180315 "Annual Frequency of Big Rock Point Spent Fuel Pool Damage Resulting From Seismic Failure of Overhead Crane." a Structural Machanics Associates. 83/07/31. 4pp 19556:121. 24X Fiche: 50-155.83/07/12.8307180302.
- 8307180020 Notification of 830719 meeting w/util in Bethesda.MB to discuss reactor vessel pressure/temp limits.
  EMCH.R.L. Operating Reactors Branch 5. 83/07/15. CRUTCHFIELD.D. Operating Reactors Branch 5. 4pp. 19560:134. 24x
  Fiche:50-155.83/07/15.8307180020.
- B307200073 Responds to Generic Ltr Bi-07 dtd B10701 re control of heavy loads. Original submittal did not distinguish "load" from "heavy load." Page 4 of Attachment 1 to B10701 submittal should be replaced w/encl. W/o encl.
  BORDINE: T. C. Consumers Power Co. B3/07/15. CRUTCHFIELD: D. Operating Reactors Branch 5. 1p. 19647: 115. 24X
  Fiche: 50-155.83/07/15.8307200073.
- 8307210032 Updates 820924 response to SEP Topic VI-4. "Containment Isolation Sys." Also corrects inaccuracy in NRC 821209 SER. All test, vent & drain valves, except feedwater sample root valves closed & placed under administrative controls. TONER, K. A. Consumers Power Co. 83/07/15. CRUTCHFIELD.D. Operating Reactors Branch 5. 4pp. 19668:343. 24% Fiche:50-155.83/07/15.

- 8307220174 Forwards page inadvertently omitted from 830715 submittal of rev to response on control of heavy loads (Generic Ltr 81-07).Page 4 of Attachment 1 to 810701 submittal should be replaced w/encl.
  BORDINE,T C Consumers Power Co. 83/07/18. CRUTCHFIELD,D. Operating Reactors Branch 5. 2pp. 19684:033. 24X Fiche:50-155,83/07/18.8307220174.
- B3D7270434 Forwards notice of consideration of issuance of amend to License DPR-6 & proposed NSHC determination & apportunity for hearing re B21220 application concerning administrative controls for second auxiliary operator & overtime limits. CRUTCHFIELD. D. Operating Reactors Branch 5. 83/07/19. VANDEWALLE, D. J. Consumers Power Co. 3pp. 19767-189. 24X Fiche: 50-155, 83/07/19, 8307270434.
- --8307270436 Notice of consideration of issuance of amond to License DPR-6 & proposed NSHC determination & opportunity for hearing re rev of administrative controls section of Tech Specs.
  WAMBACH.T.V. Operating Reactors Branch 5. 83/07/19. 6pp. 19767: 192. 24X Fiche: 50-155,83/07/19,8307270434.
- 8307250146 Summary of B30719 meeting w/util in Bethesda MD re pressure/ temp limits for reactor vessel. Util will submit proposed change & supporting matl. EMCH.R.L. Operating Reactors Branch 5. 83/07/21. Operating Reactors Branch 5. 3pp. 19706-101. 24X Fiche 50-155,83/07/21, 8307250146.
- B307230155 Advises that 780607 request for Tech Spec change re radwaste munitor incorporated into review of proposed radiological effluent Tech Specs to implement 10CFR30. App I CRUTCHFIELD. Deparating Reactors Granch 5. 83/07/21 VANDEKALLE.D.J. Consumers Power Co. 3pp. 19706-105 24X Fiche 50-155,83/07/21.8307250155
- B307250326 Forwards util analysis of structural adequacy of overhead crane to withstand ground motion resulting from seismic event to serve as testimony re O'Neill Contention IIC GALLO.J. Isham. Lincoln & Beale. GALLO.J. Consumers Power Co. B3/07/21. BLOCH.P.B., PARIS.O.H., SHON.F.J. Atomic Safety and Licensing Board Panel. 70pp 19703.043 24X Fiche 50-155.83/07/21, B307250326.
- B307240499 Notification of B3072B meeting w/util ½ Nuclear Utils Svc in Germantown,MD to discuss thermal analysis of spent fuel pool. EMCH.R.L. Operating Reactors Branch 5 93/07/22. CRUTCHFIELD,D. Operating Reactors Branch 5 3pp. 19731:334. 24X Fithe:50-155,83707/22.8307260499.
- 8307270373 Forwards notice of consideration of issuance of amend to License DPR-6 & proposed NSHC determination & opportunity for hearing re 820720 application concerning administrative controls.
  CRUTCHFIELD.D. Operating Reactors Branch 5 83/07/22 VANDEWALLE,D.J. Consumers Power Co. 3pp. 19767:299. 24X Fiche:50-155,83/07/22.8307270373.
- --8307270378 Notice of consideration of issuance of amend to License DPR-6 & proposed NSHC determination & opportunity for hearing re administrative controls.

  MAMBACH.T.V. Operating Reactors Branch 5 83/07/22. &pp 19767: 302. 24X Fiche: 50-155, 83/07/22, 8307270373.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307080446 Forwards IE Insp Rept 50-155/83-09 on 830509-12 No noncompliance noted. STREETER, J.F. Region 3, Office of Director. 83/06/22 DEWITT.R.B Consumers Power Co. 2pp 19347:248. 24% Fiche: 50-155.83/06/22, 8307080446.
- --B307080450 IE Insp Rept 50-155/B3-09 on 830509-12. No noncompliance noted Major areas inspected: nonlicensed operator training, licensed operator requalification training b resolution of previously identified insp items.

  SUTPHIN.R.N., HOLZMER.M.M., HAWKINS.F.C. Region 3, Office of Director. 83/06/22, 6pp. 19347:250. 24X Fiche: 50-155, 83/06/22, 8307080446.
- 8307180125 Forwards IE Insp Rept 50-155/83-11 on 830610.No noncompliance noted.

  SHAFER.W. D. Region 3. Office of Director 83/06/29. DEWITT.R.B. Consumers Power Co. 2pp. 19556:236. 247 Fiche 50-155,83/06/29, 8307180125.

- --8307180129 IE Insp Rept 50-155/83-11 on 830305-0610 No nuncompliance noted Major areas inspected operational safety maint, surveillance new fuel receipt preparation for refueling & independent insp.
  WRIGHT 6 C. PARKER, M. E. BOYD, D. C. Region 3. Diffice of Director. 83/06/29 4pp. 19556:238 24X fiche 50-155.83/06/29,8307180125
- B307110249 Remits Class III fee for exemption from inservice insprequirements of IOCFR50.55(g)
  BORDINE T C. Consumers Power Co. B3/07/01. MILLER, W. O. License Fee Management Branch 2pp. 19374.281 24x Fiche: 50-155, B3/07/01, B30710249.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11 Consolidated Edison Co. of New York, Inc. 154pp. (9563:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133. 24X Fiche 50-000.B3/07/12,B306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307220219 Monthly operating rept for May 1983.W/830606 ltr. AMSTUTZ, S., HOFFMAN, D. P. Consumers Power Co. 83/06/03. Director's Office, Office of Inspection and Enforcement. 5pp. 19673: 332. 24X Fiche: 50-155.83/06/03.8307220219.
- S. Reportable occurrences, LERs & related correspondence
- 8307050076 LER 83-002/03L-0 on B30523, during routine calibr of low level trip sensor LT 3181, for reactor depressurization systrip found to operate below fech Spec setpoint Cause not determined. Transmitter adjusted W/B30622 ltr.
  BORDINE.T. C. Consumers Power Co. 63/06/22. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19193:137. 24X Fiche: 30-155, 83/06/22, 8307050076.
- 8307050105 LER 83-003/03L-0: on 830523, during routine calibr of reactor low tevet trip sensor Lt 3180, sensor did not operate. Caused by defective differential pressure cell in Westinghouse Model 590P4099-7054 unit W/830622 ltr.
  BORDINE, T. C. Consumers Power Co. 83/06/22, KEPPLER, J. G. Region 3, Office of Director. 2pp. 19199: 341. 24X Fiche: 50-155, 83/06/22, 8307050105.
- 8307080443 LER 83-004/03L-0: on 830604, containment isolation valves CV 4092 & 93 in cleanup sys resin sluice line exhibited leakage in excess of Tech Spec Caused by minor seat scratches. Close tolerance polyfill seat mat! installed W/830629 ltr. BORDINE.T. C. Consumers Power Co 83/06/29, KEPPLER.J. O. Region 3, 07fice of Director. 2pp. 19346:357. 24X Fiche. 50-195, 83/06/29, 8307080443.
- T Hearing transcripts on non-antitrust matters
- 8307250407 Transcript of 830721 telephone conforence in Washington.DC. Pp 2.686-2.719.

  \* Atomic Safety and Licensing Board Panel. 83/07/21. 3pp. 19704:015 24X Fiche:50-155.83/07/21.8307250407
- V. Operator Examinations
- 8307080446 Forwards IE Insp Rept 50-155/83-09 on 830509-12.No noncompliance noted. STREETER. J.F. Region 3. Office of Director. 83/06/22 DEWITT.R.B. Consumers Power Co. 2pp. 19347 248. 24X Fiche: 50-155,83/06/22, 8307080446.
- --8307080450 IE Insp Rept 50-135/83-09 on 830509-12.No noncompliance noted Major areas inspected nonlicensed operator training, licensed operator requalification training & resolution of previously identified insp items.

  SUTPHIN.R.N., HOLZMER.M.M., HAWKINS, F.C. Region 3, Office of Director, 83/06/22, 6pp. 19347:230. 24X Fiche: 90-155,83/06/22,8307080446.

- DOCKET 50-156 UNIV. OF WISCONSIN RESEARCH REACTOR
  V. Operator Examinations
- 8307080427 Generic Ltr 83-12A to all hompower reactor licensees reissuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUI.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19543:138. 24X Fiche:50-000.83/07/11.8307080427.
- DOCKET 50-157 CORNELL UNIV. RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 8307110369 Forwards IE Safeguards Insp Repts 50-097/83-02 & 50-157/83-02 on 830602-03 No nuncompliance noted. MARTIN.T. T. Division of Engineering & Technical Programs. 83/06/22. STREETT, W.B. Cornell Univ. 2pp. 19380:261. 24X Fiche: 50-097,83/06/22,8307110369.
- --B307110372 IE Safeguards Insp Repts 50-097/83-02 & 50-157/83-02 on B30602-03 No noncompliance noted Major areas inspected: physical protection measures for protecting SNM of low strategic significance.
  SMITH.C.C. Region 1, Office of Director. 83/06/21. 3pp. 19380:263. 24X Fiche: 50-097, B3/06/22, 8307110369.
- 8. Inspection reports. IE Bulletins & correspondence
- 8307110369 Forwards IE Safeguards Insp Repts 50-097/83-02 & 50-157/83-02 on 830602-03. No noncompliance noted MARTIN, T. Division of Engineering & Technical Programs. 83/06/22. STREETT, M. B. Cornell Univ. 2pp. 19380:261. 24X Fiche: 50-097, 83/06/22, 8307110369.
- --B307110372 IE Bafeguards Insp Repts 50-097/83-02 & 50-157/83-02 on 830602-03. No moncompliance noted. Major areas inspected: physical protection measures for protecting SNM of low strategic significance.

  SMITH, 0. C., QODY, A. T. Region 1, Office of Director. 83/06/21, 3pp. 19380: 263. 24X Fiche: 50-097, 83/06/22, 8307110369.
- V. Operator Examinations
- 8307080427 Generic Ltr 83-12A to all nonpower reactor licensees reissuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EIBENHUT.D.9. Division of Licensing. 93/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/11.8307080427.
- DOCKET 50-140 GEORGIA INST. OF TECH. RESEARCH REACTOR
  V. Operator Examinations
- 8307080427 Coneric Ltr 83-12A to all nonpower reactor licensess reissuance of NRC Form 378, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D. 9. Division of Licensing. 83/07/11. Michigan. Univ. of. 14pp. 19563:138. 24X Fiche: 50-000.83/07/11.8307080427.
- DOCKET 50-163 GENERAL ATOMIC CO.
- F. Security, medical, emergency & fire protection plans
- B307140288 Requests extension for submittal of any new info re radiological contingency plans per 830610 request Extension to allow for receipt & response to addl questions from NMB9 re fuel cycle portions of plan requested.

  MOMRY, W. R. GA Fachnologies, Inc./General Atomic Co. 83/07/06 THOMAS, C. O. Standardization & Special Projects Branch. 1p. 19325:098. 24X Fiche: 50-089, 83/07/06, 8307140288.
- G. Adjudicatory correspondence
- 8307140450 Response to UCLA 830600 motion to reopen record to take official notice of class of NRC license held by GA Technologies. NRC does not oppose motion, but motion unnecessary since record not closed.
  WDDDMEAD.C.P. Hearing Branch 4. 83/07/12 Atomic Safety and Licensing Board Panel. 2pp. 19821:185. 24X Fiche: 50-000, 83/07/12, 8307140450.

## V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 370, "Personal Qualifications Statement - Licensee." Suc list encl. EISENHUT.D.G. Davision of Licensing. 83/07/11, Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/11,8307080427.

DOCKET 50-166 UNIV. OF HARYLAND RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B307210345 Responds to B30620 request for extension of time to respond to questions re emergency plan. Extension until B30930 granted.

THOMAS.C.O. Standardization & Special Projects Branch. B3/07/13. TOLL.J.S. Maryland, Univ. of. 19. 19672:324. 24% Fiche: 50-166.83/07/13.8307210345.

# Q. Inspection reports: IE Bullstins & correspondence

8307110397 Forwards IE Insp Rept 50-166/83-01 on 830525-27. No noncompliance noted. STAROSTECKI.R. Division of Project & Resident Programs. 83706/23. KERR.F. Haryland, Univ. of. 2pp. 19380:312. 24X Fiche:50-166.83706/23.8307110397.

--B307i1040i IE Insp Rept 50-166/B3-01 on B30325-27. No noncompliance noted Major areas inspected Facility operations separation of potentially contaminated water from water supply, logs & reviews & audits.

XINNEY, M. W., ELBASSER, T. C. Region 1, Office of Director.

83/06/21. 9pp. 19380:314. 24x Fiche: 50-166, 83/06/23, 8307110397.

# V. Operator Examinations

B307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee." Svc list encl. £ISENHUT, D. 0. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000,83/07/11.8307080427.

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

F. Security, medical, emergency & fire protection plans

8307050263 Discusses evaluation of emergency plan against requirements of App E to 10CFR50.Plan acceptable.Forwards Suppl 1 to SER (NURE0-0882).W/o encl.
THOMAS.C O. Standardization & Special Projects Branch. 83/06/14.
ADCOCK.B. Defense, Dept. of, Defense Nuclear Agency. 2pp. 19261:021. 24X Fiche:50-170.83/06/14.8307050263.

#### G. Adjudicatory correspondence

B30707020B Requests answer to 830616 ltr re issues of concern to Montgomery County & extends invitation to attend county council transportation & environ committee 830712 meeting. MCKENZIE:5. Nontgomery County, ND. 83/07/01. Haryland, State of. ip. 19293:362. 24X Fiche:50-170.83/07/01.830707020B.

8307070215 Forwards State of MD House of Delegates representative.HL Koss.830622 ltr endorsing Montgomery County Council position on relicensing Bethesda nuclear reactor.
8CULL.D.L. Montgomery County, MD. 83/07/01. PALLADIND.N.J. Commissioners. GRIFFITM.G.A. Defense. Dept. of. Defense Nuclear Agency. 2pp. 19293:359. 24X Fiche:50-170.83/07/01.8307070215.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee," Svc list encl. ELSENNUT.D.G. Division of Licensing. 89/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche:50-000,83/07/11.8307080427.

DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR
V. Operator Examinations

8307080427 Generic Lir B3-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan. Univ. of. 14pp. 19563:138. 24X Fiche:50-000,83/07/11.8307080427. DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
V. Operator Examinations

B3070B0427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. Q. Division of Licensing. B3/07/11. Michigan. Univ. of. 14pp. 19563:138. 24X Fiche:50-000.B3/07/11.B3070B0427.

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

#### H. General correspondence

8307280107 Advises that all correspondence to NRC ra License R-103 should be addressed to author.
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/15.
BRUGGER.R.M. Missouri, Univ. of, Columbia. 2pp. 19812:350. 24%
Fiche: 50-186:83/07/15,8307280107.

#### V. Operator Examinations

BJ07080427 Generic Ltr BJ-12A to all nonpower reactor licensess re issuance of NRC Form J98, "Personal Qualifications Statement - Licensee," Svc list encl. EISENBUT, D. O. Division of Licensing. BJ/07/ii. Michigan, Univ. of. 14pp. 19363:138. 24X Fiche: 50-000, 83/07/ii. 8307080427.

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

B307080427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee." Svc list encl EISENHUT.D.G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000, B3/07/11, B307080427.

DOCKET 50-172 UNIV. OF TEXAS RESEARCH REACTOR

E. NRC Safety Evaluation Report (SER), supple & correspondence

8307110313 SAFETY EVALUATION REPORT RELATED TO THE RENEMAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE UNIVERSITY OF TEXAS. Docket No. 50-192. (University of Texas.et al.) Puission of Licensing, NURSE-09093, 93/06/30, 100pp. Available at NRC. \$4,75, 19385;239, 24% Fiche: 50-192,83/06/30,8307110313.

# F. Security, medical, emergency & fire protection plans

B307050082 Forwards revised physical security plan. Rev withheld.
BAUER, T. E. Teras, Univ. of, Austin. TX. B3/06/30. THDMAS, C. O.
Standardization & Special Projects Branch. 1p. 19199: 320. 24X
Fiche: 50-192, B3/06/30, B307050082.

# V. Operator Examinations

B3070B0427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 378; "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.B3/07/11:B3070B0427.

DOCKET 90-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

V. Operator Examinations

B307080427 Generic Ltr B3-12A to all nonpower reactor licensees reissuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:138. 24x Fiche:50-000.83/07/11.8307080427.

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

G. Enspection reports, IE Builetins & correspondence

B3072B018B Forwards IE insp Rept 50-199/83-01 on 830606-08 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. B3/07/11, KANE, D. Manhattan College. 2pp. 19791: 231. 24X
Fiche: 50-199, 83/07/11, 83072B018B.

- --8307280194 Notice of violation from insp on 830606-08. \* Ragion i, Office of Director. 83/07/il. 1p 19791:233. 24X Fiche:50-199,83/07/il.8307280188
- --B307280200 IE Insp Rept 50-199/83-01 on 830606-08. Noncompliance noted: failure to implement operator requalification program KINNEY, W. W., ELBASSER, T. C. Region 1, Office of Director B3/06/27. 7pp. 19791: 234. 24% Fiche: 50-199,83/07/11.8307280188.

## V. Operator Examinations

- 8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Statement Licensee." Suc list encl. ETSENHUT, D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19363:13B. 24X Fiche: 50-000,83/07/11,8307080427.
- DOCKET 50~201 WEST VALLEY REPROCESSING PLANT
- F. Security, medical, emergency & fire protection plans
- 8307060075 Forwards revised Pages 7.8 & 31 from 830607 ltr clarifying location of proposed App R mode at 231-ft elevation of reactor coolant pump bays 8 & C. Mods will be performed at 231-ft elevation.

  ZIMMERMAN, 8 R. Carolina Power & Light Co. 83/06/27. VARGA, 6. A. ZIMMERMAN, B. R. Carolina mower & Cas Operating Reactors Branch 1. App. Fiche: 50-201, 83/06/29, 8307060075. 19251: 350
- P. Operating license stage documents & correspondence
- B307200495 Forwards "Analysis of Terminal Waste Form Selection for West Valley Demonstration Project."

  COPFMAN.F.E. Energy, Dept. of. B3/06/14. NRC No Detailed Affiliation Given. 1p. 19672:001. 24X Fiche: 50-201, 83/06/14, B307200495.
- 8307110632 Trip rept of 830613-14 visit to West Valley site to tour burial ground area & discuss site hydrology issues w/U908 & 830615 visit to NY Btate Geological Survey in Albany, NY regeology of West Valley area.

  MURT.R.D. Advanced Fuel & Spent Fuel Licensing Branch. 83/06/28, ROUSEL.C. Advanced Fuel & Spent Fuel Licensing Branch. 2pp. 19391:354. 24X Fiche: 50-201, 83/06/28, 8307110632.
- B307140813 Notification 83-48 of B30711 mgt meeting w/DDE in King of Prussia.PA to discuss status of West Valley Demonstration Project & DDE/NRC interfaces.Proposed agenda encl. ROTH.J. Region i. Dffice of Director. B3/06/30. Region 1. Office of Director. 201.83/06/30. 8307140813.
- 8307200190 Notification of Significant Meeting 83-48 Rev 1 on 830711 w/DDE at Region I ofc to discuss status of West Valley Demonstration Project & DDE/NRC interfaces. Proposed meeting agenda encl. ROTH, J. Reg agenus ent.". ROTH-J. Region 1, Office of Director. 83/07/08. Region 1, Office of Director. 3pp. 19670:304. 24X Fiche:30-201,83/07/08,8307200190.
- B307250026 Notification of contract execution, Mod 8 to "Geologic Study of Low Level Radwaste Burial Site at West Valley, NY." Contractor: State Univ of NY.

  BILVIS.R.M. Technical Assistance Contracts Branch. FIN B-6008.

  B3/07/14. BATSON, W. Office of Nuclear Regulatory Research, Director. HELD.E. NRC No Detailed Affiliation Given. 1p. 19723: 307. 24X Fiche: 50-201. B3/07/14. 8307250026.
- --B307250030 Requests ack of Mod 8.deobligating funds.to "Geologic Study of Low Level Radwaste Burial Site at West Valley.NY." Signed by Univ on 830425. GUSTAVE.R.P. Technical Assistance Contracts Branch. FIN 8-6008. 83/04/12. THOMPSON.J. New York.State Univ. of (Albany). ip. 19723:308. 24X Fiche: 50-201,83/07/14.8307250026.
- DOCKET 50-206 BAN DNOFRE NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8307150215 Ack receipt of 830615 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17.
  BISHOP.T.W. Region 5, Office of Director. 83/07/11. PAPAY, L.T. Sauthern California Edison Co. ip. 19530: 269. 24X Fichs: 50-206, 83/07/11, 8307150215.

- r-8307150222 Responds to NRC 830516 ltr re violations noted in IE Insp Repts 50-206/83-10.50-361/83-19 & 50-362/83-17. Corrective actions: fixed emergency lighting sys tested & instructions revised. Six addi lights will be installed. PAPAY: L.T. Southern California Edison Co. 83/06/15. MARTIN, J. B. Region 5, Office of Director. 4pp. 19530:270. 24X Fiche: 50-206, 83/07/11.8307150215.
- 8307260053 Forwards IE Safeguards Insp Rept 50-206/83-14 on 830606-10. No noncompliance noted Rept withheld (ref 10CFR2.790). NORDERHAUG.L.R. Region 5. Office of Director. 83/07/14. PAPAY.L.T. Southern California Edison Co. 2pp. 19727:263. 24X Fiche:50-206.83/07/14.8307260053.
- 8307270029 Forwards Rev 10 to physical security plan. Rev withheld (ref 100FR73, 21). Cref 100rf/3, 21).
  BASKIN K.P. Southern California Edison Co. 83/07/21. Division of Licensing. 1p. 19749: 359. 24% Fiche: 50-206, 83/07/21, 8307270029.
- B307260135 Discusses review of emergency operations facility (EOF) ventilation sys design. Potential problem w/air leakage from EOF equipment will be corrected.
  BASKIN.K.P. Southern California Edison Co. 83/07/22. EISENHUT.D.G. Division of Licensing. ip. 19727:289. 24X Fiche:50-206.83/07/22, 8307260135.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for CLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.

  EISERM-UT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03.
- 8306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT. D. 0. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 30-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc List encl. EISENVHUT. D. G. Division of Licensing. 8307706. Consolidated Edison Co. of New York, Inc. 16pp. 19669:234. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 830713024B Discusses evaluation of lift rigs for reactor coolant pump motors & equipment hatches per NUREG-0612 Evaluation complete Rigs will be constructed by Westinghouse.

  BASKIN. P. Southern California Edison Co. 83/07/06.

  CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 19474:361. 24X Fiche: 50-206,83/07/06,830713024B.
- 8307110232 Forwards response to request for addl info re NUREQ-0737, Items II.F. 1.4.II.F. 1.5 & II.F. 1.6.re containment pressure, water level & hydrogen monitors to complete post-implementation review.

  BASKIN.K.P. Southern California Edison Co. 83/07/07.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 13pp. 19380:018. 2 Fiche: 50-206.83/07/07.8307110232. 19380:018. 24X
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS evonts. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307230490 Submits info obtained to date & expected completion dates of work re adequacy of PORV block valves per TMI Item II.D.1.
  Verification of Anchor/Darling assumptions will be submitted by 831001. BASKIN, K. P. og 33001. BASKIN.K.P. Southern California Edison Co. B3/07/13. CRUTCHFIELD,D. Operating Reactors Branch 5. 4pp. 19702:044. 24X Fiche: 50-206-83/07/13.8307250450.
- 8307250379 Forwards application for Amend 112 to License DPR-13 consisting of Proposed Change 120 to Tech Specs Change to boron concentration will result in positive reactivity changes when containment integrity not intact. FUGARTY, D. J. Southern California Edison Co. 83/07/20. DENTC Office of Nuclear Reactor Regulation, Director. 1p. 19701:30 Fiche: 50-206.83/07/20,8307250379. DENTON: H. R. 19701:334

- --8307250383 Application for Amend 112 to License DPR-13, consisting of Proposed Change 120 to Tech Specs re boron concentration. Amend will result in positive reactivity changes when containment integrity not intact. W/Certificate of Svc. FDOARTY.D.J. Southern California Edison Co. 83/07/18. App. 19701: 335. 24X Fiche: 50-206.83/07/20.8307250379.
- 8. Inspection reports: IE Bulletins & correspondence
- 8307120008 Forwards response to IE Bulletin 82-04 re deficiencies in grimary containment electrical penetration assemblies mfg by Bunker Rama. Insp. conducted on 830215 verified each conductor continued into apoxy w/no evidence of splices. RAYNES. J. G. Southern California Edison Co. 83/03/03. MARTIN, J. B. Region 5, Office of Director. 5pp. 19423: 171. 24X Fiche: 50-204, 83/03/03, 8307120008.
- 8306270401 IE Info Notice B3-46, "Common Kode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 15499. 19563:293. 24X Fiche: 50-000, 83/07/11, B306270401
- 8307130215 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17.
  815HOP,T.W. Region 5, Office of Director. 83/07/11. PAPAY,L.T. Southern California Edison Co. ip. 19530:289. 24% Fiche:50-206.93/07/11,8307150215.
- --8307150222 Responds to NRC 830316 ltr re violations noted in IE Insp. Repts 50-206/83-10,50-361/83-17 & 50-362/83-17. Corrective actions: firsd emergency lighting sys tested & instructions revised Six addl lights will be installed. PAPAY.L.T. Southern California Edison Co. 83/06/15. MARTIN.J.B. Region 5, Deffice of Director. 4pp. 19330: 270. 24X F(che: 50-206, 83/07/11, 8307150215.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:133. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Ercess of NRC Limits." Svc list ancl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fichs: 50-000, 83/07/14, 8306270406.
- B307260053 Forwards IE Safeguards Insp Rept 50-206/83-14 on B30606-10.
  No noncompliance noted Rept withheld fref 10CFR2.7903.
  NORDERHAUG, L. R. Region 5. Office of Director. B3/07/14. PAPAY, L. T.
  Southern Catifornia Edison Co. 2pp. 19727:263. 24X
  Fiche: 50-206, B3/07/14, B307260093.
- A. Periodic operating reports & related correspondence
- 8307220504 Monthly operating rept for May 1983.W/830615 ltr.
  FRANCIS, J.M., RAY.H.B. Southern California Edison Co. 83/06/15.
  Hanagement Information Branch. 6pp. 19685: 266. 24X
  Fiche: 50-206.83/06/15,8307220506.
- S. Reportable occurrences, LERs & related correspondence
- B307220290 RD: on B30530, two spent Fuel pit upper lateral braces found bent & not in contact w/wall. Investigation continuing. RAY, H. B. Southern Callfornia Edison Co. B3706/30. HARTIN, J. B. Region 5. Office of Director. 2pp. 19675:355. 24X Fiche: 30-206, 83/06/30, 8307220290.
- 8307250433 LER 83-002/01T-0: on 830530, while inspecting spent fuel git for debris, two upper lateral braces of storage racks found bent & not in contact w/east wall. Caused by items suspended from bridge crane during pit evolutions. W/830713 ltr. RAY.H. B. Southern California Edison Co. 83/07/13. HARTIN, J. B. Region 5, Office of Director. 4pp. 19701: 186. 24X Fichs: 50-204, 83/07/13, 8307250433.
- 8307250335 Part 21 rept re potential defect in high pressure fuel injection line of DSR or DSRV standby diesel generator. Removal of random sample of lines to be internally borescope inspected recommended. BOYER.R.E. Transamerica Delaval. Inc. 83/07/20. Director's Office. Office of Inspection and Enforcement. 2pp. 19703:011. 24X Fiche: 50-000.83/07/20.8307250335.

- 8307260443 Requests calculations of seismic adequacy of as-loaded spent fuel storage racks, referenced in 830630 prompt rept re bent upper lateral braces in spent fuel pool Response requested within 30 days.

  CRUTCHFIELD. D. Operating Reactors Branch 5. 83/07/22. DIETCH, R. Southern California Edison Co. 2pp. 19734:117. 24X

  Fiche: 50-206, 83/07/22, 8307260443.
- DOCKET 50-20B COLUMBIA UNIV. RESEARCH REACTOR
  V. Operator Examinations
- 8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 398. "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/11.8307080427.
- DOCKET 50-213 HADDAM NECK PLANT

  F. Security, medical, emergency & fire protection plans
- 8307150351 Forwards IE Insp Rept 50-213/83-13 on 830411-0522. No nancompliance noted.
  STAROSTECKI,R. Division of Project & Resident Programs. 83/07/01. COUNSIL. M. G. Connecticut Yankee Atomic Power Co. 2pp. 19538: 287. 24X Fiche: 50-213, 83/07/01, 8307150351.
- --9307150352 IE Insp Rept 50-213/83-13 on 830411-0522. No noncompliance noted Major areas inspected:plant operations, review of periodic & special repts, shift logs & operating records, surveillance activities & physical security.
  REBELDWSKI.T.A. Region 1. Office of Director. ELSASSER, T.C. Division of Project & Resident Programs. 83/06/30. 12pp. 19538:289. 24X Fiche:50-213.83/07/01.8307150351.
- P. Operating license stage documents & correspondence
- B306060070 Generic Ltr B3-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines."

  Svc list encl.

  EISENHUT.D.O. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 17563:116. 24X Fiche: 50-000, 83/06/03.
- 8307010067 Forwards info rept re unlatched control rod drive shaft problems encountered during Core 12 refueling outage. GRAVES.R.H. Connecticut Yankee Atomic Power Co. B3/06/07. ALLAN.J.H. Region 1, Office of Director. 16pp. 19124:295. 24X Fiche:50-213,83/06/07,8307010067.
- B306270397 Generic Ltr B3-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.Svc list encl. EISENHUI, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.
- 8307190253 Forwards "Analysis of Capsule D from Connecticut Yankee Reactor Vessel Radiation Surveillance Program," per 100FR50 App H. confirming past predictions of low rate of embrittlement as function of radiation fluence.

  COUNSIL, H. G., SEARS, C. F. Connecticut Yankee Atomic Power Co. 83/07/706. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19628:168. 24X Fiche: 50-213, 83/07/06, 8307190253.
- --8307190257 "Analysis of Capsule D From Connecticut Yankee Reactor Vessel Radiation Surveillance Program." YANICHKA, S. E. , ANDERSON, S. L. , SHOGAN, R. P. Westinghouse Electric Corp. WCAP-10236. 83/01/31. 85pp. 19628:170. 24X Fiche: 50-213, 83/07/06, 8307190253.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATWS events. 8vc list encl. EISENNUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.

- B307190131 Submits revs to Corporate Organization for Nuclear Incidents Procedure Manual, per 10CFR50, App E. Section V. CDUNSIL, M. G. Connecticut Yankee Atomic Power Co. CDUNSIL, M. G. Northeast Nuclear Energy Co. (aubs. of Northeast Utilities). CDUNSIL, M. G. Northeast Utilities. B3/07/14. EISENHUT, D. O. Division of Licensing. 1p. 19636: 074. 24X Fiche 50-000,83/07/14. B307190131.
- 8307210145 Forwards safety evaluation of util 821101 analysis of post-accident sampling sys per NUREQ-0737. Item II. B. 3. Resolution of three remaining criteria requested within 90 days.
  CRUTCHFIELD. D. Operating Reactors Branch 5. 83/07/18. COUNSIL.W.Q. Connecticut Yankee Atomic Power Co. 9pp. 19666: 120. 24X Fiche: 50-213.83/07/18.8307210145.
- 8307260524 Summary of B30707 meeting w/util re NULAP/5 & NUFRAP computer programs used in small break LOCA analysis per TMI Action Item II.K. 3.30. Viewgraphs encl. ERICKBON, P. B. Operating Reactors Branch 5. 83/07/22. Operating Reactors Branch 5. 23pp. 19734:132. 24X Fiche: 50-213, 83/07/22, B307260524.
- 8307270299 Forwards safety evaluation supporting plant shielding design & corrective actions por TMI Item II.B. 2.2. Requirements met. Item closed.
  CRUTCN:FIELD.D. Operating Reactors Branch 5. 83/07/26. CQUNSIL, H. G. Connecticut Yankee Atomic Power Co. 5pp. 19769:026. 24X Fiche: 50-213,83/07/26,830/270299.
- B307270306 Advises that response to Generic Ltr B1-21, "Natural Circulation Cooldown," acceptable Requests confirmation within 60 days of receipt of ltr that training program addresses items identified in safety evaluation. GRUTCHFIELD.D. Operating Reactors Branch 5. B3/07/26. COUNSIL.W.G. Connecticut Yankee Atomic Power Co. 3pp. 19768:347. 24X Fiche: 50-213,83/07/26,8307270306.
- --B307270312 Safety evaluation supporting response to Generic Ltr B1-21, "Natural Circulation Cooldown" & requesting addition or training program.

  \* Office of Nuclear Reactor Regulation, Director. 83/07/26. Bpp. 1976B:350. 24X Fiche:50-213.B3/07/26.8307270306.
- G. Inspection reports: IE Bulletins & correspondence
- 8307140400 Comments on IE Performance Appraisal Insp Rept 30-213/82-23 conducted during Oct & Nov 1982. Concurs W/recommendation to strengthen mgt control over plant operations.

  GDUNSIL. M. G. Connecticut Yankee Atomic Power Co. 83/07/01.

  TAYLOR, J. M. Division of QA. Safeguards & Inspection Programs (Post 830103). 30pp. 19514:018. 24X Fiche: 50-213.83/07/01,8307140400.
- B30715035i Forwards IE Insp Rept 50-213/83-13 on B304i1-0522, No noncompliance noted.
  STAROSTECKIR. Division of Project & Resident Programs. B3/07/01.
  COUNSIL. W. 9. Connecticut Yankee Atomic Power Co. 2pp. 19538: 287.
  24X Fiche: 50-213, 83/07/01, 8307150351.
- --8307150352 IE Insp Rept 50-213/83-13 on 630411-0322. No noncompliance noted Major areas inspected; plant operations, review of periodic & special repts, shift logs & operating records, surveillance activities & physical security.

  REBELOWSKI.T.A. Region 1, Office of Director. ELBASSER.T.C. Division of Project & Resident Programs. 83/04/30. 12pp. 19538:289. 24X Fiche: 50-213,83/07/01,8307150351.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDÁN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche: 50-000,83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:133. 24X Fiche: 50-000,83/07/12,8306270404.
- 8307190206 Advises that violations cited in IE Insp Repts 50-245/82-24, 50-336/82-26 & 50-213/83-02 re GA program for transport packages will be changed to unresolved items until firm criteria established.

  MARTIN, T. T. Division of Engineering & Technical Programs. 83/07/13. COUNSIL. W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19632:115. 24x Fiche: 50-000.83/07/13.8307190206.

- B304270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-129 & I-131 in Ercess of NRC Limits." Svc list enci. TAYLOR, J.M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000:83/07/14.8306270406.
- 8307280312 Ack receipt of 830622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-213/82-06 & 50-213/82-16.
  MARTINIT.T. Region 4, Office of Director. 83/07/19. COUNSIL, W. O. Connecticut Yankee Atomic Power Co. 7pp. 19789:213. 24X Fiche: 50-213, 83/07/19, 8307280312.
- --8307280326 Advises that commitments made in 821006 & 0427 ltrs re violations noted in IE Insp Repts 30-213/82-06 & 50-213/82-16 implemented beyond dates specified. Corrected dates listed. COUNSIL.H.G. Connecticut Yankee Atomic Power Co. 83/06/22. MARTIN.T.T. Division of Engineering & Technical Programs. 1p. 19789: 214. 24X Fiche: 50-213, 83/07/19, 8307280312.
- R. Periodic operating reports & related correspondence
- 8307120262 "Semiannual Radioactive Effluent & Waste Disposal Rept. Jul-Dec 1982."

  ORAVES R.H. Connecticut Yankee Atomic Power Co. 83/02/14.

  Director's Diffice Office of Inspection and Enforcement. 53pp. 19422:253. 24X fiche: 50-213.83/02/14.8307120262.
- 8307220367 Monthly operating rept for May 1983. W/830614 ltr. ELMS.A., GRAVES.R.M. Connecticut Yankee Atomic Power Go. 83/06/14. Office of Resource Management. Director. 10pp. 19675: 261. 24X Fiche: 50-213, 83/06/14, 8307220367.
- S. Reportable occurrences, LERs & related correspondence
- B307050148 LER B3-013/03L-0: on B30601, emergency diesel generator EGZA failed to attain normal idle speed within specified time. Cause undetermined Unit restarted. B0UCHARD, G. H., ORAMES, R. H. Connecticut Yanker Atomic Power Co. B3/06/27. ALLAN, J. M. Region I, Office of Director. 2pp. 19199: 166. E4X Fiche: 50-213, B3/06/27, B307050148.
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT
  F. Security, medical, emergency & fire protection plans
- 8307010016 Forwards IE Insp Rept 50-219/83-14 on 830503-0608, No noncompliance noted.

  BTAROBTECKI/R. Division of Project & Resident Programs. 83/06/17. FIEDLER/P. B. General Public Utilities GPU Service Corp. 2pp. 19169: 088. 24% Fiche: 50-219,83/06/17.8307010016.
- --8307010025 IE Insp Rept 50-217/83-14 on 830503-0608. No noncompliance noted. Major areas inspected: followup of previous insp findings, review of plant operations, log & record review, plant tours, physical security & radiation protection. CGMOILL.C., THOMAS.J., CGMNER.E.L. Region 1, Office of Director. 83/04/16. iipp. 19169:090. 24% Fiche: 30-219, 83/06/17, 8307010016.
- 8307010052 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-219/83-08.
  STAROSTECKI'R. Division of Project & Resident Programs. 83/06/28. FIEDLER.P.B. General Public Utilities GPU Service Corp. 1p. 19168: 311. 24X Fiche: 50-219.83/06/28.8307010052.
- --8307010056 Responds to NRC 830505 ltr re violations noted in 1E Safaguards Insp Rept 50-219/83-08. Corrective actions withheld (ref 10CFR73, 21). FIEDLER: P. B. General Public Utilities - GPU Service Corp. 83/06/06. STAROSTECKI, R. Division of Project & Resident Programs. 2pp. 19168:312. 24X Fiche: 50-219,83/06/28,8307010052.
- 8307080424 Forwards "Program Plan For Control Room Human Factors Review at Oyster Creek Nuclear Generating Station," per emergency response capabilities.
  FIEDLER,P.B. General Public Utilities GPU Service Corp. 83/07/01.
  EISEMHUT.D.O. D(vision of Licensing. 2pp. 19347:288. 24X
  Fiche: 50-219.83/07/01.8307080424.
- --8307080426 "Program Pian For Control Room Human Factors Review at Oyster Creek Nuclear Generating Station."

  \* General Public Utilities - QPU Service Corp. 83/06/30. 96pp. 19347:290. 24X Fiche: 50-219,83/07/01,8307080424.

- 8307250231 Responds to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re emergency response capabilities. Operations support ctr approved by Region I. Addl time required for safety parameter display sys completion. FIEDLER, P.B. General Public Utilities - GPU Service Corp. 83/07/18. EISENHUT, D. G. Division of Licensing. 3pp. 19705:360. 24X Fiche: 50-219,83/07/18,8307250231.
- P. Operating license stage documents & correspondence
- 8307010143 Submits info identifying electrical equipment important to safety per 10CFR30.49(g). Also submits schedules for qualification or replacement of remaining electrical equipment.
  FIEDLER.P. B. General Public Utilities CPU Service Corp. 83/06/23.
  GRUTCHFIELD.D. Operating Reactors Branch 5. 13pp. 19169:259. 24X Fiche: 50-219.63/06/23.8307010143.
- 830706000B Forwards proprietary "Performance Evaluation of Qyster Creek Core Spray Sparger," comprising formal response to 821012 request for addl assessment of existing core spray sys. Rept withheld.
  FIEDLER: P. B. General Public Utilities GPU Service Corp. 83/06/30. EIESCHAUT, D. O. Division of Licensing. 2pp. 19237:170, 24x Fiche: 50-219, 83/06/30, 830706000B.
- 8307060139 Forwards addl info on mild environ.per NUREG-0737.Items II.F.i.4 re containment pressure monitor.III.5 re containment water level monitor & II.F.i.6 re containment hydrogen monitor.in response to 830601 telecopy ltr. FIEDLER.P.B. General Public Utilities GPU Bervice Corp. 83/06/30 CRUTCHFIELD.D. Operating Reactors Branch 5. Spp. 19250:195. 24X Fiche: 50-219.83/06/30.8307060139.
- 8307080010 Summarizes results of analyses for hydrostatic loading & floatation resistance for reactor turbine, diesel generator & new radueste hidgs.per SEP Topic III-3A, "Effects of High Hater Level on Structures."
  FIEDLER,P.B. General Public Utilities QPU Service Corp. 83/07/01.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 3pp. 19351:221. 24x Fiche: 50-219.83/07/01.8307080010.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Syc list encl. EISENHUT. D. 0. Division of Licensing. 83/07/05. Conselidated Edison Co. of New York. Inc. 16pp. 19390:317. 24x Fiche: 50-000.83/07/05.8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillence intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19869:234. 24X Fiche: 50-000, 83/07/06, 8307060329.
- B3070B0169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New Yort. Inc. 3Bpp. 19669:269. 24X Fiche: 50-000.63/07/08.8307080169.
- 8307200005 Application for amend to License DPR-16 consisting of Tech Spec Change Request 119 revising Section 3.1. "Screm Sys Reliability." Change effective on completion of mod scheduled for Cycle 10 refueling outage. FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/07/13. Office of Nuclear Reactor Regulation, Director. 6pp. 19647:116. 24X Fiche: 50-219, 83/07/13, 8307200006.
- --8307200007 Proposed Tech Spec Change Request 119 revising Section 3.1.
  "Scram Sys Reliability."

   General Public Utilities OPU Service Corp. 83/07/13. 5pp.
  19447:122. 24X Fiche:50-219,83/07/13-8307200006.
- 8307260202 Forwards application for amend to License DPR-16. consisting of Tech Spec Change Request 103 revising Section 3.5.8 to Include action statements applicable to loss of secondary containment integrity.

  FIEDLER.P.B. General Public Utilities GPU Service Corp. 83/07/18.

  Office of Nuclear Reactor Regulation. Director. 1p. 19727:250.
  24% Fiche: 50-219.83/07/18.8307260202.
- --B30726020B Tech Spec Change Request 103 revising Section 3.5.B to include action statements applicable to loss of secondary containment integrity. Certificate of Svc encl.
  FIEDLER.P.B. General Public Utilities GPU Service Corp.
  83/07/18. 6pp. 19727:251. 24X Fiche: 50-219,83/07/18,8307260202.

- --8307260211 Proposed Tech Spec for Section 3.5.1 re loss of secondary containment integrity.

  \* General Public Utilities GPU Service Corp. 83/07/18. 4pp. 19727:257. 24X Fiche: 50-219,83/07/18.8307260202.
- B307260432 Forwards fee for License Change Request 100, in response to NRC B30613 request.

  KNUBEL, J. General Public Utilities GPU Service Corp. B3/07/20.
  B1065R M. License Fee Management Branch. 2pp. 19734:175. 24X

  Fiche: 50-219.83/07/20.8307260432.
- Q. Inspection reports. IE Bulletins & correspondence
- 8307010016 Forwards IE Insp Rept 50-219/83~14 on 830503-0608. No noncompliance noted.

  8TAROSTECKI.R. Division of Project & Resident Programs. 83/06/17.
  FIEDLER.P.B. General Public Utilities GPU Service Corp. 2pp. 19167:088. 24X Fiche: 50-219,83/06/17,8307010016.
- ---8307010025 IE Insp Rept 50-219/83-14 on 830503-0608. No noncompliance noted Hajor greas inspected: followup of previous insp findings, review of plant operations, log & record review, plant tours, physical security & radiation protection. COMORILL, C., THOMAS, J., CONNER, E.L. Region i, Office of Director. B3/06/16. 11pg. 19169:090. 24X Fiche: 50-219,83/06/17.8307010016.
- 8307010143 Submits info identifying electrical equipment important to safety per 10CFR50. 49(g). Also submits schedules for qualification or replacement of remaining electrical equipment.
  FIEDLER.P.B. General Public Utilities GPU Service Corp. 83/06/23. CRUTCHFIELD.D. Operating Reactors Branch 5. 13pp. 19169:259. 243 Fiche: 50-219. 83/06/23. 8307010143.
- 8307010052 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-219/83-08
  STAROSTECKI.R. Division of Project & Resident Programs. 83/06/28.
  FIEDLER.P.B. General Public Utilities GPU Service Corp. 1p. 19168:311. 24X Fiche:50-219.83/06/28.8307010052.
- --8307010056 Responds to NRC 830505 ltr re violations noted in IE Safeguards Insp Rept 50-219/83-08. Corrective actions withheld (ref 10CFR73. 21).
  FIEDLER, P. B. General Public Utilities GPU Service Corp. 83/06/06. STAROSTECKI.R. Division of Project & Resident Programs. 2pp. 19168:312. 24X Fiche: 50-219.83/06/28.8307010032.
- B307060309 Forwards results of NRC review of relief requests from requirements of Section XI of ASME Boiler & Pressure Vessel Code SER & FR notice granting in part & denying in part relief requests.
  CRUTCHFIELD.D. Operating Reactors Branch 5. B3/06/28. FIEDLER, P. B. General Public Utilities GPU Service Corp. 3pp. 17234:244. 24X Fiche: 50-217,83/06/28,8307060309.
- --8307060318 SER, granting in part & denying in part requests for relief from inservice insp requirements of ASME Code Section XI.

  # Office of Nuclear Reactor Regulation, Director. 83/06/28. Spp. 19234:247. 24% Fiche: 50-217,83/06/28.8307060309.
- ---8307060322 Notice of granting in part & denying in part, relief from ABME Code Section XI inservice insp requirements. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/28. 2pp. 19234:255. 24x Fiche:50-219.83/06/28.8307060309.
- ---B2100401BO "Oyster Creek Nuclear Generating Station Inservice Insp Program," technical evaluation rept \* Science Applications, Inc. NRC-03-82-096. SAI-186-028-34. 82/09/30. NRC - No Detailed Affiliation Given. 32pp. 66336:148. 24X Fiche: 50-219, 83/06/28, 8307060309.
- B306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consulidated Edison Co. of New York. Inc. 154pp. 17563:273. 24X Fiche:50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 90-000.83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-129 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.H. Division of GA. Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24% Fichs: 50-000,83/07/14,8306270406.

- B307210169 Responds to NRC B3060B request for add1 info re IE Bulletin B0-11. "Masonry Wall Design." Assistance from consultants necessary to prepare response to several items. Responses will be submitted by B30729 & 1030.
  FIEDLER.P.B. General Public Utilities GPU Service Corp. B3/07/15. CRUTCHFIELD.D. Operating Reactors Branch 5. 1p. 17669:086. 24X Fiche: 50-219.83/07/15.8307210169.
- 8307280431 Discusses 830419 SALP rept & 830617 ltr re actions & comments on rept Overall performance found acceptable.Rept modified.per 830617 ltr identifying design error as opposed to procedural inadequacies during integrated leak rate test. MURLEY.T.E. Region 1. Office of Director. 83/07/20. FIEDLER.P.B. General Public Utilities GPU Service Corp. 3pp. 19797:121. 24X Fiche: 50-219.83/07/20.8307280431.
- --8307280435 SALP rept for Feb 1982 Jan 1983. \* Region I, Office of Director. 83/04/19. 36pp. 19797:124. 24x Fiche: 50-219, 83/07/20, 8307280431.
- --8307280438 Advises of 830512 meeting re SALP on 830417 W/o encl rept. STARGSTECKI.R. Division of Project & Resident Programs. 83/04/27. FIEDLER.P.B. General Public Utilities OPU Service Corp. 2pp. 19797:160. 24X Fiche: 50-219.83/07/20.8307280431.
- --8307280443 Responds to 830429 ltr re results of SALP rept & 830512 followup meeting. Rept statement that procedural inadequacies during integrated leak rate test resulted in valving error incorrect. Error caused by design deficiency. FIEDLER, P. B. General Public Utilities QPU Service Corp. 83/06/17. STAROBTECKI.R. Division of Project & Resident Programs. 3pp. 19797: 162. 24X Fichs: 50-219, 83/07/20, 8307280431.
- R. Periodic operating reports & related correspondence
- 8307220188 Monthly operating rept for May 1983, W/B30615 ltr. BARAN,R., FIEDLER,P.B. General Public Utilities ~ GPU Service Corp. B3/06/03. Office of Resource Management, Director. 7pp. 17693:338. 24X Fiche:50~219.83/06/03.8307220188.
- 8. Reportable occurrences, LERs & related correspondence
- B307210196 LER 83-004/03L-0: on B30331, during preventive maint, control rod drive feed pump NCOBA circuit breaker mechanically closed per procedure. Investigation revealed breaker should not have closed, Caused by binding trip shaft, W/830707 ltr. CUSTODID, D. B., FIEDLER, P. B. General Public Utilities GPU Service Corp. B3/07/07. Regian i. Office of Director. 4pp. 19665:172. 24X Fiche: 50-219, 83/07/07, 8307210196.
- 8307280333 PNO-I-83-077: on 830720, two employees discharged for cheating on GC certification exam taken by one employee. Other employee, certified GC inspector & personal friend of new employee, provided questions & answers on exam. CONNER, E., KEIMIG, R. Region 1. Office of Director. 83/07/21, ip. 19790:094. 24X Fiche: 50-219,83/07/21,8307280333.
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8307010040 Forwards IE Insp Rept 50-220/83-12 on 830516-20, No noncompliance noted.
  MARTIN,T.T. Division of Engineering & Technical Programs. 83/06/14. RHODE,O.K. Niagara Mohauk Power Corp. 2pp. 19169:038. 24X Fiche: 50-220,83/06/14,8307010040.
- --8307010048 IE Insp Rept 50-220/83-12 on 930516-20 No noncompliance noted Major areas inspected; emergency preparedness items from prior appraisal performed on 810817-28. COMEN.I., GORDON, C.Z., CROCKER, H. W. Region i, Office of Director. 83/06/13. 14pp. 19169: 040. 24X Fiche: 50-220, 83/06/16, 8307010040.
- 8307110463 Forwards IE Safeguards Insp Rept 50-220/83-11 on 830509-13. No noncompliance noted. MARTIN, T. Division of Engineering & Technical Programs, 83/06/24. SUNBER, J. J. Niagara Mohawk Power Corp. 2pp. 19380: 096. 24X Fiche: 50-220, 83/06/24, 8307110463.
- --8307110469 IE Safeguards Insp Rept 50-220/83-11 on 830509-13. No noncompliance noted Major areas inspected physical barriers, security sys power supply, lighting, assessment aids & access control. Proprietary details deleted (ref IOCFR73.21).

  BAILEY.R. J., GODY, A.T. Region 1, Office of Director. 83/06/21 5pp. 19380:098. 24X Fiche: 50-220,83/06/24,8307110463.

- B307140313 Forwards IE Insp Rept 50-220/83-10 on B30501-0604 No nancompliance noted.

  STARDSTECKI'R. Division of Project & Resident Programs. B3/04/27. RHODE & K. Niagara Mohawk Power Corp. 2pp. 19525:101. 24X Fiche: 50-220, 83/04/27, 8307140313.
- ---8307140315 IE Insp Rept 50-220/83-10 on 830501-0606 No noncompliance noted Major areas inspected:licensme action on previous insp findings physical security, surveillance tests, maint, shutdown margin determination, mark I torus mod. startup & LERs. HUDSON, S. D. MCBREARTY, R. A. , KISTER, H. B. Region 1, Office of Director. 83/06/23. 11pp. 19325:103. 24X Fiche: 50-220, 83/06/27, 8307140313.
- B30712038B Discusses control room design review summary rept.per requirements of Suppl 1 to NUREG-0737. Rept will provide results of efforts to identify human engineering discrepancies to resolve emergency response capabilities. MANOAN.C.V. Niagara Mohawk Power Corp. B3/07/07. VASSALLD, D B Operating Reactors Branch 2. 1p. 19426:313. 24X Fiche: 30-220, 83/07/07, 830712038B.
- B3072504B9 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19724:225. 24X Fiche 50~220,83/07/19. B3072504B9.
- --8307250495 Forwards public version of revised emergency plan implementing procedures, including Procedure EPP-2 re fire fighting EPP-3 re search & rescue & EPP-4 re personnel injury or liness.
  MANGAN.C.V. Niagara Mohawk Power Corp. 83/07/01. Document Management Branch. 1p. 19724:226. 24X Fiche:50-220,83/07/19,8307250489.
- --8307250499 Public version of revised emergency plan implementing procedures, including Procedure EPP-2 re fire flighting EPP-3 re search & rescue & EPP-4 re personal injury & illness. PERKINS, T. J., ROMAN, T. W., RAYMOND, R. L., Niagara Mahawi Power Corp. 83/06/01. 240pp. 19724:227. 24X Fithe: 50-220,83/07/19,8307250489.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307120198 Forwards Rev i to updated FSAR. Table listing FBAR mods encl. MANGAN, C. V. Niagera Mohawk Power Corp. B3/07/01. DENTON, H. Office of Nuclear Reactor Regulation. Director. Spp. 19430:018. 24X Fiche: 30-220, B3/07/01, B307120198.
- --8307120205 Rev i to updated FSAR.

  \* Niagara Mohawk Power Corp. 83/06/30. 103pp. 19430:023. 24X
  Fiche: 30-220,83/07/01:8307120198.
- P. Operating license stage documents & correspondence
- 8307140144 Forwards safety evaluation of BMR Owners Group response to NUREO-0737. Item II.K.3.18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO, D. B. Operating Reactors Branch 2. 83/06/03. RHODE, B.K. Niagara Mohawk Power Corp. 2pp. 19540:001. 24X Fiche: 50-220,83/06/03,8307140144.
- 8307140506 Forwards confirmatory order verifying 801015,810401,1007 & 821215 commitments to install permanent scram discharge sys mods by 840930, or prior to Cycle 8 operation. Proposed model Tech Specs encl for guidance.
  VASSALLO,D. 8. Operating Reactors Branch 2. 83/06/24. RHODE, G. K. Niagara Mohawk Power Corp. 2pp. 19529: 200. 24X Fiche: 50-220,83/06/24,8307140506.
- --8307140515 Confirmatory order verifying 801015,810401,1009 & 821215 commitments to install permanent scram discharge sys mods by 840730, or prior to Cycle 8 operation.
  EIBENHUT, D. O. Division of Licensing, 83/06/24. Niagera Mohawk Power Corp. 5pp. 19529:202, 24X Fiche:50-220,83/06/24, 8307140506.
- 830707003B Advises that no further mods to primary containment vent & purge sys warranted to preclude large diameter vent & purge valve operation for post-LOCA venting. Possibility of minor procedural changes under investigation.

  MANGAN.C.V. Niagara Mohawk Power Corp. 83/07/01. VASSALLO, D. B. Operating Reactors Branch 2. 1p. 19293: 251. 24X Fiche: 50-220, 83/07/01, 8307070038.

- 8307070099 Advises that review by Site Operations Review Committee re-post-accident sampling procedures addressing sample storage considerations will be conducted by 830708. Revs & draft procedures completed.

  MANOAN.C.V. Niegara Mohawk Power Corp. 83/07/01. VASSALLO, D. 8. Operating Reactors Branch 2. Ip. 19269: 359. 24X Fiche: 30-220. 83/07/01, 8307070099.
- B307120294 Informs that review of B11231 shielding design contluding that NUREO-0737. Item II. B.2 requirements met erroneous. Reexam in process.
  MANOAN.C.V. Niagara Kohauk Power Corp. B3/07/01. VASSALLO, D. B. Operating Reactors Branch 2. 1p. 19424: 070. 24X Fiche: 30-220, B3/07/01. 8307120294.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 30-000.83/07/05.8306270397.
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISCHUPUT.D. 9. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000.83/07/06.8307060329.
- 8307080167 Generic Ltr B3-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATWS events. Bvc list encl. EISENNUT.D. Q. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24x Fiche:50-000.83/07/08.8307080169.
- B307140309 Provides add1 info to suppl & clarify 770713, 1216 & 790108 proposed license amends re HPCI, augmented inservice (nsp program & continuous leak monitoring. MANOAN.C.V. Niagara Mohawk Power Corp. B3/07/08. VASSALLO.D.B. Operating Reactors Branch 2. 2pp. 19523:309. 24X Fiche: 50-220, 83/07/08, 8307140309.
- B307140348 Forwards "Nine Mile Point I Pipe Creck Task Force Rept," documenting results of intergranular stress corresion cracking phenomena investigation.per B30328 request. MAN9AN.C.V. Niagara Mohawk Power Corp. B3/07/08, VASSALLQ.D.8. Operating Reactors Branch 2. 1p. 19524:061. 24X Fiche: 30-220, B3/07/08, B307140348.
- --9307140350 "Nine Mile Point 1 Pipe Crack Task Force Rept." One oversize photograph encl. Aperture card available in PDR. DELWICHE.D.E., GORDON, G. M. Niagara Mohawk Power Corp. 83/07/08, 363pp. 19924:062. 24X Fiche: 50-220, 83/07/08, 830714034B.
- 8307190046 Notification of 830725 meeting w/util in Bethesda, MD to discuss structural & criticality aspects of proposed spent fuel gool expansion.
  HERMANN.R.A. Operating Reactors Branch 2. 83/07/08. VASSALLO, D. D. Operating Reactors Branch 2. 1p. 19636:256. 24X
  Fiche: 30-220, 83/07/08, 8307190046.
- B307190047 Notification of B30725 meeting w/util in Bethesda,MD to discuss creek in reactor bldg wall.

  HERMANN,R.A. Operating Reactors Branch 2. 83/07/08. VASSALLO,D.B. Operating Reactors Branch 2. 2pp. 19656: 254. 24X Fiche: 50-220, 83/07/08, 8307170047.
- 8307190409 Notification of 830719 meeting w/util in Bethesda, MD to discuss emergency core spray nozzle performance.

  HERMANN, R. A. Operating Reactors Branch 2. B3/07/OB VASSALLD, D. B. Operating Reactors Branch 2. 1p. 19644: 358. 24X

  Fiche: 30-220, 83/07/08, 8307190409.
- 8307290210 Forwards request for add1 info needed for NRC assessment of reactor bidg crack. Meeting on 830725 would be most expeditious method of providing info & discussing problem. VASSALLO, D.B. Operating Reactors Branch 2. 83/07/08. RHODE, Q. K. Niagara Mohaut Power Corp. 4pp. 19826:312. 24X Fiche: 50-220, 83/07/08, 8307270210.
- 8307290217 Forwards request for add1 info needed for NRC assessment of reactor bldg crack. Meeting on 830725 would be most expeditious method of providing info & discussing problem. VASSALLO.D.B. Operating Reactors Branch 2. 83/07/15. RHODE.G.K. Niagara Mohawk Power Corp. 4pp. 19826:317. 24X Fiche: 30-220.83/07/15.8307290217.

- 8307290204 Forwards safety evaluation resolving NUREO-0737, Items II.F. 1.4. "Containment Pressure Monitor," II.F. 1.5. "Containment Water Level Monitor" & II.F. 1.6. "Containment Hydrogen Monitor." VASSALLO.D. B. Operating Reactors Branch 2. 83/07/18. RHUDE.O.K. Niagara Mohawk Power Corp. 2pp. 19807:049. 24X Fiche: 50-220.83/07/18.8307290204.
- 8307290382 Forwards safety evaluation re motor starting voltages during diesel generator load sequence testing Generator maintains voltages to motors within specified limits during load sequencing to accelerate to rated speed & torque. VASSALLO.D.B. Operating Reactors Branch 2. 83/07/18. RHODE.G.K. Niagara Mohauk Power Corp. 2pp. 19888:349. 24X Fiche: 50-220:83/07/18.8307290382.
- --8307270387 Safety evaluation re motor starting voltages during dissal generator load sequence besting.

  \* NRC No Detailed Affiliation Given. 83/07/18, 7pp. 19858:351. 24X Fichs: 50-220, 83/07/18, 8307290382.
- B307240155 Responds to Generic Ltr 83-08 re potential failure mode of vacuum breakers during chagging & condensation oscillation phases of bloadown to torus during LOCA. No mods to valves required.

  LEMPGES, T. E. Niagara Mohawk Power Corp. 83/07/22. VASSALLO, D. B. Operating Reactors Branch 2. ip. 19727:115. 24X Fiche: 50-220.83/07/22, 83/07260155.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307010102 Suppls 810513 response to IE Bulletin 80-13 re core spray spargers & associated internal piging. Visual insp found no addl indications. No corrective actions required. MANOAN.C.V. Niagara Mohawk Power Corp. 83/06/10. ALLAN.J.M. Region 1. Office of Director. 1p. 19124:317. 24X Fiche:50-220.83/06/10.8307010102.
- 8307010033 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators. Check valves disassembled, inspected, reassembled & tested satisfactorily. Inservice inspectogram will be revised. LEMPGES.T.E. Niagara Mohawk Power Corp. 83/06/14. DEYOUNG.R.C. Region i. Office of Director. 2pp. 19172:259. 24X Fiche: 50-220, 83/06/14, 8307010033.
- 8307010134 Responds to IE Bulletin 83-05 re defective Hayward Tyler Pump Co pumps & parts. Pumps & parts not used at plant. LEMP086.T.E. Niagara Mohawk Pawer Corp. 83/06/15. DEYOUNG.R.C. Region i, Office of Director. 2pp. 17124:333. 24X Fiche: 50-220.83/06/15.8307010154.
- 8307010040 Forwards IE Insp Rept 50-220/83-12 on 830516-20, No noncompliance noted.
  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/16.
  RHODE O. K. Niagara Mohawk Power Corp. 2pp. 19169:038, 24X
  Fiche: 50-220, 83/06/16, 8307010040.
- --8307010048 IE Insp Rept 50-220/83-12 on 830516-20. No noncompliance noted Major areas inspected: emergency preparedness items from prior appraisal performed on 810817-28. COHEM. I., GORDON, C. Z., CROCKER, H. W. Region 1, Office of Director. 83/06/13. 14pp. 19169:040. 24X Fiche: 50-220, 83/06/16. 8307010040.
- 8307110259 Forwards IE Insp Rept 50-220/83-13 on 830516-19 & 23-25.

  No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/22.

  RHODE, G. K. Niagara Mohauk Power Corp. 2pp. 19379; 163. 24X

  Fiche: 50-220, 83/06/22, 8307110259.
- --8307110246 IE Insp Rept 50-220/83-13 on 830514-19 & 23-25. No noncompliance noted Hajor areas inspected: containment leakage testing program: including witnessing sys integrated leakage rate test & local penetration testing.

  REKITO, N. A., BETTENHAUSEN.L. Region 1, Office of Director.
  83/06/15, 10pp. 19379:145. 24X Fiche:50-220,83/06/22,8307110259.
- 8307110463 Forwards IE Safeguards Insp Rept 50-220/83-11 on 830507-13. No noncompliance noted.

  MARTIN.T. Division of Engineering & Technical Programs. 83/06/24.

  SUNSER. J. J. Niagara Mohawk Power Corp. 2pp. 19380:096. 24X

  Fichs: 50-220, 83/06/24, 8307110463.
- --8307110469 IE Safeguards Insp Rept 50-220/83-11 on 830509-13. No noncompliance noted, Major areas inspected; physical barriers, security sys power supply, lighting, assessment aids & access control. Proprietary details deleted (ref 10CFR73.21). BAILEY, R. J. 00DY, A. T. Region 1, Office of Director. 83/06/21. 5pp. 19380:098. 24X Fiche: 50-220, 83/06/24, 8307110463.

- 8307140313 Forwards IE Insp Rept 50-220/83-10 on 830501-0606. No noncompliance noted.
  8TARGSTECKI.R. Division of Project & Resident Programs. 83/06/27. RHODE.G.K. Nigara Kohawk Power Corp. 2pp. 19525:101. 24X Fiche: 50-220.83/06/27.8307140313.
- --B307140313 IE Insp Rept 50-220/83-10 on B30301-0606. No noncompliance noted Major areas inspected: licensee action on previous insp findings; physical security, surveillance tests, maint, shutdown margin determination, Mark I torus mod, startup & LERs.
  HUDBON, S. D., MCBREARTY, R. A., KISTER, H. B. Region I. Dffice of Director. 83/06/23, 1ipp. 19525:103. 24X Fiche: 50-220,83/06/27,8307140313.
- 8307140309 Provides addl info to suppl & clarify 770713, 1216 & 790108 proposed license amends re HPCI, augmented inservice insp program & continuous leak monitoring.

  MANGAN, C. V. Niagara Hohawk Power Corp. 83/07/08. VASBALLD, D. B. Operating Reactors Branch 2. 2pp. 19523; 309. 24X Fiche: 50-220, 83/07/08, 8307140309.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Syc list encl.

  JORDÁNJE, L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:273. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- B307180141 Confirmatory Action Ltr B3-07 identifying potential for compromise of containment spray sys seismic integrity. Actions taken or to be taken listed.
  BTAROBTECKI.R. Division of Project & Resident Programs. 83/07/13 RHODE.G. Niagara Mohawk Power Corp. 2pp. 19557:049. 24X Fiche: 50-220, 83/07/13. 8307180141.
- 8306270406 IE Info Notice 83-48, "Gascous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list ancl. TAYLOR,J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 17715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- 8307280334 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/83-02.

  8TAROSIECKIR. Division of Project & Resident Programs. 83/07/19.
  RHODE, G. K. Niagara Mohawk Power Corp. 2pp. 19789:005. 24X
  Fiche: 50-220, 83/07/19, 8307280334.
- --8307280389 Responds to NRC B30323 ltr re violations noted in IE Insp Rept 50-220/83-02. Corrective actions: util engineering will only direct work to const company through use of contract change & safety-related work will be done per GA program. LEMPGES.T.E. Niagara Mahauk Power Corp. 83/04/21. MARTIN.T.T. Division of Engineering & Technical Programs. 3pp. 19789:007. 24X Fiche: 50-220.83/07/19,8307280354.
- B307250436 Ack receipt of B30711 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/83-08.
  BTAROSTECKIR. Division of Project & Resident Programs. 83/07/20.
  RHODE.G.K. Niagara Mohauk Power Corp. 2pp. 19701:179. 24X
  Fiche: 50-220, 83/07/20, 8307250436.
- --8307250438 Responds to NRC 830523 ltr re violations noted in IE Insp Rept 50-220/83-08. Corrective actions: jumper/block log procedures reviewed w/individuals involved & all safetyrelated sus performed prior to startup evaluated. LEMPOES.T.E. Niagara Mohauk Power Corp. 83/07/11. STAROSTECKI.R. Division of Project & Resident Programs. lp. 19701:181, 24x Fiche: 50-220, 83/07/20, 8307250436.
- R. Periodic operating reports & related correspondence
- 8307190243 Forwards revised "Annual Environ Operating Rept, 1982." Rev corrects typographical arrors in interpretative section of rept & on Table 7 re tritium & strontium concentrations. PERKINS.T. J. Niagara Mohawk Power Corp. 83/06/23. MURLEY.T.E. Region i. Office of Director. 1p. 19629: 281. 24X Fiche: 50-220, 83/06/23, 8307190243.
- --8307190249 "Annual Environ Operating Rept.1982."

  \* Niagara Mohawk Power Corp. 83/06/23. 125pp. 19629:282. 24X
  Fiche: 50~220,83/06/23,8307190243.
- 8307150080 Monthly operating rept for June 1983. W/830708 ltr. ROMAN.T.W., LEMPGES.T.E. Niagara Mohawk Power Corp. 83/07/08. Director's Office. Office of Inspection and Enforcement. 5pp. 19536:163. 24X Fiche: 50-220.83/07/08.8307150080.

- S. Reportable occurrences. LERs & related correspondence
- 8307110263 LER 83-011/03L-0:on 830604.electromatic relief valve 121 failed to open.Caused by dirty pilot due to exide buildup during extended outage.Pilot cleaned & retested % normal shutdown initiated.M/830628 ltr.
  8UROMETER.M.J., LEMPGES.T.E. Niagara Mohawk Power Corp. 83/06/16 MURLEY.T.E. Region 1. 0ffice af Director. 3pp. 19374:263 24% Fiche:50~220.83/06/16.8307110263.
- 8307150014 LER 83-013/03L-0: on 830610, during routine surveillance, lock found missing from outside inlet valve 40-12 for cure spray sys. Valve & breaker in open position. Lock missing for no more than 15 days. Lock replaced W/830708 ltr.
  KESEL, D.T., LEMPGES, T.E. Niagara Mohawk Power Corp. 83/06/16.
  MURLEY, T.E. Region 1, Office of Director. 2pp. 19548: 206. 24X Fiche: 50-220, 83/06/16, 8307150014.
- 8307110365 LER B3-010/03L-0: on B30524; core topping pump 121 removed from svc to replace packing. Caused by air leaking due to ILTR pressure introduction in pump Packing replaced & pump returned to svc within 22 b. W/B30621 ltr. KESEL. D.T., LEMPGES, T. E. Niagara Mohauk Power Corp. B3/06/17. WRLEY, T. E. Region 1, Office of Director. 3pg. 19380: 231. 24X Fiche: 50-220, B3/06/17, B307110365.
- 8307150115 LER 83-012/03L-0: on 830609, 10 s time delay relay 11K62 stuck in energized position & failed to time out & initiate emergency cooling sys. Caused by dirty clutch plunger. Periodic cleaning of plunger initiated W/830623 ltr. BURGMEIER.M.J., LERMPGES.T.E. Niagara Mohawk Power Gorp. 83/06/17. MURLEY.T.E. Region i. Defice of Director. 3pp. 19536:218. 24X Fiche: 50-220, 63/06/17, 6307150115.
- B307220325 LER B3-014/03L-0: on B30615, 16, 17, 20 & 21, 115-kV offsite power line removed from svc for 10 h each day. Caused by need to allow const of 115 kV line for Unit 2, currently under const. Line returned to svc each day. W/B30712 ltr. BUROMEIER. LEMPGES, T.E. Niagara Mohawk Power Corp. 83/07/11. MURLEY, T.E. Region I. Office of Director. 2pp. 19679:124. 24X Fiche: 30-220, 83/07/11, 8307220325.

#### DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

#### V. Operator Examinations

B3070B0427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 39B. "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000;83/07/11;83070B0427.

DOCKET 50-224 UNIV. OF CALIFORNIA RESEARCH REACTOR
Q. Inspection reports, IE Bulletins & correspondence

- 8307060236 Forwards IE Insp Rept 50-224/83-01 on B30524-25. No noncompliance noted.
  BOOK, H. E. Region 5, Office of Director. 83/06/17. PIGTER, C. California, Univ. of, Berkeley. 2pp. 19249:001. 24X Fiche: 50-224, 83/06/17, 8307060236.
- ---B307060243 IE Insp Rept 50-224/83-01 on 830524-25. No noncompliance noted. Major areas inspected: organization, personnel monitoring, surveys, efficient repleases, instrument calibr & environ monitoring program.

  BHERMAN.C.L. Region 5, Office of Director. WENSLAWSKI, F., BODK.H.E. Division of Radiological Safety & Safeguards Program.

  B3/06/17. 9pp. 19249:003. 24X Fiche: 50-224, 83/06/17, 8307060236.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigam, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/11.8307080427.

DOCKET 50-225 RP1 CRITICAL EXPERIMENT

F. Security, medical, emergency & fire protection plans

830719043B Forwards Amend 4 to License CX-22 identifying currently approved physical security plan.
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/07 HARRIS.D.R. Rensselaer Polytechnic Inst. 3pp. 19540:203. 24X Fiche: 50-225, 83/07/07, 8307150438.

- --8307150439 Amend 4 to License CX-22 identifying currently approved physical security plan.
  THOMAS.C.O. Standardization & Special Projects Branch. 83/07/07.
  2pp. 19540:205. 24X Fiche: 50-225.83/07/07.8307150438.
- P. Operating license stage documents & correspondence
- B30715043B Forwards Amend 4 to License CX-22 identifying currently approved physical security plan.
  THOMAS, C. Standardization & Special Projects Branch. B3/07/07.
  HARRIS, D. R. Rensselaer Polytechnic Inst. 3pp. 19540:203. 24X
  Fiche: 50-225, B3/07/07.8307150438.
- --8307150439 Amend 4 to License CX-22 identifying currently approved physical security plan.
  THOMAS,C.O. Standardization & Special Projects Branch. 83/07/07.
  2pp. 19540:206. 24X Fiche: 50-225, 83/07/07, 8307150438.

#### V. Operator Examinations

8307080427 Deneric Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 398, "Personal Gualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/11,8307080427.

# DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR V. Operator Examinations

- 8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Gualifications Statement - Licensee." Svc list enci. EISENHUT, D. O. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19569:138. 24X Fiche:50-000.83/07/11.8307080427.
- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307090249 Forwards IE Safeguards Insp Repts 50-010/83-10.50-237/83-15 & 90-249/83-24 on 830823-27.

  HIND.J.A. Region 3. Office of Director. 83/06/23. REED.C. Commonwealth Edison Co. 2pp. 19198:354. 24X Fiche: 50-010,83/06/23,8307050249.
- --8307050262 IE Safequards Insp Repts 50-010/83-10 50-237/83-14 & 50-249/83-14 on 830523-27. Noncompliance noted: security violations not reported in required manner or format. Details withheld (ref 10CFR73, 21).

  PIRTLE, G. L. Region 3, Office of Director. 83/06/23, 2pp. 19198: 356. 24X Fiche: 50-010, 83/06/23, 8307050249.
- 8307040184 Forwards objectives & scope of participation proposed for 830913 small-scale emergency exercise.
  BLACKMON.T.G. Commonwealth Edison Co. 83/06/27. HIND, J. Division of Project & Resident Programs. 3pp. 19249: 290. 24X
  Fiche: 50-237, 83/06/27, 8307060186.
- 8307220425 Ack receipt of 830627 ltr transmitting scope of util participation & objectives for station 830713 emergency exercise.

  PAPERIGLED.C.J. Region 3, Office of Director. 83/07/19, REED.C. Commonwealth Edison Co. ip. 19687:269. 24X Fiche: 50-237,83/07/19,8307220425.
- 8307260018 Submits supplemental response to NUREG-0737, Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display sys verification to be performed w/verification program. SWARTZ, E. D. Commonwealth Edison Co. 83/07/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727:177. 24X Fiche: 30-000, 83/07/20, 8307260018.
- B307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLD.C. J. Region 3. Office of Director. 83/07/26. REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 50-000. 83/07/26.8307280347.

## G. Adjudicatory correspondence

8307120595 Advises that time for Commission to review Director's Daction DD-83-8 expired Commission declined review. Daction became final agency action on 830705. CHILKS J. Office of the Secretary of the Commission. 83/07/11. QUI99.C. Pollution & Environmental Problems, Inc. ip. 19433:076. 24X Fiche: 50-000, 83/07/11, 8307120595.

# K. Utility Final Safety Analysis Report (FSAR) & amends

- B307010175 Forwards amends to updated FSAR for facilities. STIEDE.W.L. Commonwealth Edison Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19123:001. 24X Fiche: 50-000.83/06/29.8307010195.
- --8307010196 Rev 1 to updated FSAR for Zion Station 1 & 2. \* Commonwealth Edison Co. 82/12/31, 65pp. 17123:003. 24X Fichs: 50-000: 83/06/27, 8307010195.
- ~-8307010198 Amend to updated FSAR for Guad Cities 1 & 2. \* Commonwealth Editor Co. 83/06/29. 508pp. 19123:069, 24X Fiche: 50~000,83/06/29,8307010195.
- --8307010201 Rev 1 to updated FSAR for Dresden Station 2 & 3. '& Commonwealth Edison Co. 83/06/30. 1pp. 17123:245. 24X Fiche: 50-000,83/06/29,8307010195.

#### P. Operating license stage documents & correspondence

- 8307260213 "Dresden Unit 2 Reactor Containment Bldg Integrated Leak Rate Test." M/830707 ltr. BCOTT, D. J. Commonwealth Edison Co. 83/04/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 74pp. 19728: 263, 24X Fiche: 50-237.83/04/17.8307260213.
- 8307070176 Forwards plant—unique analysis repts.Vols 1-7.demonstrating primary containment sys design adequacy & restoration of original design safety margins per NUREG-0661.

  RYBAN. Commonwealth Edison Co. 83/06/27. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. Zpp. 19548:242. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307070181 Rev Q to "Dresden Nuclear Power Station, Units 2 & 3,Plant-Unique Analysis Rept,Vol 1. General Criteria & Loads Hethodology."

  WIEE,R.E., KOBT,E.Q., MASBEY, J. V. NUTECH Engineers, Inc. COM-02-041-1 ROD. 83/05/31. 223pp. 19548: 244. 24X Fiche: 50-000,83/06/27,8307070176.
- --8307070184 Rev 0 to "Dresden Nuclear Power Station, Units 2 & 3, Plant-Unique Analysis Rept, Vol 2, Suppression Chamber Analysis." HOWARD G.L., ADAMS, R. H.; MCINNES: 1. D. NUTECH Engineers, Inc. COM-02-041-2 ROO. 83/05/31. 185pp. 19549: 117. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307070211 Rev 0 to "Drasden Nuclear Power Station, Units 2 & 3, Plant-Unique Analysis Rept, Vol 3, Vent Sys Analysis." SHAMSIAD, P. E., ADAMS, R. H., MCINNES, I. D., NUTECH Engineers, Inc. COM-02-041-3 ROD. 83/05/31. 218pp. 19549: 302, 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307070218 Rev 0 to "Bresden Nuclear Power Station, Units 2 & 3, Plant-Unique Analysis Rept, Vol 4, Internal Structures Analysis." TALBOTT, D.C., ADAMS, R.H., MCINNES, I.D. NUTECH Engineers, Inc. COM-O2-O41-4 ROO. 83/05/31. 33pp. 19550:160. 24% Fiche: 50-000, 83/06/27, 8307070176.
- --8307070223 "Dresden Nuclear Power Station, Units 2 & 3, Plant-Unique Analysis Rept, Vol 5, Safaty Relief Valve Discharge Piping Analysis." 4 Sargent & Lundy, Inc. 83/05/27, 138pp. 19550:194. 24X Fiche: 50-000, 83/05/27, 8307070176.
- --830707022B Rev 0 to "Dresden Nuclear Power Station, Unit 2, Plant-Unique Analysis Rept. Vol 6, Torus-Attached Piping & Suppression Chamber Penetration Analyses."
  HERLEKAR, A. B., HARLON, E. V., GAVULA, J. A. NUTECH Engineers, Inc. CDM-02-041-6 R00. 83/05/31. 172pp. 17550:332. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307070239 Rev O to "Dresden Nuclear Power Station, Unit 3, Plant-Unique Analysis Rept. Vol 7, Torus-Attached Piping & Suppression Chamber Penetration Analyses,"
  HERLEKARA.A. 3, HARLOW.E.V., QAVULA.J. A, NUTECH Engineers, Inc. COM-02-041-7 ROO. 83/05/31, 170pp. 19351:144, 24X
  Fiche: 50-000, 83/06/27, 8307070176.

- --8307180152 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept. Vol 3. Vent Sys Analysis." SHAMBZAD, M., ADAMS.R. H., MCINNES. I. D. NUTECH Engineers, Inc. CCM-02-039-3 RO. 83/05/31. 22ipp. 19533:016. 24X Fiche: 50-000, 83/06/27, 8307070176.
- ---B307180198 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept. Vol 4. Internal Structures Analysis."

  TALBOTT. D. C., ADAMS. R. H., MCINNES. I. D. NUTECH Engineers, Inc. CCM-02-039-4 ROO. B3/05/31. 34pp. 19953: 237. 24X

  Fiche: 50-000. B3/06/27, B307070176.
- ~-8307180168 "Quad Cities Station Units 1 & 2 Plant Unique Analysis Rept, Vol 5.Safety Relief Valve Discharge Piping Analysis."

  \* Sargent & Lundy, Inc. 83/06/27. 134pp. 19553:272. 24x Fiche: 50-000.83/06/27,8007070176.
- ---8307180179 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept. Vol & Unit 1 Torus Attached Piping & Suppression Chamber Penetration Analysis."
  PANDEY.P., WALLACH.G., GAVULA.J.A. NUTECH Engineers, Inc. COM--02--039-4 ROO. 83/05/31. 176pp. 19554:046. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307180186 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept. Vol 7, Unit 2 Torus Attached Piping & Suppression Chamber Penetration Analysis "PANDEY, P., WALLACH, C., GAVULA, J.A. NUTECH Engineers, Inc. COM-02-039-7 ROO. 83/05/31. 175pp. 19554: 222. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307180138 "Guad Cities Nuclear Power Station Units 1 & 2 Plant-Unique Analysis Rept, Vol 1, General Criteria & Methodology, " WISE.R.E., KOBT.E.O., MASSEY, J.V. NUTECH Engineers, Inc. CCM-02-039-1 ROO. 83/05/31, 234pp. 19551:317. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --B307180147 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept, Vol 2. Suppression Chamber Analysis." HOWARD.G.L., ADAMS.R.H., MCINNES.I.D. NUTECH Engineers, Inc. COM-02-039-2 ROO. B3/05/31. 185pp. 19952:191. 24X Fiche: 50-000, B3/06/27, B307070176.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Bvc list encl. EISENHUT. D. O. Division of Licensing. 63/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for apprating power reactors & holders of CPs for power reactors re surveillance intervals in STS Byc list encl. EISENHUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMB events. Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19649: 269. 24X Fichs: 50-000, 83/07/08, 8307080169.
- 8307130265 Forwards mod of 810113 order as revised by 830117 order. Order continues exemption & extends completion date for installation of plant mod required by App A of NUREG-0461 CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/11. FARRAR, D.L. Commonwealth Edison Co. 3pp. 19308: 248. 24X Fiche: 50-237, 83/07/11. 8307130265.
- --B307130267 Mod of B30113 order extending completion date to B30728 for installation of plant mod required by App A to NUREG-0661. PURPLE.R.A. Division of Licensing. 83/07/11. Commonwealth Edison Co. 5pp. 17508:251. 24X Fiche: 50-237, 83/07/11, 8307130265.
- 8307130303 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re Phase I of response to NUREO-0612, "Control of Heavy Loads at Nuclear Plants." Phase I acceptable. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/11. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19505:001. 24X Fiche: 50-237.83/07/11. 8307130303.
- ---8307130308 Bafety evaluation accepting util Phase I response to NUREQ-0612; "Control of Heavy Loads at Nuclear Plants," acceptable.
  4 Office of Nuclear Reactor Regulation, Director. 83/07/11. 2pp. 19505:003. 24X Fiche: 50-237.83/07/11.8307130303.

- -8306100146 "Control of Heavy Loads Comm Ed Dresden Nuclear Power Station.Units 2 % 3." revised technical evaluation rept. BOMBERGER.C. Franklin Institute/Franklin Ressarch Center. NRC-03-81-130 TER-C5506-350/35! Rl. 83/06/08 SINGH.A. NRC -No Detailed Affiliation Given. 33pp. 19505:003. 24X Fiche: 50-237.83/07/11.8307(30303.
- B3071901B7 Notifies that Westinghouse info re environ qualification of electrical equipment detailed in B30313 ltr determined nonproprietary.

  RYBAK, B Commonwealth Edison Co. B3/07/11. DENTON, M.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19630:142. 24X

  Fiche: 50-000, 83/07/11, 8307190:87
- 8307190062 Forwards "Dynamic Analysis of Wetwell-to-Drywell Vacuum Breakers" & "Improved Dynamic Vacuum Response," in response to Generic Ltr 83-08. Results demonstrate that as-built 18-inch A&M vacuum breaker valves meet ASME Code criteria. RYBAN. B. Commonwealth Edison Co. 83/07/12. DENTON. M.R. Office of Nuclear Reactor Regulation, Director. 7pp. 19633:173. 24X Fiche: 50-000,83/07/12.8307190062.
- "-8307190067 Rev 0 to "Dynamic Analysis of Wetwell-to-Drywell Vacuum Breakers for Guad Cities Station,Units I & 2." MODNKA, A. K., CHEW, G. P., MASSIE, H. M. NUTECH Engineers, Inc. CCM-08-023 ROO, 81/09/29, 100pp. 19633:180. 24X Fiche: 50-000,83/07/12,8307190062.
- --B307190074 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Quad Cities 1 & 2." BILANIN.A.J. Continuum Dynamics, Inc. 82-7 R01. 82/09/30. 29pp. 19633:292. 24X Fiche: 80-000.83/07/12,8307190062.
- 830719017B Forwards "Dresden Unit 2 Cycle 9 Startup Test Summary," per NRC request & Tech Specs.
  RYBAK.B. Commonwealth Edison Co. 83/07/12. DENTON.H.R. Office of Nuclear Reaction Regulation. Director. 1p 19630:174. 24X
  Fiche: 50-237.83/07/12.8307190178.
- --8307190180 "Dresden Unit 2 Cycle 9 Startup Test Summary." \* Commonwealth Edison Co. 83/07/12. lp. 19630:175. 24X Fiche: 50-237,83/07/12,8307190178.
- --8307190183 "Dresden Unit 2 Cycle 9 Startup Test L.Core Vorification & Audit." \* Commoπωealth Edison Co. 83/07/12. ip. 19630:176. 24X Fiche: 50-237,83/07/12,8307190178.
- --8307190189 "Dresden Unit 2 Cycle 9 Startup Test 2.Control Rod Operability & Subcriticality Check." \* Commonwealth Edison Co. 83/07/12. 2pp. 19630:177. 24X Fiche: 50-237,83/07/12,8307190178.
- --8307190192 "Dreaden Unit 2 Startup Test 3. Transversing In-Core Probe Sys Symmetry Uncertainty." \* Commonwealth Edison Co. 83/07/12. 5pp 19630: 179, 24x Fiche: 50-237, 83/07/12, 8307190178.
- ---8307190195 "Dresden Unit 2 Cycle 9. Initial Criticality Comparison." \* Commonwealth Edison Co. 83/07/12. 2pp 19630: 184. 24X Fiche: 30-237,83/07/12,8307190178.
- G307220495 Discusses status of proposed mods to automatic depressurfiation sys.per NVREG-0737. Item II. K. 3. IB. Gption 4 re timer installation described in GE BMR Owners Group response. selected for implementation Mods IIsted. RYBAN, B. Commonwealth Edison Co. B3/07/IB. DENTON, H. R. Gffice of Nuclear Reactor Regulation, Director. 2pp. 19685:181. 24X Fiche: 30-000.83/07/IB.8307220495.
- 8307260020 Forwards Sargent & Lundy thermal growth analysis repts for main steam line snubber failure, per 830527 & 0606 commitments.

  RYBAK, B. Commonwealth Edison Co. 83/07/19. KEPPLER, J. G. Region 3, Office of Director. ip. 19727:124. 24X Fiche: 50-237, 83/07/17, 8307260020.
- --8307260024 Rev 00 to "Dresden 2 Main Steam Sys Monitoring:Review of 62-Day Outage Data."
  MCFARLAND, D. M., BHATTI, M. H., DLSON, D. E. Sargent & Lundy, Inc. 83/07/13, 10pp. 19727; 125. 24X Fiche: 50-237, 83/07/19, 8307260020.
- --B307260028 Rev 00 to "Dresden 2 Main Steam Monitoring Procedure Test-Analysis Correlation."

  AZZAZY.S.E., MCFARLAND.D.M., GLBON.D.E. Sergent & Lundy, Inc.

  83/06/18. 39pp. 17727:135. 24X Fiche: 50-237.89/07/19,8307260020.

- 8307270398 Forwards notice of consideration of issuance of license amends & opportunity for hearing re 830613 application concerning time limits for inoperability of ECCS ring header snubbers.
  CRUICHFIELD.D. Operating Reactors Branch 5. 83/07/20. FARRAR.D. L. Commonwealth Edison Co. 2pp. 19767:308. 24% Fiche: 50-237,83/07/20. 8307270398.
- --B307270404 Notice of consideration of issuance of amends to Licenses DPR-19 & DPR-23 & proposed NSHC determination & opportunity for hearing re snubbers.

  WAMBACH, T. V. Operating Reactors Branch 5. 83/07/20. 7pp. 19767: 310. 24X Fiche: 50-237.83/07/20, 8307270398.
- 8307250304 Discusses qualitative review to determine effects of bellow repair on fatigue life of bellows. Repair being applied will last for remainder of plant life. More refined analysis will be performed.

  RYBAK/B Commonwealth Edison Co. 83/07/21, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19701:348, 24X Fiche: 50-237, 83/07/21, 8307250304.
- 8307250448 Provides commitments on leakage monitoring. Floor drain leakage will be measured once every 4 h when reactor is at operating pressure. NRC will be notified within 24 h if action points exceeded.

  REED. C. Commanwealth Edison Co. 83/07/21. Office of the Sacretary of the Commission. 2pp. 19701:176. 24X Fiche: \$0-000.83/07/21.8307250448.
- 8307250480 Grants exemption from requirements of 10GFR30.App J re Type A leak test following containment boundary repairs.Type A pressure test not required for weld repair performed on expansion bellows for vacuum breaker 2-1601-328. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/21. FARRAR, D. L. Commonwealth Edison Co. 3pp. 19701:207. 24X Fiche: 50-237.83/07/21, 8307250480.
- --B307250484 Exemption from 10CFRSQ.App J. Section IV. A requirements re Type A leak testing following containment boundary repairs. Test need not be performed until next scheduled test. PURPLE,R.A. Division of Licensing. 83/07/21. Commonwealth Edison Co. 4pp. 19701:210. 24X Fiche: 50-237. B3/07/21. 8307250480.
- G. Inspection reports. IE Bulletins & correspondence
- 8305240276 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18.

  KEPPLER, J. G. Region 3, Office of Director. 83/05/13, REED, C. Commonwealth Edison Ce. 1p. 18548:067. 24X Fiche: 50-000, 83/05/13, 8305240276.
- 8307050249 Forwards IE Safeguards Insp Repts 50-010/83-10.50-237/83-15 & 50-247/83-24 on 830523-27.

  HRND.J.A. Region 3, Office of Director. 83/06/23, REED.C. Commonwealth Edison Co. 2pp. 17198:334. 24X Fiche: 50-010.83/06/23, 8307050249.
- --8307050262 IT Safeguards Insp Repts 50-010/83-10 50-237/83-14 & 50-249/83-14 on 830523-27. Noncompliance noted security violations not reported in required manner or format Details withheld (ref 100F873, 21).
  PIRTLET G. L., KNICELEY, U.R., CREED, J.R., Region 3, Office of Director. 83/06/23, 2pp. 19198:356. 24X Fiche:50-010,83/06/23,8307050249.
- 830704018i Ack receipt of 830520 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-237/83-08 & 50-249/83-07.
  HIND. J.A. Division of Radiological & Materials Safety Programs. 83/06/30. REED.C. Commonwealth Edison Co. ip. 19249:284. 24X Fiche: 50-237,63/06/30,830706018i.
- B305270401 IE Info Notice B3-45, "Common Mode Valve Failures Degrade Surry Rectrolation Spray Subsystam." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563: 293. 24X Fiche. 50-000, B3/07/11, B305270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 14ipp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & 1-121 in Excess of NRC Limits." Syc list
  - guards & Inspection Programs (Post ed Edison Co. of New York, Inc. 200,83/07/14,8306270406.

- 8307280287 Forwards IE Insp Repts 50-010/83-11,50-237/83-19 & 50-249/83-17 on 830606-10 & 17. No noncompliance noted. PAPERIELLOC. J. Division of Emergency Preparedness & Operational Support. 83/07/14. REED. C. Commonwealth Edison Co. 2pp. 19790: 209. 24X Fiche: 50-010. 83/07/14. 8307280287.
- --8307280293 IE Insp Repts 50-010/83-11,50-237/83-19 & 50-249/83-17 on 830406-10 & 17. No noncompliance noted Major areas inspected: records & repts of effluents, effluent control instrumentation & procedure for controlling releases. PAULIR.A., CREGER, L. R. Region 3, Office of Director. 83/07/13, 7pp. 19790: 211. 24X Fiche: 50-010,83/07/14,8307280287.
- 8307200207 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-237/83-06, 50-249/83-05, 50-254/83-04 & 50-265/83-04. SPESSARD, R. L. Division of Engineering. 83/07/15, REED, C. Commonwealth Edison Co. 2pp. 19651: 026. 24X Fiche: 50-000, 83/07/15, 8307200207.
- --830720021& Responds to NRC 830405 ltr re violations noted in IE Insp. Repts 50-237/83-04.50-249/83-05.50-234/83-04 & 50-265/83-04. NUTECH quality engineering procedures & util project unique instructions revised. REED. C. Commonwealth Edison Co. 83/04/08. 8PESBARD, R. L. Division of Engineering. 131pp. 19651:027. 24X Fiche: 50-000, 83/07/15, 8307200207.
- B307220463 Ack receipt of B30714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/83-12, 30-247/83-13 t 50-265/83-11. LITTLE, H. S. Region 3, Office of Director. 83/07/19, REED, C. Commonwealth Edison Co. 1p. 17684:325. 24X Fiche: 50-000, 83/07/19, 3307220463.
- --8307220476 Responds to NRC 830616 ltr re violations noted in IE Insp. Repts 30-237/83-12.50-249/83-10.50-294/83-13 & 50-265/83-11. Corrective actions: existing support configuration for pipe anchor R133 modified.
  FARRAR, D. L. Commonwealth Edison Co. 83/07/14. LITTLE.W. 8. Region 3. Office of Director. 4pp. 19684:326. 24X Fiche: 50-000,83/07/19.8307220463.
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util.per 830715 discussion.
  NGRELIUS.C.E. Division of Project & Resident Programs. 83/07/22.
  REED.C. Communwealth Edison Co. 2pp. 19791:169. 24X
  Fiche: 30-000.83/07/22,8307280084.
- --8307280102 Confirms request for NRC & util senior mgt meeting on 830726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.
  REED.C. Commonwealth Edison Co. 83/07/11. DAVIS, B.A. Region 3, Office of Director. 1p. 19791:171. 24X Fiche: 50-000, 83/07/22, 8307280084.
- 8307280446 Forwards BALP Repts 90-010/83-13, 50-237/83-18 & 50-249/83-16 for Jan-Dec 1982. Endorses that assessments are indicative of util efforts to improve performance at facilities.

  KEPPLER, J. G. Region 3, Office of Director. 83/07/25, REED, C. Commonue elth Edison Co. 2pp. 19797: 206. 24X Fiche: 30-010, 83/07/25, 8307280446.
- --B307280450 BALP Repts 50-010/B3-13,50-237/83-18 % 50-249/83-14 for Jan-Dec 1982.

  \* Region 3, Office of Director. 83/07/25. 27pp. 19797:208. 24X Fiche: 50-010,83/07/25,8307280446.
- --B3072B0454 Discusses upcoming B30512 meeting in Olen Ellyn IL to discuss BALP rept for Jan-Dec 1982. HIND, J. A. Division of Radiological & Materials Safety Programs. B3/04/22. REED. C. Commonwealth Edison Co. 2pp. 19797: 236. 24X Fiche: 50-010, 83/07/25, 83072B0446.
- ---8307280437 Forwards comments on SALP repts based on 830512 meeting. Practice of issuing reduced rating to all five operating plant sites for same alleged corporate weakness tends to overemphasize algnificance of alleged deficiency. REED.C. Commonwealth Edison Co. 83/05/31. KEPPLER.J.G. Region 3, Office of Director. 6pp. 19797: 238. 24X Fiche: 50-010, 83/07/25,8307280446.
- R. Periodic operating reports & related correspondence
- 9307150194 Monthly operating repts for June 1983.W/830701 ltr. SCHROEDER, B. A., SCUTT, D. J. Commonwealth Edison Co. 83/07/01. Director's Office, Office of Inspection and Enforcement. 24pp 19531:068. 24X Fiche:50-237.B3/07/01,8307150194.

## Reportable occurrances. LERs & related correspondence

97040239 Updated LER 93-071/03L-1: on 830426, operator observed narrow range Gemac (2-640-29A) & wide range Yarway (2-243-106A) reactor water level indicators pegged high. Caused by loose packing nut on pressure switch 2-263-11A. W/8306/7 ltr. 20YLE.L.M., SCOTT, D.J. Commonwealth Edison Co. 83/06/14. 4EPPLER, J.G. Region 3, Diffice of Director. 3pp. 19239:263. 24X riche: 50-237,83/06/14,8307060239.

37080496 Updated LER 83-010/03X-1: on 830129, MPCI turbine exhaust switch 23688 tripped Caused by incorrect reconnection of gire dislodged during ground checks. Procedure developed to focument wire movement W/830623 ltr.

NANDAPPA.A., SCOTT.D.J. Commonwealth Edison Co. 83/06/23.

LEPPLER.J. 9. Region 3. Office of Director. 3pp. 19346: 334. 24X ficha: 50-237, 83/06/23, 8307080496.

>77110189 Updated LER 82-053/03X-1: on 821215, while performing LPCI /#Nes operability surveillance, 2A LPCI HX bupass valve ; osition identification lost. Breaker trip setting found to ; at one setting too low. Cause unknown. W/B30424 Itr. &TA: H., BCOTT, D. J. Commonwealth Edison Co. B3/06/24. KEPPLER, J. Q. tegion 3. Office of Director. Spp. 19375: 010. 24X fiche: 50-237, B3/06/24. B307110189.

b7110359 LER 83-045/03L-0: on 830508, during normal operation, circuit ireaker for core spray injection valve M02-1402-258 tripped.

Laused by incorrect setting on circuit breaker, due to ersonnel error. Breaker set correctly, W/B30629 ltr.

COVLE.L.M., SCOTT.D.J. Commonwealth Edison Co. 83/06/29.

IEPPLER, J. 9. Region 3, Office of Director. 4pp. 17380: 247. 24X richs: 50-237, 83/06/29, 8307110359.

17110115 LER 83-044/03L-0: on 830403, review of Area X temp showed necesse of approx 25 F due to crack in test tap on MSIV 2C.

-aused by fatigue due to improper support of 3/4-inch test onnection. Steam line cut & capped W/830430 ltr.

IAXMELL.D.: SCOTT.D.J. Commonwealth Edison Co. 83/06/30

EPPLER.J.G. Region 3, Office of Director. 3pp. 19375:138. 24X

'iche: 50-237, 83/06/30, 8307110115.

720016B Updated LER 83-020/03X-1: on 830320, core spray injection alve MO 1402-25B remained open when close signal given.

Aused by breaker incorrectly set due to procedure madequacy, Breaker reset W/B30705 ltr.

OYLE, L., SCOTT, D. U. Commonwealth Edison Co. 83/07/03, EPPLER, J. 9. Region 3, Office of Director. 3pp. 19647:277. 24X iche: 50-237, 83/07/05, 830720016B.

7200174 LER B3-046/03L-0: on B3D615, after using LPC1 sys to lower uppression pool level, MO 2-1301-13A failed to reopen upon PCI sys shutdown. Caused by valve motor operator mounting olts snappling off. Bolts replaced & retorqued, W/B30711 ltr. HRIBTEL, B., BGDTT, D. J. Commonwealth Edison Co. 83/07/11. EPPLER, J. G. Region 3, Office of Director. 3pp. 19647:303. 24X iche: 50-237, B3/07/11, B307200174.

7200302 LER 83-049/03L-0: on 830616, while attempting to equalize Grus/drywell differential pressure, valves 2-1601-60 & 61 Ould not open. Caused by inadvertent closure of air supply solation valve 2-4713-512. Valve opened W/830711 ltr. ANO WEE, D. PSCOTT, D. J. Commonwealth Edison Co. 83/07/11. EPPLER, J. 9. Region 3, Office of Director. 3pp. 19648: 068. 24X 1che: 50-237, 83/07/11, 8307200302.

7200191 LER 83-048/03L-0: on 830616, during reactor vessel low water evel ECCS initiation (D18-500-3), level indicating switch ~263-728 tripped at 11.3 inches delta P. Gaussed by setpoint rift. Setpoint adjusted. W/830712 ltr.
DYLEL., 860TT, D. J. Commonwealth Edison Co. 83/07/12.
EPPLER, J. G. Region 3, Office of Director. 3pp. 19647:312. 24% iche: 50-237, 83/07/12, 8307200191.

7220231 LER 83-050/03L-0; on 830617, snubber 42 on steam line A found thave loose pipe clamp which had dropped 2 inches from granal position. Probably caused by inadequate tightening of lamp boits during original installation. W/830714 ltr. CHROEDER, B. A., SCOTT, D. J. Cleveland Electric Illuminating Co. 3/07/14, KEPPLER, J. 0. Region 3, Office of Director. 3pp. 7684:247. 24% Fiche: 50-237, 83/07/14, 8307220231.

8307250452 Discusses hole discovered on 830717 on expansion bellows for torus vacuum breaker 2-1601-320.Caused by inadvertent arc strike while welding on adjacent piping. Hole to be repaired by welding over area. Exemption requested.

RYBAN.B. Commonwealth Edison Co. 83/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19701:172. 24X Fiche: 90-237. 83/07/20, 8307250452.

8307260541 PNO-1II-83-064: on 830719, 1/8-inch diameter hole found in metal bellows in primary containment drywell-to-torus vacuum breater. Caused by welding strike during Mark I torus mods. Unit placed in cold shutdown.

MADISON.A., SHAPER, W. Region 3. Office of Director. 83/07/20. 1p. 19732: 027. 24X Fiche: 50-237,83/07/20,8307260541.

DOCKET 50-243 DREGON STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

B307260434 Application to amend License R-106 revising surveillance intervals to be consistent w/ANS/ANSI 15.1-1782 std. "Tech Bpecs for Research Reactors."
MONG, C. R. PARSONS, T. D. Oregon State Univ. 83/07/19. CARYER, R. Btandardization & Special Projects Branch. 5pp. 19734:039. 24x Fiche: 30-243, 83/07/19, 8307260454.

--8307260458 Marked-up revised Tech Spec Section 4 re surveillance requirements. \* Oregon State Univ. 83/07/19. 5pp. 19734:044. 24X Fiche:50-243,83/07/19.8307260454.

B3072B014B Forward's Amend 8 to License R-106, reducing authorized amount of U-235.
THOMAS, C. D. Standardization & Special Projects Branch. 83/07/20.
WANO, C. H. Oregon State Univ. 3pp. 19826: 268. 24X
Fiche: 50-243, 83/07/20, 8307280168.

--8307280179 Amend 8 to License R-106, reducing authorized amount of U-238. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/20. 2pp. 19826:271. 24X Fiche:50-243.83/07/20.8307280168.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nunpower reactor licensees re issuance of NRC Form 37B, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D.Q. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000, 83/07/11, 8307080427.

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT. UNIT 1

F. Security, medical, emergency & fire protection plans

8307110536 Forwards IE Insp Rept 50-244/83-14 on 830607-09. No noncompliance noted.

MARTINIT.T. Division of Engineering & Technical Programs. 83/06/22.

MALER, J.E. Rochester Gas & Electric Corp. 2pp. 19380: 134. 24X

Fiche: 50-244.83/06/22,8307110536.

--8307110339 IE Insp Rept 50-244/83-14 on 830607-09. No noncompliance noted Major areas inspected: public prompt notification sys.

COHEN.T., CRUCKER, H. W. Region 1, Office of Director. 83/06/21.

3pp. 19380: 136. 24X Fiche: 50-244: 83/06/22, 8307110536.

8307120025 Releases public version of revised emergency plan implementing procedures.
FELTON.J.M. Division of Rules and Records, 83/06/24. Documen Management Branch. 1p. 17509:001. 24X Fiche: 50-244, 83/06/24, 8307120025.

--8307120031 Forwards public version of revised emergency plan implementing procedures, including Procedures SC-233 research & rescue operation, SC-703 re plant status rept & SC-704 resafeguard status form.

MAIER.J.E. Rochester Oas & Electric Corp. B3/05/31. ALLAN, J. M. Ragion I, Office of Director. Ip. 19507:002. 24X Fiche: 50-244, 83/04/24, 8307120025.

--8307i20037 Public version of revised emergency plan implementing procedures, including Procedures 8C-233 re search & rescue operation.8C-703 re plant status rept & 8C-704 re safeguard status form.

\* Rochester Oas & Electric Corp. 83/05/18, 110pp. 19509:003. 24X Fiche:50-244,83/06/24,8307120025.

- 8307140371 Forwards IE Insp Rept 50-244/83-13 on 830508-0616 & notice of violation.
  STARGSTECKI.R. Division of Project & Resident Programs. 83/06/27.
  MAIER.J E. Rochester Gas & Electric Corp. 2pp. 195(4:001. 24X Fiche: 50-244,83/06/27,830714037).
- --8307(40396 Notice of violation from insp on 830508-0616. \*\* Region 1, Office of Director. B3/06/27. 2pp. 19514:003. 24x Fich: 50-244, B3/06/27, B307(4037).
- ~~8307140403 IE Insp Rept 50~244/83-13 on 830508-0616. Noncompliance noted failure to follow operating & surveillance test procedures & failure to identify hatch door leak rate exceeding surveillance test acceptance criteria. ZIMMERMAN.R.P. Region 1. Office of Director. KISTER.H.B. Division of Project & Resident Programs. 83/06/27. 7pp. 19514-005. 24X Fiche: 50-244.83/06/27.8307140971.
- 8307270465 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.N. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19788:246. 24X Fiche: 50-244,83/07/19,8307270465.
- --830727046B Forwards public version of revised emergency plan implementing procedures including Procedures SC-605 re site contingency call list.SC-420 re estimating offsite doses & SC-323 re emergency offsite radiation survey teams.

  HAIER-J.E. Rochester Gas & Electric Corp. 83/06/24. MURLEY.T.E. Region i, Office of Director. ip. 19788:247. 24X fiche.50-244.83/07/19.8307270465.
- --8307270471 Public version of revised emergency plan implementing procedures, including Procedures SC-605 re site contingency call list SC-420 re estimating offsite doses & SC-323 re emergency offsite radiation survey teams.

   Rochester Gas & Electric Corp. 83706/21. 86pp. 19788:248. 24X Fiche: 50-244,83/07/19,8307270465.

## 8. Adjudicatory correspondence

- 8307050163 Forwards 830628 notice of availability of NRC EIA re util application for full-term OL. EIA evaluated Dec 1973 FES supporting conversion of provisional OL to full-term OL. YOUNG, M.A. Hearing Branch 4. 83/06/30. GROSSMAN, H., LUEBKE, E. A., COLE, R.F. Atomic Safety and Licensing Board Panel. 2pp. 19199:162 24X Fiche. 50-244, 83/06/30. 8307050163.
- 8307190004 Response to ASLB 830615 order requesting further status rept. Recommends ASLB establish 2-month period for intervenor to file new or amended contentions after issuance of conversion SER suppl. Certificate of Svc encl. YOUNG.M.A. Hearing Branch 4. 83/07/15. Atomic Safety and Licensing Board Panel. 14pp. 19635:016. 24X Fiche: 50-244,83/07/15. 8307190004.
- 8307190270 Response to ASLB 830615 order, recommending that period of discovery not commence until all future issuances reintegrated plant safety assessment rept (NUREG-0821) available VOIGT.H. H. Rochester Gas & Electric Corp. VOIGT.H. H. LeBosuf, Lamb, Leiby & MacRae. 83/07/15. 3pp. 19628:304. 24X Fithe: 50-244.83/07/15.8307190270.
- --8307170273 Mamorandum of law supporting licensee position re need to renotice apportunity to intervene ASLE should not order renotice. Since neither law nor golicy counsel favor renotice. Certificate of Svc encl. VOIGT.H.H. Rochester Gas & Electric Corp. VOIGT.H.H. LeBoeuf, Lamb, Leiby & MacRae. 83/07/15. Atomic Safety and Licensing Board Panel. 9pp. 19628:307. 24X Fiche. 30-244.83/07/15, 8307190270.
- B307200227 Status rept as of B30715. Util has no further issuances. NRC has two issuances expected by B30901. Author expects to file revised/add1 contentions. Prehearing conference unnecessary. Certificate of Svc encl. Related correspondence. BLADE, B.L. Affiliation Unknown. B3/07/15. 7pp. 19648: 053. 24X Fiche: 50~244, B3/07/15, B307200227.
- P. Operating license stage documents & correspondence
- 8304040070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs rs safety evaluation of "Emergency Response Guidelines" Svc list encl EISENHUT.D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp 19563 116 24X Fiche: 50-000.83/06/03.

- B307060184 Forwards SER accepting corrective actions proposed in B30316 & C422 submittals for resolving leakage detection systissues raised in integrated plant safety assessment rept (NUREG-0821), Section 4. 13.
  CRUTCHFIELD.D. Operating Reactors Branch 5. B3/06/28, MAIER, J. E. Rochester Oas & Electric Corp. 3pp. 19236:056. 24X Fiche: 50-244, 83/06/28, 8307060184.
- --8307060187 SER accepting licensee actions proposed in 830316 & 0422 submittals to resolve leakage detection sys issues raised in integrated plant safety assessment ropt (NUREO-0821). Section 4.13.
  - 4.13. \* Office of Nuclear Reactor Regulation, Director. 83/06/28. 3pp. 19236:059. 24% Fiche:50-244,83/06/28.8307060184.
- B307060263 Forwards safety evaluation of SEP Topic III-1 re integrated plant SAR (NUREG-0821). Section 4.7. "Classification of Structures. Sys & Components." Info supplied B30124 acceptable to resolve open items in Section 4.7. CRUTCHFIELD.D. Operating Reactors Branch 5. B3/06/28. MAIER, J. E. Rochester Gas & Electric Corp. 9pp. 19239: 294. 24X Fiche: 50-244, 83/06/28, 8307060263.
- 8307060247 Advises that 820426 response to restart SER (NUREG-0916) Item 17 re early operation of loose parts monitoring system viewed & installation & operation of system should assure continued safe operation of plant. Item 17 resolved. CRUTCHFIELD.D. Operating Reactors Branch 5. 83/07/01. MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 19237:182. 24X Fichs: 50~244,83/07/01,8307060269.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity. Svc list encl. EISENHUT, D. O. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 17390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. ElseNHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 30-000, 83/07/06, 830/7060329.
- B307120490 Responds to NRC B30531 ltr clarifying B21213 SER re environ qualification of electrical equipment Previous responses on B30201,0408 & 0519 adequately address 10CFR30.49.No addlinfo required.

  MAIER.J.E. Rochester Qas & Electric Corp. B3/07/06. CRUTCHFIELD.D. Operating Reactors Branch 5. ip. 19425:028. 24X Fiche: 50-244.B3/07/06.B307120490.
- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATHB events, 8vc list encl. EISENHUT, D. 0. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269. 24X Fichs: 50-000, 83/07/08, 8307080169.
- 830713001) Forwards evaluation of 830411 & 0616 responses to integrated plant SAR (IPSAR) Section 4.25.3, "Flooding Due to Failure of Tanks." Issue resolved.
  GRUTCHTELD.D. Operating Reactors Branch 5. 83/07/08. MAIER, J. E. Rochester Oas & Electric Corp. 5pp. 19474:204. 24X Fiche:50-244,83/07/08,8307130011.
- 8307180417 Advises that, based on review of 830524 & 0609 submittals re mod to steam generator tube sleeving process, Class II fee applicable.

  BIO05.R.M. License Fee Management Branch. 83/07/12. MAIER.R.E. Rochestor Gas & Electric Corp. 1p. 17566: 355. 24X Fiche: 30-244, 83/07/12, 8307180417.
- B307260445 Proposes mod to commitment made in NUREG-0821 per SEP Topic III-5.8 to protect main steam safety & relief valves from effects of block wall failures. Mod would ensure structural integrity.

  MAIER.J.E. Rochester Gas & Electric Corp. 83/07/20. CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 19734:207. 24X
  Fiche:50-244,83/07/20,8307260445.
- 8307260449 Forwards comproprietary version of safety evaluation supporting pretensioning mods to steam generator sleeving process Froprietary version issued 8306i6.
  CRUICHFIELD, D. Operating Reactors Branch 5, 83/07/25, MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 19731:199. 24X
  Fiche: 30-244,83/07/25,8307260449.
- --B307260450 Nonproprietary version of safety evaluation supporting pretensioning mods to steam generator sleeving process. \* Office of Nuclear Reactor Regulation, Director. B3/07/25. 11pp. 19731: 201. 24X Fiche: 50-244, 83/07/25, 8307260449.

- G. Inspection reports: IE Bulletins & correspondence
- 8307060022 Forwards IE Insp Rept 50-244/83-12 on 830509-13. No noncompliance noted.

  MARTIN.T. T. Division of Engineering & Technical Programs. 83/06/20. MAIER. J. E. Rochester Gas & Electric Corp. 2pp. 19251: 337. 24X Fiche: 50-244, 83/06/20, 8307060022.
- --B307060029 IE Insp Rept 50-244/B3-12 on 830309-13. No noncompliance noted Major areas inspected: B&W steam generator brazed sleeves & double explosively welded tube sheat sleeves, feedwater ring J tube replacement & maint welding. REYNOLDB, B. D. , DURR, J. Region 1, Office of Director. B3/06/17. 10pp. 19251: 339. 24X Ficha: 50-244, B3/06/20, B307060022.
- B307110536 Forwards IE Insp Rept 50-244/B3-14 on B30607-09. No noncompliance noted. MARTIN.T.T. Division of Engineering & Technical Programs. B3/06/22 MALER.J.E. Rochester Gas & Electric Corp. 2pp. 19380: 134, 24X Fiche: 50-244, B3/06/22, B307110536.
- --B307110939 IE Insp Rept 50-244/B3-14 on 830607-09. No noncompliance noted Major areas inspected: public prompt notification sys.

  GUHEN, T., CROCKER, H. W. Region 1, Office of Director. 83/06/21.

  5pp. 19380: 136. 24X Fiche: 30-244, 83/06/22, 8307110936.
- B307140371 Forwards IE Insp Rept 50-244/83-13 on B30508-0616 & notice of violation.

  STAROSTECKI.R. Division of Project & Resident Programs. B3/06/27.
  MAIER.J.E. Rochester Gas & Electric Corp. 2pp. 19514:001. 24X
  Ficha: 50-244,83/06/27,8307140371.
- --8307140396 Notice of violation from insp on 830508-0616.

  \* Region 1, Diffice of Director, 83/06/27, 2pp. 19514:003. 24X Ficha: 50-244,83/06/27,8307140371.
- --8307140403 IE Insp Rept 50-244/83-13 on 830508-0616 Noncompliance noted: failure to follow operating & surveillance test procedures & failure to identify hatch door leak rate exceeding surveillance test acceptance criteria. ZIMMERMAN.R.P. Region 1. Office of Director. KISTER.H.B. Division of Project & Resident Programs. B3/06/27. 7pp. 19514:005. 24X Fiche: 50-244,83/06/27,8307140371.
- B306270401 IE Info Notice B3~46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JURDAN,E.L. Division of Emergency Praparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B307220160 Notification of Significant Licenses Meeting 83-50 w/util on 830721 in Ontario:NY to discuss results of SALP.
  KISTERH. Region i. Office of Director. 83/07/13. Region i. Office of Director. 1p. 19692:354. 24X Fiche:50-244,83/07/13.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syr list encl.
  TAYLOR, J. M. Division of GA: Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14.8306270406.
- B307190164 Ack receipt of B30630 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/83-10.
  BTAROSTECKIR. Division of Project & Resident Programs. 83/07/15.
  MAIER.J.E. Rochester Gas & Electric Corp. 1p. 19636:261. 24X Fichs: 50-244,83/07/15,8307190164.
- --8307190169 Responds to NRC 830531 ltr re violations noted in IE Insp Rept 50-244/83-10 Corrective actions: new Test Procedure PT-2,2A, "RHR 6ys 8hutdown Operability Test," written & penformed on 830502.

  MAIER, J.E. Rochester Gas & Electric Corp. 83/06/30. ALLAN, J. M. Region 1, Office of Director. 2pp. 19636: 262, 24X Fiche: 50-244, 83/07/15, 8307190164.
- 8307280337 Responds to NRC ltr re violations noted in IE Insp Rept 50-244/83-16. Corrective actions: maint procedures revised to require verbal notification & documentation.
  MAIER, J.E. Rochester Gas & Electric Corp. 83/07/21. MURLEY, T. E. Region I, Office of Director. 3pp. 19789:053. 24X Fiche: 50-244,83/07/21,8307280337.

- R. Periodic operating reports & related correspondence
- 8307220178 Monthly operating rept for May 1983.W/830608 itr. MCNAMARA:A.E., SNOW:B.A. Rochester Qas & Electric Corp. B3/06/08. Office of Resource Management, Director. 7pp. 19684:019. 24X Fiche:30-244,83/06/08.8307220178.
- S. Reportable occurrences, LERs & related correspondence
- B307150379 RD: on B30609, during safety injection functional test, when safety injection signal initiated by simulating high containment pressure, charging pump IC did not trip, causing operation of reactor overpressure protection sys. MAIER. J. E. Rochester Gas & Electric Corp. B3/07/08. MURLEY. T. E. Region 1, Office of Director. 3pp. 1939:139. 24% Fiche: 50-244.83/07/08,8307150379.
- 8307220262 LER 83-019/03L-0: bn 830613, while changing from cold to hot shutdown, containment spray pumps found in pull-stop position at 207 F. Caused by changes in Tech Spec interpretation. Pumps placed in auto. W/880713 ltr. BEATTY, E. J. MAIER, J. E. Rochester Oas & Electric Corp. 83/07/13. MVRLEY, T. E. Region 1, 0ffice of Director. 2pp. 19684:175. 24X Fichs: 50-244,83/07/13.8307220262.
- 8307220377 LER 83-020/03L-0: on 830613, during startup from refueling outage, RCS chloride concentration exceeded 15 ppm at greater than 250 Fr. Causad by increased chloride solubility due to increasing RCS temp & contamination. H/930713 ltr. FILKINS. D.: MAIER. J.E. Rochester Qas & Electric Corp. 83/07/13. MURLEY.T.E. Region 1, 0ffice of Director. 3pp. 19675: 249, 24X Fiche: 50-244, 83/07/13, 8307220377.
- 8307280366 LER B3-023/03L-0:on 830619, following manual turbine trip due to loss of electro-hydraulic turbine control, block valve MOV 516 closed due to indicated leakage through pressurizer PORY-430. Caused by high pressurizer pressure. #/830719 ltr. LARIZZA-G.F., MAIER. J.E. Rochester Gas & Electric Corp. 83/07/19. MURLEY, T.E. Region 1, Office of Director. 3pp. 19796:118. 24X Fiche: 50-244, 83/07/19, 8307280366.
- DOCKET 50-245 MILLBTONE NUCLEAR POWER STATION, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 8307010074 Forwards Rev 17 to modified amended security plan. Rev withheld (ref 10GFR2.770).
  COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  COUNBIL.W.O. Northeast Utilities. 83/06/09.
  MURLEY.T.E. Region 1. Defice of Director. 1p. 19124: 339. 24X Fiche: 50-245, 83/06/09, 8307010074.
- 8307010195 Forwards IE Insp Repts 50-245/83-08 & 90-336/83-10 on B30508-0604. No noncompliance noted.

  8TARGSTECKI, R. Division of Project & Resident Programs. B3/06/14.

  COUNSIL, W. O., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19170:086. 24X Fiche: 50-245, 83/06/14, 8307010155.
- --8307010167 IE Insp Repts 50-245/83-08 & 50-336/83-10 on 830508-0604. No noncompliance noted Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, physical security & fire protection.

  8HEDLOBKY.J. T., LIPINSKI.D.R. Region i, Office of Director.
  EL8ASSER.T.C. Division of Project & Resident Programs. 83/06/10.
  11pp. 19170:088. 24X Fiche:50-245.83/06/14.8307010195.
- B307010072 Forwards IE Insp Repts 50-245/83-10 & 50-336/83-12 on B30516-19. No noncompliance noted. MARTIN.T.T. Division of Engineering & Technical Programs. B3/06/15. COUNSIL.M.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19168:132. 24X Fiche:50-245.89/06/15.8307010072.
- --8307010080 IE Insp Repts 50-245/83-10 & 50-336/83-12 on 830516-19. No noncompliance noted. Major areas inspected: followup of amergency preparedness items from IE Insp Repts 50-245/82-01 & 50-336/82-01 on 820104-14. MILLER.M., 9MITH.R., CROCKER.H.W. Region 1, Office of Director. 83/06/15, 17pp. 19168: 134. 24X Fiche: 50-245,83/06/15,8307010072.
- 8307110019 Forwards Rev 1 to suitability, training & qualification plan. Rev withheld (ref 10CFR2.790).
  COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  COUNSIL.W.Q. Northeast Utilities. 83/06/24.
  MURLEY, T.E. Region i, Office of Director. ip. 19374:202. 24X
  Fiche: 50-245, 83/06/24, 8307110019.

- B307260346 Application for amend to License DPR-21, proposing Tech Spec changes to correct typographical errors, promote clarity & standardize testing on carbon dioxide & Halon 1301 fire control sys. Class II amend fee encl.
  COUNSILL M. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CBUNSILL M. G. Northeast Utilities. B3/07/15.
  CGUICHTELD D. Operating Reactors Branch S. 2pp. 19733:024. 24X Fiche. 50-245,83/07/15,8307260346.
- --8307260351 Proposed Tech Spec 3/4 12-7 & Table 3.12.2 re carbon dioxide & Halon 1301 sys & fire protection instruments.

   Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  83/07/15. 2pp. 19733:026. 24X Fiche:50-245,83/07/15.8307260346.

#### J. Insurance & indemnity information

- 8307200111 Forwards Secondary Financial Protection Certificates N-15 & N-16 to NELIA Policy 1 & Secondary Financial Protection Certificates M-15 & M-16 to MAELU Policy 1.
  Certificates M-15 & M-16 to MAELU Policy 1.
  SINIBIJ.M. Marsh & McLennan, Inc. 83/07/12. BALTIMAN, J.D.
  Assistant Director for State & Licensee Relations. 29pp. 17646:001
  24X Fiche: 50-245, 83/07/12, 8307200111.
- P. Operating license stage documents & correspondence
- 8307110616 Monthly notice of amends to OLs involving NSHC issued since 830923 CLARK.R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24x Fiche: 50-000.83/06/14.8307110616.
- 8307060082 Advises that undervoltage setpoint of 84-volt ac chosen to prevent spurious trips due to voltage transients caused by starting large loads while remaining conservatively above dropout relay voltages.

  CDUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CDUNSIL.W.O. Northeast Utilities. 83/06/24.

  CRUTCHFIELD.D. Operating Reactors Branch 5. 1p. 19251:356. 24X Fiche:50-245,83/06/24,8307060082.
- B30709018? Forwards "Integrated Plant Bafety Assessment Rept," for Sections 4, 9,4,10,2 & 4,56.1 re effects on pipe break on components inside containment & jet impingement criteria outside containment. Requests Tech Spec amend within 90 days. SHEA. J. Operating Reactors Branch 5, 83/06/29, COUNSIL.W.G. Northeast Nuclear Energy Co. (Subs. of Northeast Utilities). Spp 19199:197. 24K Fiche: 50-245,83/06/29,8307050189.
- 8306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveitlance requirements for diesel fuel impurity. Syc list enci.
  EISENHUT.D. Q. Division of Licensing. 83/07/09. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X
  Fiche: 50-000:83/07/05:8306270397.
- 8307080434 Forwards safety evaluation of util 621203 response to integrated plant safety assessment rept (NUREG-0824). Section 4.3.2, on ventilation sys. Loss-of-ventilation tests & proposed procedural & design mods acceptable.
  8H&A.J.J. Operating Reactors Branch 5. 83/07/05. COUNSIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp 19346: 132. 24% Fiche: 50-245, 83/07/05, 8307080434.
- --8307080439 Safety evaluation accepting util 821203 response to integrated plant safety assessment rept (NUREO-0824). Section 4.32 re ventilation sys.based on listed procedural & hardware mods

  \* Office of Nuclear Reactor Regulation, Director, 83/07/05. Spp. 19346.154. 24X Fiche: 50-245, 83/07/05.8307080434.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors to surveillance intervals in STB Svc list encl. EISEMHUT.D.G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York Inc. 16pp. 19659:294. 24X Fiche: 50-000.83/07/06.8307060329.
- 8307130282 Forwards evaluation be response to integrated plant SAR Section 4.20. "Containment Isolation Sys." Design mod acceptable.
  SHEA.J. Operating Reactors Branch 5. 83/07/07. COUNSIL.W.C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp 19308:209. 24X Fiche: 50-245,83/07/07,8307130282.
- --8307130289 Evaluation concluding info % proposed corrective action re integrated plan SAR Section 4.20, "Containment Isolation Sys" acceptable. 4 Operating Reactors Branch 5 83/07/07. 3pp. 19508:211. 24X Fiche.50-245,83/07/07.8307130282.

- 8307150193 Application for amend to Licenses DPR-21 & DPR-65, revising Bection 6 of administrative Tech Specs to reflect updated wtil policies & practices.
  COUNSIL, W.C., SEARS, C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  COUNSIL, W.G., SEARS, C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  COUNSIL, W.G., Northeast Utilities.
  83/07/07.
  CLARK, R.A., Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 19538:030. 24X Fiche: 50-245, 83/07/07, 8307190193.
- --8307150197 Proposed rev to administrative Tech Specs reflecting updated util policies & practices.

  \* Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  83/06/30. 32pp. 19538:032. 24X Fiche: 50-245:83/07/07:8307150193.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events, Svc list encl. EISBNHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Ca. of New York, Inc. 38pp. 1969:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307190131 Submits revs to Corporate Organization for Nuclear Incidents Procedure Manual.per 100FR30, App E. Section V. COUNSIL. W. G. Counscitivit Yankse Atomic Power Co. COUNBIL. W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL. W. G. Northeast Utilities. 83/07/14. EISENNUT. D. G. Division of Licensing. 1p. 19636:074. 24% Fiche: 50-000.83/07/14. B307190131.
- B307260346 Application for amend to Liconse DPR-21, proposing Tech Spec changes to correct typographical errors, promote clarity & standardize testing on carbon dioxide & Halon 1301 fire control sys. Class II amend fee encl.
  COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. O. Northeast Utilities. B3/07/15.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 19733:024. 24X Fiche: 50-245,83/07/15,8307240346.
- --8307260351 Proposed Tech Spec 3/4 12-7 & Table 3.12.2 re carbon dioxide & Halon 1301 sys & Fire protection instruments.

  \* Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  83/07/15, 2pp. 19733:026. 24X Fiche:50-245/83/07/15/8307260346.
- 8307250524 Notification of 830809 meeting w/utils.Franklin Research & Teledyne Engineering Svc in Framingham.MA to discuss Mark I long-term program implementation & unresolved questions restructural integrity.

  SHEA: J. J. Deprating Reactors Branch 5. 83/07/20. CRUTCHFIELD.D. Operating Reactors Branch 5. 1p. 19782:240. 24X Fiche: 50~000.83/07/20.8307250524.
- 8307260493 Notifies that gas turbine preventative maint program will be revised to require calibr of control circuit timers during each refueling outage, per SEP Topic VIII-2, "Onsite Emergency Power Sys."

  COUNSIL, W. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNBIL, W. 9. Northeast Utilities. 83/07/20. CRUICHTELD, D. Operating Reactors Branch 9. 1p. 19734:049. 24X Fiche: 50-245, 83/07/20, 8307260453.
- 8307260522 Forwards "Responses to NRC Request for Info:Mark 1 Torus Program Plant-Unique Rept.Millstone 1." in response to NRC 830428 request Info will be included in torus attached piping plant-unique analysis rept to be submitted 830801. CDUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CDUNSIL.W.O. Northeast Utilities. 83/07/20. CRUTCHFIELD.D. Operating Reactors Branch 5. 1p. 19733;315. 24X Fiche: 50-245,83/07/20,8307260522.
- --8307260527 "Responses to NRC Request for Info:Mark 1 Torus Program Plant-Unique Rept. Millstone 1."

  \* Teledyne Engineering Services. 83/07/31. 19pp. 19733:316. 24X Fiche:50-245.83/07/20,8307260522.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307010135 Forwards IE Insp Repts 50-245/83-08 & 50-336/83-10 on 830508-0604. No noncompliance noted. STAROSTECKI.R. Division of Project & Resident Programs. 83/06/14. COUNSIL.W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19170:086. 24X Fiche:50-245,83/06/14.8307010135.
- --8307010167 IE Insp Repts 50-245/83-08 & 50-336/83-10 on 830508-0604. No noncompliance noted Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, physical security & fire protection.

  SHEDLOSKY, J. T., LIPINBKI, D. R. Region 1, Office of Director. ELSASSER, T. C. Division of Project & Resident Programs. 83/06/10 1pp. 19170:088. 24X Fiche: 50-245,83/06/14.8307010155.

- 8307010072 Forwards IE Insp Repts 50-245/83-10 & 50-336/83-12 on 830516-19. No noncompliance noted.

  MARTIN,T. T. Division of Engineering & Technical Programs. 83/06/15. COUNSIL W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19168: 132. 24X Fiche: 50-245. 83/06/15. 8307010072.
- ---B307010080 IE Insp Repts 50-245/83-i0 & 50-336/83-i2 on 830516-19. No noncompliance noted Major areas inspected followup of amergency preparadness items from IE Insp Repts 30-245/82-01 & 50-336/82-01 on 820104-14.

  MILLER.M., SMITH.R., GROCKER.H.W. Region 1, Office of Director. 83/06/15, 17pp. 19168:134, 24X Fiche: 50-245/83/06/15, 8307010072.
- 8307120429 Ack receipt of 830620 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-06 & 50-336/83-08, STAROBTECKI.R. Division of Project & Resident Programs. 93/07/05. COUNSIL-W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p. 19425:236. 24X Fiche: 50-245, 83/07/05, 8307120429.
- --8307120432 Responds to NRC 830523 ltr re violations noted in IE Insp Repts 50-245/83-06 & 50-336/83-08. Corrective actions:logging requirement implemented for periodic verification of computer updating. COUNSIL.H. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,H.0, Northeast Utilities. 83/06/20. STAROSTECKI.R. Division of Project & Resident Programs. 2pp. 19425:237. 24X Fiche:50-245.83/07/05.8307120427.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list enci. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDANIE. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153, 24X Fiche: 50-000,83/07/12,8306270404.
- 8307190206 Advises that violations cited in IE Insp Repts 50-245/82-24, 50-336/82-26 & 50-213/83-02 re QA program for transport packages will be changed to unresolved items until firm criteria established.

  MARTIN.T. T. Division of Engineering & Technical Programs. 83/07/13. COUNBIL.W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19632:115. 24X Fiche: 50-000.83/07/13.8307190206.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. enct. TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307220104 Monthly operating rept for May 1983. H/830615 ltr.
  HARRAN.G., MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of
  Northeast Utilities). MROCZKA,E.J. Northeast Utilities. 83706/07
  Office of Resource Management, Director. 7pp. 19683:354. 24X
  Fiche: 50-245,83706/07,8307220104.
- 8. Reportable occurrences. LERs & related correspondence
- 8307010122 LER 83-018/03L-0: on 830917, gas turbine started & achieved ready to load status within 50,74 s. Tech Specs require 48 s. Caused by natural end-of-life of components. One ignitor replaced. Second to be replaced later. W/830614 ltr. THULL, T. B. , MRGCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRGCZKA, E. J. Northeast Utilities. 83/06/14. MRRCZKA, E. J. Rotheast Utilities. 83/06/14. Fiche: 50-245, 83/06/14, 8307010122.
- 8307060343 Updated LER 82-023/03X-2: on B21005, while performing local leak tests; atmosphere control valves found leaking in excess of Tech Specs limit. Caused by packing leaks & worn seat. Packing replaced. IV/830618 ltr.

  THULL, T. S.; MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). THULL, T. S., Northeast Utilities. 83/06/18. MRILEY, T. E. Region i. Office of Director. 6pp. 19234:170. 24X Fiche: 50-245, 83/06/18, 8307060343.
- 8307010027 LER 83-020/01T-0: on 830607, while performing cleanup systounds, crack indication identified on weldolet weld. Caused by vibration & fatigue during blowdown through relief valve. Heldolets to be visually inspected. M/830621 ltr. THULL, T.S., MRDCZKA, E.J., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRDCZKA, E.J., Northeast Utilities. 83/06/21. MRRCZKA, E.J., Northeast Utilities. 83/06/21. MRRCZKA, E.J., Spp. 19167:200. 24X Fiche: 50-245, 83/06/21, 8307010027.

- 8307120409 RO: on 830512, reactor protection sys master scram contactor 590-1080 burned out. Caused by end-of-life-cyle. Contactor rebuilt w/new core armature & coil.
  MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities. B3/06/24.
  MURLEY,T.E. Region 1. Office of Director. 2pp. 19430:130. 24X Fiche: 50-245, 83/06/24, 8307120409
- B307060027 PNS-I-83-015A: updates B30616 marijuana cigarette discovery reported on B30617. Seven contract security personnel terminated because of accusations or admissions of usage DUNLOP, J. GODY.A. Region J. Office of Director. B3/06/30 1p. 19251: 349. 24X Fiche: 50-245. B3/06/30. B307060027.
- 8307110281 LER 83-022/03L-0: on 830603, time delay relay 590-1230 tripped during turbine centrol valve fast closure function 5 calibr test. Caused by low tolerance Tolerance bank increased & setpoints decreased W.830701 lts.
  THULL, T. S., MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/07/01. MRRLEY, T. E. Region 1, Office of Director. 4pp. 19379:152. 24X Fiche: 50-245, 83/07/01, 8307110281.
- 8307190193 LER 83-023/03L-0: on 830616, discovered acoustical valve monitor function test not performed since 821123 Caused by test inadvertently left off production maint mgt sys schedule printout. Surveillance performed W/830711 ltr.
  THULLITS. MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Otilities. 83/07/11. MRRCZKA, E. J. Northeast Utilities. 83/07/11. Fiche: 90-245, 83/07/11. 8307190193.
- 8307190138 LER 83-024/03L-0: on 830612, while performing rounds on gas turbine generator: ECR oil pump motor discovered hot to touch & failed rendering generator insperable. Caused by motor natural end of life. Motor replaced W/830712 ltr.
  THULL, T.S., MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Otilities). MROCZKA-E. J. Northeast Utilities. 83/07/12 MRREZY, T.E. Region I. Office of Director. 3pp. 19636:106 24X Fiche: 50-245, 83/07/12, 8307190138. 83/07/12.
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8307010129 Informs that addl QA audit repts for transport packages did not fulfill appropriate criteria, per JE Insp. Rept 50-247/83-05. Branch technical position will be developed for similar fire protection packages. MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/24. 0'10DLE.J.D. Consolidated Edison Co. of New York. Inc. 2pp. 19169:278. 24X Fiche: 50-247.83/06/24.0307010129
- B307140004 Forwards preliminary views on B30623 questions re strike at facility % impact of strike on emergency planning % preparedness.
  PALLADING.N.J. Commissioners. B3/06/28. OTTINGER.R.L. House of Rep., Energy & Commerce. 3pp. 17656-267. 24X Fiche: 90-247, 83/06/28.8307140004.
- --8307140007 Requests answers to listed questions re employee strike at facility & impact of strike on emergency planning & preparedness, by 830628.

  OTTINGER.R. L. House of Rep., Energy & Commerce 83/06/23 PALLADING,N.J. Commissioners. 1p. 19656:270 24×
  Fiche:50-247,83/06/28,8307140004
- B307250070 Forwards draft SER re B30110 App R exemption requests. Corrections to SER & proposed actions on denied exemptions requested within 3 wks.
  EISENHUT, D. G. Division of Licensing. 83/06/29. 0/IDQLE, J. D. Consolidated Edison Co. of New York, Inc. 46pp. 19724:094. 2 Fiche: 50~247, 83/06/29, 8307250070.
- 8307120231 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-11.

  8TAROBTECKI.R. Division of Project & Resident Programs. B3/07/01.
  0/100LE.J.D. Consolidated Edison Co. of New York. Inc. 2pp 19423:208. 24X Fiche: 50-247,83/07/01.8307120231.
- --8307120235 Responds to NRC B30516 ltr re violations noted in IE Insp Rept 50-247/B3-11 Safeguards info deleted (ref 10CFR2.790 % 73.21). 73 21).
  0/TOOLE, J. D. Consolidated Edison Co of New York, Inc. 83/06/15.
  STARDSTECKI, R. Division of Project & Resident Programs. 2pp
  19423:210. 24X Fiche:50-247.83/07/01.8307120231.
- 8307210007 Forwards IE Insp Rept 50-247/83-14 on 830523-27. No NOZIOUN FORMATUS IE INSPIRENT SO STATUS IN INC. TO STATUS IN INC. STAROSTECKI R. Division of Project & Resident Programs. 83/07/00L6. J.D. Consolidated Edison Co. of New York, Inc. 2pp. 19669: 221. 24X Ficho: 50-247, 83/07/05, 8307210007. 83/07/05

- --8307210014 IE Insp Rept 50-247/83-14 on 830523-27 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737. Item II 8 2 re design of plant shielding & vital area assessment BAUNACK, W H . EAPEN.P.K. KISTER.H B. Region 1. Office of Director. 83/06/30. 8pp. 19669-283. 24X Fiche.50-247.83/07/05, 8307210007
- 830727022! Forwards NRC draft SER re exemptions requested from LOCFR50, App R.
  MOORE, J. E. Hearing Branch 1. 83/07/22 GLEASON, J.P., PARIS, O.B., SHON, F. J. Atomic Safety and Licensing Board Panel. 45pp.
  19749:124. 24X Fiche: 50-247, 83/07/22, 8307270221

#### G. Adjudicatory correspondence

- B307120563 Memorandum opposing PIRG of New York motion for reconsideration of Commission B30610 order PIRG should not be parmitted to relitigate arguments fully considered & ruled upon by Commission.
  BRANDENBURG. G. Consolidated Edison. Co. of New York, Inc. 83/07/07. Commissioners. 3pp. 19433:131. 24X Fiche: 50-247, 83/07/07, 8307120363.
- --B307120567 Confirms B30630 telcon w/D McCloskey re info on util program to assist State of NY in performing emergency response activities detailed in radiological emergency response interim plan for implementing compensating measures.

  O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/07/01. CROCKER, H. W. Region i, Dffice of Director. 2pp. 19433: 134. 24X Fiche 50-247, 83/07/07, 8307120563.
- 8307120565 Response opposing PIRG of New York motion for reconsideration of Commission 830610 order. Motion untimely, identifies no matters of fact or law & improperly raises new issues. Certificate of Syc encl. MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/07/07. Commissioners. 10pp. 19433:136. 24X Fiche. 30-247,83/07/07,8307120585.
- B307120546 Order approving util & NRC 830615 transcript corrections, w/listed exceptions.
  GLEASON.J.P. Atomic Safety and Licensing Board Panel. 83/07/08.
  Office of the Executive Legal Director. 5pp. 19433-398. 24X
  Fiche: 90-247, 83/07/08, 8307120546.
- 8307120039 Proposed findings of fact, conclusions of law-upinions & recommendations re Commission Questions 1-6 (Vols 1-3). HDRGAN.C. Power Authority of the State of New York. MDRGAN.C. Morgan Associates. 83/07/11. 947pp 19420:001. 24X Fiche: 50-247,83/07/11.8307120035.
- 8307130077 Proposed findings of fact & conclusions of taw. Certificate of Svc encl.

  \* Union of Concerned Scientists. \* Public Interest Research Group, New York \* West Branch Conservation Association. 83/07/11. 323pp. 19472. 323. 24X Fiche: 50-247, 83/07/11, 8307130077.
- 8307130234 Proposed opinion findings of fact, conclusions of law & recommendations. Certificate of Svc encl MOORE, J E., HASSELL, D F., MGGURREN.H. J. Hearing Branch i. B3/07/ii. 362pp. 19305:038. 24X Fiche: 50-247.B3/07/ii.8307130234.
- B307180040 Proposed findings of fact to Commission Questions 1-4 & proposed opinion, conclusions of law & recommendations.

  Certificate of Svc encl
  BRANDENURG, B. Consolidated Edison Co. of New York, Inc. B3/07/11.

  994pp. 19557 091. 24x Fiche: 50-247,83/07/11.B307180060.
- B307(B007) Forwards proposed findings of fact & conclusions per B30422 memo. D'ROURKE,A.P. Westchester County, NY. B3/07/11 QLEASON,J.P. Atomic Safety and Licensing Board Panel 1p 19560:161. 24X Fiche: 50-247,83/07/11,8307(B007).
- --8307180074 Proposed findings of fact & cunclusions. Certificate of Syc
  - encl. \* Westchester County, NY. 83/07/11 37pp 19560:162. 24X Fiche: 50-247,83/07/11,8307180071.
- B30721005) Forwards two corrected pages to NRC proposed opinion, findings of fact, conclusions to law & recommendations.
  MCGURREN.H.J. Hearing Branch 1. 83/07/13. OLEASON.J.P., SHON.F.J.,
  PARTS,O.H. Adomic Safety and Licensing Board Panel. 1p. 19668:274.
  24X Fiche.50-247,83/07/13,8307210051
- --8307210041 Two corrected pages to NRC proposed opinion.findings of fact.conclusions of law & recommendations. \* Office of the Executive Legal Director. 83/07/13. 2pp. 19668.275. 24X Fiche: 50-247.83/07/13.8307210051

- 8307270221 Forwards NRC draft SER re exemptions requested from 10CFR50, App R.
  MODRE, J. E. Hearing Branch 1. 83/07/22. GLEASON, J. P., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 43pp. 19749: 124. 24X Fiche: 50-247, 83/07/22, 8307270221
- 8307270117 Order extending time until 830824 for Commission to act to review 830627 Director's Decision.
  CHILK.S. J. Office of the Serretary of the Commission. 83/07/25.
  Commissioners. 1p. 19749:346. 24X Fiche:50-247.83/07/25.
  8307270117.
- 8307290094 Memorandum re PJ Amico, ASLB consultant, 830624 rept on testimony on Commission Guestian 5. No need exists for further testimony or party comments on rept. CLEASON.J.P. Atomic Safety and Licensing Board Panel. 83/07/27, 2pp. 19822: 214. 24X Fiche: 50-247, 83/07/27, 8307290094.
- --8307290108 Presents results of review of testimony on Commission Question 5. Testimony on Question 5 is as complete as possible but suffers from same deficiencies re relative risk.

  AMICO.P. J. Applied Risk Technology Corp. 83/07/01. GLEABON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 7pp. 19822:216. 24X Fiche: 50~247,83/07/27,8307290094.

#### H. General correspondence

- 8307050100 Forwards Rockland County Legislature Resolution 389 requesting plants cease operation until County radiological plan approved.
  8AMUELS P. Rockland County, NY. 83/06/27, PALLADIND, N. J. Commissioners. 3pp. 19199: 344. 24X Fiche: 50-247, 83/06/27, 8307090100.
- --8307050110 Forwards Rockland County Legislature Resolution 390 requesting State of NY Legislature to pass legislation regulating nuclear power industry, based on accommic consequences of radiological accidents & nuclear waste. SAMUELS, P. Rockland County, NY. 83/06/27. PALLADING, N. Commissioners. 3pp. 19199:347. 24X Fiche: 50-247, 83/06/27, PBD/0250100.
- --8307050i16 Forwards Rockland County Legislature Resolution 391 authorizing County atty to take legal action if NRC does not shot down plants on 830609.

  6AMUEL6.P. Rockland County, NY. 83/06/27. PALLADING, N. J. Commissioners. 4pp. 19199: 350. 24X Fiche: 50-247, 83/06/27, 8307050100.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307250493 Forwards Rev 1 to updated FSAR. 8CHOPPMAN.M. NUS Corp. 83/07/22. POLK.P. NRC - No Detailed Affiliation Given. 1p. 19710:203. 24X Fiche:50-247.83/07/22. 8307250493.
- --8307250302 Rev 1 to updated FSAR. \* Consolidated Edison Co. of New York, Inc. 83/07/22. 604pp. 19710: 204. 24X Fiche: 50-247,83/07/22,8307250493.
- P. Operating license stage documents & correspondence
- 8307050152 Forwards application for amend to License DPR-26, changing Tech Specs to revise operability requirements & limiting conditions for operation for reactor cavity level monitoring instrumentation.

  O'TOOLE J D. Consolidated Edison Co. of New York, Inc. 83/05/03. WARQA S. A. Operating Reactors Branch 1 1p. 19199:151. 24X Fiche: 90-247, 83/05/03,8307050152.
- --8307050162 Application for amend to License DPR-26.changing Tech Specs to revise operability requirements & limiting conditions for operation for reactor cavity level monitoring instrumentation.

  O'TODI.E. J. D. Consolidated Edison Co. of New York, Inc. 83/05/04.

  2pp. 19197: 152. 24X Fiche: 50-247, 83/05/03, 8307050152.
- --8307050169 Proposed Tech Specs revising operability requirements & limiting conditions for operation for reactor cavity level monitoring instrumentation.

  \* Consolidated Edjson Co. of New York, Inc. 83/05/04. 8pp, 19199:154. 24X Ficho: 50-247, 83/05/03, 8307050152.
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines."

  Svc list enci.
  EISCNRUT.D. 0. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19863:116. 24x Fiche: 50-000,83/06/03,8306060070.

- 8307040325 Staff requirements memo re 830417 briefing on impending strike by util employees. Commission requested that Region I determine if personnel that util intends to use in control room meet regulatory requirements.

  CHILK.S. J. Office of the Secretary of the Commission. 83/06/27. Office of the Secretary af the Commission. 1p. 17279:276. 24X Fichs: 50-247,83/06/27,8307060325.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390 317 24X Fiche: 90-000,83/07/05,8306270397.
- B307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re survaillance intervals in STS. Swc list encl. ETSENHUT.D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000.83/07/06.8307060329.
- 8307230126 Forwards Amend 84 to License DPR-26, safety evaluation & notice of issuance & availability. Amend permits one-time 48 h extension to current 24 h limitation of operation w/ containment spray pump 21 out of svc. VARGA.S.A. Operating Reactors Branch 1. 83/07/06. 0'TUOLE, J. D. Consolidated Edison Co. of New York, Inc. 3pp. 19738:119. 24x Fiche: 50-247,83/07/06,8307250126.
- ---8307250128 Amend 64 to License DPR-26, permitting one-time 48 h extension to current 24 h limitation of operation w/containment spray pump 21 out of svc. VARGA. S. A. Dperating Reactors Branch 1. 83/07/06. 4pp. 19738: 122. 24X Fiche: 50-247, 83/07/06, 8307250126.
- ---B307250136 Safety evaluation supporting Amend 84 to License DPR-26.

  \* Office of Nuclear Reactor Regulation, Director. 83/04/28, 4pp 19738: 126. 24% Fiche: 50-247,83/07/06,8307250126.
- ---8307250141 Notice of issuance & availability of Amend 84 to License DPR-26. VAROA: S.A. Operating Reactors Branch 1. 83/07/06. 2pp. 19738: 130. 24X Fiche: 50-247, 83/07/06, 8307250126.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 8307270023 Advises that due to inactivity re 740313 request for change to Tech Spec to permit underfrequency trip setpoint on reactor coolant pump to be lowered to 55.0 Hz, issue closed. Application must be resubmitted to pursue issue. VARGA, 8. A. Operating Reactors Brench 1. 83/07/21. 0'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 17824:355. 24x Fiche: 50-247,83/07/21,8307270023.
- G. Inspection reports, IE Bulletins & correspondence
- 8307050449 Forward SER granting in part. & denying in.part relief from inservice inspectant requirements. License amend request to update Tech Bpec Section 4.2 reflecting SER required within 43 days of receipt of ltr. VAROA.S. A. Operating Reactors Branch 1. 83/06/17. D'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 19262:289. 24X Fiche: 50-247, 83/06/17. 8307050449.
- --8307050453 Bafety evaluation granting in part, & denying in part, relief from inservice insp exam requirements. \* Office of Nuclear Reactor Regulation, Director. 83/06/17. 13pp. 19262: 291. 24X Fiche: 50-247.83/06/17,8307050449.
- 8307010129 Informs that addl QA audit repts for transport packages did not fulfill appropriate criteria.per IE Insp. Rept 30-247/83-05. Branch technical position will be developed for similar fire protection packages. MARTIN, T. T. Division of Engineering & Technical Programs. 83/06/24. 0'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 19169; 278. 24X Fiche: 50-247, 83/06/24, 8307010129.
- 8307110386 Forwards IE Insp Rept 50-247/83-13 on 830517-20. No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/24 0'TOOLE.J.D. Consoltdated Edison Co. of New York, Inc. 2pp. 19380:277. 24X Fiche: 50-247.83/06/24.8307(10386.

- --8307110388 IE Insp Rept 50-247/83-13 on 830517-20.No noncompliance noted Major areas inspected: effluent control & radwaste mgt programs, including administrative control of effluent releases & radiochemical analyses of samples.

  WHITE.J.R., MCGRIDE, M. H., SHANBAKY, M. Region 1, Office of Director, 83/06/23. Spp. 19380: 279. 24X Fiche: 30-247,83/06/24,8307110386.
- B307060295 Advises of Nov 1983 completion date of analytical study needed to resolve IE Bulletin 80-04, "PWR Main Steam Line Break M/Continued Feedwater Addition," O'TODLE, J. D. Consolidated Edison Co. of New York, Inc. B3/06/30, VARGA, S. A. Operating Reactors Branch 1. 1p. 19238: 341, 24X Fiche: 30-247, 83/06/30, 8307060295.
- 8307060305 Forwards response to 830512 request for add1 info re 830816 response to 1E Bulletin 80-11. "Massnry Wall Design."
  Brick wall shear stresses discussed. 0'TOOLE.J.D. Consolidated Edison Co. of New York, Inc. 83/06/30. VARGA.S.A. Operating Reactors Branch 1. 7pp. 19238:324. 24X Fiche: 30-247.83/06/30, 8307060305.
- 8307120231 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-II.

  STAROSTECKI,R. Division of Project & Resident Programs. 83/07/01.

  O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp.

  19423:208. 24X Fiche: 50-247,83/07/01,8307120231.
- --8307120235 Responds to NRC 830516 itr re violations noted in IE Insp. Rept 50-247/83-11. Safeguards info deleted (ref 10CFR2.790 & 73.21).

  O'TOOLE.J.D. Consolidated Edison Co. of New York, Inc. 83/06/15. STAROSTECKI, R. Division of Project & Resident Programs. 2pp. 19423:210. 24X Fiche: 50-247,83/07/01.8307120231.
- 8307210007 Forwards IE Insp Rept 50-247/83-14 on 830523-27 No noncompliance noted. 81AROSTECKIR. Division of Project & Resident Programs. 83/07/05. 0'1700LE.J.D. Consolidated Edison Co. of New York: Inc. 2pp. 19649: 221. 24X Fiche: 30-247,83/07/05,8307210007.
- --8307210014 IE Insp Rept 50-247/83-14 on 830523-27. No noncompliance noted Major areas inspected: licensee actions taken to comply w/requirements described in NUREG-0737. Item II. B. 2 re design of plant shielding & vital area assessment. BAUNACK. M. H. , EAFEN, P. K. , KISTER. H. B. Region 1, Office of Director. B3/06/30. 8pp. 19669: 223. 24X Fiche: 50-247, B3/07/03, B307210007.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:273. 24X Fithe: 50-000.83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563: 153, 24X Fiche: 50-000.83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Roleases of Radioactive I-125 & I-131 in Ercess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Bafeguards & Inspection Programs (Post 830103), 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- R. Periodic operating reports & related correspondence
- 8307220365 Monthly operating rept for May 1983.W/830615 ltr. EICH.E.F., O'TOOLE, J.D. Consolidated Editon Co. of New York, Inc. 83/06/06. MCDONALD.W.O. Office of Resource Management, Director. 11pp. 19676:109. 24x Fiche:
- 8307220429 Monthly operating rept for June 1983.W/830715 ltr. EICH.E.F., D'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 83/07/05. MCDONALD, W. O. Office of Resource Management, Director. 7pp. 19687: 275. 24X Fiche: 50-247.83/07/05.8307220429.
- S. Reportable occurrences, LERs & related correspondence
- 8307010156 LER 83-023/03L-0: on 830517. during normal operation motor operator would not close valve 205 in charging line to RCS. Cause unknown. Motor tested w/valve linkage disconnected. Closing torque switch adjusted W/830616 ltr. HINRICHS.G., 0/TOOLE.J.D. Consolidated Edison Ca. of New York, Inc. 83/06/16. ALLAN.J.M. Region 1, Office of Director. 2pp. 17124:335. 24X Fiche: 50-247, 83/06/16, 8307010156.

- 330715006: LER 83-024/03L-0 on 830527, during normal operation, boron injection tank level channel 944F became inoperable Caused by erroneous level indication due to solidification of boric acid in instrument line. Affected line cleared W/830626 ltr. OfTOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/06/26. MURLEY, T. Region 1. Office of Director. 2pp. 19548:200. 24X Fiche: 50-247, 83/06/26, 8307150061.
- B307150119 Part 21 rept re deviation in installation of ABCO 302A1264C transfer switches. Evaluation in progress. Next rept will be submitted within 60 days of itr date.

  MANNA.F. J. Automatic Switch Co. 83/06/27 Region 4, Office of Director. 1p. 19536-227. 24X Fiche: 50-247-83/06/27,8307150119.
- B307180151 LER 83-025/03L-0: on 830601. flow control valve 604A on abviliary feedwater pump 21 discharge line to steam generator 21 did not open when required during surveillance test. Caused by chipped cage on valve. W/830701 ltr.
  HINRICHS.G., O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 83/07/01. MURLEY, T.E. Region 1. Office of Director. 3pp. 19556: 252. 24X Fiche: 50-247.83/07/01, 8307180151.
- 3307220203 LER 93-022/03L-0: on 830310, valve 850A in safety injection pump discharge header could not be fully closed. Cause unknown. Valve closed by hand to clear seat of solidified boric acid. M/890705 ltr.
  HINRICHS, G. D'TODLE, J. D. Consolidated Edison Co. of New York, Inc. 83/07/05. MURLEY, T. E. Region t. Office of Director. 2pp. 19684:035. 24X Fiche: 50-247-83/07/05, 8307220203.
- 9307220275 Updated LER 82-049/01X-1:on 82110B; review of video tapes obtained during Cycle 5/6 refueling & maint outage indicated four Region 5 & one Region 6 fuel assemblies w/clad degradation. Caused by hydriding, W/830711 ltr.
  LIMOSES, C. O'TOOLE, J. D. Consulidated Edison Co. of New York, Inc. 83/07/11 MVRLEY, T.E. Region 1. Office of Director. 4pp. 19684:127. 24X Fiche: 50-247.83/07/11.8307220275.
- B307220280 Updated LER B3-003/01X-1: on B30213, increase in RCS leakage identified. RHR valve 731 packing leaked through controlled leakoff collection sys to reactor colant drain tank Caused by failed valve gland packing. Valve repacked. B/330711 ltr. HINRICHS.G., D'TODLE, J.D. Consolidated Edison Co. of New York, Inc. 83/07/11. MURLEY, T.E. Region I, Office of Director. 3pp. 19684:151. 24X Fiche: 50-247,83/07/11,8307220280.
- B307220555 Updated LER 82-026/03X-1:on 820618, essential svc water sys supplied by svc water pumps 21,22 & 23 declared inoperable due to low pump head values. Caused by excessive wear of pump impeller. Pumps replaced. W/830711 ltm.
  HINRICHS. G., G'TQOLE. J. Consolidated Edison Co. of New York, Inc. 83/07/11 hVDLEV,T.E. Region 1. Office of Director. 2pp. 19686:097. 24X Fiche: 50-247.83/07/11,8307220555.
- T. Hearing transcripts on non-antitrust matters
- 8307080287 Transcript of ACRS Combined Subcommittees on Indian Point & Reliability & Probabilistic Assessment 830706 meeting in Washington DC. Pp 1-253. Supporting documentation encl.

   ACRS Advisory Committee on Reactor Safeguards. 83/07/04.
  328pp. 19353:122. 24X Fiche:50-247.83/07/06.8307080287.
- 8307250678 Forwards Commission determination statement releasing transcript of 830519 briefing on enforcement matter.
  CHILK.S.J. Office of the Secretary of the Commission. 83/07/19.
  Public Document Branch. 2pp. 19718:106. 24X Fiche: 50-247,83/07/19. 8307250678
- 8307250681 Transcript of Commission 8305J9 closed meeting re-enforcement actions based on emergency planning deficiencies in Washington, DC. Pp. 1-20.
   Commissioners. 83/07/19. 31pp. 19718: 108. 24X Fiche: 50-247, 83/07/19. 8307250678.
- U. Congressional/Executive Correspondence
- 6307140004 Forwards preliminary views on 830623 questions re strike at facility & impact of strike on emergency planning & preparedness.
  PALLADING.N. J. Commissioners. 63/06/28. DTTINGER.R. L. House of Rep., Energy & Commerce. 3pp. 17656:267. 24X Fiche:50-247, 83/06/28,8307140004.
- --8307140007 Requests answers to listed questions re employee strike at facility & impact of strike on emergency planning & preparedness by 830628 ortiNgER.R.L. House of Rep: Energy & Commerce. 83/06/23. PALLADIND.N.J. Commissioners. ip. 19656:270. 24% Fiche 50-247.83/06/28.8307140004.

- B307270054 Responds to B30620 ltr re plant status, addressing special proceeding, emergency preparedness & plant operational status. status. DIRKUS W. J. Office of the Executive Director for Operations. 83/07/13. LUNDINE S. House of Rep. 6pp. 19811:045. 24X Fiche: 50-247,83/07/15,8307270034.
- -8307270055 Requests info re status of facility on behalf of constituent.
  LUNDINE.S. Hause of Rep. 83/06/20. KAMMERER.C.C. Office of
  Cangressional Affairs. 2pp. 19811:050. 24X Fiche:30~247,
  83/07/15,8307270054.
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION: UNIT 3 F. Security, medical, emergency & fire protection plans
- 8307050249 Forwards IE Safeguards Insp Repts 50-010/83-10,50-237/89-15 & 50-249/83-24 on 830923-27.
  HIND,J.A. Region 3, Office of Director. 83/06/23. REED.C.
  Commonwealth Edison Co. 2pp. 19198:354. 24X Fiche:50-010,83/06/23.
- -B307050262 IE Safeguards Insp Repts 50-010/B3-10 50-237/B3-14 & 50-249/B3-14 on B30523-27. Noncompliance noted security violations not reported in required manner or format Details withheld (ref 100FR73.21).
  PIRTLE G.L. Region 3. Office of Director. B3/06/23. 2pp. 19198: 356. 24X Fiche: 50-010, B3/06/23, B307050249.
- B307060186 Forwards objectives & scope of participation proposed for B30913 small-scale emergency exercise.
  BLACKMON.T. G. Commonwealth Edison Co. B3/06/27. HIND, J. Division of Project & Resident Programs. 3pp. 19249:290. 24X
  Fiche: 50-237, B3/06/27, B307060186.
- 8307220425 Ack receipt of 830627 ltr transmitting scope of util participation & objectives for station 830913 emergency exercise.

  PAPERIELLD.C.J. Region 3, Office of Director. 83/07/19. REED.C. Commonwealth Edison Co. 1p. 19687:249. 24X Fiche: 50-237, 83/07/19, 8307220425.
- 8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLO,C. J. Region 3. Office of Director. 83/07/26. REED, C. Commonwealth Edison Co. 10pp. 19789: 018. 24X Fiche: 50-000. 83/07/26. 8307280347.
- G. Adjudicatory correspondence
- 8307120595 Advises that time for Commission to review Director's Decision DD-83-8 expired Commission declined review. Decision became final agency action on 830705. CHILK.S.J. Office of the Secretary of the Commission. 83/07/11. GUIGG.C. Pollution & Environmental Problems, Inc. ip. 17433:076. 24X Fiche: 50-000, 83/07/11. 8307120595.
- H. General correspondence
- B307220430 Comments on Bangor Daily News & MTV repts of NRC order to shut down five facilities for insp of cooling pipes.
  Bubsequent rescission considered under gressure from private owners of plants. Requests stronger enforcement. HEINRIGH.B.C. Affiliation Unknown. B3/07/15. DENTON, H.R. NRC Detailed Affiliation Given. 2pp. 19686:082. 24X
  Fiche: 50-000, 83/07/15, 8307220450. DENTON, H. R. NRG - No
- K. Utility Final Safety Analysis Report (FBAR) & amends
- B307010195 Forwards amends to updated FSAR for facilities. STIEDE.M.L. Commonwealth Edison Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19123:001. 24X Fiche: 50-000, 83/06/29, B307010195.
- ---B307010201 Rev 1 to updated FSAR for Dresden Station 2 & 3. \* Commonwealth Edison Co. B3/06/30. 1pp. 19123:245. 24X Fiche: 50-000, B3/06/29, 8307010195.

- P. Operating license stage documents & correspondence
- 8307070176 Forwards plant-unique analysis repts.Vols 1-7.demonstrating primary containment sys design adequacy & restoration of original design safety margins per NUREG-0661.

  RYBAK.B. Commonwealth Edison Co. 83/06/27 DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp 19548:242. 24X Fiche: 50-600,83/06/27.8307070176.
- --8307070181 Rev O to "Oresden Nuclear Power Station, Units 2 & 3, Plant-Unique Analysis Rept. Vol 1, General Criteria & Loads Methodology, " WISE.R.E., KOST, E.G., MASSEY, J. V. NUTECH Engineers, Inc. CCM--02-041-1 ROO. 83/05/31. 225pp. 1954B: 244. 24X Fiche. 50-000, 83/06/27, 8307070176.
- ---8307070184 Rev O to "Dresden Nuclear Power Station.Units 2 & 3,Plant-Unique Analysis Rept,Vol 2,Suppression Chamber Analysis." HOWARD.G. L., ADAMS.R.H., MCINNES.I.D. NUTECH Engineers, Inc. CCM\*-02-041-2 ROO. 83/05/31.
- --8307070211 Rev O to "Dresden Nuclear Power Station Units 2 & 3,Plant-Unique Analysis Rept.Vol 3,Vent Sys Analysis." SHAMSZAD.P.E., ADAMS,R.H., MCINNES,I.D. NUTECH Engineers, Inc. COM-02-041-3 ROO. 83/05/31. 218pp. 19549:302. 24X Fiche: 50-000, 83/06/27,8307070176.
- ---B307070218 Rev O to "Dresden Nuclear Power Station, Units 2 & 3, Plant~ Unique Analysis Rept, Vol 4, Internal Structures Analysis." TALBOTT, D. C., ADAMS, R. H., MCINNES, I. D. NUTECH Engineers, Inc. COM-02-041-4 ROO. B3/05/31. 33pp. 19550: 160. 24X Fiche: 50-000, B3/06/27, B307070176.
- --B307070223 "Dresden Nuclear Power Station. Units 2 & 9. Plant-Unique Analysis Rept. Vol 5. Safety Relief Valve Discharge Piping Analysis." \* Sargent & Lundy. Inc. 83/06/27. 138pp. 19550: 194. 24X Fiche: 50-000, 83/06/27. 8307070176.
- --8307070239 Rev O to "Dresden Nuclear Power Station, Unit 3, Plant-Unique Analysis Rept. Vol 7, Torus-Attached Piping & Suppression Chamber Penetration Analyses."

  HERLEKAR, A. S., HARLOW, E. V., GAVULA, J. A. NUTECH Engineers, Inc. CDM-02-041-7 ROO. 83/05/31. 173pp. 19551: 144. 24X

  Fiche: 50-000, 83/06/27, 8307070176.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche:50-000.83/07/05.8306270397.
- 8307060329 Generic Ltr 83-27 to all licensess & applicants for operating power reactors & holders of CPs for power reactors re survaillance intervals in STS. Svc list encl.
  EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669: 254. 24X
  Fiche: 50-000,83/07/06,8307060329.
- 8307080306 Forwards safety evaluation supporting util 830425 request to extend deadline for Cycle 8 confirmatory calculations of MAPLHGR fuel rod internal pressure & fuel centerling temp.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 83/07/07. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19350:165. 24X Fiche: 50-249,83/07/07,8307080306.
- --8307080311 Safety evaluation supporting util 830425 request to extend deadline for Cycle 8 confirmatory calculations of MAPLHOR fuel rod internal pressure & fuel conterline temp. \* Office of Nuclear Reactor Regulation Director. 83/07/07. ip. 19350:167. 24X Fiche: 50-249, 83/07/07. B307080306.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. Q. Division of Licensing, 83/07/08. Consolidated Edison Co. of New York, Inc., 38pp. 17669:269. 24X Fiche: 50-000.83/07/08.8307080169.
- 8307130303 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept me Phase I of response to NUREG-0612. "Control of Heavy Loads at Nuclear Plants." Phase I acceptable. CRUTCHFIELD.D. Operating Reactors Branch 5. 83/07/11. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19505:001. 24X Fiche: 50-237.83/07/11. 8307130303.

- --8307130308 Safety evaluation accepting util Phase I response to NUREG-0612. "Control of Heavy Loads at Nuclear Plants." acceptable
  - NUREG-UAI2: "Control or meavy codes at notices clauses; acceptable.

    \* Office of Nuclear Reactor Regulation, Director. B3/07/11. 2pp. 19305:003. 24% Fiche: 50-237.83/07/11.8307130303.
- --8306100146 "Control of Heavy Loads.Comm Ed Dresden Nuclear Power Station.Units 2 & 3," revised technical evaluation rept.
  BOMBERGER.C. Franklin Institute/Franklin Research Center.
  NRC-03-81-130. TER-C5306-330/331 R1. B3/06/08. SINGH.A. NRC No Detailed Affiliation Given. 33pp. 19303:005. 24X
  Fiche: 50-237,83/07/11.8307130303.
- 8307190187 Notifies that Hestinghouse info re environ qualification of electrical equipment detailed in 830513 ltr determined nonproprietary.

  RYBAK, B. Commonwealth Edison Co. 83/07/11. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19630:142, 24X

  Fiche: 50-000, 83/07/11, 8307190187.
- B307190062 Forwards "Dynamic Analysis of Wetwell-to-Drywell Vacuum Breakers" & "Improved Dynamic Vacuum Response," in response to Generic Ltr B3-0B.Results demonstrate that as-built 18-inch A&M vacuum breaker valves meet ASME Cods criteria. RYBAK.B. Commonwealth Edison Co. B3/07/12. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 7pp. 19633:173. 24X Fiche: 50-000.B3/07/12.B307190062.
- 8307220306 Application for amend to License DPR-25 to allow use of eight ASEA-Atom (A-A) control rod blades planned for testing by use during Cycle 9. Blade design performance verification rept withheld (ref 10CFR2.790).

  RYBAK.B. Commonwealth Edison Co. 83/07/18. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19675:286. 24X Fiche:50-249.83/07/18.8307220306.
- --8307220309 Proposed Tech Spec changes re use of ASEA-Atom control rod drive blades. Evaluation of significant hazards consideration & application to withhold blade design performance verification encl.
  \* Commonwealth Edison Co. 83/07/18, 7pp. 19875:288, 24X Fiche: 30-249, 83/07/18, 8307220306.
- 8307220495 Discusses status of proposed mode to automatic depressurization sys,per NUREO-0737. Item II.K. 3. 18. Option 4 re timer installation described in QE BWR Duners Group response,selected for implementation. Mode listed.
  RYBAK, B. Commonwealth Edison Co. 83/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 17685:181. 24X
  Fiche: 90-000/83/07/18, 8307220495.
- B307270398 Forwards notice of consideration of issuance of license amends to opportunity for hearing re 830613 application concerning time limits for inoperability of ECCS ring header snubbers.

  CRUTCHFIELD.D. Operating Reactors Branch 5. 83/07/20. FARRAR.D.L.. Commonwealth Edison Co. 2pp. 19767:308. 24X Fiche: 30-237.83/07/20.8307270398.
- --B307270404 Notice of consideration of issuance of amends to Licenses DPR-19 & DPR-25 & proposed NSHC determination & opportunity for hearing re-snubbers. HAMBACH.T.V. Operating Reactors Branch 5. 83/07/20. 7pp. 19767:310. 24X Fichs: 50-237,83/07/20,8307270398.
- B307250448 Provides commitments on leakage monitoring.Floor drain leakage will be measured once every 4 h when reactor is at operating pressure.NRC will be notified within 24 h if action points exceeded.

  REED.C. Communumealth Edison Co. B3/07/21. Office of the Secretary of the Commission. 2pp. 19701:176. 24X
  Fiche:50~000.83/07/21.8307250448.
- G. Inspection reports, IE Bulletins & correspondence
- 8303240296 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-237/82-20, 30-247/82-21, 50-254/82-16 & 50-255/82-18.

  KEPPLER.J. G. Region 3, Office of Director. 83/05/13, REED.C. Commonwealth Edison Co. 1p. 18548:067. 24% Fiche: 50-000, 83/05/13, 8305240296.
- 8307050249 Forwards IE Bafeguards Insp Repts 50-010/83-10.50-237/83-15 & 30-249/83-24 on 830523-27.

  HIND J.A. Region 3, Defice of Director. 83/06/23. REED.C. Commonwealth Edison Co. 2pp. 19198:354. RAX Fiche: 50-010.83/06/23. 8307050249.

- --8307050262 IE Safeguards Insp Repts 50-010/83-10 50-237/83-14 & 50-249/83-14 on 830523-27. Noncompliance noted: security violations not reported in required manner or format Datails withheld (ref 10CFR73, 21). PIRTLE, G. L., KNICELEY, J. R., CREED, J. R. Region 3, Office of Director. 83/06/23, 2pp. 19198: 356. 24X Fiche: 50-010, 83/06/23, 8307050249.
- 8307040181 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/83-08 & 50-249/83-07.
  HIND, J. A. Division of Radiological & Materials Safety Programs. 83/06/30. REED, C. Commonwealth Edison Co. 1p. 19249:284. 24x Fiche: 50-237,83/06/30,8307060181.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JORBAN,E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- 8304270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list ancl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fichs: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48. "Oaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 28% Fiche:50-000-83/07/14.8306270406.
- 8307280287 Forwards IE Insp Repts 50-010/83-11,50-237/83-17 & 50-249/83-17 on 830606-10 & 17. No noncompliance noted. PAPERIELLO,C. J. Division of Emergency Preparadness & Operational Bupgort 83/07/14. RED.C. Commonwealth Edison Co. 2pp. 19790:209. 24X Fiche: 50-010,83/07/14,8307280287.
- --8307280293 IE Insp Repts 50-010/83-11.50-237/83-19 & 50-249/83-17 on 830606-10 & 17. No noncompliance noted Major areas inspected: records & repts of effluents.effluent control instrumentation & procedure for controlling releases. PAUL.R.A., GREGER.L.R. Region 3, Office of Director. 83/07/13. 7pp. 19790:211. 24X Fiche:50-010,83/07/14,8307280287.
- 8307200207 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/83-06, 50-247/83-05, 50-254/83-04 & 50-265/83-04. BPESBARD, R. L. Division of Engineering. 83/07/15. REED, C. Commonwealth Edison Co. 2pp. 19651:026. 24X Fiche: 50-000, 83/07/15, 8307200207.
- --8307200216 Responds to NRC 830405 ltr re violations noted in IE Insp. Repts 50-237/83-06.50-249/83-05.50-294/83-04 & 50-265/83-04. NUTECH quality engineering procedures & util project unique instructions revised.

  REED.C. Commonwealth Edison Co. 83/06/08. SPESSARD, R. L. Division of Engineering. 131pp. 19651:029. 24X Fiche: 50-000.83/07/15.8307200207.
- 8307220463 Ack receipt of B30714 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-237/83-12. 30-247/83-10. 50-254/83-13 & 50-265/83-11. LITTLE,W.S. Region 3. Dffice of Director. 83/07/19. REED,C. Commonwealth Edison Co. 1p. 19684:325. 24X Fiche:50-000,83/07/19,8307220463.
- --8307220476 Responds to NRC 830616 ltr re-violations noted in IE Insp. Repts 50-237/83-12.50-249/83-10.30-254/83-13 & 50-265/83-11. Corrective actions:existing support configuration for pipe anchor Ri33 modified. FARRAR, D. L. Commonwealth Edison Co. 83/07/14. LITTLE, W. S. Region 3, Office of Director. 4pp. 19684:326. 24% Fiche: 50-000,83/07/19,8307220463.
- #307260559 Requests add1 info by #30804 re extent of intergranular stress corrosion cracking in BMR recirculation sys & RHR sys piping.per IE Bulletins #2-03.Rev I & 83-02.

  EIBENHUT.D. 9. Division of Licensing. #83/07/21 FARRAR.D.L. Commonwealth Edison Co. 5pp. 19732:006. 24X Fiche: 50-249.83/07/21. #8307260559.
- B307280084 Confirms B30726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & wtil.per B30718 discussion. NRRLIUS.C.E. Dévision of Project & Resident Programs. B3/07/22. REED.C.. Commonwealth Edison Co. 2pp. 19791:169. 24X Fiche: 30-000, B3/07/22, B307280084.

- --B307280102 Confirms request for NRC & util senior mot meeting on 830726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.

  REED, C. Commonwealth Edison Co. B3/07/11. DAVIS.B.A. Region 3, Dffice of Director. 1p. 19791:171. 24X Fiche: 50-000, 83/07/22, 8307230064.
- 8307280446 Forwards SALP Repts 50-010/83-13,50-237/83-18 & 50-249/83-16 for Jan-Dec 1982. Endorses that assessments are indicative of util efforts to improve performance at facilities.

  KEPPLER, J. G. Region 3. Office of Director 83/07/25. REED, C. Commonwealth Edison Co. 2pp. 19797: 206. 24X Fiche: 50-010, 83/07/25, 8307280446.
- --8307280450 SALP Repts 50-010/83-13,50-237/83-18 & 50-249/83-16 for Jan-Dec 1982.

  \* Region 3. Office of Director. 83/07/25. 27pp. 19797:208. 24x Fiche: 50-010,83/07/25.8307280446.
- --8307280454 Discusses upcoming 830512 meeting in Glen Ellyn, IL to discuss BALP rept for Jan-Dec 1982.
  HIND.J.A. Division of Radiological & Materials Safety Programs.
  B3/04/22. REED, C. Commonwealth Edison Co. 2pp. 19797: 236 24X
  F1che: 50-010.83/07/25,8307280446.
- --8307280457 Forwards comments on BALP repts based on B30512 meeting. Practice of issuing reduced rating to all five operating plant sites for same alleged corporate weakness tends to overemphasize significance of alleged deficiency. REED.C. Commonwealth Edison Co. B3/05/31. KEPPLER, J. Q. Region 3, Office of Director. 6pp. 19797:238. 24X Fiche: 50-010, B3/07/25, B307280446.
- R. Periodic operating reports & related correspondence
- 8307150194 Monthly operating repts for June 1983 W/830701 ltr. SCHROEDER.S.A., SCOITT.D.J. Commonwealth Edison Co. 83/07/01. Director's Office, Office of Inspection and Enforcement. 24pp. 19531:068. 24X Fiche:50-237.83/07/01.8307150194.
- 8. Reportable occurrences, LERs & related correspondence
- 8307060084 LER 83-023/01T-0: on 830615.while performing LPCI sys valve operability test.containment spray valve 1501-28A failed to open.Caused by faulty auxiliary contact in valve circuitry. Contact replaced.W/830623 ltr. CHRISTEL,B., SCOTT.D.J. Consolidated Edison Co. of New York, Inc. 83/06/23. KEPPLER,J.Q. Region 3. Office of Director. 4pp. 19251:357. 24X Fiche:50-249,83/06/23,8307060084.
- 8307110409 Updated LER 82-048/03x-t: on 82i126, during normal operation, oxygen analyzer unit failed w/high oxygen alarm up in control room. Caused by failed light bulb, tripping photo electric cell. Bulb replaced, W/830623 ltr.
  ATA:H., SCOTT, D.J. Commonwealth Edison Co. 63/06/23. KEPPLER, J. Q. Region 3. Office of Director. 3pp. 19382:283. 24X Fiche: 50-249, 83/06/23, 8307110407.
- 8307200218 LER 83-024/03L-0: on 830615, while performing component cooling syc water pump test-pressure regulating valve MD 3-1501-38 could not be opened past 50% using differential pressure controller. Caused by high resistance. W/830707 ltr. CHRISTEL, B., SCOTT, D.J. Commonwealth Edison Cd. 83/07/07, KEPPLER, J.O. Region 3, Office of Director. 3pp. 19651; 023. 24% Fiche: 50-249, 83/07/07, 8307200218.
- 8307220260 LER 83-025/03L-0: on 830623 & 24.3D main steam line radiation monitor found reading low Caused by weak electrometer tubes. Monitor repaired & calibr. W/630712 ltr. LEAHY, M., SCOTT, D. J. Commonwealth Edison Co. 83/07/12. KEPPLER, J. Q. Region 3, Office of Director. 4pp. 17684:213. 24% Fiche: 50-249, 83/07/12, 8307220260.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.

  LITKA: T. J. Elcen Metal Products Co. 83/07/15. KEPPLER: J. G. Region 3. Office of Director. 26pp. 19686:086. 24X Fiche: 50-000, 83/07/15. 8307220446.

- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F. Security, medical, emergency & fire protection plans
- 8307140170 Discusses understanding of 830325 itr re emergency exercise. Real time manning of emergency operations facility will not be demonstrated during exercise, but will be accomplished at support ctr.

  STORM, J. P. Division of Support Constant of Constant of Support Constant of Constant o
  - se memonsurates contains support ctr.
    stopport ctr.
    STOHR.J.P. Division of Emergency Preparedness & Materials Safety.
    83/04/21. UHRIG.R.E. Florida Power & Light Co. ip. 19523:206.
    24X Fiche: 50-250,83/04/21,8307140170.
- 8307140339 Discusses 1984 full-scale emergency exercise per 830426 meeting Exercise will extend over 3-day period Emergency operations facility will operate at reduced level after first day.

  0'RETLLY, J.P. Region 2, Office of Director. 83/03/26. UMRIG, R.E. Florida Power & Light Co. 2pp. 17523:325. 24X

  Fichs: 50-000, 83/03/26, 8307140339.
- 830714027B Informs that Boise Interagency Fire Ctr contracted to perform surveys of radiofrequency & electromagnetic interference. Assistance requested. VERRELLID.M. Division of Project & Resident Programs. 83/05/31. UHRIO, R. E. Florida Power & Light Co. 22pp. 19522:297. 24X Fiche: 50-000, 83/05/31, 8307140278.
- 8307110357 Releases public version of rev to emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. B3/06/24. Document Management Branch. ip. 19384:196. 24X Fiche:50-250,83/06/24, 8307110357.
- ~-8307110361 Forwards public version of revised emergency plan implementing procedures, including Procedures 20101 re duties of emergency coordinator, 20103 re classification of emergencies & 20104 re emergency roster.

  UNRIG.R.E. Florida Power & Light Co. 83/06/13. 0'REILLY, J. P. Region 2, Office of Director. 1p. 19384:197. 24X
  Fichs: 50-250,83/06/24,8307110357.
- --8307110368 Public version of revised emergency plan implementing procedures, including Procedures 20101 re duties of emergency coordinator, 20103 re classification of emergencies & 20104 re emergency roster.

  HAYB. J. K. Florida Power & Light Co. 83/05/24, 59pp. 19384:148, 24X Fichs: 50-250, 83/06/24, 8307110357.
- B307280098 Forwards add1 info to util 830415 response to NUREG-0737. Suppl 1 re safety parameter display sys.detailed control room design review & Reg Ouide 1.97. UHRIO.R.E. Florida Power & Light Co. 83/07/25. VARGA.S.A. Operating Reactors Branch 1. 4pp. 19791:179. 24% Fiche: 30-230.83/07/25.8307280098.
- J. Insurance & indemnity information
- 8307130187 Forwards Endorsement 67 to NELIA Policy NF-185 & Endorsement 57 to MAELU Policy MF-55.

  DUCK.J.R. Marsh & McLennan, Inc. 83/07/05, SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19465:344. 24X Fiche: 50-250,83/07/05,8307130187.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensess, applicants for GLs & holders of CPs for Westinghouse PWRs re-safety evaluation of "Emergency Response Ouidelines." Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000,83/06/03, 8306060070.
- 6307140065 Concurs in 630516 request for extension until 830627 to submit call—in drills (staff augmentation/time saving measures).

  DANCE.H.C. Division of Project & Resident Programs. 63/06/20. UHRIO.R.E. Florida Power & Light Co. ip. 19514:091. 24X Fichs: 50-000.63/06/20.8307140065.
- 8307060070 Forwards fee for 830603 proposed Class I & IJI amends to Licenses DPR-31 & DPR-41 re optimized fuel assembly & wet annular burnable absorber. UHRIQ:R.E. Florida Power & Light Co. 83/06/30. EISENHUT.D.O. Division of Licensing. ip. 19251:336. 24X Fiche:50-250,83/06/30,8307060070.

- B307060207 Forwards revs to inservice test program for pumps & valves. Inservice test program for valves, w/remote indicators, revised to provide verification that valve operation accurately indicated.

  UHRIO, R.E. Florida Power & Light Co. B3/06/30. VARGA, S. A. Operating Reactors Branch 1. 2pp. 19239:044. 24X

  Fiche: 50-250, 83/06/30, 8307060207.
- --8307060213 Revs to inservice test program for pumps & valves.
  \* Florida Power & Light Co. 83/06/30. 75pp. 19239:046. 24X
  Fiche 50-250.83/06/30.8307060209.
- 8307060216 Notifies that interim core damage assessment guidelines will be provided 830708.per post-THI requirements for post-accident sampling sys.

  UHRIGA.E Florida Power & Light Co. 83/06/30. VARGA.S.A.

  Operating Reactors Branch 1. ip. 19238.351. 24X

  Fiche: 50-230.83/06/30.8307060216.
- 8307250235 Forwards safety evaluation of util 800111.820107 & 0427 responses to NUREO-0737.1tem II. B. 2. 2, "Plant Shielding Mods for Vital Area Access." Guidance & criteria met. VARGA, S. A. Dperating Reactors Branch I. 83/05/30. UHRIG.R. E. Florida Power & Light Co. 4pp. 19725:350. 24X Fiche: 50-250, 83/06/30, 8307250235.
- 8307070084 Advises that mods to reduce potential radiological exposure of control room operator following postulated LOCA complete.

  Add1 work to remove & replace 4-inch blocks will extend completion of block wall repair to 830727.

  URRIG.R.E. Florida Power & Light Co. 83707701. VAROA.S.A. Operating Reactors Branch 1. 2pp. 19269:355. 24X

  Fiche: 50-250.83/07/01.8307070084.
- 8306270397 Generic Ltr 83-26 to all applicants for BLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390.317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list enct. EISENHUT.D.G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 14pp. 19669:234. 24X Fichs: 50-000, 83/07/06, 8307060329.
- 8307120467 Requests meeting to discuss future submittal of Tech Specs & supporting safety analysis to resolve pressurized thermal shock issues for Cycle 7 licensing. Update meeting requested first wk in Aug.
  UHRIO.R.E. Florida Power & Light Co. 83/07/06. EISENHUT.D.G. Division of Licensing. 3pp. 19424:191. 24X Fiche: 50-250,83/07/06.8307120469.
- 8307150434 Forwards request to amend Licenses DPR-31 % DPR-41. Preliminary evaluation determined that proposed amends do not involve significant hazards consideration. W/o encl. MCDONALD.D.G. Operating Reactors Branch 1. 83/07/07. CLARK, U. Florida, State of. 1p. 19540:202. 24X Fiche: 50-250, 83/07/07, 8307130434.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Swc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 30-000,83/07/08,8307080169.
- 8307140198 Forwards interim rept, "Guidelines for Determination of Extent of Core Damage," to be implemented at facilities.
  Rept submitted in response to post-TMI requirements covering post-accident sampling sys.
  UKRIO, R.E. Florida Power & Light Co. 83/07/08, VARGA, S. A. Operating Reactors Branch 1. 7pp. 19522:055. 24X
  Fiche: 50-250,83/07/08,8307140198.
- 8307150216 Rev to 820710 application for amend to Licenses DPR-31 & DPR-41-revising proposed radiological effluent Tech Specs in response to NRC comments. List of examptions from NUREG-0472 requirements and!

  UHRID.R.E. Florida Power & Light Co. 83/07/11. EISENHUT.D. 0. Division of Licensing. 3pp. 19530:274. 24X Fiche: 50-250, 83/07/11, 8307150216.
- --8307150221 Revised pages to proposed radiological effluent Tech Specs. # Florida Power & Light Co. 83/07/11. 64pp. 19530:277. 24X Fiche: 50-250:83/07/11.8307150216.

- 8307190031 Advises that 30-day public notification period required for 830902 applications for amend to Licenses DPR-31 & DPR-41. Bases for 830601 amend issuance is operational flexibility, which is insufficient reason not to require notice. VAROA, S. A. Operating Reactors Branch I. 83/07/11. UHRIG, R. E. Florida Power & Light Co. 2pp. 19636:262. 24% Fiche: 50-250, 83/07/11. 8307190031.
- B30719002B Advises that based on review of B30505 request for deletion of terrestrial & other munitoring programs & 830603 request for optimized fuel assembly Tech Specs two Class III & Class I fees appropriate.
  D1905; R H. License Fee Management Branch. B3/07/12 UHRIG.R.E. Florida Power & Light Co. 1p. 19569:333. 24% Fiche:50-250. 83/07/12, B30719002B.
- B307i90132 Application for amend to Licenses DPR-31 & DPR-41 changing Tack Specs to allow continued operation by accommodating expected increase in inventory of spent fuel assemblies above existing storage capacity.

  URIO.R.E. Florida Power & Light Co. 83/07/15. EIBENHUT.D.G. Division of Licensing. 8pp. 19627:195. 24X Fiche: 50-250, 83/07/15, 8307190132.
- --B307190133 Proposed Tech Specs allowing continued operation by accommodating expected increase in inventory of spent fuel assemblies above capacity of existing storage facility.

  \* Flurida Power & Light Co. B3/07/19. 4pp. 19627: 203. 24% Fiche: 50-250, 83/07/15, 8307190132.
- --8307190134 "Spent Fuel Storage Facility Mod." \* Florida Power & Light Co. 83/07/15. 57pp. 19627: 207. 24X Fiche: 50-250.83/07/15.8307190132.
- B307250173 Forwards Class I & III fees in payment of proposed license amend re spent fuel storage facility expansion. UHRIG.R.E. Florida Power & Light Co. B3/07/19. EISENHUT.D.O. Division of Licensing. 1p. 19706:11B. 24X Fiche: 50-250. B3/07/19. B307250173.
- Q. Inspection reports. IE Bulletins & correspondence
- 8307140229 Requests that liquid samples spixed w/radionuclides be analysed for tritium.Sr-89 & Sr-90 content within 60 days of receipt of spixed samples. Samples will be sent annually as part of routine insp program.
  LEHIS,R.C. Division of Project & Resident Programs. 83/02/07. UHRIG.R.E. Florida Power & Light Co. 1p. 17924:060. 24X Fiche: 50-000, 83/02/07. 8307140227.
- 8307140181 Forwards IE Insp Repts 50-250/83-21 & 50-251/83-21 on 830926-27. No noncompliance noted.

  DANCE, H. C. Division of Project & Resident Programs. 83/06/17. UHRIG, R. E. Florida Power & Light Co. 2pp. 19514: 247. 24X Fiche: 50-250, 83/06/17, 8307140151.
- --8307140136 IE Insp Repts 50-250/83-21 & 50-251/83-21 on 830526-27. No noncompliance notes. Major areas inspected: followup on LERs. LENAHAN, J.J., CUNLON. T. E. Region 2, Office of Director. 83/06/16. 5pp. 19514: 249. 24X Fiche: 50-250, 83/06/17, 8307140151.
- 8307140191 Forwards IE Insp Repts 90-250/83-20 & 50-251/83-20 on 830517-20. No noncompliance noted.

  BANCE, R. C. Division of Project & Resident Programs. 83/06/20. URIO, R. E. Florida Power & Light Co. 2pp. 17522:067. 24X Fiche: 50-250, 83/06/20, 8307140191.
- --8307140208 IE Insp Repts 50-250/83-20 & 50-251/83-20 on 830517-20. No noncompliance noted. Major areas inspected: radioactive effluent releases, reactor coolant quality, testing of filter sys & calibr & functional test of effluent release monitors. HOSEY. C.M. Region 2. Office of Director. 83/04/17. App. 19322: 069. 24X Fiche: 50-250, 83/06/20, 8307140191.
- 8307140083 Forwards IE Insp Repts 50-250/83-12 & 50-251/83-12 on 830601-03.No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/24. UHRIG, R. E. Florida Power & Light Co. 2pp. 19514:183. 24X Fiche: 50-250,83/06/24,8307140083.
- --8307140088 IE Into Regts 50-250/83-12 & 50-251/83-12 on 830401-03 No noncompliance noted Major steas inspected inservice insp. KLEINSBRGE, N. P. , BLAKE, J. J. Region 2. Office of Director. 83/06/22. 5pp. 19514:185. 24X Fiche: 50-250.83/06/24.8307140083.
- 8307140131 Forwards IE Insp Repts 50-250/83-22 & 50-251/83-22 on 830426-0525. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/24. UHRIO, R. E. Floride Power & Light Co. 2pp. 17514; 153. 24X Fiche: 50-250, 83/06/24, 8307140131.

- --8307140141 IE Insp Repts 50-250/83-22 & 50-251/83-22 on 830426-0925. No noncompliance noted Major areas inspected; followup of IE bulletins, maint activities, plant operations, surveillance testing & plant tours.

  VBOT-LOWELL, R., AGLES, J. A. Region 2. Office of Director.

  JULIAN, C. Division of Project & Resident Programs. 83/06/24.

  3pp. 19514:155. 24X Fiche: 50-250.83/06/24,8307140131.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:273. 24X Fiche: 50-000,83/07/11,8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Bnubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering JURDAN.E.L. Division of Emergency Preparedness & Engineering JURDAN.E.L. Division of Emergency Preparedness & Engineering JURDAN.E.L. Division Co. of New York, Inc. 141pp. 19563:153, 24X Fiche: 50-000.B3/07/12.8306270404.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 30-000, B3/07/14, B306270406.
- R. Periodic operating reports & related correspondence
- 9307220329 Monthly operating repts for May 1983.W/830615 ltr. PACE, P. L., WILLIAMS, J. W. Florida Power & Light Co. 83/06/15. Office of Resource Management. Director. 17pp. 19675:132. 24X Fiche: 50-000, 83/06/15, 8307220329.
- S. Reportable occurrences. LERs & related correspondence
- B307150266 LER B3-009/03L-0: on B30610, during operability test of auxiliary feedwater pump A, pump failed to come up to speed & no flow delivered. Caused by failed differential pressure transmitter. Transmitter replaced. W/B30711 ltr. BERRY, Z. E., WILLIAMS, J. W. Florida Power & Light Co. B3/07/11. B7RILLY, J. P. Region 2, Office of Director. 2pp. 19538: 089. 24X Fiche: 50-250, B3/07/11, B307150266.
- 8307220478 LER 83-00B/03L-0; on 830614, conduit for future safety parameter display sys accidentally damaged during installation. One containment spray pump involved. Caused by incorrect drawing. Repairs initiated. W/830711 ltr. BERRY, Z. E., WILLIAMS, J.W. Florida Power & Light Co. 83/07/11. D'REILLY, J.P. Region 2, Office of Director. 3pp. 19485: 189. 24X Fiche: 50-250, 83/07/11, 8307220478.
- B307260134 Recommends mods to proposed AO writeup of 830419 loss of auxiliary feedwater event, per 830624 request.

  DENTON, H.R. Office of Nuclear Reactor Regulation, Director.

  B3707/20. HELTEMES, C. J. Director's Office. ip. 19787; 310. 24X

  Fiche: 50-250, 83/07/20, 8307260134.
- ---8307140009 Forwards draft Commission paper w/proposed FR notice repotential AQ concerning loss of all three auxiliary feedwater pumps at facility. Comments & concurrences requested by 830705.
  HELTEMES.C. J. Director's Office. 83/06/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 10pp. 19787: 311. 24X Fiche: 50-250, 83/07/20, 8307260134.
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
  F. Security, medical, emergency & fire protection plans
- B307140170 Discusses understanding of B30329 ltr re emergency exercise. Real time manning of emergency operations facility will not be demonstrated during exercise but will be accomplished at support ctr.

  BTOHR.J.P. Division of Emergency Preparedness & Materials Safety. B3704/21. UHRIG.R.E. Florida Power & Light Co. 1p. 19523:206. 24X Fiche: 50-250. B3704/21, B307140170.
- 8307140339 Discusses 1784 full-scale emergency exercise per 830426 meeting. Exercise will extend over 3-day period. Emergency operations facility will operate at reduced level after first day.

  O'REILLY, J. F. Region 2, Office of Director. 83/05/26. UHRIG, R. E. Florida Power & Light Co. 2pp. 19523:325. 24X

  Fiche: 50-000:03/05/26.8307140339.

- B30714027B Informs that Boise Interagency Fire Ctr contracted to perform surveys of radiofrequency & electromagnetic interference. Assistance requested.

  VERRELLI,D.M. Division of Project & Resident Programs. B3/05/31.

  URRIG.R.E. Florida Power & Light Co. 22pp. 19522:297. 24X

  Fiche: 50-000; B3/05/31; 830714027B.
- 8307110357 Releases public version of rev to emergency plan implementing procedures.
  FELTON.U.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19384:196. 24X Fiche: 50-290,83/06/24, 8307110357.
- ~-8307i1036i Forwards public version of revised emergency plan implementing procedures, including Procedures 20101 re duties of emergency coordinator, 20103 re classification of emergencies & 20104 re emergency roster.

  UMRIG.R.E. Florida Power & Light Co. 83/06/13. D'REILLY, J.P. Region 2. Office of Director. 1p. 19384:197. 24X Fiche: 50-250, 83/06/24, 8307110337.
- --B30711036B Public version of revised emergency plan implementing procedures including Procedures 20101 re duties of emergency coordinator, 20103 re classification of emergencies & 20104 re emergency roster.

  MAYB.J.K. Florida Pawer & Light Co. B3/05/24. 59pp. 19384:198. 24X Fiche: 50-280.83/06/24. B307110337.
- 8307280098 Forwards addl info to util 830415 response to NUREG-0737, Suppl 1 re safety parameter display sys, detailed control room design review & Reg Guide 1.97.
  UHRIG,R.E. Florida Power & Light Co. 83/07/25. VARGA, S. A. Operating Reactors Branch 1. 4pp. 19791:179. 24% Fiche: 50-250, 83/07/25, 8307280098.

#### J. Insurance & indemnity information

- 8307130187 Forwards Endorsement 67 to NELIA Policy NF-185 & Endorsement 57 to MAELU Policy MF-55.

  DUCK, J. R. Marsh & McLennan, Inc. 83/07/05, SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19465:344. 24x Fiche: 50-250,83/07/05,8307130187.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines."

  Svc list encl.

  EISENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 30-000, 83/06/03. 8306060070.
- 8307140065 Concurs in 830516 request for extension until 830627 to submit call—in drills (staff augmentation/time saving measures).

  DANCE, H. C. Division of Project & Resident Programs. 83/06/20. UHR10, R. E. Florida Power & Light Co. 1p. 19514:091. 24X Fiche: 50-000: 83/06/20, 8307140065.
- 8307050070 Forwards fee for 830503 proposed Class I & III amends to Licenses DPR-31 & DPR-41 re optimized fuel assembly & wet annular burnable absorber.

  URIO, R. E. Florida Power & Light Co. 83/06/30. EISENHUT, D. G. Division of Licensing. ip. 19251:336. 24X Fiche: 50-250,83/06/30,8307050070.
- B307060216 Notifies that interim core damage assessment guidelines will be provided B30706,per post-TM1 requirements for post-accident sampling sys.
  UHRIO,R.E. Florida Power & Light Co. B3/06/30. VARGA,S.A.
  Operating Reactors Branch I. lp. 19238:351. 24X
  Fichs: 50-250,83/06/30,8307060216.
- 8307250235 Forwards safety evaluation of util 800111,820107 & 0427 responses to NUREG-0737. Item II. B. 2.2, "Plant Shielding Mods for Vital Area Access." Quidance & criteria met. VARGA, S. A. Operating Reactors Branch 1. 83/06/30. UHRIG, R. E. Florida Power & Light Co. 4pp. 19725:350. 24X Fiche: 50-250,83/06/30,8307250235.
- B307070084 Advises that mods to reduce potential radiological exposure of control room operator following postulated LOCA complete. Addl work to remove & replace 4-inch blocks will extend completion of block wall repair to B30729.

  UHRIG.R.E. Florida Power & Light Co. B3/07/01. VARGA.S.A. Operating Reactors Branch 1. 2pp. 19269:355. 24X

  Fiche: 50-250,83/07/01.8307070084.

- B306270397 Generic Ltr B3-26 to all applicants for ULs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317 24X Fiche: 50-000, B3/07/05, 8306270397.
- B307110153 Application for amend to License DPR-41, proposing Tech Spec changes for 4 h extension of Limiting Condition for Operation 3.0.1 as result of B30703 incident involving vent valve Leakage on accumulator 4B. Amend requested by B30705. UHRIG.R.E. Florida Power & Light Co. B3/07/05. EISENNUF.D.G. Division of Licensing. 2pp. 19375.032. 24% Fiche: 50-251, B3/07/05, B307110153.
- 8307060329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENRUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:294. 24X Fiche: 50-000.83/07/06.8307060329.
- 8307120469 Requests meeting to discuss future submittal of Tech Specs & supporting safety analysis to resolve pressurized thermal shock issues for Cycle 9 licensing. Update meeting requested first wk in Aug.
  UHR10, R.E. Florida Power & Light Co. 83/07/06. EISENHUT. D. G.
  Division of Licensing. 3pp. 19424:191. 24X Fiche: 50-250.83/07/06.8307120469.
- B307150434 Forwards request to amend Licenses DPR-31 & DFR-41.
  Preliminary evaluation determined that proposed amends do
  not involve significant hazards consideration. M/o enci.
  MCDONALD, D. G. Operating Reactors Branch 1. B3/07/07. CLARK, U.
  Florida, State of. 1p. 19540: 202. 24X Fiche: 50-250, B3/07/07,
  8307150434.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events Evc list encl. EISENHUT.D.G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 830714019B Forwards interim ropt, "Quidelines for Determination of Extent of Core Damage." to be implemented at facilities. Rept submitted in response to post-TMI requirements covering post-accident sampling sys. UHRIO, R.E. Florida Power & Light Co. 83/07/08. VARGA, S. A. Operating Reactors Branch 1. 7pp. 19522:055. 24X Fiche: 50-250, 83/07/08, 8307140198.
- B307130216 Rev to B20910 application for amend to Licenses DPR-31 & DPR-41, revising proposed radiological effluent Tech Specs in response to NRC comments. List of exemptions from NUREG-0472 requirements enci.
  URRIG.R.E. Florida Power & Light Co. B3/07/11. EIBENHUT.D.G. D1/1416n of Licensing. 3pp. 19530:274. 24X Fiche: 50-250, B3/07/11. B307150216.
- --8307150221 Revised pages to proposed radiological effluent Tech Specs. \* Flurida Power & Light Co. 83/07/11. 64pp. 19530:277. 24X Fiche:50-250,83/07/11:8307150216.
- 8307190031 Advises that 30-day public notification period required for 830502 applications for amend to Licenses DPR-31 & DPR-41. Bases for 830401 amend issuance is operational flexibility, which is insufficient reason not to require notice. VAROA, S. A. Operating Reactors Branch 1, 83/07/11. UHRTG, R. E. Fiche: 30-230, 83/07/11, 8307190031.
- 8307190028 Advises that based on review of 830505 request for deletion of terrestrial & other monitoring programs & 830603 request for optimized fuel assembly Tech Specs, two Class III & Class I fees appropriate.

  I fees appropriate.

  101005.R.M. License Fee Management Branch.
  Florida Power & Light Co. 1p. 17569: 333. 24X Fiche: 50-250, 83/07/12, 8307190028.
- B307190132 Application for amend to Licenses DPR-31 & DPR-41 changing Tech Specs to allow continued operation by accommodating expected increase in inventory of spent fuel assemblies above existing storage capacity.

  UHRIQ.R.E. Florida Power & Light Co. B3/07/15. EISENHUT.D.G. Division of Licensing. Bpp. 19827:195. 24X Fiche: 30-250.83/07/15.8307190132.
- --8307190133 Proposed Tech Specs allowing continued operation by accommodating espected increase in inventory of spent fuel assemblies above capacity of existing storage facility.
  4 Florida Power & Light Co. 83/07/15. 4pp. 19627: 203. 24X Fichs: 50-250, 83/07/15.8307190132.

- 8907270173 Forwards Class I & III Fees in payment of proposed license amend re apent fuel storage facility espansion UMRIG.R E. Florida Power & Light Co. 83/07/19 EISENHUT.D.G. Division of Licensing 1p. 19706-118 24X Fiche: 50-250.83/07/19.8337250173
- d Inspection reports, IE Bulletins & correspondence
- B307140227 Requests that liquid samples spiked w/radionuclides be analyzed for tritium.Sr-89 & Sr-90 content within 60 days of receipt of spiked samples Samples will be sent annually as part of routine insp grogram.

  LEMIS.R C Division of Project & Resident Programs. B3/02/07.

  UMFIG.R E Fibrida Power & Light Co. 1p. 19524:080. 24X

  Fiche 30-000.83/02/07.8307140229.
- 8307140151 Forwards IE Insp Repts 50-250/83-21 & 50-251/83-21 on 830725-27 No noncompliance noted. DANCE.M C. DIVISION of Project & Resident Programs. 83/06/17. UMRIGA C. Florida Power & Light Co. 2pp. 19514:247. 24X Fiche 50-230.83/06/17.8307140151.
- --8307140176 IE Insp Repts 50-250/83-21 & 50-251/83-21 on 830526-27. No noncompliance noted Major areas inspected; followup on LERs. LENAMAL J J. CONLON.T.E. Region 2, Office of Director. 83/06/16. Spp. 19314 249. 24X Fiche: 50-230.83/06/17.8307140151.
- E307140191 Forwards IE Insp Repts 50-250/83-20 & 50-251/83-20 on B30517-20. No noncompliance noted.

  DANCE H C Division of Project & Resident Programs. 83/06/20. UHRIG-R E Florida Fower & Light Co 2pp. 19522:067. 24X Fiche 50-250.83/06/20.8307140191.
- ### 24/07/140083 Forwards IE Insp Repts 50-250/83-12 & 50-251/83-12 on ### 633601-03 No noncompliance noted.

  CANCE H C Division of Project & Resident Programs. 83/06/24. U-RIG R E Florida Power & Light Co. 2pp. 17514:183. 24X Fichs: 50-250, 83/06/24, 8307140083.
- E307140131 Forwards IE Insp Repts 50-250/83-22 % 50-251/83-22 on 830426-0525 No noncompliance noted.

  DANCE, M.C. Division of Project & Resident Programs. 83/06/24. UHRIG: # Florida Power & Light Co. 2pp. 19514:153. 24X Fiche 50-250. 83/06/24, 8307140131.

- BE304270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JOHOAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19353:153. 24x Fiche: 50-000, 83/07/12, 8306270404.
- Periodic operating reports & related correspondence
- PACE.P L. WILLIAMS.J.W. Florida Power & Light Co. 83/06/15.

  Office of Resource Management, Director. 17pp. 19675; 132. 24:

- 8307220518 Forwards "Steam Generator Repair Program for Turkey Point Unit 4" Final Radiological Progress Rept 4 for 821010 -830516. UHRIG,R.E. Florida Power & Light Co. 83/07/15. VARGA.S.A. Operating Reactors Branch 1. 1p. 19685: 228. 24X Fiche: 50-251:83/07/15.8307220518.
- --8307220523 "Steam Generator Repair Program for Turkey Point Unit 4." Final Radiological Progress Rept 4 for 821010 - 830514. \* Florida Power & Light Co. 83/07/15. 37pp. 19685:229. 24x Fiche:50-251.83/07/15.8307220518.
- S. Reportable occurrences, LERs & related correspondence
- B307120424 LER 83-004/03L-0: on B30526, valve MDV-4-1405 failed to open during routine test of auxiliary feedwater pump B. Caused by high resistance across contacts inside motor operator. Contacts cleaned & valve tested.
- B307110153 Application for amend to License DPR-41 proposing Tech Bpec changes for 4 h extension of Limiting Condition for Operation 3.0.1 as result of B30705 incident involving vent valve leakage on accumulator 48. Amend requested by B30705. UHRIO.R.E. Florida Power & Light Co. 83/07/05. EIBENHUT, D. O. Division of Licensing. 2pp. 19375:032. 24X Fiche: 50-251, 83/07/05, 8307110153.
- DOCKET 50-292 UNIV. OF NEW MEXICO REBEARCH REACTOR

  R. Periodic operating reports & related correspondence
- 8307290310 "Rept on Facility License R-102, Univ of New Mexico AGN-201M Reactor, Juli 1982 June 1983." W/830715 ltm.
  WHAN, O. A. New Mexico, Univ. of. 83/06/30. Director's Office, Office of Inspection and Enforcement. 3pp. 19701:344. 24X Fiche: 50-252:83/06/30,8307250310.
- V. Operator Examinations
- B307080427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee." Syc list encl. EISENHUT.D. 0. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000,83/07/11,8307080427.
- DOCKET 50-254 GUAD-CITIES STATION. UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8307120197 Forwards exemption from requirements of App R to 10CFR30, Section III.9 re fire protection of safe shutdown capability, in response to 820701 % 0923 requests. VASBALLO, D. B. Operating Reactors Branch 2, 83706/23, FARRAR, D. L. Commonwealth Edison Co. 3pp. 19435:188, 24X Fiche: 50-254, 83/06/23, B307120137,
- --B307120145 Exemption from requirements of App R to 10CFR50, Bection III.0 for fired fire suppression associated w/panels, switchgear & motor control ctrs.
  EISENHUT, D. G. Division of Licensing, B3/06/R3, Commonwealth Edison Co. App. 19435: 191. 24X Fiche: 50-254, B3/06/R3, B307120137.
- B307120062 Releases public version of rev to emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. B3/06/24. Document Management Branch. 1p. 19435:260. 24X Fiche: 30-254, 83/06/24,
- ---8307120068 Public version of revised emergency plan implementing procedures, including Procedures GEP 330-0 re assessment actions & GEP 330-11 re estimation of I-131 release by field team measurements. Revised index encl. GERNER.L., KOVACK, T.J. Commonwealth Edison Co. 83/06/30. App. 17435: 261. 24X Fiche: 50-254, 83/06/24, 8307120062.
- B307260018 Submits supplemental response to NUREQ-0737, Buppl 1 (Generic Street Street) Description of parameter selection criteria to be submitted by B31231. Human factors to safety parameter display says verification to be performed w/verification program. SWARTZ.E.D. Commonwealth Edison Co. B3/07/20. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19727:177. 24X

- B307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLD.C. J. Region 3, Office of Director. 83/07/26. REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 50-000, B3/07/26.8307280347.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010195 Forwards amends to updated FSAR for facilities. STIEDE.W. L. Commonwealth Edison Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19123:001. 24X Fiche: 50-000.83/06/29.8307010195.
- --8307010198 Amend to updated FSAR for Guad Cities 1 % 2. \* Commonwealth Edison Co. 83/06/29. 508pp. 19123:069. 24X Fiche: 50-000, 83/06/29, 8307010195.
- P. Operating license stage documents & correspondence
- 8307250498 Rev 3, to "Process Control Program for Solidification of Radwaste." \* Commonwealth Edison Co. 83/03/31. 9pp. 19701:220. 24X Fiche: 30-254,83/03/31,8307250498.
- 8305240240 Informs that beta spectra measurements will be conducted on 830524 for NRC project, "Beta Particle Measurement & Dosimetry Requirements at NRC-Licensed Facilities." RATHBUN,L. A. Battelle Memorial Institute, Pacific Northwest Laboratory, FIN 9-2448, 83/05/20, KEPPLER, J. C. Region 3, Office of Director. 1p. 18597:337, 24X Fiche: 50-254,83/05/20,8305260240.
- 8307120152 Forwards response to BWR Owners Group study of alternatives to NUREG-0737. Item II.K. 3.18, "Automatic Depressorization Sys Logic Mod." Two of seven alternatives acceptable. Implementation schedule should be provided within 45 days. VASSALLO, D. B. Operating Reactors Branch 2. 83/06/03. FARRAR, D. L. Commonwealth Edison Co. 9pp. 19435:179. 24X Fiche: 50-254,83/06/03. 8307120152.
- 8307140514 Advises that requirements of TMI Item II.K.3.13, "HPCI/RCIC Initiation Level," met. Item resolved.

  VASSALLO.D. B. Operating Reactors Branch 2. 83/06/17. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19527:345. 24X Fiche:50-254,83/06/17,8307140514.
- 8307120125 Forwards confirmatory order re util 810115 & 820316 commitments to install permanent scram discharge sys mods prior to startup after 830901 refueling. Model Tech 8pecs encl as guidance for use in preparing Tech 8pec changes. VASSALLO.D. B. Operating Reactors Branch 2. 83/06/24. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19435:097. 24X Fiche: 50-254, 83/06/24, 8307120125.
- ~~8307120128 Confirmatory order re util 810115 & 820316 commitments to install permanent scram discharge sys mods prior to startup after 840901 refueling.
  EISENHUT, D. G. Division of Licensing. 83/06/24. Commonwealth Edison Co. 35pp. 19435:097. 24X Fiche: 50-254, 83/06/24, 8307120125.
- 8307070176 Forwards plant-unique analysis repts, Vols 1-7, demonstrating primary containment sys design adequacy & restoration of original design safety margins per NUREO-0661. RYBAK. B. Commonwealth Edison Co. 83/06/27. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19548:242. 24X Fiche: 50-000,83/06/27.8307070176.
- --8307180152 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept. Vol 3, Vent Sys Analysis."

  SHAMSZAD, M. ADAMS, R. H. MCINNES, I. D. NUTECH Engineers, Inc. CGM-02-039-3 ROO. 83/05/31. 221pp. 19553:016. 24X Fichs: 50-000, 83/06/27, 8307070176.
- --8307180158 "Quad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept, Vol 4, Internal Structures Analysis." TALBOTT, D. C., ADAMS, R. H., MCINNES, I. D. NUTECH Engineers, Inc. COM-02-039-4 ROO. 83/05/31
- --830718016B "Quad Cities Station Units 1 & 2 Plant Unique Analysis Rept, Vol 5. Safety Relief Valve Discharge Piping Analysis." \* Sargent & Lundy, Inc. 83/06/27. 134pp. 19553:272. 24X Fiche: 50-000.83/06/27,8307070176.

- --8307180179 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept, Vol 6, Unit 1 Torus Attached Piping & Suppression Chamber Penetration Analysis." PANDEY, P., HALLACH, Q., GAVULA, J.A. NUTECH Engineers, Inc. COM-02-039-6 ROO. 83/05/31. 174pp. 19354:046. 24X Fichs: 50-000, 83/06/27, 8307070176.
- --B3071B0138 "Quad Cities Nuclear Power Station Units 1 & 2 Plant-Unique Analysis Rept,Vol 1,General Criteria & Methodology." WISE.R.E., KOBT.E. 0., MASSEY, J. V. NUTECH Engineers, Inc. COM-02-037-1 R00. 83/05/31. 234pp. 19551:317. 24X Fiche:50-000,83/06/27,8307070176.
- ---B307180147 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept.Vol 2, Suppression Chamber Analysis." HUMARD, G. L. ADAMER, H. MCINNES, I. D. NUTECH Engineers, Inc. CUM-02-039-2 ROO. B3/05/31. 185sp. 19552: 191. 24X Fiche: 50-000, B3/06/27, B307070176.
- B307180026 Forwards SER re NUREO-0612, "Control of Heavy Loads" & technical evaluation rept. Phase I acceptable.

  VASBALLO, D. B. Deersting Reactors Branch 2. 83/06/27. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19567:301. 24X Fiche: 50-254,83/06/27,8307180026.
- ~-8307180030 Safety evaluation of util 801222 responses to NUREG-0612, "Control of Heavy Loads." Phase I acceptable.

  \* NRC No Detailed Affiliation Given. 83/06/27. 2pp. 19367:303. 24X Fiche: 50-254,83/06/27,8307180026.
- --B306060295 "Control of Heavy Loads (C-10), Quad Cities Station Units 1 & 2," technical evaluation rept.

  BOHBERGER, C., BARGENT, I. H., Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-386/387. 83/06/01. SINGH, A., CHAN, T. NRC No Detailed Affiliation Given. 31pp. 19567:305. 24X Fiche: 50-254, B3/06/27, B307180026.
- B307200524 Forwards order modifying Bi0113 & B20119 orders reinstallation of plant mods in compliance w/acceptance criteria of NVREG-0661. Completion date extension to Spring 1984 outage, requested in B30615 ltr, granted. VASBALLO, D. B. Operating Reactors Branch 2. B3/06/30, FARRAR D. L. Commonwealth Edison Co. 2pp. 19671:344. 24X Fiche: 50-254, B3/06/30, B307200524.
- --8307200531 Order modifying Bioli3 & B20119 orders re installation of plant mods in compliance w/NUREO-0661 requirements.

  Completion date extended to Spring 1984 refueling outage.

  PURPLE.R.A. Division of Licensing. B3/06/30. Commonwealth

  Edison Co. 4pp. 19671:346. 24X Fiche:50-254,83/06/30.8307200524.
- 8304270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24% Fiche: 30-000, 83/07/05, 8306270397.
- 8307060327 Opneric Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 818.8vc list enci. EISENHUT.D.O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.
- B3070B0169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATW8 events. Svc list encl. EISENHUT, D. O. Division of Licensing. B3/07/OB. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24x Fiche: 50-000.83/07/OS.83070B0169.
- 8307190187 Notifies that Westinghouse info re environ qualification of electrical equipment detailed in 830513 ltr determined nonproprietary.

  RYBAK,B. Commonwealth Edison Co. 83/07/11. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19630:142. 24X Fiche: 50-000.83/07/11.8307190187.
- 8307190062 Forwards "Dynamic Analysis of Wetwell-to-Drywell Vacuum Breakers" & "Improved Dynamic Vacuum Response," in response to Generic Ltr 83-08. Results demonstrate that as-built 18-inch AMM vacuum breaker valves meet ASME Code criteria. RYBAK.B. Commonwealth Edison Co. 83/07/12. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 7pp. 19633:173. 24X Fiche: 59-000, 83/07/12, 8307190062.
- ---B307190067 Rev O to "Dynamic Analysis of Wetwell-to-Drywell Vacuum Breakers for Guad Cities Station Units 1 & 2."

  MGDNKA: A.K.; CHEW.O.P.; MARBIE.H.W. NUTECH Engineers, Inc. COM-08-023 ROO. 81/09/29. 100pp. 19633:180. 24X

  Fiche: 50-000, 83/07/12, 8307190062.

- --8307190074 Rev | to "Improved Dynamic Vacuum Breaker Valve Response for Quad Cities | 1 & 2." BILANIN.A.J. Continuum Dynamics, Inc. 82-7 ROL 82/09/30. 29pp. 19633:292 24X Fiche:50-000.83/07/12.8307190062.
- 8307220495 Discusses status of proposed mods to automatic depressurization sys.per NUREG-0737. Item II. K. 3. 18. Option 4 re timer installation described in GE BHR Owners Group response, selected for implementation. Mods listed. RYBAK.B. Commonwealth Edison Co. 83/07/18. DENTON. H. R. Dffice of Nuclear Reactor Regulation. Director. 2pp. 19685:181. 24X Fiche: 50-600, 83/07/18, 8307220495.
- 8307250448 Provides commitments on leakage monitoring. Floor drain leakage will be measured once every 4 h when reactor is at operating pressure. NRC will be notified within 24 h if action points exceeded.

  REED.C. Commonwealth Edison Co. 83/07/21. Office of the Secretary of the Commission. 2pp. 19701:176. 24X

  Fiche: 50-000.83/07/21,8307250448.

## Q. Inspection reports, IE Bulletins & correspondence

- B305240276 Ack receipt of B30413 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/82-20, 50-249/82-16 & 50-245/82-18.

  KEPPLER.J Q. Region J. Office of Director. B3/05/13. REED.C. Commonwealth Edison Co. Ip. 18548:067. 24X Fiche: 3D-000.83/05/13.8309240276.
- B307060278 Ack receipt of B30603 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-234/80-16 & 30-234/83-12. Response withheld (ref 10CFR2, 790).
  MILLER, J. R. Region 3, Office of Director. 83/06/15. REED, C. Commonwealth Edison Co. 1p. 19237:241. 24X Fiche: 30-254,83/06/15,8307060278.
- 8307250478 Forwards IE Insp Rept 50-254/83-11 on 830311-29 & enforcement conference swamary on 830327 t 0408.

  KEPFLER. J. G. Region 3, Office of Director. 83/06/21. 9°CONNOR, J. J. Commonwealth Edison Co. 2pp. 19701:288. 24% Fiche: 50-254, 83/06/21,8307250478.
- --830725048t IK Insp Rept 50~254/83-11 on 830311-29 & enforcement conference summary on 830327 & 0408. Noncompliance noted: failure to follow shutdown procedures administrative procedures to maintain accurate plant shutdown records. CHRISSOTINDS.N. WALKER.R.D. Region 3. Office of Director. 83/05/10. 7pp. 19701:290. 24X Fiche:50~254.83/06/21.8307250478.
- 8307040044 Responds to IE Bulletin 83-03 Action Item 5 re diesel generator cooling water pump discharge check valve 1-3999-86. Valve found free to swing fully open & closed. Pin area worm. New check valve & gaskets installed.
  BARNES.F.L. Commonwealth Edisun Co. 83/06/28. KEPPLER. J. G. Region 3. Office of Director. 3pp. 19251: 327. 24X Fiche: 50-254, 83/06/28.
- 8307110531 Informs that Action Item 3 of IE Bulletin 83-03 re diesel generator couling water pump completed. New check valves & gaskets installed.

  BARNES, P. L. Commonwealth Edison Co. 83/06/28. KEPPLER, J. G. Regii 3. Office of Director. 3pp. 19380: 086. 24X Fiche: 50-254, 63/06/28, 8307110531
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83~47. "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl.
  TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270 24X Fiche: 50-000, 83/07/14.8306270406.
- 8307200207 Ack receipt of 830500 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/83-06, 50-247/83-05, 50-254/83-04 \$ 50-265/83-04. SPESSARD.R.L. Division of Engineering 83/07/15. REED, C. Commonwealth Edison Co. 2pp. 19651: 026. 24X Fiche: 50-000, 83/07/15, 8307200207.

- --8307200216 Responds to NRC 830405 itr re violations noted in IE Insp Repts 50-237/83-06,50-249/83-05,50-254/83-04 & 50-265/83-04. MUTECH quality engineering pracedures & util project unique instructions revised. REED.C. Commonwealth Edison Co. 83/06/08. SPESSARD.R.L. Division of Engineering. 131pp. 19651:029. 24X Fiche: 50-000,83/07/15,8307200207.
- 8307220463 Ack receipt of B30714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/83-12, 50-2497/83-10, 50-254/83-13 & 50-265/83-11. LITTLE.M.S. Region 3, Office of Director. B3/07/19. REED.C. Commonwealth Edison Co. 1p. 19684: 325. 24X Fiche: 50-000, 83/07/19, 8307220463.
- --8307220476 Responds to NRC 830616 ltr re violations noted in IE Insp. Repts 50-237/83-12.50-249/83-10,50-254/83-13 & 50-265/83-11. Corrective actions: existing support configuration for pipe anchor Ri33 modified. FARRAR, D. L. Commonwealth Edison Co. 83/07/14. LITTLE, W. S. Region 3. Office of Director. 4pp. 19684:326. 24X Fiche: 50-000, 83/07/17, 8307220463.
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util, per 830719 discussion.

  NORELIVS, C. E. Division of Project & Resident Programs. 83/07/22, REED. C. Commonwealth Edison Co. 2pp. 19791:169. 24X

  Fiche: 50-000, 83/07/22, 8307280084.
- --B307280iD2 Confirms request for NRC & util senior mgt meeting on B30726 in Chicago. IL to discuss licenses regulatory performance & relationship w/NRC.

  REED.C. Commonwealth Edison Co. B3/07/11. DAVIS.B.A. Region 3, Office of Director. 1p. 19791:171. 24X Fiche: 50-000.83/07/22, B307280084.
- R. Periodic operating reports & related correspondence
- 8307130219 Monthly operating rept for June 1983.W/830701 ltr. MISAK.A., KALIVIANAKIS.N. Commonwealth Edison Co. 83/07/05. Director's Office of Inspection and Enforcement. 21pp 19508: 029. 24X Fiche: 50-254.83/07/05.8307130219.
- 5. Reportable occurrences. LERs & related correspondence
- 8307110061 LER 83-024/03L-0:on 830610, during monthly exercise GOS 1600-1.Div 1 position indication lights for vacuum breaker i-1601-33F indicated valve not fully closed. Caused by malfunctioning limit suitch. Repairs planned. W/830620 ltr. KIMLER, D. KALIVIANAKIS, N. Commonwealth Edison Co. 83/06/20. KEPPLER, J. G. Region 3. Office of Director. 3pp. 19375; 141. 24X Fiche: 30-254, 83/06/20, 8307110061.
- B307220234 LER 83-025/03L-0:on B30621.maint dept observed valve yoke pulled away from valve bonnet & valve steam bent.Caused by bolts vibrating loose.Bent stem straightened & locking tabs installed on yoke-to-bonnet bolting.W/B30707 ltr. CAREV.G. Cleveland Electric Illuminating Co. KALIVIANAKIS.N. Commonwealth Edison Co. B3/07/07. KEPPLER.J.G. Region 3. Office of Director. 3pp. 19684:242. 24X Fiche:50-254.83/07/07,8307220234.
- B307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.

  LITKA, T. J. Elcen Metal Products Co. B3/07/15. KEPPLER, J. O. Region 3, Office of Director. 26pp. 19686:086. 24X Fiche: 50-000, 83/07/15, 8307220446.

DOCKET SO-255 PALISADES NUCLEAR PLANT

- F. Security, medical, emergency & fire protection plans
- 8307060276 Forwards IE Insp Rept 50-255/83-11 on 830524-27. No noncompliance noted.

  PAPERIELLO.C.J. Region 3, Office of Director. 83/06/20.

  DEMITT.R.B. Consumers Power Co. 2pp. 19238:300, 24X

  Fiche: 90-255,83/06/20,8307060296.
- --B307040303 IE Insp Rept 50-235/83-11 on B30524-27 No noncompliance noted Major areas inspected emergency preparedness exercise & emergency shift augmentation program & observations of key functions.
  PLOSKI,T., SNELL,W., AXELSON,W.L. Region 3, Office of Director. B3/06/18, 21pp. 19238:302. 24% Fiche:50-255,83/06/20,8307060296.

- B307120033 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/06/24. Docum Management Branch. 1p. 19438:342. 24X Fiche:50~295,83/06/24,8307120033.
- --8307120040 Forwards public version of revised emergency plan implementing procedures including Procedures EI-4.1 re technical support ctr.EI-3 re communications & notifications & EI 7.2 re post-accident analysis.

  \* Consumers Power Co. 83/05/23. NRC No Detailed Affiliation Given. 25pp. 19438:343. 24X Fiche:50-255,83/06/24:8307120033.
- --8307120044 Public version of revised emergency plan implementing procedures including Procedures El-4.1 re technical support ctr.EI-3 re communications & notifications & EI-7.2 re post-accident analysis.
  KRICH.R.M. Consumers Power Co. 83/05/23. 227pp. 19439:006. 24X Fiche: 50-255,83/06/24,8307120033.
- 8307120049 Releases public version of rev to emergency plan implementing procedure.
  FELTON, J. M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19439: 359. 24X Fiche: 50-255, 83/06/24, 8307120049.
- --8307120050 Public version of Rev 3 to Emergency Plan Implementing Procedure EI-4.2. "Operational Support Ctr Activation." MONTROBS.R.W. Consumers Power Ca. 82/11/04. 2pp. 19439;360. 24X Fiche: 50-255,83/06/24,8307120049.
- 8307140412 Forwards IE Insp Rept 50-255/83-15 on 830613-17 & notice 307140412 ruines 2 ... of violation. STREETER, J. F. Region 3, Office of Director. 83/06/30. DEWIT Consumers Pawer Co. 2pp. 19521:111. 24K Fiche:50-255,83/06/ 83/06/30. DEWITT, R. B.
- --8307140415 Notice of violation from insp on 830613-17. STREETER, J. F. Region 3, Office of Director. 83/06/ 19521:113. 24X Fiche: 50-255, 83/06/30, 8307140412. 83/06/30. 10.
- ---B307140417 IE Insp Rept 50-255/B3-15 on B30613-17 Noncompliance noted: inadequate procedures for recording pilot cell specific gravity & temp.hydrometer serial number & use of calibr stop watch during emergency generator surveillance. FARRELL.R.E., HAMKING.F.C. Region 3, Office of Director. B3706/30, 4pp. 19521:114, 24X Fiche:50-235.B3/06/30,B307140412.
- 8307080303 Responds to 82i105 ltr transmitting Rev 6 to security plan. Changes acceptable w/exceptions identified in encl.Encl withheld (ref 10CFR73.21).
  CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/07.
  VANDEWALLE, D. J. Consumers Power Co. 2pp. 19350:181. 24X
  Fiche: 50-255, 83/07/07, 8307080303.

### H. General correspondence

- E307210242 Requests available nontechnical info re problems w/
  engineering design/specs & or implementation of engineering
  work for plants.
  WAONER, C. W. Michigan, State of. 83/07/08. KEPPLER, J. G. Region 3,
  Office of Director. ip. 17664:164. 24X Fiche: 50-000, 83/07/08,
  8307210242.
- P. Operating license stage documents & correspondence
- $\Theta307110616$  Monthly notice of amends to OLs involving NSHC issued since CLARK, R. A. Uperating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fiche: 50-000, 83/06/14, 8307110616.
- B307080259 Forwards backfit cost figures for addl seven utils per original B30208 request. Cost figures for 20 utils transmitted B304i1.
  TOURTELLOTTE, J. Regulatory Reform Task Force. B3/06/22. PALLADING, N. Commissioners. 2pp. 19363:313. 24X Fiche: 50-000, 83/06/22, 8307080259.
- ---B307080321 Forwards backfit cost info for facility, per NRC 830208 request. Category 1 imposed by NRC regulations/orders, Category 2 imposed by NRC bulletins & NUREG-0737 requirements & Category 3 initiated by util.

  SELBY. J. D. Consumers Power Co. B3/04/14, TGURTELLOTTE, J. Regulatory Reform Task Force. 5pp. 19363:315. 24X Fiche: 50-000,83/06/22,8307080259.

- 8307060158 Forwards C-E Owners Group program description for resolving TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltr 83-108.per util 830323 Tunips: In response to Generic Let 83-108-per Util 830323 commitment.

  JOHNBON J. D. Consumers Power Co. 83/07/01 E19ENHUT.D.G. Division of Licensing. 7pp. 19250:272. 24% Fiche:50-255.83/07/01, 8307060158.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel inpurity. Svc list encl. EISENHUT.D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- B307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated and Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000.83/07/06.8307060329. Consolidated
- 8307080387 Forwards Amend 77 to License DPR-20 & safety evaluation, Amend permits extension until Aug 1983 refueling outage, to perform 18-month surveillance tests. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/07. VANDEWALLE, D.J. Consumers Power Co. 3pp. 19347:276. 24X Fiche: 50-235,83/07/07.8307080387.
- --B3070B0394 Amend 77 to License DPR-20, permitting extension until Aug 1983 refueling outage to perform 18-month surveillance tests. tests. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/07. 3pp. 19347: 279. 24% Fiche: 50-255, 83/07/07, 8307080387.
- --8307080399 Safety evaluation supporting Amend 77 to License DPR-20.

  \* Office of Nuclear Reactor Regulation, Director. 83/07/07, 3; 19347:282. 24% Fiche:50-255,83/07/07,8307080387.
- 8307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Balem ATMB events. Svc list encl. EIBENHUT.D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X Fiche: 50-000.83/07/08.8307080167.
- B3071301B2 Requests response to three unresolved items in Section 3.1 of NUREO-0612. "Control of Heavy Loads at Nuclear Power Plants." TER-C5306-377 & guidelines for NUREG-0612 compliance forwarded. CRUTCHFIELD.D. Operating Reactors Branch 3. 83/07/14. VANDEMALLE, D. J. Consumers Power Co. 3pp. 17531:013. 24X Fiche: 50-255, 83/07/14, 8307150182.
- G. Inspection reports, IE Bulletins & correspondence
- 8307060276 Forwards IE Insp Rept 50-255/83-11 on 830524-27.No noncompliance noted.

  PAPERIELLO, C. J. Region 3, Office of Director. 83/06/20.

  DEWITT, R. B. Consumers Power Co. 2pp. 19238:300. 24X

  Fiche: 30-235.83/06/20.8307060296.
- --8307060303 IE Insp Rept 50-295/83-ii on 830524-27. No noncompliance noted Major areas inspected emergency preparedness exercise & emergency shift augmentation program & observations of key functions.
  PLOSKI, T., 8NELL, W., AXELSON, W. L.. Region 3, Office of Director. 83/06/18. 21pp. 19238:302. 24X Fiche 50-255.83/06/20,8307060276.
- 8307140412 Forwards IE Insp Rept 50-255/83-15 on 830613-17 & motice of violation.

  STREETER, J. F. Ragion G, Office of Director. 83/06/30. DEWITT.R. 8.
  Consumers Power Co. 2pp. 19521:111. 24% Fiche: 50-255,83/06/30,
  8307140412.
- --8307140415 Notice of violation from insp on 830613-17. STREETER, J. F. Region 3, Office of Director. 83/06/30. 1p. 19521:113. 24% Fiche:50-259,83/06/30,8307140412.
- --8307140417 IE Insp Rept 50-255/83-15 on 830613-17. Noncompliance noted: inadequate procedures for recording pilot cell specific gravity & temp.hydrometer serial number & Use of calibr stop watch during emergency generator surveillance. FARRELL.R.E., HAMKINS,F.C. Region 3. Office of Director, 83/06/30. 4pp. 19521:114. 24X Fiche: 50-255.83/06/30.8307140412.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Dagrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consulidated Edison Co. of New York: Inc. 154pp. 19563:293. 24X Fiche.50-000,83/07/11.8306270401

- 8306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563-153. 24x Fiche: 50-000, 83/07/12. 8306270404.
- 8307200251 Informs of June 1983 insp of valves & controls for engineered safety sys per NRC 791109 order. Insp verified compliance w/Tech Spec limiting conditions for operation requirements.

  JOHNSON, B. D. Consumers Power Co. 83/07/13. KEPPLER, J. G. Region 3, 8307200251.
- 3306270405 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list
- encl.
  TAYLOR, U.M. Division of QA. Safeguards & Inspection Programs (Post 830103). 83/07/14 Consolidated Edison Co. of New York, Inc. 149p. 19715.270. 24X Fiche: 50-000.83/07/14.8306270406.
- l. Periodic operating reports & related correspondence
- 307150124 Monthly operating rept for June 1983 W/830709 ltr. PETERSON, D. A., KENNEDY, D. M. Consumers Power Co. B3/07/09. No Detailed Affilation Given. 5pp. 19535:237. 24X Fithe: 50-255, 83/07/09, 8307150124. NRC -
- Reportable occurrences. LERs & related correspondence
- 307050140 LER B3-D41/01T-0:on 830610, during routine sampling of C safety injection tank T-82C, tank level fell below Tech Spec limit. Caused by refisef valve RV-3161 failure to reset after lifting. Valve will be repaired. N/830623 ltr. JOHNSON, B. D. Consumers Power Co. B3/06/23. KEPPLER, J. G. Region 3, B307050140.
- 80708048) LER 83-042/017-0: on 830531, auto & manual indication lights for FIC-0737A discovered out-rendering CV-0737A inoperable.

  W/830629 ltr.

  JOHNSON, B. D. Consumers Power Co. 83/04/29, KEPPLER, J. G. Region 3, 6307080481.
- 07190012 LER 83-043/03L-0: on 830609, boron contentration of safety injection tank D sample did not reach Tech Spec Limit of 1.720 ppm. Caused by boron dilution due to minor leakage. Primary colant leak rate being monitored W/830708 itr. JOHNSON, B. D. Consumers Power Co. 83/07/08. KEPPLER, J. G. Region diffice of Director. 2pp. 19635: 048. 24% Fiche: 50-255, 83/07/08, 8307190012.
- 07190205 LER B3-044/01T-0: on B30625, during planned power reduction, sample from safety injection tank T-82D showed boron oncentration below Tech Specs. Caused by minor leak past loop chock valve. Valves will be inspected W/80708 ltr. (JCHNSON. B. D. Consumers Power Co. B3/07/08. KEPPLER. J. G. Region 3, 1967190205.
- KET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 Security, medical, emorgency & fire protection plans
- 7140390 Forwards emergency preparedness evaluation rept from ay 1981 Mar 1982 emergency preparedness approxisal. TOHR, J.P. Division of Emergency Preparedness & Naterials Safety, 3/02/07. PARRIS, H.C. Tennessee Valley Authority. 1p. 19529:075. 4x Fiche: 50-259, 83/02/07, 8307140390.
- 307140395 Forwards emergency preparedness evaluation rept, as followed to implementation appraisal. Emergency plan provides adequate planning basis for acceptable state of emergency preparedness.

  PAGAND, F. O. Emergency Preparedness Branch. 82/12/28. STOHR, J. P. Division of Emergency Preparedness & Materials Safety. 1App. 19525: 076. 24X Fiche: 50-259, 83/02/07, 8307140390.
- 140062 Advises that NRR & Region II final decision on 830201 quest to change current fire door insp program to require nthly instead of daily, visual insps & maint insps at—month intervals, expected within 30 days.

  WIS.R.C. Division of Project & Resident Programs. 83/02/17.

  RRIS.H G. Tennessee Valley Authority. 1p. 19514:121. 24X che: 50-259, 83/02/17, 8307140062.

- B307140360 Confirms B30316 telcon between JA Domer & FS Cantrell refire door insp & maint program at facility. Util will continue daily visual insp & semiannual maint insp program of all fire doors as outlined in 810403 ltr.

  LEWIS, R. C. Division of Project & Resident Programs. B3/03/25. PARRIS, H. G. Tennessee Valley Authority. 1p. 19523: 328. 24x Fiche: 50-259, B3/03/25, B307140360.
- 8307200095 Application for amend to License DPR-33 changing Tech Specs for Reload 5 Cycle 6 operation Change reflects mods performed during refueling outage Approval needed by 830929. MILLS,E.M. Tennessee Valley Authority. 83/07/13. DENTON.H.R. Office of Nuclear Reactor Regulation Director. 2pp. 19647:176. 24X Fiche: 50-259, 83/07/13, 8307200075.
- --B307200100 Proposed Tech Spec revs for Reload 5,Cycle 6 operation. \* Fennessee Valley Authority. B3/07/13. 69pp. 19647:178. 24X Fiche: 50-289,B3/07/13:B307200095.
- 8307220528 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations & deviation noted in IE Insp Repts 50-259/83-15.50-260/83-15 & 50-296/83-15. LEMB.R.C. Division of Project & Resident Programs. 83/07/15. PARRIS, H. 6. Tennessee Valley Authority. 1p. 19685:009. 24X Fiche: 50-259, 83/07/15, 8307220528.
- --9307220947 IE Insp Repts 50-259/83-15, 50-260/83-15 & 50-296/83-15 on 830326-0425. Noncompliance noted: failure to foliou procedures for RHR svc water functional test & to conduct insp of RHR svc water air vacuum valves during Unit 2 operating cycle. PAULK, G. L. Region 2. Office of Director. 83/05/10. 7pp. 19685: 020. 24X Fiche: 50-259, 83/07/15, 8307220528.
- 8307250626 Releases public version of revised emergency plan implementing procedures. FELTON,J.M. Division of Rules and Records. 83/07/19, Document Management Branch. 1p. 19717: 200. 24X Fiche: 50-259, 83/07/19, 8307250626.
- --9307250633 Forwards public version of revised emergency plan implementing procedures, including div of nuclear power emergency ctr implementing procedures & Knoxville emergency ctr implementing procedures.

  MILLS.L.M. Tennessee Valley Authority. 83/05/02. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. ip. 19717:20124X Fiche: 50-259, 83/07/19, 8307250626.
- -8307250639 Public version of revised emergency plan implementing procedures, including div of nuclear power emergency ctr implementing procedures & Knoxville emergency ctr implementing procedures.

  \* Duke Power Co. 83/04/18 210pp. 19717:202. 24x Fiche: 50-259, 83/07/19, 8307250626.
- J. Insurance & indemnity information
- 8307130297 Forwards Endorsements 66 & 67 to NELIA Policy NF-198 & Endorsements 55 & 36 to MAELU Policy MF-66. DUCK, J.R. Marsh & McLennan, Inc. 83/07/09. SALTZMAN, J. Assistant Director for State & Licensee Relations. Spp. 19507:339, 24X Fiche: 50-259, 83/07/05, 8307130287.
- 8307200146 Forwards Endorsement 68 to NELIA Policy NF-198 & Endorsement 57 to MAELU Policy MF-46.
  DUCK, J. R. Marsh & McLennan, Inc. 83/07/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19651:008. 24X Ficha: 50-259, 83/07/15, 8307200146.
- P. Operating license stage documents & correspondence
- 8307140150 Forwards safety evaluation of BHR Owners Group response to NUREG-0737, Item II.K. 3.18. "Mod of Automatic Depressurization Sys Logic..." Two acceptable options include elimination of high drywell pressure permissive. VASSALLD.D.B. Operating Reactors Branch 2. 83/06/03. FARRIS.H.O. Tennessee Valley Authority. 2pp. 19529:334. 24X Fiche: 50-259, 83/06/03, 8307140150.
- 9307140193 Forwards safety evaluation concluding requirements of TMI Items II F.1.4. "Containment Pressure Monitor." II.F.1.5. "Containment Water Level Monitor" & II.F.1.6. "Containment Hydrogen Monitor." met. Items resolved. VASSALLO, D. D. Operating Reactors Branch 2. 83/06/16. PARRIS.H. 0. Tennessee Valley Authority. 7pp. 19540:041. 24X Fiche: 50-259.83/06/16.8307140153.
- 8307080259 Forwards backfit cost figures for addl seven utils per original 830208 request. Cost figures for 20 utils transmitted 830411.
  TOURTELLOTTE. J. Regulatory Reform Task Force. 83/06/22.
  PALLADING.N. Commissioners. 2pp. 19363:313. 24X
  Fiche: 50-000, 83/06/22, 8307080259.

- --8307080358 Forwards backfit cost estimates for facilities.per NRC 830315 ltm. Costs do not reflect extending scheduled outages due to backfits & mods.
  PARRIS.H.G. Tennessee Valley Authority. 83/05/02.
  TOURTELLOTTE.J. Regulatory Reform Task Force. 5pp. 19364:009.
  24X Fiche: 50-000, 83/06/22, 8307080259.
- 8307070122 Application for amend to Licenses DPR-33.DPR-52 & DPR-68, requesting changes to Tech Spec Table 3.7.A to reflect correct valve positions for operating pressure suppression head tank sys.dustification encl.No.fees necessary. MILLS.L.M. Tennessee Valley Authority. 83/06/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19294:130. 24X Fiche: 50-257, 83/06/24, 8307070122.
- --8307070124 Proposed changes to Tech Spec Table 3.7. A reflecting correct valve positions for operating pressure suppression head tank sys.

  \* Tennessee Valley Authority. 83/06/24. App. 17274:132. 24X Fiche: 50-259, 83/06/24, 8307070122.
- B307060218 Informs that NUTECH analysis indicated that low-flow control mod & reactor water cleanup sys crosstie mod detailed in NUREG-0619, not required at facility. Vendor rept will be submitted by B30816.
  MILLS,L.M. Tennessee Valley Authority. B3/07/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 1924B:361. 24X Fiche:50-239,83/07/01.8307060218.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. 8vc list encl. EISENHUT. D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05, 8306270397.
- B307210030 Confirms B30701 discussion re processing of B30613 request for license amends modifying required surveillance interval for standby gas treatment sys testing. Notice of consideration of issuance will be issued.

  VASSALLO, D. B. Operating Reactors Branch 2. B3/07/05. PARRIS, H. G. Tennessee Valley Authority. 2pp. 19672:359. 24X
  Fiche: 50-259, B3/07/05, B307210030.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS, 8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 30-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269, 24X Fichs: 50-000, 83/07/08, 8307080169.
- 8307120575 Forwards response to 830511 request for add1 info re NUREG-0737. Item 11. K. 3. 28. "Gualification of Automatic Depressurization Sys (ADS) Accumulators." ADS valves & equipment capable of performing function described in FBAR. MILLS.L.M. Tennessee Valley Authority. 83/07/08. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19433:193. 24X Ficho: 50-259,83/07/08.8307120375.
- B307250578 Submits more recent results of pipe cracking at BWRs to update Table 1 of BECY-83-267.
  DIRCKS,W.J. Office of the Executive Director for Operations, BECY-83-267A. 83/07/11. 4pp. 19716:347. 24X Fiche:50-000-83/07/11.8307250578.
- 8307200099 Application for amend to License DPR-33, changing Tech Specs for Reload 5, Cycle 6 operation. Change reflects mods performed during refueling outage. Approval needed by 830929, MILLB.L.M. Tennessee Valley Authority, 83/07/13, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19647; 176. 24X Fiche: 50-259, 83/07/13, 8307200095.
- --8307200100 Proposed Tech Spec revs for Reload 5,Cycle 6 operation.

  \* Tennesses Valley Authority. 83/07/13. 69pp. 19647:178. 24X
  Fiche: 50-289,83/07/13,8307200095.
- --B307200105 Rev 0 to "Supplemental Reload Licensing Submittal for Browns Ferry, Unit i.Reload 5."
  ELLIOTT.P.E., HILF.C.L., CHARNLEY, J. S. General Electric Co. 22AB559 R00. B3/05/31. 30pp. 19647:247. 24X
  Fiche: 50-259, B3/07/13, B307200095.

- 8307260032 Application for amend to Licenses DPR-33.DPR-32 & DPR-68, revising Tech Specs to clarify plant staffing & propose use of senior reactor operator trained in fuel handling for refueling.

  MILLS,L.M. Tennessee Valley Authority. 83/07/18. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19727:116. 24X Fiche: 50-259.83/07/18.8307260032.
- --8307260041 Proposed revs to Tech Specs, clarifying plant staffing & proposing use of senior reactor operator trained in fuel handling for refueling. Evaluation of significant hazards consideration encl.

  \* Tennessee Valley Authority. 83/07/18. App. 19727:118. 24X Fiche: 50-259.83/07/18.8307260032.
- 8307260270 Forwards NEDO-24056. Rev 1. "LOCA Analysis for Browns Ferry. Unit 1:" to support 830713 amend request. LOCA rept revised to reflect addition of new fuel type & to differentiate between most limiting assumed breaks.

  KAMMER.D. S. Tennessee Valley Authority. 83/07/21. DENTON. H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19726:141. 24X Fiche: 50-259.83/07/21.8307240270.
- --8307260279 Rev 1 to "LOCA Analysis for Browns Ferry,Unit 1."

  \* General Electric Co. NEDD-24056 R01. 83/05/31. 47pp.
  19726:143. 24% Fiche: 50-259,83/07/21,8307260270.
- 8307270109 Forwards results of tests verifying analyses performed to demonstrate adequacy of electrical distribution sys voltages. Measured data not more than 390 below analytically predicted results. Actions complete. KAMMER. D. S. Tennessee Valley Authority. 83/07/22. DENTON. H. R. Office of Nuclear Reactor Regulation. Director. 4pp. 19822:035. 24X Fiche: 50-259, 83/07/22, 8307290109.
- B307290206 Forwards response to B30603 request for add1 info re NVREO-0737. Item II.K.3.18, "Automatic Depressurtization Sys Logic Mod." Proposed changes can be accomplished w/no loss of plant safety factor. Existing sys adequate. KAMMER.D. B. Tennessee Valley Authority. B3/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19821: 144. 24X Fiche: 30~259.83/07/22.8307290206.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140062 Advises that NRR & Region II final decision on 830201 request to change current fire door insp program to require monthly, instead of daily, visual insps & maint insps at 18-month intervals, expected within 30 days.
  LEWIS,R.C. Division of Project & Resident Programs. 83/02/17. PARRIES.H.G. Tennessee Valley Authority. 1p. 19514:121. 24X Fiche: 50-259, 83/02/17, 8307140062.
- B307140340 Confirms B30316 telcon between JA Domer & FS Cantrell re fire door insp & maint program at facility. Util will continue daily visual insp & semiannual maint insp program of all fire doors as outlined in 810403 ltr. LEWIS-R. C. Division of Project & Resident Programs. 83/03/25. PARRIS. H. G. Tennessee Valley Authority. 1p. 19823: 328. 24X Fiche: 50-259, 83/03/25, 8307140340.
- B307140035 Forwards IE Insp Repts 50-259/B3-20,50-260/B3-20 & 50-296/B3-20 on 830524-27. No noncompliance noted. VERRELLI, D. M. Division of Project & Resident Programs. 83/06/16. PARRIS, M. G. Tennessee Valley Authority. 2pp. 19514:211. 24X Fiche: 50-259, B3/06/16, B307140035.
- --8307140041 IE Insp Repts 50-259/83-20.50-260/83-20 & 50-269/83-20 on 830524-27. No noncompliance noted Major areas inspected: inservice insp work & work activities data & evaluations. IE Bulletin 83-02 & licensee event followup. COLEY. J. L. BLAKE, J. J. Region 2. Office of Director 83/06/10. 6pp. 19514:213. 24X Fiche: 50-259,83/06/16.8307140035.
- 8307140046 Forwards IE Insp Repts 50-259/83-21,50-260/83-21 & 50-276/83-21 on 830602-03. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. 83/06/23. PARRIS, H. G. Tennessee Valley Authority. 2pp. 19514: 220. 24X Fiche: 50-259, 83/06/23, 8307140046.
- --8307140053 IE Insp Repts 50-259/83-21.50-260/83-21 & 50-296/83-21 on 830602-03.No noncompliance noted Major areas inspected: licensee program for keeping radiation exposure ALARA. HOBEY, C. M., WRAY, J. R., BARR, K. P. Region 2. Office of Director. 83/06/23. 3pp. 19514:222. 24X Fiche:50-259.83/06/23.8307140046.
- 8307110639 Notification of 830706 meeting w/util in Bethesda,MD to discuss results of licensee insp of recirculation sys piping & proposed analysis & repair program.

  CLARK,D. Operating Reactors Branch 2. 83/06/30. VASSALLO,D.B. Operating Reactors Branch 2. 1p. 19391:358. 24X Fiche:50-259,83/06/30,8307110639.

- 8307220155 Forwards response to IE Bulletin 80-13. "Cracking in Core Spray Spangers " No abnormalities found in core spray 307220135 Formards response to the stand in core sparger of No abnormalities found in core sparger & piping MILLS.LM Tennessee Valley Authority, 83/07/Region 2, Office of Director, 2pp. 19684-076. Fiche 30-259.83/07/08.8307220155 83/07/08. G'REILLY, J.P. 884-076. 24X
- B307220211 Responds to IE Bulletin 80-07 re jet pump beam holddown bolt assemblies. Since assemblies will be replaced during current Cycle 5 outage bulletin no longer applicable. Required insps will be discontinued.

  MILLS.L.M. Tennessee Valley Authority B3/07/08 O'REILLY, J.P. Region 2. Office of Director. 1p. 19684.330. 24X Fichs: 50-259.83/07/08.8307220211.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830163). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563.293. 24X Fiche: 50-000.83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563.153. 24X Fiche:50-000,83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Efficent Releases Radioactive 1-125 & I-131 in Ercess of NRC Limits." Svc 1 .J.M. Division of QA, Safeguards & Inspection Programs (F ) B3/07/14. Consolidated Edison Co. of New York, Inc. 19715: 270. 24X Fiche: 50-000, B3/07/14, B306270406. TAYLOR, J. M. B301031
- 8307220528 Ack receipt of 830701 itr informing NRC of steps taken to correct violations & deviation noted in IE Insp Repts 50-259/83-15.50-260/83-15 & 50-296/83-15. EBMISR C Division of Project & Resident Programs. 83/07/15. PARRIS.H. 0 Tennessee Valley Authority. Ip. 19685:009. 24X Fiche: 50-259,83/07/15.8307220528.
- --8307220933 Responds to NRC 830526 ltr re violations & deviation noted in IE Insp Repts 50-259/83-15.50-260/83-15 & 50-296/83-15. Corrective actions: schedule sys & plant procedures will be revised & mechanical maint instructions will be reviewed. MILESL M. Tennessee Valley Authority. B3/07/701. D'REILLY, J. P. Region 2, Office of Director. Opp. 19683:010. 24X Fiche.50-259,83/07/15,8307220528.
- --9307220538 Forwards IE Insp Repts 50-259/83-15.50-260/83-15 & 50-294/83-15 on 830326-0415 & notice of violation.
  Description of actions to improve effectiveness of mgt control sys re mechanical maint area required LEMIS.R. C. Division of Project & Resident Programs. 83/05/PARRIS.H. G. Tennessee Valley Authority. 2pp. 17685:016.
  Fiche: 50-257, 83/07/15, 8307220528 83/05/26
- --8307220540 Notice of violation from imap on 830326-0425.

  \* Region 2, Office of Director. 83/05/26. ip. 1966 Fiche:50-259.83/07/15,8307220528. 19685: 018 24Y
- --8307220543 Notice of deviation from insp on 830326-0425. Region 2, Office of Director. 83/05/26. 1p. 19685:019. 24X Fiche:50-259.83/07/15.8307220528
- --B307220547 IE Insp Repts 50-259/83-15, 50-260/83-15 & 50-296/83-15 on 830326-0425. Noncompliance noted: failure to follow procedures for RHR syc water functional test & to conduct insp of RHR syc water air vacuum valves during Unit 2 operating cycle. PAULK.G.L. Region 2. Office of Director. CANTRELL.F.S. Division of Project & Resident Programs. 83/05/10. 7pp. 19685:020. 24X Fiche: 50-299, 83/07/15. 8307220528.
- 8307250127 Forwards Rev 3 to integrated schedule re IE Bulletin 80~11. "Masonry Wall Design" mods Rev 4 will be submitted in Jan 1984. Jan 1984. MILLS.L M. Tennessee Valley Authority. 83/07/18. DE Office of Nuclear Reactor Regulation. Director. 12pp. 24X Fiche: 50-259, 83/07/18, 8307250127. DENTON, H. R. 19704: 083
- R. Periodic operating reports & related correspondence
- B307220313 Monthly operating wepts for Mar 1983. THOM.T. Tennessee Valley Authority. 83/04/01. 45pp. 19674:233. 24% Fiche:50-259.83/04/01.8307220313.
- 8307220433 Monthly operating repts for May 1983 W/830610 ltr. THOM.T., COFFEY, J.A. Tennessee Valley Authority 83/06/01. Office of Resource Management, Director. 4ipp. 19687:284. Fiche:50-259,83/06/01,8307220433.

- 5. Reportable occurrences: LERs & related correspondence
- 8307120219 Telecopy RD: on 830613 & 14, train B discovered by operability of standby gas treatment sys trains excellent Specs for approx 6 h. Caused by malfunctioning squared converter. Plant instruction rev in progress. COFFEY. J. A. Tennessee Valley Authority. 83/04/29, Office of Director. 2pp. 19423: 241. 24% Fiche: 50-2: 8307120219.
- 8307120470 LER B3-029/03L-0: on B30604, during standby gas operability test train B found inoperable. Caused by er McDunnel & Miller AF-1 flow switches. Damper 0-65-503 adjusted M/830630 ltr.

  SOLLEY, S. M., OREEN, M. J. Tennossee Valley Authority. O'REILLY, J.P., Region 2, Office of Director. 3pp. 15 Fiche: 50-239, 83/06/30, 8307120470.
- 8307120501 Updated LER 83-007/03X-1: on 830205, following main steam relief valve 1-1-22 failed to close & drywe unidentified leakage exceeded 5 gpm. On 830203, during r heatup: leakage exceeded 5 gpm. WB30630 ltr. HGLDER: E. T., GREEN: H. J. Tennesses Valley Authority. O'REILLY. J. P. Region 2, Office of Director. 18pp. 1 Fiche: 90-259, 83/06/30, 8307120501.
- 8307120544 LER 83-028/03L-0:on 830602, stack gas radiatio RK-90-147 & 148 found inoperable due to sample pump fa Caused by broken glass oil filter boul on sample pump, mechanical failure of pump B. Bowl replaced. W/830630 it BURTON.J.W., GREEN.H.J. Tennessee Valley Authority, 10/REILLY.J.P. Region 2, Office of Director. 3pp. 19-Fiche: 50-259, 83/06/30, 8307120544.
- 8307220266 Telecopy RD 50-259/B3036: an 830703; seven two-Ruck relief valves tested at Wyle Labs for as-found sel pressure failed to lift within allowable range. Caused i evaluation. Valves will be reset & retested. COFFEY. J. A. Tennessee Valley Authority. 83/07/06. Office of Director. 2pp. 19684: 179. 24X Fiche: 50-25; 8307220266.
- 8307110282 PNO-II-B3-053: on B30705, workers removed contressible for perform maint on valve-leaving unguarded a path to reactor containment. Guard observed sleeping at post. Security evaluated incidents during B30706 % 07 in CLARK. K. M. , OILLILAND. J. T. Region 2, Office of Directo 2pp. 19374: 270. 24X Fiche: 50-259, 83/07/08, 8307110292.
- 8307110307 PNO-II-83-052: during insps per IE Bulletin 83-identified in 33 of 91 pipe welds in recirculation sys of 32 pipe welds in RHR sys. Caused by intergranular str corrosion cracking. Evaluation ongoing. CANTRELL.F.S., VERRELLI, D.M. Repion 2, Office of Direc 83/07/08. 1p. 19378:329. R4X Fiche: 50-259, 83/07/08, 8
- 8307220217 LER 83-035/01T-0: on 830614, standby gas treatmer flows adjusted w/faulty instrument readings. Caused by component failure. Instrument repaired & calibr. M/830711 CHAMBERS. 0. T. , GREEN. H. J. Tennessee Valley Authority. O'REILLY, J. P. Region 2. Office of Director. 3pp. 176; Fiche: 50-259, 83/07/11, 8307820217.
- B307220435 LER B3-030/03L-0: on B30612, during refueling out sample pump B tripped making both stack monitoring chant inoperable. Caused by overcurrent. Pump B replaced. Failure being investigated. W/B30711 tr.
  SOLLEY.S.W. OREEN.H.J. Tennessee Valley Authority. B5 O'REILLY.J.P. Region 2. Office of Director. 3pp. 1746 Fiche: 50-259, B3/07/11, B307220435.
- 8307220440 LER 83-032/03L-0: on 830612, during refueling out alarm came in for control bay elevation 393 fire protect panel 1-25-325, zone 14. Caused by power loss to some smok detectors due to losse wires. W/830711 ltr. SGLLEY, S. W., GREEN, H. J. Tennessee Valley Authority, 83 0'REILLY, J. P. Region 2, Office of Director. 3pp. 1968 Fiche: 50-259, 83/07/11, 8307220440.
- 8307220111 Supplemental RO: on 830A04.13.14 & 15 standby gatrain B declared inoperable. Caused by increased damper closure since measurements made in May 1983. Dampers return to preset position.

  GREEN,H. J. Tennessee Valley Authority. 83/07/12. 87RE Region 2. Diffice of Director. App. 19484:043. 24X Fiche: 50-259, 83/07/12, 8307220111.
- B307220529 LEH B3-034/03L-0: on 830613; standby gas treatment inoperable due to heaters being unavailable in automatic caused by incorrect damper adjustment Damper readjusted: W/830712 ltr.
  VAIL.H.M., GREEN.H.J. Tennessee Valley Authority, 83/07 0'REILLY,J.P. Region 2, Office of Director. 3pp. 1768; Fiche: 50-259, 83/07/12, 8307220529.

\*7220544 LER 83-031/03L-0: on 830614, during performance of instrument hecks & observations, nitrogen level transmitter LI-84-2A ound indicating 100%. Caused by leak in sensing line of ransmitter, resulting in false high readings. W/930712 ltr. RBY, B. J. GREEN, H. J. Tennessee Valley Authority. 83/07/12. \*\*YREILLY, J.P. Region 2, Office of Director. 3pp. 19686:038. 24% iche: 50-259, 83/07/12, 8307220544.

7220261 LER 83-036/01T-0: on 830630 during Cycle 5 refueling outage, aven of 13 two-stage relief valves tested for as-found set ressure initially failed to lift within allowable 1% olerance. Cause being evaluated. W/830713 ltr. CRHAM, J. E., OREEN, H. J. Tennessee Valley Authority. 83/07/13. (REILLY, J. P. Region 2, Office of Director. 3pp. 19684:193. 24% iche: 50-259, 83/07/13, 8307220261.

7290230 NPDES noncompliance hotification: on 830619, samples from mergency equipment cooling water sys contained excessive otal residual chlorine concentrations. Caused by misaligned alve in chlorination injection sys.

L-ASHRY, M. T. Tennessee Valley Authority. 83/07/26. 3pp. 9822:028. 24X Fiche: 50-259, 83/07/26, 8307270230.

#### Operator Examinations

7140269 Confirms 830506 telcon re Region II interpretation of edical restrictions explicitly entered on operator & senior perator licenses. Interpretation based on definition in NSI N456-1976 (ANS-3.4). EWIS.R.C. Division of Project & Resident Programs. 83/05/11. ARRIB.H.G. Tennessee Vallug Authority. 2pp. 19522:331. 24X iche: 50-259, 83/05/11, 8307140269.

KET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 Security, medical, emergency & fire protection plans

7140390 Forwards emergency preparedness evaluation rept from ay 1981 - Mar 1982 emergency preparedness appraisal. TOHR, J. P. Division of Emergency Preparedness & Materials Safety. 3/02/07. PARRIS, H. C. Tennessee Valley Authority. 1p. 19525:075. 4X Fiche: 50-259,83/02/07,8307140390.

307140395 Forwards emergency preparedness evaluation rept.as followup to implementation appraisal Emergency plan provides adequate planning basis for acceptable state of emergency preparedness.

PAGAND.F.G. Emergency Preparedness Branch. 82/12/28. STOHR.J.P.
Division of Emergency Preparedness & Materials Safety. 16pp.
19325:076. 24X Fiche: 50-259, 83/02/07, 8307140390.

fi40062 Advises that NRR & Region II final decision on 836201 squest to change current fire door insp program to require anthly instead of daily, visual insps & maint insps at 3-month intervals, expected within 30 days.

EMIS.R.C. Division of Project & Resident Programs. 83/02/17. MRRIS.H.Q. Tennessee Valley Authority. 1p. 17514:121. 24X lche: 50-259, 83/02/17, 8307140062.

7140360 Confirms 830316 telcon between JA Domer & FS Cantrell re tre door insp & maint program at facility.Util will ontinue daily visual insp & semiannual maint insp program all fire doors as outlined in 810403 itr. INTER.C. Division of Project & Resident Programs. 83/03/25. ARRIS.H.G. Tennessee Valley Authority. 1p. 19523:328. 24X..the:50-259.83/03/25.8307140360.

'220528 Ack receipt of 830701 ltr informing NRC of steps taken to prect violations & deviation noted in IE lnsp Repts 1-257/83-15. 50-260/83-15 & 50-276/83-15. KHS.R.C. Division of Project & Resident Programs. 83/07/15. 4RRIS.H.G. Tennessee Valley Authority. Ip. 19685:009. 24X che: 50-259, 83/07/15, 8307220528.

IO7220347 IE Insp Repts 50-259/83-15, 50-260/83-15 & 50-296/83-15 on 830326-0425. Noncompliance noted: Failure to follow procedures for RHR svc water functional test & to conduct insp of RHR svc water air vacuum valves during Unit 2 operating cycle. PAULK, G. L. Region 2, Office of Director. 83/05/10. 7pp. 19685:020. 24X Fiche: 50-259, 83/07/15, 8307220528.

250626 Releases public version of revised emergency plan plementing procedures. LTON.J.M. Division of Rules and Records. 83/07/19. Documagement Branch. 1p. 19717:200. 24X Fiche: 50-259,83/07/19.07250626.

- --8307250633 Forwards public version of revised emergency plan implementing procedures, including div of nuclear power emergency ctr implementing procedures & Knoxville emergency ctr implementing procedures.

  HILLS.L.M. Tennessee Valley Authority. B3/05/02 DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 1p. 19717: 201. 24X Fiche: 50-259, 83/07/19, 8307250626.
- -8307250639 Public version of revised emergency plan implementing procedures, including div of nuclear power emergency ctr implementing procedures & Knoxville emergency ctr implementing procedures.

  4 Duke Power Co. 83/04/18. 210pp. 19717:202. 24X Fiche: 50-299, 83/07/19, 8307250626
- J. Insurance & indemnity information
- 8307130257 Forwards Endorsements 66 % 67 to NELIA Palicy NF-198 % Endorsements 35 % 56 to MAELU Policy MF-66. DUCK. J. R. Harsh & McLennan, Inc. 83/07/05. SALTZMAN. J. Assistant Director for State & Licensee Relations. 5pp. 19507:339. 24X Fiche: 50-259,83/07/05,8307130257.
- 8307200146 Forwards Endorsement 68 to NELIA Policy NF-198 & Endorsement 107200143 FBTWARDS ENGINEERING OF THE TOTAL STATES OF THE STATES OF THE
- P. Operating license stage documents & correspondence
- 8307140150 Forwards safety evaluation of BMR Owners Group response to NVREG-0737. Item II. K. 3. 18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO.D. B. Operating Reactors Branch 2. 83706/03. PARRIS. H. G. Tennessee Valley Authority. 2pp. 17529: 334. 24X Fiche: 50-259.83706/03.8307140150.
- 8307140193 Forwards safety evaluation concluding requirements of TMI Items II.F. 1.4, "Containment Pressure Monitor:" II.F. 1.5, "Containment Water Level Monitor:" & II.F. 1.6, "Containment Hydragen Monitor:" met Items resolved. VASSALLO, D.B. Operating Reactors Branch 2. 83/06/16. PARRIS, H. G. Tennessee Valley Authority. 7pp. 19540:041. 24X Fiche: 80-259, 83/06/16, 8307140153.
- 8307080259 Forwards backfit cost figures for add1 seven utils per original 830208 request Cost figures for 20 utils transmitted 830411.
  TOURTELLOTTE, J. Regulatory Reform Task Force. 83/06/22.
  PALLADIND, N. Commissioners. 2pp. 19363:313. 24X
  Fiche: 50-000:83/06/22,8307080259.
- --8307080358 Forwards backfit cost estimates for facilities, per NRC 830315 ltm. Costs do not reflect extending scheduled outages due to backfits & meds. PARRIS.H.O. Tennessee Valley Authority. 83/05/02. TOURTELLOTTE, J. Regulatory Reform Task Force. Spp. 19364:009. 24X Fiche: 30-000, 83/06/22, 8307080239.
- 8307070122 Application for amend to Licenses DPR-33, DPR-52 & DPR-48, requesting changes to Tech Spec Table 3.7. A to reflect correct valve positions for operating pressure suppression head tank sys. Justification encl. No fees necessary.

  MILLS, L. M. Tennessee Valley Authority. 83706/24. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19294: 130. 24% Fiche: 50-259, 83706/24, 8307070122.
- --8307070124 Proposed changes to Tech Spec Table 3.7. A reflecting correct valve positions for operating pressure suppression head tank sys.

  \* Tennesses Valley Authority. 83/06/24. 6pp. 19294:132. 24X fiche: 50-259.83/06/24.8307070122.
- 8307070079 Confirms understanding reached during 830224 joint TVA/Mestinghouse demo licensing meeting re licensing submittals for QUAD+ demonstration assemblies for NRC review of Cycle 6 reload.
  RAME, E. P. Westinghouse Electric Corp. 83/06/27. EISENHUT, D. Q. Division of Licensing. ip. 19293:137. 24X Fiche: 30-260,83/06/27,8307070079.
- 8307060218 Informs that NUTECH analysis indicated that low-flow control mod & reactor water cleanup sys crosstie mod detailed in NUREQ-0619, not required at facility. Vendor rept will be submitted by 830816.

  HILLS.I. M. Tennesse Valley Authority. 83/07/01. DENFON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19248:361. 24X Fiche: 50-259, 83/07/01. 8307060218.

- 8306270397 Generic Ltr 83-2b to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENVILLE D Division of Licensing 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp 19390-317 24X Fiche: 50-000,83/07/05,8306270397.
- 8307210030 Confirms 830701 discussion re-processing of 830613 request for license amends modifying required surveillance interval for standby gas treatment sys testing. Notice of consideration of issuance will be issued VASSALLO.D.B. Operating Reactors Branch 2. 83/07/05. PARRIS.H.O. Tennessee Valley Authority 2pp. 19672-359. 24X Fiche: 50-259. 83/07/05. 8307210030
- B307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. 8vc list encl. EISEMHUT, D. G. Division of Licensing 83/G7/08. Consolidated Edison Co of New York, Inc. 38pp. 19669: 269. 24X Fiche: 50-000.83/07/08.8307080169.
- 8307120375 Forwards response to 830511 request for add1 info re NUREG-0737. Item J1. K. 3. 28, "Qualification of Automatic Depressurization Sys (ADS) Accumulators." ADS valves & equipment capable of performing function described in FSAR. MILLSL. M. Tennessee Valley Authority. 83/07/08. DENTON. H. R. Office of Nuclear Reactor Regulation. Director. 3pp. 19433: 193. 24X Fiche: 50-259, 83/07/08, 8307120575.
- 8307260032 Application for amend to licenses DPR-33, DPR-52 & DPR-68, revising Tech Specs to clarify plant staffing & propose use of senior reactor operator trained in fuel handling for refueling.

  MILLS,L.M. Tennessee Valley Authority. 83/07/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727; 116. 24X Fiche: 30-259, 83/07/18, 8307260032
- --8307260041 Proposed rays to Tech Specs, clarifying plant staffing & proposing use of senior reactor operator trained in fuel handling for refueling Evaluation of significant hazards consideration encl \* Tennessee Valley Authorsty. 83/07/18. App. 19727:118. 24X Fiche: 50-259, 83/07/18, 8307260032.
- 8307290109 Forwards results of tests verifying analyses performed to demonstrate adequacy of electrical distribution sys voltages. Measured data not more than 390 below analytically predicted results. Actions complete.

  KAMMER: D.S. Tennessee Valley Authority. 89/07/22 DENTON. H. R. Diffice of Nuclear Reactor Regulation. Director 4pp. 19822:035. 24X Fiche: 50-259, 83/07/22, 8307290109.
- B307290206 Forwards response to B30603 request for add1 info re NUREO-0737. Item 11 K. 3.18. "Automatic Depressurization Sys Logic Mod." Proposed changes can be accomplished w/no loss of plant safety factor. Existing sys adequate. KAMMER.D. 5. Tennessee Valley Authority 63/07/22. DENTON.M.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19821: 144. 24% Fiche: 50-259, 83/07/22, 8307290206
- G. Inspection reports, IE Bulletins & correspondence
- 8307140062 Advises that NRR & Region El Final decision on 830201 request to change current fire door insp program to require monthly, instead of daily, visual insps & maint insps at 18-month intervals, expected within 30 days.
  LEWIS.R C. Division of Project & Resident Programs 83/02/17. PARRIS.H.O Tennessee Valley Authority 1p 19914: 121. 24X Fiche: 50-259, 63/02/17. 8307140062
- 8307140360 Confirms 830316 telcon between JA Domer & FS Cantreli refire door insp & maint program at facility. Util will continue delly visual insp & semiannual maint insp program of all fire doors as outlined in 810403 ltr.

  LEWIS R. C. Division of Project & Resident Programs. 83/03/25, PARRISH 6. Tennessee Valley Authority 1p. 19523-328. 24X Fiche: 50-259, 83/03/25, 8307140360.

- --8307140041 IE Insp Repts 50-259/83-20.50-260/83-20 & 50-269/83-20 on 830524-27 No noncompliance noted Major areas inspected: inservice insp work & work activities, data & evaluations, IE Bulletin 83-02 & licensee event followup. COLEY, J. L., BLAKE, J. J. Region 2. Office of Director. 83/06/10. 6pp. 19514:213. 24X Fiche: 50-259.83/06/16.8307140035.
- 8307140046 Forwards IE Insp Repts 50-259/83-21,50-260/83-21 & 50-296/83-21 on 830602-03. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. 83/06/23. PARRIS.H. G. Tonnessee Valley Authority. 2pp. 19514: 220. 24X Fiche: 50-259, 83/06/23, 8307140046.
- --8307140033 IE Insp Repts 50-259/83-21.50-260/83-21 & 50-276/83-21 on 830602-03. No noncompliance noted Major areas inspected: Licansee program for keeping radiation exposure ALARA. HUSELY.C.M., MRAY.U.R., BARR.K.P. Region 2, Office of Director. 83/06/23. 3pp. 19314:222. 24X Fiche: 50-259.83/06/23,8307140046.
- 8307110639 Notification of B30706 meeting w/util in Bethesda, MD to discuss results of licensee insp of recirculation sys piping & proposed analysis & repair program. CLARK.D. Dperating Reactors Branch 2. B3/06/30. VASSALLO, D. B. Operating Reactors Branch 2. 19. 19391: 35B. 24X Fiche: 50-257, 83/06/30, B307110639.
- 8304270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. UCRPANEE. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:273. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48. "Oascous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 11489. 19715:270. 24X Fiche: 50-000. 83/07/14. 8306270406.
- 830722052B Ack raceipt of 830701 ltr informing NRC of steps taken to correct violations & deviation noted in IE Insp Repts 30-259/83-15. 50-260/83-15 & 50-296/83-15. LEWIS.R.C. Division of Project & Resident Programs. 83/07/15. PARRIS.H.G. Tannessee Valley Authority. 1p. 19685:009. 24X Fiche: 30-259/83/07/15,830722052B.
- ~-B307220533 Responds to NRC 830526 ltr re violations & deviation noted in IE Insp Repts 50-259/83-15,50-260/B3-15 & 50-276/83-15. Corrective actions: schedule sys & plant procedures will be revised & mechanical maint instructions will be revised & mechanical maint instructions will be revised. MILLS-L.M. Tennessee Valley Authority. B3/07/01. G'REILLY, J. P. Region 2. Dffice of Director. 6pp. 19685:010. 24X Fiche: 50-259.83/07/15.8307220528.
- --8307220538 Forwards IE Insp Repts 50-259/83-15,50-260/83-15 & 50-296/83-15 on 830326-0415 & notice of violation. Description of actions to improve effectiveness of mgt control sys re mechanical maint area required. LEHIS.R.C. Division of Project & Resident Programs. 83/05/26. PARRIS.H.G. Tennessee Valley Authority. 2pp. 19685:016. 24X Fiche: 50-259,83/07/15,8307220528.
- --8307220540 Notice of violation from insp on 830326-0425. + Region 2, Office of Director. 83/05/26. ip. 19685:018. 24X Fiche: 50-259, 83/07/15, 8307220528.
- --8307220543 Notice of deviation from insp on 830326-0425. \* Region 2, Office of Director. 83/05/26. 1p. 17685:019. 24X Fiche: 50-259, 83/07/15, 8307220528.
- --8307220547 IE Insp Repts 50-259/83-15, 50-260/83-15 & 50-296/83-15 on 830326-0425. Noncompliance noted: failure to follow procedures for RHR sec water functional test & to conduct insp of RHR sec water air vacuum valves during Unit 2 operating cycle. PAULK-6 L. Region 2. Office of Director. CANTRELL-F.S. Division of Project & Resident Programs. 83/05/10. 7pp. 19685:020. 24X Fiche 50-259,83/07/15,8307220528.
- 8307250127 Forwards Rev 3 to integrated schedule re IE Bulletin 80-11, "Masonry Wall Design" mods.Rev 4 will be submitted in Jan 1984 MILLS.L.M. Tennessee Valley Authority. 83/07/18. DENTON.H.R. Dffice of Nuclear Reactor Regulation. Director. 12pp. 19704:083. 24X Fiche.50-259.83/07/18.8307250127.

- R. Periodic operating reports & related correspondence
- 8307220313 Monthly operating repts for Mar 1983. THOM.T. Tennessee Valley Authority. 83/04/01. 45pp. 19674:233. 24X Fiche: 50-269,83/04/01.8307220313.
- 8307220433 Monthly operating repts for May 1983.W/830610 ltr.
  THOM.T. COFFEY, J. A. Tennessee Valley Authority. 83/06/01.
  Office of Resource Management, Director. 4(pp. 19687:284, 24X
  Fiche: 50-259,83/06/01,8307220433.
- S. Reportable occurrences, LERs & related correspondence
- 8307120091 LER 83-031/3L-0: on 830605, drywell leak detection radiation monitor RM-90-236 sample pump tripped. Caused by blown fuse. Fuse raplaced & CAM indine channel found inoperable. Indine channel repaired. W/830701 ltr. NORMODD, D. W., or GREEN, H. J. Tennessee Valley Authority. 83/07/01. O'REILLY, J. P. Region 2, Office of Director. 3pp. 19423: 041. 24X Fiche: 50-260, 83/07/01, 8307120091.
- 8307120418 LER 83-030/03L-0: on 830407, torus exhaust valve FCV-64-34 bypass to standby gas treatment sys failed to operate within 5 s time limit. Caused by indicating limit switches being out of adjustment. Switches adjusted. W/830706 ltr.

  HENRY, G. D.: GREEN, H. J. Tennessee Valley Authority. 83/07/06.

  G'REILLY, J. P. Region 2, Office of Director. 3pp. 19425: 079. 24X Fiche: 50-260, 83/07/06, 8307120418.
- 8307150021 LER 83-032/03L-0: on 830610, number of offsite power sources available reduced to one when main transformer 2B removed from svc for maint. Caused by inadequate brazing of low voltage coil connections. Connections repaired. W/830707 ltr. VAIL, H. W., GREEN, H. Tennessee Valley Authority, 83/07/07. O'REILLY, J. P. Region 2, Office of Director. 3pp. 17548:203. 24X Fiche: 50-260, 83/07/07, 8307150021.
- 8307220229 LER 83-034/03L-0: on 830615, during normal operation, HPCI sys declared inoperable. Caused by blown inverter fuse F1. Fuse replaced. Failure considered random. W/830713 ltr. CARTER, S., OREEN, H. J. Tennessee Valley Authority. 83/07/13. D'REILLY, J. P. Region 2, Diffice of Director. 3pp. 19484: 238. 24X Fiche: 50-260, 83/07/13, 8307220229.
- 8307220268 LER 83-033/03i.-0: on 8306i4, following rod adjustment & preconditioning during normal operation.core max fraction of limiting power density & CMAPR greater than Tech Spec limits. Caused by xenon transient. Flow reduced. W/8307i3 ltr. POPPELL.F. S. oREEN. H. J. Tennessee Valley Authority. 83/07/13. O'REILLY, J. P. Region 2, Office of Director. 3pp. 19684: 254. 24X Fiche: 50-240, 83/07/13, 8307220268.
- 8307260564 LER 83-035/03L-0: on 830621; during local power range monitor calibr, calculated R factor, MAPLHOR & linear heat generation rate limits exceeded, Caused by uncalibr range monitor distribution due to sat up of new rod pattern, M/830719 ltr. HENRY, G. D., OREEN, H. J. Tennessee Valley Authority. 83/07/19. 074E1LLY, J. P. Region R. Office of Director. 3pp. 19732: 002, 24X Fiche: 50-260, 83/07/19, 8307260364.
- 8307290230 NPDES noncompliance notification: on 830419, samples from emergency equipment cooling water sys contained excessive total residual chlorine concentrations. Caused by misaligned valve in chlorination injection sys.

  EL-ABHRY.M.T. Tennessee Valley Authority. 83/07/26, 3pp. 19822:028. 24X Fiche: 80-259, 83/07/26, 8307290230.

#### V. Operator Examinations

- 8307140269 Confirms 830506 telcon re Region II interpretation of medical restrictions explicitly entered on operator & senior operator licenses, Interpretation based on definition in ANGI N436-1976 (ANB-3.4).

  LEWIG.R. C. Division of Project & Resident Programs. 83/05/11. PARRIES.H. G. Tennessee Valley Authority. 2pp 19322:331. 24: Fiche: 50-259, 83/05/11, 8307140269.
- DOCKET 50-261 H. B. ROBINSON PLANT, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8307180090 Forwards IE Bafeguards Insp Rept 50-261/83-19 on 830620-24 & notice of violation. Corrective actions to prevent recurrence completed prior to conclusion of insp. Notice of violation & insp rept datails withheld (ref 10CFR73.21).

  VERRELLI,D. Division of Project & Resident Programs. 83/07/13. UTLEY,E.E. Carolina Power & Light Co. 2pp. 19556:328, 24X Fiche:50-261,83/07/13,8307180090.

- --8307180094 IE Safeguards Insp Rept 50-261/83-19 on 830620-24.
  Noncompliance noted in area of access controls Details withheld (ref 10CFR73.21).
  TOBIN.H.J. Region 2. Office of Director. MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety. 83/07/11. 1p. 19356: 330. 24X Fiche: 50-261,83/07/13,8307180090.
- B307290500 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19721:100. 24X Fiche: 50-261,83/07/19, 8307250500.
- --8307250504 Forwards public version of revised emergency glan implementing procedures, including Procedures PEP-2. 3 reemergency control alert.PEP-2. 5 reemergency control general emergency & PEP-2. 6. 21 reemergency communicator. ZIMMERMAN, S. R. Carolina Power & Light Co. 63/06/23. 0/8E1LLY, J.P. Region 2. Office of Director. lp. 19721:101. 24X Fiche: 50-261,83/07/19,8307250500.
- --8307250510 Public version of revised emergency plan implementing procedures, including Procedures PEP-2.3 re emergency control alert. PEP-2.5 re emergency control general emergency & PEP-2.6.21 re emergency communication.
  ZIMMERMAN.9.R. Carolina Power & Light Co. 83/06/14. 27pp. 19721:102. 24X Fiche: 50-261.83/07/19.8307230500.
- 9. Adjudicatory correspondence
- 8307050231 Response to interrogatories & requests for documents.Related correspondence.
  MATTHEMS.B.A. Hartsville Group. B3/06/27. Office of the Executive Legal Director. 8pp. 19198:335. 24X
  Fiche: 50-261.83/06/27.8307050231.
- --8307050234 Response to first set of interrogatories. Affidavit of Svc encl. MATTHEWS, B. A. Hertsville Group. 83/06/27. Carolina Power & Light Co. App. 19198:343. 24% Fiche: 50-261,83/06/27,8307050231.
- B307060191 Answers to first set of interrogatories & requests to produce documents re administrative organization. Cartificate of Bvc encl. Related correspondence. COATS,R.M., HILBON,L.B., DANKB,H.R. Carolina Power & Light Co. B3/06/30. Hartsville Group. 110pp. 19249:071. 24X Fiche: 50-261.83/06/30, B307060191.
- 8307060207 Forwards objections to Hartsville Group first set of interrogatories & requests to produce Svc list encl.

  TROWRENIOGE.O.F. Shaw. Fittman. Potts & Trowbridge. TROWRENDOE.O.F.
  Carolina Power & Light Co. 83/06/30. MARQULIES,M.B., KLINE,J.R.,

  HETRICK.D.L. Atomic Safety and Licensing Board Panel. 3pp.

  19249:037. 24X Fiche: 50-261, 83/06/30, 8307060207.
- --8307060212 Objections to Hartville Group first set of interrogatories & requests to produce Certificate of Svc enc1.

  TROHBRIDGE.G.F. Carolina Power & Light Co. TROHBRIDGE.G.F. Shaw, Pittman, Potts & Trowbridge. 83/06/30. Atomic Safety and Licensing Board Panel. 12pp. 19249:040. 24X
  Fiche: 50-261,83/06/30,8307060207.
- 8307110037 Response to interrogatories, Prof qualifications & Certificate of Svc encl.
  LOIS.L. Core Performance Brench. VIBSING, G., REGUA, G. Operating Reactors Branch 1, 83/07/07. Hartsville Group, 97pp, 19374:084.
  24X Fiche: 50-261,83/07/07,8307110037.
- 8307150346 Motion to compel applicant responses to interrogetories & requests to produce documents. Util objections assert numerous insubstantial & unwarranted objections. Affidavit of Svc encl.
  MATTHEMS.B.A. Hartsville Group. 83/07/11. Atomic Safety and Licensing Board Panel. 22pp. 19538:305. 24X Fiche: 50-261.83/07/11, 8307150346.
- 8307170274 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  TRIUBRIDGE, O. F. Shaw. Pittman. Potts & Troubridge. 83/07/13.
  MARQULIEG.M. B., KLINEJ.J.R., HETRICK, D.L., Atomic Bafety and Licensing Board Panel. 1p. 17641:304. 24X Fiche: 50-261.83/07/13.83071702744.
- --8307190299 Notifies of employment at law firm VR Harding will not participate in any case pending before NRC. Svc list encl. HARDING: V.R. Shaw. Pittman. Potts & Troubridge. 83/07/13. MARGULIES, M.B., KLINE, J.R., HETRICK, J.R. Atomic Safety and Licensing Board Panel. 3pp. 19641:305. 24% Fiche: 50~261, 83/07/13,8307190294.

- 8307220352 Request for extension until 830815 to file status rept on proceeding. Hearing cannot be held in Sept 1983 since NRC has not issued DES or safety evaluation. Hartsville Group & util are to confer on interrogatories. Certificate of Svc encl.
  TROMBRIDGE.G.F. Carolina Power & Light Cd. TROMBRIDGE.G.F. Shaw. Pittman, Potts & Troubridge. 83/07/20. Abonic Safety and Licensing Board Panel. Spp. 19676:093. 24X Fiche: 50-261,83/07/20,8307220352.
- 8307220353 Request to extend until 830815 filing date for responding to Hartsville Group 830711 motion to compel applicant response to Hartsville 830516 interrogatories. Applicant & Hartsville are to discuss motions. Certificate of Svc enct. ROUMBIDGE. G. F. Carolina Power & Light Co. TROWBIDGE. G. F. Shaw. Pittman, Potts & Trowbridge. 83/07/20. Atomic Safety and Licensing Board Panel. 5pp. 19676:088. 24% Fiche: 50-261.83/07/20. 830722053.
- 8307250290 Suppl to answers to Interrogatory 1-35.Certificate of Syc encl. 21MMERHAN, S. R. Carolina Power & Light Co. 83/07/20, Hartsville Group. 4pp. 19705;309. 24X Fiche: 30-261,83/07/20,8307250290.
- 8307280375 Forwards util B30714 ltr to SA Varga w/correct attachment. W/o ltr or attachment. W/svc list. FLYNN, S.F. Carolina Power & Light Co. B3/07/20. HAROULIES, M. B., HETRICK, D.L., KLINE, J.R. Atomic Safety and Licensing Board Panel. 3pp. 19704: 010. 24% Fiche: 50-261, B3/07/20, B307250375.
- 8307250393 Grder granting util request for extension until 830815 to file status rept. Good cause shown.

  MARGULIES, M.B. Atomic Safety and Licensing Board Panel. 83/07/21.

  Carolina Power & Light Co. 1p. 19701:328. 24%

  Fiche: 50-261,83/07/21,8307250393.
- 8307250492 Order granting util request for extension until 830815 to respond to Hartsville Group motion to compel. Good cause shown.

  MARGULIES, M.B. Atomic Safety and Licensing Board Panel. 83/07/21. Carolina Power & Light Co. 1p. 19701:275. 24X Fiche: 50-261.83/07/21,8307250492.
- P. Operating license stage documents & correspondence
- B307140207 Confirms B3020B telcon re NRC approval of request for 24 h extension to maint period per Tech Spec 3.3.7. Extension allows plant to remain in sower operation mode while repairs completed on syc water booster pump B.

  O'REILLY, J.P. Region 2. Office of Director. B3/02/11. UTLEY, E.E. Carolina Power & Light Co. 1p. 19325: 074. 24X

  Fiche: 50-261-83/02/11.8307140207.
- 8307140049 Extends invitation to attend 830628 mgt meeting in Atlanta, GA to discuss replacement/repair of steam generators, per 830606 telcon.

  O'REILLY, J. P. Region 2. Office of Director. 83/06/09. UTLEY, E. E. Carolina Power & Light Co. ip. 19514: 141. 24x
  Fiche: 50-261, 83/06/09, 8307140049.
- 8307270350 Forwards corrected order confirming commitments on post-TMI-related (ssues in Item III. D.3.4, "Control Room Habitability."

  VARQA.S.A. Operating Reactors Branch J. 83/06/21. UTLEY.E.E. Carolina Power & Light Co. 2pp. 19788: 356. 24X

  Fiche: 50~261,83/06/21,8307270350.
- --8307270356 Corrected order confirming licensee commitments on post-TMIrelated issues per Item III.D.3.4, "Control Room Habitability." EIBENNUT.D.C. Division of Licensing. 83/06/21. Carolina Power & Light Co. 1p. 19788:338. 24X Fiche: 50-261,83/06/21,8307270350.
- 8307270320 Responds to 830401 request for review of achievability of flux reduction action plan for Cycle 10 core reload schedule. Schedule acceptable & achievable provided proposed licensing actions submitted on time & w/complete content. VARGA, S. A. Operating Reactors Branch 1. 83/06/27. UTLEY, E. E. Carolina Power & Light Co. 3pp. 19812:021. 24X Fiche: 50-261,83/06/27,8307270320.
- 8307070172 Forwards Rev O to "HB Robinson Steam Electric Plant, Unit 2, 10CFR50, App J. Testing Program," in response to IE Insp Rept 50-261/82-82. Detailed exemption requests encl. ZIMMERMAN, S. R. Carolina Power & Light Co. 83/06/30. VARGA, S. A. Operating Reactors Branch 1. 3pp. 19267: 338. 24X Ficha: 50-261, 83/06/30, 8307070172.

- --8307070175 Rev O to "HB Robinson Steam Electric Plant, Unit 2, 10CFR50, App J. Testing Program,"

  FARMER, S. W. Carolina Power & Light Co. 83/04/30. 67pp. 19267:341. 24% Fiche: 50~241.83/06/30.8307070172.
- B30711005B Forwards final repts on evaluation of qualification of Westinghouse containment fan cooler motors & RHR pump motor to clarify util B3042B response to environ qualification SER.

  ZIMMERMAN, S. R. Carolina Power & Light Co. B3/07/01. VAROA, S. A. Operating Reactors Branch 1. 3pp. 19374:283. 24X Fiche: 50-261, B3/07/01, B30711005B.
- --8307i10064 "Final Rept on Evaluation of Gualification of Model 685.55, Reactor Containment Fan Cooler (RCFC) Motors Provided by Mestinghouse Electric Corp for Use in HB Robinson Unit 2."

  R07; F. L. Patel Engineers. PEI-TR-83-6-8A, 83/06/22, 22pp. 19374:286. 24% Fiche:50-261.83/07/01,8307110098.
- --8307i10077 "Final Rept on Evaluation of Gualification of Model 506UPZ RHR Pump Motor Provided by Westinghouse Electric Corp for Use in HB Robinson - Unit 2. ROV.F.L. Patel Engineers. PEI-TR-83-6-88. 83/06/24. 17pp. 19374:308. 24X Fiche: 50-261.83/07/01.8307110058.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIBENHUT.D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Bvc list encl. EISENHUT.D. Q. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307140251 Confirms schedule for 830708 mgt meeting at Raleigh-Durham Airport.Raleigh.NC to discuss status of outstanding regulatory issues. Proposed meeting agenda encl.

  D'REILLY, J. P. Region 2, Office of Director. 83/07/06. UTLEY, E. Carolina Power & Light Co. ip. 19523:044. 24X

  Fiche: 50-000, 83/07/06, 8307140251.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMB events Svc list encl. EIBENNUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B3071B0430 Notification of B30715 meeting w/wtil in Bethesda,MD to discuss results of steam generator tube eddy current tests & justification for continued operation for greater than three EFPM.
  REBUA, 0. Operating Reactors Branch 1. B3/07/08. VARGA,S.A. Operating Reactors Branch 1. 2pp. 19566:344. 24X
  Fiche: 50-261,B3/07/08,B307180430.
- 8307140063 Responds to NRC 830511 request for add1 info re final steam generator repair rept. Polar crane to be modified to make special heavy lifts required during steam generator replacement.

  ZIMMERMAN, B. R. Carolina Power & Light Co. 83/07/11. VARGA, S. A. Operating Reactors Branch I. 4pp. 19514: 117. 24X Fiche: 50-261, 83/07/11, 8307140063.
- 93072003B1 Forwards request for add1 info re application for amends to allow repair of steam generators by replacement of major components. Info will be used in preparation of EIS for subjapplication.

  VARGA. S. A. Operating Reactors Branch 1. 93/07/11. UTLEY, E. E. Carolina Power & Light Co. App. 19469:343. 24X

  Fiche: 50-261,83/07/11,8307200381.
- 8307220378 Forwards addl info re final steam generator repair rept.to assist in EIS preparation.per request.

  ZIMMERMAN.S.R. Carolina Power & Light Co. 83/07/14. VARGA.S.A. Operating Reactors Branch i. 19pp. 19684: 286. 24X Fiche: 50-261.83/07/14.8307220578.
- 8307220322 Forwards revised response to request for add1 info re final steam generator rept discussed during 830506 meeting. Responses to telecopied questions on 830323 also encl. ZIMMERMAN, S.R. Carolina Power & Light Co. 83/07/15. VARGA, S.A. Operating Reactors Branch 1. 22pp. 19675:098. 24X Fiche: 50-261, 83/07/15, 8307220322.

- B307250120 Responds to NRC B30620 request for participation in NRC research program addressing Unresolved Safety Issue A-47. "Safety Implications of Gontrol Sys." Participation declined due to lack of resources. EURY, L.W. Carolina Power & Light Co. B3/07/19. EISENHUT, D. G. Division of Licensing. 2pp. 19706:072. 24X Fiche: 50-261, 83/07/19, 8307250120.
- 8307280364 Forwards proprietary Rev O to XN-NF-711(P), "Extension of XNB Correlation to PWR Fuel Assembly Designs W/Spacer Pitch Greater Than 22 Inches." Withholding of proprietary rept requested per 10CFR2.790, Affidavit encl.
  ZIMMERMAN.S.R. Carolina Power & Light Co. 83/07/25. EISENHUT.D.O. Division of Licensing. 7pp. 19797: 245. 24X Fiche: 50-261, 83/07/25. 8307280364.
- B307280411 Forwards add1 info.for EIS.on util B30714 response to NRC questions re steam generator replacement.per NRC B30718 request.

  ZIMMERMAN, B. R. Carolina Power & Light Co. B3/07/25, VAROA: S. A. Operating Reactors Branch 1. 9pp. 19797: 352, 24X Fiche: 50-261, B3/07/25, B307280411.
- B307290174 Provides status of program re pressurized thermal shock. Issue would be resolved if NRC screening criteria conservative & if critical weld will not reach criteria prior to OL expiration.
  UTLEY.E.E. Carolina Power & Light Co. B3/07/26. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19821:158. 24X Fiche: 50-261, 83/07/26. 8307290174.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140314 Responds to NRC 821203 ltr re violations noted in 1E Insp Rept 50-261/82-40. Corrective actions: all unusual waste shipments suspended. UTLEY.E.E. Carolina Power & Light Co. 83/01/05. O'REILLY.J.P. Region 2. Office of Director. 4pp. 19525: 208. 24X Fiche: 50-261.83/01/05.8307140314.
- --8307140316 Forwards IE Insp Rept 50-261/82-40 on 821110 & notice of violation.
  O'REILLY, J.P. Region 2, Defice of Director. 82/12/03. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19525:212. 24X Fiche: 50-261,83/01/05.8307140314.
- --8307140317 Notice of violation from insp on 821110. \* Region 2. Office of Director. 82/12/03. 2pp. 19525:214. 24X Fiche: 50-261,83/01/05,8307140314.
- --B307140321 IE Insp Rept 50-261/B2-40 an 821110. Noncompliance noted: two 55-gallon drums containing radioactive matl, not specified per 10CFR30. 41. found leaking black sludge upon arrival at waste factility.

  ALBRIGHT, R. H. Region 2. Office of Director. BARR, K. P. Division of Engineering & Radiological Safety Programs. 82/11/30. 5pp. 17525: 216. 24X Fiche: 50-261, 83/01/05, 8307140314.
- 8307140392 Informs that liquid samples spiked w/redionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analyzed for tritium. Br-89 & Sr-90 content within 60 days.

  LEWIS.R.C. Division of Project & Resident Programs. 83/02/07.

  JONES.J.A. Carolina Power & Light Co. 1p. 19523:354. 24X

  Fiche: 50-000, 83/02/07, 8307140392.
- 8307140060 Forwards IE Insp Rept 50-261/83-14 on 830503-06.No noncompliance noted.

  VERRELLI,D.M. Division of Project & Resident Programs. 83/06/13.

  UTLEY,E.E. Carolina Power & Light Co. 2pp. 19514:122. 24X

  Ficha: 50-261,83/06/13.8307140060.
- --8307140066 IE Insp Rept 50-261/83-14 on 830503-06. No nancompliance noted Major areas inspected: respiratory protection; surveys, external exposure control, radiation work permits & posting, labeling & control.
  ALBRIGHT, R. H., BARR, K. P. Region 2, Office of Director. 83/06/09, 5pp. 19514:124. 24X Fiche: 50-261,83/06/13,8307140060.
- 8307140081 Forwards IE Insp Rept 50-261/83-16 on B30602-03 No noncompliance noted.
  O'REILLY, J. P. Region 2, Office of Director. 83/06/24, UTLEY, E. E. Garolina Power & Light Co. 2pp. 19323:227, 24X
  Fiche: 50-261,83/06/24,8307140081.
- --8307140089 IE Insp Rept 50-261/83-16 on 830602-03. No noncompliance noted Major areas inspected: external exposure control. ALBRIGHT.R.H. Region 2. Office of Director. 83/06/21. App. 19523: 227. 24X Fiche: 50-261.83/06/24.8307140081.

- 8307070172 Forwards Rev O to "HB Robinson Steam Electric Plant,Unit 2, 10CFR50,App J.Testing Program," in response to IE Insp. Rept 30-261/82-22, Detailed exemption requests encl. ZIMMERMAN,S.R. Carolina Power & Light Co. 83/06/30 VARGA,S.A. Operating Reactors Branch i. 3pp. 19267:338. 24X Fiche: 50-261,83/06/30,8307070172
- --8307070175 Rev 0 to "HB Robinson Steam Electric Plant, Unit 2,10CFR50, App J.Testing Program " FARKER,S.M. Carolina Power & Light Co. 83/04/30. 67pp. 1926/.34i. 24X Piche: 50-261,83/06/30.8307070172.
- 8307120337 Forwards "MB Robinson Unit 2 1983 Intersm Cycle Steam Generator Insp Rept." STARKEY.R B. Carolina Power & Light Co. 83/07/08. VARGA.S.A. Operating Reactors Branch 1. 2pp. 19429:148. 24X Fiche: 50-261.83/07/08.8307120337.
- --8307120338 "HB Robinson Unit 2 1983 Interim Cycle Steam Generator Insp. Rept." PAINELE V. Carolina Power & Light Co. 83/06/30. 16pp. 17429:150. 24X Fiche:50-261/83/07/08/8307120337.
- B306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness % Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24x Fiche:50-000.83/07/12.8306270404.
- 8307180090 Forwards IE Bafeguards Insp Rept 50-261/83-19 on 830620-24 & notice of violation Corrective actions to prevent recurrence completed prior to conclusion of insp. Notice of violation & insp rept details withheld (ref 10CFR73.21).

  VERRELLI, D. Division of Project & Resident Programs. 83/07/13.

  UTLEV, E. E. Carolina Power & Light Co. 2pp. 19556:328. 24X

  Fiche: 50-261.83/07/13.8307180090.
- --B307180094 IE Safeguards Insp Rept 50-261/83-19 on B30620-24.
  Noncompliance noted in area of access controls Details withheld (ref 10CR73,21).
  TOBIN.W.J. Region 2. Office of Director. MCGUIRE.D.R. Division of Emergency Preparedness & Materials Safety. B3/07/11. 1p. 19556:330. 24X Fiche:50-261.83/07/13.8307180090.
- 8307220001 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-08.

  LEMIS, R. C. Division of Project & Resident Programs. 83/07/13.

  UTLEY, E. E. Carolina Power & Light Co. 1p. 19673: 344. 24X Fiche: 50-261, 83/07/13, 8307220001.
- --8307220002 Responds to NRC B30523 ltr re violations noted in IE Insp Rept 50-261/83-08. Corrective actions: procedures revised re handling, segregation, insp & packaging of compactible, dry active waste. STARKEY, R. 8. Carolina Power & Light Co. B3/06/22. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19673:345. 24X Fiche: 50-261, B3/07/13, B307220001.
- --8307220003 Forwards IE Insp Rept 50-261/83-08 on 830322-25 & notices of violation & deviation.

  LEWIS.R.C. Division of Project & Resident Programs. 83/05/23.

  UTLEY.E.E. Canclina Power & Light Co. 2pp. 19673:348. 24X

  Fiche:50-261,83/07/13,8307220001.
- --B307220004 Notice of violation from insp on B30322-25.

  \* Region 2. Office of Director. B3/05/23. 1p. 19673:350. 24X
  Fiche: 50-261,83/07/13.8307220001.
- --8307220005 Notice of deviation from insp on 830322-25. \* Region 2, Office of Director. 83/05/23. 1p. 19673:351. 24X Fiche: 50-261,83/07/13,8307220001.
- --8307220006 IE Insp Rept 90-261/83-08 on 830322-25. Noncompliance noted: unauthorized person disposed of liquid waste containing licensed meth & individuals not trained in requirements of packaging radioactive meths, per IE Rulletin 79-19.

  ALBRIGHT.R. H. Region 2. Office of Director. BARR.K.P. Division of Engineering & Radiological Safety Programs. 83/04/29. 6pp. 19673:332. 24X Fiche: 50-261.83/07/13.8307220001.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & 1-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. B. Division of GA, Safeguards & Inspection Programs (Post 830(03). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14. 8306270406.

- 8307220445 Ack receipt of 830724 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-12 LEVIS.R C Division of Project & Resident Programs. 83/07/15. UTLEV.E E. Carolina Power & Light Co 1p. 19684.331. 24X Fichs 50-261.83/07/15.830722045.
- --B307220459 Responds to NRC B30526 itr re violations noted in IE Insp Rept 50-261/B3-12 Corrective actions; increased emphasis placed on closing out old mods:safety-related instrument busses cleaned & methods of checking for leaks discussed. STARKEY: R. B. Carolina Power & Light Co. B3/06/24. O'REILLY, J. P. Region 2: Office of Director 4pp. 19684:332 24X Fiche 50-261,83/07/15,8307220445.
- --8307220468 Forwards (E Insp Rept 50-261/83-12 on 830411-0509 & notice of violation.

  LEMIS.R C Division of Project & Resident Programs. 83/07/15.

  UTLEY.E E. Carolina Power & Light Co 2pp. 19684:336. 24X
  Fiche.50-261.83/07/15.8307220445.
- --8307220471 Notice of violation from insp on 830411-0509.

  + Division of Project & Resident Programs. 83/07/15. 2pp. 19684 338. 24X Fiche: 50-261.83/07/15.8307220445.
- --8307220479 IE Insp Rept 50-261/83-12 on 830411-0509. Noncompliance noted: foilure to adequately establish, implement & maintain operations work procedure & administrative & maint instructions.

  WEISE, 5 Region 2. Office of Director. 83/05/23. 13pp. 19684.340. 24x Fiche: 50-261.83/07/15,8307220445.
- 8307290167 Forwards response to 830617 request for add1 info re IE BUIIstin EO-11. "Hasonry Wall Design " Effects of higher modes can be neglected in considering total seismic shear loadings as masonry walls assumed to be relatively stiff. IIMERMAN.S.R. Carolina Power & Light Co. 83/07/25. VARGA,S.A. Operating Reactors Branch 1. 4pp. 19821:036. 24X Fiche: 50-261-83/07/25.8307290167.
- R. Periodic operating reports  $\boldsymbol{b}$  related correspondence
- B307130059 Monthly operating rept for June 1983.W/B3070B ltr.
  MGRRIS.H.R., STARKEY,R.B. Carolina Power & Light Co. B3/07/OB.
  DEYOUNG.R.C. Director's Office of Inspection and
  Enforcement. 4pp. 19474:212. 24x Fiche:50-261.B3/07/08.8307130059.
- S. Reportable occurrences, LERs & related correspondence
- 8307110274 LER 83-011/03L-0: on 830603, circuit breaker for boron injection tank heater channel 8 tripped. Caused by component failure due to normal end of life. Failed heater replaced. W/830705 ltr. COX.H.T., SFARKEY, R.B. Carolina Power & Light Co. 83/07/05. GTREILLY, J.F., Region 2, Office of Director. 3pp. 19374: 239. 24X Fiche: 50-261.83/07/05.8307110294.
- B307260493 LER B3-014/01T-0: on B30704, suc water leak discovered on containment fan cooler HVH-2, resulting in degradation of containment boundary per IE Bulletin B0-24. Caused by currosion/erosion of cooler tubing. W/830718 ltr. COX.H T. STARKEY, R. B. Carolina Power & Light Co. 83/07/18. 0'REILLY, J. P. Region 2, Office of Director. 3pp. 19733: 354. 24X Fiche: 50-261, 83/07/18, 9307260493.
- ### 8307290179 LER B3-015/01T-0: on ### 830622.w/unit at ### 80% power, increase in total primary sym leakage to 1.19 gpm identified. Caused by defective sensing line fitting Abnormal degradation of ### RCPB declared on ### 830705. Fitting replaced, #### 830719 ltr. COX.H.T.. STARKEY.R.B. Carolina Power & Light Co. ### 83/07/19. 0'REILLY.J.F. Region 2. Office of Director. 4pp. 19821: 152. 24% Fiche: 50-261. ### 83/07/19. ### 8307290179.
- B307290106 LER B3-012/03L-0 on B30621, auxiliary foedwater pump discharge value V2-16C breaker tripped during performance of Periodic Fest 22 IC. Cause unknown. Circuit breaker for V2-15C immediately reclosed & valve cycled. W/830721 ltr. COX. H. T., STARKEY.R. B. Carolina Power & Light Co. B3/07/21. 0'REILLY. J. P. Region 2, Office of Director. Jpp. 19822:039. 24X Fiche: 30-261. B3/07/21. B307290106.

# DOCKET 50-262 BRIGHAM YOUNG UNIV. RESEARCH REACTOR V. Operator Examinations

9307080427 Generic Ltr 83-12A to all nonpower reactor licenses re issuance of NRC Form 398. "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000.83/07/11.8307080427.

- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT
  F. Security, medical, emergency & fire protection plans
- 8307170339 Forwards exemption from requirements of Section III. 9 of App R per 820430 & 1028 requests Requests for intake structure pump room, structural steel & control room denied. EISENHUT, D. O. Division of Licensing. 83/06/16. MUSOLF, D. M. Northern States Power Co. 3pp. 19631:257. 24X Fiche: 50-263,83/06/16,8307190359.
- --8307190361 Exemption from requirements of Section III. 0.2 of App R to 10CFR50 for automatic suppression pool area (Fire Zone TF). PURPLE.R.A. Assistant Director for Licensing, 83/06/16. Northern States Power Co. 4pp. 19651:260. 24X Fiche:50-263,83/06/16.8307190359.
- --8307190370 Safety evaluation supporting exemption from Baction III.O of App R for suppression pool & recommending denial of exemption from Saction III.O of App R re structural steel, intake structure & control room.

  \* Office of Nuclear Reactor Regulation, Director. 83/06/16.
  19pp. 19651:264. 24X Fiche:50-263,83/06/16,8307190389.
- 830701017B Forwards Rev 5 to security force training & qualification plan. Rev withheld (ref 10CFR73, 21), MUSQLF, D.M. Northern States Power Co. 83/06/24, Office of Nuclear Reactor Regulation, Director. 2pp. 19172:261, 24X Fiche: 50-000, 83/06/24, 8307010178.
- B307120538 Forwards IE Insp Rept 50-263/83-09 on 830516-20 & notice of violation.

  PAPERIELLO.C.J. Region 3, Office of Director. B3/06/28, CARSON.C.E. Northern States Power Co. 2pp. 19434:011. 24X
  Fichs: 50-263,83/06/28,8307120538.
- --8307120542 Notice of violation from insp on 830516-20.
  PAPERIELLO.C.J. Region 3, Office of Director. 83/06/27. ip. 17434:013. 24X Fiche: 50-263.83/06/28.8307120538.
- --8307120547 IE Insp Rept 50-243/83-07 on 830516-20. Noncompliance noted: failure to rept unusual event within 15 minutes, per 100F850. App E. Bection IV. D. 3. PATTERSON, J. P., GLOBERSEN, W. B., AXELBON, H. L. Region 3. Dffice of Director. 83/06/27. 13pp. 19434:014. 24X Fiche: 50-263, 83/06/28, 8307120538.
- 8307220461 Responds to NRC 830207 ltr re Rev 12 to security plan. Previously approved wording reinstituted per NRC request. Security guard force procedures remain unchanged. MySOLF. D. Northern States Power Co. 83/07/15. Office of Nuclear Reactor Regulation, Director. 1p. 19696:112. 24X Fiche: 50-263,83/07/15,8307220461.
- 8307250632 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Hanagement Branch. 1p. 19718:144. 24X Fiche: 50-000, 83/07/19, 8307250632.
- ~~8307250642 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.1 recorporate emergency response plan. EPIP 1.1.2 renotifications & EPIP 1.1.3 republic info.

  MARD.E.C. Northern States Power Co. 83/05/20. Region 3, Office of Director. ip. 19718:145. 24X Fichs:50-000,83/07/19,8307250632.
- --B307250650 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.1 re corporate emergency response plan.EPIP 1.1.2 re notifications & EPIP 1.1.3 re public info.Rev 12 to table of contents encl. HUDSON, G., WARD, E.C. Northern States Power Co. 83/05/20. 145pp. 19718:146. 24X Fiche: 50-000.83/07/19.8307250632.
- J. Insurance & indemnity information
- B307260475 Forwards Endorsements 65 & 66 to NELIA Policy NF-174, Endorsements 54 & 55 to NELIA Policy NF-197 & Endorsements 54 & 47 to MELU Policies MF-51 & MF-60, respectively, JUHNSON, R. Q. Northern States Power Co. B3/07/18. DINITZ, I. Antitrust & Economic Analysis Branch (Utility Finance). 7pp. 19731:156. 24X Fiche: 50-000, B3/07/18, B307260475.
- 8307260479 Forwards Endorsement 67 to NELIA Policy NF-147 & Endorsement 55 to MAELU Policy MF-51.

  JOHNSDN,R.O. Northern Btates Power Co. 83/07/21. DINITZ, I. Division of Engineering. 3pp. 19734: 209. 24X Fiche: 50-263, 83/07/21, 8307260479.

- P. Operating license stage documents & correspondence
- 8208060366 Board Notification 82-70: notifies of differing prof opinion re sensitization of BMR stainless steel weldments.
  EISENNUT.D. G. Division of Licensing. 82/07/20. PALLADINO, N. J.
  Commissioners. 4pp. 17043:001. 24X Fiche: 50-000,82/07/20,
  B208040364
- 8307110097 Forwards safety evaluation re BWR Owners Group response to TMI Item II.K.3.18, "Mod of Automatic Depressurization Sys." Elimination of high drywell pressure permissive & bypass after sustained low water level acceptable, VASBALLO.D.B. Operating Reactors Branch 2. 83/06/03. MUSOLF, D.M. Northern States Power Co. 2pp. 19386:275. 24X Fiche: 50-263,83/06/03,8307(10099.
- 8307180173 Forwards safety evaluation concluding that seven of eight equipment items environmentally qualified & require no justification for continued operation.

  VASBALLO, D. B. Operating Reactors Branch 2. 83/06/16. MUSDLF, D. M. Northern States Power Co. 2pp. 17567:348. 24X

  Fiche: 50-263,63/06/16,8307180173.
- --8307180180 Safety evaluation supporting continued operation per environ qualification review.

  \* Office of Nuclear Reactor Regulation, Director. 83/06/16. 6pp. 19367:330. 24X Fiche: 30-263.83/06/16.8307180173.
- 8307180183 Informs that YMI Action Plan Item II. K. 3. 13 re HPC1/RCIC initiation level resolved, per 830421 notification of adherence to 830316 approved design.

  VASSALLO, D. B. Operating Reactors Branch 2. 83/06/17. MUSOLF, D. M. Northern States Power Co. 2pp. 19562:001. 24X Fiche: 50-263, 83/06/17, 8307130133.
- 8307010104 Application to amend License DPR-22.changing Tech Specs to comply w/NURE9-0737, Items II.F. 1.1 II.F. 1.6 re accident monitoring instrumentation, per Generic Ltr 83-02.

  MUSDLF.D. Northern States Power Co. 83/06/24. Office of Nuclear Reactor Regulation, Director. 3pp. 19168: 211. 24X

  Fiche: 50-263, 83/06/24, 8307010104.
- --8307010123 Proposed Tech Spec changes restricting employee overtime, requiring mafety/relief valve failures & challenges to be reported & adding limiting condition for operation & surveillance requirements for RGIC sys suction transfer.

  \* Northern States Power Co. 83/06/24, 44pp. 19168:214. 24X Fiche: 50-263.83/06/24.8307010104.
- B3070B0030 Forwards response to NRC B30511 ltr requesting addl info re TMI Item II.K.3.28. "Gualification of Automatic Depressurization Sys (ADB)." Designated allowable leakage criteria for ADB is zero.
  MUSQLF.D. Northern States Power Co. 83/06/28. Office of Nuclear Reactor Regulation, Director. App. 19351:316. 24X Fichs: 50-263, 83/06/28, 8307080030.
- 8306270397 Generic Ltr 83-26 to all applicants for QLs & holders of QPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19370:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 1969:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080167 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- G. Inspection reports, IE Bulletins & correspondence
- 8307080021 Forwards IE Insp Rept 50-263/83-11 on 830516-20 & 24-27 & notice of violation.

  8TREETER: J. F. Region 3, Office of Director. 83/06/24. LARBDN. C. E. Northern States Power Co. 2pp. 17351: 324. 24X

  Fiche: 50-263:83/06/24:8307080021.
- --8307080023 Notice of violation from insp on 830516-20 & 24-27. STREETER, J. F. Region 3, Office of Director. 83/06/24. 2pp. 19351: 326. 24X Fiche: 50-263, 83/06/24, 8307080021.

- --8307080026 IE Insp Rept 50-263/83-)1 on 830516-20 & 24-27. Noncompliance noted failure to approve temporary changes to procedures & follow procedures re drawing control. CHOULES.N.C., HAWKINS.F.C. Region 3. Office of Director. 83/06/24. 12pp. 19351:328. 24X Fiche:50-263.83/06/24.8307080021.
- B307120006 Forwards IE Insp Rept 50-263/83-10 on 830524-26 & 0601. No noncompliance noted.

  PAPERIELLO.C.J. Region 3. Office of Director 83/06/27.

  LARSON.C.E. Northern States Power Co. 2pp. 19423:176. 24X

  Fiche: 30-263:83/06/27.8307120006.
- --8307120007 IE Insp Rept 90-263/83-10 on 830524-26 & 0601.No noncompliance noted. Major areas inspected confirmatory measurements & radiological environ monitoring programs. ROZAK.S., DESTMANN,M.J., SCHUMACHER.M. Region 3, Office of Director. 83/06/24. 8pp. 19423:178. 24X Fiche: 50-263,83/06/27,8307120006.
- 8307180011 Forwards IE Insp Rept 50-263/83-12 on 830502-0601. No noncompliance noted.

  SHAFER.W. D. Region 3, Office of Director. 83/06/27. LARSDN.C. E. Northern States Power Co. 2pp. 17560:274. 24X

  Fiche: 50-263, 83/06/27, 8307180011.
- --8307180013 IE Insp Rept 50-263/83-12 on B30502-0601. No noncompliance noted. Major areas inspected operational safety verification menthly maint abservation, onsite review committee, monthly surveillance observation & outage for maint.
  BROWN, C. H., WALKER, R. D. Region 3. Office of Director. 83/06/24, 5pp. 19560: 296. 24X Fiche: 50-263, 83/06/27, 8307180011.
- 8307120538 Forwards IE Insp Rept 50-263/83-09 on 830514-20 & notice of violation. PAPERIELLO.C.J. Region 3, Office of Director. B3/06/28. CAR80N.C.E. Northern States Power Co. 2pp. 19434:011. 24X Fiche: 50-263.83/06/28.8307120538.
- --8307120542 Notice of violation from insp on 830516-20.
  PAPERIELLO,C,J. Region 3. Office of Director. 83/06/27. 1p. 19434:013. 24X Fiche: 50-263, 83/06/28, 8307120538.
- --8307120547 IE Insp Rept 80-263/63-09 on B30516-20 Noncompliance noted: failure to rept unusual event within 15 minutes.per 10CFR50.App E. Bection IV.D. 3. PATTERBON.J.P., GLOERSEN.W.B., AXELSON.W.L. Region 3, Office of Director. 83/06/27. 13pp. 19434:014. 24X Fiche:50-263.83/06/28.8307120538.
- B307180127 Forwards IE Insp Rept 50~263/83-13 on 830606-09 & notice of violation.
  PAPERIELLO,C. J. Region 3, Office of Director. B3/07/01.
  LAR80N.C.E. Northern States Power Co. 2pp. 19556: 224. 24X
  Fiche: 50~263, B3/07/01, B307180127.
- --8307180130 Notice of violation from insp on 830606-09.
  PAPERIELLO,C, J. Region 3, Office of Director. B3/06/30. 1p. 19596: 226. 24X Fiche: 50-263, 83/07/01, 8307180127.
- ---B307180133 IE Insp Rept 50-263/83-13 on 830606-09. Noncompliance noted: unauthorized temporary shielding added to Model F8V-1 shipping cask. ORANT.W.B., GREGER.L.R. Region 3, Office of Director. 83/06/30. 9pp. 17556: 227. 24X Fiche: 50-263, 83/07/01, 8307180127.
- 8306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Perparedness & Englineering Response (Post B30103). 83/07/11. Consolidated Edison Co. of New York: Inc. 154pp. 19563:293. 24X Fiche: 50-000: 83/07/11: 8306270401.
- 8306270404 IE info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice B3-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLDR.J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14. 8306270406.
- B30728035i Ack receipt of B30718 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-263/83-11.
  STREETER. J. F. Region 3. Office of Director. B3/07/26. LARSON. C. E. Northern States Power Co. 1p. 19789:010. 24X Fiche: 50-263, 83/07/26, 8307280351.

- --8307280353 Responds to NRC 830624 ltr re violations noted in IE Insp. Rept 50-263/83-11. Corrective actions: no notes will be placed on procedures being used in work sequence unless actual temporary changes & closer surveillance will be maintained. LARSON.C. E. Northern States Power Co. 83/07/18. STREETER, J. F. Region 3. Office of Director. Spp. 19789: 011. 24X Fiche: 50-263, 83/07/26, 8307280351.
- R. Periodic operating reports & related correspondence
- 8307080363 Provides June 1983 status rept on seismic Category I piping & supports per 810608 commitment. Mods being installed in emergency svc water sys, so that models used for dynamic analysis conform to current modeling techniques. LARSON.C.E. Northern States Power Co. 83/06/27. KEPPLER, J. 9. Region 3. Defice of Director. 3pp. 19390:303. 24X Fiche: 50-263,83/06/29,8307080363.
- S. Reportable occurrences, LERs & related correspondence
- 8307060252 LER 83-015/01T-0: on 830613, investigation of 250-volt do battery fault revealed grounded MPCI Woodward Governor EDR hydraulic actuator coil. Caused by out-of-spec nonhomogeneous lube oil. Lube oil replaced. W/830627 ltr. WOJCHOUSKIJ.A.V., WOBLEF.D. Northern States Power Co. 83/06/27. Region 3. Office of Director. 2pp. 19239: 311. 24X Fiche: 50-243, 83/06/27, 8307060252.

DOCKET 50-264 DOW CHEMICAL CO.

V. Operator Examinations

- B3070B0427 Generic Ltr B3-12A to all nonpower reactor licensees re Issuance of NRC Form 398, "Personal Qualifications Statement - Licensee," Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp 19963:138. 24X Fiche:50-000.83/07/11.63070B0427.
- BOCKET 50-265 QUAD-CITIES STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8307120137 Forwards exemption from requirements of App R to 10CFR50, Section III.0 re fire protection of safe shutdown capability in response to 820701 & 0923 requests.

  VASSALLO, D.B. Operating Reactors Branch 2. 83/06/23. FARRAR, D.L. Commonwealth Edison Co. 3pp. 19435:188. 24X Fiche: 50-254,83/06/23, 8307120137.
- --8307120145 Exemption from requirements of App R to 10CFR50. Section III.0 for fixed fire suppression associated w/panels, switchgear & motor control ctrs.
  EISEMHUTI.D.0. Division of Licensing. 83/06/23. Commonwealth Edison Co. 6pp. 19435:191. 24X Fiche: 50-254, 63/06/23, 8307120137.
- 6307120062 Releases public version of rev to emergency plan implementing procedures.
  FELTON.J.H. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 17435: 260. 24X Fichs: 50-254, 83/06/24, 8307120062.
- --8307120068 Public version of revised emergency plan implementing procedures, including Procedures GEP 330-0 re assessment actions & GEP 330-11 re estimation of I-131 release by field team measurements. Revised index encl. GERNER.L. & KOVACK.T. J. Commonwealth Edison Co. 83/06/30. App. 19435:261. 24X Fiche: 50-254, 83/06/24, 8307120062.
- 8307260018 Submits supplemental response to NUREO-0737, Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display says verification to be performed w/verification program. BHARTZ, E. D. Commonwealth Edison Co. 83/07/20, DENTON, M. R. Office of Nuclear Reactor Regulation, Director. 2gp. 19727:177. 24X Fiche: 50-000, 83/07/20, 8307260018.
- 8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLO, C. J. Region 3. Office of Director. 83/07/26. REED, Commonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 30-000, 83/07/26, 8307280347.

- H. General correspondence
- 8307220450 Comments on Sangor Daily News & MTV repts of NRC order to shot down five facilities for insp of cooling pipes.

  Subsequent rescission considered under pressure from private owners of plants. Requests stronger enforcement.

  MEINRICK: B. C. Affiliation Unknown. 83/07/15. DENTON, H. R. NRC Na Datailed Affiliation Given. 2pp. 19686: 082. 24X

  Fiche: 50-000, 83/07/15, 8307220450.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 8307010195 Forwards amends to updated FBAR for facilities. STIEDE.W.L. Commonwealth Edison Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19123:001. 24X Fiche: 50-000, 83/06/29, 8307010195.
- --8307010198 Amend to updated FSAR for Quad Cities 1 & 2. \* Commonwealth Edison Co. 83/04/29, 508pp. 19123:069, 24X Fiche: 50-000, 83/04/29, 8307010198.
- $P_{\rm c}$  Operating license stage documents & correspondence
- 8307250498 Rev 3, to "Process Control Program for Solidification of Radwaste."

  \* Commonwealth Edison Co. 83/03/31. 9pp. 19701:220. 24X Fiche: 50-254,83/03/31,8307250498.
- 8305240240 Informs that beta spectra measurements will be conducted on 830524 for NRC project. "Beta Particle Heasurement & Dosinetry Requirements at NRC-Licensed Facilities." RATHBUN.L.A. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2448. 83/05/20. KEPPLER.J.G. Region 3, Office of Director. ip. 18599:337. 24X Fiche:50-254.83/05/20.8305260240.
- 8307120132 Forwards response to BHR Duners Group study of alternatives to NVREG-0737, Item II. K. 3. 18, "Automatic Depressurization Sys Logic Mod." Two of seven alternatives acceptable. Implementation schedule should be provided within 45 days. VASSALLO. D. B. Operating Reactors Branch 2, 83/06/03, FARRAR. D. L. Commonwealth Edison Co. 9pp. 19435:179, 24X Fiche: 50-254,83/06/03,8307120152.
- 8307140514 Advises that requirements of TMI Item II.K.S.13, "HPCI/RCIC Initiation Level," met. Item resolved. VASSALLO.D.B. Operating Reactors Branch 2. 83/06/17. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19527:345. 24X Fichs: 50-254.83/06/17.8307140514.
- 8307120125 Forwards confirmatory order re util 810115 & 820316 commitments to install permanent scram discharge sys mods prior to startup after 830901 refueling Model Tech Specs encl as guidance for use in preparing Tech Spec changes. VASSALLO, D. B. Operating Reactors Branch 2. 83/06/24. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19435:097. 24X Fiche: 50~234,83/06/24,8307120125.
- --8307120128 Confirmatory order re util 810115 & 820316 commitments to install permanent scram discharge sys mods prior to startup after 840701 refueling.

  EISENHUT, D. Q. Division of Licensing. 83/06/24. Commonwealth Edison Co. 35pp. 19435:099, 24X Fichs:50-254,83/06/24, 8307120125.
- 8307070176 Forwards plant-unique analysis rept, Vols 1-7, demonstrating primary containment sys design adequacy & restoration of original design safety margins per NUREG-0661.
  RYBAK. 8. Commonwealth Edison Co. 83/06/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19290; 001. 24X Fiche: 50-000; 83/06/27, 8307070176.
- --8307180152 "Quad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept. Vol 3. Vent Bys Analysis."

  8HAMBZAD. H., ADANS.R. H., MCINNEG. I. D. NUTECH Engineers, Inc. CCM-CO2-039-3 ROO. 83/05/21. 221pp. 19953:016. 24X Fiche: 50-000.83/06/27.8307070176.
- --8307180158 "Quad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept, Vol 4, Internal Structures Analysis."

  TALBOTT, D.C., ADAMS, R. H., MCINNES, I. D., NUTECH Engineers, Inc. COM-02-039-4 ROO. 83/05/31. 34pp. 17553: 237. 24X

  Fiche: 50-000, 83/05/27, 8307070176.
- --8307180168 "Quad Cities Station Units 1 & 2 Plant Unique Analysis Rept. Vol 5. Safety Relief Valve Discharge Piping Analysis."

  \* Sargent & Lundy, Inc. 83/06/27, 134pp. 19553:272. 24X Siche: 50-000,83/06/27,8307070176.

- --8307180186 "Guad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept, Vol 7, Unit 2 Torus Attached Piping & Suppression Chamber Penetration Analysis."

  PANDEY, P., WALLACH, G., GAVULA, J. A. NUTECH Engineers, Inc. COM-02-039-7 ROO. 83/05/31. 175pp. 19354: 222. 24X Fiche: 50-000, 83/06/27, 8307070176.
- --8307180138 "Quad Cities Nuclear Power Station Units 1 ½ 2 Plant-Unique Analysis Rept. Vol 1. General Criteria ½ Methodology." WIBE.R.E., KOBT.E.O., MASSEY, J. V. NUTECH Engineers, Inc. COM-02-039-1 ROO. 83/05/31. 234pp. 19551:317. 24X Fiche: 50-000,83/06/27,8307070176.
- --8307180147 "Quad Cities Nuclear Power Station Units 1 & 2 Plant Unique Analysis Rept, Vol 2, Suppression Chamber Analysis."
  HOWARD, G. L., ADAMS, R. H., MCINNES, I. D., NUTECH Engineers, Inc. COM-02-039-2 ROO. 83/05/31, 185pp. 19552:191. 24X Fiche: 50-000, 83/06/27, 8307070176.
- B307180026 Forwards SER re NUREO-0612. "Control of Heavy Loads" & technical evaluation rept. Phase I acceptable. VASSALLO.D.B. Operating Reactors Branch 2. 83/06/27. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19567:301. 24X Fiche:50-254,83/06/27,8307180026.
- --8307180030 Safety evaluation of util 801222 responses to NUREG-0612, "Control of Heavy Loads." Phase I acceptable.

  \* NRC No Detailed Affiliation Given. 83/06/27. 2pp. 19967:303. 24% Fiche: 50-234.83/06/27.8307180026.
- --8306060295 "Control of Heavy Loads (C-10), Quad Cities Station Units 1 & 2;" technical evaluation rept.
  BOMBERGER.C., BARGENT, I.H. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-386/387. 83/06/01. SINOH, A.; CHAN, T. NRC ~ No Detailed Affiliation Given. 31pp. 19567:305. 24X Fiche: 50-254,83/06/27,8307180026.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. 0. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000, 83/07/05, 8306270397.
- B307120435 Application to amend License DPR-30, changing Tech Specs to reduce max critical power ratio operating limit & to clarify labeling of one MAPLHOR curve.
  BCHROEDER.C.W. Commonwealth Edison Co. B3/07/08. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19425:248. 24X Fiche: 50-265, B3/07/05, B307120435.
- --830712043B Proposed Tech Spec change re max critical power ratio & MAPHLOR limits. \* Commonwealth Edison Co. 83/07/05. 6pp. 19425:250. 24X Fiche: 50-265,83/07/05,8307120435.
- --8307120446 Rev O to "Bupplemental Reload Licensing Submittal for Guad Cities Nuclear Power Station.Unit 2,Reload 6 (Cycle 7)." ELLIOTT.P.E. HILL.R.T., CHARNLEY, J.S. General Electric Co. 22AB360 ROO. 83/05/31. 18pp. 19425:256. 24X Ficha: 50-265,83/07/05,8307120435.
- 8307060329 Generic Ltr 83-27 to all licensess & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 815.8vc list encl. EIBENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fichs: 50-000.83/07/06.8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors; applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events, 8vc list encl. EIBENHUT.D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307190187 Notifies that Westinghouse info re environ qualification of electrical equipment detailed in 830513 ltr determined monproprietary.

  RYBAK.B. Commonwealth Edison Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19630:142. 24X

  Fiche: 50-000, 83/07/11, 8307190187.
- 8307190062 Forwards "Dynamic Analysis of Wetwell-to-Drywell Vacuum Breakers" & "Improved Dynamic Vacuum Response," in response to Generic Ltr 83-08. Results demonstrate that as-built 18-inch A&M vacuum breaker valves meet ABME Code criteria. RYBAK, B. Commonwealth Edison Co. 83/07/12. DENTON, H. R. Dffice o Nuclear Reactor Regulation, Director. 7pp. 19633:173. 24X Fiche: 50-000, 83/07/12, 8307190062.

- --8307170067 Rev O to "Dynamic Analysis of Hetwell-to-Drywell Vacuum Breakers for Quad Cities Station.Units 1 % 2." MOONKA.A.K., CHEN, G.P., MASSIE, H. W. NUTECH Engineers, Inc. COM-08-023 ROO. 81/09/27. 100pp. 19633:180. 24X Fiche: 50-000, 83/07/12, 8307190062.
- --B307190074 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Quad Cities 1 & 2 " BILANIN.A.J. Continuum Dynamics, Inc. B2-7 RO1. B2/09/30. 29pp. 19633:292. 24X Fichs:50-000.B3/07/12.8307190062.
- B307210030 Application to amend License DPR-30, changing safety relief actuating setpoint of Target Rock valve to 1,135 psig & electromagnetic relief valves to 1,115 psig. RYBAK, B. Communuealth Edison Co. B3/07/15. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 1966B: 277. 24X Fiche: 90-265,83/07/13,8307210050.
- ---8307210052 Proposed Tech Spec Pages 1.2/2.2-1 & 3.6/4.6-4 re RCS. Evaluation of significant hazards consideration encl. \* Commonwealth Edison Co. 83/07/15. 4pp. 17668:279. 24X Fiche: 90-265, 83/07/15.8307210050.
- 8307220495 Discusses status of proposed mods to automatic depressurization sys.per NUREO-0737.Item II K. 3.18. Option 4 re timer installation described in GE BUR Owners Group response, selected for implementation. Mods listed.
  RYBAK.B. Commonwealth Edison Co. 83/07/18. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 17685;191. 24X Fichs: 50-000.83/07/18.8307220473.
- 830723044B Provides commitments on loakage monitoring. Floor drain leakage will be measured once every 4 h when reactor is at operating pressure. NRC will be notified within 24 h 1f action points exceeded.
  REED.C. Commonwealth Edison Co. 83/07/21. Office of the Secretary of the Commission. 2pp. 19701:176. 24X Fiche: 50-000. B3/07/21, B30725044B.
- Q. Inspection reports, IE Bulletins & correspondence
- ### 8305240276 Ack receipt of ### 830413 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-237/82-20, 50-249/82-21.50-254/82-16 & 50-265/82-18. 
  #### REPPLER. J. C. Region 3, Office of Director. ### 83/05/13. REED. C. Commonwealth Edison Co. 1p. 18548:067. 24X Fiche: 50-000, 83/05/13, 8308320394
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  URDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York. Inc. 154pp. 19363:293. 24X Fiche:50-000.83/07/11,8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list enci. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York Inc. 141pp. 17563:153. 24X Fiche:50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Caseous Effluent Releases of Radioactive 1-125 & 1-131 in Excess of NRC Limits," Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270, 24X Fiche: 50-000.83/07/14.8306270406.
- 8307200207 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 90~237/83-04, 50-249/83-05, 50-254/83-04 & 50-263/83-04. 8PEBSARD.R.L. Division of Engineering. 83/07/15. REED, C. Commonwealth Edison Co. 2pp. 17651:026. 24X Fiche: 50-000, 83/07/15, 8307200207.
- --8307200216 Responds to NRC 830409 ltr re violations noted in IE Insp Repts 50-237/83-06, 50-249/83-05, 50-284/83-04 & 50-265/83-04. NUTECH quality engineering procedures & util project unique instructions revised. REED.C. Commonwealth Edison Co. 83/06/08 SPESSARD, R. L. Division of Engineering, 131pp, 19651:029, 24X Fiche: 50-000, 83/07/15, 8307200207.
- 8307220463 Ack receipt of 830714 ltr informing NRC of steps taken to correct violations noted in IE Imsp Repts 50-237/83-12, 50-249/83-10.50-254/83-13 & 50-265/83-11.

  LITTLE.W.S. Region 3, Office of Director. 83/07/19, REED.C. Commonwealth Edison Co. 1p. 19684:325. 24X Fiche: 50-009.83/07/19, 8307220463.

- ~-830722047& Responds to NRC 830616 ltr re violations noted in lE Insp. Repts 50-237/83-12.50-249/83-10.50-254/83-13 & 50-265/83-11. Corrective actions: existing support configuration for pipe anchor R133 modified.
  FARRAR, D. L. Commonwealth Edison Co. 83/07/14. LETTLE, N. S. Region 3. Office of Director. 4pp. 19684: 326. 24X Fiche: 50-000, 83/07/19, 8307220463.
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util.per B30715 discussion.

  NORELIUG. C. E. Division of Project & Resident Programs. B3/07/22.

  REED. C. Commonwealth Edison Co. 2pp. 19791:169. 24X

  Fiche: 50-000, 83/07/22, 8307280084.
- --9307280102 Confirms request for NRC & util senior mgt masting on 830726 in Chicago. IL to discuss licensee regulatory performance & retationship w/NRC.
  REED.C. Commonwealth Edison Co. 83/07/11. DAVIS.8.A. Region 3, Dffice of Director. 1p. 19791:171. 24X Fiche: 50-000,83/07/22,8307280084.
- S. Reportable occurrences, LERs & related correspondence
- 8307220256 LER 83-009/01T-0:on 830630, isolation valves to core spray discharge pressure switches PS-2-1462C & PS-2-1462D for automatic depressurization sys low pressure pump running permissive found isolated & sealed LU/830712 ltr. LIHOU,H.; KALIVIANAKIS,N. Commonwealth Edison Co. 83/07/12, KEPPLER,J. Region 3. Office of Director. 4pp. 19684:207. 24X Fiche: 50-265,83/07/12,8307820258.
- 8307220446 Part 2( rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or compliants registered against subs products. Encl list of springs identified for Comm Ed only.

  LITKA: T. J. Elcen Metal Products Co. 83/07/15. KEPPLER, J. G. Region J. Office of Director. 26pp. 19686:086 24X Fiche: 50-000, 83/07/15, 8307220446.
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 8307110339 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19384: 262. 24X Fiche: 50-266, 83/06/24, 8307110339.
- ---B307110343 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1.3 reestimation of source term & EPIP 1.4 re radiological dose evaluation. Receipt form encl.

  FAY.C. H., KNDRR. J.E. Misconsin Electric Power Co. 83/06/15.
  DENTON, H. R. Office of Nuclear Reactor Regulation. Director. CLARK. R. A. Operating Reactors Branch 3. 3pp. 19384:263. 24X Fiche: 50-264, 83/06/24, 8307110339.
- --8307110348 Public version of revised emergency plan implementing procedures including Procedures EPIP 1.3 re-estimation of source term & EPIP 1.4 re-radiological dose evaluation. # Wisconsin Electric Power Co. 83/05/27. 64pp. 19384: 266. 24X Fichs: 50-266, 83/06/24, 8307110339.
- 8307110480 Ack receipt of 830A28 itr amending 830121 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-266/82-17 & 50-301/82-17. SpessARD.R.L. Division of Engineering. 83/07/06. BURNSTEIN.S. Wisconsin Electric Power Co. 1p. 19380:169. 24X Fiche: 50-266.83/07/06.8307110480.
- --8307110487 Suppls response to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17. Corrective actions: transient combustible control procedure developed, however implementation delayed until 830930. FAY.C. M. Wisconsin Electric Power Co. 83/06/28. KEPPLER, J. C. Region 3, Office of Director. 3pp. 19380:170. 24X Fiche: 50-266,83/07/06,8307110480.
- 8307260335 Itemizes clarification of encl to 830428 itr re request for App R fire protection exemptions, including revised description of proposed plant mods to Fire Zones I-4. FAY, C. M. Hisconsin Electric Power Co. 83/07/20. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. CLARK, R. A. Operating Reactors Branch 3 2pp. 19726:090. 24X Fiche: 50-266, 83/07/20, 8307260335.

## G. Adjudicatory correspondence

- B307120348 Memorandum & order requesting NRC assessment of eddy current testing techniques to ensure early detection & repair of significant degradation.

  SHDEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. B3/07/08.

  Office of the Executive Legal Director. 4pp. 19432:133. 24X

  Fiche: 50-246.83/07/08.8307120548.
- 8307120387 Order extending time until 830807 for Commission to act to review ALAB-719.
  CHILK.B. J. Office of the Secretary of the Commission. 83/07/08. Commissioners. 1p. 19432:141. 24X Fiche:50-266,83/07/08,8307120587.
- B307180176 Notifies of VR Harding employment at law firm per Disciplinary Rule 9-102. Harding will not participate in any case currently pending before NRC. RIDOWAY.D.A. Shaw, Pittman, Potts & Trowbridge. 83/07/13. MODRE, T. S. , JOHNSON, W. R. ; GDTCHY, R. L. Atomic Safety and Licensing Appeal Panel. 1p. 19355:068. 24X Fiche: 50-266.83/07/13.8307180176.
- --8307180183 Notifies of author employment at law firm per Disciplinary Rule 9-102. Author will not participate in any case currently pending before NRC.
  HARDING, V. R. Shaw, Pittman, Potts & Troubridge. 83/07/13.
  MOCRE, T. S. JUHNSON, W. R. , GOTCHY, R. L. Atomic Safety and Licensing Appeal Panel. 3pp. 19355:069. 24X Fiche: 50-266.83/07/13, 8307180176.
- B307180200 Notifies of VR Harding employment at law firm per Disciplinary Rule 9-102. Harding will not participate in any case currently pending before NRC.
  RIDGWAY.D.A. Bhaw, Pittman, Potts & Trowbridge. RIDGWAY,D.A. Wiscansin Electric Power Co. 83/07/13. MODRE,T.S., JOHNSON,W.R., OTCHY.R.L. Atomic Safety and Licensing Appeal Penel. 1p. 19353:141. 24X Fiche: 50-266,63/07/13,8307180200.
- --B307180205 Notifies of author employment at law firm per Disciplinary Rule 9-102. Author will not participate in any case currently pending before NRC.
  HARDING.R. Shaw. Fittmen, Potts & Trowbridge. B3/07/13.
  MODRE.T.B., JCHNSON, W. P., GOTCHY, R. L. Atomic Safety and Licensing Appeal Panei. 4pp. 19555:142. 24X Fiche: 50-266.83/07/13, B307180200.
- 8307180218 Informs that VR Harding formerly of OELD, will be associate in law firm general corporate practice Harding will not participate in any cases now pending before NRC. RIDOWAY.D.A. Shaw. Pittman. Potts & Trowbridge. 83/07/19. NRC No Detailed Affillation Given. 2pp. 19555:101. 24X Fiche: 30-266.83/07/13.8307180218.
- --8307180229 Informs that author will be associate in law firm general corporate practice & will not participate in any cases now pending before NRC Certificate of Svc encl.

  HARDING, V. R. Shaw, Pittman, Potts & Trowbridge, 83/07/13, NRC No Detailed Affiliation Given, 4pp. 19555:102, 24X Fiche: 50-266,83/07/13,8307180218.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307260439 Forwards Rev 1 to updated FSAR. FAY.C.W. Wisconsin Electric Power Co. 83/07/18. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. ip. 19778:328. 24X Fiche:50-246.83/07/18.8307260439.
- --8307270382 Rev 1 to updated FSAR.

  \* Wisconsin Electric Power Co. 83/06/30. 436pp. 19778:329. 24X
  Fiche: 30-266,83/07/19,8307260439.
- P. Operating license stage documents & correspondence
- B306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list enci.
  EISENHUT. D. G. Division of Licensing. B3/06/03. Vankee Atomic Electric Co. 10pp. 19543:116. 24X Fichs:50-000,83/06/03, 8306060070.
- 8307070021 Advises that installation & calibr of SA-ii monitors complete & monitors fully operational per TMI Item II.F.i.i. Integration of instruments into other plant operating & emergency procedures & operator training incomplete. FAY.C.W. Wisconsin Electric Power Co. 83/06/29. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19293:232. 24X Fiche: 50-266, 83/06/29, 83070700021.

- 8307070113 informs of no significant changes to electrical distribution sys described in FSAR which would affect degree of conformance w/QDC-17. Available info adequate to determine intent of GDC-17 re offsite power distribution sys.

  FAY. C. W. Wisconsin Electric Power Co. 83/06/30. DENTON: H. R. Office of Nuclear Reactor Regulation. Director. CLARK. R. A. Derating Reactors Branch 3. 1p. 19294:094. 24X

  Fiche: 50-266, 83/06/30, 8307070113.
- 8307150395 Forwards for review & comments, "Control of Heavy Loads (C-10), Point Beach Units 1 & 2," updated draft technical evaluation rept.

  CLARK, R. A. Operating Reactors Branch 3 83/06/30 FAY, C. W. Wisconsin Electric Power Co. 2pp. 19540:103. 24X Fiche: 50-266, 83/06/30, 8307150395.
- --B307070582 "Control of Heavy Loads (C-10), Point Beach Nuclear Plants Units I & 2," draft final technical evaluation rept.
  BQMBERGER, C., AHMED, N. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-382/383 DR. 83/06/17. SINCH, A., CHAN, T. NRC No Detailed Affiliation Given. 56pp. 19540:105. 24X Fiche: 50-266, 83/06/30, 8307130395.
- 8305270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307120344 Mod to application to amend License DPR-24 consisting of Tech Spec Change Request 90 re steam generator repair/ replacement.
  FAY.C. H. Wisconsin Electric Power Co. 83/07/05. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. CLARK.R. A. Operating Reactors Branch 3. 2pp. 19429:096. 24X Fiche: 50-246.83/07/05.8307120364.
- --B307120369 Proposed Tech Spec re repair/replacement of steam generators.

  \* Wisconsin Electric Power Co. B3/07/05. 3pp. 19429:098. 24X Fiche: 50-266, B3/07/05, 9307120364.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/06. Consolidated Edison Co of New York, Inc. 16pp. 19669: 254. 24X Fiche: 50-000. B3/07/06. B307060329.
- 8307130226 Requests extension until 830730 to complete response to questions from 820602 & 03 meetings re development of final radiological effluent Tech Specs submittal using meeting summary & draft Rev 3 to NUREC-0472 as guidance.
  FAY.C. W. Wisconsin Electric Power Co. 83/07/06. DENTON, H. R. Office of Nuclear Reactors Regulation. Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19473:288. 24X
  Fiche: 50-266. 83/07/06. 8207130286.
- 8307130220 Provides correction to Table 1.8-1, Item 13 of 830410 rev to Section 1.8 of updated FBAR re GA program. Commits to follow Reg Guide 1.146 for audits of in-plant activities per Generic Ltr 81-01.
  FAY.C.W. Wisconsin Electric Power Co. 83/07/07. KEPPLER.J.G. Region 3. Office of Director. 1p. 19474:346. 24X Fiche:50-266.83/07/07.8307130220.
- 8307140240 Forwards responses, per 830706 à 0623 requests for further technical & economic info, re replacement of steam generators. Confirmation that listed documents provided to NRC during 830423 meeting provided.
  FAY.C.W. Wisconsin Electric Power Co. 83/07/07. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. 19pp. 19524: OOI. 24X
  Fiche: 50-266, 83/07/07, 8307140260.
- --8307140268 "Present Status & Projected Future Progression of Steam Generator Tube Corrosion/Degradation at Point Beach Unit 1. Wisconsin Electric Power Co. Two Creeks. WI." MYERB, J. R. J.R. Associates, B3/06/08, 37pp. 19524:020, 24X Fiche. 50-266. 83/07/07.8307140260.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Syc list encl. EISENHUTED. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24% Fiche: 50-000, 83/07/08, 8307080169.

- B307250157 Confirms B30627 telcon re results of heat balance calculations of containment etmosphere temp calculations. Post-accident containment sampling procedure will be modified to include 10 minute sampling period. FAY.C.W. Wisconsin Electric Power Co. B3/07/12. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19706:108. 24X Fiche: 50-266.83/07/12.8307290157.
- 8307220356 Forwards "Nuclear Environ Qualification Test Program on Foxboro N-E10 Series Pressure Transmitters," Vols I-III. Results should be reviewed per qualification requirements of NUREO-0588 & 1067R30. 49.
  FAY.C.H. Wisconsin Electric Power Co. 83/07/15. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. NODNAN.V.S. Equipment Qualification Branch. 2pp. 19676:120. 24X Fiche: 50-266,83/07/15,8307220356.
- ~~8307220359 "Nuclear Environ Qualification Test Program on Forboro N-E10 Series Pressure Transmitters," Vols I-III. GAMBLIN.L., JOHNSON.F.R., ROBERTS, N. B. Wyle Laboratories, 45592-4, 83/05/18, 1620pp. 19676:123. 24X Fiche: 50-266, 83/07/15,8307220356.
- 8307270027 Forwards DES (NUREG-1011) re steam generator repair & notice of availability. Comments due within 45 days following FR publication. W/o DES.

  CLARK, R.A. Operating Reactors Branch 3. B3/07/15. Wisconsin. Univ. of. Oreen Day. 1p. 19811:201. 24X Fiche: 50-266.83/07/15, 8307270027.
- --8307270030 Notice of availability of DES (NUREG-1011) re-steam generator repair. CLARK,R.A. Operating Reactors Branch 3. 83/07/15. 7pp. 19811:202. 24X Fiche:50-266.83/07/15.8307270027.
- 8307270245 Forwards DES (NUREO-1011) & re repair of steam generators & notice of availability. DES not encl.
  CLARK.R.A. Decrating Reactors Branch 3. 83/07/15. FAY.C.W.
  Hisconsin Electric Power Co. 3pp. 19812:013. 24X
  Fiche: 30-266:83/07/15.8307270245.
- 8307270333 Forwards DES (NUREG-1011) re steam generator repair, notice of availability & request for comments by interested persons. Notice of availability only enci.
  CLARK.R.A. Operating Reactors Branch 3. B3/07/15. PERRIN.B. Environmental Protection Agency. 2pp. 19812:008. 24X
  Fiche: 30-266.83/07/15.8307270333.
- B307290464 Forwards safety evaluation re steam generator major component reglacement NRC environ review in progress. CLARK.R. A. Decrating Reactors Branch 3. B3/07/15. FAY.C.W. Misconsin Electric Power Co. 2pp. 19856: 320. 24X Fiche: 50-266.B3/07/15.B307290464.
- ---8307290469 Safety evaluation re steam generator major component replacement. \* Office of Nuclear Reactor Regulation, Director. 83/07/15. 50pp. 19856: 322. 24X Fiche: 50-266.83/07/15.8307290464.
- 8307250323 DRAFT ENVIRONMENTAL STATEMENT RELATED TO STEAM GENERATOR REPAIR AT THE POINT BEACH NUCLEAR FLANT UNIT NO. 1.
  Docket No. 50-266. (Wisconsin Electric Power Company)
  COLDBURN. T. G. Division of Licensing. NuREG—1011. 83/07/31. 43pp.
  19725:284. 24X Fithe:50-266:83/07/31.8307250323.
- Q. Inspection reports, IE Bulletins & correspondence
- B3071B0044 Forwards IE Insp Repts 50-266/B3-0B & 50-301/B3-0B on B30509-11 & 0609 & notice of violation. PAPERIELLO.C.U. Region 3. Office of Director. B3/07/01. BURSTEIN.S. Hisconsin Electric Power Co. 2pp. 19560; 234. 24X Fiche: 30-266.B3/07/01.B3071B0044.
- --8307180045 Notice of violation from insp on 830509-11 % 0609. PAPERIELLO.C. J. Region 3. Office of Director. 83/06/30. 2pp. 19540: 236. 24X Fiche: 50-266.83/07/01.8307180044.
- --B3071B0047 IE Insp Repts 50-266/83-08 & 50-301/83-08 on B30509-11 & O609. Noncompliance noted: failure to collect air samples on B30331 during reactor vessel head removal & cavity flood operations & to install BA-11 main steam line monitors. LOVENDALE, P. C. . OREGER, L. R. Region 3, Office of Director. B3/06/30. Spp. 19560:238. 24X fiche: 50-266, B3/07/01, B3071B0044.
- 8307110480 Ack receipt of B30628 ltr amending 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-266/82-17 & 30-301/82-17.

  SPESSARD.R.L. Division of Engineering. B3/07/06. BURNSTEIN.S. Wisconsin Electric Power Co. 1p. 19380:169. 24X Fiche: 30-266.83/07/06.8307110480.

- --8307110487 Suppls response to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 % 50-301/82-17. Corrective in IE Insp Repts 50-266/82-17 % 50-301/82-17. Corrective actions: transient combustible control procedure developed, however implementation delayed until 830930. however implementation delayed until 830930. FAY.C.S. Wisconsin Electric Power Co. 83/06/28. KEPPLER, J. G. FAY.C.S. Visconsin Electric Power Co. 83/06/28. KEPPLER, J. G. Region 3. Office of Director. 3pp. 19380:170. 24X Fiche: 50-266, 83/07/06, 8307110480.
- B306270401 IE Info Notice 83-46: "Common Mode Valva Failures Degrade Survey Recirculation Spray Subsystem." Byo list enci.

  Surry Recirculation of Emergency Preparedness & Engineering JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fithe: 50-000, B3/07/11, B306270401, York, Inc. 154pp. 19363:293.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E.L. Division of Emergency Preparadness & Engineering JORDAN, E.L. Bivision of Emergency Preparadness & Engineering Associated Edison Co. of New Response (Fost 830103). 83/07/12. Consolidated Edison Co. york, Inc. 141pp. 19563: 193. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of RAdioactive 1-125 & 1-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B301031. B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 30-000, B3/07/14, B306270406.
- 8307250371 Ack receipt of 830506 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-266/83-03 & correct violations noted in 1E Insp Repts 50-266/83-03 & 50-301/83-03. Mods to HVAC filter maint & testing program desirable to ensure radiation doses maintained ALARA. HIND. J.A. Division of Radiological & Materials Safety Programs. HIND. J.A. Division of Radiological & Materials Safety Programs. 83/07/20. BURSTEIN.S. Wisconsin Electric Power Co. 1p. 19704:002. 24X Fiche: 50-266, 83/07/20, 8307250371.
- R. Periodic operating reports & related correspondence
- 8307150046 Monthly operating repts for June 1983 W/830711 ltr.

  97 FAY.C.W. Misconsin Electric Power Co. B3/07/07. Office of Nuclear Reactor Regulation. Director. 9pp. 19548: 187. 24X Fiche: 50-266.83/07/07.8307150066.
- DUCKET 30-267 FORT ST. VRAIN NUCLEAR GENERATING STATION
  F. Security, medical, emergency & fire protection plans
- 8307290137 Forwards IE Insp Rept 50-267/83-11 on 830418-22.No noncompliance noted.
  MADSEN.g.L. Region 4, Office of Director. 83/06/16. LEE.D.R. Public Service Co. of Colorado. 2pp. 19821:061. 24X Fiche:50-267.83/06/16.8307290137.
- --8307290141 IE insp Rept 50-267/83-11 on 830418-22. No noncompliance noted Major areas inspected: licensee radiation protection operation program including mpt controls, exposure control, respiratory protection program & health physics instruments, respiratory protection program & health physics instruments of MILBORN, L., MURRAY, B., WESTERMAN, T.F. Region 4, Office of Director. 83/06/08. i3pp. 19821:063. 24X Fichs: 50-267,83/06/16, 8307290137.
- B30726021B Clarifies B30414 response to Generic Ltr 82-33 re emergency response facilities (ERF). Safety parameter display sys, Reg Outde i.97 instrumentation.control room design review & ERF activities will be completed by fourth (Dec 1985) refueling. BCEV.H.L. Public Service Co. of Colorado. 83/07/05. COLLINS. J. T., WAGNER.P. Region 4, Office of Director. 1p. 19727:242. 24% Fiche: 30-267.83/07/05.8307260218.
- 8307260338 Forwards control room design review program plan.per Suppl 1 to NUREG-0737 (Generic Ltr 82-33) re emergency response capability as followup to estimated schedule contained in 830414 ltr.

  BREV-H.1. Public Service Co. of Colorado. 83/07/13. CDLLINS.J.T. Region 4. Office of Director. 1p. 19726:011. 24% Fichs: 50-267.83/07/13.8307260338.
- --8307260343 "Control Room Design Review Program Plan." 4 Public Service Co. of Colorado. 83/07/13. 58pp. 19726; 012. 24X Fiche: 50-267, 83/07/13. 8307260338.
- J. Insurance & indemnity information
- 8307260474 Advises that 830328 ltr should be considered request for exemption from 1006830.54(w), "Excess Property Insurance," rather than annual rept. Addl insurance coverage would result in needless addl costs.
  WAREMBOURGO, B. W. Public Service Co. of Colorado. 83/06/30. Office of the Service of the Commission. 2pp. 19733:352. 24% Fiche: 50-267.83/06/30.8307260494.

- 8307190103 Discusses results of investigation of circumstances surrounding util compliance w/10CFR30.54(W) re property surrounding util compliance w/10CFR30.54(W) re property surrounding util response to 830620 memo. Util admonished to insurance, in response to 830620 memo. Util admonished to submit timely examption requests.

  SUMMING. T. Region 4. Defice of Director. 83/07/07. KERR, G. W. Office of State Programs, Director. 3pp. 19634:250. 24X Office 50-267.83/07/07.8307190103.
- --8307190105 Requests exemption from requirements of 10CFR50.54(W) re excess property insurance.

  WAREMBOURG.D.W. Public Service Co. of Colorado. 83/06/30.

  URBEMBOURG.D.W. Public Service Co. of Colorado. 83/06/30.

  Office of the Secretary of the Commission. 2pp. 19634:253. 24X

  Fiche: 50-267, 83/07/07, 8307190103.
- P. Operating license stage documents & correspondence
- 8307110616 Monthly notice of amends to OLs involving NSHC issued since 830523. CLARK.R.A. Operating Reactors Branch 3. 83/06/14, 26pp. 19391:132. 24X Fiche: 50-000, 83/06/14, 8307110616.
- 8307180446 Forwards monthly FR notice of amends to OLs involving NBHC. \* Office of Nuclear Reactor Regulation, Director. 83/06/15. WHRIG.R.E. Florids Power & Light Co. 2pp. 19641:347. 24X Fichs: 50-000, 83/06/15, 8307180446.
- --8307190001 Monthly notice of amends to DLs involving NSHC. CLARK, R. A. Operating Reactors Branch S. 83/06/07. 15pp. 19641:349. 24% Fiche:50-000:83/06/15.8307180446.
- B307040256 Advises that matl receipt progressed w/o incident, per B30620 teleon. MARCHBOURG, D. W. Public Service Co. of Colorado. B3/06/20. COLLING, J. T. Region 4, Office of Director. ip. 19239; 291. 24X Fiche: 50-267, B3/06/20, B307060256.
- 8307060244 Advises that matl receipt progressed w/o incident per 830622 telcon. UAREMBOURG, D. W. Public Service Co. of Colorado. B3/06/22. CULLING. J. T. Region 4. Defice of Director. 1p. 19239: 274. 24X Fiche: 50-247.83/06/22.8307060244.
- 8307050069 Forwards payment of fees for review of 830520 application to amend Tech Spec Bactions 4.5 & 5.3. HAREMBOURG.D. Public Bervice Co. of Colorado. 83/06/23. HAREMBOURG.D. Public Bervice Co. of Colorado. 19220: 173. 24X COLLING.J.T. Region 4. Diffice of Director. 2pp. 19220: 173. 24X Fiche: 50~267.83/06/23,8307050069.
- 8307060132 Requests FR publication of notice of consideration of issuance of amend to License BPR-34 & proposed no significant hazards consideration determination & significant hazards consideration determination & opportunity for hearing re snubber testing requirements. AMDEN, C. Region 4. Diffice of Director. 83/06/28. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19252:240. 24X Fichs: 50-267.83/06/28.8307060132.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D.G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390; 317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in B13.6vc list encl. Consolidated EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fichs: 50-000, B3/07/06, 8307060329.
- B3070B0169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fiche: 30-000, 83/07/08, 8307080169.
- 8307180273 Forwards draft agenda for meeting on proposed Tech Spectanges re instrument setpoints as result of review of 801001 application to amend Tech Spect.

  MADBEN, O.L. Region 4, Office of Director. 83/07/11. LEE, O.R. Public Service Co. of Colorado. dpp. 19556: 162. 24X Piche: 50-267, 83/07/11, 8307180273.
- --8307180276 Proposed Tech Spec changes assuring operability of plant protective sys limiting conditions for operation defining trip setpoint operability.

  \*\*\*Public Service Co. of Colorado. 83/07/11. 19pp. 19856:168. 24X Fiche: 50-267,83/07/11,8307180273.

- 8307190156 Discusses status of facility licensing actions. Considerable amount of time devoted to Suppl 1 to NUREO-0737 during last reporting period.

  WAGNER, P. C. Region 4, Office of Director. 83/07/11. MADSEN, G. L. Region 4. Office of Director. 2pp. 19636: 256. 24X Fiche: 50-267, 83/07/11, 8307190156.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307120255 Forwards IE Insp Rept 50-267/83-06 on 830228-0304.No noncompliance noted. MADSEN,G.L. Region 4. Office of Director. 83/05/23. LEE.O.R Public Service Co. of Colorado. 2pp. 19419;343. 24X Fiche: 50-267,83/05/23,8307120255.
- --8307120259 IE Insp Rept 50-267/83-06 on 830228-0304. No noncompliance noted Major areas inspected: nadwaste program, including liquid & gaseous radioactive effluent releases, records & repts of radioactive effluent & solid radwasts.
  HOLLEY, M. L., MURRAY, B., WESTERMAN, T. F. Region 4, Office of Director. 83/05/13, 13pp. 17419:345. 24X Fiche: 50-267,83/05/23,8307120255.
- 8307120408 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators. Procedures incorporated into annual preventive maint program. No check valves in discharge sys meeting bulletin criteria.

  LEE.O.R. Public Bervice Co. of Colorado. 83/06/08. COLLINS, J. T. Region 4. Office of Director. 4pp. 19429: 359. 24X

  Fiche: 50-267, 83/06/08, 8307120408.
- 8307050119 Forwards IE Insp Rept 50-267/83-12 on 830516-20 & notice of violation.

  MADSEN G. L. Region 4, Office of Director. 83/06/16. LEE.O.R. Public Service Co. of Colorado. 2pp. 19220:035. 24X Fiche: 50-267,83/06/16
- --8307050121 Notice of violation from insp on 830514-20.

  \* Region 4: Diffice of Director. 83/06/16. 2pp. 19220:037. 24X Fiche: 50-267.83/06/16.8307050119.
- --8307050129 IE Insp Rept 50-267/83-12 on 830516-20. Noncompliance noted: failure to follow Procedure SRS. 4.5-M, failure to review access control procedures & failure to follow Procedure G-13.

  REDANG, R. T., MCCRAY, B. L., WESTERMAN, T. F. Region 4, Office of Director. 83/06/14. 15pp. 19220:039. 24X Fiche: 50-267, 83/06/16, 8307030119.
- 8307290137 Forwards IE Insp Rept 50-267/83-11 on 830418-22. No noncompliance noted.

  MADSEN.G.L. Region 4. Office of Director. 83/06/16. LEE.O.F. Public Service Co. of Colorado. 2pp. 1982: 061. 24X Fiche: 50-267.83/06/16.8307290137.
- --B307270141 IE Insp Rept 50-267/B3-11 on B30418-22. No noncompliance noted, Major areas inspected: licensee radiation protection operation program, including mgt controls, exposure control, respiratory protection program & health physics instruments. WILBORN, L., MURRAY, B., WESTERMAN, T.F. Region 4, Office of Director. B3/06/08, 13pp. 19821:063. 24X Fiche: 50-267,83/06/16,8307290137.
- 8307150133 Forwards IE Insp Rept 50-267/83-15 on 830501-31 & notice of violation.

  MADSEN, G. L. Region 4, Office of Director. 83/06/24. LEE, D. R. Public Service Co. of Colorado. 2pp. 19535:213. 24X Fiche: 50-267, 83/06/24, 8307150133.
- --B307150135 Notice of violation from insp on B30901-31. \* Region 4: Office of Director. B3/06/24. 2pp. 19535:215. 24X Fiche: 50-267: B3/06/24, B307130133.
- --B307150140 IE Insp Rept 50-267/83-15 on 830501-31. Noncompliance noted: failure to follow preventative maint procedures on emergency diesel generator breakers.

  DICKERSON, M. W., PLUMLEE, Q. L., WESTERMAN, T. F. Region 4, Office of Director. B3/06/16. 13pp. 19535:217. 24X Fiche: 50-267, 83/06/24, 8307150133.
- 8307140157 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," for reproduction & distribution.
  HAREMBOURG, D. Public Bervice Co. of Colorado. 83/06/27. NRC No Detailed Affiliation Given. 1p. 19514:254. 24X Fiche: 50-267,83/06/27,8307140157.
- B307120390 Ack receipt of 830407 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-09.

  MADBEN.G.L. Region 4. Office of Director. 83/06/28. LEE, D. R. Public Service Co. of Colorado. 1p. 19426: 314. 24X Fiche: 50-247, 83/06/28, 8307120390.

- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 134pp. 19363:293. 24X Fiche: 50~000.83/07/11.8306270401.
- B306270404 IE info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Syc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8307290398 Responds to NRC 830616 ltr re violations noted in IE Insp Rept 50-267/83-12 Corrective actions:responsibility for recording temps in warehouses assigned to senior storekeeper. MAREMBOURG, D. N. Public Service Co. of Gulorado, 83/07/13, COLLINS. J.T. Region 4, Office of Director. 3pp. 19705:140. 24X Fiche: 50-267,83/07/13,8307250398.
- 8306270406 IE Info Notice 83-48, "Caseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103), 83/07/14. Consolidated Edison Co. of New Yort, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14,8306270406.
- R. Periodic operating reports & related correspondence
- 8307050002 Forwards "Fort St Vrain Initial Approach to Power Tests (B-Series)," Interim Startup Rept 27 for 830223-0522. WAREMBOURG, D. Public Service Co. of Colorado. 83706/21. COLLINS.J.T. Region 4. Office of Director. 1p. 19192:121. 24X Fiche: 50-267,83706/21,8307050002.
- --8307050008 "Fort St Vrain Initial Approach to Power Tests (B-Series),"
  Interim Stantup Rept 27 for 830223-0522.

  \* Public Service Co. of Colorado. 83/05/22. 10pp. 19192:122.
  24X Fiche: 50-257:83/06/21,8307050002.
- S. Reportable occurrences, LERs & related correspondence
- 8307010041 Updated LER 80-041/03x-2: on 800724, one of 12 helium circulator seal malfunction pressure differential switches discovered w/trip point outside Tach Spec limits. Caused by dirt accumulation in electrical switches. W/830622 ltr. WAREMBOURG. D. Public Service Co. of Colorado. 83/06/22. COLLINS. J. T. Region 4, Office of Director. 8pp. 19169:030. 24X Fiche: 50-267,83/06/22,8307010041.
- 8307030106 Revised LER 83-013/03L-1:on 830309, phase-to-ground fault at unit auxiliary transformer rendered transformer inoperable. Caused by arring of transformer bushing due to leaking cooling water tube in isolated phase bus duct.th/830824 ltr. HAREMBURG.D. Public Service Co. of Colorado. 83/06/24. COLLINS.J.T. Region 4. Office of Director. 6pp. 19199:396. 24X Fiche: 50-267, 83/06/24, 8307050106.
- 8307120087 LER 83-020/03L-0: on B30604, emergency feedwater header supply to Loop I helium circulator turbine water drive (solated & bearing water make up pump taken out of svc. Caused by fleritallic gasket failure due to normal wear. W/B30701 ltr. MAREMBOURG, D. Public Bervice Co. of Colorado. B3/07/01. CCULINS. J.T. Region 4, Office of Director. Spp. 19423:081. 24X Fiche: 50-267, 83/07/01, 8307120087.
- B307190010 LER B3-022/03L-0: on B30610, Class I hydraulic shock suppressor found inoperable. Caused by faulty rod seal allowing gradual loss of operating fluid. Snubber replaced. W/B30708 itr.
  NOVACHEK, F. J., WAREMBOURG, D. Public Service Co. of Colorado. B3/07/08. COLLINS, J. T. Region 4. Office of Director. 5pp. 19635:049. 24X Fiche: 50-267, B3/07/08, B307190010.
- U. Congressional/Executive Correspondence
- 8307270047 Forwards monthly FR notice of consideration of issuance of amends to OLs involving NSHC determination & opportunity for hearing.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

  83/06/22. STAFFORD.R.T., SIMPSDN.A. Senate, Environment & Public Works. UDALL.M.K. House of Rep., Interior & Insular Affairs. 2pp. 19811:018. 24X Fiche: 50-000, 83/06/22, 8307270047.
- --B307270050 Monthly notice of consideration of issuance of amends to CLs involving NSHC determination & opportunity for hearing. CLARK.R.A. Operating Reactors Branch 3. 83/04/07. 15pp. 19811:020. 24X Fiche:50-000,83/04/22.8307270047.

- DOCKET SO-269 OCCNEE NUCLEAR STATION, UNIT 1 F. Servrity, medical, energency & fire protection plans
- 8307140164 Advises that objectives & scenario for emergency exercise scheduled for Apr 1983 discussed w/C Jennings.ger util 830118 & 0214 ltrs 970HR J P Division of Emergency Preparedness & Materials Safety. 83/03/29 TUCKER.H B. Duke Power Co 1p. 19523:182. 24X Fiche 50-269.83/03/27.8307140164
- B307140244 Refers to B30324 conversation be emergency electise training requirements for NRC 5 contract personnel. Training 6 experience for evaluation team members documented.
  STORM J P Division of Emergency Preparedness 6 Materials Safety.
  B3/03/29 TUCKER.M B. Duke Power Co 2pp. 19323:059, 24X Fiche: 30-269, 83/03/29. 8307140244
- 8307140252 Advises that LASL will revisit Facilities to gather addlene info in identifying plant vital areas, per mods to NRC vital area analysis programs. Safeguards info gathered uil) be protected per 1007873 21.

  LEMIS.R C Division of Project & Resident Programs. 83/06/29.

  TUCKER.H B. Dute Power Co. 1p. 19523:043. 24x

  Fiche. 50-269. 83/06/29. 8307140252
- 830714004B Forwards fees for amends to Licenses DPR-38, DPR-47, DPR-55 & NRF-9 re location of emergency operating facility & addition of license condition for verifying acceptability of Model D2 steam generator design mod, respectively, RUTHERFORD, N.A. Dute Power Co. 83/07/08, D100S, R.M. License Fee Management Branch. lp. 19514-227. 24X Fiche: 50-000, 83/07/08, 830714004B
- B307250300 Requests elemption from standby shutdown facility fire protection requirements re source range monitors & steam generator pressure indication.per 830608 rule.Design meets 10CFR30.App 8.Section 111 G 3 & III.L requirements. TUCKER.H B. Dute Power Co. 83/07/15. DeNTON.H.R. Office of Nuclear Reactor Regulation, Director. STDL2.J.F. Operating Reactors Branch 4 2pp. 19701:350. 24% Fiche:50-269,83/07/15.8307250300.
- 8307250101 Releases public version of revised crisis mgt plan for nuclear stations.

  FELTON, J. M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19737: 287. 24% Fiche: 50-000, 83/07/19.
- --8307250110 Public version of Rev 9 to crisis mgt plan for nuclear stations.W/830630 ltr. VAUGMM.T.S.. TUCKER.M.B. Dute Power Co. 83/06/15. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 127pp. 19737:288. 24X Fiche 50-000.83/07/19.8307250101
- B307250717 Releases public version of revised crisis mgt plan implementing procedures.
  FELTON J M Division of Rules and Records 83/07/19. Document Hanagement Branch. ip. 19719:314. 24X Fiche:50-000.83/07/19. B307220717.
- --8307250730 Forwards public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3 2 re crisis news group plan & Rev 5 to Procedure 5.3 3 re administrative & logistics Rev 3 to Procesore 3.3 3 Fe doministrative & 10913-2125 support group TUCKER.H.B. Duke Power Co. 83/05/02. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19719:315. 24X Fiche 50-000,83/07/19.8307250717
- --8307250744 Public version of Rev 1 to Crisis Mgt Plan Implamenting Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. 2 Dute Power Co. 83/03/16. 186pp. 19719.317. 24X Fiche 50-000.83/07/19.8307250717.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307070087 FBAR 1982 update for Oconse Units 1.2 t 3.W/B30630 ltr. TUCKER.H B. Dute Power Co. 83/07/01. DENTON.H R. Office of Nuclear Reactor Regulation, Director. STOL2, J.F. Operating Reactors Branch 4. 2009p. 19298:281. #4X Fichs:30-269.83/07/01.8307070087.
- P Operating license stage documents & correspondence
- 8307180262 Forwards FR notice of consideration of issuance of amend to License DPR-38 % proposed NSHC determination % opportunity for hearing re 830519 amend application for Cycle 8 reload SUERNAN, J. F. Dperating Reactors Branch 4 83/06/27, TUCKER, H. B. 8307180262

- --8307180268 Notice of consideration of issuance of amend to License DPR-38 & proposed NBHC determination & opportunity for hearing re Cycle B reload.
  STOL7.J.F. Operating Reactors Branch 4. B3/06/27. 8pp.
  19564:211. 24X Fiche: 50-249, 83/06/27, 8307180262.
- 8307110226 Advises that info re proposed reactor coolant pump trip criteria, per TMI Action Plan Item II.K.3.5, will be provided by end of Jul 1983.
  TUCKER.H.8. Duke Power Cg. 83/06/29. DENTON, H.R. Office of by end of Jul 1983. TUCKER.H.B. Duke Power Co. B3/06/27. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. BTOLZ.J.F. Operating Reactors Branch 4. 1p. 19380:033. 24X Fiche.50-269.83/06/29,8307110226.
- B307080362 Forwards eight oversize drawings, inadvertently omitted from util B30624 response to NRC B30523 request for addl info re proposed reracking of spent fuel pool. Aperture cards are available in PDR.
  TUCKER.H.B. Duke Power Co. B3/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZIJ.F. Operating Reactors Branch 4. 2pp. 19347:246. 24X Fiche: 50~269, B3/06/30, B307080362.
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list enct. EISENHUTD, D. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000,83/07/03,8306270397.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 30-000, 83/07/06, 8307060329.
- B3070B0169 Generic Ltr 83-28 to all liconsees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISCNHUT.D.O. Division of Licensting. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 83070B0169.
- B307140049 Forwards fees for amends to Licenses DPR-38.DPR-47.DPR-55 & NPF-9 re location of emergency operating facility & addition of license condition for verifying acceptability of Model D2 steam generator design mod, respectively. RUTHERFORD.N.A. Duke Power Co. B3/07/08. DIGOS,R.M. License Fee Management Branch. ip. 19514:227. 24x Fiche: 50-000,83/07/08. B307140048.
- 8307190267 Requests corrections to updated FBAR, consisting of deletion of Tables 3.9-35 through 3.9-38, Table 3.9-44 & Figures 3.9-15 through 3.9-17.

  REAVIS.J. Duke Power Co. 83/07/11. NRC No Detailed Affiliation Given. 1p. 19629:275. 24X Fiche: 50-269, 83/07/11, 8307190267.
- 8307150244 Forwards proprietary "Gadolinia-Bearing Lead Test Assemblies Design Rept." Info includes design, testing & analysis for five lead test assemblies w/12 gadolina-bearing fuel rods to be loaded in Cycle 8. Rept withheld (ref 10CFR2. 790). TAYLOR. J. H. Babcock & Wilcox Co. 83/07/12. SUCRMANN, J. Office of Nuclear Reactor Regulation. Director. 8pp. 19532:234. 24X Fich: 50-249, 83/07/12, 8307150244.
- 8307190835 Supplemental application for amend to License DPR-3B, proposing Tech Spec changes to support full-rated power during Cycle 8 & revising BAW-1774, "Cycle 8 Reload Rept," to reflect implementation of NUREG-0630 in LOCA analysis.

  TUCKER, H. B. Duke Power Co. 83/07/13, BENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOL2, J. F. Operating Reactors Branch 4. 3pp. 19636:075, 24X Fiche: 50-269, 83/07/13, 8307190135.
- --B307190137 Revised proposed Tech Spacs, supporting full-rated power during Cycle 8.

  \* Duke Power Co. B3/07/13. 20pp. 19636:078. 24X
  Fiche: 50-269,83/07/13,8307190135.
- --8307190139 Revised pages to "Oconee Unit 1 Cycle 8 Reload Rept." Util description of work scope for justification of use of FLECSET encl.

  \* Babcock & Wilcox Co. BAH-1774 EBR 83/07/13
  - -Babcock & Wilcox Co. BAW-1774 ERR. 83/07/13. 7pp. 19636:098. 24X Fiche:50-269,83/07/13,8307190135.
- B307220636 Summary of B3060B appeal meeting w/utils & Bechtel restandby shutdown sys monitors for source range flux & steam generator pressure. Viewgraphs encl.
  BIRKEL,R.A. Licensing Branch 4. 83/07/15. Licensing Branch 4. 32pp. 19697:045. 24X Fiche 50-000. 83/07/15, 8307220636.

- 8307260304 Forwards proposed response dates to concerns in NRC 830608
  Itr providing approval of proposed wide-range hot leg level/
  reactor vessel head monitoring concept for coolant inventory
  tracking w/pumps off.
  TUCKER.H. B. Dute Power Co. 83/07/18 DENTON.H.R. Office of
  Nuclear Reactor Regulation, Director. STOLZ.J.F. Operating Reactors
  Branch 4. App. 19726:070. 24X Fiche: 50-269, 83/07/18.8307260304.
- 8307250117 Advises that mods to relief & safety valve discharge piping will be implemented during next refueling outage schoduled for early 1985, per 830121 ltr re NUREG-0737, Item II.D. 1, "Performance Testing of Reactor Relief & Safety Valves."
  TUCKER.H. B. Duke Power Co. 83/07/19, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 870LZ, J.F. Operating Reactors Branch 4. 1p. 19706:071. 24X Fiche, 50-269, 63/07/19, 8307250117.
- 8307260412 Forwards response to 830307 request for add1 info re natural circulation cooldown procedures & supporting analytical bases. Natural circulation cooldown unlikely undertaking at facility. Procedures & training provide appropriate guidance TUCKER.H. B. Duke Power Co. 63/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. STOLZ.J.F. Operating Reactors Branch 4. 5pp. 19733:138. 24X Fiche: 50-267.83/07/19.8307260412.
- --8307260417 "Planned Initiation of Natural Circulation & Natural Circulation Cooldown." \* Duke Power Co. 81/12/22. 17pp. 19733:143. 24X Fiche: 50-269,83/07/19,8307260412.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140336 Informs that liquid samples spiked w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analyzed for tritium, Sr-89 & Sr-90 content within 60 days.

  LEWIS.R.C. Division of Project & Resident Programs. 83/02/07. TUCKER.H.B. Duke Power Co. ip. 19325:120. 24X

  Fiche: 30-000, 83/02/07, 8307140336.
- 8305270612 Ack receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-06, 50-270/83-06 & 30-287/83-06.

  DANCE,H.C. Division of Project & Resident Programs. 83/04/25. TUCKER,H.B. Duke Power Co. 1p. 18646:248. 24X Fiche: 80-269,83/04/25,8305270612.
- --8305270627 Responds to NRC 830307 ltr re violations noted in 1E Insp Repts 50-269/83-06,50-270/83-06 & 50-287/83-06. Corrective actions: cited door locked closed immediately after being found open. TUCKER.H.B. Duke Power Co. 83/04/06. O'REILLY, J. P. Region 2, Office of Director. 2pp. 18646:249. 24X Fiche: 50-269,83/J4/25, 8305270612.
- --8305270630 Forwards IE Insp Rept 50-269/83-06, 50-270/83-06 & 50-287/83-06 on 830111-0210 & notice of violation. DANCE: M. C. Division of Project & Resident Programs. 83/03/07, TUCKER: M. B. Duke Power Co. 2pp. 18646: 251. 24% Fiche: 50-269, 83/04/28, 8305270612.
- --8305270434 Natice of violation from insp on 830111-0210. \* Region 2, Office of Director. 83/03/07. 1p. 18444:253. 24X Fiche: 50-249, 83/04/25, 8305270612.
- --8305270643 IE Insp Repts 50-269/83-06.50-270/83-06.50-287/83-06 on 830111-0210. Noncompliance noted: whescorted entrance to high radiation area.

  BRYANT, J., FALCONER, D. Region 2. Office of Director.
  IGNATONIE, A. J. Division of Project & Resident Programs. 83/03/04.
  10pp. 18646: 254. 24X Fiche: 50-269, 83/04/25, 8305270612.
- 8307140067 Responds to IE Bulletin 83-03 re check valve failures in diesel generator water cooling sys. Valve CCM-284 in standby shutdown facility only affected valve per Item 4. Item 5 response will be submitted within 90 days of checkout. TUCKER.H.B. Duke Power Co. 83/06/20, D'REILLY.J.P. Region 2, Office of Director. 4pp. 19514:097. 24X Fiche: 30-269, 83/06/20, 8307140067.
- 8307140026 Forwards IE Insp Repts 50-269/83-15, 50-270/83-15 & 50-287/83-15 on 830411-0510. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/22. TUCKER, H. B. Duke Power Co. 2pp. 19514:196. 24X Fiche: 50-269, 83/06/22, 8307140026.
- --8307140030 IE Insp Repts 50-269/83-15, 50-270/83-15 & 50-287/83-15 on 830411-0510. No noncompliance noted Major areas inspected operations, maint activities, surveillance & LER review.
  BRYANT, J., FALCONER, D. Region 2, Office of Director.
  BROWNLEE, V. L. Division of Project & Resident Programs. 83/06/21.
  App. 19514: 198. 24X Fiche: 50-269, 83/06/22, 8307140026.

- 8307040275 Responds to 830402 ltr re violations & proposed imposition of civil penalties noted in IE. Insp. Repts. 50-269/83-11. 50-270/83-11 & 50-287/83-11 Corrective action: procedures per TMI Item I.C & reviewed.

  TUCKER.H.B. Duke Power Co. 83/07/01 Director's Office, Office of Inspection and Enforcement. 21pp. 19238:352. 24% Fichs: 50-269.83/07/01.8307060275.
- 8307130263 Forwards revised request for relief from ASME Section XI inservice inap requirements (hydrostatic) supplementing 821004 request No addl license fees provided.

  TUCKER, H. B. Duke Power Co. 83/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19508 246. 24X Fiche: 50-269.83/07/06.8307130263.
- B306270401 (E Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363.293. 24X Fiche: 50-000.83/07/11.8306270401.
- B306270404 IE Info Notice B3-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche.50-000.83/07/12,8306270404.
- 8306270406 LE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of OA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consulidated Edison Co. of New York. Inc. 114pp. 19718:270. 24X Fiche: 50-000,83/07/14,8306270406.
- S. Reportable occurrences, LERs & related correspondence
- 8307120613 LER 83-011/03L-0: on 830525, lockout indication received for startup transformer CT3. Cause unknown CT3 energized. W/830624 ltr. PETTY.J.C., TUCKER.H.D. Duke Power Co. 83/06/24. D'REILLY, J.P. Region 2. Office of Director. 3pp. 19433:014. 24X Fiche: 50-269, 83/06/24, 8307120613.
- B307120289 RO: on B30623, visual inspirevealed three broken holddown springs. Investigation incomplete RO 269/B3-13 will be submitted by B30721.

  TUCKER.R.B. Duke Power Co. 83/07/01. O'REILLY, J.P. Region 2, Office of Director. 1p. 19424.098. 24X Fiche: 50-269, B3/07/01. B307120289.
- 8307120609 RO: on 930525, fire barrier penetrations found nonfunctional Caused by design deficiency. Fire watch posted, penetrations repaired & procedures revised TUCKER.H.B. Duke Power Co. B3/07/01. O'REJLLY, J. P. Region 2, Office of Director. 2pp. 19433:012. 24X Fiche: 50-269, 83/07/01, 8307120609.
- B307290054 LER B3-014/0)T-0: on B30705, while determining water influx, valves ICCW-1 & CCW-8 opened, rendering emergency condenser circulating water sys inogenable. Caused by personnel error. Valves closed W/B30719 ltr.
  PETTY, J. C., TUCKER, M. B. DUKE Power Co. B3/07/19 O'REILLY, J. P. Region 2. Office of Director. 3pp. 19821:010. 24X Fiche: 50-269, B3/07/19, B307290054.
- 8307270033 LER 83-013/01T-0: on 830623, during video insp of fuel assemblies, three or four broken hold-down springs found. Caused by component failure due to fatigue induced cracking at existing flaw Springs will be replaced W/830721 ltr PETTY.J.C. TUCKER.H.B. Duke Power Co. 83/07/21. O'REILLY, J.P. Region 2. Office of Director. 4pp. 19815-387. 24X Fiche: 50-269,83/07/21. 8307290033.
- DOCKET 50-270 OCCNEE NUCLEAR STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8307140164 Advises that objectives & scrnario for emergency exercise acheduled for Apr 1783 discussed w/C Jennings.per util 830118 & 0214 ltrs.

  8TOHR, J. P. Division of Emergency Preparedness & Materials Safety. 83/03/27. TUCKER.H.B. Duke Power Co. 19. 17523:182. 24X Fiche: 50-269.83/03/29.8307140164.
- 8307140244 Refers to 830324 conversation re emergency exercise training requirements for NRC & contract personnel Training & experience for evaluation team members documented.

  STOHR, J. P. Division of Emergency Preparedness & Materials Safety, 83/03/29. TVCKER, H. B. Duke Power Co. 2pp. 19523:059, 24X Fiche: 50-269, 83/03/29, 8307140244.

- 8307140297 Advises that LASL will revisit facilities to gather add! info in identifying plant vital areas, per mods to NRC vital area analysis programs Safeguards info gathered will be protected per 100FR73.21

  LEMIS-R C Division of Project & Resident Programs. 83706/29. TUCKER-M B Duke Power Co Ip 19923.043, 24X

  Fiche: 50-269.83706/29.8307140292.
- 8307140049 Forwards fees for amends to Licenses DPR-38, DPR-47, DPR-55 & NPF-9 re location of emergency operating facility by addition of license condition for verifying acceptability of Model DP steam generator design mod/respectively. RUTHERFORD.N A Dute Power Co. 83/07/08. DIGGS,R.M. License Fee Management Branch. 1p. 19514:227. 24X Fiche.50-000.83/07/08.
- 8307250300 Requests exemption from standby shotdown facility fire protection requirements re source range monitors & steam generator pressure indication, per 830608 rule. Design meets 10CFR50. App R. Section III 6, 3 & 111. L. requirements. TUCKER.H. 8. Dute Power Co. 83/07/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 2pp. 19701:350. 24X Fische: 50-269.83/07/15.8307250300.
- 8307250101 Releases public version of revised crisis mgt plan for nuclear stations. FELTON.J.H. Division of Rules and Records. 83/07/19. Documen Management Branch. 1p 19737:287. 24X Fiche: 50-000:83/07/19, 8307250101
- --B307250110 Public version of Rev 9 to crisis mgt plan for nuclear stations H/830630 ltr. VAUGHN.T.S., TUCKER.H.B. Duke Power Co. 83/06/15, DENTGN.H.R. Office of Nuclear Reactor Regulation, Director, 127pp. 19737:288. 24% Fiche: 50-000, 83/07/19, 8307250101.
- B307250717 Releases public version of revised trisis mgt plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. B3/07/19. Document Management Branch. lp. 19719:314. 24X Fiche:50-000,83/07/19, 8307250717.
- --8307250730 Forwards public version of Rev 1 to Crisis Mot Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group.

  TUCKER, H. B. Duke Power Co. 83/05/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19719:315. 24x Fiche: 50-000, 83/07/19, 8307250717.
- --B307250744 Public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. \* Dute Power Co. 83/03/16. 186pp. 19719:317. 24X Fiche 50-000.83/07/19.8307250717.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307070087 FSAR 1982 update for Oconee Units 1.2 & 3.4/830630 ltr.
  TUCKER,H 8. Duke Power Co. 83/07/01. DENTON,H.R. Office of
  Nuclear Reactor Regulation, Director. STOL2,J.F. Operating Reactors
  Branch 4. 200pp. 19298:281. 24X Fiche: 50~269,83/07/01,8307070087.
- P. Operating license stage documents & correspondence
- 8307110226 Advises that info re proposed reactor coolant pump trip criteria.per IMI Action Plan Itam II.K. 3.5.will be provided by end of Jul 1983.
  TUCKER.H B Duke Power Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. STOL7, J.F. Operating Reactors Branch 4 1p. 19380:033. 24X Fichs 50-269, 83/06/29, 8307110226.
- 8307080362 Forwards eight oversize drawings, inadvertently omitted from util 830624 response to NRC 830523 request for addl info re proposed reracking of spent fuel pool. Aperture cards are available in PDR TUCKER, H B Duke Power Co. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19347:246. 24X Fiche: 50-267, 83/06/30, 8307080362.
- B306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svr list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp 19390:317. 24X Fachs: 50-000,83/07/05,8306270397.

- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:294. 24X Fichs: 50-000,83/07/06,8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for Di. & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fichs: 50-000, 83/07/08, 8307080169.
- B30714004B Forwards fees for amends to Licenses DPR-38.DPR-47.DPR-55 & NPF-9 re location of emergency operating facility & addition of license condition for verifying acceptability of Model D2 steam generator design modirespectively.
  RUTHERFORD.N.A. Duke Power Co. 83/07/08. DIGGS.R.M. License Fee Management Branch. 1p. 19514:227. 24X Fiche: 90-000.83/07/08.
- 8307190267 Requests corrections to updated FSAR, consisting of deletion of Tables 3, 9-35 through 3, 9-38, Table 3, 9-44 & Figures 3, 9-15 through 3, 9-17.

  REAVIS, J. Dute Power Co. 83/07/11. NRC No Detailed Affiliation Given. ip. 19629:275. 24X Fiche: 50-269, 83/07/11, 8307190267.
- 8307220636 Summary of 830608 appeal meeting w/utils & Bechtel restandby shutdown sys monitors for source range flux & steam generator pressure. Viewgraphs encl.
  BIRKELIR.A. Licensing Branch 4. 83/07/15. Licensing Branch 4. 32pp. 19697:045. 24X Fiche: 50-000, 83/07/15, 8307220636.
- 8307260304 Forwards proposed response dates to concerns in NRC 830608 life providing approval of proposed wide-range hot log level/reactor vessel head monitoring concept for coolant inventory tracking w/pumps off.
  TUCKER, H.B. Duke Power Co. 83/07/18. DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director. STDL2, J.F. Operating Reactor Branch 4. 6pp. 19726:070. 24% Fiche: 50-269, 83/07/18, 8307260304.
- B307250117 Advises that mods to relief & safety valve discharge ciping will be implemented during next refueling outage scheduled for early 1985, per 830121 ltr re NUREG-0737, Item II. D. 1.
  "Performance Testing of Reactor Relief & Safety Valves."
  TUCKER, H. B. Duke Power Co. B3/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. STULZ, J. F. Operating Reactors Branch 4. 1p. 19706:071. 24X Fiche: 50-269, 83/07/19, B307250117.
- 8307260412 Forwards response to 830509 request for add1 info re natural circulation cooldown procedures & supporting analytical bases. Natural circulation cooldown unlikely undertaking at facility. Procedures & training provide appropriate guidance. TUCKER.H.B. Duke Power Co. 83/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. STOLZ.J.F. Operating Reactors Branch 4. Spp. 19733:138. 24X Fiche: 50-269,83/07/19.8307260412.
- --8307260417 "Planned Initiation of Natural Circulation & Natural Circulation Cooldown."

  a Duke Power Co. 81/12/22. 17pp. 19733:143. 24x
  Ficha: 50-269,83/07/19,8307260412.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140336 Informs that liquid samples spiked w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analysed for tritium, Sr-89 & Sr-90 content within 60 days.

  LEWIS.R.C. Division of Project & Resident Programs. 83/02/07. TUCXER.H.B. Duke Power Co. ip. 19525: £20. 24X Ficha: 50-000, 83/02/07, 8307140336.
- B305270612 Ack receipt of B30406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-06, S0-270/83-06 & 50-287/83-06 DANCE, H.C. Division of Project & Resident Programs. B3/04/29, TUCKER, H.B. Duke Power Co. 1p. 18646:248, 24X Fichs: 50-269, B3/04/25, B305270612.
- --8305270627 Responds to NRC 830307 ltr re violations noted in IE Insp Repts 50-269/83-06, 50-270/83-06 & 50-287/83-06. Corrective actions: cited door locked closed immediately after being found open. FUCKER.H.B. Duke Power Co. 83/04/06. O'REILLY, J. P. Region 2, Office of Director. 2pp. 18646:249. 24X Fiche: 50-269, 83/04/25, 8305270612.
- --B309270630 Forwards IE Insp Rept 50-269/83-06, 50-270/83-06 & 50-287/83-06 on 830111-0210 & notice of violation. DANCE, H. C. Division of Project & Resident Programs, 83/03/07, TUCKER, H. B. Duke Power Co. 2pp. 18646: 251, 24X Fiche: 50-269, 83/04/25, 8305270612.

- ---8305270636 Notice of violation from insp on 830111-0210.

  \* Region 2, Dffice of Director. 83/03/07. 1p. 18646:253. 24X Fiche: 50-269,83/04/25,8305270612.
- --8305270643 IE Insp Repts 50-269/83-06, 50-270/83-06 & 50-287/83-06 on B30111-0210. Noncompliance noted: unescorted entrance to high radiation area.

  BRYANT, J. FALCONER, D. Region 2. Office of Director.

  IONATONISA, J. Division of Project & Resident Programs. B3/03/04.

  10pp. 18646: 254, 24X Fiche: 50-267, 83/04/29, 8305270612.
- 8307140067 Responds to IE Bulletin 83-03 re check valve failures in diesel generator water cooling sys. Valve CCW-284 in standby shutdown facility only affected valve per Item 4. Item 5 response will be submitted within 90 days of checkout. TUCKER.H. B. Duke Power Ca. 83/06/20. 0'REILLY,J.P. Region 2. Office of Director. 4pp. 19514:097. 24X Fiche: 50-269.83/06/20.8307140067.
- 8307140026 Forwards IE Insp Repts 50-269/83-15.50-270/83-15 & 50-287/83-15 on 830411-0510. No noncompliance nated. DANCE, H. C. Division of Project & Resident Programs. 83/06/22. TUCKER, H. B. Duke Pawar Co. 2pp. 19514:196. 24X Fichs: 50-269,83/06/22,8307140026.
- --B307140030 IE Insp Repts 50-269/83-15,50-270/83-15 & 50-287/83-15 on 830411-0510. No noncompliance noted. Najor areas inspected: operations, maint activities, surveillance & LER review. BRYANI.J., FALCONER, D. Region 2. Office of Director. BROWNLELV.L. Division of Project & Resident Programs. 83/06/21. 4pp. 19514:198. 24X Fiche: 50-269,83/06/22,8307140026.
- 8307040275 Responds to 830602 ltr re violations & proposed imposition of civil penalties noted in IE Insp Repts 50~26763~11. 50~270783-11 & 50~287763~11. Corrective action: procedures per THI Item I. C. 6 reviewed.
  TUCKER.H. 8. Duke Power Co. 83/07/01. Director's Office of Inspection and Enforcement. 21pp. 19238: 352. 24X Fiche: 50~249, 83/07/01, 8307040275.
- 8307130263 Forwards revised request for relief from ASME Section XI inservice insp requirements (hydrostatic) supplementing 821004 request No addi license fees provided.
  TUCKER, H. B. Duke Power Co. 83/07/06. DENYON, H. R. Office of Nuclear Reactor Regulation, Director. 570L2, J. F. Operating Reactors Branch 4. 2pp. 19508:246. 24X Fiche: 50-269,83/07/06,8307130263.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19863:293. 24X Fiche: 50-000,83/07/11.8306270401.
- 8306270404 lE Info Notice 93-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 50-000,83/07/12,8306270404
- 8306270406 IE Info Notice 83-48, "Gassous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl.
  TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- S. Reportable occurrences, LERs & related correspondence
- B307120093 LER 83-008/03L-0: on 830531, motor driven emergency feedwater pump became imperable when power removed from circuitry for repair of automatic initiation switch 2PS-3BB. Caused by component failure. Switch replaced & recalibr. W/830630 ltr. PETTY.J.C., TUCKER.H.B. Duke Power Co. 83/06/30. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19423; 078. 24x Fiche: 50-270, 83/06/30, 8307120093.
- 8307220272 LER 83-007/03L-O: on 830607, HP1 pump 2F removed from svc to repair oil leak at sight glass tap into motor housing. Caused by component failure due to failure of threaded scalant.

  Pump motor repaired & returned to svc. W/830707 ltr.

  GUILL, P.F., TUCKER. H. G. Duke Power Co. 83/07/07. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19684: 259. 24X

  Fiche: 50-270, 83/07/07, 8307220272.

- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

  F. Security, modical, emergency & fire protection plans
- B307070058 Forwards Rev 8 to physical security plan. Rev withheld (ref 10CFR73.21).
  BINCLAIR.J. B. Vermont Yanker Nuclear Power Corp. 83/06/16.
  ALLAN.J.M. Region 1. Office of Director. 2pp. 19293: 209. 24X
  Fiche: 50-271.83/06/16.8307070058.
- B307210130 Responds to 830614 ltr re Temporary Change Notification 83-1 to physical security plan. Change & compensatory measures to be applied 830711-15 while temporary change in effect acceptable.

  MARTIN, T. T. Division of Engineering & Technical Programs. B3/07/09. MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 3pp. 19666:092. 24X Fiche: 50-271,83/07/09,8307210130.
- B307220393 Ack receipt of B30525 ltr informing NRC of steps taken to correct violations noted in TE Insp Rept 30-271/83-08.
  Attachment A of ltr will not be placed in PDR per 10CFR73.21.
  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/14. MURPHY.H.P. Vermont Yankee Nuclear Power Corp. 19. 19675:177. 24X Fiche: 50-271.83/07/14.8307220393.
- --B307220397 Responds to NRC 830505 ltr re violations noted in IE Insp. Rept 50-271/83-08. Response to violation re security-related activities withheld (ref 100FR/3.21).
  MURPHY.W.P. Vermont Yankee Nuclear Power Corp. 83/05/25.
  MARTIN.T. T. Region 1, Office of Director. 1p. 19675:178, 24X
  Fiche: 50-271, 83/07/14, 8307220393.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307260480 Forwards Rev 1 to updated FSAR denoting changes during B20120-B30120.

  HEIDER.L.H. Vermont Yankee Nuclear Power Corp. 83/07/20.

  BENTON, H.R. Office of Nuclear Reactor Regulation, Director. ip. 19734: 212. 24X Fiche: 50-271, 83/07/20, 8307260480.
- --8307260481 Rev 1 to updated FSAR.

  \* Vermont Yankee Nuclear Power Corp. 83/07/20. 201pp. 19734: 213. 24X Fiche: 50-271, 83/07/20, 8307260480.
- P. Operating license stage documents & correspondence
- 8307140160 Forwards safety evaluation of BWR Dwners Group response to NVREO-0737. Item II. K. 3. 18. "Mod of Automatic Depressurization Sys Lagic...." Two acceptable options include elimination of high drywell pressure permissive. VASBALLO, D. B. Operating Reactors Branch 2. 83/06/03. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 2pp. 17540:032. 24X Fiche: 50-271, 83/06/03. 8307140160.
- 8307120045 Forwards request for add1 info re review of structural aspects of plant-unique analysis rept for Mark I containment long-term program. Heeting should be held to expedite review. VASBALLO,D. B. Operating Reactors Branch 2. 83/04/09. SINCLAIR, J. D. Vermont Yankee Nuclear Power Corp. 8pp. 17508:305. 24X Fiche: 50-271, 83/04/09, 8307120045.
- 8307110072 Authorizes plant restart based on 830615 commitments & acceptability of corrective actions re unacceptable ultrasonic indications in piping. Commitments will be addressed by confirmatory order.

  VA8564LLQ, D. B. Operating Reactors Branch 2. 83/06/16. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 2pp. 19386:300. 24X

  Fiche: 50-271,83/06/16,8307110072.
- 8307150162 Forwards mod of 810113 order, revised by 811125 & 820114 orders. Order continues exemption & extends completion date for installation/mod of support to torus piping of Mark I containment to not later 90 days after fuel Cycle 10.

  VASSALLO. D. B. Operating Reactors Branch 2, 83/06/17. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 2pp. 19542:356. 24X
- --8307150169 Mod of 810113.i125 & 820114 orders extending completion date to not later than 90 days after start of Fuel Cycle 10 for installation of support to torus piping of Mark I containment required by App A of NUREG-0661.

  PURPLE. R. A. Division of Licensing. 83/06/17. Vermont Yankee Nuclear Power Corp. Spp. 19542.358. 24X Fiche: 50-271.83/06/17, 8307150162.

- 630627039° Jeneric Ltr 63-26 to all applicants for DLs 5 holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel inpurity Svc list encl EISENHUT. D G Division of Licensing #39/07/05 Consolidated Editor (5 of New York) Inc. 16pp 19396-317 24x Fiche 50-000.63/07/05.8306270397
- 8307070103 Submits supporting info on Lifting devices to be used in transporting activated reactor components to liceused disposal site Design of proposed lifting device adequate to uithstand dynamic loads imposed by overhead handling sys. SINCLAIR. J. B. Vermont Yankee Nuclear Power Corp. 83707705. VASSALUG.D. B. Operating Reactors Branch 2. 2pp. 19294:115. 24X Fiche: 50-271, 63707705, 8307070103.
- 0307060329 Generic Ltt 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors te surveillance intervals in STG Svc list encl EigenHULD G Division of Licensing 83/07/06 Consolidated Edison & of Nsw York. Inc. 16pp 17669:254. 24x Fiche. 30-000.83/07/04,8307060329
- B307080169 Seheric Ltr 83-28 to all licensies of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EigEnvult. D G Division of Licensing 83/07/08. Consolidated Edison CD of New York. Inc. 38pp 19669 269 24x Fich. 50-000, 83/07/08.8307080169
- 8307250541 Notification of rescheduled 830726 meeting w/util.BNL. Princeton Univ & Teledyne in Framingham.MA to discuss questions re Mark I program plant-unique analysis rept resulting from BNL, post-implementation audit review. ROBNEY.V L. Operating Reactors Branch 2. 83/07/15. VASSALLO.D.B. Operating Reactors Branch 2. 2pp. 19725:359. 24X Fiche 50-271.83/07/15.8307250341.
- 8307250524 Notification of 830809 meeting u/utils.Franklin Research & Teledyne Engineering Svc in Frankham.MA to discuss Mark I leng-term program implementation & unresolved questions restructural integrity.

  SHEAL J. Operating Reactors Branch 5. 83/07/20 CRUTCHFIELD.D. Operating Reactors Branch 5. 1p. 19782:240. 24x

  Fiche. 90-000.83/07/20.8307250524
- B307260408 Provides add1 info re Proposed Change 101 to Tech Specs proposing to raise current full power torus temp limit. Rev 1 to Figure 3 entl correcting improper factoring of subdergence elevation of tee quencher 61NcLAIR. J.B. Vermont Vankes Nuclear Power Corp. B3/07/20. VAESALLO.D.B. Sperating Reactors Branch 2 3pp 19733:135. 24X Fichs:50-271.83/07/20.8307260408.
- G Inspection regords. IE Bulletins & correspondence
- 8307010137 Forwards IE Insp Rept 50-271/83-07 on 830329-0401.0503-06 & 09-13 No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/14.

  MURRHY.H.P. Vermont Yankee Nuclear Power Corp. 2pp. 19168:356.
- --8307010146 IE Insp Rept 50-271/83-07 on 830329-0401,0503-06 & 09-13. No moncompliance noted Major areas inspected: recirculation sus pipsing & associated activities in response to IE Bulletin 83-02 at Each Center of the Solid Solid
- 8307050117 Forwards IE Insp Rept 50-271/83-05 on 830310-11.No noncompliance noted MARTIN.T I Division of Engineering & Technical Programs. 83/05/20 MURPHY.W P Vernort Yanker Nuclear Power Corp. 2pp 17251.192. 24% Fiche 50-271.83/05/20.8307050117.
- --83070601P4 IE insp Rept 50-271/83-05 on 830310-(1. No noncompliance noted Major areas inspected licensee response to Item 1 of IE Builtetin 83-02 & ultrasonic test methodology validation performance at EPRI NDE Ctr in Charlotte, NC MCBREARTY, R A. DURR, J. P. Region 1. Office of Director. 83/06/17. 200 1925(194. 24X Fiche: 50-271, 83/06/20, 8307060117.
- B3071t0627 Notafication of significant licensee B30628 meeting w/util in Vernon.VI to discuss SALP. GALLOR M. Division of Project & Resident Programs B3/06/21. Division of Project & Resident Programs Ep. 19391:353. 24X Fiche 50-271.83/06/21.8307110629
- 8307110493 Forwards IE Insp. Rept 50-271/83-16 on 830606-10. No nancompliance noted HARIIN, T. Division of Engineering & Technical Programs. 83/06/24. NuRPHY.N.P. Versont Yankee Nuclear Power Corp. 2pp. 19380: 143-24% Fiche 50-371,83/06/24,8307116498

- --8307110503 IE Insp Rept 50-271/83-16 on 830606-10. No noncompliance noted Major areas inspected environ monitoring program for operations 0C of analytical measurements. Licensee action on previous insp findings & meteorological monitoring.
  STRUCKMEYER, JANG.C., PASCIAK.W.J. Region 1, Office of Director. 83/06/23. 4pp. 19380:147. 24X Fiche: 50-271, 83/06/24, 8307110478.
- 8307010089 Ack receipt of 830619 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/82-23 STAROSTECKIR. Division of Project & Resident Programs. 83/06/27. MURPHY. M. P. Vermont Yankes Nuclear Power Corp. 1p. 19169: 210. 24% Fiche: 80-271, 83/06/27, 8307010089.
- --8307010098 Responds to NRC 830401 ltr re violations noted in IE Inap
  Rept 50-271/82-23. Corrective actions: Administrative
  Procedure 0020 for temporary electrical jumpers, lifted
  leads & mechanical bypasses will be revised.
  HURPHY, W.P. Vermont Yankoe Nuclear Power Corp 83/06/15.
  STAROSTECKI, R. Division of Project & Resident Programs. Jpp.
  19169: 211. 24X Fiche: 50-271, 83/06/27, 8307010089.
- B307180055 Forwards order confirming licensee commitments to repair recirculation sys piping identified during insp. VASSALLO,D.B. Operating Reactors Branch 2. B3/06/27. BINCLAIR, J.B. Vermont Yankes Nuclear Power Corp. 2pp. 19566.316. 24X Fichs: 50-271, 83/06/27, 8307180055.
- --B3071B0058 Order confirming licenses commitments to repair recirculation sys piping discovered during insp. EISENNUT.D.C. Division of Licensing. B3706/27, Vermont Yankee Nuctear Power Corp. 6pp. 19566;318, 24% Fiche: 50-271,83/06/27,83071B0055.
- 8307110385 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-01.
  8TAROSTECKI,R. Division of Project & Resident Programs. 83/07/01.
  MURPHY,M.P. Vermont Yanker Nuclear Power Corp. 2pp. 19380:340.
  24X Fiche:50-271.83/07/01/8307110385.
- --B3071103B9 Responds to NRC 830324 ltr re violations noted in 1E Insp. Rept 50-271/B3-01. Corrective actions: valve SB16-19-7B capped, root isolation valve AC-60C positioned full-open & personnel reinstructed re fuel receipt procedures.

  MURPHY, M. P. Vermont Yanken Nuclear Power Corp. B3/06/23. STARBSTECKI, R. Division of Project & Resident Programs. 2pp. 19380: 342. 24X Fiche: 50-271, 83/07/01, 8307110385.
- 8307220484 Responds to IE Bulletin 83~03 re check valve failures in raw cooling water sys of diesel generators. Radiographic eram of valves V70~43A & V70~43B confirmed valve discs intact. Check valves will be included in inservice testing program. HURPHY, M.P. Vermont Yankse Nuclear Power Corp. 83/07/07. MURLEY, T. E. Region 1. Office of Director. 2pp. 19683:183. 24X Fiche: 50-271,83/07/07.8307220484.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 930103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563; 293. 24X Fiche: SO-000, 83/07/11, 8306270401.
- B306270404 IE Info Notice 83-47. "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Bvc list encl. URRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche: 50~000, B3/07/12, B306270404.
- 8306270406 tE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Ca. of New York, Inc. 114pp. 19715: 270. 24x Fiche: 50-000, 83/07/14, 8306270406.
- 8307210053 Ack receipt of 830707 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropt 50-271/83-02.
  STARGSTECKIR. Division of Project & Resident Programs. 83/07/14.
  MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 1p. 17668: 271. 24: Fiche: 50-271, 83/07/14. 8307210053.
- --8307210056 Responds to NRC 830401 ltr re violations noted in IE Insp Rept 50-271/83-02. Corrective actions: memo sent to personnel stressing requirements for obtaining health physics surveys prior to entering normally inaccessible plant areas. MURPHY.N.P. Vermont Yanke Nuclear Power Corp. 83/07/07. STARGSTECKI.R. Division of Project & Resident Programs. 2pp. 19668: 272. 24X Fiche: 50-271, 83/07/14, 8307210053.

- 8307220393 Ack receipt of 830525 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-08.
  Attachment A of Itr will not be placed in PDR per Attachment A of itr will not be placed in PDR per 10CFR73.21. MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/14. MURPHY.M.P. Vermont Yankee Nuclear Power Corp. 1p. 19675:177. 24X Fiche: 50-271.83/07/14.8307220393.
- --B307220397 Responds to NRC 830505 ltr re violations noted in IE Insp. Rept 50-271/83-08. Response to violation re security-related activities withheld (ref 10CFR73.21).

  MURPHY. M. P. Vermont Yankee Nuclear Power Corp. B3/05/25.

  MARTIN. T. T. Region i, Office of Director. 1p. 17675: 178. 24X

  Fiche: 50-271, B3/07/14, B307220373.
- R. Periodic operating reports & related correspondence
- 8307150288 "Vermont Yankee Nuclear Power Corp Annual Radiological Environ Burveillance Rept. 1982." W/830711 1tr. \* Vermont Yankee Nuclear Power Corp. 83/07/11. MURLEY, T. E. Region 1. Office of Director. 69pp. 19530:001. 24X Fiche: 50-271, 83/07/11. 8307150288.
- B307190078 Monthly operating rept for June 1983.W/830712 ltr.
  BURGER, F. J., MURPHY, W. P. Vermont Yankee Nuclear Power Corp.
  B3707/12. Office of Resource Management, Director. 7pp.
  19635:112. 24X Fiche: 50-271.B3/07/12.B307190078.
- 3. Reportable occurrences: LERs & related correspondence
- 3307010022 LER 83-015/01P-0: on 830608, Yankee Atomic Electric Co 307010022 LER 83-015/01P-0: on 830608, Yankee Atomic Electric to informed util that addl piping supports required to support piping in svc water sys & torus attached piping. Cause & corrective actions to be provided in next rept. M/830609 ltr. PELLETIER, J.P. Vermont Yankse Nuclear Power Corp. 83/06/09. MURLEY, T.E. Region 1, Office of Director. 2pp. 19169: 107. 24X Fiche: 50-271, 83/06/09, 8307010022.
- 3307010105 Updated LER 83-015/01X-1: on 830608, rept received from Yankee Atomic Electric Co re error in design & use of spacing table for copper piping in svc water sys. Caused by failure to follow ANSI 831, i. W/830616 ltr. PELLETIER, U.P. Vermont Yankee Nuclear Power Corp. 83/06/16, MURLEY, T.E. Region i. Office of Director. 3pp. 19168: 194. a Fiche: 50-271, 83/06/16, 8307010105.
- 307010085 LER 83-015/01T-0:on 830608,error discovered in spacing table developed for support of copper piping in svc water sys. Addi supports required to fully comply w/ANBI 831.1. W/830622 ltr. PELLETIER.J.P. Vermont Yankee Nuclear Power Corp. 83/06/22. MURLEY.T.E. Region 1. Office of Director. 3pp. 19169:214. 24X Fiche: 50-271,83/06/22,8307010085.
- 307060149 PNO-I-83-073: on 830629, following discovery of RHR logic relay, spurious signal generated resulting in closure of recirculation pump discharge valves, causing recirculation pump the property of t
- 307150354 Updated LER 83-003/03X-1: on 830114, low temp alarm on diesel generator A coolant jacket received. Caused by defective seat in check valve on excess fuel oil return line. No corrective action necessary.

  PELLETIER.J.P. Vermont Yankee Nuclear Power Corp. 83/06/30.

  MURLEY.T.E. Region 1, Defice of Director. 3pp. 19538: 301. 24X Fiche: 50-271,83/06/30,8307150354.
- ICKET 50-272 SALEM NUCLEAR GENERATING STATION: UNIT 1 Security, medical, emergency & fire protection plans
- 107030437 Forwards exemption from certain requirements of Section 50.48 & App R to 10CFR30 re fire protection of safe shutdown capability. No exemption required for RHR HX area. Safety evaluation encl.

  VARGA.S.A. Operating Reactors Branch 1. 83/06/17. UDERITY.R.A.
- VARQA.S.A. Operating Reactors Branch 1. 83/06/17. U Public Service Electric & Gas Co. of New Jersey, 4pp. 24X Fiche: 50-272, 83/06/17, 8307050457. UDERITZ, R. A
- B307050458 Exemption granting relief from certain requirements of App R to 10CFRSO, Bection III.6.
  EISENHUT, D. G. Division of Licensing, 83/06/17. Public Service Electric & Gas Co. of New Jersey, App. 19262:308, 24X Fiche: 50-272, 83/06/17, 8307050457.
- B307050463 Safety evaluation supporting exemption from certain requirements of App R of 10CFR30, Section III. 9 re safe shutdown capability.

  # Diffice of Nuclear Reactor Regulation, Director. B3/06/17. 21pp. 19262:314. 24X Ficha: 50-272, 83/06/17, 8307050457.

- B307070057 Forwards Amend I to security contingency plan reflecting changes in internal communications Amend withheld (ref 10CFR73.21).

  LIDENIE A. Public Gervice Electric & Gas Co. of New Jersey.
  B3/07/01 Region I, Office of Director. 2pp. 19293:347. 24X
  Fiche: 50-272, B3/07/01, B307070057.
- 8307150264 Terminates actions required by 820818 Confirmatory Action Ltr 82-22,per 830603 request & IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 Safeguards info deleted (ref 10CFR73.21). STAROSTECKI,R. Division of Project & Resident Programs. 83/07 UDERITZ,R.A. Public Service Electric & Gas Co. of New Jersey. 19338: 085. 24% Fiche 50-272,83/07/11.8307150264. 83/07/11
- 8307200004 Corrects previous responses to Generic Ltr 82-33 recompletion of Reg Guide 1.97 mods for emergency response capability. Confirmation that proposed schedule for implementation acceptable requested.
  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  83/07/12. VARGA.S.A. Operating Reactors Branch 1. 2pp. 17647:127.
  24X Fiche: 50-272,83/07/12,8307200004.
- 8307250449 Provides supplemental info re design of emergency operations facility (EOF). Encl depicts layout of ventilation sys. EQF located at training ctr.
  LIDEN.E.A. Public Service Electric & Gas Co. of New Jarsey.
  83/07/18. VARGA.S.A. Operating Reactors Branch 1. 4pp. 19702:158.
  24X Fiche: 50-272,83/07/18,8307250449.
- 8307220423 Forwards request for additinfore safeguards regulatory effectiveness review rept, in response to 830323 ltr. Response on first item requested within 30 days Encl withheld (ref 100FR73.21).

  VARQA, S. A. Operating Reactors Branch 1. 83/07/19. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 19687: 26724X Fiche: 50-272,83/07/19,8307220423.

#### H. General correspondence

- B307140121 Responds to B30601 itr expressing concerns re NRC decision to permit facility operation in light of serious incidents occurring in Feb 1983.NRC instituted augmented insp program to monitor activities. Plant can be operated safely. DIRCKB, M. J. Office of the Executive Director for Operations. 83/07/01. CASTLE, M. N. Delaware, State of 2pp. 19539:334. 24X Fithe: 30-272, 83/07/01, 8307140121.
- --B307140127 Bubmits comments on behalf of concerned citizens re operation of factlity. Plant should be shut down due to gross mismanagement causing serious health & safety risk. NRC should carefully scrutinize operations CABTLE.M.N. Delaware, State of. B3/06/01 PALLADIND.N.J. Commissioners. 2pp. 19539: 356. 24X Fiche: 50-272, B3/07/Q1, B307140121.
- J. Insurance & indemnity information
- B307130240 Forwards Endorsements 59 th 60 to NELIA Policy NF-230 the Endorsements 46 th 47 to MAELU Policy MF-90.

  GDLDEN, M. P. Marsh & McLennan, Inc. B3/07/06. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 19474:352. 24X Fiche: 50-000, B3/07/06, B307130240.
- B307280407 Forwards Endorsements & & & & B to NELIA Policy NF-230 & MAELU Policy NF-90 respectively.

  GDLDEN, M.P. Marsh & McLennan, Inc. 83/07/20. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19797:349. 24X Fiche: 50-272,83/07/20,8307280407.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8307090095 Summarizes 276th ACR8 meetings on 830414-16 w/utils to review request for GL. Agenda for 830512-14 meetings encl. EBERSOLE, J. ACR8 Advisory Committee on Reactor Safeguards. 83/04/27. PALLADING, N. J. Commissioners. 3pp. 19366:058. 24X Fiche: 50-000, 83/04/29, 8307090095.
- P. Operating license stage documents & correspondence
- B307250020 Add1 response to FOIA request for 22 categories of documents. Forwards App A & B documents. Portions of App B documents withheld (ref FOIA Exemptions 7 & 3). FELTON. J.M. Division of Rules and Records. B3/05/05. SHOLLY, S.C. Union of Concerned Ecientists. App. 19729:108. 24X Fiche: 50-000, B3/05/05, B307250020.

- --8307250038 Requests that specific followup actions be taken re current situation at facility. Actions include reviewing emergency notification procedure & listing plant sys that should be checked in future instances of suspected sabotage.

  DIRCKS, H. J. Office of the Esocutive Director for Operations. 82/09/04. HAYNES, R. C. Region 1. Office of Director. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. [p. 19725:122 24X Fiche: 50-000, 83/05/05, 8307250020.
- --8307250044 Forwards FBI 820428.0502 & 05 teletypes.Ofc of Administration should take corrective action re delay in teletype distribution.
  CUMMINGS.J. J. Diffice of Inspector & Auditor. 82/05/06.
  PALLADING.N.J. Commissioners. 3pp. 19725:123. 24x
  Fiche: 50-000, 83/05/05, 8307250020.
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs ra safety evaluation of "Emergency Response Guidelines." Svc List encl.
  EISENHUT.D. 9. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche 50-000.83/06/03.
- 8307210104 Modified application for amend to Licenses DPR-70 & DPR-75, clarifying determination that NSHC involved in Implementation of proposed Tech Spec chages re ETS & administrative controls.

  LIDEN.E.A. Public Service Electric & Gas Co. of New Jerseg. 83/07/01. VARCA.S.A. Operating Reactors Branch 1. 11pg. 19668:219 24X Fiche: 50-272, 83/07/01. 8307210104.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesal fuel impurity Svc list encl. EISENMIN.D.G. Division of Licensing 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24x Ficha:50-000.83/07/05.8306270397.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for aperating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list entl EISENHUT. D. G. Division of Licensing. 83/07/06 Consolidated Edison Co. of New York, Inc. 16pp 19669:254 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for 8L & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENMUT.D. 0. Bivision of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649-259. 24X Ficha: 80-000, 83/07/08, 8307080169.
- 8307200067 Responds to B30412 safety evaluation items requiring add1 action re request for relief from inservice testing requirements. Replacement pages to test program, per amend, enci.

  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  83/07/11. VARGA.S.A. Operating Reactors Branch 1. Spp. 17647: 041. 24X Fiche: 50-272, B3/07/11, 8307200067
- B307250427 Submits response to B3042B commitment re corrective action program mods. Proposed ATMS rule in final stages of review prior to presentation for approval. Breaker shunt trip function will be incorporated into automatic trip circuits. LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey. B3707715. VARCA.S.A. Operating Reactors Branch (. 2pp. 19701:190. 24X Fiche: 50-272.83/07/15.8307250427.
- 8307270402 Submits current status of conformance w/830708 Generic Ltr 83-28 re required actions based on generic implications of reactor trip breaker failures on 830222 & 25. LIDEN.E.A. Public Service Electric & Gas Co of New Jersey, 83/07/22. VARCA.S.A. Operating Reactors Branch L. 4pp. 19767:111. 24X Fiche: 50-272, 83/07/22, 8307270402.
- --8307270406 Rev 3 to Procedure AD-16, "Post-Reactor Trip/Safety Injection Review," \* Public Service Electric & Gas Co. of New Jersey. 83/07/14. 2tpp. 19767:115. 24X Fiche:50-272,83/07/22.8307270402.
- B307290180 Application for amend to Liceuse DPR-70 revising Tech Specs by extending interval of surveillance requirement for integrated leak rate testing of containment bldg Safety evaluation encl.

  LIDEN.E A. Public Service Electric & Gas Co. of New Jersey.
  B3/07/22. VARCA.S. Operating Reactors Branch 1. 6pp. 19822:045.
  24X Fiche: 50-272.83/07/22,8307290180.

- --8307290185 Proposed Tech Spec changes extending interval of surveillance requirement for integrated leak rate testing of containment bldg.

  \* Public Service Electric & Qas Co. of New Jersey. 83/07/22, 1p. 19822:051. 24X Fiche: 50-272, 83/07/22, 8307290180.
- Q. Inspection reports. IE Dulletins & correspondence
- 8307010007 Forwards IE Insp Repts 50-272/83-18 & 50-311/83-17 on 830517-24 No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/14.

  UDERITZ.R.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 19169:068. 24X Fiche: 50-272, 83/06/14, 8307010007.
- --8307010012 IE Insp Repts 50-272/83-18 & 50-311/83-17 on 830517-24.No noncompliance noted Major areas inspected followup of previous insp findings re procedure review test witnessing & results avaluation of local & integrated leak rate testing. PULLANI.S.V., BETTENHAUSEN.L. Region 1. Office of Director. 83/06/09, 9pp. 19169:070. 24X Fiche: 50-272,83/06/14.8307010007.
- B307130306 Responds to B30305 notice of violation & proposed imposition of civil penalties re B30222 & 25 ATMS events. Magnitude of civil penalty disputed. Events were isolated occurrences. BELOVER.R. E. Public Bervice Electric & Gas Co. of New Jorsey. B3/07/06. DEYDUNG.R. C. Director's Defice. Office of Inspection and B307130306.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JQRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp, 19563: 293. 24X Fiche: 50-000, 83/07/11, B306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563; 153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270405 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24x Fiche: 50-000, 83/07/14, 8306270406.
- B307270462 Forwards proposed augmented insp plan for monitoring & evaluating util performance improvement program & Mgt Analysis Co final rept. "Mgt Assessment & Action Plan for Improvement of Salem Stations I & 2 Operations." EISENHUT, D. 9. Division of Licensing. 83/07/20. Division of Licensing. 83/07/20. B307270462.
- --B107270464 Discusses proposed augmented insp plan for monitoring & evaluating util performance improvement program over next 2 yrs.

  STAROSTECKI, R. Division of Project & Resident Programs. B3/06/23.

  DENTON, H. R. Office of Nuclear Reactor Regulation. Director.

  DEYDUNG, R. C. Director's Office, Office of Inspection and Enforcement. MURLEY, T. Region 1. Office of Director. 7pp. 19802: 156. 24% Fiche: 50-272. B3/07/20, 8307270462.
- --8307270466 "Mgt Assessment & Action Plan for Improvement of Balem Stations 1 & 2 Operations." # Management Analysis Co. 83/06/24. 73pp. 19802:163. 24X Fiche: 50-272,83/07/20,8307270462.
- 8307280211 Forwards IE Mgt Meeting Repts 50-272/83-21 & 50-311/83-21 on 830518.
  8TAROSTECKI,R. Division of Project & Resident Programs. 83/07/20.
  UDERITZ,R. Public Service Electric & Gas Co. of New Jersey. 2pp. 19794: 004. 24X Fiche: 50-272, 83/07/20. 8307280211.
- ---8307280229 IE Mgt Meeting Repts 50-272/83-21 & 50-311/83-21 on 830518.

  Major areas discussed diagnostic objectives & initial findings of Mgt Analysis Co evaluation.

  ACOBS.R. Region i. Office of Director. TRIPP.L. Division of Project & Resident Programs. 83/07/19. 4pp. 19794:006. 24X

  Fiche: 50-272.83/07/20.8307280211.
- 8307270395 Supple 830706 response to NRC 830305 notice of violation & proposed imposition of civil penalties re 830222 & 25 events at Unit 1. Requests that civil penalties be eliminated in SELOVER.R. E. Public Service Electric & Gas Co. of New Jersey. 83/07/22. DEYDUNG.R.C. Director's Office. Office of Inspection and 8307270395.

- --8307270416 Submits response to 830428 commitment to submit detailed rept describing corrective action program mods Surveillance, maint & insps increased to ensure reliability of reactor trip sys.

  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  83707715. VARGA.S.A. Operating Reactors Branch 1. 2pp.
  19767:236. 24X Fiche: 50-272, 83/07/22, 8307270395.
- R. Periodic operating reports & related correspondence
- 8307150072 Monthly operating rept for June 1983.W/830710 ltr.
  MILLER, L. K., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 83/07/10. Director's Office. Office of Inspection and Enforcement. 18pp. 19535:269. 24x Fiche 50-272,83/07/10, 8307150072.
- S. Reportable occurrences, LERs & related correspondence
- B307250020 Add1 response to FOIA request for 22 categories of documents. Forwards App A & B documents. Portions of App B documents withheld (ref FOIA Exemptions 7 & 3).

  FELTON.J.M. Division of Rules and Records. 83/05/05. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 19725:10B. 24X Fiche: 50-000, 83/05/05, 8307250020.
- --8208030682 Forwards rept on chronology of 820428 attempted sabotage. No individuals identified as being involved tabor problems probably caused incidents.

  DIRKKS.W.J. Office of the Executive Director for Operations.
  82/06/08. PALLADING.N.J. Commissioners 73pp. 19725: 223. 24X Fiche: 50-272, 83/05/05, 8307230020.
- --B307250067 Requests summary rept re event including followup actions by licensee.NRC & other govt agencies by B20510. Rept should also indicate corrective actions for any problems encountered during response.

  PALLADING, N. J. Commissioners. B2/04/30. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 19725: 219. 24X

  Fiche: 50-000, 83/05/05, 8307250020.
- 8307120490 LER 83-023/01P: on B30602, info received from Westinghouse identifying potential unreviewed safety question reexcessive power peaking. Investigation in progress. Detailed rept within 14 days.

  ZUPKO, J. M. Public Bervice Electric & Gas Co. of New Jersey.
  B3/06/02. ALLAN.J. Region 1, Office of Director. ip. 19425: 348.
  24X Fiche: 50-272, 83/06/02, 8307120450
- 8307070446 Documents understanding of commitments made at 830601 meeting to provide info re 830527-30 annuclator problems. Response requested within 30 days. LAINASG.C. Assistant Director for Operating Reactors. 83/06/06. UDERITZ.R.A. Public Service Electric & Cas. Co. of New Jersey. 2pp 19300:190. 24X Fiche: 50-272, 83/06/06, 8307070446.
- B307050036 LER B3-024/03L-0: on B30525, supply breaker to vital instrument IC inverter inadvertently opened. Automatic transfer to alternate power supply occurred w/no loss of equipment or indication. W/B30622 itr.
  FRAHM.R., ZUPKO, J.M. Public Bervice Electric & Gas Co. of New Jersey, B3706/15. ALLAN.J. Region 1, Office of Director. 4pp. 19220: 307. 24X Fiche: 50-272, B3/06/13, B307050036.
- B307050043 LER B3-026/03L-0: on B30530, containment fan coil unit (CFCU) i7 svc water flow observed below Tech Specs. CFCU declared inoperable. Caused by valve 158W57 boing plugged w/shells & debris from cleaning of svc water sys. W/B30622 itr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. B3/06/15. ALLAN, J. Region 1, Office of Director. 4pp. 19199:313. 24X Fiche: 50-272, 83/06/15, 8307050043.
- B307110103 Advises Commission of proposed generic actions resulting from ATMS events on B30222 & 25 Salem Generic Implications Task Force identified weaknesses in overall licensee mgt & reactor trip sus reliability.

  DIRCKB, M. J. Office of the Executive Director for Operations.

  SECY-83-248. 83/06/22. 20pp. 19386:239. 24X Fiche: 50-272, 83/06/22, 8307110103.
- B307140001 LER B3-027/03L-0: on B30602, hydrogen analyzer 12 chart recorder tailed offscale high Caused by line voltage transient on vital instrument bus 2B, causing instrument airroprocessor to lose contents W/B30628 ltr. FRAHM.R. Public Service Electric & Gas Co. of New Jersey. B3/06/22. ALLAN.J. Region 1. Office of Director. 4pp. 19514:192. 24X Fiche: 50-272, B3/06/22, 8307140001.

- 8307140142 LER 83-028/03L-0: on 830606, control room operator observed pressurizer backup & control heaters deenergized. Caused by failure of control relay for oil heater trip function. Relay coil replaced. W/830628 ltr.
  FRANN.R., ZUPKD.J. M. Public Service Electric & Gas Co. of New Jersey, 83/06/22. ALAN.J. Region 1. Office of Director. 4pp. 19514:064. 24% Fiche: 50-272.83/06/22.8307140142.
- 8307130276 Discusses actuation of first-out annunciators on 830527,28 & 30. Caused by maifunction of annunciator circuitry.
  Circuit boards replaced & pressure switch F-37 recalibr.
  LIDEN, E.A. Public Service Electric & Gas Co. of New Jarsey.
  83/07/01 LAINAS, G. C. Operating Reactors Branch 1. 4pp.
  19508:290. 24X Fiche: 50-272,83/07/01,8307130276.
- B307140501 Forwards AEDD/P301, "Rept on Implications of ATMS Events at Salem Nuclear Power Plant on NRC Program for Collection & Analysis of Operational Experience," for comment. DIRCKS, M. J. Office of the Executive Director for Operations, B3/07/05, PALLADING, N., GILINSKY, V., ROBERTS, T. Commissioners. 1p. 19526:149. 24% Fiche: 90-272, 83/07/05, 8307140501.
- --B307140507 "Rept on Implications of ATHS Events at Salem Nuclear Power Plant on NRC Program for Collection & Analysis of Operational Experience." \* Program Technology Brench. 83/07/31. 113pp. 19526:150. 24X Fiche: 50-272,83/07/05,8307140501.
- 8307220343 LER B3-029/03L-O: on 830617, control room operator discovered three RPI channels indicating greater than max allowed deviation in Tach Specs. Caused by calibr drift in two channels. Channels recalibr. W/830714 ltr. FRAHM.R.: ZUPKO, J. M. Public Service Electric & Qas Co. of New Jersey. 83/07/06. MURLEY.T. E. Region i. Office of Director. Spp. 19676:078. 24x Fiche: 50-272, 83/07/06, 8307220343.
- 8307180291 Staff requirements memo re 830705 briefing in Washington, DC on evaluation of implications of Salem event. Commission concurred in proposed ltrs to licensees, revised to include rept on status of complianca.

  CHILLA, B. J. Office of the Secretary of the Commission. 83/07/11, DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17566:163. 24X Fiche: 50-272, 83/07/11, 8307180291.
- 8307290045 Reviews AEOD final rept.AEOD/P301, "Rept on Implications of ATWS Events at Balem Nuclear Power Plant on NRC Programs for Collection & Analysis of Operational Experience." Subj of reactor trip reliability well treated.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
  83/07/21. HELTEMES.C.J. Director's Office. 1p. 19858:171. 24X Fiche: 50-272.83/07/21,8307290045.
- --B307130129 Forwards "Rept on Implications of ATMS Events at Balem Nuclear Power Plant on NRC Program for Collection & Analysis of Operational Experience."
  HELTEMES.C. J. Director's Office, 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19858:172. 24x Fiche: 50-272,83/07/21,8307290045.
- T. Hearing transcripts on non-antitrost matters
- B307110106 Transcript of Commission 830705 meeting re evaluation of implication of Salem event (Part II) in Washington, DC, Pp 1-82. Bupporting documentation encl. # Commissioners. B3/07/05. 100pp. 19386: 137. 24% Fiche: 50-272, B3/07/05, B307110106.
- 8307200137 Transcript of Commission 830713 public meeting in Mashington, DC re-continuation of evaluation of implications of Balam event. Pp 1-79. Supporting documentation encl. # Commissioners. 83/07/13. 91pp. 19471: 251. 24X Fiche: 50-272,83/07/13,8307200137.
- DUCKET 50-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR
  V. Operator Examinations
- B307080427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Btatement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche: 50-000,83/07/11,8307080427.

- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans
- B307120512 Forwards IE Insp Repts 50-275/83-19 & 50-323/83-15 on 830501-28 No noncompliance noted. B16HOP.T.W. Region 5. Office of Director 83/06/24. SCHUYLER, J. O. Pacific Gas & Electric Co. 2pp. 19433: 218. 24X Fiche: 50-275, 83/06/24, 8307120312.
- --8307120322 IE Insp Repts 50-275/83-19 % 50-323/83-15 nn 830501-28 No noncompliance noted Major areas inspected: plant operations. surveillance testing maint: TMI Item II. 8: 2: emergency preparedness; prepareditional besting & plant tours CARLSON. J. D., MENDONCA, M. M., KIRSCH, D. F. Region 5. Diffice of Director. 83/06/24. 7pp. 19433: 220. 24X Fiche: 50-275, 63/06/24, 8307120512.
- B30704017B Forwards "Procedures Ceneration Package," in response to Oeneric Ltr B2-33, Suppl 1 to NUREG-0737 re emergency response capability.

  SCHUYLER, J. O. Pacific Gas & Electric Co. 83/07/01. EISENHUT, D. G. Divition of Licensing. 1p. 19249:246. 24X Fiche: 50-275, 83/07/01, 8307060178.
- B307060180 "Procedures Generation Package." BEXTON, J. A. Pacífic Gas & Electric Co. 83/06/24. 37pp 19249:247. 24X Fiche: 50-275, 83/07/01, 8307060178.
- B307280101 Forwards Rev O to "Diable Canyon Power Plant Unit t.PG&E Review of IOCFR50, App R. Sections III. 0.III. J & III. J. "
  supplementing B11001 rept & completing requirement of License DPR-75. Section 2.C. (61) requirements.
  SCHUYLER, J. O. Pacific Oas & Electric Co. B3/07/15. EISENHUT, D. C. Division of Licensing. 1p. 19792: 261. 24X Fiche: 50-275.83/07/15, B307280101.
- --8307280115 Rev 0 to "Diable Canyon Power Plant.Unit 1.PG&E Review of 10CFR50.App R. Bections III. 0.III. J & III. 0."

  \* Pacific Gas & Electric Co. 83/07/15. 352pp. 19792:262. 24x
  Fiche: 50-275, 83/07/15, 8307280101.
- 8307250132 Releases public version of revised emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19738:172. 24X Fiche: 50-275, 83/07/19, 6307250132.
- --8307250139 Forwards public version of Rev O to Emergency Plan Implementing Procedure EP DP-4A re loss of electrical power & Rev O to Procedure EP DP-4B re loss of all ac power. CRANE.P.A. Pacific Oss & Electric Co. 83705718. MARTIN.J.B. Region 5, Office of Director. 2pp. 19738:173. 24X Fiche: 50-275,83/07/19.8307250132.
- --8307250196 Public version of Rev O to Emergency Plan Implementing Procedure EP OP-4A re loss of electrical power & Rev O to Procedure EP OP-4B re loss of all ac power.
  THORNBERRY, R. C. Pacific Gas & Electric Co. 83/04/07. 105pp. 19738: 175. 24X Fiche: 50-275,83/07/19,8307350132.
- R307270186 Releases public version of revised emergency plan implementing procedures.
  FELTON, J. M. Division of Rules and Records. 83/07/19. Document Managament Branch. 1p. 19811:103. 24X Fiche: 50-275, 83/07/19.
- --8307270195 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EP OP-11 re loss of component cooling water & Rev 4 to Procedure EP OP-3B re anticipated transient w/o trip. H/o Procedure EP OP-3B.

  SCHUYLER. J. O. Public Service Electric & Gas Co. of New Jersey.
  83/07/01. MARTIN, J. B. Region 5, Office of Director. 1p.
  19811: 104. 24X Fiche: 50-275, 83/07/19, 8307270186.
- --830727020i Public Version of Rev 3 to Emergency Plan Implementing Procedure EP OP-ii re loss of component caoling water. SCHUYLER, J. O. Public Service Electric & Gas Co. of New Jersey. 83/06/10. 26pp. 17811:105. 24X Fiche: 50-275, 83/07/17, 8307270186.
- G. Adjudicatory correspondence
- 8307030242 Response to 830610 first set of interrogatories re design QA. Certificate of Syc encl.
  REYNOLDS, J. R. Joint Intervenors-Diablo Canyon. REYNOLDS, J. R.
  Canter for Law in the Public Interest. 83/06/17. Pacific Gas & 8307050242.

- B307050241 Response to first set of interrogatories Personal qualification statement of RB Hubbard & Certificate of Svc encl. Related correspondence.

  DURBIN.S.L. California, State of, 83/06/27, Pacific Gas & Electric Co. 5ipp. 19197; 214, 24X Fiche: 50-275,83/06/27, B307050241.
- B307050075 Objects to Norton B30624 proposed schedule for reopened hearings on design GA. STRUMWASSER, M. California, State of B3/06/28. MODRE, T. S. Atomic Safety and Licensing Appeal Panel. 3pp. 19199:317 24X Fiche: 50-275, 83/06/28, 8307050075.
- 8307010115 Proposes alternate schedule for reopened hearing on design GA. Factors affecting schedule include NRC SER issuance scheduled for late Jul 1983 & hearing on motions to reopen record planned for 830719-22.

  CHANDLER, L. J. Hearing Branch 2. 83/06/30 MODRE, T. S. BUCK, J. H., JOHNSON, M. R. Atomic Safety and Licensing Appeal Panel. 2pp. 19168: 390. 24X Fiche: 50-275, 83/06/30, 8307010115.
- B307060437 Notice of correction to B30627 response to util first set of interrogatories.

  REYMOLDS.J.R. Joint Intervenors-Diable Canyon. REYMOLDS.J.R. Center for Law in the Public Interest. B3/06/30 2pp. 19239: 337. 24X Fiche: 50-275, 83/06/30, 8307060437.
- --B307060441 Verification & corrected Page I to B30627 responses to util first set of interrogatories. Certificate of Svc encl. 

  4 Jaint Intervenors-Diablo Canyon. 83/06/29. Pacific Gas & Electric Co. 4pp. 19239; 339. 24X Fiche: 50-275, 83/06/30, 8307060437.
- --B307060405 Forwards application for subpoena directed to VH Tennyson.

  DURBIN, S. L. California, State of. B3/07/01. MODRE, T. B. Atomic
  Safety and Licensing Appeal Panel. Ip. 19239: 326. 24X

  Fiche: 50-275, 83/07/01, 8307060397.
- ---B307060415 Application for issuance of subpoena directing VH Tennyson to testify at B30719 hearings. Proposed subpoena & Certificate of Svc encl.

  DURBIN.S.L. California, State of, B3/07/01, 9pp. 19239; 327.

  24X Fiche: 80-275,83/07/01,8307060397.
- 8307070235 Subposena directing VH Tennyson to appear on 830719 in San Luis Obispo, CA. MOGRE, T. S. Atomic Safety and Licensing Appeal Panel. 83/07/05. TENNYSON, V. H. Affiliation Unknown. 2pp. 19294:078. 24X Fiche: 50-275, 83/07/05, 8307070235.
- B3070B0207 Requests removal of listed names & firm from referenced docket svc list.Certificate of Svc enc.l. LANPHER.L.C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. B3/07/05. 4pp. 19391:340. 24X Fiche:50-275,83/07/05.8307080209.
- 8307070201 Motion to present evidence, not contained in CA Governor & Joint Intervenors 830606 motions, to reopen record. Info includes Board Notifications 83-83 & 83-87, unavailable when NRC 830606 response filed W/Certificate of 8vc. CHANDLER, L. J. Hearing Branch 2. 83/07/06. Atomic Safety and Licensing Appeal Panel. 4pp. 17267:158. 24X Fiche: 50-275, 83/07/06.
- B307070210 Forwards IE insp repts re const QA,per ASLAB B3062B order. W/o encis.

  CHANDLER, L. J. Hearing Branch 2. B3/07/06. MOURE, T. S., BUCK, J. H., JOHNSQN, M. R. Atomic Safety and Licensing Appeal Panel. 2pp, 19293: 357. 24% Fiche: 50-275, B3/07/06, B307070210.
- 8307080464 Order advising that scheduling conference to discuss milestones for reopened proceeding on design GA will be held at conclusion of hearing on motions to reopen record re const GA.

  8HOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 83/07/06. 2pp. 19346:304. 24X Fiche: 50-275,83/07/06,8307080464.
- 8307080469 Order clarifying 830628 order scheduling 830719 oral argument on motions to reopen record on const GA.NRC & util should provide uitnesses to testify re Board Notification 83-09 & PNOU-0-83-022A.
  SHOEMAKER.C.J. Atomic Safety and Licensing Board Panel. 83/07/06. 2pp. 19346: 320. 24X Fiche: 50-275. 83/07/06. 8307080469.

- B307120571 Suppl to Joint Intervenors 830510 motion to reopen record on const GA. Documents submitted are PNO-V-83-022A, notice of violation & IE Insp Rept 50-275/83-20. Certificate of Svc encl REYNOLDS, J. R. Joint Intervenors-Diablo Canuon. REYNOLDS, J. R.
  - encl
    REYNOLDS, J. R. Joint Intervenors-Diablo Canyon. REYNOLDS, J. R.
    Center for Law in the Public Interest. 83/07/06. Atomic Safety
    and Licensing Appeal Panel. 4pp. 19433:147. 24X
    Fiche: 50-275, 83/07/06, 8307120371.
- 8307120605 Order extending time until 830808 for Commission to act to review ALAB-728.

  CHILK.S J. Office of the Secretary of the Commission. 83/07/08.

  Commissioners 1p. 19432.268. 24X Fiche: 50-275.83/07/08.

  8307120605
- 8307130072 Second set of interrogatories propounded to independent design verification program contractors. DURBINS.L. California, State of. 83/07/08. 20pp. 19474:227. 24X Fiche:50-275,83/07/08,8307130072.
- ---8307130074 Second set of interrogatories Certificate of Svc encl, KAUFMAN.P.H. California, State of. 83/07/08. Pacific Gas & Electric Co. 19pp. 19474:247. 24X Fiche: 90-275, 83/07/08, 8307130072.
- 8307150357 Second set of interrogatories propounded to independent dasign verification program contractors. DURBIN,S.L. California, State of. 83/07/08. 20pp. 19539:110. 24X Fiche:50-275,83/07/08,8307150357.
- "-8307130361 Second set of interrogatories. Certificate of Svc encl. KAUFMAN.P.H. California. State of 83/07/08. Pacific Gas & Electric Co. 19pp. 19539: 130. 24X Fiche: 50-275, 83/07/08. B307150357.
- 8307130225 Response to Joint Intervenors 830706 suppl to 830510 motion to reapen record on const GA per ASLAB 830628 order. No objection to suppl record, provided insp rept & cover lite included w/notice of violation. Certificate of Syc encl. CHANDLER.L.J. Hearing Branch 2. 83/07/ii. Atomic Safety and Licensing Appeal Panel. 6pp. (9465:254. 24X Fiche: 50-275,83/07/ii. 8307130225.
- 8307150218 Response to motions to present add1 evidence by requesting acceptance of transmittal ltr & "Rept on Investigation of Reactor Coolant Pipe Weld Thickness at Diablo Canyon." H/o ltr & rept. Certificate of Svc encl.
  CRANE.P.A. Pacific Gas & Electric Co. 83/07/11. Atomic 8afety and Licensing Appeal Panel. 4pp. 19537:353. 24X
  Fichs: 50-275,83/07/11,8307150218.
- B307180070 Response to NRC. Joint Intervenors & CA governor motions to present addl evidence. Rept re reactor coolant pipe weld thickness investigation should be admitted. W/o rept. Certificate of Svc encl. CRANE.P. A. Pacific Gas & Electric Go. 83/07/11. Atomic 8afety and Licensing Appeal Panel. 4pp. 19560:157. 24X Fiche: 50-275,83/07/11,8307180070.
- B307200203 Motion to compel California Governor Deukmejian answers to B30610 interrogatories. Certificate of Syc encl. Related correspondence.

  NORTON, B. Pacific Gas & Electric Co. NORTON, B. Norton, Burke, Barry & French. B3/07/12. Atomic Safety and Licensing Appeal Panel. 15pp. 17648: 119. 24X Fiche: 50-273, B3/07/12, B307200203.
- 8307200311 Motion to compal Joint Intervenors answers to 830610 Interrogatories. Joint Intervenors totally disregarded discovery responsibilities & seek to undermine preparation for hearing. Certificate of Svc encl. Related correspondence. NORTON, B. Pacific Gas & Electric Co. NORTON, B. Norton, Burke, Berry & French. 83/07/12. Atomic Safety and Licensing Appeal Panel. 24pp. 19648:071. 24X Fiche: 50-275, 83/07/12, 8307200311.
- B307180022 Notice of appearance in proceeding Certificate of Svc encl. MCGURREN, H. J. Hearing Branch 1. 83/07/14. 3pp. 19360:154. 24X Fichs: 50-275,83/07/14,8307180022.
- B307180235 Lists schedule for review of independent design verification program & supplemental SER & consideration of NRC recommendations & responses.
  CHILK, S. J. Office of the Secretary of the Commission. 83/07/15.
  OHLBACH.R. Pacific Oas & Electric Co. REYNOLDS, J. R. Center for Law in the Public Interest. STRUMMASSER.W. California, State of. 2pp. 19555; 274. 24X Fiche: 50-275, 83/07/15, 8307180235.
- B307190133 Suppl to independent design verification program initial responses to first set of interrogatories. Certificate of Svc encl. Related correspondence.
  RABKIND. B. Lowenstein, Newman, Reis, Axelrad & Toll. 83/07/15.
  STRUMMASSER.M. California, State of. REYNDLDB.J.R. Center for Law in the Public Interest. 16pp. 19636:216. 24X Fichs:50-275, 83/07/15,8307190153.

- B307200122 Response to first document production request Certification of counsel encl.

  DURBIN,S.L. California, State of. 83/07/15. Pacific Gas & Electric Co. 8pp. 19645:336. 24X Fiche:50-275,83/07/18,8307200122.
- 8307260253 Response to 830610 first document production request.
  Certificate of Svc encl.Related correspondence.
  HAVIAN.E. Joint Intervenors—Diablo Canyon. HAVIAN.E. Center for
  Law in the Public Interest. 83/07/15. Pacific Gas & Electric Co.
  6pp. 19727:094. 24X Fiche: 50-275.83/07/15,8307260253.
- 8307260275 Motion to compal production of documents by Governor Daukmejian Correspondence, notes & other gubernatorial documents clearly fall within licenses request Certificate of Svc encl. Related correspondence.

  NORTON, B. Pacific Gas & Electric Co. NORTON, B. Norton, Burke, Berry & French. 83/07/20. Atomic Safety and Licensing Appeal Panel. 12pp. 19726:193. 24X Fiche: 30-275, 83/07/20, 8307260275.
- B307270147 Answers to second set of interrogatories. Certificate of Bvc encl. Related correspondence.
  LOCKE. R.F. Pacific Gas & Electric Co. B3/07/25. California, Btate of. 66pp. 19765: 26B. 24X Fiche: 30-275.83/07/25.8307270147.

#### H. General correspondence

- 8307180169 Expresses concerns re erosion problems on Pecho Ranch as result of Oct 1982 fire. Info re IE procedures requested.
  Listed pages of addendum to FES for clarification on licensing requirements encl.
  BRUND, G. E. Affiliation Unknown. 83/07/11. DENTON, H. Office of Nuclear Reactor Regulation. Director. 7pp. 19555:086. 24X Ficha: 30-275/83/07/11/8307180169.
- 8307180269 Responds to 830701 ltr requesting ASLAB consider concerns. ABLAB cannot consider concerns due to Commission rules of practice. Ltr forwarded to NRR Director for consideration. SHOEMAKER.C.J. Atomic Safety and Licensing Appeal Panel. B3/07/14. FUNK.D.J. Pismo Beach. CA. 1p. 19556:194. 24X Piche:30-275.83/07/14.8307180269.
- --8307180272 Forwards City of Pismo Beach, CA 830701 ltr expressing concerns re San Luis Diispo County emergency response plan.
  Ltr referred for consideration.
  SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel.
  83/07/14. DENYUN.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19556:195. 24X Fiche: 50-275, 83/07/14, 8307180269.
- --8307180274 Expresses concern re plant licensing Deficiencies in San Luis Obispo County emergency plan should be considered. FUNK.D.J. Pismo Beach. CA. 83/07/01. MORRELT. Atomic Safety and Licensing Appeal Panel. 16pp. 19556:196. 24X Fiche: 50-275,83/07/14,8307180269.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for GLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Outdelines." Svc list enci.
  EISENHUT.D.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563: 116. 24X Fiche: 50-000, 83/06/03. 8306060070.
- B307260379 Forwards proposed change to FSAR Chapter 17 re company QA organization. W/one oversize figure. Aperture card is available in PDR.

  SCHUYLER.J.O. Pacific Oas & Electric Co. 83/06/10. MARTIN. J. B.

  Region 3. Office of Director. 22pp. 19731:173, 24x

  Fiche: 50-275, 83/06/10, 8307260379.
- 8307150368 Notification of 830617 meeting w/util, Bechtel & SNL in Bethesda, MD to discuss results of BNL seismic analysis of buried tanks in connection w/independent design verification program.

  SCHIERLING, H. Licensing Branch 3. 83/06/15. KNIOHTON, G. W. Licensing Branch 3. 2pp. 19340:341. 24X Fiche: 50-275,83/06/15,8307150368.
- 8307050359 Submits followup to B30609 % 10 telcons re resolution of issue of appropriate intake temp to be used in component cooling water sus post-accident heat removal analysis. Draft should be submitted prior to 830701 submittal.

  KNIGHTON. 6. Licensing Branch 3. 83/06/22. SCHUYLER, J. O. Pacifi Gas & Electric Co. 4pp. 19263: 330. 24X Fiche: 50-275, 89/06/22, 8307050359.

- 8307050365 Requests add1 written info addressing eight allegations concerning design verification effort Info requested within 2 wis of itr receipt. WhiGHTON, G.W. Licensing Branch 3. 83/06/22. SCHUYLER, J. D. Pacific Gas & Electric Co. 3pp. 19263:327. 24X Fiche: 50-275, 83/06/22. 8307080345
- 8307010163 Forwards add1 info re component cooling water sys. Mat1 provides info on affects on sys performance from air operated valves assuming "fax1-safe" position on loss of instrument air 2 evaluation of max blow capabilities.
  SCHUYLER.J.O. Pacific Gas & Electric Co. 83/06/27. EISENHUT.D.O. Division of Licensing. 4pp. 19170:081. 24X Fichs: 50-275,83/06/27,8307010163.
- 8307060233 Summarizes 830622 meeting w/util % RL Cloud Associates reports outstanding requests for info on repture restraints from independent design verification program. Meeting notes available for review.

  COOPER, W. E. Teledyne Engineering Services. 83/06/29. DENTON, M. R. Office of Nuclear Reactor Regulation. Director. MARTIN, J. B. Region 5. Office of Director. MANEATIS, G. A. Pacific Cas & Electric Co. 2pp. 19239.354. 24X Fiche: 50-275.83/06/29,8307060233.
- B307140155 Notification of B30706 meeting w/wtil, Bechtel & BNL in Bethesda, MD to discuss seismic analysis of buried tanks. SCHIERLING. H. Licensing Branch 3, B3706729, KN10H70N.O. H. Licensing Branch 3, 6pp. 19540:020, 24X Fiche: 50-275,83/06/29, B307140155.
- 8307060088 Forwards add1 info re component cooling water sys requested 830622 Info demonstrates adequacy of sys operation for applicable conditions. Proposed Tech Spec on Item 4 re ocean water intake temp will be submitted by 830701. SCHUYLER, J. O. Pacific Gas & Electric Co. 83/06/JO. KNIGHTON, G. H. Licensing Branch J. App. 19252:001. 24X Fiche: 50-275, 83/06/JO. 8307060088.
- 8307040194 Forwards application to amend License DPR-76, consisting of Request 83-07, revising Tech Specs re ultimate heat sink to address intake ocean water temp monitoring 2 action taken in event temp exceeds 64 F. Class III amend fee encl.

  SCHUYLER, J. D. Pacific Gas & Electric Co. 83/07/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. Ip. 19249; 294. 24X Fiche: 50-273, 83/07/01, 8307060196.
- --8307060199 Application to amend License DPR-76, consisting of Request 83-07, revising Tech Specs re-ultimate heat sink to address intake ocean water temp monitoring & action taken in event temp exceeds 67 F.

  BRAND. D. A., CRANE, P. A. Pacific Gas & Electric Co. 83/07/01. 2pp. 19249: 295. 24X Fiche: 50-275, 83/07/01, 8307060196.
- --8307060202 Tech Specs 3/4.7.12 re ultimate heat sink (Pacific Ocean). \* Pacific Oas & Electric Co. 83/07/01 2pp. 19249:297. 24X Fiche: 50-275, 83/07/01, 8307060196.
- B307070026 Notifies that mods to fuel bldgs completed & actions parmitted by Amends 3 & 5 to License DPR-76 ceased by B30620 Original requirements of Tech Spec 3/4.9.7 will prevail.

  SCHUYLER, J. D. Pacific Gas & Electric Co. 83/07/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19293: 241. 24X Fiche: 30-275, 83/07/01.8307070026.
- 8307130221 Forwards response to 830622 ltr re anonymous allegations identified in DS Fleischaker 830328 ltr to DG Eisenhut re design verification effort Containment structure stability analysis indicates large safety factor against overturning. SCHUYLER. J. D. Pacific Gas & Electric Co. 83/07/01. KNIGHTON, G. W. Licensing Branch 3. 15pp. 19508:014. 24x Fiche: 50-275.83/07/01. 8307130221.
- B307130278 Forwards "Final Rept on Evaluation of Spot-Welded Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Campon Power Plant." supplementing Bechtel rept transmitted by POSE B30225 ltr.
  SCHUYLER, J. D. Pacific Gas & Electric Co. B3/07/01. EISENHUT, D. O. Division of Licensing. 19. 19474:006. 24X Ficho: 50-275, 83/07/01. 8307130278.
- --8307130281 "Final Rept on Evaluation of Spot-Welded Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Campon Fower Plant " 8 Bechtel Corp. 83/07/01. 19pp 19474:007. 24X Fiche: 50-275,83/07/01,8307130278.
- --8307130286 "Outline for Sampling Preparation & Testing of Spot-Welded Superstrut Members for Diablo Canyon Power Plant." 
   Bechtel Corp. 0072C/0109. 83/06/02. 12pp. 19474:026. 24X Fiche: 50-275,83/07/01.8307130278.

- --8307130291 "Statistical Analysis of Shear Strength Data for Support Strut Spot Welds, Diablo Canyon Power Plant." \* Jack R. Benjamin & Associates, Inc. 113-090-H-01. 83/06/30, 18pp. 19474:038. 24x Fiche:50-275,83/07/01,8307130278.
- --B307:30298 Forwards "Investigation of Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diable Cangon."
  Superstrut spot-welded members meet design requirements & may be installed.
  CRANE.P.A. Pacific Gas & Electric Co. B3/02/25. ENGELKEN.R.H., MORRILL.P.O. Region 5. Diffice of Director. 1p. 19474:056. 24x Fiche: 30-275,83/07/01,8307130278.
- --8307130302 "Investigation of Matls Used in Support Sys for Electrical Conduit & Cable Trays at Biablo Canyon."

  \* Bechtel Corp. 83/02/25. 39pp. 19474:037. 24X
  Fiche: SO-275,83/07/01,8307130278.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/05, Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307140499 Provides status of final repts re design verification effort by util & independent design verification program. Suppl to EER will be prepared providing basis for NRC recommendation to Commission re reinstatement of suspended license.

  DIRCKE, W. J. Diffice of the Executive Director for Operations.

  83/07/05. PALLADIND, N., GILINSKY, V., AHEARNE, J. Commissioners.

  2pp. 19326:141. 24X Fiche: 50~275,83/07/05,8307140499.
- 830719044( Requests assessment of factual circumstances surrounding independent design verification program interaction w/util at 830614 meeting.per encl Ctr for Law in Public Interest 830629 ltr.
  EISENHUT, D. G. Division of Licensing. 83/07/05. COOPER.W. E. Teledyne Engineering Services. 3pp. 19540: 208. 24X Fiche: 50-275.83/07/05.8307150441.
- B307040329 Openric Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669: 267. 24X Fiche: 50-000, 83/07/08. B307080169.
- B307120533 Notification of B30710 significant licensee meeting w/util in Walnut Creek.CA to discuss licensee presentation on RCB plping min wall thickness. Agenda encl.

  MDRRILL.P. J. Region 5. Office of Director. 83/07/08. EISENHUT.D.O.

  Division of Licensing. BUCKLEY.B.C. SCHIERLING.H.E. Office of Nuclear Reactor Regulation, Director. 5pp. 19433:317. 24X

  Fiche: 50-275.83/07/08.8307120333.
- 8307130097 Responds to 830705 ltr requesting info on 830614 meeting re independence of independent design verification program. Meeting does not evidence any violation of or inadequacy in procedures adopted to maintain independence. CDOPER.W.E. Teledyne Engineering Services. 83/07/08. EISEMUT.D.Q. Division of Licensing. 3pp. 19465:341. 24X Fiche: 50-275:83/07/08. 8307130097.
- B307110002 Board Notification 83-76 forwards PQ&E 830705 ltr transmitting "Rept on Investigation of Reactor Coolant Pipe Weld Thickness." EISEN-WILT, D. 9. Division of Licensing. 83/07/11. PALLADIND, N. J., OILINSKY, V., ROBERTS, T. M. Commissioners. 3pp. 19381:315. 24X Fichs: 50-275,83/07/11.8307110002.
- "-8307110406 Forwards "Rept on Investigation of Reactor Coolant Pipe Held Thickness." SCHUYLER, J. D. Pacific Gas & Electric Co. 83/07/05, MARTIN, J. B. Region 5, Defice of Director. 45pp. 1938i: 318. 24X Fiche: 50-275, 83/07/11, 8307110002.
- B307180002 Forwards corrected page of Section 4.2 in B30510 submittel re pump & valve inservice testing program Valves FCV-676 & 7 incorrectly listed w/exercise frequency of G. Valves cannot be exercised during operation.

  BCHUYLER.J. D. Pacific Gas & Electric Co. 83/07/12. KNIGHTON.G.H. Licensing Branch 3. 2pp. 19560:326. 24X Fiche:50-275,83/07/12,8307180002.

- B306270407 Board Notification 83-98 forwards info items re design verification program including trip rept of 830512 technical exchange meeting & transcript of 830706 meeting re seismic analysis of buried pipes.
  EIGENHUT.D.O. Division of Licensing. 83/07/14. PALLADINO, N., OILINSKY, V., ROBERTS, T. Commissioners. 3pp. 17627:262. 24X Fiche: 50-275,83/07/14,8306270407.
- --8307190070 Transcript of Commission 830706 meeting in Bethesda.MD redesign verification program seismic analysis of buried tanks.Pp 1-101.Supporting documentation encl.

  \* Commissioners. 83/07/06. 125pp. 19627:269. 24X
  Fiche: 50-275.83/07/14.8306270407.
- B307190171 Advises that Joint Intervenors charged that independent design verification program (IDVP) yielded to util pressure & util seeking to disute IDVP independence. Disputes charges. BCHUYLER, J. G. Pacific Qas & Electric Co. B3/07/14. DENTON, H. Office of Nuclear Reactor Regulation. Director. 3pp. 19634:167. 24X Fiche: 50-275, B3/07/14, B307190171.
- 8307290170 Forwards FR notice of consideration of issuance of amend to License DPR-76 & proposed NBHC determination & opportunity for hearing re Tech Spec changes on installation of two new inverters & associated buses. NSHC determination withheld.

  BUCKLEY.B. Licensing Branch 3. 83/07/15. BCHUYLER.J.O. Pacific Oas & Electric Go. 4pp. 19857:037. 24X Fiche: 30-275,83/07/15,8307270190.
- --8307290192 Notice of consideration of issuance of amend to License DPR-76 & proposed NBHC determination & opportunity for hearing re Tech Spec changes on installation of two new inverters & associated buses to satisfy NUREG-0737. KNTOHTON, O.W. Licensing Branch J. 83/07/12. Spp. 19857:041, 24X Fiche: 50-275, 83/07/15, 8307290190.
- B307190044 Advises of 830721 meeting in Ban Francisco.CA to discuss rupture restraint program. Agenda included. COOPER.M.E., CRAOIN.J.G. Teledyne Engineering Services. 83/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ip. 19635:135. 24X Fiche: 50-275,83/07/19.8307190044.
- B307280292 Forwards Rev O to "Diablo Canyon Independent Design Verification Program, Containment Annulus Structure Vertical Ssismic Evaluation," Interim Technical Rept 50.
  COOPER, W. E. Teledyne Engineering Services. B3/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. MANEATIS, O. A. Pacific Gas & Electric Co. MARTIN, J. D. Region 5. Office of Director. 2pp. 19787: 327. 24X Fiche: 50-275, 83/07/22, 8307280292.
- --8307280297 Rev O to "Diablo Canyon Independent Design Verification Program, Containment Annulus Structure Vertical Seismic Evaluation," Interim Technical Rept 50. WRAY, R., BIQOS.J. M., HOLLEY, M. J. Teledyne Engineering Services. 83/07/22. B4pp. 19789: 327. 24X Fiche: 50-275, 83/07/22, 8307280292.
- 8306270417 Board Notification 83-103: forwards matl re safety issue on design adequacy which will be used in formulating NRC position on low power license reinstatement.
  EIGENHUT, D. G. Division of Licensing, 83/07/26. PALLADING, N. J., ofLINSKY, V., ROBERTS, T. M. Gommissioners, 4pp. 19815:271. 24X Fiche: 50-275, 83/07/26, 8306270417.
- 8307290195 Advises that change in ESF response time for containment spray initiation does not involve significant reduction in safety or significant hazard consideration defined in iOCFR50. 92. supporting 830623 request for license amend. SCHUVLER.J. O. Pacific Oas & Electric Co. 83/07/26. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19821: 142. 24X Fiche: 50-275, 83/07/26, 8307290195.
- 8307220334 Notification of B30727~28 meetings w/NRC in San Francisco.CA to discuss independent design verification program closure plan & implementation of plan by discipline areas. Meeting agenda enci.
  COOPER.W. E., CRAOIN, J. Q. Teledyns Engineering Services. 89/07/27.
  Teledyna Engineering Services. 2pp. 19675:353. 24X
  Fiche: 30-275,83/07/27.8307220334.
- 8307290221 Forwards response to NRC question re classification of instrumentation & control for containment isolation valves FCV-37 & FCV-38.

  80HUYLER, J. D. Pacific Gas & Electric Co. 83/07/27. KNIOHTON, C. Licensing Branch 3. Spp. 19822:025. 24x Fiche: 50-275,83/07/27,8307270221.
- 8306270419 Board Notification 83-077A: forwards summary of evaluation of allegation re-release of NRC draft rept. Basis for allegation inaccurate.

  EISENAUT.D. 9. Division of Licensing. 83/07/28. PALLADIND, N. J., OILINSKY, V., ROBERTB, T. M. Commissioners. 5pp. 19815: 328. 24X Fiche: 80-275, 83/07/28, 8306270419.

- G. Inspection reports, IE Bulletins & correspondence
- 8307120512 Forwards IE Insp Repts 50-275/83-19 & 50-323/83-15 on 830501-28 No noncompliance noted.
  BISHDP.T W. Region 5. Office of Director. 83/06/24. SCHUYLER, J. D. Pacific Gas & Electric Co. 2pp. 19433:218. 24X
  Fiche: 50-275,83/06/24,8307120512.
- --8307120522 IE Insp Repts 30-275/83-19 & 50-323/83-15 on 830501-28. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, maint TMI Item II. B. 2, emergency preparedness, preoperational testing & plant tours. CARLSON. J. D., MENDONCA. M. M., KIRSCH. D. F. Region 5, Office of Director. 83/06/24, 7pp. 19433: 220. 24X Fiche: 50-275,83/06/24,8307120512.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche: 50-000:83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid," Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141gp. 19563:153. 24X Fichs:50-D00.83/07/12.8306270404.
- B306270406 IE Info Notice B3-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list ancl. TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000:B3/07/14.B306270406.
- R. Periodic operating reports & related correspondence
- 8307220476 Monthly operating rept for May 1983.W/830602 ltr.
  KELLY,W.J., THORNBERRY,R.C. Pacific Gas & Electric Co. 83/06/02.
  Office of Resource Management Director. 7pp. 19685:142. 24X
  Fiche: 50-275.83/06/02.8307220476.
- B307010170 Furwards final installment of "Design Verification Program Phase I Final Rept," per Order CLI-Bi-30.

  BCHUYLER.J. D. Pacific Gas & Electric Co. 83/06/21. EISENHUT.D. 9. Division of Licensing. 380pp. 19170:101. 24X Fiche: 50-275. B3/06/21.8307010170.
- 8307050349 Comments on Interim Technical Repts (ITR) 13,16,39 & 40 re independent design verification program. ITRs should be revised & combined w/remaining geotechnical issues into single rept.
  EISENNUT.D.O. Division of Licensing. 83/06/21. COOPER.W.E. Teledyne Engineering Services. Spp. 19263:334. 24X
  Fiche: 50-275.83/06/21.8307050349.
- 8307120324 Forwards "Semimonthly Rept 40: Diablo Canyon Verification Program, 830607-20." SCHUYLER, J. G. Pacific Oas & Electric Co. 83/06/24. DENTON, M. R. Office of Nuclear Reactor Regulation. Director. MARTIN, J. B. Region 5. Office of Director. ip. 19429: 289. 24x Piche: 50-275, 83/06/24, 8307120324.
- --8307120327 "Semimonthly Rept 40: Diablo Canyon Verification Program, 830607-20." HOCH J.B. Pacific Gas & Electric Co. 83/06/24. 69pp. 19429: 290. 24% Fiche: 50-275,83/06/24,8307120324.
- 8307030093 Forwards sixth text submittal of independent design verification program final rept.Final submittal scheduled for 830430.
  COUPER.W. E. Teledyne Engineering Services. 83/06/28. DENTON,H. R. Office of Nuclear Reactor Regulation. Director. MARTIN.J.B. Region 5. Office of Director. MANEATIS.G.A. Pacific Gas & Electric Co. 82pp. 19197:286. 24X Fiche: 50-275.83/06/28,8307030093.
- 8308110806 Board Notification 83-89: forwards Teledyne Engineering Svc "Independent Design Verification Rept - Fifth Text 8ubmittal" % "Independent Design Verification Rept - Errata Package 2." EISENHUT, D. 0. Division of Licensing. 83/06/29. PALLADINO, N. J. Commissioners. 3pp. 19172: 263. 24X Fiche: 50-275, 83/06/29, 8305110506.

- 6 B01210121 Formards Rev O to TAidl Verification of Selection of Sys Design Bressing (1.6 TAid) Verification of Circuit Department (1.6 Taid) Verification of Circuit Department (1.6 Taid) Verification of 49, respectively ARCHINIO 0 & Bone & Wester Engineering Corp. 83/06/30. Extros 48 of Effice of Nuclear Peactor Regulation, Director, manting 3 Gegion 5. Office of Enector MARCHING. A. Pacific Las & Electric Co. 1p. 1920 116 24x Fichs. 50-275.83/06/30. 030710103
- -830-150:31 Re. 6 to 'Aidi Vetification of Selection of Sys Design Ressure 5 fem & Oifferential Pressure Across Power Pressure 5 fem & Oifferential Pressure Across Power Pressure values. Independent Design Verification Program, "Interim Technical Rept 46 COSTAM. 5 Stone 6 Medister Engineering Corp. 83/06/27. 28pp. 19221 117 ZAX Fiche 50-275.83/06/30.8307050134.
- m-0337050143 Reu G to "Addi Verification of Environ Consequences of Fistulated Pipe Ruptures Cutside of Containment Independent Design Verification Frograp." Interin Technical Rept. 47. SESTAM: P. Stone & Webster Engineering Corp. 83/06/27. 29pp. 19221 144 24X Fiche 50-275.83/05/30.8307050134.
- -- -6337050142 Rev O to "AddI Verification of Circuit Separation & Single Failure Review of Safety-Pelated Electrical Equipment Independent Design Verification Program." Interim Technical Rept 47

  55876w.F. Stone & Webster Engineering Corp. 63/06/23. 16pp. 19721 173 24x Fishe 50-275.63/06/30.8307050134
- BB37C5C249 Forwards "Independent Design Verification Program Final Rept 'seventh text submittal CODPER.W E Telegane Engineering Services B3/06/30. DENTON.H.R. Defice of Nuclear Reactor Repulation. Director. MARTIN.J.B. Region 5. Geffice of Director MAREATIS.G A Pacific Gas & Electric Co. But 19194 259 244 Fichs 5C-275.83/C6/30.8307050245.
- 0306270376 Deard Notification 83-09: forwards info on status of activities cerformed as part of design verification efforts for facility info relevant to formulating recommendation receives testestes of low-power license suspended by CLI-BI GLOCHAULD & Division of Licensing 83/07/01. PALLADIND.N.J., GLINERY V. AMEARKE.J.F. Commissioners. 3pp. 19266-001. 24X Figns 51-175-53/07/01.8306270376
- 633627C40) Board Notification 83-92 Forwards sixth & seventh submittals of independent design verification program for Diablo Cartary, Unit 1, Final repts
  EISENMENT 0 & Division of Licensing, 83/07/07, PALLADINO, N. J., GLINGKY V. AMERANEL J.F. Commissioners 3pp 19345:001, 24X
- G-307130207 Forwards "Diable Canyon Nuclear Power Plant Unit 1 Independent Design Verification Program." Second Friday Seminonthic rept for Jul 1983 COGFEW, W.E. Feledyne Engineering Services. 83/07/08. DENTON, H.R. G. Files of Nuclear Reactor Regulation. Director. MARTIN, J.S. Region 19 19828 15B 24x Fiche 50-275, 83/07/08, 8307130207.
- ED 307130243 Forwards Rev I to Open Item Rept Li28. Rev O to Repts 133. 134. 133 1336 % 1337. Seminonthly rept for Jul 1983 % premium tell page describing station battery racks: large bore DEFNISCHE F Robert L. Cloud Associates, Inc. 83/07/08. EDENISCHE F Right L. Cloud Associates, Inc. 83/07/08. EMARTIN. J Brigion 5. Office of Director Regulation, Director. Gas & Electric Co. 8pp. 19507-344 24x Fiche. 59-275. 83/07/08.

- 8307180154 Advises that no open item repts issued since last semimonthly rept.

  RECHTING. J. E. Stone & Webster Engineering Corp. 83/07/08, DENTON.H.R. Office of Nuclear Reactor Regulation, Director, MARTIN.J. B. Region 5, Office of Director, MANEATIS. G. A. Pacific Oas & Electric Co. 1p. 17556:249. 24x Fiche: 50-275,83/07/08,8307180154.
- B307220362 Forwards 41st semimonthly status rept for design verification program. Rept summarizes progress of technical work from B30621-0705.
  SCHOYLER.J.D. Pacific Gas & Electric Co. 89/07/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MARTIN.J.B. Region 5. Office of Director. 47pp. 19676:001. 24X Fiche: 50-275.83/07/08, 8307220362.
- B307200081 Forwards Errata Package 3 to "Independent Design Verification Program Final Rept." Next submittal scheduled for B30730.

  COUPER, W.E. Teledyne Engineering Services. B3/07/15. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. MARTIN, J. D., Region 5, Office of Director. MANEATIS, G.A. Pacific Gas & Electric Co. ip. 19645:210. 24% Fiche:50-275, B3/07/15, B307200081.
- --B307200084 Errata Package 3 to "Independent Design Verification Program Final Rept."

   Teledyne Engineering Services. 83/07/15. 150pp. 17645:211. 24X Fiche: 50-275, 83/07/15, 8307200081.
- B307260505 Forwards list of effective pages for independent design verification program final rept.1983. List gives current page number, rev number & page code for every page of final rept. COOPER.W.E. Teledyne Engineering Borvices. B3/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. MARTIN, J.B. Region 5. Office of Director. MANEATIS.Q.A. Pacific Gas & Electric Co. 58pp. 19733:256. 24X Fiche: 50-276.83/07/22.8307260506.
- 8307260537 Forwards "Diable Canyon Nuclear Power Plant Independent Design Verification Program," semimenthly rept for Jul 1983. COPER. H. E. Teledyne Engineering Services. 83/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MARYIN. J. B. Region 5, Office of Director. MANEATIS. G. A. Pacific Gas & Electric Co. 19. 19732:028. 24X Fichs: 50-275,83/07/22,8307260539.
- --8307260544 "Diable Canyon Nuclear Power Plant Independent Design Verification Program," semimenthly rept for Jul 1983. \* Teledyne Engineering Services. B3/07/22. 61pp. 19732: 029. 24X Fiche: 50-275, 83/07/22, 8307260539.
- 8307280296 Forwards "Semimonthly Rept 42: Diable Conyon Verification Program, 830706-18," per Commission Order CLI-81-30. SCHUYLER, J. O. Pacific Oas & Electric Co. 83/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MARTIN, J. B. Region 5. Office of Director. ip. 19789: 249. 24X Fiche: 50-275, 83/07/22, 8307280296.
- --8307280301 "Semimonthly Rept 42: Diablo Canyon Verification Program, 830706-18." HOCH.J.B. Pacific Oas & Electric Co. 83/07/18. 72pp. 19789: 250. 24X Fiche: 50-275, 83/07/22, 8307280276.
- S. Reportable occurrences, LERs & related correspondence
- B307270257 Forwards AEOD technical review rept of B30419 event involving intentional gouges in main coolant pipe. Licensee has taken corrective measures. Plant has had some security ZVKOR, D. Reactor Operations Analysis Branch. B3/06/15. SEYFRIT, K. V. Reactor Operations Analysis Branch. 1p. 19826:329. 24X Fiche: 50-275, 83/06/15, B307270257.
- --8307290268 "Gouges in Main Coolant Bys Piping," AEOD technical review rept.
  ZUKOR, D. Reactor Operations Analysis Branch. 83/06/15, 3pp.
  19826: 330. 24% Fiche: 50-275,83/06/15,8307290257.
- 8307130092 LER 83-015/03L-0: on 830526, annunciator window in channel functional test procedure for vent iodine sampler RM-24 reflect design change. Procedure updated procedures to KELLY, M. J., SHIFFER, J. D., Pacific Gas & Electric Co. 83/06/27, MARTIN, J. B., Region 5, Office of Director. 3pp. 17465:336. 24X
- 8307220271 LER 83-016/03L-0: on 830606, plant vent flow rate monitor FR-12 discovered deenergized. Caused by personnel error. Approval. W/830705 ltr research clearance requests prior to KELLEY, U.J. SHIFFER, J. Pacific Gas & Electric Co. 83/07/05. Fiche: 50-275, 83/07/05, 8307220271.

### T. Hearing transcripts on non-antitrust matters

- 8306270407 Board Notification 83-98 forwards info items re design vertification program, including trip rept of 830912 technical exchange meeting & transcript of 830706 meeting re seismic analysis of bursed pipes EISENBUT.D G Division of Licensing. 83/07/14. PALLADINO,N., OLL INSENT. PROBERTS.T. Commissioners. 3pp. 19627-262. 24x Fiche: 50-275,83/07/14.8306270407
- --8307190070 Transcript of Commission B30706 meeting in Bethesda. MD re design verification program - seismic analysis of buried tanks Pp 1-101 Supporting documentation encl. \* Commissioners. 83/07/04. 125pp. 19627. 269. 24X Fiche 50-275, 83/07/14. 8306270407
- B307260532 Transcript of 830719 hearing in San Luis Obispo.CA.Pp 1-225. # Atomic Safety and Licensing Appeal Panel. 83/07/19. 226pp. 19732: 107 24X Fiche 50-275.83/07/19.8307260932.
- 8307270003 Transcript of 830720 hearing in San Luis Obispo, CA, Pp 226-498.

  \* Atomic Safety and Licensing Appeal Panel. 83/07/20. 273pp. 19748:210. 24X Fiche. 50-275, 83/07/20, 8307270003.
- 8307270021 Transcript of 830721 hearing in San Luis Obispo, CA. Pp 499-768. \* Atomic Safety and Licensing Appeal Panel. 83/07/21. 270pp. 19745: 242 24X Fiche: 50-275. 83/07/21. 8307270021.
- # Atomic Safety and Licensing Appeal Panel. #83/07/22. 55pp. 19749.204 24% Fiche: 50-275,83/07/22,8307270024.

DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR
V. Operator Examinations

- 8397080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche 50-000.83/07/11,8307080427.
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- B307260421 "Exercise Manual Peach Bottom Atomic Power Station NRC/FEMA Chserved Emergency Response Exercise on B30628." W/one oversize figure. Aperture card is available in PDR. W/830525 ltr.
  DALTROFF, S. L. Philadelphia Electric Co. 83/05/25. ALLAN, J. M. Region 1. Dffice of Director. 285pp. 19730:159. 24X Fiche: 50-277, B3/05/25, B307260421
- 8307150292 Informs that 830527 ltr on status of 47 mods to fire protection sys contained errors in status of mods to emergency lighting sys 480-volt circuit breaker settings. Corrected status & revised completion dates provided. BOYER.V.S. Philadelphia Electric Co. 83/07/11. EISENHUT.D.G. Division of Licensing. 4pp. 19532:193. 24X Fiche: 50-277, 83/07/11, 8307150292.
- 8307220058 Discusses 830708 meeting w/util re deficiencies identified during annual emergency preparedness exercise conducted on 830628. Emergency preparedness drill should be conducted to evaluate listed activities.

  MARTIN.T. Division of Engineering & Technical Programs. 83/07/13. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 19674:028. 24X Fiche: 50-277, 83/07/13, 8307220058.
- 8307250672 Releases public version of revised emergency plan implementing procedures. FECTON.J M Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19719 219 24X Fiche: 50-277.83/07/19, 8307250672.
- --8307250576 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-101 re classification of emergencies, EP-102 re unusual event response & EP-103 re alert response Affidavit encl. DALTROFF, S. L. Philadelphia Electric Co. 83/05/13. ALLAN. J. M. Region i. Office of Director. 4pp. 19719. 220. 24x Fiche 50-277, 83/07/19, 8307250672.

- --B3072506B0 Public version of revised emergency plan implementing procedures including Procedures EP-101 re classification of emergencies, EP-102 re unusual event response & EP-103 re alert response.

  DALTROFF, B. L. Philadelphia Electric Co. 83/04/13. 80pp. 19719: 224. 24X Fiche: 50-277, 83/07/19, 8307250672.
- 8307270041 Releases public version of revised emergency plan implementing procedures.

  FELTON, J. M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19806:236. 24X Fiche: 90-277,83/07/19, 8307270041.
- --8307270043 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-316 recumulative population dose calculations, EP-206A refire fighting group & EP-206B redamage repair group.

  DALTROFF, S.L. Philadelphia Electric Co. 83/07/01. ALLAN, J. M. Region 1, Office of Director. 1p. 19806: 257. 24X Fiche: 50-277, 83/07/19, 8307270041.
- --8307270046 Public version of revised emergency plan implementing procedures including Procedures EP-316 re cumulative population dose calculations EP-206A re fire fighting group & EP-206B re damage repair group.

  \* Philadelphia Electric Ca. 83/05/31. 238pp. 19806: 258. 24X Fiche: 50-277, 83/07/19, 8307270041.
- B307290101 Updates items in pending fire penetration seal exemption request Mod to add emergency lighting in fifth bay of diesel bldg complete & no exemption request forthcoming.

  BOYER,V.S. Philadelphia Electric Co. 83/07/22. EISENHUT, D. O. Division of Licensing. 3pp. 19820:357. 24X Fiche: 50-277, 83/07/22, 8307290:01.
- G. Adjudicatory correspondence
- 8307210249 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC. SILDERG, JE. Shaw. Pitthan. Potts & Trombridge. 83/07/13. PALLADIND, N. J., GILINSKY. V. AHEARNE, J. F. Commissioners. 1p. 19664:061. 24X Fiche: 50-000, 83/07/13. 8307210248.
- --8307210251 Notifies of employment at law firm.VR Harding will not participate in any case pending before NRC Svc list encl. HARDING, V.R. Shaw. Pittman. Potts & Trowbridge. 83/07/13. FALLABIND, N.J. GILINSKY, V. AHERANE, J.F. Commissioners. 5pp. 19664:062. 24X Fiche: 50-000,83/07/13,8307210248.
- J. Insurance & indemnity information
- 8307080454 Forwards Endorsement 102 to NELIA Policy NF-140. Endorsement 55 to MAELU Policy MF-67. BRADLEY.E.J. Philadelphia Electric Co. 83/07/01. SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance). 3pp. 19347:222. 24% Fiche: 50-277, 83/07/01, 8307080454.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307220238 Forwards Rev 1 to updated FSAR. BRADLEY.E.J. Philadelphia Electric Co. 93/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19673:001. 24X Ficha: 50-277, 83/07/20, 8307220239.
- --8307220241 Rev 1 to updated FSAR. W/23 oversite figures. Aperture cards are available in PDR.

   Philadelphia Electric Co. 83/01/31. 326pp. 17673: 005. 24X Fiche: 50-277, 83/07/20, 8307220238.
- P. Operating license stage documents & correspondence
- B307080259 Forwards backfit cost figures for add1 seven utils per original 830208 request Cost figures for 20 utils transmitted 830411.
  TOURTELLOTTE, J. Requiatory Reform Task Force. B3/06/22.
  PALLADINO, N., QILINSKY, V., AHEARNE, J. Commissioners. 2pp. 19363:313. 24X Fiche: 50-000, B3/06/22, B307080259.
- --8307080352 Forwards backfit cost tabulations for facilities, per NRC 830208 request.

  KEMPER.J.S. Philadelphia Electric Co. 83/05/04. TOURTELLOTTE, J. Regulatory Reform Task Force. 6pp. 19364:003. 24X
  Fiche: 50-000.83/06/22,8307080259.
- B307010009 informs that during 1982, there were no challenges to primary cootant sys safety & relief valves, per NUREQ-0737, Item
  II.K.3.3
  DALTROFF, S.L. Philadelphia Electric Co. B3/06/27, EISENHUT, D. Q.
  Division of Licensing. 1p. 19169, 205. 24X Fiche: 50-277, B3/06/27,

- 8307060081 Suppls 810121 ltr re implementation of NUREG-0619 "BWR feedwater Norrle & Control Rod Drive Return Line (CRDRL) Norrle Cracking. "Feedwater low flow controller installed on both units. Detailed rept scheduled for 830930.

  DALTROFF, S. L. Philadelphia Electric Co. 83/06/30. EISENHUT, D. Q. Division of Licensing. 2pp. 19251:354. 24X Fiche: 50-277, 83/06/30, 8307060081.
- B30714029B Forwards additinfore safety evaluation of continued operation w/circumferential crack indications in RHR system 14 per 830627 meeting. Insps & repairs will be performed during 1983 refueling outage, per 18 Bulletin 83-02.

  DALTROFF, S. L. Philadelphia Electric Co. 83/07/01. EISENHUT, D. G. Division of Licensing. 49pp. 19523:135. 24X Fiche: 50-277, 83/07/01, 8307140298.
- --8307140297 "Fracture Mechanics Evaluation of Circumferential Indications at Weld 10-0-06 in Peach Bottom 2 RHR Supply Line." MENTA, H. S. , RANSAMATH, S. General Electric Co. 83/06/30, 24pp. 19523: 184. 24X Fiche: 50-277, 83/07/01, 8307140278.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIBENHUT, D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. L6pp. 19390:317. 24X Fiche: 30-000, 83/07/05, 8306270397.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISEANUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list enci. EISENHUT.D.Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8397180080 Forwards noise study data taken to implement Tech Spec 2.3/3.3 of App B to Licenses DPR-44 & DPR-56,per NRC 830630 teleon request. Data will be reviewed during consideration to delete provision from App B.
  ALDEN.W.M. Philadelphia Electric Co. 83/07/08. GEARS, G. E. Operating Reactors Branch 4. ip. 19556:300. 24X Fiche: 50-277, 83/07/08, 8307180080.
- --8307180084 Noise tayel measurements surveillance test results. • Philadelphia Electric Co. 75/07/22. 5pp. 19556:301. 24x Fiche: 50-277,83/07/08,8307180080.
- --8307180085 Noise level measurements surveillance test results. \* Philadelphia Electric Co. 75/04/30. Spp. 19556:306. 24x Fiche: 50-277,83/07/08,8307180080.
- --B307180087 Noise level instruments surveillance test results. CRAMFORD.R. D. Philadelphia Electric Co. 74/07/25. 5pp. 19556:311. 24X Fiche:50-277,83/07/08.8307180080.
- --8307180091 Noise level measurements surveillance test results.

  Fhiladelphia Electric Co. 74/02/24. 5pp. 19556:316. 24x
  Fiche: 50-277.83/07/08.8307180080.
- --B307180092 Noise level measurements surveillance test results. CRAMFORD R.D. Philadelphia Electric Co. 74/10/29. Spp. 19556: 321. 24X Fiche: 50-277, 83/07/08, 8307180080.
- B307270259 Forwards request for add1 info re review of plant-unique analysis rept evaluating loads for Mark I containment long-term program Meeting to discuss response requested. BTOLI.J.F. Operating Reactors Branch 4. B3/07/14. BAUER, E. G. Philadelphia Electric Co. Spp. 19811: 181. 24x Fichs: 50-277, 83/07/14, 8307270259.
- B307200298 Responds to NRC 830603 ltr re safety evaluation of seven alternatives proposed by BWR Owners Group to modify present automatic depressurization sys logic per NUREO-0737. Item 11. N. 3. 18. Mods will be implemented during refueling outage. DALTROFF, B. L. Philadelphia Electric Co. B3/07/15. STOLZ, S. F. Operating Reactors Branch 4. 2pp. 19648: 134. 24% Fiche: 50-277, B3/07/15, B307200298.

- G. Inspection reports, IE Bulletins & correspondence
- B307280286 Responds to unrespived IE Insp Rept Items 277/82-23-01 & 278/82-22-01 re TMI Item II.B.2. "Design Review of Plant Shielding."

  BALTRGF, S. L. Philadelphia Electric Co. B3/05/13. STAROSTECKI, R. Region I. Office of Director. 33pp. 19790:176. 24X

  Fiche: 30-277, B3/05/13, B307280286.
- 8307130164 Discusses IE insp on 830223-0312 & forwards notice of violation & proposed imposition of civil penalty.
  ALLAN, J. M. Region 1, Office of Director. 83/06/13. BOYER, V. Philadelphis Electric Co. 4pp. 19540: 347. 24X
  Fiche: 30-277, 83/06/13, 8307150164.
- --8307150171 Notice of violation & proposed imposition of civil penalty in amount of \$40.000. Noncompliance noted: failure to properly implement approved station surveillance test procedure.

  ALLAN. J. M. Region 1. Offsce of Director. 83/06/13. 4pp. 19340: 351. 24X Fiche: 50-277.83/06/13.8307130164.
- 8307010106 Forwards interim surveillance & limiting conditions for operations, transmitted by 830323 ltr.in response to IE Bulletin 83-02. Plans for into ar mod of recirculation sys & other RCPB sys. for next refueling outage, will be submitted. DALTROFF, S. L. Philadelphia Electric Co. 83/06/27. EISENHUT, D. G. Division of Licensing. 6pp. 19124: 311. 24X Fiche: 50-277, 83/06/27, 8307010106.
- 830714029B Forwards add1 info re safety evaluation of continued operation w/circumferential crack indications in RHR sys weld, per 830627 meeting. Insps & repairs will be performed during 1983 refueling outsage, per IE Bulletin 83-02.
  DALTROFF, S. L. Philadelphia Electric Co. 83/07/01. EISENHUT, D. G. Division of Licensing. 49pp. 19529:135. 24X Fiche: 50-277, 83/07/01, 8307140278.
- 8307140542 Notification of B30707 meeting w/util in Bethesda.MD to discuss pipe crack insps.

  OEARS.0. Operating Reactors Branch 4. 83/07/06. STOLZ.J.F. Operating Reactors Branch 4. 2pp. 17527:360. 24X

  Fiche: 50-277.83/07/06.8307140542.
- B307150059 Confirms B30706 discussion w/wtil re administrative exposure control sys & radiation protection procedures for NRC personnel conducting confirmatory measurements including NDE of RHR & rectrculation piping at facility. MURLEY, T. E. Region 1, Office of Director. B3/07/06. FLEISHMANN, R. Philadelphia Electric Co. 1p. 19548: 202. 24X Fiche: 50-277, B3/07/06, B307150059.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830[03]). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24x Fiche: 50-000, 83/07/11, 8306270401.
- B307180423 Notification of B30714 meeting w/util in Bethesda.MD to discuss pipe crack insps. OEARS.0. Operating Reactors Branch 4. 83/07/11. STOLZ.J.F. Operating Reactors Branch 4. 2pp. 19364:353. 24X Fiche: 50-277,83/07/11,8307180423.
- 830-6270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563: 153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307150255 Ack receipt of 830622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-12 & 50-278/83-12 MARTIN T. T. Division of Engineering & Technical Programs. 83/07/13. DALTROFF, S. L. Philadelphia Electric Co. ip. 19538: 339. 24X Fiche: 50-277, 83/07/13, 8307150255.
- --8307150258 Responds to NRC 830523 ltr re violations noted in 1E Insp Repts 50-277/83-12 & 50-278/83-12. Corrective actions: incorrect Unit 3 log entry for jumper 4-3 closed out. Current test rev issuance will be monitored. DALTROFF, B. L. Philadelphia Electric Go. 83/06/22. MARTIN, T. T. Division of Engineering & Technical Programs. 2pp. 19538:340. 24X Fiche: 50-277,83/07/13,8307150255.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Bafeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000. B3/07/14.8306270406.

- 8307270318 Ack receipt of 830712 ltr containing full payment of proposed civil penalty.

  AXELRAD.J.A. Enforcement Staff. 83/07/25. BOYER, V. Philadelphia Electric Co. 2pp. 19858:154. 24X Fiche: 50-277,83/07/25,8307290318.
- R. Periodic operating reports & related correspondence
- 8307220300 Monthly operating repts for Mar 1983.W/830413 ltr. ALDEN.W.M., COONEY.M.J. Philadelphia Electric Co. 83/04/12. Director's Office, Office of Inspection and Enforcement. 10pp. 19683:259. 24% Fiche:50-277,83/04/12
- 8307210045 Monthly operating repts for June 1983. W/830714 ltr. CODNEY.M. J. ALDEN.H. M. Philadelphia Electric Co. 83/07/14. Director's Office. Office of Inspection and Enforcement. 11pp. 19668:304. 24x Fiche: 50-277,83/07/14,8307210045.
- S. Reportable occurrences, LERs & related correspondence
- 8306100097 EN-B3-040: on B30630, notice of violation & proposed imposition of civil penalty to be issued in amount of \$40,000 re failure to satisfy primary containment integrity limiting condition for operation.

  BARBER.G., AXELRAD.J. Director's Office, Office of Inspection and Enforcement. 83/06/08. 1p. 18602:225. 24X Fiche: 50-277, 83/06/08, 8306100099.
- 8307110473 PND-I-83-074: on B30704 & 05.unit voluntarily shut down for addi NDE of recirculation & RHR piping welds. Addi exams being made by NDE team from separate vendor organization. Subsequent licensee actions being discussed.

  TRIPP.L., KEIMIG.R. Region I. Office of Director. 83/07/05. Ip. 19380:184. 24X Fiche: 50-277, 83/07/05, 8307110473.
- 8307220404 LER 83-015/03L-0: on 830611, while performing surveillance test reactor water cleanup inboard isolation valve MD-2-12-15 failed to close. Caused by open auxiliary contact in motor control ctr. preventing close signal. Contact freed. CDONEY.M. J. Philadelphia Electric Co. 83/07/11. MURLEY, T. E. Region 1. Office of Director. 1p. 19687: 362. 24X Fiche: 50-277, 83/07/11, 8307220404.
- 8307220469 LER 83-018/03L-0: on 830624, while performing HPCI sys logic functional surveillance test.HPCI turbine control valve failed to open. Caused by burned out dropping resistar in power supply to Woodward emergency generator motor.

  COONEY, M. J. Philadelphia Electric Co. 83/07/11. MURLEY, T. E. Region i. Office of Director. ip. 19685: 002. 24X
  Ficha: 80-277,83/07/11,8307220469.
- 8307220466 LER 83-019/03L-0: on B30626, during surveillance testing, standby gas treatment filter train outlet valve AD-20475-2 failed to open. Caused by binding in solenoid valve meg by ASCD. Solenoid replaced & valve returned to svc. CODNEY.M.J. Philadelphia Electric Co. 83/07/12. MURLEY.T.E. Region 1. Office of Director. 1p. 17685: 003 24X Fiche: 50-277.83/07/12.8307220466.
- 8307220424 LER B3-016/03L-0: on 830617, isolation valve BV2671C in sample lines to drywell oxygen analysers failed to fully close. Caused by bent stem in Isolation valve SV2978C. Valve disassembled & damaged parts replaced. COUNEY, M. J. Philadelphia Electric Co. 83/07/13. MURLEY, T. E. Region i. Office of Director. 1p. 19691: 341. 24X Fiche: 50-277, 83/07/13, 8307220424.
- 8307210124 PND-I-83-074A: on 830704, unit taken affline & into cold shutdown for add1 NDE of RHR & recirculation sys piping welds. Significant indications found in RHR suction piping weld 10-0-5, 20-inch diameter pipe to elbow weld. RRIPP, L., KEIMIO, R. Rogion i, Office of Director. 83/07/15. Ip. 19468: 361. 24X Fiche: 50-277, 83/07/15, 8307210124.
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
  F. Security, medical, emergency & fire protection plans
- 8307260421 "Exercise Manual Peach Bottom Atomic Power Station NRC/FEMA Observed Emergency Response Exercise on 830628." W/one oversize figure. Aperture card is available in PDR. W/830525 ltr.
  DALTROFF, S. L. Philadelphia Electric Co. 83/05/25. ALLAN, J. M. Region i. DPfice of Director. 285pp. 19730:159. 24X Fiche: 50-277, 83/05/25, 8307260421.

- 8307190292 Informs that 830927 ltr on status of 47 mods to fire protection sys contained errors in status of mods to emergency lighting sys 480-volt circuit breaker settings. Corrected status & revised completion dates provided. BOYER.V.S. Philadelphia Electric Co. 83/07/11. EISENHUT.D.G. Division of Licensing. 4pp. 19832-193 24X Fichs.30-277.83/07/11.8307150292.
- 8307220058 Discusses B30708 meeting w/util re deficiencies identified during annual emergency preparedness exercise conducted on 830628. Emergency preparedness drill should be conducted to evaluate listed activities.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/13. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 19674:028. 24X Fiche: 50-277.83/07/13.8307220058.
- 8307250672 Releases public version of revised emergancy planimplementing procedures. FELTON,J.M. Division of Rules and Records 83/07/19. Document Management Branch. Lp. 19719:219. 24X Fiche:50-277,83/07/19, 8307250672
- --8307256576 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-10) re classification of emergencies.EP-102 re unusual event response & EP-103 re alert response. Affidavit encl. DALTROFF.S.L. Philadelphia Electric Co. 83/05/13. ALLAN.J.M. Region 1. Office of Director. 4pp. 17719.220 24X Fiche: 50-277.83/07/19.8307250672.
- --8307250660 Public version of revised emergency plan implementing procedures including Procedures EP-101 re classification of emergencies EP-102 re unusual event response & EP-103 re alert response.

  BALTROFF, S. L. Philadelphia Electric Co. 83/04/13. 80pp. 19719, 224. 24x Fiche: 50-277, 83/07/19, 8307250672.
- 8307270041 Releases public Version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 17806:256. 24X Fiche: 50-277.83/97/19. 8307270041.
- --8307270043 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-316 recumulative population dose calculations. EP-306A re fire flighting group & EP-206B re damage repair group, DAL TROFF, S. L. Philadelphia Electric Co. B3/07/01. ALLAN, J M Regian 1. Office of Director. 1p. 19806. 257. 24% Fiche. 50-277, 83/07/19, 8307270041.
- --8307270046 Public version of revised emergency plan implementing procedures including Procedures EP-316 re cumulative population dose calculations. EP-206A re fire fighting group & EP-206B re damage repair group.
  4 Philadelphia Electric Co. 83/09/31 238pp. 19806: 298. 24% Fiche: 50-277,83/07/19,8307270041.
- B307290101 Updates items in pending fire penetration seal exemption request. Mod to add emergency lighting in fifth bay of diesel bldg complete & no exemption request forthcoming.
  BOYER, V.S. Philadelphia Electric Co. 83/07/22. EISENHUT, D. O. Division of Licensing. 3pp. 19820-397. 24X Fiche: 50-277, 83/07/22, 8307290101
- G. Adjudicatory correspondence
- 8307210248 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  81LBERG.J.E. Shaw. Pittman. Potts 5 Trowbridge. 83/07/13.
  PALLADINO.N.J., GELINSKY,V., AHEANDE, J.F. Commissioners. 1p.
  19644:061. 24X Fiche: 50-000.83/07/13.8307210248.
- --B30721025t Notifies of employment at law firm VR Harding will not participate in any case pending before NRC Svc list encl.

  HARDING, V. R. Shaw, Pittman, Patts & Troubridge, B3707713.

  PALLADING, V. J., GILINSKY, V., AHEARNE, J. F. Commissioners, 5pp. 17464:062. 24X Fiche: 50~000, 83/07/13, 8307210248.
- J. Insurance & indemnity information
- 8307080454 Forwards Endorsement 102 to NELIA Policy NF-)40. Endorsement 55 to MAELU Policy MF-67. BRADLEY.E. J. Philadelphia Electric Co. 83/07/01. SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance). 3pp. 19347: 222. 24X Fiche: 50-277, 83/07/01, 8307080454.

- K Utility Final Safety Analysis Report (FSAR) & amends
- 830722023B Forwards Rev 1 to updated FSAR. BRADLEY.E.J. Philadelphia Electric Co. 83/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 4pp. 19673:001 24X Fiche. 50-277.83/07/20.830722023B.
- --8307220241 Rev 1 to updated FSAR. W/23 oversize figures. Aperture cards are available in PDR.

  a Philadelphia Electric Co. 83/01/31. 326pp. 19673:005. 24x Fiche: 50-277, 83/07/20. 8307220238.
- P Deerating license stage documents & correspondence
- B307080259 Forwards backfit cost figures for addl seven utils per original B30208 request.Cost figures for 20 utils transmitted B30411.
  TOURTELLOTTE.J. Regulatory Reform Task Force. B3/06/22.
  PALLADING.N. Commissioners. 2pp. 19363:313. 24x
  Fiche: 50-000, B3/06/22, B307080259.
- --B3070B0352 Forwards backfit cost tabulations for facilities, per NRC B3020B request. KEMPER, J. S. Philadelphia Electric Co. B3/05/04, TDURTELLOTTE, J. Regulatory Reform Task Force. 6pp. 19364:003. 24X Fiche: 50-000.83/06/22,8307080259.
- 8307080690 Forwards confirmatory order & proposed Tech Spocs re commitment to install permanent scram discharge sys mods by 831231. STOLZ-J F. Operating Reactors Branch 4. 83/06/24. BAUER, E. G. Philadelphia Electric Co. Spp 19364: 137. 24X Fiche: 50-278, 83/06/24, 8307080650.
- --B3070B0655 Confirmatory order to install long-term BWR scram discharge sys mods. EIBENNUT.D.Q. Division of Licensing. B3/06/24. Philadelphia Electric Co. Spp. 19364:142. 24% Fiche: 50-278,83/06/24, 83070B0650.
- --8307080463 Model Tech Specs re safety limit setpoints & refueling operations in response to commitment to install permanent scram discharge sys mods.

  \* Division of Licensing. 83/06/24. 30pp. 19364:147. 24X Fiche:50-278,83/06/24,8307080650.
- 3307010007 Informs that during 1982, there were no challenges to primary coolant sys safety & relief valves, per NUREO-0737. Item
  11. K. 3.3

  DALTROFF, S. L. Philadelphia Electric Co. 83/06/27. EISENHUT, D. 9.
  DIVISION of Licensing. Ip. 19169-205 24X Fiche: 50-277, 83/06/27.
  8307010009.
- 8307060081 Suppls 810121 ltr re implementation of NUREC-0619 "BWR Feedwater Notile & Control Rod Drive Return Line (CRDRL) Notile Cracking." Feedwater low flow controller installed on both units Detailed rept scheduled for 830930 DALTROFF, 8 L. Philadelphia Electric Co. 83/06/30. EISENHUT, D. C. Division of Licensing. 2pp. 19251-354. 24X Fiche: 30-277, 83/06/30, 8307060081.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for gower reactors re clarification of surveillance requirements for diesel fuel impurity. Svc. 1(st encl. EISENHUT.D G. Division of Licensing 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000.83/07/03.8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list enc? ElsENHUT.D.G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,63/07/06,8307060329
- 8307080169 Ceneric Lit 83-28 to all licensees of operating reactors, applicants for OL % holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. Elsenwirt, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307180080 Forwards noise study data taken to implement Tech Spec 2.3/3.3 of App 0 to Licenses DPR-44 & DPR-56.per NRC B30630 telcon request Data will be reviewed during consideration to delete provision from App B.

  ALDEN, M. M. Philadelphia Electric Co. 83/07/08 GEARS, G.E. Operating Reactors Branch 4 1p. 19956.300. 24x

  Fiche: 50-277.83/07/08.8307180080.

- --8307180084 Noise level measurements surveillance test results.

  # Philadelphia Electric Co. 75/07/22. 5pp. 19556:301. 24x
  Fiche: 50-277, 83/07/08, 8307180080.
- --B3071800B5 Noise level measurements surveillance test results.

  4 Philadelphia Electric Co. 75/04/30. 5pp. 19556:306. 24X Fiche:50-277.B3/07/08.B3071800B0.
- --83071800B7 Noise level instruments surveillance test results. CRAMFORD, R. D. Philadelphia Electric Co. 74/07/25, 5pp. 19356: 311. 24x Fiche: 50-277, 83/07/08, 8307180080.
- --8307180091 Noise level measurements surveillance test results.

  \* Philadelphia Electric Co. 74/02/24. Spp. 19556:316. 24X
  Fiche: 50-277,83/07/08,8307180080.
- --8307180092 Noise level measurements surveillance test results. CRAWFORD.R. D. Philadelphia Electric Co. 74/10/29. 5pp. 19354: 321. 24X Fiche: 50-277,83/07/08,8307180080.
- 8307250578 Submits more recent results of pipe cracking at BWRs to update Table 1 of SECY-83-267.
  DIRCUS.W.J. Office of the Executive Director for Operations. SECY-83-267A. 83/07/11. 4pp. 19716:347. 24X Fiche:50-000, 83/07/11.8307250578.
- 8307270259 Forwards request for add1 info re review of plant-unique analysis rept evaluating loads for Mark I containment iong-term program Meeting to discuss response requested. STOLZ. J. F. Operating Reactors Branch 4. 83/07/14. BAUER, E. G. Philadelphia Electric Co. 5pp. 19811:181. 24X Fiche: 50~277, 83/07/14, 8307270259.
- 8307200298 Responds to NRC 830603 ltr re safety evaluation of seven alternatives proposed by BWR Owners Group to modify present automatic depressurization sys logic per NUREG-0737. Item II. K. 3. 18. Mods will be implemented during refueling outage. SALTROFF, S. L. Philadelphia Electric Co. 83/07/15. STOLZ, S. F. Operating Reactors Branch 4. 2pp. 19648: 134. 24X Fiche: 50-277, 83/07/15, 8307200298.
- Q. Inspection reports, IE Bulletins & correspondence
- B307280286 Responds to unresolved IE Insp Rept Items 277/82-23-01 & 278/82-22-01 re TMI Item II. B. 2, "Design Review of Plant Shielding."

  DALTROFF, S. L. Philadelphia Electric Co. 83/05/13. STAROSTECKI, R. Region I, Office of Director. 33pp. 19790:176. 24x

  Fiche: 30-277, B3/05/13, 8307280286.
- 8307130164 Discusses IE insp on 830223-0512 % forwards notice of violation & proposed imposition of civil penalty.
  ALLAN, J. M. Region i Office of Director, 83706/13. BOYER, V. Philadelphia Electric Co. 4pp. 19540:347, 24X
  Fiche: 50-277, 83/06/13, 8307150164.
- --8307130171 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted:failure to properly implement approved station surveillance test procedure.

  ALLAN. J. M. Region 1, Office of Director. 83/06/13, 4pp. 19540: 351. 24X Fiche: 50~277,83/06/13,8307150164.
- 8307010106 Forwards interim surveillance & limiting conditions for operations, transmitted by 830523 ltr.in response to IE Butletin 83-02. Plans for insp or mod of recirculation sys & other RCPB sys.for next refueling outage.will be submitted. DALTROFF, S. L. Philadelphia Electric Co. 83/06/27, EISENHUT.D.O. Division of Licensing. App. 19124:311. 24X Fiche: 50-277, 83/06/27, 8307010106.
- B30627040: IE Info Notice B3-46, "Common Mode Valve Failures Dagrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11, B306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307150255 Ack receipt of 830622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-12 & 50-279/83-12. MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/13. DALTROFF, S. L. Philadelphia Electric Co. 1p 19538; 339. 24X Fiche: 50-277, 83/07/13, 8307150255.

IO7150298 Responds to NRC 830523 ltr ve violations noted in IE Insp. Repts 50-277/83-12 & 50-278/83-12 Corrective actions: incorrect Unit 3 log entry for jumper 4-5 closed out: Current test rev issuance will be monitored. DALTROFF,8 L. Philadelphia Electric Co. 83/06/22. MARTIN, T.T. Division of Engineering & Technical Programs. 2pp. 19538:340. 24X Fiche: 50-277, 83/07/13, 8307150255.

.270406 IE Info Notice 83-48, "Gaseous Effluent Releases of dioactive I-125 & I-131 in Excess of NRC Limits." Syc list icl. .. "YLOR, J.M. Division of QA, Safeguards & Inspection Program

VYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 10103). 83/07/14. Consolidated Edison Co. of New York, Inc. 4pp. 19715:270, 24X Ficha: 50-000,83/07/14,8306270406.

'290318 Ack receipt of 830712 ltr containing full payment of opposed civil penalty.

ELRAD, J. A. Enforcement Staff. 83/07/25. BOYER.V. Philadelphia actric Co. 2pp. 19858: 154. 24% Fichs: 50-277.83/07/25.8307290316.

#### 'eriodic operating reports & related correspondence

'220300 Monthly operating repts for Mar 1983.W/830413 ltr. .DEN.W.M., COONEY.M.J. Philadelphia Electric Co. 83/04/12. rector's Office, Office of Inspection and Enforcement. 10pp '683:259. 24X Fiche: 50-277,83/04/12.8307220300.

210045 Monthly operating repts for June 1983, W/830714 ltr. BONEY, M. J., ALDEN, W. M. Philadelphia Electric Co. 83/07/14. rector's Office, Office of Inspection and Enforcement. 11pp. 468: 304. 24X Fiche: 50-277, 83/07/14, 8307210045.

eportable occurrences, LERs & related correspondence

'010049 PND-1-B3-068: on B30624, while performing exams per IE illetin B3-02 & NUREG-0313, stress corrosion cracking found i recirculation & RHR piping sys. Crack welded Facility in ild shutdown while evaluation continues.

INETER, 5. DURR, J. Region 1. Office of Director, B3/06/24, 1p. '168: 309. 24X Fiche: 50-278, 83/06/24, 8307010049.

## ET 50-280 SURRY POWER STATION, UNIT 1

tecurity, medical, emergency & fire protection plans

140048 Ack receipt of 830214 ltr & Rev 5 to guard training & salification plans. Revs acceptable per 10CFR50, 54(p). Mod plementation will be examined in forthcoming insprept. MIG.R.C. Division of Project & Resident Programs. 83/04/22. EWART.W.L. Virginia Electric & Power Co. 1p. 17514:070. 24X cha: 30-000, 83/04/22, 8307140068.

110179 Releases public version of revised corporate emergency sponse plan.
LTON.J.H. Division of Rules and Records. B3/06/24. Document nagement Branch. 1p. 19386:001. 24X Fiche: 50-000. B3/06/24. 07110179.

O7:10184 Public version of Rev 3 to corporate emergency response plan.W/B30614 ltr.
STEWART.W.L. Virginia Electric & Power Co. 83/05/15.
O'REILLY.J.P. Region 2. Office of Director. 6pp. 19386:002. 24X
Fiche: 50-000, 83/06/24, 8307110179.

110474 Releases public version of revised amergency plan. LTDN.J.M. Division of Rules and Records. 83/06/24. Document nagement Branch. 1p. 19384:133. 24X Fiche: 50-280,83/06/24, 07110474.

O7110479 Public version of revised amergency plan.W/830615 ltr. RUNNER.W.R. WILSON.J., STEWART.W.L. Virginia Electric & Power Co. 83/05/26. O'REILLY.J.P. Region 2. Office of Director. 37pp. 19384:134. 24X Fiche:50-280,83/06/24,8307110474.

140223 Ack receipt of 830520 ltr informing NRC of steps taken to rrect violations noted in IE Insp Repts 50-280/83-09 & -281/83-09.

WIS.R.C. Division of Project & Resident Programs. 83/06/28.

EWART:M.L. Virginia Electric & Power Co. 1p. 17523:064. 24X che: 50-280,83/06/28,8307140223.

--8307140228 Responds to NRC 830421 ltr re violations noted in IE Insp. Repts 50-280/83-09 & 50-281/83-09. Corrective actions: Abnormal Procedure AP-17 included in Apr 1983 review & Administrative Procedure 37 revised.
STEWART.W. L. Virginia Electric & Power Co. 83/05/20.
078EILLY.J.P. Region 2. Office of Director. 3pp. 19523:065. 24X Fiche: 50-280.83/06/28.8307140223.

--B307140231 Forwards IE Insp Repts 50-280/83-09 & 50-281/83-09 on B30321-25 & notice of violation.

LEWIS-R.C. Division of Project & Resident Programs. 83/04/21.

STEMART.M.L. Virginia Electric & Power Co. 2pp. 19523:068. 24X Fichs: 50-280:83/06/28,8307140223.

--8307140234 Notice of violation from insp on 830321-25.

\* Region 2. Office of Director. 83/04/21. 1p. 19523:070. 24% Fiche: 50-280, 83/06/28, 8307140223.

--8307140236 IE Insp Repts 50-280/83-07 & 50-281/83-07 on 830321-25.

Noncompliance noted: failure of licensed & senior licensed operators to review abnormal & emergency procedures & failure to update controlled drawing files.

BELISLE.G.A., DEBBAGE.A.G., SKINNER.P.H. Region 2, Office of Director. 83/04/19, 16pp. 19523:071. 24X Ficha: 50-280,83/06/28,8307140223.

B307120386 Forwards procedures generation package for emergency operating procedures in response to NUREO-0737, Suppl 1 (Generic Ltr B2-33).
STEMART.M.L. Virginia Electric & Power Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. EIBENNUT, D.G. Division of Licensing. 15pp. 19426:209. 24X Fiche: 50-000, 83/07/01, 8307120386.

--8307120392 Administrative Procedure ADM 98, "Emergency Usage Procedures Writers Guide." \* Virginia Electric & Power Co. 83/05/18. 89pp. 19426:224. 24X Fiche: 50-000,83/07/01,8307120386.

8307270329 Forwards response to 830322 ltr re Rev & to security plan.
Response withheld (ref 10CFR2.790).
BTEWART.W.L. Virginia Electric & Power Co. 83/07/22. DENTON, M.R.
Defice of Nuclear Reactor Regulation. Director. 1p. 19767:238. 24X
Fiche: 50-280, 83/07/22, 8307270329.

#### J. Insurance & indemnity information

8307130068 Forwards Endorsements 70, 53, 32 & 43 to NELIA & MAELU Policies NF-186, MF-57, MF-96 & NF-240, respectively, Endorsements 1-6 to NELIA Certificates N-27 & N-28 & Endorsements 1-3 to MAELU Certificates M-27 & M-28, PAINTER, B.F. Virginia Electric & Power Co. 83/07/05, DINITZ, I. Antitrust & Economic Analysis Branch (Utility Finance). 33pp. 19474:150. 24X Fiche: 50-000, 83/07/05, 8307130068.

#### P. Operating license stage documents & correspondence

B30510010B Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREQ-0472. "Offste Dose Calculation Manual" also entl. BTEMART.W.L. Virginia Electric & Power Co. B3/03/04. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. VAROA.B.A. Operating Reactors Branch 1. 3pp. 19527:026. 24% Fiche: 50-280.83/05/04.8305100108.

--8305100111 Proposed revs to radiological effluent Tech Specs.in accordance w/Rev 3 to NURES-0472.

\* Virginia Electric & Power Co. 83/05/04. 87pp. 19527:029. 24X
Fiche: 50-280, 83/05/04, 8305100108.

--8307140264 "Offsite Dose Calculation Manual." + Virginia Electric & Power Ca. 83/05/04. 167pp. 19527:117. 24X Fiche: 50-280, 83/05/04. 8305100108.

8304040070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Mestinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Bvc list encl.
EISENHUT, D. Q. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563; 116. 24X Fiche: 50-000, 83/06/03, 8306060070.

8307060230 Application for amend to Licenses DPR-32 & DPR-37, supplementing 820316 & 0628 proposed changes to Tach Specs to reflect reorganization within nuclear operations & security depts. No unreviewed sefecty question involved.

STEWART.W.L. Virginia Electric & Power Co. B3/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. VAROA.S.A. Operating Reactors Branch 1. 4pp. 19239:343. 24% Fiche: 50-280.83/06/30.8307060830.

- --63376E0735 Proposed Tech Specs & 1-12 & 15 & Figures & 1-1 & 2 re reorganization of nuclear operations & security depts. Ouscussion of proposed changes encl. \* Virginia Electric & Power Co 83/06/30 &pp. 19239:347. 24X Fiche 50-220.83/06/30.8307060230
- 83-36270397 Generic Ltr 83-26 to all applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Sv. list encl. EISSRAPT. D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390; 317. 24X Fiche 50-000.83/07/05, 8306270397.
- 9307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors to surreillance intervals in STS Svc list encl. EISENBULD Q Division of Licensing 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche 50-060.83/07/06.8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem AIHS events Svc list encl. EISENHULD G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X
- 6307190020 Forwards FR notice of consideration of issuance of amends to Licenses DPR-32 & DPR-37 & proposed NSMC & opportunity for hearing re 830502 application to revise rod insertion limits
- nits Division of Licensing. 83/07/12. STEWART.W.L. Virginia Electric Pawer Co. 2pp. 19569:351. 24% Fiche:50-280,83/07/12,8307190020.
- --B307190022 Notice of consideration of issuance of amonds to Licenses DPR-32 & DPR-37 & proposed NSHC & opportunity for hearing re 830502 application to revise rod insertion limits. VARCA.S.A. Operating Reactors Branch 1. 83/07/11. 7pp. 19569-353 24X Fiche: 50-280/83/07/12, 8307190020.
- ### B307210205 Informs that post-accident sampling sys operational procedures approved & installed at plant by ### B30701 per THI Action Item II. 8 3 Due to recent sys malfunctions: alternatives investigated to improve reliability.

  STEMARI. H. Virginia Electric & Power Co. ### B30707/IB. DENTON. H. R. Office of Nuclear Reactor Regulation, Director. ### EISENHUT, D. Q. DIVISION of Licensing. 1p. 19665.111. 24X Fiche: 50-280, ### B307210205.
- 9307280419 Forwards "Reactor Containment Bldg Integrated Leak Rate Test Type A.B & C Periodic Test," per 10CFR30.App J. STEMART.H 1. Virginia Electric & Power Co. 83/07/26. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 1p. 19795:345. 2 Fiche 53-280.83/07/26.8307280418.
- ---9307280425 "Reactor Containment Bldg Integrated Leak Rate Test. Type A, B & C Periodic Test."

  \* Stone & Webster Engineering Corp. 83/04/30. 48pp. 19795:346. 24X Fiche: 50-280,83/07/26.8307280418.
- 9 Inspection reports. IE Bulletins & correspondence
- B307140212 Discusses completed evaluation of IE Circular B1-07, per B11120 request Circular contains adducte guidance re release of matls for unrestricted use Description of experiment encl.

  O'REILLY, J.P. Region 2, Office of Director, B3/02/09, BTEMART, W. L. Fichs 50-280, B3/02/09, B307140212.
- B307140223 Act receipt of B30520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-09 & LEWIS.R C Division of Project & Resident Programs. B3/06/28. B3EMARI, W L. Virginia Electric & Power Co. 1p. 19523.064. 24x Piche 50-280, B3/06/28, B307140223.
- --8307140228 Responds to NRC 830421 ltr re violations noted in IE Insp. Repts 50-280783-09 & 50-281/83-09. Corrective actions:
  Administrative Procedure AP-17 included in AP 1783 review & STEMART. B L. Virginia Electric & Power Co. 83/05/20.
  GREILLY, J. Region 2, Office of Director 3pp. 19523: 065. 24)
  Fichs 50-280. 83/06/28, 8307140223. 19523: 065. 24X
- --8307140231 Forwards IE Insp Repts 50-280/83-09 & 50-281/83-09 on 830321-29 & notice of violation.
  LEMIS.R C. Davision of Project & Resident Programs. 83/04/21.
  STEWART. U. L. Virginia Electric & Power Co. 2pp. 19523.068.

- --B307140234 Notice of violation from insp on 830321-25.

  \* Region 2, Office of Director. B3/04/21. ip. 17523:070.
  Fiche: 50-280, 83/06/28, 8307140223.
- -8307140236 IE Insp Repts 50-280/83-07 & 50-281/83-07 on 830321-25 Noncompliance noted: failure of licensed & senior licensed operators to review abnormal & smorgancy procedures & failure to update controlled drawing files.

  BELISLE, O. A. DEDBAGE, A. G. SKINNER, P. H. Region 2, Office of Director. 83/04/19. 16pp. 17923:071. 24X Fichs: 50-280.83/06/28.8307140223.
- 8307120251 Forwards fee for IE insps conducted during Mar 1982 -MAR 1983. STEMART M.L. Virginia Electric & Power Co. 83/07/06. DENTON: II & Office of Nuclear Reactor Regulation, Director. BARRY.L.W. Division of Accounting. Ip. 19419:360. 24% Fichs: 50-280:83/07/06.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 194pp. 19563: 293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Enubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparudness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17363:153. 24X Fiche: 50-000, 83/07/12, 8306270404
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Syc list enci, TAYLOR, J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715; 270. 24X Fiche: 30-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- B307220385 Monthly operating repts for May 1983, W/830615 ltr.
  JONES, V. H., BTEWART, W. L. Virginia Electric & Power Co. 83/06/02.
  HALLER, N. M. Office of Resource Management, Director. 50pp.
  19675: 179. 24X Fiche: 50-280, 83/06/02, 8307220385.
- 8307200194 Forwards monthly operating repts for June 1983 & corrected page to monthly operating rept for May 1983.
  STEMART.W.L. Virginia Electric & Power Co. 83/07/15. HALLER,N M. Office of Management and Program Analysis. 1p. 19847:315. 24x
  Fiche: 50-280, 83/07/15, 8307200194.
- --8307200195 Corrected page to monthly operating rept for May 1783. JONES, V. H. Virginia Electric & Power Co. 03/06/02. 1p. 19447:316. 24X Fiche: 50-280,83/07/15,8307200194.
- -8307200197 Monthly operating repts for June 1983. JONES.V.H. Virginia Electric & Pawer Co. 63/07/07. 19647: 317. 24X Fiche: 50-280, 83/07/19, 8307200194. 43pp.
- S. Reportable occurrences, LERs & related correspondence
- 8307290298 Forwards AEOD technical review rept of 830209 event involving failure of recirculation spray syc water valves. Event suggested to Data Mgt Section as AD. 27KOR, D. Reactor Operations Analysis Branch. 83706/13. 8EYRIT.K. V. Reactor Operations Analysis Branch. 1p. 19057:056. 24X Fiche: 30~280, 83706/13, 8307290298.
- --8307290307 "Failure of Recirculation Spray Svc Water MOVs." AEGD technical reviow rept.
  ZUKOR, D. Reactor Operations Analysis Branch. 83/06/13. 3pp. 19857: 007. 24X Fiche: 50-280, 83/06/13, 8307290298.
- B307290414 Forwards AEDD technical review rept, " Check Valve in Instrument Air Line to PORV Installed Backwards." Event may upcoming SALP review. Rept should be included in plant ZUKOR, D. Reactor Operations Analysis Branch. B3/06/15. EYPRITIK, V. Reactor Operations Analysis Branch. [p. 19857;073. 24X Fiche: 50-280. 83/06/15, 8307290414.
- --8307290434 "Check Valve Installed Backwards in Instrument Air Line to PORV." AEOD technical review rept. ZUKUR.D. Reactor Operations Analysis Branch. 83/06/15. 1p. 19857:074. 24X Fiche: 50-280, 83/06/15, 8307290414.

- 8307120225 LER 83-025/03L-0: on 830601, control bank B rod position indicators found out of calibr. Caused by calibr error. Indicators recalibr. W/830627 ltr. WILSON, J.L. Virginia Electric & Power Co. 83/06/27. O'REILLY, J. P. Region 2, Office of Director. 3pp. 19423:213. 24X Fiche: 30-280, 83/06/27, 8307120225.
- B307250467 LER B3-026/03L-0: on B30616 & 17, containment partial air pressure at value greater than Tech Spec requirements. Caused by svc water temp increasing faster than containment pressure decreasing. W/B30711 ltr.
  WILSON, J. L. Virginia Electric & Power Co. B3/07/11. D'REILLY, J. Ragion 2, Office of Director. 3pp. 19701:192. 24X Fiche: 50-280, 83/07/11. B307250447.
- 8307270173 Updated LER 82-094/03X-1: on 820815.TV-85-106A & 8 (reactor coolant hot leg sample trip valves) failed to fully close after RCB sample. Cause undetermined valves tested satisfactorily & returned to svc. W/830720 ltr.
  HILSON.J. L. SAUDERS.R.F. Virginia Electric & Power Co. 83/07/20. 0'REILLY.J.P. Region 2. Office of Director. 3pp. 19821:047. 24x Fiche: 50-280, 83/07/20, 8307290173.
- DOCKET 50-291 SURRY POWER STATION: UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8307140068 Ack receipt of 830216 ltr & Rev 5 to guard training & qualification plans. Revs acceptable per 100FR50. 54(p). Hod implementation will be examined in forthcoming insp rept. LEWIS.R. C. Division of Project & Resident Programs. 83/04/22. BTEWART, W. L. Virginia Electric & Power Co. 1p. 19514:090. 24X Fiche: 50-000,83/04/22,8307140068.
- 8307110179 Releases public version of revised corporate emergency response plan.
  FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19386:001. 24x Fiche: 50-000, 83/06/24, 8307110179.
- --B307i10184 Public version of Rev 3 to corporate emergency response plan. H/B30614 ltr.
  BTEWART, M. L. Virginia Electric & Power Co. 83/05/15.
  O'REILLY, J.P. Region 2, Office of Director. 5pp. 19386: 002. 24X
  Fiche: 50-000, 83/06/24, 8307i10179.
- B307110474 Releases public version of revised emergency plan. FELTON.J.M. Division of Rules and Records. B3/06/24. Document Management Branch. 1p. 19384:133. 24X Fiche: 50-280, 83/06/24, B307110474.
- --8307110479 Public version of revised emergency plan. W/830615 ltr. RUNNER, W. R., WILBON, J., STEWART, W. L. Virginia Electric & Power Co. 83/05/26. O'REILLY, J. P. Region 2, Office of Director. 57pp. 19384: 134. 24X Fiche: 50-280, 83/06/24, 8307110474.
- B307010020 Suppls 830503 request for exemption to 10CFR50.4B(c)(4), due to rev in refueling outage schedule for 10CFR50.App R, Section III. G. 3 mods. Outage scheduled for 830627.

  STEWART, W. L. Virginia Electric & Power Co. 83706/27. DENTON, H. R. Office of Nuclear Reactors Regulation, Director. VARGA, S. A. Operating Reactors Branch 1, 1p. 19169: 108. 24X Fiche: 50-281, 83/06/27, 8307010020.
- 8307140223 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-09 & 50-281/83-09.

  LEWIS,R.C. Division of Project & Resident Programs. 83/06/28.

  STEWART, W. L. Virginia Electric & Power Co. 1p. 17923:064, 24X Fiche: 50-280,83/06/28,8307140223.
- --8307140228 Responds to NRC 830421 ltr re violations noted in IE Insp. Repts 50-280/83-09 & 50-281/83-09. Corrective actions:
  Abnormal Procedure AP-17 included in Apr 1983 review & Administrative Procedure 37 revised.
  STEMART.W.L. Virginia Electric & Power Co. 83/05/20.
  O'RETLLY, J.P. Region 2, Office of Director. 3pp. 19523:065. 24X Fiche: 50-280, 83/06/28, 8307140223.
- --8307140231 Forwards IE Insp Repts 50-280/83-07 & 50-281/83-07 on 830321-25 & notice of violation.

  LEMIB, R. C. Division of Project & Resident Programs, 83/04/21, STEMART, H. L. Virginia Electric & Power Co. 2pp. 19523:068. 24X Fiche: 50-280, 83/06/28, 8307140223.
- --8307140234 Notice of violation from insp on 830321-25.

  \* Region 2, Defice of Director. 83/04/21. ip. 17523:070. 24x
  Fiche: 50-280, 83/06/28, 8307140223.

- --8307140236 IE Insp Repts 50-280/83-07 & 50-281/83-07 on 830321-25.

  Noncompliance noted:failure of licensed & senior licensed operators to review abnormal & emergency procedures & failure to update controlled drawing files.

  BELISLE, G. A. Region 2, Office of Director. UPRIGHT, C. M. Division of Emergency Preparedness & Materials Safety. 83/04/19. 16pp. 19523: 071. 24X Fiche: 50-280, 83/06/28, 8307140223.
- B307120386 Forwards procedures generation package for emergency operating procedures in response to NUREG-0737. Suppl 1 (Oeneric Ltr 82-33).

  STEMART, M. L. Virginia Electric & Power Co. B3/07/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 15pp. 19426: 209. 24X Fiche: 50-000, B3/07/01, B307120386.
- --8307120372 Administrative Procedure ADM 98, "Emergency Usage Procedure: Writers Guide." \* Virginia Electric & Power Co. 83/05/18. B9pp. 19426:224. 24X Fiche: 50-000,83/07/01,8307120386.
- B307270327 Forwards response to B30322 ltr re Rev 6 to security plan.
  Response withheld (ref 100FR2.790).
  STEWART, W. L. Virginia Electric & Power Ca. B3/07/22. DENTON, H. R.
  Office of Nuclear Reactor Regulation, Director. ip. 19747: 238. 24)
  Fiche: 50-280, B3/07/22. B307270329.
- J. Insurance & indemnity information
- 8307130068 Forwards Endorsements 70,53,32 & 43 to NELIA & MAELU Policies NF-186. MF-37. MF-96 & NF-240, respectively, Endorsements i-6 to NELIA Certificates N-27 & N-28 & Endorsements i-3 to MAELU Certificates M-27 & M-28. PAINTER, B. F. Virginia Electric & Power Co. 83/07/05. DINITZ, I. Antitrust & Economic Analysis Branch (Utility Finance). 93pp. 19474: 150. 24X Fiche: 50-000. 83/07/05. 8307130068.
- P. Operating license stage documents & correspondence
- B3051001QB Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREQ-0472. "Offsite Dose Calculation Manual" also encl. STEMART, W. L. Virginia Electric & Power Co. 83/05/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 3pp. 19927:026. 24X Fiche: 50-280, 83/05/04, 8305100108.
- --8305100111 Proposed revs to radiological effluent Tech Specs, in accordance w/Rev 3 to NUREO-0472.

  \* Virginia Electric & Power Co. 83/05/04. 87pp. 19527:029. 24x Ficha: 50-280.83/05/04.8305100108.
- --B307140264 "Offsite Dose Calculation Manuel." \* Virginia Electric & Power Co. B3/05/04. 167pp. 19527:117. 24X Fichs: 50-280, 83/05/04, 8305100108.
- 8304040070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Mestinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT.D.O. Division of Licensing. 83/04/03. Yankee Atomic Electric Co. 10pp. 19563:114. 24X Fiche: 50-000.83/04/03, 8304040070.
- 8307060230 Application for amend to Licenses DPR-32 & DPR-37, supplementing 820316 & 0628 proposed changes to Tech Specs to reflect reorganization within nuclear operations & security depts. No unreviewed safety question involved. STEWART, W. L. Virginia Electric & Power Co. 83706/30. DENTON, H. R. Office of Nuclear Reactor Regulation Director. VARGA, S. A. Querating Reactors Brench 1. 4pp. 19239: 343. 24X Fiche: 50-280,83/06/30,8307060230.
- --B307060235 Proposed Tech Spacs 6.1-12 % 15 % Figures 6.1-1 & 2 re reorganization of nuclear operations % security depts.

  Discussion of proposed changes encl.

  \* Virginia Electric & Power Co. B3/06/30. 6pp. 19239:347. 24x

  Fiche: 50-280, 83/06/30, 8307040230.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENNUT.D.Q. Division of Licensing. 83707/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENNUT. D. G. Divisign of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669: 254. 24x Fiche: 50-000, 83/07/06, 8307060329.

- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CFs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENAULIO G. Division of Licensing 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000.83/07/08.8307080169.
- 8307190020 Forwards FR notice of consideration of issuance of amends to Licenses DPR-32 & DPR-37 & proposed NSHC & opportunity for hearing re 830502 application to revise rod insertion
  - 13mts. • Division of Licensing. 83/07/12 STEWART.W.L. Virginia Electric & Power Co. 2pp. 19569: 351. 24X Fiche: 30-280, 83/07/12, 8307190020.
- --B307190022 Notice of consideration of issuance of amends to Licenses DPR-32 & DPR-37 & proposed NSHC & opportunity for hearing re B30502 application to revise rod insertion limits. VARGA.5.A. Operating Reactors Branch 1 B3/07/11. 7pp. 19569: 353. 24X Fiche: 50-280, B3/07/12, B307190020.
- 8307210205 Informs that post-accident sampling sys operational procedures approved & installed at plant by 830701 per TMI Action Item II. 8.3. Due to recent sys majfunctions, alternatives investigated to improve reliability.

  STEMART.W.L. Virginia Electric & Power Co. 83/07/18. DENTON, M.R. Office of Nuclear Reactor Regulation. Director. EISENHUT, D. G. Division of Licensing. 1p. 19465:111. 24X Fiche: 50-280,83/07/18,8307210205.
- 8307250320 "Surry Unit 2.Cycle 6 Core Performance Rept." W/undated ltr. HENDRIX50N.E.S. Virginia Electric & Power Co. VEP-NOS-6. 83/07/31. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. VARSA.S A. Operating Reactors Branch 1 50pp. 19705:215. 24X Fiche: 50-281.83/07/31.8307250320.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140212 Discusses completed evaluation of IE Circular 81-07, por 811120 request. Circular contains adequate guidance re release of matls for unrestricted use Description of experiment encl.

  O'REILLY, J. P. Region 2, Office of Director. 83/02/09. STEWART, W. L. Virginia Electric & Power Co. App. 19322:021. 24X Fiche: 50-280, 83/02/09. 8307140212.
- B307140223 Ack receipt of B30520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-09 & 50-281/83-07.

  LEMIS,R.C. Division of Project & Resident Programs. B3/06/28. STEMARI,W.L. Virginia Electric & Power Co. ip. 19523:064. 24X Fiche: 50-280,83/06/28,8307140223.
- --8307140228 Responds to NRC 830421 ltr re violations noted in IE Ensp Repts 50-280783-09 & 50-281783-09. Corrective actions: Abnormal Procedure AP-17 included in Apr 1983 review & Administrative Procedure 37 revised. STEMART.W.L. Virginia Electric & Power Co. 83705720. O'REILLY, J. P. Region 2, Office of Director. 3pp 19523:065. 24X Fiche: 50-280,83706728.8307140223
- --8307140231 Forwards 1E Insp Repts 50-280/83-09 & 50-281/83-09 on 830321-23 & notice of violation.

  LEMIS.R.C. Division of Project & Resident Programs. 83/04/21.

  STEWART.W.L. Virginia Electric & Power Co. 2pp. 19523.068. 24X Fiche 50-280.83/04/28.8307140223.
- --8307140234 Notice of violation from this on 830321-25.
   Region 2, Office of Director. 83/04/21. 1p. 19523:070. 24X Fiche: 50-280, 83/04/28, 8307140223.
- --B307140236 IE Insp Repts 50-286/80-07 & 50-281/80-07 on B30321-25.

  Noncompliance noted: failure of licensed % senior licensed operators to review abnormal & emergency procedures & failure to update controlled drawing files.

  BELISLE.G.A. DEBBAGE.A.G., SKINNER.P.H. Region 2, Office of Director. 83/04/17. 16pp. 19520:07t. 24X Fiche: 50-280.83/06/28, B307140220.
- B307120251 Forwards fee for IE insps conducted during Mar 1982 -Mar 1983. STEMART.W.L. Virginia Electric & Power Co. B3/07/06. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. BARRY,L.W. Division of Accounting. ip. 19419:360. 24% Fiche:30-280,83/07/06, 8307120251.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Davision of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11 Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11, 8306270401.

- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pg. 19563:193. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B304270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-123 & I-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 17713:270. 24X Fiche: 50-000. B3/07/14. B306270404.
- R. Periodic operating reports & related correspondence
- 8307220365 Monthly operating repts for May 1983. W/830615 ltr.

  JONES. V. H.: STEMART. W. L.: Virginia Electric & Power Co. 83/06/02.

  HALLER, N. M. Gréice of Resource Management, Director. 50pp.

  19675:179. 24X Fiche: 50-280. 83/06/02. 8307220385.
- 8307200194 Forwards monthly operating repts for June 1983 & corrected page to monthly operating rept for May 1983.

  8TENART. W. L. Virginia Electric & Power Co. 83/07/13. HALLER, N. H. Office of Management and Program Analysis. 1p. 19647:315, 24X Fiche: 50-280-83/07/15-8307200194.
- --B307200197 Monthly operating repts for June 1983. JONES, V. H. Virginia Electric & Power Co. 83/07/07. 43pp. 19447: 317. 24X Fiche: 50-280, 83/07/15, 8307200194.
- 8. Reportable occurrences, LERs & related correspondence
- 8307290298 Forwards AEDD technical review rept of 830209 event involving Pailure of recirculation spray svc water valves. Event suggested to Data Mgt Section as AO. 19408. B. Reactor Operations Analysis Branch. 83/06/13. 8497817.K.V. Reactor Operations Analysis Branch. 1p. 19857:056. 24X Fiche: 50-280, 83/06/13, 8307290298.
- --8307290907 "Failure of Recirculation Spray Svc Water MQVs," AEOD technical review rept.

  ZUKQR, D. Reactor Operations Analysis Branch. 83/06/13, 3pp. 19857: 057. 24X Fiche: 50-280, 83/06/13, 8307290298.
- B307120535 LER 83-028/03L-0: on 830523, ampero reading for heat tracing panel 8. circuit 23C. found below acceptance criteria of PT-27C. Caused by excessive heat. Defective heat tracing replaced Design change installation commenced. W/830623 ltr. WILSON, J. L. Virginia Electric & Power Co. 83/06/23, 0'REILLY, J. P. Region 2, Office of Director. 3pp. 19433: 329. 24X Fiche: 50-281, 83/06/23, 8307120535.
- 8307250485 LER 83-031/03L-D: on 830622, independent rod position indication for control rod K-2 fluctuated greater than 12 steps. Cause undetermined. Signal conditioner module voltage adjusted & fluctuations ceased. W/830711 ltr. WILSON. J. L. Virginia Electric & Power Co. 83/07/11. O'REILLY. J.P. Rogion 2. Office of Director. 3pp. 19701: 279. 24X Fiche: 50-281.83/07/11.8307250485.
- DOCKET 50-202 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- B307050283 Forwards table of schedular milestones to be negotiated during B30624 meeting re smargency response capability provided (n util B30515 response to Generic Ltr B2-33. DIIANNI.D.C. Operating Reactors Branch 3. B3/06/14. MUSCLF.D.M. Northern States Power Co. 3pp. 19263:216. 24X Fiche: 50-282.83/06/14.8307050283.
- 8307060315 Forwards IE Insp Repts 90-282/83-07 & 50-306/83-07 on 830401-30 & notice of violation. SHAFER.W.D. Region 3, Diffice of Director. 83/06/20. LARSON.C.E. Northern States Power Co. 2pp. 19234:231. 24X Fiche: 50-282, 83/06/20, 8307060315.
- --8307040324 Notice of violation from insp on 830401-30. SHAFER.W.D. Region 3, Office of Director. 83/06/20. 2pp 19234:233. 24X Fiche:50-282,83/06/20,8307060315.
- --8307060328 IE insp Repts 50-282/83-07 & 50-306/83-07 on 830401-30.

  Noncompliance noted: failure to perform daily check of main steam line radiation monitors & monthly functional test for 4-kV safeguards buses & to verify valve position.

  FELERABEND, C. D., WILLIAMS, D. L., JACKIN, I. N. Region 3, Office of Director. 83/06/20, 9pp. 19234:235. 24X Fiche: 50-282,83/06/20,8307060315.

- 8307010178 Forwards Rev 5 to security force training % qualification plan. Rev withheld (ref 1905R73.21).
  MUSDLF,D.M. Northern States Power Co. 83/06/24. Office of Nuclear Reactor Regulation. Director. 2pp. 19172;261. 24X
  Fiche: 30-000.83/06/24,8307010178.
- B307180323 Releases public version of revised emergency plan implementing procedures.

  FELTON.J.M. Division of Rules and Records. B3/06/24. Document Management Branch. 1p. 19966:003. 24X Fiche: 50-282,83/06/24. B307180323.
- --8307180326 Forwards public version of revised emergency plan implementing procedures, including Procedures A. 2-001 re emergency organization, A. 2-107 re activation of operations support ctr & A. 2-402 re contamination control.

  MARD.E.C. Northern States Pawer Co. 83/06/07. Region 3, Office of Director. ip. 19566:004. 24X Fiche: 50-282, 83/06/24, 8307180323.
- --8307180327 Public version of revised emergency plan implementing procedures including Procedures A. 2-001 re emergency organization. A. 2-107 re activation of operations support ctr & A. 2-402 re contamination control.

  FEY, F. L. Northern States Power Co. 93/05/20. 92pp. 19566:005. 24X Fiche: 50-282, 83/06/24, 8307180323.
- 8307180437 Advises that Rev 9 to security plan acceptable w/exception of Page 21.5ection 3.2.2. I requiring designated vehicles be limited in use to onsite functions.

  CLARK.R. A. Operating Reactors Branch 3. 83/07/07. MUSCLF.D. M. Northern States Power Co. 3pp. 19366:339. 24X

  Fiche: 50-282,83/07/07,8307180437.
- B307180107 Forwards IE Safeguards Insp Repts 50-282/83-11 & 50-306/83-11 on 930613-17.No noncompliance noted.
  MILLER J. R. Region 3. Office of Director. B3/07/14. LARSON, C. E. Northern States Power Co. 2pp. 19597: 027 24X
  Fiche: 50-282.83/07/14.8307180109.
- --8307180112 IE Safeguards Insp Repts 50-282/83-11 & 50-306/83-11 on B30613-17. No noncompliance noted Major areas inspected: security plan & implementing procedures, locks, keys & combinations, Safeguards info deleted (ref 10CFR73, 21). FIRTLE, G. L.: KNICELEY, J. R.: CREED, J. R. Region 3, Office of Director. B3/07/13, 2pp. 19557: 029. 24X Fiche: 50-282, 83/07/14, 8307180109.
- 8307220561 Responds to 830310 ltr re Rev 8 to physical security plan. Procedures changed to establish lock rotation per Reg Quide 5.12. "General Use of Locks in Protection & Centrol of Facilities & SMM." Plan will be revised. MUSDLF.D. Northern States Power Co. 83/07/15. Office of Nuclear Reactor Regulation, Director. 1p. 17486:028. 24X Fiche: 50-282, 83/07/15, 8307220561.
- 8307290632 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19718:144. 24X Fichs: 50-000.83/07/19, 8307250632.
- --8307250642 Forwards public version of revised emergency plan implementing procedures; including Procedures EPIP 1.1.1 recorporate emergency response plan; EPIP 1.1.2 renotifications & EPIP 1.1.3 republic info.

  WARD, E. C. Northern States Power Co. 83/05/20. Region 3, Office of Director. 1p. 19718:145. 24X Fichs:50-000,83/07/19,8307250632.
- --8307280650 Public version of revised emergency plan implementing procedures including Procedures EPIP 1.1.1 re corporate emergency response plan. EPIP 1.1.2 re notifications & EPIP 1.1.3 re public info. Rev 12 to table of contents encl. HUDBON, G., WARD, E.C. Northern States Power Co. 83/05/20. 145pp. 19718:146. 24X Fiche: 50-000.83/07/19.8307250632.
- J. Insurance & indemnity information
- B307260475 Forwards Endorsements 65 & 66 to NELIA Policy NF-174, Endorsements 54 & 55 to NELIA Policy NF-197 & Endorsements 54 & 47 to MAELU Policies MF-51 & MF-68, respectively. JOHNSON, R. G. Northern States Power Co. B3/07/18, DINITZ, I. Antitrust & Economic Analysis Branch (Utility Finance). 7pp. 19731:196. 24X Fichs:50-000,83/07/18,8307260475.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307080198 Forwards Rev 1 to updated FBAR.
  MUSDLF.D. Northern States Power Co. B3/06/30. Office of Nuclear
  Reactor Regulation, Director. 22pp. 19348:196. 24x
  Fiche: 50-282, B3/06/30, B307080198.

- ~~8307080204 Rev 1 to updated FSAR. \* Northern States Power Co. 82/12/31, 448pp, 19348; 219, 24X Fiche: 50~282, 83/06/30, 8307080198.
- P. Operating license stage documents & correspondence
- 8307050342 Forwards safety evaluation re seismic qualification of auxiliary feedwater sys, based on util 810714 & 820903 responses to Generic Ltr 81-14. Sys can withstand postulated safe shutdown earthquake.

  CLARK.R.A. Operating Reactors Branch 3. 83/06/17. MUSOLF.D.M. Northern States Power Co. 2pp. 19263:295. 24X

  Fiche: 50-282,83/06/17,8307050342.
- --B307050345 Bafety evaluation re util responses to Generic Ltr 81-14 on seismic qualification of auxiliary foedwater sys. Auxiliary feedwater sys can withstand postulated safe shutdown earthquake.

  8 Office of Nuclear Reactor Regulation, Director. 83/06/16, 10pp. 19263:297. 24X Fiche: 50-282, 83/06/17, 8307050342.
- 8307010144 Forwards application for amend to Licenses DFR-42 & DFR-60, changing Tech Spec Section 3.10 resulting from new LOCA analysis.

  MUSDLE, D. Northern States Power Co. 83/06/24. Office of Nuclear Reactor Regulation, Director. 1p. 19173:277. 24X
  Fiche: 50-282,83/06/24,8307010144.
- --8307010149 Application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Section 3.10 resulting from new LOCA analysis. MUSDLF, D. Northern States Power Co. 83/06/24, 3pp. 19173:278. 24X Fiche: 50-282,83/06/24,8307010144.
- --8307010153 Proposed changes to Tech Spec Section 3.10 resulting from new LOCA analysis.

  \* Northern States Power Co. 83/06/24. 9pp. 19173:281. 24X Fiche: 50-282.83/06/24.8307010144.
- --8307010137 "Prairie Island Units 1 & 2 Limiting Break LOCA-ECCB Analysis Using EXEM/PWR." CHANDLER.J.C. Exxon Nuclear Co., Inc. (Subs. of Exxon Copp.). XN-NF-B3-3B. B3/05/27. 56pp. 19173:291. 24X Fiche: 50-282, 83/06/24, 8307010144.
- 8307050092 Forwards application to amend Licenses DPR-42 & DPR-60, revising Tech Specs re-containment sys recombiners control room air treatment sys & ref to FSAR Table 7,7-2 Changes do not constitute significant hazards consideration. MUSDLF.D. Northern States Power Co. 83/07/01. Office of Nuclear Reactor Regulation, Director. tp. 19193:311. 24X Fiche: 50-282,83/07/01.8307050092.
- --8307050098 Application to amend Licenses DFR-42 & DFR-60, revising Tech Specs re containment sys recombiners, control room air treatment sys & ref to FSAR Table 7, 7-2.
  MUBOLF, D. Northern States Power Co. 83/07/01. App. 19193:312.
  24X Fiche: 50-282,83/07/01,8307050092.
- --8307080102 Proposed Tech Spece re containment sys recombiners control room air treatment sys & ref to FSAR Table 7.7-2.

  \* Northern States Power Co. 83/07/01. 14pp. 19193:318. 24x Fichs: 50-282,83/07/01,8307080092.
- B304270397 Generic Ltr 83-24 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EIBENHUT, D. Q. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390;317. 24X Ficha: 50-000, 83/07/05, 8304270397.
- 8307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in BTB. Svc list encl. EIBENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17667:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Balem ATMB events. Svc list encl. EIBENRUT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24x Fiche: 30-000, 83/07/08, 8307080169.
- 8307270001 Notice of consideration of issuance of amend to Licenses DPR-24 & DPR-60 & proposed NSHC determination & opportunity for hearing re-sodium hydroxide concentration in containment spray sus spray additive tank. CLARK.R.A. Operating Reactors Branch S. 83/07/08. 8pp. 19826:333. 24X Fiche: 50-282.83/07/08.8307270001.

- 8307270283 Clarifies location of Rosemount transmitters classified as Category II.B items in util 830505 ltr to NRC.
  MUSOLF, D. Northern States Power Co. 83/07/13. Office of Nuclear Reactor Regulation. Director. 2pp. 19769:031. 24X
  Fiche: 50-282, 83/07/13, 8307270283.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307060315 Forwards IE Insp Repts 50-282/83-07 & 50-306/83-07 on 830401-30 & notice of violation.
  SHAFER, W. D. Region 3, Office of Director. 83/06/20. LARSON, C. E. Northern States Power Co. 2pp. 19234: 231. 24X
  Fiche: 50-282, 83/06/20, 8307060315.
- --8307060324 Notice of violation from insp on 830401-30, SHAFER.H.D. Region 3, Office of Director. 83/06/20, 2pp. 19234: 233. 24X Fiche: 50-282, 83/06/20, 8307060315.
- --B307060328 IE Insp Repts 50-282/83-07 % 50-306/83-07 on 830401-30.

  Noncompliance noted: failure to perform daily theck of main steam line radiation monitors & monthly functional test for 4-kV safeguards buses & to verify valve position.

  FEIGRABEND.C.D., WILLIAMS.D.L., JACKIN.I.N. Region 3, Office of Director. B3/06/20, 7pp. 19234:235. 24X Fiche: 50-282,83/06/20, 8307060315.
- 8307180102 Forwards IE Insp Repts 50-282/83-08 & 50-306/83-08 on 830606-10. No noncompliance noted. PAPERIELLO, C. J. Region 3, Office of Director. 83/07/01. LARBON, C.E. Northern States Power Co. 2pp. 19557:010. 24X Fiche: 50-282,83/07/01,8307180102.
- --8307180107 IE Insp Repts 50-282/83-08 & 50-306/83-08 on 830606-10. No noncompliance noted Major areas inspected: madiological environ protection program including mgt controls GC & implementation & confirmatory measurements.

  JANUSKA: A. 9. NICHOLSON, N. A., SCHUMACHER, M. C. Region 3, Office of Director. 83/06/30. 7pp. 19357:012. 24x Fichs: 50-282, 83/07/01, 8307180102.
- B307280190 Forwards IE Insp Repts 50-282/83-12 % 50-306/83-12 on B30613-17. No noncompliance noted.

  STREETER, J. F. Region 3, Office of Director. 83/07/08. LARSDN.C.E. Northern States Power Co. 2pp. 19791:259. 24X
  Ficha: 50-282, 83/07/08, 8307280190.
- --8307280196 IE Insp Repts 50-282/83-12 & 50-306/83-12 on 830613-17. No noncompliance noted Major areas inspected maint program & implementation of maint program.

  CHOULES, N. C., KISH, J. N., HAWKINS, F. C. Region 3, Office of Director. 83/07/07. 7pp. 19791:261. 24X Fiche: 50-282,83/07/08,8307280190.
- 83Q6270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Sprag Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York: Inc. 154pp. 19563:293. 24X Fiche: 50-000, 93/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Conteminated Hydraulic Fluid." Svc list encl.
  JORDAN, E. L. Division of Energency Preparedness & Engineering Response (Post 930103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12:8306270404.
- 8306270496 IE Info Notice 83-48, "Gaseous Effluent Releases of Redicative I-125 & I-131 in Excess of NRC Limits." Bvc list encl.
  TAYLOR-J. M. Division of QA, Bafeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24x Fiche: 50-000, 83/07/14, 8306270406.
- 8307180109 Forwards IE Safeguards Insp Repts 50-282/93-11 & 50-306/83-11 on 830613-17. No noncompliance on nated. MILLER, J. R. Region 3, Office of Director, 83/07/14. LARSON, C. E. Northern States Power Co. 2pp. 19557:027. 24X Fiche: 50-282, 83/07/14, 8307180109.
- --B307180112 IE Safeguards Insp Repts 50-282/83-11 & 50-306/83-11 on 830613-17. No noncompliance noted Major areas inspected: security plan & implementing procedures locks keys & combinations. Safeguards info delated (ref 100FR73, 21). PIRILE. 6. L., KNICELEY. J. R., CREED. J. R. Region 9, Office of Director. 83/07/13. 2pp. 19557: 029. 24X Fiche: 50-282,83/07/14,8307180109.

- R. Pariodic operating reports & related correspondence
- 8307150065 Monthly operating repts for June 1983 M/830708 ltr. DUOSTAD, D., MUSOLF, D. Northern States Power Co. 83/07/05. of Resource Management, Director. 10pp. 19536:196. 24X Fiche: 50-282,83/07/05,8307150065.
- 8. Reportable occurrences, LERs & related correspondence
- 8307270059 Forwards safety evaluation of 811216 spent fuel assembly top morrie degradation event. Incident does not appear to have any generic implications re fuel assembly design, fabrication, handling or storage.

  CLARK, R. A. Dperating Reactors Branch 3. 83/07/11. MUSDLF, D. M. Northern States Power Co. 2pp. 19811:188. 24X

  Fichs: 50-282, 83/07/11, 8307270059.

Office

- --8307270072 Safety evaluation of 811216 spent fuel assembly top notile degradation event. Recommends that sulfate analysis be included in routine primary water & spent fuel pool water chemistry monitoring & analysis programs.

  9 Office of Nuclear Reactor Regulation, Director. 83/07/11, 9pp. 19811: 190. 24X Fiche: 50-282, 83/07/11, 8307270059.
- DOCKET 50-284 IDAHO STATE UNIV. RESEARCH REACTOR

  R. Periodic operating reports & related correspondence
- 8307010151 "Annual Operating Rept for 1982." SMITH.T.W. Iowa State Univ. 83/06/23. REID.R.W. Operating Reactors Branch 4. 3pp. 19175:333. 24X Fiche: 50-284.83/06/23. 8307010151.
- V. Operator Examinations
- B307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 398, "Personal Gualifications Statement Licensee," Svc list encl.
  EISENHUT, D. G. Division of Licensing, 83/07/11, Michigan, Univ. of. 14pp. 19563:138, 24X Fiche: 50-000, 83/07/11, 8307080427.
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
  F. Sacurity, medical, emergency & fire protection plans
- 8307040135 Discusses IE insp on 830418-22 % forwards notice of violation. Details will be included in IE Insp Rept 30-285/83-10.

  BEIDLE:M. C. Region 4. Diffice of Director. 83/05/04. JUNES, W. C. Omaha Public Power District. 2pp. 19252:242. 24X

  Fichs: 50-285, 83/05/04, 8307040135.
- --8307060141 Notice of violation from insp on 830418-22 Noncompliance noted: inadequate training of shift supervisors & emergency duty officers in emergency response Corrective actions & date of full compliance requested within 30 days.

  Region 4, Dffice of Director. 83/05/04. 2pp. 19252:244. 24) Fiche: 50-285, 83/05/04, 8307060135.
- 8306160016 Releases public version of revised radiological emergency response plan.
  FELTON.U.M. Division of Rules and Records. 83/06/06. Document Management Branch. 1p. 18872: 219. 24X Fiche: 50-285.83/06/06.
- --B306160022 Public Version of Rev 2 to radiological emergency response plan. W/B30511 ltr. Revised table of contents encl. JDNE6. W. C. Omaha Public Power District. 83/05/09. COLLINB, J. T. Region 4. Office of Director. 71pp. 18872: 220. 24X Fiche: 50-285, 83/06/06, 8306160016.
- 8307060015 Forwards IE Insp Rapt 50-289/83-10 on 830418-22 Notice of Violation forwarded by NRC 830504 ltr. SEIDLE, H. C. Region 4, Office of Director. 83/06/06. JONES, W. C. Omaha Public Power District. 2pp. 19251:026. 24X Fiche: 50-285, 83/06/06, 8307060015.
- --8307040017 IE Insp Rept 50-285/83-10 on 830418-22. Noncompliance noted: inadequate training of shift supervisor/emergency duty officer in emergency response. MONTGOMERY, J. L. , BAIRD, J. B. , JOHNSON, W. D. Region 4, Office of Director. 83/06/03. 7pp. 19251: 028. 24X Fiche: 50-285, 83/06/06, 8307060015.

- 8307250410 Ack receipt of 830513 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50~285/83-10.
  8EIDLE:W.C. Region 4. Office of Director. 83/06/06. JONES, W.C. Omaha Public Power District. 2pp. 19701: 255. 24X
  Fiche: 50-285, 83/06/06, 8307250410.
- --8307250428 Responds to NRC 830504 ltr re violations noted in IE Insp. Rept 50-285/83-10. Corrective actions: shift supervisors retrained on emergency response procedures. Generic implications of inspector findings under review. JONES.W.C. Omaha Public Power District. 83/05/13, 8EIDLE, W.C. Region 4, Office of Director. 5pp. 19701:257. 24X Fiche: 50-285,83/06/06,8307250410.
- 9307060033 Forwards 1E Insp Rept 50-285/83-14 on 930516-20. No noncompliance noted.

  BEIDLE,W.C. Region 4, Office of Director. 93/06/30, JONES,W.C. Omaha Public Power District. 2pp. 19251:324. 24X Fiche: 50-285,83/06/30,8307060033.
- --8307060040 IE Insp Rept 30-285/83-14 on 830516-20. No noncompliance nated Major areas inspected: security plan & implementing procedures: security organization. locks, keys & combinations. Details withheld (ref 10CFR73, 21).

  EVANS,C. A., KELLY, J. A. F., JOHNBON, M. D. Region 4. Dffice of Director. 83/06/28. ip. 17251: 326. 24X Fiche: 50-285, 83/06/30, 8307060033.
- B307270261 Informs that B11123 evaluation of design plan for emergency response facilities based on NUREG-0B14 not applicable per issuance of Suppl 1 to NUREG-0737.
  GLARK.R.A. Operating Reactors Branch 3. 83/07/11. JUNES, W. C. Omaha Public Power District. 2pp. 19811:186. 24X
  Fiche: 50-285,83/07/11,8307270261.

#### H. General correspondence

- B307150006 Advises that review of license amend request proposing mod to spent fuel pool to increase capacity of spent fuel storage racks to 729 fuel assemblies nearing completion, per 930606 ltr. W/o encl licensee application matls.
  TOURIGNY.E.Q. Operating Reactors Branch 3. B3/06/30. BIMMONB, H. E. Nebrasks, State of. 1p. 19562:337. 24X Fiche: 50-285, 83/06/30. B307150006.
- 8307070075 Informs that effective 830630,MT Shaw resigned as util atty. HM Voigt should be substituted on distribution list w/ same firm & address.
  VOIGT. H.H. LeBesuf, Lamb, Leiby & MacRae. 83/07/01. TOURIGNY, E. G. Operating Reactors Branch J. ip. 19269:360. 24X Fiche: 50-285,83/07/01,8307070075.

#### I. Financial information

- 8307190125 Forwards statement of cash flow from operations as guarantee for payment of deferred retrospective premiums.

  JUNES. W. C. Omeha Public Power District. 83/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19635: 227. 24X Fichs: 50-285, 83/07/06, 8307190125.
- J. Insurance & indemnity information
- B307170125 Forwards statement of cash flow from operations as guarantee for payment of deferred retrospective premiums.

  JONEB: W. C. Dmaha Public Power District. 83/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19635: 227. 24X Fiche: 50-283, 83/07/06, 8307170125.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307260031 Rev 1 to updated FSAR. Transmittal & receipt form encl.

  9 Omaha Public Power District. 83/07/31. 518pp. 19729:001. 24X
  Fiche: 50-285, 83/07/31, 8307260031.
- P. Operating license stage documents & correspondence
- 8307260179 Forwards current QA program.

  JONES, W. C. Omaha Public Power District, 83/06/10. COLLINS, J. T. Region 4, Office of Director. 1p. 19727:311, 24X

  Fiche: 50-285,83/06/10,8307260179.
- --B307260182 9A program.

  \* Omaha Public Power District. 83/06/10. 30pp. 19727:312. 24X Fiche: 50-285, 83/06/10. 8307260179.
- B307110616 Monthly notice of amends to DLs involving NSHC issued since B30523. CLARK, R. A. Dperating Reactors Branch 3. B3/06/14. 26pp. 19391:152. 24X Fiche: 50-000, B3/06/14, B307110616.

- 8307180446 Forwards monthly FR notice of amends to OLs involving NSHC. \* Office of Nuclear Reactor Regulation, Director, 83/06/15, UHRIG.R.E. Florida Power & Light Co. 2pp. 19641:347. 24X Fiche: 50-000, 83/06/15, 8307180446.
- --8307190001 Monthly notice of amends to OLs involving NSHC. CLARK, R. A. Operating Reactors Branch 3. 83/06/07. 15pp 19641: 349. 24X Fiche: 50-000, 83/06/15, 8307180446.
- 830706009B Responds to Generic Ltr 83-10B re resolution of TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Util endorses C-E Dwners Group program in resolving reactor coolant pump trip issue, UNNEG.W.C. Omaha Public Power District. 83/06/30. CLARK.R.A. Operating Reactors Branch 3. 6pp. 19231:186. 24X Fiche: 50-285, 83/06/30, 830706009B.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, 8vc list encl. E18ENHUT.D. O. Division of Licensing, B3/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 50-000, B3/07/05, B306270397.
- 8307040329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT, D. G. Division of Licensing. 63/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19649: 254. 24x Fiche: 50-000, 83/07/06, 8307060329.
- B3070B0169 Generic Ltr 83-2B to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 8307250548 Notification of 830726 meeting w/util in Bethesda,MD to discuss Tech Spacs on inoperability of safety sys channels. TOURIONY.E. G. Operating Reactors Branch 3. 83/07/18. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19716:009. 24X Fiche: 50-285,83/07/18,8307250548.
- 8307270498 Requests final submission of radiological effluent Tech Bpecs using encl Draft 7 of NUREG-0472.Rev 3, "Std Radiological Effluent Tech Bpecs for PWRs." Sept 1982.as guidance. Summary of unresolved issues encl. CLARM.R. A. Operating Reactors Branch 3. 83/07/19, JONES.W.C. Omaha Public Power District. 115pp. 19857:228. 24% Fiche: 50-285,83/07/19,8307290498.
- 8307260143 Advises of completed actions re NUREG-0737. Items II.F. 1.6 & III.D. 3.4 concerning containment hydrogen monitors & control room habitability, respectively, per 830308 & 14 ltrs. Final action to be completed by 840630.
  JUNES, W.C. Omaha Public Power District. 83/07/22. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19727: 286. 24X
  Fiche: 50-285.83/07/22.8307260143.
- G. Inspection reports. IE Bulletins & correspondence
- 8307040135 Discusses IE insp on 830418-22 % forwards notice of violation. Details will be included in IE Insp Rept 50-285/83-10.

  SEIDLE: M.C. Region 4, Office of Director: 83/05/04. JONES: M.C. Omeha Public Power District. 2pp. 19252: 242. 24X Fiche: 80-285: 83/05/04, 8307060135.
- --B307060141 Notice of violation from insp on B30418-22. Noncompliance noted: inadequate training of shift supervisors & energency duty officers in emergency response. Corrective actions & date of full compliance requested within 30 days.

  # Region 4, Office of Director. 83/03/04. 2pp. 19252:244. 24x Fiche: 30-285,83/05/04,8307060135.
- 8307220416 Responds to violation contained in IE Insp Rept 50-285/83-03. Corrective actions: upgraded mgt attention directed to assuring that technician & decontamination waste worker activities comply w/plant procedures.

  JONEG W. C. Omaha Public Power District. 83/03/13. SEIDLE, W. C. Region 4: Defice of Director. 12pp. 19687: 228. 24x
  Fiche: 50-285, 83/05/13, 8307220416.
- B307120487 Forwards IE Insp Rept 50-285/89-11 on B30401-30 & notice of violation.

  SEIDLE,W. G. Region 4, Office of Director. 83/05/18. JONES,W. G. Omaha Public Power District. 2pp. 19425:040. 24X Fiche:50-285/83/05/18/B307120487.

- --8307120492 Notice of violation from insp on 830401-30. # Region 4: Office of Director. 83/05/18. 1p. 17425:042. 24X Fiche: 50-285, 83/05/18, 8307120487.
- --8307120497 IE Insp Rept 50-285/83-11 on 830401-30 Noncompliance noted: failure to maintain logs to document removal of annunciators A13-83U, A-2-C3L & A2-C4L from svc. YANDELL, L. A., JOHNSON, H. D. Region 4, Office of Director. 83/05/16. 9pp. 19425:043. 24X Fiche: 50-285.83/05/18,8307120487.
- 8307060015 Forwards IE Insp Rept 50-285/83-10 on 830418-22 Notice of violation forwarded by NRC 830504 ltr.
  8EIDLE.W. C. Region 4. Office of Director. 83/06/06. JONES.W. C. Omaha Public Power District. 2pp. 17251:026. 24X
  Fiche: 50-285.83/06/06.8307060015.
- --8307060019 IE Insp Rept 30-285/83-10 on 830418-22. Noncompliance noted: imadequate training of shift supervisor/emergency duty officer in emergency response.

  MONTGOMERY, J. L., DAIRD, J. B., JOHNSON, W. D. Region 4, Office of Director. 83/06/03. 7pp. 19251: 028. 24X Fiche: 30-285, 83/06/06. 8307060015.
- 8307250410 Ack receipt of 830313 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-10.

  BEIDLE,W.C. Region 4. Office of Director. 83/06/06. JONES,W.C. Omeha Public Power District. 2pp. 19701:255. 24X Fichs:50-285.83/06/06,8307250410.
- --8307250428 Responds to NRC B30504 ltr re violations noted in IE Insp. Rept 50-285/83-10. Corrective actions: shift supervisors retrained on emergency response procedures. Generic implications of inspector findings under review. JONES.H.C. Omaha Public Power District. B3/05/13. GEIDLE.H.C. Region 4. Defice of Director. Spp. 19701:257, 24X Fiche:50-285,83/06/06.8307250410.
- B307240435 Ack receipt of 830513 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-03. Notice of violation response adequate. Notice of deviation response inadequate re min experience required of chemist. SEIDLE:W.C. Region 4. Office of Director. 83/06/06. JONES,W.C. Omaha Public Power District. 3pp. 19734:171. 24X Fiche: 50-285,83/06/06,8307260435.
- --8307120523 IE Insp Rept 50-285/83-13 on 830501-31.No noncompliance noted Major areas inspected operational safety verification, startup testing, surveillance testing, maint activities & followup on violations & NUREG-0737 items.

  YANDELL, L. A., JOHNEON, H. D. Region 4, Office of Director. 83/06/14, 12pp. 19433:204. 24X Fiche: 50-285, 83/06/14, 8307120514.
- 8307080423 Forwards response to IE Bulletin 82-02,Action Item 4 re insp of RCP8 threaded fasteners in PWR plants per ABME Code, Section XI. No major corrosion identified. JUNES, M. C. Dmaha Public Power District. 83/06/24. COLLINS, J. T. Region 4. Dffice of Director. Spp. 19347:269. 24X Fiche: 50-285,83/06/24,8307080423.
- B307150073 Forwards IE Insp Rept 50-285/83-15 on 830531-0603 & notice of violation.

  SEIDLE: W. C. Region 4, Office of Director. B3/06/27. JONES, W. C. Omaha Public Power District. 2pp. 19536:170. 24X

  Fiche: 50-285, 83/06/27, 8307150073.
- --8307150074 Notice of violation from insp on 830531-0603.
  \* Region 4, Office of Director, 83/06/27, ip. 19536:172. 24X
  Fiche:50-285.83/06/27,8307150073.
- --8307130079 IE Insp Rept 80~285/83-15 on 830531-0603. Noncompliance noted: failure to follow Procedures G-22 & G-25 re storage of critical quality elements & stores control respectively. REDAND.R.T., MCCRORY.S.L., MESTERMAN.T.F. Region 4, Office of Director, 83/06/23, 9pp. 19536;173. 24X Fiche: 50-285,83/06/27,8307150073.
- 9307060033 Forwards IE Insp Rept 50-285/83-14 on 830516-20. No noncompliance noted.

  8EIDLE, M.C. Region 4, Office of Director. B3/06/30. JONES, W. C. Gmaha Public Power District. 2pp. 19251:324. 24X

  Fiche: 50-285, 83/06/30, 8307060033.

- --8307060040 IE Insp Rept 50-285/83-14 on 830516-20. No noncompliance noted Major areas inspected: security plan & implementing procedures, security organization, locks, keys & combinations. Datails withheld (ref 10CER73.21).

  EVANS.C.A., KELLY.J.A.F., JOHASON.W.D. Region 4, Office of Director. 83706/28. 1p. 19251:326. 24X Fiche: 50-285, 83706/30, 8307060033.
- 8307120449 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-09, SEIDLE, M. C. Region 4, Office of Director, 83/07/01, JONES, W. C. Chaha Public Power District, 1p. 17425:343, 24X Fiche:50-285,83/07/01,8307120449.
- --8307120454 Responds to NRC 830506 ltr re violations noted in IE Insp. Rept 50-285/83-08. Corrective actions: GA Procedurs 19 replaced by dept manual procedure establishing requirement for individual training files.

  JONES W. C. Omaha Public Power District. 83/06/03. BEIDLE, H. C. Region 4, Office of Director. 4pp. 19425: 344. 24X Fiche: 50-285, 83/07/01, 8307120449.
- 8307120460 Ack receipt of 830617 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-11.Add1 info re annunciator status log required within 30 days. SEIDLE.H.C. Region 4. Office of Director. 83/07/01. JONES.H.C. Omaha Public Power District. 1p. 19425:359. 24X Fiche:50-283,83/07/01.8307120460.
- --8307120465 Responds to NRC 830518 ltr re violations noted in IE Insp. Rept 50-285/83-11. Corrective actions: ltr issued from operations supervisor to operations personnel, reemphasizing need for strict compliance re annunciator log.

  JONES. M. C. Omaka Public Power District. 83/06/17. BEIDLE, M. C. Region 4, Dffice of Director. 3pp. 19425:360. 24X
  Fiche: 50-285,83/07/01,9307120460.
- 8307120482 Forwards "Steam Generator Tube Eddy Insp Rept. Steam Generators A & B.1983 Refueling Outage."

  JONES.C. Omaha Public Power District. 83/07/01. CLARK.R.A. Operating Reactors Branch 3. ip. 19425:067. 24X

  Fiche: 50-285, 83/07/01.8307120482.
- --8307120487 "Steam Cenerator Tube Eddy Current Insp Rept.Steam Generators A & B.1983 Refueling Outage." \* Omaha Public Power District. 83/07/01. 8pp. 19425:068. 24X Fiche: 50-285.83/07/01.8307120482.
- 8307180182 Forwards relief requests from exam requirements of Winter 1980 addends to ASME Boiler & Pressure Vessel Code. Section XI.re rules for insp of nuclear power plant components, per 10CFR30. 55a(g)(5)(iii).
  JONES W. C. Omaha Public Power District. 83/07/07. CLARK.R. A. Operating Reactors Branch 3. 16pp. 19555:037. 24X Fiche: 50-285.83/07/07,8307180182.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JURDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19863:293. 24X Fiche:50-000,83/07/11,8306270401.
- 830-6270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Syc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Qassous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. H. Division of GA: Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307270338 Forwards inservice insp rept conducted during 821207-830407 by SHRI.
  JONES, H. C. Omaha Public Power District. 83/07/15. DENTON, H. R.
  Office of Nuclear Reactor Regulation, Director. 1p. 19767:241. 24X
  Fiche: 50-285, 83/07/15, 8307270338.
- --8307270345 Inservice insp rept conducted during 821207-830407 by SWRI. Describes NDE of selected components at facility. VANELI,J.A. Dmaha Public Power District. 83/07/11. 60pp. 19767:242. 24X Fiche: 50-285,83/07/15.8307270338.

#### R. Periodic operating reports & related correspondence

B307190158 Monthly operating rept for June 1983. H/B30714 ltr.
MATTHEWB.T.P., JONES.W.C. Omaha Public Power District. B3/07/14.
DEYOUNG.R.C. Director's Office. Office of Inspection and
Enforcement. 10pp. 19636:243. 24X Fiche:50-285.83/07/14.
B307190158.

#### U. Congressional/Executive Correspondence

- B307270047 Forwards monthly FR notice of consideration of issuance of amends to OLs involving NSHC determination & opportunity for hearing.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

  B3706/22. BTAFFORD.R.T. Senate, Environment & Public Works. 2pp. 1981:018. 24X Fiche: 50-000, 83/06/22, 8307270047.
- --B307270050 Monthly notice of consideration of issuance of amends to OLs involving NSHC determination & opportunity for hearing. CLARK.R.A. Operating Reactors Branch 3. 83/06/07. 15pp. 19811:020. 24X Fiche: 50-000. 83/06/22.8307270047.

#### DOCKET 50-284 INDIAN POINT STATION, UNIT 3

## F. Security, medical, emergency & fire protection plans

- B307110410 Forwards IE Safeguards Insp Rept 50-286/83-12 on 830516-20 & notice of violation.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/22, BRONG.J.C. Power Authority of the State of New York. 2pp. 19382:286. 24X Fiche: 50-286:83/06/22:8307110410.
- --8307110418 Notice of violation from insp on 830516-20 Proprietary details delated (ref 10CFR73.21).

  \*\*Region 1, Office of Director. 83/06/22. 1p. 19382:288. 24X Ficha:50-286.83/06/22,8307110410.
- ---8307110425 IE Bafeguards Insp Rept 50-286/83-12 on 830516-20.

  Noncompliance noted: failure to include portion of protected area barrier in intrusion detection sys. Proprietary details deleted (ref 100FR73. 21).

  MCKEONN.L.H., DUNLAP.J.H., GDDY.A.T. Region 1. Office of Director. 83/06/17. 3pp. 17382:287. 24X Fiche: 50-286.83/06/22.8307110410.
- B307120023 Releases public version of revised emergency plan implementing procedures.

  FELTON:J.M. Division of Rules and Records. 83/06/24. Document Hanagement Branch. 1p. 19509:113. 24X Fiche: 50-286,83/06/24,8307120023.
- --B307120027 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1002 redetermination of magnitude of release, IP-1011 re offsite monitoring & IP-1047 re operations support ctr.
  LCHONACO, L. M. Power Authority of the Btate of Naw York. B3/05/27.
  NRC No Detailed Affiliation Given. 2pp. 19509:114. 24X Fiche: 50-286, 83/06/24, 8307120023.
- --B307120032 Public version of revised emergency plan implementing procedures, including Procedures IP-1002 rs determination of magnitude of release, IP-1011 rs offsits monitoring & IP-1047 rs operations support ctr.

  BELL.D. D., LOMONACO. L. Power Authority of the State of New York B3/05/27, 168pp. 19509:116. 24% Fiche: 50-286, 83/06/24, 8307120023.
- B3071403B6 Forwards IE Insp Rept 50-286/83-10 on 830531-0603.No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. B3/06/29 BRONS.J.C. Power Authority of the State of New York. 2pp. 17523:355. 24X Fiche: 50-286.B3/06/27.B307140386.
- --8307140391 IE Insp Rept 50-286/83-10 on 830531-0603. No noncompliance noted Hajor areas inspected annual emergency exercise performed on 830602.

  MILLER, H. . CROCKER, H. W. Division of Engineering & Technical Programs. 83/06/17. 6pp. 19523:357. 24X Fiche:50-286:83/06/29.8307140386.
- 8307270221 Forwards NRC draft SER re exemptions requested from 10CFR50, App R.
  MOORE, J. E. Hearing Branch 1. 83/07/22. QLEASON, J. P. Atomic Safety and Licensing Board Panel. 45pp. 19749:124. 24X
  Fichs: 50-247, 83/07/22, 8307270221.
- B307280304 Forwards IE Insp Rept 50-286/83-13 on 830516-0615. No noncompliance noted.

  BTAR08TECKI, R. Division of Project & Resident Programs. B3/07/24.

  BRONS, J. C. Power Authority of the State of New York. 2pp. 19789: 197. 24X Fiche: 50-286,83/07/24,8307280304.

---B3072B031i IE Insp Rept 50-286/83-13 on B30516-0615. No noncompliance noted Major areas inspected: plant operations, monthly operating rept, followup on IE bulletins, App R equipment testing & potential loose locks on fire dampers.

KENNY,T. J., ROSSBACH. L. M. Region 1, Office of Director.

COLLING, S. Division of Project & Resident Programs. B3/06/23.

11pp. 19789: 199. 24X Fichs: 50-286,83/07/24,8307280304.

#### Q. Adjusticatory correspondence

- 8307120563 Memorandum apposing PIRG of New York motion for reconsideration of Commission 830610 order. PIRG should not be permitted to relitigate arguments fully considered & ruled upon by Commission.

  BRANDENBURG.B. Consolidated Edison Co. of New York, Inc. 83/07/07. Commissioners. 3pp. 19433:131. 24X Fiche: 50-247,83/07/07, 8307120563.
- 8307120365 Response opposing PIRO of Naw York motion for reconsideration of Commission 830610 order. Motion untimely, identifies no matters of fact or law & improperly raises new issues. Certificate of Svc encl.

  MORGAN.C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/07/07. Commissioners. 10pp. 19433:136. 24X Fiche: 50-247,83/07/07,8307120565.
- 8307120946 Order approving util & NRC 830615 transcript corrections. W/listed exceptions. GLEASON.J.P. Atomic Bafety and Licensing Board Panel. 83/07/08. Office of the Executive Legal Director. 5pp. 19433:358. 24% Fiche: 50-247.83/07/08.8307120546.
- 8307120035 Proposed findings of fact conclusions of law opinions & recommendations re Commission Questions 1-6 (Vols 1-3).
  MORGAN.C. Power Authority of the State of New York. MORGAN.C.
  Morgan Associates. 83/07/11. 947pp. 19420:001. 24X
  Fiche: 50-247.83/07/11.6307120035.
- 8307130077 Proposed findings of fact & conclusions of law Certificate of Svc encl.

  # Union of Concerned Scientists. # Public Interest Research Oroug, New York. # West Branch Conservation Association. 83/07/11.
  323pp. 19472:325. 24X Fiche:50-247,83/07/11.8307130077.
- 8307130234 Proposed opinion, findings of fact, conclusions of law & recommendations. Cartificate of Svc ancl. MODRE, J.E., HABSELL, D. F., MCGURREN, H. J. Hearing Branch 1. 83/07/11. 562pp. 19505: 03B. 24X Fiche: 50-247.83/07/11.8307130234.
- 8307180060 Proposed findings of fact re Commission Questions 1-6 & proposed opinion, conclusions of law & recommendations.
  Certificate of Svc encl.
  BRANDEMBURG, B. Consolidated Edison Co. of New York, Inc. 83/07/11.
  994pp. 19557:091. 24X Fithe: 50-247.83/07/11.8307180060.
- B307180071 Forwards proposed findings of fact & conclusions per B30422 memo.

  O'ROURKE, A. P. Westchester County, NY. B3/07/11. QLEABON, J. P. Atomic Safety and Licensing Board Panel. 1p. 19560:161. 24X Fiche: 50-247,83/07/11,8307180071.
- --8307180074 Proposed findings of fact & conclusions. Certificate of Sycenci.

  \* Westchester County, NY. 83/07/11. 37pp. 19560:162. 24X
  Fichs: 50-247, 83/07/11. 8307180071.
- 8307210051 Forwards two corrected pages to NRC proposed opinion, findings of fact, conclusions to law & recommendations. MCGURREN.H.J. Hearing Branch 1. 83/07/13. GLEABON,J.P., BHON,F.J., FARIS, O.H. Atomic Safety and Licensing Board Panel. 1p. 19668;274. 24X Fiche: 50-247,83/07/13,8307210051.
- --8307210061 Two corrected pages to NRC proposed opinion, findings of fact, conclusions of law & recommendations.

  \* Office of the Executive Legal Director. 83/07/13. 2pp. 19668:275. 24X Fiche: 30-247,83/07/13,8307210051.
- 8307270221 Forwards NRC draft SER rs exemptions requested from 10CFR50, App R.
  MOORE J.E. Hearing Branch 1. 83/07/22. QLEABON, J.P., PARIB, Q.H., EHON, F.J. Atomic Safety and Licensing Board Panel. 45pp. 19749: 124. 24X Fichs: 50-247, 83/07/22, 8307270221.
- 8307270117 Order extending time until 830824 for Commission to act to review 830627 Director's Decision.
  CHILK. S. J. Office of the Secretary of the Commission. 83/07/25.
  Commissioners. ip. 19749:346. 24X Fiche: 50-247.83/07/25.
  B307270117.

- 8307290094 Memorandum re PJ Amico, ASLB consultant, 830624 rept on testimony on Commission Questian 5. No need exists for further testimony or party comments on rept. GLEASON.J.P. Atomic Safety and Licensing Board Panel. 83/07/27. 2pp. 1982:214. 24x Fiche: 50-247, 83/07/27, 8307290094.
- --8307290108 Presents results of review of testimony on Commission Question 5. Testimony on Question 5 is as complete as possible but suffers from same deficiencies re relative rist.

  AMICO.P.J. Applied Risk Technology Corp. 83/07/01. QLEASON, J.P., SMON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel. 7pp. 19822:216. 24% Fiche: 50-247.83/07/27,830/2790094.

#### H. General correspondence

- 8307060629 Ack receipt of 830523 ltr requesting info re air locks, NRC has no records re mfg of air locks. Review of application for OL identified Westinghouse as NSSS supplier. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 83706/21. INDELICATO, C. O'Dwyer & Bernstein. 2pp. 19299:211. 24X Fiche: 50-286, 83706/21, 8307060629.
- --8307060632 Informs that firm represents J O'Boys in lawsuit arising from injuries sustained on 820801 while working in 80-ft airlock in vessel containment. Info on airlock manufacturer & any other info requested.

  INDELICATO.C. O'Duyer & Bernstein. 83/05/23. NRC No Detailed Affiliation Given. ip. 19299:213. 24X Fiche:50-286.83/06/21, 8307060629.
- B307050100 Forwards Rockland County Legislature Resolution 3B9 requesting plants cease operation until County radiological plan approved.

  BANUELS P. Rockland County, NY. B3/06/27. PALLADIND. N. J. Cummissioners. 3pp. 19197: 344. 24X Fiche: 50-247, 83/06/27, 8307050100.
- --8307050110 Forwards Rockland County Legislature Resolution 370 requesting State of NY Legislature to pass legislation regulating nuclear power industry, based on economic consequences of radiological accidents & nuclear waste, SANUELS,P. Rockland County, NY. 83/06/27, PALLADING,N, Commissioners. 3pp. 19199;347. 24X Fiche: 50-247,83/06/27,8307050100.
- --8307050116 Forwards Rockland County Legislature Resolution 391 authorizing County atty to take legal action if NRC does not what down plants on 830609;

  SAMUELS, P. Rockland County, NY. 83/06/27, PALLADING, N. J. Commissioners. 4pp. 19199; 350. 24X Fiche: 50-247, 83/06/27, 8307050100.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307250194 Forwards FSAR 1983 update re new designation of procedures & performance dept to QA & reliability dept.
  BAYNE, J.P. Power Authority of the State of New York. B3/07/20. DENTIN.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19704:309. 24X Fiche: 50-284, B3/07/20, B307250194.
- --8307250200 FSAR 1983 updats.

  4 Power Authority of the State of New York. 83/07/31. 174pp. 19704:311. 24X Fiche: 50-286, 83/07/20, 8307250174.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Mestinghouse PMRs re safety evaluation of "Emergency Response Quidelines." Bvc list encl.
  EISEMHUT.D. 0. Division of Licensing. 83/06/02. Yankse Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 80-000, 83/06/03. 8306060070.
- 8307030371 Forwards SER re 811116 response to Generic Ltr 81-21, "Natural Circulation Cooldown." Response acceptable since upper head voiding not safety concern. VARGA, 8. A. Operating Reactors Branch I. 83/06/10. BAYNE, J. P. Power Authority of the State of New York. 2pp. 19263: 317. 24X Fichs: 50-286, 83/06/10, 8307050371.
- --8307050376 SER re 8:1116 response to Generic Ltr 81-21, "Natural Circulation Cooldown." Licensee confirmation of listed training program items requested Resolution of adequacy of training procedures deferred to TMI Item I.C.1.

  \*\* NRC No Detailed Affiliation Given. 83/06/10. Spp. 19263:319. 24X Fiche:50-286.83/06/10.8307050371.

- 8307060389 Forwards SER granting relief from inservice testing requirements & defining alternate schedules & procedures. License amend request modifying Tech Specs to reflect approval for items requested within 45 days. VARGA. 5. Derating Reactors Branch 1. 83/06/13. BAYNE, J. P. Power Authority of the State of New York. 2pp. 19300:029. 24x Fiche: 50-286,83/06/13,8307060389.
- --8307060392 BER granting relief from inservice testing requirements & defining alternate schedules & requirements.

  \* NRC No Detailed Affiliation Given. 83/06/13. 48pp. 19300:031. 24X Fiche: 50-286, 83/06/13, 8307060389.
- 8307050450 Forwards safety evaluation re NUREQ-0737.TMI Items II.F.1.4, "Containment Pressure Monitor," II.F.1.5, "Containment Water Level Honitor " & II.F.1.6, "Containment Hydrogen Monitor," Items resolved,
  VARCA B.A. Operating Reactors Branch 1. 83/06/14, 8AYNE, J.P. Power Authority of the State of New York, Spp. 17262:281, 24X Fiche: 50-286, 83/06/14, 8307050450.
- B307080259 Forwards backfit cost figures for add1 seven utils per original B30208 request Cost figures for 20 utils transmitted B30411. TOURTELLOTTE. J. Regulatory Reform Task Force. B3/06/22, PALLADINO, N. Commissioners. 2pp. 19363:313. 24X Fiche: 50-000: 83/06/22, 8307080259.
- --B307080337 Forwards backfit & regulatory impact cost analysis for facility, per NRC B3020B request. Analysis, formerly confidential atty work product, released to intervenors & now to task force.

  BAYNE, J. P. Power Authority of the State of New York. 83/06/01. TOURTELLOTTE, J. Regulatory Reform Task Force. ip. 19363:321. 24% Fiche: 50-000, 83/06/22, 8307080259.
- --8307080341 "Determining Portion of Regulatory Burden on Indian Point 3 Capital & D&M Expenditures 1976 - 1986: 10-Yr Cost Projection Also Included." \* Power Authority of the State of New York. 83/04/30. 36pp. 19369: 322. 24X Fiche: 50-000, 83/06/22, 8307080259.
- 830725008B Approves 821018 request for withholding Rev 1 to Westinghouse WCAP-10145 from public disclosure (ref 10CFR2.790).
  VAROA, B. A. Operating Reactors Branch 1. 83/06/27. BAYNE, J. P. Power Authority of the State of New York. 4pp. 19720:337. 24X Fiche: 50-286, 83/06/27, 830725008B.
- B307270243 Approves request for withholding Rept B3-155, "Fracture Mechanics Analysis of Indian Point 3 Nuclear Generating Station Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions," (ref 10CFR2,790).
  VARQA, B. A. Operating Reactors Branch 1. B3/06/27. BAYNE, J.P. Power Authority of the State of New York. App. 1981: 167. 24x Fiche: 50-286, B3/06/27, B307270243.
- 8307220138 Summary of B30127 meeting w/util in Bethesda. MD re sys interaction (SI) program at facility. Util indicates complete SI program will be submitted in Fall 1983. Meeting agenda t visuagraphs encl. POLK. P. J. Operating Reactors Branch 1. 83/06/29. Operating Reactors Branch 1. 83/06/29. 3307220138.
- 8307250528 Requests that design info used by Ebasco in performing sys interaction methodology studies be provided directly to BNL & LLL. Effort important to resolution of Unresolved Safety Issue A-17.
  VARQA, B. A. Operating Reactors Branch 1. 83/06/29. BAYNE, J. P. Power Authority of the State of New York. 3pp. 19739; 272. 24x Fiche: 50-286, 83/06/29, 8307250528.
- --8306020348 Forwards list of all plant-descriptive info provided by EBASCO & PABNY.
  ALESSO,P. Lawrence Livermore Laboratory. 83/05/27. CONRAN.J. Reliability & Risk Assessment Branch. 7pp. 19739:275. 24X Fiche:50-286.83/06/29.8307250528.
- 8306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISEMMUT.D.Q. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000, B3/07/05, 8306270397.
- 8307220128 Forwards SER re util 811116 response to Generic Ltr 81-21. "Natural Circulation Cooldown." Mods recommended by Hastinghouse study demonstrate sufficient condensate supply consistent w/procedures. Response acceptable. VARGA.5. Operating Reactors Branch 1. 83/07/05. BAYNE, J. P. Power Authority of the State of New York. 2pp. 17672:274. 24X Ficha: 50-286, 83/07/05, 8307220128.

- -8307220134 SER re util 811116 response to Ceneric Ltr 81-21. "Natural Circulation Cooldown." Licensee demonstrated ability to cooldown w/o voiding.

  \*\*Office of Nuclear Reactor Regulation, Director. 83/07/05. 8pp. 19692: 296. 24X Fiche: 50-286, 83/07/05, 8307220128.
- 8307270249 Requests meeting be planned in Bethesda.MD re sys fnteraction study at plant based on previous 830127 meeting & draft guidelines VARGA.S.A. Operating Reactors Branch 1. 83/07/05. BAYNE.
  - & draft guidelines.

    VARGA,S.A. Operating Reactors Branch 1. 83/07/05. BAYNE,J.P.

    Power Authority of the State of New York 2pp. 19811: 171. 24X

    Fiche: 50-286,83/07/05,8307270249.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EIEENHUT.D.O. Division of Licensing. 83/07/06 Consolid. Edison Co. of New York, Inc. 16pp. 17669:254. 24x Fiche: 50-000, 83/07/06, 8307060329. Consolidated
- B307110427 forwards application for amend to License DPR-64, changing Tech Specs re DHR capability, in response to NRC 830611 request.

  BAYNE, J.P. Power Authority of the State of New York, 83/07/06, VARGA, S.A. Operating Reactors Branch 1, 2pp. 19382; 250, 24x Fiche: 50-286, 83/07/06, 8307110427.
- --8307110433 Application for amend to License DPR-64, changing Tech Specs re DHR capability. BAYNE, J.P. Power Authority of the State of New York. 83/07/06. 1p. 19382:252. 24X Fiche: 50-286, 63/07/06.8307110429.
- --8307110438 Proposed Tech Spec changes re DHR capability. \* Power Authority of the State of New York. 83/07/06. 12pp. 19382:253. 24X Fiche:50~286.83/07/06.8307110429.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EIEENMHVI.D.O. Division of Litensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000,83/07/08.8307080169.
- 8307190436 Requests remittance of add1 sum to complete fees require for 821018 application re-steam generator tube & girth weld repair program.

  DIGGS.R M License Fee Management Branch. 83/07/08. BAYNE, J.P. Power Authority of the Stato of New York. 1p. 19656:167. 24X Fiche: 50-286, 83/07/08, 8307190436.
- G. Inspection reports, IE Bulletins & correspondence
- 8307070495 Forwards SER & technical evaluation rept re util analysis of main steam line break w/continued feedwater addition in response to IE Bulletin 80-04. Analysis acceptable. VARQA, S. A. Operating Reactors Branch 1. 83/06/10. BAYNE, J. P. Power Authority of the State of New York. 2pp. 19300:198, 24x Fiche: \$0-286, 83/06/10, 8307070495.
- --8307070504 SER re main steam line break w/contained feedwater addition per IE Bulletin 80-04.Util analysis acceptable.
  \* Containment Systems Branch. 83/06/10. 6pp. 19300:200. 24X
  Ftche: 50-286.83/06/10.8307070499.
- --8306140197 "PWR Main Steam Line Break W/Continued Feedwater Addition for Indian Point Nuclear Power Plant Unit 3," technical evaluation rept.

  VOSBURY,F. W. Franklin Institute/Franklin Research Center.

  NRC-03-81-130. TER-C5506-130. 83/05/25. HEARN,P. NRC No Detailed Affiliation Given. 22pp. 19300:206. 24X

  Fiche: 50-286, 83/06/10, 8307070495.
- 8307270275 Forwards SER re inservice inspirelief requests. Relief granted from exam requirements determined impractical to perform. License amend request modifying Tech Specs should be submitted within 45 days to complete inservice inspirely before. VARGA. B. A. Operating Reactors Branch 1. 83/06/13. BAYNE, J. P. Power Authority of the Btate of New York. 2pp. 19812:047. 2: Fishe: 50-298. 83/06/13. 83022/025 Fiche: 50-286, 83/06/13, 8307270275
- --B307270282 SER supporting request for relief from inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code due to plant design, component geometry & const matls, \* Office of Nuclear Reactor Regulation, Director. B3/06/13, 13pp. 19812:049. 24X Fiche: 50-286, 83/06/13, 8307270275.
- 8307110410 Forwards IE Safeguards Insp Rept 50-286/83-12 on 830516-20 & notice of violation.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/22.

  BRONS.J.C. Power Authority of the State of New York. 2pp.

  19382:286. 24X Fiche: 50-286.83/06/22.8307110410.

- --8307110418 Notice of violation from insp on 830516-20.Proprietary details deleted (ref 10CFR73.21).
  4 Region 1, Office of Director. 83/06/22. lp. 19382:288. 24% Fiche:50-286,83/06/22.8307110410.
- --8307110425 IE Safeguards Insp Rept 50-286/83-12 on 830516-20.

  Noncompliance noted: failure to include portion of protected area barrier in intrusion detection sys. Proprietary details deleted (ref 10CFR/3.21).

  MCKEOWN,L.M., DUNLAP, J.M., GDDY, A.T. Region 1, Office of Director.
  83/06/17. 3pp. 19382: 289. 24X Fiche: 50-286, 83/06/22, 8307110410.
- 8307140386 Forwards IE Insp Rept 50-286/83-10 on 830531-0603.No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/29, 87008.J.C. Power Authority of the State of New York. 2pp. 19523:355. 24X Fiche: 50-286, 83/06/29, 8307140386.
- --8307140391 IE Insp Rept 30-286/83-10 on 830531-0603. No noncompliance noted Major areas inspected: annual emergency exercise performed on 830602.

  MILLER.M., CROCKER.H.W. Division of Engineering & Technical Programs. 83/06/17. 6pp. 19523:357. 24X Fiche: 50-286.83/06/29, 6307140386.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Efficent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list TAYLOR, J. M. Division of QA. Safeguards & Inspection Programs (P 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- 8307240448 Forwards addl info re integrally-welded pump support metls, per 810630 response to NRC 810403 request for info concerning inservice insp program. Use of austonitic stainless steel support feet not feasible.

  BAYNE, J. P. Power Authority of the State of New York. 83/07/20. VAR9A, S. A. Operating Reactors Branch I. 2pp. 19733:345. 24% Fiche: 50-286,83/07/20,8307260468.
- 8307280304 Forwards IE Insp Rept 50-286/83-13 on 830516-0615. No noncompliance noted.
  STAROBIECKI,R. Division of Project & Resident Programs. 83/07/24.
  BRONS, J. C. Power Authority of the State of New York. 2pp. 19789:197.
- --8307280311 IE Insp Rept 50-286/83-13 on 830516-0615. No noncompliance noted Major areas inspected; plant operations, monthly operating rept, followup on IE bulletins. App R equipment testing & potential loose locks on fire dampers.

  KENNY.T.J. ROSSBACH.L.W. Region 1, Office of Director.

  COLLINS.S. Division of Project & Resident Programs. 83/06/23.

  11pp. 19787:199. 24X Fiche: 50-286, 83/07/24, 8307280304.
- R. Periodic operating reports & related correspondence
- 8307220251 Monthly operating rept for May 1983.W/830610 ltr. KELLY.L.: BRONS.J.C. Power Authority of the State of New York. B3/06/01. Division of Data Automation & Management Information. Bpp. 19684:217. 24% Fiche:50-286.B3/06/01.B307220251.
- 8. Reportable occurrences, LERs & related correspondence
- 8307150119 Part 21 rept re deviation in installation of ASCO 302A1264C transfer switches. Evaluation in progress. Next rept will be submitted within 60 days of ltr date.

  MANNA,F. J. Automatic Switch Co. 83/06/27. Region 4, Office of Director. 1p. 19536:227. 24X Fiche: 50-247.83/06/27.8307150119.
- 8307130018 LER 83-004/03L-0: on 830604, leak observed at elbow-to-pipe weld on charging pump 31 relief line 210 downstream of relief valve RV231. Cause not stated. Valve 231 replaced & pump returned to syc. W/830627 ltr.

  GUMBLE.F. W. BRONS.J. C. Power Authority of the State of New York.
  837/04/27. MURLEY.T.E. Region 1. Office of Director. 3pp.
  17536: 208. 24X Fiche: 50-286, 83/04/27, 8307150018.

- 8307130254 LER 83-003/03L-0; on 830531, while in hot shutdown, leak observed at elbow-to-pipe weld on charging pump 31 relief 1 ine. Leak located on line 210 downstream of relief valve RV231. Caused by vibration, H/630627 ltr.

  OUMBLE,F.W. BRONG.J.C. Power Authority of the State of New York. 83/06/29. MURLEY,T.E. Region 1. Office of Director. 3pp. 19538: 336. 24% Fiche: 50-286,83/06/29,8307150254.
- T. Hearing transcripts on non-antitrust matters
- 8307080287 Transcript of ACRS Combined Subcommittees on Indian Point & Reliability & Probabilistic Assessment 830706 meeting in Washington DC. Pp 1-283. Supporting documentation encl. ACRS Advisory Committee on Reactor Safeguards. 83/07/06. 328pp. 19353:122. 24X Fiche: 50-247,83/07/06,8307080287.
- 8307250678 Forwards Commission determination statement releasing transcript of 830519 briefing on enforcement matter. CHILM.B. J. Office of the Secretary of the Commission. 83/07/19. Public Document Branch. 2pp. 19718:106. 24X Fiche: 50-247,83/07/19,8307250678.
- ---8307250681 Transcript of Commission 830519 closed meeting re enforcement actions based on emergency planning deficiencies in Washington, DC. Pp 1-30. > Commissioners. 83/07/19. 31pp. 19718:108. 24X Fiche: 50-247.83/07/19.8307250678.
- U. Congressional/Executive Correspondence
- B307270054 Responds to B30620 ltr re plant status.addressing special proceeding.emergency preparedness & plant operational status.

  DIRCKS.H.J. Office of the Executive Director for Operations.
  B3/07/15. LUNDING.S. House of Rep. 6pp. 19811:045. 24X

  Pichs: 50-247.B3/07/15.B307270054.
- --8307270055 Requests info re status of facility on behalf of constituent.
  LUMDINES. House of Rep. 83/06/20. KAMMERER, C. C. Office of Congressional Affairs. 2pp. 19811:050. 24X Fiche: 50-247, 83/07/15, 8307270054.
- DOCKET 50-287 ECONEE NUCLEAR STATION, UNIT 3
- F. Security, medical, emergency & fire protection plans
- B307140164 Advises that objectives & scenario for emergency exercise scheduled for Apr 1983 discussed w/C Jennings.per util B30118 & 0214 ltrs.
  B70HR.J.P. Division of Emergency Preparedness & Materials Safety.
  B3/03/27. TUCKER.H.B. Duke Power Co. 1p. 19523:162. 24X
  Fichs: 50-269.83/03/27,8307140164.
- 8307140244 Refers to 830324 conversation or emergency exercise training requirements for NRC & contract personnel. Training & experience for evaluation team members documented.

  8708R; J.P. Division of Emergency Preparadness & Materials Safety.
  83/03/29. TUCKER: H. B. Duke Power Co. 2pp. 19523:039. 24x
  Fiche: 30-269, 83/03/29, 8307140244.
- 8307140252 Advises that LASL will revisit facilities to gather additing in identifying plant vital areas, per mods to NRC vital area analysis programs. Safeguards info gathered will be protected per IOCFR73. 21.

  LEWIS,R.C. Division of Project & Resident Programs. 83/06/29. TUCKER,H.B. Duke Power Co. 1p. 19523:043. 24X

  Fichs: 50-269,83/06/29,8307140252.
- 830714004B Forwards fees for amends to Licenses DPR-GB, DPR-47, DPR-55 & NPF-9 re location of emergency operating facility & addition of license condition for verifying acceptability of Model D2 steam generator design mod, respectively, RUTHERFORD, M. A. Duke Power Co. 83/07/08, DIGGS, R. M. License Fee Management Branch. 1p. 19514:227. 24X Fiche: 50-000, 83/07/08, 8307140048.
- 8307250300 Requests examption from standby shutfown facility fire protection requirements re source range monitors & steam generator pressure indication, per 830608 rule. Design meets 1007850, App. R. Saction III. 0.3 & III. L. requirements.
  TUCKER, H. B. Duke Power Co. 83/07/15. DENTON. H. R. Office of Nuclear Reactor Regulation, Director. 8TOLZ, J. F. Operating Reactors Branch 4. 2pp. 19701: 350. 24X Fiche: 50-269, 83/07/15.8307250300.
- 8307290101 Releases public version of revised crisis mgt plan for nuclear stations.
  PELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. lp. 19737: 287. 24X Fiche: 50-000, 83/07/19. 8307250101.

- --8307250110 Public version of Rev 9 to crisis mgt plan for nuclear stations. W/830630 ltr. VAUGHN-T.S., TUCKER.H.B. Duke Power Co. 83/06/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 127pp. 19737: 288, 24K Fiche: 50-000, 83/07/19, 8307250101.
- B307250717 Releases public version of revised crisis mgt plan implementing procedures.
  FELTON, J. M. Division of Rules and Records. B3/07/19. Document Management Branch. lp. 19719:314. 24X Fiche:50-000.B3/07/19, B307250717.
- --8307250730 Forwards public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group.

  TUCKER.H.B. Duke Power Co. 83/05/02. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19719:315. 24X Fiche: 50-000.83/07/19.8307250717.
- --8307250744 Public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. b Duke Power Co. 83/03/16. 186pp. 19719:317. 24X Fiche: 30-000, 83/07/19, 8307250717.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B3070700B7 FBAR 1982 update for Oconee Units 1,2 & 3.W/B30630 ltr.
  TUCKER.H.B. Duke Power Co. B3/07/01. DENTON.H.R. Office of
  Nuclear Reactor Regulation, Director. BTOLZ.J.F. Operating Reactors
  Brench 4. 200pp. 1927B: 281. 24X Fiche: 50-269, 83/07/01, 83070700B7.
- P. Operating license stage documents & correspondence
- B307110226 Advises that info re proposed reactor coolant pump trip criteria.per TMI Action Plan Item II.K.3.5.will be provided by end of Jul 1983.
  TUCKER.H.B. Duke Power Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19380:033. 24X Fiche: 50-269,83/06/29,8307110226.
- 8307080362 Forwards eight oversize drawings, inadvertently omitted from util 830624 response to NRC 830523 request for addl info re proposed reracking of spent fuel pool. Aperture cards are available in FDR.

  TUCKER, H. B. Dute Power Co. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 870LZ, J. F. Operating Reactors Branch 4. 2pp. 19347:246. 24X Fiche: 50-269, 83/06/30, 8307080362.
- 8307120403 Forwards suppl to Abnormal Transient Operating Quidelines 76-1123298-00.per 830521 ltr. Suppl provides add1 operator guidance & basis for actions during ATWS & small break LOCA events.

  HHITNEY,D.D. Babcock & Wilcox Operating Plants Owners Group.

  HHITNEY,D.D. Bacramento Municipal Utility District. 83/07/02.

  EISENHUT,D.D. Division of Licensing. 26pp. 19430:229. 24X

  Fiche: 50-287,83/07/02,8307120403.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clamification of surveillance requirements for diesel fuel impurity. Bvc list encl. EISENHVIT.D.Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060327 Generic Ltr 83-27 to all licensess & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:234. 24X Piche: 50-000,83/07/06,8307060327.
- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHMIT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:269. 24X Fiche: 50-000.83/07/08,8307080169.
- 8307140048 Forwards fees for amends to Licenses DPR-38, DPR-47, DPR-55 & NPF-9 re location of amergency operating facility & addition of license condition for verifying acceptability of Model D2 steam generator design moderespectively. RUTHERFORD, N. A. Duke Power Co. 83/07/08. DIGOS, R.M. License Fee Management Branch. 1p. 19514:227. 24X Fiche: 50-000, 83/07/08, 8307140048.

- B307190267 Requests corrections to updated FSAR, consisting of deletion of Tables 3.9-35 through 3.9-38, Table 3.9-44 & Figures 3.9-15 through 3.9-17.
  REAVIS.J. Duke Power Co. B3/07/11. NRC No Detailed Affiliation Given. ip. 19629:275. 24X Fiche: 50-269, 83/07/11, 8307190267.
- 8307250441 Forwards add1 info supplementing 830624 ltr re proposed reracting to expand storage capacity of spent fuel pool to 825 spaces. Results of key structural calculations & comparisons w/allowable values for shear stresses provided. TUCKER.H.B. Duke Power Co. 83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. STDLZ, J.F. Operating Reactors Branch 4. App. 19701:282. 24% Fiche:50-287.83/07/14.8307250441.
- 8307220636 Summary of 830608 appeal meeting w/utils & Bechtel restandby shutdown sys monitors for source range flux & steam generator pressure. Viaugraphs encl.
  BIRKEL.R.A. Licensing Branch 4.
  32pp. 17697:045. 24X Fiche: 50-000.83/07/15.8307220636.
- 8307280304 Forwards proposed response dates to concerns in NRC 830608

  1tr providing approval of proposed wide-range hot leg level/
  reactor vessel head monitoring concept for coolant inventory
  tracking wipumps off.
  TUCKER,H. B. Duke Power Co. 83/07/18. DENTON,H.R. Office of
  Nuclear Reactor Regulation, Director. 8TOLZ, J. F. Operating Reactors
  Branch 4. 6pp. 19726:070. 24% Fiche: 50-269, 83/07/19, 8307260304.
- B307250117 Advises that mods to relief & safety valve discharge piping will be implemented during next refueling outage scheduled for early 1985, per B30121 ltr re NUREO-0737, Item II.D.; "Performance Testing of Reactor Relief & Bafety Valves."

  TUCKER.H. B. Duke Power Co. B3/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. STOLI.J.F. Operating Reactor. Branch 4. lp. 19706:071. 24X Fiche: 50-269, 83/07/19, 8307250117.
- 8307260412 Forwards response to 830509 request for additinfo re natural circulation cooldown procedures & supporting analytical bases. Natural circulation cooldown unlikely undertaking at facility. Procedures & training provide appropriate guidance. TUCKER.H.B. Duke Power Co. 83/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. STOLZ, J. F. Operating Reactors Branch 4. Spp. 19733: ISB. 24X Fiche: 50~269, 83/07/19, 8307260412.
- ---B307260417 "Planned Initiation of Natural Circulation & Natural Circulation Cooldown."

  \* Duke Power Co. 81/12/22, 17pp, 19733:143, 24X
  Fiche: 50-269,83/07/19,8307260412.
- G. Inspection reports, IE Bulletins & correspondence
- B307140336 Informs that liquid samples spiked w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analyzed for tritium. ST-87 & ST-90 content within 60 days.

  LEWIS.R.C. Division of Project & Resident Programs. B3/02/07. TUCKER.H.B. Duke Power Co. 1p. 19525:120. 24X

  Fiche: 50-000.83/02/07.8307140336.
- 8305270612 Ack receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-06, 50-270/83-06 & 50-287/83-06. DANCE, H. C. Division of Project & Resident Programs. 83/04/25. TUCKER, H. B. Duke Power Co. 1p. 18646:248. 24X Fiche: 50-269,83/04/25,8305270612.
- --8305270627 Responds to NRC 830307 ltr re violations noted in IE Insp. Repts 50-269/83-06,50-270/83-06 & 50-287/83-06. Corrective actions: cited door locked closed immediately after being found open. round open.
  TUCKER.H.B. Duke Power Co. 83/04/06. O'REILLY, J.P. Region 2,
  Office of Director. 2pp. 18646:249. 24X Fiche: 50-269, 83/04/25,
  8305270612.
- --8305270630 Forwards IE Insp Rept 50-269/83-06.50-270/83-06 & 50-287/83-06 on 830111-0210 & notice of violation. DANCE, H. C. Division of Project & Resident Programs. 83/03/07, TUCKER, H. B. Duka Power Co. 2pp. 18646:251, 24X Fiche: 50-269, 83/04/25, 8305270612.
- --8305270636 Notice of violation from insp on 830111-0210.

  \* Region 2, Office of Director. 83/03/07. 1p. 18646:253, 24X Fiche: 50-269,83/04/25,8305270612.
- --B305270643 IE Insp Repts 50-269/B3-06, 50-270/B3-06 & 50-287/B3-06 on 830111-0210. Noncompliance noted: unescorted entrance to high 83011-0210. Noncomparance notes, onests, and a sector addation area.

  BRYANT, J., FALCONER, D. Region 2, Office of Director.

  IGNATONIS, A. J. Division of Project & Resident Programs. 83/03/04, 10pp. 18646: 254. 24X Fiche: 50-267, 83/04/25, 8305270612.

- 8307140067 Responds to IE Bulletin 83-03 re check valve failures in diesel generator water cooling sys. Valve CCW-284 in standby shutdown facility only affected valve per Item 4. Item 5 response will be submitted within 90 days of checkout. TUCKER.H.B. Duke Power Co. 83/06/20. 0'REILLY.J.P. Region 2. Office of Director. 4pp. 19514:097. 24X Fiche: 50-269.83/06/20. 8307140067.
- 8307140026 Forwards IE Insp Repts 50-269/83-15, 50-270/83-15 & 50-287/83-15 on 830411-0510. No moncompliance noted. DANCE: H. C. Division of Project & Resident Programs. 83/06/22. TUCKER. H. B. Du's Power Co. 2pp. 17514: 196. 24X Fichs: 50-269, 83/06/22, 8307140026.
- --B307140030 IE Insp Repts 50-269/83-15, 50-270/83-15 & 50-287/83-15 on 830411-0510. No noncompliance noted. Major areas inspected: operations, maint activities, surveillance & LER review. BRYANT, J., FALCONER, D., Region 2. Office of Director. BROWNLEE, V. L. Division of Project & Resident Programs. 83/06/21, 4pp. 19514: 198. 24X Fiche: 50-269, 83/06/22, 8307140026.
- B307060275 Responds to B30602 itr re violations & proposed imposition of civil penalties noted in IE Insp Repts 30-269/83-ii. 50-270/83-ii & 50-287/83-ii. Corrective action:procedures per TMI Item I. C. & reviewed. TUCKER.H. B. Duke Power Co. B3/07/01. Director's Office, Office of Inspection and Enforcement. 21pp. 19238:352. 24% Fiche: 50-269,83/07/01.8307060875.
- 8307130263 Forwards revised request for relief from ASME Section XI inservice insp requirements (hydrostatic) supplementing B21004 request. No add1 license fees provided. TUCKER.H.B. Duke Power Co. B3/07/06. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. STOLZ.J.F. Operating Reactors Branch 4. 2pp. 19508:246. 24X Fiche: 50-269, 83/07/06.8307130263.
- 8306270401 IE Info Notice 83-46. "Common Hode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svr list encl.

  JCRDAN.E. L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24x Fiche: 50-000.83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19863:183. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Release Radioactive I-125 & I-131 in Excess of NRC Limits." By: Regions Court and the control of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000.83/07/14.8306270406.
- S. Reportable occurrences, LERs & related correspondence
- B307129604 RD: on B30509 & 12.fire barrier smoke exhaust penetrations 3-K-3-2.3-C-5-3 & 4 found w/o seal & 3-C-5-3 did not have fusible damper, respectively. Caused by inadequate info & insufficient guidance provided by design angineering. TUCKER.H.D. Duke Power Co. 83/06/29. 0'REILLY.J.P. Region 2, Office of Director. 3pp. 19433:009. 24X Fiche: 50-287.83/06/29, B307129604.
- B307220511 LER B3-007/03L-0: on B30525, while welding on hanger, fire started in cable providing control power to valve 38V-90 which controls valve 3HP-5. Breaker opened to repair cable. Cause under investigation. Fire extinguished. J/8307098 tr. QUILL. P.F.. TUCKER. H. B. Duke Power Co. 83/07/08. O'REILLY, J. P. Region 2. Defice of Director. 4pp. 19685: 138. 24X Fiche: 50-287,83/07/08,8307220511.
- DOCKET 50-208 REED COLLEGE RESEARCH REACTOR V. Operator Examinations
- 8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Qualifications Statement Licensee." Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19363:138. 24X Fichs:50-000,83/07/11,8307080427.

- DOCKET 50-287 THREE MILE ISLAND NUCLEAR STATION, UNIT I F. Security, medical, emergency & fire protection plans
- 8307210049 Procedure 1000-PNL-40101, "GPU Nuclear Corp Radiation Protection Plan." W/830705 ltr. HILDEBRANCH, J.; HUKILL-H.D. General Public Utilities - GPU Service Corp. B2/11/05 MURLEY, T. A. Region 1; Office of Director. 16pp. 1966B: 283. 24X Fiche: 50-289, 82/11/05, 8307210049.
- B307110595 Releases public version of revised emergency plan implementing procedures. FELION.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. Ip. 19391:112. 24X Fiche: 50-289, 83/06/24, 8307110595.
- --83071t0999 Public version of Rev 2 to Emergency Plan Implementing Procedure 1004.32, "Activation of Annex to Nearsite Emergency Operations Facility."

  STANGE, S. J. General Public Utilities GPU Service Corp. 83/06/02
- 6307120051 Releases public version of rev to emergency plan. FELTON, J. H. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19434:142. 24X Fiche: 50-289, 83/06/24, 8307120051.
- --8307120052 Public Version of Rev 4 to emergency plan.W/830509 ltr. HUKILL.H. D. General Public Utilities - GPU Service Corp. 83/04/21. 314pp. 19434:143. 24% Fiche: 50-289,83/06/24, 8307120051.
- 8307120069 Releases public version of rev to emergency plan implementing procedure. FELYON, J. M. Division of Rules and Records. 83/06/24. Document Management Branch. ip. 19435: 248. 24X Fiche: 50-289, 83/06/24, 8307120069.
- --8307120073 Public version of Rev 4 to Emergency Plan Implementing Procedure 1004.20 re personnel/vahicle monitoring & decontamination. W/830602 ltr.
  STANOE.S.J. General Public Utilities GPU Service Corp.
  83/06/02. ilpp. 19435:249. 24X Fiche: 50-289,83/06/24.8307120069.
- 8307150323 Informs of plans to modify once through steam generator tube rupture guidelines & emergency procedures.per 830627 telcon. Mods will be completed by 830801 Limits correspond to site emergency declaration limits.

  HUKILL.H.D. General Public Utilities GPU Service Corp. 83/07/DB. 870LZ.J.F. Operating Reactors Branch 4. tp. 19538:120. 24X Fiche: 50-289, 83/07/08, 8307/50323.
- 8307180295 Notification of B30719 maeting woutil & Rockbestos in Bethesda, MD to discuss proposed fireproof cable development & test program. VAN VLIET. J. Operating Reactors Branch 4. 83/07/11. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 19566: 156. 24x Fiche: 50-289, 93/07/11, B307180295.
- E307180098 Forwards clarification to 830418 integrated implementation schedule for completing NUREG-0737. Suppl 1 items research response capabilities, per Generic Ltr 82-33. [tems not dependent on fuel cyrle identified.

  HUKILL, H. D. General Public Utilities GPU Service Corp. 83/07/12. EISENHUT, D. G. Division of Licensing. 2pp. 19557:001. 24X
- 8307190149 Provides update on amergency operations facility const schedule per Generic Ltr 92-33: Facility should be ready for occupancy by 831001 & fully functional by 831101. HUKIKLIHD. General Public Utilities - GPU Service Corp. 83/07/14. STOLT.J.F. Operating Reactors Branch 4. 1p. 19634:196. 24X Fiche: 30-289, 83/07/14. 8307190149.
- B307270031 Forwards Rev 18 to security plan. Rev withheld (ref 10CFR73\_21).

  HUKILL,H.D. General Public Utilities ~ OPU Service Corp. B3/07/20
  DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19749; 360. 24X Fiche: 50-289, 83/07/20, B307270031.
- G. Adjudicatory correspondence
- B305100326 Comments on IE Info Notice B3-15 re NRC response to discovery of contractor falsification of preemployment screening records for security guards at nuclear power plants. Response inadequate to protect safety of public AAMDDT,M.M. Aamodts, The. B3/05/05. JRBANN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 2pp 8379:001. 24X Fiche: 50-289, 83/05/06. 8305100326

- 8307050071 Petition of J Lee B Molholt & N Aamodt to intervene in hearing on steam generator tube repair.

  LEE.J. MOLHOLT, B. Affiliation Unknown. AAMODT, N. Aamodts, The. 83/06/28. Commissioners. 1p. 19193:183, 24X

  Fiche: 50-289, 83/06/28, 8307050071.
- 8307050109 Order rescheduling B30720 oral argument for 830803 re three motions to reopen record on mgt issues. NRC memorandum on progress of revalidation of position due 830727.

  BHQEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/06/29, 2pp. 19199: 354. 24X Fiche: 50-289, 83/06/29, 8307050109.
- B307050123 Forwards documents potentially relevant & mati to matters under adjudication. Documents include info on reactor coolant pump trip, PCRV corrosion & emergency feedwater flow devices Controlotron. Svc list encl.
  BAXTER.J.A. Shaw, Pittman, Potts & Trowbridge. BAXTER.J.A. Metropolitan Edison Co. B3/06/27. CHILK.S.J. Office of the Secretary of the Commission. IBpp. 19220:221. 24X
- 8307050271 Response to ALAB-729 Condition 5 proposing long-term solution for steam generator bypass logic problem.
  Certificate of Svc encl.
  BAXIER,T.A. Metropolitan Edison Co. BAXTER,D.C. Shaw, Pittman, Patts & Troubridge. 83/06/29, 14pp. 19199:293. 24X
- B307070212 Urges full hearing re adequacy & safety of steam generator repairs. Proposed NRC determination that repairs do not involve significant hazards considerations, contrary to Congressional intent.

  DAVIS.F. D. Affiliation Unknown. B3/06/29. Docketing & Services Branch. 1p. 19269: 321. 24X Fiche: 50-289, 83/06/29, 8307070212.
- 8307050147 Request parties identify documents partinent to NRC review of documentation from GPU vs B&W litigation.

  WAGNER,M.E. Hearing Branch 4. 83706/30. Office of the Executive Legal Director. ip. 19220:162. 24X Fiche:50-289,83/06/30.
- B307050157 Memorandum & order denying MM Aamodt 830621 motions for provision of info & to lift order of confidentiality of reopened hearing. Request essentially discovery request & premature since no ruling issued on reopening record.

  BHQEMAKER.C.J. Atomic Safety and Licensing Appeal Panel. 83/06/30. Aamodts, The. 3pp. 19199:168. 24% Fiche:50-289,83/06/30.
- 8307050185 Comments on 830531 FR notice re amend request to change Tech Sper & approval of steam generator repair. Release of SERs on amend prior to final decision on safety hazards consideration requested. CERUSKY, T.M. Pennsylvania, Commonwealth of, 83/06/30. Docketing & Services Branch. 2pp. 19199:309. 24X Fiche:50~289,83/06/30,8307050185.
- B307060190 Comments on ASLAB B30616 order re NRC awareness of falsified leak rates, separation of individual performance from mgt competence & notification to Commission of mgt changes. Certificate of Svc enci.
  BLAZEY, D. R. Pennsylvania, Commonwealth of, 83/06/30. 7pp. 19250: 244. 24X Fiche: 50-289, 83/06/30. 8307060190.
- 8307050254 Advises that Commissioner Gilinsky 830629 memo to EDO being served on parties, per Commissioner Gilinsky request.
  STUCKY, S. W. Docketing & Services Branch. 83/07/01. Office of the Executive Legal Director. 1p. (9198: 358. 24% Fiche: 50-289, 83/07/01, 8307050254.
- --B307050257 Requests info on why NRC Mar or Apr 1980 beliefs that leak rate tests falsified before 790328 accident not communicated to ASCB or Commission. GILINSKY, V. Commissioners. B3/06/29. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 19198:359. 24X Fiche: 50-289, 83/07/01, 8307050254.
- 6307060201 Motion to reschedule oral argument on motions to reopen record to 630810. Lead counsel on mgt & cheating issues has long standing vacation plans. Certificate of Svc encl. GDLDBERG, J. R. Hearing Branch 2. 83/07/01. Atomic Safety and Licensing Appeal Panel. Bpp. 19250:205. 24X Fiche: 50-287, 83/07/01. 8307060201.
- 8307060206 Comments in response to ASLAB 830616 order scheduling oral argument on three pending motions to reopen record. Certificate of 8vc encl. GDLDBERG, J. R. Hearing Branch 2. 83/07/01. 13pp. 19249: 299. E4X Fiche: 50-289, 83/07/01, 8307050206

- 8307060208 Response to ASLAB 830616 order re bearing of new info on three motions to reopen record. Certificate of Svc enct AMMODT,M.M. AAMMODT,M.D. Aamodts, The. 83/07/01. 33pp. 19249:314. 24X Fiche: 50-289, 83/07/01, 8307060208
- 8307060393 Add1 comments on motions to reopen record Supports
  Commission decision not to separate individuals from
  organization to decide mgt competence Statement of T Martin
  at Commission 830924 meeting relevant W.Certificate of Svc.
  DCROSHOW.J. Three Mile Island Alert 83/07/01. Atomic Safety and
  Licensing Appeal Panel. 5pp. 19236:064. 24X Fiche.50-289,83/07/01.
- 8307110300 Comments on ASLAB 830616 order re-motions to reopen record on issues of mgt competence & integrity. NRC knowledge of leak rate testing falsification & temporary reassignment of individuals.

  WEISB.E.R. Union of Concerned Scientists. 83/07/01. 6pp. 19375:001. 24X Fiche: 50-289:83/07/01.8307110300.
- B307130228 Interim comments on QPU vs B&W trial record Evidence dramatically illustrates util unfit to operate TMI-1 & error in ABL8 finding that util mgt competent. Util incapable of learning from mistakes.

  DOROSHOW, J. Three Mile Island Alert. B3/07/01. 64pp. 19465:260.
  24X Fiche: 30-289, 83/07/01, 8307130228.
- 8307080475 Order granting NRC motion to change date of oral argument on pending motions to reopen record scheduled for 830803.

  Gral argument rescheduled for 830728. NRC memorandum on progress of revalidation due 830721.

  SHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 83/07/06.

  Office of the Executive Legal Director. 2pp. 19346:318. 24x

  Fichs: 50-289, 83/07/06, 8307080475.
- 8307110050 Notice of rescheduling 830803 oral argument to 830728 repending motions to reopen record in mgt phase.

  SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/07/06.

  1p. 19375:020. 24X Fiche: 50-289, 83/07/06, 8307110050.
- 8307190329 Stipulation re employment of personnel involved in cheating incident.
  BLAKE,E.L. General Public Utilities GPU Service Corp. BLAZEY,D.R. Pennsylvania, Commonwealth of,. BLAKE,E.L. Metropolitan Edison Co. 83/07/06. 3pp. 19538:254. 24X Fiche: 90-289,83/07/06.8307150329.
- --8307150335 Motion to withdraw romaining three exceptions, constituting entire withdrawal of Commonwealth of PA appeal. Certificate of Svc encl.
  BLAZEY, D. R. Pennsylvania, Commonwealth of, 83/07/06. Atomic Safety and Licensing Appeal Panel. 4pp. 17938:257. 24X Fiche: 50-289, 83/07/06, 8307150327.
- 8307130204 Advises that independent in-depth studies warranted re steam generator tube repair. Incompetent ASLB members should be removed & truth re TMI revealed. HERMAN.A. A. Affiliation Unknown. 83/07/08. PALLADIND.N. J. Commissioners. Ip. 19474:345. 24X Fiche:50-289,83/07/08, 8307130204.
- B307140318 Forwards list of OPU vs B&W trial exhibits containing depositions of util witnesses. WURTZ,M.E. Davis, Polk & Wardwell. 83/07/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 70pp. 19823:237. 24X Fichs:30-289,83/07/08.8307140318.
- B307130069 Order extending time until 830812 for Commission to act to review ALAB-729.

  CHILK, B. J. Office of the Secretary of the Commission. B3/07/11.

  Commissioners. 1p. 19465:360. 24X Fiche: 50-287, 83/07/11.

  B307130069.
- 8307140449 Forwards WJ Dircks 830629 memo to Commission re reportability of licensee rept on Hartman allegations. Investigation into itr-designated Individual VV & Miller incident complete NRC views submitted to Commission. GULDBERG, J.R. Hearing Branch Z. 83/07/12. EDLEB, G. J., KOHL, C.N., BUCK, J.H. Atomic Safety and Licensing Appeal Panel. 9pp. 19320:345. 24X Fiche: 50-289, 83/07/12, 8307140449.
- B307140441 Amended petition of J Lee.B Molholt & N Aamodt for leave to intervene re steam generator tube repair.Extensive damage detected in tubes, Mathod of repair novel & unproven.

  AAMODT.N.O. Aamodts, The. B3/07/13. Commissioners. Spp. 19320:334. 24X Fiche: 50-287, 83/07/13, 8307140441.
- B307140453 Forwards articles on scientists testifying for hire & discovery of isotopes near site.

  LEE, U. Affiliation Unknown, B3/07/13, GOTCHY NRC No Detailed Affiliation Given. 2pp. 19521:248, 24X Fiche: 50-289,83/07/13, B307140453.

- 8307190274 Notifies of VR Marding employment at law firm Harding will not participate in any case currently pending before NRC.

  BAXTER.T. A. Shaw. Pittman. Potts & Trowbridge. BAXTER.T. A.

  Metropolitan Edison Co. B3/07/13. PALLADING.N.J., GILINEKY.V.,

  ASSELSTINE.J.K. Commissioners ip. 19632:073. 24X

  Fiche: 30-289,83/07/13,8307190274.
- ~-B307190278 Notifies of employment at law firm.VR Harding will not participate in any case pending before NRC Svc list encl.

  HARDING, V.R. Shaw, Pittman, Potts & Trowbridge 83/07/13.

  PALLADING, V.J. GILINSKY, V., ASSELBTING, J.K. Commissioners. 5pp 19632 074. 24x Fiche: 50-289, 83/07/13, 8307190274.
- B307150306 Advises that JR Goldberg will represent NRC at B30728 oral argument on three pending motions to reopen mpt record. GDLDBERG, J. R. Hearing Branch 2. 83/07/14. SHOEMAKER.C. J. Atomic Bafety and Licensing Appeal Panel. 1p. 19532:311. 24X Fiche: 50-289, 83/07/14, 8307190306.
- B307190077 Notifies that author will present argument for licensee at B30728 oral argument re pending motions to reopen mgt capability phase of proceeding per ASLAB 830629 memorandum & order Svc list encl.

  BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge. BLAKE, E. L. Metropolitan Edison Co. B3/07/14. SHDEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 3pp 19635:109. 24X Fiche: 30-289, 83/07/14, 8307190077.
- B307190198 Discusses concerns expressed in B30602 ltr re cheating on aperator qualifying exam safety of TMI-2 cleanup & operator competence & integrity at TMI. Final decision on restart will not be made until outstanding concerns addressed. PALLADINO.N. J. Commissioners. B3707714. THORNBURGH.R. Pennsylvania. Commonwealth of. 2pp. 19630:109. 24X Fiche: 50-289, 83/07/14, 8307190198.
- B307180220 Order referring TMJ Alert B30519 request for hearing on util 830509 application for amend to CL re steam generator repairs, to ASLB, for appropriate action. CHILK, B. J. Office of the Secretary of the Commission. B3/07/15. 2pp. 19955, 272. 24X Fiche: 50-289, 83/07/15, 8307180220.
- B307190003 Forwards WJ Dircks B30719 memo to Commission re NRC proposals to implement NRC B30628 guidance on NRC completion of TMI-1 restart review.

  GLDBERG.J.R. Hearing Branch 2. 83/07/15 EDLES.G.J., KUHL.C.N., BUCK.J.H. Atomic Safety and Licensing Appsal Panel. 6pp. 19652:006. 24X Fiche: 50-289, 83/07/15, 8307190003.
- B307190163 Order extending time until B30725 for Commission to act to review ALAB-724.

  CHILK, S. J. Office of the Secretary of the Commission. B3/07/15.

  Commissioners. 1p. 19636: 260. 24X Fiche: 50-289: B3/07/15, B307190163.
- B307200113 Notice of ASLB constitution BJ Wolfe, chairman & DL Hetrick & JC Lamb, members.

  COTTER, B.P. Atomic Safety and Licensing Board Panel. 83/07/15

  2pp. 19647:066. 24X Fiche: 50-289,83/07/15,8307200113.
- B307200097 Response to TMI Alert supplemented request for adjudicatory hearing on steam generator repair amend TMI Alert has mot interest requirements & should be admitted if one litigable contention submitted on time. Certificate of Svc encl. WAGNER.M.E. Hearing Branch 4. 83/07/18. Atomic Safety and Licensing Board Panel. 6pp. 19647:129. 24X Fiche: 50-289.83/07/18, B307200097.
- 8307200215 Comments on Commission 830A28 memorandum & related documents. Licensee retains confidence in capability & integrity of present GPU Nuclear organization & personnel to operate & support TMI. Svc list encl.
  BLAKE.E.L. Shaw, Pittman, Potts & Trowbridge. BLAKE, E.L. Metropolitan Edison Co. 83/07/18, PALLADINO, N. J., GILINSKY, V., ROBERYS, T. M. Commissioners. 69pp. 19631:172. 24X
  Fiche: 50-289, 83/07/18, 8307200215.
- 8307210280 Order reconfirming 830728 oral argument in Bethesda, MD on motions to respen record re mgt issues. SHDEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/07/19. 2pp. 19664: 284. 24% Fiche: 50-289, 83/07/19, 8307210280.
- B307250263 Responds to B30629 memo posing question on NRC action re util falsification of leak rate tests. Fact that Hartman allegations referred to DOJ was not withheld from public. DIRCKS, W.J. Office of the Executive Director for Operations. 83/07/19. GILINSKY.V. Commissioners. 3pp. 19705:279. 24X Fiche: 50-289, 83/07/19, 8307250263.

- 8307220370 Response opposing J Lee.B Molholt & N Aamodt 830628 petition for adjudicatory hearing on steam generator repair amend. Interest requirement not met. Certificate of Svc encl.

  MAGNER, M. E. Hearing Branch 4: 83/07/20. Atomic Safety and Licensing Board Panel. 12pp. 19475:237. 24X Fiche: 50-289, 83/07/20, 8307220370.
- 8307250327 Hembrandum on status of NRC TMI-1 restart review.per ASLAB 830616 & 0706 orders. Completion of NRC review of open issues & formulation of NRC position on mgt integrity realistically appear to be many months away.

  GDLDBERO, J. R. Hearing Branch 2. 83/07/21. 8pp. 19703:023. 24X Fiche: 30-287, 83/07/21, 8307250327.
- -8307250334 Responds to request for info re nature & current status of NRC review of GPU vs B&W lawsuit documents. As of B30720, screening review approx 75% complete. RUSELL.H.T. NRC No Detailed Affiliation Given. 83/07/20. GOLDBERG.J. Hearing Branch 2. lp. 19703:031. 24% Fiche 50-289,83/07/21,8307250327.
- -0307250344 Defines scope, purpose & approach re NRR review of GPU vs B&W lawsuit documents. Review comprises audit review similar to normal NRC safety review. Completion by Sept 1983 should be normal NRC safety review. Completion by Sept 1983 should be scheduled.

  DENTON, H. R. Office of Nuclear Reactor Regulation, Director, B3/07/11. EISENBUT, D. O. Division of Licensing. SPEIS, T. P. Division of Safety Technology. VOLLMER, R. H. Division of Engineering. 4pp. 19703.032. 24X Fiche: 30-289, 83/07/21, 8307250327.
- --8307230352 Staff requirements memo re 830521 discussion of guidance to NRC on restart pending immediate effectiveness decision on restart. Certificate of Svc encl.
  CHILK.S.J. Office of the Secretary of the Commission. 83/06/28.
  DIRCKS.N.J. Office of the Executive Director for Operations. 7pp. 19703:036. 24X Fiche:50-289.83/07/21.8307230327.
- 8307250362 Forwards UCS comments on util rept on investigations of Ltr-Designated Individuals VV & O incident.Util investigation is transparent effort to esculpate util & employees rather than investigate facts.
  WEISS.E.R. Union of Concerned Scientists. 83/07/21, PALLADIND, N. J., GILINSKY, V., RUBERTS, T. M. Commissioners. 1p. 19705: 163. 24x fiche: 50-289, 83/07/21, 8307250362.
- --8307250366 Forwards comments on util rept on investigation of Ltr-Designated Individuals VV & O incident.
  WEIGS,E.R. Union of Concerned Scientists. 83/07/21. EDLES,G.J., BUCK,J.H., KDH.,C.N. Atomic Safety and Licensing Appeal Panel. ip. 19703:164. 24x Ficha:50-289,83/07/21,8307250362.
- --8307250368 Comments on util rept on investigation of Ltr-Designated Individuals VV & O Incident Rept is transparent effort to exculpate util w/o qualities of independence.crifical thought skepticism & rigor.Certificate of Svc encl. WEISS.E.R. Union of Concerned Scientists. WEISB.E.R. Harmon & Weiss. 83/07/21. 34pp. 19705:165. 24X Fiche:50-289,83/07/21,8307250362.
- 8307290127 Opposes proposal to bifurcate license amend to steam generator tubes. TM1 Alort requested hearing before plant operation.
  - operation.
    DORGSHON,U. Three Mile Island Alert. 83/07/21. PALLADINO,N.J.,
    QILINSKY,V., RODERYS,T.M. Commissioners. 2pp. 19822:140. 24x
    Fiche: 50-289,83/07/21,8307290127.
- 8307250347 Statement of Commission CLI-83-20, authorizing issuance of notice of violation & proposed imposition of civil penalties in amount of \$140,000 re failure to implement retraining program properly & math false statements.

  CHILK.S. J. Office of the Secretary of the Commission. 83/07/22, 12pg. 19703:259. 24X Fiche 50-289, 83/07/22, 8307250347.
- B307260264 Reply to TMI Alert. J Lee. B Molholt & N Aamodt B30628 & 0713 Joint petition & amended petition to intervene. Util does not oppose intervention if one allowable contention submitted. Cartificate of Svc encl.

  IROWERIBGE. G. F. Metropolitan Edison Co. TROWERIBGE. G. F. Shaw, Pittman. Potts & Troubridge. 83/07/22. Atomic Safety and Licensing Board Panel. App. 19731: 348. 24X Fiche: 50-289, 83/07/22. 8307260264.
- B307270025 Forwards NRC B30722 ltr to util & notice of violation & proposed imposition of civil genalty.
  OBLOBERG.J.R. Hearing Branch 2. B3/07/25 EDLES.O.J. KOHL.C.N., BUCK.J.H. Atomic Safety and Licensing Appeal Panel. Bpp. 19749:351. 24X Fiche: 50-289, 63/07/25, 8307270025.
- B307270128 Order extending time until B30729 for Commission to act to review ALAG-724.
  CHILK,S.J. Office of the Secretary of the Commission. B3/07/25, Commissioners. 1p. 19749:316. 24X Fiche.50-289.83/07/25, B307270128.

- 8307270135 Advises that ER Weiss will not appear at 830628 oral argument due to real estate transactions. UCS will submit case on fillings.

  WEISS.E.R. Harmon & Weiss. WEISS.E.R. Union of Concerned Scientists. 83/07/26. EDLES.G.J., BUCK, J.H., KOHL, C.M. Atom Safety and Licensing Board Panel. 1p. 19749:317. 24X Fiche: 50-289, 83/07/26, 8307270135. Atomic
- 8307270239 Response to Commonwealth of PA 830706 motion to withdraw remaining exceptions to ASLB 820727 partial initial decision on mgt issues NRC does not object to motions Cartificate of SVC encl.

  HANNER, M. E. Hearing Branch 4. B3/07/26. Atomic Safety and
  Licensing Appeal Panel. 6pp. 19749: 326. 24X Fiche: 50-289, 83/07/26,
  8307270239.
- 8307290130 Forwards "Responses to Recommendations of Basic Energy Technology Assoc, Inc Bet Forth in Rept Dtd Feb 28, 1983."
  BLAKE, E. L. Shaw, Pittman, Potts & Trombridge. BLAKE, E. L. Metropolitan Edison Co. 83/07/26. EDLES, G. J., BUCK, J. H., KONL, Atomic Safety and Licensing Appeal Panel. 45pp. 19822:089. 24 Fiche: 50-289, 83/07/26, 8307290130. . KOHL.C.N.
- 8307290138 Response to NRC intervention requirements for adjudicatory hearing on steam generator repair amend. Petitioner has standing due to close proximity of residence to plant. Certificate of Svc encl.

  LEE, J. Affiliation Unknown. 83/07/26. Atomic Safety and Licensing Board Panel. 3pp. 19822:003. 24X Fiche: 50-289,83/07/26,8307270138.
- 8307280155 Comments on EDD 830715 memo re NRC proposals to implement Commission 830628 guidance on NRC completion of restart review. Restart decision need not await completion of NRC investigations & evaluations. Certificate of Svc encl. TROUBERIDGE, G. F. Metropolitan Edison Co. TROUBERIDGE, G.F. Shaw, Pittman, Potts & Troubridge. 83/07/27. 10pp. 19792:039. 24X Fiche: 50-289, 83/07/27, 8307280155.
- B3072900il Forwards NRC B30AO3 response to TMI Alert request for adjudicatory hearing on steam generator repair amend.

  MAGNER.M.E. Hearing Branch 4. B3/07/28. WOLFE.B.J., HETRICK.D.L., LAMB.J.C. Atomic Safety and Licensing Board Panel. 12pp. 19821:078. 24X Fiche: 50-289. B3/07/28, B307290011.
- H. General correspondence
- 8307060321 Forwards responses to 830424 questions re TMI-1 steam generator repair program. Current allowable steam generator tube leak rate remains 1 gpm combined leakage from all tubes of both steam generators.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
  83/06/17. HOSSLER.D.E. Affiliation Unknown. 8pp. 19299:268. 24X Fiche: 50-289,83/06/17,8307060321.
- 8307050075 Expresses outrage at NRC proposal to waive hearing on GL amend re steam generator repair, based on no signifiant hazards consideration.

  DAVIS.B. Affiliation Unknown. B3/04/27. Office of the Secretary of the Commission. 3pp. 19220: O20. 24X Fiche: 50-289,83/04/27, B307050075.
- 8307060200 Requests public hearings on method of steam tube repairs & future reliability of repairs.

  HURST, J. B., HOSBLERD, E. Affiliation Unknown. 83/06/30, Office of the Secretary of the Commission. 2pp. 19250:229, 24X Fiche: 50-289, 83/06/30, 8307040200.
- B307210252 Requests encl J Lee ltr to Commission re steam generator tubes be placed on svc list.
  LEE, J. Affiliation Unknown. B3/07/20. GILINSKY, V. Commissioners.
  1p. 19664:140. 24X Fiche: 50-287, 83/07/20, 8307210252.
- --8307210254 Poses questions re steam generator tubes, primary coolant break & thiosulphate in primary coolant sys. LEC.J. Affiliation Unknown. 83/07/20. Commissioners. App. 19664:141. 24X Fiche: 50-287, 83/07/20, 8307210252.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307270316 Forwards Update 2 to FSAR. Dath of affirmation encl.
  HUXILL, H D. General Public Utilities GPU Service Corp. 83/07/18.
  DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director. 2pp.
  19780: 045. 24X Fiche: 50-289, 83/07/18, 8307270316.
- --B307270318 Update 2 to FBAR.

  \* General Public Utilities -- GPU Service Corp. 83/07/31. 548pp. 19780: 047. 24% Fiche: 50-289, 83/07/18, 8307270316.

- P. Operating license stage documents & correspondence
- 8307210049 Procedure 1000-PNL-40101, "GPU Nuclear Corp Radiation Protection Plan." #/830705 ltr. HILDEBRANCH.J., HUXILL.H.D. General Public Utilities - GPU Service Cdrp. 82/11/05, MURLEY.T.A. Region 1, Office of Director. 16pp. 19468:283. 24X Fiche:50-289,82/11/05,8307210049.
- B307110616 Monthly notice of amends to QLs involving NSHC issued since B30523. CLARK.R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fiche: 50-000:83/06/14.8307110616.
- 8307070553 Staff requirements memo on 830615 brising in Washington, DC re NRC certification in restart proceeding Final no significant hazards consideration determination will be proposed for concurrence by end of June, CHILKS. J. Office of the Secretary of the Commission. 83/06/22. DIRCKS. W. J. Office of the Executive Director for Operations. 1p. 19362: 226. 24X Fiche: 50-289. 83/06/22, 8307070553.
- B307030145 Forwards Tech Spec Change Request 128 requesting amend to App A to License DPR-50 re effluent discharge monitor relocation.

  HUKILLH.D. General Public Utilities GPU Service Corp. 83/06/24, BTOLZ Operating Reactors Branch 4. 1p. 19220:163. 24X Fiche: 50-289, 83/06/24, 8307050145.
- --8307050154 Application for Tech Bpec Change Request 18 requesting amend to App A to License DPR-50 re effluent discharge monitor relocation.
  HUKILL-H D. General Public Utilities -- GPU Service Corp.
  83/06/24. 2pp. 19220:164. 24X Fiche: 50-289,83/06/24,8307050145.
- --8307050161 Proposed Tech Spec re effluent discharge monitoring, # General Public Utilities - GPU Service Corp. 83/06/24, 7pp. 19220:166. 24X Fiche: 50-289, 83/06/24, 8307050145.
- 8307140525 Summary of 830518 meeting w/util in Bethesda, MD re results of leak & eddy current tests on repaired steam generator & PORV & pressurizer corrosion. Viewgraphs encl.

  SILVER, H. Operating Reactors Assessment Branch. 83/06/27.

  Operating Reactors Assessment Branch. 3pp. 19526:262. 24X

  Fiche: 50-289, 83/06/27, 8307140525.
- 8306270397 Generic Ltr 83-26 to all applicants for ULs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D. 9. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19370:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307270022 Forwards request for add1 info needed for EG&G to review util 82:203 response to NUREG-0737, Item II.D.1 re relief & safety valve testing. Jul 1983 meeting proposed to receive & discuss response since item is to be resolved by 830830.
  8TOLZIJ.F. Operating Reactors Branch 4. 63/07/05. HUKILL, H.D. General Public Utilities GPU Service Corp. Spp. 19811:234. 24X Fiche: 50-289, 83/07/05, 8307270022.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in ST6. Evc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19649: 254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307190310 Proposes meeting in Parsippany, NJ to train NRC members in use of GPU computerized record sys in order to access GPU vs R&W lawsvit documents from Bethesda, MD ofcs. Info generated would be placed in PDR. DENTON, H. R. Office of Nuclear Reactor Regulation, Director, B3/07/06. ARNOLD, R. C. General Public Utilities GPU Service Corp. 1p. 19656: 174, 24X Fiche: 50-287, 83/07/06, 8307190310.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events 8vc list encl. EISENHUT, D. G. Division of Licensing, 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669: 267. 24%. Fiche: 50-000, 83/07/08, 8307080169.
- 8307150323 Informs of plans to modify once through steam generator tube rupture guidelines & emergency procedures, per 830629 telcon. Mods will be completed by 830801. Limits correspond to site emergency declaration limits.

  HUXILL, H. D. General Public Utilities GPU Service Corp. 83/07/08.

  STGLZ, J. F. Operating Reactors Branch 4. 1p. 19538:120. 24X

  Fiche: 50-289, 83/07/08, 8307150323.

- 8307290012 Forwards evaluation of containment purge & vent valve operability & proposed Tech Specs re reactor coolant activity including lodine spiking. Analysis of ECCS back pressure requested by 830720.
  8TOL2, J. F. Operating Reactors Branch 4. 83/07/08. HUKILL, H. D. General Public Utilities GPU Service Corp. 4pp. 19826:341. 24X Fiche: 50-289, 83/07/08, 8307290012.
- --8307270014 Bafety evaluation of demonstration of containment purge & vent valve operability (8-24). Util demonstrated ability of 48-inch purge & vent valves to close against containment pressure buildup in event of LOGA. Modified 818 encl. # Operating Reactors Branch 4. 83/07/08, 8pp. 19826:347. 24% Fiche: 30-289, 83/07/08, 8307290012.
- 8307150008 Summarizes 830630 mgt meeting w/util in King of Prussia,PA
  re recent changes in util organizational structure.8vc list,
  list of attendees & viewgraphs encl.
  MURLEY,T.E. Region i, Office of Director. B3/07/11. ARNOLD,R.C.
  Oeneral Public Utilities GPU Service Corp. 27pp. 19548:208. 24X
  Fiche: 50-289,83/07/11,8307150008.
- B307180294 Notification of B30713 meeting w/util in Bethesda. MD to discuss steam generator tube repair amend request. SILVER.H. Operating Reactors Assessment Branch. B3/07/11. STOLZ.J.F. Operating Reactors Branch 4. 2pp. 19566:159. 24X Fiche: 50-289, 83/07/11, 8307180294.
- 8307190226 Forwards application to 4mend License DFR-50, consisting of Tech Spec Change Request 126 changing surveillance stds, operational review, records & independent onsite safety review group.

  HUKILL,H.D. General Public Utilities GPU Service Corp. 83/07/11.

  8TOLZ, J.F. Operating Reactors Branch 4. 1p. 19629:228. 24X Fiche: 50-289,83/07/11.8307190226.
- --8307\$90231 Application to amend License DPR-50, consisting of Tech Spec Change Request 126 changing surveillance stds.operational review.records & independent onsite safety review group. Certificate of Svc encl. HUKILL.H.D. General Public Utilities - OPU Service Corp. 83/07/11. 4pp. 19829:227. 24X Fiche: 50-289,83/07/11.8307190226.
- --8307190234 Tech Bpec Change Request 126 re surveillance stds, operational safety review, records & independent onsite safety review group.

  4 General Public Utilities CPU Service Corp. 83/07/11. 3pp. 19629: 233. 24X Fiche: 50-289. 83/07/11, 8307190226.
- B30725016B Notification of contract execution.Mod 2 to "Reanalysis of Existing Data From Survey re TMI." Contractor.Natl Inst of Mental Health.

  SILVIB.R.M. Technical Assistance Contracts Branch. FIN 8-8621.

  B3/07/12. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. REGAN.H.H. NRC No Detailed Affiliation Given. 1p. 19725:355. 24X Fiche:50-289,83/07/12.8307250168.
- --8307250174 Mod 2.extending period of performance to 830430 to
  "Reanalysis of Existing Data From Survey ra TMI."

  \* Health & Human Services: Dapt. of: QUSTAVE.R.P. Division of Contracts. FIN B-6821. 83/07/12. ip. 19725:356. 24X
  Fiche: 50-289,83/07/12,8307250168.
- 8307190148 Requests that NRC grant add1 opportunity for public input after issuance of SER re steam generator repair while allowing licensee to proceed w/precritical hot functional testing.

  DIECKAMP.H. General Public Utilities GPU Service Corp. 83/07/13, DENTON.H. NRC No Detailed Affiliation Given. 2pp. 19436:194. 24X Fiche: 50-289, 83/07/13, 8307190148.
- 8307270348 Advises that proposal to separate in-containment high-range radiation monitors by approx 30 ft & to maintain conduit separation acceptable. Design meets criteria of NUREO-0737. Item II.F. i.3.

  870LZ.J.F. Derating Reactors Branch 4, 83/07/i3, HUKILL.H.D. General Public Utilities QPU Bervice Corp. 3pp. 19802:345, 24x Fiche: 50-289:83/07/i3.8307270348.
- 8307270359 Forwards draft SER re NUREO-0737, Item II. B.G. "Post-Accident Sampling Bys." Five of it criteria met Meeting proposed to discuss compliance w/six criteria.

  STOLZ.J.F. Operating Reactors Branch 4. 83/07/13. HUKILL.H.D. General Public Utilities GPU Service Corp. 13pp. 17802:332. 24X Fichs: 50-289,83/07/13,8307270359.
- B307190235 Forwards "Bounding Analytical Assessment of NUREO-0630 Models on LDCA & Operating kW/Ft Limits," in response to 820713 ltr.

  HUKILL, H. D. General Public Utilities GPU Service Corp. 83/07/14.

  NOVAK, T. M. Assistant Director for Licensing. 2pp. 19630:083. 243

  Ficha: 50-289, 83/07/14, 8307190235.

- --8307190238 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA & Operating kW/Ft Limits."

   General Public Utilities GPU Service Corp. 83/07/14. 18pp. 19630:085. 24X Fiche: 50-289, 83/07/14. 8307190235.
- 8307190003 Forwards HJ Dircks 830715 memo to Commission Te NRC proposals to implement NRC 830628 guidance on NRC completion of TMI-1 restart review.

  OLDBERO, J. R. Hearing Branch 2. 83/07/15. EDLES, G. J., KOHL, C. N., 8
- 8307220374 Forwards documents resistan generator eddy current test grogram per 830715 telcon request. Util SER & safety analysis conclusions restinatic expansion changes in defectability threshold valid as unitten.
  CLARK, P. R. General Public Utilities QPU Service Corp. 83/07/18.
  BTOLZ, J. F. Operating Reactors Branch 4. 7pp. 19675:279, 24% Fiche: 50-289, 83/07/18, 8307220374.
- 8307220485 Suppl to 830509 application to amend License DPR-50, parmitting operation following repair of steam generators by any method other than plugging Evaluation of significant hazards consideration encl.

  CLARK.P.R. General Public Utilities GPU Service Corp. 83/07/18.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director. Spp. 19485:352. 24X Fichs: 50-289, 83/07/18, 8307220485.
- 8307260196 Forwards Conam Insp 830718 ltr confirming concurrence w/ 830715 meeting minutes re eddy current test program of steam generator tubing concurres.

  CLARK-P.R. Openeral Public Utilities GPU Service Corp. 83/07/20. STOLZ:J.F. Openeting Reactors Branch 4. 5pp. 19727:106. 24X Fiche: 50-289:83/07/20.8307860196.
- 8307260509 Discusses addl results of post-repair testing of steam generators through early Jul 1983 including early results of reactor primary sys claening. Pre-critical hot testing of steam generators espected to commence in early Aug 1983. HUKILL-H.D. General Public Utilities GPU Service Corp. 83/07/20. STGLZ.J.F. Operating Reactors Branch 4. 2pp. 19731:340. 24X Fiche:50-289:83/07/20,8307260509.
- 8307290130 Forwards "Responses to Recommendations of Basic Energy Technology Assoc.Inc Set Forth in Rept Dtd Feb 28, 1983."

  8LAKE.E.L. Shaw, Pittman, Potts & Troubridge. BLAKE.E.L. Hetropolitan Edison Co. 83/07/26. EDLES.G.J., BUCK.J.H., KOHL.C.R. Atomic Safety and Licensing Appeal Panel. 45pp. 19822:089. 24X Fiche: 50-289,83/07/26,8307290130.
- Q. Inspection reports. IE Bulletins & correspondence
- 8307120214 Ack receipt of 830613 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-287/83-09.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/06.

  HUKILL.H.D. General Public Utilities GPU Service Corp. 2pp.

  19423:263. 24X Fiche:50-289,83/07/06.8307120214.
- --8307120227 Responds to NRC 830513 ltr re violations noted in IE Insp. Rept 50-289/83-09. Corrective actions: pneumatic trip units for 1P & 15 bus feeder breakers reset & Flush procedure written to upgrade interconnecting piping lines. HUKILL, H. D. General Public Utilities GPU Service Corp. 83/06/13. MURLEY, T. A. Region 1, Office of Director. 4pp. 19423: 265. 24X Fiche: 50-289, 83/07/06,8307120214.
- 8305270401 IE Info Notice 83-45. "Common Mode Valva Failures Dagrade Surry Recirculation Spray Subsystem." Syc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19553: 293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Conteminated Hydraulic Fluid." Svc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp, 19563: IS3. 24X Fiche: 30-000, B3/07/12. B306270404.
- B307140449 Forwards MJ Dircks B30629 memo to Commission re reportability of licenses rept on Hartman allegations. Investigation into itr-designated individual VV & Miller incident complete. NRC views submitted to Commission. GOLDBERG.J.R. Hearing Branch Z. B3/07/12. EDLES.G.J., KOHL.C.N., BUCK.J.H. Atomic Safety and Licensing Appeal Panel. 9pp. 19520:345. 24X Fiche: 50-289,83/07/12.B307140949.
- 8306270406 IE info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.

- 8307270025 Forwards NRC 830722 Itr to util & notice of violation & proposed imposition of civil penalty.
  GOLDBERG, J.R. Hearing Branch 2. 93/07/25. EDLES, O. J., KOHL, C. N., BUCK, J. H. Atomic Safety and Licensing Appeal Panel. 8pp. 19749:351. 24X Fiche: 50-289, 83/07/29, 8307270025.
- R. Periodic operating reports & related correspondence
- 8307220182 Monthly operating rept for May 1983.W/830615 ltr. SMYTH.C.W., HUMILL.H.D. General Public Utilities - QPU Service Corp. 83706715. Management Information Branch. 10pp. 19684:001. 24x Fiche: 50-289.83706715.8307220182.
- S. Reportable occurrences, LERs & related correspondence
- 8307110436 LER 83-015/01T-0: on 830611. oxygen concentration in waste gas sys remained in excess of 2% for greater than 1 h. Caused by failure to recognize maint activities affected when oxygen introduced in waste gas sys. W/830627 ltr.
  82CZECH.R.A. HUKILL. H.D. General Public Utilities GPU Service Corp. 83/06/27. MURLEY.T.A. Region 1. Office of Director. 3pp. 19382:238. 24% Fiche: 50-289, 83/06/27, 8307110436.
- 8307050123 Forwards documents potentially relevant & matt to matters under adjudication. Documents include into an reactor coolant pump trip. PDRV corrosion & emergency feedwater flow devices Controlotron. Svc list encl.

  BAXTER.J.A. Shaw. Pittman. Potts & Trowbridge. BAXTER.J.A. (Astropolitan Edison Co. 83/06/29. CHILK.S.J. Office of the Becretary of the Commission. 18pp. 1920: 221. 24X
- B307130007 PNO-THI-83-004: on 83070B, leakage occurred from letdown sysflow instrument when w/one reactor coalant pump in operation, util switched to other pump so that one pump was running in other RCS loop. Caused by loose fittings.

  HIEBE, J., KEIMIG, R. Region 1, Office of Director. 83/07/0B. ip. 19465: 357. 24X Fiche: 30-289, 83/07/0B, 8307130007.
- B307260364 EN-83-045: on B30722, notice of violation & proposed imposition of civil penalties will be issued in amount of \$140,000. Action based on submittal of matl false statement & violation re operator requalification program.

  ROSAND.R., AXELRAD.J. Director's Office, Office of Inspection and Enforcement. 83/07/22. ip. 19733:005. 24% Fiche:50-289,83/07/22.
- T. Rearing transcripts on non-antitrust matters
- 8307080558 Transcript of Commission 830621 public meeting in Washington OC re completion of restart review Pp 1-72. \* Commissioners. 83/06/21. 87pp. 19364:307. 24X Fiche: 50-289, 83/06/21, 8307080558.
- U. Compressional/Executive Correspondence
- 8307060437 Informs that five lists of documents re TMI-2 accident will be compiled per 830607 request.
  PALLADINO, N. J. Commissioners. 83/06/24. UDALL, M.K. House of Rep. interior & Insular Affairs. 4pp. 19300:153. 24X
  Fiche: 50-287,83/06/24,8307060437.
- --8307060443 Ack receipt of NRC 830826 ltr responding to 830427 request for info re forthcoming decision on TMI-1 restart & B&W vs GPU trial record. Commission majority response to 830427 ltr inappropriate.

  UDALL.M.K. House of Rep., Interior & Insular Affairs. 83/06/07, PALLADINO.N.J. Commissioners. 1p. 19300:137. 24X Fiche: 50-289,83/06/24,8307060437.
- V. Operator Examinations
- 8307270044 Advises that Procedure &210-ADM-2604.01, "Control of Exams for Units 1 & 2," Rev 1.meets 820727 partial initial decision requirements & is acceptable.

  STOLZ.J.F. Operating Reactors Branch 4. 83/07/13. HUKILL, H. D. General Public Utilities OPU Service Corp. 3pp. 17811:260. 24X Fiche: 30-289, 83/07/13. B307270044.
- 8307270327 Advises that revised procedure re control of erams meets requirements imposed by 830426 partial initial decision.
  8TOLZ, J.F. Operating Reactors Branch 4, 83/07/13, HUKILL, H. D. General Public Utilities GPU Service Corp. 3pp. 19812:018, 24X Fiche: 50-289, 83/07/13, 8307270327.

- DUCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8307140404 Forwards IE Insp Rept 50-293/83-10 on 830419-0523 % notice of violation. Notice of violation withheld (ref 10CFR73.21).
  STAROSTECKI.R. Division of Project % Resident Programs. 83/06/30.
  HARRINGTON.W.D. Boston Edison Co. 3pp. 19521:083. 24X
  Fiche: 50-293.83/06/30.8307140404.
- --8307140409 IE Insp Rept 50-293/83-10 on 830419-0523. Noncompliance noted: failure to control safeguards info & access control card properly. Portions withheld (ref 10CFR73.21).
  JOHNBON, J., EICHENHOLZ, H., GALLO, R. Region 1, Office of Director.
  83/06/15. 20pp. 19521:086. 24X Fiche: 50-293,83/06/30,8307140404.
- 8307120227 Forwards description of safeguards info protection program, per NRC 830421 ltr responding to util 820505 ltr of appeal re use of particular combination padiock. Encl withheld tref IOCFR73. 21).

  HARRINOTON, W. D. Boston Edison Co. 83/07/06. VASSALLO, D. B. Operating Reactors Branch 2. ip. 19423. 212. 24X
  Fiche: 50-293, 83/07/06, 8307120229.
- 8307150068 Application to amend License DPR-35 changing Tech Specs re core & containment cooling sys & fire protection Submittal is initial segment of total of seven submittals re fire Protection.

  HARRINGTON.W.D. Boston Edison Co. B3/07/11. VABSALLO.D.B.

  Diperating Reactors Branch 2. 5pp. 19536:182. 24X

  Fiche: 50-293.83/07/11.B307150068.
- --8307150070 Proposed Tech Specs re fire protection mods. \* Boston Edison Co. 83/07/11. 9pp. 19936:187. 24x Fiche: 50-293,83/07/11,8307150068.
- 8307260371 Responds to 830513 telcon request for add1 info re 820625 submittal concerning fire protection. List of fuses planned to be removed for fires & photographs of fuse installation
  - HARRINGTON.W.D. Boston Edison Co. 83/07/22. VASSALLO,D.B. Operating Reactors Branch 2. 4pp. 19732:102. 24X Fiche: 50-293,83/07/22,8307260571.

#### G. Adjudicatory correspondence

- 8307260573 Forwards petition of Massachusetts PIRO for Emergency & Remedial Action & supporting documents per 10GFR2.206.
  ERNBT. M.D. Massachusetts Public Interest Research Group. 93/07/Office of Nuclear Reactor Regulation. Director. 1p. 19732:091
  24X Fiche: 50-293,83/07/20,8307260573. 93/07/20
- --8307260976 Petition of MA PIRG for Emergency & Remedial Action per 10CFR2, 206. Petition seeks immediate action to remedy serious deficiencies in facility offsite emergency response plan.
  ERNST.M.D. Massachusetts Public Interest Research Group.
  83/07/10. Commissioners. 10pp. 19732:092. 24X
  Fiche: 50-273, 83/07/20, 8307240573.

### H. Ceneral correspondence

- 8307220450 Comments on Bangor Daily News 2 MTV repts of NRC order to shut down five facilities for insp of cooling pipes.

  Bub sequent rescission considered under pressure from private owners of plants. Requests stronger enforcement.

  HEINRICH B. C. Affillation Unknown. 83/07/15. DENTON, H. R. NRC No Detailed Affillation Qiven. 2pp. 17686:082. 24X

  Fiche: 50-000;83/07/15,8307220450.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307260166 Forwards Rev 2 to updated FSAR.
  HARRINGION, H. D. Boston Edison Co. 83/07/19. DENION, H. R. Office of
  Nuclear Reactor Regulation, Director. 1p. 19735:054, 24X
  Fiche: 50-293,83/07/19,8307260166.
- --8307240172 Rev 2 to updated FSAR. \* Boston Edison Co. 83/07/31. 490pp. 19735:056. 24X Fiche: 50-293,83/07/19,8307260166.

- P. Operating license stage documents & correspondence
- 8307190165 Forwards evaluation of BMR Owners Group generic response to NUREG-0737. Item II. K. 3.18 "Automatic Depressurfration Sys Logic Mods." Two acceptable options include elimination of high drywell pressure permissive VABSALLO.D.B. Operating Reactors Branch 2 83/06/03. HARRINGTON.W.D. Boston Edison Co. 2pp 19562:304. 24X Fiche: 50~293,83/06/03,8307150165.
- B30715015B Advises that requirements of TM1 ltem II.K.3.13, "HPCI/RCIC Initiation Level," met.Item resolved. VASSALLO,D.B. Operating Reactors Branch 2 B3/06/17, HARRINGTON,W.D. Boston Edison Co 2pp 19542-354, 24X Fiche: 90-293, 83/06/17, 8307150158
- B307140512 Forwards confirmatory order verifying util 810213.0421.820526 & B30510 commitments to install permanent scram discharge sys mods by B50223.or prior to operation after mid-Cycle 7 mod outage. Proposed model Tech Specs encl. VASSALLO.D.B. Operating Reactors Branch 2 B3/06/24 HARRINGTON.W.D. Boston Edison Co. 2pp. 19329:163. 24X Fiche: 50-293.83/06/24.8307140512.
- --B307140516 Confirmatory order verifying util B10213,0421,820526 & B30510 commitments to install permanent scram discharge sys mods by B50223,or prior to operation after mid-Cycle 7 mod outage. EISENHUT, D. G. Division of Licensing. 63/06/24. Boston Edison Co. 5pp. 19529:165. 24X Fiche 50-293,83/06/24,8307140512.
- 8306270397 Generic Ltr 83-26 to all applicants for ULs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT.D.G. Division of Licensing 83/07/05 Consolidated Edison Co. of New York Inc. 16pp. 19390-317. 24% Fiche: 50-000, 83/07/05, 8306270397
- 8307110356 Application for amend to License DPR-35, incorporating license condition requiring util to follow lang-term implementation plan reflecting fiscal & manpower resources w/modified schedules.

  HARRINGTON.W.D. Boston Edison Co. 83/07/05. VASCALLO.D.B. HARRINGTON, N.D. Boston Edison Co. 83/07/05. VASSALLO, D. B. Licensing Branch 2. 11pp. 19380-238. 24K Fiche: 50-293, 83/07/05, 8307110356.
- B307060327 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in BTB. Svc list encl. EIGENHUT. D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307060327.
- B307120351 Confirms commitment to perform photographic survey of points along seaward face of breakwater from boat, per NRC 830607 request. Survey will affirm position of each visible seaward side stone.

  HARRINGTON. D. B. Boston Edison Co. B3/07/07. VASSALLO, D. B. Operating Reactors Branch 2. 1p. 19429: 107 24X Fiche: 50-293, 83/07/07, 8307120351.
- B307130080 Forwards current description of QA program & revs to program per 830616 schedule Program will be implemented following NRC approval or 60 days from 830707. MARRINGTON, W. D. Boston Edison Co. 83/07/07. Region 1, Office of Director. 9pp. 19474:266. 24X Fiche 50-293,83/07/07,8307130080.
- --8307130082 "9A ManualiVol II." HARRINGTON, H. D. Boston Edison Co. 83/07/07 66pp. 19474: 275. 24X Fiche: 50-293, 83/07/07, 8307130080.
- B307080169 Generic Ltr 83-28 to all litensees of operating reactors, applicants for CL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 30-000, B3/07/08, 8307080169.
- 830715004B Application to amend License DPR-35 changing Tech Specs re core & containment cooling sys & fire protection. Submittal is initial segment of total of seven submittals re fire Protection.

  HARRINOTON, N. D. Boston Edison Co. B3/07/11. VASSALLO, D. B
  Operating Reactors Branch 2 Spp. 19536, 182. 24X

  Fiche: 50-293, B3/07/11, 8307150068.
- --8307150070 Proposed Tech Specs re fire protection mods. \* Boston Edison Co. 83/07/11. 9pp. 19536:187. 24x Fiche: 50-293, 83/07/11, 8307150068

- B307t50123 Forwards Rev i to "Inservice Testing Program for Pumps & Valves,Pilgrim Nuclear Power Station "
  HARRINOTON.W.D. Boston Edison Co. B3/07/11. VABSALLO.D.B.
  Operating Reactors Branch 2. 1p. 19537.212. 24X
  Fiche: 50~293.83/07/11.8307150123.
- --8307150128 Rev 1 to Procedure 808-03-0201. "Inservice Testing Program for Pumps & Valves,Pilgrim Nuclear Power Station." KIN. J. N., PICKENS,T. A., GAVULA, J. A. NUTECH Engineers, Inc. 83/05/25. 120pp. 19537:213. 24X Fiche: 50-293,83/07/11, 8307150123.
- 8307190016 Forwards responses to Franklin Research Ctr B20212 draft rept on handling of heavy loads & response to 801222 request for add1 info re lifting devices, Mods & procedure emplacements will be completed by 841231.

  HARRINGTON. H. D. Boston Edison Co. 83/07/13. EISENHUT. D. G. Division of Licensing. 49pp. 19633:084. 24X Fiche: 50-293,83/07/13. B307190016.
- 8307220376 Forwards Teledyne Rept 5310-9, "Responses to NRC Request for Info: Mark I Torus Program Plant-Unique Rept," in response to 22 questions from 830414 ltr.
  HARRINGTON, H. D. Boston Edison Co. 83/07/19. VASSALLO, D. B. Operating Reactors Branch 2. ip. 17686: 188. 24X
  Fiche: 50-273,83/07/19,8307220376.
- --9307220378 "Responses to NRC Request for Info:Mark I Torus Program Plant-Unique Rept." W/two oversize drawings. Aperture cards are available in PDR.

  \* Teledyne Engineering Services. 5310-9. 83/07/13. 25pp. 19484: 189. 24X Fiche: 50-293: 83/07/19, 8307220376.
- 8307250524 Notification of 830809 meeting w/utils,Franklin Research & Teledyne Engineering Svc in Framingham.MA to discuss Mark 1 long-term program implementation & unresolved questions restructural integrity.

  SHEA-J.J. Operating Reactors Branch 5. 83/07/20. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 19782:240. 24x Fiche: 50-000,83/07/20,8307250324.
- 8307260402 Advises that design gas concentration of two compressed gas bottles in calibr gas subsystem modified from 4% hydrogen & 7% axygen to 19.9% & 20.9% respectively.per 830609 ltr re NUREO-0737. Item II.F.1.6.
  HARRINGTON.W.D. Boston Edison Co. 83/07/22. VASSALLO.D.B. Ogerating Reactors Branch 2. [p. 19733:118. 24% Fiche: 50-293,83/07/22,8307260402.

# 9. Inspection reports, IE Bulletins & correspondence

- B307010082 Notifies of completion of all plant mode associated w/IE Bulletins 79-02 & 79-14. Proposed Mode 2,3 & 4 completed in May 1983. Froposed Mode 1 not implemented HARRINGTON. W.D. Boaton Edison Co. 83/06/16. Region 1, Office of Director. 2pp. 19124.346. 24X Fiche: 30-293, B3/06/16, B307010082.
- 8307050252 Advises of proposed alternate testing schedule re inservice insp based on testing conducted through integration w/valve betterment program & local rate testing. Completion expected prior to startup from Refuel Dutage 7. HARRITATION.W.D. Boston Edison Co. 83/06/27. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19199:059. 24X Fiche: 50-293.83/06/27,8307050252.
- B307060030 Ack receipt of B30614 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/83-12.

  MARTIN.T.T. Division of Engineering & Technical Programs. B3/06/30. HARRINGTON W. Boston Edison Co. 2pp. 19251:065. 24X Fiche: 50-293. B3/06/30, 8307060030.
- --8307060037 Responds to NRC 830518 itr re violations noted in IE Insp Rept 30-293/83-12 Required empirical data of representativeness of main stack & reactor bldg vent sampling will be provided by 830730. HARRINGTON, M. Boston Edison Co. 83706/14. MARTIN, T. T. Division of Engineering & Technical Programs. ip. 19251:067. 24X Fiche: 50-293, 83/06/30, 8307060030.
- --B307060048 Responds to B30518 ltr re violations noted in IE Insp Rept 50-293/83-12. Corrective actions: clean waste pump room & chemical/waste treatment pump room posted per 10CFR20, 203(d) & sampled for airborne radioactivity.

  HARRINGTON.H. Boston Edison Co. B3/06/14. HARRINGT.T. Division of Engineering & Technical Programs. 3pp. 19251:068, 24x Fiche: 50-293,83/06/30,8307060030.
- 8307140404 Forwards IE Insp Rept 50-293/83-10 on 830419-0523 & notice of violation withheld (ref 10CFR73.21).
  STAROSTECKI, R. Division of Project & Resident Programs. 83/06/30.
  HARRINGTON.W.D. Boston Edison Co. 3pp. 19521:083. 24X
  Fiche: 50-293,83/06/30,8307140404.

- --B307140409 IE Insp Rept 50-293/83-10 on 830419-0523. Noncompliance noted: failure to control safeguards info & access control card properly. Portions withheld (ref 10CFR73.21). JGHNSON.J., EICHENNOLZ.H., GALLQ.R. Region 1, Office of Director. 83/06/15. 20pp. 19521:086. 24% Fiche:50-293,83/06/30.8307140404.
- 8307210018 Forwards IE Insp Rept 50-293/83-11 on 830426-29 & 0503-05. No noncompliance noted.
  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/06.
  HARRINOTON, U.D. Boston Edison Co. 2pp. 19669:206. 24X
  Fiche:50-293,83/07/06,8307210018.
- --8307210025 IE Insp Rept 50-293/83-11 on 830426-29 & 0503-05. No noncompliance noted. Major areas inspected: licensee actions per IE Bulletins 79-02 re pipe support base plate designs & 79-14 re seismic analysis for as-built piping sys.

  VARELA.A.A. DURR.J.P. Region 1, Office of Director. 83/06/15. Spp. 19469: 208. 24X Fiche: 50-293, 83/07/06, 8307210018.
- 8306270401 IE Info Notice 83~46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Bubsystem." Svc 11st encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:273. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydravlic Enubbers as Result of Contaminated Hydravlic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits," Svc list encl. TAYLOR, J. M. Division of OA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- 8307210123 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-293/82-04 & 50-293/82-19.

  8TAROSTECKI.R. Division of Project & Resident Programs. 83/07/14. HARRINOTON.W.D. Boston Edison Co. ip. 19666:081. 24X Fiche: 50-293,83/07/14,8307210123.
- --B307210140 Responds to NRC ltr re violations noted in IE Insp Repts 50-293/82-04 & 30-293/82-19. Corrective actions: Procedures 8. 2. 3 retired & 8. 7. 1. 5 re local leak rate test of primary containment penetrations & isolation valves revised. HARRINGTON, W. D. Boston Edison Co. B3/06/16. BTARCBTECKI. R. Division of Project & Resident Programs. 3pp. 19666:082. 24% Fiche: 50-293, 83/07/14, 8307210123.
- B3072B0444 Forwards IE Insp Rept 30-293/B3-14 on B30523-0620, No noncompliance noted.

  BTAROSTECKLR. Division of Project & Resident Programs. B3/07/14.

  HARRINGTON.W.D. Boston Edison Co. 2pp. 19797: 322. 24X

  Ficha: 50-293, B3/07/14, B3072B0444.
- --8307280449 IE Insp Rept 50-293/83-14 on 830523-0620. No noncompliance noted. Major areas inspected: review of surveillance & maint activities, operational safety verification & followup of previous findings, events, LERs & IE bulletins.

  UDHNSON, J., EICHENHOLZ, H., BRIGGS, L. Region 1, Office of Director. 83/07/14, 25pp. 19797: 324. 24X Fiche: 50-293, 83/07/14, 8307280444.
- R. Periodic operating reports & related correspondence
- 8307220197 Monthly operating rept for May 1983.W/830614 ltr. WHITNEY,G.G., HARRINGTON,W.D. Boston Edison Co. 83/06/06. Office of Resource Management, Director. 7pp. 19684:094, 24X Fiche:80-293.83/06/06,8307220197.
- 8307190040 Monthly operating rept for June 1983.W/830713 ltr. WHITNEY.G.G., HARRINOTON.W.D. Boston Edison Co. 63/07/13. Director's Office. Office of Inspection and Enforcement. Bpp. 19635:141. 24% Fiche: 50-293,83/07/13.8307190040.
- 8307280399 Forwards "Rept of Changes Tests & Experiments Performed at Pilgrim Nuclear Power Station, 820701-830121," per 10CFR50. 57. Future annual submittals will be for period anding Jan 21 to coincide w/FSAR update submittal. HARRINOTON.W.D. Boston Edison Co. 83/07/19. MURLEY, T. E. Region 1, Office of Director. ip. 19796:049. 24X Fiche: 50-293, 83/07/19, 8307280399.
- --8307280404 "Rept of Changes, Tests & Experiments Performed at Pilgrim Nuclear Power Station, 820701-830121." \* Beston Editon Co. 83/07/19. 10pp. 19796:050. 24X Fiche: 50-293, 83/07/19.8307280399.

- S. Reportable occurrences, LERs & related correspondence
- B307010134 LER 83-027/O3L-0 on B30518, during routine insp, folding fire door found inoperable Caused by operating cable becoming detached from pulley due to slack. Cable reattched % operating mechanism adjusted (MB30316) ltr.
  WHITNEY, G. G., HARRINGTON, W. D. Boston Edison Co. B3/06/16. Region 1, Office of Director. 2pp. 19175: 319. 24% Fiche: 50-293, B3/06/16, B307010134.
- 8307010066 LER 83-029/01X-0: on 830617. util informed that spent fuel pit HX supports A not capable of withstanding seismic loadings. Caused by incorrect installation of supports during initial const. Mods being developed to modify supports.
  WHITNEY, G. G. Boston Edison Co. 83/06/20. Region 1, Office of Director. 1p. 19168:151. 24X Fiche: 50-273,83/06/20.8307010066.
- 8307120507 Updated LER 79-007/03X-1: on 790212, while performing Test 8.7. 4.3 valves AD-5033A: CV-5065-10, 15, 16 & 17 failed to give proper position indication when cycled & to close within specified tolerance, Cause not stated W/B30621 ltr. WHITNEY, 9. 9. HARRINGTON, M. D. Boston Edison Co. 83/06/21. Region 1. Office of Director. 2pp. 19433: 262. 24X Fiche: 50-293, 83/06/21, 8307120507.
- 8307110476 LER 83-030/03L-0: on 830527, both HPCI area smoke detection sys alarmed in main control prom. Caused by valve A02301-31 steam leak causing false indications. Valve repaired. H/830624 ltr.
  WHITNEY, G. G. HARRINGTON, W. D. Boston Edison Co. 83/06/24. Region 1. Office of Director. 2pp. 19380: 182. 24X Fiche: 50-293,83/06/24,8307110476.
- 8307110506 LER 83-031/03L-0: on 830528, HPCI sys made inoperable to repair steam leak on AO 2301-31. Caused by leaking stem packing. Packing replaced. Valve tested satisfactorily. Sys returned to svc. W/830624 ltr.
  WHITNEY. 9. 9. HARRINGTON, W. D. Boston Edison Co. 83/06/24. Region 1. Office of Director. 2pp. 19380: 084. 24X Fiche: 50-293, 83/06/24, 8307110506.
- 8307120423 Updated LER 80-053/03X-1: on 800814.0907 & 14.HPC1 turbine exhaust line snubber 23-3-36 determined inoperable Caused by transient hydrodynamic shock during startup & shutdown.
  8nubbers upgraded.W/830624 ltr.
  VENDER.J., HARRINOTON, W. D. Boston Edison Co. 83/06/24. Region 1, Office of Director. 2pp. 19424:208. 24X Fiche:50-293.83/06/24, 8307120423.
- B30712051B Updated LER 82-03B/03X-1: on 820B17.RCIC steam line high differential pressure alarm received. Caused by air in sensing lines to pressure switches. Cross threaded cap found on in-line snubber suplaced. W/B30624 ltr. VENDER. J., HARRINOTON, W. D. Boston Edison Co. B3/06/24. Region 1, Office of Director. 2pp. 19433:198. 24X Fiche: 50-293, B3/06/24, B307120518.
- 8307150127 LER B3-033/03L-0: on B30601, governor for diesel generator B failed to properly respond to control signals. Caused by malfunctioning mechanical governor supplied by Woodward Governor Co. Governor replacad w/spare. W/830627 LT. WHITNEY, O. O., HARRINGTON, W. D. Boston Edison Co. B3/06/27. Region 1. Office of Director. 2pp. 19535:259. 24X Fiche: 50-293, 83/06/27, B307150127.
- 8307010011 PND-I-83-071: on 830627, licensee bagan shutting down to inspect for unidentified RCS leakage.Licensee identified two packing leaks on 830628. Outage estimated to last 3-4 days. JOHNSON J. HUDSON B. ELSASSER.T. Region 1. Office of Director. 83/06/28. 1p. 19169: 087. 24X Fiche: 50-273, 83/06/28, 8307010011.
- B307150022 LER B3-034/03L-0: on B30606, nitrogen purge isolation valve AO 5033B failed to mest Tech Spec required closing time. Caused by use of 3/B-inch solenoid air supply valve 8V 5033B. Valve replaced w/1/2-inch solenoid valve. W/830630 ltr. HHITNEY, 0.0., HARRINOTON, W. D. Boston Edison Co. B3/06/30. Region 1, Office of Director. 2pp. 19536:206. 24X Fiche: 50-293.83/06/30, B307150022.
- 8307150245 LER 83-029/01T-0: on 830617, spent fuel pool A HX E206-A supports found incapable of withstanding seismic loads. Caused by deviation from original design during initial const. Supports modified, M/830630 ltr. WHITNEY, O., HARRINGTON, W. D. Boston Edison Co. 83/06/30. Region 1, Office of Director. 2pp. 19531:095. 24X Fiche: 50-293,83/06/30,8307150245.
- 8307130262 LER 83-032/99X-0: on 830601, organization changes made to station & corporate structures in Tech Spec Section 4, 2. Changes intended to provide more direct & effective support of station operations. W/830630 itr.
  WHITNEY, G. O. HARRINGTON, W. D. Boston Edison Co. 83/06/30. Region 1, Office of Director. 4pp. 19338: 076. 24X Fiche: 50-293, 83/06/30, 8307130262.

- 8307220430 Updated LER 80-034/03X-1:on 800701 & 16.HPC1 turbine discharge line snubber found severed & HPC1 declared inoperable. Caused by transient hydrodynamic shock during startup & shutdown of HPC1 turbine. W/83070706 | tr. VENDER.J. HARRINGTON.W.D. Boston Edison Co. 83/07/06. Region 1: Dffice of Director. 2pp. 19687:282. 24X Fiche: 50-293.83/07/06. 8307220430.
- B307220551 Updated LER 79-050/03X-1 on 791221, HPC1 exhaust line snubber S5-23-3-31 strut assembly found bent & thread assembly out of wall mount Caused by transient hydro shock. Snubbers upgraded & add1 snubbers added W/B30706 ltr. VENDER.J. HARRINGTON.W.D. Boston Edison Co. B3/07/06 Region 1-Office of Director. 2pp. 19686:095. 24X Fiche: 50-293. B3/07/06. B307220591.
- 8307220519 LER 83-035/03L-0: on 830610, three of four motor operator mounting cap strews found backed out of core spray test valve MOV 1400-4A. Caused by insufficient cap screw torque. Screws coated & torqued. W/830707 ltr.
  WHITMEY: 0.0., HARRINGTON, W.D. Boston Edison Co. 83/07/07. Region 1, Office of Director. 2pp. 19683: 226. 24X Fiche: 50-293,83/07/07. 8307220519.
- B307220206 LER B3-036/03L-0: on B30616, overtravel alarm received during routine coupling check for control rod 30-91, indicating possible uncoupled rod. Cause unknown. Drive position recoupled. M/B30714 ltr.
  HHITNEY, O. G., HARRINGTON Boston Edison Co. B3/07/14. Region 1, Office of Director. 2pp. 19684.052 24X Fiche: 50-273, B3/07/14, B307220206.
- B307220331 LER 83-037/03L-0: on B30617, Fire Door 64 between emergency diesel generator air compressor rooms would not latch properly. Caused by door out of adjustment Door latch adjusted. W/B30714 ltr.
  WHITNEY, G. 9., HARRINGTON, W. D. Boston Edison Co. B3/07/14. Region 1, Office of Director. 2pp. 19679: 351. 24x Ficho: 50-293, 83/07/14. B307220331.
- B3072B0059 LER B3-03B/03L-0: on B30622. one signoff sheet found not initialed for 2 h period during unscheduled supervisory inspect fire patrols. Caused by failure to read & comprehend list of areas to be patrolled. Individual instructed. W/83071B ltr. WHITNEY, Q. Q., HARRINGTON, W. D. Boston Edison Co. B3/07/18. Region 1, Office of Director. 2pp. 19791: 189. 24X Fiche: 50-293. B3/07/1B, B3072B0059.

# DOCKET 50-294 MICHIGAN STATE UNIV. RESEARCH REACTOR F. Security, medical, emergency & fire protection plans

- B307110205 Releases public version of licensee ltr re submittal of changes to emergency plan.
  FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19389:353. 24% Fiche: 50-274.83/06/24. 8307110205.
- --8307110220 Forwards public version of request for extension until 831101 to submit required changes to emergency plan.pot 830610 ltr. Changes unnecessary if reactor transfer to McClellan Air Force Base authorized.
  MILKINSON.B.W. Michigan State Univ. 83/06/15. THOMAS.C.O. Standardization & Special Projects Branch. 1p. 19385:354. 24X Fiche: 50-274.83/06/24.8307110205.
- 8307180427 Advises that 830615 request for extension until 831101 to respond to questions re emergency plan granted.
  THOMAS.C.O. Standardization & Special Projects Branch. 83/07/05. MILKINSON.B. Michigan State Univ. 2pp. 19566:349. 24X Fiche:50-294.83/07/05.8307180427.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307080254 Forwards IE Insp Rept 50-294/83-01 on 830519-20. No noncompliance noted.

  PAPERIELLO.C.J. Division of Emergency Preparedness & Operational Support. 83/06/13. TERRY.S.H. Michigan State Univ. 2pp. 19352:038. 24X Fiche: 50-294.83/06/13.8307080254.
- --8307080263 IE Insp Rept 50-274/83-01 on #30517-20. No nuncompliance noted Major areas inspected; qualifications, audits, training, radiation protection procedures, instruments & equipment, exposure control & labeling.

  GRANT.W.B., GREGER, L.R. Region 3, Office of Director. 83/06/10. 7pp. 19352:040. 24X Fiche: 50-274,83/06/13,8307080254.

#### V. Operator Examinations

B307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing 83/07/11. Michigan, Univ. of. 14pp. 19543:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

# DOCKET 50-295 /ION NUCLEAR POWER STATION. UNIT 1 F. Security, medical, emergency & fire protection plans

- 830708030: Recommends imposition of civil penalty in amount of \$10,000 for violations found during special safeguards insp on 830319. Util 830609 response provides no basis for further mittigation Draft ltr to licensee encl. SCHULTZ.W.H. Region 3, Office of Director 83/07/05. AXELRAD, J. A. Enforcement Staff. 4pp. 19350:185. 24X Fiche: 50-295,83/07/05, 8307080301.
- 8307110131 Confirms 830705 telcon between F Lentine & M Holimer re 830708 security enforcement meeting at Region III ofcs to review 830615 breach of security event & corrective actions to prevent recurrence. KEPPLER-J. G. Region 3, Office of Director. 83/07/05. REED.C. Commonwealth Edison Co. 1p. 19375:125. 24X Fiche:50-295,83/07/05, 8307110131.
- 8307120391 Notifies that request for license amends to clarify responsibility of licensee during emergencies withdrawn. Addition of Paragraphs x & y to lOCFRSO. 54 provided necessary clarification.

  LENTINE, F. G. Commonwealth Edison Co. 93/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19430:142. 24% Fiche: 50-295, 83/07/06, 8307120391.
- B307280266 Forwards IE Insp Repts 50-295/83-09 & 50-304/83-09 on B30613-17. No noncompliance noted. PAPERIELLO,C.J. Division of Emergency Preparedness & Operational Support. B3/07/12. REED.C. Commonwealth Edison Co. 2pp. 19791:341. 24X Fiche: 50-295.83/07/12.8307280266.
- --8307280274 IE Insp Repts 50-275/83-09 & 50-304/83-09 on 830613-17. No noncompliance noted Major areas inspected: emergency preparedness program including licensee actions on previously identified items.

  PHILLIPS.M.P., LICKUS,R.M., AXELSON,W.L. Region 3, Office of Director, 83/07/08. 18pp. 19791:343. 24X Fiche: 50-295, 83/07/12, 8307280266.
- 8307290293 Releases public version of Rev 3 to emergency plan implementing procedure. FELTON J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19858:163. 24X Fiche: 50-295, 83/07/19, 8307290293.
- --8307290299 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP 140~1. "Maint Director Emergency Plan Implementing Procedure." Receipt form & 830621 ltr encl. NYKIRK.J.H. Commonwealth Edison Co. 83/06/20. DENTON,H.R. NRC No Detailed Affiliation Given. Spp. 19858:164. 24X Fiche: 50-275,83/07/19,8307290293.
- 8307260018 Submits supplemental response to NUREO-0737, Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display sys verification to be performed w/verification program. SMARTZ.E.D. Commonwealth Edison Co. 83/07/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727: 177. 24X Fiche: 30-000, 83/07/20, 83/07260018.
- B307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions enci.

  PAFERIELLO.C. J. Region 3, Office of Director. B3/07/26, REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24x Fiche: 50-000, B3/07/26, B307280347.

# G. Adjudicatory correspondence

B307120595 Advises that time for Commission to review Director's Decision DD-83-8 expired Commission declined review. Decision became final agency action on 830705. CHILKS.J. Office of the Secretary of the Commission. 83/07/11. GUIGG.C. Pollution & Environmental Problems, Inc. 1p. 19433:07/24X Fiche: 50-000,83/07/11,8307120595.

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010195 Forwards amends to updated FSAR for facilities. STIEDE.M.L. Commonwealth Edison Co. 83706/29. DENTON.H.R. Dffice of Nuclear Reactor Regulation, Director. 2pp. 19123:001. 24X Fiche: 50-000:83706/29,8307010195.
- --8307010196 Rev 1 to updated FSAR for Zion Station 1 & 2. \* Commonwealth Edison Co. 82/12/31. 66pp. 19123:003. 24X Fiche: 50-000, 83/06/29, 8307010195.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Byc list encl. EISENHUT.D.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000,83/06/03, 8306060070.
- 8307270343 Forwards request for addl info clarifying 820716 response reATMS. Trip of main feed pumps will cause main turbine to trip, however, unclear exactly what loss of feedwater events would lead to turbine trip.

  VARGA: S. A. Operating Reactors Branch 1. 83/06/23. FARRAR, D. L. Commonwealth Edison Co. 8pp. 19802:348. 24X Fichs: 30-275,83/06/23,8307270343.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in BTB. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:234. R4X Fiche: 50-000, 83/07/06, 8307060329.
- B307120391 Notifies that request for license amends to clarify responsibility of licensee during emergencies withdrawn. Addition of Paragraphs x & y to 10CFR50.54 provided necessary clarification. LENTING.F.Q. Commonwealth Edison Co. B3/07/06. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ip. 19430:142. 24X Fiche: 50-295, 83/07/06, 8307120391.
- 8307080169 Generic Ltr 83-28 to all licenses of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Bvc list encl. EISENHUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of Naw York, Inc. 38pp. 19649: 269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307280375 Discusses plans for upgrading core exit thermocouples, supplementing 830319 response to Generic Ltr 82~28 re inadequate core cooling instrumentation sys. Upgrading of field cable & ref junction boxes under evaluation. LENTINE, F. G. Commonwealth Edison Co. 83/07/14, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19796: 104, 24X Fiche: 50~295, 83/07/14, 8307280375.
- 8307280482 Forwards draft of revisw rept for Zion Probabilistic Bafety Study, Vols I & II. Comments requested by 830812. W/o encl. VARGA, S.A. Operating Reactors Branch I. 93/07/22. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19826:046. 24X Fiche: 50-295, 83/07/22, 8307280482.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307010103 Forwards requests for relief from inservice insp program requirements of ASME Section XI Code: 1974 Edition through Summer 1975 Addenda: per 10CFR50. 85a(g) (5). Roview requested. LENTINE, F. O. Commonwealth Edison Co. 83/04/27. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 37pp. 1916B: 157. 24X Fich: 50-295, 83/04/27, 8307010103.
- 8307080301 Recommends imposition of civil penalty in amount of \$10,000 for violations found during special safeguards insp on 830315. Util 830607 response provides no basis for further mittgation. Draft 1 tr to licensee sncl.

  8CHULTI, M. H. Region 3, Office of Director. 83/07/05. AXELRAD, J. A. Enforcement Staff. 4pp. 19350:185. 24X Fiche: 50-295,83/07/05,8307080301.

- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDANIE, L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fichs:50-000,83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307280266 Forwards IE Insp Repts 50-295/83-09 & 50-304/83-09 on 830613-17. No noncompliance noted. PAPERIELLO,C. J. Division of Emergency Preparedness & Operational Support. 83/07/12. REED.C. Commonwealth Edison Co. 2pp. 19791:341. 24X Fiche:50-295.83/07/12.8307280266.
- --8307280274 IE Insp Repts 30-298/83-09 & 50-304/83-09 on 830613-17. No noncompliance noted Major areas inspected amergency preparedness program, including licensee actions on previously identified items.

  PHILLIPS.M.P., LICKUS.R.M., AXELBON.W.L. Region 3, Office of Director. 83/07/08. 18pp. 19791:343. 24X Fiche: 50-295,83/07/12,8307280266.
- 9306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl.

  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 930103). B3/07/14, Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24% Fiche:50-000.83/07/14.8306270406.
- 8307280084 Confirms 830726 mgt meeting in Chicago IL to discuss licensee regulatory performance & communication problems between RC & util.per 830715 discussion.
  NORELIUG.C.E. Division of Project & Resident Programs. 83/07/22.
  REED.C. Communuealth Edison Co. 2pp. 19791:169. 24X
  Fiche: 50-000, 83/07/22, 8307280084.
- --8307280102 Confirms request for NRC & util senior mgt meeting on 830726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.
  REED.C. Commonwealth Edison Co. 83/07/11. DAVIS, B.A. Region 3. Office of Director. ip. 19791:171. 24X Fiche: 50-000, 83/07/22, 8307280084.
- R. Periodic operating reports & related correspondence
- 8307180198 Monthly operating repts for June 1983.W/830708 ltr. AUSTIN.G., GRAESSER.K.L. Commonwealth Edison Co. 83/07/08. Director's Office, Office of Inspection and Enforcement. 12pp. 19555:193. 24X Fichd: 50-295.83/07/08,8307180198.
- 8. Reportable occurrences. LERs & related correspondence
- B3070B0233 LER B3-043/03L-0: on B3061; refueling/cold shutdown surveillance (PT-23) performed to verify repairs. Valve failed to close in 5 s. Gaused by incorrect setting of pressure relief valve in hydraulic circuit W/B30627 ltr. GAJIC. Z. ORAESBER, K. L. Commonwealth Edison Co. 83/06/29. KEPPLER. J. 9. Region 3. Office of Director. 2pp. 19352:050. 24X Fiche: 50-295,83/06/29,8307080233.
- 8307060334 PNO-III-83-056: on 830629, security personnel found several rolled digarette butts believed to be manijuana. Visitors denied access to site & alleged controlled substances turned over to police for analysis. Util awaiting results.

  CREED, J. MILLER, J. Region 3. Office of Director. 83/06/30. 1p. 19234: 141. 24X Fiche: 50-275, 83/06/30, 8307060334.
- 8307080020 PNO-III-83-058: on B30701: bomb threat received from unknown female stating that bomb would go off in 10 minutes.
  Licensee security force put on alert status. No explosion occurred. State police not notified due to lack of time.
  MADEDA.T., CREED.J. Region 3: Office of Director. 83/07/01. 1p. 19351:216. 24X Fiche: 90-275,83/07/01,8307080020.
- 8307110131 Confirms 830705 telcon between F Lentine & M Holzmer re 830708 security enforcement meeting at Region III ofcs to review 830615 breach of security event & corrective actions to prevent recurrence.

  KEPPLER, J. G. Region 3, Office of Director. 83/07/05, REED, C. Commonwealth Edison Co. ip. 19375:125. 24X Fiche: 50-275, 83/07/05, 8307110131.

- 8307200183 LER 83-018/03L-0: on 830609, during monthly surveillance, RHR miniflow control valve switch 1FIC610A failed & would not close miniflow valve at 1,000 gpm. Caused by inoperable micro-switch (Barton Model 288), W/830713 ltr.
  LANE, R. E. , GRAESER, K. L. Commonwealth Edison Co. 83/07/13. KEPPLER, J. Q. Region 3, Office of Director. 2pp. 19647:306. 24X Fiche: 50-275, 83/07/13, 8307200183.
- 8307200199 Updated LER 82-030/03X-1:on 820919, charging flow was 30 gpm less than letdown flow. Increase demand on charging flow did not increase flow rate. Operator tripped pump IB & declared pump inoperable. Pump IA started.

  LANE. R. E. GRAEBSER, K. L. Commonwealth Edison Co. 83/07/13.

  KEPPLER, J. Q. Region 3. Office of Director. 2pg. 19647:36C. 24X

  Fiche: 50-295,83/07/13,8307200199.
- 8307200213 LER 83-017/03L-0: on 830613, high steam flow safety injection occurred during MSIV iD partial close test (PT-3D). Caused by operator erroneously placing MSIV test switch in reset position. Operators reinstructed. W/830713 ltr. GAJIC.Z., GRAESSER, K. L. Commonwealth Edison Co. 83/07/13, KEPPLER, J. G. Region 3, Office of Director. 3pp. 19648:030. 24X Fiche: 50-295, 83/07/13, 8307200213.
- 8307200287 LER 83-019/03L-0: on 830613, during insp. diesel generator 1A found leaking water out of left bank air intake manifold. Diesel declared inoperable. Caused by personnel error. Valve closed, filling manifold w/water. W/830713 ltr. FANNINO, G., ORAESSER, K. L. Commonwealth Edison Co. 83/07/13, KEPPLER, J. O. Region 3, Defice of Director. 2pp. 19651:164. 24X Fiche: 50-295, 83/07/13, 8307200287.
- 8307280377 EN-83-028A: on 830428, Commission notified of intent to issue notice of violation & proposed imposition of civil panalty in amount of \$10,000. Notice issued 830726 re unauthorized entry into protected area. ROSANO.R. AXELRAD. J. Director's Office. Office of Inspection and Enforcement. 83/07/26. ip. 19796:103. 24X Fiche: 50-295,83/07/26,8307280377.
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
  F. Security, medical, emergency & fire protection plans
- 8307140390 Forwards emergency preparedness evaluation rept from May 1981 Mar 1982 emergency preparedness appraisal. STOHR, J. P. Division of Emergency Preparedness & Materials Safety. 83/02/07. PARRIS, H.C. Tennessee Valley Authority. 1p. 19325:075. 24X Fiche: 50-259, 83/02/07, 8307140390.
- --8307140395 Forwards emergency preparedness evaluation rept.as followup to implementation appraisal. Emergency plan provides adequate planning basis for acceptable state of emergency preparedness. PAOANO.F. Q. Emergency Preparedness Branch. 82/12/28. BTOHR.J.P. Division of Emergency Preparedness & Materials Bafety. 14pp. 19525:076. 24X Fiche: 50-259, 83/02/07, 8307140390.
- 8307140062 Advises that NRR & Region II final decision on 830201 request to change current fire door insp program to require monthly instead of deily, visual insps & maint insps at 18-month intervals, expected within 30 days.

  LEWIS.R.C. Division of Project & Resident Programs. 83/02/17. PARRIS.H.G. Tennessee Valley Authority. ip. 19514: 121. 24X Fiche: 50-259, 83/02/17, 8307140042.
- 8307140360 Confirms 830316 telcon between JA Domer & FB Cantrell refire door insp & maint program at facility.Util will continue daily visual insp & semiannual maint insp program of all fire doors as outlined in 810403 ltr.

  LEWIB, R. C. Division of Project & Resident Programs. 83/03/25. PARRIS, H. G. Tennessee Valley Authority. ip. 19523:328. 24X Fiche: 50-259,83/03/25,8307140360.
- 8307220528 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations & deviation noted in IE Insp Repts 50-259/83-15, 50-269/83-15 & 50-296/83-15. LEWIS.R.C. Division of Project & Resident Programs. 83/07/15. PARRIE.H.O. Tennessee Valley Authority. 1p. 19685:009. 24X Fiche: 50-259, 83/07/15, 8307220528.
- --8307220547 IE Insp Repts 50-239/83-15.50-260/83-15 & 50-296/83-15 on 830326-0425. Noncompliance noted: failure to follow procedures for RHR svc water functional test & to conduct insp of RHR svc water air vacuum valves during Unit 2 operating cycle. PAULK. Q.L. Region 2. Office of Director. 83/05/10. 7pp. 19685: 020. 24X Fiche: 50-259.83/07/15.8307220528.
- B307250626 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19717:200. 24X Fiche:50-259,83/07/19, B307250626.

- TBDO7250633 Forwards public version of revised energency plan implementing procedures, including div of nuclear power emergency ctr implementing procedures & Knozville emergency ctr implementing procedures.

  MILLS.L M. Tennessee Valley Authority. 83/05/02. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. ip. 19717: 201. 24x Fiche: 50-259, B3/07/19, B307250626.
- P307250637 Public version of revised emergency plan implementing procedures, including div of nuclear power emergency ctr implementing procedures & Knozville emergency ctr implementing procedures

   Dute Power Co. 83/04/18. 210pp. 19717:202. 24X
  Fiche. 50-259, 83/07/19, 8307250626.
- J. Impurance & indemnity information
- BESO 7130257 Forwards Endorsements 66 & 67 to NELIA Policy NF-198 & Endorsements 55 & 56 to MAELU Policy MF-66.

  DUCK.J.R Harsh & McLennan, Inc. 83/07/05. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 19307:339. 24X Fichs:50-259,83/07/05,8307130257.
- D307200146 Forwards Endorsement 68 to NELIA Policy NF-198 & Endorsement 57 to MAELU Policy MF-66.
  DUCK, J.R. Marsh & McLennan, Inc. 83/07/15. SALTZMAN, J. Assistant Director for State & Lirensee Relations. 3pp. 19651:008. 24X Fiche: 50-259, 83/07/15. 8307200146.
- P. Operating license stage documents & correspondence
- BEOF340150 Forwards safety evaluation of BMR Owners Group response to NURREG-0737. Item II. K. 3.18. "Mod of Automatic Depressurization Bys Logic...." Two acceptable options include slimination of high drywell pressure permissive. VASSALLO.D.B. Operating Reactors Branch 2. B3/06/03. PARRIS.H. G. Tennessee Valley Authority. 2pp. 19529:334. 24X Fiche: 50-259. 83/06/03. 8307140150.
- BIO7140153 Forwards safety evaluation concluding requirements of TMI I tems II.F.1.4, "Containment Pressure Honitor," II.F.1.5, "Containment Water Level Honitor" & II.F.1.6, "Containment Hydrogen Honitor," web. Items resolved.

  VASSALLO.D.B. Operating Reactors Branch 2. 83/06/16. PARRIB, H. G. Tannessee Valley Authority. 7pp. 19540:041. 24X Fiche: 50-259.83/06/16.8307140153.
- HICHOPO70122 Application for amend to Licenses DPR-33, DPR-52 & DPR-48, requesting changes to Tech Spec Table 3.7. A to reflect correct valve positions for operating pressure suppression head tank sys. Justification encl. No fees necessary.

  MILLS.L.M. Tennessee Valley Authority. 83/06/24. DENTON, H. R. OPFice of Nuclear Reactor Regulation. Director. 2pp. 19294: 130. 24X Fiche: 50-259, 83/06/24, 8307070122.
- © 7060218 Informs that NUTECH analysis indicated that low-flow control mode & reactor water cleanup sys crosstic mod detailed in NUREG-0619, not required at facility. Vendor rept will be wubsitted by 830816.

  MIELES,L. M. Tennessee Valley Authority. 83/07/01. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19248:361. 24X Fiche: 50-259.83/07/01.8307060218.
- #206270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. #ISENAUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- 9307210030 Confirms 830701 discussion re processing of 830613 request for license amends modifying required surveillance interval for standby gas treatment sys testing Notice of consideration of issuance will be issued.

  VASSALLO.D. B. Operating Reactors Branch 2. 83/07/05. PARRIS.H. G. Transssee Valley Authority. 2pp. 19672:359. 24X.

  Fiche: 50-239, 83/07/05. 8307210030.

- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events, Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19469:269. 24X Fichs: 50-000, B3/07/08, 8307080169.
- B30712057D Forwards response to B30511 request for addl info re NUREO-0737, Item II. K. 3. 28, "Qualification of Automatic Depressorization Bys (ADS) Accumulators." ADS valves & squipment capable of performing function described in FBAR. MILLS, L. M. Tennessee Valley Authority, B3/07/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17433: 193, 24X Fiche: 50-259, 83/07/08, 8307120575.
- B307260032 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, revising Tech Space to clarify plant staffing & propose use of senior reactor operator trained in fuel handling for refueling.

  MILLS, L. M. Tennessee Valley Authority. B3/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19727; 116. 24X Fichs: 50-257, 83/07/19, 8307260932.
- --8307260041 Proposed revs to Tech Specs, clarifying plant staffing & proposing use of senior reactor operator trained in fuel handling for refueling Evaluation of significant hazards consideration enci.

  \* Tennessee Valley Authority. 83/07/18. 6pp. 19727:118. 24X Fiche: 50-259.83/07/18.8307260032.
- B307290109 Forwards results of tests verifying analyses performed to demonstrate adequacy of electrical distribution system voltages. Measured data not more than 390 below analytically predicted results. Actions complete.

  KAMMER, D. S. Tennesses Valley Authority. 83/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 4pp. 19822:035. 24X Fiche: 50-259, 83/07/22, 8307270109.
- B307270206 Forwards response to B30603 request for add1 info re NUREO-0737. Item 11. K. 3. 18, "Automatic Depressurization Sys Logic Mod." Proposed changes can be accomplished w/no loss of plant safety factor. Existing sys adequate. XAMMER. D. S. Tennessee Valley Authority. 63/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19821:144 24X Fiche: 50-259, 83/07/22, 8307270206.
- 8307280370 Clarifies need for expeditious handling of 030602 request to permit operation w/increased core flow. End-of-cycle coastdown begins wk of 830725. Hax power necessary due to demands created by unseasonably warm weather. KAMMER, D. 8. Tennesses Valley Authority. 83/07/25. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19796:105. 24X Fiche: 50-296.83/07/25.8307280370.
- 9. Inspection reports. IE Bulletine & correspondence
- B307140062 Advises that NRR & Region II final decision on B30201 request to change current fire door insp program to require monthly, instead of daily, visual insps & maint insps at 18-month intervals, expected within 30 days.

  LEMIS, R. C. Division of Project & Resident Programs. 83/02/17. PARRIS, H. G. Tennessee Valley Authority. 1p. 19514:121. 24X Fiche: 30-239,83/02/17,8307140062.
- 8307140340 Confirms 830316 telcon between JA Domer & FS Cantrell refire door insp & maint program at facility. Util will continue daily visual insp & semiannual maint insp program of all fire doors as outlined in 810403 itr.
  LEWIS R. C. Division of Project & Resident Programs. 83/03/25. PARRIS. H. G. Tennessee Valley Authority. 1p. 19323: 328. 24X Fiche: 50-259, 83/03/25, 8307140360.
- 8307140035 Forwards IE Insp Repts 50-259/83-20, 50-260/83-20 4 50-276/83-20 on 830524-27. No noncompliance noted. VERRELL I.D. M. Division of Project & Resident Programs. 83/06/16. PARRIS. H. O. Tennesses Valley Authority. 2pp. 19514: 211. 24X Fichs: 50-259, 83/06/16, 8307140035.
- --8307140041 IE Insp Repts 50-259/83-20.50-260/83-20 & 50-269/83-20 on 830524-27. No noncompliance noted Major areas inspected: inservice insp work & work activities data & evaluations. IE Bulletin 83-02 & licenses event followsp. COLEY, J. L., BLAKE, J. Region 2, Office of Director, 83/06/10. App. 19514: 213. 24X Fichs: 50-257,83/06/16,8307140035.
- 8307140046 Forwards IE Insp Repts 50-259/83-21, 50-260/83-21 t 50-296/83-21 on 830402-03. No noncompliance noted, VERRELLI, D.M. Division of Project t Resident Programs. 83/06/23. PARRIS, H.O. Tennessee Vailey Authority. 2pp. 19514: 220. 24X Fichs: 50-259,83/06/23,8307140046.

- --B307140053 IE Insp Repts 50-259/B3-21.50-260/B3-21 & 50-296/B3-21 on B30602-03. No noncompliance noted. Major areas inspected: licensee program for keeping radiation exposure ALARA. HOSEY, C.M., WRAY, J.R., BARR, K.P. Region 2, Office of Director. B3/06/23. 3pp. 19514:222. 24X Fiche: 50-239, B3/06/23, B307140046.
- 8307110639 Notification of 830706 mesting w/util in Bethesda. MD to discuss results of licensee insp of recirculation sys piping & proposed analysis & repair program. CLARK. D. Operating Reactors Branch 2. 83/06/30. VASBALLO. D. 8. Operating Reactors Branch 2. 19. 19371: 358. 24% Fiche: 50-259, 83/06/30. 8307110639.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list and.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York. Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11:8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 3306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." 8vc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14. 8306270406.
- C307220528 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations & deviation noted in IE Insp Rapts 50-2297/83-15, 50-260/83-15 & 50-296/83-15. LEHIB, R. C. Division of Project & Resident Programs. 83/07/15. PARRIS.H. Q. Tennessee Valley Authority. ip. 19685:009. 24X Fiche: 50-259, 83/07/15, 8307220528.
- --B307220533 Responds to NRC 830524 ltr re violations & deviation notad in IE Insp Repts 50-297/83-15, 50-280/83-15 & 50-294/83-15. Gorrective actions: schedule sys & plant procedures will be revised & machanical maint instructions will be revised. MILLS, L.M. Tennessee Valley Authority. B3/07/01. 0'REILLY, J. P. Region 2, Dfrice of Director. App. 19685:010. 24X Fiche: 50-259, 83/07/15, 8307220528.
- ~-8307220538 Forwards IE Insp Repts 50-299/83-15.50-260/83-15 & 50-296/83-15 on 830326-0415 & notice of violation.

  Description of actions to improve effectiveness of mgt control sys re mechanical maint area required.

  LEMIS.R.C. Division of Project & Resident Programs. 83/05/26.

  PARRIS.H.G. Tennessee Valley Authority. 2pp. 17685:016. 24X Fiche: 50-259.83/07/15,8307220528.
- ---8307220540 Notice of violation from insp on 830326-0425.

  \* Region 2, Office of Director. 83/05/26. 1p. 19685:018. 24X Fiche: 50-259, 83/07/15, 8307220529.
- ---B307220543 Notice of deviation from insp on B30326-0425. \* Region 2: Office of Director. B3/05/26. ip. 19685:019. 24X Fiche: 50-259, 83/07/15, 8307220528.
- --8307220547 IE Insp Repts 50-259/83-15, 50-260/83-15 & 50-294/83-15 on 830326-0425. Noncompliance noted: Faliure to follow procedures for RHR svc water functional test & to conduct insp of RHR svc water air vacuum valves during Unit 2 operating cycle. PAULK, O.L. Region 2, Office of Director. CANTRELL, F. S. Division of Project & Resident Programs. 83/05/10. 7pp. 19685:020. 24X Fiche: 50-259,83/07/15,8307220528.
- 8307230127 Forwards Rev 3 to integrated schedule re IE Bulletin 80-11, "Masonry Wall Design" mods. Rev 4 will be submitted in Jan 1984. MILLS. L. M. Tennesse Valley Authority. 83/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 12pp. 19706; 083. 24X Fiche: 50-257, 83/07/18, 8307250127.
- R. Periodic operating reports & related correspondence
- 8307220313 Monthly operating repts for Mar 1983. THOM, T. Tennassee Valley Authority, 83/04/01, 45pp. 19674:233. 24X Fiche: 50-259, 83/04/01, 8307220313.
- 8307220433 Monthly operating repts for May 1983. W/830610 ltr. THOM.T., COFFEY, J.A. Tennasses Valley Authority. 83/06/01. Office of Resource Management, Director. 41pp. 17687; 284, 24X Fishe: 50-289, 83/06/01, 8307220433.

- S. Reportable occurrences, LERs & related correspondence
- 8307120078 LER 83-033/03L-0: on 830601 diesel generator 3EA lube oil circulating pump motor tripped off. Caused by failure of motor bearings. Delco Model 12724-YI motor replaced. W/830630 ltr.
  CHRISTOPHER W., GREEN, H. J. Tennessee Valley Authority. 83/06/30, D'REILLY, J.P. Region 2, Office of Director. 3pp. 19423:144. 24% Fiche: 30-276.83/06/30, 8307120078.
- 8307220246 LER 83-036/03L-0: on 830618, two control rods indicated uncoupled by rod overtravel alarm. Caused by disconnected inner filter, damaged spud &/or crud accumulation. Control rod electrically disarmed. W/830715 ltr.
  WINDO.M.D., OREEN.M.J. Tennesuse Valley Authority, 83/07/15.
  Region 2: Office of Director. 3pp. 19684:196. 24X
  Fichs: 50-296.83/07/15,8307220246.
- 8307290487 LER 83-037/03L-0: on 830617; during normal steady-state operation, charging water for RHR & core spray switched from condensate head tank to PSC head tank w/charging water pressure falling to 42 psig. Sys restored. W/890714 1 tr. WINGO, M. D., OREEN, H. J. Tennessee Valley Authority. 83/07/15. U'REILLY, J. P. Region 2, Office of Director. 3pp. 19701: 214. 24X Piche: 30-296: 83/07/15. 8307230487.
- 8307260532 LER 83-035/03L-0: on 830620, while performing primary containment isolation valve operability test, valve FCV-69-2 would not fully close. Caused by valve operator motor breaker tripping due to armature winding failure. M/830719 ltm. CHRISTOPHER, W., GREEN, M. J. Tennessee Valley Authority. 83/07/19. greELLV, J. P. Region 2, Office of Director. 3pp. 17731:274, 24X Fiche: 50-296, 83/07/19, 8307260532.
- B307290083 LER B3-03B/03L-0: on B30624. while performing SI 4.2. F-6 (suppression chamber water temp), TI-64-55A temp indicator found out of tolerance. Cause not stated. Failure determined to be random occurrence. W/B30721 ltr. ODODWIN. D. C., GREEN, H. J. Tennessee Valley Authority. B3/07/21. 0'REILLY, J. P. Region 2, Office of Director. 3pp. 17822:201. 24X Fiche: 50-296,83/07/21,8307290083.
- 8307270230 NPDES noncompliance notification: on 830619, samples from emergency equipment cooling water sys contained excessive total residual chlorine concentrations. Caused by misaligned valve in chlorination injection sys.
  EL-ABHRY.M.T. Tennessee Valley Authority. 83/07/26. 3pp. 19822:028. 24X Fiche: 50-259, 83/07/26, 8307290230.

# V. Operator Examinations

- B307140269 Confirms B30506 telcon re Region II interpretation of medical restrictions explicitly entered on operator & senior operator liesness. Interpretation based on definition in ANBI N456-1976 (ANB-3.4).

  LEWIS,R. C. Division of Project & Resident Programs. B3/05/11. PARRIS.H. O. Tennessee Valley Authority. 2pp. 19522: 331. 24) Fiche: 50-259, 83/05/11. 8307140269.
- DOCKET 30-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR F. Security, medical, emergency & fire protection plans
- B307070161 Forwards Rev 3 to Pulstar reactor security plan,eliminating control room access keys. Rev withheld.

  BRAY.T.C. North Carolina State Univ. B3/05/16. THOMAS.C.O. Standardization & Special Projects Branch. 2pp. 19294: 259. 24X Fiche: 50-297.83/05/16.8307070161.

### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398. "Personal Gualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.83/07/11,8307080427.

#### DOCKET 30-298 COOPER NUCLEAR STATION

- F. Security, medical, emergency & fire protection plans
- 8307260514 Forwards IE Insp Rept 50-298/83-07 on 830404-07.No noncompliance noted.

  MADSEN.G. L. Region 4: Office of Director. 83/06/24. PILANT, J.M. Nebraske Public Power District. 20p. 19733:335. 24X
  Fiche: 50-298,83/06/24,8307260514.

- --830726053; IE Insp Rept 50-298/83-07 on 830404-07. No noncompliance noted Major areas inspected emergency procedures.

  HACKNEY.C.A., KELLY.J. Region 4. Office of Director. KENOYER.J. Battelle Memorial Institute, Pacific Northwest Laboratory.

  B3/06/24. Bpp. 19733:337. 24X Fiche: 50-298.83/06/24.8307260514.
- B307260280 Forwards IE Insp Rept 50-298/83-13 on B30509-13. No noncompliance noted.

  MADBEN.C.L. Region 4. Office of Director. B3/07/21. PILANT, J. M. Nebraske Public Power District. 2pp. 19726: 128. 24X Fiche: 50-298
- --8307260286 IE Insp Rept 50-298/83-13 on 830509-13. No noncompliance noted Major areas inspected: security organization response, keys & combinations, security sys power supply & lighting.
  Details withheld fref 100FR73. 211.
  CALDMELL.R.A., KELLY, J.A.F., HUNNICUTT, D.M. Region 4, Office of Director 83/07/22. 1p. 19726:130. 24X Fiche: 50-298,83/07/21,8307260280.

#### H. General correspondence

- 8307260410 Confirms 830426 telcon re P Thomason nomination as acting superintendent of facility.

  JONES C. R. Nebrasia Public Power District. 83/04/26. CQLLINS, J. T. Region 4. Office of Director. 1p. 19733:201. 24X
  Fiche: 50-298.83/04/26.8307260410.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307120407 Corrected Page D-2-15 of updated FSAR re safety-related (essential) sys covered by GA program. M/830505 ltr.
  PILANT.J.M. Nebrasta Public Power District. 83/05/05. COLLING, J. T. Region 4. Office of Director. 2pp. 19430:128. 24X
  Fiche: 50-298/83/05/05/8307120407.
- B307280073 Forwards Rev 1 to updated FSAR, incorporating Mark I containment program results.

  KUNCL.L.G. Nebraska Public Power District. 83/07/22. VABSALLG, D. B. Operating Reactors Branch 2. 2pp. 19794:161. 24X

  Ficha: 50-298, 83/07/22, 8307280073.
- --8307280093 Rev 1 to updated FSAR.

  \* Nebrasia Public Power District. 83/07/22. 455pp. 19794:163. 24X Fiche: 50-298.83/07/22.8307280073.
- P. Operating license stage documents & correspondence
- 8307120244 Submits updated progress rept & corrective actions re Mark i mod program steel plate problem. Rework on 70 supports planned. Final assessment of matl testing will be completed & reported in 821203 progress rept.
  PILANT.J.H. Nebraska Public Power District. 82/11/05. COLLINS.J.T. Region 4. Office of Director. 2pp. 17423:192. 24X Fiche: 50-298.82/11/05.8307120244.
- 8307120480 Submits final results & corrective actions re-steel plate problem involving Mark I mod program. Macro-etching results completely acceptable. Physical properties acceptable withree exceptions. Test results resulve concerns re-traceability. PILANT. J. M. Nebraska Public Power District. 82/12/03. COLLINS, J. T. Region 4. Office of Director. 2pp. 19425:062. 24X Ficha: 50-298, 82/12/03, 8307120480.
- 8307260361 Informs that while reviewing GA documentation & work packages provided by Dravo Util Constructors. Inc for Mark I, penetration welds performed by unqualified welders. OE NDT personnel will examine welds beginning 830418.

  PILANTIJ M. Nebraska Public Power District. 83/04/13. COLLING. J. Region 4. Dffice of Director. 2pp. 17733:036. 24X Fiche: 50-298.83/04/13.8307260361.
- 8307120404 Requests extension until 830425 to provide add1 info re updated FSAR, in response to 830415 telecopy.
  PILANT, J.M. Nebresta Public Power District. 83/04/15, COLLINB, J. T. Region 4, Office of Director. ip. 19430:255. 24X
  Fiche: 50-298,83/04/15,8307120404.
- B307120406 Requests 90-day extension to complete Mark I containment program due to ongoing evaluation & corrective measures for unacceptable welds.
  PILANTIJ.M. Nebraska Public Power District. 83/04/29.
  VASSALLO.D.B. Operating Reactors Branch 2. 2pp. 19430:126. 24x
  Fiche: 50-298, 83/04/29, 8307120406.
- B307260230 Confirms B30523 telcon request for 30-day time period to determine if LRS Consultants.inc "Mgt Appraisal Rept" dtd Apr 1983 contains proprietary info per 100FR2.790.
  JONES, C. R. Nebraska Public Power District. 83/05/23. MADSEN, Q. L., Region 4. Office of Director. 1p. 19727:187. 24X
  Fiche: 50-298, B3/05/23, B307260230.

- 8307140130 Forwards safety evaluation of BWR Owners Group response to NUREO-0737. Item II.K. 3.18. "Mod of Automatic Depressurization Bys Logic..." Two acceptable options include elimination of high drywell pressure permissive. VASBALLO.D.B. Operating Reactors Branch 2. 83/06/03. PILANT, J.M. Nebraska Public Power District. 2pp. 19328:347. 24X Fiche: 50-298.83/06/03.8307140130.
- B307260221 Requests extension until B30815 to submit util analysis of recommendations contained in LRS Consultants "Nuclear Mgt Appraisal Rept." Additime needed due to nature of rept & organizational changes.

  JONES, C.R. Nebraska Public Power District. B3/06/09. COLLING, J.T. Region 4. Office of Director. 2pp. 19727: 243. 24X
  Fiche: 50-298, 83/06/09, 8307260221.
- 8307110060 Advises that requirements of TMI Item II.K. 3.19, "HPCI/RCIC Initiation Level," met. Item resolved.
  VASBALLO, D. B. Operating Reactors Branch 2. 83/06/17, PILANT, J. M. Nebraska Public Power District. 2pp. 19387:001, 24X
  Fiche: 50-298, 83/06/17, 8307110060.
- 8307010126 Requests extension to comply w/deadline requirements for environ qualification of electrical equipment specified in 10CFR50.49, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants." PLANTI, J. M. Nebraska Public Power District. 83/06/24, VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19169:276. 24X Fiche: 50-298, 83/06/24, 8307010126.
- 8307050187 Forwards add1 fee for 821124 application for Tech Spec change approved as Amend 82, in response to NRC 830615 request. PILANT, J. M. Nebraska Public Power District. 83/06/27. DIGGB, R. M. License Fee Management Branch. ip. 19199:029. 24X Fiche: 50-298, 83/06/27, 8307050187.
- 8307260008 Forwards organizational charts depicting reorganized staff levels of nuclear power group. Changes will remedy mgt deficiencies.

  8CHAUFELBERGER Nebraska Public Power District. 83/07/01.
  COLLINS. J. T. Region 4. Office of Director. ip. 19727:179. 24X fiche: 30-278.83/07/01,8307260008.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT. D. Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000.83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fichs: 50-000,83/07/06,8307060329.
- B3070B0169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISEMMUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- B30725057B Submits more recent results of pipe cracking at BWRs to update Table 1 of SECY-83-267. DIRCKS: M.J. Office of the Executive Director for Operations, SECY-83-267A, 83/07/11, 4pp. 19716:347. 24X Fiche:50-000, 83/07/11,8307250578.
- B307180056 Application for amend to License DPR-46, consisting of proposed Tach Spec Change 5, permitting rallef from inservice insp requirements per 100FR50.55a(g). RUNCC, L. O. Nebraeka Public Power District. 83/07/12. VABSALLO, D. B. Operating Reactors Branch 2. 2pp. 19560:253. 24X Fiche: 50-298, 83/07/12, 8307180056.
- --8307180057 Proposed Tech Spec Change 5, permitting relief from inservice insp requirements per 10CFR30, 35a(g).

  \* Nebraska Public Power District. 83/07/12. App. 17540:255. 24X Fiche: 50-278,83/07/12,8307180056.
- 8307240433 Requests list of valves that perform pressure isolation function for RCPB re inservice testing program.List should identify valves by number, sys & coordinates, MADSEN,O.L. Region 4. Office of Director. 83/07/18. PILANT, J. M. Nebraske Public Power District. 2pp. 19731:278. 24x Fiche: 80-298,83/07/18,8307260433.

- 8307290193 Forwards discussion of implementation of NUREG-0737, Item II.K. 3.18, "Automatic Depressurization Sys Logic Mods," per 830803 request High drywell pressure permissive will be eliminated & manual inhibit switch added.
  PILANT, J. M. Nebraska Public Power District. 83/07/22.
  VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19821:146. 24X Fiche: 50-298, 83/07/22, 8307290193.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307120405 Forwards IE Insp Rept 50-298/83-10 on 830427-29,0504-13 & 23-27. No noncompliance noted.

  MADEEN, G. L. Region 4, Office of Director, 83/06/17, PILANT, J. M. Nebraska Public Power District. 2pp. 19430:256. 24X

  Fiche: 50-298.83/06/17,8307120405.
- --B307120414 IE Insp Rept 50-298/83-10 on B30427-27.0504-13 & 23-27. No noncompliance noted. Major areas inspected: inservice insp. actions taken in response to IE Bulletin B3-02 & review of evaluation & repair of Mark I mods.
  TUHLINSON.D.P., HUNNICUTT.D.M., WESTERMAN.T. Region 4, Office of Director. B3/06/16. 7pp. 19430:258. 24% Fiche:50-298.83/06/17,8307120405.
- 8307150303 Forwards IE Insp Rept 50-298/83-12 on 830501-31.No noncompliance noted.

  MADBEN.O.L. Region 4, Office of Director. 83/06/24. PILANT.J.M. Nebraska Public Power District. 2pp. 19532:287. 24X Fichs: 50-298,83/06/24,8307150303.
- --8307150315 IE Insp Rept 50-298/83-12 on 830501-31.No noncompliance noted Major areas inspected; operational safety varifications, monthly/refueling surveillance & maint observations & LER & IE bulletin followup, DUBOIS, D. L., WESTERMAN.T.F. Region 4, Office of Director, 83/06/21. 7pp. 19532:289. 24X Fiche: 50-298,83/06/24,8307150303.
- 8307260514 Forwards IE Insp Rept 50-298/83-07 on 830404-07. No noncompliance noted.

  MADBEN.O.L. Region 4. Office of Director. 83/06/24. PILANT, J. M. Nebraske Public Power District. 2pp. 19733: 335. 24X
  Fiche: 50-298.83/06/24.8307260514.
- --B307260531 IE Insp Rept 50-298/83-07 on 830404-07. No noncompliance noted. Hayor areas inspected; emergency procedures.

  HACKNEY.C. A., KELLY.J. Region 4. Office of Director. KENDYER.J. Battelle Memorial Institute, Pacific Northwest Laboratory.

  83/06/24. 8pp. 19733:337. 24X Ficha: 50-298.83/06/24.8307260514.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Dagrade Surry Rectrculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- B306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid," Svc list sncl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 14ipp. 17563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 830718003A Application for amend to License DPR-46, consisting of proposed Tech Spec Change 5, permitting relief from inservice insp requirements per 10CfR30.55a(g).

  XUNCL.L. Q. Nebraska Public Power District. 83/07/12. VASBALLO.D.B.

  Dperating Reactors Branch 2. 2pp. 19360:253. 24X

  Fiche: 50-298.83/07/12.8307180036.
- --8307180057 Proposed Tech Spec Change 5, permitting relief from inservice insp requirements per 10CFR50.55a(g).

  \* Nebraska Public Power District. 83/07/12. 4pp. 19560:255.
  24% Fiche: 50-296,83/07/12.8307180056.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl. TAYLOR, J. M. Division of GA, Bafeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19713:270. 24X Fiche: 50-000,83/07/14,8306270406.
- 8307260280 Forwards IE Insp Rept 50-298/83-13 on 830509-13.No noncompliance noted. MADSEN.G. L. Region 4: Office of Director. 83/07/2i. PILANT.J.M. Nebraska Public Power District. 2pp. 19726:128. 24X Fiche: 50-298/83/07/2i.8307260280.

- --8307260286 IE Insp Rept 50-298/83-13 on 830509-13. No noncompliance noted. Major areas inspected: security organization response, keys & combinations, security sys power supply & lighting. Details withheld (ref 10CFR73. 21).
  CALDHELL, R. A., KELLY, J. A. F., HUNNICUTT, D. M. Region 4, Office of Director. 83/07/22. ip. 19726:130. 24X Fiche: 50-298, 83/07/21, 8307260280.
- R. Periodic operating reports & related correspondence
- B307220184 Monthly operating rept for May 1983 W/830604 ltr. BALLINGER.P.L., THUMASON,P.V. Nabraska Public Power District. B3/06/04. Office of Resource Management. Director. 5pp. 19683:349. 24X Fiche: 30-298:83/06/04:8307220184.
- S. Reportable occurrences: LERs & related correspondence
- 8307R60397 Amended LER 82-014/03X-i:on 820607.rejectable indications found in heat affected zones of welds 8J-13, BJ-15, BJ-20 & BJ-23. Caused by improper fabrication techniques. Affected piping & fittings replaced. M/830203 ltr.
  FREBORO, S. S., LEBSOR, L. C. Nebraska Public Power District. 89/02/03, COLLING. J. T. Region 4, Office af Director. 5pp. 19733:043. 24X Fiche: 50-298,83/02/03,8307260357.
- B307120550 LER B3-00B/O3L-0: on B30530, HFA relay 9-17-16A K6B contacts failed to open Cause not determined Relay coil replaced. By stematic replacement of all relays within 4-yr period planned w/83062B ltr.
  JOBE, S. J., THOMABON, P. V. Nebraska Public Power District. B3/06/2B. COLLING. J. T. Region 4, Office of Director. 3pp. 17432: 130. 24X Fiche: 50-29B, B3/06/2B, B307120550.
- B307060122 PND-IV-B3-021: through-wall crack discovered in heat-affected area of weld connecting reactor water cleanup sys to RHR sys. OE will perform 100% ultrasonic test insp of reactor water cleanup sys welds.

  MEBTERMAN. T.F., MADSEN. G. L. Region 4. Office of Director. 83/06/30. ip. 19252: 223. 24% Fiche: 50-298.83/06/30.8307060122.
- 8307150213 LER 83-009/01T-0: on 830629, pinhole leaks found in heataffected zone of weld CNA-8J-2 during insulation removal on 6-inch reactor water cleanup suction line. Caused by intergranular stress corrosion cracking, W/830708 ltr. FREBORG. S.S., THOMASON.P.V. Nebrasta Public Power District. 83/07/08. COLLINS.J.T. Region 4. Office of Director. 10. 19530:088. 24X Fiche: 50-29B, 83/07/08, 8307150213.
- B30719000B PND-IV-83-024: two weaping leaks reported on reactor side of first isolation valve on core spray loop A. Visual exam indicates cracks may be circumferential. Detailed insp being performed.
  HUNNICUTT. D. H. Region 4. Office of Director. B3/07/11. ip. 19405.057. 24% Fiche: 80-298.83/07/11.8307190008.
- 8307260441 LER 83-010/03L-0: on 830617, during functional surveillance testing by Wyle Lab, one main steam snubber failed to meet bleed rate criteria & one svc water snubber failed to meet lockup rate. Caused by plugging by foreign mati. M/830715 ltr. BALLINGER, P. L., THOMASON, P. V. Nebraska Public Power District. B3/07/15. COLLING, J. T. Region 4, Office of Director. 3pp. 19731: 281. 24X Fiche: 50-278, 83/07/15, 8307260441.
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

  F. Security, medical, emergency & fire protection plans
- B307110339 Releases public version of revised emergency plan implementing procedures.
  FELTON.U.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19384: 262. 24X Fiche: 50-266.83/06/24. 8307110339.
- --8307110343 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1.3 re estimation of source term & EPIP 1.4 re radiological dose evaluation. Receipt form encl.
  FAY, G. W., KNORR, J. E., Hisconsin Electric Power Co. 83/06/15. DENTON. H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp. 19384: 263. 24x Fichs: 50-266, 83/06/24, 8307110339.
- --B307i10348 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1. 3 re estimation of source term & EPIP 1.4 re radiological dose evaluation.

  \* Wisconsin Electric Power Co. B3/05/27. 44pp. 19384:266. 24X Fiche: 50-266.83/06/24.8307110339.

- 8307110480 Ack receipt of 830628 ltr amending 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-246/82-17 & 50-301/82-17.

  SPESSARD.R.L. Division of Engineering. 83/07/06 BURNSTEIN, S. Hisconsin Electric Power Co. 1p. 19380:169. 24X Fiche: 50-266, 83/07/06, 8307110480.
- --8307110487 Suppls response to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17. Corrective actions: transient combustible control procedure developed, however implementation delayed until 830730.

  FAY.C. W. Wisconsin Electric Power Co. 83/06/28. KEPPLER, J. G. Region 3. Uffice of Director. 3pp. 19380:170. 24X
  Ficha 50-266.83/07/06.8307110480.
- B307260335 Itemises clarification of encl to B30428 ltr re request for App R fire protection exemptions, including revised description of proposed plant mods to Fire Zones 1-4. FAY.C.W. Wisconsin Electric Power Co. B3/07/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pc. 19726:090. 24X Fiche: 50-266.83/07/20,8307260335.

#### G. Adjudicatory correspondence

- B307180175 Notifies of VR Harding employment at law firm per Disciplinary Rule 9-102. Harding will not participate in any case currently pending before NRC. RIDGMAY.D.A. Shaw, Fittman, Potts & Troubridge. 83/07/13. MOGRE, T.S., JOHNSON, W.R., GDTCHY.R.L. Atomic Safety and Licensing Appeal Panel. 1p. 19355:068. 24X Fiche: 50-246, B3/07/13, B307180176.
- --8307180183 Notifies of author employment at law firm per Disciplinary Rule 9-102 Author will not participate in any case currently pending before NRC.
  HARDING V. R. Shaw, Pittman, Potts & Trowbridge, 83/07/13, MOORE T. S., JOHNSON, W. R., GUTCHY, R. L., Atomic Safety and Licensing Appeal Panel. 3pp. 19555:069, 24X Fiche: 30-266, 83/07/13, 8307180176.
- K. Utility Final Safety Aπalysis Report (FSAR) & amends
- 8307260439 Forwards Rev I to updated FSAR. FAY.C.W. Wisconsin Electric Power Co. 83/07/18. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 1p. 19778:328. 24X Fiche:30-266.83/07/18.8307260439.
- --8307270382 Rev 1 to updated FSAR.

  \* Wisconsin Electric Power Co. 83/06/30. 436pp. 19778:329. 24X
  Fiche:50-266:83/07/18:8307260439.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Quifelines." Svc list encl.
  EISENMUT. D. 9. Division of Licensing 83/06/03. Yankee Atomic Electric Co. 10pp. 19363:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307050246 Advises that new core characteristics remain less limiting than previously accepted values, due to replacement of two fuel assemblies from spent fuel pool Conclusions in 830203 ltr remain valid re Cycle 10 reload.
  FAY.C.W. Wisconsin Electric Power Co. 83/06/24. DENTON, H. R. Office of Nuclear Reactor Regulation Director. CLARK, R. A. Openating Reactors Branch 3. 1p. 19197:213. 24X Fiche: 50-301, 83/06/24, 8307050246.
- 8307070021 Advises that installation & calibr of SA-11 monitors complete & monitors fully operational per TMI Item II.F. 1.1. Integration of instruments into other plant operating & emergency procedures & operator training incomplete. FAY.C.W. Wisconsin Electric Power Co. 83/06/29. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19293:232. 24X Fiche: 50-266, 83/06/29, 83070700021.
- 8307070113 Informs of no significant changes to electrical distribution—sys described in FBAR which would affect degree of conformance w/ODC-17. Available info adequate to determine intent of ODC-17 we offsite power distribution sys. FAY, C. W. Wisconsin Electric Power Co. 83/06/30, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3: 1p. 19294-094. 24X Fiche: 50-266.83/06/30, 8307070113.

- 8307190395 Forwards for review & comments. "Control of Heavy Loads (C-10).Point Beach Units 1 & 2." updated draft technical swaluation rept.
  CLARK.R.A. Operating Reactors Branch 3. 83/06/30. FAY,C.W. Wisconsin Electric Power Co. 2pp. 19540:103. 24X Fiche:50-266.83/06/30.8307150375.
- --8307070592 "Control of Heavy Loads (C-10).Point Beach Nuclear Plants Units 1 & 2," draft final technical evaluation rept.

  BDMBERGER,C., AHMED,N. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-382/383 DR. 83/06/17.

  SINCH,A., CHAN.T. NRC No Detailed Affiliation Given. 56pp. 19540:105. 24X Fiche: 50-266,83/06/30,8307150395.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list enci. EISENHUT, D. 0. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT. D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060327.
- 8307130226 Requests extension until 830930 to complete response to questions from 820602 & 03 meetings re development of final radiological effluent Tech Specs submittal using meeting summary & draft Rev 3 to NUREO-0472 as guidance.
  FAY.C.W. Wisconsin Electric Power Co. 83/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19473: 288. 24X Fiche: 50-264,83/07/06,8307130226.
- 8307130220 Provides correction to Table 1.8-1.1tem 13 of 830610 rev to Saction 1.8 of updated F8AR re QA program. Commits to follow Reg Quide 1.146 for audits of in-plant activities per Queric Ltr 81-01.
  FAY.C.M. Wisconsin Electric Power Co. 83/07/07. KEPPLER, J. G. Region 3. Office of Director. 1p. 19474:346. 24X Fiche: 50-266.83/07/07,8307130220.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events 8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269. 24X Fiche: 30-000, 83/07/08, 8307080169.
- 8307250157 Confirms 830627 telcon re results of heat balance calculations of containment atmosphere temp calculations. Post-accident containment sampling procedure will be modified to include 10 minute sampling period. FAY.C.W. Wisconsin Electric Power Co. 83/07/12. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19706:108. 24X Fiche: 50-266.83/07/12.8307250157.
- B307220356 Forwards "Nuclear Environ Qualification Test Program on Foxboro N-E10 Beries Pressure Transmitters: " Vols I-III. Results should be reviewed per qualification requirements of NUREO-0598 & 100FR90.49.
  FAY.C.W. Wisconsin Electric Power Co. 83/07/15. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. NDONAN, V. 8. Equipment Qualification Branch. 2pp. 19676: 120. 24X Fiche: 50-266, 83/07/15, 8307220356.
- --8307220359 "Nuclear Environ Qualification Test Program on Foxboro N-E10 Series Pressure Transmitters." Vols I-III. GAMBLIN.L., JOHNBON.F.R., ROBERTS,W.B. Wyle Laboratories. 4559-4. B3/05/18. 1620pp. 19676:123. 24X Fiche: 30-266. 83/07/15.8307220356.
- 8307270145 Forwards for for 830113 application re ASME Section XI relief, in response to NRC 830708 request.
  FAY.C.W. Hisconsin Electric Power Co. 83/07/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. DIOGS.R.M. License Fee Management Branch. ip. 19822:002. 24X Fiche: 50-301, 83/07/20, 8307270145.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307180044 Forwards IE Insp Repts 50-266/83-08 & 50-301/83-08 on 830509-11 & 0609 & notice of violation.

  PAPERIELLO,C. J. Region 3, Office of Director. 83/07/01.

  BURSTEIN,S. Wiscomain Electric Power Co. 2pp. 19360: 234. 24X Fiche: 50-266.83/07/01.8307180044.

- --8307180045 Notice of violation from insp on 830509-11 & 0609.

  PAPERIELLO, C. J. Region 3, Office of Director. 83/06/30. 2pp 19560: 236. 24% Fiche: 50-266, 83/07/01, 8307180044.
- --8307180047 IE lnsp Repts 50-266/83-08 & 50-301/83-08 on 830509-11 & 0.609. Noncompliance noted: failure to collect air samples on 830331 during reactor vessel head removal & cavity flood operations & to install SA-11 main steam line monitors. LOVENDALE.P.C., GREGER.L.R. Region 3, Office of Director. 83/06/30. 8pp. 19360:238. 24X Fiche 30-266.83/07/01.8307180044.
- 8307110480 Ack receipt of 830628 ltr amending 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17.

  SPESSARD.R.L. Division of Engineering. 83/07/06. BURNSTEIN.S. Historish Electric Power Co. ip. 19380:169. 24X Fiche: 50-266.83/07/06.8307110480.
- --8307i10487 Suppls response to NRC B21130 itr re violations noted in IE Insp Repts 30-266/82-17 & 50-301/82-17. Corrective actions: transient combustible control procedure developed, however implementation delayed until 830930.

  FAY.C.W. Wisconsin Electric Power Co. 83/06/28. KEPPLER.J. G. Ragion 3, 0ffice of Director. 3pp. 19380:170. 24X Fiche: 50-266,83/07/06:8307110480.
- 8307190372 Requests remittance of Class III fee for 830113 request for relief from ASME Section XI inservice insp requirements. BIQOS,R.M. License Fee Management Branch. 83/07/08. FAY,C.W. Hisconsin Electric Power Co. 1p. 17656:046. 24X Fiche: 50-301,83/07/08,8307190372.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:273. 24X Fiche: 50-000, 83/07/11, 8306270401.
- B306270404 IE Info Notice B3-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list uncl. JDRDAN.E.L. Division of Emergency Proparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:133. 24X Fiche: 50-000,83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8308270406.
- 8307290371 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-03 & 50-301/83-03 Mods to HVAC filter maint & testing program desirable to ensure radiation doese maintained ALARA. HIND J. A. Division of Radiological & Materials Safety Programs. 83/07/20. BURSTEIN S. Wisconsin Electric Power Co. 1p. 19704:002. 24X Fiche: 50-266.83/07/20.8307250371.
- R. Periodic operating reports & related correspondence
- B307150066 Monthly operating repts for June 1983.W/830711 ltr. FAY.C.W. Wisconsin Electric Power Co. B3/07/07. Office of Nuclear Reactor Regulation, Director. 9pp. 19548:187. 24X Fiche: 50-266.83/07/07,8307150066.
- S. Reportable occurrences, LERs & related correspondence
- B307190174 LER B3-008/01T-0:on B30617, during refueling, containment air radiation monitoring sys inoperable. Caused by failed sample pump due to blown fuse in data acquisition monitor circuit. Instrumentation repaired. W/B30705 ltr. FAY.C. W. Wisconsin Electric Power Co. B3/07/05. KEPPLER, J. O. Region 3. Office of Director. 4pp. 17634: 241 24X Fiche: 50-301, 83/07/05, 8307190174.
- B307220210 LER 83-004/01T-0:on B30409 during Type B & C leakage test, total as-found leakage exceeded Tach Spec limit Valve 755A stuck open causing leakage.Followup valve maint did not identify cause of failure.W/B30715 ltr. FAY.C.H. Wisconsin Electric Power Co. B3/07/15 KEPPLER, J. G. Region 3, Office of Director. 4pp. 19684:071. 24X Fiche: 50-301,83/07/15,8307220210.

- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
  F. Security, medical, emergency & fire protection plans
- 8307140050 Ack receipt of 821117 1tr re emorgency exercise scheduled for 830222 % 23. Exercise objectives discussed w/L Hill of util. Addi comments await receipt of complete exercise scenario STOHR, J. P. Division of Emergency Preparedness & Materials Safety, 83/01/27. HANCOCK, J. A. Florida Power Corp. 1p. 19314:142. 24X Fiche: 50-302, 83/01/27, 8307140050
- 8307140414 Forwards IE Insp Rept 50-302/83-04 on 830214-18 % notice of violation.

  LEWIS, R.C. Division of Project & Resident Programs. 83/03/23.

  HANCOCK, J. A. Florida Power Corp. 2pp. 19521-118. 24X

  Fiche: 30-302,83/03/23,8307140414.
- --B307140416 Notice of violation from insp on 830214-18.

  \* Region 2, Office of Director. 83/03/23, ip. 19521:120. 24X
  Fiche 50-302,83/03/23,8307140414.
- ---8307140421 IE Insp Rept 50-302/83-04 on 830214-18 Noncompliance noted failure of licensed personnel to read abnormal & emergency procedures.

  BELISLE.G.A., DEBDAGE, A.G., SKINNER, P.H. Region 2, Office of Director. 83/03/18. 13pp. 19521-121. 24X Fiche: 50-302, 83/03/23, 8307140414.
- 8307140265 Informs that Boise Interagency Fire Ctr contracted to perform surveys of radiofrequency & electromagnetic interference. Assistance requested. VERRELLI.D.M. Division of Project & Resident Programs. 83/05/3 WILGUS.W.S. Florida Power Corp. 23pp. 17522:339 24X Fiche: 50-302:83/05/31,8307140265.
- 8307140294 Advises that review of Rev 2 to radiological emergency response plan indicates emergency plan continues to meet iOCFR50. 47(b) planning stds.

  DANCE, H. C. Division of Project & Resident Programs. 83/06/22.

  WILCOUS. W. S. Florida Power Corp. 2pp. 19925:099. 24X

  Fiche: 50-302.83/06/22.8307140294.
- 8307210240 Forwards IE Insp Rept 50-302/83-11 on 830426-0520.No noncompliance noted. DANCE,H C. Division of Project & Resident Programs. 83/07/01. WILCUS.W S. Florida Power Corp. 2pp. 19664:167. 24X Fiche:50-302,83/07/01
- --8307210275 IE Insp Rept 50-302/83-ii on 830426-0520. No noncompliance noted Major areas inspected; plant operations, security, radiological controls. LERs & nonconforming operations repts & action on previous insp items.

  STETKA: T. F. Region 2. Office of Director PANCIERA: V. Division of Project & Resident Programs. 83/07/01. iOpp. 1964:169. 24X Fiche: 50-302, 83/07/01. 8307210240.
- 8307150333 Advises that Reg Guide 1.97, Rev 3. supersedes Rev 2 referenced in Generic Ltr 82-33 (NUREO-0737, Suppl 1) re emergency response capability.

  WESTAFER, G. R. Florida Power Corp. 83/07/12. STOLZ, J. R. Operating. Reactors Branch 4. lp. 17538:334 24X Fiche: 50-302, 83/07/12, 8307150333.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B3070B0275 Rev 3 to updated F5AR.W/B30701 ltm.
  WESTAFER.G.R. Florida Power Corp. B3/07/01. DENTON.H.R. Office of
  Nuclear Reactor Regulation. Director. 170pp. 1934B:026. 24X
  Fiche: 30~302.B3/07/01, B307080275.
- P. Operating license stage documents & correspondence
- B307120495 Forwards updated FSAR Section 1.7, describing quality program for operational phase, per 10CFR30.54(a)/(2). Info will be incorporated into next updated FSAR annual rev. Justification encl.

  WEBTAFER, G. R. Florida Power Corp. B3/06/10. O'REILLY, J. P. Region 2, Office of Director. 78pp. 19424:285. 24X Fiche.50-302,83/06/10. B307120495.
- B307110616 Monthly notice of amends to OLs involving NGHC issued since 830923. CLARK,R.A. Operating Reactors Branch 3 83/06/14. 26pp. 19391:152. 24X Fiche: 50-000.83/06/14.8307110616.

- 8307060478 Denies util 830331 Tech Spec Change Request 82, extending intervals between surveillances for Cycle 5 operation to 24 months to correspond w/longer fuel cycle Reasons for denial discussed
  LAINAS.G.C. Assistant Director for Operating Reactors. 83/06/20.
  WILGUS.W.S. Florida Power Corp. 3pp. 19299;121. 24X
  Fiche:50-302.83/06/20.8307060478.
- 8307070031 Application for Tech Spec Change Request 82 to License DPR-72, amending shutdown margin. Attachments C & E encl. per 830331 submittal. W/Certificate of Svc. WESTAFER, G.R. Florida Power Corp. 83/06/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 17273: 266. 24X Fiche: 50-302, 83/06/22, 8307070031.
- --B307070033 Proposed Tech Spec changes re shutdown margin \* Florida Power Corp. 83/06/22. 73pp. 19293:271. Fiche: 50-302.83/06/22.8307070031.
- 8307060227 Notifies that submittal of generic program w/8&H Dwners Group: in support of revised manual reactor coolant gump trip criteria per NUREG-0737. Item II. K. 3.5, deleyed until 830930. WESTAFER, G. R. Florida Pawer Corp. 83/07/01. EISENHUT. D. G. Division of Licensing. 1p. 17249: 034. 24X Fiche: 50-302, 83/07/01, 8307060227.
- 8306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp 19390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254, 24X Fiche: 50-000. 83/07/06. 8307060329.
- 8307110447 Forwards add1 info in support of Tech Spec Change Request 82 re Cycle 5 aperation w/reactor coolant pump power monitors (RCPPM) per 830701 request Testing of all RCPPM strings prior to startup will consist of checking time delays.
  WESTAFER.G.R. Florida Power Corp. 83/07/06. DENTON, H.R. Office of Nuclear Reactor Repulation, Director. 17pp. 19380:200. 24X
  Fiche: 50-302,83/07/06.8307110447.
- B307120370 Forwards record sheets & justification for continued operation w/four motor operated valves DHV-5.DHV-6.DHV-34 & DHV-35, assuring that plant can be safely operated until new motors received & installed.per B30520 commitment.
  WESTAFER.9.R. Florida Power Corp. 83/07/06. STQL7.J.F. Opera Reactors Branch 4. 9pp. 19429:039. 24% Fiche:50-302.83/07/06, 8307120370.
- 8307120552 Requests continuance of relief from test requirements per B30701 telcon. Interim relief from testing until Refuel IV granted in Amend 61 may be extended until Refuel V or until approval of Request 105.
  WESTAFER. C.R. Florida Power Corp. 83/07/06. DENYON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19432:128. 24X Fiche: 50-302,83/07/06,8307120552.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL. & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche:50-000.83/07/08.8307080169.
- 8307180393 Nutification of 830713 meeting w/util in Bethesda, MD to discuss licensee amend application re frequency of ESF testing.

  HERNAN, R. Operating Reactors Branch 4. 83/07/12. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19641; 284. 24X Fiche: 50-302, 83/07/12, 8307180393.
- 8307200465 Forwards Amend 64 to License DPR-72 & safety evaluation. Amend extends 18-month surveillance requirements to 24 months to correspond to extended core lifetime for Cycle 5. STOLZ.J.F. Operating Reactors Branch 4. 83/07/12. WILCUB, W.S. Florida Power Corp. 3pg. 19672:086. 24X Fiche:50-302,83/07/12,8307200465.
- --8307200469 Amend 64 to License DPR-72, extending 18-month surveillance requirements to 24 months to correspond to extended core lifetime for Cycle 5. STOLZ.J.F. Operating Reactors Branch 4. 83/07/12. 66pp. 19672:089. 24X Fiche: 50-302, 83/07/12, 8307200465.

- --8307200471 Safety evaluation supporting Amend 64 to License DPR-72.

  \* Office of Nuclear Reactor Regulation, Director. 83/07/12.
  17pp. 19672:196. 24% Fiche:50-302,83/07/12,8307200465.
- 8307250471 Supplemental application for amend to License DPR-72, consisting of Tech Spec Change Request 105, re ESF actuation sys testing requirements. Proposed significant hazards evaluation encl.

  WESTAFER.G.R. Florida Power Corp. B3/07/14. DENTON, H.R. Office of Nuclear Regulation. Director. 7pp. 19701: 234. 24X

  Fiche: 50-302,83/07/14,8307250471.
- B307210209 Forwards conceptual design, overall schedule for angineering, procurement & installation & NRC checklist for compliance \( \omega / \) NUREQ-0737, Item II. F. 2. Approval of conceptual design & NRC checklist requested by B30902.

  WESTAFER, O. R. Florida Power Corp. 83/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 43pp. 17665:068. 24X Fiche: 30-302, 83/07/18, B307210209.

#### Q. Inspection reports, IE Bulletins & correspondence

- 8307140246 Informs that liquid samples spiked w/radionuclides will be sent to facility for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analysed for tritium ST-89 & ST-90 content within 60 days.

  LENIS.R.C. Division of Project & Resident Programs. 83/02/07. HANCOCK, J.A. Fiorida Power Corp. 1p. 19523:051. 24X Fiche: 30-302,83/02/07,8307140246.
- 8307140414 Forwards IE Insp Rept 50-302/83-04 on 830214-18 & notice
- --B307140416 Notice of violation from insp on B30214-18.

  \* Region 2, Office of Director. B3/03/23, 1p. 19521:120. 24X
  Fiche:50-302,83/03/23,8307140414.
- --8307140421 IE Insp Rept 50-302/83-04 on 830214-18.Noncompliance noted: failure of licensed personnel to read abnormal & emergency procedures. procedures.

  BELISLE.G. A., DEBBAGE, A. G., SKINNER, P. H. Region 2, Office of Director, 83/03/18. 13pp. 19521: 121. 24X Fiche: 50-302, 83/03/23, 8307140414.
- 8307060319 Forwards full payment of fees as result of IE insps conducted from Mar 1982 Mar 1983. WESTAFER.O.R. Florida Power Corp. 83/07/01. License Fee Management Branch. 2pp. 19239:177. 24X Fiche: 50-302.83/07/01. 8307060319.
- 8307210240 Forwards IE Insp Rept 50-302/83-11 on 830424-0520. No noncompliance noted.
  DANCE, H. C. Division of Project & Resident Programs. 83/07/01.
  WILCUS. M. S. Florida Power Corp. 2pp. 19664:167. 24X
  Fiche: 50-302.83/07/01,8307210240.
- --B307210275 IE Insp Rept 50-302/83-ii on B30426-0520. No noncompliance nated. Major areas inspected: plant operations, security, radiological controls, LERs & nonconforming operations repts & action on previous insp items.

  BTETKA, T. F. Region 2, Office of Director. PANCIERA, V. Division of Project & Resident Programs. B3/07/01. 10pp. 19664: 169. 24% Fiche: 50-302, 83/07/01. 8307210240.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Bubsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11,8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid," Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153 24X Fiche: 50-000.B3/07/12.B306270404.
- 8307250702 Forwards notice of granting relief from seven listed ASME inservice inso code requirements in response to 830314 & 25 requests.
  STOLZ: J.F. Operating Reactors Branch 4, 83/07/13, WILQUS, W.S.
  Florida Power Corp. 6pp. 19720:143. 24X Fiche: 50-302, 83/07/13,
- ~-8307250706 Notice of granting relief from ABME code inservice insprequirements, in response to 830314 & 25 requests.
  STOLZ-J.F. Operating Reactors Branch 4. 83/07/13. 2pp.
  19720:149. 24X Fiche: 50-302, 83/07/13, 8307250702.

- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits," Svc list encl.

  TAYLDR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- R. Periodic operating reports & related correspondence
- B30715008B Monthly operating rept for June 1983.W/B30711 ltr.
  BUGART.D., WESTAFER,G.R. Florida Power Corp. 83/07/11.
  DEYOUNG.R.C. Director's Office, Office of Inspection and
  Enforcement. 3pp. 19536.09B. 24% Fiche: 50-302.83/07/11,830715008B.
- S. Reportable occurrences, LERs & related correspondence
- 8307120249 LER 83-023/017-0: on 830613, fire damper FD-86, in duct work between auxiliary bldg & control complex, discovered missing. Cause unknown. Cantinuous fire watch established Evaluation underway. W/B30627 ltr.

  8UFE. J. L. , HUGHES, P. G. , MODRE, G. C. Florida Power Corp. 83/06/27. D'REILLY J. P. Region 2. Office of Director. 3pp. 17423:038. 24) Fiche: 50-302, 83/06/20, 8307120249.
- 8307250127 Updated LER 82-037/03L-1: on 820510 & 21, leak discovered at weld penetration on McV-272. On 820531, leak discovered at weld penetration on McV-283. Caused by vibration of makeup sys. Supports/restraints added in sys piping. W/830706 1tr.
  THOMPSON.R.H., WESTAFER.G.R. Florida Power Corp. 83/07/06.
  O'REILLY, J. P. Region 2, Office of Director. 4pp. 19706: 041. 24X Fiche: 50-302, 83/07/06, 8307250129.
- 8307250185 Updated LER 82-013/03L-1: on 820228, leak discovered on pressure side of MUV-292 in heat affected area of weld. Caused by vibration. Supports/restraints added to makeup sys. Vibration eliminated. W/830706 ltr.
  THCMPSON-R. H. , WESTAFER, G. R. Florida Power Corp. 83/07/06. 0'REILLY, J.P. Region 2, Office of Director. 4pp. 19705: 354. 24X Fiche: 50-302, 83/07/06, 8307250185.
- 8307220254 Updated LER 83-018/01T-1: un 830413, preliminary repts received from 84W indicated 51 of 120 upper core barrel bolts w/ultresunic flaw indications. Caused by intergranular stress corrosion cracking Bolts replaced W/830712 ltr. BUFE. J. L. : THOMPSDN.R. H. : WESTAFER. G. R. Florida Power Corp. 83/07/12. 0', REILLY, J. P. Region 2, Office of Director. 5pp. 19684: 202. 24X Fiche: 50-302, 83/07/12, 8307220254.
- 8307250483 Updated LER 82-002/03L-i: on 820106, after removing MUP-1B pump casing by MP-126, discovered pump casing was seismic anchor. Caused by failure of Procedure MP-126 to identify required spismic evaluation. Maint procedure revised.

  BROWN.C. G., WEBTAFER, G. R. Florida Power Corp. 83/07/13.

  0'REILLY, J. F. Region 2, Office of Director. 3pp. 19701: 276. 24X Fiche: 50-302, 83/07/13, 8307250483.
- 8307290184 Updated LER 83-023/01T-1: on B30613, fire damper discovered missing Approx 55 add1 dampers & chase connecting control complex 108 & 165 ft elevations degraded due to incorrect fire rating. Caused by personnel error. W/830720 ltr.
  BUFE, J. L. . HUQKES, P. O. . MESTAFER, G. R. Florida Power Corp. 83/07/20. 0'RELLY, J. P. Region 2: Office af Director. 4pp. 19822: 052. 24X Fiche: 50-302, 83/07/20, 8307290184.
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2
  F. Security, medical, emergency & fire protection plans
- 8307120058 Releases public version of rev to emergency plan implementing procedure, FELTON.J.M. Division of Rules and Records. 83/06/24, Document Management Branch. 1p. 19435:267. 24X Fiche:50-304,83/06/24, 8307120058.
- --8307120064 Public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 420-1, "Technical Support Ctr Guarterly Surveillance," W/830519 itr.
  NYKIRK, J. W. Commonwealth Edison Co. 83/05/17. DENTON, H. NRC -- No Detailed Affiliation Given. 6pp. 19435: 268. 24X Ficha: 50-304,83/06/24,8307120058.
- 8307080301 Recommends imposition of civil penalty in amount of \$10,000 for violations found during special safeguards insp on 830315. Util 830609 response provides no basis for further mittgation. Draft itr to licensee enci.
  8CHULTZ.W.H. Region 3, Office of Director. 83/07/03. AXELRAD.J.A. Enforcement Staff. 4pp. 19350:185. 24X Fiche: 50-295.83/07/05.8307080301.

- 8307110131 Confirms 830705 telcon between F Lentine & M Holzmer re 830708 security enforcement meeting at Region III ofcs to review 830615 breach of security event & corrective actions to prevent recurrence.

  KEPPLER. J G. Region 3, Office of Director. 83/07/05, REED.C. Commonwealth Edison Co. 1p. 19375:125 24X Fiche:50-295,83/07/05,83071/0131
- B307120391 Notifies that request for license amends to clarify responsibility of licensee during emergencies withdrawn. Addition of Paragraphs x & y to 10CFR50.54 provided necessary clarification.

  LENTINE.F. G. Commonwealth Edison Co. 83/07/06, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19430:142. 24X Fiche: 50-295.83/07/06.8307120391.
- 8307280266 Forwards IE Insp Repts 90-295/83-09 % 50-304/83-09 on 830613-17 No noncompliance noted. PAPERIELLO.C.J Division of Emergency Preparedness & Operational Support 83/07/12. REED.C. Commonwealth Edison Co. 2pp. 19791:341. 24% Fiche: 50-295,83/07/12.8307280266.
- --8307280274 IE Insp Repts 50-295/B3-09 & 50-304/B3-09 on B30613-17. No noncompliance noted, Major areas inspected: emergency preparedness program including licensee actions on praviously identified items.
  PHILLIPS M.P. Region 3. Office of Director. 83/07/08. 18pp. 19791: 343. 24x Fiche: 50-295, 83/07/12, 8307280266.
- 8307290293 Releases public version of Rev 3 to emergency plan implementing procedure. FELION.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19858:163. 24% Fiche:50-295,83/07/19. 8307290293.
- --8307290299 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP 140-1, "Maint Director Emergency Plan Implementing Procedure." Receipt form \$630621 ltr encl. NYKIRK.J.W. Commonwealth Edison Co. 83/06/20. DENTON,H.R. NRC ~ No Detailed Affiliation Given. 5pp. 19898:164. 24X Fiche: 50-295.83/07/19.8307290293.
- 8307260018 Submits supplemental response to NUREG-0737, Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by B31231. Human factors & safety parameter display sys verification to be performed w/verification program. SMARTZ.E.D. Commonwealth Edison Co B3/07/20 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp. 19727:177. 24X Fiche: 50-000, 83/07/20, 8307260018.
- 8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLO.C.J. Region 3. Office of Director. 83/07/26. REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 50-000, 83/07/26, 8307280347.
- 9. Adjudicatory correspondence
- B307120395 Advises that time for Commission to review Director's Decision DD-83-8 expired Commission declined review Decision became final agency action on B30705. CHILK.B. J. Office of the Secretary of the Commission. B3/07/11. GUIGO.C. Pollution & Environmental Problems, Inc. 1p. 19433:076. 24X Fiche: 50-000, 83/07/11. 8307120595.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010195 Forwards amends to updated FSAR for facilities. 9TIEDE:W.L. Commonwealth Edison Co. 83/06/29. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19123:001. 24K Ficho: 50-000.83/06/29, 8307010195.
- --8307010196 Rey 1 to updated FSAR for Zion Station 1 & 2. \* Commonwealth Edison Co. 82/12/3t. 66pp. 19123:003. 24x Fiche: 50-000: 83/06/29: 8307010195.
- P. Operating license stage documents & correspondence
- B304040070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.

  EISENNUT.D. 0. Division of Licensing. B3/04/03. Yankee Atomic Electric Co. 10pp. 17543:116. 24X Fiche: 50-000, B3/06/03. B306040070.

- 8307270343 Forwards request for add1 info clarifying 820716 response re ATMS. Trip of main feed pumps will cause main turbine to trip. however, unclear exactly what loss of feedwater events would lead to turbine trip VARQA. S. A. Operating Reactors Branch 1. 83/06/23, FARRAR. D. L. Commonwealth Edison Co. 8pp. 19802:348. 24X Fiche: 50-295, 83/06/23, 8307270343.
- B30A270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York Inc. Lépp. 19370:317. 24X Fiche: 50-000, 83/07/05, 830A270397.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 875 Svc list encl. EISENHUT.D.G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fichs: 50-000, 63/07/06. B307060329.
- 8307120391 Notifies that request for license amends to clarify responsibility of licensee during emergencies withdrawn.
  Addition of Paragraphs x & y to 10CFR30.54 provided necessary clarification.
  LENTINE, F. G. Commonwealth Edison Co. 83/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19430:142. 24X Fiche: 50-295, 83/07/06, 9307120391.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENWIJ.D.O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-600,83/07/08.8307080169.
- 8307280375 Discusses plans for upgrading core exit thermocouples, supplementing 830319 response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys. Upgrading of field cable & ref junction boxes under evaluation. LENTINE.F.G. Commonwealth Edison Co. 83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. [p. 19796:104. 24X Fiche: 50-295,83/07/14,8307280375.
- 8307280482 Forwards draft of review rept for Zion Probabilistic Safety Study, Vols 1 & II. Comments requested by B30812. W/o encl. VARGA: B. A. Operating Reactors Branch 1. 83/07/22. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19826: 046. 24X Fichs: 50-295, 83/07/22, B307280482.
- G. Inspection reports, IE Bulletins & correspondence
- 8307050155 Forwards response to IE Bulletin 82-02 re insp of threaded fasteners of closure connections. Insp revealed no severe corresion/erosion wastage or cracking affecting sys safety.

  BARNES, P.L. Commonwealth Edison Ca. 83/06/24. KEPPLER, J. G. Region 3, Office of Director. 4pp. 19199:330. 24% Fiche:50-304.83/06/24, 8307050155.
- 8307010103 Forwards requests for relief from inservice insp program requirements of ABME Section XI Code, 1974 Edition through Summer 1975 Addenda, per 10CFR50. 55a(g)x(5). Review requested. LENTINE, F. G. Commonwealth Edison Co. 83/06/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 37pp. 19168:157. 24X Fiche: 50-295, 83/06/27, 8307010103.
- B307080301 Recommends imposition of civil penalty in amount of \$10,000 for violations found during special safeguards inso on B30315.Util B30609 response provides no basis for further mitigation. Draft itr to licensee encl.

  B6HULTZ.W. H. Region 3, Office of Director. B3/07/05. AXELRAD, J.A. Enforcement Staff. 4pp. 19350:185. 24X Fiche:50-295.83/07/05, B307080301.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post B30103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:273. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fichs: 50-000,83/07/12,8306270404.
- 8307280266 Forwards IE Insp Repts 50-295/83-07 & 50-304/83-09 on 830843-17. No noncompliance noted. PAPERIELLO.C. J. Division of Emergency Preparadness & Operational Support. 83/07/12. REED.C. Commonwealth Edison Co. 2pp. 19791:341. 24X Fiche: 50-295, 83/07/12, 8307280266.

- --8307280274 IE Insp Repts 50-275/83-09 & 50-304/83-09 on 830613-17. No noncompliance noted Major areas inspected: emergency preparedness program including licensee actions on previously identified items.
  PHILLIPS.M.P., LICKUS.R.M., AXELBON.W.L. Region 3, Office of Director, 83/07/08. 18pp. 19791: 343. 24X Fiche: 50-295, 83/07/12, 8307280266.
- 8305270405 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 30-000, 83/07/14, 8306270406.
- 9307280084 Confirms 830726 mpt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util, per 830715 discussion.
  NRRELIVIS.C.E. Division of Project & Resident Programs. 83/07/22, REED.C. Commonwealth Edison Co. 2pp. 19791:169. 24X Fiche: 50-000, 83/07/22, 8307280084.
- --B307280102 Confirms request for NRC & wtil senior mgt meeting on B30726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.
  REED. C. Commonwealth Edison Co. B3/07/11. DAVIS, B. A. Region 3, Office of Director. 1p. 19791: 171. 24X Fiche: 50-000, B3/07/22, B307280084.
- R. Periodic operating reports & related correspondence
- 8307180198 Monthly operating repts for June 1983. W/830708 ltr. AUSTIN.C., GRAESEER.K.L. Commonwealth Edison Co. 83/07/08, Director's Dffice. Office of Inspection and Enforcement. 12pp. 19555:193. 24X Fiche: 50-295, 83/07/08, 8307180198.
- S. Reportable occurrences. LERs & related correspondence
- B307290272 Forwards AEOD technical review rept of 821216 event involving problems w/dissel-driven containment spray pump. Licensee unable to determine cause of problem. No further AEOD action necessary.

  ZUKOR.D. Reactor Operations Analysis Branch. 63/06/13.

  EYPRIT, K. V. Reactor Operations Analysis Branch. 1p. 19826: 325.

  24X Fiche: 50-304,83/06/13,8307290272.
- --8307270280 "Problems W/Diesel-Driven Containment Spray Pump." AEOD technical review rept.
  ZUKOR.D. Reactor Operations Analysis Branch. 83/06/13. 3pp. 19826: 326. 24% Fiche: 50-304.83/06/13.8307270272.
- B307030118 LER B3-017/03L-0: on B30524, hydrogen purge fan 2A ran for 2 minutes, then tripped. Caused by faulty auxiliary contact in starting circuit. Contact replaced. M/B30623 ltr. MODDB, J. T., GRAESSER, K.L. Commonwealth Edison Co. B3/06/23, KEPPLER, J. Region 3, Office of Director. 2pp. 17220: 033. 24X Fiche: 30-304, B3/06/23, B307050118.
- 8307030066 LER 83-018/03L-0: on 830527 & 29. steam generator 2D steam flow channel 2F-533 observed spiking erratically. Caused by electronic clock circuitry in extractor out of alignment. Module replaced. H/830624 ltr.
  CANTMELL.P.F., GRAESSER K. L. Commonwealth Edison Co. 83/06/24. KEPPLER.J. Q. Region 3, Defice of Director. 2pp. 19193: 189. 24X Fichs: 50-304, 83/06/24, 8307050066.
- B307060334 PND-III-B3-056; on B30629, security personnel found several rolled cigaratte butts believed to be manijuana. Visitors denied access to site & alleged controlled substances turned over to police for analysis. Util awaiting results. CREED. J., MILLER. J., Region 3, Office of Director. B3/06/30. 1p. 19234: 141. 24X Fiche: 30-295, 83/06/30, 8307060334.
- B307080020 PND-III-B3-05B: on B30701, bumb threat received from unknown female stating that bomb would go off in 10 minutes.
  Licensee security force put on alert status. No explosion occurred. State police not notified due to lack of time.
  MADEDA, T., CREED, J. Region 3, Office of Director. B3/07/01. ip. 19351: 216. 24X Fiche: 50-295, 83/07/01, B3070B0020.
- 8307110131 Confirms 830705 beloan between F Lentine & M Holzmer re 830708 security enforcement meeting at Region III ofcs to review 830615 breach of security event & corrective actions to prevent recurrence.

  KEPPLER J. 9. Region 3. Office of Director. 83/07/05. REED, C. Commonwealth Edison Co. 1p. 17375:125. 24X Fiche: 50-295, 83/07/05, B307110131.

- B307110423 LER B3-019/03L-0: pn B3060B, during normal operation, blower for steam jet air ejector gas monitor 2RE-0015 failed. resulting in zero flow. Caused by depleted oil reserve. Blower replaced & gas monitor returned to svc. W/B30705 ltr. KABSNER. C., GRAESSER. K. L. Commonwealth Edison Co. B3/07/05. KEPPLER. J. C. Region 3, Office of Director. 2pp. 19382: 270. 24X Fiche: 50-304,83/07/05, B307110423.
- B3072B0377 EN-B3-02BA: on B3042B. Commission notified of intent to issue notice of violation & proposed imposition of civil penalty in amount of \$10,000. Notice issued B30726 re unauthorized entry into protected area.

  ROSANO.R.: AXELRAD.J. Director's Office Office of Inspection and Enfercement. B3/07/26. lp. 19796:103. 24X Fiche: 50-295, B3/07/26. B3072B0377.

# DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

- F. Security, medical, emergency & fire protection plans
- B307110239 Forwards listed radiological emergency response plan implementing procedures, per 10CFR50, App E. W/o encl. GIESLER, C. M. Wisconsin Public Service Corp. B3/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19379; 236. 24X Fiche: 50-303, B3/06/30, B307110239.
- G307270473 Releases public version of revised radiological emergency response plan implementing procedures.
  FELTON.J.M. Division of Rules and Records, B3/07/19. Document Management Branch. 1p. 19788:165. 24X Fiche: 50-305, 83/07/19, 8307270473.
- --B307270502 Forwards public version of revised radiological emergency response plan implementing procedures, including Procedures EP-AD-11 re emergency radiation controls & EP-ENV-3A re environ protection director actions.

  GIESLER,C.W. Wisconsin Public Service Corp. B3/06/30.

  DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19788: 166. 24X Fiche: 50-305, B3/07/19, B307270473.
- --B307270506 Public version of revised radiological emergency response plan implementing procedures including Procedures EP-AD-11 re emergency radiation controls & EP-ENV-3A re environ protection director actions.

  \*\*Wisconsin Public Service Corp. B3/06/21. 78pp. 19788:168. 24X Fithe: 50-305, 83/07/19, 8307270473.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B3071900B3 Forwards ravised pages to updated FBAR for Kewaunes Nuclear Power Plant. Rev due to minor typographical errors & editorial comments. Technical content unchanged.

  OIEBLER, C. H. Wisconsin Public Service Corp. B3/07/15. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 6pp. 17631:212. 24X Fiche: 50-305, 83/07/15, 8307190083.
- --8307190086 Revised pages for updated FBAR for Kewaunee Nuclear Power Plant. \* Wisconsin Public Service Corp. 83/07/01. 204pp. 19631:218. 24X Fiche: 50-305,83/07/15.8307190083.
- P. Operating license stage documents & correspondence
- 8304040070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISEMMUT.D.O. Division of Licensing. 83/04/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000.83/04/03. 8304040070.
- 8307070232 Forwards synopsis of issues associated w/NUREG-0612 recontrol of heavy loads, as discussed in 830617 telcon.
  Responses to open issues must be provided within 30 days of litr date.
  VARQALS.A. Operating Reactors Branch 1. 83/06/21. GIESCER.C.W.
  Misconsin Public Service Corp. 13pp. 19362:227. 24X
  Fiche:50-305,83/06/21.8307070232.
- 8307270441 Forwards two remaining outstanding amend requests for facility. Subsequent amend requests will be forwarded by util upon submittal of application to NRC W/o encl. GRUTENHUIS, M. Operating Reactors Branch 1. 93/06/27. RIEDERER, C. Wisconsin, State of. 2pp. 19788: 357. 24X Fiche: 50-305, 83/06/27, 8307270441.

- 8307070002 Describes interim containment venting procedure, to be used until mod to smaller diameter sys completed. Procedure will minimize possibility of valve closure problems & assure containment isolation under LDCA conditions.

  GIESLER.C. W. Washington Public Power Supply System. 83/07/01. VAROA.S A. Operating Reactors Branch 1 2pp. 19293:223. 24x Fiche: 50-305.83/07/01.8307070002
- B307060329 Ceneric Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 518 Svc list encl E15ENAUT.D G Division of Licensing. B3/07/06. Consulidated Edison Co. of New York. Inc. 16pp. 19669-254. 24X Fithe: 50-000.83/07/06.8307060329.
- 8307270443 Forwards SER re NUREG-0737.Action Item 111 D.3.4, "Control Room Habitability." Design acceptable.
  VARGA.5.A. Operating Reactors Branch 1 83/07/07. GIESLER.C.W. Histonsin Public Service Corp. Spp. 19802:238. 24X
  Fiche:50-305.83/07/07.8307270443.
- B3070B0i&7 Generic Ltr B3-2B to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATWS events. See list encl. ELBENHUT.D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 3Bpp. 19669:269. 24x Fiche: 30-000.83/07/08.8307080169.
- B307250488 Discusses commitment to perform 48 h test to monitor performance of auxiliary feedwater pumps.per 830506 ltr.
  Bimilar test will be performed on turbine-driven pump during next refueling outage.
  G1ESLER.C.W. Wisconsin Public Service Corp. 83/07/20. VARGA.S.A. Operating Reactors Branch 1. 1p. 19701:217. 24X
  Fiche: 50-305,83/07/20,8307250488.
- G. Inspection reports, IE Buildtins & correspondence
- 830707023B Forwards suppl to SER supporting util analysis in response to IE Bulletin 80-04 re main steamline break w/continued feedwater addition.

  VARGA:B.A. Operating Reactors Branch 1. 83/06/08. GIESLER:C.W. Wisconsin Public Service Corp. 2pp. 19344.358. 24%
  Fiche:50-305,83/06/08.830707023B.
- --8307070242 Safety evaluation supporting util analysis in response to IE Bulletin 80-04 re main steamline break w/continued feedwater addition.

  \* Containment Systems Branch. 83/06/08. 2pp. 19344:360. 24X
  Fiche: 50-305,83/06/08,8307070238.
- B30.7060107 Advises that revised response to 1E Bulletin B0-11. "Seismic Gualification of Masonry Walls." will be provided on B40101.in response to findings in 1E Insp Rept 50-305/83-05. QIESLER.C W. Wisconsin Public Service Corp. 83/06/30. VARGA.S.A. Operating Reactors Branch 1. 1p. 19252-213. 24X Fiche: 50-305,83/06/30.8307060107.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svr list encl.

  JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Cansolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- B307180271 Requests submittal of Tech Specs omitted from util 810713 response to IE Bulletin 80-12 re DHR sys Response requested within 60 days.

  VARGA: S.A. Operating Reactors Branch 1. B3/07/11. GIESLER, C. W. Wisconsin Public Service Corp. 3pp. 19566. 206. 24X Fiche: 50-305, 83/07/11, B307180271.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12 Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche:50-000.83/07/12,8306270404.
- 8305270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715.270. 24X Fiche: 30-000,83/07/14,8306270406.
- B307250276 Responds to 1E Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PMR Plants." Indications found on stud surface. Studs replaced No boric acid correction wastage found on fasteners.

  GESLER, C. W. Wisconsin Public Service Corp. B3/07/14. KEPPLER, J. O. Region 3. Office of Director. App. 19705:314 24X Fiche: 50-305, 83/07/14, 8307250294.

- 8307250286 Modifies 830308 commitment re performance of surface exam on 100% of weld over 40-yr period, per util request for relief from performing volumetric exams of reactor collant pump welds. Sections of welds will be examined over 30-yr period. GIESLER.C.W. Wisconsin Public Service Corp. 83/07/19. EISCNHUT, D.G. Division of Licensing. 3pp. 19705.306. 24X Ficher50-305.83/07/19.8307250286.
- R. Periodic operating reports & related correspondence
- 8307120263 Monthly operating rept for June 1983.W/830708 ltr.
  RUITER.G.H., GIESLER.C.W. Hisconsin Public Service Corp. 83/06/30.
  Director's Office. Office of inspection and Enforcement. 5pp.
  19422:248. 24% Fiche:50-305
- 6307250340 "Kewaunee Nuclear Power Plant Cycle 9 Startup Rept for June 1983." W/630715 ltr. GIESLER.C.W. Wisconsin Public Service Corp. 83/07/15. VARGA.S.A. Operating Reactore Branch 1. 41pp. 19703:113. 24X Fiche: 50-205
- S. Reportable occurrences. LERs & related correspondence
- 9307110277 LER 83-015/03L-0: on B30606, during valve timing test for TD auxiliary Feedwater pump, valve failed to electrically open.
  Caused by Faulty torque suitch & maladjusted tripper cam.
  Valve operator rebuilt & cam reset. W/B30701 ltr.
  BERNHOFT, S. L., THOROGERSEN, J. G., ØIESLER, C. W. Washington Public Power Supply System, B3/07/01, KEPPLER, J. C., Region J. Office of Director Spp. 19379:136. 24X Fiche: 50-305,83/07/01,8307110277.
- 8307110284 LER B3-014/03L-0: on B30603, while performing monthly RHR pump & valve surveillance test, containment sump B isolation valve 61-350B would not cycle closed Caused by mechanical interlock sticking in open position. M/830701 itr.
  BERNHOFT, S. L. , THURGERSEN, J. G. , GLESLER, C. W. Wisconsin Public Service Corp. B3/07/01, KEPPLER, J. G. , Region 3, Office of Director. 2pp. 19379: 149 24X Fiche: 50-305, 83/07/01, 8307110284.
- DOCKET 50-306 PRAIRIE (SLAND NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307050283 Forwards table of schedular milestones to be negotiated during 830624 meeting re emergency response capability provided in util 830515 response to Generic Ltr 82-33. DIIANNI.D.C. Operating Reactors Branch J. 83706714. MUSGLF.D.M. Northern States Power Co. 3pp. 19263.216. 24X Fiche: 50-282,83706714,8307050283.
- 8307060315 Forwards 1E Insp Repts 50-282/83-07 & 50-306/83-07 on 830401-30 & notice of violation. SHAFER.W.D. Region 3. Office of Director. B3/06/20. LARSON.C.E. Northern States Power Co. 2pp. 19234 231 24X Fiche: 30-282
- --8307060324 Notice of violation from insp on 830401-30. SHAFER.W.D. Region 3. Office of Director. 93/06/20. 2pp. 19234: 233. 24X Fiche: 50-282,83/06/20,8307060315.
- --8307060328 IE Insp Repts 50-282/83-07 & 50-306/83-07 on 830401-30. Noncompliance noted:failure to perform daily check of main steam line radiation monitors & monthly functional test for 4-iV safeguards buses & to verify valve position. FEIERABEND.C D. Region 3. Office of Director. 83/06/20. 9pp. 19234-235. 24X Fiche:50-282.83/06/20.8307060315.
- 8307010178 Forwards Rev 5 to security Force training & qualification plan. Rev withheld (ref 10CFR73.21).
  MUSQLF.D M. Northern States Power Co 83/06/24. Office of Nuclear Resolver Regulation. Director 2pp 19172:261. 24X
  Fiche: 50-000.83/06/24.8307010178
- 8307180437 Advises that Rev 9 to security plan acceptable w/exception of Page 21. Section 3.2.2.1 requiring designated vehicles be limited in use to onsite functions CLARK. A. Operating Reactors Branch 3. B3/07/07 MUSDLF, D. M. Northern States Power Co. 3pp. 19566: 339. 24X Fiche: 50~282, 83/07/07.8307180437.
- 8307180107 Forwards IE Safeguards Insp Repts 50-282/83-11 & 50-306/83-11 on 630613-17. No noncompliance noted.
  MILLER, J. R. Region 3, Office of Director. 63/07/14. LARSON, C. E. Northern States Power Co. 2pp 19557: 027. 24X Fichs: 50-282, 83/07/14, 8307180107

- ~~8307180112 IE Safeguards Insp Repts 50-282/83-11 & 50-304/83-11 on 830613-17. No noncompliance noted. Major areas inspected: security plan & implementing procedures; locks, keys & combinations. Safeguards info deleted (ref 10CFR73.21). PIRTLE.G.L. Region 3, Office of Director. 83/07/13. 2pp. 19357:029. 24X Fiche: 50-282, 83/07/14,8307180109.
- 8307220561 Responds to 830310 ltr re Rev 8 to physical security plan. Procedures changed to establish lock rotation per Reg Quide 5.12, "General Use of Locks in Protection & Control of Facilities & SNM." Plan will be revised.
  MUSQLF.D. Northern States Power Co. 83/07/15. Office of Nuclear Reactor Regulation, Director. ip. 19486:028. 24X
  Ficha: 50-282.83/07/15.8307220561.
- B307250632 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19718: 144. 24X Fiche: 50-000, 83/07/19, 8307250632.
- --8307250642 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.1 recorporate emergency response plan. EPIP 1.1.2 renotifications & EPIP 1.1.3 republic info.

  WARD, E.C. Northern States Power Co. 83/05/20. Region 3, Office of Director. 1p. 19718:145. 24X Fiche: 50-000, 83/07/19, 8307250632.
- --8307250450 Public version of revised emergency plan implementing procedures including Procedures EPIP 1.1.1 re corporate emergency response plan.EPIP 1.1.2 re notifications & EPIP 1.1.3 re public info.Rev 12 to table of contents encl. HUDSON.6. WARD.E.C. Northern States Power Co. 83/05/20. 145pp. 19718:146. 24X Fiche: 50-000, 83/07/19,8307250632.
- J. Insurance & indemnity information
- B307260475 Forwards Endorsements 69 & 66 to NELIA Policy NF-174, Endorsements 34 & 35 to NELIA Policy NF-197 & Endorsements 54 & 47 to MAELU Policies MF-51 & MF-6B: respectively.

  JCHNSON.R.G. Northern States Power Co. 83/07/18. DINITY.I. Antitrust & Economic Analysis Branch (Utility Finance). 7pp. 19731:136. 24X Fiche: 50-000, 83/07/18, 8307260475.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307080198 Forwards Rev 1 to updated FSAR.
  MUSDLF.D. Northern States Power Co. 83/06/30. Office of Nuclear
  Reactor Regulation. Director. 22pp. 19348:196. 24X
  Fiche:30-282.83/06/30.8307080198.
- --8307080204 Rev 1 to updated FSAR.

  \* Northern States Power Co. 82/12/31. 448pp. 19348: 219. 24X
  Fiche 50-282, 83/06/30, 8307080198.
- P. Operating license stage documents & correspondence
- B307090342 Forwards safety evaluation re seismic qualification of auxiliary feedwater sys.based on util 810714 & 820503 responses to Generic Ltr B1-14. Sys can withstand postulated safe shutdown earthquate.

  CLARK.R.A. Operating Reacturs Branch 3. 83/06/17. MUSOLF.D.M. Northern States Power Co. 2pp. 19263:293. 24X

  Fiche: 50-282, 83/06/17, 8307050342.
- --8307050345 Safety evaluation re util responses to Generic Ltr B1-14 on selsmic qualification of auxiliary feedwater sys. Auxiliary feedwater sys can withstand postulated safe shutdown earthquake.

  \* Dffice of Nuclear Reactor Regulation, Director. 83/06/16. 10pp. 19263:297. 24X Fiche: 50-282,83/06/17,8307050342.
- 8307010144 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Section 3.10 resulting from new LOCA analysis.

  MUSDLF.D. Northern States Power Co. 83/06/24. Office of Nuclear Reactor Regulation, Director. 1p. 191/3:277. 24X

  Fiche: 50-282:83/06/24:8307010144.
- --8307010149 Application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Section 3.10 resulting from new LOCA analysis. MUSGLF, D. Northern States Power Co. 83/06/24. 3pp. 19173:278, 24% Fiche: 80-282, 83/06/24, 8307010144.
- --8307010153 Proposed changes to lech Spec Section 3.10 resulting from new LOCA analysis. \* Northern Slates Power Co. 83/06/24. 9pp. 19173:281. 24X Fiche: 50-282, 83/06/24, 8307010144.

- ---8307010157 "Prairie Island Units 1 & 2 Limiting Break LOCA-ECCS Analysis Using EXEM/PMR." TAHVILI, T., KAYBER, M. V., CHANDLER, J. C. Exxon Nuclear Co., Inc. (Subs. of Exxon Corp.) XN-NF-83-38, 83/05/27, 56pp. 19173:291 24X Fiche: 50-282,83/06/24,8307010144.
- 8307050092 Forwards application to amend Licenses DPR-42 & DPR-60, revising Tech Spacs re containment sys recombiners, control room air treatment sys & ref to FSAR Table 7, 7-2. Changes do not constitute significant hazards consideration. MUSDLF.D. Northern States Power Co. 83/07/01. Office of Nuclear Reactor Regulation, Director. 1p. 19193:311. 24X Fiche: 50-282, 83/07/01, 8307050092.
- --8307050098 Application to amend Licensus DPR-42 & DPR-60 revising Tech Spacs re containment sys recombiners control room air treatment sys & ref to FSAR Table 7.7-2. MUSOLF, D. Northern States Power Ca. 83/07/01. 6pp. 19193:312. 24X Fiche: 50-282,83/07/01,8307050092.
- --8307050102 Proposed Tech Specs re containment sys recombiners, control room air treatment sys & ref to FSAR Table 7.7-2.

  \* Northern States Power Co. 83/07/01. 14pp. 19193:318. 24x Fiche: 50-282,83/07/01.8307050092.
- 8304270397 Generic Ltr 83-24 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENNUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24% Fiche: 50-000.83/07/05.8304270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York Inc. 16pp. 19649:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events 8vc list encl. EISENHUT, D. G. Division of Licensing, 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307290001 Notice of consideration of issuance of amend to Licenses DPR-24 & DPR-60 & proposed NSHC determination & opportunity for hearing re sodium hydroxide concentration in containment spray sys spray additive tank.

  CLARK,R.A. Operating Reactors Branch 3 83/07/08. 8pp. 19826.333. 24X Fiche: 50-282,83/07/08,8307290001
- B307270283 Clarifies location of Rosemount transmitters classified as Category II.B items in util B30808 ltr to NRC.
  MUSDLF.D. Northern States Power Co. 83/07/13. Office of Nuclear Reactor Regulation, Director. 2pp. 19749
- Q. Inspection reports, IE Bulletins & correspondence
- 8307060315 Forwards IE Insp Repts 50-282/83-07 & 50-306/83-07 on B30401-30 & notice of violation.
  SHAFER.M. D. Region 3. Office of Director. 83/06/20. LARSDN.C.E. Northern States Power Co. 2pp. 19234: 231 24X
  Fiche: 50-282,83/06/20,8307060315.
- --8307060324 Notice of violation from insp on 830401-30. SHAFER, W. D. Region 3, Office of Director. 83/06/20. 2pp. 19234: 233. 24X Fiche: 50-282, 83/06/20, 8307060315.
- --8307060328 IE Insp Repts 50-282/83-07 % 50-306/83-07 on 830401-30. Noncompliance noted: failure to perform daily check of main steam line radiation monitors & monthly functional test for 4-kV safeguards buses & to verify valve position. FEIERABEND.C.D., WILLIAMS.D.L., JACKIW.I.N. Region 3, Office of Director. B3/06/20, 9pp. 19234: 235. 24X Fiche: 50-282,83/06/20,8307060315.
- 8307180102 Forwards IE Insp Repts 50-282/83-08 & 90-306/83-08 on 830606-10.No noncompliance noted. PAPERIELLO.C. J. Region 3. Office of Director. 83/07/01. LARBON.C. E. Northern States Power Co. 2pp. 19557:010. 24% Fiche: 50-282, 83/07/01, 8307180102.
- ---8307180107 IE Insp Repts 50-282/83-08 & 50-306/83-08 on 830806-10. No noncompliance noted Major areas inspected radiological environ protection program including mgt controls 60 & implementation & confirmatory measurements.

  JANUSKA.A.O., NICHOLSON.N.A., SCHUMACHER.M.C. Region 3, Office of Director. 83/06/30 7pp. 19557:012. 24X Fiche: 50-282, 83/07/01, 8307180102.

- 8307280190 Forwards IE Insp Repts 50-289/83-12 & 50-306/83-12 on 830613-17 No moncompliance nated STREETER J F Region 3, Office of Director 83/07/08. LARSON, C E. Northern States Power Co. 2pp 19791 259 24X Fiche: 50-282, 83/07/08, 8307280190.
- --8307280196 IE Insp Repts 50-282/83-12 & 50-306/83-12 on 830613-17. No noncompliance noted Major Gless Inspected maint program & implementation of maint program.

  CHOULES.N.C., XISH.J.N., HAWKINS.F.C. Region 3, Office of Director. 83/07/07. 7pp 19791.261 24X Fiche.50-282.83/07/08.8307280190.
- 830627040) IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem " Svc list enc) JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 63/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293 24X Fiche 50-000.83/07/11,8306270401
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list enc!

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche.50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715 270 24X Fiche: 50-000.83/07/14.8306270406.
- 8307180109 Forwards IE Safeguards Insp Repts 50-282/83-11 & 50-304/83-11 on 830413-17 No noncompliance noted MILLER. J. R. Region 3, Office of Director: 83/07/14. LARSON. C. E. Northern Statos Power Co. 2pp. 19557:027 24x Fiche: 50-282. 83/07/14.8307180109.
- --B307180112 IE Safeguards Insp Repts 50-282/83-11 & 50-306/83-11 on B30613-17. No noncompliance noted Major areas inspected: security plan & implementing procedures; locks, keys & combinations. Safeguards info deleted (ref 10CFR73, 21). PIRTLE, G. L., KNICELEY, J. R., CREED, J. R. Region 3. Office of Director. B3/07/13. 2pp 19557, 029 24X Fiche: 50-282, 83/07/14, B307180109.
- R. Periodic operating reports & related correspondence
- 8307150045 Monthly operating repts for June 1983 W/830708 ltr.
  DUGSTAD.D.: MUSGLE.D. Northern States Power Co. 83/07/05. Offic
  of Resource Management, Director 10pp 19936:196. 24X
  Fichs: 50-282.83/07/05.8307190069.
- 8. Reportable occurrences, LERs & related correspondence
- 8307060229 LER B3-014/01T-0: on 830613, containment inservice purge supply isolation failed local leakage rate test. Caused by dirty valve seats. Valve suats cleaned. Blind flunges to be installed during nest outage W/830627 ltr HUNSTAD.A.A., MUSGLF,D. Northern States Power Co. 83/06/27. Region 3. Dffste of Director. 2pp 19249:035, 24x Fiche: 80-306,83/06/27,8307060229.
- 830727005? Forwards safety evaluation of 811216 spent fuel assembly top notife degradation event. Incident does not appear to have any generic implications refuel assembly design. fabrication, handling on storage.

  CLARK, R. A. Operating Reactors Branch 3. 83/07/11 MUSOLF, D. M. Northern States Power Co. 2pp. 198(1:188 24X Fiche: 50-282, 83/07/11, 8307270059.
- --8307270072 Safety evaluation of 811216 spent fuel assembly top nozzle degradation event Recommends that sulfate analysis be included in routine primary water & spent fuel pool water chemistry monitoring & analysis programs.

  \* Office of Nuclear Reactor Regulation, Director 83/07/11, 9pp. 19811:190. 24X Fiche: 50-282, 83/07/11, 8307270059.
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

  F. Security, modical, emergency & fire protection plans
- 8307140163 Responds to util 810601 & 821216 ltrs re primary & backup emergency operations facility. Facility location acceptable. Other features & approval will be determined during post-implementation appraisal. EISENHUT, D. G. Division of Licensing 83/06/23, GARRITY, J. H. Maine Yankee Atomic Power Co. 2pp. 19540.018. 24X Fiche. 50-309, 83/06/23, 8307140163.

- 8307110325 Releases public versions of revised emergency plan implementing procedures FELYON, J. M. Division of Rules and Records. 83/06/24. Document Management Branch 1p 19384-930. 24% Fiche: 50-309, 83/06/24, 8307110325
- ---830711032B Forwards public version of revised emergency plan implementing procedures, including Procedure 2, 50.1 renotification of unusual event, 2,50.2 re alert 6,2,50.3 resite area emergency.

  \* Maine Yankee Atomic Power Co. 83/05/25 Document Management Branch 2pp 19384.331. 24X Fiche 50-309,83/06/24,8307110325.
- --8307110334 Public version of revised emergency plan implementing procedures, including Procedure 2, 50, 1 re notification of unusual event, 2, 50, 2 re alert & 2, 50, 3 re site area emergency.

  \* Maine Yankee Atomic Power Co. 83/05/25, 200pp. 19384: 333. 24% Fiche: 50-309, 83/06/24, 8307;10325.
- 8307180405 Releases public version of emergency plan implementing procedure change repts.
  FELTON.J. M. Division of Rules and Records 83/06/24. Document Management Branch. 1p. 19641:231. 24X Fiche: 50-309.83/06/24.
- --8307180408 Forwards public version of Emergency Plan Implementing Procedure Change Ropts 83-231.83-230 & 83-232 for revised Procedures 2.50.2 re alert, 2.50.3 re site area emergency t 2.50.4 re general emergency respectively.

  \* Maine Yankee Atomic Power Co. 83/05/31. Document Management Branch. ip. 19641:232. 24x Fiche:50-309,83/06/24,8307180405.
- --8307180409 Public version of Emergency Plan Implementing Procedure Change Repts 83-231.83-230 & 83-232 for revised Procedures 2.50.2 re alert.2.50.3 re site area emergency & 2.30.4 re general emergency, respectively, \* Maine Vankee Atomic Power Co. 83/05/27. 3pp. 19641:233. 24x Fiche:50-309.83/06/24.8307180405.
- 8307110450 Forwards fees for health, safety & environ insps (100FR170, 23) & safeguards insps (100FR170, 24), per 100FR170, 12(g), OARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/06. MILLER, W. O. License Fee Management Branch. Ep. 19380:217, 24X Fiche: 50-309, 83/07/06, 8307110450.
- B307250057 Summary of B30628 meeting w/util in Bethesda,MD re auxiliary feedwater sys evaluation. Further NRC guidance will be provided in formulation of App R-related Tech Specs. HEIYNER,W.L. Operating Reactors Branch 3. 83/07/08. CLARK,R.A. Operating Reactors Branch 3. 93/07/08. 24X Fichs: 50-309. 83/07/08. 8307250057.
- 8307280269 Forwards IE Insp Rept 50-309/83-09 on 830523-27 & notice of violation MARTIN.T.F. Division of Engineering & Technical Programs. 83/07/13. RANDAZZA.J.B. Maine Yankee Atomic Power Co. 2pp. 19790:165. 24X Fiche:50-309.83/07/13.8307280269
- --8307280275 Notice of violation from insp on 830523-27. Details withheld (ref 10CFR73, 21).

  \* Region 1. Office of Director. 83/07/13. 2pp. 19790:167. 24x
  Fiche: 50-309, 83/07/13, 8307280269.
- --8307280284 IE Insp Rept 50-309783-09 on 830523-27 Noncompliance noted: failure to observe portion of isolation zone & failure to maintain barrier to access controlled area Portions withheld (ref 10CR73, 21).

  BAILEY,R. J., GUDY, A. T. Region 1, Office of Director. 83/07/11.

  7pp. 19790 169. 24X Fiche: 50-309,83/07/13,8307280269
- 8307260476 Documents understanding that either Rev 2 or Rev 3 to Reg Guide 1.97 acceptable to NRC for addressing guidelines of NUREG-0737, Suppl 1 (Generic Ltr B2-33) re emergency response capability.

  GARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/21. CLARK, R. A. Operating Reactors Branch 3. 1p. 19734.163. 24x

  Fiche 30-309, 83/07/21, 8307260476.
- 9. Adjudicatory correspondence
- 3307060165 Answers to 830405 second set of interrogatories & request for production of documents & motion for protective order. Related correspondence. GAD.R.K. Maine Yankee Atomic Power Co. GAD.R.K. Ropes & Gray. 83/06/30. Maine, State of. 195pp. 19253.278. 24X Fiche; 50-309,83/06/30.8307060165.

- 8307150330 Submits distribution list for correspondence between NRC & util.

  GARRITY.J.H. Maine Yankee Atomic Power Co. 83/07/11. CHILK, S.J.
  Office of the Secretary of the Commission. 2pp. 19538:346. 24X
  Fiche: 50-309,83/07/11,8307150330.
- 8307190159 Order extending time until 830725 for Commission to act to review Director's Decision dtd 830214.
  CHILK.S.J. Office of the Secretary of the Commission. 83/07/15.
  Commissioners. 1p. 19636:255. 24X Fiche:50-309,83/07/15,
- B307270122 Order extending time until B30729 for Commission to act to review B30214 Director's Decision.
  CHILK, S. J. Office of the Secretary of the Commission. B3/07/25.
  Commissioners. 1p. 19749: 342. 24X Fiche: 50-309, 83/07/25.
- P. Operating license stage documents & correspondence
- 8307050432 Forwards SER on review of 801215,820514 & 0615 submittals re TMI Action Flan Items II.F.1.4, "Containment Pressura Monitor," II.F.1.5, "Containment Water Level Monitor" & II.F.1.6 "Containment Hydrogen Monitor." CLARK,R.A. Operating Reactors Branch 3. 83/06/17, GARRITY, J. H. Maine Yankee Atomic Power Co. 8pp. 19262:346. 24X Fiche: 50-309, 83/06/17, 8307050432.
- 8307060373 Informs that review of 830107 submittal on shutdown margin definition, including procedures for verifying that shutdown margin requirements are met in case of slow control element assembly completed. Actions acceptable.

  CLARK.R.A. Operating Reactors Branch 3. 83/06/21. GARRITY, J. H. Maine Yankee Atomic Power Co. 2pp. 19299: 331. 24x

  Fiche: 50-309, 83/06/21, 8307060373.
- --B3070603B0 Safety evaluation supporting util mode re shutdown margin verification.

  \* NRC No Detailed Affiliation Given. B3/06/21. 2pp. 19299: 333. 24X Fiche: 50-309, B3/06/21, B307060373.
- B307140139 Discusses util B20721 request for exemption from shift manning rule. Request considered withdrawn due to understanding that util can comply w/revised version of rule.

  CLARK. R. A. Operating Reactors Branch 3. B3/06/23. GARRITY, J. Maine Yankee Atomic Power Co. 2pp. 17529:361. 24X Fiche: 50~309, B3/06/23, B307140159.
- B307190287 Forwards comments on util status rept for seismic design review presented at 830510 meeting Addl meeting necessary to address concerns.

  CLARK.R.A. Operating Reactors Branch 3. 83/06/29. GARRITY, J. H. Maine Yankee Atumic Power Co. 18pp. 19656:175. 24X

  Fiche: 50-309, 83/06/29, 8307190289.
- 8306270397 Generic itr 83-26 to all applicants for OLs & helders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity. Svc list encl. EISENHUT. D. Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317, 24x Fiche: 50-000, 83/07/05, 8306270397.
- B307t20496 Informs that on B30601.shortnose sturgeon found alive in catch bag of intake structure, per NRC 810324 ltr. Sturgeon transported to area several hundred yards from intake & released.

  GARRITY. J. H. Maine Yankes Atomic Power Co. B3/07/05. GLARK, R. A. Operating Reactors Branch J. 2pp. 19425:023. 24X fiche: 50-309, 83/07/05, 8307120496.
- B30706032? Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISEN-MUT.D.G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000. B3/07/06. B307060329.
- 8307110378 Advises that concerns raised in NRC 830301 ltr re need for more complete Tech Specs for pressurizer heaters reviewed. Revs not necessary due to ability to power heaters from emergency buses.

  GARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/06. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19380:335. 24x

  Fiche: 50-309, 83/07/06, 8307110378.
- 8307080167 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENNUT.D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17667:267. 24x Fiche: 50-000.83/07/08,8307080169.

- 107250057 Summary of 830628 meeting w/util in Bethesda.MD re auxiliary feedwater sys evaluation.Further NRC guidance will be provided in formulation of App R-related Tech Specs.
  HEITNER.K.L. Operating Reactors Branch 3. 83/07/05. CLARK.R.A. Operating Reactors Branch 3. 5pp. 19723:343. 24X
  Fiche: 50-309,83/07/08.8307250057.
- O7190128 Application for Proposed Change 97 to amend License DPR-36 re fuel handling accident inside containment. FRIZZLE.C.D. Maine Yankee Atomic Power Co 83/07/14. CLARK, R.A. Operating Reactors Branch 3. 3pp. 19636:053. 24X Fiche: 50-309.83/07/14.8307190128.
- 8307190130 Proposed Tech Specs re fuel handling accident inside containment.

  \* Maine Yankee Atomic Power Co. 83/07/14. 17pp. 19636:056. 24X Fiche: 50-309, 83/07/14, 8307190128.
- O7260090 Rev i to Notification 83-51 of 830722 meeting w/util in King of Prussia:PA to discuss unauthorized attachment of lead shielding to safety-related piping & effects upon sys operability.

  KELLEY.G. Region i, Office of Director. 83/07/15. Region 1, Office of Director. ip. 19786:221. 24X Fiche: 50-309,83/07/15, 8307260090
- 07270543 Accepts conclusions in licensee 830706 ltr that adequate pressurizer heater capacity available to maintain sufficient heater capacity for natural circulation cooldowns. No rev to Tech Spec or further action required. CLARK.R.A. Operating Reactors Branch 3 83/07/19. GARRITY, J. H. Maine Yankee Atomic Power Co. 2pp. 19857:082. 24X Fiche: 50-309, 83/07/19, 8307290543.
- D7290548 Forwards safety evaluation re demonstration of purge & vent valve operability (B-24). Operability of B-inch pressure relief valve not yet demonstrated. Long-term option of blocking 42-inch purge/vent valves acceptable.
  CLARK.R.A. Operating Reactors Branch 3. 83/07/19. GARRITY, J. H. Maine Yankes Atomic Power Co. 2pp. 19857: 075. 24X Fiche: 50-309, 83/07/19, 8307290548.
- B307290550 Befety evaluation re demonstration of operability of 42-inch purge & 8-inch vent valves. Eight-inch valve should be sealed closed & verified to be closed at least once every 31 days.

  \* Office of Nuclear Reactor Regulation, Director. 83/07/19. 4pp. 19857:077. 24X Fiche: 50-309.83/07/19.8307290548.
- 07280317 Forwards Rev 2 to GA program resulting from NRC 830519 request for add1 info. Two other revs included to resolve Jnresolved Item 82-02-12 & Violation 82-17-B. 1. 9ARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/20. MURLEY, T. E. tegion i, Office of Director. 2pp. 19789: 217. 24X Fiche: 50-309, 83/07/20, 8307280317.
- 3307280320 Rev 2 to GA program. \* Maine Yankes Atomic Power Co. 83/06/10. 15pp. 19789:219. 24X Fiche: 50-309, 83/07/20, 8307280317.
- Inspection reports. IE Bulletins & correspondence
- )7010038 Forwards IE Insp Rept 50-307/83-08 on 830503-05. No ioncompliance noted. ITAROBTECKI.R. Division of Project & Resident Programs. 83/06/17 ANDAZZA.J.B. Maine Yankee Atomic Power Co. 2pp. 19169:017. 24 Fiche: 50-309, 83/06/17.8307010038.
- 3307010047 IE Insp Rept 50-309/83-08 on 830503-05. No noncompliance noted Major areas inspected licensee actions taken to comply w/NUREG-0737. Item II. B. 2, "Design Review of Plant
- Shielding."
  LAZARUS.M.J., KELLY.E. Region 1, Office of Director. QADivision of Project & Resident Programs. 83/06/13. 7pp. 19169:019. 24X Fiche: 50-309, 83/06/17, 8307010038. QALLO, R. M.
- )7050347 Submits Confirmatory Action Ltr 83-05, verifying actions to seaken or planned due to potential overloading of lafety-related piping & supports caused by unauthorized lead shielding installation.

  TAROSTECKI.R. Division of Project & Resident Programs. 83/06/22.

  RANDAZZA, J.B. Waine Yankee Atomic Power Co. 2pp. 19263:339. 24X 71che: 50-309, 83/06/22, 8307050347.
- 17110251 Forwards IE Insp Rept 50-309/83-11 on 830517-20 & notice of
- riolation. (ARTIN,T. T. Division of Engineering & Technical Programs, 83/06/22. RANDAZZA, J. B. Maine Yankes Atomic Power Co. 2pp. 19374: 272. 24X (iche: 50-309, 83/06/22, 8307110251.
- |307110255 Notice of violation from insp on 830517-20. # Region 1, Office of Director. 83/06/22. 1p. 19374:274. 24X Ficha: 30-309.83/06/22. 8307110251.

- --B307110265 IE Insp Rept 50-309783-11 on 830517-20 Noncompliance noted failure to have plant operation review committee approve procedures.

  TANGU C., PASCIAK, W. J. Region 1, Office of Director. 83706/16.
  6pp. 19374-275. 24X Fiche: 50-309, 83706/22, 8307110251.
- 8307110450 Forwards fees for health, safety & environ insps (100FR170, 23) & safaguards insps (100FR170, 24), per 100FR170.12(g).
  GARRITY.J.H. Maine Yankee Atomic Power Co.
  License Fee Management Branch. 1p. 19380Fiche: 50-309,83/07/06.8307110450. 83/07/06 MILLER, W. D. 19380-217
- 8307120617 Forwards inservice insp exam root for 820711-830224. Info re exams performed as-found conditions & corrective actions taken discussed. taken discussed. GARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/06 CLARK, R.A. Operating Reactors Branch 3. 1p. 19432, 269. 24X Fiche: 50~309, 83/07/06, 8307120617.
- --8307120626 Inservice insplexam rept for 820711-830224 Infolice exams performed as-found conditions & corrective actions taken discussed. \*\* Maine Yankee Atomic Power Co. 83/02/24. 99pp. 19432:270. 24X Fiche:50-309:83/07/06,8307120617.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem " Svc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 134pp. 19363-293 24X Fiche 30-000,83/07/11.8306270401.
- B306270404 IE Info Notice 83-47: "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluis." Svc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563.153. 24X Fiche.50-000.83/07/12.8306270404.
- 8307280269 Forwards IE Insp Rept 50-309/83-09 on 830523-27 & notice of violation.

  MARTIN-T. T. Division of Engineering & Technical Programs. 83/0

  RANDAZZA: J.B. Maine Yankee Atomic Power Co. 2pp. 19790:165.

  Fiche: 50-309,83/07/13-8307280269.
- --8307280275 Notice of violation from insp on B30523-27 Details withheld (ref 10CFR73.21).

  \* Region 1, Defice of Director. B3/07/13. 2pp. 19790:167. 24X Fiche: 50-309, 83/07/13, 8307280269
- ---8307280284 IE Insp Rept 50-309/83-09 on 830523-27 Noncompliance noted failure to observe portion of isolation zone 5 failure to maintain barrier to access controlled area Portions withheld (ref IOCFR73, 21). BAILEY, R. J., GODY, A. T. Region i, Office of Director. 83/07/11. 7pp. 19790:169. 24X Fiche:50-309.83/07/13.8307280269.
- 8307280276 Forwards IE Inso Rept 50-309/83-07 on 830420-0630 & notice of violation.
  STARDSTECKI.R. Division of Project & Resident Programs.
  RANDAZZA.J.B. Maine Yankee Atomic Power Co. 3pp. 1980
  Fiche: 50-309.83/07/13.8307280276. 19802:112.
- --8307280280 Notice of violation from insp on 830420-0630. \* Region 1. Office of Director. 83/07/13. 1p. 1980 Fiche: 50-309, 83/07/13, 8307280276. 19802:115. 24X
- ---B307280290 lE Insp Rept 50-309/B3-07 on B30420-0630. Noncompliance noted: failure to report unplanned radioactive gas release within 1 h & installation of leak shielding on safety-related piping w/o consideration to plant design criteria. SMETLAND.P. COLLING.S. HOLDEN.C. Region 1, Office of Director. 83/07/08. 13pp. 19802:116. 24x Fiche: 50-309.83/07/13.830?280276.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list enci. TAYLDR.J.M. Division of QA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York: Inc. 114pp. 19715:270. 24X Fiche:50-000.83/07/14.8306270406.
- 8307280436 Submits addi response to IE Rulletin 83-04, "Und Trip Function of Reactor Trip Breakers." New surveillance procedure will permit testing reactor trip breaker undervoltage trip coils independent of shunt trip coils. GARRITY.J.H. Maine Yankee Atumic Power Co. 83/07/20 M Region 1. Office of Director. 2pp. 19797-107. 24X Fiche: 50-309, 83/07/20, 8307280436. "Undervoltage MURLEY, T. E.

#### R. Periodic operating reports & related correspondence

- 8305090466 Forwards "Annual Rept of Facility Changes & Relief & Safety Valve Failures & Challenges, 1982." No challenges or failures of pressurizer or steam generator safety or relief valves occurred during 1982.

  GARRITY, J. H. Maine Yankee Atomic Power Co. 83/04/28. ALLAN, J & Region I. Dffice of Director. 2pp. 18362:184. 24% Fiche: 50-307, 83/04/28, 8305090466.
- B307220012 Monthly operating mept for May 1983.W/830607 ltr.
  BATTERSON.S., GROCE,R.H. Maine Yankee Atomic Power Co. 83/06/07.
  Office of Resource Management, Director. 5pp. 19674:059. 24X
  Fiche:50-309.83/06/07.8307220012.
- 8307120311 Forwards INPO, "Evaluation of Maine Yankee Atomic Power Plant for 1983," from site evaluation conducted during 830116-23.

  BRUNNER, E. J. Division of Project & Resident Programs. 83/07/08.

  TAYLOR-J. M. Division of Reactor Programs (Pre 830103). CASE, E. G. Office of Nuclear Reactor Regulation, Director 1p. 19429:108. 24X Fiche: 50-309, 83/07/08, 8307120311.
- --8307(203)4 "Evaluation of Maine Yankee Atomic Power Plant for 1983." \* Institute of Nuclear Power Operations. 83/05/31. 39pp. 19429:109. 24X Fiche:50-309.83/07/08.8307(203)1.
- S. Reportable occurrences, LERs & related correspondence
- B307010006 RD: on B30305, constant increase observed in real time computer-calculated containment weight of air parameter in monitoring sys. Caused by stuck Exactel monitoring device.

  Device replaced.

  GARRITY, J. H. Maine Yankee Atomic Power Co 83/05/27. ALLAN, J. M. Region I. Office of Director. 2pp. 19149:066. 24X Fiche: 50-307, 83/05/27, 8307010006.
- 8307110444 LER 83-022/01T+0: during survey of safety class piping certain sections of ECCS piping found w/lead shielding installed w/o engineering evaluation of seismic qualification impact. Administrative measures developed. WOOD-E.C. Maine Yankes Atomic Power Co. 83/06/21, MURLEY.T.E. Region 1. Office of Director. 10. 19380.191. 24X Fiche: 50-309.83/06/21,8307110444.
- 8307110269 Updated LER 83-021/01T-0, re control rod drop enalysis. Procedure deficiency specified in 830610 ltr determined not reportable. Procedure changes will remain in effect. MODD.E.C. Maine Yanke Atomic Power Co. 83/06/23. MURLEY, T. E. Region 1. Office of Director. 1p. 19374:257. 24X Fiche: 50-309, 83/06/23, 8307110269.
- B307:10299 Updated LER 83-020/01T-1: on B30607.HPCI line boron concentration not verified. Caused by inadequate startup procedures. Procedures will be revised by 8307:5. H/830701 ltr.
  GARRITY. J. H., LAFLAMME. S. J. Maine Yankee Atomic Power Co. 83/07/01. MURLEY. T. E. Region i, Office of Director 3pp. 19374: 357. 24X Fiche: 50-309.83/07/01.8307110299.
- B307120082 Updated LER B3-022/01T-1: on B30521; during survey of safety class piping, certain sections of piping identified on which lead radiation shielding installed w/o engineering evaluation. Bhielding removed W/B30705 ltr.

  LAFLAMME, S. J., GARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/01. MURLEY, T. E. Region 1, Office of Director. 3pp. 19423: 086. 24X Fichs: 50-309, B3/07/01, 8307120082.
- 830712046B Updated LER 82-009/03'-1: on 82030B, control room ventilation motor operator valve failed to close. Caused by motor failure due to oil & dirt accumulation in motor housing. Valve motor replaced Velve operators will be repriented. W/830701 ltr. CROSBY, R. C., CARRITY, J. H. Maine Yankee Atomic Power Co. 83/07/01. MURLEY, T. E. Region 1. Dffice of Director. 3pp. 19424:194. 24X Fiche: 50-309, 83/07/01, 830712046B.
- 8307150233 LER 83-016/03X-1: on 830507, during routine ECCS hat monthly surveillance testing, safeguards recirculation stop valve SIA-M-54 failed to operate Caused by mechanical binding of valve stem Stem lubricated W/830706 ltr.
  MORRISON, G. M., GARRITY, J. H. Maine Yantee Atomic Power Co. 83/07/06. MURLEY, T. E. Region 1, Office of Director, Spp. 19530: 212, 24X Fiche: 50-309, 83/07/06, 8307150233.
- 8307210006 i.ER 83-024/03L-0: on 830515, while phasing diesel generator D0-18 online per monthly surveillance testing procedure, smoke detector in D0-18 cubicle alarmed Probably caused by accumulated lube oil smoldering. W/830714 itr.
  TIFFANY.T.A. OARRITY.J.H. Malne Yanke Atomic Power Co. 83/07/14. MURLEY.F.E. Region 1. Office of Director 3pp. 17669:231. 24X Fiche: 50-309, 83/07/14. 8307210006.

- 8307220072 Notification of Significant Licensee Meeting 83-51 on B30719 in Region I ofc to discuss unauthorized attachment of lead shielding to safety-related piping & effects on sys operability.

  KELLY.9. Region I. Office of Director. B3/07/14. Region i. Office of Director. 2pp. 19691:346. 24X Fiche:50-309,83/07/14,8307220072.
- B307220451 LER B3-023/03L-O: on B30614, operations personnel removed train A valve HSI-M-41 from svc for maint on valve operator. Train A of ECCS declared inoperable Maint activities completed within 2 h.W/B30714 ltr.
  TIFFANY.T.A., OARRITY, J. H. Maine Yankse Atomic Power Co. B3/07/14 MURLEY.T.E. Region 5, Office of Director. 3pp. 19686:083. 24X Fichs: 50-309,83/07/14,8307220451.
- DOCKET 50-311 SALEM NUCLEAR OF SEATING STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8307210037 Application to amend License DPR-75 adding license conditions to ensure timely implementation of App R fire protection commitments.
  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  83/06/30. VAROA.S.A. Operating Reactors Branch 1. 4pp. 19668:326.
  24X Fichs:50-311,83/06/30,8307210037.
- 8307070057 Forwards Amend i to security contingency plan reflecting changes in internal communications. Amend withheld (ref 10CFR73. 21).
  LIDEN, E. A. Public Service Electric & Qas Co. of New Jersey.
  83/07/01. Region I. Office of Director. 2pp. 19293:347. 24X
  Fiche: 50-272,83/07/01,8307070057.
- 8307150264 Terminates actions required by 820818 Confirmatory Action Ltr 82-22, per 830603 request & IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06. Safeguards info deleted (ref 10CFR73.21).
  STAROSTECKI.R. Division of Project & Resident Programs. 83/07/11. UDERITZ.R.A. Public Service Electric & Gas Co. of New Jersey. 3pp 19538: 085. 24X Fiche: 50-272.83/07/11.8307150264.
- 8307200004 Corrects previous responses to Generic Ltr 82-33 re completion of Reg Guide 1.97 mods for emergency response capability. Confirmation that proposed schedule for implementation acceptable requested.

  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  83/07/12. VAROA.S.A. Operating Reactors Branch 1. 2pp. 19647:127.
  24X Fiche: 50-272,83/07/12,8307200004.
- 8307250449 Provides supplemental info re design of emergency operations facility (EOF). Encl depicts layout of ventilation sys. EOF located at training ctr.
  LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey.
  B3/07/18. VARGA:S.A. Operating Reactors Branch 1. 4pp. 19702:158.
  24X Fiche: 50-272, B3/07/18, B307250449.
- B307220423 Forwards request for add1 info re safeguards regulatory effectiveness review rept. in response to 830323 ltr.Response on first item requested within 30 days. Encl withheld (ref 10CFR73.21).
  VAROA. S. A. Operating Reactors Branch 1. B3/07/19. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 19487: 267. 24X Fiche: 50-272, 83/07/19. B307220423.

#### H. General correspondence

- 8307140121 Responds to 830&01 ltr expressing concerns re NRC decision to permit facility operation in light of serious incidents occurring in Feb 1983 NRC instituted augmented insp program to monitor activities. Plant can be operated safely. DIRCKS.M. J. Office of the Executive Director for Operations. 83/07/01. CASTLE.M.N. Delaware, State of. 2pp. 19539: 354. 24X Fiche: 50-272, 83/07/01, 8307140121.
- --8307140127 Submits comments on behalf of concerned citizens re operation of facility.Plant should be shut down due to gross mismanagement causing serious health & safety risk. NRC should carefully scrutinite operations.

  CASTLE.M.N. Delaware, State of. 83706701. PALLADINO, N. J. Commissioners. 2pp. 19539:356. 24X Fiche: 50-272, 83/07/01, 8307140121.
- J. Insurance & indemnity information
- 8307130240 Forwards Endorsements 59 & 60 to NELIA Policy NF-230 & Endorsements 46 & 47 to MAELU Policy MF-90.
  GOLDEN, M. P. Marsh & McLennan, Inc. 83/07/06. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 19474:352. 24X Fiche: 50-000, 83/07/06, 8307130240.

- 8307280407 Forwards Endorsements 61 & 48 to NELIA Policy NF-230 & MAELU Policy MF-90, respectively.

  GLUEEN, M. P. Marsh & McLennan, Inc. 83/07/20. SALTZMAN, J.
  Assistant Director for State & Licensee Relations. 3pp. 19797:349.

  24X Fiche: 50-272,83/07/20,8307280407.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8307070095 Summarises 276th ACRS meetings on 830414-16 w/utils to review request for OL Agenda for 830512-14 meetings encl. EBERBOLE, J. ACRS Advisory Committee on Reactor Safeguards. 83/04/29. PALLADING, N.J. Commissioners. 3pp. 19366:058. 24X Fiche: 50-000.83/04/29.8307090095.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PWRs rs safety evaluation of "Emergency Response Guidelines." 8vc list encl.
  EISENNUT. D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19363:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307210037 Application to amend License DPR-75 adding license conditions to ensure timely implementation of App R fire protection commitments.
  LIDEN.E.A. Public Service Electric & Oas Co. of New Jersey.
  B3/06/30. VARCA.S.A. Operating Reactors Branch 1. 4pp. 17668:326.
  24X Fiche: 50-311.83/06/30.8307210037.
- 8307210104 Modified application for amend to Licenses DPR-70 & DPR-75, clarifying determination that NSHC involved in implementation of proposed Tech Spec chages re ETS & administrative controls.

  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  B3/07/01. VAROA.B.A. Operating Reactors Branch i. 11pp.
  19468:219. 24X Fiche: 50-272,83/07/01,8307210104.
- 8304270397 Generic Ltr 83-26 to all applicants for DLs & helders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. O. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. O. Division of Licensing, 83/07/06. Consolidated Edison Co. of New York, Inc. 1699. 19669:254. 24X Fichs: 50-000,83/07/06,8307060329.
- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. 8vc list encl. EISENHUT. D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X Fiche: 50-000.83/07/08.8307080169.
- 8307250427 Submits response to 830428 commitment re corrective action program mods. Proposed ATMS rule in final stages of review prior to presentation for approval. Breaker shunt trip function will be incorporated into automatic trip circuits. LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey. 83070715. VAROA.B.A. Querating Reactors Branch 1. 2pp. 19701:190. 24X Fiche: 50-272, 83/07/15, 8307250427.
- 8307270402 Submits current status of conformance w/830708 Generic Ltr B3-28 re required actions based on generic implications of reactor trip breaker failures on 830222 & 25. LIDEN.E.A. Public Service Electric & Gas Co. of New Jarsey. 83/07/22. VAROA.S.A. Operating Reactors Branch 1. 4pp. 19767:111. 24X Fiche: 50-272.83/07/22.8307270402.
- --B307270406 Rev 3 to Procedure AD-16, "Post-Reactor Trip/Bafety Injection Review,"

  \* Public Service Electric & Gas Co. of New Jersey, B3/07/14, 21pp. 19767:115. 24X Fiche: 50-272, 83/07/22, 8307270402.
- G. Inspection reports: IE Bullstins & correspondence
- 8307010007 Forwards IE Insp Repts 50-272/83-18 & 50-311/83-17 on 830517-24. No noncompliance noted.
  MARTIN.T. T. Division of Engineering & Technical Programs. 83/06/14.
  UDERITZ.R.A. Public Bervice Electric & Gas Co. of New Jersey. 2pp. 19169:068. 24X Fiche: 50-272, 83/06/14.8307010007.

- --8307010012 IE Insp Repts 50-272/83-18 & 50-311/83-17 on 830517-24. No noncompliance noted Major areas inspected: followup of previous insp findings re procedure review test witnessing & results evaluation of local & integrated leak rate testing. PULLANI: S. V. BETTENHAUSEN.L. Region 1. Office of Director. 83/06/09. 9pp. 19169:070. 24X Fiche: 50-272,83/06/14,8307010007.
- B307140232 Forwards 1E Insp Rept 50-311/83-14 on 830417-18,21 & 22 & notice of violation.

  MARTIN.T. T. Division of Engineering & Technical Programs. 83/06/28, UDERITZ.R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 19523:087. 24X Fiche: 50-311,83/06/28,8307140232.
- --8307140233 Notice of violation from insp on 830417-18.21 & 22.

  \* Region 1, Office of Director, 83/06/28. ip. 17523:089. 24X
  Fiche: 50-311.83/06/28.8307140232.
- --8307140235 IE Insp Rept 50-311/83-14 on 830417-18,21 & 22. Noncompliance noted: failure to implement engineering controls per 100FR20. 103. Bection 5 & failure to perform airborns radioactivity measurements per 100FR20.103(a); Bection 6, NIMIT2.R.L., SHANBAKY.M.M. Region 1, Office of Directon. 83/06/08. 15pp. 19523:090. 24X Fiche: 50-311,83/06/28,8307140232.
- 8307130306 Responds to 830505 notice of violation & proposed imposition of civil penalties re 830822 & 25 ATMS events. Magnitude of civil penalty disputed. Events were isolated occurrences.

  SELOVER, R. E. Public Bervice Electric & Gas Co. of New Jersey.
  83/07/06. DEVOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 44pp. 19474:106. 24X Fiche: 50-272, B3/07/06.
  8307130306.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JURDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbere as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gassous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307270462 Forwards proposed augmented insp plan for monitoring & evaluating util performance improvement program & Mgt
  Analysis Co final rept. "Mgt Assessment & Action Plan for
  Improvement of Salem Btations i & 2 Operations."
  EISENHUT.D.Q. Division of Licensing. 83/07/20. Division of
  Licensing. 2pp. 17802:134. 24X Fiche: 50-272,83/07/20,B307270462.
- --8307270464 Discusses proposed augmented insp plan for monitoring & evaluating util performance improvement program over next 2 yrs.

  8TAROSTECKI,R. Division of Project & Resident Programs. 83/06/23.

  BENTON, H.R. Diffice of Nuclear Reactor Regulation, Director.

  DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. MURLEY, T. Region 1, Diffice of Director. 79p. 19802; 156. 24X Fiche: 50-272,83/07/20,8307270462.
- --8307270466 "Mgt Assessment & Action Plan for Improvement of Salem Stations 1 & 2 Operations." \* Management Analysis Co. 83/06/24. 73pp. 19802:163. 24X Fiche: 50-272, 83/07/20, 8307270462.
- 8307280211 Forwards 1E Mgt Meeting Repts 50~272/83~21 & 50~311/83~21 on 830518.

  STAROSTECKI,R. Division of Project & Resident Programs. 83/07/20. UDERITZ,R. Public Service Electric & Gas Co. of New Jersey. 2pp. 19794:004. 24X Fiche: 50~272, 83/07/20, 8307280211.
- --8307280227 IE Mgt Meeting Repts 50-272/83-21 & 50-311/83-21 on 830518. Major areas discussed:diagnostic objectives & initial findings of Mgt Analysis Co evaluation. JACOBS, R. Region 1. Office of Director. TRIPP, L. Division of Project & Regident Programs. 83/07/19. 4pp. 19794:006. 24X Fiche: 50-272,83/07/20,8307280211.
- 8307290487 Notification of significant licensee 830722 enforcement conference in King of Prussia, PA.
  KISTER.H. B. Region i, Office of Director. 83/07/20, Region i, Office of Director. 1p. 19858: 292. 24X Fiche: 50-311, 83/07/20, 8307290487.

- 8307270395 Suppls 830704 response to NRC 830505 notice of violation & proposed imposition of civil penalties re 830222 & 25 events at Unit 1 Requests that civil penalties be eliminated in light of reasons stated.

  BELOVER.R.E. Public Service Electric & Gas Co of New Jersey.
  83/07/22. DEYDUNG.R.C. Director's Office. Office of Inspection and Enforcement. 10pp. 19767:201. 24x Fiche: 50-272.83/07/22.
- --B307270416 Submits response to B30428 commitment to submit detailed rept describing corrective action program mods. Surveillance, maint & insps. increased to ensure reliability of reactor trip sys.
  LIDEN.E.A. Public Service Electric & Gas Co. of New Jersey.
  B3707/15. VARGA.S.A. Operating Reactors Branch 1. 2pp.
  19767:236. 24X Fiche: 50-272, B3/07/22, B307270375.
- A. Periodic operating reports & related correspondence
- 8307150105 Monthly operating rept for June 1983.W/830710 ltr.
  MILLER.L.K., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 83/07/10. Director's Office, Office of Inspection and Enforcement. 21pp. 19534:134. 24x Fiche:50-311,83/07/10, contributes.
- S. Reportable occurrences, LERs & related correspondence
- 8307120243 LER 83-021/0iP: on 830525, vital instrument bus inverter 2C taken out of svc for planned maint rendering associated ac electrical bus train inoperable. Containment air locks could not be closed during maint investigation undermay. ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 83/05/26 ALLAN. J. Region 1. Office of Director. ip. 19423: 194. 24X Fiche: 50-311, 83/05/26, 8307120243.
- 930712023B LER 63-022/01P: on 830530; during routine shutdown operation, loss of power occurred, rendering ac electrical bus train inoperable investigation in progress. Detailed rept will be submitted within 14 days.
  ZUPKO.J.M. Public Service Electric & Gas Co. of New Jersey.
  B3/05/31 ALLAM.J. Region 1. Office of Director. 1p. 19423:200.
  24X Fiche: 50-311, B3/05/31, B30712023B.
- B307190123 Corrected LER B3-023/03L-0 on 830117-0418, seven containment isolation valves experienced leakage rates preater than max range of test equipment. Total containment Tupe B & C leakage could not be demonstrated. Valves repaired. W/B30711 ltr. FRAHM.R., ZUPKO.J. M. Public Service Electric & Qas Co. of New Jarsey. B3/06/08. MURLEY, T. E. Region 1, Office of Director. Spp. 19636:046. 24X Fiche: 50-311, 83/06/08. B307190123.
- 8307050025 LER 83-026/04L-0: on 830529, diesel fuel oil storage tanks overfilled resulting in release of approx 200 gallons of oil into Delaware River Spill contained w/booms. Caused by operator error. W/830622 ltr. FRAHM, R., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 83/06/15. ALLAN, J. Region 1, Office of Director. App. 19193:332. 24X Fiche: 50-311.83/06/15.8307050025.
- 8307140196 LER 83-D28/O3L-0; on 830607, discovered that auxiliary bldg ventilation sys charcoal absorber failed freen test due to absorber degradation Caused by refrigeration coolant leaks & leakage from freen decontamination unit. 0/830628 ltr. FRAHM, R. ZUPKOLJ, M. Public Service Electric & Gas Co. of New Jersey. 63/06/22. ALLAN, J. Region 1. Office of Director. App. 19522:062. 24X Fiche: 50-311, 83/06/22. 8307140196.
- 8307140293 LER 83-027/03L-0:on 830604, during t8-month surveillance of fuel handline area ventilation sys, charcoal absorber failed freen test Caused by saturation from water vapor due to humid fuel storage atmosphere Study underway, M/830628 ltr. FRAHM. R. ZUPKD, J. M. Public Service Electric & Gas Co. of New Jersey. 83/06/22. ALLAN, J. Region 1, Office of Director. App. 19523:318. 24x Piche: 50-311, 83/06/22. 8307140293.
- B307210003 Supplemental LER 62-077/01X-1: on 820818, leakage discovered from containment fan coil 21 Caused by erasion of cupper nickel piping. Cooling coils replaced w/erasion-resistant matl. W/B30707 ltr.
  FRAHMER. 7 CUPKG.J.M. Public Service Electric & Gas Co. of New Jersey. B3/06/29. ALLAN.J. Region 1. Office of Director. Spp. 1968: 185. 24X Fiche: 50-311. B3/06/29. 8307210003.
- 8307210007 Supplemental LER 82-024/03X-1: on 820328, sample results from boric acid storage tank 21 % boron injection tank 22 indicated concentrations below Tech Spec limit Cause unknown Boric acid added W/830707 Itr FRAHM, R. 7 ZUPKO, J. H. Public Service Electric & Cas Co. of New Jersey. 83/04/29. ALLAN, J. Region J. Office of Director. Spp. 19649; 249. 24X Fiche: 50-311, 83/06/29, 8307210009.

- 8307210112 Updated LER 82-078/01X-1: on 820819, svc water leak discovered within containment, Caused by sitt in svc water eroding containment fan coil 25 motor cooler. Design Change Request 2EC-0307 issued & cooler replaced. W/830707 ltr. FRAHM.R., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jarsey, 83/06/29, ALLAN, J. Region 1, Office of Director, 5pp. 19668: 207. 24X Fiche: 50-311, 83/06/29, 8307210112.
- 8307210134 Supplemental LER 82-070/01X-1: on 830809, 0.5 gpm syc water leak observed on containment fan coil 24. Caused by failed cooling coil resulting from silt erosion by particles in syc water. M/830707 ltr.
  FRAHM.R. ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 83/06/29, ALLAN.J. Region 1, Office of Director. 5pp. 19666:093. 24X Fiche: 50-311, 83/06/29, 8307210134.
- B307130255 Notifies that short-term items contained in corrective action program relating to reactor trip breaker failures on 830222 & 25 complete.

  LIDEN.E. A. Public Service Electric & Gas Co. of New Jersey.
  B3/07/01. VARCA.B. A. Operating Reactors Branch 1. 1p. 19474:362.
  24X Fiche: 30-311,83/07/01,8307130255.
- 8307220345 LER B3-029/97L-0: on 830617, test safety injection actuation initiated & charging pump 22 inadvertently left in svo. causing actuation of pressurizer overpressure protection systalves. Caused by delay in initiating test. W/830714 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 83/07/06. MURLEY, T. E. Region 1, Office of Director. 4pp. 19675:328. 24X Fiche: 30-311,83/07/06.8307220345.
- 8307220558 LER 83-030/03L-0: on 830620, during routine shutdown operation, infeed breaker 28 460-volt transformer tripped on timed overcurrent relay operation. Caused unknown. Investigation underway. Transformer replaced. W/830714 ltr. FRAHM.R. ZUPKO.J. M. Public Service Electric & Gas Co. of New Jersey. 83/07/04. MURLEY.T. E. Region 1, Office of Director. 4pp. 19686:066. 24X Fiche: 30-311,83/07/06.8307220558.
- 8307290045 Reviews AEOD final rept, AEOD/P301, "Rept on Implications of ATMS Events at Salem Nuclear Power Plant on NRC Programs for Collection & Analysis of Operational Experience." Subj of reactor trip reliability well treated.

  DENTON, H.R. Defice of Nuclear Reactor Regulation, Director.

  83707/21. HELTEMES, C. J. Director's Office. 1p. 19858:171. 24X

  Fiche: 50~272, 83/07/21, 8307270045.
- ---8307130129 Forwards "Rept on Implications of ATMS Events at Balem Nuclear Power Plant on NRC Program for Collection & Analysis of Operational Experience."

  HELTEMES.C.J. Director's Office. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19858:172. 24X Fiche: 50-272.83/07/21,8307290045.
- 8307280458 PNG-1-83-078: on B30722, startup commenced following first refueling outage on B30121. Zero power physics testing will be conducted for 2-3 days. Corrective actions per 830506 order re ATMS events verified.

  SUMMERS,R., JACOBS,R., KISTER,H. Region 1. Office of Director.
  B3/07/22. 1p. 19797:244. 24X Fiche: 50-311,83/07/22,8307280458.
- 8307280358 LER 83-035/01P: on 830725, during zero power physics testing for Cycle II startup, flux map results indicated enthalpy hot channel factors would be exceeded for operation at low. More conservative control rod insertion limits established. ZUPKO, J.M. Public Bervice Electric & Oas Co. of New Jersey. 83/07/26. MURLEY, T. E. Region 1, Office of Director. 1p. 19789: 239. 24X Fiche: 50-311, 83/07/26, 8307280358.
- 8307280427 LER 83-036/01P-0:on 830726. during startup.emergency core cooling accumulator 23 level exceeded Tech Spec limit, rendering accumulator inoperable. Cause under investigation. Accumulator drained to restore level.
  ZUPRO.J.M. Public Service Electric & Gas Co. of New Jersey. 83/07/26. MURLEY.T.E. Region 1, Office of Director. 19. 19795:312. 24X Fiche: 50-311, 83/07/26. 8307280427.
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION
  F. Security, medical, emergency & fire protection plans
- 8307060376 Forwards draft findings based on review of encl FEMA draft lth & evaluation of emergency response plan for Rancho Seco Nuclear Generating Station & on IE Insp Rept 50-312/83-09. Corrective actions requested within 4 months. MARTIN.J.B. Region 5. Office of Director. 83/06/15. RODRIGUEZ.R.J. Sacramento Municipal Utility District. 4pp. 19236:258. 24X Fichs: 50-312,83/06/15,8307060376.
- ---8307060384 Evaluation of emergency response plan for Rancho Seco Nuclear Generating Station Major deficiencies identified. • Federal Emergency Management Agency. 82/06/23. 72pp. 19236: 262. 24X Fiche: 50-312.83/06/15.8307060376.

- 8307060422 Forwards exemption from annual full-scale emergency preparedness exercise requirement of 10CFR50, App E. Baction IV.F. I. in response to 830303 request & 830331 suppl. Full-scale exercise should be conducted no later than 840131. STOLZ. J. F. Operating Reactors Branch 4. 83/06/15. RODRIQUEZ.R. J. Sacramento Municipal Utility District. 4pp. 19299:355. 24X Fiche: 50-312.83/06/15,8307060422.
- --8307060427 Exemption from 10CFR30.App E.Section IV.F.1 requirements for annual full-scale emergency preparedness exercise.subj to listed mods & conditions.

  PURPLE.R.A. Division of Licensing. 83/06/13. Bacramento Municipal Utility District. 4pp. 19299:339. 24X

  Fiche: 50-312,83/06/15,8307060422.
- 8307060021 Discusses review of results of Rev 15 to emergency plan submitted by 821217 ltr per App E of 10CFR50. Section 50.47 & Reg Ouide 1.101. Rev 2 which endorses NUREG-0654. Deficiencies still exist in emergency plan.

  NORDERHAUG, L. R. Region 3. Office of Director. 83/06/20.

  RODRICONEZ, R. J. Bacramento Municipal Utility District. 5pp. 19251:042. 24X Fiche: 50-312.83/06/20.8307060021.
- 8307250233 Suppl 1 to 830217 proposed Amend 83 to License DPR-54 re NUMEO-0737 items & fire protection. RODMIOUEZ,R.J. Sacramento Municipal Utility District. 83/07/12. 818EMHUT.D.O. Division of Licensing. 1p. 19706:045. 24X fiche: 50-312.83/07/12.8307250233.
- --8307250240 Proposed Tech Specs re nuclear svc bus extensions & fire protection.

  \* Bacramento Municipal Utility District. 83/07/12. 7pp. 19706:046. 24X Fiche:50-312.83/07/12.8307250233.
- 8307280445 Forwards corrective action plan to address emergency preparedness deficiencies.
  RODRIGUEZ, J. Bacramento Municipal Utility District. 83/07/15.
  HARTIN, J. B. Region 5. Office of Director. 11pp. 19797:311. 24X
  Fiche: 50-312, 83/07/15, 8307280445.
- 8307260015 Forwards estimated completion dates for emergency response capability upgrade items & revised dates for Reg Guide 1.97 position & justification repts, in response to NUREO-0737, Buppl 1 & Generic Ltr 82-33, RODRIOUEZ, R. J. Bacramento Municipal Utility District. 83/07/20. STOLI.J.F. Operating Reactors Branch 4. 3pp. 19727:174, 24X Fiche: 90-312, 83/07/20, 8307260015.

#### 9. Adjudicatory correspondence

- 8307:90229 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC. BAXTER.T.A. Shaw, Pittman, Potts & Trowbridge. BAXTER.T.A. Bacramento Municipal Utility District. 83/07/13. ROSENTHAL.A.S., BUCK.J.H.; KOHL.C.N. Atomic Bafety and Licensing Appeal Panel. 1p. 17630:106. 24X Fiche: 50-312,83/07/13,8307170227.
- --8307190242 Notifies of employment at law firm. VR Harding will not participate in any case pending before NRC. Svc list encl. HARDING, V.R. Shaw, Pittman, Potts & Trowbridge. 83/07/13. ROSENTHAL, A.B., BUCK, J.H., KOHL, C.N. Atomic Safety and Licensing Appeal Panel. 2pp. 19630:107. 24X Fiche: 50-312,83/07/13,8307190229.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307270433 Forwards Amend 1 to updated FSAR. RODRIGUEZ, R. J. Sacramento Municipal Utility District. 83/07/22. BTOLZ, J. F. Operating Reactors Branch 4. lp. 19765:082. 24X Fiche: 50-312, 83/07/22, 8307270433.
- P. Operating license stage documents & correspondence
- 8307220585 Notice of consideration of issuance of amend to License DPR-54 & proposed NSHC detarmination & opportunity for hearing re changes in core design for sixth reload cycle. 8TOLZ, J.F. Operating Reactors Branch 4. 83/06/17. 10pp. 19498:295. 24X Fichs: 30-312.83/06/17.8307220585.
- 8307040317 Forwards BAN-1784, "B&W Umners Group Bolting Task Force Bummary Rept of NRC/B&W Owners Meeting on Reactor Vessel Internals Bolting." Test results support continued operation w/original lower core harrel bolts.

  RODRIGUEZ, R. J. Bacramento Municipal Utility District. 83/06/24.

  EISENHUT, D. 9. Division of Licensing. 3pp. 19237: 243. 24X

  Fiche: 50-312, 83/06/24, 8307060317.

- B30706043D Forwards safety evaluation of util proposed mod for storage of reactor cavity annular ring above reactor during operation. Proposed mod meets AISC & uppraded FSAR requirements & is acceptable.

  BTOL7.J.F. Operating Reactors Branch 4. B3/06/24. RODRIQUEZ, R. J. Bacramento Municipal Utility District. 3pg. 19300:080. 24X
  Ficha: 50-312,83/06/24,8307060430.
- --8307060433 Safety evaluation of util proposed mod for storage of reactor cavity annular ring above reactor during operation. Mod will simplify shutdown operation. Approval recommended. \* Operating Reactors Branch 4. 63/06/24. 2pp. 19300:083. 24X Fiche: 50-312,83/06/24,8307060430.
- 8307080236 Forwards supplemental safety evaluation input re control room radiation monitor & containment ventilation isolation manual switches. Upgrading control room radiation monitor to safety-grade & design for manual isolation acceptable.
  870LZ.J.F. Operating Reactors Branch 4. 83/06/24. RODRIGUEZ.R.J. Bacramento Municipal Utility District. 3pp. 19364:016. 24X Fiche: 50-312.83/06/24.8307080236.
- --8307080250 Supplemental safety evaluation of override of containment purge isolation. Upgrading control room radiation monitor to safety-grade & design provisions for manual isolation acceptable.

  \* NRC No Detailed Affiliation Given. 83/06/24. ip. 19364:019. 24X Fiche: 50-312, 83/06/24, 8307080236.
- B307010034 Provides rept on reactor vessel maths surveillance program. Tech Specs remain valid & limits will be modified before expiration to account for ongoing irradiation & to extend applicable surveillance period.

  RODRIQUEZ.R.J. Sacramento Municipal Utility District. B3/06/27.

  BT0L2.J.F. Operating Reactors Branch 4. 2pp. 19169:026. 24X Fiche: 50-312.83/06/27, 8307010034.
- 8307070012 Forwards Class III fee for review of 830106 request re mods for storing reactor cavity annular sealplate during operation request for air filter charcoal disposal methods evaluation & 830031 request for exemption from order. RODRIGUEZ, R. J. Bacramento Municipal Utility District. 83/06/28. HILLER, M. O. License Fee Management Branch. 1p. 17273: 225. 24X Fiche: 50-312,83/06/28,8307070012.
- 8307070441 Requests remittance of balance due for review of 830106, 0213,0328 & 31 submittals & 830217 application.
  MILLER.W. 9. License Fee Management Branch. 83/06/29,
  RDDR10MEZ.R.J. 8acrammento Municipal Utility District. 1p.
  19362:225. 24x Fiche:50-312,83/06/29,8307070441.
- B307110235 Forwards suppl to proposed Amend 94 to License DPR-54 revising calibr section of bases for Tech Specs Part 4.1, operational safety review No addl license fee required. RODRIGUEZ/R. J. Sacramento Municipal Utility District. B3/06/29. EISENHUT. D. Q. Division of Licensing. 1p. 19380:016. 24X Fiche: 50-312.83/06/29.8307110235.
- --8307110237 Proposed Tech Spec changes, revising callbr section of bases from operational safety review.Part 4. 1.

  + Sacramento Municipal Utility District. 83/06/29. 1p. 19380:017. 24X Fiche:50-312.83/06/29.8307110235.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of DPs for power reactors re clanification of surveillance requirements for dissel fuel impurity. Svc list encl. EIBENHUT, D. 0. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- B307040329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in BTS. Byo List encl. EISENHUT. D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 1969:254. 24X Fiche: 50-000,83/07/06,8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Bvc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307190012 Updates status of low temp overpressurization protection controls. Ability to comply w/submittal schedule contingent on receipt of acceptable SER by 840405.
  RODRIGUEZ,R.J. Sacramento Municipal Utility District. 83/07/11.
  8TOLZ.J.F. Operating Reactors Branch 4. 2pp. 19560:292. 24X Fiche: 50-312.83/07/11.8307180012.

- B307250233 Suppl 1 to 830217 proposed Amend 83 to License DPR-54 re NUREG-0737 items & fire protection.
  RODRIGUEZ.R.J. Sacramento Municipal Utility District. 83/07/12.
  EISENNUT.D.G. Division of Licensing. 1p. 19706:045. 24X
  Fiche: 50-312.83/07/12.8307250233.
- ---8307250240 Proposed Tech Specs re nuclear svc bus extensions & fire protection.

  \* Sacramento Municipal Utility District. 83/07/12. 7pp. 19706:046. 24X Fiche: 50-312.83/07/12.8307250233.
- B307280350 Forwards response to NRC B30628 & 0707 requests for addlinfo re NURED-0737. Item II. B. 2. "Plant Shielding." RODR50HEZ.R.J. Sacramento Municipal Utility District. 83/07/14. HARTIN.J. B. Region 3. Office of Director. 6pp. 19790:111. 24x Fiche: 50-312. B3/07/14. B3072B0350.
- B30726017B Provides add1 info re NUREG-0737. Item II.K. 2.10 re anticipatory reactor trip sys.in support of request for etemption from NRC B30314 order. Request applies only to loss of main feedwater.

  RUDRIGUEZ.R. J. Sacramento Municipal Utility District. B3/07/20. BTOLZ.J.F. Operating Reactors Branch 4. 2pp. 19727:100. 24X Fiche: 50-312, B3/07/20, B30726017B.
- 8307260352 Forwards addition of spent fuel rack mod in response to B30719 telcon. Spent fuel cooling sys designed to quality & seismic Category 2 & ASME Section III Nuclear Class 3. No pipe break assumed since mod does not change analysis. ROBRIGUEZ, R. J. Sacramento Municipal Utility District. 83/07/22. STOLZ, J.F. Operating Reactors Branch 4. 7pp. 19733:017. 24x Fiche: 50-312,83/07/22,8307260352.
- G. Inspection reports. IE Bulletins & correspondence
- B307060376 Forwards draft findings based on review of encl FEMA draft lit & evaluation of emergency response plan for Rancho Seco Nuclear Generating Station & on IE Insp Rept 50-312/83-09. Corrective actions requested within 4 months. MARTIN.J. B. Region 5. Office of Director. 83/06/15. RODRIQUEZ.R.J. Bacramento Municipal Utility District. 4pp. 19236:258. 24x Fiche: 50-312, B3/06/15. B307060376.
- --8307060384 Evaluation of emergency response plan for Rancho Seco Nuclear Cenerating Station. Major deficiencies identified. \* Federal Emergency Management Agency. 82706723. 72pp. 19236: 262. 24X Fiche: 50-312, 83706715, 8307060376.
- B307120511 Forwards IE Insp Rept 50-312/B3-17 on B30430-060B No noncompliance noted.
  STERNBERG, D. M. Region 5, Office of Director. B3/06/20.
  RODRIGUEZ, R. Sacramento Municipal Utility District. 2pp. 19433; 227. 24X Fiche: 50-312, 83/06/20, 8307120511.
- --8307120519 IE Insp Rept 50-312/83-17 on 830430-0608.No noncompliance noted Hajor areas inspected:maint & surveillance operations. This modification of LERS:plant operations, followup on antorcement items & regional requests & media contacts. CANTER:H.L., O'SRIEN.J., YOUNG.T. Region 5: Office of Director. 83/06/17. 15pp. 19433:229. 24x Fiche:50-312.83/06/20.8307120511.
- B307190099 Forwards rept of annual reactor bldg structural integrity insp performed during June & Jul 1983.
  RODRIGUEZ, R. J. Sacramento Municipal Utility District. 83/07/07.
  MARTIN. J. B. Region 5. Office of Director. 2pp. 19634:256. 24X
  Fiche: 50-312.83/07/07.8307190099.
- --8307190102 Rev 3 to Procedure SP 205.04, "Surveillance of Containment Structure Interior & Exterior Surfaces."

  a Secretain Municipal Utility District. 83/01/13. 16pp. 19634: 238. 24X Fiche: 50-312,83/07/07,8307190099.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 33/07/II. Consolidated Edison Co. of New York. Inc. 154pp. 19363: 293. 24x Fiche: 50-000, 83/07/II. 8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc List encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Past 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133. 24% Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive 1-125 & 1-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.

- 8307260459 Forwards status rapt on implementation of electrical squipment environ qualification upgrades in response to IE Bulletin 79-018. Scotch insulation tape replaced by qualified Raychem matis.
  RODRIQUEZ.R.J. Sarramento Municipal Utility District. 83/07/20. STOLZ.J.F. Operating Reactors Branch 4. opp. 19731:169. 24X Fiche: 50-312, 83/07/20. 8307260459.
- 8307280250 Informs that insp of two fuel assemblies that operated in core Location O-3 during Cycles 3.4 & 5 completed. Lower end fittings inspected using underwater video camera. No damage noted.

  RDDRIGUEZ.R. J. Sacramento Municipal Utility District. 83/07/22.

  8TOLZ, J. F. Operating Reactors Branch 4. 1p. 19795:277. 24X Fiche: 50-312,83/07/22,8307280250.
- R. Periodic operating reports & related correspondence
- 8307260553 Monthly operating rept for June 1983.W/830713 ltr. COLUMBO.R., DUBRE.R.P. Sacramento Municipal Utility District. 83/06/30. Director's Office, Office of Inspection and Enforcement. 8pp. 19734:017. 24X Fiche:50-312.83/06/30,8307260553.
- S307190099 Forwards rept of ennual reactor bldg structural integrity insg performed during June & Jul 1983.
  RODRIGUEZ.R. J. Sacremento Municipal Utility District. 83/07/07.
  MARTIN.J.B. Region 5. Office of Director. 2pp. 19634:256. 24X
  Fiche: 50-312.83/07/07.8307190099.
- --8307190102 Rev 3 to Procedure SP 205.04. "Surveillance of Containment Structure Interior & Exterior Surfaces." \* Sacramento Municipal Utility District. 83/01/13. 14pp. 17634:258. 24X Fiche: 50-312.83/07/07.8307190099.
- S. Reportable occurrences. LERs & related correspondence
- B307180010 Updated LER 83-007/03L-1: on B30204 & 0330-31, reactor coolant pump power relays found out of spec. Caused by stuck internal relay or bad diode & potentiometer. Other relays tested satisfactorily, Relays repaired. W/B30705 ltr.
  COLOHBU, R. W., RODRIGUEZ, R. U. Sacramento Municipal Utility District. B3/04/2B. MARTIN. J. B. Region 5, Office of Director. 3pp. 17560: 203. 24x Fiche: 50-312,83/04/2B.8307180010.
- 8307150111 Part 21 rept re 8-inch uninsulated section of red conductor on 3-conductor 12 gauge wire supplied to facility during 1980. Info obtained 830616. Cause under investigation.
  ROBERTS, L. B. Brand-Res Co. 83/06/20. COLLING. J. Region 4. Office of Director. 2pp. 19536:213. 24% Fiche: 50-312.83/06/20.8307150111.
- 8307060055 Corrected PNS-V-83-008: on 830620, QC inspector discovered three nonsafety-related cables cut near termination & two meters smashed Possibly caused by termination of employees.

  CANTER.H.: YOUNG.T. Region 5. Office of Director. 83/06/22. ip. 19250: 285. 24X Fiche: 50-312,83/06/22,8307060055.
- B307060049 RO B3-23: on B30526: pump P-261A. DHR pump A failed to start. Cause not stated. Breaker ITE 4 kV racked out & back in & Pump started. B306024. GORROUGEZ.R. J. Bacramento Municipal Utility District. B3/06/24. HARTIN.J. B. Region 5, Office of Director. ip. 17250: 342. 24X Fiche: 50-312,83/06/24,8307060049.
- 8307040068 RO 50-312/83-04: on 830517 & 21. diesel-driven fire pump engine overheated resulting in loss of coolant. Caused by KX coolant leak. Replacement parts ordered & engine repaired & returned to svc on 830601.
  ROBRIGUEZ.R. J. Sacramento Municipal Utility District. 83/06/24. MARTIN.J. B. Region 5. Office of Director. 1p. 19250:361. 24X Fiche: 50-312,83/06/24,8307060068.
- B307170161 LER B3-023/03L-0: on 830526, DHR pump A failed to start on demand. Cause unknown. Breaker racked out, then racked back in, Pump started.
  COLOMBD.R. M., RODRIGUEZ, R. J. Sacramento Municipal Utility District. B3/06/24, MARTIN. J. B. Region 5, Office of Director. 2pp. 19636: 258. 24X Fiche: 50-312,83/06/24,8307190161.
- 8307060152 RO 83-05: on 830610, snce-through steam generator B tubes 75-13 & 73-5 found to have outer diameter crack indications at tube support plate (TBP) 15. Top plugs incorporated stabilizer rod from TSP 14.

  RODRIGUEZ, R. J. Sacramento Municipal Utility District. B3/06/27. MARTIN, J. B. Region 5. Office of Director. 1p. 19249: 205. 24X Fiche: 50-312, 83/06/27, 8307060152.

- 8307180240 RO 83-026: on 830625, air-operated safety features valve SFV 66307 found inoperable in open position. Caused by broken plastic inside control relay. During period valves inoperable, fuel moved in reactor bldg, violating Tech 8pecs. COHARD. G. A. Sacramento Municipal Utility District. 83/06/27. MARTIN. J. B. Region 5, Office of Director. 2pp. 19555:264. 24X Fiche: 50-312, 83/06/27, 8307180240.
- 8307290043 Part 21 rept re speed settings on nameplate for EGB-13C actuator. Caused by binding nameplate for spare actuator. Actuator will be tested w/nameplate installed & aligned. Purchase order of Bi1020 encl.
  ZMIEO.A. Moodward Governor Co. B3/06/29. COLLINS.J.T. Region 4 Office of Director. 10pp. 19821:024. 24X Fiche: 50-312.83/06/29, 8307290043.
- 8307120521 LER 83-025/03L-0: on 830601, during records review, effluent sample on Release ERDF 83-56 discovered not performed.

  Gaused by operator failing to notify chem-rad officer at onset of release. Procedure revised. W/830630 ltr.

  COLOMBO.R.W., RODRIQUEZ.R.J. Sacramento Municipal Utility District.
  83/06/30. MARTIN.J.B. Region 5. Office of Director. 2p.
  19433:085. 24X Fiche:50-312:83/06/30,8307120521.
- B307190109 LER B3-026/01T-0: on 830625, valve SFV 66309 found inoperable in open position. Caused by piece of plastic undged in stab connection & misalignment in relay contacts. Inplace field mods no longer performed. W/B30629 ltr. COLOMBO.R.W., RODRIQUEZ.R.J. Sacramento Municipal Utility District. B3/06/30. MARTIN.J.B. Region 5, Office of Director. 3pp. 19634:245. 24X Fiche: 50-312,83/06/30,8307190109.
- 8307210122 Interim Part 21 rept re 8-inch uninsulated section of red canductor, 3-conductor, 12-pauge wire shipped during 1980 to facility. Info obtained 830616. Condition under evaluation. ROBERTS, L. B. Brand-Rex Co. 83/07/01. Director's Office, Office of Inspection and Enforcement. 2pp. 19668: 195. 24x Fiche: 50-312, 83/07/01, 8307210122.
- B307280393 LER B3-029/O3L-0: on B30617, individual entered reactor bldg hatch from inside bldg & closed inner door & then opened outer door causing inner door to open. Caused by individuals not observing door position warning light W/B30714 ltr. CGLDMBO.R.W., RODRIOUEZ.R.J. Bacramento Municipal Utility District. B3/07/14. MARTIN.J.B. Region 5. Office of Director. 3pp. 19796:060. 24X Fiche: 50-912,83/07/14,8307280393.
- 8307280432 Rev 1 to RO 83-05: on 830610, once-through steam generator B tubes 75-13 & 73-5 removed from svc by explosive plugging. Crack indications found at 15th tube support plate (TSP). Top plugs incorporated stabilizer rods from 14th TSP. RODRIOUEZ, R. J. Sacramento Municipal Utility District. 83/07/14, MARTIN.J. B. Region 5, Office of Director. 1p. 19797:120. 24X Fichs: 50-312, 83/07/14, 8307280432.
- DOCKET 50-313 ARKANSAS NUCLEAR DNE, UNIT 1
- F. Becurity, medical, emergency & fire protection plans
- 8307120269 Notifies that Procedures 1405.16 & 2405.16 "Electrical Penetration Fire Barriers," revised per 830405 ltr. Procedures reflect insp requirements for barriers instituted from App R analysis. Procedures implemented after 830603. MARSHALL, J.R. Arkansas Power & Light Co. 83/05/31. SEIDLE, W.C. Region 4, Dffice of Director. 2pp. 19424:159. 24X Fiche: 50-313, 63/05/31, 6307120269.
- 8307060282 Forwards IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830518-22. No noncompliance noted.

  BEIDLE, W. C. Region 4, Office of Director. 83/06/27, GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 17238: 344. 24X
  Fiche: 50-313, 83/06/29, 8307060282.
- --8307060291 IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830418-22. No noncompliance noted Major areas inspected security plan & implementing procedures & security program audit. Bafeguards info withheld (10CFR73. 21).

  EVANG. G.A., KELLY, J.A., JOHNSON, W.D. Region 4, Office of Director. 83/06/23. ip. 19238:346. 24X Fiche: 50-313,83/06/29,8307060282.
- B307180079 Advises that util will cease further expedited efforts to provide schedule per request for exemption from App R rebarrier & suppression/detection sys & NRC 830617 ltr.pending receipt of addl NRC clerification.

  MARSHALL, J. R. Arkenses Power & Light Co. 83/07/12, BTOLZ, J.F., CLARK, R. A. Operating Reactors Branch 4. 3pp. 19560: 263. 24X Fiche: 50-313, B3/07/12, B307180079.

- B307190155 Provides addl info in support of B20729 schedular request for exemption from iOCFRSO, App R. in order to complete proposed mods to redundant safe shutdown equipment in Fire Zones 2100-2 & 2101-AA.

  MARSHALL.J.R. Arkansas Power & Light Co. B3/07/13. BTOLZ, J.F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19636:232. 24% Fiche: 50-313, 83/07/13, 8307190155.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307250482 Forwards Amend 1 to updated FSARs W/a Unit 2 rept.
  MARSHALL.J.R. Arkansas Power & Light Co. 83/07/15. NRC No
  Detailed Affiliation Given. 1p. 19708:100. 24X
  Fiche: 50-313.83/07/15.8307250482.
- ---B307250486 Amend 1 to Updated FSAR.

  \* Arkansas Power & Light Co. B3/07/15. i,000pp. 19708:101. 24X
  Fichs:50-313.83/07/15. 83097250482.
- P. Operating license stage documents & correspondence
- 8307190386 Forwards safety evaluation supporting continued operation of PWRs w/Dresser primary safety valves. Facility operation at present valve settings acceptable. NUREO-0737, Item II. D. I evaluation continuing.

  870L2.J.F. Operating Reactors Branch 4. 83/04/27, GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 17643:345. 24X Fiche: 30-313,83/04/27,8307190386.
- 8305270018 Forwards seven revised oversize drawings. Aperture cards are available in PDR. Drawing transmittal list encl.
  SHIVELY.C. Arkansas Power & Light Co., 83/05/18, NRC No Detailed Affiliation Given. 2pp. 18638:181. 24X
  Fiche: 50-313/83/05/18/8305270018.
- 8307220310 Forwards Rev 6 to GA program topical rept, "GA Manual Operations." Rev deletes procedural refs throughout text & changes organization of energy supply dept.

  MARSHALL,J.R. Arkansas Power & Light Co. 83/06/10. COLLINB.J.T. Region 4. Office of Director. 3pp. 17674:081. 24X

  Ficha: 50-313.83/06/10.8307220310.
- --8307220314 Rev 6 to "QA Manual Operations."

  \* Arkansas Power & Light Co. 83/06/10, 148pp. 19674:084, 24X Fiche: 50-313,83/06/10,8307220310.
- B307060051 Responds to B30510 request for final submittals of radiological effluent Tech Bpecs.offsite dose calculation manual & process control program within 30 days. Response plan to be submitted by B30930 based on ongoing activities. MARBHALL, J. R. Arkansas Power & Light Co. B3706/29. B70LZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19250:340. 24X Fiche: 50-313,83/06/29,8307060051.
- 8307050072 Application for amend to Licenses DPR-91 & NPF-6, ravising Tech Specs to ref ANSI/ASME DM4-1982 guidelines for functional testing, per safety-related hydraulic shock snubber operability requirements.

  ORIFFIN.J.M. Arkansas Power & Light Co. 83/06/30. STDLZ, J.F. Deerating Reactors Branch 4. CLARK, R.A. Operating Reactors Branch 3. 3pp. 19193:159. 24X Fiche: 50-313,83/06/30,8307050072.
- --8307030079 Proposed Tech Specs referencing ANSI/ASME OM4-1982 guidelines for functional testing, per safety-related hydraulic shock snubber operability requirements, \*\* Arkansas Power & Light Co. 83/06/30. 22pp. 19193:162. 24X Fiche: 50-313,83/06/30,8307050072.
- 8307130345 THE EFFECT OF SOME OPERATIONS AND CONTROL ROOM IMPROVEMENTS ON THE BAFETY OF THE ARKANSAS NUCLEAR ONE, UNIT DNE, NUCLEAR POWER PLANT.

  BELL, B. J. Battalle Memorial Institute, Columbus Laboratories.
  - EELL, B. J. Battelle Memorial Institute, Columbus Laboratories. KOLB. G. J. Sandia Laboratories. FIN A-1241. NUREG/CR-3246. 83/06/30. Division of Risk Analysis. 41pp. 19596: 316. 24X Fiche: 50-313,83/06/30.8307150365.
- 8307080413 Requests extension until Aug 1783 for submittal of plans & schedules for resolution of reactor coalant pump trip issue. Delay caused by late submittal of 8&M Owners Group plan.

  MARSHALL.J.R. Arkansas Power & Light Co. 83/07/01. 8TOLZ.J.F. Operating Reactors Branch 4. 1p. 19347: 275. 24X Ficha: 80-313,83/07/01,8307080413.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Bvc list encl. EISENHUT.D.G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 30-000, B3/07/05, B306270397.

- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in SIS.Svc list encl. FISENAUT.D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. lapp. 19669:254. 24X Fiche. 50-000, 83/07/06, 8307060329.
- 8307120306 Advises that based on review of 830126 & 0415 SERs reserviron qualifacation submittals do not require proprietary classification & may be made publicly available.

  MARSHALLJ.R. Artansas Power & Light Co. 83/07/07. 870LZ,J.F. Operating Reactors Branch 4. CLARK.R.A. Operating Reactors Branch 3. 1p. 19424:103. 24X Fiche: 50-313.83/07/07.8307120306.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. 0. Division of Licensing 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24% Fiche: 50-000,83/07/08.8307080169.
- E307190181 Forwards electrical schematic diagrams/drawings showing control circuitry of emergency feedwater pumps & valves, per 821026 request. Drawings final, but minor changes may be necessary W/11 oversize drawings. Aperture cards in PDR. HARBHALL, J. R. Arkansas Power & Light Co. 83/07/12. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19630: 172. 24X Fiche: 50-313,83/07/12,8307190181.
- B307170065 Responds to B30524 request for add1 info re util B1111B submittal on natural circulation cooldown. Operators trained on mechanics of void formation & recognition techniques. Operator actions uould preclude head bubble expansion. MARSHALL, J. R. Arkansas Power & Light Co. 83/07/13. STCLZ, J. F. Operating Reactors Branch 4. 3pp. 19435:129. 24X Fiche: 50-313, 83/07/13, 8307190085.
- 8307250544 Requests FR publication of notice of consideration of iswance of amends to Licenses DPR-51 & NPF-6 & proposed NSHC & opportunity for hearing re hydrogen/oxygen concentration limitations in radwaste gas sys.

  810LZ.J.F. Operating Reactors Branch 4. 83/07/13. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19715:350. 24X Fiche: 50-313.83/07/13.8307250544.
- 9307270281 Forwards SER re analysis of effect of NUREG-0630 on facility ECCS analysis Administratively imposed temporary restrictions on facility operating limits identified in 630610 itr appropriate & necessary pending NRC approval. STOLZ.J.F. Uperating Reactors Branch 4. 83/07/13. GRIFFIN.J.M. Arkansas Power & Light Co. 2pp. 19802:358, 24X Fiche:50-313.83/07/13.8307270281.
- ---8307270286 SER supporting temporary restrictions administratively imposed on facility operating limits re analysis of effect of NUREQ-0630 on facility ECCS analysis.

  + Diffice of Nuclear Reactor Regulation, Director. 83/07/13, 3pp, 19802:360. 24% Fiche: 50-313,83/07/13,8307270281.
- 8307250663 Forwards draft safety evaluation concluding that util meets Criteria 1 & 3-9 in Item II. B.3 of NUREC-0737. "Post-Accident Sampling Sys." Addl info requested within 60 days on Criteria 2:10 & 11 to complete evaluation. CLARK, R.A. Operating Reactors Branch 3. STOLZ, J.F. Operating Reactors Branch 4. 83/07/14. GRIFFIN.J.M. Arkansas Power & Light Co. 199p. 19718:291. 24X Fiche: 50-313,83/07/14.8307250663.
- 8307210189 Advises of submittal of Amend 1 to updated FSAR on 830715.
  Brief description of safety evaluation for design changes
  made to facility & completed during 1982 & early 1983 encl.
  MARSHALL.J.R. Arkansas Power & Light Co. 83/07/15. STOLZ.J.F.
  Deerating Reactors Branch 4. 1ipp. 19669:187. 24X
  Fiche: 50-313.83/07/15.8307210159.
- 8307210299 Withdraws two proposed Tech Spec changes re low temp overpressure protection & change requested by NRC as result of IE Bulletsns 79-05A:79-05B & 790517 order. MARSHALL.J.R. Arkansas Power & Light Co. 83/07/15. STOLZ.J.F. Operating Reactors Branch 4. 1p. 19444:283. 24X Fiche: 50-313.83/07/15.830/210299.
- 8307270045 Requests add1 info re util responses to Generic Ltr 81-14 concerning seismic qualification of auxiliary feedwater sys. Response expected by 830730.
  870LZ.JF Derating Reactors Branch 4. 83/07/15. GRIFFIN, J.M. Arkansas Power & Light Co. 3pp. 17811.263. 24X Fiche: 50-313, 83/07/15, 8307270045.

- G. Inspection reports, IE Bulletins & correspondence
- B307260094 Advises that add1 info re IE Insp Rept 50-313/B3-03 concerning fuel shuffle will be provided by B30620, per NRC B30519 request.

  HARSHALL, J. R. Arkanses Power & Light Co. B3/06/08. BEIDLE, W. C. Region 4. Defice of Director. Ip. 19732:341. 24x Fiche: 50-313, B3/06/08, B307260094.
- 8307120240 Forwards IE Insp Repts 50-313/83-10 & 50-368/83-10 on 830501-31 & notice of violation. SEIDLE, W. C. Region 4, Office of Director. 83/06/15, GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 19423:001. 24X Fiche: 50-313, 83/06/15, 8307120240.
- --8307120242 Notice of violation from insp on 830501-31.
  \* Region 4, Office of Director. 83/06/15. 3pp. 19423:003. 24X Fichs: 50-313,83/06/15,8307120240.
- --8307120247 IE Insp Repts 50-313/82-10 & 50-368/83-10 on 830501-31. Noncompliance noted: failure to follow procedures for proper labeling of radwaste & use of inadequate procedure to perform monthly maint.

  CALLAN. L. J., CUMMINS, J. E., JOHNSON, W. D. Region 4, Office of Director. 83/06/14, 19pp. 19423:006. 24X Fiche: 50-313, 83/06/15, 8307120240.
- 83070&0282 Forwards IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830518-22. No noncompliance noted. SEIDLE.W.C. Region 4. Office of Director. 83/06/29. ORIFFIN, J. M. Artansas Fower & Light Co. 2pp. 19238: 344. 24X Fiche: 50-313,83/06/29,8307060282.
- --8307060291 IE Insp Repts 50-313/83-08 & 50-348/83-08 on 830418-22. No noncompliance noted Major areas inspected security plan & implementing procedures & security program audit Safeguards info withheld (10CFR73.21).

  EVANS.C.A. KELLY.J.A. JDHN80N.W.D. Region 4, Office of Director. 83/06/23. Ip. 19238:346. 24X Fiche:50-313.83/06/27.8307060282.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:273. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000.83/07/14.8306270406.
- B307210299 Withdraws two proposed Tech Spec changes re low temp overpressure protection & change requested by NRC as result of 1E Bulletins 79-05A:79-05B & 790517 order. MARSHALL.J.R. Arkansas Power & Light Co. 83/07/15. STOLZ.J.F. Operating Reactors Branch 4. 1p. 19664:283. 24X Fiche: 30-313:83/07/15.8307210299.
- 8307220512 Ack receipt of 830502 & 0620 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept S0-313/83-03.

  BEIDLE, M. C. Region 4. Office of Director. 83/07/18. ORIFFIN, J. M. Arkansas Power & Light Co. 2pp. 19685: 134. 24X

  Fiche: 50-313, 83/07/18, 8307220312.
- --B307220517 Responds to request for add1 info re violation noted in IE Insp Rept 50-313/83-03 concerning failure to follow requirements for changes to refueling shuttle procedure. Procedure modified to detail sequence changes. MARSHALL.J.R. Arkansas Power & Light Co. 83/06/20. SEIDLE, W. C. Region 4. Office of Director. 2pp. 19685:136, 24X Fiche: 50-313,83/07/18,8307220512.
- B307220560 Provides status & overview of waste gas sys upgrades per B21220 commitment in response to SALP rept. Mods include replacing large amount of carbon steel pipe w/stainless steel & rerouting to minimize low spots in sys.

  MARSHALL, J.R. Arkansas Power & Light Co. 83/07/18. STOLZ, J.F. Dperating Reactors Branch 4. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19686:029. 24X Fiche: 50-313,83/07/18,8307220560.

# R. Periodic operating reports & related correspondence

- B307260180 Submite fifth monthly status rept on progress of regulatory response & commitment control program for B30514-0614.
  Rept on passive commitment tracking expected by B30801.
  MARSHALL, J.R. Arkansas Power & Light Co. B3/06/14. COLLINS, J.T.
  Region 4, Defice of Director. 2pp. 19727:102. 24X
  Fiche: 50-313, B3/06/14, B307260180.
- 8307220278 Monthly operating rept for May 1783. W/830615 ltr.
  MORTON.K.L., MARSHALL, J.R. Arkansas Power & Light Co. 83/06/15.
  BASSETT.H.S. Division of Data Automation & Management Information.
  11pp. 17684: 162. 24X Fiche: 50-313,83/06/15,8307220278.
- S. Reportable occurrences, LERs & related correspondence
- 8307150271 LER 83-015/03L-0: on 830616, while in hot shutdown after reactor trip, HPI control valve CV-1219 failed to open on demand from control room. Cause not determined. Operator & switches inspected & switch settings checked. W/830705 1tr. RODERS, P. C., MARSHALL, J. R. Arkansas Power & Light Co. 83/07/05. 85IDLE, M. C. Region 4, Office of Director. 3pp. 19538: 097. 24x Fiche: 50-313, 83/07/05, 8307150271.
- 8307150383 LER 83-014/03L-0: on 830609, auxiliary feedwater pump P-75 rendered inoperable. Caused by supply piping seal break due to piping misalignment. Piping replaced & realigned to reduce stress. W/830705 ltm.
  ROGERB, P. C. . MARSHALL J. R. Arkansas Power & Light Co. 83/07/05. SEIDLE, W. C. Region 4, Office of Director. 2pp. 19539: 154. 24x Fiche: 50-313, 83/07/05, 8307130383.
- B307120074 PNO-IV-B3-023: on B30708, reactor shut down following indications that tubs leak in steam generator A increased. Preparations for steam generator tubs insp made. Dutage of 2 wks expected. JOHNSON. H. D. , CALLAN. L. J. Region 4, Office of Director. B3/07/08. Ip. 19423: 147. 24X Fiche: 50-313, B3/07/08, B307120074.
- DOCKET 50-315 DONALD C. COOK NUCLEAR POHER PLANT, UNIT 1

  F. Security, medical, emergency & fire protection plans
- B307110607 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records, B3/06/24. Document Management Branch. 1p. 19391:130. 24X Fiche: 50-315,83/06/24, B307110607.
- --8307110612 Public version of Rev O to Emergency Plan implementing Procedure PMP 2081 EPP.029, "Initial Core Damage Assessment." W/830601 ltr & receipt form.
  TOMMLEY,E.L. Indians & Michigan Electric Co. 83/06/01. 2ipp. 19391:13i. 24X Fiche: 50-315,83/06/24,8307110607.
- B307120600 Releases public version of ray to emergency plan implementing procedures.
  FELTON.U.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19508:314. 24X Fiche: 50-315, 83/06/24, 8307120600.
- --8307120607 Forwards public version of revised emergency planimplementing procedures including Procedures PMP 2081 EPP.014 re offsite dose assessments & PMP 2081 EPP.004 re protective action guides. Procedure temporary sheets encl. # Indiana & Michigan Electric Co. 83/05/26. GRIMES, B. NRC - No Datailed Affiliation Given. ip. 19508:316. 24X Fiche: 50-315, 83/06/24, 8307120600.
- --8307120610 Public version of revised emergency plan implementing procedures, including Procedures PMP 2081 EPP. 014 re offsite assessments & PMP 2081 EPP. 004 rs protective action guides. QLABSMAN, M. A. Indiana & Michigan Electric Co. 83/05/26. 12pp. 17508:317. 24X Fichs: 50-315,83/04/24,8307120600.
- B307250076 Summary of B30623 meeting w/utils & Bechtel in Bethesda, MD re proposed exemptions from 100FR50, App R on firs protection & review of alternate safe shutdown analysis rept.
  WIOOINTON, D. Operating Reactors Branch 1, 83/06/29. Operating Reactors Branch 1, 5pp. 19724:043, 24X Fithe: 50-315,83/06/29, 8307250076.
- B307200130 Forwards safety & safeguards insp fam for Mar 1982 Mar 1983.
  ALEXICH M.P. Indiana & Michigan Power Co. 83/07/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19651: 021. 24X Fiche: 50-315, 83/07/15, 8307200130.

#### H. General correspondence

- 8307070089 Requests that all correspondence addressed to officers of American Electric Power Svc Corp or Indiana & Michigan Electric Co be mailed to listed address effective 830705.

  ALEXICH.M.P. Indiana & Michigan Electric Co. 83/06/27.

  DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ip. 19293:346. 24X Fiche: 50-315,83/06/27,8307070089.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307290162 Forwards FBAR 1983 update.containing original FBAR & B4 amends in support of application for OL & Jul 1982 FSAR update. Changes to Chapter 14.Unit 2 under review.

  ALEXIGH.H.P. Indiana & Michigan Electric Co. 83/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19817: 109. 24X Fiche: 30-315.83/07/22.8307290162.
- --8307270166 F9AR 1983 update.

  \* Indiana & Michigan Electric Co. 83/07/31. 1300pp. 17817: 112.
  24X Fiche: 50-315, 83/07/22, 8307270162.
- P. Operating license stage documents & correspondence
- 8306060070 Opneric Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Syc list encl.
  EIBENHUT.D.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19363:116. 24X Fiche: 30-000, 83/06/03, 8306060070.
- B307080288 Forwards safety evaluation re util responses to NUREG-0737. Items II.F. 1.4. "Containment Pressure Monitor," II.F. 1.5. "Containment Hater Level Monitor," & II.F. 1.6. "Containment Hydrogen Monitor." Items resolved. VARQA.S.A. Operating Reactors Branch 1. 83/06/08. DDLAN, J. Indiana & Michigan Electric Co. 9pp. 19363; 304. 24X Fiche: 50-315, 83/06/08, 8307080288.
- B307110616 Monthly notice of amends to OLs involving NSHC issued since B30523. CLARK,R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fiche: 50-000. 83/06/14. 8307110616.
- B307250239 Requests addl info re reactor physics & fuels, based on review of B30511 Cycle B reload analysis.

  VAROA.B. A. Operating Reactors Branch I. B3/06/29. DDLAN, J. Indiana & Michigan Electric Co. 4pp. 19720: 357. 24X
  Fiche: 50-315, B3/06/29, B307250239.
- B307060391 Confirms B30628 conversation re result of recent unscheduled Unit 2 outage. Estimated target date for having operational monitors available extended to wk after plant returns to svc on B30707.

  ALEXICH.M.P. Indiana & Michigan Electric Co. B3/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19234:142. 24X Ficha: 30-315, 83/06/30, 8307060351.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X fiche: 50-000,83/07/05,8306270397.
- 8307110290 Forwards WCAP-10230, "Evaluation of Acceptability of Reactor Vessel Head Lift Rig,Reactor Vessel Internals Lift Rig,Load Cell & Load Cell Linkage to Requirements of NUREG-0612" & responses to NRC recommendations.

  ALEXICH.M.P. Indiana & Michigan Electric Co. 83/07/05. DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director. 2pp. 19378: 332. 24X Fiche: 50-315,83/07/05,8307110290.
- --B307110295 "Evaluation of Acceptability of Reactor Vessel Head Lift Rig,Reactor Vessel Internals Lift Rig,Load Cell & Load Gell Linkage to Requirements of NUREO-0612." SANDNER,H.H.; MARSHALL,J.R. Hestinghouse Electric Corp. WGAP-10230, 83/04/30, 150pp. 19378: 334. 24X Fiche: 50-315,83/07/05,8307110290.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STB. Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307040329.

- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISCHUTU.D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307120400 Application for amend to Licenses DPR-98 & DPR-74 changing Tech Spec Table 4.3-1 re reactor trip sys instrumentation surveillance requirements.

  ALEXICH, H.P. Indiana & Michigan Electric Co. 83/07/08. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 5pp. 19430:219. 24X Fiche: 50-315.83/07/08,8307120400.
- --B307120401 Froposed Tech Spec Table 4.3-1 changing reactor trip sys instrumentation surveillance requirements \* Indiana & Michigan Electric Co 83/07/08. Spp. 19430:224. 24% Fiche: 50-315,83/07/08.8307120400
- B307280341 Supplemental application for amend to License DPR-58, requesting add1 Tech Spec changes for Cycle 8 operations.

  ALEXICH.M.P. Indiana & Michigan Electric Co. B3/07/25. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 4pp. 19789: 036. 24X Fiche: 50-315, 83/07/25, 8307280341.
- ---8307280344 Proposed Tech Spec changes for Cycle 8 operations.

  \* Indiana & Michigan Electric Co. 83/07/25. 9pp. 19789: 040.
  24X Fiche: 50-315. 83/07/25. 8307280341.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307120266 Forwards IE Insp Repts 50-315/83-08 & 50-316/83-09 on 830427-29 & 0303-06 & notice of violation PAPERIELLO,C.J. Region 3, Office of Director. 83/06/28. DDLAN,J.E. American Electric Power Service Corp. BOLAN,J.E. Indiana & Michigan Electric Co. 2pp. 19424-136. 24X Fiche: 50-315,83/06/28,8307120266.
- --8307120271 Notice of violation from insp on 630427-29 % 0503-06.
  PAPERIELLO.C. J. Region 3, Office of Director. 83/06/27. 1p.
  19424: 13B. 24% Fiche: 50-315, 83/06/28, 8307120266.
- --8307120280 IE Insp Repts 50-315/83-08 & 50-316/83-09 on 830427-29 & 0503-06. Noncompliance noted: Failure to perform evaluation when whole body vivo count data indicated exposure to greater than 40 h control measure.

  HVETER.L.J., GREGER.L.R. Region 3, Office of Director. 83/06/23, 13pp. 19424: 139. 24X Fiche: 50-315, 83/06/28, 8307120266.
- 8306270401 IE Info Notice 83-45, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JURDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563-293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of Nau York: Inc. 14fpp. [9563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 % I-131 in Ercess of NRC Limits." Eve list encl.
  TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307200269 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~315/83-07 & 50~316/83-08.

  STREETER, J. F. Division of Engineering, 83/07/14. DDLAN, J. E. American Electric Power Service Corp. DDLAN, J. E. Indiana & Michigan Electric Co. 1p. 19648:061. 24X Fiche: 50-315,83/07/14,8307200269.
- --8307200273 Responds to NRC 930601 ltr re violations noted in IE Insp. Repts 50-315/83-07 % 50-316/83-08. Corrective actions: procedures & instructions amended to include description of master plant file vault & records policy statement. SMITH.W. 9. Indiana & Michigan Electric Co. 83/07/01, KEPPLER.J. 9. Region 3. Office of Director. 2pp. 19648:062. 24% Fiche: 50-315,83/07/14,8307200269
- 8307200130 Forwards safety & safeguards insp fee for Mar 1982 -Mar 1983 ALEXICH,M P. Indiana & Michigan Power Co. 83/07/15. BENTON,H.R. Office of Nuclear Reactor Regulation, Director. ip. 19651:021, 24X Fiche:50-315,83/07/15,8307200130

- R. Periodic operating reports & related correspondence
- 8307220097 Monthly operating rept for May 1983. W/830613 ltr.
  MIGHT.A. SMITH.W.G.. SVENSSON.B.A. Indiana & Michigan Electric Co.
  83/06/13. Office of Resource Management. Director. 10pp.
  19683:314. 24X Fiche: 50-315, 83/06/13, 8307220097.
- S. Reportable occurrences, LERs & related correspondence
- 8307050054 Forwards LERE 83-051/03L-0 & 83-052/03L-0. SMITH.M.G. Indiana & Michigan Electric Co. 83/06/22. Region 3. Diffice of Director. 1p. 19192:152. 24X Fiche: 50-315, 83/06/22. 8307050054.
- ~\*8307050062 LER 83~051/03L-0: on 830328, loop 1 wide range pressure transmitter NPS-122 output drifted low. Cause not stated. Transmitter recalibr. Applicable bistable procedures modified by lowering administrative setpoint tolerances. PALMER.R.A. Indiana & Michigan Electric Co. 83/06/22. Region 3. Office of Director. 1p. 19192:153. 24X Fiche: 50-315, 83/06/22, 83/07050054.
- ~-8307050068 LER 83~052/03L-0: on 830525. axial flux difference target band limit exceeded. Caused by axial burnup distribution, large negative moderator temp coefficient & considerable rod withdrawal required to overcome zenon buildup. PALMER.R.A. Indiana & Michigan Electric Co. 83/06/22 Region 3. Office of Director. 5pp. 19192:154. 24X Fiche: 50-315, 83/06/22.8307050054.
- 8307050019 LER 83-053/017-0: on 830612.performance of train B boron injection tank inlet piping heat trace circuitry questioned but train not declared inoperable until 830616. Missed surveillance under investigation. W/830624 ltr. KRAUSE.D.F. SMITH.W.O. Indiana & Michigan Electric Co. 83/06/24, KEPPLER.J.G. Region 3, Office of Director. 2pp. 19220; 239. 24X Fiche: 50-315, 83/06/24, 8307050019.
- 8307050090 LER 83-054/03L-0: on 830526, fuel oil day tank lavel column high side isolation found closed during diesel generator IAB valve lineup surveillance. Cause not determined. Documentation indicates valve restored to normal. W/830624 ltr. KRAUSES.D.F.. SMITH, W.G. Indiana & Michigan Electric Co. 83/06/24. KEPPLER.J. G. Region 3. Office of Director. 3pp. 19199: 334. 24x Fiche: 30-315, 83/06/24, 8307050090.
- B307060372 LER 83-055/03L-0: on 830529, Mercoid Corp wast motor driven auxiliary feed pump low suction pressure switches Mercoid Corp triped. Cause unknown. Reset valves found out of spec. Switches replaced W/B30627 ltr. PALHER.R.A. SMITH.W.G. Indiana & Michigan Electric Co. 83/06/27. KEPPLER.J.G. Region 3, Office of Director. Spp. 19236:217. 24X Fiche: 50-315, 83/06/27, 8307060372.
- 8307110333 Forwards LERs 83-056/03L-0 & 83-037/03L-0. 8MITH, H. G. Indiana & Michigan Electric Co. 83/06/29. KEPPLER, J. Q. Region 3, Office of Director. 1p. 19381:294. 24X Fiche: 50-315, 83/06/29, 8307110333.
- --8307110340 LER 83-056/03L-0: on 830401, during surveillance test, check valve NS-262 found leaking. Caused by dirt buildup on valve seating surfaces. Check valve disassembled & cleaned. ROBINSON, D. Indiana & Michigan Electric Co. 83/06/29. Region 3. Office of Director. Ip. 19381:292. 24X Fiche: 50-315,83/06/29,8307110333.
- --8307110347 LER 83-057/03L-0: on 830402, during normal operation, steam generator 4 bloudown containment isolation DCR-340 failed closed Caused by ruptured diaphragm of valve operator. Diaphragm replaced, Valve stroke limits adjusted. ROBINSON, D. Indiana & Michigan Electric Co. 83/06/29. Region 3, Office of Director. 1p. 19381:293. 24X Fiche: 50-315,83/04/29,8307110333.
- B307180140 LER 83-058/03L-0: on 830609, operator discovered that containment sump flow monitoring recorder (1-CS-001) not advancing. Caused by holes in chart paper. Chart paper realigned on grive wheel. W/830706 ltr. PALMER.R.A., SMITH, N.O. Indiana & Michigan Electric Co. 83/07/06. KEPPLER.J.G. Region 3, Office of Director. 2pp. 19557:051. 24X Fiche: 50-315,83/07/06,8307180140.
- B307290320 Forwards AEOD anigneering evaluation of numerous events involving frozen (ce condenser intermediate deck doors. Most problems occurred while plant was new to have decreased as operational experience gained.

  ZUKOR, D. J. Reactor Operations Analysis Branch. B3/07/11, SEYFRIT, K. V. Reactor Operations Analysis Branch. 2pp. 19857:060.

- --B307290377 "Frozen Ice Condenser Intermediate Deck Doors," AEOD engineering evaluation rept.
  ZUKOR, D. Reactor Operations Analysis Branch. B3/07/11. 6pp.
  19857: 062. 24X Fiche: 50-000. 83/07/11. 8307290320.
- 8307220384 LER 83-059/O3L-O: on 830624 during normal operation, control room access Fire Door 412 failed to operate properly. Caused by failure of closure support arm. Closure arm repositioned & closing spring tightened W/80714 ltr. KDEN10.E.C., SMITH.W.O. Indiana & Michigan Electric Co. 83/07/14. KEPPLER.J.O. Region 3, Office of Director. 2pp. 19675:252. 24X Fichs: 50-315, 83/07/14, 8307220384.
- DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307110607 Releases public version of revised emergency plan implementing procedure. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19391: 130. 24X Fiche: 50-315, 83/06/24, 830710607.
- ---8307i106i2 Public version of Ray O to Emergency Plan Implementing Procedure PMP 2081 EPP. 029, "Initial Core Damage Assessment." W/83060i ltr & receipt form. TOWNLEY,E.L. Indiana & Michigan Electric Co. 83/06/01. 2ipp. 19391: 131. 24X Fiche: 50-315,83/06/24,8307110607.
- 8307120600 Releases public version of rev to emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19508:314. 24X Fiche: 50-315.83/06/24, 8307120600.
- --8307120607 Forwards public version of revised emergency plan implementing procedures, including Procedures PMP 2081 EPP, 014 re offsite dose assessments & PMP 2081 EPP, 004 re protective action guides. Procedure temporary sheets encl. \* Indiana & Michigan Electric Co. 83/05/26. GRIMES, B. NRC No Detailed Affiliation Given. 1p. 19508:316. 24X Fiche: 50-315, 83/06/24, 8307120600.
- --9307120610 Public version of revised emergency plan implementing procedures, including Procedures PMP 2081 EPP. 014 re offsite assessments & PMP 2081 EPP. 004 re protective action guides. GLASSMAN.M. A. Indiana & Michigan Electric Co. 83/05/26. 12pp 19508: 317. 24X Fiche: 50-315, 83/06/24, 8307120600.
- B307250076 Summary of B30623 meeting w/utils & Bechtel in Bethesda, MD re proposed exemptions from 10CFR50. App R on fire protection & review of alternate safe shutdown analysis rept.
  MIGGINTUN, D. Operating Reactors Branch 1, B3/06/29, Operating Reactors Branch 1, B3/06/29, B307250076.
- B307200130 Forwards safety & safeguards insp fee for Mar 1982 --Mar 1983. ALEXICH.M.P. Indiana & Michigan Power Co. B3/07/15. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. ip. 19651:021. 24X Fiche: 50-315,83/07/15,8307200130.
- H. General correspondence
- 8307070089 Requests that all correspondence addressed to officers of American Electric Power Svc Corp or Indiana & Michigan Electric Co be mailed to listed address.effective 830705. ALEXICH.M.P. Indiana & Michigan Electric Co. 83/06/27. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 19.19273:346. 24X Fiche:50-315,83/06/27.8307070089.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307290162 Forwards FSAR 1983 update, containing original FSAR & 84 amends in support of application for OL & Jul 1982 FSAR update. Changes to Chapter 14, Unit 2 under review. ALEXIGH.M.P. Indiana & Michigan Electric Co. 83/07/22, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19817:109. 24X Fichs: 50-315,83/07/22,8307290162.
- --8307270166 F8AR 1983 update. \* Indiana & Michigan Electric Co. 83/07/31. 1300pp. 19817:112. 24X Fiche: 50-315, 83/07/22, 8307290162.

- P. Operating license stage documents & correspondence
- B306060070 Generic Ltr B3-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Mestinghouse PWRs re safety avaluation of "Emergency Response Guidelines." Bvc list encl.
  EISENHUT.D. G. Division of Licensing. 83/06/03. Yankes Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 30-000, 83/06/03, 8306060070.
- 8307080288 Forwards safety evaluation re util responses to NUREO-0737, Items II.F. 1.4, "Containment Pressure Monitor," II.F. 1.5, "Containment Hater Level Honitor," & II.F. 1.6, "Containment Hydrogen Monitor." Items resolved.
  VARGA.S. A. Operating Reactors Branch 1, 83/06/08, DOLAN, J. Indiana & Michigan Electric Co. 9pp. 19363:304, 24X Fiche: 50-315,83/06/08,8307080288.
- 8307110616 Monthly notice of amends to OLs involving NSHC issued since 830523. CLARM.R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fiche: 50-000.83/06/14.8307110616.
- 8307040331 Confirms B3062B conversation re result of recent unscheduled Unit 2 outage Estimated target date for having operational monitors available extended to uk after plant returns to svc on 830707.

  ALEXICH.M.P. Indiana & Michigan Electric Co. 83/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19234:142. 24X Fiche: 50-315,83/06/30,8307060351.
- 8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of GPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. 8vc list enci. EIGENHUT, D. O. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307110290 Forwards MCAP-10230, "Evaluation of Acceptability of Reactor Vessel Head Lift Rig, Reactor Vessel Internals Lift Rig, Load Cell & Load Cell Linkage to Requirements of NUREG-0612" & responses to NRC recommendations.

  ALEXIGH.M.P. Indiana & Michigan Electric Co. 83/07/05. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19378:332. 24X Fiche: 50-315,83/07/05,8307110270.
- --8307i10295 "Evaluation of Acceptability of Reactor Vessel Head Lift Rig,Reactor Vessel Internals Lift Rig.Load Cell & Load Cell Linkage to Requirements of NUREO-Ooil2." SANDNER.H.H., MARSHALL,J.R. Westinghouse Electric Corp. WCAF-10230. 83/04/30. 150pp. 19378:334. 24X Fiche: 50-315,83/07/05,8307110290.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Byc list encl. EIGENHUT. D. O. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19649:254. 24X Fiche: 50-000.83/07/06, 8307060329.
- B3070B0169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 30-000, 83/07/08, 8307080169.
- 8307120400 Application for amend to Licenses DPR-58 & DPR-74 changing Tech Spec Table 4.3-1 re reactor trip sys instrumentation surveillance requirements.
  ALEXICH.M.P. Indiana & Michigan Electric Go. 83/07/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 19430; 219. 24X Fiche: 50-315, 83/07/08, 8307120400.
- --B307120401 Proposed Tech Spec Table 4.3-i changing reactor trip mys instrumentation surveillance requirements. \* Indiana & Michigan Electric Co. 83/07/08. 5pp. 19430:224. 24X Fiche: 50-315, 83/07/08, 8307120400.
- 8307120445 Forwards addl info in response to 830502 ltr re seismic qualification of mercoid pressure switches & switchgear components.

  ALEXIGH.M. P. Indiana & Michigan Electric Co. 83/07/08, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19426:039, 24X Fiche: 50-316, 83/07/08, 8307120445.
- --8307120451 "Seismic Simulation & Radiation Test Program on Seven Pressure Switches." THORNBERRY.R. Wyle Laboratories. 44285-1. 78/10/26. 52pp. 19426:042. 24X Fiche: 30-316.83/07/08.8307120445.

- Q. Inspection reports, IE Bulletins & correspondence
- 8307060131 Forwards IE Insp Rept 50-316/83-04 on 830101-0214 & 0426-0520 & notice of violation.
  8HAFER.M.D. Region 3. Office of Director. 83/06/20. DQLAN, J.E. American Electric Power Bervice Corp. DQLAN, J.E. Indiana & Michigan Electric Co. 2pp. 17251:258. 24X Fiche:50-316.63/06/20.6307060131.
- --8307060134 Natice of violation from insp on 830101-0214 & 0426-0520. SHAFER.W.D. Region 3, Office of Director. 83/06/20. 3pp. 19251:260. 24X Fiche:50-316,83/06/20.8307060131.
- --8307060138 IE Insp Rept 50-316/83-04 on 830101-0214 & 0426-0520. Noncompliance noted: failure to meet insp requirements & failure to prepare & foliou preoperational test procedures. SMANSON, E.R., HOLZMAN, M.M., BOYD, D.C. Region 3, Office of Director. 83/06/20, 13pp. 17251:263. 24X Fiche: 50-316,83/06/20,8307060131.
- 8307120266 Forwards IE Insp Repts 50-315/83-08 & 50-316/83-09 on 830427-29 & 0503-06 & notice of violation. PAPERIELLO, C. J. Region 3, Office of Director. 83/06/28. DDLAN, J. E. American Electric Power Service Corp. DDLAN, J. E. Indiana & Michigan Electric Co. 2pp. 19424:136. 24X Fiche: 50-315,83/06/28,8307120266.
- --8307120271 Notice of violation from insp on 830427-27 & 0503-06.
  PAPERIELLO,C.J. Region 3, Office of Director. 83/06/27. ip. 19424:138. 24% Fiche: 50-315, 83/06/28, 8307120266.
- --8307120280 IE Insp Repts 30-315/83-08 & 50-316/83-09 on 830427-29 & 0503-06. Noncompliance noted: Failure to perform evaluation when whole body vivo count data indicated exposure to greater than 40 h control measure.

  HUETER, L. J., GREGER, L. R. Region 3, Offica of Director. 83/06/23, 13pp. 19424: 139. 24x Fiche: 50-315, 83/06/28, 8307120266.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.

  JCRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293, 24X Fiche: 50-000,83/07/11,8306270401.
- B306270404 IE Info Notice B3~47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." See list sec!.
  TAYLOR.J. M. Division of OA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- 8307200269 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-08.
  878EETER.J.F. Division of Engineering. 83/07/14. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 1p. 17648:061. 24X Fiche: 50-315,83/07/14.8307200267.
- --8307200273 Responds to NRC 830601 ltr re violations noted in IE Insp. Rapts 50-315/83-07 & 50-316/83-08. Corrective actions: procedures & instructions amended to include description of master plant file vault & records policy statement. SMITH.W.O. Indiana & Michigan Electric Co. 83/07/01. KEPPLER.J.O. Region 3. Office of Director. 2pp. 19648:062. 24x Fiche: 50-315,83/07/14,8307200269.
- 8307200130 Forwards safety & safeguards insp fee for Mar 1982 Mar 1983.
  ALEXICH, M. P. Indiana & Michigan Power Co. 83/07/15, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19651:021, 24X Fiche: 50-315, 83/07/15, 8307200130.
- R. Periodic operating reports & related correspondence
- 8307220008 Monthly operating rept for May 1983.4/830613 ltr. MIGHT.A., SMITH.W.G., SVENSSON.B.A. Indiana & Michigan Electric Co. 83/06/13. Office of Resource Management, Director. 8pp. 19674:051. 24X Fichs: 50-316,83/06/13,8307220008.

- S. Reportable occurrences. LERs & related correspondence
- 8307080007 LER 83-050/01T-0: on 830416, during review of Sampling & analysis data for waste gas sys oxygen & hydrogen concentrations, 12 h sampling requirement discovered not met. Caused by personnel error. W/830628 ltr.
  PALMER.R.A., SMITH.M.O. Indians & Michigan Electric Co. 83/06/28 KEPPLER, J.G. Region 3, Office of Director. 3pp. 17351: 241. 24X Ficha: 50-316,83/06/28,8307080007.
- 8307110193 Forwards LER 83-051/03L-0 & updated LER 83-035/03X-1.
  8MITH.M. G. Indiana & Michigan Electric Co. 83/06/29. KEPPLER, J. G. Region 3. Office of Director. 1p. 19379: 234. 24X
  Fiche: 50-316.83/06/29, 8307110193.
- --8307110200 Updated LER 83-035/03X-1: on 830319, trip function of proximity switch made inoperable for replacement, resulting from failure of main turbine stop valves on 830312. Caused by relay in solid state protection dropping too much voltage. PALMER, R. A. Indiana & Michigan Electric Co. 83/06/29, Region 3. Office of Director. 1p. 19379: 231. 24X Fiche: 50-316, 83/06/29, 8307110193.
- --8307110209 LER 83-051/03L-0: on 830A04, reset function for proximity switch on stop valve C. train B, failed to operate immediately & made inoperable for replacement. Caused by input bay relay in solid state protection sys dropping too much voltage. PALMER.R.A. Indiana & Michigan Electric Co. 83/06/29. Region 3, Office of Director. 2pp. 19379:232. 24x Fiche: 50-316, 83/06/29, 8307110193.
- 8307180104 RO: on 830704, during routine tour of containment, leak discovered in nonessential svc water sys. Written rept will be forwarded within 14 days, per IE Bulietin 80-24.

  SMITH.H. G. Indiana & Michigan Electric Co. 83/07/05. KEPPLER, J. G. Region 3. Office of Director. 1p. 19557: 019. 24X Fiche: 50-316, 83/07/05, 8307180104.
- 8307290320 Forwards AEOD enigneering evaluation of numerous events involving frozen ice condenser intermediate deck doors. Most problems occurred while plant was new & have decreased as operational experience gained. ZUKDR, D. J. Reactor Operations Analysis Branch. 83/07/11. SEYRRIT. K. V. Reactor Operations Analysis Branch. 2pp. 19857: 060 24X Fiche: 50-000, 83/07/11, 8307270320.
- --8307290377 "Froid Ice Condenser Intermediate Deck Doors," AEOD engineering evaluation rept.
  ZUKOR D. Reactor Operations Analysis Branch. 83/07/11. 6pp.
  19857: G62. 24X Fiche: 50-000, 83/07/11, 8307290320.
- 8307220403 Forwards LERs 83-053/03L-0 & 83-054/03L-0. 8MITH.M.G. Indiana & Michigan Electric Co. 83/07/14. KEPPLER, J. G. Region 3. Office of Director. ip. 19687:354, 24X Fiche: 50-316, 83/07/14, 8307220403.
- --8307220410 LER 83-053/03L-0: on 830520, during surveillance log review, containment air lock 3-day door tests not performed by required time. Caused by personnel misunderstanding. Test immediately performed satisfactorily.

  PALMER.R.A. Indiana & Michigan Electric Co. 93/07/14. Region 3. Office of Director. 2pp. 17687:355. 24X Fiche: 50-316, 83/07/14,8307220403.
- --8307220426 LER 83-054/03L-0: on 830623; during normal operations, Fire Door 386 between Quad 2 & NESW valve gallery failed to latch properly. Caused by bent latch plate. Plate removed, straightened & reinstalled.

  CARTEAUX.P. Indiana & Michigan Electric Co. 83/07/14. Region 3. Office of Director. 1p. 19687:357. 24X Ficha: 50-316,83/07/14, 8307220403.
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8307070180 Rev 10 to Emergency Response Plan Implementing Procedure ERPIP App B. 1, "Index of Equipment Checklist." W/830427 ltr & receipt form. RAYBURN, C. R. Baitimore Gas & Electric Co. 83/06/22. WELCH, S. Director's Office, Office of Inspection and Enforcement. 44pp. 17293:157. 24X Fiche: 50-317.83/06/22.8307070180.
- 8307120039 Releases public version of rev to emergancy plan implementing procedure. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19439:344. 24X Fiche: 50-317, 83/06/24, 8307120039.

- --830712D043 Public version of Rev 9 to Emergency Plan Implementing Procedure ERPIP 4.1.21. "Personnel Assembly " W/830527 Itr & receipt form.
  RUSSELL,L. B. RAYBURN, C. R. Baltimore Gas & Electric Co. 83/05/CLARK, R. A. Office of Nuclear Reactor Regulation. Director 14 19439: 345. 24X Fiche: 50-317, 83/06/24, 8307120039.
  - 83/05/23
- 8307120080 Releases public version of revised emergency response plan implementation procedure. FELTON, J. M. Division of Rules and Records. 83/06/24. Documentation procedure. 1p. 19435:208. 24X Fiche: 50-317: 83/06/24. 8307120080.
- --8307120083 Public version of Rev 2 to Emergency Response Plan Implementation Procedure ERPIP 4.4 7.6. "Post-Accident Sampling Sys & Analysis." W/830616 ltr % receipt form. RUSSELL,L. B. B. Baltimore Gas & Electric Co. 83/06/01 CLARK NRC No Detailed Affiliation Given 38pp. 19435:209. 24x Ficha: 50-317.83/06/24,8307120080. 93/06/01 CLARKIR.A. 19435:209. 24X
- B307190484 Advises that Class III & I fees remitted w/B30223 application for exemption from certain fire protection schedular requirements will be applied to alternate safe shutdown portion of 810319 request.
  MILLER.W.O. License Fee Management Branch. B3/07/08. LUNDVALL, A.E. Baltimore Gas & Electric Go. 2pp. 19456:165. 24X
  Fiche: 50-317, B3/07/08. B307190484.
- B307200135 Confirms current use of C-E Owners Group generic emergency procedure guidelines described in B30415 response to Suppl i to NUREG-0737. "Emergency Response Capability."
  LUNDVALL, A.E. Baltimore Gas & Electric Co. B3/07/15. CLARK, R. A. Operating Reactors Branch 3. ip. 19651.020. 24X
  Fiche: 50-317, B3/07/15, B307200135.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307210013 Forwards Rev 2 to updated FSAR, per 10CFR50, 71. LUNDVALL, A. E. Baltimore Gas & Electric Co. B3/07/18. CLARK, R. A. Operating Reactors Branch 3. App. 1966): 296. 24X Fiche: 50-317, 83/07/18, 8307210013.
- --8307210017 Rev 2 to Calvert Cliffs updated FSAR

  \* Baltimore Gas & Electric Co. 83/07/18. 830pp. 19661:301. 24X
  Fiche: 50-317, 83/07/18, 8307210013.
- P. Operating license stage documents & correspondence
- B307190376 Forwards generic safety evaluation supporting continued operation of PWRs u/Dresser primary safety valves, until final resolution of NUREG-0737. Item II. D. I CLARK, R. A. Operating Reactors Branch 3 83/05/03 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp. 19656:092. 24X Fiche: 50-317, 83/05/03, 8307190376.
- --8307190383 Safety evaluation supporting continued operation of PWRs w/Dresser primary safety valves until final resolution of NUREG-0737, Item II. D. 1.

  \* Office of Nuclear Reactor Regulation, Director. 83/04/18.
  13pp. 19656:054. 24X Fiche: 90-317, 83/05/03, 8307190376.
- B307200344 Summary of B30601 meeting w/litensee & C-E in Bethesda.MD re resolution of Unresolved Safety Issue A-47, "Safety Implications of Control Bys."

  SZUKIEMNICZ.A. Generic Issues Branch. 83/06/14. KNIEL.K. Generic Issues Branch. 4pp. 19670:007. 24X Fiche: 50-317.83/06/14.
- ---8305250564 Confirms proposed recommendations for improving NRC task action plan for Unresolved Safety Issue A-47, "Safety Implications of Control Sys." Approach would minimize adverse impact on engineering resources Meeting requested. POINDEXTER.C. H. Baltimore Gas & Electric Co. B3/04/14. DIRCKS.W.J. Office of the Executive Director for Operations. 4pp. 19670:011. 24X Fiche: 50-317, 83/06/14, 8307200344.
- --8305250595 Responds to 830414 proposal re-participation in activities concerning Unresolved Safety Issue A-47, "Safety Implications of Control Sys." Proposal meritorious Meeting to discuss proposal planned for 830523 in Bethesda MD. DIRCKS M.J. Office of the Executive Director for Operations. 83/05/16. POINDEXTER.C.H. Baltimore Gas & Electric Co. 88pp. 19670:015. 24X Fiche: 50-317, 83/06/14, 8307200344.
- 8307180446 Forwards monthly FR notice of amends to OLs involving NSHC. # Office of Nuclear Reactor Regulation, Director. 83/06/15 UHRIG.R.E. Florida Power & Light Co. 2pp. 19641:347. 24X Fiche: 50-000, 83/06/15, 8307180446.

- --B307190001 Menthly notice of amends to Dis involving NSHC.
  CLARM.R.A. Operating Reactors Branch 3 83/04/07 15pp.
  19641 349 24X Fiche. 50~000, B3/04/15, B307180446.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re-clarification of surveillance requirements for diesel fuel impority Svc list encl EISEMHULD @ Division of Licensing 83/07/09 Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24x Fiche 50-000.83/07/05.8306270397
- B307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENVILLD @ Division of Licensing 83:707/06 Consolidated Edison Co of New York, Inc. 16pp. 19669-254 24X Fiche: 50-000.83/07/06.8307060329
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENMUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669-269. 24x Piche: 30-000.83/07/08.8307080169
- 8307270303 Forwards safety evaluation of util Billia response to Generic Ltr Bi-21. "Natural Circulation Cooldown " Upper head voiding does not pose safety concern for facilities. Procedures will be reviewed per TMI Item I C. 1 CLARK,R.A. Operating Reactors Branch 3. 83/07/09. LUNDVALL.A E Baltimore Gas & Electric Co. 2pp. 19812.024 24x Fiche: 50-317,83/07/08. 8307270303.
- --8307270313 Safety evaluation of util 811113 response to Generic fitr 81-21. "Natural Circulation Cooldown" Upper head voiding not safety concern provided that operator equipped w/adequate training & procedures

   Office of Nuclear Reactor Regulation, Director. 83/07/08. 6pp. 19812:026 24X Fiche: 50-317. 83/07/08. 8307270303
- B30728010B Discusses results of review of incidence of personnel errors in performance of safety-related activities Electrical maint personnel training program should be instituted at earliest class. A Operating Reactors Brench 3. 83/07/08. LUNDVALL.A.E Baltimore Gas & Electric Co. 2pp 17812 348. 24x Fiche: 50-317.83/07/08.8307280108.
- 8307210198 Withdraws 830224 request for amend (Change 9) re fuel oil tank surveillance.Review continuing Request may be resubmitted later.
  LUNDVALL-A.E. Raltimore Gas & Electric Co. 83/07/11. GLARK.R A. Operating Reactors Branch 3. 1p. 19669 061 24X
  Fiche: 50-317,83/07/11,8307210198.
- 6307280199 Forwards program description for resolving IMI Action Plan Item II. K. 3. 5. "Automatic Trip of Reactor Coolant Pumps." Generic portion scheduled for completion by end of yr. LUNDVALL.A.E. Baltimore Gas & Electric Co. 83/07/25. CLARK.R.A. Operating Reactors Branch 3. 6pp. 19791 241. 24x Fiche: 50-317, 83/07/25, 8307280199
- B307280430 Reaffirms that continued uparation of facilities during installation of automatic trip of main feedwater sys pumps upon containment high pressure not under risk to public health // safety Mods will be completed by 831117 LUNDVALL. A. E. Baltimore Gas // Electric Co. B3/G7/25. CLARK.R A Operating Reactors Branch 3 App. 19797-252. 24x Fiche: 50-317, 83/07/25, 8307280430.
- Q Inspection reports, IE Bulletins & correspondence
- B307110627 Notification of significant licensee B30701 enforcement conference w/util in King of Prossia.PA.
  OREENMAN.E.G. Division of Project & Resident Programs. B3/06/27.
  Division of Project & Resident Programs. ip 19391-352. 24X
  Fichs: 50-317, 83/06/27, 8307110627.
- 830719089 Forwards IE Insp Repts 50-317/83-15 % 50-318/83-15 on 830929-0601 No noncompliance noted STARGSTECKI, Division of Project & Resident Programs. 83/0/LUNDVALL, A. E. Balttmore Gas & Electric Co. 2pp 19936: 103. Fiche. 50-317, 83/06/27, 8307190089
- --8307150093 IE Insp Repts 50-317/83-15 & 50-318/83-15 on 830525-0601 No noncompliance noted Major areas inspected isolation of salt water to ECCS pump room air coolers resulting in potential inoperability of ECCS & containment spray sys.

  ARCHITZELR E , TRIMBLE, D.C. Region 1, Office of Director.
  83/06/27. Spp. 19536:105 24X Fiche. 50-317,83/06/27,8307150089

- 8307060292 Discusses planned insp of rate of control element assembly fretting wear & ability to achieve design lifetime Util will eddy current test five assemblies from known high-wear locations during refueling outage after Cycle 6. LUNDVALL.A.E. Baltimore Gas & Electric Co. 83/06/30. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19238.342. 24X Fiche: 59-317,83/06/30,8307060272.
- 8307120559 Responds to 830623 request for statistical evaluation of actual math strengths for containment tendons, per IE Bulletin 80-04. Significant containment loads will not be transferred until after reinforcing steel approached. MONTGOMERY. B.S. Baltimore Gas & Electric Co. 83/07/01. CLARK.R.A. Operating Reactors Branch 3. 1p. 19433.087 )24X Fiche 50-317.83/07/01.8307120559.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/11. Consolidated Edison Co. of New York. Inc. 154pp 19563 293 24x Factor 50-000.83/07/11.8306270401.
- 8307150101 Ack receipt of 830613 itr informing NRC of steps taken to correct violations noted in IE this Repts 50-317783-11 & 50-318783-11 & 50-318783-11 & 50-318783-11 & 50-318783-11 & 50-318784-11 &
- -9307150110 Responds to NRC 830516 ltr re violations noted in IE Insp Repts 50-317/83-11 & 50-318/83-11. Corrective actions:logs will be required to name individual receiving grab sample info & air filter test performed on affected filters. LUNDVALL.A.E Baltimore Gas & Electric Co. 83/06/13. STAR031ECMI, R. Division of Project & Resident Programs. 2pp. 19530-076 24X Fiche: 50-317.83/07/11.8307150101.
- B306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563.153 24X Fiche:50-000.83/07/12.8306270404.
- B306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & [-131 in Ercess of NRC Limits," Svc list encl. TAYLOR, J.M. Division of GA. Safeguards & Inspection Programs (Post B30103) B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp 19715:270. 24x Fiche:50-000:B3/07/14,B306270404.
- 8307280307 Forwards IE Insp Repts 50-317/83-13 & 50-318/83-13 on 830510-0614 & notice of violation. STAROSTECKIR. Division of Project & Resident Programs. 83/07/14 LUNDVALLIA E. Baltimore Gas & Electric Co. 2pp. 19796; 027. 24X Fiche: 50-317,83/07/14,8307280307.
- --8307280310 Notice of violation from insp on 830510-0614, \* Region 1, Office of Director. 83/07/14, 2pp. 19796:029. 24X Fiche 50-317.83/07/14,8307280307.
- --8307260315 IE Insp Repts 50-317/83-13 & 30-318/83-13 on 830510-0614. Noncompliance noted failure to properly implement surveillance requirements for electric motor driven fire suppression water sys pump ARCHITZELIR.E., TRIMBLE.D.C., HIGGINS.J. Region 1, Office of Director. 83/07/13, 18pp. 19796:031. 24X Fiche:50-317.83/07/14.8307280307.
- 8307280343 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-317/83-08 & 50-318/83-08.
  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/21 LUNDVALL.A E. Baltimore Gas & Electric Co. 2pp. 19789:032. 24X Fiche: 50-317:83/07/21.8307280343.
- --8307280352 Responds to NRC 830520 ltr re violations noted in IE Insp Repts 50-317/83-08 & 50-318/83-08. Corrective actions: outside lab contracted to perform future strontium analyses. Sampling geometries procedure will be revised. LUNDVALL.A.E. Baltimore Gas & Electric Co. 83/06/15. MARTIN.T.T. Division of Engineering & Technical Programs. 2pp. 19789:034. 24X Fiche: 50-317,83/07/21,8307280343.
- R. Periodic operating reports & related correspondence
- 8307120244 "Semiannual Effluent Release Rapt for Calvert Cliffs Nuclear Power Plant-Second Half - 1982 " W/530301 ltr. LUNDVALL A E. Baltimore Gas & Electric Co. 83/03/01 HAYNEB, R. C. Region 1. Office of Director 19pp. 19424:116. 24X Ficha: 50-317,83/03/01.8307120244

- 8307200169 Monthly operating repts for June 1983 W/830715 ltr. LDTITG.E. Baltimore Gas & Electric Co. B3/07/14. Director's Office: Office of Inspection and Enforcement. 11pp. 19447:280. 24 Fiche:50-317.83/07/14.8307200169.
- S. Reportable occurrences, LERs & related correspondence
- B307:10443 Updated LER 83-022/03X-i:on 830331.oyster samples collected during First Quarter 1983 from Camp Canoy location showed Ag-110m to be 464 plus/minus 41 pCi/kg (wet).Caused by oysters to bioconcentrating environ silver. W/830622 ltr. BRQ88T.0.E., RUSSELL.L.B. Baitimore Gas & Electric Co. 83/05/05. MURLEY.T. Region 1, Office of Director. 2pp. 19380:189. 24X Fiche:50-317.83/05/05,8307110443.
- 8307120479 LER 83-028/01T: on 830524 & 25.ECCS pump air cooler 12 isolated to facilitate salt water draining from piping.
  Research in progress. Complete rept will be provided.
  RUSSELL, L. B. Baltimore Gas & Electric Co. 83/05/21. ALLAN, J. M. Region 1, Office of Director. 1p. 19425: 054. 24X Fiche: 50-317, 83/05/27, 8307120479.
- B307010076 Updated LER B3-002/03L-2:on B30104.containment sump valve MOV-5462 would not operate. Caused by excessively worn worm gean Gear replaced W/B30616 ltr.
  LAGIEMSKI.J.S., UNKLE.T.J., RUSSELL.L.B. Baltimore Gas & Electric Co. B3/06/16. ALLAN, J. M. Region 1. Office of Diractor. 3pp. 19124: 342. 24X Ficho: 50-317.83/06/16.8307010076.
- B307010083 LER B3-026/03L-0: on 830521, erratic metrascope indication for CEA 18 & metrascope associated alarms received when reed switch position transmitter stack failed Cause under investigation W/830616 ltr.
  PIERINGER, P.A., RAYNOR, J. W., RUSSELL, E. B. Haltimore Gas & Electric Co. 83/06/16. ALLAN, J. M. Region i, Office of Director. 2pp. 19124: 348. 24X Fiche: 50-317.83/06/16.8307010083.
- 8307010142 LER 83-032/03L-0: on 830523 containment isolation sys B logic module would not actuate Caused by defective Vitro Labs set logic module. Module replaced, Failed module returned to Vitro Labs for repair & testing W/830616 ltr.
  JUNGE.M.A., BASSG.L.F., RUSSELL.L.B. Baltimore Gas & Electric Co. 83/06/16. ALLAN.J.M. Region 1, Office of Director. 2pp. 19169:257. 24X Fiche: 50-317.63/06/16.8307010142.
- 8307010160 LER 83-030/03L-0: on 830519 during normal operations, plant computer taken out of svc to replace defective fam. Gaused by bearing fam failure. Fam replaced & computer returned to svc. W/630616 ltr.
  PORTER. R. J. , RAYNOR, J. W., RUSSELL, L. B. Baltimore Gas & Electric Co. 83/06/16. ALLAN J. M. Region 1. Dffice of Director. 2pp. 19170: 099. 24X Fiche: 50-317.83/06/16.8307010160.
- 8307120144 Updated LER 81-980/03X-1:on Bill16, discovered weep from cracked weld on spent fuel cooling pump discharge vent line 12 Caused by inadequate support of vent line. Support assembly installed M/830682 ltr.
  LAGIENSKI.J.S., FARRELL.E.V., RUSSELL.L.B. Baltimore Cas & Electric Co. B3/06/22, MURLEY, T. Region 1, Office of Director. 3pp. 19423:166 24X Fiche: 50-317,83/06/22,8307120144.
- 8307110456 LER B3-029/03L-0: on 830524, during normal operation, surveillance testing indicated neither spent fuel pool eihaust fans il or 12 would maintain required negative pressure Caused by clogged HEPA filters W/B30623 ltr. PIERINGER P. RAYNOR, J., RUBSELL, L. B. Baltimore Gas & Electric Co. 8370623. MURLEY, T. Region 1, Office of Director. 2pp. 19380:122 24X Fiche: 50-317,63706/23,8307110456.
- 8307110427 LER 83-034/03L-0: on 830525,ECCS pump room cooler 12 taken out of svc for maint & declared inoperable rendering ECCS subsystem inoperable. Caused by debris in saltwater supply piping & strainer. Piping & strainer cleaned. W/830624 ltr. JUNGE, M.A., BRANT, K.T., RUSBELL, L.B. Baltimore Oas & Electric Co. 83/06/24. NURLEY, T. Region I. Office of Director. 3pp. 19382:265-24X Fiche:50-317.83/06/24,8307110427.
- B307180187 LER B3-031/03L-0: on B30604.T hot signal to channel A reacto protection sys failed low.Caused by broken 120-volt ac input lead to temp channel power supply.Longer lead installed W/B30701 ltr.
  PDRTER.R.J. RAYNOR.J.W., RUSSELL,L.B. .Baltimore Gas & Electric Co. 83/07/01. MCREV.T Region 1. Office of Director. 2pp. 19355:205-24X Fiche: 50-317.63/07/01.8307180187.
- 8307180207 LER 83-025/03L: on 830602.T hot signal to channel A reactor protection sys. failed low, rendering automatic trip units for high power, thermal margin/low pressure & axial power distribution inoperable. Units replaced, W/830701 ltr. RAYNOR.J. W. PORTER.R. J. RUSSELL.L. B. Baltimore Gas & Electric Co. 83/07/01 MURLEY.T. Region I. Office of Director. 2pp. 1955: 109 24% Fiche. 50-317.83/07/01, 8307(80207.

- B307180245 LER B3-036/017-0 on B30618, during steady-state operation at B3% power, reed switch position indication lost for all control element assemblies. Caused by overloaded power supply. Transmitter will be replaced W/820701 ltr PIERINGER, P. RAYNOR. J. W. RUSSELL. B. Baltimore Gas & Electric Co B3/07/01. MURLEY. T. Region 1. Office of Director 3pp 19555: 233 24% Fiche: 50-317, 83/07/01, 8307180245.
- 8307210285 LER 83-035/03L-0 on 830610.during normal power operation.ESF actuation sys channel 2G steam generator level tripped Caused by failed Vitro isolator module Module replaced W/830708 ltr.
  PORTER, R. J., BASSO, L. F., RUSSELL, L. B. Baltimore Gas & Electric Co. 83/07/08. MURLEY, J. Region 1, Office of Director. 2pp. 17664:202-24X Fiche: 50-317.83/07/08.8307210285.
- B307210287 LER 83-033/03L-0 on 830603, fire detection instrumentation in containment southeast electrical penetration determined inoperable. Repair impossible due to inaccessability of Protecto wire. W/830708 ltr.

  JUNGE, M. A., BASSG, L. F., RUSSELL, L. B. Baltimore Gas & Electric Co. 83/07/08. MURLEY, T. Region 1. Office of Director. 2pp. 19664:204. 24% Fiche: 50-317, 83/07/08, 8307210287.
- U. Congressional/Executive Correspondence
- B30727004? Forwards monthly FR notice of consideration of issuance of amends to GLs involving NSHC determination & apportunity for hearing.

  DENTON, H. R. Office of Nuclear Reactor Regulation, Director.

  B3/06/22. STAFFORD, R. T., SIMPSUN, A. Senate, Environment & Public Works. UDALL, M. K. House of Rep., Interior & Insular Affairs. Spp. 19811:018. 24X Fiche: 50-000, B3/06/22, B307270047.
- -8307270000 Monthly notice of consideration of issuance of amends to OLs involving NSHC determination & opportunity for hearing. CLARK, R. A. Operating Reactors Branch 3. 83/06/07. 15pp. 19811:020. 24X Fiche:50-000,83/06/22,8307270047.
- DOCKET 50-318 CALVERY CLIFFS NUCLEAR POWER PLANT: UNIT 2 Security, medical, emergency & fire protection plans
- 8307070180 Rev 10 to Emergency Response Plan Implementing Procedure ERPIP App B.1. "Index of Equipment Checklist " W/830627 ltr & receipt form.

  RUSSELL,L.B. RAYBURN, C.R. Baltimore Gas & Electric Co. 83/06/22 WELCH, S. Director's Office, Office of Inspection and Enforcement, 44pp. 19293: 159. 24X Fiche 50-317.83/06/22,8307070180.
- EGO7120039 Releases public version of rev to emergency plan implementing procedure. FELTON.J.M. Division of Rules and Records 83/06/24. Docum Management Branch. 1p. 19439:344 24X Fiche:50-317,83/06/24-8307120039.
- ---B307120043 Public version of Rev 9 to Emergency Plan Implementing Procedure ERPIP 4.1.21. "Personnel Assembly " N/B30527 itr & receipt form.

  RUSSELL.L.B., RAYBURN, C.R. Baltimore Gas % Electric Co. 83/05/23.

  CLARK, R.A. Office of Nuclear Reactor Regulation, Director 14pp. 19439: 345. 24X Fiche. 50-317, 83/06/24, 8307120039.
- 3307120080 Releases public version of revised emergency response plan implementation procedure.

  FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch lp. 19435: 208 24% Fiche. 50-317, 83/06/24, 8307120080.
- --8307120083 Public version of Rev 2 to Emergency Response Plan Implementation Procedure ERPIP 4 4.7.6, "Post-Accident Sampling Sys & Analysis." W/830616 ltr & receipt form. RUSSELL.L.B. Baltimore Gas & Electric Co. 83/06/01. CLARK,R.A. NRC No Detailed Affiliation Given 38pp 19435:209. 24X Fiche: 50-317,83/06/24,8307120080.
- I307190484 Advises that Class III & I fees remitted u/830223 application for exemption from certain fire protection schedular requirements will be applied to alternate safe shutdown portion of 810319 request.
  MILLER.W.O. License Fee Management Branch 83/07/08 LUNDVALL.A E Baltimore Gas & Electric Co. 2pp. 19656 165 24X Fiche: 50-317.83/07/08.8307190484.

- R. Utility Final Safety Analysis Report (FSAR) & amends
- B307210013-Forwards Rev 2 to updated FSAR.per 1006R50 71 LUNDVALL.A E Baltimore Gas & Electric Co B3/07/18 Operating Reactors Branch 3 depp 19461 296 24x Fiche 50-317-83/07/18-830/21/013 CLARK. FLA
- ---8307210017 Rev 2 to Calvert Cliffs updated FSAR Baltimore Gas & Electric Co 93/0°/18 6 Fiche 50-917.83/07/18.8307210013 630gp 19661.301 24x
- P. Operating license stage documents to consequence
- 8307190376 Forwards generic safety evaluation supporting continued operation of FWRs w/Dresser primary safety valves until final resolution of NUREG-0737. Item 11 D 1 CLARK A Deprating Reactors Branch 3 83/05/03 LUNDWALL A Baltimore Gas & Electric Co 2pp 1965/6 052 24x Fiche: 50-317.83705/03.8307190376 83/05/03 LUNDVALL A E 052 841
- 8307200344 Summary of 830601 meeting w/licensee & C-E in Bethesda.MD re resolution of University Safety Issue A-47, "Safety Implications of Control Sys" 83706714, kNIEL, K. Generic Issues Branch. 4pp 19670 007 24% Fiche.50-317,83706714, 8307200344.
- --B305250564 Confirms proposed recommendations for improving NRC task action plan for Unresolved Safety Issue A-47. "Safety Implications of Control Sys " Approach would minimize adverse impact on engineering resources Meeting requested POINDEXTER.C H Baltimore Gas & Electric Co B304214. DIRCKS.N.J Office of the Elecutive Director for Operations 4pp. 19670.011. 24X Fiche.50-317.83/06/14.8307200344
- --B309250559 Responds to B30414 proposal reparticipation in activities concerning Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Proposal meritorious Meeting to discuss proposal planned for B30523 in Bethesda.MD. DIRCKS.H.J. Office of the Executive Director for Operations. B3709716. POINDEXTER.C.H. Galtimore Gas & Electric Co. B8pp 19670-015 24X Fiche 50-317,83702/14.8307200344
- 8307180446 Forwards monthly FR notice of amends to BLs involving NSHC.

  \* Office of Nuclear Reactor Regulation, Director. 83/06/15.
  UHRIO.R.E Florida Power & Light Co. 2pp. 19641: 347. 24X
  Fiche: 50-000. 83/06/15. 8307180446
- --8307190001 Monthly notice of amends to DLs involving NSHC CLARK F. A. Operating Reactors Branch 3. 83/06/07. 15 19641 349. 24x Fiche 50-000.83/06/15,8307180446.
- B307110129 "Reactor Containment Bldg Integrated Leakage Rate Test Rept." W/B30701 Ltr. LUNDVALLIA.E Baltimore Gas & Electric Co B3/07/01, CLARK.R.A. Operating Reactors Branch 3, 45pp 19379 182 24X Fiche: 50~JIB: B3/07/01
- R306270397 General Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl EISENHUT-D.G DIVISION of Licensing 83707705 Consolidated Edison Co. of New York. Inc. 16pp. 19390 117 24x Fishe 50-000.83707705.8306270297
- B30706032V Generate Ltr B3-27 to all increases 5 applicants for operating power reactors 5 holders of CPs for power reactors re-surveillance intervals in BTS Svc list with EBERNUID G. Division of Licensing B3/07/06. Consolidation Co. of New York. Inc. 16pp. 19669-254. 24% Fiche 50-600, B3/07/06, B307060329
- #307080169 Generic Ltr #3-28 to all licenses of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem AIMS events Svc list encl. #EISENHULL OF Division of Licensing #307708. Consolidated Edison Co. of New York, Inc. 38pp. 19569-269. 24X Fiche 50-000. #3307708. #307080169.
- 8307270303 Forwards safety evaluation of util 811133 response to Generic Ltr 81-21. "Natural Circulation Cooldown " Upper head voiding does not pose safety concern for Facilities Procedures will be reviewed per TM liem I C 1 CLARK, R.A. Operating Reactors Smanch 3 83/07/08 LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 19812-024 24x Fiche 50-317,83/07/08.8307270303

- \*\*-B307270313 Safety evaluation of util B11113 response to Generic Ltr 81\*\*-21. "Natural Circulation Cooldown " Upper head voiding not safety concern provided that operator equipped b/adequate training & procedures
   Office of Nuclear Reactor Regulation. Director 83/07/08. App 19812 026 24% Fiche 50-317.83/07/08.8307270303
- 8307280108 Discusses results of review of incidence of personnel errors in performance of safety-related activities Electrical maint personnel training program should be instituted at earliest practicable date CLARK, R.A. Operating Reactors Branch 3 83/07/08 LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 19812, 348, 24X Fiche: 50-317, 83/07/08, 8307280108
- 6307210198 Withdraws 830224 request for amend (Change 9) refuel oil tank surveillance. Review continuing. Request may be resubmitted later.

  LUMBVALL-A.E. Baltimore Gas & Electric Co 83/07/11 CLARK.R A. Operating Reactors Branch 3 ip 19669 Obl. 24X

  Fiche: 50-317, 83/07/11, 8307210198.
- 8307280199 Forwards program description for resolving TMI Action Plan Item 11 K. 3 5. "Automatic Trip of Reactor Coolant Pumps." Generic portion scheduled for completion by end of yr. LVNDVALLA E. Baltimore Gas & Electric Co. 83/07/25. CLARK.R.A. Operating Reactors Branch 3. App. 1979; 241 24X Fiche. 50-317,83/07/25,8307280199.
- 8307280430 Reaffirms that continued operation of facilities during installation of automatic trip of main feedwater sys pumps upon containment high pressure not undue risk to public health % safety, Mods will be completed by B31117. LUNDVALL.A.E. Baltimore Gas & Electric Co. 83/07/25 CLARK.R A Operating Reactors Branch 3 App. 19797:252. 24x Fiche:50-317.83/07/25.8307280430.
- G. Inspection reports. IE Bulletins & correspondence
- B307110627 Notification of significant licensee B30701 enforcement conference w/util in King of Prossia.PA GREENMAR.E G Division of Project & Resident Programs. B3/06/27. Division of Project & Resident Programs. B3/06/27. Fiche: 50-317. B3/06/27. B307110627.
- 8307150089 Forwards IE Insp Repts 50-317/83-15 & 50-318/83-15 on 830525-0601 No noncompliance noted STAROSTECKI R. Division of Project & Resident Programs 83/06/27. LUNDVALLA E. Baltimore Gas & Electrix Cu 2pp 19536:103. 24x Fiche: 50-317.83/06/27.8307150089.
- --B307150093 IE Insp Regts 50-317/83-15 % 50-318/83-15 on 830525-0601.No noncompliance noted Major areas inspected isolation of salt water to ECCS pump room air coolers, resulting in potential inoperability of ECCS & containment spray sys ARCMITZEL.R E . TRIMBLE.D C. Region 1. Office of Director. 83/06/27 Spp 19536:105. 24% Firms 50-317.83/06/27.8307150089.
- B307120559 Responds to B30623 request for statistical evaluation of actual math strengths for containment tendons.per IE
  Bulletin B0-04 Significant containment loads will not be transferred until after reinforcing steel approached.
  MONTGOMERY.D.S. Baltimore Gas & Electric Co. B3/07/01. CLARK.R A Operating Reactors Branch 3. 1g. 19433.087 24x
  Fichs. 50-317.83/07/01.8307120559
- 8306270401 IE Info Notice 83-46, "Common Made Valvo Failures Degrade Surry Rectroulation Spray Subsystem." Sec list encl JORDAN,E. L. Division of Emergency Proparedness & Engineering Response (Post 830603). 83/07/11 Consolidated Edison Co. of New York, Inc. 154pp. 19563:293 24X Fiche 50-000.83/07/11.8306270401.
- 8307130101 Ack receipt of 830613 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept< 50-317/83-11 & 50-318/83-11 50-318/83-11 STAROSTECKI,R Division of Project & Resident Programs 83/07/11, LUNDVALL,A E. Galtimore Gas & Electric (o. 20p. 19530:074 24x Fiche:50-317,83/07/11,8307150:01
- --8307150110 Responds to NRC 830516 itr re-violations noted in IE Insp. Repts 50-317783-11 & 50-348783-11 Corrective actions logs will be required to name individual receiving grab sample info bair filter test performed on affected filters.

  LUNDVALL, A. E. Baltimere Gas & Electric Co. 83706713.

  STARGSIECKI, R. Division of Project & Resident Programs 2pp 19530 076. 24X Fiche:50-317.83707711.9307150101
- B306270404 IE info Notice B3-47. "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Florid." Svc list encl. URDAN.E. L. Division of Emergency Propagations 3. Engineering Response (Post 830103). 83/07/12 (onsalidated Edison Co. of New York, Inc. 141pp. 19563-153 24x Fische 50-000-83/07/12-8306270404.

- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list enc].
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103) 83/07/14. Consolidated Edison Co of New York, Inc. 114pp. 19715.270. 24X Fiche.50-000.83/07/14.8306270406. B30103)
- 8307280307 Forwards IE lnsp Repts 50-317/83-13 & 50-318/83-13 on 830510-0614 & notice of violation STAROSTECKI, R. Division of Project & Resident Programs. 83/0 LUNDVALL.A.E. Baltimore Gas & Electric Co. 2pp 19796:027. Fiche: 50-317, 83/07/14, 8307280307
- --8307280310 Notice of violation from insp on 830910-0614. \* Region 1, Office of Director. 83/07/14. 2pp. 197 Fiche: 50-317, 83/07/14, 8307280307. 19796: 029. 24x
- --8307280315 IE Insp Repts 30-317/83-13 % 50-318/83-13 on 830510-0614. Noncompliance noted: failure to properly implement surveillance requirements for electric motor driven fire Suppression water sys pump.

  ARCHTZEL/R. E. TRIMBLE D.C. HIGGINS J. Region 1, Office of Director. 83/07/13. IBpp. 19796:031. 24X Fiche.50-317,83/07/14, 8307280307.
- B307280343 Ack receipt of B30613 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-317/83-08 & 30-318/83-08. MARTIN: T. Division of Engineering & Technical Programs. 83/07/6 &UNDVALL: A. E. Baltimore Gas & Electric Co. 2pp. 19789: 032. 243 Fichs: 50-317: 83/07/21: 8307280343.
- --8307280352 Responds to NRC 830520 ltr re violations noted in IE Insp. Repts 50-317/83-08 & 50-318/83-08 Corrective actions:outside lab contracted to perform future strontium analyses. Sampling geometries procedure will be revised.

  LUNDVALL.A.E. Baltimore Gas & Electric Co. 83/06/15. MARTIN.T.T. Division of Engineering & Technical Programs. 2pp. 19789:034.

  24X Fiche: 50-317,83/07/21,8307280343. MARTIN, T. T.
- R. Periodic operating reports & related correspondence
- B307120264 "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant, Second Half 1982." W/B30301 ltr LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 19pp. 19424:116. 24X Fiche: 50-317, 83/03/01, 8307120264.
- B307200169 Monthly operating repts for June 1983 W/B30719 ltr.
  LOTITO.E. Baltimore Gas & Electric Co. 83/07/14. Director's Office Office of Inspection and Enforcement. ilpp. 17647:280. 24X Fiche: 50-317.83/07/14.8307200169.
- S. Reportable occurrences, LERs & related correspondence
- 8307010124 LER 83-030/03L-0: on 830516, pressurizer pressura decreased to 2, 185 psia & pressurizer level decreased to 128 inches. Caused by closed hydraulic dampener bypass valves on turbine bypass control valves. Valves opened. W/8306f5 ltr. JUNGE, M.A. Baltimore Gas & Electric Co. 83/06/15. ALLAN, J. M. Region 1, Office of Director. 2pp. 19168: 354. 24X Fiche: 50-318/83/06/15.8307010124.
- 8307010087 LER 83-027/03L-0: on 830522, power-dependent insertion limit (PDIL) for Group 5 rods found inoperable, rendering control element assembly motion inhibit inoperable. Caused by failure of PDIL auctioneering card semiconductor W/830616 ltr. PORTER, R. J., RAYNOR, W., RUSSELL, L. B. Baltimore Gas & Electric Co. 83/06/16. ALLAN, J. M. Region 1, Office of Director. 2pp. 19124: 353 24X Fiche: 50-318, 83/06/16, 8307010087
- 8307180193 LER 83-031/03L-0: on 830606, containment cooler 21 failed to start in slow speed upon containment spray actuation test signal. Caused by failure of low speed contacts. Replacement relay to be installed W/B30706 ltr.
  JUNGE, M. A., RAYNOR, J. M., RUSSELL, L. B. Baltimore Gas & Electric Co. 83/07/06. MURLEY, T. Region 1. Office of Director 2pp. 19555: 266. 24X Fiche: 50-318, 83/07/06, 8307180193
- 8307220507 LER 83-032/03L-0: on B30611, during MSIV surveillance testing, cold leg temp exceeded Tech Spec limit Caused by improper limit switch arm position. Switch arm adjusted W/830708 ltr. MENDERLICH, R. L., BASSO, L. F., RUSSELL, L. B. Baltimore Gas & Electric Co. 83/07/08 MURLEY, T. Region 1. Office of Director. 3pp. 19685: 272 24X Fiche: 50-318, 83/07/08, 8307220509.

#### U. Congressional/Erecutive Correspondence

- B307270047 Forwards monthly FR notice of consideration of issuance of amends to OLs involving NSHC determination & opportunity for hearing.

  DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director.

  B3706722. STAFFORD.R.T. Senate, Environment & Public Works.

  OTTINGER.R.L. House of Rep., Energy & Commerce 2pp. 19811 018.

  24X Fiche: 50-000, 83706722. 8307270047
- --8307270050 Monthly notice of consideration of issuance of amends to DLs involving NSMC determination & opportunity for hearing CLARK.R.A. Operating Reactors Branch 3 83/06/07. 15pp. 19811:020. 24X Fiche:50-000.83/06/22.8307270047
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION. UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307180330 Releases public version of rev to emergency plan administrative procedure. FELTON.J.M. Division of Rules and Records. 83/06/24 Document Management Branch. 1p. 19565:337. 24X Fiche:50-320.83/06/24. 8307180330.
- --8307180332 Public version of Rev 1 to Emergency Plan Administrative Procedure 1055, "Emergency Planning Training," KANGA.B.K. General Public Utilities - GPU Service Corp. 83/05/27. 14pp. 19565:338. 24X Fiche:50-320,83/06/24,8307180330.
- 8307190427 Advises that resolution to NRC comment on General Project Design Criteria Section 2.5 "Mini DHRs" & new wording for Section 3.4.1(1) on App R criteria should be incorporated into Rev 3.

  SYNDER: B. J. TMI Program Office. 83/07/07. KANGA. B. K. General Public Utilities GPU Service Corp. 2pp. 19636:043. 24X Fiche: 50-320, 83/07/07, 8307190429.
- 8307270031 Forwards Rev 18 to security plan Rev withheld (ref 10CFR73.21). HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/07/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19749:360. 24X Fiche:50-289,83/07/20,8307270031.

#### G. Adjudicatory correspondence

- 8307190259 Notifies of VR Harding employment at law firm. Harding will not participate in any case currently pending before NRC. RIDGMAY.D.A. Shaw. Pittman. Potts & Trowbridge. 83/07/13 MOLF.J.F. PARIS, O.H., SHON,F.J. Atomic Safety and Licensing Board Panel. ip. 19629:276. 24X Fiche:50-320,83/07/13,8307190259.
- ---B307190263 Notifies of employment at law firm.VR Harding will not participate in any case pending before NRC Svc list encl. HARDING.V.R. Shaw, Pittman, Potts & Trowbridge. B3/07/13. WOLF.J.F., PARIS.O.H., SHON,F.J. Atomic Safety and Licensing Board Panel. 2pp. 19629:277. 24X Fiche: 50-320.83/07/13.8307190259.
- B307210248 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  BILBERG, J.E. Shaw, Pittman, Potts & Trombridge, 83/07/13.
  PALLADINO, N. J., GILINSKY, V., A
- ---8307210251 Notifies of employment at law firm.VR Harding will not participate in any case pending before NRC. Svc list encl. HARDING.V.R. Shaw, Pittman. Potts & Trombridge. 83/07/13. PALLADIND.N.J. GILINSKY.V. AHEANNE, J.F. Commissioners. Spp. 19644:062. 24X Fiche: 50-000, 83/07/13, 8307210248.
- 8307190198 Discusses concerns expressed in 83060P ltr re cheating on operator qualifying exam, safety of TM1-2 cleanup & operator competence & integrity at TMI. Final decision on restart will not be made until outstanding concerns addressed. PALLADIND, N. J. Commissioners. 83/07/14. THORNBURGH.R. Pennsylvania. Communwealth of. 2pp. 19630: 109. 24x Fiche: 50-289, 83/07/14, 8307190198.
- B307250263 Responds to 830627 memo posing question on NRC action re util falsification of leak rate tests. Fact that Hartman allegations referred to DOJ was not withheld from public. DIRCKS. M. J. Office of the Executive Director for Operations. B3/07/19. GILINSKY, V. Commissioners. 3pp. 19705:279. 24x Fiche: 50-289, 83/07/19, 8307250263.

- 8307250027 Memorandum on status of NPC TMT-1 restart review.per ASLAB 830616 3 0706 orders Completion of NPC review of open issues & formulation of NPC position on agt integrity realistically appear to be many months away GOLDBERG.J R. Hearing Branch 2 83/07/21 8pp 19703:023 24X Fiche 50-289,83/07/21,8307250327
- --8307290034 Responds to request for info no nature & current status of NRC review of GPU vs B&W lawfult documents As of 800720. screening review approx 75% complete RUSSELE.H.T. NRC No Detailed Affiliation Given 60/07/20. GOLDBERG.J. Hearing Branch 2 ip 19700-031. 24% Fiche 50-289.83/07/21.8307250327
- --8307250344 Defines scope, purpose & approach re NRR review of GPU vs B&W lawsuit documents Review comprises audit review similar to normal NRC safety review. Completion by Sept 1983 should be scheduled
  DENTON-H R. Office of Nuclear Reactor Regulation. Director 83/07/11. EISENHUT.D. G. Division of Licensing SPEIS.T P Division of Safety Technology. VOLLMEP.P H. Division of Engineering. 4pp. 19703.032 24X Fiche 50-289.83/07/21, 8307250327.
- 8307250347 Statement of Commission CLI-83-80, authorizing issuance of notice of violation & proposed imposition of aivil penalties in amount of \$140.000 re failure to implement retraining program property & matl fairs statements CHILK.S.J. Diffice of the Serretary of the Commission 83/07/22 12pp. 19703:259. 24% Fiche 50-289.83/07/22.8307250347.

#### H General correspondence

- B306100004 Forwards BEIR rept. "Effect on Fegulation of Exposure to Low Lovels of Ionizing Radiation." in response to B30411 request for info re health impact estimate W/a encl SNYDER.B. J. TMI Program Office B3706766. HURST. J. Affiliation Unknown 3pp. 18815.324. 24X Fishe 50-320.83706706.8306100004.
- 8307270017 Responds to constituent 8 0 No.1 830419 Ith expressing concerning cleanup. OPC of Investigations is investigating allegations re-polar chane safety 8 cleanup issues First phase to be completed in Aug 1983 DIRCKS.W J. Office of the Executive Director for Operations 83/07/13. SPECTER.A. Senate 5pp 19811 012 24% Fiche. \$0-320.83/07/13.8307270017
- --B307270019 Requests findings & views on constituent B O'Neil encl B30419 ltr re cleamup & alleged safety violations SPECTER,A. Senate B3/04/19 Office of Congressional Affairs 2pp. 19811 016. 24X Fiche 50-320/83/07/13,830/2370017
- P Operating license stage documents & correspondence
- 8307070147 Forwards responses to NRC 830602 ltr re-underhead characterijation SERs. Approximity voll exchanges per day would occur under reactor vessel head w/velocity in H-8 manipulator of 1 ft/s.

  KANGA: B K General Public Utilities GPU Service Corp. 83706789 BARRETT. L H. TMI Program Office. 12pp. 19294:240 24X Fichs: 50-320,83706/29,8307070149
- B3070B000B Forwards Rev 3 to polar crane functional description for use in evaluating refurbishment of polar crane KANDA.B.K. General Public Utilities GPU Service Corp. B3/06/30 BARRETT.L.H. TMI Program Office 2pp 19351 244. 24x Fiche: 50-320, 83/06/30, 83070B000B.
- B307120004 Forwards Page 3 to polar crans SFR describing relocating internals indexing filture.assembly of test load. load test & disassembly of test load. RANGA, 8 K. General Public Utilities 5 GPU Service Corp. 83/06/30 BARRETT.L.N. TM1 Program Office. 2pp. 19423-188. 24X Fiche: 50-320.83/06/30.8307120004.
- 8306270397 Generic Ltr 83-26 to all applicants for ULs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl EISENHUI,D.G. Division of Licensing 83:707705 Consolidated Edison Co. of New York: Inc. 16pp. 19370.317 24x Fiche: 50-000.83/07705.8306270397.
- BU07060329 Generic Ltm 83-27 to all licensees 5 applicants for operating power reactors 5 holders of CPs for power reactors re-surveillance intorvals in STS Svc list encl EISENMUT-D. G. Division of Licensing 63/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19469-254. 24x Fiche: 50-000, 83/07/06. 8307060329.

- 8307180166 Forwards payment of licensing fees required by 10CFR170 22 for previously submitted requests KANGA-B k. General Public Utilities GPU Service Corp. 83/07/06. MILLER, W.O. License Fee Management Branch 2pp 19555:240. 24X Fiche 50-320. 83/07/06. 8307180166
- 8307190319 Proposes meeting in Parsippang.NJ to train NRC members in use of GPU computerized record sys in order to access GPU vs B2W Lawsuit documents from Bethesda.MD ofcs. Info generated would be placed in PDR.
  DENTON.H R. Office of Nuclear Reactor Regulation, Director.
  B3/07/06 ARNOLD.R C General Public Utilities GPU Service Corp 19 19496 174 24x Ficher 50~289.83/07/06.830/7190310.
- 8307120342 Forwards application for amend to License DPR-73, consisting of Tech Spec Change Request 42 re temporarily deleting ref to requirements for monitoring, instrumentation 5 valves. ARNOLD R C. General Public Utilities GPU Service Corp. B3/07/07 SYNDER/B J. TMI Program Office. 1p. 19425-093. 24X Fiche: 50-320, 83/07/07, 8307120342
- --8307120347 Application for amend to License DPR-73, consisting of Tech Spec Change Request 42 temporarily deleting ref to requirements for monitoring, instrumentation & valves. ARNOLD.R.C. General Public Utilities - CPU Service Corp. 83/07/07. 4pp 19425:094. 24% Fiche: 50-32G, 83/07/07, 8307120342.
- --8307120352 Tech Spec re monatoring instrumentation & valves.
  4 General Public Utilities GPU Service Corp. 83/07/07. 23pp
  19425-998. 24X Fiche: 50-320: 83/07/07: 8307120342.
- 8307190429 Advises that resolution to NRC comment on General Project Design Criteria Section 2.5 "Mini DRRs" & new wording for Section 3.4.1(1) on App R criteria should be incorporated into Rev 3
  5\*NDER.B J. TMI Program Office 83/07/07. KANGA.B K. General Public Utilities ~ OPU Service Corp. 2pp 19656-043. 24X
  Fiche: 50-320.83/07/07.8307190429.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHULD, G. Division of Licensing 63/07/08. Consolidated Edison Co. of New York, Inc. 38pp 19669. 269. 24X Fiche: 50-000, 83/07/08, 8307080169
- a307190119 Informs that last EPICOR II prefilter shipped 830712 ahead of schedule per 821215 ltr MANGALS.K. General Public Utilities - GPU Service Corp. 83/07/12. BAPRETTIL.H TMI Program Office 1p 19636:045. 24X Fiche: 50-320 83/07/12 830/190119
- B307290169 Notification of contract execution.Mod 2 to "Reanalysis of Existing Data From Survey re TMI." Contractor:Nat! Inst of Mental Health.

  SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-8621.

  B3/07/12 DENTON.H.R. Office of Nuclear Reactor Regulation.

  Director. REGAN.W.H. NRC No Detailed Affiliation Given. 1p.

  19729:355 24X Fiche: 50-287, 83/07/12,8307250168.
- --9307250176 Mod 2. extending period of performance to 830430, to "Reanalysis of Existing Data From Survey re TMI" a Health & Human Services, Dept of, GUSTAVE.R.P. Division of Contracts. FIN 8-8621. 83/07/12 ip 19725:356. 24X Fiche 50-289.83/07/12.8307250168
- 8307150159 Submits proposal to change reserve tank requirement to maintain min of 100,000 gallons freeboard between tanks until approval of 830527 Amend Request 3 MANGA.B.K. General Public Utilities GFU Service Corp. 83/07/13. BARRETT-L H. IMI Program Office 2pp 17535-234, 24X Fiche: 50-320-83/07/13, 8307150159.
- 0307270026 Discusses safety evaluations for reactor vessel underhead characterization study Environ impacts from proposed operation fall within scope of activities previously considered in programmatic EIS DARRETTLH. TMI Program Office. 83/07/13 KANGA.B.K. Ceneral Public Utilities GPU Service Corp. 4pp. 19811.242. 24X Fiche: 50-320.83/07/13,8307270026.
- 8307290542 Comments on manuscript "Progress in Cleanup of TMJ 2."
  List of refs should be expanded Paper acceptable for publication.
  SNYDER-B J. TMI Program Office 83/07/13 COTTRELL-M.B. Gak Ridge National Laboratory. 2pp 19857.084. 24x fiche:50-320.03/07/13.8307290542

- 8307200164 Notifies of minor variation in criteria for preparation of submerged demineralizer sys Liner D10011 for shipment.

  Johnson Screen & fill piping to be filled to 98% capacity to maintain control of radiolythical gases.

  KANGA, B. K. General Public Utilities GPU Service Corp. 83/07/15.

  BARRETTI. H. Till Program Office. 2pp. 19647-275. 24% Fiche: 50-320, 83/07/15, 8307200164.
- 8307270032 Concurs w/proposed plan to remove upper & lower tank farm from required reserve waste water tankage.in response to 830713 ltr. BARRETT.L.H. TMI Program Office. 83/07/15. KANGA.B.K. General Public Utilities - GPU Service Corp. 2pp. 17811:246. 24X Fiche:50-320.83/07/15.8307270032.
- 8307270037 Responds to 830715 ltr requesting variation of catalyst addition criteria for submerged demineralizer sys Liner D10011 Adequate recombiner matl present to control any potential combustible radiolytic gases.

  BARRETT.L. H. TMI Program Office. 83/07/15. KANGA.B.K. General Public Utilities GPU Service Corp. 3pp. 19811.297. 24X Fiche: 50-320.83/07/15.8307270039.
- B307250331 Forwards Rev 2 to "TM1-2 Core Debris Grab Bamples Safety Evaluation." Core debris sample program can be accomplished w/o undue risk to public health & safety.

  KANGA B. K. General Public Utilities GPU Service Corp. B3/07/20.

  BARRETT. L H. TMI Program Office. 1p. 19703:013. 24X

  Fiche: 50-320,83/07/20,8307290331.
- --8307250336 Rev 2 to "TMI-2 Core Debris Grab Samples Safety Evaluation," \* General Public Utilities - GPU Service Corp. 83/07/20. 9pp. 19703:014. 24X Fiche: 50-320,83/07/20,8307250331.
- 830725045A Forwards response to NRC 830615 request that util provide adequate justification for each instance Tech Spec surveillance invoked due to occupational exposure considerations.

  KANGA.B.K. General Public Utilities GPU Service Corp. 83/07/20. SNYDER.B.J. TMI Program Defice. 23pp. 19702:041. 24X Fiche: 30-320:83/07/20.8307250454.
- 8307260474 Forwards Rev 1 to "Containment Air Control Envelope," technical evaluation rept & design criteria. Fee enct.
  KANDA, B. K. General Public Utilities GPU Service Corp. 83/07/22.
  BARRETTL H. THI Program Office. 1p. 19734:050. 24X
  Fiche: 50-320.83/07/22.8307260474.
- --8307260477 Rev i to "Containment Air Control Envelope," technical evaluation rept.

  \* General Public Utilities GPU Service Corp. 93/07/31. 30pp. 19734.051. 24% Fiche: 50-320,83/07/22,8307260474.
- 8307280397 Forwards evaluation of reactor bldg reflood options.

  Disadvantages of full or partial reflood far outweigh
  benefits Present mode will be continued.

  KANOA.B.K. General Public Utilities GPU Service Corp. 83/07/26.

  BARRETT, L. H. TMT Program Office. 6pp. 17796:316. 24X

  Fiche: 90-320.83/07/26.8307280357.
- 0. Inspection reports, IE Bulletins & correspondence
- 8307010117 Forwards responses to 1E Bulletins 79-15,82-02 & 82-04.1E Bulletins 82-01.82-03 & 82-04 inapplicable.
  KANOA.B.K. General Public Utilities GPU Service Corp. 83/06/13.
  ALLAN.J.M. Region 1, Office of Director. 8pp. 19169:245. 24X Fiche: 50-320.83/06/13.3307010117.
- H307110392 Forwards IE Insp Rept 50-320/83-07 on 830502-30. No noncompliance noted.

  STARCSIECKI.R. Division of Project & Resident Programs. 83/06/23. KANOA.B.K. General Public Utilities GPU Service Corp. 2pp. 19380:296. 24X Fiche: 50-320, 83/06/23, 8307110392.
- --8307110376 IE Insp Rept 50-320/83-07 on 830502-30. No noncompliance noted Major areas inspected: licensee action on previous insp findings.routine plant operations. LERs, routine maint, health physics & environ review & reactor bldg entries. MEBELJ, BARKIK, MBGARKIT, Region 1, Office of Director. 83/06/22, 9pp. 19380: 278. 24X Fiche 50-320, 83/06/23, 8307110372.
- 8307190432 Requests stress analyses & dotailed plans for corrective action required for undersized words discovered during 830408 insp of head lift tripud. Comparison of proposed plans w/actions taken for other DXM reactors requested. BARRETT.L.H. TMI Program Office. 83/07/08. KANGA, B.K. General Public Utilities GPU Service Corp. 3pp. 19656:067. 24X Fiche: 50-320,83/07/08,8307190432.

- 8307250403 Forwards IE Insp Rept 50-320/83-06 on 830404-0527 % natice
  - 80/200403 Forwards in 1999 Nept to Sect the Resident Programs. B3/07/08 GAROSTECKI,R. Division of Project & Resident Programs. B3/07/08 KANGA,B.K. General Public Utilities GPU Service Corp. 2pp. 19703:168. 24X Fiche 50-320.83/07/08.6307250403
- --8307250406 Notice of violation from insp on 830404-0527 \* Region 1. Office of Director. 83/07/08. 2pp 19 Fiche. 50-320.83/07/08.8307250403. 19703 170 243
- ~-8307250413 IE insp Rept 50-320/83-06 on 830404-0527 Noncompliance noted: failure to adhere to administrative & radiological control procedures re congestion of work areas w/eicess
  - matls. O'NEILL.B., MOSLAK.T., BARR.K. Region 1. Office of Director. 83/07/05. 37pp. 19703.172. 24X Fiche: 50-320,83/07/08.8307250403
- 9306270401 IE Info Notice 83-46, "Common Mude Valve Failures Degrade Surry Recirculation Spray Subsystem" Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293, 24X Fiche: 50-000, 83/07/11, 8306270401.
- 3306270404 IE Info Notice 83~47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17963:193. 24X Fiche 50-000,83/07/12,8304270404
- 9306270406 IE Info Notice 83-48, "Gaseous Effluent Releases Radioactive I-125 & I-131 in Excess of NRC Limits." Svc 1 encl. TAYLOR: J. M. M. Division of GA. Safeguards & Inspection Programs (Post 83/07/14. Consolidated Edison Co. of New York, Inc. 9715: 270. 24% fiche: 50-000, 83/07/14, 8306270406. B301031. 19715: 270.
- 3007280447 Informs that enci list of IE bulletins not applicable to facility in present post-accident condition. Bulletins classified as restart will be reevaluated when restart considered.

  KANDA, B. K. General Public Utilities GPU Service Corp. 83/07/2 MURCEY/T.E. Region 1, Office of Director. 3pp. 19797:308. 24X Fiche: 50-320, 83/07/21, 8307280447. 83/07/21
- Periodic operating reports & related correspondence
- 1307290527 Forwards TMI Program Ofc weekly status rept for wk of 307290327 Formerus III F. Sy. L.M. M. B. 30710-16.
  BARRETT L. H. TMI Program Office. 83/06/18. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. SNYDER, B. J. TMI Program Office. 11pp. 19857: 154. 24X Fiche: 50-320, 83/06/18, 8307290527.
- H307180410 Forwards TMI Program Ofc weekly status rept for wk of 107180410 Forwards III. 195 BARRETT, L. H. TMI Program Office. 83/06/27. DENTON, H. R. Office Nuclear Reactor Regulation, Director. SNYDER, B. J. TMI Program Office. 10pp. 17641: 258. 24x Fiche: 50-320, 83/06/27, 8307180410. Office of
- 1307180412 Forwards TMI Program Ofc weekly status rept for wk of 80/180412 POTWARDS INT PROGRAM OFFICE 83/07/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office 81/07/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office. 12pp. 19641:246. 24X Fiche:30~320,83/07/01,8307180412.
- I307080225 Forwards groundwater monitoring data including individual computer graphs of tritium concentrations & water levels through May 1983.

  KANGA, B. K. General Public Utilities GPU Service Corp. 83/07/05.

  BARRETT, L. H. TMI Program Office. 40pp. 19352:052. 24X

  Fiche: 50-320, 83/07/05, 8307080225.
- 307180413 Forwards TMI Program Ofc weekly status rept for wk of 830703-09.
  BARRETTILLH. TMI Program Office. 83/07/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. SYNDER, B. J. TMI Program Office. 10pp. 17441; 234. 24X Fiche 50-320, 83/07/11, 8307180413
- . Reportable occurrences. LERs & related correspondence
- 307220537 LER 83-004/03L-0: on 830218, air intake tunnel sump level had risen such that there was standing water on 1/4 of floor.
  Caused by deluge leaks due to heat tracing Failure Leaks repaired, heat tracing & detectors replaced W/83032i ltr.
  CHAPLIN,S. D., KANGA, B. K. General Public Utilities GPU Service Corp. 83/03/21 HAYNES,R. C. Region 1, Office of Director. 4pp. 19686: 033. 24X Fithe: 50-320,83/03/21,8307220537.

- B307010059 Updated LER B3-014/03L-1 on B30905 air intake tunnel Halon sys actuated causing actuation of daloge sys 5 trip of auxiliary 5 feel handling blogs supply 5 without fans Caused by short in actuation leads Sys repaired WA30617 tr CHAPLIN.5.D. KANGA.B K. General Public Utilities GPU Service Corp. B3066/17. MURLEY T.E. Region 1. Office of Director. App. 19169:237 24X Fiche: 50-320. 83/06/17. 830/010055
- B307110441 LER 83-017/03L-0 on 830527.reactor bldg water level instrumentation indication unchanged all wk despite addition of 24,000 gallons of water Coused by improper seating of level instrument equalizing valve W/B30627 ltr CHAPLIN.5 D. KANDA.B.K. General Public Utilities GPU Service Corp. 83/06/27 MWRLEY.T.E. Region 1. Office of Director. 3p; 19380:186 24X Fiche: 50-320, 83/06/27, 2307110441
- B307110448 LER B3-015/03L-0: on B30527, one Halon bottle found w/low pressure & low weight during surveillance of air intake tunnel Halon sys Caused by development of leak in bottle or fittings. Bottle replaced. M/830627 ltr CHAPLIN.S D. KANOA.B.K. General Public Utilities GPU Service Corp. B3/06/27 MURLEY.T.E. Region 1. Office of Director. 4pp. 19380.192 24X Fiche: 50-320.83/06/27, 9307110448
- B307180178 LER 83-018/03L-0 on 830603 rupture disc on inboard flange of reactor bidg containment penetration 8%1 breached Caused by high pressure hose rupture due to line pressure polising Hose & rupture disc replaced W/830705 for WECLS:R., KAN9A.B.K. General Public Utilities GFU Service Corp. 83/07/05 MURLEY-T.E. Region 1, Office of Director. App. 19595:063 24X Fiche 50-320.63/07/09.8307180178
- 8307220527 LER 83-020/03L-0 on 830610. Flowrate for auxiliary bldg exhaust fans AH-E-8/8 decreased below Tech Spec limit Caused by vortex damper linkage problems Parts ordered to repair linkage W/830711 tor WELLS.R. KANOA.B.K. General Public Utilities GPU Service Corp 83/07/11. MURLEY.T.E. Region 1. Dffice of Director. App. 19685:176 24X Fiche: 50-320, 83/07/11, 8307220527
- B307220556 LER B3-022/03L-0 on B30609, while Railey B55 computer out of svc for checks, loop A T-hot instrument declared inoperable. Caused by inadvertent removal of instrumentation fuse. Fuse replaced. M/830711 ltr KANGA, B. K. General Public Utilities GPU Service Corp. B3/07/11. MURLEY, T. E. Region 1, Dffice of Director. Jpp. 19686-063, 24X Fiche: 90-320, 83/07/11, 8307220556.
- 8307220565 LER 83-019/01L-0: on 830610 containment isolation valves BBA-V-004 & 005 discovered opened & closed for decon evolutions w/o valid procedure between 830215-0610 Caused by personnel error. New procedure issues W/830711 ltr. CHAPLIN.S D. KANOA.B.X. General Public Utilities GPU Service Corp. 83/07/11. MURLEY.T.E Region I. Office of Director 4p; 19486: 001 24X Fiche: 30-320, 83/07/11.8307220565.
- 8:307220550 Updated LER 83-004/03x-1 on 830216, while performing 907220500 Updated LER 83-004703x-1 on 830212.0611e performing surveillance on fire sys valves, air intake tunnol sump water level rose approx 1/4 on air intake tunnel floor Caused by failed heat tracing Leaks repaired W/830713 ltr CHAPLIN.S. D. KANGA, B.K. General Public Utilities - OPU Service Corp. 83/07/13. MURLEY.T.E. Region 1. Office of Director. 4pp. 19684:051. 24X Fiche: 50-320, 83/07/13, 8307220550
- 8307210282 LER 83-021/03L-0: on 830616, while performing 12-month surveillance of Firewall-50 fire barrier seals, nine seals found to be nonfunctional Caused by dehydration cracking, no conduit seals, agen pull bares & deformation. W/830718 ltr. CHAPLIN. S.D., KANOA. B.K. General Public Utilities GPU Serv Corp. 83/07/18, MURLEY. T.E. Region 1, 0ffice of Director. 17464: 206. 24% Fiche: 50-320, 83/07/18, 8307210282
- 8307260364 EN-83-045 on 830722 notice of violation & proposed imposition of civil penalties will be issued in amount of \$140.000 Action based on submittal of matl false statement & violation re operator requalification program.
  RDSAND.R., AXELRAD.J. Director's Office. Office of Inspection and Enforcement. 83/07/22. 1p. 19793 COS. 24x Fiche.50-287.83/07/22. 8307260364
- 8307280381 PNG-TMI-83-004: on 830727, util informed TML Program Ofc that 30/28038) PNUMINI-83-008: On 830/27, 5011 Informed INI PRI R Parks & Bechtel reached settlement on R Parks Dept or Labor complaint Neither party will make further public comment other than simultaneous press announcements. BARRETT.L. TML Program Office. B3/07/27. 1p 19796 Fiche: 50-320,83/07/27,8307280381. 19796 099. 24x
- U. Congressional/Executive Correspondence
- 8307060439 Informs that five lists of documents re IMI-2 accident will be compiled per 830607 request PALLADINO.N.J. Commissioners. 83/06/74. UDALL.M.K. House of Rep., Interior & Insular Affairs. 4pp. 19300:153. 24X Fiche: 90-289, 83/06/24. 8307060439

- --8307060443 Ack receipt of NRC 830526 ltr responding to 830427 request for tisfo re forthcoming decision on TM1-1 restart & B&N vs GPU tital record Commission majority response to 830427 ltr inappropriate.

  UDALLIM K. House of Rep. Interior & Insular Affairs 83/06/07. PALLADING.N.J. Commissioners. Ip 19300-157. 24X Fiche 50-287,83/06/24.8307060439
- V Operator Examinations
- B307270327 Advises that revised procedure re-control of exams meets requirements imposed by B30426 partial initial decision. STDLZ. J F Operating Reactors Branch 4 B3/07/13. HUKILL.H D. General Public Utilities GPU Service Curp. 3pp 19812:018. 24x Fiche 50-289,83/07/13,8307270327.
- DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT. UNIT 1

  F. Security, medical, emergency & fire protection plans
- B307140225 Forwards FEMA Region IV rept of observation results from B21208-09 emergency exercise b Georgia Emergency Mgt Agency response. Encourages continued work w/offtite agencies as necessary to resolve open issues O'REILLY, J. P. Region 2. Office of Director. 83/03/25. KELLY, R. J. Georgia Pawer Co. 25pp. 19523:126. 24x Fiche: 50-321, 83/03/25. B307140225.
- 83070A0887 Forwards IE Safeguards Insp Repts 50-321/83-12 & 50-364/83-12 on 830424-28 & natice of violation Notice of violation withheld (ref 10CFR73 21) LEWIS.R C Division of Project & Resident Programs. 83/05/17. KELLY.R. J Georgia Power Co. 2pp. 19238 297. 24X Fiche.50-321.83/05/17.8307060287.
- --B307060299 IE Safeguards Insp Repts 50-32:/83-12 & 50-366/83-12 on 630424-28. Noncompliance moted in area of personnel access control. Details withhold (ref 100FR73 21) HALL, BL Region 2, Office of Director, MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety. 83/05/16 1p. 19238: 299 24X Fiche: 50-321, 83/03/17, 830/060287.
- 8307110173 Releases public version of revised emergency plan cross-reference procedure. FELTON,J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19386-008. 24X Fiche,50-321,83/06/24, 8307110173
- --8307i10176 Public version of Rev 1 to Emergency Plan Cross-Reference Procedure GPND 13.Receipt form encl GUCWALL T Georgia Power Co 63/05/10. Office of Nuclear Reactor Regulation, Director. 3pp 19386:009, 24X Fiche. 50-321, 83/06/24, 8307110173.
- 8307180249 Releases public version of transmittal sheet notifying of change to emergetcy plan implementing procedure. FELTON J. H. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19567-336. 24X Fiche: 50-321, 83/06/24.
- --8307180231 Forwards public version of transmittal sheet notifying of deletion of Emergency Plan Implementing Procedure HNP-8133 NIX.H.C. Georgia Power Co. 83/05/27. Office of Nuclear Reactor Regulation, Director. 2pp. 19567.337 24X Fiche: 50-321/83/06/24.
- 8307140467 Ack receipt of 830516 ltr informing NRC of eteps taken to correct violations noted in IE Insp Repts 90-321/83-13 & 50-366/83-13.

  LEWIS R C. Division of Project & Resident Programs. 83/06/27.

  KELLY.R.J. Georgia Power Co. 1p. 19520:203. 24x

  Fiche: 90-321, 83/06/27, 8307140467.
- --8307140472 Responds to NRC 830520 ltr re violations noted in IE Insp Repts 50-321/83-13 % 50-366/83-13 Corrective actions: carbon filter replaced & critoria for carbon filter testing being evaluated. Results & Schedule will be available by 830714 GUCHAL T. Georgia Power Co. 83/06/16. D'RETLLY, U.P. Region 2, 09fice of Director. 2pp. 19520: 204. 24X Fiche: 50-321, 83/06/27, 8307140467.
- --8307140473 Forwards 1E Insp Repts 50-321/83-13 / 50-346/83-13 on B30324-0423 / notice of violation.

  LEMIS.R.C. Division of Project & Resident Programs. B3/05/20. KELLY.R.J. Georgia Power Co. 2pp. 19520-206. 24X

  Fiche: 50-321, 83/06/27, 8307140467.
- --8307140474 Notice of violation from this on 830326-0423 \* Region 2. Office of Director 83/05/20 lp. 19520:208. 24x Fiche:50-321,83/06/27,8307140467

- --8307140476 IE Insp Repts 50-321/83-13 % 50-366/83-13 on 830326-0423.

  Noncompliance noted:halogenated hydrocarbon & carbon not sampled following extensive control room mods.

  GRIENJAK, R. V. HOLMES-RAY, J. Region 2. Office of Director.

  BROWNLEG, V. L. Division of Project & Resident Programs. 83/05/16.

  4pp. 19520:209. 24% Fiche:50-321,83/06/27,8307140467.
- 8307060346 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-321/83-12 & 30-366/83-12.

  DANCE, H.C. Division of Project & Resident Programs. 83/06/30.

  KELLY,R. J. Georgia Pawer Co. 1p. 19234:178. 24X

  Fiche: 50-321,83/06/30,8307060346.
- --B307060352 Responds to NRC B30517 ltr re violations noted in IE Safeguards Insp Repts 50-321/83-12 \$ 30-366/83-12 Corrective actions withheld (ref 10CFR73.21).

  9UCWALL.T. Georgia Power Co. B3/06/16. O'REILLY, J. P. Region 2, Office of Director. 1p. 19234:179. 24X Fiche: 50-321, 83/06/30, 8307060346.
- 8307220501 Suppls response to Generic Ltr 82-83 re emergency response capability clarifying position re schedule for implementation of guidance in Reg Guide 1.97, Rev 2 Schedule will be developed per NUREG-0737, Suppl 1.

  BECKHAH, J. T. Georgia Power Co. 83/07/18. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19685:149. 24x Fiche: 50-321, 83/07/18, 8307220501.
- 8307290514 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19857:174, 24X Fiche: 50-321, 83/07/19, 8307290514.
- --8307290523 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-4530 re alert operations supervisor & HNP-8002 re radiation exposure limits. Transmittal sheet encl.

  NIX.M.C. Georgia Power Co. B3/06/28. Office of Nuclear Reactor Regulation, Director. 2pp. 19857:175. 24X Fiche: 50-321, 83/07/19, 8307290514.
- --8307290530 Public version of revised emergency plan implementing procedures, including Procedures HNP-4530 re alert operations supervisor & HNP-8002 re radiation exposure limits

  NIX.H. C., ROGERS, W. H. Georgia Pawer Co. 83/05/29, 49pp. 19857; 177, 24X Fiche: 50-321, 83/07/19, 8307290514.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307270039 Forwards Rev 1 to updated FSAR for EI Hatch Nuclear Plant, Units 1 & 2. BECKHAM, J. T. Georgia Power Co. B3/07/22. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19775: 264. 24X Fiche: 50-321, 83/07/22, 8307270039.
- --8307270038 Rev 1 to updated FSAR for Et Hatch Nuclear Plant, Units 1 & 2. # Georgia Power Co. 63/07/31, 1142pp. 19775: 266. 24X Fiche: 50-321, 63/07/22, 8307270035.
- P. Operating license stage documents & correspondence
- 8307140376 Ack receipt of 830802 ltr advising of preliminary results of safety relief valve test program & plans to continue testing. Adjustment of Unit 1 test frequency to be consistent w/Unit 2 acceptable.

  LEWIS.R.C. Division of Project & Resident Programs. 83/03/18, BECKHAM, J. T. Georgia Power Co. 1p. 17523:327. 24X

  Fiche: 50-321, 83/03/18, 8307140376.
- 8307070069 Forwards "Primary Reactor Containment Integrated Leakage Rate Test Rept." NIX.H.C. Georgia Power Co. B3/06/16. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19268:304. 24X Fiche:30-321.B3/06/16.8307070069.
- --8307070072 "Primary Reactor Containment Integrated Leakage Rate Test Rept." 4 Bechtel Corp. 83/02/28 105pp. 19268:305. 24X Fiche: 50-321.83/06/16.8307070069.
- 8307070554 Forwards confirmatory order re commitment to install permanent scram discharge sys mode by 831231 Proposed model Tech Specs also encl.
  STOLZ, J. F. Operating Reactors Branch 4 83/06/24. BECKHAM, J. T. Georgia Power Co. 2pp. 19300: 267. 24X Fiche: 50-321, 83/06/24, 8307070554.

- ~-B307070557 Order confirming licensee commitments to install mods to scram discharge sys by 831231. EISENHUT.D.G. Division of Licensing. 83706/24 Georgia Power Co. 34pp. 19300:269. 24X Fiche:50-321.83706/24.8307070554
- 8307140359 Approves 830606 request to delay submittal of QA program description until 830630.

  LEWIS.R. C. Division of Project & Resident Programs. 83/06/24 GUCWA.L.T. Georgia Power Co. 1p. 19525-227 24x Fiche: 50-321,83/06/24,8307140359.
- B3070B0553 Advises that requirements of TMI Item II.K 3 13, "HPCI/RCIC Initiation Level" met.ltem resolved STOLZ, J.F. Operating Reactors Branch 4. 83/06/27. BECKHAM, J T Georgia Power Co. 4pp. 19365-035 24X Fiche.50-321,83/06/27. 83070B0553.
- B307040270 Requests mod to NRC B30330 order confirming licenses commitments on post-TMI-related issues, allowing extension for implementation of NUREG-0737, Item II. B 3, "Post-Accident Sampling," to B30901.

  QUCMA, L. T. Georgia Power Co. 83/06/28. STOLZ, J. F. Operating Reactors Brench 4, 2pp. 19239:166, 24X Fiche: 50-321, 83/06/28. B307060270.
- B307120014 Advises that return piping for reactor water cleanup sys on both units rerouted via feedwater piping to feedwater noziles.per Section 4.2 of NUREG-0601. Fracture mechanic analysis per Generic Lir 81-11 expected by B30729.
  BECKHAM. J. T. Georgia Power Co. B3/06/30. STCLZ. J. F. Operating Reactors Branch 4. 2pp. 19423:153. 24X Fiche: 50-321, B3/06/30, B307120014.
- B307270170 Forwards revised B30330 order re commitments to implement NUREG-0737 items.extending completion date for Item II.B. 3, "Post-Accident Sampling," to B33091.
  STOLZ, J. F. Operating Reactors Branch 4 B3/07/01 BECKHAM, J. T. Georgia Power Co. 3pp. 19811:146. 24X Fiche: 50-321, 83/07/01, 8307270170.
- --8307270179 Mod of order confirming licenses commitments on post-TMIrelated issues, extending completion date for Item II.8.3, "Post-Accident Sampling," to 830901. EISENNUT.D.G. Division of Licensing. 83/07/01. Georgia Power Co. Spp. 19811:149. 24X Fiche:50-321,83/07/01,8307270170.
- 8306270397 Generic Ltr 83~26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re swrveillance intervals in STS Svc list encl.
  EIBENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307090169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for CL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 63/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307180424 Notification of 830713 meeting w/util.consultants & GE in Bethesda.MD to discuss util arguments re NRC request for Tech Specs assuring operability of plant high water level trip & turbine bypass sys.

  RIVENBARK.G. Operating Reactors Branch 4. 83/07/11. STGLZ.J.F. Operating Reactors Branch 4. 2pp. 19566:331. 24X

  Fiche: 50-321,83/07/11,8307180424.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140292 Requests that liquid samples spiked w/radionuclides.be analyzed for tritium.Sr-89 & Sr-90 content within 40 days of receipt of samples.Spiked samples will be sent annually as part of routine insp program.

  LEWIS.R. C. Division of Project & Resident Programs. 83/02/07. KELLY.R. J. Georgia Power Co. 19. 1925:134. 24X Fiche: 50-321.83/02/07.8307140292
- 8307060287 Forwards IE Safeguards Insp Repts 30-321/83-12 & 50-366/83-12 on 830424-28 & notice of violation Notice of violation withheld (ref 10CFR73.21).
  LEWIS,R.C. Division of Project & Resident Programs. 83/05/17. KELLY,R.J. Georgia Power Co. 2pp. 19238.297. 24X Fiche: 50-321,83/05/17,8307060287.

- --8307060299 IE Safeguards Insp Repts 50-321/83-12 & 50-366/83-12 on 830424-28. Noncompliance noted in area of personnel access control Details withheld (ref 100FR73 21) HALL-B.E. Region 2. Office of Director MCGUIRE.D R. Division of Emergency Preparedness & Materials Safety, 830/03/16. 1p. 19238: 299. 24X Fiche: 50-321.83705/17-8307060287.
- B307140243 Responds to 1E Builetin 80-25. "Operating Problems W/Target Rock Safety Relief Valves at PWRs." High pressure relief valve & high pressure alaim sys installed & dripuell pneumatic sys pressure switches reset BECKHAM. J. T. Georgia Power Co. 83/06/24. GYRE/LLY, J. P. Region 2, Office of Director. 2pp. 19523:061. 24X F)che 50-321,83/06/24, G307140243.
- 8307140467 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 90-321/83-13 & 90-364/83-13.

  LEWIS,R.C. Division of Project & Resident Programs. 83/06/27 KELLY,R.J. Georgia Power Co. ip 19520 203. 24x Fiche: 50-321/83/06/27,8307140467.
- --B307140472 Responds to NRC B30520 ltr re violations noted in IE Insp Repts 50-321/83-13 & 50-364/83-13. Corrective actions: cerbon filter replaced & criteria for carbon filter testing being evaluated. Results & schedule will be available by 830714. GUCWALLT. Georgia Power Co. 83/06/16. GTREILLYJUP. Region 2, Office of Director. 2pp. 19520: 204. 24X Fiche: 50-321, B3/06/27, B307140467.
- --8307140473 Forwards IE Insp Repts 50-321/83~13 & 50-326/83-13 on 830326-0423 & notice of violation. LEWIS R.C. Division of Project & Resident Programs. 83/05/20. KELLY.R J. Georgia Power Co. 2pp 19520:206. 24X Fiche:50-321,83/06/27,8307140467
- --B307140474 Notice of violation from insp on 830326-0423. \* Region 2, Office of Director. 83/05/20. lp. 17920:208. 24X Fichs:50-321,83/06/27,8307140467.
- ~~B307140476 IE Insp Repts 50-321/B3-13 5 50-366/83-13 on B30326-0423.
  Noncompliance noted halogenated hydrocarbon 5 carbon not sampled following extensive control room mods CRLENJAK,R.V., HOLMES-RAY,J Region 2. Office of Director.
  BROWNLEE,V.L. Division of Project 5 Resident Programs. 83/05/16.
  4pp. 19520:209. 24X Fiche:50-321,83/06/27,8307140467.
- 8307060346 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-321/83-12 & 50-364/83-12

  DANCE, H.C. Division of Project & Resident Programs 83/06/30

  KELLY, R.J. Georgia Fower Co. 1p. 19234:178. 24X

  Fiche: 50-321, 83/06/30, 8307060346.
- --B307060352 Responds to NRC 830517 ltr re violations noted in 1E Safeguards Insp Repts 90-321/83-12 & 50-366/83-12 Corrective actions withheld (ref LOCFR73.21). GUCWA.L.T. Georgia Power Co. 83/06/16. D'RE[LLY, J.P. Region 2, Office of Director. 1p. 19234:179. 24X Flohe.50-321.83/06/30.
- 8304270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563.293. 24X Fiche 90-000.83/07/11.8306270401
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid " Svc list one). JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12 Consolidated Edison Co. of New York, Inc. 141pp. 19563.153 24X Fiche 50-000,83/07/12,8306270404
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive 1-125 & 1-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche 50-000.83/07/14.8306270406.
- R. Periodic operating reports & related correspondence
- 8307190004 Monthly operating repts for June 1983. W/830710 ltr. NIX.H.C., REDWANZ.F.J. Georgia Power Co. 83/07/10 Director's Office Office of Inspection and Enforcement. 42pp. 19635:058. 24x Fiche: 50-321, 83/07/10, 8307190064.

- S. Reportable occurrences. LERs & related correspondence
- 8307120579 LER 83-056/03L-0 on 830523 & 0669.RCIC trip & throttle valve failed to trip upon signal during Procedure HNP-1-3415. Caused by component failure Trip & throttle valve repaired by lubricating stem W/830616 ltr TIPPS.S. B., NIX.H.C. Georgia Power Co. 83/06/16. D'REILLY, J.P. Region 2. Office of Director. Spp. 19432-156. 24X Fiche: 50-321, 83/06/16. 8307120579
- 8307120586 LER 83-054/03L-0: on 830530, during Drywell Fission Products Monitors Calibr Procedure HNP-7408, fission monitoring sys recorded no flow, Caused by closed solenoid valve on discharge line Valve opened & repaired W/830621 ltr. IIPPS, S. D., NIX, H. C. Georgia Power Co. 63/06/21, 0'REILLY, J. P. Region 2, Office of Director. App. 19432 137, 24x Ficha: 50-321, 83/06/21, 8307120586.
- 8307150121 LER 93-051/03L-0: on 830607.loop B core spray test valve E21-F0158 failed to close when returning loop to svc. Caused by torque switch failure. Switch replaced W/830628 ltr.

  TIPPS.E.B., NIX.H.C. Georgia Power Co. B3/06/28. G/REILLY, J.P. Region 2, Office of Director 4pp. 19536.232. 24X Fiche: 50-321.83/06/28.8307150121.
- B307250293 LER B3-059/03L-O:on B30610, personnel received fission product monitor high/low flow alarm & found monitor w/no drywell sample flow.Caused by personnel lifting whre from coil of K5 relay. Wire replaced W/B30708 ltr.
  TIPPS, S. B. NIX,H. C. Georgia Power Co. B3/07/08. D'REILLY, J. F. Region 2, Office of Director App 19705:271. 24X
  Fiche: 50-321,83/07/08,8307250293.
- 8307250191 LER 83-061/03L-0: on 830615, stendby gas treatment sys filter inlet damper & exhaust fan discharge damper would not open. Gaused by blown power supply fuse Fuse replaced W/830712 ltr.

  TIPPS.S.B., NIX.H.C. Georgia Power Co. 83/07/12. D'REFLLY, J.P. Region 2. Office of Director. 4pp. 19705 350. 24X

  Fiche: 50-321,83/07/12,8307250191.
- 8307230214 LER 83-062/03L-0: on 830615, safety relief valves 1821-F013 A; B & K failed to open during reactor scram Caused by component failure. Pilot assemblies replaced for valves A & K & pilot valve & solenoid replaced on valve B.W/830714 ltr. TIPPS,S.B., NIX,W.C. Georgia Power Co. 83/07/14, 0'REILLY, J.P. Region 2, Office of Director, 4pp 19705-337 24X Fiche: 50-321, 83/07/14, 8307250214.

### V. Operator Examinations

- 8307140319 Informs that written plant oral & simulator operator & tenior operator licensing exams scheduled for while 630926. Approved ref math required by 830726 Applications must be submitted 60 days prior to exam.

  DANCE, H. C. Division of Project & Resident Programs. 83/06/24.

  BECKHAN, J. T. Georgia Power Co. 3pp. 19525:114 24X

  Fiche: 50-321, 83/06/24, 8307140319.
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

  A. Application/construction stage documents > correspondence
- 8307010112 Forwards summary of evaluation on environ qualification confirming grevious conclusions. Nonsafety-related electric equipment evaluated to ensure that failure under postulated accident conditions could not prevent intended function. SMITH.J. L. Long Island Cighting Co. 83/06/24. DENTON.H.R. Office of Nuclear Reactor Regulation. Director Spp. 19169:218. 24X Fiche:50-322,83/06/24,8307010112.
- B307110620 Notification of significant licensee 830630 meeting w/util & Suffolk County,NY in King of Prussia.PA to discuss emergency diesel performance analysis MCCABE.E.C. Division of Project & Resident Programs. 83/06/26. Division of Project & Resident Programs. 83/06/26. Piche: 50-322, 83/06/26, 8307110620.
- 8307010004 Advises that based on 830607 presentation in which both generic & plan-specific aspects of vacuum breaker test program presented.NRC concern re bypass leatage resolved. SM17H.J.L. Long island Lighting Co. 83706/27. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19169:079. 24X

- 8307050091 Fowards revised responses to Acceptance Review Ruquests 212.14,212.76,212.104,223.38,223.72 & 223.73, re Level 8 instrumentation, reactor pump trip electrical schematics & rod sequence control, to be included in next FSAR update. SMITH.J.L. Long Island Lighting Co. 83/06/28. DENTON.H.R. Offic of Nuclear Reactor Regulation, Director. Sipp. 19221:300. 24x Fiche:50-322,83/06/28,8307050091.
- 8306270395 Generic Ltr 83-24 to all BWR applicants for GL & helders of GLs for Grand Gulf.LaSalle & Susquehanna re TMI Task Action Plan Item I G. I. "Special Low Power Testing & Training & Recommendations for BMRs." Svc list encl EISENHUT.D. G. Division of Licensing 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche.50-000.83/06/29, 8306270395.
- 8307010176 Forwards Rev 1 to "Independent Design Review, Shoreham Nuclear Power Plant." Final classification of listed items included.
  LANDERS, D.F. Teledyne Engineering Services. 83/06/29. DENTON, H. Office of Nuclear Reactor Regulation, Director. 9pp. 19168:300, 24X Fiche: 50-322, 83/06/29, 8307010176.
- ~-8307010179 Rev 1 to "Independent Design Review, Shoreham Nuclear Power Plant."

  BARRON, L. E., FLAHERTY, J. A., CANDERS, D. F. Teledyne Engineering Services. 83/06/27. Bpp. 19168: 301. 24X Fiche: 50-322, 83/06/29, 8307010176.
- 8307050038 Describes proposed conceptual design for mod to core spray injection valve low pressure permissive,per 830218 commitment Mod should resolve NRC concerns reoverpressurization of core spray sys piping.

  SMITH.J.L. Long Island Lighting Co. 83/06/29. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19220:314. 24X Fiche: 50-322,83/06/29,8307050038.
- 8307070066 Forwards revised FSAR Table 3.11.1-2 "Environ Qualification for Class IE Balance of Plant (BOP) Equipment Contained in BOP Specs." Table will be included in Aug 1983 amend SMITH.J. L. Long Island Lighting Co. 83/06/30. 055370514.5.
- SMITHJ L. Long Island Lighting Co. 83/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 9pp. 19293:106. 24X Fichs: 50-322, 83/06/30, 8307070066
- 8307070094 Forwards draft revs to FSAR Chapters 13.1, 13.4 & 17.2 reflecting organizational changes. Revs will be incorporated into final FSAR rev prior to scheduled fuel load date in Aug 1983.

  SMITH, J.L. Lung Island Lighting Co. 83/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 33pp. 17269:053, 24X Fiche: 50-322, 83/06/30, 8307070094.
- 8307080398 Discusses evaluation of conservative pressure/temp domain during normal plant operation.w/o exceeding peak calculated drywell pressure for design basis LOCA Meeting proposed to address Tech Spec 3/4.6.1.6. SMITH.J.L. Long Island Lighting Co. 83/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation. Director 6pp. 19349:309, 24X Fiche: 50-322, 83/06/30, 8307080398.
- 8307080561 Transcript of Commission 830630 affirmation, discusion & vote in Washington, DC re SECY-83-255A on low power OL for Shoreham & ALAB-714. Pp 1-8.

  \* Commissioners. 83/06/30. 12pp. 19364: 295. 24X Fiche: 50-322, 83/06/30, 8307080561.
- 8307200002 Amend 48 to application for QL/consisting of Rev 30 to FSAR, correcting discrepancies identified by plant configuration review program.
  SMITH.J.L. Long Island Lighting Co. 83/06/30. DENTUN, H.R. Defice of Nuclear Reactor Regulation, Director 4pp. 19652:001. 24X Fichs: 50-322, 83/06/30, 8307200002.
- B307070015 Advises that results of facility specific local to bulk temp study will be submitted 90 days after LaSalle submittal of generic test program.

  SMITH.J. Long Island Lighting Co. B3/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director 2pp. 19293:226. 24X

  Fithe:50-322,83/07/01.8307070015.
- B3070B01B4 Forwards executive summary of final rept. "Independent Design Review for Shoreham Nucler Power Station." Final rept will be available end of Jul.Related correspondence. EARLEY.A.F. Hunton & Williams. EARLEY.A.F. Long Island Lighting Co. 83/07/05. BRENNER.L. CARPENTER.J. H. MORRIS,P.A. Atomic Safety and Licensing Board Panel. 43pp 19351:356. 24X Fich: 50-322.83/07/05.8307080184.

- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors resurveillance intervals in STS Svc list encl EISENHUT, D.G. Division of Licensing 83/07/06 Consolidated Edison Co. of New York, Inc. 1app 19669-254 24x Fiche 50-000,83/07/06,8307060329
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re-required actions based on generic implications of Salem ATMS avents Svc list encl. EISENNUT. D. G. Division of Licensing #3707708 Consolidated Edison Co. of New York. Inc. 38pp | 19669.269 | 24x | Fiche: 50-000, 83/07708, 8307080169
- 8307140200 Forwards Vols 1-4 to final PRA Pept PRA logic model will be maintained in state reflecting current plant design & new technological developments in field of PRA techniques & data base applications.

  SMITM.J.L. Long Island Lighting Co. 83/07/11. DENTON.H.R. Office of Nuclear Reactor Regulation. Director App. 19514.259 24X Fichs: 90-322,83/07/11,8307140200.
- ---B307140205 Vols 1-4 to "Final PRA Shoreham Nuclear Power Station, Unit 1." \* Science Applications, Inc. SAI-572-83-PA-01 83/04/24, 2058pp. 19514:264, 24x Fiche, 50-322,83/07/11,8307140200.
- 8307140356 Advises that util has signed contract w/ODE per Generic Ltr 83-07 re requirements of Nuclear Woste Policy Act SMITH/J L. Long Island Lighting Co 83/07/11 DENTON/H.R. Office of Nuclear Reactor Regulation, Director 2pp. 19525:225. 24X Fiche: 50-322,83/07/11,8307140356
- --8307260525 Forwards WT Russell 830662 momo providing independent assessment & recommendations to resolve WH Contan differing prof opinion re says interaction (Unresolved Safety Issue A-17) & safety classification. Recommendations adopted. DENTON-H.R. Diffice of Nuclear Roactor Regulation. Director. 83/07/11. SPEIST.P. Division of Safety Technology. 4pp. 19782: 243. 24% Fiche: 50-000, 63/07/11. 8307260516.
- --8307110305 Informs that independent assessment of issues raised in JH Conran differing prof opinion conducted, per 830415 request Issues A & B essentially same fundamental issue -- mgt of unresolved Safety Issue A-17 RUSSELL/M T. Systematic Evaluation Fragram Branch. 83/06/22. DENTON, H.R. Office of Nuclear Reactur Regulation, Director. 7pp 19782: 247. 24X Fiche: 50-000, 83/07/11, 8307260516.
- --8306080379 Submits statement of differing prof opinion recertain aspects of existing policy & practice in areas of sysinteraction & safety classification Excerpt from statement of mgt views to Shoreham board encl. CONRAN.J.H. Reliability & Risk Assessment Branch. 83/03/31. COFFMAN.F.D. Reliability & Risk Assessment Branch. 55pp. 19782 254. 24X Fiche: 50-000.83/07/11.8307260316.
- ~-B307260940 Forwards transcript of presentation to American Stds Associated hoc committee on nuclear research re NRC statistics.

  RUBINSTEIN.D. Applied Statistics Branch 81/02/04. ABRAMSON, L.,
  BASSETT, M., ABELL, T., NRC NO Detailed Affiliation Civen. Bpp.
  19782-317. 24X Fiche: 50-000, 83/07/11, 8307260516.
- --B307260545 Draft "Random Thoughts on Uncertainties, Risk Analysis & Nuclear Regulation."
  ROBINSTEIN,D. NRC -- No Detailed Affiliation Given. B1/10/26.
  12pp. 19782: 325. 24X Fiche: 50-000-83/07/11, 8307260516.
- ---B304140030 Forwards JH Conran B30331 memo & attachments re differing prof opinion. Memo forwarded to ASLB hearing Contention 7B.

  Differing prof opinion should be expedited per Manual Chapter 4125. W/o encl.

  SPEIS.T.P. Division of Safety Technology. B3/04/05. DENTON, H.R. Office of Nuclear Reactor Regulation. Director 1p. 19783 014.

  24X Fiche: 50-000. B3/07/11. B307260916.
- --8304200084 Concurs w/k suppls F Coffman comments on JH Conran 9303211 differing prof opinion re Unresolved Safety Issue A-17. New A-17 program plan adequate basis for proceeding w/sys interaction issue.

  SPEIS.T.P. Division of Safety Technology. RDWBOME.F.H. Assistant Director for Technology Review. THADANI.A. Reliability & Risk Assessment Branch. 83/04/14 DENTON.H.R Office of Nuclear Reactor Regulation, Director. 4pp. 19783:015. 24X Fiche 50-000.83/07/11.8307260514.

- --8305050085 Comments on JH Conran 830331 differing prof opinion (DPO) re sys interaction program topic of Unresolved Safety Issue A-17.
  - A-17. COFFMAN.F D. Reliability & Risk Assessment Branch. 83/04/13. THADANI.A.C. Reliability & Risk Assessment Branch. 4pp. 19783:019 24X Fiche 50-000/83/07/11/8307260516.
- --8309060655 Comments on JH Connent differing prof opinion on Issue C.
  "Insufficient Priority Given to Resolution of Known Safety
  Classification Problems." Addl action needed to resolve
  issue generically.
  MATTSON.R.J Division of Systems Integration (post 811005).
  VOLLMER.R.H Division of Engineering. B3/04/13. DENTON.H.R.
  Office of Nuclear Reactor Regulation, Director. 3pp. 19783:023.
  24X Fiche: 50-000.83/07/11.8307260516.
- --8307240563 Designates MT Russell responsible manager for independently assessing issues raised by JH Conran differing prof opinion.

  Assessment should be completed by 830504.

  DENTON,H.R. Office of Nuclear Reactor Regulation, Director.

  83/04/15. RUSSELL,M.T. Systematic Evaluation Program Branch. 1p.
  19783:026. 24X Fiche:50-000,83/07/11,8307240516.
- --8304270394 Requests written comments on manager views expressed in 830413 % 14 memos re 830331 differing prof opinion by 830425 Relevant documents also requested. RUSSECLL.M.T. Systematic Evaluation Program Branch. 83/04/18. CONRAN, J.H. Reactor Risk Branch. 1p. 19783:027. 24X Fiche: 50-000,83/07/11,8307780936
- ---B3060803B3 Recommends board notification be issued re JH Conran written statement of differing prof opinion on sys interaction issue. FUNCHES.J.L. Planning & Program Analysis Staff. 93/04/21. EIBENHUT.D.G. Division of Licensing. 1p. 19783:028. 24X Fiche:50-000,83/07/11,8307260516.
- --B307260372 Forwards JH Conran differing prof opinion re sys interaction issue & related info Cognizant boards will be notified through board notification procedure. W/o brol.

  DENTON, H. R. Office of Nuclear Reactor Regulation. Director.

  B3/04/26. COTTER, B. P. Atomic Safety and Licensing Board Panel.

  ROSENTHAL, A. S. Atomic Safety and Licensing Appeal Panel.

  19783:027. 24X Fiche: 50-000, 83/07/11, 8307260516.
- --8309050338 Forwards relevant documents per 830418 request re differing prof opinion of JH Conran re Unresolved Safety Issue A-17 & NUREG/CR-1321.

  CDFFMAN,F.D. Reliability & Risk Assessment Branch. 83/04/28.
  RUSSELL.W.T. Systematic Evaluation Program Branch. 2pp. 19783: 030. 24X Fiche: 90-000, 83/07/11, 8307260916.
- --8305260333 Comments on status of differing prof opinion. NRR decided to provide Boards, via usual notification process of J Comran & NRR views.
  RUSSELL-W.T. Standardization & Special Projects Branch. B3/05/05. CONRAN, J.H. Reliability & Risk Assessment Branch. 1p. 19783: 032. 24X Fiche: 50-000, 83/07/11, 8307260516.
- --8304290048 Requests that Commission & recipients of Board Notifications 83-17 & 83-44 be provided w/Suffalk County 830323 testimony on Contention 7B.

  LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips.

  LETSCHE, K. J. Suffalk County, NY. 83/04/21 RAMSON, R. J. Hearing Branch 4. 2pp. 19783:295. 24X Fiche: 50-000, 83/07/11, 8307260516.
- --8306080367 Forwards comments on mgt views & positions on sys interaction per differing prof opinion in response to 830418 & 0505 memos. Excerpts from Suffolk County 830509 submittal & proposed request for addl info re Byran/Braidwood encl. CONRAN.J.H. Reliability & Risk Assessment Branch. 83/05/25. RUSSELL.W.T. Systematic Evaluation.Program Branch. 74pp. 19783:033. 24X Fiche: 50-000.83/07/11.8307260516.
- --8306080373 Comments on prediction intervals per J Ahearne 821102 memo. Prediction intervals do not provide panacea to risk analysis problems, yet merit exploration as tool in limited arsenal of risk assessment methodologies. Related info encl. RUBINSTEIN.D. Reliability & Risk Assessment Branch. 83/03/09. RUBINSTEIN.D. Reliability & Risk Assessment Branch. 37pp. 19783:203. 24X Fiche: 50-000.83/07/11.8307260516
- --8306080387 Discusses 830421 ltr based on belief that Board Notification 83-44 constituted violation of 10CFR2.780 re ex parte communications.NRC does not consider board notification to be in violation.

  RAMBON.R.J. Office of the General Counsel. 83/05/11.

  LETSCHE.K.J. Kirkpatrick. Lockhart. Hill, Christopher & Phillips.

  1p. 19783.297. 24X Fiche: 50-000.83/07/11.8307260916.

- --B304080390 Responds to B30421 request for explanation of two sentences contained in Board Notification 83-44 ve Unresolved Issue A-17 re sys interactions.
  EISENUTI,D.C. Division of Licensing 83/05/04. LETSCHE,R.J. Kirtpatrick, Lockhart, Hill. Christopher & Phillips. 3pp. 19783:301. 24X Fiche: 50-000,83/07/11.8307240516.
- --8306080394 States reason for declining to concur w/Congressman Downey
  ltr re achedules & resource allocation to Unresolved Issue
  A-17. Significant differences exist between personal views
  & views of Reliability & Risk Assessment Branch.
  CONRAN.J.H. Reliability & Risk Assessment Branch.
  COFFMAN.F.D. Reliability & Risk Assessment Branch.
  19783:304. 24X Fiche: 50-000.83/07/11.8307260516.
- --8307190481 Forwards documents containing history of resources assigned to Unresolved Safety Issue A-17. including organizational & personnel changes, per 830616 ltr. Historical summary of program planning also encl.
  DIRCKS,M.J. Office of the Executive Director for Operations.
  93/05/10. DDMNEY,T.J. House of Rep. 5pp. 19783:305. 24X
  Fiche: 50-000,83/07/11.8307260316.
- ~~8307260381 Discusses Board Notification 83-44 re differing prof opinion concerning safety interaction (Unresolved Safety Issue A-17. All boards & Commission considered concerns raised in 830209 affidavit resolved.

  CUNRAN.J. NRC No Detailed Affiliation Given. 83/04/20.

  CUFFAN.F. NRC No Detailed Affiliation Given. Ip. 19783: 294.

  24X Fiche: 50-000, 83/07/11, 8307260516.
- --8307260594 Approves request for 30-day extension to complete evaluation of JH Conran differing prof opinion.

  DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 83/05/27. RUSSELL, N.T. Systematic Evaluation Program Branch. Ip. 19783:311. 24X Fiche: 50-000, 83/07/11, 8307260516.
- 8307190002 Forwards HR Denton 830711 memo resolving UH Conran differing prof opinion re potential safety significance of lack of progress in resolving Unresolved Safety Issue A-17. "Sys Interaction."

  RAMBON.R.J. Hearing Branch 3. 83/07/14 BRENNER.L. MORRIS.P.A.. CARPENTER.J.L. Atomic Safety and Licensing Board Panel. 11pp. 19635:036. 24% Fiche: 50-322.83/07/14.8307190002.
- 8307200012 Confirms agreements reached during 830622 telcon re cables for low energy lighting fixtures. Redundant circuit protection device (fuse) will be sized & located to ensure no credible faults can damage Class IE cables. SMITH.J.L. Long Island Lighting Co. 83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 17647:049. 24X Fiche: 50-322,83/07/14,8307200012.
- 8307200087 Forwards encis to Teledyne Engineering Svcs 830712 itr to NRC re independent design verification program Encis unavailable when itr sent on 830712. Certificate of Svc enci. BDRDENICK, D. M. Alearing Branch 3. 83407718. BRENNER, L., FERGUSON, G. A., MORRIS, P. A. Atomic Safety and Licensing Deard Panel. 40pp. 19647:075. 24X Fiche 50-322,83707718,8307200089.
- 8307250592 Notification of 830720 meeting w/util in Wading River.NY to discuss applicant staffing & qualifications.
  CARUSO,R. Licensing Branch 2. 83/07/18. SCHWENCER.A. Licensing Branch 2. 4pp. 19718:059. 24X Fiche:50-322.83/07/18.8307250592.
- 8307250477 Provides description of mods to portion of reactor vessel water level measurement sys & ECCS initiation logic.based on agreement reached during ASLB hearings.

  SMITH. J. L. Long Island Lighting Co. 83/07/19. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. App. 19701:201. 24X Fichs: 50-322,83/07/19.8307250477.
- 8307280127 Notification of 830720 mosting w/util & Suffolk County in King of Prussia.PA to discuss emergency dieset cylinder head cracking. HCCABE.E. Region I, Office of Director. 83/07/19. Region I, Office of Director. 2pp. 19826:036. 24X Fiche:50-322,83/07/19, 8307280127.
- 8307280100 Advises that util 930630 ltr re Tech Spec trip setpoints inadvertently assigned incorrect SNRC number Correct number should be SNRC-927.

  SMITH.J.L. Long Island Lighting Co. 83/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19791:183. 24X Fiche: 50-322.83/07/20.8307280100.

- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8307050256 Forwards monthly status of equipment summary list, including balance of plant \$ NSSS equipment to resolve SER Issue 8 redynamic qualification SMITH.J.L. Long Island Lighting Co. 83706727 DENION, H.R. Office of Nuclear Reactor Regulation. Director 52pp 19197-159. 24x Fiche: 80-322,83706727,8307090256
- B307200141 Forwards Rev 5 to "Environ Gualification Rept for Class IE Equipment for Shoreham Nuclear Power Station Unit 1." in effort to resolve SER Outstanding Issue 9.

  SMITH. J.L. Long Island Lighting Co. B3/05/27 DENTON, M.R. Office of Nuclear Reactor Regulation. Director. 2pp 17648, 155. 24X

  Fiche: \$0-382,83/06/27,8307200141
- --8307200145 Rev 5 to "Environ Qualification Rept for Class IE Equipment for Shoreham Nuclear Power Station Unit 1." \* Long Island Lighting Co 83/06/27. 571pp. 19648:157. 24X Fiche: 50-322, 83/06/27, 8307200141
- 8307050031 Forwards info completing resolution of three generic items of concern re-Dutstanding Issue 8 of Suppl 3 to SER covering balance of plant equipment, fatigue testing & Category I equipment change records.

  SHITH, U.L. Long Island Lighting Co. 83/06/28 DENTON.H.R. Office of Nuclear Reactor Regulation, Pirector 114pp. 19193:197. 24X Fiche: 50-322,83/06/28,8307050031.
- B307050274 Forwards revised responses to Requests 112.6, 112 9, 223.10 & 223.69 re dynamic qualification test results/pump 5 valve operability tests to resolve SER Dutstanding Issue 8. Rev will be included in next FSAR rev expected Aug 1983. SMITH, U.L. Long Island Lighting Co. B3/06/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 35pp. 19220:067. 24X Fiche: 50-322, 83/06/29, 8307050274.
- 8307080269 Forwards justification for interim operation for equipment which may not be fully qualified at 830831 scheduled fuel load per SER Outstanding Item 8 SMITH.J.L. Long Island Lighting Co. 83/06/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 16pp. 19352:092. 24X Fiche: 50-322, 83/06/30, 8307080269.
- F. Security medical, emergency & fire protection plans
- B307270034 Forwards Rev & to security plan Rev withheld (ref 10CFR73.21).

  MUSELER, W. J. Lung Island Lighting Co. B3/07/19. DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp. 19749; 324. 24X Fiche: 50-322, 83/07/19. 8307270034.
- 8307280075 Forwards preliminary datalled control room design review program plan, per 830414 commitment.

  SMITH, J. L. Long Island Lighting Co. 83/07/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 19790:249. 24X Fiche: 50-322, 83/07/20, 830/280075.
- ---B307280081 "Detailed Control Room Design Review Program Plan for Shoreham Station." \* General Physics Corp. 83/07/19 Long Island Lighting Co. 69pp. 19790:251: 24X Fiche. 50-322, 83/07/20, 8307280075.
- 8307260049 Forwards NRC 830601 & 17 ltrs to FEMA requesting FEMA findings b determinations on emergency plans.
  BORDENICK, B.M. Hearing Branch 3. 63/07/25. LATHAM S.B. Twomey, Latham b Shea. 4pp 19727:351. 24X Ficha 50-322
- 8307290008 Forwards NRC 830722 ltr to FEMA re util transition plan.W/o encl BORDENICK, B.M. Hearing Branch 3 83/07/28, LATHAM, S.B. Twomey, Latham & Shea 2pp. 19815: 355. 24x Fiche. 50-322, 83/07/28, 8307290008.
- G. Adjudicatory correspondence
- 8306190383 Reply to Suffolk County 830531 response to NRC & util oppositions to County 830502 mution & 830510 addendum reproposed emergency diesel generator contention. Certificate of Svc encl. Related correspondence.

  IRWIN.D.P. Long Island Lighting Co. IRWIN.D.P. Hunton & Williams. 83706707. Atomic Safety and Licensing Board Panel. 27pp. 18847:204. 24x Fiche: 50-322,83706707,8306150383.
- B307030180 Adopts Suffolk County answer & apposition to util motion for low-power OL & contentions.

  LATHAN, S. B. Twomey, Latham & Shea, LATHAM, S. B. Southampton, NY, B3/06/27 MORRIS. P. A., CARPENTER, J. H., BRENNER, L. Atomic Safety and Licensing Appeal Panel. 1p 17178; 362, 24% Fiche: 50-322, 83/06/27, 8307050180.

- 8307050261 Requests to submit written limited appearance statement for probability conference. PRICE-N C. Affiliation Unknown. 83/06/28. NRC No Detailed Affiliation Given. 1p. 19197:143. 24x Fiche 50-322,83/06/28,8307050261.
- 8307050246 Joint compilation of settlement agreement obligations per 830201 request. List of obligations made under settlement agreements & resolution of Phase I emergency planning contentions encl. Certificate of Svc encl.

  REPKA, D. A. Hearing Branch 3. IRWIN, D.P. Long Island Lighting Co. LETECHE, M. J. Suffolk County, NY. 83/04/28, 39pp. 19197:104. 24 Fiche: 90-322,83/04/28,8307050246.
- 8307050046 Motion to defer Commission action on certified question resemengency planning until views of parties heard. Since no adequate offsite emergency preparedness exists or planned, low-power OL issuance futile. Certificate of Syc encl.
  DYNNER.A.R. Suffolk County, NY. DYNNER.A.R. Kirkpatrick, Lockhart.
  Hill. Christopher & Phillips. 83/06/27. Commissioners. lipp.
  19192:164. 24X Fiche: 50-322.83/06/29.8307050046.
- 8307050067 Opposes NRC proposed issuance of order permitting util to operate plant at low power w/o workable offsite emergency response plan.
  COHALAN.P.F. Suffolk County, NY. 83/06/29. PALLADINO, N. J., OILINSKY, V., ASSELSTINE, J. M. Commissioners. 2pp. 19192:147. 24) Fiche: 80-322, 83/06/29, 8307050067.
- 8307060224 Requests to make limited appearance statement at 830714 hearing in Hauppauge,NY.
  RICHARD,M.E. Affiliation Unknown. 83/06/27. Office of the Secretary of the Commission. 1p. 17237:361. 24X
  Fiche: 50-322,83/06/27,8307060224.
- 8307070203 Response opposing Citizens for Orderly Energy Policy, Inc B30614 petition to intervene Criteria for late filing not met. Substantive interests can be protected through limited appearance statements. W/Certificate of Svc.
  LATHAM. S. B. Southampton, NY. B3/06/29. Atomic Safety and Licensing Board Panel. 14pp. 19269-274. 24X Fiche: 50-322. 83/06/29, 8307070203.
- B30701006B Forwards list of specific mods to draft emergency planning contentions which might eliminate portion of redundancy. Encl listing does not address propriety of contentions, defects in form or other possible objections.

  REPKA, D. A. Hearing Branch J. B3706/30 LETSCHE, K. J. MCMURRAY, C. M. Kirkpatrick, Lockhart, Hill. Christopher & Phillips. DOUGHERTY, J. Dougherty, J. B. 6pp. 19171-121. 24X Fiche: 50-322, B3706/30. B30701006B.
- 8307050115 Order CLI-83-17 accepting ASLB 830420 certification of issue re issuance of low-power OL Uncertainty re util compliance w/emergency planning requirements does not bar issuance of low-power OL. CHILK.S.J. Commissioners. 83/06/30. 8pp 19220:025. 24X Fiche: 50-322.83/06/30.8307050115.
- B307090192 Answer opposing util B30429 motion to defer Commission action. Moves to strike PF Cohalon itr. Motion is mere delaying tactic. Certificate of Svc sncl.
  REVELEY, W. T. Long Island Lighting Co. REVELEY, W. T. Hunton & Williams. B3706/30. Commissioners. Spp. 19199: IB9. 24X Fiche: 30-322,83706/30.8307050192.
- B3D7040167 Requests to make limited appearance statement at B3D713 & 14 prehearing conference in Hauppauge, NY.
  LATHAM.K.L. Affiliation Unknown. B3/07/01. Office of the Secretary of the Commission. 1p. 19249-189. 24X Fiche: 50-322, 83/07/01, 8307040167.
- 8307070192 Forwards util requests for relief from ASME Section XI inservice tosting program requirements for check valves.

  Nature of relief, justifications %/or alternate testing provided for each request.Related correspondence.
  FLANAGAN.D.D. Hunton & Williams. 93/07/01. BRENNER, L.,
  MORRIS.F.A., CARPENTER, J.H. Atomic Safety and Licensing Board Panel.
  24pp. 19269:176. 24X Fiche: 50-322,83/07/01,8307070192.
- 8307080184 Forwards executive summary of final rept. "Independent Design Review for Shoreham Nucler Power Station." Final rept will be available end of Jul.Related correspondence. EARLEY.A.F. Long Island Lighting Co. 83/07/05. BRENNER.L. CARPENTER.J.H. MORRIS.P.A. Atomic Safety and Licensing Board Panel. 43pp. 19351:355. 24X Fiche: 50-322,83/07/05,8307080184.
- B307080194 Proposed schedule for resolution of amergency diesel generator cylinder head cracking issue per ASLB 830622 memorandum & order. Long-term effects of vibration will be resolved informally. Certificate of Svc enci. EARLEY. A. F. Long Island Lighting Co. 83/07/06. 6pp. 19351: 350. 24X Fiche: 50-322. 83/07/06. 8307080194.

- B307080423 Concurs w/proposed B30722 target date for determining whether diesel generator head cracking issues amenable to settlement or requires litigation REIS.E.J. Hearing Branch 3. B3/07/06. BRENNER.L., MORRIS.P.A., CARPENTER.J.L. Atomic Safety and Licensing Board Panel. 2pp. 19347.267. 24X Fiche: 50-322.83/07/06.8307080425.
- 8307110296 Submits schedule rept re contention on cylinder head cracking
  DYNNER, A.R. Kirkpatrick, Lockhart, Hill, Christopher & Phillips.
  DYNNER, A.R. Suffolk County, NY 83/07/06 BRENNER, L.J.,
  CARPENTER, J.L., MORRIS, P.A. Atomic Safety and Licensing Board Panel,
  3pp. 19374:360. 24x Fiche 50-322,83/07/06,8307110296.
- 8307110358 Request for leave to reply to Suffolk County 830627 answer opposing util 830608 motion for low power OL Arguments opposing motion could not be anticipated & recent developments need to be addressed Certificate of Svc encl. CHRISTMAN.J.N. Long Island Lighting Co. 83/07/06. Atomic Safety and Licensing Board Panel. Spp. 19380:220. 24X Fiche:50-322.83/07/06.8307110398.
- 8307110039 Response to Suffolk County Shoreham Opponents Coalition & Town of Southhampton draft emergency planning contentions which were consolidated w/North Shore Committee contentions. Certificate of Svc encl.

  REPKA.D.A. Hearing Branch 3. 83/07/07. Atomic Safety and Licensing Board Panel. 43pp. 19379.255. 24x Fiche: 50-322,83/07/07,8307110039.
- B307110042 Response opposing Citizens for Orderly Energy Policy B30623 draft contentions supporting util offsite emergency plan. Contentions unnecessary to support intervention of party supporting license application WCertificate of Sc. REPKA.D.A. Hearing Branch 3. B3/07/07. Atomic Safety and Licensing Board Panel. Bpp. 19375-305. 24X Fiche: 50-322,83/07/07, B307110042.
- 8307110315 Order granting util 830706 motion for extension until 830708 to respond to intervenor revised emergency planning contentions. Response must be served by CDR on 830708. Good cause shown.

  LAVMENSON. J. A. Atomic Safety and Licensing Board Panel. 83/07/07 Long (sland Lighting Co. 2pp 19381:262 24x

  Fiche: 50-322.63/07/07.8307110315.
- 8307110319 Order pranting stil 830706 request for leave to reply to Suffolk County answer opposing util motion for low power OL. Reply due 830718.NRC may file reply on same data.Courtesy notification enci.

  BRENNER.L. Atomic Safety and Licensing Board Panel 83/07/07.
  Long Island Lighting Co. 3pp. 19381-275. 24X Fiche: 50-322, 83/07/07,8307110319.
- 8307110336 Memorandum & order setting diasol generator contention schedule. Courtesy notification encl.

  BRENNER.L. Atomic Safety and Licensing Board Panel. 83/07/07. 6pp. 19381: 295. 24X Fiche: 50-322,83/07/07,8307110336
- 8307110363 Advises that draft contentions filed by Citizens for Orderly Energy Policy, Inc. on 830683, should be considered final contentions.

  BWARTZ.L.L. Pacific Legal Foundation. SWARTZ.L.L. Affiliation Unknown. 83/07/07 LAURENSON, J.A., WILINE, J.R., Atomic Safety and Licensing Board Panel. 1p. 19380: 260. 24X Fiche: 50-322, 83/07/07, 8307110363.
- 8307120350 Forwards final consolidated emergency planning contentions. LETSCHE.K.J. Kirkpatrick, Lockhort. Hill. Christopher & Phillips. LETSCHE.K.J. Surfolk County, NY. LETSCHE.K.J. North Shore Committee Against Nuclear & Thermal Pollution. 83/07/07. LAURENSON.J.A. KLINE.J.R.. LIVINOSTON.M S. Atomic Safety and Licensing Board Panel. 1p. 19426-318 24x Fiche 50-322.83/07/07.8307120350.
- --8307120367 Final consolidated emergency planning contentions.

  Certificate of Svc encl.

  LETSCHE.K.J. Suffolk County, NY. DDUGHERTY, J.B. Shoreham
  Opponents Coalition. SHAPTRO.R. North Shore Committee Against
  Nuclear & Thermal Pollution. 83/07/07. Atomic Safety and
  Cicensing Board Panel. 204pp 19426:319. 24X
  Fiche 50-322.83/07/07.8307120350.
- 8307120593 Forwards util motion for summary disposition of diesel generator cylinder head cracking issue Related correspondence.

  EARLEY, A.F. Hunton & Milliams EARLEY, A.F. Long Island Lighting Co. 83/07/07 BRENNER, L. Atomic Safety and Licensing Board Panel, ip. 19433:017. 24X Fiche: 50-322, 83/07/07, 8307120593.

- --8307120596 Motion for summary disposition of Suffolk County diesel generator contention No genuine issue of matl fact exists tutil entitled to favorable decision. Statement of matl facts encl.

  EARLEYA.F. Long Island Lighting Co. \* Hunton & Williams
  83/07/07. Atomic Safety and Licensing Board Panel. 20pp
  19433:018. 24X Fichs: 50-322, 83/07/07, 8307120593
- --8307120401 Affidavit of EJ Youngling re diesel generator cracks.
  Reasonable assurance erists that no addicracks or leaks in remaining cylinder heads will occur due to 400 h operation.
  YOUNGLINGE. J. Long Island Lighting Co. 83/07/07. 9pp.
  19433:038. 24X Fiche:50-322,83/07/07,8307120593.
- --8307120606 Affidavit of RA Pratt re diesel generator cracking.
  Reliability record of improved.corrent prodoution cylinder
  heads provides add1 assurance cylinder heads free from
  costing imperfections. Prof qualifications encl.
  PRATT.R.A. Long Island Lighting Co PRATT.R.A. Transamerica
  Delaval, Inc. 83/07/07. 27pp. 19433:047. 24x
  Fiche: 50-322, 83/07/07, 8307120993.
- --8307120616 Advises that final PRA completed & sent to NRC & Suffolk County ASLBs. Other parties will not be served due to expense of reproducing multi-vol PRA. EARLEV.A.F. Hunton & Williams. 83/07/07. BRENNER,L., LAURENSON.J.A. Atomic Safety and Licensing Board Panel. 2pp. 19433:074. 24X Fiche: 50-322,83/07/07.8307120593.
- B307150290 Affidavit of RA Pratt re cracks in cylinder heads of diesel generators. Reasonable assurance exists that casting imperfections unlikely in original model cylinder heads. Related correspondence.
  PRATT,R.A. Trane Co. B3/07/07, 16pp. 19532:177, 24X Fiche: 50-322, 83/07/07, 8307150290.
- 830712038) Objections to intervenor 830705 draft consolidated emergency planning contentions. Contentions lengthy, wordy, reputitive & not sequentially numbered Certificate of Svc encl. MCCLESKEY.K.E. Long Island Lighting Co. MCCLESKEY.K.E. Hunton & Milliams. 83/07/08. Atomic Safety and Licensing Board Panel. 72pp. 19426:094. 24X Fiche: 50-322, 83/07/08, 8307120381.
- --8307120426 Prehearing conforence order re 820720 prehearing conference re proposed contentions on util emergency plan.
  BRENNER, L., MORRITS, P. A., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 82/07/27, 43pp. 19426.166. 24x
  Fiche: 50-322,83707/08,8307120381.
- 8307120554 Answer opposing Suffolk County 830627 motion for leave to file contentions re onsite emergency preparedness. W/specific objections to contentions & Centificate of 8vc. CHRISTMAN.J.N. Long Island Lighting Co. CHRISTMAN.J.N. Hunton & Williams. 83/07/08. Atomic Safety and Licensing Board Panel. 52pp. 19432:075. 24X Fiche: 50-322,83/07/08.8307(20554.
- 8307200222 Affidavit of EJ Youngling re Suffolk County diesel generator contention. Three leaking Delaval cylinder heads replaced All heads to be replaced as soon as practicable Related correspondence.

  YOUNGLING.E.J. Long Island Lighting Co. 83/07/08. 9ap. 17648:096. 24X Fiche: 50-322.83/07/08.8307200222.
- 8307130298 Opposes granting of low power OL. LATHAM.K.L. Affiliation Unknown. 83/07/09. Atomic Safety and Licensing Board Panel. 1p. 19532:212. 24X Fiche:50-322,83/07/09, 8307150298.
- 8307140447 Advises that plant const will be complete by Aug.
  Administrative work necessary for fuel load will not be
  complete until Sept.
  REVELEY.W.T. Hunton & Williams REVELEY.W.T. Long Island Lighting
  Co. 83/07/11. BRENNER.L.. CARPENTER.J.H. MORRIS, P. A. Atomic
  Safety and Licensing Board Panel. 1p. 19521:242. 24x
  Fiche: 50-322.83/07/11.8307140447.
- 8307140471 Notice of appearance in proceeding. Certificate of Svc encl.
  BIRKENHEIER, J. Suffolk County, NY. BIRKENHEIER, J. Kirkpatrick,
  Lockhart, Hill. Christopher & Phillips. 83/07/11. 4pp. 19520: 266.
  24X Fiche: 50-322,83/07/11.8307140471.
- 8307180082 Expresses shock at recent NRC action re "entitlement" of LfLCD to low power license despite existing uncertainties re offsite emergency planning Current regulations absurd, inconsistent & distressing Careful consideration urged. CUDMLM.M. New York, State of, 82/07/11, COTTER.P. Atomic Safety and Licensing Board Panel. 2pp. 19560:266. 24X Fiche:50-322,83/07/11.8307180082.

- 8307140439 Forwards Teledyne Engineering Svcs 830629 ltr to NRC re independent design verification program. Certificate of Svc encl. BORDENICK, B. M. Hearing Branch 3. 83/07/12. BRENNER, L., CARPENTER, J. L., MORRIS, P. A. Atomic Safety and Licensing Board Panel. 4pp. 19520:338. 24x Fiche. 50-322, 83/07/12, 8307140439.
- 8307140442 Advises of commencement of NRC insp of diesel generator vendor, by Region IV. Region will attempt to expedite insp. Written rept to be issued approx 30 days after insp. completion. SERDENICK, B. M. Hearing Branch 3. 83/07/12. BRENNER, L., MORRIS, P. A., CARPENTER, J. L. Atomic Safety and Licensing Board Panel, 2pp. 19920: 343. 24X Fiche: 50-322, 83/07/12, 8307140442.
- 8307140444 Forwards Suffolk County response to util objections to intervenor consolidated emergency planning contentions & NRC response to dreft emergency planning contentions.

  MILLER.M.S. Kirkpatrick, Lockhart, Hill, Christopher & Phillips.

  MILLER.M.S. Soffolk County, NY, 63/07/12, LAURENSON, J. A., KLINE, J. A., LIVINGSTON, M.S. Atomic Safety and Licensing Board Panel, lp. 19521: 271. 24X Fiche: 50-322, 83/07/12, 8307140444.
- -8307140448 Response to util 830708 objections to intervenor consolidated emergency planning contentions & NRC 830707 response to draft emergency planning contentions. Certificate of Svc encl.

  MILLER.M.S. Suffolk County, NY. MILLER.M.S. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 83/07/12. Atomic and Licensing Board Panel. 42pp. 19321:272. 24X Fiche: 50-322,83/07/12,8307140444. Atomic Bafety
- 8307140446 Responds to 830708 informal document request re diesel generator cylindar head cracking contention. NRC sent portion of documents on 830712. Issuance of Energy Consultants. Incrept imminent. 8080ENICK, B. M. Hearing Branch 3. 83/07/12. DYNNER, A. R. Kirtpatrick, Lockhart, Hill, Christopher & Phillips. 2pp. 19521:254. 24X Fiche: 50-322,83/07/12.8307140446.
- B307140470 Cross-reference for emergency planning contentions, between Suffalk County, Shareham Opponents Coalition & Town of Southhampton B30623 separate draft contentions & intervenor B30707 final contentions, Certificate of Svc enc.

  REPKA.D.A. Hearing Branch 3. B3/07/12. Atomic Safety and Licensing Board Panel. 13pp. 19920: 270. 24X Fiche: 50-322, 83/07/12, B307140470.
- 8307150309 Citizens for Orderly Energy Policy. Inc reply to NRC 830629 opposition to Citizens petition to intervene Particularized injury demonstrated, petition timely & contentions within scape of proceeding Certificate of Svc encl.
  SWARTZ.L.L. Pacific Legal Foundation. 83/07/12. Atomic Safety and Licensing Board Panel. 12pp. 19932: 329. 24X
  Fiche: 30-322, 83/07/12, 8307190308.
- 8307180213 Disputes alleged 830707 agreement not to request add1 time to revise response to 830623 contentions. Related correspondence. MCLEBKEY.K.E. Hunton & Williams. 83/07/12. LETSCHE,K.J. Kirkpatrick. (.ockhart, Hill. Christopher & Phillips. 3pp. 19555; 106. 24X Fiche: 50-322, 83/07/12, 8307180213.
- 8307150314 Answer apposing Suffolk County B30627 motion for leave to file contentions me ansite emergency planning. Motion involves matters dismissed from & stipulated out of proceeding & is untimely. Certificate of Svc encl. REIS. E. J. Hearing Branch 3. 83/07/13. Atomic Safety and Licensing Board Panel. 31pp. 19532:341. 24X Fiche: 50-322,83/07/13. 8307150314.
- 8307190002 Forwards HR Denton B30711 memo resolving JH Conran differing prof opinion re-potential safety significance of lack of progress in resolving Unresolved Safety Issue A-17. "Sys Interaction."
  RAHBON.R. J. Hearing Branch 3. B3/07/14. BRENNER.L., MORRIS, P. A., CARPENTER, J. L. Atomic Safety and Licensing Board Panel, 11pp. 19635:036. 24X Fiche: 50-322, 83/07/14, 8307190002.
- B307200210 Confirms discussions at B307t3 prehearing conference re providing Town of Southhampton & other emergency planning parties w/correspondence between NRC & FEMA on FEMA review of util interim offsite emergency response plan. LATHAM.S. Twomey, Latham & Shea. 83/07/14. BORDENICK, B. M. Hea Branch 3 PERRY, S. Federal Emergency Management Agency. 2pp. 19648:028. 24% Fiche: 50-322, 83/07/14. 8307200210.
- 8307180134 NRC schedule estimates for const completion & readiness for fuel loading, per 830707 request. Final site SER expected by end of Aug 1983. Closeout of open items anticipated to support proposed Oct 1983 fuel load date.

  BORDENICK, B. M. Hearing Branch 3. 83/07/15. 4pp. 19557:064. 24X Fiche: 50-322,83/07/15,8307180134.

- 8307180231 Order ruling Suffolk County motion for Commission ruling on plan for emergency proparedness is precluded by NRC rules.

  Objections should be presented to ASLAB w/motion for directed certification. W/Commissioner Gilinsky dissent.

  CHILK. S. J. Office of the Secretary of the Commission. 83/07/15.

  3pp. 19595:093. 24X Fiche 50-322.83/07/15.8307180231.
- 8307190325 Reaffirms ASLB commitment to adjudicatory responsibilities, in response to 830711 ltr. ASLB decisions based solely on record & free from external influences COTTER.B.P. Atomic Safety and Licensing Board Panel. 83/07/15. CUDMD.M.M. New York, State of. 2pp. 19632:110 24X Fiche: 50-322,83/07/15,8307190325.
- 8307200089 Forwards encls to Teledyne Engineering Svcs 830712 itr to NRC re independent design verification program Encls unavailable when itr sent on 830712.Certificate of Svc encl. BORDENICK, B. M. Hearing Branch 3. 83/07/18. BRENNER-L.. FERROUSDN. G. A. MDRRIS, P. A. Atomic Safety and Licensing Board Panel. 40pp. 19647:073. 24X Fiche: 50-322,83/07/18,8307200089.
- 8307200102 Response to Suffolk County answer opposing util 830629 motion for low power DL. Reiterates conditional support of motion. Addl findings must be made by NRC before low power DL issued. Certificate of Svc encl.

  BORDENICK, B. M. Hearing Branch 3. 83/07/18. Atomic Safety and Literating Board Penel. 10pp. 19647:146. 24X Fiche: 50-322, 83/07/18. 8307200102.
- B307210164 Response to Suffolk County 830627 opposition to applicant B30608 motion for low power OL. County answer attempts to reopen questions resolved by ASLB & Commission. Certificate of Svc encl.
  CHRISTMAN. H. T. Long Island Lighting Co. CHRISTMAN. W. T. Hunton & Williams. B3/07/18. Atomic Bafety and Licensing Board Panel 23pp. 17669:112. 24X Fiche: 50-322.83/07/18.8307210164.
- B307260076 Staff requirements memo re B30714 affirmation/discussion & vote approving rev to 10CFR71 & order dismissing Suffolk County motion for Commission to reject licensee emergency plan.

  CHILKIB. J. Office of the Secretary of the Commission. B3/07/18.

  DIRCKS.W. J. Office of the Executive Director for Operations.

  PLAINE.H. H. Office of the General Counsel. FDUCHARD. J. J. Office of Public Affairs. 2pp. 19786:219. 24X Fiche: 50-322, B3/07/18.

  B307260076.
- 8307260302 Motion to compel discovery of documents identified in Buffolk County 830708 request to util. Five-day extension requested to decide on head cracking contention due to util tardiness. Certificate of Svc encl.

  DYNNER, A. R. Suffolk County, NY. DYNNER, A. R. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 83/07/19. Atomic Safety and Licensing Board Panel. 50pp. 19726: 232. 24X Fiche: 50~322,83/07/19,8307260302.
- B307220357 Response to util & NRC B30708 & 13, respectively, oppositions to Buffalk County B30627 motion for leave to file contentions re unsite emergency preparedness. Contentions allege inadequacy in util plan. Certificate of Svc encl. LANPHER.L.C. Suffalk County, NY. LANPHER.L.C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. B3/07/20. Atomic Safety and Licensing Board Panel. 25pp. 19675:149. 24X Fiche: 50-322, B3/07/20, B307220357.
- B307220366 First prehearing conference order re 830713 prehearing conference in HauppaugerNY & notice of 830807 second prehearing conference in Riverhead.NY. Intervenors ordered to file redrafted contentions by 830726. LAURENBON.J.A. Atomic Safety and Licensing Board Panel. B3/07/20. 6pp. 19676:098. 24X Fiche: 50-322. B3/07/20. G307220366.
- B307220369 Memorandum & order denying Suffolk County B30719 motion for deferral of B30722 date to respond to util motion for summary disposition re cracks in diesel generator cylinder heads.

  BRENNER, L. Atomic Bafety and Licensing Board Panel. B3/07/20.
  Buffolk County, NY. Spp. 19676: 104. 24X Fiche: 50-322, 83/07/20, B307220349.
- 8307250140 Advises that NRC will forward future correspondence between NRC & FEMA re FEMA review of util interim offsite radiological emergency response plan to extent correspondence otherwise available in PDR.
  BORDENICK.B.M. Hearing Branch 3. B3/07/21. LATHAM, S.B. Twomey, Latham & Shea. 2pp. 19706:099. 24X Fiche: 50-322, 83/07/21. 8307250140.
- 8307260411 Advises that util will issue Rev 1 to plant local offsite radiological emergency response plan by end of Jul.Rev will include response to FEMA review & will address Suffolk County comments & minor inconsistencies. MCCLEGREV.K.E. Hunton & Williams. 83/07/21. LAURENSON.J.A., KLINE, J.R., LIVINGSTON.M.S. Atomic Safety and Licensing Board Panel. 2pp. 19733:133. 24X Fiche: 50-322.83/07/21.8307260411.

- 8307250270 Forwards NRC response to util motion for summary disposition of Suffolk County diesel generator contention EG Greenman executed affidavit forthcoming.

  BORDENICK.B.M. Hearing Branch 3. 83/07/22. BRENNER, L., FERGUSON, G. A., MORRIS, P. A. Atomic Safety and Licensing Board Panel. 2pp. 19705.295. 24X Fithe. 50-322, 83/07/22, 8307250270.
- --8307250279 Response supporting util 830707 motion for partial summary disposition of Suffolk County diesel generator contention. No issue of matl fact exists. EO Greenman unerecuted affidavit & Certificate of Svc encl
  BORDENICK.B.M Hearing Branch 2 83/07/22. Atomic Safety and Licensing Board Panel. 8pp. 19705:297 24X Fichs 50-322, 83/07/22.8307250270.
- 8307260347 Forwards Suffolk County answer & opposition to util motion for partial summary disposition of Suffolk County diesel generator contention re-cylinder head cracking W/o encl. DYNNER.A.R. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. DYNNER.A.R. Suffolk County, NY. 83/07/22. BRENNER.L.J. Atomic Safety and Licensing Board Panel. 1p. 19726:001 24X Fiche: 50-322,83/07/22,8307260347.
- 8307280409 Forwards EJ Youngling unexecuted affidavit re questions raised in ASLB 830720 memorandum & order on diesel generators, Prior to fuel load, util will implement commitment to replace cylinder heads. Certificate of Svc encl. EARLEY, A. F. Hunton & Williams. 83/07/22. BRENNER, L., MORRIS, P. A., FERGUSON, G. A. Atomic Safety and Licensing Board Panel. 11pp. 19733:191. 24X Fiche: 50-322.83/07/22.8307260409.
- 8307260049 Forwards NRC 830501 % 17 ltrs to FEMA requesting FEMA findings & determinations on emergency plans.
  BORDENICK, B.M. Hearing Branch 3. 83/07/25. LATHAM, S. B. Twomey, Latham & Shea. 4pp. 19727:351. 24X Fiche: 50-322.83/07/25. 8307260049.
- B307270140 Advises that util requested to send ASLB final PRA.Four volset will be shipped separately.
  EARLEY.A.F. Hunton & Williams. EARLEY.A.F. Long Island Lighting Co. B3/07/25. BRENNER.L. Atomic Safety and Licensing Board Panel. 1p. 19749:341. 24X Fiche:50-322,83/07/25,8307270140.
- 8307290154 Forwards revised emergency plenning contentions & memorandum re revised contentions.

  LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips.

  LETSCHE, K. J. Suffolk County, NY. LETSCHE, K. J. Southampton, NY.

  83/07/26. LAURENSON, J. A. KLINE, J. R., LIVINGSTON, H. S. Atomic Safety and Licensing Board Panel. 1p. 1982: 162. 24X

  Fiche: 50-322: 83/07/26, 8307290154.
- --8307290159 Memorandum re revised emergency planning contentions.
  Contentions sequentially numbered redrafted to eliminate repetition & redundancies & reorganized per new subj.matter categories. Certificate of Svc encl.
  LETSCHE.K.J. Suffolk County, NY. DOUGHERTY, J.B. Shoreham Opponents Coalition. SHAPIRO.R. North Shore Committee Against Nuclear & Thermal Pollution. 83/07/26. Atomic Safety and Licensing Board Panel. 200pp. 19821:163. 24X
  Fiche: 50-322,83/07/26,8307290154.
- 8307280037 Forwards EG Greenman executed affidavit supporting util motion for summary disposition of Suffolk County diesel generator contention.
  BORDENICK, B. M. Hearing Branch 3. 83/07/27. BRENNER, L., FERGUSGN, G. A., MCRRIS, P. A. Atomic Safety and Licensing Board Panel. 2pp. 19791:190. 24X Fiche:50~322.83/07/27,8307280037.
- --B307280043 Affidavit of E0 Greenman supporting util motion for partial summary disposition of Suffolk County diesel generator contention. Imposition of Tech Spec requirements is adequate safeguard against loss of offsite power consequences. GREENMAN.E. O. Division of Project & Resident Programs. 83/07/25. 3pp. 19791:172. 24X Fiche: 50-322,83/07/27,8307280039.
- 8307290008 Forwards NRC 830722 ltr to FEMA re util transition plan.W/o encl.
  BORDENICK.B.M. Hearing Branch 3. 63/07/28. LATHAM.S.B. Twomey.
  Latham 5 Shea. 2pp. 17815:355 24X Fiche: 50-322,83/07/28.
  8307290008.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8307200002 Amend 48 to application for OL consisting of Rev 30 to FSAR. correcting discrepancies identified by plant configuration review program.

  SHITH, J. L. Long Island Lighting Co. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 4pp. 19492:001. 24% Fiche: 50-322.83706/30.8307200002.
- --8307200003 Rev 30 to FSAR.

  \* Long Island Lighting Co. 83/06/30. 749pp. 19652:006. 24X Fiche: 50-322,83/06/30,8307200002.

- P. Operating license stage documents & correspondence
- 8305270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list enci. EISEMUNT, D. 0. Division of Licensing. 83/67/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- Q. Inspection reports, IE Bulletins & correspondence
- B307010035 Ack receipt of B30513 ltr informing NRC of steps taken to correct violations noted in 18 Insp Rept 50-322/82-04.

  MARTIN.T.T. Division of Engineering & Technical Programs. B3/06/14.

  FOLLOCK, M. S. Long Island Lighting Co 2pp. 19169:054, 24X

  Fiche: 50-322, 83/06/14, 8307010035.
- --8307010043 Responds to ASLB request re spray blockage issue noted in IE Insp Rept 30-322/62-04 Reduction in flow has no impact on peak pressure after DBA as peak pressure is reached prior to spray actuation.

  SMITH. J. L. Long Island Lighting Co. 83/05/13. MARTIN. T. T. Division of Engineering & Technical Programs. 10pp. 17167:056. 24X Fiche: 50-322,83/06/14,8307010035.
- B307010014 Forwards IE Insp Rept 50-322/83-15 on 830516-19.No noncompliance noted.

  MARTIN.I.T. Division of Engineering & Technical Programs. B3/06/15. POLLOCK,M. S. Long Island Lighting Co. 2pp. 19124:320. 24X Fiche: 50-322,83/06/15,8307010014.
- --B30701002: IE Insp Rept 50-322/83-15 on 830516-19. No noncompliance noted Major areas inspected: licensee action on previous insp findings, preoperational test program including test program status & implementation & test procedure review. NICHOLAS, N. H., BETTENHAUSEN, L. Region 1, Office of Director. 83/06/15, lipp. 19124:322. 24X Fiche: 50-322,83/06/15,8307010014.
- B307110280 Forwards IE Insp Rept 50-322/83-19 on 830531-0403 No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/24.

  PGLLGCK.M.S. Long Island Lighting Co. 2pp. 19374:245. 24X

  Fiche: 50-322,83/04/24,8307110280.
- --B307110287 IE [nsp Rept 50-322/83-19 on B30531-0A03 No noncompliance noted Major areas inspected preoperational testing of area, process & effluent radiation monitors solid liquid & gaseous raduaste sys & licensee action on IE Bulletin B3-10. NIKITI.R L.. SHANBAKY, M.M. Region 1. Office of Director. B3/06/22. 10pp. 19374:247. 24X Fiche: 50-322.83/06/24.8307110280.
- 8307070090 Submits corrective action to Item II of IE Insp Rept 50-322/82-15, per 830609 meeting w/NRC. All trip setpoints will be verified prior to fuel load Commitments should resolve item.

  SMITH, S. L. Long Island Lighting Co. 83/06/30. DENTON, H. R. Office Nuclear Reactor Regulation, Director. 3pp. 19295:133. 24X Fiche: 30-322,83/06/30.8307070090.
- 830707012! Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators," 5 RM Starostecki 830401 ltr. Initial valve integrity verification procedures will be performed for six check valves prior to fuel load. SMITH, J. L. Long Island Lighting Co. 83/06/30, MURLEY, I.E. Region 1, Office of Director. Spp. 19294:125, 24x Fichs: 50-322,83/06/30,8307070121.
- 8307210023 Forwards IE Insp Rept 50-322/83-18 on 830531-0603 No noncompliance noted.

  MARTEN.T. T. Division of Engineering & Technical Programs. 83/07/06. POLLOCK, M.S. Long Island Lighting Co. 2pp. 17669:197. 24X

  Fiche: 50~322, 83/07/06, 8307210023
- --8307210026 IE Insp Rept 50-322/83-18 on 830531-0603 No noncompliance noted Major areas inspected: actions on previously identified items, insp activities to comply w/NASLP hearing agreement re electrical raceway separation & QA involvement. RICHARDS. S. ANDERSON, C. Region 1, Office of Director. 83/06/28. 5pp 19669: 201. 24X Fiche: 50-322, 83/07/06, 8307210023.
- B307140329 Ack receipt of 830627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/83-10.
  BTARDSTECKLYR. Division of Project & Resident Programs. B3/07/08. POLLOCK.M.S. Long Island Lighting Co. 1p. 19525:092. 24X
  Fiche: 50-322, 83/07/08, 8307140329.

- --B307140335 Responds to NRC B30527 ltr re violations noted in IE Imap Rept 50-322/83-10 Corrective actions: Test Change Notice I to PT. 307. 005C written to change tolerances on 22 h diesel run to 3500 + 70 kW. PGLLOCK.M.S. Long Island Lighting Co. B3/06/27. STAROSTECKI.R. Division of Project & Resident Programs. Spp. 19325: 093. 24X Fiche: 50-322, B3/07/08, 8307140329.
- 8307250437 Forwards IE Insp Rept 50-322/83-17 on 830910-0621 & notice of deviation.
  STARDSTECKI.R. Division of Project & Resident Programs. 83/07/08.
  POLLACK.M.S. Long Island Lighting Co. 2pp. 19702:068. 24X
  Fiche: 50-322,83/07/08,8307250437.
- --8307250439 Notice of deviation from insp on 830510-0621. \* Region 1. Office of Director. 83/07/08. 1p. 19702:070. 24X Fiche: 50-322,83/07/08.8307250437.
- --8307250442 IE Insp Rept 50-322/83-17 on 830510-0621 Deviation noted: failure to perform NDT when jet pump hold-down beams detensioned.
  HIGGINS.U.C., PETRONE.C.D., MCCABE.E.C. Region 1, Office of Director. 83/06/23. 11pp. 19702:071. 24X Fiche: 50-322,83/07/08,8307250437.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Gubsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fishe: 30-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270404 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, B3/07/14, 8306270406.
- 8307190321 EN-B3-023A: notice of violation to proposed imposition of civil penalty in amount of \$40.000 issued to licensee. Action based on licensee approval of preoperational test results even though one test acceptance criteria not satisfied. KLINGLER.G., AKELRAD.J. Director's Office. Office of Inspection and Enforcement. B3/07/15. 1p. 19632: 109. 24X Fiche: 50-322,83/07/15.
- R. Periodic operating reports & related correspondence
- 8307060428 Provides daily highlight for 830622. ASLB admitted portions of new contention me vibration induced failures of diesel generator components.

  CARUSO.R. Licensing Branch 2. 83/06/24. DENTON.H.R., CASE.E.B., Office of Nuclear Reactor Regulation. Director. 1p. 19300:079. 24x Fiche: 50-322,83/06/24.8307060428.
- B307010091 Forwards executive summary of final rept, "Independent Design Review for Shoreham Nuclear Power Station." Final rept will be submitted by 830731.

  LANDERS, D. F. Teledyne Engineering Services. B3/06/30. DENTON.H.R. Dffice of Nuclear Reactor Regulation, Director. 1p. 19168; 258. 24x Fiche: 50-322, B3/06/30, B307010091.
- --8307010100 "Independent Design Review for Shoreham Nuclear Power Statton," executive summary of final rept. \* Teledyne Engineering Services. TR-5633-3. 83/06/30. 40pp. 19168: 260. 24X Fiche: 50-322. 83/06/30. 8307010091.
- 8307180203 Forwards "Test Review, Data Analysis & Review of Emergency Diesel Generator Operational Reliability Problems at Shoreham, Unit 1, " final rept. STARGSTECKI.R. Division of Project & Resident Programs. NRC-05-82-249, 83/07/13, POLLOCK.M.S. Long Island Lighting Co. 280. 17955; 111. 24% Fiche: 50-322, 83/07/13, 8307180203.
- --8307180212 Forwards "Test Review Data Analysis % Review of Emergency Diesel Generator Operational/Reliability Problems as Shoreham Unit 1." final rept Rept incorporates NRC comments provided at 830629 meeting at Region I ofcs.

  KAYE.J.A. Energy Consultants, Inc. NRC-05-82-249. 83/07/12. MCCABE, E. B. Region i, Office of Director. 1p. 17955:113. 24X Fiche 50-322,83/07/13,8307180203.

- --8307180222 "Test Review Data Analysis & Review of Emergency Diesel Generator Operational/Reliability Problems at Shoreham Unit I." final rept. KUNKLE,G.L. Energy Consultants, Inc. NRC-05-82-249. 83/07/12. 27pp. 19555:114. 24X Fiche:50-322,83/07/13.8307180203.
- 8307290160 Forwards Books 1-3 of "Independent Design Review for Shoreham Nuclear Power Station," final technical rept.

  LANDERS.D.F. Teledyne Engineering Services. 83/07/26. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 1p. 19823:122. 24x Fiche: 50-322.83/07/26,8307290160.
- ---8307290163 Books 1-3 of "Independent Design Review for Shoreham Nuclear Power Station," final technical rept. \* Teledune Engineering Services. TR-3633-4. 83/07/26. 1800pp. 19823: 123. 24X Fiche: 50-322, 83/07/26, 83/07290160.
- S. Reportable occurrences, LERs & related correspondence
- B3072B0300 Interim deficiency rept re failure of Limitorque keys between motor pinion gear & motor shaft of two motor operated valves in RHR sys. Initially reported on B30617, in response to IE Info Notice B1-OB. Keys replaced.

  SMITH, J. L. Long Island Lighting Co. B3/07/18, MURLEY, T. E. Region in Office of Director. 3pp. 19789:194. 24X Fiche: 50-322, 83/07/18, B307280300.
- 8307250335 Part 21 rept re potential defect in high pressure fuel injection line of DSR or DSRV standby diesel generator. Removal of random sample of lines to be internally borescope inspected recommended. BOYER.R.E. Transamerica Delaval, Inc. 83/07/20. Director's Dffice, Office of Inspection and Enforcement. 2pp. 19703:011. 24X Fiche: 50-000, 83/07/20, 8307250335.
- B307250461 Part 21 rept re defect in component of DSR-48 standby diesel generator. Improved design jacket water pump assembly retrofitted to all facility engines in Nov 1982. Assembly proven successful during several hours tested.
  BDYER.R. E. Transamerica Delaval, Inc. 83/07/20. Director's Office. Office of Inspection and Enforcement. 2pp. 19701:321. 24X Fiche: 50-322, 83/07/20, 8307250461.
- T. Hearing transcripts on non-antitrust matters
- 8307050440 Transcript of Commission B30628 affirmation/discussion & vote in Washington, DC re SECY-83-190A on review of ALAB-687 & SECY-83-215A on low-power DL for Shoreham.Pp 1-7.

  \* Commissioners. 83/06/28. 10pp. 19262:336. 24X
  Fiche: 50-322, 83/06/28, 8307050440.
- 8307180078 Transcript of 830713 hearing in Hauppauge, NY. Pp 1-118. \* Atomic Safety and Licensing Doard Panel. 63/07/13. 120pp. 19360:008. 24X Fiche: 50-322.83/07/13.8307180078.
- 8307190168 Transcript of 830714 hearing in Hauppauge, NY, Pp. 119-314.

  Supporting documentation encl.

  \* Atomic Sefety and Licensing Board Panel. 83/07/14. 206pp.
  19633; 321. 24X Fiche: 50-322, 83/07/14, 8307190168.
- B307290082 Transcript of B30714 affirmation/discussion & vote in Washington, DC re BECY B3-240 on Suffolk County motion on emergency planning & BECY B3-232 on JOCFR71.

  \* Commissioners, 83/07/14, 630.
  Ficha: 50-322, 83/07/14, 8307250082.
- 830728011B Informs of Commission determination to withhold transcript of 830419 closed Commission meeting from public disclosure.

  CHILK: 5. J. Office of the Secretary of the Commission. 83/07/20. Public Document Branch. ip. 19812:346. 24X Fiche: 50-322,83/07/20.
- --8307280122 Advises that Commission has not objected to proposed withholding of 830415 meeting transcript. Transcript will not be released.
  CHILK.S.J. Office of the Secretary of the Commission. 83/05/23.
  PLAINE, H. H. Office of the General Counsel. 1p. 19812:347. 24X Fiche: 50-322,83/07/20,8307280118.
- 8307280468 Informs of Commission determination re public disclosure of 830405 briefing. Transcript should be withheld.
  CHILK: S. J. Office of the Secretary of the Commission. 83/07/20. Public Document Branch. ip. 19826:044. 24X Fiche: 50-322,83/07/20.8307280468.

- --8307280469 Advises that Commission has not objected to proposed withholding of 830405 meeting transcript Transcript will not be released.
  CHILK.S.J. Office of the Secretary of the Commission. 83/05/23.
  PLAINE.H.H. Office of the General Counsel. 1p. 19926:045. 24X Fiche: 50-322,83/07/20.8307280468
- B307290255 Forwards B30713 & 14 prehearing & limited appearance transcripts, per verbal request W/o encl.
  BURDENICK, B.M. Hearing Branch 3. 83/07/21. GLASS, S. Federal Emergency Management Agency. 1p. 17705-336. 24X
  Fithe: 50-322, 83/07/21. B307250255.
- DOCKET 90-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT.D.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 17963:116. 24X Fiche: 30-000.83/06/03. 8306060070.
- B307240379 Forwards proposed change to FSAR Chapter 17 re company QA organization. W/one oversize figure. Aperture card is available in PDR. SCHUYLER, J. D. Pacific Gas & Electric Co B3/06/10. MARTIN, J. B. Region 5. Office of Director. 22pp. 19731:175. 24X Fiche: 50-275, B3/06/10, B307260379.
- 8307130278 Forwards "Final Rept on Evaluation of Spot-Welded Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Canyon Power Plant," supplementing Bechtel rept transmitted by PG&E 830225 itr.

  SCHUYLER.J.D. Pacific Gas & Electric Co. 83/07/01 EIRENHUT.D.G. Division of Licensing. 1p. 19474:006. 24X Fiche: 50-275.83/07/01.8307130278.
- ---B3071302B1 "Final Rept on Evaluation of Spot-Welded Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Canyon Power Plant." \* Bential Corp. 83/07/01. 19pp. 19474:007. 24X Fiche: 50-275.83/07/01.8307130278.
- --8307130286 "Outline for Sampling,Preparation & Testing of Spot-Welded Superstrut Members for Diabla Canyon Power Plant." \* Bechtel Corp. 0072C/0109. 83/06/02. 12pp. 19474:026. 24X Fiche: 50-275.83/07/01.8307130278
- --8307130871 "Statistical Analysis of Bhear Strength Data for Support Strut Spot Welds, Diablo Canyon Power Plant." \* Jack R. Benjamin & Associates, Inc. 113-090-H-01. 83/06/30. 18pp. 19474:038. 24% Fiche:50-275,83/07/01,8307130278.
- --8307130298 Forwards "Investigation of Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Cangon."
  Superstrut spot-welded members meet design requirements & may be installed.
  CRANE.P.A. Pacific Gas & Electric Co. 83/02/25. ENGELKEN.R.H., MORRILL.P.G. Region 5, Office of Director. 1p. 19474:056. 24X Fiche: 30-275,83/07/01:8307130278.
- --8307130302 "Investigation of Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Canyon." \* Bechtel Corp. 83/02/25. 39pp. 19474:037. 24x Fiche:50-275.83/07/01.8307130278.
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT. D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events. Bxc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000:83/07/08, 8307080169.

- 8307120533 Notification of 830710 significant licensee meeting w/util in Walnut Creek.CA to discuss licensee presentation on RCS ploing min well thickness. Agenda encl MORRILL.P. J. Region 5. Office of Director. 83/07/08. EISENHUT, D. G. Division of Licensing. BUCKLEY.B.C. SCHIERLING.H.E. Office of Nuclear Reactor Regulation, Director. 5pp. 19433:317. 24X Fiche: 50-275, 83/07/08, 8307120533.
- 9307190171 Advises that Joint Intervenors charged that independent design verification program (IDVP) yielded to util pressure b util seeking to dilute IDVP independence. Disputes charges. SCHUYLER.J.O. Pacific Gas & Electric Co. 83/07/14. DENTON.H. Office of Nuclear Reactor Regulation. Director. 3pp. 19634:167. 24X Fiche. 50-275,83/07/14,8307190171.
- B307190044 Advises of B30721 meeting in San Francisco.CA to discuss rupture restraint program Agenda included.
  COOPER, W. E. . CRAGIN. J. G. Teledyne Engineering Services. B3/07/19.
  DENTON. H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19635: 135 24X Fiche: 50-275, B3/07/19, B307190044.
- 8306270419 Board Notification 83-077A forwards summary of evaluation of allegation re-release of NRC draft rept.Basis for allegation inaccurate.
  EISENHUI.D.G. Division of Licensing. 83/07/28. PALLADINO.N.J., GILINSKY.V., ROBERTS.T.M. Commissioners. 5pp. 19815:328. 24X Fiche:50-275,83/07/28.8306270419.
- F. Security, medical, emergency & fire protection plans
- B307120512 Forwards IE Insp Repts 50-275/83-19 & 50-323/B3-15 on B30501-28. No noncompliance noted. BISHOP-T.W. Region 5. Office of Director. B3/06/24. SCHUYLER, J. D. Pacific Gas & Electric Co. 2pp. 19433: 218. 24X Fiche: 50-275, 83/06/24. B307120512.
- --8307120522 IE Insp Repts 50-275/83-17 & 50-323/83-15 on 830501-28.No noncompliance noted Major areas inspected: plant operations, survoillance testing, maint. TMI Item []. 8. 2. emergency preparedness, preoperational testing & plant tours.

  CARLSON, J. D. Region 5, Office of Director. 83/06/24. 7pp. 19433: 220. 24X Fiche: 50-275, 83/06/24, 8307120512.
- B30704017B Forwards "Procedures Generation Package," in response to Generic Ltr 82-33. Suppl 1 to NUREC-0737 re emergency response capability.
  SCHUYLER, J. D. Pacific Gas & Electric Co. B3/07/01. EISENHUT, D. G. Division of Licensing. 1p. 17249: 246. 24X Fiche: 50-275, B3/07/01, B307040178.
- --8307060180 "Procedures Generation Package." SEXTON.J.A. Pacific Gas & Electric Co. 83/06/24. 37pp. 19249: 247. 24X Fiche: 50-275, 83/07/01, 8307060178.
- 8307250132 Releases public version of revised emergency plan implementing procedures. FELION.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19738:172. 24X Fiche: 50-275, 83/07/19, 8307250132.
- --8307250139 Forwards public version of Rev O to Emergency Plan Implementing Procedure RP OP-4A re loss of electrical power & Rev O to Procedure EP OP-4B re loss of all ac power. CRANE, P. A. Pacific Oas & Electric Co. 83/05/18, MARTIN, J. B. Region 5, Office of Director. 2pp. 19738:173. 24X Fiche 50-275,83/07/19,8307250132.
- ---8307250156 Public version of Rev O to Emergency Plan Implementing Procedure EP OP-4A re loss of electrical power & Rev O to Procedure EP OP-4B re loss of all ac power.
  FIIGRIBERRY, R. C. Pacific Oas & Electric Go. 83/04/07. 105pp.
  19738:175. 24X fiche:50-275.83/07/19,8307250138.
- 8307270184 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. ip. 19811:103. 24X Fiche:30-275,83/07/19, 8307270186.
- --8307270195 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EP OP-11 to loss of component cooling water & Rev 4 to Procedure EP OP-38 re anticipated transient w/o trip. W/o Procedure EP OP-38. SCHUYLER.J. D. Public Service E)ectric & Gas Co. of New Jersey. 83/07/01. MARTIN.J.B. Region 5. Office of Director. tp. 19811:104. 24X Ficbe: 50-275.83/07/19.8307270184.
- \*\*-8307270201 Public version of Rev 3 to Emergency Plan Implementing Procedure EP OP-11 re loss of component cooling water. SCHUYLER, J. O. Public Service Electric & Qas Ca. of New Jersey. 83/06/10. 26pp. 19811:105. 24x Fiche:30-273,83/07/17.8307270186.

١

#### G. Adjudicatory correspondence

- 8307030242 Response to 830610 first set of interrogatories re design GA. Certificate of Svc encl.
  REYNOLDS, J. R. Joint Intervenors-Diablo Canyon. REYNOLDS, J. R.
  Center for Law in the Public Interest. 83706/17. Pacific Gas & Electric Co. 13pp. 19197: 265. 24X Fiche: 50-275, 83706/17, 8307050242.
- B307050241 Response to first set of interrogatories Personal qualification statement of RB Hubbard & Certificate of Svc encl. Related correspondence.

  DURBIN.S.L. California, State of. B3/06/27. Pacific Qas & Electric Co. Sipp. 19197:214. 24X Fiche: 50-275, 83/06/27, B307050241.
- 8307050075 Objects to Norton 830624 proposed schedule for reopened hearings on design QA. STRUNWARSER.M. California, State of, 83/06/28, MDDRE,T.S. Atom'r Safety and Licensing Appeal Panel. 3pp. 19199:317, 24X Fiche: 50-275, 83/06/28, 8307050075.
- B307010115 Proposes alternate schedule for respende hearing on design QA. Factors affecting schedule include NRC SER issuance scheduled for late Jul 1783 & hearing on motions to reopen record planned for B30719-22. CHANDLER, L. J. Wearing Branch 2. B3/04/30. MODRE, T. S., BUCK, J. H., JOHNSON, W. R. Atomic Safety and Licensing Appeal Panel. 2pp. 1916B: 330. 24% Fiche: 30-275, B3/06/30, B307010115.
- 8307060437 Notice of correction to 830627 response to util first set of interrogatories. REYNOLDS, J. R. Joint Intervenors-Diablo Canyon. REYNOLDS, J. R. Center for Law in the Public Interest. 83/06/30. 2ρp. 19239:337. 24X Fiche: 50~275, 83/06/30, 8307060437.
- --8307060441 Verification & corrected Page 1 to B30627 responses to util first set of interrogatories. Certificate of Svc encl.

  \* Joint Intervenors-Diable Canyon. 83/06/29. Pacific Gas & Electric Co. 4pp. 19239: 339. 24X Fiche: 50-275, 83/06/30, 8307060437.
- 8307040397 Requests confirmation of State of CA understanding re NRC insp repts on const GA, to be entered into record.

  KAUFMAN.P.H. California, State of. 83/07/01. MODRE, T. S. Atomic Safety and Licensing Appeal Panel. 2pp. 19239; 324. 24X

  Ficha: 50-275.03/07/01.8307060397.
- --8307060405 Forwards application for subpoena directed to VH Tennyson.
  DURBIN: S. L. California: State of. 83/07/01. MOORE, T. S. Atomic
  Safety and Licensing Appeal Panel. 1p. 19237:326. 24X
  Fiche: 50-275:83/07/01.8307060397.
- --8307060415 Application for issuance of subpoena directing VH Tennyson to testify at 830717 hearings. Proposed subpoena & Certificate of Evc encl. DURBIN.S.L. California, State of. 83/07/01. 9pp. 19239:327, 24X Fiche:50-275,83/07/01,8307060397.
- B307070235 Subpoena directing VH Tennyson to appear on 830719 in Ban Luis Obispo.CA. MODRE.T.S. Atomic Safety and Licensing Appeal Panel. 83/07/05. TENNYSON.V.H. Affiliation Unknown. 2pp. 19294:078. 24X Fiche:50-275.83/07/05.8307070235.
- B3070B0209 Requests removal of listed names & firm from referenced docket svc list Certificate of Svc enci.
  ANPHER.L.C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips.
  B3/07/05. 4pp. 19351; 340. 24X Fiche: 50-275, 83/07/05, 83070B0209.
- 8307070201 Motion to present evidence not contained in CA Governor & Joint Intervenors 830406 motions to reopen record. Info includes Board Notifications 83-83 & 83-87, unavailable when NRC 830606 response filed W/Certificate of Svc. CHANDLER.L. J. Hearing Branch 2. 83/07/06. Atomic 8afety and Licensing Appeal Panel. 4pp. 19269:158. 24X Fithe: 50-275,83/07/06,8307070201.
- 8307070210 Forwards IE insp repts re const QA,per ASLAB 830628 order. W/o encls.
  CHANDLER,L. J. Hearing Branch 2. 83/07/06. MOORE,T.S., BUCK,J.H., JOHNSON,W.R. Atomic Safety and Licensing Appeal Panel. 2pp. 17293:357. 24X Fiche:50-275,83/07/06,8307070210.
- B307080464 Order advising that scheduling conference to discuss milestones for reopened proceeding on design QA will be held at conclusion of hearing on motions to reopen record re const QA.

  SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel, 83/07/06.
  2pp. 19346:304. 24% Fiche:50-275.83/07/06.8307080464.

- 8307080469 Order clarifying 830628 order scheduling 830719 oral argument on motions to reopen record on const GA. NRC & util should provide witnesses to testify re Board Notification 83-09 & PND-V-83-022A. SHOEMAKER.C. J. Atomic Safety and Licensing Board Panel. 83/07/06. 2pp. 19346: 320. 24X Fiche: 50-275, 83/07/06, 8307080469.
- B307120971 Suppl to Joint Intervenors B30510 motion to reopen record on const QA. Documents submitted are PNO-V-83-022A, notice of violation & IE Insp Rept 50-275/83-20. Certificate of Svc encl.
  - encl.
    REYNOLDS, J.R. Joint Intervenors-Diablo Canyon. REYNOLDS, J.R.
    Center for Law in the Public Interest. 83/07/06. Atomic Safety
    and Licensing Appeal Panel. 4pp. 19433:149. 24X
    Fiche: 50-275, 83/07/06, 8307120571.
- 8307120605 Order extending time until 830808 for Commission to act to review ALAB-728.

  CHILK, S. J. Office of the Secretary of the Commission. 83/07/08.

  Commissioners. 1p. 19432: 268. 24X Fiche: 30-275, 83/07/08.
- 8307130072 Second set of interrogatories propounded to independent design verification program contractors.

  DURBIN.S.L. California: State of: 83/07/08. 20pp. 19474:227. 24X Fiche:50-275.83/07/08.8307130072.
- --8307130074 Second set of interrogatories.Certificate of Svc encl. KAUFMAN,P. H. California, State of. 83/07/08. Pacific Gas & Electric Co. 19pp. 19474:247. 24X Fiche:50-275,83/07/08, 8307130072.
- B307150357 Second set of interrogatories propounded to independent design verification program contractors. DURBIN.S.L. California, State of. B3/07/08. 20pp. 19539:i10. 24X Fiche:50-275, B3/07/08.8307150357.
- --830713036: Second set of interrogatories Certificate of Svc encl. KAUFMAN, P. H. California: State of. 83/07/08. Pacific Gas & Electric Co. 19pp. 19539: 130. 24X Fiche: 50-275, 83/07/08, 8307130357.
- 8307130225 Response to Joint Intervenors 830706 suppl to 830510 motion to reapen record on const QA per ASLAB 830628 order. No objection to suppl record, provided inspiregit & cover ltr included w/hotice of violation. Certificate of Svc encl. CHANDLER.L.J. Hearing Branch 2. 83/07/11. Atomic Safety and Licensing Appeal Panel. 6pp. 19465:294. 24X Fiche: 50-275,83/07/11,8307130225.
- 8307150218 Response to motions to present add1 evidence by requesting acceptance of transmittal ltr & "Rept on Investigation of Reactor Coolant Pipe Weld Thickness at Diablo Canyon." M/o ltr & rept. Certificate of Svc encl.
  CRANE.P.A. Pacific Gas & Electric Co. 83/07/11. Atomic Safety and Licensing Appeal Panel. 4pp. 19537:353. 24X
  Fiche: 50-275,83/07/11,8307150218.
- 8307180070 Response to NRC, Joint Intervenors & CA governor motions to present addl evidence. Rept re reactor coolant pipe weld thickness investigation should be admitted. Wo rept. Gentificate of Svc encl. GRANE, P. A. Pacific Gas & Electric Ca. 83/07/11. Atomic Safety and Licensing Appeal Panel. 4pp. 17540:157. 24X Fiche: 50-275, 83/07/11, 8307180070.
- 8307200203 Motion to compel California Governor Deukmejian answers to 830610 interrogatories. Certificate of Svc encl. Related correspondence.
  NORTON, B. Pacific Oas & Electric Co. NORTON, B. Norton, Burke, Berry & French, 83/07/12. Atomic Safety and Licensing Appeal Panel. 15pp. 17648:119. 24X Fiche: 50-275, 63/07/12, 8307200203.
- 8307200311 Motion to compel Joint Intervenors answers to 830610 interrogatories. Joint Intervenors totally disregarded discovery responsibilities & seek to undermine preparation for hearing. Certificate of Svc ancl. Related correspondence. NORTON. B. Pacific Gas & Electric Co. NORTON, B. Norton, Burke. Berry & French. 83/07/12. Atomic Safety and Licensing Appeal Panel. 24pp. 19648:071. 24X Fiche: 50-275, 83/07/12, 8307200311.
- B307180022 Notice of appearance in proceeding Certificate of Svc encl. MCGURREN, H. J. Hearing Branch 1. 83/07/14. 3pp. 19560:154. 24X Fiche: 50-275, 83/07/14, B307180022.
- 8307170133 Suppl to independent design verification program initial responses to first set of interrogatories. Certificate of Svc encl. Related correspondence.

  RASKIN, D. B. Lowenstein, Newman, Reis, Arelrad & Toll. 83/07/15.

  BIRUMWASSER, M. California, State of REYNOLDS, J. R. Center for Law in the Public Interest. 16pp. 19636:216. 24% Fiche: 30-275, 83/07/15,8307190153.

- 8307200122 Response to first document production request. Certification of counse) encl.

  DURBIN.S L. California, State of 83/07/15. Pacific Gas & Electric Co. 8pp. 19649: 396. 24X Fiche: 50-275,83/07/15,8307200122.
- 8307240253 Response to 830610 first document production request
  Certificate of Svc encl. Related correspondence.
  MAVIAN.E. Joint Intervenors-Diablo Canyon. HAVIAN.E. Center for
  Law in the Public Interest. 83077/15. Pacific Gas & Electric Co.
  6pp. 19727:094 24X Fiche: 50-275,83/07/15,8307260253.
- B307260275 Motion to compel production of documents by Governor Deukmejian Correspondence notes & other gubernatorial documents clearly fall within licensee request Certificate of Svc encl. Related correspondence.
  NORTON.B. Pacific Gas & Electric Co NORTON.B. Norton. Burke.
  Berry & French. B3/07/20. Atomic Safety and Licensing Appeal Panel. 12pp. 19726:193. 24X Fiche: 50-275.63/07/20.8307260275.
- 8307270147 Answers to second set of interrogatories. Certificate of Syc encl. Related correspondence. LOCKE, R. F. Pacific Qas & Electric Co. 83/07/25. California, State of. 66pp. 19765: 26B. 24X Fiche: 50-275, 83/07/25, 8307270147.
- H. General correspondence
- 8307180169 Expresses concerns re erosion problems on Pecho Ranch as result of Oct 1982 fire. Info re 1E procedures requested. Listed pages of addendum to FES for clarification on licensing requirements encl.

  BRUND.G.E. Affiliation Unknown. 83/07/11. DENTON.H. Office of Nuclear Reactor Regulation. Director. 7pp. 19555:086. 24X

  Fiche: 50-275,83/07/11,8307180169.
- 8307180269 Responds to 830701 ltr requesting ASLAB consider concerns. ASLAB cannot consider concerns due to Commission rules of practice. Ltr forwarded to NRR Director, for consideration. BHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. BU/07/14. FUNK, D. J. Pismo Beach, CA. ip. 19556:194, 24X Fiche: 50-275,83/07/14,8307180269.
- --8307180272 Forwards City of Pismo Beach.CA 830701 ltr expressing concerns re San Luis Obispo County emergency response plan.
  Ltr referred for consideration.
  SHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel.
  83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation.
  Director. 1p. 19556:195. 24X Fiche: 50-273,83/07/14.8307180269.
- --8307180274 Expresses concern re plant licensing Deficiencies in San Luis Obispo County emergency plan should be considered. FUNK.D.J. Pismo Beach. CA. 83/07/01. MORRELT. Atomic Safety and Licensing Appeal Panel. 14pp. 19555:196. 24X Fiche:50-275.83/07/14.8307180269.
- P. Operating license stage documents & correspondence
- B306270397 Generic Ltr B3-24 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT, D. G. Division of Licensing, B3/07/09. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, B3/07/05, B306270397.
- O. Inspection reports, IE Bulletins & correspondence
- 8307120512 Forwards IE Insp Repts 50-275/83-19 & 50-323/83-15 on B30501-28 No noncompliance noted. BISHDP.T.W. Region 5. Office of Director. 83/06/24. SCHUYLER.J.G. Pacific Gas & Electric Co. 2pp. 19433:218. 24X Fiche:50-275.83/06/24.8307120512.
- --8307120522 IE Insp Repts 50-275/83-19 & 90-323/83-15 on 830501-28 No noncompliance noted Major areas inspected; plant operations, surveillance testing, maints fMI Item III. B.2. emergency preparedness, preoperational testing & plant tours. CARLSDN.J.D., MENDONCA.M.M., KIRSCH.D.F. Region 9, Office of Director. B3/06/24, 7pp. 19433:220. 24X Fiche: 50-275, B3/06/24, 8307120512.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list enci. JORDAN.E.E. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563: 293. 24X Fiche: 50-000, 83/07/11, 8306270401
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Evo list encl. JORDANIEL. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche:50-000.83/07/12,8306270404.

- 8305270405 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Swc list
  - Radioactive 1-125 & 1-132 & 1-
- 5. Reportable occurrences, LERs & related correspondence
- 8307120582 Interim deficiency rept re malfunction of Limitorque valve operator. Initially reported on 830526 Investigation continuing to confirm extent of problem & determine corrective action. Final rept to be submitted by fuel load. SCHUYLER, J. D. Pacific Gas & Electric Co. 83/06/27. MARTIN, J. B. Region 5. Office of Director. 2pp. 19432:131. 24x Fiche: 50-323, 83/06/27, 8307120582.
- T. Hearing transcripts on non-antitrust matters
- 8307260532 Transcript of 830719 hearing in San Luis Obispo.CA.Pp. 1-225. # Atomic Safety and Licensing Appeal Panel. 63/07/19. 226pp. 19732:107. 24X Fiche: 50-275, 63/07/19, 8307260532.
- 8307270003 Transcript of 830720 hearing in San Luis Obispo.CA.Pp :-498 Atomic Safety and Licensing Appeal Panel. 93/07/20. 273pp. 748:210. 24% Fiche:50-275,83/07/20.8307270003.
- 8307270021 Transcript of 830721 hearing in San Luis Obispo.CA.Pg 499-768 477-766 \* Atomic Safety and Licensing Appeal Panel 83/07/21. 270pp. 19745: 242. 24X Fiche: 50-275: 83/07/21, 8307270021.
- 8307270024 Transcript of 830722 hearing in San Luis Obispo.CA.Pp 1-54. \* Atomic Safety and Licensing Appeal Panel. 83/07/22. 55pp. 19749:204. 24x Fiche: 50-275.83/07/22.8307270024.
- DOCKET 50-324 DRUNSWICK STEAM ELECTRIC PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307140194 Discusses understanding of 830303 & 31 itrs & 0415 telcon re 830517 full-scale energency exercise. Exercise objectives & scenario description coordinated w/State of NC. STOHR.J.P. Division of Emergency Preparedness & Materials Safety. 83/04/20. HOME.P.H. Carolina Power & Light Co. (p. 19522:066, 24X Fiche: 50-324, 83/04/20, 8307140194.
- 8307140357 Describes NRC radio sys & antenna to be installed by util per 830323 meeting Plans will be developed to permit high frequency communications between site & Region II.
  8TOHR.J.P. Division of Emergency Preparedness & Materials Safety.
  83/04/25. UTLEY.E.E. Carolina Power & Light Co. 4pp. 19525: 228.
  24X Fiche: 50-324.83/04/25.8307140357.
- 8307140161 Advises that Boise Interagency Fire Ctr will conduct first radio frequency & electromagnetic interference site survey on 830606-08 to develop communications design & deployment plans & conduct propagational analysis.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/05/31.

  UTLEY, E. E. Carolina Power & Light Co. 23pp. 19523:183. 24X

  Fiche: \$0-324,83/05/31,830714016!.
- 8307140214 Forwards details to IE Insp Repts 50-324/83-16 & 50-325/83-16 on 830517-18 No noncompliance noted Major areas inspected: esercise scenario & emergency organization. VERRELLI.D.M. Division of Project & Resident Programs. B3/06/15. HILEY.E E. Carolina Power & Light Co. 10pp. 19522:008. 24x Fiche: 50-324, 83/06/15, 8307140214.
- 8307110370 Releases public vertion of revised emergency plan & emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/06/24. Docum Management Branch. .1p. 19391:009. 24X Fiche: 50-324, 83/06/24, 8307110370.
- --8307110578 Forwards public version of Rev 8 to emergency response plan & revised smergency plan implementing procedures, including Procedures PEP-02.1 re initial emergency actions & PEP-02.6.4 re radiological control director.

  ZIMMERMAN.S.R. Caroline Power & Light Co. B3/06/01.

  O'REILLY,J.P. Region 2. Office of Director. 2pp. 19371:010. 24X Fiche: 50-324, 83/06/24, 8307110570.
- -G307110386 Public version of revised emergency plan implementing procedures, including Procedures PEP-02. I re initial emergency actions & PEP-02. 6. 4 re radiological control director. Girector BOYER, L. E. Carolina Power & Light Co. B3/05/04 19391:012 24X Fiche:50-324,83/06/24,8307110570.

- -8307110589 Public version of Rev 8 to emergency response plan. BOYER.L.E. Carolina Power & Light Co. B3/05/04. 78pp. 19391:035. 24X Fiche:50-324.83/06/24.8307110570.
- 8307260084 Clarifies info re panetrations in reactor & svc water bldgs, per 830711 telcon. Safe operation assured during time required to perform alternate shutdown capability analysis, establish fire-area boundaries & implement subsequent mod. HOME, P. W. Carolina Power & Light Co. 83/07/21. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19727:307. 24X Fiche: 50-324,83/07/21,8307260084.
- B307270435 Provides clarification of B30502 commitments concerning alternate shutdown capability analysis & proposed mods to comply w/10CFR50, App R.

  ZIMMERMAN, S. R. Carrolina Power & Light Co. B3/07/21. MACKAY, S. D.
  Division of Licensing. 3pp. 19767:186. 24X Fiche: 50-324, 83/07/21, B307270435.
- K. Utility final Safety Analysis Report (FSAR) & amends
- 8307290197 Forwards Amend 1 to updated FSAR.
  UILEV.E.F. Carolina Power & Light Co 83/06/20. DEF
  Office of Nuclear Reactor Regulation. Director. 1p.
  Fiche: 50-324.83/06/20.8307290197. DENTON, H. R 19706:119. 24%
- --9307250211 Amenú 1 to updated FSAR. \* Carolina Power & Light Co. 83/07/20. 314pp. 19706:120. 24X Fiche: 50-324,83/06/20,8307250197.
- P. Operating license stage documents & correspondence
- B30714013B Forwards safety evaluation of BWR Owners Group response to NUREG-0737, Item II. K. 3. 18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure parmissive. VASSALLO. D. B. Operating Reactors Branch 2. 83/06/03. UTLEY, E. E. Carolina Power & Light Co. 2pp. 19528:338. 24X Fiche: 50-324, 83/06/03, 8307140138.
- 8307140137 Advises that requirements of TMI Item II.K.3.13, "HPC1/RCIC Initiation Level," met. Item resolved.

  VASSALLO, D.B. Operating Reactors Branch 2. 83/06/17. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19529: 359.
- 8307140126 Forwards exemption from certain requirements of Section 30,44(c)(3)(ii) re combustible gas control extending date for compliance to 831231. Review of permanent exemption request nearly complete.

  VASSALLO, D. B. Operating Reactors Branch 2. 83/06/21. UTLEY, E. E. Carolina Power & Light Co. 2pp. 19528: 356. 24X

  Fiche: 50-324,83/06/21,8307140126.
- --B307140135 Exemption from certain requirements of Section 50.44(c)(3)(ii) re combustible gas control, extending data for compliance to 831231.

  EISENHUT,D. O. Division of Licensing. 83/06/21. Carolina Power & Light Co. 4pp. 19528: 358. 24X Fiche: 50-324, 83/06/21, 8307140126.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors is clarification of surveillance requirements for dissel fuel impurity. Syc list encl. EISENHUT, D. 0. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307070128 Forwards response to 830511 request for add1 info re NUREO-0737, Item II. K. 3.28, "Qualification of Automatic Depressurization Sys (ADS) Accumulator Sys." Accumulator leakage is of negligible concern. ZIMHERMAN, S.R. Carolina Power & Light Co. 83/07/05. VASSALLO, D. B. Operating Reactors Branch 2. 18pp. 19294: 138. 24% Fiche; 50-324, 83/07/05, 8307070128.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENRUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.
- 8307140251 Confirms schedule for B30708 mgt meeting at Raleigh-Durham Airport, Raleigh, NC to discuss status of outstanding regulatory issues, Proposed meeting agenda encl. O'REILLY, J.P. Region 2, Office of Director. 83/07/06. UTLEY, E.E. Carolina Power & Light Co. 1p. 19523:044. 24X Fiche: 50-000,83/07/06,8307140251.

- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307280295 Requests 830811 meeting w/NRC, Franklin Research Ctr & BNL in Raleigh, NC to discuss NRC 830414 request for add1 info re loads evaluation of plant-unique analysis rept. Responses will be submitted by 830826.

  ZIMMERMAN, S. R. Consumers Power Co. 0Perating Reactors Branch 2 2pp. 19705:322. 24X
  Fiche: 50-324, 83/07/15, 8307250295.
- 8307260498 Application to amend Licenso DPR-62, revising Tech Specs re supression chamber water level monitoring instrumentation per NUREQ-0737, Item II.F. 1. 5. HOWE.P.W. Carolina Power & Light Co. 83/07/22, VASSALLO, D. B. Operating Reactors Branch 2. 3pp. 19731:329, 24x Fiche:50-324,83/07/22,8307260498.
- --8307260504 Tech Spec Tables 3.3.5.3-1 & 4.3.5.3-1 re post-accident monitoring instrumentation & post-accident monitoring instrumentation surveillance requirements, respectively, \* Carolina Power & Light Co. 83/07/22. 2pp. 19731:332, 24X Fiche: 50-324,83/07/22. B307260498.
- 8307270070 Requests review of util 830317 submittal, NRC 830603 itr & clarification re whether NRC request concerning TMI Item II.K. 3.18, "Automatic Depressurization Sys Logic Mods," appropriate.
  ZIMMERMAN.S.R. Carolina Power & Light Co. 83/07/26, VABSALLO, D. B. Operating Reactors Branch 2, 2pp. 19822:149, 24X Fiche: 50-324,83/07/26,8307290070.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140372 Informs that liquid samples spiked w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analyzed for tritium.8r-89 & 8r-90 content within 60 days.

  LEMIS.R.C. Division of Project & Resident Programs. 83/02/07.

  JONES.J.A. Carolina Power & Light Co. 1p. 19523:354. 24X

  Fichs: 50-000.83/02/07.8307140392.
- 8307220204 Forwards IE Insp Repts 50-324/82-28 & 50-325/82-28 on 820712-14 & 20-22 Enforcement action arising from insp addressed in 830218 ltr.
  LEWIS,R.C. Division of Project & Resident Programs. 83/02/22, UTLEY, E.E. Carolina Power & Light Co. 2pp. 19684:041. 24X Fiche: 50-324,83/02/22,8307220204.
- --8307220207 IE Insp Repts 50-324/82-28 & 50-325/82-28 on 820712-14 & 20-22. Noncompliance noted: failure to perform surveillance tests, to prepare surveillance procedures & to take corrective action.

  HARDIN.A.K., MYERB.D.O., GARNER.L.W. Region 2, Office of Director. 82/08/25, 9pp. 19484:043. 24X Fiche: 50-324.83/02/22.8307220204.
- 8306140100 Confirms IE enforcement meeting on 830426 to discuss util actions & atatements re G-list equipment Proposed meeting agenda entl.

  0'REILLY, J. P. Region 2. Office of Director. 83/04/19. UTLEY, E. E. Carolina Power & Light Co. 2pp. 18839:101. 24X
  Fiche: 50-324, 83/04/19, 8306140100.
- 8307140214 Forwards details to IE Insp Repts 50-324/83-16 & 50-325/83-16 on 830517-18. No noncompliance noted Major areas inspected exercise scenario & emergency organization. VERRELLI, D. M. Division of Project & Resident Programs. 83/06/15. WILEY, E. E. Carolina Power & Light Co. 10pp. 19522:008. 24X Fiche: 50-324, 83/06/15, 8307140214.
- 8307130247 Forwards order imposing civil monetary penalties for FR publication. W/o encl.
  AKELRAD, J. A. Director's Office, Office of Inspection and Enforcement. 83/06/29. Docketing & Services Branch. 1p. 19474: 360. 24X Fiche: 50-324, 83/06/29, 8307130247.
- B307220202 Forwards IE Insp Repts 50-324/B3-15 & 50-323/B3-15 on B30415-0515 No noncompliance noted. VERRELLID.M. Division of Project & Resident Programs. B3/04/29, UTLEY, E.C. Carolina Power & Light Co. 2pp. 19684:116. 24X Fiche: 50-324, B3/06/29, B307220202.
- --8307220207 IE Insp Repts 50-324/83-15 & 50-325/83-15 on 830415-0514. No noncompliance noted Major areas inspected operations safety verification, maint, surveillance & LER & plant transient review.
  MEYERS, D. O., GARNER, L. W.: HARDIN, A. K. Region 2, Office of Director. 83/06/21. 7pp. 17684:118. 24X Fiche: 50-324,83/06/27,8307220202.

- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JCRDAN,E L. Divisian of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563.293. 24X Fiche: 50-000.83/07/11.8306270401.
- B306270404 IE Info Notice B3-47. "Failure of Hydravlic Snubbers as Result of Contaminated Hydravlic Fluid." Svc list encl.

  JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830)03). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563.193. 24X Fiche 50-000.83/07/12.8306270404.
- 8307220294 Ack receipt of 830424 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~324/83-03 & 50~325/83-03. LEMIS.R.C. Division of Project & Resident Programs. 83/07/13. UTLEY.E.E. Carolina Power & Light Co. 1p. 19693:233. 24X Fiche: 50~324/83/07/13. 8307220299
- --8307220298 Responds to NRC 830525 ltr re violations noted in 1E Insp Repts 50-324/83-03 & 50-325/83-03. Corrective actions: Plant Procedure FH-11 re control fuel movements revised to require control rod insertion prior to moving fuel. UTLEY.E.E. Carolina Power & Light Co. 83/06/24. G'REILLY, J. P. Region 2. Office of Director. Spp. 19683: 234. 24X Fiche: 50-324, 83/07/13, 8307220294
- --8307220301 Forwards IE Insp Repts 50-324/83-03 & 50-325/83-03 on 821215-830215 & notice of violation.

  U'REILLY, J. P. Region 2, Office of Director. 83/05/25. UTLEY, E. E. Carolina Power & Light Co. 2pp. 19683:239. 24x

  Fiche: 50-324.83/07/13.8307220294.
- --8307220307 Notice of violation from insp on 821215-830215 # Region 2, Office of Director. 83/05/25. 2pp. 19883-241. 24X Fiche: 50-324, 83/07/13, 8307220294.
- --B307220317 IE Insp Repts 50-324/83-03 & 50-325/83-03 on 821215-830215.

  Noncompliance noted: failure to adequately review procedure change promptly isolate reactor water cleanup & implement refueling operation procedures.

  MYERS.D.O. OARNER, L.W. Region 2. Office of Director. BEMIS.P. Division of Project & Resident Programs. B3/05/24. 16pp.

  19483: 243. 24X Fiche: 50-324. 83/07/13.8307220294.
- 8307220962 Ack receipt of B30524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-10 & 50-325/83-10.

  LEWIS.R.C. Division of Project & Resident Programs. B3/07/13.

  UTLEY.E.E. Carolina Power & Light Co. 1p. 19684.309. 24X

  Fiche: 50-324.83/07/13.8307220562.
- --8307220966 Responds to NRC 830523 ltr re violations noted in lE Insp Repts 50-324/83-10 & 50-325/83-10. Corrective actions: administrative instructions for procedural rev being rewritten. DIETZ.C.R. Carolina Power & Light Co. 83/06/24. O'REILLY.J.P. Region 2. Office of Director. 2pp. 19684:310. 24X Fiche:50-324,83/07/13,8307220562.
- --8307220869 Forwards IE Insp Repts 50-324/83-10 % 50-328/83-10 on 830313-0415 & notice of violation.

  CEWIS.R.C. Division of Project & Resident Programs. 83/05/23. UTLEY.E.E. Carolina Power & Light Co. 2pp. 19684:312. 24X Fiche: 50-324,83/07/13,8307220562.
- --8307220571 Notice of violation from insp on 830315-0415.

  \* Region 2, Office of Director. 83/05/23. 1p. 19684:314. 24X Fiche:50-324,83/07/13,8307220562.
- --8307220576 IE Insp Repts 50-324/83-10 % 50-325/83-10 on 830315-0415.
  Noncompliance noted: failure to establish & implement procedure for tracking temperary procedure changes.
  MYERS, D. D., GARNER, L. W. Region 2, Office of Director. BEMIS, P. Divisian of Project & Resident Programs. 83/05/20. 10pp.
  19684.315. 24X Fiche: 50-324,83/07/13,8307220562.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Linits." Svc list encl. TAYLOR. J. M. Division of QA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- 8307190042 Forwards response to IE Bulletin 83-02. "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants." Ultrasonic sys leak tests indicate no immediate concern. Continued operation justified HOWE, P. W. Carolina Power & Light Co. 83/07/14. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19635: 136. 24X Fiche: 50-324, 83/07/14, 8307190042.

# R. Periodic operating reports & related correspondence

- B307130212 Monthly operating repts for June 1983. W/B30706 ltr. MARRISUN.F., DIETZ.C.R. Carolina Power & Light Co. B3/07/06. Enforcement. 12pp. 19508:052. 24X Fiche: 50-324.63/07/06.
- S. Reportable occurrences. LERs & related correspondence
- B307150242 LER B3-054/03L-0: on B30405, while withdrawing control rods to increase reactor power level, control rod 26-19 did not have RTGB position indication as required. Caused by faulty position indication probe W/B30705 itr. PASTVA.M. J. DIETZ.C.R. Carolina Power & Light Co. 83/04/05. D'REILLY, J.P. Region 2, Office of Director. 2pp. 19531: 093. 24X Fiche: 50-324, 83/04/05, 8307150242.
- 8307120129 LER 83-054/03L-0:on 830530, reactor turbine generator board indicators 2-CAC-LT-2601-1 & 2601-3 showed erroneous indications. Caused by demineralized water spraying on transmitter 2-CAC-LT-601, M/830628 ltr. PASTVA, M. J., DIETZ, C. R. Carolina Power & Light Co. 83/06/28, 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19423:052. 24x Fiche: 50-324, 83/06/28, 8307120129.
- 8307110432 LER 83-051/03L-0: on 830524, while performing PT-03.1.2P, HPCI sys condensate storage tank low water level instrument 2-E41-LSL-NOO3 did not respond to applied test input. Caused by deposit blockage of instrument vent line. M/830701 ltr. PDULK.R. H., DIETZ.C.R. Carolina Power & Light Co. 83/07/01. D'REILLY.J.P. Region 2, Office of Director. 3pp. 19382:245. 24X Fiche: 50-324, 83/07/01, 8307110432.
- B307150024 LER B3-05B/03L-0:on B30606.HPC1 sys steamline area differential temp high logic A isolation signal occurred causing automatic closure of HPC1 sys steam supply outboard valve PCIV 2-E41-F003.W/830706 ltr.
  PASTVA.M.J. DIETZ, C.R. Carolina Power & Light Co. B3/07/06. B1/07/06. B1/07/06. B1/07/06. B1/07/06. B3/07/06. B1/07/06. B3/07/06. B3/07/06.
- B307260496 RO: on B30601, gamma analysis of two bottom sediment samples detected excessive Co-60 concentration at Sample Stations 33 & 34. No Tadiation hazard or exposure to public Sampling frequency increased, BIETZ, C. R. Carolina Power & Light Co. B3/07/18. O'REILLY, J. P. Region 2, Opfice of Director. 2pp. 19733:254. 24X Fiche: 50-324, 83/07/18, 830/260496.
- 8307260404 LER 83-063/03L-0: on 830624, while securing from ventilation purging of dryweil/suppression pool atmosphere, exhaust valve Z-CAC-V22 would not fully close using valve motor operator. Cause not stated. Investigation underway. W/830719 ltr. PASTVA.M.J., DIETZ.C.R. Carolina Power & Light Co. 83/07/19. U'REILLY.J.P. Region 2. Office of Director. 2pp. 19733:061. 24X Fiche: 50-324,83/07/19,8307260404.
- 8307270132 RD 2-SR-83-18:on 830614, five barrier limiting conditions for operations generated for two fire doors in diesel generator bldg. Two fire doors declared inoperable due to broken counterbalance spring & misalignment.
  DIETZ.C.R. Carolina Famour & Light Co. 83/07/21. O'REILLY, J.P. Region 2, Office of Director. 2pp. 19822:074. 24X
  Fiche: 50-324, 83/07/21, 8307270132

# V. Operator Examinations

- 8307140248 Forwards list of randomly selected candidates & five alternates for operator & senior operator requalification erams, per 830415 ltr.

  O'REILLY, J. P. Region 2, Office of Director. 83/06/15, HDWE, J. P. Carolina Power & Light Co. 2pp. 19523:048. 24X

  Fiche: 50-324, 83/06/15, 8307140248.
- 8307260460 Requests that individuals from technical staff, meeting shift technical advisor requirements be permitted to augment four fully qualified advisers until completion of current license class scheduled for Feb 1984.

  HDMELP.W. Caralina Power & Light Co. 83/07/21. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19728: 360. 24x

  Fiche: 50-324,83/07/21,8307260460.

- DDCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

  F. Security, medical, emergency & fire protection plans
- B307140194 Discusses understanding of B30303 & 31 ltrs & 0415 telcon re 830517 full-scale emergency exercise. Exercise abjectives & scenario description coordinated w/State of NC. STORR.J.P. Division of Emergency Preparedness & Materials Bafety, 83/04/20. HOME.P.W. Carolina Power & Light Co. 1p. 19522:066. 24X Fiche: 50-324, 83/04/20, 8307140194.
- 8307140337 Describes NRC radio sys & antenna to be installed by util per 830323 meeting. Plans will be developed to permit high frequency communications between site & Region II. STOHR, J. P. Division of Emergency Preparedness & Materials Bafety. 83/04/25. UTLEY, E. E. Carolina Power & Light Co. 4pp. 19525: 228, 24% Fiche: 50-324, 83/04/25, 8307140397.
- 8307140161 Advises that Boise Interagency Fire Ctr will conduct first radio frequency & electromagnetic interference site survey on 830606-08 to develop communications design & deployment plans & conduct propagational analysis.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/05/31.

  UTLEY, E. E. Carolina Power & Light Co. 23pp. 19523: 183, 24x Fiche: 30-324, 83/05/31, 8307140161.
- B307140214 Forwards details to IE Insp Repts 50-324/83-16 & 50-325/83-16 on 830517-18. No noncompliance noted Major areas inspected: exercise scenario & emergency organization. VERRELLI.D.M. Division of Project & Resident Programs. 83/06/15. H1LEY.E.E. Carolina Power & Light Co. 10pp. 17522:008. 24X Fiche: 50-324, 83/06/15, 8307140214.
- 8307110570 Releases public version of revised emergency plan & emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19391:007. 24X Fiche: 50-324, 83/06/24, B307110570.
- --8307110578 Forwards public version of Rev 8 to emergency response plan & revised emergency plan implementing procedures, including Procedures FEP-02.1 re initial emergency actions & FEP-02 6.4 re radiological control director.

  ZIMMERMAN.S.R. Carolina Power & Light Co. 83/06/01.

  0'REILLY.J.P. Region 2. Office of Director. 2pp. 19391:010. 24x Fiche: 50-324,83/06/24,8307110570.
- --8307it0386 Public version of revised emergency plan implementing procedures including Procedures PEP-02.1 re initial emergency actions & PEP-02.6.4 re radiological control director.

  BOYER, L. E. Carolina Power & Light Co. 83/05/04. 23pp. 19391:012. 24X Fiche: 50-324.83/06/24.8307110370.
- ~-8307110589 Public version of Rev 8 to emergency response plan. BOYER, L. E. Carolina Power & Light Co. 83/05/04, 78pp. 19391: 035. 24X Fiche: 50~324, 83/06/24, 8307110570.
- B3072600B4 Clarifies info re penetrations in reactor & svc water bldgs, per B30711 telcon. Safe operation assured during time required to perform alternate shutdown capability analysis, establish fiter-area boundaries & implement subsequent mod. HOME, P. M. Carolina Power & Light Co. B3/07/21. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 19727: 307. 24X Fiche: 50-324, 83/07/21, 8307260084.
- 8307270435 Provides clarification of 830502 commitments concerning alternate shutdown capability analysis & proposed mods to comply w/10CFR50, App R. ZIMMERMAN, S. R. Carolina Power & Light Co. 83/07/21. MACKAY, S. D. Division of Licensing. 3pp. 19767:186. 24X Fichs:50-324,83/07/21,83/07/21,
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307230197 Forwards Amend 1 to updated FSAR.

  UTLEY, E. E. Carolina Power & Light Co. 83/06/20. DENTON, H. R.

  Diffice of Nuclear Reactor Regulation, Director. ip. 19706: 119. 24X

  Fiche: 50-324,83/06/20,8307250197.
- --8307250211 Amend I to updated FSAR. \* Carolina Power & Light Co. 83/07/20. 314pp. 19706:120. 24X Fiche: 50~324,83/06/20,8307250197.

#### P. Operating license stage documents & correspondence

- 8307140138 Forwards safety evaluation of BUR Owners Group response to NUREG-0737. Item IT K. 3. 18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO. D. B. Operating Reactors Branch 2. 83/06/03. UTLEY, E. Carolina Power & Light Co. 2pp. 19328: 338. 24X Fiche: 50-324.83/06/03.8307140138.
- B307180446 Forwards monthly FR notice of amends to DLs involving NSHC. \* Office of Nuclear Reactor Regulation, Director. 83/06/15. UHRIO,R.E. Florida Power & Light Co. 2pp. 19641:347. 24X Fiche:30-000.83/06/15.8307180446.
- --8307190001 Monthly notice of amends to OLs involving NSHC. CLARK.R.A. Operating Reactors Branch 3. 83/06/07. 15pp. 19641:349. 24X Fiche:50-000.83/06/15.8307180446.
- B307140137 Advises that requirements of TM1 Item II.K.3.13, "HPC1/RCIC Initiation Level," met. Item resolved.

  VASSALLO.D.B. Operating Reactors Branch 2. 83/06/17. UTLEY.E.E. Carolina Power & Light Co. 2pp. 19529: 359. 24K
  Fiche: 50-324, 83/06/17, 8307140137.
- B307140126 Forwards exemption from certain requirements of Section 80.44(c)(3)(ii) re combustible gas control, extending date for compliance to B31231. Review of permanent exemption request nearly complete.

  VASSALLO.D.B. Operating Reactors Branch 2. 83/06/21. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19528: 356. 24X

  Fiche: 50-324, 83/06/21, 8307140126.
- --8307140135 Exemption from certain requirements of Section 50.44(c)(3)(ii) re combustible gas control, extending date for compliance to 831231.

  EISEN(UT.D. G. Division of Licensing. 83/06/21. Carolina Power & Light Co. 4pp. 19528:358. 24X Fiche:50-324.83/06/21, 8307140126.
- 8307130018 Forwards Amend 56 to License DPR-71 & safety evaluation. Amend changes Tech Specs to establish revised operating limits for Fuel Cycle 4 & changes control rod scram insertion times.

  VASSALLO, D. B. Operating Reactors Branch 2. 83/06/28. UTLEY, E. E. Garolina Power & Light Co. 2pp. 19511:316. 24X

  Fiche: 50-325, 83/06/28, 8307130018.
- --8307130021 Amend 56 to License DPR-71, changing Tech Specs to establish revised operating limits for Fuel Cycle 4 & changing control red scram insertion times.
  VASSALLG.D. B. Operating Reactors Branch 2. 83/06/28. 33pp. 17511:318. 24X Fiche:50-325.83/06/28.8307130018.
- --8307130025 Safety evaluation supporting Amend 56 to License DPR-71.

  \* Office of Nuclear Reactor Regulation, Director: 83/06/28. 6pp
  19911:351. 24X Fiche:50-325,83/06/28.8307130018.
- B306270397 Ceneric Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307070128 Forwards response to 830511 request for addl info re NUREG-0737, Item II. K. 3. 28, "Gualification of Automatic Depressurisation Sys (ADS) Accumulator Sys." Accumulator leakage is of negligible concern.
  218MERMAN.S.R. Carolina Power & Light Co. 83/07/05, VASSALLO, D. B. Operating Reactors Branch 2. 18pp. 19294:138. 24X Fiche: 50-324, 83/07/05, 8307070128.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS, Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307140251 Confirms schedule for 830708 mgt meeting at Raleigh-Durham Airport, Raleigh.NC to discuss status of outstanding regulatory issues, Proposed meeting agenda encl. G'REILLY, J. P. Region 2, Office of Director. 83/07/06. UTLEY, E. Carolina Power & Light Co. 1p. 19523:044. 24X Fiche: 30-000, 83/07/06, 8307140251.

- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl. EISENHUT, D. G. Division of Licensing 83/07/08. Consolidated Edison Co of New York, Inc. 38pp 1969:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 8307250295 Requests 830811 meeting w/NRC.Franklin Research Ctr & BNL in Raleigh, NC to discuss NRC 830414 request for addl info re loads evaluation of plant-unique analysis rept. Responses will be submitted by 830826.
  ZIMMERMAN, S. R. Consumers Power Co. 83/07/15 VASSALLO, D. B. Operating Reactors Branch 2. 2pp 19705, 322, 24% Fiche: 50-324, 83/07/15, 8307250295.
- 8307290090 Requests review of util 830317 submittal.NRC 830403 ltr & clarification re whether NRC request concerning IMI Item II.K.S.18. "Automatic Depressurization Sys Logic Mods." appropriate.
  2IMMERMAN.S.R. Carolina Power & Light Co. 83/07/26. VASSALLO.D.B. Deparating Reactors Branch 2. 2pp. 19622:149 24X
  Fiche: 90-324, 83/07/26, 8307290090.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140392 Informs that liquid samples spited w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analyzed for tritium:87-89 & Sr-90 content within 60 days.

  LEWIS.R. C. Division of Project & Resident Programs. 83/02/07.

  JONES.J. A. Carolina Power & Light Co. 1p. 19523;354. 24X

  Fiche: 50-000.83/02/07.8307140392.
- 8307220204 Forwards 1E Insp Repts 50-324/82-28 & 50-325/82-28 on 820712-14 & 20-22 Enforcement action arising from insp addressed in 830218 ltr.

  LEWIS, R. C. Division of Project & Resident Programs. 83/02/22.

  UTLEY, E. E. Carolina Power & Light Co. 2pp. 19684.041. 24X Fiche: 50-324.83/02/22,8307220204.
- ~-8307220209 IE Insp Repts 50-324/82-28 & 50-325/82-28 on B20712-14 & 20-22. Noncompliance noted: Fashure to perform surveillance tests, to prepare surveillance procedures & to take corrective action.

  HARDIN, A. K., MYERS, D. O., GARNER, L. W. Region 2, Office of Director. 82/08/25. 9pp. 19684:043. 24X Fiche: 50-324, 83/02/22, 8307220204
- B306140100 Confirms IE enforcement meeting on 830426 to discuss util actions & statements re Q-list equipment Proposed meeting agenda encl.

  0'REILLIV.J.P. Region 2. Office of Director. B3/04/19. UTLEY.E.E. Carolina Power & Light Co. 2pp. 18839:101. 24X
  Fiche: 50-324,83/04/19,8306140100.
- 8307140214 Forwards details to IE Insp Repts 50-324/83-16 & 50-325/83-16 on 830517-18. No noncompliance noted Major areas inspected: exercise scenario & emergency organization.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/06/15.

  WILEY, E. E. Carolina Power & Light Co. 10pp. 19522:008. 24%

  Fiche: 50-324, 83/06/15, 8307140214.
- 8307130247 Forwards order imposing civil monetary penalties for FR publication M/o encl.

  AXELRAD.J.A. Director's Office Office of Inspection and Enforcement. 83706/29. Docketing & Services Branch. 1p. 19474:360. 24X Fiche:80-324.83/06/29.8307130247.
- B307220202 Forwards IE Insp Repts 50-324/83-15 % 50-325/83-15 on B30415-0515 No noncompliance noted VERRELLI,D.M. Division of Project & Resident Programs. B3/06/29. UTLEY,E.E. Carolina Power & Light Co. 2pp. 19684:116. 24X Fiche; 50-324,83/06/29,8307220202.
- --8307220207 IE Insp Repts 50-324/83-15 & 50-325/83-15 on 830415-0514. No noncompliance noted Major areas inspected operations safety verification maint, surveillance & LER & plant transient review.

  MEYERS, D. D. GARNER, L. M., HARDIN, A. K., Region 2, Office of Director. 83/06/21, 9pp. 19684 118 24X Fiche 50-324,83/06/29,8307220202.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list enci. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11 Consolidated Edison Co. of New York: Inc. 154pp. 19563:293. 24X Fiche 50-000.83/07/11.8306270401
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDAN, E. L. Division of Emergency Proparodness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 14ipp. 19563:153. 24X Fiche: 50-000, B3/07/12, B306270404.

- 8307220294 Ack receipt of 830624 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-324/83-03 & 50-325/83-03.

  LEWIS.R.C. Division of Project & Resident Programs. 83/07/13.

  LEWIS.R.C. Carolina Power & Light Co. 1p. 19683:233. 24X

  Fix8e:30-324.83/07/13.8307220294.
- --B307220298 Responds to NRC 830525 itr re violations noted in IE insp. Repts 50-324/83-03 & 50-325/83-03. Corrective actions:Plant Procedure Firl re control fuel movements revised to require control red insertion prior to moving fuel.

  UTLEY.E.E. Carolina Power & Light Co. 83/06/24. O'REILLY, J. P. Region 2, Office of Director. Spp. 19683:234. 24X Fiche: 50-324, 83/07/13, 8307220294.
- --B307220301 Forwards IE Insp Repts 50-324/83-03 & 50-325/83-03 on 821215-830215 & notice of violation.

  O'REILLY, J. P. Region 2. Office of Director. 83/05/25. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19683: 239. 24X

  Fich: 50-324, 83/07/13, 8307220294.
- --B307220307 Notice of violation from insp on 821215-830215. \* Region 2, Office of Director. B3/05/25. 2pp. 196B3; 241. 24X Fiche. 30-324. 83/07/13, B307220294.
- --8307220317 IE Insp Repts 50-324/83-03 & 50-325/83-03 on 821215-830215.

  Noncompliance noted: failure to adequately review procedure change-promptly isolate reactor water cleanup & implement refuelting operation procedures.

  MYERS.D. O. GARNER.L. W. Region 2, Office of Director. BEMIS.P. Division of Project & Resident Programs. 83/05/24. 16pp. 19683:243. 24X Fiche: 50-324.83/07/13.8307220294.
- B307220542 Ack receipt of B30424 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-10 & 50-325/83-10. LENIS.R.C. Division of Project & Resident Programs. B3/07/13. LENIS.R.C. Division of Project & Resident Programs. B3/07/13. UTLEY.E.E. Carolina Power & Light Co. 1p. 17484:309. 24X Fiche: 50-324,83/07/13,8307220542.
- --B307220966 Responds to NRC B30523 ltr re violations noted in IE Insp. Repts 50-324/83-10 & 50-325/83-10. Corrective actions: administrative instructions for procedural rev being rewritten.

  DIETZ.C.R. Carolina Power & Light Co. 83/06/24. 0'REJLLY, J. P. Region 2, Office of Director. 20p. 17684:310. 24X Fiche: 50-324.83/07/13,8307220562.
- --8307220559 Forwards IE Insp Repts 50-324/83-10 & 50-325/83-10 on 830313-0415 & notice of violation.
  LEWIS.R.C. Division of Project & Resident Programs. 83/05/23.
  UTLEY.E.E. Carolina Power & Light Co. 2pp. 19684:312. 24X
  Fiche: 50-324,83/07/13,8307220562.
- --8307220571 Natice of violation from thep on 830315-0415. \* Region 2, Office of Director. 83/05/23. ip. 19684:314. 24X Fiche:50-324.83/07/13,8307220562.
- --8307220576 IE Insp Repts 50-324/83-10 & 50-325/83-10 on 830315-0415.
  Noncompliance noted: failure to establish & implement procedure for tracking temporary procedure changes.
  MYERS.D.O., GARNER, L.W. Region 2. Office of Director. BEMIS.P.
  Division of Project & Resident Programs 83/05/20. 10pp.
  19684:315. 24% Fiche: 50-324.83/07/13.8307220562.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Syc list encl. TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307200150 Commits to submit plan for add1 insp of recirculation piping welds of 20-inch diameter or larger for stress corrosion cracking during Nov 1983 Mar 1984 outage within 30 days of issuance of confirmatory order. HURFORD, M. J. Carolina Power & Light Co. 83/07/19. VABSALLO, D. N. Ugsrating Reactors Branch 2. ip. 19691 251. 24X Fiche: 50-325, 83/07/19, 8307200190.
- R. Periodic operating reports & related correspondence
- 8307130212 Nonthly operating repts for June 1983 M/830706 ltr.
  MARRISON.F., DIETZ.C.R. Carolina Power & Light Co. 83/07/06.
  DEYOUNG.R.C. Director's Office. Office of Inspection and
  Enforcement. 12pp. 19508:052. 24X Fiche 50-324,83/07/06.
  8307130212.

- S. Regortable occurrences, LERs & related correspondence
- B3D7110510 LER 83-024/03L-0: on B30602, during refueling outage, position indication light for B core spray inboard injection valve inoperable. Caused by plant personnel inadvertently bumping witch to off position. W/830630 ltr. POULK: R. M., DIETZ, C. R. Carolina Power & Light Co. 83/06/30. 0'REILLY, J. P. Region 2, Office of Director. 3pp. 19385:344. 24X Fiche: 50-325, 83/06/30, 8307110510.
- 8307120271 Updated LER 83-019/03L-1: on 830425, standby liquid control sys relief valve operability test revealed SLCS valves 1-041-f029A & f0298 lifted at 1321 psig & 1392 psig, respectively. Caused by setpoint drift, W/830630 ltr. PARTVA,M. J., DIETZ,C.R. Carolina Power & Light Co. 83/06/30, 0/8ETLLY,J.P. Region 2, Office of Director. 3pp. 19424:067. 24x Fiche: 50-325, 83/06/30, 8307120291.
- 8307150102 LER 83-028/03L-0: on 830606, supervisory review determined that standby liquid control sys unknowingly rendered inoperable for 1 h 20 minutes on 830604. Caused by personnel failure to update log index. M/830706 itr. PASTVA, M. J. DIETZ, C. R. Carolina Power & Light Co. 83/07/06. 0/REILLY, J. P. Region 2, Office of Director. 3pp. 19536:127. 24X Fiche: 50-325, 83/07/06, 8307150102.
- 8307220405 LER 83-014/03L-0: on 830406 & 08, during ongoing refueling, 1isted control rods had no indications for identified positions. Caused by defective prototypic inlet piping (PJP) connectors, reed switch & PJP probe. W/830712 ltr. PASTVA, M. J. DIETZ, C. R. Carolina Power & Light Co. 83/07/12. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19687: 358. 24X Fiche: 50-325, 83/07/12, 8307220405.
- 8307260496 RD: on 830601, gamma analysis of two bottom sediment samples detected excessive Co-60 concentration at Bample Stations 33 & 34. No radiation hazard or exposure to public Sampling frequency increased.

  DIETZ.C.R. Carolina Power & Light Co. B3/07/18. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19733: 254. 24X Fiche: 30-324. 83/07/18. B307260496.
- B307260397 Updated LER B3-017/03L-1: on B30326-28 & 0402, listed control rods had no indications for identified positions. Caused by loose prototypic inlet piping connectors due to undervessel work. Connectors will be properly fastened. W/830719 1tr. PABTVA.M.J., DIETZ.C.R. Carolina Power & Light Co. B3/07/19. U/REILLY.J.P. Region 2, Office of Director. 2pp. 19733:116. 24X Fiche: 50-325, 83/07/19, B307260397.
- U. Congressional/Executive Correspondence
- 8307270047 Forwards monthly FR notice of consideration of issuance of amends to OLs involving NSHC determination & apportunity for hearing.

  DENTON, H. R. Office of Nuclear Reactor Regulation, Director.

  83/04/22. STAFFORD.R.T. Senate, Environment & Public Works. 2pp.
  17811:018. 24X Fiche: 50-000,83/04/22,8307270047.
- --8307270050 Monthly notice of consideration of issuance of amends to DLs involving NSHC determination & apportunity for hearing. CLARK, R. A. Deerating Reactors Branch 3. 83/06/07. 15pp. 19811:020. 24X Fiche: 50-000, 83/06/22, 8307270047.
- V. Operator Examinations
- B30714024B Forwards list of randomly selected candidates & five alternates for operator & senior operator requalification exams, per B30415 ltr.
  O'REILLY, J. P. Region 2, Office of Director. B3/06/15. HDME, J. P. Carolina Power & Light Co. 2pp. 17523:048. 24X
  Fiche: 50-324, B3/06/15, B307140248.
- 8307260460 Requests that individuals from technical staff, meeting shift technical advisor requirements be permitted to augment four fully qualified advisors until completion of current license class scheduled for Feb 1788.

  HOME.P.M. Carolina Power & Light Co. 83/07/21. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17728: 360. 24X

  Fiche: 50-324,83/07/21,8307260460.
- DOCKET 50-326 UNIV. OF CALIFORNIA AT IRVINE RES. REACTOR
  R. Periodic operating reports & related correspondence
- 8307010168 "Annual Operating Rept for 820701-830625."
  MILLER, G. E. California, Univ. of, Irvine. 83/06/27. Director's Office, Office of Inspection and Enforcement. 23pp. 19124:239. 24x Fiche: 50-326, 83/06/27. 8307010168.

# 5. Reportable occurrences. LERs & related correspondence

- 8307010171 RD: on 830624, fast transient rod failed to insert when scrammed. Caused by dryness of air-cylinder portion of rod drive. Sys completely cleaned w/solvent & seals inspected.
  MILLER, G. E. California, Univ. of, Irvine. 83/06/25.
  Standandization & Special Projects Branch. 1p. 19169:226. 24X
  Fiche: 50-326, 83/06/25, 8307010171.
- B307210237 RO: on B30701, during withdrawal of adjustable transient rod cylinder, control rod began to withdraw. Probably caused by dirt in air sys due to clogged permanent filter. Regular maint of filter planned.

  ROGERS, P. J. California. Univ. of, Irvine. B3/07/08.
  Btandardization & Special Projects Branch. 2pp. 19644:182. 24X
  Fiche: 50-326:83/07/08:8307210237.

#### V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess resissuance of NRC Form 398, "Personal Qualifications
Btatement - Licensee." Svc list encl.
EIBENHUT, D. G. Division of Licensing. 83/07/11. Michigan. Univ.
of. 14pp. 19563:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

#### DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8307140220 Ack receipt of 830513 itr re emergency exercise scheduled during Jul 1983. Scenario presently under review. Any addition will be made by telcon will Marks.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/06/21. PARR18, H. C. Tennessee Valley Authority. 1p. 19923:164. 24X Fiche: 50-327, 83/06/21. 8307140220.
- 8307140340 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-08 & 50-328/83-08.

  LEWIS,R.C. Division of Project & Resident Programs. 83/06/27. PARRIS,H.G. Tennessee Valley Authority. 1p. 17525:235. 24X Fiche: 50-327,83/06/27,8307140340.
- --8307140349 Submits revised response to NRC 830917 ltr re violations noted in IE Insp Repts 50-327/83-08 £ 50-328/83-08 Corrective actions: site-specific health physics training will be required as of 830627, for unescorted access.
  MILLS, L.M. Tennessee Valley Authority. 83/06/24. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17525: 236. 24X Fiche: 50-327, 83/06/27, 8307140340.
- --B307140351 Responds to NRC 830617 ltr re violations noted in IE Insp. Repts 50-327/83-08 & 50-328/83-08. Corrective actions: personnel reinstructed re general escort responsibilities, including desimetry requirement.

  MILLS.L.M. Tennessee Valley Authority. 83/06/16. 0'REILLY, J.P. Region 2. Office of Director. 4pp. 19325:240. 24X Fiche:50-327,83/06/27,8307140340.
- --8307140355 Forwards IE Insp Repts 50-327/83-08 & 50-328/83-08 on B30412-15 & notice of violation.
  LEWIS,R.C. Division of Project & Resident Programs. B3/05/17.
  PARRIS,H.G. Tennessee Valley Authority. 2pp. 19325:244. 24X Fiche: 50-327, B3/06/27, B307140340.
- --B307140363 Notice of violation from insp on B30412-15.

  \* Region 2, Office of Director. B3/05/17. 2pp. 19525:246. 24X ficha: 50-327, 83/06/27, 8307140340.
- --8307140368 IE Insp Repts 50-327/83-08 & 50-328/83-08 on 830412-15.

  Noncompliance noted: failure to issue proper dosimetry to & to provide adequate radiation protection training for two individuals.

  CULLINS.T.R. Region 2. Diffice of Director. BARR.K.P. Division of Emergency Preparedness & Materials Safety. 83/05/10. 7pp. 19525: 248. 24X Fiche: 50-327, 83/06/27, 8307140340.
- 8307140258 Discusses 830705 conversation between B Marks & ON Huffman re training requirements for NRC & contract personnel entering facilities. List of NRC & NRC contract personnel observing emergency exercise encl.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/07/08.

  PARRIS.H. G. Tennessee Valley Authority. 3pp. 19523:004. 24X

  Fiche: 50-327, 83/07/08, 8307140258.
- 8307140158 Forwards IE Bafeguards Insp Repts 50-327/83-11 & 50-328/83-11 on 830606-10. No noncompliance noted. VERRELLI.D. Division of Project & Resident Programs. 83/07/11 PARRISH.9. Tennessee Valley Authority. 2pp. 19523:213. 24X Fiche: 50-327, 83/07/11, 8307140158.

- ---B307140165 IE Safeguards Insp Repts 50-327/83-11 to 50-328/83-11 on 830606-10. No noncompliance noted Major areas inspected; site orientation, security plan to implementing procedure to security organization mgt. Details withheld (ref 10CFR73, 21). MOORE, D. E. Region 2. Defrice of Director. MCGUIRE, D. R. Division of Emergency Preparedness to Materials Safety. 83/07/08. 1p. 19523-215. 24X Fiche: 50-327, B3/07/11, B307140158
- B307250219 Advises that util emergency operating instruction being revised to manually energize permanent hydrogen mitigation system to delay in completion of Wastinghouse Owners Group emergency response guidelines.
  MILLS.L.M. Tennessee Valley Authority. B3/07/19. ADENSAM.E. Licensing Branch 4. 2pp. 19706:030. 24x Fiche: 50-327.83/07/19. B307250219.

#### J. Insurance & indemnity information

- 8307080031 Forwards Endorsement 33 to NELIA Policy NF-47 & Endorsement 27 to MAELU Policy NF-102.

  DUCK, J. R. Marsh & McLennan, Inc. 83/04/30. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19351: 313. 24X Fiche: 50-327, 83/04/30. 8307080031.
- 8307200008 Forwards Endorsement 34 to NELIA Policy NF-247 & Endorsement 28 to MAELU Policy MF-102.

  BUCK, J.R. Marsh & McLennan, Inc. 83/07/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19647:173. 24X Fiche: 50-327, 83/07/15, 8307200008.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensessapplicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24% Fiche:50-000.83/06/03. 8306060070.
- B307080259 Forwards backfit cost figures for add1 seven utils per original 830208 request Cost figures for 20 utils transmitted B30411. TOURTELLOTTE, J. Regulatory Reform Task Force. B3/06/22. PALLADINO.N. Commissioners. 2pp. 19363:313. 24X Fiche: 50-000, 83/06/22, 8307080259.
- --8307080358 Forwards backfit cost estimates for facilities.per NRC 830315 ltr.Costs do not reflect extending scheduled outages due to backfits & mods.
  PARRIS.H.G. Tennessee Valley Authority. 83/05/02.
  TOURTELLOTTE.J. Regulatory Reform Task Force. 5pp. 19364:009. 24% Fiche: 50-000, 83/06/22, 8307080259.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. BISENHUT, D. G. Division of Licensing. B3707705. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, B3/07/05, B306270397.
- B307060329 Generic Ltr B3-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT. D. G. Division of Licensing. B307706 Consolidated Edison Co. of New York, Inc. 16pp. 19669-254. 24X Fiche: 50-000.83/07/06.8307060329.
- B307080169 Generic Ltr 83-28 to all licensers of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. ETSENHUT. D. 6: Division of Licensing. 82/67/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08. 8307080169.
- 8307190166 Forwards LOCA (major RCS pipe ruptures) reanalysis for Cycle 2 assuming 2% uniform steam generator tube plugging & containment purging at time of accident.

  HILLS, L.M. Tennessee Valley Authority. 83/07/14. ADENSAM.E. Licensing Branch 4. 80pp. 19636:264. 24% Fiche:50-327.83/07/14. 8307190166.
- 8307260207 Forwards justification for continued operation of electrical equipment in Categories I.B.11 A 5 IV.Final submittal for remaining items will be sent by 830729.

  KAMMER.D.S. Tennesses Valley Authority. 83/07/20. ADENSAM.E. Licensing Branch 4. 52pp. 19731:084. 24X Fiche:50-327.83/07/20. 8307260207.

- 8307270036 Application for amené to Licenses DPR-77 & DPR-79, changing Tech Specs re hydrogen igniter surveillance test requirement, containment isolation valve operability & pressurizer spray norzile operational limits & Table 3.2-1. KAMMER.D.S. Tennesses Valley Authority 83/07/21. ADENBAM.E. Licensing Dranch 4. 2pp. 19749:169. 24x Fiche: 50-327, 83/07/21, 8307270036.
- --B307270040 Proposed Tech Specs re hydrogen igniter surveillance test requirement containment isolation valve operability % pressurizer spray nozzle operational limits % changes to Table 3.2-1 for DNB parameters.

  ### Tennessee Valley Authority. 83/07/21. 33pp. 19749:171. 24X Fiche: 50-327.83/07/21.8307270034.
- G. Inspection reports, !E Bulletins & correspondence
- 8307140072 Forwards IE Insp Repts 50-327/83-09 % 50-328/83-09 on 830404-0505. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. 83/06/24. PARRIS.H.G. Tennessee Veiley Authority, 2pp. 19514:160. 24X Fiche: 50-327, 83/06/24. 8307140072.
- --8307140077 IE Insp Repts 50-327/83-07 % 50-328/83-07 on 830406-0505.No noncompliance noted Major areas inspected: sys operability verification. IE bulletin & circular review. Fech Spec surveillance observation & open item review. FORDLE.J. BUTLER.S.D. Region 2. Office of Director. QUICK, D.R. Division of Project & Resident Programs. 83/06/24. 6pp. 19514: 162. 24X Fiche: 50-327, 83/06/24, 8307140072.
- 8307140085 Forwards IE Insp Repts 50-327/83-10 & 50-328/83-10 on 830506-0605 No noncompliance noted VERRELLID.M. Division of Project & Resident Programs. 83/06/24. PARRIS.M.G. Tennessee Valley Authority. 2pp. 19514:068. 24X Fichs: 50-327, 83/06/24, 8307140085.
- --B307140092 IE Insp Repts 50-327/83-10 & 50-328/83-10 on 830506-0605. No noncompliance noted Major areas inspected: ESF sys operability, operational safety verification, reactor trip followup & LER review.
  FORD, E. J., BUTLER, S. D., Region 2, Office of Director, QUICK, D. R., Division of Project & Resident Programs, 83/06/24, app. 19514: 070. 24X Fiche: 50-327, 83/06/24, 8307140085.
- 8307140340 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-08 & 50-328/83-08.

  LEMIS.R.C. Division of Project & Resident Programs. 83/06/27. PARRIS.H.O. Tennessee Valley Authority. 1p. 19525: 235. 24X Fiche: 50-327, 83/06/27, 8307140340.
- --8307140345 Submits revised response to NRC 830517 itr re violations noted in IE Insp Repts 50-327/83-08 & 50-328/83-08. Corrective actions:site-specific health physics training will be required as of 830627. for unescorted access. MILLS.L.M. Tennessee Valley Authority. 83/06/24. O'REILLY, J. P. Region 2, Office of Director. 4pp. 19525:236. 24x Fiche: 50-327, 83/06/27, 8307140340.
- --8307140351 Responds to NRC 830617 itr re violations noted in 1E Insp. Repts 50-327/83-08 & 50-328/83-08. Corrective actions: personnel reinstructed re general excort responsibilities, including dosimetry requirement.

  MICLS.L.M. Tennesses Vailey Authority. 83/06/16. 0'REILLY, J.P. Region 2, Office of Director. App. 19525: 240. 24X

  Fiche: 50-327, 83/06/27, 8307140340.
- --8307140363 Natice of violation from insp on 830412-15. \* Region 2. Office of Director. 83/05/17. 2pp. 19525:246. 24X Fishe: 50-327,83/06/27,8307140340.
- --8307140368 IE insp Repts 50-327/83-08 & 50-328/83-08 on 830412-15.

  Noncompliance noted: failure to issue proper desimetry to & to provide adequate radiation protection training for two individuals.

  COLLINS, T. R. Region 2. Office of Director. BARR.K. P. Division of Emergency Preparedness & Materials Safety. 83/05/10. 7pp. 19325: 248. 24X Fiche: 50-327.83/06/27.8307140340.
- B306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svr list encl. JORDAN-E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York. Inc. 154pp. 19563:293. 24x Fiche: 50-000. B3/07/11. B306270401.

- 8307140158 Forwards IE Safeguards Insp Repts 50-327/83-11 & 50-328/83-11 on 830606-10. No noncompliance noted. VERRELLI, D. Division of Project & Resident Programs. 83/07/11. PARRIS.H. G. Tennessee Variage Project & Resident Programs. 83/07/11. Fiche: 50-327, 83/07/11. 8307140198.
- --8307140165 IE Safeguards Insp Repts 50-327/83-11 & 50-328/83-11 on 830606-10. No noncompliance noted. Major areas inspected: site orientation. security plan & implementing procedure & security organization mgt. Details withheld (ref 10CFR73.21). MODRE, D. E. Region 2. Office of Director. MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety. 83/07/08. 1p. 19323: 215. 24X Fiche: 30-327, 83/07/11, 8307140138.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JCRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gascous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 9307220474 Monthly operating repts for May 1983 W/830613 ltr. MASON, C.C., DUPREE, D. Tennessoe Valley Authority, 83/06/03, Office of Resource Management, Director, 45pp, 19685:046, 24X Fiche: 50-327,83/06/03,8307220474.
- B307060071 Forwards "Aquatic Environ Conditions in Chickamauga Reservoir During Dperation-Second Annual Rept 1982," per NPDES Permit TN0026450. EL-ABHRY.M.T. Tennessee Valley Authority. B3/06/29. TRAINA.P. J. Environmental Protection Agency. 2pp. 19248:018. 24X Fiche: 50-327, B3/06/29, B307060071.
- --8307060133 "Aquatic Environ Conditions in Chickamauga Reservoir During Operation of Sequoyah Nuclear Plant.Second Annual Rept 1982" \*\* Tennessee Valley Authority. 63/06/30. 334pp. 19248:020. 24x Fiche:50-327,83/06/29.8307060071.
- S. Reportable occurrences, LERs & related correspondence
- B307120422 LER B3-077/03L-0: on B30531, auxiliary feedwater automatic valve 1-PCV-3-122 declared inoperable Caused by clogged hydraulic Moog valve & hydraulic pump motor failure due to high amperage. Valve, pump & motor replaced W/B3062B ltr. R0GERS.H.R., HARDING.M.R., GREEN.H.J. Tennessee Valley Authority. B3/06/2B. 0'REILLY.J.P. Region 2, Office of Director. 2pp. 19425:222. 24X Fiche: 50-327, B3/06/2B, B307120422.
- 8307120086 LER 83-084/03L-0: on 830603, two upper head injection level switches 1-L9-87-22 & 23 declared inoperable. Caused by setpoint drift. Suitches recalibr. W/830701 ltr. ROGERS. H. R. HARDING, N. R., GREEN, H. J. Tennessee Valley Authority. 83/07/01. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19419: 361. 24X Fiche: 50-327, 83/07/01, 8307120086.
- 8307120420 LER 83-083/03L-0:on 830607, flow rate measuring device for shield bldg declared inoperable due to sense lines becoming clogged w/dirt from stack discharge.Line blown out & flow monitor declared operable H/830706 ltm.
  ROSERS,H.R., HARDING,M.R., GREEN,H.J. Tennessee Valley Authority.
  83/07/06. 0'REILLY,J.P. Region 2, Office of Director. 2pp.
  19425:218. 24X Fiche: 80-327, 83/07/06, 8307120420.
- 8307270320 Forwards AEDD enigneering evaluation of numerous events involving frozen ico condenser intermediate deck doors. Most problems occurred while plant was new & have decreased as operational experience gained.

  ZUKOR, D. J. Reactor Operations Analysis Branch. 83/07/11.

  SEYFRIT, K. V. Reactor Operations Analysis Branch. 2pp. 19857:060.

  24X Fiche: 30-000, 83/07/11, 8307290320.
- --8307290377 "Frozen ice Condenser Intermediate Deck Doors," AEOD engineering evaluation rept.
  ZUKOR.D. Reactor Operations Analysis Branch. 83/07/11. 6pp.
  1985: 062. 24X Fiche: 50-000, 83/07/11, 8307270320.
- 8307290039 RO 83-03:on 830616, two mechanical fire penetrations in auxiliary bldg breached for period greater than 7 days. Caused by lack of communication between personnel. Breached penetrations sealed & breaching permits will be posted. GREEN.H.J. Tennessee Valley Authority. 83/07/21. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19821:034. 24X Fiche: 50-327, 83/07/21. 8307290039.

8307270076 LER 83-088/03L-0:on 830624.during STEAR 83-07.steam generator 3 auxiliary feedwater inlet valve handswitch 1-LCV-3-148A did not work Caused by stripped ramp portion of internal operator.W/830721 ltr. DUOGIN.G.E., HARDING.M.R., GREEN.H.J. Tennesses Valley Authority. 83/07/21. D'REILLY.J.P. Region 2. Office of Director. 2pp. 19822:206. 24X Fiche:50-327.83/07/21,8307290076.

## V. Operator Examinations

8307140275 Advises that abbreviated operator training program for mitigating core damage satisfies intent of NUREO-0737. Item II.B. 4. Training will be given to managers & technicians in health physics.plant chemistry & instrumentation. MILLS.L.M. Tennessee Valley Authority. 63/07/08. ADENSAM.E. Licensing Branch 4. 2pp. 19522:325. 24X Fiche: 50-327, 83/07/08, 8307140275.

DOCKET 30-328 SEGUCIAH NUCLEAR PLANT: UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8307140220 Ack receipt of B30513 itr re emergency exercise scheduled during Jul 1983, Scenario presently under review. Any addl comments on exercise details will be made by telcon w/B Marks.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/06/21. PARRIS, H. G. Tennessee Valley Authority. Jp. 19523;164, 24X Fiche: 50-327,83/06/21,8307140220.
- 8307140340 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-327/83-08 & 50-328/83-08.

  LEMES,R.C. Division of Project & Resident Programs. 83/06/27.

  PARRIS.H.G. Tennessee Valley Authority. ip. 19325:235, 24X

  Fiche: 50-327,83/06/27,8307140340.
- --B307140345 Submits revised response to NRC B30517 ltr re violations noted in IE Insp Repts 50-327/83-08 & 30-328/83-08. Corrective actions: site-specific health physics training will be required as of 830627, for unexcorted access. MILLS, L. M. Tennessee Valley, Authority, B3/06/24, 0'REILLY, J. P. Region 2, Office of Director, 4pp. 19525: 236. 24X Fiche: 50-327, 83/06/27, 8307140340.
- ---9307140351 Responds to NRC 830617 ltr re violations noted in IE Insp. Repts 30-327/63-08 & 50-328/83-08. Corrective actions: personnel reinstructed re general escort responsibilities, including dosimetry requirement.

  MILLS.L.M. Tennessee Valley Authority. 83/06/16. D'REILLY, J. P. Region 2, Office of Director. 4pp. 19525:240. 24x
  Fiche: 50-327,83/06/27,8307140340.
- --8307140355 Forwards IE Insp Repts 50-327/83-08 & 50-328/83-08 en 830412-15 & notice of violation. LEWIS.R.C. Division of Project & Resident Programs. 83/05/17. PARRIS.H.G. Tennessee Valley Authority. 2pp. 17525:244. 24X Fiche: 50-327,83/06/27,8307140340.
- --8307140363 Notice of violation from insp on 830412-15. \* Region 2, Office of Director. 83/05/17. 2pp. 19525:246. 24X Fiche: 50-327,83/06/27,8307140340.
- --8307140368 IE Insp Repts 50-327/83-08 & 50-328/83-08 on 830412-15.

  Noncompliance noted: Failure to issue proper dosimetry to & to provide adequate radiation protection training for two individuals.

  COLLINS.T.R. Region 2, Office of Director. 83/05/10. 7pp. 19525:248. 24X Fiche: 50-327,83/06/27,8307140340.
- B307140258 Discusses 830705 conversation between B Marks & ON Huffman re training requirements for NRC & contract personnel entering facilities. List of NRC & NRC contract personnel observing emergency exercise encl.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/07/08, PARRIS. H. G. Tennessee Valley Authority. 3pp. 17523:004. 24X Fiche: 50-327, 83/07/08, 8307140258.
- G30714013B Forwards IE Safeguards Insp Repts 50-327/83-11 & 50-328/83-11 on 830806-10. No noncompliance noted. VERRELLI, D. Division of Project & Resident Programs. B3/07/11. PARRIS.H.G. Tennesses Valley Authority. 2pp. 19323: 213. 24X Fiche: 30-327, 83/07/11, 8307140158.
- -8307140165 IE Safeguards Insp Repts 30-327/83-11 & 50-328/83-11 on 830606-10. No noncompliance noted Major areas inspected: site orientation, security plan & implementing procedure & security organization mgt. Details withheld (ref 10CFR73.21). MODRE, D. E. Region 2, Office of Director. 83/07/08. lp. 19523: 215. 24X Fiche: 50-327, 83/07/11, 8307140158.

B307250219 Advises that util mmergency operating instruction being ravised to manually energize permanent hydrogen mitigation system to delay in completion of Westinghouse Owners Group amergency response guidelines.
MILLS,L.M. Tennessee Valley Authority. B3/07/19. ADENSAM.E. Licensing Branch 4. 2pp. 19706:030. 24X Fiche: 50-327, B3/07/19, B307250219.

# J. Insurance & indemnity information

- 9307080031 Forwards Endorsement 33 to NELIA Policy NF-47 & Endorsement 27 to MAELU Policy NF-102.

  DUCK, J.R. Marsh & McLennan, Inc. 83/06/30. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19351:313. 24X Fiche:30-327,83/06/30,8307080031.
- 8307200008 Forwards Endorsement 34 to NELIA Policy NF-247 & Endorsement 28 to MAELU Policy MF-102.

  DUCK, J. R. Marsh & McLennan, Inc. 83/07/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 19647:173. 24X Fiche: 50-327, 83/07/15, 8307200008.

# P. Operating license stage documents & correspondence

- 8306060070 Generic Ltr B3-22 to all operating reactor licensess, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Guidelines."

  BVC list enci.
  E18ENHUT.D.Q. Division of Licensing. B3/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche:50-000,83/06/03,8306060070.
- B307080259 Forwards backfit cost figures for add1 seven utils per original B30208 request Cost figures for 20 utils transmitted B30411.
  TOURTELLOTTE, J. Regulatory Reform Task Force. B3/06/22.
  PALLADINO, N. Commissioners. 2pp. 19363:313. 24X
  Fiche: 50-000.83/06/22,8307080259.
- --B307080358 Forwards backfit cost estimates for facilitiss, per NRC B30315 ltr. Costs do not reflect extending scheduled outages due to backfits & mods.

  PARRIS,H.9. Tennessee Valley Authority. B3/05/02.

  TOURTELLOTTE, J. Regulatory Reform Task Force. 5pp. 19364:009.

  24X Fiche: 50-000. B3/06/22. B307080259.
- 8307070003 Application for amend to License DPR-79, changing Tech Specs to accommodate Cycle 2 reload operations Class III fees applicable per 105FR170.22.

  MILLS, L. M. Tannessee Valley Authority. 83/07/01. ADENSAM. E. Licensing Branch 4. 2pp. 19269:223. 24X Fiche: 50-329.83/07/01.8307070003.
- --8307070005 "Relead Safety Evaluation, Sequoyah Unit 2, Cycle 2."

  \* Tennessee Valley Authority. 83/07/01. 25pp. 19249: 225. 24X
  Fiche: 50-328, 83/07/01, 8307070003.
- --8307070011 Proposed Tech Specs re Cycle 2 reload operations, \* Tennessee Valley Authority. 83/07/01. 44pp. 19247:250. 24x Fiche: 50-328, 83/07/01, 8307070003.
- B307130354 Forwards notice of consideration of issuance of amend to License DPR-79 & proposed no significant hazards consideration determination & opportunity for hearing resurveillance requirements for rod drop tests.

  ADENBAM E. O. Licensing Branch 4. 83/07/01. PARRIS.H.Q. Tennessee Valley Authority. 2pp. 19508:345. 24X Fiche:50-328.83/07/01.
- ~-B3071303B3 Notice of consideration of issuance of amend to License DPR-79 & proposed no significant hazards consideration determination & opportunity for hearing re surveillance requirements for rod drop tests.

  ADENBAM.E. G. Licensing Branch 4. 83/06/23. 4pp. 1950B:347. 24X Fiche: 50-32B.83/07/01.8307130354.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity, Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. [App. 17370:317, 24X Fiche: 30-000, 83/07/05, 8306270397.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for gower reactors re surveillance intervals in BTS. Svc list encl. E18EANHUT.D.O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254, 24X Fiche:50-000,83/07/06,8307060327.

- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENRAT. D. O. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 8307140043 Advises that 830616 & 21 requests to amend License DPR-79 have been approved by nuclear safety review board. MILLS,L.M. Tennessee Valley Authority. 83/07/08. ADENSAM,E. Licensing Branch 4. 1p. 17514:190. 24X Fiche:50-328,83/07/08,8307140043.
- B307190089 Application to amend License DPR-79, supplementing B30701 proposed Tech Specs supporting Cycle 2 reload operations. MILLS.L.H. Tennesses Valley Authority. B3/07/13. ADEMSAM.E. Licensing Branch 4. 1p. 19635:008. 24% Fiche: 50-328.83/07/13. B307190089.
- --8307190094 Revised pages to proposed Tech Specs supporting Cycle 2 reload operations.

  \* Tennessee Valley Authority. 83/07/13. 6pp. 19635:009. 24X fiche:50-328,83/07/13,8307190089.
- 8307190166 Forwards LOCA (major RCS pipe ruptures) reanalysis for Cycle 2 assuming 2% uniform steam generator tube plugging & containment purging at time of accident. MILLS.L.M. Tennessee Valley Authority. 83/07/14. ADENSAM.E. Licensing Branch 4. 80pp. 19636:264. 24% Fiche: 50-327, 83/07/14, 8307190166.
- 8307270290 Forwards Amend 20 to License DPR-79 & safety evaluation. Amend changes Tech Specs to permit change in surveillance requirements for rod drop time & full length control rod position limit switches.

  ADENSAM.E.Q. Operating Reactors Branch 4. 83/07/15. PARRIS, H. G. Tennessee Vallsy Authority. 2pp. 19812:032. 24X Fiche: 50-328, 83/07/15, 8307270270.
- --8307270297 Amend 20 to License DPR-79, changing Tech Specs to permit change in surveillance requirements for rod drop time & full length control rod position limit switches.

  ADENBAM, E. G. Operating Reactors Branch 4. 83/07/15. Spp. 19812:034. 24X Fiche: 50-32B. 83/07/15. 8307270290.
- --8307270301 Safety evaluation supporting Amend 20 to License DPR-79.

  \* NRC No Detailed Affiliation Olven. 83/07/15, 3pp.
  19812:039. 24X Fiche:50-328,83/07/15,8307270290.
- B307260207 Forwards justification for continued operation of electrical equipment in Categories I.B. II.A & IV. Final submittel for remaining items will be sent by 830729.

  KAMMER, D. S. Tannessee Valley Author(ty. 83/07/20. ADENBAM, E. Licensing Branch 4. 52pp. 19731:084. 24X Fiche: 50-327, 83/07/20, 8307260207.
- 9307270036 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs re hydrogen igniter surveillance test requirement containment isolation valve operatifity & pressurtier spray nozzle operational limits & Table 3.2-1.

  KAMMER.D.S. Tennessee Valley Authority. B3/07/21. ADENBAM.E. Licensing Branch 4. 2pp. 19749:169. 24X Piche:30-327,83/07/21, B307270036.
- --8307270040 Proposed Tech Specs re hydrogen igniter surveillance test requirement, containment isolation valve operability & pressurizer spray nozzle operational limits & changes to Table 3.2-1 for DNB parameters.

  \* Tennesse Valley Authority. 83/07/21. 33pp. 19749:171. 24X Fiche: 50-327, 83/07/21, 8307270036.
- Q. Inspection reports. IE Bulletins & correspondence
- 8307140072 Forwards IE Insp Repts 50-327/83-09 & 50-328/83-09 on B30408-0505. No noncompliance noted. VERRELLI, D. M. Division of Project & Resident Programs. 83/06/24. PARRIB, H. G. Tehnesse Veiley Authority. 2pp. 17514:16D. 24X Fiche: 50-327, 83/06/24, 8307140072.
- --B307140077 IE Insp Repts 30-327/83-09 & 50-328/83-09 on B30406-0505. No noncompliance noted Major areas inspected: sys operablity varification, IE bulletin & circular review. Tech Spec surveillance observation & open item review.

  FORD, E. J., BUTLER, S. D. Region 2: Office of Director. GUICK, D. R. Division of Project & Resident Programs. B3/06/24. App. 19314:162. 24X Fiche: 50-327, B3/06/24, B307140072.
- 8307140085 Forwards IE Insp Repts 50-327/83-10 % 50-328/83-10 on 830506-0605. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. 83/06/24. PARRIS, H. Q. Tennessee Valley Authority. 2pp. 19514: 068. 24X Fiche: 50-327, 83/06/24. 8307140085.

- --B307140092 IE Insp Repts 50-327/B3-10 & 50-328/B3-10 on B30306-0605.No noncompliance noted Major areas inspected: BBF sys operability, operational safety verification, reactor trip followup & LER review.
  FORD.E. J. BUTLER B. D. Region 2. Office of Director. GUICK, D. R. Division of Project & Resident Programs. B3/06/24. 6pp. 19514: 070. 24X Fiche: 50-327, B3/06/24, B307140085.
- 8307140340 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-08 & 50-328/83-08.

  LENIS,R.C. Division of Project & Resident Programs. 83/06/27. PARRIS,M.Q. Tennessee Valley Authority. 1p. 19525:235. 24X Fiche: 50-327, 83/06/27, 8307140340.
- --8307140345 Submits revised response to NRC 830517 ltr re violations noted in IE Insp Repts 50-327/83-08 & 50-328/83-08. Corrective actions: site-specific health physics training will be required as of 830627, for unescorted access. MLLS, L. M. Tennessee Valley Authority. 83/06/24. O'REILLY, J. P. Region 2, Office of Director. 4pp. 19525:236. 24X Fiche: 50-327, 83/06/27, 8307140340.
- --8307140351 Responds to NRC 830617 itr re violations noted in IE Insp Repts 50-327/83-08 & 50-328/83-08. Corrective actions: personnel reinstructed re general escort responsibilities, including dosimetry requirement. MILLS,L.M. Tennessee Valley Authority. 83/06/16. D'REILLY,J.P. Region 2. Office of Director. 4pp. 19525: 240. 24x Fiche: 50-327, 83/06/27, 8307140340.
- --8307140355 Forwards IE Insp Repts 50-327/83-08 & 50-328/83-08 on 830412-15 & notice of violation. LEMIS.R.C. Division of Project & Resident Programs. 83/05/17. PARRIS.H. 9. Tennessee Valley Authority. 2pp. 19525:244. 24X Fiche: 50-327,83/06/27.8307140340.
- --8307140363 Notice of violation from insp on 830412-15. \* Region 2: Office of Director. 83/05/17. 2pp. 19525:246. 24X Fiche: 30-327, 83/06/27, 8307140340.
- --8307140368 IE Insp Repts 50-327/83-08 & 50-328/83-08 on 830412-15.
  Noncompliance noted: failure to issue proper dosimetry to & to provide adequate radiation protection training for two individuals.
  COLLING.T.R. Region 2. Office of Director. BARR.K.P. Division of Colling.T.R. Region 2. Office of Director. BARR.K.P. Emergency Preparedness & Materials Safety. 83/05/10. 7pp. 19525:248. 24X Fiche: 50-327,83/06/27,8307140340.
- 8306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surmy Recirculation Spray Subsystem." Svc list encl. URDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563: 293. 24X Fiche: 50-000, B3/07/11, 8306270401,
- 8307140198 Forwards IE Safeguards Insp Repts 50-327/83-11 & 50-328/83-11 on 830606-10.No noncompliance noted. VERRELLI.D. Division of Project & Resident Programs. 83/07/11. PARRISH.G. Tennessee Vailey Authority. 2pp. 19523:213. 24X Fiche: 80-327, 83/07/11, 8307140138.
- --8307140165 IE Safeguards Insp Repts 50-327/83-11 & 50-328/83-11 on 830606-10. No noncompliance noted. Major areas inspected: site orientation, security plan & implementing procedure & security organization mgt. Details withheld (ref 10CFR73.21). MIDRE, D. E. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/07/08, 1p. 19523:215. 24% Fiche: 50-327, 83/07/11, 8307140158.
- B306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:133. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24x Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307220474 Monthly operating repts for May 1983 W/830419 ltr. MASON, C. C., DUPREE, D. Tennessee Valley Authority. 83/06/03. Office of Resource Management, Director. 4Spp. 19695:046. 24X Fiche: 50-327,83/06/03,8307220474.

- 8307060071 Forwards "Aquatic Environ Conditions in Chickamauga Reservoir During Operation-Second Annual Rept 1982." per NPDES Permit TN0026450. EL-ASHRY. M.T. Tennessee Valley Authority 83/06/29. TRAINA Environmental Protection Agency. 2pp 19248-018. 24X Fiche: 50-327-83/06/29. 8307060071 TRAINA P. J.
- --8307060133 "Aquatic Environ Conditions in Chickamauga Reservoir During Operation of Sequoyah Nuclear Plant Second Annual Rept 1982."
  - 1982." \* Tennessee Valley Authority. 83/06/30 334pp. 19248:020. 24X Fiche: 50-327:83/06/29,8307060071

### S. Reportable occurrences, LERs & related correspondence

- B307120267 LER 83-0B1/03L-0: on 830529, upper containment outer airlock door found broken Caused by two failed operating machanism cam follower bearings due to normal upar, heavy use 2 improper maint during const Bearings replaced M/830627 ltr. CARVER, A. M., HARDING, M.R., GREEN, H. J. Tennessee Valley Authority, B3/06/27. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19424: 152. 24X Fiche: 50-328, 83/06/27, 8307120267.
- B307120414 LER 83-085/03L-0:on 830614.RCS subcouling margin monitor declared inoperable due to loss of plant process computer on two accasions. Caused by loss of power during start bus transfer & blown fuso, respectively. B/830706 ltr. ROGERS.M.R. HARDING.M.R., GREEN.H.J. Tennessee Valley Authority. B3/07/06. 0'REILLY,J.P. Region 2, Office of Director. 2pp. 17425:088. 24% Fiche: 50-328.83/07/06,8307120416.
- B3071205B9 LER B3-082/03L-0: on B30607, remote shutdown instrumentation channel for RHR flow rate declared inoperable due to being out of tolerance. Probably caused by Instrument drift.
  Instrument recalibr. W/830706 ltr.
  ROSERS, H. R., HARDING, M. R., GREEN, H. J. Tennessee Valley Authority.
  B3/07/06. 0'REILLY, J. P. Region 2. Office of Director. 2pp.
  19432: 144 24X Fiche: 50-328,83/07/06,83071205B9.
- 8307220235 LER 83-086/03L-0: on 830610, w/RCB temp at 558 F & pressure at 2:215 psig, steam generator blowdown containment isolation valve 2-FCV-1-32 failed closed Caused by high temp environ.

  Higher temp resistant diaphragm installed W/830708 ltr.

  CARVER, A. M., HARDING, M. R. GREEN, H. J. Tennessee Valley Authority.

  83/07/08 O'REILLY, J. P. Region 2, Office of Director. 2pp.

  19684: 245 24 Fiche 50-328, 83/07/08, 8307220235.
- BG07220420 LER 83-087/03L-0: on 830609, while reducing power for maint, axial flux difference discovered outside target band for time period exceeding Tech Specs Caused by inoperability of D-8 control rod Setpoints adjusted W/830708 ltr. CARVER, A. M., HARDING, M.R., GREEN, M. J. Tennessee Valley Authority, 83/07/08. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19687: 263. 24X Fiche: 50-328,83/07/08,8307220420.
- 8307290320 Forwards AEOD enignoering evaluation of numerous events involving frozen ice condenser intermediate deck doors. Most problems occurred while plant was new & have decreased as operational experience gained.
  2UXOR.D.J. Reactor Operations Analysis Branch. 83/07/11.
  SEYFRIT.K.V. Reactor Operations Analysis Branch. 2pp. 19857:06
  24x Fiche: 50-000, 83/07/11, 8307290320.
- --8307270377 "Frozen Ice Condenser Intermediate Deck Noors," AEOD engineering evaluation rept.
  ZUKOR, D. Reactor Operations Analysis Branch. 83/07/11. App. 1987: 062. 24% Fiche: 50-000, 83/07/11, 8307270320.

#### V. Operator Examinations

B307140275 Advises that abbreviated operator training program for mittigating core damage satisfies intent of NUREG-0737, Item II.B. 4. Training will be given to managers & technicians in health physics plant chemistry & instrumentation.
MILLS.L.M. Tennessee Valley Authority. 83/07/08. ADENSAM,E Licensing Branch 4. 2pp. 19522:325. 24x Fiche:50-327,83/07/08.

# DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- E307110405 Forwards Rev 1 to "Const Project Evaluation of CPC Midland Energy Ctr Project Units 1 ½ 2."
  COCK.J.W. Consumer's Power Co. 83/03/09 KEPPLER, J.G. Region 3, Office of Director. 2pp. 19382: 292. 24X Fiche: 50-329, 83/03/09, 8307110405

- 830714025/ Forwards 830307/08/0405 % 07 meeting notes, including associated documents provided to NRC on 830315/R Landsman 830412 discussion verifying that Region [II] will provide authorization to ercavate portions of fire 8E/W MILLER.D. B. Consumers Power Co. 83/04/14 HARRISON.J. J. Region 3/04/14 of Director. 29pp. 19523/009/24X Fiche.50-329.83/04/14, 830714025/
- 8307140211 Forwards response to Items A1.2.3.4.6.7.8 % 9 submittal in NRC 830328 itr re const completion program covering procedures for controlling reladed of new work & personnel training. CODX.J.W. Consumers Power Co. 83/04/22 KEPPLER.J.G. Region 3. 04/22 KEPPLER.J.G. Region 3. 04/22 OZ7 24X Fiche 50-329.83/04/22.
- 8307080453 Forwards Rev 1 to QC Instrumentation 10.01, "Const Implementation Overview Assessment" BARANON,S W. Stone & Webster, Inc. 83/06/28 KEPPLER.J.Q. 3, Office of Director 1p 19347-256, 24X Fiche: 50-329, 85 8307080453. " 83/04/28: KEPPLER, J. Q. Region 254: 24x Fiche: 50-329, 83/04/28,
- 8307080808 Confirms that listed responses to Region III inspector R Landsman questions, provided to B Burgess, NRC resident inspector, on 830608 Responses concern concrete truck drum revolving & Drawing C-1427.

  MOUNEY, J. A. Consumers Power Co. 83/06/28 HARRISON, J. J. Regioffice of Director. 2pp. 19346: 348. 24X Fiche. 50-329, 83/06/28 8307080508. 83/06/28 HARRISON, J. J. Region 3. 348. 24% Fiche, 50-329, 83/06/28.
- B30711003B Forwards Rev I to QC Instruction GCI 10 O1, "Const Implementation Overview Assessment" BARANOW, S.W. Stone & Webster, Inc. 83/06/28, KEPPLER, J.G. Region 3, Office of Director. Ip. 19375-278 24X Fiche 50-327, B3/06/28, B30711003B.
- --8307110040 Rev 1 to GC Instruction OC1 10.01, "Const Implementation Overview Assessment." \* Stone & Webster, Inc. 83/06/27 App. 19375:299, 24X Fiche 50-329,83/06/28,8307110038.
- 8307050093 Advises that review of Zack Co welding procedures & welder performance testing completed Util authorized to proceed w/fabrication & welding of HVAC sym HARRISON.J. J. Region 3. Office of Director 83/04/29. MILLER.D. Consumers Power Co. 2pp. 19192:159 24x Fiche:50-329,83/06/29,8307090053.
- B307t10555 Discusses staff requirements memo re B306t5 brisfing on GA deficiency status. Deficiencies resulted in safety-related work stoppage on B21203 & resulted from work performed subsequent to Aug 1980 reorganization DIRCKS.W.J. Office of the Executive Director for Operations 53/06/29. CHILM.S.J. Office of the Secretary of the Commission. 1p. 19434.138. 24X Fiche: 50-329, B3/06/29, B307110555.
- --8307110564 Stoff requirements memo re 830615 briefing in Washington DC on GA problems. Commissioner Gilinsky requested info whether deficiencies involved const completed before or after Aug 1980 GA dept formation.

  CHILK, S. J. Office of the Secretary of the Commission. 83/06/20. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 19434-139. 24X Ficha: 50-329.83/06/29.8307110555.
- 8307060057 Provides info re natural circulation testing addressing concerns on boron mixing & use of reactor vessel head vent temp indication in response to NRC 830617 telcon request. GA program approving FSAR change notice encl DEWITT-R.B. Consumers Power Co. 63/06/30. DENTON-H.R. Office of Nuclear Reactor Regulation. Director. 6pp. 19250: 350. 24x Fiche: 90-329.83/06/30, B307060057.
- 8307110305 Forwards comments on mgt review committee 830623 meeting re-bulk hanger organization Mods ready for implementation. BARANON-5.W. Stone & Webster, Inc. 83/06/30. REPPLER, J. C. Region 3, Office of Director. 2pp. 19378, 330 24X Fiche: 50-327, 83/06/30, 8307110309.
- 8307120245 Forwards Core Damage Assessment Procedure Station 9918.1, "Estimation of Extent of Core Damage" Excl changes to NUREO-0737, Item 11.8.3 re post-accident analytical accuracies will be incorporated into FSAR rev. CODA, J. W. Consumers Power Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp 19422:308. 24X Fiche: 50-329, 83/07/01. 8307120245.
- 8307120248 Core Damage Assessment Procedure STATION 9918.1, "Estimation of Extent of Core Damage "
  4 Consumers Power Co. 83/06/30 47pp 19422:315. 24X
  Fiche: 50-329, 83/07/01, 8307120245

- B307130335 Trip rept of B30422 visit to TERA Corp in Bethesda.MD to observe filing sys for controlled documents associated w/facility independent design // verification program. HOOD, D. 2 Licensing Branch 4, 83/07/01. Licensing Branch 4, 4pp. 19508:352 24x Fiche 50-329, 83/07/01, 8307130335
- 8306270397 Generic Ltr 83-26 to all applicants for DLs % holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390-317 24% Fiche: 50-000, 83/07/05, 8306270397.
- 8307t10010 Advises that remedial soils activities identified in Section 1 of Attachment A & presently scheduled for Jul 1983 have been identified as critical Details of activities requested to assist in review.

  MARRISON, J J. Region 3, Office of Director. 83/07/05 MILLER, D. B. Consumers Power Co. 3pp. 19374: 211. 24x Fiche: 50-329, 83/07/05, 830/110010
- 8307260547 Rev 1 to "Third-Party Const Implementation Overview."
  W/830714 ltr.
  KELLY:R.B.: BARANOW.S.W. Stone & Webster, Inc. B3/07/05.
  KEPPLER.J.G. Region 3, Office of Director App. 19731:320. 24X
  Fiche: 50-329:83/07/05
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in SIS.Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche:50-000.83/07/06.8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19869:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307110311 Authorizes Remedial Soils Work 312150011 & 322150011 for const of new ring beam for month of Jul.
  HARRISON.J.J. Region 3: Office of Director. 83/07/08. MILLER.D.B. Consumers Power Co. 2pp. 19381:001. 24X Fiche: 90-329:83/07/08. 8307110311
- B3071B0301 Summary of B30705 meeting w/util in Washington DC redevelopment of const completion program.

  CUNNINGHAM.O. H. Office of the Executive Legal Director. B3/07/08.

  Office of the Executive Legal Director 1p. 19566:118. 24X

  Fiche: 50-327.83/07/08.8307180301.
- 8307200079 Forwards 19 oversize drawings & figures & various hydrographs from observation wells & piezometers nearest containments in response to NRC request for info re reactor bldg settlement Aperture cards are available in PDR. MODNEY, J. A. Consumers Power Co. 83/07/08. MARRISON, U. J. Region 3, Office of Director. 186pp. 19650:008. 24% Fiche: 50-329, 83/07/08. 8307200079.
- B307200316 Summarizes B30619 telcon w/applicant re accuracies in required post-accident analytical chemistry procedures per NUREG-0737.1tem II.B.3. Acceptable gamma spectrum analysis will be submitted in early Jul 1983.
  AILLER.M.A. Licensing Branch 4. B3/07/11 Licensing Branch 4. 4pp. 19656:343 24X Fiche:50-329.83/07/11.8307200316.
- 8307200318 Summarizes 630628 telcon w/applicant & Bechtel re NRC request for addl info on motion before hearing board to reopen contentions concerning effect of decatering on settlement of Unit 1 reactor containment bldg. MILLER.M.A. Licensing Branch 4. 63/07/11. Licensing Branch 4. 4pp. 19656: 339. 24X Fiche: 50-329.63/07/11.6307200318.
- 8307220402 Forwards Rev 3 to "NSSS Equipment & Piping," Vol VIII to Seismic Margin Review." COOK, J. W. Consumers Power Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19691:175. 24X Fiche. 50-329, 83/07/11, 8307220402.
  - -8307220411 Rev 3 to "NSSS Equipment & Piping," Vol VIII to "Seismic Margin Review," KIPP, T.R., CAMPBELL, R.D., KENNEDY, R.P., Structural Mechanics Associates, SMA 13701.05R003 V08, 83/07/31, 35pp. 19491:179, 24X Fiche: 50-329,83/07/11,8307220402,
- B307250233 Forwards Rev 1 to "Third-Party Const Implementation Overview Procedure "Procedure revised for clarity Requirement for monthly repts deleted.
  BARANOW,S.W. Stone & Webster Engineering Corp. 83/07/14.
  KEPPLER.J. G. Region 3, Office of Director 1p. 19705: 134. 24X
  Fiche: 50-329, 83/07/14, 8307250253.

- ---8307250261 Rev 1 to "Third-Party Const Implementation Overview Procedure."

  BARANDW, S. W. Stone & Webster, Inc. 83/07/05. 5pp. 19705:135. 24% Fiche: 50-329, 83/07/14:8307250253.
- B307280434 Requests authorization to excavate & backfill trench for ground cable east of technical support ctr in accordance w/Mork Authorization Procedure 942450300.
  MCDNEY, J. A. Consumers Power Co. B3/07/14. HARRISON, J. J. Region 3, Office of Director. 1p. 19797:119. 24X Fiche: 50-329, 83/07/14, 93073930434
- 8307210125 Requests appropriate details of remedial soils work activities scheduled for month of Jul 1983 to assist in review due to criticality of activity.

  HARRISON.J.J. Region 3, Office of Director. 83/07/15. MILLER.D.B Consumers Pawer Co. 3pp. 19666:085. 24X Fiche: 50-329,83/07/15,8307210125.
- ---B307210144 Requests authorization to excavate & backfill trench for ground cable east of technical support ctr per work authorization procedure.

  MODNEY, J. A. Consumers Power Co. 83/07/14. HARRISON, J. J. Region 3, Office of Director. 1p. 19666:088. 24X Fiche: 50-327,83/07/15,8307210125.
- B307210208 Forwards "Rept of Overhead Fluid Grouting Testing Program," info re svc water pump structure, procedure for drilling in "G" concrete & justification for continuing soils work, in response to NRC B30714 questions re soil drilling.
  MOUNEY, J. A. Consumers Power Co. B3/07/15 HARRISON, J. J. Region 3, Office of Director. 20pp. 19667: 034. 24X Fiche: 50-329, 83/07/15, 8307210208.
- --8307210210 "Rept of Overhead Fluid Grouting Test Program," \* Consumers Power Co. 83/07/15, 47pp. 19667:054, 24X Fiche: 50-329, 83/07/15, 8307210208.
- 8307260320 Forwards B&W info re non-nuclear instrumentation/integrated control sys failures for generic pressurized thermal shock study, BAW-1743, Table B revised to reflect Failure 4 description.
  CION, J. W. Consumers Power Co. 83/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 19726:302. 24X Fichs: 50-329, 83/07/18, 8307260320.
- 8307250470 Discusses concerns re structural adequacy of diesel generator bldg due to numerous structural cracks occurring throughout bldg over yrs. Recommends remedial structural fixes be undertaken to ensure structural integrity.

  LANDSMAN.R.B. Region 3, Office of Director. 83/07/19. WARNICK.R.F. Region 3, Office of Director. 2pp. 19701:195. 24X

  Fiche: 50-329, 83/07/19, 8307250470.
- 8307290113 Forwards "Seismic Margin Review, Vol III, Auxiliary Bldg," describing method of analysis & resulting seismic margins. Considerable amount of margin exists in design. BUCKMAN, F. M. Consumers Power Co. 83/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19822:223. 24X Fiche: 90-329, 83/07/22, 8307290113.
- --8307290118 "Seismic Margin Review, Vol III. Auxiliary Blég." WEBLEY, D. A., KENNEDY, R. P., KINCAID, R. H. Structural Mechanics Associates. SMA 13701.036003 VO3. 83/06/30. 259pp. 19822:227. 24X Fiche: 50-329, 83/07/22, 8307290113.
- 8307290191 Forwards Rev 14 to Vol I of GA program manual Policy 1, "Organization." Changes organizational Previous commitments remain unchanged.
  BUCKMAN,F.W. Consumers Power Co. 83/07/22. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19821:111. 24X
  Fiche: 50-329, 83/07/22, 8307290191.
- --8307290196 Rev 14 to Vel I of GA program manual, Policy 1, "Grganization."
  4 Consumers Power Co. 83/06/29. 25pp. 19821:114. 24X Fiche: 50-329,83/07/22,8307290191.
- 8307280339 Summarizes 830720 meeting w/Rechtel in Olen Ellyn, IL reactions as result of certain NRC concerns on procurement quality issues discussed at 821029 meeting in Ann Arbor, MI. WARNICK, R. F. Region 3, Office of Director. 93/07/26. Region 3 Office of Director. 93/07/26. 8307280339.

# E. NRC Safety Evaluation Report (SER), suppls & correspondence

- 8307060061 Submits add1 info on SER Confirmatory Issue 19 re testing of auxiliary feedwater pump suction transfer logic. Proposed quarterly test of pump suction transfer logic will be reflected in revised Tech Specs.

  DEWITT.R.B. Consumers Power Co. 83/06/27. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp 19251:060. 24X

  Fiche: 50-327,83/06/27,8307060061.
- 8307060089 Forwards info to complete SER Confirmatory Issue 14 redesign bases used to categorize containment penetrations as essential or nonessential info will be included in next FBAR rev.

  DEWITT.R.B. Consumers Power Co. 83/06/30. DENTGN, H.R. Office of Nuclear Reactor Regulation. Director. 8pp. 19251:052. 24X Fiche: 50-329, 83/06/30, 8307060059.
- 8307070192 Submits info re util turbine missile prevention commitment, per SER Open Item 2.in response to NRC 830504 ltr.
  Commitment to Option 2 should enable NRC to reclassify Open Item 2 on turbine missiles as confirmatory item.
  CDDK, J.W. Consumers Power Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19294:252. 24X
  Fiche: 50-929, 83/07/01, 8307070192.
- 8307120393 Forwards response to 830531 request for add1 info re hUmerical data used in conjunction w/setpoint methodology to calculate Tech Spec setpoints to complete review of SER Confirmatory Item 15.
  REYNOLDS, J. W. Consumers Power Co. 83/07/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 54pp. 19430:143. 24X Fiche: 50-329, 83/07/05, 8307120393.
- 8307130346 Clarifies 830504 itr re turbine sys maint program options for resolution of SER Open Item 2 on turbine missiles.

  NOVAK, T. M. Assistant Director for Licensing. 83/07/07. CODK, J. M. Consumers Power Co. 3pp. 19508:336. 24X Fiche: 50-329, 83/07/07, 8307130346.
- 8307240236 Provides info re RCS makeup (MU) nozzles in response to NRC 830713 telcom & topics concerning SER Open Item 8. Commits to maintaining min continuous makeup flow of between 1.2 % 3 gpm. Info completes response to SER (tem. CODK, J.W. Consumers Power Co. 83/07/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727:188. 24X Fiche: 50-327,83/07/18.8307260236.

#### Q. Adjudicatory correspondence

- B307070198 Discussion of UB Army Corps of Engineers dynamite depot in vicinity of Detroit,MI & record before ASLB MARSHALL,M.H. Mapleton Intervenors. MARSHALL,M.H. Marsh & MCLennan, Inc. 83/06/28. 3pp. 19269:315. 24X Fiche: 90~329,83/06/28,8307070198.
- 8307070020 Forwards Ofc of Investigation rept re alleged violation of ASLB 820430 order Rept in conjunction w/brief oral direct testimony constitutes NRC testimony to be presented at 830725 hearing on order violation W/o encl. MRIGHT.N.A. Hearing Branch 2. 83/07/01. BECHHOEFER.C., COWAN.F.P., HARBOUR.J. Atomic Safety and Licensing Board Panel. 2pp. 19293: 230. 24x Fiche: 50-329.83/07/01.8307070020.
- B3070B0462 Response to B30407 Request for Production of Documents B(b).

  Draft rept & investigator handwritten notes will be offered to ASLB for in camera review.

  MRIGHT.N.A. Hearing Branch 2. B3/07/06. BERNABELL. Stamiris, B. BERNABELL. Government Accountability Project. lp. 19346:361. 24X Fiche: 50-329, 83/07/06, 8307080462.
- B307110150 Forwards first installment of proposed findings of fact & conclusions of law on remedial soils issues, sommanizing record on spismology & seismic models. Certificate of Svc excl.

  STEPTOE, P. P. Isham, Lincoln & Beale. STEPTOE, P.P. Consumers Power Co. B3/07/06. BECHMOFFER, C., COWAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 4pp. 19375:034. 24X
  Fiche: 50-329, 83/07/06. 8307110150.
- --8307i10154 Proposed findings of fact & conclusions of law on remedial solis issues & seismic models.

  \* Consumers Power Co. 83/07/06. 59pp. 19375:038. 24X Ficha: 50-329, 83/07/06, 8307i10130.
- B307150195 Response opposing deponent motion to quash subpoense of L Clark.T Devine.BP Garde & L Hallberg re identity of anonymous whistleblowers.Appropriate protective order should be entered as alternative.Certificate of Svc encl. PROCTOR.S.D. Consumers Power Co. PROCTOR.S.D. Isham, Lincoln & Beale. 83/07/11. Atomic Safety and Licensing Board Panel. 8p; 19530:361. 24X Fiche:50-329.83/07/11.8307150195.

- 8307180077 Advises that S Maralla deposition rescheduled for 830719. PROCTOR S.D. Isham, Lincoln & Beale 83/07/12. KELLEY, F.J., STEINBERG, C. Michigan, State of 2pp 19560:261. 24X Fiche: 50-329,83/07/12,8307180077
- B307200104 Response opposing Govt Accountability Project motion to quash B30627 subpoenas Motion based on incorrect premise since identification of informants not sought Certificate of Svc enci WRIGHT.N.A. Hearing Branch 2. B3/07/18 Atomic Safety and Licensing Board Panel App. 19647:135. 24X Fiche: 50-329,83/07/18.8307200104.
- 8307210239 Response to B Stamin's 830627 motion to reopen record on Stamin's Contention 4 re integrity of containment & soils underpinning operations foounded upon glacial till Motion unsubstantiated & should be denied Certificate of Svc ancl. STEPTOE.P.P. Consumers Power Co. STEPTOE.P.P. Isham, Lincoln & Beale. 83/07/18. Atomic Safety and Licensing Board Panel. 10pp 19665:001. 24X Fiche: 50-329,83/07/18,8307210259.
- --B307210261 Affidavit of P Shunmugavel re significance of observed cracks in Containment.

  SHUNMUGAVEL.P. Consumers Power Co. SHUNMUGAVEL.P. Dechtel Corp.

  83/07/15. 15pp. 19665:011. 24x Fishe 50-329.83/07/18,8307210259.
- --8307210266 Affidavit of WG Corley re visual insp of cracks in containments near anchorages in Rooms 110 ½ 116.

  CURLEY.W. G. Consumers Power Co. CURLEY.W. G. Construction Technology Laboratorios. 83/07/15. App. 19665:026. 24X Fiche: 50-329, 83/07/18, 8307210259.
- --8307210271 Revised "Visual Insp of Cracks in Containments Near Anchorages in Rooms 110 & 116." CORLEVIM O. Construction Technology Laboratories. 83/04/30. 7pp. 1965:032. 24X Fiche:50-327.83/07/18.8307210259.
- 8307220347 Forwards correct document request to 830509 subpoenas Svc list encl. PROCTOR S.D. Isham, Lincoln & Beale. 83/07/18, KARR.J.W. Karr & Lyons. 2pp. 19675: 335. 24X Fiche: 50-329, 83/07/18, 8307220347.
- --8307220349 Correct document request to 830509 subpoenas.
  \* Isham, Lincoln & Deale. 83/07/18. 2pp. 19675:337. 24X
  Fiche: 50-329, 83/07/18, 8307220347
- 8307260413 Forwards Jul 1983 crack maps of containments at buttress-base slab junctions, per telcon.
  STEPTOE.P.P. Isham, Lincoln & Beale. 83/07/18. WILCOVE, M. N.
  Hearing Branch 2. 12pp. 19733:179. 24X Fiche: 50-329, 83/07/18, 8307260413.
- B307250409 Memorandum & order postponing B30725-27 evidentiary hearings, scheduling B30728-30 & 0801-05 hearings, scheduling B30726 oral argument on motion to quash subpoenas & granting B Stamiris motion to compel production of NRC documents.

  BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 83/07/21. Stamiris, B. Bpp. 19705:125. 24X Fiche: 50-329, 83/07/21, 8307250409.
- 8307250390 Response apposing B Stamiris 630627 aral motion to reopen 791206 order modifying CP record on Stamiris Contention 4. Stds for reopening record not met.Certificate of Svc encl. WILCOVE.N.N. Hearing Branch 2. 83/07/22. Atomic Safety and Licensing Board Panel. 11pp 19705:143. 24X Fiche.50-329,83/07/22,8307250390.
- --8307250396 Affidavit of J Kane re geotechnical engineering issues. Natural preconsolidated "very stiff to hard" clay soils is competent & acceptable foundation layer. KANE, J. Structural & Geotechnical Engineering Branch. 83/07/22. 7pp. 19705:154. 24x Fiche. 50-329, 83/07/22, 8307250390.
- --8307250402 Affidavit of F Rinaldi re cracks in containment bldg. NRR will evaluate cause/significance of cracks in containment bldg. Review will be finished after util performs structural integrity test.
  RINALDI,F. Structural & Geotechnical Engineering Branch.
  83/07/22. 2pp. 19705:161. 24X Fiche: 50-329,83/07/22.8307250390.
- B307260254 Notice of receipt of Govt Accountability Project request fo action under 10CFR2.206 to modify CPs by imposing mandatory hold points on remaining const work & by requiring mgt audit.

  JDRDAN, E. t. Director's Office, Office of Inspection and Enforcement 83/07/22. 2pp. 19727:087. 24X Fiche: 50-329, 83/07/22, 8307260254.
- B307280153 Corrects mischaracteritation & misrepresentation rerelationship between CPC & G Charnoff & attendance at 821124 meeting. MILLER,M.I. Isham Lincoln & Beale. 83/07/25 BECHNUEFER, C., CUMAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 5pp. 19791: 295. 24X Fiche: 50-329, 83/07/25, 8307280153.

- SOCRACTION Motion to squash supposes issued to employees & negretaritatives of Gout Accountability Projectinequesting simulations of successions contributed of SVC and Rejuster concessorance of SVC BERNAGEL & Standard & SERNABELL Standard & SERNABELL Standard Accountability Project 83/07/24 Atomic Safety and Strenard Accountability Project 83/07/24 Atomic Safety and Strenard Sernagel Socratability Project 83/07/24 Piche: 50-329,83/07/26, 0307/26/161
- H General istraspondence
- E30705010: Responds to E30418 concerns relact of prof engineering registration of certain Sechtel employees performing work at facility 6 lack of qualified/trained people doing Zack design work Insplin progress REPRIES U.S. Region 3. Office of Director 83/06/27. SINCLAIR.M. Aveillation Unknown 2pp 19220.001 24X Fiche: 30-029, 83/06/27. Gittabioliti
- --GDD70tD11: Discusses subcontractor employee concerns re unqualified pensornel at plant site in jobs of critical importance to mafety, poor installation & lack of worker qualification on lack design investigation requested SINGLAIR/M Affiliation Unknown B3/G4/18 MEPPLER, J. Region 3, 84fice of Director lipp 19220.003 24x Fiche: 50-329, 83/06/27, 6007240101
- B337CT0184 Forwards response to B30531 ltr re util independent thirdparty dws19m & const verification program & const completion program Actions being taken should provide assurance to community that plant constructed safely. MEPFLER: 9 Region 3. Office of Director. 83/06/28. ROMO,L.R. Long Tree Council 3pp. 19195-162. 24X Fiche: 50-329, B3/06/28, B317CT0184
- --0307050100 Ack receipt of response re independent audit of facility. Truly independent audit should include full scope overview of completed const done by third party rather than util. REMOLUR Lone Tree Council 83/05/31. KEPPLER.J.G. Region G. Office of Director 3pp. 17195-033 24X Fiche: 50-329, 83/06/28, 8307050104
- 8337210242 Pequests available nontechnical info re problems w/ engineering design/specs & or implementation of engineering work for plants MATMERIC W. Michigan, State of, 83/07/08 KEPPLER, J. Q. Region 3/ 0ffice of Director ip 19664-164 24X Fiche: 50-000, 83/07/08, 8307210242
- 9 Inspection reports, IE Bulletins & correspondence
- 8307720001 FOIA request for all records re NRC insps & evaluations of util const activities in soils work leading to Spessard meta GARDE. 8 P. Gavernment Accountability Project. 83/03/22. TOMS: N. OFFice of Administration ip. 19787: 321. 24x Fiche: 50~329, 83/03/22.63072.0001.
- 8307220002 Respands to FOIA request for records re IE insps & evaluations of util const activities in soils work leading to Spesserd mans Forwards documents listed in App A. FELTON. J. B. Division of Rules and Records 83/05/18. GARDE, B. Gavernment Accountability Project 2pp. 19787:323. 24X Fichs 50-329.83/05/18,8307240002.
- --8307210004 "Insp Evaluation," re IE Insp Repts 50-329/82-11 & 50-330/82-11 on 820519-0702 LANSSMAN,R B NRC No Detailed Affiliation Given 82/09/02. Sp 19787 325. 24% Fiche 50-329.83/05/18.8307260002.
- --83372c0006 "Insp Evaluation," re IE Insp Repts 50-329/82-17 & 50-339/82-17 on 820809-13. PIN-M. P.GGINSON, D. NRC - No Detailed Affiliation Given. 62/08/20 2pp 19787-327 24X Fiche 50-329,83/05/18,8307260002.
- --8307200011 Notifies of 820330 meeting w/otil re underpinning activity. Principle points to be discussed include practicality of requirements 5 transition between various phases of project. MELLAMB.C. LITTLE-N.S. NRC No Detailed Affiliation Given. 82/03/24 NORELIUS.C.E. Pagion 3. Office of Director. 3pp. 1978/ 331 24x Fiche 50-329,83/05/18,8307260002.

- --8307260014 Requests list of actions for licensee to correct deficiencies noted in underpinning.piping & electrical areas. Info needed for meeting preparation.

  NORELIUS, C. E. Region 3. Office of Director. 82/05/07.

  LITTLE.W.S. Region 3. Office of Director. 19. 19787:336. 24X

  Fiche: 50-329,83/05/18,8307260002.
- --B307260019 Discusses participation in 820521 ACR8 briefing on facility OA program Statement should be drafted by 820519.
  NORELIUS.C.E. Region 3. Office of Director. 82/05/14.
  LITTLE.W.S. NRC No Detailed Affiliation Given. 1p. 19787:337.
  24X Fiche: 50-329.83/05/18.8307260002.
- --8307240021 Forwards comments on ASLB orders & applicant response reconstractivities.
  NORELIUS.C.E. Division of Engineering. 82/05/18. ADENSAM.E. Licensing Branch 4. App. 19787:338. 24X Fiche:30-329,83/05/18,8307260002.
- B307060349 Ack receipt of 830624 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-06 & 50-330/83-06. WARNICK,R.F. Region 3, Office of Director. B3/06/30. COOK, J. H. Consumers Power Co. 1p. 19234:180. 24X Fiche: 50-329,83/06/30, 8307060349
- --8307060356 Responds to NRC 830527 itr re violations noted in 1E Insp Repts 50-327/83-06 & 50-330/83-06. Corrective actions: D&W OC procedures re supplier quality evaluation revised to clarify requirements for performing audits. CDOK, J. W. Consumers Power Co. 83/06/24. KEPPLER, J. G. Region 3, Office of Director. 4pp. 19234: 181. 24X Fiche: 50-329, 83/06/30, 8307060349.
- B307140337 Forwards IE Insp Repts 50-329/83-10 & 50-330/83-10 on 830321-0520 & notice of violation.

  MARNICK.R.F. Region 3, Office of Director. 83/06/30. CODK, J. W. Consumers Power Co. 2pp. 19525:255. 24X Fiche: 50-329, 83/06/30, 8307140337.
- --8307140341 Notice of violation from inso on B30321-0520. WARNICK, R.F. Region 3, Office of Director. 83/06/30. 1p. 19525: 257. 24X Fiche: 50-329, 83/06/30, 8307140337.
- ---8307140344 IE Insp Repts 50-329/83-10 & 50-330/83-10 on 830321-0520, Noncompliance noted: inadequate storage facilities for HVAC components, BURGESS, B.L., COOK, R. J., GARDNER, R. N. Region 3, Office of Director, 83/06/30, 9pp. 19525: 258. 24X Fiche: 50-329,83/06/30,8307140337.
- --B307140349 "Independent Assessment of Auxiliary Bldg Underpinning Heekly Rept 24." for 830313-19. W/830323 ltr.
  LUCKS.A.S. Stone & Webster, Inc. B3/03/23. COOK, R. NRC Na
  Datafled Affilation Given. 9pp. 19325:267. 24X
  Fiche: 50-329,83/06/30,8307140337.
- --8307140352 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 27." for 830320-26.M/830401 ltr. LUCKB.A S. Stone & Webster, Inc. 83704701. CDOK, R. NRC - No Detailed Affiliation Given. 7pp. 19525:276. 24X Fiche: 50-329.83706730.8307140337.
- ---8307140354 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 28." for 830327-0402. W/830407 ltr.
  LUCKB.A.B. Stone & Webster, Inc. 83/04/07. COOK.R. NRC No Detailed Affiliation Given. 9pp. 19525:285. 24X
  Fiche: 50-329.83/06/30.8307140337.
- --8307140358 "Independent Assessment of Auxiliary Bldg Underpinning Heekly Rept 29," for 830403-09. W/830415 ltm. LUCKS.A.S. Stone & Webster, Inc. 83/04/15. COOK,R. NRC - No Detailed Affiliation Given. 9pp. 19925:274, 24X Fiche: 50-329,83/06/30,8307140337.
- --8307140361 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 30." for 830410-16. W/830421 ltr. LUCKS.A.S. Stone & Webster, Inc. 83/04/21. CDCK,R. NRC No Detailed Affiliation Given. 9pp. 17525:303. 24X Fiche: 50-329,83/06/30.8307140337.
- --8307140365 "Independent Assessment of Auxiliary Bidg Underpinning Weekly Rept 31," for 830417-23.W/830427 ltr.
  LUCKS.A.S. Stone & Webster, Inc. 83/04/27. CDOK.R. NRC No Detailed Affiliation Given. 10pp. 19525:312. 24X Fiche: 50-329,83/06/30.8307140337.
- --8307140370 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 32." for B30424-30.W/B30505 ltr.
  LUCKS.A.S. Stone & Webster Inc. B3/05/05. CBQK,R. NRC No Detailed Affliation Given. 9pp. 19525:322. 24X
  Fiche:50-329,83/06/30.8307140337.

- -8307140373 "Independent Assessment of Auriliary Bldg Underpinning Weekly Rept 33," for 830501-07.W/830510 ltr LUCKS-A-S. Stone & Webster: Inc. 83/05/10. COBK,R. NRC No Detailed Affiliation Given. 10pp. 19525:331. 24X Fiche:50-329,83/06/30,8307140337.
- --8307140378 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 34." for 830508-14.W/830518 ltr.
  LUCKS.A.S. Stone & Webster. Inc. 83/05/18 CDOK.R. NRC No Detailed Affiliation Given. 9pp. 19525:337. 24X
  Fiche: 50-329.83/06/30.8307140337.
- 8307140032 Forwards IE Insp Repts 50-329/83-07 % 50-330/83-07 on 830420-21.25-29 & 0509-20 & notice of violation.

  MARNICK.R.F. Region 3. Office of Director. 83/07/01. COOK, J. W. Consumers Power Co. 2pp. 19514: 203. 24X Fiche: 50-329, 83/07/01, 8307140032.
- --8307140038 Notice of violation from insp on 830420-21.25-29 & 0509-20. WARNICK, R. F. Region 3, Office of Director. 83/07/01. 2pp. 19514:203. 24X Fiche: 50-329, 83/07/01.8307140032.
- ~~8307140044 IE Inso Repts 50-327/83-07 & 50-330/83-07 on 830420-21,25-27 NO/140044 IE Insp Repts 50-327/83-07 to 00-330/83-07 on 830420-21:25: \$ 0509-20. Noncompliance noted: failure to take corrective action re pipe hangers & hanger components found in Kelly bldg w/o release for const tags attached. SIMON, J.A.; SATHER.A., HARTISON, J.J. Region 3, Office of Director, 83/06/30. 4pp. 19514:207. 24X Fiche:50-329.83/07/01:8307140032.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDÁN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- B306270404 IE Info Notice 83-47, "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York: Inc. 141pp. 17963:153. 24X Fichs: 50-000.83/07/12.8306270404.
- 8307250123 Forwards amended response to JG Keppler 830523 ltr re notice of violation, item B, concerning failure to establish measures for Q matls associated w/diesel generator eshaust muffler, supplementing 830624 ltr.
  COOK J. W. Consumers Power Co. 83/07/12. KEPPLER, J. G. Region 3, Office of Director. 9pp. 19706:074. 24X Fiche:50-329,83/07/12,8307250123.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York. Inc. 114pp. 19715: 270. 24X Fiche: 50-000.83/07/14.8306270406.
- 8307210259 Response to B Stamiris 830627 motion to reapen record on Stamiris Contention 4 re integrity of containment & soils underprinting operations founded upon glacial till Motion unsubstantiated & should be denied Certificate of Svc encl. STEPTOE.P.P. Consumers Power Co. STEPTOE.P.P. Isham, Lincoln & Beale. 83/07/18. Atomic Safety and Licensing Board Panel. 10(17465:00). 24X Fiche: 50-329, 83/07/18, 8307210259.
- --8307210271 Revised "Visual Insp of Cracks in Containments Near Anchorages in Rooms 110 & 116." CORLEY.H.G. Construction Technology Laboratories. 83/04/30. 7pp. 19665:032. 24X Fiche:50-329,83/07/18,8307210259.
- 8307260451 Suppls B30503 commitment to implement expanded cooling pond dike surveillance program. Damaged turf on dike will be repaired within 1 month—after detection consistent w/insp program

  COOK.J.W. Consumers Power Co. 83/07/18. DENTON.H.R. Office of
  Nuclear Reactor Regulation. Director. 2pp. 19734:204. 24X

  Fiche: 50-329, 83/07/18, 8307260451.
- R. Periodic operating reports & related correspondence
- B307050006 Forwards util status rept for Apr-May 1983 covering electrical cables remedial soils work & significant meetings.

  HARNICK, R.F. Region 3. Office of Director. B3/06/28. KEPPL Region 3. Office of Director. ip. 19172:113. 24X Fiche: 50-329.83/06/28.8307050006. 83/06/28. KEPPLER: J. G.
- --8307050017 Forwards util status rept for Apr-May 1983 covering electrical cables, remedial soils work & significant meetings.

  GODK.R.J. Region 3, Office of Director. 83/06/24, WARNICK.R.F. Region 3, Office of Director. 3pp. 19192:114. 24X Fiche: 50-329, 83/06/28, 8307030006.

- 8307080514 Forwards proposed list of work per "NRC & CPC Work Authorization Procedure." for month of Jul 1983. Supplemental work activity list for Aug 1983 also encl. MCONEY, J.A. Consumers Power Co. 83/06/30. HARRISON, J. J. NRC No Detailed Affiliation Given. 22pp. 19362:114. 24X Fiche: 50-329, 83/06/30, 8307080514.
- 8307140337 Forwards IE Insp Repts 50-329/83-10 % 50-330/83-10 on 830321-0520 % notice of violation.

  HARNICK R F. Region 3. Office of Director. 83/06/30 COOK, J W. Consumers Power Co. 2pp. 19325:255 24% Fiche:50-329,83/06/30, B307140337
- -8307140349 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 26," for B30313-17.W/830323 ltr.
  LUCKS.A.S. Stone & Webster, Inc. 83/03/23 CODK.R. NRC No Detailed Affiliation Given. 7pp. 19325.267. 24X
  Fiche: 50-329.83/06/30.8307140337.
- --8307140352 "Independent Assessment of Aurillary Bldg Underpinning Weekly Rept 27," for 830320-26 W/830401 ltr.
  LUCKS-A.S. Stone & Webster, Inc. 83/04/01. COOK.R. NRC No Detailed Affiliation Given. 9pp. 19525:276. 24x
  Fiche: 50-329,83/06/30,8307140337.
- -8307140354 "Independent Assessment of Auxiliary 81dg Underpinning Weekly Rept 2B." for 830327-0402. W/830407 itr. LUCKB.A.S. Stone & Webster, Inc. 83/04/07. CODK.R. NRC No Detailed Affillation Given. 9pp. 19525:285. 24X Fiche: 50-329,83/06/30,8307140337.
- --8307140358 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 29." for 830403-09. W/930415 ltr. LUCKS.A. S. Stone & Webster, Inc. 83704715. COOK,R. NRC No Detailed Affilation Given. 9pp. 19325: 294. 24X Fiche: 50-329,83706/30,8307140337.
- -8307140361 "Independent Assessment of Auxiliary Blóg Underpinning Weekly Rept 30." for 830410-16.W/830421 ltr. LUCKS.A.S. Stone & Webster, Inc. 83/04/21. CODK,R. NRC No Detailed Affiliation Given 9pp. 19525:303. 24X Fiche. 50-329,83/06/30.8307140337.
- --B307140365 "Independent Assessment of Auriliary Bldg Underpinning Weekly Rept 31." for B30417-23.W/B30427 ltr. LUCKS-A S. Stone Webster, Inc. B3/04/27. CODK.R. NRC No Detailed Affiliation Given. 10pp. 19525:312. 24X Fiche: 50-329.B3/06/30.B307140337.
- -8307140370 "Independent Assessment of Auviliary Bldg Underpinning Heakly Rept 32," for 830424-30.W/830505 ltr. LUCKS.A.S. Stone & Webster, Inc. 83/05/05. COOK,R. NRC No Detailed Affiliation Given. 9pp. 19925:322. 24X Fiche:50-329,83/06/30.8307140337
- --8307140373 "Independent Assessment of Auxiliary Bldg Underpinning Heekly Rept 33," for 830501-07. M/830910 ltr. LUCKG.A S. Stone & Webster, Inc. 83/05/10. CODK,R. NRC Na Detailed Affilation Given. 10pp 19925: 331 24X Fiche: 50-329,83/06/30,8307140337.
- -8307140378 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 34," for 830508-14.W/B30518 ltr. LUCKS.A.S. Stone & Webster, Inc. 83/05/18. CODK.R. NRC No Detailed Affiliation Given 9pp. 19325:337 24X Fiche: 50-329,83/06/30,8307140337.
- B307210225 Forwards "Midland Independent Design & Const Verification Program," second monthly status rept for B30528-0630. LEVIN.H A TERA Corp. B3707715. KEPPLER.J G. Region 3. Office of Director. CODK.J M. Consumers Power Co. EISENHUT.D.C. Division of Licensing 3pp. 19666:217. 24X Fiche 50-329.83/07/15.8307210225.
- --8307210233 "Midland Independent Design & Const Verification Program," Monthly Btatus Rept 2 for 830520-830630. LEVIN-H.A., TULODIESKI, D., BECK, J. TERA Corp. 83/07/15. 70pp. 19666:220. 24X Fiche:50-329.83/07/15.8307210225
- B30721029) Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept 2." second monthly status rept for B30528-0630.

  LEVIN.H.A. TERA Corp. 83/07/15. EISENHUT.D.G. Division of Licensing. KEPPLER.J.O. Region 3. Office of Director. COOK.J.W. Consumers Power Co. 3pp. 17664:210. 24X Fiche: 50-329, 83/07/15.
- --8307210296 "Midland Independent Design & Const Verification Program Monthly Status Rept 2," second monthly status rept for 830528-0630.
  LEVIN:H.A., TULODIESKI,D. TERA Corp. 83/06/30. 70pp. 19664:213. 24X Fiche: 50-329,83/07/15,8307210291.

- 5. Reportable occurrences, LERs & related correspondence
- 8307050011 Interim deficiency rept re delivered safety-related electrical equipment not meeting project requirements. Task force established to investigate & resolve MCAR 65. Next rept by 830812.
  CDCM. J. W. Consumers Power Co. 83/06/29. KEPPLER, J. G. Region 3. Office of Director 10pp. 19251:016. 24X Fiche: 50-329, 83/06/29, 8307069011.
- 8307060310 PNO-III-83-055:Region III authorized resumption of safety-related welding on HVAC sys at const site. Zack Co welding procedures & observations of welding performance demonstrations reviewed.

  OARDNER.R.: HARRISON.J. Region 3. Office of Director. 83/06/29. ip. 19238:331 24x Fiche:50-329.83/06/29.8307060310.
- 8307060340 PND-III-83-057: on 830629, Dechtel firad lead welding engineer for allegedly instructing rod room attendant to falsify number of weld rod withdrawal slips. No safety significance resulted from incident.

  LANDSMAN. R. HARRISON. J. Region 3, Office of Director. 83/06/30. ip 19236: 254. 24X Fiche: 50-329, 83/06/30, 8307060340.
- 8307080436 Interim deficienty rept re loose locking clips (Tinnerman speed nots). Vendor approved tooling & installation & insp procedures for replacing Tinnerman speed nots, beginning in late Jul. Nest rept to be submitted by 830930.

  CDBK.J.W. Consumers Power Co. B3/06/30. KEPPLER, J. O. Region 3, Office of Director. 2pp. 19346:359. 24X Fiche: 50-327, 83/06/30, 8307080436.
- 8307180171 Interim deficency rept re potentially unsafe situation concerning tripping of reactor coolant pumps during certain primary sys high void fraction conditions Pump trip criteria will be established per NRC Generic Ltr 83-t0. COOK, J. W. Consumers Power Co. 83/07/11. KEPPLER, J. G. Region 3. 0ffice of Director. 2pp. 19555:084. 24X Fichs: 50-329, 83/07/11. 8307180171
- B307180270 Interim deficiency rept re reactor bldg spray piping supports. Initially reported on 791221. Increased loads observed on piping & piping anchors caused by simplifying modeling assumptions.

  COOK, J. W. Consumers Power Co. B3/07/11. KEPPLER, J. G. Region 3, Office of Director. 7pp. 19556. 187. 24X Fiche: 50-329, B3/07/11, B307180270.
- 8307200195 PNO-III-83-061: on 830714, Region III notified that Dow Chemical Co terminating contract w/util to supply process steam to facility. Suit seeking court judgement that all contract obligations canceled filed.

  HARRISON. J., WARNICK. R. Region 3, Office of Director. 83/07/15.

  1p. 19651: 246. 24X Fiche: 50-329, 83/07/15, 8307200155.
- 830725043! Interim deficiency rept re electrical accessories associated w/safety-related mat1 requisitions. Guidelines & checklist being developed for review of safety-related mat1 requisition requirements. Next rept espected by 831014. COOK, J. W. Consumers Power Co. B3/07/15, KEPPLER, J. G. Region 3, Office of Director. 6pp. 17702:162. 24% Fiche:50-329,83/07/15,8307250431.
- 8307280191 Final deficiency rept re absence of close-latch anti-shock spring in Brown Boveri Electric type HK circuit breakers mfg between June 1975 & June 1977. Initially reported on 8300623. Corrective actions will be completed by 830824. COOK, J.W. Consumers Power Ca. 83/07/22. KEPPLER, J. G. Region 3, 0ffice of Director. 6pp. 19791:247. 24x Fiche:50-329,83/07/22,8307280191.
- 8307280272 First interim deficiency rept reliack of dc-backed power supplies for FDGG interlack relays in auxiliary feedwater sys. Initially reported on 830622 Schematic diagram E-158(g) & associated compaction & panel drawings revised. COOK, J.W. Consumers Power Co. 83/07/22. KEPPLER, J.G. Region 3, 05fice of Director. 4pp. 19791:207. 24% Fiche: 50-329,83/07/22,8307280272.
- T Hearing transcripts on non-antitrust matters
- B307010058 Transcript of B30627 hearing in Midland, MI. Pp. 17, 978-18, 234.
  Supporting documentation encl.
  \* Atomic Safety and Licensing Board Panel. 83/06/27. 900pp.
  19174: 180. 24x Fiche: 50-329, 83/06/27, 8307010058.
- B307060451 Forwards five viewgraphs used at B30615 briefing to be included in transcript.
  TIPTON.A. Office of the Secretary of the Commission. B3/06/27.
  Public Document Branch. 6pp. 19299:115 24X Fiche 50-329, 83/06/27.

- 8307050044 Transcript of 830628 hearing in Midland, MI. Pp 18, 235-18, 504.
  - 18,304. \* Atomic Safety and Licensing Board Panel. 83/06/28. 7pp. 19192:175. 24X Fiche:50-329,83/06/28,8307050044.
- 8307050073 Transcript of 830629 hearing in Midland.MI.Pp 18,505-18,771. \* Atomic Safety and Licensing Board Panel. 83/06/29. 268pp. 19198:006. 24X Fiche:50-329,83/06/29.8307050073.
- # Atomic Safety and Licensing Board Panel. # 37/06/30. 19352: 290. 24X Fiche: 50-329, 83/06/30, 8307080274.
- 8307080279 Transcript of 830701 hearing in Midland, MI. Pp. 18, 959-19, 071. \* Atomic Safety and Licensing Board Panel. 83/07/01. 114pp. 19352: 174. 24X Fiche: 50-329, 83/07/01, 8307080279.
- 8307210194 Testimony of RM Wheeler & BH Pack re QA inadvertently omitted from 830630 transcript of hearing in Midland, MI. Supporting documentation encl. \* Atomic Safety and Licensing Board Panel. 83/07/12. 60pp. 19665: 112. 24X Fiche: 50-329, 83/07/12, 8307210194.
- 8307190252 Forwards PS Glass & R Black testimony, Tentative schedule of witnesses listed Certificate of Svc encl.
  LAUER, R. J. Isham, Lincoln & Beale. LAUER, R. J. Consumers Power Co. B3/07/15. HARBOUR, J., BECHHOEFER, C., COWAN, F. P. Atomic Safety and Licensing Board Panel. 4pp. 19628:03B. 24X Fiche: 50-329, 83/07/15, B307190252.
- --8307190298 Testimony of R Black re events during late Winter 1982 & early Spring 1982 & installation of cable related to instrumentation for underpinning work on auxiliary bldg. BLACK.R. Consumers Power Co. BLACK.R. Bechtel Corp. 83/07/11. 24pp. 19628:042. 24X Fiche:50-327.83/07/15.8307190252.
- --8307190260 Testimony of PS Glass re cable & conduit installation for underpinning instrumentation of auxiliary bldg. Oversize matrix encl. Aperture card available in PDR. GLASS, P. S. Gonsumers Power Co. GLASS, P. S. Bechtel Corp. B3/07/11. 15pp. 17428:064. 24X Fiche: 50-329, 83/07/15, 8307190252.
- 8307220351 Forwards RL Black affidavit on testimony Svc list encl. LAUER, R. J. Isham, Lincoln & Beale. LAUER, R. J. Consumers Power Co. 83/07/18. HARBOUR, J. COMAN. F. P., BECHHOEFER. C. Atomic Safety and Licensing Board Panel. 3pp. 19675: 332. 24X Fiche: 50-329, 83/07/18, 8307220351.
- 8307280180 Transcript of 830726 oral argument in Bethesda, MD. Pp 19,072-19,174. \* Atomic Safety and Licensing Board Panel. 83/07/26. 102pp. 19793: 254. 24X Fiche: 50-329, 83/07/26, 8307280180.
- DOCKET 50-330 MIDLAND PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 8307110405 Forwards Rev 1 to "Const Project Evaluation of CPC Midland Energy Ctr Project Units 1 & 2."
  CDOK.J.W. Consumers Power Co. 83/03/09, KEPPLER.J.G. Region 3, 07fice of Director. 2pp. 19382:292. 24X Fiche: 50-329, 83/03/09,
- 8307140256 Forwards 830307.08.0405 & 07 meeting notes, including associated documents provided to NRC on 830315.R Landsman 830412 discussion verifying that Region III will provide authoritation to excayate portions of Pier 85/M. MELLER, D. B. Consumers Power Co. 63/04/14. HARRISON, J. J. Region 3, Office of Director. 25pp. 19523:009. 24X Fiche: 50-329, 83/04/14, 8307140256.
- 830714021: Forwards response to Items A1, 2, 3, 4, 6, 7, 8 % submittal in NRC 830328 ltr re const completion program covering procedures for controlling release of new work & personnel training.
  CODK, J. W. Consumers Power Co. 83/04/22, KEPPLER, J. 9, Region 3, Office of Director. 17pp. 17522:027. 24X Fiche: 50-327, 63/04/22, 8307140211.
- B307080453 Forwards Rev 1 to GC Instrumentation 10.01. "Const Implementation Overview Assessment." BARANON, S.W. Stone & Webster, Inc. 83/06/28. KEPPLER, J. G. Region 3. Office of Director. 1p. 19347:256. 24X Fiche: 50-329, 83/06/28, 8307080453.

- 8307080508 Confirms that listed responses to Region III inspector R Landaman questions, provided to B Burgess. NRC resident inspector, on 830608. Responses concern concrete truck drum revolving & Drawing C-1427.

  MOGNEY, J. A. Consumers Power Co. 83/06/28. HARRISON, J. J. Regio Office of Director. 2pp. 19346:348. 24X Fiche: 50-327.83/06/28. Region 3.
- 830711003B Forwards Rev 1 to 0C Instruction GCI 10.01, "Const Implementation Overview Assessment." 8ARANOM, S.W. Stone & Webster, Inc. 83/06/28, KEPPLER, J. G. Regio 3, Office of Director. 1p. 19375: 298, 24X Fiche: 50-329, 83/06/28,
- --5307110040 Rev 1 to GC Instruction QCI 10.01, "Const Implementation Qverview Assessment."

  \* Stane & Webster, Inc. 83/06/27. 6pp. 19373:299. 24X Fiche: 30-329,83/06/28,8307110038.
- 8307050033 Advises that review of Zack Co welding procedures & welder performance testing completed. Util authorized to proceed w/fabrication & welding of HVAC sys.

  HARRISON, J. J. Region 3, Office of Director. 83/06/29. MILLER, D. Consumers Power Co. 2pp. 19192:159. 24X Fiche: 50-329, 83/06/29, 83/05053.
- B307110555 Discusses staff requirements memo re B30615 brisfing on GA deficiency status. Deficiencies resulted in safety-related work stoppage on B21203 & resulted from work performed subsequent to Aug 1980 reorganization.
  DIRCKG,W.J. Office of the Executive Director for Operations.
  B3/06/29. CHILK,S.J. Office of the Secretary of the Commission.
  1p. 19434:138. 24X Fiche:50-329,83/06/29,8307110555.
- --8307110564 Staff requirements memo re 830615 briefing in Washington.DC on GA problems. Commissioner Gilinsky requested info whether deficiencies involved const completed before or after Aug 1980 GA dept formation.
  CHILK,S. J. Office of the Secretary of the Commission. 83/06/20.
  DIRCKS.W. J. Office of the Executive Director for Operations. 1p. 19434:137. 24X Fiche: 50~329, 83/06/27, 8307110355.
- 8307060037 Provides info re natural circulation testing addressing concerns on boron mixing & use of reactor vessel head vent temp indication in response to NRC 830617 telcon request GA program approving FSAR change notice encl.

  DEWITT.R.B. Consumers Power Co. 837/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 19250:350. 24X Fiche: 50-329, 83/06/30, 8307060057.
- B307110305 Forwards comments on mgt review committee 830623 meeting re-bulk hanger organization. Mods ready for implementation. BARANDW, S. W. Stone & Webster, Inc. B3/06/30, KEPPLER, J. G. Region 3, Office of Director. 2pp. 19378: 330. 24X Fiche: 30-327, B3/06/30, B307110305.
- 8307120245 Forwards Core Damage Assessment Procedure Station 9918.1, "Estimation of Extent of Core Damage." Encl changes to NUREG-0737.1tem II. B. 3 re post-accident analytical accuracies will be incorporated into FSAR rev. COOX, J. W. Consumers Power Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 19422:308. 24X Fiche: 50-329.83/07/01.8307120245.
- --8307120248 Core Damage Assessment Procedure STATION 9718.1, "Estimation of Extent of Core Damage."

  \* Consumers Power Co. 83/06/30. 47pp. 19422:315. 24X
  Fiche: 50-329,83/07/01,8307120245.
- B307130335 Trip rept of B30422 visit to TERA Corp in Bethesda, MD to observe filing sys for controlled documents associated w/facility independent design & verification program. HODD, D. S. Licensing Branch 4. 4pp. 19508:352. 24X Fiche:50-329,83/07/01,8307130335.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIEENMUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307110010 Advises that remedial soils activities identified in Section 1 of Attachment A & presently scheduled for Jul 1983 have been identified as critical Details of activities requested to assist in review.

  HARRISON, J. J. Region 3, Office of Director. 83/07/05, MILLER, D. B. Consumers Power Co. 3pp. 19374:211. 24X Fiche: 50-329,83/07/05,8307110010.

- 8307260547 Rev 1 to "Third-Party Const Implementation Overview" W/830714 ltr.
  KELLY,R B., DARANDW,S.W. Stone & Webster, Inc. 83/07/05.
  KEPPLER.J.G. Region 3, Office of Director 6pp. 19731: 320. 24X
  Fiche: 50-329, 83/07/05, 8307260547.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.Svc list encl. EISENHUT.D.C. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669-254 24X Fiche: 30-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENNUT.D.G. Division of Licensing. 83/07/08. Consultdated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307110311 Authorizes Remedial Soils Work 312150011 & 322150011 for const of new ring beam for manth of Jul. HARRISON J. J. Region 3, Office of Director. B3/07/08. MILLER, D. B. Consumers Power Co. 2pp. 19381:001 24X Fiche: 50-327, 83/07/08, 9307110311
- B307180301 Summary of B30709 meeting w/otil in Washington DC re-development of const completion program. CUNNINGHAM, O. H. Office of the Executive Legal Director. B3/07/08 Office of the Executive Legal Director. 1p. 19546:11B. 24x Fiche: 50-329, 83/07/08, 8307180301.
- 8307200079 Forwards 19 oversize drawings & figures & various hydrographs from observation wells & piezometers nearest containments, in response to NRC request for info re reactor bldg settlement, Aperture cards are available in PDR. MODNEY, J. A. Consumers Power Co. 83/07/08. HARRISON, W. J. Region 3, Office of Director. 186pp. 19650.008. 24x Fiche: 50-329, 83/07/08, 8307200079.
- 8307200316 Summarizes 830615 telcon w/applicant re accuracies in required post-accident analytical chemistry procedures per NUREG-0737. Item II. 8.3. Acceptable gamma spectrum analysis will be submitted in early Jul 1983.

  MILLER, M. A. Licensing Branch 4. 83/07/11. Licensing Branch 4. 87/07/11. Biography 19656: 343. 24% Fiche: 50-327. 83/07/11. 8307200316.
- 8307200318 Summarizes 830628 telcon w/applicant & Bechtel re NRC request for add1 info on motion before hearing board to reapen contentions concerning effect of dewatering on settlement of Unit 1 reactor containment bldg.

  MILLER.M.A. Licensing Branch 4. 83707711. Licensing Branch 4. 4pp. 19656:339 24% Fiche: 50-329,83707711,8307200318.
- 8307220402 Forwards Rev 3 to "NSSS Equipment & Piping," Vol VIII to Seismic Margin Review."

  GOOK, J. W. Consumers Power Co. 83/07/11. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19691:175. 24X
  Fiche: 50-329, 83/07/11. 8307220402.
- --8307220411 Rev 3 to "NSSS Equipment 3 Piping," Vol VIII to "Seismic Margin Review." KIPP, T.R., CAMPBELL, R.D., KENNEDY, R.P. Structural Mechanics Associates. SMA 13701.08R003 VOS. 83/07/31. 35pp. 19691:179. 24X Fiche: 50-329, 83/07/11, 8307220402.
- B307250253 Forwards Rev 1 to "Third-Party Const Implementation Overview Procedure." Procedure revised for clarity Requirement for monthly repts deleted.

  BARANOWS. M. Stone & Webster Engineering Corp. 83/07/14.

  KEPPLER. J. G. Region 3. Office of Director. 1p. 19705:134. 24X

  Fiche: 50-329, 83/07/14, 8307250253.
- --8307250261 Rev 1 to "Third-Party Const Implementation Overview Procedure." BARANON 5. H. Stone & Webster, Inc. 83/07/05. 5pp. 19705:135. 24X Fiche: 50-329, 83/07/14, 8307250253.
- 8307280434 Requests authorization to excavate & backfill trench for ground cable east of technical support ctr in accordance w/Work Authorization Procedure 942450300 MOONEY, J. A. Consumers Power Co. 83/07/14. HARRISON, J. J. Region 3, Office of Director. Ip. 19797.119. 24X Fiche: 50-329, 83/07/14, 8307280434.
- 8307210125 Requests appropriate details of remedial soils work activities scheduled for month of Jul 1983 to assist in review.due to criticality of activity.

  HARRISON, J. J. Region 3: Office of Director. 83/07/15. MILLER, D. B. Consumers Power Co. 3pp. 19666:085. 24X Fiche:50-329.83/07/15, 8307210125.

- --8307210144 Requests authorization to excavate % backfill trench for ground cable east of technical support ctr per work authorization procedure.

  MCONEY, J.A. Consumers Power Co. 83/07/14, HARRISON, J. J. Region 3, Office of Director. 1p. 19666.088, 24X Fiche:50~329,83/07/15,8307210125.
- 8307210208 forwards "Rept of Overhead Fluid Grouting Testing Program," info re svc water pump structure, procedure for drilling in "G" concrete & justification for continuing soils work in response to NRC 830714 questions re soil drilling. MODNEY, J. A. Consumers Power Co. 83/07/15, MARRISON, J. J. Region 3, 0ffice of Director. 20pp. 19667.034. 24X Fiche: 50-329,83/07/15, 8307210208.
- --8307210210 "Rept of Overhead Fluid Grouting Test Program." \* Consumers Power Co. 83/07/15, 47pp. 19667;054, 24x Fiche 50-329,83/07/15,8307210208.
- 8307240320 Forwards B&W info re non-nuclear instrumentation/integrated control sys failures for generic pressurized thermal shock study BAW-1743, Table B revised to reflect Failure 4 description.

  CODK, J. M. Consumers Power Co. 83/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 19726; 302. 24X Fiche: 50-329, 83/07/19, 8307260320.
- 8307250470 Discusses concerns re structural adequacy of diesel generator bldg due to numerous structural cracks occurring throughout bldg over yrs. Recommends remedial structural fires be undertaken to ensure structural integrity.

  LANDSMAN.R. D. Region 3. Office of Director. 83/07/19. MARNICK.R.F. Region 3. Office of Director. 2pp 19701:195. 24X

  Fiche: 50-327,83/07/19,8307250470.
- B307290113 Forwards "Seismic Margin Review, Vol III, Auxiliary Bldg," describing method of analysis & resulting seismic margins. Considerable amount of margin exists in design. BUCKMAN.F.W. Consumers Fower Co. 83/07/22. DENTON, N.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19822: 223. 24X Fich: 50-329, 83/07/22, 8307270113.
- --B307290118 "Seismic Margin Review.Vol III.Auxiliary Bldg."
  WESLEY, D. A., KENNEDY, R.P., KINCAID, R.H. Structural Mechanics
  Associates. SMA 13701.038003 V03. B3/06/30. 255pp. 19822:227
  24X Fiche: 50-329,83/07/22,8307290113.
- 8307290191 Forwards Rev 14 to Vol 1 of GA program manual, Policy 1, "Organization." Changes organizational, Previous commitments remain unchanged BUCKMAN.F.W. Consumers Power Co. 83/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19821: E11. 24X Fiche: 50-329.83/07/22.8307290191.
- --8307290196 Rev 14 to Vol I of GA program manual, Policy 1, "Organization." a Consumers Power Co. 83/06/29, 25pp. 19821:114, 24X Fiche, 50-029, 83/07/22, 8307290191.
- B307280339 Summarizes 830720 meeting w/Bechtel in Olen Eilyn, IL reactions as result of certain NRC concerns on procurement quality tasues discussed at 821029 meeting in Ann Arbor, MI. WARNICK, R. F. Region 3, Office of Director. 83/07/26. Region 3, Office of Director. 83/07/26, 83/07/26, 9307280339.
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 830706006: Submits add1 info on SER Confirmatory Issue 19 re testing of auxiliary feedwater pump suction transfer logic Proposed quarterly test of pump suction transfer logic usl1 be reflected in revised Tech Specs.

  DEWITT, R.B. Consumers Power Co. 83/06/29 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 2pp. 19251:060. 24X Fiche: 50-329, 83/06/29, 8307040061.
- 8307040057 Forwards info to complete SER Confirmatory Issue 14 re design bases used to categorize containment penetrations as essential or nonessential. Info will be included in next FSAR DEWITT.R. B. Consumers Power Co. 83/06/30. DENTON.H R. Office of Nuclear Reactor Regulation. Director. Spp. 19251:052. 24x
- 9307070152 Submits info re util turbine missile prevention commitment, per SER Open Item 2, in response to NRC 830504 Itr.
  Commitment to Option 2 should enable NRC to reclassify Open Item 2 or turbine missiles as confirmatory item.
  C40K.J.W. Consumers Power Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19294:252. 24X
  Fiche: 50-329,83/07/01.8307070152.

- B307120393 Forwards response to B30531 request for add1 info re numerical data used in conjunction w/setpoint methodology to calculate Tech Spec setpoints to complate review of SER Confirmatory Item 15.

  REYNOLDS, J. W. Consumers Power Co. 83/07/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 54pp. 19430:143. 24X Fich: 50-329,83/07/05,8307120393.
- 8307130346 Clarifies 830504 ltr re turbine sys maint program options for resolution of SER Open Item 2 on turbine missiles. NOVAK,T.M. Assistant Director for Licensing. 83/07/07. COOK, J. N. Consumers Power Co. 3pp. 19508:336. 24X Fichs: 50-327,83/07/07, 8307130346.
- 8307190423 Forwards supplemental SER input on environ qualification program for electrical equipment Schedules for completion of open items prior to future suppl requested. Input serves as summary of 83011-13 meetings.

  NOVAK.T.M. Assistant Director for Licensing. 83/07/08. COGK, J. M. Consumers Power Co. 32pp. 19644:318. 24X Fiche: 50-330, 83/07/08, 8307190423.
- 8307260236 Provides info re RCS makeup (MU) nozzles in response to NRC 830713 telcon & topics cancerning SER Open Item B. Commits to maintaining min continuous makeup flow of between 1.2 & 3 gpm. Info completes response to SER Item. CDGK, J.W. Consumers Power Co. 83707/18. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727:188. 24X Fiche: 50-327.83/07/18.8307260236.
- G. Adjudicatory correspondence
- 8307070020 Forwards Ofc of Investigation rept to alleged violation of ASLB 820430 order Rept, in conjunction w/brief oral direct testimony, constitutes NRC testimony to be presented at 830725 hearing on order violation. W/o encl. WRIGHT, N. A. Hearing Branch 2. 83/07/01. BECHHOEFER, C., COWAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 19273: 230. 24X Fiche: 50-327, 83/07/01, 8307070020.
- B307080462 Response to B30407 Request for Production of Documents B(b). Draft rept & investigator handwritten notes will be offered to ASLB for in camera review. WRIGHT.N.A. Hearing Branch 2. B3/07/06. BERNABEI.L. Stamiris, B. BERNABEI.L. Government Accountability Project. 1p. 19346:361. 24X Fiche:30-329,83/07/06,8307080462.
- B307110130 Forwards first installment of proposed findings of fact & conclusions of law on remedial soils issued, summarizing record on selsmology & seismic models. Certificate of Svc encl.

  STEPTUS.P.P. Isham, Lincoln & Beale. STEPTUS.P.P. Consumers Power Co. B3/07/06. BECHHUEFER.C., COWAN.F.P., HARBOUR.J. Atomic Safety and Licensing Board Panel. 4pp. 19373:034. 24X
  Fiche: 50-329, B3/07/06, B307110150.
- --8307110154 Proposed findings of fact & conclusions of law on remedial soils issues & seismic models.

  4 Consumers Power Co. 83/07/06. 59pp. 19375:038. 24X
  Fiche: 50-329, 83/07/06, 8307110150
- 8307150175 Response opposing deponent motion to quash subpoenas of
  L Clark.T Devine.BP Garde & L Hallberg re identity of
  anonymous whistleblowers. Appropriate protective order should
  be entered as alternative. Certificate of Svc encl.
  PROCTOR.S.D. Consumers Power Co. PROCTOR.S.D. Isham, Lincoln &
  Beale. 83/07/11. Atomic Safety and Licensing Board Panel. 3pp.
  19530:361. 24X Fiche:50-329,83/07/11.8307150195.
- 8307180077 Advises that 8 Marello deposition rescheduled for 830719. PROCTOR, S. D. Isham, Lincoln & Beale. 83/07/12. XELLEY, F. J., STEINBERG, C. Michigam, State of. 2pp. 19360:261. 24X Fiche: 50-329, 83/07/12, 8307180077.
- B307200104 Response opposing Govt Accountability Project motion to quash B30627 subportas. Motion based on incorrect premise since identification of informants not sought. Certificate of Svc encl.
  WRIGHT.N.A. Hearing Branch 2. B3/07/18. Atomic Bafety and Licensing Board Panel. 6pp. 19647:135. 24X Fiche:50-327,83/07/18.
- 8307210259 Response to B Stamiris 830627 motion to reopen record on Stamiris Contention 4 re integrity of containment & soils underpinning operations founded upon glacial till. Motion unsubstantiated & should be denied. Certificate of Svc encl. STEPTOE, P.P. Consumers Power Co. STEPTOE, P.P. Isham, Lincoln & Boale. 83/07/18. Atomic Safety and Licensing Board Panel. 10pp. 19465:001. 24X Fiche: 50-329, 83/07/18, 8307210259.

- --8307210261 Affidavit of P Shunmugavel re significance of observed cracks in containment.
  SHUNMUGAVEL.P. Consumers Power Co. SHUNMUGAVEL.P. Bechtel Corp.
  83/07/13. 13pp. 17665:011. 24X Fiche: 50-329, 83/07/18. 8307210239.
- ---B307210266 Affidavit of WG Corley re visual insp of cracks in containments near anchorages in Rooms 110 & 116.
  CORLEY, M.G. Consumers Power Co. CORLEY, M.G. Construction Technology Laboratories. B3/07/15. 6pp. 19665:026. 24X Fiche: 50-329,83/07/18,8307210259.
- B307220347 Forwards correct document request to B30509 subpoemas. Svc list encl. PAGCTOR, S. D. Isham, Lincoln & Beale. B3/07/1B. KARR, J. W. Karr & Lyons. 2pp. 19675: 335. 24X Fiche: 50-329, 83/07/18, B307220347.
- --8307220349 Correct document request to 830509 subpoenss. \* Isham, Lincoln & Beale. 83/07/18. 2pp. 19675:337. 24X Fiche: 50-329, 83/07/18, 8307220347.
- 8307260413 Forwards Jul 1983 crack maps of containments at buttress—base slab junctions, per telcon.
  816PTOE, P. P. Isham, Lincoln & Beale. 83/07/18. WILCOVE, M. N.
  Hearing Branch 2. 12pp. 19733:179. 24X Fiche: 50-329, 83/07/18, 8307260413.
- B307250409 Memorandum & order postponing B30725-27 evidentiary hearings, scheduling B30728-30 & OBO1-05 hearings, scheduling B30726 oral argument on motion to quash subpoenss & granting B Stamiris motion to compel production of NRC documents.

  BECHHOEFER.C. Atomic Safety and Licensing Board Panel. B3/07/21.

  Stamiris. B. Bpp. 19705:125. 24X Fiche: 50-329, 83/07/21, 8307250409.
- B307250390 Response opposing B Stamiris B30627 oral motion to reopen 791206 order modifying CP record on Stamiris Contention 4.
  Stds for reopening record not met. Certificate of Svc encl.
  WILCOVE, M. N. Hearing Branch 2. B3/07/22. Atomic Safety and Licensing Board Panel. 11pp. 19705:143. 24X Fiche: 50-329, 83/07/22, 8307250390.
- --8307250396 Affidavit of J Kane re geotechnical engineering issues.

  Natural preconsolidated "very stiff to hard" clay soils is
  competent & acceptable foundation layer.

  KANE.J. Structural & Geotechnical Engineering Branch. 83/07/22.
  7pp. 19705:154. 24X Fiche: 50-329, 83/07/22, 8307250390.
- --8307250402 Affidavit of F Rinaldi re cracks in containment bldg.NRR will evaluate cause/significance of cracks in containment bldg.Review will be finished after util performs atructural integrity test.
  RINALDI,F. Structural & Geotechnical Engineering Branch.
  83/07/22. 2pp. 19705:161. 24X Fiche: 50-329, 83/07/22, 8307250390.
- B307260254 Notice of receipt of Govt Accountability Project request for action under IOCFR2.206 to modify CPs by imposing mandatory hold points on remaining const work & by requiring mgt audit.

  JORDAN.E. L. Director's Office, Office of Inspection and Enforcement, B3/07/22. 2pp. 19727:089. 24X Fiche: 50-327, 83/07/22, 8307260254.
- B307280153 Corrects mischaracterization & misrepresentation re relationship between CPC & G Charnoff & attendance at 821124 meeting. MILLER, M. I. Isham, Lincoln & Beale. 83/07/29. BECHHOEFER, C., COMAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 5pp. 19791: 295. 24X Fiche: 50-329, 83/07/25, 8307280133.
- 9307280161 Motion to squash subpoenas issued to employees & representatives of Oovt Accountability Project requesting documents re internal communications. Certificate of Bvc entl. Related correspondence.

  BERNABELL. Sinclair, M. BERNABELL. Stamiris, B. BERNABELL. Government Accountability Project. 83/07/26. Atomic Safety and Licensing Board Panel. 7pp. 19792:069. 24X Fiche: 50-329, 83/07/26, 8307280161.

## H. General correspondence

8307050101 Responds to 830418 concerns re lack of prof engineering registration of certain Bechtel employees performing work at facility & lack of qualified/trained people doiny 7ock design work. Insp in progress.

KEPPLER, J. G. Region 3, Uffice of Director. 83,02/27, 81NCLAIR, M. Affiliation Unknown. 2pp. 19220:001. 24X Fiche: 50-329,83/06/27,8307050101.

- --8307050111 Discusses subcontractor employee concerns re unqualified personnel at plant site in jobs of critical importance to safety, poor installation to lack of worker qualification on Zack design. Investigation requested SINCLAIR.M. Affiliation Unknown. 83/04/18. KEPPLER, J. Region 3, Office of Director. 11pp. 19220:003 24X Fiche: 50-327, 83/06/27, 8307050101.
- 8307090184 Forwards response to 830531 ltr re util independent thirdparty design & const verification program & const completion program Actions being taken should provide assurance to community that plant constructed safely. KEPPLER, J. O. Region 3, Office of Director 83/06/28, ROMO, L. R. Lone Tree Council. 3pp. 19195.162. 24X Fiche: 50-329, 83/06/28, 8307090184
- --8307050188 Ack receipt of response re independent audit of facility. Truly independent audit should include full scope overview of completed const done by third pairty rather than util. ROMO.L.R. Lone Tree Council. 63/05/31. XEPPLER, J.G. Region 3, Office of Director. 3pp. 19196:033 24X Fiche:50-329,83/06/28,8307050184.
- 8307210242 Requests available nontechnical info re problems w/ engineering design/specs & or implementation of engineering work for plants. MAGNER.C.W. Michigan, State of. 83/07/08 KEPPLER.J.G. Region 3. Office of Director. Ip. 19664: 164. 24X Fiche: 50-000.83/07/08, 8307210242
- 0. Inspection reports, IE Bulletins & correspondence
- 8307260001 FOIA request for all records re NRC insps & evaluations of util const activities in soils work leading to Spessard memo.

  ORDER B.P. Government Accountability Project 83/03/22 TOMS N. Office of Administration. 1p. 19787 321. 24X Fiche: 50-329, 83/03/22.6307260001.
- 8307280002 Responds to FOIA request for records re IE insps & evaluations of util const activities in soils work leading to Spessard memo. Forwards documents listed in App A FELTON.J.M. Burision of Rules and Records. 83/05/18. GARDE, E Government Accountability Project. 2pp 19787-323. 24X Fiche: 50-329, 83/05/18, 8307260002.
- --8307260004 "Insp Evaluation." re IE Insp Repts 50-329/82-11 & 50-330/82-11 on 820519-0702. LANDSMAN.R.B. NRC - No Detailed Affiliation Given. 82/09/02. 2pp. 19787: 325. 24X Fiche: 50-329, 83/05/18, 8307260002.
- --8307260006 "Insp Evaluation," re IE Insp Repts 50-329/82-17 & 30-339/82-17 on 820809-13.
  RING.M., RDBINSON,D. NRC -- No Detailed Affiliation Given.
  82/08/20. 2pp. 19787:327 24X Fiche:50-329,83/03/18,8307260002.
- --8307260009 "Insp Evaluation," re IE Insp Repts 50-329/82-19 & 50-330/82-19 on 820920-24 ROBINSON, D. , JACK, J. N. NRC -- No Detailed Affiliation Given. 82/09/27. 2pp. 19787: 329. 24% Fiche: 50-329,83/09/18,8307260002.
- --8307260011 Notifies of 820330 meeting w/util re underpinning activity. Principle points to be discussed include practicality of requirements & transition between various phases of project. WILLIAMS.C. LITTLE.W.S. NRC No Detailed Affiliation Given. 62/03/24. NDRELIUS.C.E. Region 3. Office of Director. 5pp. 19787:331. 24X Fiche: 50-329, 83/05/18.8307260002.
- --8307260014 Requests list of actions for licensee to correct deficiencies noted in underpinning, piping & electrical areas. Info needed for meeting preparation.
  NORELIUS.C.E. Region 3, Office of Director. 82/05/07.
  LITTLE,W.S. Region 3, Office of Director ip. 19787:336. 24X Fiche: 50-329,83/05/18,8307260002.
- --8307260019 Discusses participation in 820521 ACRG briefing on facility GA program Statement should be drafted by 820519.
  NORELIUS, C.E. Region 3, Office of Director. 82/05/14.
  LITTLE, M.S. NRC No Detailed Affiliation Given. lp. 19787:337.
  24X Fiche: 50-329, 83/05/18, 8307260002.
- --8307260021 Forwards comments on ASLB orders & applicant response reconst activities.

  NORELIUS.C.E. Division of Engineering. 62/05/18. ADENSAM.E.

  Licensing Branch 4. 4pp. 19787:338 24X Fiche:50-329.83/05/18.

  B307260002

- 8307060349 Ack receipt of 830624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-06 & 50-330/83-06 MARNICK,R F. Region 3, Office of Director. 83/06/30. CODK,J.W. Consumers Fower Co. 1p 19234:180. 24X Fiche 50-329,83/06/30,8307060349.
- --8307060356 Responds to NRC 830527 ltr re violations noted in IE Insp. Repts 50-329/83-06 & 50-330/83-06 Corrective actions: 8&W GC procedures re supplier quality evaluation revised to clarify requirements for performing audits.

  COOK.J.W. Consumers Power Co. 83/06/24. KEPPLER, J. O. Region 3, Office of Director. 4pp. 19234: 181 24X Fiche: 50-329, 83/06/30, 8307060349.
- 8307140337 Forwards IE Insp Repts 50-329/83-10 & 50-330/83-10 on 830321-0520 & notice of violation. WARNICK.R.F. Region 3, Office of Director. 83/06/30. CDOK.J.W. Consumers Power Co. 2pp. 19525:255. 24X Fiche:50-329,83/06/30, 8307140337.
- --8307140341 Notice of violation from insp on 830321-0520. MARNICK.R.F. Region 3. Office of Director. 83706730. lp 159325-257. 24X Fiche: 50-329,83706730.8307140330.
- --B307140344 IE Insp Repts 50-329/83-10 & 50-330/83-10 on 830321-0520. Noncompliance noted: inadequate storage facilities for HVAC components.

  BURGESS.B.L., COOX.R.J., GARDNER.R.N. Region G. Office of Director: 83/06/30. 9pp. 19325-258. 24X Fiche: 50-329.83/06/30. B307140337.
- 8307140032 Forwards IE lnsp Repts 50-329/83-07 & 50-330/83-07 on 830420-21,25-29 & 0509-20 & notice of violation.

  WARNICK R. F. Region 3. Office of Director. 83/07/01. CODK, J. W. Consumers Power Co. 2pp. 19514:203. 24X Fiche: 50-329,83/07/01,8307140032.
- --8307140038 Natice of violation from insp on 830420-21,25-29 & 0509-20. WARNICK.R.F. Region 3, Office of Director. 83/07/01. 2pp. 19514:205. 24X Fiche:50-329,83/07/01,8307140032.
- --8307140044 IE Insp Repts 50-329/83-07 % 50-330/83-07 on B30420-21,25-29 % 0509-20. Noncompliance noted: failure to take corrective action re pipe hangers & hanger components found in Kelly bldg w/o release for const tags attached. SIMON. J. A. SATHER, A. HARRISON, J. J. Region 3. Office of Director. B3/06/30. 4pp. 19514.207. 24X Fiche: 50-329,83/07/01,8307140032.
- B306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24% Fiche: 50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydrautic Snubbers as Result of Contaminated Hydrautic Fluid." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- B307230123 Forwards amended response to JG Keppler B30523 ltr re notice of violation. Item 8. concerning failure to establish measures for 9 matis associated w/diesel generator exhaust muffler, supplementing B30624 ltr.
  COGK, J. N. Consumers Power Co. B3/07/12. KEPPLER, J. G. Region 3. Office of Director. 9pp. 19706:074. 24X Fiche: 50-329, 83/07/12. B307250123.
- 8306270406 IE Info Notice 83-48, "Caseous Efficient Releases of Radioactive I-125 & I-131 in Excess of NRC Limits," Svc list encl.

  IAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post B30103), 83/07/14, Consolidated Edison Co. of New York, Inc. 114pp. 19715 270. 24% Fiche: 30-000.83/07/14,8306270406.
- 8307210259 Response to B Stamiris 830627 motion to reopen record on Stamiris Contention 4 Pe integrity of containment & soils underprinning operations founded upon glacial till Motion unsubstantiated & should be denied Certificate of Svc encl. STEPTOE.P.P. Consumers Power Co. 83/07/IB. Atomic Safety and Licensing Board Panel. 10pp. 19665.001. 24X Fiche: 50-327,83/07/IB, 8307210259.
- --8307210271 Revised "Visual Insp of Cracks in Containments Near Anchorages in Rooms 110 & 116." CCRLEV.N.9. Construction Technology Laboratories 83/04/30. 7pp. 19665:032. 24X Fiche:50-329,83/07/18,8307210259

- 8307260451 Suppls 830503 commitment to implement expanded cooling pand dike surveillance program. Damaged turf on dike will be repaired within 1 month after detection consistent w/insp program.

  CCOK.J.W. Consumers Power Co. 83/07/18. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19734:204. 24X Fiche: 50-329.83/07/18.8307260451.
- R. Periodic operating reports & related correspondence
- 8307050006 Forwards util status rept for Apr-May 1983 covering electrical cables, remedial solis work & significant meetings.

  WARNICK, R. F. Region 3. Office of Director. 83/06/28. KEPPLER, J. Q. Region 3. Office of Director. 1p. 19192:113. 24X Fiche: 30-327.83/06/28. 8307050006.
- --B307050017 Forwards util status rept for Apr-May 1983 covering electrical rables, remedial soils work & significant meetings.

  COOK,R.J. Region 3, Office of Director. B3/06/24. WARNICK,R.F. Region 3, Office of Director. 19192:114. 24X Fiche:50-329,83/06/28,8307050006.
- B307080314 Forwards proposed list of work per "NRC & CPC Work Authorization Procedure," for month of Jul 1983. Supplemental work activity list for Aug 1983 also encl. MODNEY, J. A. Consumers Power Co. B3/06/30. HARRISON, J. J. NRC No Detailed Affiliation Given. 22pp. 19362:114. 24X Fiche: 50-329, 83/06/30, 8307080514.
- 8307140337 Forwards IE Insp Repts 50-329/83-10 & 50-330/83-10 on 830321-0520 & notice of violation. MARNICK.R.F. Region 3, Office of Director. 83/06/30, COOK, J.W. Consumers Power Co. 2pp. 19525: 255, 24X Fiche: 50-329, 83/06/30, 8307140337.
- --8307140349 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 26," for 830313-19. H/830323 ltr. LUCKB.A.S. Stone & Webster Inc. 83/03/23. CDOK, R. NRC No Detailed Affiliation Given. 9pp. 19525:267. 24X Fiche: 50-329,83/06/30/8307140337.
- --8307140352 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 27," for 830320-26. W/830401 ltr.
  LUCKG.A.S. Stone & Webster, Inc. 83/04/01. CDOK, R. NRC No Detailed Affiliation Given. 9pp. 19525: 276. 24X
  Fiche: 50-329, 83/06/30, 8307140337.
- --8307140354 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 20," for 830327-0402. W/830407 ltr.
  LUCKS.A.S. Stone & Webster, Inc. 83/04/07. COOK, R. NRC No
  Detailed Affiliation Given. 9pp. 19525: 283. 24X
  Fiche: 50-329, 83/06/30.8307140337.
- --8307140358 "Independent Assessment of Auxiliary Bldg Underpinning Heekly Rept 29," for 830403-09. W/830415 ltr.
  LUCKS.A.S. Stone & Hebster, Inc. 83/04/15. COOK, R. NRC No Detailed Affilation Given. 9pp. 19525: 294. 24X
  Fiche: 50-329,83/06/30,8307140337.
- --8307140361 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 30." for 830410-16, W/830421 ltr. LUCKB.A. 8. Stone & Webster, Inc. 83/04/21. CDOK, R. NRC No Detailed Affiliation Given. 9pp. 19925:303. 24X Fiche: 50-329,83/06/30,8307140337.
- --8307140365 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 31." for 830417-23. W/830427 ltr. LUCKB.A. 8. Stone & Webster, Inc. 83/04/27. CODK, R. NRC - No Datafied Affiliation Given. 10pp. Fiche: 50-329,83/06/30,8307140337.
- --8307140370 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 32." for 830424-30. W/830505 ltr.
  LUCKS.A.B. Stone & Webster, Inc. 83/05/05. COOK, R. NRC No Detailed Affiliation Given. 9p. 19525:322. 24X
  Fiche: 50-329,83/06/30,8307140337.
- --B307140373 "Independent Assessment of Auxiliary Bldg Underpinning Weekly Rept 33." for B30501-07. W/B30510 ltr.
  LUCKS:A.S. Stone & Webster, Inc. B3/05/10. COOK, R. NRC No Detailed Affiliation Given. 10pp. 19525:331. 24X Fiche:50-329,83/06/30.8307140337.
- --8307140378 "Independent Assessment of Auxiliary Bldg Underpinning Heekly Rept 34," for 830508-14. W/830518 ltr. LUCKS, A.S. Stone & Webster, Inc. 83/05/18. COOK, R. NRC No Detailed Affiliation Given. 9p. 19525: 337. 24X Fiche: 50~329, 83/06/30, 8307140337.

- 8307210225 Forwards "Midland Independent Design & Const Verification Program," second monthly status rept for 830528-0630. LEVIN.H.A. TERA Corp. 83/07/15. KEPPLER.J.G. Region 3. Dffice of Director. CODK.J.W. Consumers Power Co. EISENHUT.D.G. Division o Licensing. 3pp. 19666:217. 24X Fiche: 50-329,83/07/15,8307210225.
- --8307210233 "Midland Independent Design & Const Verification Program." Monthly Status Rept 2 for 830528-830630. LEVIN.H.A., TULODISSKI,D., BECK.J. TERA Corp. 83/07/15. 70pp. 19646: 220. 24X Fiche: 50-329, 83/07/15, 8307210225.
- B307210291 Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept 2," second monthly status rept for 830528-0430.

  LEVIN.H.A. TERA Corp. 83/07/15. EISENHUT, D. G. Division of Licensing. KEPPLER, J. G. Region 3, Office of Director. CODK, J. W. Consumers Power Co. 3pp. 19664:210. 24X Fiche: 50-329,83/07/15,8307210291.
- ---8307210296 "Midland Independent Design & Const Verification Program Monthly Status Rept 2," second monthly status rept for 830528-0630. 830528-0630. LEVIN.H.A., TULODIESKI,D. TERA Corp. 83/06/30. 70pp. 19664:213. 24% Fiche:50-329,83/07/15.8307210291.
- S. Reportable occurrences, LERs & related correspondence
- 8307060011 Interim deficiency rept re delivered safety-related electrical equipment not meeting project requirements. Task force established to investigate & resolve MCAR &6. Next rept by 830812.

  CODK. J. W. Consumers Power Co. 83/06/29. KEPPLER. J. G. Region 3. Office of Director, 10pp. 19251:016. 24X Fiche: 50-329,83/06/29.
- 8307060310 PND-III-83-055: Region III authorized resumption of safety-related welding on HVAC sys at const site. Zack Co welding procedures & observations of welding performance demonstrations reviewed.

  OARDMER,R., HARRISON,J. Region 3, Office of Director. 83/06/29.

  1p. 19238: 331. 24X Fiche: 50-329, 83/06/29, 8307060310.
- B307060340 PNO-III-B3-057: on B30629, Bechtel fired lead welding engineer for allegedly instructing rod room attendant to falsify number of weld rod withdrawal slips. No safety significance resulted from incident.

  LANDSHAN, R., HARRISON, J. Region 3, Office of Director. B3/06/30.

  19. 19236:254, 24X Fiche: 50-329, B3/06/30, B307060340.
- 8307080436 Interim deficiency rept we loose locking clips (Tinnerman speed nuts). Vendor approved tooling & installation & insp procedures for replacing Tinnerman speed nuts, beginning in late Jul. Next rept to be submitted by 830930.

  CDDK, J. W. Consumers Power Co. 83/06/30, KEPPLER, J. C. Region 3, Office of Director. 2pp. 19346:359. 24X Fiche: 50-329, 83/06/30, 8307080436.
- 8307180171 Interim deficency rept re potentially unsafe situation concerning tripping of reactor condant pumps during certain primary sys high void fraction conditions. Pump trip criteria will be established per NRC Generic Ltr 83-10. COOK, J. H. Consumers Power Co. 83/07/11. KEPPLER, J. G. Region 3. Office of Director. 2pp. 19555; 084. 24X Fiche: 50-329, 83/07/11, 8307180171.
- 8307180270 Interim deficiency rept re reactor bldg spray piping supports. Initially reported on 791221. Increased loads observed on piping & piping anchors caused by simplifying modeling assumptions.

  COOK, J. W. Consumers Power Co. 83/07/11. KEPPLER, J. Q. Region S Office of Director. 7pp. 19356: 187, 24X Fiche: 50-329, 83/07/11, 8307180270.
- 8307200155 PNO-III-83-041: an 830714.Region III notified that Daw Chemical Co terminating contract w/util to supply process steam to facility. Suit seeking court judgement that all contract obligations canceled filed.
  HARRISON.J., WARNICK.R. Region 3, Office of Director. 83/07/15.
  ip. 17651:246. 24X Fiche:30-327.83/07/15.8307200155.
- B307250431 Interim deficiency rept re electrical accessories associ w/safety-related matl requisitions. Guidolines & checklist being developed for review of safety-related matl requisition requirements. Next rept expected by B31014. CODK. J. W. Consumers Power Co. 83/07/15. KEPPLER. J. G. Region 3 Office of Director. 6pp. 19702: 162. 24X Fiche: 50-327, 83/07/15. B307230431.

- 830728019) Final deficiency rept re absence of close-latch anti-shock spring in Brown Boveri Electric type HK circuit breakers mfg between June 1975 k June 1977. Initially reported on 830023. Corrective actions will be completed by 830824. CDOK, J. W. Consumers Power Co. 83/07/22. KEPPLER, J. G. Region J. Office of Director. App. 19791-247. 24% Fiche 50-329.83/07/22. 8307280191.
- 8307280272 First interim deficiency mept re lack of dc-backed power supplies for FOGG interlock relays in auxiliary feedwater sys Initially reported on 830622 Schematic diagram E-158(Q) & associated connection & panel drawings revised.

  CDOK. J. W. Consumers Power Co. 83707/22 KEPPLER, J. G. Region 3. Office of Director. 4pp. 19791:207 24X Fiche: 50-329, 83/07/22, 830728072 6307280272
- T. Hearing transcripts on non-antitrust matters
- 8307010058 Transcript of 830627 hearing in Midland, MI. Pp 17, 978-18, 234 Supporting documentation encl. 83/06/27. S00pp. 19174:180 24X Fiche: 50-297, 83/06/27. 83/06/27. 83/06/27.
- 8307060451 Forwards five viewgraphs used at 830615 briefing, to be included in transcript. TIPTON, A. Diffice of the Secretary of the Commission. 83/06/27. Public Document Branch. App. 19299:115. 24% Fiche.50-329,83/06/27.
- 8307050044 Transcript of 830428 hearing in Midland.MI.Pp 18.235-18,504 is 304.

  Atomic Safety and Licensing Board Panel. B3/06/28. 7pp. 19192:175. 24X Fiche: 50-329. B3/06/28. B307050044.
- 8307050073 Transcript of 830629 hearing in Midland, MI. Pp. 18, 505-
- 19,771. \* Atomic Safety and Licensing Board Panel. 83/06/29. 268pp. 19198:006. 24X Fiche:50-327.83/06/29.8307050073.
- B3070B0274 Transcript of B30630 hearing in Midland.MI.Pp 18,772-18,961. \* Atomic Safety and Licensing Board Panel. B3/06/30. 192pp. 19352:290. 24X Fiche:50-329.B3/06/30.83070B0274.
- 8307080279 Transcript of B30701 hearing in Midland MI. Pp 18,959-19,071.

  \* Atomic Safety and Licensing Board Panel. B3/07/01. 116pp 19352: 174. 24X Fiche: 50-329,83/07/01, B307080279.
- 8307210194 Testimony of RM Wheeler & BH Pack re 9A inadvertently omitted from 830630 transcript of hearing in Midland.MI. Supporting documentation encl.

  \* Atomic Safety and Licensing Board Panel. 83/07/12. 60pp. 19665:112. 24X Fiche: 50-329.83/07/12.8307210194.
- 8307190252 Forwards PS Glass & R Black testimony Tentative schedule of witnesses listed Certificate of Svc encl.
  LAUER, R. J. Isham. Lincoln & Beale. LAUER, R. J. Gonsumers Power Co.
  83/07/15. HARBOUR, J., BECHHOEFER, C., COHAN, F.P. Atomic Safety and Licensing Board Panel. 4pp. 19628: 038. 24X F(che: 50-327, 83/07/15, 8307190252.
- --8307190258 Testimony of R Black re events during late Winter 1982 & early Spring 1982 & installation of cable related to instrumentation for underpinning work on auxiliary bldg. BLACK,R. Consumers Power Co. BLACK,R. Bechtel Corp. 83/07/11. 24pp. 19628:042. 24X Fiche:50-327.83/07/15.8307190252.
- --B307190260 Testimony of PS Glass re cable & conduit installation for underpinning instrumentation of auxiliary bldg. Oversize matrix encl. Aperture card available in PDR. GLASS.P.S. Consumers Power Co. GLASS.P.S. Bechtel Corp. B3/07/11. 15pp. 19628:O66. 24X Fiche: 50-329,83/07/15.8307190252.
- 8307220351 Forwards RL Black affidavit on testimony, Svc list encl. LAUER, R. J. Isham, Lincoln & Beale. LAUER, R. J. Consumers Power Co. 83/07/18. HARBOUR, J., COMAN, F. P., BECHHOEFER, C. Atomic Safety and Licensing Beard Panel. 3pp. 19675:332. 24X Fiche: 50-329,83/07/18,8307220351.
- 8307280180 Transcript of 830726 oral argument in Bethesda, MD. Pp 19,072-19, 174. \* Atomic Safety and Licensing Board Panel. 83/07/26. 102pp. 19793: 254. 24X Fiche: 50-329, 83/07/26. 8307280180.

- DOCKET 50-33: DUANE ARNOLD ENERGY CENTER
- F. Security, medical, emergency & fire protection plans
- B21019002B Releases public version of revised emergency plan implementing procedure. FELTOW-J.M. Division of Rules and Records. 82/10/01. Document Hanagement Branch. tp. 15760:345. 24x Fiche 50-331.82/10/01, 821019002B.
- --8210190031 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 4.1. "Plant b Site Evacuation."

  \* Ioua Electric Light & Power Co. 82/08/25. Office of Nuclear Reactor Regulation, Director. ip. 24x Fiche: 50-331, 82/10/01.
- --B210190034 Public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 4.1. "Plant & Site Evacuation." Revision 9 to procedures control sheet ancl.
  4. Ioua Electric Light & Power Co. 62/08/25. 17pp. 15760:346.
  24x Fiche: 50-331.82/10/01.8210190028
- B307210005 Forwards IE Safeguards Insp Rept 50-331/93-03 on B30225-0425 & notice of violation, Encls withheld (ref 10CFR73, 21).
  SMAFER, H. D. Region 3, Office of Director, B3/05/18, LIU, L. Iowa Electric Light & Power Co. 3pp. 19669: 234, 24X
  Fiche: 50-331, 83/05/18, 8307210005.
- B3070B03B1 Ack receipt of 830A17 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-331/83-03.

  BMAFER.W D. Region 3. Office of Director. 83/06/29. LIU.L. Iowa Electric Light & Power Co. 1p. 19350:183. 24x

  Fiche: 50-331.83/06/29, B307080381.
- --B3070B03B6 Responds to NRC 830518 ltr re violations noted in IE Ensp Rept 50-331/B3-03. Corrective actions withheld (ref IOCFR73, 21). HCGAUGHY, W. laws Electric Light & Pawer Co. B3/06/17. KEPPLER, J. G. Region J. Office of Director. lp. 19350:184. 24X Fichs: 50-331, 83/06/29, 83070B0381.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B3070101B1 Rev 1 to UBAR W/B30630 ltm.
  MCGAUGHY, P. M. Iowa Electric Light & Power Co. B3/06/30.
  BENTON.H.R. Office of Nuclear Reactor Regulation, Director. B00pp.
  19180:190. 24x Fiche: 50-331.83/06/30.8307010181.
- P. Operating license stage documents & correspondence
- B307120112 Forwards response to BHR Dwners Group study of alternatives to RUREG-0737. Item II.K. 3.18. "Automatic Depressurization Sys Logic Mod " Two of seven alternatives acceptable. In the should be provided within 45 days. Cleckric Light & Power Co. 9pp. 19435: 199. B3706/03. LIU.L. Iowa Fiche: 50-331.83706/03. 8307120112.
- 8307120117 Ack receipt of 830420 ltr providing response to NRC request for approved design in implementing THI Action Plan Item II.K. 3. 13. "HPCI/RCIC Initiation Level." Requirements met. tem closed. VASSALLO, D.B. Operating Reactors Branch 2. 83/06/17. LIU.L. Iowa Fiche: 50-331.83/06/17. B307120117.
- 8307120146 Forwards synopsis of Issues associated w/NUREG-0612, "Control of Heavy Loads," to resolve open Items & draft final technical evaluation rept. Response should be provided within 40 days.

  VASSALLO.D.B. Operating Reactors Branch 2. 83/06/23. LIU.L. Iowa Fiche: 50-331, 63/06/23, 8307120146.
- -- 9307120149 "Control of Heavy Loads (C-10). Duane Arnold Energy Ctr." draft technical evaluation rept.
  VDSBURY,F. W. Franklin Institute/Franklin Research Center.
  NRC-03-81-130. TER-C5506-352 ORFI. 83/04/08. CLEMENSON,F. NRC -- No Detailed Aftiliation Given. 32pp. 19435:147. 24X
- 307090096 Forwards responses to Commissioner Ahearne 830601 questions re Commission 830714 meeting on SECY-83-183, "1983 Policy & Planning Guidance Coordinating Regulatory Requirements," DIRCKS, M. J. Office of the Executive Director for Operations. 83708/27. PALLADING, N. J., GILINSKY, V., AMEARNE, J. Commissioners, 8pp. 19365:250. 24X Fiche: 50-331,83/06/27,8307090096.

- --8306160669 Forwards detailed guidance for project manager use in negotiations w/utils re response to Generic Ltr 82-33 concerning emergency response capability. Negotiations should be completed by 830701.
  EISENNUT.D.G. Division of Licensing. 83/06/01. Division of Licensing. 19pp. 19366:268. 24X Fiche: 50-331, 83/06/27.
- ~8307090100 Submits questions on SECY 83-183 re plan for integrated scheduling of plant mods. Answers should be prepared for requested briefing.
  AMEARNE, J. Commissioners. 83/06/01. DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 19366: 294. 24% Fiche: 50-331.83/06/27,8307090096.
- B307200485 Forwards safety evaluation of B30321 submittal re NUREG-0737, Items II. F. 1, 4, II. F. 1, 5 & II. F. 1.6, "Addl Accident Monitoring Instrumentation." Items resolved W/o
- 8307040177 Forwards response to 830511 request for add1 info re NUREO-0737. Item II.K. 3.28. "Qualification of Automatic Depressurfration Sys (ADS) Accumulators." Current sys provides sufficient capacity to meet FSAR requirements. MCGAUGHY. R. W. Iowa Electric Light & Power Ca. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 19249: 234. 24X Fiche: 50-331.83/06/30.8307060177.
- 8307060249 Forwards Duane Arnold Energy Ctr plant-unique analysis rept, Vol 6, Rev O. "Torus Attached Piping & Suppression Chamber Penetrations Analyses," ger 820119 order. Carrected pages to Vols 1,2,5 & App A also encl. MCGAUGHY, R. M. Iowa Electric Light & Power Co. 83/06/30. DENTON.H. Office of Nuclear Reactor Regulation, Director. 3pp. 19238:010. 24X Fiche: 50-331,83/06/30,8307060249.
- --B307060267 Duane Arnold Energy Ctr plant-unique analysis rept Vol 1, Rev 1, "General Criteria & Loads Methodology."
  SANCHEZ, R. A., BUND, H. J., HOEDEMAN, K. A., NUTECH Engineers, Inc. ICH-40-199-1 VOI ROI. 83/06/17. 7pp. 19238:015. 24X
- --8307060285 Duane Arnold Energy Ctr plant-unique analysis rept Vol 2. Rev 1. "Suppression Chamber Analysis." STEFFEY, N. J., 6UND, H. J., HUEDEMAN, K. A. NUTECH Engineers, Inc. 10N-40-199-2 VO2 ROL. 83/06/17. 4pp. 19238: 022. 24X
- --8307060293 Duane Arnold Energy Ctr plant-unique analysis rept Vol 5, Rev 1. "Safety Relief Valve Discharge Line Piping Analysis." SIETZ.J.D., SUND.H.J., HOEDEMAN.K.A. NUTECH Engineers, Inc. ION-40-197-5 V05 ROL. 83/06/17. 14pp. 19238:026, 24X Fiche: 50-331, 83/06/30, 8307060249.
- --8307060306 Rev 1 to App A, "Duane Annold Energy Ctr Responses to Current Containment & Piping Licensing Issues."

  NUTECH Engineers, Inc. IOM-40-199-A ROL. 83/06/30. Spp. 19238: 040. 24% Fiche: 50-331-83/06/30.8307060249.
- --B3070603i3 Duane Arnold Energy Ctr plant-unique analysis rept Vol 6, Rev O, "Torus Attached Piping & Suppression Chamber Penetrations Analyses."
  FONG.B.E., SUND, H.J., HDEDEMAN, K.A., NUTECH Engineers, Inc. 10H-40-197-6 Vob ROO. B3/06/17. 200pp. 19238:045. 24X
  Fiche: 50-33i, 83/06/30, B307060249.
- 8305270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for nower reactors re clamification of surveillance requirements for dissel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- B307150376 Notification of B30712 meeting w/util in Bethesda, MD to resolve App I issue re annual dose design objective. APICELLA: F. L. Operating Reactors Branch 2. 83/07/05. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19540: 303. 24x Fiche: 50-331, 83/07/05, 8307150376.
- B307060329 Generic Ltr B3-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fichs: 50-000.83/07/06.8307060329.

- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307190419 Requests remittance of Class III fee for B30310 application for Tech Specs changes re containment load case avoidance.
  MILLER.W. D. License Fee Management Branch. 83/07/08. LIU.L. Jowa Electric Light & Power Co. 2pp. 19644:360. 24X
  Fiche: \$0-331.83/07/08.8307190419.
- B307190100 Advises of completion of Mark I containment mod program per B2011B order Plant mods & structural reassussments meet NUREQ-0661 acceptance criteria. MCGAUDHY.R.W. Iowa Electric Light & Power Co. B3/07/12. DENTON.H. Dffice of Nuclear Reactor Regulation. Director. ip. 19634:255. 24: Fiche: 30-331.83/07/12.8307190100.
- B307230108 Application for amend to License DPR-49, proposing Tech Spec Change RTS-154 re RCIC automatic reset & automatic suction switchover from condensate storage tank to suppression pool, per NUREG-0737. Items II. M. 3. 35 & II. M. 3. 22. HCGAUGHY, R. M. Inwa Electric Light & Power Co. B3/07/20. DENTON, H. Office of Nuclear Reactor Regulation, Director. 5pp. 19706:061. 24X Fiche: 50-331, 83/07/20. 8307250108.
- --8307250113 Proposed Tech Spec Change RTB-154 re RCIC automatic reset & RCIC automatic suction switchover from condensate storage tank to suppression pool.

  \* Iowa Electric Light & Power Co. 83/07/20. 3pp. 19706:066.
  24X Fiche: 50-331, 83/07/20, 8307250108.
- 8307250215 Application for amend to License DPR-49, consisting of Change RTS-153, revising Tech Specs re annual reporting of safety/relief valve challenges, malfunctions & procedures, per TMI Action Item II. K. 3. 3.

  MCGAUGHY, R. W. Iowa Electric Light & Power Co. 83/07/20. DENTON, H. Office of Nuclear Reactor Regulation, Director. 3pp. 19706:032. 24X Fiche: 50-331, 83/07/20, 8307250215.
- --B307250227 Proposed Tech Specs revising Section 6.11.1 & Table 6.11-1 re annual reporting of safety/reliof valve challenges, malfunctions & procedures.

  8 Iowa Electric Light & Power Co. B3/07/20. 4pp. 19706:035. 24X Fiche: 50-331, 83/07/20, 8307250215.
- 8307260497 Application for amend to License DPR-49, proposing Tech Spec Change RTS-132 re reduced flow rate requirements for RHR svc water sys. Proprietary NEDE-30051 & NEDC-22082-P encl.
  Repts withheld (ref 100FR2.790).
  MCGAUGHYR.W. Iowa Electric Light & Power Co. 83/07/20.
  DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 11pp. 19731: 299. 24X Fiche: 50-331.83/07/20.8307260497.
- --8307260501 Proposed Tech Spec Change RTS-152 re reduced flow rate requirements for RHR svc water sys.

  \* Towa Electric Light & Pawer Co. 83/07/20. 10pp. 19731: 310. 24X Fiche: 50-331. 83/07/20. 8307260497.
- 8307260140 Forwards Class III fee for 830310 Tech Spec Change Request RTS-148. MCCAUDHY,R. W. lowa Electric Light & Power Co. 83/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ip. 19727:288. 24X Fiche: 50-331,83/07/22,8307260140.
- G. Inspection reports: IE Bulletins & correspondence
- 8307210005 Forwards IE Bafeguards Insp Rept 50-331/83-03 on 830225-0425 & notice of violation. Encls withheld (ref 100FR73.21).

  SHAFER, W. D. Region 3, Office of Director. 83/05/18. LIU, L. Iowa Electric Light & Power Co. 3pp. 19649: 234. 24X

  Fiche: 50-331, 83/05/18, 8307210005.
- 8307200161 Submits results of analyses of special confirmatory measurements as followup to IE Insp Rept 50-331/82-15. All results decayed to 830301 levels.
  MINECK, D.L. Iowa Electric Light & Power Co. 83/06/20.
  8CHUMACHER, M. Region 3, Office of Director. lp. 19647: 274. 24X Fiche: 30-331, 83/06/20, 8307200161.
- B3070B0381 Ack receipt of B30617 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/83-03.

  BHAFER, W. D. Region 3, Office of Director. 83/06/29. LIU, L. Iowa Electric Light & Power Co. 1p. 19350:183. 24X

  Fiche: 50-331,83/06/29,8307080381.

- --8307080386 Responds to NRC 830518 ltr re violations noted in IE Insp. Rept 50-331/83-03. Corrective actions withheld (ref. 100FR73.21).

  MCGAVCHY.R.M. Jowa Electric Light & Power Co. 83/06/17.

  KEPPLER.J. G. Region 3: Office of Director. lp. 19350:184. 24X Fiche: 50-331.83/06/27,8307080381.
- 830706010B Discusses 83022B telcon w/former nongermanent worker at plant re radiation safety concerns documented in IE Insp. Rept. 50-331/83-05. Worker contacted on 830320 & 22 by radiation specialists for followup discussion. HUETER. J. . PAUL.R A. Region 3. Office of Director. 83/06/30. Region 3. Office of Director. 1p. 19251: 196. 24X Fiche: 50-331/83/06/30,8307060108.
- 8307180038 Forwards results of inservice imaps of welds & components conducted during Nov 1982 & Feb-Apr 1983.

  MCGAUGHY, R. W. Towa Electric Light & Power Co. 83/06/30.

  MEPPLER J. G. Region 3. Office of Director. 21pp. 19560:213. 24X

  Fiche: 50-331,83/06/30,8307180038.
- 8306270401 IE Info Notice B3-46, "Common Mode Valve failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/61, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270404 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & 1-131 in Excess of NRC Limits." Syc list enci. TAYLOR, J. M. Division of QA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc 114pp. 19718:270. 24x Fiche: 50-000, 83/07/14.8306270406.
- 8307260484 Forwards final SALP Rept 50~331/83-09 for Apr 1982 ~ Mar 1983 interporating SALP Board 830615 ltr & util 830711 ltr. KEPPLER J. G. Region 3. Office of Director. 83/07/20. LIU.L. lowa Electric Light & Power Co. 2pp. 19734:081. 24X Fiche: 50-331.83/07/20.8307260484.
- --B307260487 SALP Rept 50-331/83-09 for Apr 1982 Mar 1983 Gverall util regulatory performance significantly improved as result of mgt commitment to regulatory improvement program.

  \* Region 3, Office of Director 83/07/20, 29pp 19734:083. 24X Fiche: 50-331,83/07/20,8307260484.
- --8307260488 Nutifies of 830621 meeting to discuss encl preliminary SALP rept for Apr 1982 Mar 1983. W/o encl HIND, J. A. Division of Radiological % Materials Safety Programs. 83/06/15. LIV.L. Iowa Electric Light & Power Co. 2pp. 19734:112. 24X Fiche: 50-331,83/07/20.8307260484.
- --8307260491 Responds to 830615 request for comments on draft BALP rept. Comments adequately addressed at 830621 meeting w/NRC. MCGAUGHYR.W. Lowe Electric Light & Power Co. 83/07/11. KEPPLER, J. G. Region 3, Office of Director. 3pp. 19734:114. 24X Ficha: 50-331,83/07/20,8307260484.
- R. Periodic operating reports & related correspondence
- 8307220281 Monthly operating rept for May 1983.W/830615 ltr.
  ANDERSON.M. MINECK.D.L. Iowa Electric Light & Power Co.
  Director's Office, Office of Inspection and Enforcement.
  19684:157. 24% Fiche: 50-331.83/06/15.8307220281.
- 8307190132 Monthly operating rept for June 1983.W/830715 ltr.
  ANDERSON.M., MINECK.D.L. lowe Electric Light & Power Co.
  Director's Office. Office of Inspection and Enforcement. Bpp.
  19636:208. 24X Fiche:50-331.83/07/15.8307190152.
- S. Reportable occurrences, LERs & related correspondence
- B30709005G LER B3-017/03L-0: on B30523, while operating in torus cooling mode, pressure differential across RHR svc water strainer 18-90B increased. Caused by sheared motor coupling shear pins. Two shear pins installed. W/B30522 ltr. ANDERSEN, N. W., MINECK, D. L. Iowa Electric Light & Power Co. 83/06/22. KEPPLER, J. O. Region 3, Office of Director. 2pp. 19192: 161. 24X Fiche: 50-331, 83/06/22, 8307050090.

- B307050120 LER B3-01B/03L-0 on B30523 during routine surveillance testing. HPCI pump failed to meet requirements for output pressure Caused by speed indication circuit for turbine out of calibr Speed circuit recalibr M/830422 ltr.

  KIBLER, D.R., MINECK, D.L. Iowa Electric Light & Power Co. B3/06/22 KEPPLER, J Q. Region 3, Office of Director. 2pp. 19220:054. 24X Ficha: 50-331.83/06/22.8307050120.
- 8307050214 LER 83-019/03L-0: on 830924, breaker supplying reactor water cleanup isolation valve MO 2701 position & motive power found open w/valve in open position Probably caused by personnel inadvertently bumping breaker. W/830623 ltr. MILLER.W. J. MINECK.D. L. Iowa Electric Light & Power Co. 83/06/23. KEPPLER.J. O. Region 3. Defice of Director. 3pp. 19197: 279. 24X Fiche: 90-331,83/06/23,8307050214.
- 8307030135 LER 83-020/03L-0 on 830525 undervoltage relay for instrument bus 27-1721 failed to trip within required time limits during surveillance testing Caused by target flag misalignment preventing contact operation.W/830824 ltr. REIMERS, C.A., MINECK.D.L. Inwa Electric Light & Power Co. 83/06/24. KEPPLER.J.G. Region 3, Office of Director. 2pp. 19220:056. 24X Fiche: 50-331.83/06/24.8307050135.
- 8307040123 LER 83-023/03L-0: on B3052B during normal operation surveillance testing control bldg B discharge valve AV-7318B would not open in manual or auto mode Caused by plugged dirt in pilot positioner Positioner cleaned W/830627 lfr. ANDERSON. M.A., MINECK. D.L. Iowa Electric Light 2 Power Co. B3/06/27. KEPPLER. J. G. Region 3, Office of Director. 2pp. 19252: 224. 24X Fiche: 50-331, 83/06/27, 8307060123.
- 8307210067 Updated LER 82-064/03L-1: on 820929. standby filter unit B heater tripped on sheath overtemp. Caused by low setting of 500 F. Setting increased to 550 F. Engineering evaluation will determine uptimum setting, W/830711 ltr.

  RE IMERS. G. A. MINECK, D. L. Iowa Electric Light & Power Co. 83/07/11.

  KEPPLER, J. G. Region 3. Office of Director. 2pp. 17668:262. 24X Fiche: 50-331.83/07/11.8307210067.
- 8307210151 RD: on 830712, engineering calculations performed during piping walkdown identified 3/4-inch HLE pipe exceeded design basis code allowable pipe stress. Design change will be implemented to return line to within allowable conditions. MINECK.D.L. Iowa Electric Light & Power Co. 83/07/12. KEPPLER, J. 9. Region 3, Dfice of Director. 1p. 17669:178. 24X Fiche: 50-331,83/07/12.8307210151.
- DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT
  F. Security, medical, emergency & fire protection plans
- 8307140406 Forwards IE Safeguards Insp Rept 50-333/83-13 on 830606-10. No noncompliance noted.

  MARTIN.T. T. Division of Engineering & Technical Programs. 83/06/28. MCNELL.C. A. Power Authority of the State of New York. 2pp. 19521:104. 24X Fiche: 50-333/83/06/28/8307140406.
- --8307140410 IE Safeguards Insp Rept 50-333/83-13 on 830606-10.No noncompliance noted. Major areas inspected: site orientation to review of security plan & implementing procedures, security program audit, security organization & testing & maint. DUNLAF, J. M., MCKEOWN, L. M., GODY, A. T. Region 1, Office of Director. 83/06/27, 3pp. 19521:108. 24X Fiche: 50-333,83/06/28,8307140406.
- 8307050023 Forwards response to Generic Ltr 82-33, Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability."

  BAYNE, J. P. Power Authority of the State of New York. 83/06/30. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19220: 318. 24X Fiche: 50-333, 83/06/30, 8307050023.
- --B307050029 Rev O to "Technical Guidelines for Emergency Operating Procedures." LISEND.R.: CHILDS.W.N. Power Authority of the State of New York. B3/06/15. 52pp. 19220:320. 24X Fiche: 50-333, B3/06/30, B307050023.
- --8307050034 Rev 3 to AP 2.2 "Procedure for Emergency Operating Procedures." W/five oversize drawings Aperture cards are available in PDR.

  \* Power Authority of the State of New York. 83/06/03. 53pp. 19221: 010. 24X Fiche: 50-333.83/06/30.8307030023.
- 8307210326 Forwards exemption from contain fire protection requirements of App R & iOCFR50.48 rs control room & torus room.per 820225 request.
  VASSALLO.D.B. Operating Reactors Granch 2. 83/07/01. BAYNE.J.P. Power Authority of the State of New York. 3pp. 19672:344. 24x Fiche: 50-333,83/07/01. B307210326.

- --B30721033: Exemption from certain fire protection requirements of App R to 10CFR30 re control room & tarus room.

  PURPLE.R.A. Division of Licensing. B3/07/01. Power Authority of the State of New York. App. 19672:347. 24X

  Fiche: 50-333. B3/07/01. B307210326.
- 8307110223 Forwards payment for fee re App R to 10CFR50, "Alternate Safe Shutdown Capability." Fee paid under protest pending final determination of legality of fee schedule.

  BAYNE, J. P. Power Authority of the State of New York. 83/07/06.

  MILLER, W. O. License Fee Management Branch. 3pp. 19380:074. 24X

  Fiche: 50-333,83/07/06,8307110223.
- 8307270305 Requests arrangements be made to support NRC representative, JJ Hawhurst, B30804 site visit re atmospheric transport & diffusion modeling supporting emergency dose calculations & projections.

  VASSALLO, D. B. Operating Reactors Branch 2. 83/07/19. BAYNE, J. P. Power Authority of the State of New York. 2pp. 19858: 161. 24X Fiche: 30-333, 83/07/19, 8307270305.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307250238 Forwards Rev i to updated FSAR.
  BAYNE, J.P. Power Authority of the State of New York. 83/07/20.
  DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1g
  19707:074. 24X Fiche: 50-333.83/07/20,8307250238.
- --8307250248 Rev 1 to updated FSAR.

  BAYNE J.P. Power Authority of the State of New York. 83/07/31.

  385pp. 19707:075. 24X Fiche: 50-333.63/07/20,8307250238.
- P. Operating license stage documents & correspondence
- B306100021 Forwards safety evaluation re NUREO-0737, Item II. B. 2, "Design Review of Plant Shielding." Item resolved. VASSALLO.D.B. Operating Reactors Branch 2. 83/05/25, BAYNE.J.P. Power Authority of the State of New York. 5pp. 18815:309. 24% Fiche: 50-333.83/05/25,8306100021.
- 8307120041 Requests util choose one of two acceptable alternatives in BWR Dwners Group study re NUREG-0737 Item II, K. 3. 18. "Automatic Depressurization Sys Logic Mods." Schedule for implementing mods should be provided within 45 days. VASSALLO.D.B. Operating Reactors Branch 2. 83/06/03. BAYNE, J. P. Power Authority of the State of New York. 3pp. 19435:350. 24X Fiche: 50-333.83/06/03.8307120041.
- 830712003B Advises of acceptability of deviation from approved QE Owners Group conceptual design for TMI Item II.K.3.13, "HPCI/RCIC Initiation Level." Item resolved. VASSALLO, D.B. Operating Reactors Branch 2, 83/06/17, BAYNE, J.P. Power Authority of the State of New York. 2pp. 19435;359. 24X Fiche: 50-333,83/06/17,8307120038.
- 8307140504 Forwards confirmatory order verifying 801216,810513,820111 & 830512 commitments to install permanent scram discharge sys mods prior to Cycle & operation. Proposed model Tech Specs encl.
  VASSALLO, D. B. Operating Reactors Branch 2. 83/06/24. BAYNE, J. P. Power Authority of the State of New York. 2pp. 17528:301. 24X Fiche: 50-333,83/06/24,8307140504.
- --8307140509 Confirmatory order verifying 801216,810513,820111 & 830512 commitments to install permanent scram discharge sys mods prior to Cycle 6 operation.
  EISENHUT, D. G. Division of Licensing. 83/06/24. Power Authority of the State of New York. 5pp. 19528:303. 24X Fichs:50-333,83/06/24,8307140504.
- 8307010110 Requests exemption from 10CFR50. 44 (c)(3)(ii), interim hydrogen control requirements. Current plant design provides sufficient protection to public health & safety, based on review of BWR Owners Group Rept NEDO-22155.

  BAYNE, J. P. Pawer Authority of the State of New York. B3/06/29. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19168: 352. 24% Fiche: 50-333, B3/06/29, B307010110.
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 818. Svc list enci. EISENHUT.D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254, 24X Fiche: 50~000,83/07/06,8307060329.

- 8307i10225 Forwards application to amend License DPR-59, revising Tech Specs to reduce susceptibility of scram discharge vol sys to common cause failures. BAYNE, J.P. Power Authority of the State of New York. 83/07/07. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 19380:034. 24X Fiche: 50-333, 83/07/07, 8307110225.
- --8307110229 Application to amend License DPR-59, revising Tech Specs to reduce susceptibility of scram discharge vol sys to common cause failures.

  BAYNE. J.P. Power Authority of the State of New York. B3/07/01.

  1p. 19380:037. 24X Fiche: 50-333.83/07/07.8307110225.
- --8307110233 Proposed Tech Specs re-scram discharge vol sys mods. \* Power Authority of the State of New York. 83/07/07. 33pp 19380:038. 24X Fiche:50-333,83/07/07,8307110225.
- 8307110314 Forwards description of defect in control rod drive return line proposed mod for capping reactor notate appraising history of return line & implementation schedule for all NUREG-0619 mods.

  BAYNELUP. Power Authority of the State of New York. 83/07/07. VASBALLO, D.B. Operating Reactors Branch 2. 11pp. 19381: 264. 24x Fiche: 50-333, 83/07/07, 8307110314.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATWS events, Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Cansolidated Edison Co. of New York, Inc. 3Bpp. 19669:269. 24X Fichs: 50-000, 83/07/08, 8307080169.
- B30718010B Forwards rev to 830623 response to NRC 830202 request for add1 info re NUREO-0737. Items II.F. 1.4, "Containment Pressure Monitor" & II.F. 1.5, "Containment Water Level Honitor," to correct inaccuracies in original data.
  BAYNE, J. P. Power Authority of the State of New York. B3/07/12. VASSALLO, D.B. Operating Reactors Branch 2. Spp. 17997: 022. 24X Fiche: 50-333, 83/07/12, 8307180108.
- 8307210011 Requests exemption from 10CFR50 44 interim requirements re hydrogen control pending results of NEDD-22155. "Generation & Mitigation of Combustible Gas Mixtures in Inerted BUR Mark I Containments." BAYNE J. P. Power Authority of the State of New York. 83/07/19. VASSALLO, D. B. Operating Reactors Branch 2. 4pp. 19649:245. 24X Ficha:50-333.83/07/19.8307210011.
- 8307270335 Advises that high drywell pressure permissive will be eliminated & manual inhibit switch added by 850430, per NVREG-0737, Item II. K. 3, 18, "Mod of Automatic Depressurization Sys Logic."
  BAYNE. J. P. Power Authority of the State of New York. 83/07/25. VASSALLO, D. B. Operating Reactors Branch 2 2pp. 19767:239. 24x Fiche: 50-333, 83/07/25, 8307270335.
- 8307270439 Suppl to 821229 application to amend License DPR-59, allowing plant operation w/single recirculation loop out of svc for unrestricted duration at power levels not exceeding 50%. Errets & addends to NEDO-24281 encl.

  BAYNE.J.P. Power Authority of the State of New York. 83/07/25. VA85ALLD, D. B. Operating Reactors Branch 2. 2pp. 19767; 180. 24% Fiche: 50-333, 83/07/25, 8307270439.
- --8307270440 Errata & addenda to NEDO-24281, "Single Loop Operation." \* General Electric Co. NEDO-24281 ERR. 80/12/31. 4pp. 19767:182. 24X Fiche:50-333,83/07/25,8307270439.
- G. Inspection reports, IE Bulletins & correspondence
- 8307010111 Responds to IE Bulletin B3-09, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co." No ASME Code pumps or spare parts mfg by Hayward Tyler Pump Co used in facility.

  MCNEILL, C.A. Power Authority of the State of New York. 63/06/17. MCNELY.T.E. Region 1, Office of Director. 2pp. 17167:234. 24X Fiche: 50-333,83/06/17,8307010111.
- --8307110417 Notice of violation from insp on 830501-31. \* Region 1, Office of Director. 83/06/22. 1p. 19382:013. 24X Fiche: 50-333,83/06/22,8307110414.

- --8307110421 IE Insp Rept 50-333/83-12 on 830501-31 Noncompliance noted: E-7018 covered electrode in partable oven 1-39 not maintained at 50 to 250 F b welding rod not returned to weld rod storage attendant at end of shift CINVILLE, J C. DOERFLEIN, L. T , KISTER, H B . Region i, Office of Director. 83/06/17. 7pp. 19382.014 24X Fiche:50-333,83/06/22.8307110414.
- 8307140406 Forwards IE Safeguards Insp Rept 50-333/83-13 on 830606-10. No noncompliance noted.

  MARTIN:T.T. Division of Engineering & Technical Programs. 83/06/28. MCNELL.C.A. Power Authority of the State of New York. 2pp. 19321-106. 24X Fiche:50-333-83/06/28.8307140406.
- --B307140410 IE Safeguards Insp Rept 50-333/83-13 on B30606-10. No noncompliance noted Major areas inspected site orientation & review of security plan & implementing procedures, security program audits security organization & testing & maint. DUNLAP.J.M., MCKEDWN.L.M., GODY.A. T. Region I. Office of Director. B3/06/27. 3pp. 19521:108 24X Fiche: 50-333. B3/06/28. B307140406.
- B307110394 Ack receipt of B30622 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropt 50-333/83-09.
  BTAROSTECKIR. Division of Project & Resident Programs. B3/07/01.
  MCNETLL.C.A. Power Authority of the State of New York. 1p.
  19380: 323. 24X Fiche: 50-333, 83/07/01. 8307110394.
- --8307110400 Responds to NRC 830523 ltr re violations noted in IE Insp. Rept 50-333/83-09. Corrective actions: two lost torque wrenches will be calibr if found calibr records located & maint calibr program rewritten. MCNEILL, C.A. Power Authority of the State of New York. B3/06/22. BTAROSTECKI, R. Division of Project & Resident Programs. 3pp. 19380: 324. 24x Fiche: 50-333, 83/07/01, 8307110394.
- B306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 8330103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche:50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice B3-47. "Failure of Hydravlic Snubbers as Result of Contaminated Hydravlic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche 50-000,83/07/12,8306270404.
- 8307280278 Forwards IE Insp Rept 50-333/H3-03 on 830208-11.No nencompliance noted MARTIN/T.T. Division of Engineering & Technical Programs. 83/07/13 MCNEILL.C.A. Power Authority of the State of New York. 2pp. 19791:313. 24X Fiche:50-333/83/07/13/8307280278.
- --B307280283 IE Insp Rept 50-333/83-03 on 830208-11 No noncompliance noted Major areas inspected: design, installation & testing of MBIV leakage collection sys.

  EAPEN, P. K., ANDERSON, C.J. Region 1, Office of Director. 83/07/09, 5pp. 19791:315. 24X Fiche:50-333/83/07/13/8307280278.
- B306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits:" Svc list encl. TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000.B3/07/14.B306270406.
- 8307280291 Forwards SALP rept conducted on 630222 & discussed w/licensee on 830320 covering period Jan-Dec 1982. Overall performance acceptable. High attention & involvement agreesive in area of security & safeguards.

  MORLEY.T. E. Region 1. Office of Director. 63/07/20. BAYNE. J. P. Power Authority of the State of New York. 4pp. 19790: 121. 24X Fiche: 50-333, 83/07/20, 830/280291.
- --8307280295 SALP rept for Jan-Dec 1982 \* Region 1, Office of Director: 83/05/20. 36μp. 19790:125. 24X Fiche: 50-333, 83/07/20, 8307280291.
- 8307250267 Forwards 830610 ltr in response to NRC 830525 request for add1 info re IE Bulietin 80-11. "Masonry Wall Design." Ltr inadvertently misplaced.
  BAYNE, J. P. Power Authority of the State of New York. 83/07/21. VASSALLO, D. B. Operating Reactors Branch 2. 1p 19701:354. 24X Fiche: 50-333,83/07/21,8307250267.
- --B307250278 Forwards response to NRC 630925 request for add1 info re IE Bulletin B0-11, "Masonry Wall Design." Use of increased allowable stresses justified per NRC 820426 request. Methodology used to analyze masonry walls submitted. BAYNE, J.P. Power Authority of the State of New York. 83/06/10. VASSALLO.D.B. B. Operating Reactors Branch 2. Spp. 19701:355. 24X Fiche:50-333.83/07/21.8307250267.

- R. Periodic operating reports & related correspondence
- 8307120527 Monthly operating rept for June 1983 W/830708 ltr. COOK, J., MCNEILL, C.A. Fower Authority of the State of New York 83/07/08. Director's Office, Office of Inspection and Enforcement. [1pp. 17433:281. 24X Fiche 50-333.83/07/08.8307120527.
- S. Reportable occurrences, LERs & related correspondence
- 8307010060 LER 83-022/03L-0: on 830507, during performance of local leak rate testing of containment spray, penetration X-39A found w/ leakage that may exceed Tach Spec limits, Cause undetermined. Details will be provided within 30 days W/830616 itr. KEITH.H.N. MCNEILL.C. A. Power Authority of the State of New York. 83/06/16. ALLAN.J.M. Region 1. Office of Director 2pp. 19169: 243. 24X Fiche: 50-333, 83/06/16, 8307010060.
- 8307010046 LER 83-021/03L-0: on B30605, rod block calibr not performed within 7 days of 830603 planned reactor shutdown. Caused by inadequate mpt controls to implement Tech Spacs Procedures to be revised. W/B30618.

  KEITH, H. N. , MCNEILL, C. A. Power Authority of the State of New York. B3706/19. ALLAN, J. H. Region 1, Office of Director. 2pp. 19169: 192. 24X Fiche: 50-303,83/06/18.830/010046.
- 8307010017 LER 83-023/01T-0: un 830407, water seepage discovered from weld in stainless steel pipe section of control rod hydraulic return line. Caused by intergranular stress corrosion cracking. Piping will be removed. W/830420 ltr. PETERS, R. MCNEILL. C. A. Power Authority of the State of New York. 83706720. MURLEY.T.E. Region 1. Office of Director. 2pp. 19169:101. 24X Fiche: 50-333,83/06/20,8307010017.
- 8307110309 Advises of patential nonconformance re design of pipe supports for normal loads. Visual insp of 20 pipe supports in progress. Not reportable per Part 21. Evaluation will be completed prior to startup from refueling outage.

  BAYNE, J.P. Power Authority of the State of New York. 83/07/07. VASSALUD. B. Operating Reactors Branch 2 2pp 19380:344. 24) Fiche: 50-333. B3/07/07, B307110309.
- 8307220179 PNO-1-83-076: on 830715, during ultrasonic exams required by IE Bulletin 83-02, pipe crack identified in end cap to pipe weld of 22-inch diameter distribution header on circulation loop A. Caused by intergranular stress corrusion. LAZARUS, M. J., XISTER, H. B. Region 1, Office of Director. 83/07/18 ip. 19484:012. 24X Fiche: 50-333,83/07/18.8307220179.
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8307010096 Forwards IE Insp Rept 50-334/83-10 on 830503-0606. No noncompliance noted. STAROSTECK1,R. Division of Project & Resident Programs. 83/06/14. CAREY,J. J. Duquesne Light Co. 2pp. 19124: 262. 24X Fiche: 50-334,83/06/14,8307010096.
- --8307010107 IE Insp Rept 50-334/83-10 on 830503-0606 No noncompliance noted Major areas inspected licensee action on previous insp findings plant operations, housekeeping, fire protection, IE bulletins & LER followup.
  TROSKOSKI, W. M., TRIPP, L. E. Region 1, Office of Director. 83/06/10, 23pp. 19124: 264. 24x Fiche: 50-334,83/06/14,8307010096.
- B307070442 Discusses B30418 & 0520 ltrs re installation of encapsulated control power transformers in 480-volt emergency motor control ctrs instead of installing fuses on secondary side of existing transformers. Design acceptable.
  VARGA-S.A. Operating Reactors Branch 1. 83/06/20. CAREY.J. J. Duquesne Light Co. 2pp. 19300:188. 24X Fiche: 50-334.83/06/20. 8307070442.
- 8307200115 Forwards Rev O to Issue 3 of physical security plan. Rev withheld (refs 10CRR2.790 & 10CFR73.21).
  CAREY, J. Duquesne Light Co. 83/06/27. MURLEY, T.E. Region 1, 0ffice of Director. 1p. 19647.068. 24x Fiche: 50-334, 83/06/27.
- G. Adjudicatory correspondence
- 8307250020 Add1 response to FDIA request for 22 categories of documents Forwards App A & B documents Portions of App B documents withhald (ref FDIA Exemptions 7 & 3).
  FELTON, J. M. Division of Rules and Records 83/05/05. SHOLLY, S. C. Union of Concerned Scientists. App. 19725:108. 24X
  Fiche: 50-000, B3/05/05, 8307250020.

- --8307250027 Hause Resolution 82 directing Hause of Representatives Committee in Mines & Energy Mgt to conduct investigation into incidents that allegedly occurred at facility.

  \* Pennsylvania, Commonwealth of. 81/06/15. ip. 19725:119. 24X Fiche. 50-000, 83/05/05, 8307250020.
- --8307250033 Notifies of 811112 meeting in Harrisburg, PA to hear testimony re facility incident Committee will attempt to limit subj matter to nuclear plant security requirements.

  TAYLOR, F. R. Pennsylvania, Commonwealth of. 81/10/21.

  DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 19725: 120. 24X Fiche: 50-000, 83/05/05, 8307250020.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B3072B029B Forwards Rev 1 to updated FSAR, reflecting info & analyses submitted to NRC & clarification or editorial changes. Revs to Bection 14.3 will be provided during Sept 1983. Ack of receipt requested.

  CAREY. J. J. Duquesne Light Co. B3/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 19813:001. 24X Fiche: 50-334, 83/07/22, 83072B0298.
- --B3072B0303 Rev t to updated FSAR.

  \* Duquesne Light Co. 83/01/31, 897pp, 19813:005, 24X
  Fiche: 50-334,83/07/22,8307280298.
- P. Operating license stage documents & correspondence
- B3072500PO Add1 response to FOIA request for 22 categories of documents. Forwards App A & B documents. Portions of App B documents withheld (ref FOIA Exemptions 7 & 3).
  FELTON. J. M. Division of Rules and Records. B3/05/05. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 19725:108. 24X Fiche: 50-000, 83/05/05, 8307250020.
- 8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for CLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 17863:116. 24X Fiche: 50-000, 83/06/03, 830660070.
- 8307110616 Monthly natice of amends to OLs involving NSHC issued since 830523. CLARK, R. A. Dperating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fiche:50-000/83/06/14,8307110616.
- 8307070115 Forwards "Pressurizer Safety & Relief Line Evaluation Summary Rept." per TMI Item II.D. 1 containing results of second iteration of thermal hydraulic evaluation & structural analysis on piping & supports.
  CAREY.J. J. Duquesne Light Co. 83/06/24. VARGA, S. A. Operating Reactors Branch I. 2pp. 19267: 265. 24X Fiche: 50-334.83/06/24.8307070115.
- --8307070119 "Pressurizer Safety & Relief Line Evaluation Summary Rept." NG.C.K. Westinghouse Electric Corp. SMITH.L.C., CHANG.K.C. Duquesne Light Co. 83/06/30. 71pp. 19267:267. 24X Fiche:50-334.83/06/24.8307070115.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel inpurity. Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/05. Consolidated Edison Co. af New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307180118 Requests copy of Div of Operating Reactors 791228 generic review on inadvertent safety injection during cooldown to assure facility adequately bounded by review.

  CAREY. J. D. Duquesne Light Co. 83/07/05. VARGA.S.A. Operating Reactors Branch 1. 1p. 19556:266. 24X Fiche:50-334.83/07/05.8307180118.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000. 83/07/06. 8307060329.
- B30715011B Confirms info exchanged during B30627 conference call re N-1 loop operations. Isolation valves not needed on 3-inch DHR lines on secondary side. CAREY, J. Duquesne Light Co. 83/07/06. VARGA, S. A. Operating Reactors Branch i. 5pp. 19536:222. 24x Fiche: 50-334, 83/07/06, 930715011B.

- B307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT, D. G. Division of Licensing 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669-269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307280244 Rev to Change Request 78 for License DPR-66, revising Tech Specs to incorporate hydraulic snubbers located on main feedwater piping upstream of auxiliary freedwater injection piping in Table 3.7-4a. Safety evaluation encl. CAREY, J. Duquesne Light Co. B3/07/14. VARGA, S. A. Operating Reactors Branch 1 Spp. 19795; 271. 24X Fiche: 50-334, 83/07/14, B307280244.
- ---8307280248 Proposed Tech Specs Table 3.7-4a re safety-related hydraulic snubbers. • Duquesne Light Co. 83/07/14 ip. 19795:276. 24X Fiche: 90-334,83/07/14,8307280244.
- B307280277 Application for amend to License DPR+66, consisting of Proposed Change Request 86 re administrative changes to Tech Specs.

  CAREY, J. J. Duquesne Light Co. 83/07/14. VAROA, S. A. Operating Reactors Branch 1. 2pp. 19791: 320. 24X Fiche: 50-334, 83/07/14, 8307280277.
- --8307280282 Proposed Tach Spec Change Request 86 re administrative changes. \* Duquesne Light Co. 83/07/14. 19pp. 19791:322. 24X Fiche: 50-334.83/07/14.8307280277.
- B307270192 Rev to Change Request 79 for License DPR-66 re boron concentration reduction in boron injection tank. CAREY, J. Duquesne Light Co. 83/07/15. VARGA, S.A. Operating Reactors Branch 1. 3pp. 19749.332. 24X Fiche: 50-334,83/07/15.830/270192
- --8307270197 Proposed revs to Tech Spec Change Request 79 re boron concentration reduction in boron injection tank. Safety evaluation encl.

  \* Duquesne Light Co. 83/07/15. 3pp. 19749:335. 24X Fiche: 50-334,83/07/15,8307270192.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307250020 Addl response to FDIA request for 22 categories of documents. Forwards App A & B documents. Portions of App B documents withheld (ref FDIA Exemptions 7 & 3). FELTON. J. M. Division of Rules and Records. 83/05/05. SHOLLY, S. C. Union of Concerned Scientists. 4pp 19725:108. 24X Fiche: 50-000, 83/05/05, 8307250020.
- --83072500&0 IE Investigation Rept 50-334/81-1& on 810&06-18.30.0701.02.09 & 10.Noncompliance noted: failure to maintain operable high pressure ECCS during power operation & failure to properly administer approved operator training program.

  DEVLIN.J.W. BECKMAN.D.A. REKITO.W.A. Region i. Philadelphia, Office of the Director. 81/12/07. 24pp. 19725:139. 24X Fiche: 50-000.83/05/05.8307250020.
- 8307010096 Forwards IE Insp Rept 50-334/83-10 on 830503-0606. No noncompliance noted.

  BTAROSTECKI.R. Division of Project & Resident Programs. 83/06/14. CAREY.J. J. Duquesne Light Co. 2pp 19124: 262. 24X

  Fiche: 50-334.83/06/14.8307010096.
- --8307010109 IE Insp Rept 50-334/83-10 on 830503-0606. No noncompliance noted Major areas inspected licensee action on previous insp findings plant aperations, housekeeping, fire protection, IE bulletins & LER followup.
  TROSKOSKI, W. M., TRIPPILE. Region 1, Office of Director.
  83/06/10. 23pp. 19124:264. 24X Fiche:50-334,83/06/14,8307010096.
- 8307110362 Forwards IE Insp Rept 50-334/83-11 on 830924-27. No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/22. CAREY.J. J. Dequesne Light Co. 2pp. 19380: 253. 24X
  Fiche: 50-334
- --8307110366 IE Insp Rept 50-334/83-11 on 830524-27 No noncompliance noted Major areas inspected radiation protection program, including outstanding items outsge advanced planning & preparation, procedures, training & posting & control. CLEMONS.P., EANNBAKY, M. Regian 1. Office of Director. 83/06/RO. 5pp. 19380: 255. 24X Fiche: 50-334, 83/06/22, 8307110362.
- 8307120463 Ack receipt of 830623 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-334/83-08.

  BTAROSTECKI'R. Division of Project & Resident Programs. B3/07/08.
  CAREY, J. D. Duquesne Light Co. 1p. 19424:205. 24X
  Fiche: 50-334,83/07/08,8307120463.

- --B307120475 Responds to NRC B30523 ltr re violations noted in IE Insp Rept 50-334/83-08. Corrective actions: requirement to cycle MOV-81 B62A & B on 31-day frequency added to GST 1.11.6 & 1.11.7 via Operating Manual Change Notices B3-143 & 83-144. CAREY.J. J. Duquesne Light Co. B3/06/23. BTARCBTECKI.R. Region 1. Office of Director. 2pp. 19424:204. 24X Fiche: 50-334. B3/07/08.B307120463.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Suc list encl.

  JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 194pp. 19963:293. 24X Fiche: 50-000, B3/07/11; 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Bnubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-128 & I-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- R. Periodic operating reports & related correspondence
- B307220308 Monthly operating rept for May 1983.W/830610 ltr. HOLTZ.J.L., CAREY.J.J. Duquesne Light Co. 83/06/10. Office of Resource Management, Director. Bpp. 19683:285. 24X Fiche:50-334.83/06/10,8307220308.
- B307270182 "NPDES Discharge Monitoring Rept. June 1983." W/830725 ltr. BTEAD.L.S., FEITKNECHT.C. Duquesne Light Co. 83/07/26. REID.R.W. Querating Reactors Branch 4. 18pp. 19822:036, 24X Fiche: 50-334. B3/07/26.8307290182.
- S. Reportable occurrences, LERs & related correspondence
- 8307250020 Addl response to FOIA request for 22 categories of documents. Forwards App A & B documents. Portions of App B documents withheld (ref FOIA Exemptions 7 & 3).
  FELTON, J. M. Division of Rules and Records. 83/05/05. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 19725:108. 24x
  Fiche: 50-000, 83/05/05, 8307250020.
- --8307250025 Sequence of events re mispositioned high-head safety injection common.suction valve.

  \* Duquesne Light Co. 81/06/05. 3pp. 19725:116. 24X Fiche: 50-000-83/08/05.8307250020.
- --8307250049 Forwards info re util response to 810606 possible act of sabotage per PA House of Representatives Mines & Energy Mgt Committee Resolution 82 conveyed in 811021 & 1104 ltrs. DIRCKS, W. J. Office of the Executive Director for Operations. 81/12/10. TAYLOR.F.R. Pennsylvania, Commonwealth of. 2pp. 19725:126. 24X Fiche: 50-000, 83/05/05, 8307250020.
- --8307250054 "Special Rept to PA House of Representatives Response to Apparent Act of Sabotage."

  \* NRC No Detailed Affiliation Given. 83/05/05. App. 19725: 134. 24x Fiche: 50-000. 83/05/05. 8307250020.
- B307010136 LER 83-017/03L-0: on B30528, following reactor trip, one source range nuclear detector observed not indicating & other source range began spiking high Bath declared inoperable.

  Cause not determined Both detectors replaced, W/B30615 ltr.

  LACEY, W. S. Duquesne Light Co. B3/06/15. ALLAN, J. M. Region 1, Office of Director. 4pp. 19124: 358. 24X Fiche: 50-334, B3/06/15. B307010:36.
- B307110412 LER B3-016/03L-0: on B3052B, supply breakers to 4, 160-volt buses 1A & 1B opened due to inadvertent operation of pilot wire protection relay, causing loss of offsite ac source & reactor trip. Caused by ground fault on panel.N/B30622 ltr. LACEY, M. S. Duquesne Light Co. B3/06/22. ALLAN, J. M. Region 1, Office of Director. 4pp. 19382:276. 24X Fiche: 50-034, B3/06/22, B307110412.
- 8307110446 LER B3-018/03L-0: on B30527.08T 1.16.5 (monthly fuel bldg ventilation sys verification) not performed since B30308.

  Caused by failing to schedule test in Apr & May.08T performed satisfactorily.W/B30622 ltr.

  LACEY.W.S. Duquesne Light Co. B3/06/22. ALLAN.J.M. Region 1. Office of Director. 4pp. 19380:196. 24X Fiche: 50-934.83/06/22.8307110446.

- GO7180170 Updated LER 81-082/01X-1: on 811005, review of structural calculations for Catagory I structures showed that allowable code working stresses could be exceeded for floor loading in excess of 100 psf. Mods completed N/830628 ltr. LACEY, M. S. Buquesne Light Co. 83/06/28. ALLAN, J. M. Region 1. Office of Director. 4pp. 19556: 213. 24X Fiche: 50-334, 83/06/28, 8307180170.
- 307220277 LER 83-019/03L-0: on 830611, while in hot standby, lift settings on 10 of 15 main steam safety valves and by Dresser found outside Tech Spec limits. Caused by valve lift setpoint drift. Settings readjusted within bolerance. W/830707 ltr. LACEY, W. S. Duquesne Light Co. 83/07/07. ALLAN, J. H. Region 1, Office of Director. 4pp. 19684: 135. 24X Fiche: 50-334, 83/07/07, 8307220277.
- 307220443 Updated LER 83-002/03X-2:on 830107,138-tV bus 1 lost Caused by Inadvertent operation of bus back-up timer relay 62-241.
  82FU & SRU relays interchanged,88FU relays modified & physical barrier around 88FU switch installed.W/830708 1tr.
  LACEYY-N.S. Duquesne Light Co. 83/07/08. ALLAN.J.M. Region 1,
  0ffice of Director. 4pp. 19486:12B. 24X Fiche:50-334.83/07/08,
  8307220443 8307220443
- DCKET 50-335 BT. LUCTE PLANT, UNIT 1
- . Security, medical, emergency & fire protection plans
- 307140276 Ack receipt of 821227 ltr providing status of corrective actions re public info & educ programs. NRC finding of adequacy will be based on mathalong w/FEMA review of emergency plann/during Jan 1983 exercise.

  O'REILLY.J.P. Region 2. Office of Director. 83/01/26. UHRIG.R.E Florida Fower & Light Co. 1p. 19522:324. 24X Fiche:50-335, 83/01/26.8307140276. UHRIG, R. E.
- 307140420 Forwards FEHA evaluation rept of 830120-21 amergency exercise per IE Insp Repts 30-335/83-04 & 30-389/83-12.

  DANCELH.C. Division of Project & Resident Programs. 83/03/30.

  URRIO.R.E. Florida Power & Light Co. 1p. 19520:213. 24X

  Fiche: 50-335.83/03/30.8307140420.
- 8307140424 "St Lucie Nuclear Power Plant Full-Scale Local Exercise Conducted on 830120," final evaluation rept. \* Federal Emergency Management Agency. 83/03/08. 36pp. 19520:214. 24X Fiche:50-335.83/03/30.8307140420.
- 07140339 Discusses 1984 full-scale emergency exercise per 830426 meeting. Exercise will extend over 3-day period. Emergency operations facility will operate at reduced level after first day.
  0 (REILLY, J.P. Region 2, Office of Director. 83/05/26, UHRIG, R. Florida Power & Light Co. 2pp. 19523: 325. 24X
  Fiche: 50-000, 83/05/26, 8307140339.
  - 93/05/26, UHRIG, R. E.
- 07140278 Informs that Boise Interagency Fire Ctr contracted to perform surveys of radiofrequency & electromagnetic interference. Assistance requested. VERRELLI, D.M. Diviston of Project & Resident Programs. 83/05/3i. UMRIO.R.E. Florida Power & Light Co. 22pp. 19522:297. 24X Fiche: 50-000,83/05/3i.8307140278.
- 07190269 Forwards notice of consideration of issuance of amend to License DPR-67 & proposed NSHC determination & opportunity for hearing re Tech Spec changes adding fire protection equipment. M Division of Licensing. 83/06/21. Docketing & Services Brand pp. 19636: 196. 24X Fiche: 50-335: 83/06/21: 8307190269.
- Division of Licensing. 83/06/21. Docketing & Services Branch. 19456:196. 24X Fiche:50-335,83/06/21.8307190269.
- B307190272 Notice of consideration of issuance of amend to License DPR-67 & proposed NSHC determination to opportunity for hearing re Tech Spec changes adding fire protection equipment to reporting requirements.

  CLARK.R.A. Operating Reactors Branch 3. 83/06/21. Bpp. 19636: 197. 24X Fiche: 50-335, 83/06/21, 8307190269.
- 07140152 Responds to util 830511 ltr re revs to Chapters 5 & 6 to security plan. Changes consistent w/10CFR50.54(p) & acceptable.

  KNIGHTON, G. W. Licensing Branch 3. 83/07/06. UHRIG, R.E. Florida Power & Light Co. 2pp. 19540:048. 24X Fiche: 50-335.83/07/06. 3307140152.
- 07270351 Forwards Rev 7 to physical security plan Rev withheld fref 1005R73.21). HRIG,R.E. Florida Power & Light Co. 83/07/07. O'REILLY, J. P. tegion 2. Office of Director. 2pp. 19747.297. 24X Liche: 30-335, 83/07/07, 8307270351.

- 8307150347 Forwards IE Safeguards Insp Repts 50-335/83-25 & 50-389/83-50 on 830613-15. No moncompliance noted. DANCE, H. C. Region 2, Office of Director. 83/07/12. WRIG, R. E Florida Fower & Light Co. 2pp. 19538: 284. 24X Fiche: 50-335,83/07/12,8307190347.
- -8307(3035) TE Safeguards Insp Repts 50-335/83-25 & 50-389/83-50 on 8306(3-15. No noncompliance noted Major areas inspected: physical security plan & (mplementing procedures re-records & repts Details withheld (ref 10CFR73.21). MODRE, D. E. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/07/11. 1p. 19538: 286. 24X Fiche: 50-335,83/07/12,8307150347.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 9307290314 Forwards Amend 1 to updated FSAR, reflecting plant changes during 820123-830122 List of plant changes/mods per 307280319 Forwards Ameno 1 to updated FORMITE STREET PROBLEM 1 to updated FORMITE STREET PROBLEM 1 to updated FORMITE STREET PROBLEM 10CFR30. 59 enc.l.
  UHRIO, R.E. Florida Power & Light Co. 83/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 8pp. 19790: 321. 24X Fiche: 50-335, 83/07/22, 8307280314.
- --8307280316 Amend 1 to updated FSAR.

  \* Florida Power & Light Co. 83/07/31. 200pp. 19790:329. 24X
  Fiche: 50-335.83/07/22,8307280314.
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- B307190327 Comments on reactor vessel thermal stress during cooldown in response to 830520 ltm. Concurs w/Taylor Ref 3 that large thermal gradients could have developed if no mixing of stagnant fluid at low temps accurred.

  ZUDANS. Z. Franklin Institute/Franklin Research Center. ZUDANS. Z. ACRS Advisory Committee on Reactor Safeguards. B3/05/31.

  MCKINLEY. J. C. ACRS Advisory Committee on Reactor Safeguards. 1p. 19656:171. 24X Fiche: 50-335, 83/05/31, 8307190327.
- P. Operating license stage documents & correspondence
- 8307080599 Notice of consideration of issuance of amend to License DPR-67 & proposed no significant hazards consideration determination & opportunity for hearing re installation of overpressure mitigation sys.

  CLARK.R.A. Operating Reactors Branch 3 83/06/10. 8pp. 19364:275. 24X Fiche: 50-335,83/06/10.8307080599.
- 8307110288 Notice of consideration of issuance of amend to License DPR-67 & proposed NSHC determination to opportunity for hearing re-radiological effluent Tech Specs compliance w/10CFR50, App I. CLARK-R. A. Operating Reactors Branch 3. 83/06/10. 7pp. 19387:003. 24% Fichs: 50-335, 83/06/10, 8307110288.
- 8307110616 Monthly notice of amends to DLs involving NSHC issued since 830523. CLARK.R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:132. 24X fiche: 50-000.83/06/14.8307110616.
- 8307140065 Concurs in 830516 request For extension until 830627 to submit call—in drills (staff augmentation/time saving measures).

  DANCE, H.C. Division of Project & Resident Programs. 83/06/20.

  UHRIG, R.E. Florida Power & Light Co. 1p. 19514:091. 24X

  Fiche: 50-000, 83/06/20, 8307140065.
- 8307190269 Forwards notice of consideration of issuance of amend to License DRR-67 & proposed NSHC determination & opportunity for hearing rs Tech Spec changes adding fire protection equipment. Division of Licensing. 83/06/21. Pocketing & Services Branch. 19656:196. 24X Fiche:50-335,83/06/21,8307190269.
- --8307190272 Notice of consideration of issuance of amend to License DPR-67 & proposed NSHC determination & apportunity for hearing re Tech Spec changes adding fire protection equipment & reporting requirements.

  CLARK, R.A. Operating Reactors Branch 3. 83/06/21. 8pp. 17656: 197. 24X Fiche: 90-339, 83/06/21, 8307170267.
- 8307010078 Responds to NRC 830617 ltr re date for submittal of beta fose analysis used in equipment qualification methodology. Reanalysis will be submitted by 830715.
  UHRIGR.E. Florida Power & Light Co. 83/06/24. CLARK, R. A. Operating Reactors Branch 3. 1p. 19124:345. 24X Fiche: 50-335,83/06/24,8307010078.

- 8307050016 Informs that intake structure crane fully complies w/Guideline 7 of NUREO-0612, "Crane Design." based on Franklin Research Ctr & Dresser Industries studies UHRIG.R.E. Florida Power & Light Co. 83/06/28. CLARK.R.A. Operating Reactors Branch 3. 1p. 19193:085. 24X Fiche: 50-335,83/06/28,8307050016.
- 8307060223 Discusses use of C-E Windsor simulator in requalification training to prevent & mitigate voiding during natural circulation cooldown per 830426 request Simulator does not have capability to model upper head voiding.
  UHRIG.R.E. Florida Power & Light Co. 83/06/30. CLARK.R.A. Operating Reactors Branch 3. 1p. 19239:360. 24X
  Fiche: 50-335,83/06/30,8307060223.
- B307040233 Submits addl info supporting B30216 request for amend to License DPR-67 revising surveillance requirements of 123-volt dc batteries in conjunction w/sys mods, in response to NRC request Unit 1 dc sys modified identically to Unit 2. UHR10.R.E. Florida Power & Light Co. 83/06/30. EISENHUT, D. G. Division of Licensing. 4pp. 17239: 287. 24X Fiche: 30-335, 83/06/30, 8307060253.
- 8307070077 Forwards description of C-E Gwners Group program for resolving TMI Item II.K.3.5 "Automatic Trip of Reactor Coolant Pumps" & Generic Ltr 83-101. Program scheduled for completion by end of 1983.
  UHRIO.R.E. Florida Power & Light Co. 83/07/01. EISENHUT, D. Q. Division of Licensing. 6pp. 19293:076. 24X Fiche: 50-335,83/07/01,8307070077.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Ficha: 50-000,83/07/05,8306270397.
- 8307040329 Generic Ltr 83-27 to all licensess & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche: 50-000, 83/07/06, 8307060329.
- 8307130205 Requests withholding of Rev ! to GTR105. "Qualification of EA180 Series Limit Switches for Use in Nuclear Power Plants in Compliance W/IEEE Stds 323-1974.382-1972 & 344-1975." per 10CFR2.790.

  SWANSUN.N.E. Acme-Cleveland Development Co. 83/07/07. NRC No Detailed Affiliation Given. 1p. 19465.353. 24X

  Fiche: 50-335.83/07/07.8307130205.
- 8307080167 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:267. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307270255 Forwards request for add1 info re 830505 justification for continued operation for Item 114 re environ qualification of Category II. B equipment Info requested within 30 days. CLARK, R.A. Operating Reactors Branch 3. 83/07/11. UHRIG, R.E. Florida Power & Light Co. 4pp. 1981: 177. 24X Fiche: 50-335, 83/07/11, 8307270255.
- G307280465 Requests ex-core detector neutron noise & accelerometer data taken at plant. GRNL will analyze data to establish possible correlations to thermal shield motion & vibration. CLARK.R.A. Operating Reactors Branch 3. 83/07/11. UHRIG.R.E. Florida Power & Light Co. 2pp. 19824:040. 24X Fiche: 50-335, 83/07/11, 8307280465.
- 8307190141 Advises that 830714 menting re reactor vessel internals & inspiresults per plant recovery program rescheduled for 830721. Followup documentation will be submitted by 830728. UHRIG.R.E. Fiorida Power & Light Co. 83/07/13. CLARK.R.A. Operating Reactors Branch 3. 1p. 17436: 174. 24X Fiche: 50-335, 83/07/13, 8307190141.
- B307190395 Notification of 830721 meeting w/utils & CrE in Bethesda.MD to discuss damage to Millstone thermal shield & status of St Lucie thermal shield disposal.
  LEECH.P. Operating Reactors Branch 3. 83/07/13. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19654:035. 24X Fiche: 50-000.83/07/13.8307190395.

- 8307190160 Forwards final response to NRC 830216 ltm re purge valve operability. Revised purge valve rept addresses remaining NRC concerns re operability of 48-inch containment purge valves for facility.

  UHRIO.R.E. Florida Power & Light Co. 83/07/15. CLARK.R.A. Operating Reactors Branch 3 6pp. 19628 080. 24X

  Fiche: 50-335,83/07/15,8307190160.
- --B307190165 Procedure FLO-B770.114. "Isolation/Purge Valve Analysis for 48-Inch RIA Butterfly Valve Blocked at 40 Degrees." W/two oversize drawings Aperture cards are available in PDR KAZA.R.N. Ebasco Services, Inc. (subs. of Enserch Corp.). 83/04/27 B2pp. 19628:086 24x Fiche.50-335.83/07/15.8307190160.
- B307220503 Forwards analysis supporting conclusion that B30128 proposed changes to Tech Specs re shutdown margin & moderator temp coefficient limits involve NSHC.

  UHRIO, R.E. Florida Power & Light Co. B3/07/15. CLARK, R.A.

  Operating Reactors Branch 3. App. 19685:275. 24X

  Fiche: 50-335, B3/07/15, 8307220503.
- B307220508 Forwards Rev 1 to "Equipment Gualification Radiation Dose Map Development." per NRC 830617 request. UHR10.R.E. Fibrida Power & Light Co. B3/07/15. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19685:104. 24X Fiche: 50-335.83/07/15.8307220508.
- --8307220514 Rev 1 to "Equipment Qualification Radiation Dose Map Development " \* Florida Power & Light Co. 83/06/24. 16pp. 19685:106. 24X Fiche:50-335,83/07/15,8307220308.
- G. Inspection reports. IE Bulletins & correspondence
- 8307140227 Requests that liquid samples spiked w/radionuclides be analyzed for tritium. Sr-89 % Sr-90 content within 60 days of receipt of spiked samples. Samples will be sent annually as part of routine insp program. LEWIS, R. C. Division of Project & Resident Programs. 83/02/07, UHR10, R. E. Florida Power & Light Co. 1p. 19524:060. 24% Fiche: 50-000.83/02/07.8307140229.
- 8307140420 Forwards FEMA evaluation rept of 830120-21 emergency exercise per IE Insp Repts 50-335/83-04 & 50-387/83-12 DANCE, H. C. Division of Project & Resident Programs. 83/03/30. UHRIOR, E. Florida Power & Light Co. 1p. 19520:213. 24X Fiche: 50-335,83/03/30,8307140420.
- 8307140217 Confirms 830426 request for extension of time to respond to IE Tasp Rept 50-335/83-16. Response will be submitted by 830007. UHRIG.R E. Florida Power & Light Co. 83/05/03. O'REILLY, J. P. Region 2. Office of Director. 1p. 19921:332 24X Fiche: 30-335.83/05/03.8307140217.
- B307140147 Forwards IE Insp Repts 50-335/83-09 % 50-389/83-22 on 830311-0410. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/14 UHRIGA, R. E. Florida Power & Light Co. 2pp 19514:231. 24X Fiche: 50-335,83/06/14,8307140147.
- --B307140154 IE Insp Repts 30-335/83-07 & 50-389/83-22 on 830311-0410.No noncompliance noted Major areas inspected meint & surveillance observations, plant operations. IE bulletins, circulars & info notices.LERs new fuel handling. ELROD. S.A., BIBB.H.E. Region 2. Office of Director. JULIAN.C. Division of Project & Resident Programs. 83/06/13. 14pp. 19514: 233. 24X Fiche: 50-335, B3/06/14, B307140147.
- 8307140374 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-339/83-12.

  DANCE,H C. Division of Project & Resident Programs. 83/06/27.

  UHRIGR E. Florida Power & Light Co. ip. 19520:166. 24X

  Fiche: 50-335, 83/06/27, 8307140394.
- --8307140398 Responds to NRC 836516 ltr re violations noted in IE Insp. Rept 50-335/83-12. Corrective actions, documents correctly posted inside security check point to prevent unauthorized removal. Full compliance achieved 830412.

  UHR10.R.E. Florida Power & Light Co. 83/06/13. 0'REILLY, J. P. Region 2. Dffice of Director 2pp. 19520:167. 24X
  Fiche: 50-335,83/06/27,8307140394
- --8307140405 Forwards IE Insp Repts 50-335/83-12 & 50-389/83-32 on B30411-15 & notice of violation.

  DANCE H.C. Division of Project & Resident Programs. 83/03/16. UHRIG.R.E. Florida Power & Light Co. 2pp. 19520-169, 24x Fiche: 50-335, 83/06/27, 8307140394.
- --8307140407 Notice of violation from this on 830411-15.
  \* Region 2, Office of Director. 83/05/16. lp. 19320:171. 24X Fiche. 50-335, 83/06/27, 8307140394.

- --8307140411 [E Insp Repts 50-335/83-12 & 50-389/83-32 on 830411-15 Noncompliance noted: failure to post specified documents per 100FRI9-11. WRAY,J.R. Region 2: Office of Director. BARR.K.P. Division of Engineering & Radiological Safety Programs. 83/05/11. 9pp. 19520:172. 24X Fiche: 50-335, 83/06/27, 8307140394.
- 8307220015 Forwards IE Insp Rept 50-335/83-22 on 830531-0603. No noncompliance noted. DANCE:H C. Division of Project & Resident Programs. 83/06/28. UHRIG:R E. Florida Power & Light Co. 2pp. 19674:067. 24X Fiche: 90-335
- --8307220022 IE Insp Rept 50-335/83-22 on 830531-0603 No noncompliance noted Major areas inspected inservice testing of pumps & valves & plant water chemistry.
  GIRARD,E., ROSS, W. J. Region 2, Office of Director. BLAKE, J. J. Division of Engineering & Radiological Safety Programs. 83/06/24. 5pp. 19674:069. 24X Fiche: 50-335,83/06/28,8307220015.
- 8307140373 Ack receipt of 630523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/83-05. LEWIS.R.C. Division of Project & Resident Programs. 83/06/29. UMRIG.R E. Florida Power & Light Co. 1p. 17521:314. 24X Fiche. 90-335.83/06/29.8307140393.
- --8307140401 Responds to NRC 830421 ltr re violations noted in 1E Insp Rept 50-335/83-05. Corrective actions operations personnel reinstructed in importance of proper & timely use of procedures by means of 830509 night order. URRIO.R.E. Florida Power & Light Co. 83/05/23. O'REILLY, J. P. Region & Dffice of Director. 2pp. 19521:315. 24X Fiche.50-335,83/06/29,8307140393.
- --B30714040B Forwards IE Insp Repts 50-335/83-05 & 50-389/83-15 on 830211-0310 & notice of violation. LEWIS.R.C. Division of Project & Resident Programs. 83/04/21. URRIG.R.E. Florida Power & Light Co. 2pp. 19521:317. 24X Fiche:50-335,83/06/29,8307140393.
- --8307140413 Notice of violation from insp on 830211-0310. Region 2. Office of Director. 83/04/21. 1p. 1991 Fiche.50-339. 83/06/29. 8307140/39. . 19521:319. 24X
- --8307140418 IE Insp Repts 50-335/83-05 & 50-387/83-15 on 830211-0310. Noncompliance noted: failure to follow refueling sequencing procedure during refueling operations. ELROD.5.A., BIBD.H.E. Region 2, Office of Director. JULIAN.C.A. Division of Project & Resident Programs. 83/04/21. 12pp. 19521:320. 24X Fiche: 50-335,83/04/29,8307140393.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830(03). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche:50-000.83/07/12.8306270404
- 8307130347 Forwards IE Safeguards Insp Repts 50-335/83-25 & 50-389/83-50 on 830613-15. No noncompliance noted.

  DANCE.H.C. Region 2. Office of Director. 83/07/12. UHRIG.R.E. Florida Power & Light Co. 2pp. 19538: 284. 24X
  Fiche: 50-335.83/07/12.8307150347.
- -B307150355 IE Safeguards Insp Repts 90-335/E3-25 & 50-389/83-50 on 830613-15. No noncompliance noted Major areas inspected: physical security plan & implementing procedures re records & repts Details withheld (ref IOCFR'3 21). MODRE, D. E. Region 2. Office of Director. MCGUIRE, D. R. Division of Emergency Pregaredness & Materials Safety. 83/07/11. lp. 19538:286. 24X Fiche: 50-335/83/07/12/8307150347.
- 8307190141 Advises that 830714 meeting re reactor vessel internals & inspiresults per plant recovery program rescheduled for 830721. Followup documentation will be submitted by 830728. UHRIG.R.E. Florida Power & Light Co. 83/07/13. CLARK.R.A. Operating Reactors Branch 3. 1p. 19636:176. 24X Fiche: 30-335, 83/07/13. 8307190141.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list Radioactive i-120 & 1-131 in Excess of Min Edward Constitution of QA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche 50-000.83/07/14.8306270406.

- 8307220381 Ack receipt of 830511 & 0624 ltrs informing NRC fo steps taken to correct violations noted in IE Insp Rept 50-335/83-08. эр-дарид-ры. DANCE,H.C. Division of Project & Resident Programs. 83/07/15. UHRIG.R.E. Florida Power & Light Co. 1p. 19687:337. 24X Fiche:50-335,83/07/15,8307220381.
- --8307220389 Provides add) info re violations noted in IE Insp Rept 50-335/83-08. Corrective actions: codes & insp section will develop necessary procedures & revs to GA manual prior to next refueling outage in Oct 1983.

  URRIGR E. Florida Power & Light Co. 83/06/24. O'REILLY, J. P. Rejion 2. Office of Director. 2pp. 19687: 338. 24X Fiche: 50-335, 83/07/15, 8307220381.
- --8307220372 Responds to NRC 8304ii ltr re violations noted in IE Insp Rept 50-335/83-06. Corrective actions: computerized capability of flagging timely events being developed & event status will be provided to mgt. UMRIG.R.E. Florida Power & Light Co. 83/03/11. O'REILLY, J. P. Region 2. Defice of Director. 2pp. 19687: 340. 24X Fiche: 50-335, 83/07/15, 8307220381.
- ~8307220395 Forwards IE Insp Rept 50~335/83-08 on 830315-18 & notice of violation.

  DANCE H.C. Division of Project & Resident Programs. 83/04
  UHRIG.R.E. Florida Power & Light Co. 2pp. 19687:342. 24
  Fiche: 30-335,83/07/15.8307220381.
- --8307220398 Notice of violation from insp on 830315-18.

  \* Region 2, Office of Director. 83/04/11. 1p. 19687:344. 24X Fiche:50-335,83/07/15,8307220381.
- ---B307220400 IE Insa Rept 50-335/B3-0B on B30315-18. Noncompliance noted: failure to establish measures to correct conditions adverse to quality.

  GROWLEY, B. R. BLAKE, J. J. Region 2. Office of Director. B3/04/0B. ality. EY,B.R., BLAKE,J.J. Region 2, Office of Director. 83/04/08. 19687: 345. 24X Fiche: 50-335, 83/07/15, 8307220381.
- 8307260905 Reschedules 830721 meeting to discuss reactor vessel internals & inspiresults for plant recovery program. New meeting date will be determined by 830727.

  UHRIG.R.E. Florida Power & Light Co. 83/07/20. CLARK.R.A. Operating Reactors Branch 3. ip. 19733:314. 24X

  Fiche: 50-335
- R. Periodic operating reports & related correspondence
- B307220329 Monthly operating repts for May 1783.W/B30415 ltr. PACE.P.L.: WILLIAMS.J.W. Florida Power & Light Co. B3/06/15. Office of Resource Management, Director. 17pp. 19675:132. 24X Fiche:30-000:83/06/15.B307220329.
- S. Reportable occurrences, LERs & related correspondence
- 8307120166 LER 83-027/03L-0: un B30531, periodic surveillance of fuel handling bldg area radiation monitors not performed par Tech Spers. Caused by incorrect surveillance procedure & personnel error. Procedure revised W/B30630 ltr. WALLING.G.E., WILLIAMS, J.W. Florida Power & Light Co. 83/06/30. UnRILLY.J.P. Region 2, Office of Director. 2pp. 19423:162. 2: Fiche: 50-335:83/06/30.8307120166.
- V. Operator Examinations
- 8307140300 Forwards list of personnel licensed to operate both units & of personnel licensed to operate only Unit 2 per 821129-1210,830124 & 0424 exams. Addl info re 820219 westing request to lift separate license restriction needed.

  DANCE, H. C. Division of Project & Resident Programs, 83/06/16, UHRIO, R. E. Florida Power & Light Co. 4pp. 19523:233, 24X Fiche: 50-335,83/06/16,8307140300.
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307010074 Forwards Rev 17 to modified amended security plan. Rev withhold (ref 10CFR2.790).
  CCUMSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CCUMSIL.W.G. Northeast Utilities. 83/06/09.
  MURLEY.T.E. Region 1, Office of Director. 1p. 19124:339. 24X Fiche:50-245.83/06/09.8307010074.
- 8307010195 Forwards IE Insp Repts 50-249/83-08 & 50-336/83-10 on 830508-0604. No noncompliance noted.
  STARGSTECKLR. Division of Project & Resident Programs. 83/06/14. COUNSIL, N. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19170:086. 24X Fiche 50-245, 83/06/14, 8307010155.

- ~-8307010167 IE Insp Repts 50-245/83-08 & 50-336/83-10 on 830508-0604. No noncompliance noted Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, physical security & fire protection.

  SHEDLOSKY, J. T. Region 1, Office of Director. 83/06/10. 11pp. 19170: 088. 24X Fiche: 50-245, 83/06/14, 8307010155.
- 8307010072 Forwards IE Insp Repts 50-245/83-10 & 50-336/83-12 on 830516-19. No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/15. COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19168:132. 24X Fiche: 50-245.83/06/15.8307010072.
- --8307010080 IE Insp Repts 50-245/83-10 & 50-336/83-12 on 830516-19. No noncompliance noted Major areas inspected: followup of emergency preparedness items from IE Insp Repts 50-245/82-01 & 50-336/82-01 on 820104-14.
  MILLER.M. Region 1. Office of Director. 83/06/15. 17pp. 19168: 134. 24X Fiche: 50-245, 83/06/15, 8307010072.
- 8307110019 Forwards Rev 1 to suitability training & qualification plan.
  Rev withheld (ref 100FR2.790).
  GDUNSILL.W.G. Northeast Nuclear Energy Co. (subs. of Northeast
  Utilities). COUNSIL.W.G. Northeast Utilities. B3/06/24.
  MURLEY.T.E. Region 1, Office of Director. 1p. 19374:202. 24X
  Fiche: 50-245, B3/06/24, B307110019.
- J. Insurance & indemnity information
- 8307200111 Forwards Secondary Financial Protection Certificates N-15 & N-16 to NELIA Policy 1 & Secondary Financial Protection Certificates M-15 & M-16 to MAELU Policy 1.

  8INISI.J.M. Marsh & McLennan, Inc. 83/07/12. SALTZMAN, J. D.

  Assistant Director for State & Licensee Relations. 27pp. 17646:001.

  24X Fiche: 50-245, 83/07/12, 8307200111.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307040136 Forwards Rev 1 to updated FBAR for Millstone Unit 2.
  COUNBIL.W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B3706/30.
  DENTON.M.R. Office of Nuclear Reactor Royalation, Director. 3pp. 19252:012. 24x Fiche: 50-336, B3706/30, B307060136.
- --8307060140 Rev 1 to updated FSAR for Millstone Unit 2.

  \* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). \*
  Northeast Utilities. 83/06/30. 200pp. 19252:015. 24X
  Fiche: 50-336.83/06/30.8307060136.
- P. Operating license stage documents & correspondence
- B307110616 Monthly notice of amends to OLs involving NSHC issued since B30923. CLARK.R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fiche: 50-000.83/06/14.8307110616.
- 8307060284 Requests FR publication of notice of consideration of issuance of amend to License DPR-65, proposed NSHC & opportunity for hearing re changes to Cycle & refueling specs. NSHC determination withheld.
  CLARK.R.A. Operating Reactors Branch 3. 83/06/27. Operating Reactors Branch 3. 83/06/27. Branch 3. 4pp. 19300:160. 24X Fiche: 50-336, 83/06/27, 8307060284.
- 8307140148 Ack receipt of util 811231,820416,0625,1229,830308 & 0328 submittals on TMI Action Plan Items II.F.1.4,II.F.1.5 & II.F.1.6 re containment monitors. Items resolved. Safety evaluation encl.
  CLARK.R.A. Operating Reactors Branch 3. 83/06/27, COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 8pp. 19529:351. 24X Fiche: 50-336,83/06/27,8307140148.
- 8307080333 Forwards program description & schedule for resolving NUREO-0737. Item II. K. 3. 5, "Automatic Trip of Roactor Coplant Pumps." Program completion scheduled for end of 1983. Results of analysis & training dates will be communicated by 831293. COUNSIL. W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL. W. G. Northeast Utilities. 83/07/01. E18ENHAUT. D. G. Division of Licensing. 7pp. 19350:306. 24X Fiche: 50-336, 83/07/01. 8307080353.
- 8307080400 Forwards response to 830610 request for addl info remethodology used to perform safety analyses supporting Cycle 6 operation. Analyses performed based on C-E Owners Group Rept CEN-199 in response to NUREG-0737. Item II. K. 2. 17. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. B3/07/01. CLARK. A. Operating Reactors Branch 3. 9pp. 19349: 315. 24X Fiche: 50-336, 83/07/01, 8307080400.

- 8306270397 Generic Ltr 83-26 to all applicants for CLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390.317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT.D G. Division of Licensing, 83/07/06. Consolidated Edison Co of New York, Inc. 16pp 19669:254 24X Fiche: 50-000.83/07/06.8307060329.
- 8307150193 Application for amend to Licenses DPR-21 & DPR-65, revising Section 6 of administrative Tech Specs to reflect updated util policies & practices.
  GDUNSTL.W.G. SEARS.C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSTL.W.G. Northeast Utilities. 83/07/07.
  CLARK.R.A. Operating Reactors Branch 3. CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 19538:030. 24X Fiche: 50-245.83/07/07.
  B307150193.
- --8307150197 Proposed rev to administrative Tech Specs reflecting updated util policies & practices.

  \* Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  83/06/30. 32pp. 19538:032. 24X Fiche:50-245,83/07/07,8307150193.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL ½ holders of CPs ro required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307190395 Notification of 830721 meeting w/utils % C-E in Dethesda, MD to discuss damage to Millstone thermal shield & status of St Lucie thermal shield disposal.

  LEECH, P Operating Reactors Branch 3. 83/07/13 CLARK, R. A. Operating Reactors Branch 3. 29p. 19654: 035. 24x

  Fiche: 50-000, 83/07/13, 8307190395.
- 8307190131 Submits revs to Corporate Organization for Nuclear Incidents Procedure Manual, per 10CFR50, App E. Section V. COUNSIL, M. G. Connecticut Yankee Atomic Power Co. COUNSIL, M. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, M. G. Northeast Utilities. 83/07/14. EISENHUT, D. G. Division of Licensing. 1p. 19636: 074. 24X Fiche: 50-000, 83/07/14, 8307190131.
- B307250469 Forwards add1 info re methodology utilized in performing safety analysis supporting Cycle 6 operation, in response to Guestion 400.5 in 830701 ltr.
  CGUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CCUNSIL.W.O. Northeast Utilities. B3/07/15.
  CLARK.R.A. Operating Reactors Branch 3. 19pp. 19701:300. 24X Fiche: 30-336, B3/07/15, B307250469.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307010155 Forwards IE Insp Repts 50-245/83-08 & 50-336/83-10 on 830508-0604. No noncompliance noted.
  8TAROSTECKIP. Division of Project & Resident Programs. 83/06/14. COUNSIL.W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19170:086. 24X Fiche:50-245,83/06/14,8307010155.
- --8307010167 IE Insp Repts 50-245/83-08 & 50-336/83-10 on 830508-0604 No noncompliance noted Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, physical security & fire protection.

  SHEDLOSKY, J. T., LIFINSKI, D.R. Region I, Office of Director, ELSASSER, T.C. Division of Project & Resident Programs. 83/06/10. 11pp. 19170:088. 24X Fiche: 50-245-83/06/14-8307010155.
- B307010072 Forwards IE lnsp Repts 50-245/83-10 & 50-336/83-12 on B30516-19. No noncompliance noted.

  MARTIN/T.T. Division of Engineering & Technical Programs. B3/06/15. COUNSIL/W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19168:132. 24X Fiche: 50-245/83/06/15/8307010072.
- --B3070100B0 IE Insp Repts 50-245/83-10 & 50-336/83-12 on 830516-19. No noncompliance noted. Major areas inspected: followup of emergency preparedness items from IE Insp Repts 50-245/82-01 & 50-336/82-01 on 820104-14.
  MILLER.H., SMITH.R., CROCKER.H.W. Region 1, Office of Director. 83/06/15. 17pp. 19168:134. 24X Fiche: 50-245/83/06/15, 8307010072.
- 8307120429 Ack receipt of 830620 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-06 & 50-326/83-08.

  STAROSTECKI.R. Division of Project & Resident Programs. 63/07/08. COUNSIL.W. 6. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). Ip. 19425:236. 24X Fiche 50-245.83/07/05.8307/203807/2038

- --8307120432 Responds to NRC 830923 ltr re violations noted in IE Insp. Repts S0-245/83-06 & 50-336/83-08. Corrective actions: logging requirement implemented for periodic verification of computer updating COUNSIL W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.G. Northeast Utilities. 83/06/20. STARGSTECKI, R. Division of Project & Resident Programs. 2pp. 19425. 237. 24X Fiche: 50-245, 83/07/05, 8307120429.
- 8306270401 IE Info Notice 83-44, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24x Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche:50-000.83/07/12.8306270404.
- 8307190206 Advises that violations cited in IE Insp Repts 50-245/82-24, 50-336/82-26 & 50-213/83-02 re QA program for transport packages will be changed to unresolved items until firm criteria established.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/13. COUNSILE M. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19632:115. 24X Fiche:50-000,83/07/13,8307190206.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Ercess of NRC Limits." Svc list encl.
  TAYLOR.J. M. Division of GA. Safeguards & Inspection Programs (Post 830103) 83707714. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24x Fiche: 50-000.83/07/14.8306270406.
- R. Periodic operating reports & related correspondence
- 8307220042 Monthly operating rept for May 1983 W/830614 ltr. GIBSON.J. MROCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA.E.J. Northeast Utilities. 83/06/10. Office of Resource Management. Director. 6pp. 19683:294. 24X Fiche: 50-336.83/06/10.8307220042.
- S. Reportable occurrences, i.ERs & related correspondence
- 8307010030 Updated LER B3-016/03X-1:on 830421, steam driven auriliary feedwater pump removed from svc to replace pump packing. Caused by leaky pump due to packing failure. Packing to be replaced at 3-yr intervals. W/830622 ltr. FILBURN.T., HRGCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). HRGCZKA.E.J. Northeast Utilities. 83/06/22. MURLEY.T.E. Region i. Office of Director. 1p. 19169:028. 24X Fiche: 50-336,83/06/22,8307010030.
- 8307050104 LER B3-023/03L-0: on 830526, inservice insp of low pressure safety injection B detected excessive noise emanating from pump. Caused by rubbing of pump inpeller lower wear ring due to worn lower bearing in pump motor. H/830624 ltr. FILBURN. T., KELLEY, J. J. Northeast Nucluar Energy Co. (subs. of Northeast Utilities. 83/06/24, MURLEY, T.E. Region 1. Office of Director. 2pp. 19199:339, 24% Fichs: 50-336.83/06/24,8307050104.
- 8307060024 LER 83-022/03L-0: on 830528, while cooling down ESF actuation sys: pressurizer pressure block permissive alarmed in nonconservative direction. Caused by personnel error. Event covered in detail in training session. W/80627 ltr. DESLANDES: K. D. MRGCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRGCZKA, E. J. Northeast Utilities. 83/06/27. MURLEY. T. E. Region 1. Office of Director. 2pp. 19251: 047. 24X Fiche: 50-336, 83/06/27, 8307060024.
- Q307060259 LER 83-020/01T-0: on 830613, during scheduled inservice eddy current erams of steam generator tubing approx 900 tubes in each steam generator found w/degradation exceeding 40%. Cause unrnoun, 40d1 exams continuing, W/830627 ltr. BLANCHARD.T. MRGCZKA.E.J. Northeast Utilities. MRGCZKA.E.J. Northeast Utilities. MRGCZKA.E.J. 83/06/27. MURLEY.T. Region 1, Office of Director. 2pp. 19239: 292. 24% Fiche: 30-336,83/06/27,8307060259.
- B3070603B1 LER B3-021/03L-0: on B3052B, setpoints for 11 of 16 main steam safety valves drifted outside limits during testing. Cause unknown. Investigation indicated valve springs relaxed due to cyclic heating. W/830627 ltr.
  B74DNICK.5. MRGCZKA.E.J. Northeast Utilities. MRGCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  B3/06/27. MURLEY.T.E. Region 1, Office of Director. 2pp. 19236: 120. 24X Fiche: 50-336.83/06/27.8307060381.

- B307060027 PNS-1-83-015A: updates B30616 marijuana cigarette discovery reported on B30617. Seven contract security personnel terminated because of accusations or admissions of usage. DUNLOP.J. GODY.A. Region 1, Office of Director. B3/06/30. 1p. 19251:349. 24X Fiche: 50-245.83/06/30.8307060027.
- 8307180164 RO 50-336/83-24: initial insp of reactor vessel internals on core barrel & thermal shield revealed damage to thermal shield. Damage similar to that at Maine Yankee & St Lucie, Investigation continuing.

  MROCZKA: E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA: E. J. Northeast Utilities. 83/07/01.

  MURLEY.T.E. Region i, Office of Director. 1p. 19595:268. 24X Fiche: 50-336,83/07/01.8307180164.
- 8307220408 LER 83-019/03L-1: on 830528, following reactor trip from 40% power, greater than 1.0 uCi per g I-131 indicated in primary coolant. Caused by degraded fuel pins. Results of fuel sipping performed 830622-30 encl. W/830712 ltr.
  PARILLO, J., MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/07/12. MVRLEY, T.E. Region 1, 0ffice of Director. 4pp. 19691:169. 24X Fiche: 50-336, 83/07/12, 8307220408.
- 8307210012 LER 83-024/01T-0: on 830630, during scheduled insps of reactor vessel core barrel & thermal shield damage to thermal shield discovered. Cause unknown. Shield will be removed from core barrel assembly to prevent recurrence. W/830714 ltr. BATES.R. H., MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities. MROCZKA, E. J. Northeast Utilities. B3/07/14. MURLEY, T. E. Region i. Office of Director. 2pp. 19669: 243. 24X Fiche: 50-336, 83/07/14, 8307210012.
- 8307210342 RO: on 830421, following preliminary manual test insertion (MTI) test actuation module lights came on due to module energizing. Cause unknown. Operators stationed to mitigate problems or actuation if MTI required.

  MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/07/15. DEYOUNO. R. C. Director's Office. Office of Inspection and Enforcement. 3pp. 17664:359. 24%
  Fiche: 50-336,83/07/15,8307210342.
- DOCKET 80-338 NORTH ANNA POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8307140068 Ack receipt of 830216 ltr & Rev 5 to guard training & qualification plans. Revs acceptable per 10CFR30. 54(p). Mod implementation will be examined in forthcoming insp rept. LEWIS.R.C. Division of Project & Resident Programs. 83704/22. STEWART, W.L. Virginia Electric & Pawer Co. 1p. 19514:090. 24X Fiche: 50-000.83/04/22.8307140068.
- 8307140353 Ack receipt of 830318 ltr re emergency exercise scheduled during June 1983. Scenario under review. Addl comments on exercise details will be made by telephone. DANCE, H. C. Division of Project & Resident Programs. 83/06/15. STEWART. W. L. Virginia Electric & Power Co. 1p. 19525: 232. 24x Fiche: 50-338, 83/06/15, 8307140353.
- B307110159 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. B3/06/24. Document Management Branch. 1p. 19386:014. 24X Fiche: 50-338, 83/06/24, 8307110159.
- --8307110165 Forwards public version of revised emergency plan implementing procedures. Including Procedures EPIP-1.01 remergency manager controlling procedure & EPIP-3.02 reactivation of technical support ctr. Receipt form encl. Yirginia Electric & Power Co. 83/04/20. NRC No Detailer Affiliation Given. ip. 19386:015. 24% Fiche: 50-338,83/06/24,8307110159.
- --8307110169 Public version of revised emergency plan implementing procedures, including Procedures EPIP-1.01 we emergency manager controlling procedure & EPIP-3.02 we activation of technical support ctm.
  PAXTON.0.J. Virginia Electric & Power Co. 83/04/20. 100pp. 19386:016. 24X Fiche: 50-338,83/06/24,8307110159.
- 8307i10i79 Releases public version of revised corporate emergency response plan. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19386:001. 24X Fiche: 50-000.83/06/24, 8307110179.
- --B307110184 Public version of Rev 3 to corporate emergency response plan. W/B30414 ltr.
  STEMART. M. L. Virginia Electric & Power Co. B3/05/15.
  D'REILLY, J. P. Region 2, Office of Director. App. 19386: 002. 24X Fiche: 50-000, B3/06/24, B307110179.

- 8307120302 Forwards suppl to proposed Tech Spec changes re 820624 application to amend Licenses NPF-4 % NPF-7 reflecting reorganization in GA dept & addition of director emergency planning to nuclear operations dept.

  STEMART.W.L. Virginia Electric & Power Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19424:073. 24X Fiche: 50-338,83/07/01,8307120302.
- --BJ07120308 Proposed Tech Spec changes reflecting reorganization in QA dept & addition of director emergency planning to nuclear operations dept.

  4 Virginia Electric & Power Co. BJ/07/01. 28pp. 17424:075. 24x Fiche: 50-338,83/07/01,8307120302.
- 8307120386 Forwards procedures generation package for emergency operating procedures in response to NUREO-0737. Suppl 1 (Generic Ltr 82-33).
  STEMART.W.L. Virginia Electric & Power Co. 83/07/01. DENTON, H. R. Defice of Nuclear Reactor Regulation, Director. EISENHUT. D. G. Division of Licensing. 15pp. 19426:209. 24X Fiche: 50-000, 83/07/01, 8307120386.
- 8307120561 Suppl to 820624 application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs re mgt reorganization & records of annual audits for emergency & security plans.

  STEMART.W.L. Virginia Electric & Power Co. B3/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK, R.A. Operating Reactors Branch 3. 2pp. 19433:098. 24X

  Fiche: 50-338,83/07/01,8307120361.
- 8307190041 Forwards IE Safeguards Insp Repts 50-338/83-16 & 50-338/83-15 on 830626-30. No noncompliance noted. DANCE, M. C. Division of Project & Rasident Programs. 83/07/15. STEMART, W. L. Virginia Electric & Power Co. 2pp. 19635:138. 24X Fiche: 50-338, 83/07/15, 8307190041.
- --8307190060 IE Safeguards Insp Repts 50-338/83-16 & 50-339/83-15 on 830626-30. No noncompliance noted Major areas inspected: security mgt, repts & records, maint, physical barriers & protected areas. Details witheld (ref 10CFR73, 21). HALL, B. Region 2. Office of Director. MCGUIRE, D.R. Division o Emergency Preparedness & Materials Safety. 83/07/14. 1p. 19635:140. 24X Fiche: 50-338, 83/07/15, 83/07/190041.
- 8307270289 Forwards response to 830322 comments re inconsistencies in Rev B to security plan & ltr of understanding between util & NRC, Encls withheld (ref 10CFR2, 790), STEWART, W. L. Virginia Electric & Power Co. 83/07/22, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19768:358, 24 Fiche: 50-338, 83/07/22, 8307270289.

## G. Adjudicatory correspondence

- 8307120053 Advises of HJ McGurren reassignment from Hearing Div I to Hearing Div II & transfer of North Anna case from Hearing Div II & transfer of North Anna case from Hearing Div II to Hearing Div II, effective 830712.
  CHRISTERBURYN: E. Hearings Division. 83/07/08. RUTBERG, J. Hearing Branch 2. TREBY.S. Hearing Branch 1. ip. 19423:152. 24X Fiche: 50-338,83/07/08,8307120053.
- 8307150299 Advises that Commission 830630 Memorandum & Order CLI-83-19 vacated ALAB-687 to extent inconsistent w/decision. ASLB cited ALAB-687 in 821203 & 830610 memoranda. WOLFE, S. J. Atomic Safety and Licensing Board Panel. 83/07/14. MAUPIN.M.W. Hunton & Williams. MCGURREN.H.J. Hearing Branch 1. COLEMAN.J.M. Beveridge, Fairbanks & Diamond. 1p. 19538:304. 24X Fiche: 50-338, 83/07/14, 8307190299.
- B307180019 Responds to ASLB 830610 order for estimated dates of issuance of SERs & EIAs for proposed actions to receive & store Surry spent fuel at North Anna & expand capacity of North Anna fuel pool. Documents to be issued at end of yr. MCGURREN.H.J. Hearing Branch I. B3/07/14. WOLFE.S.J., KLINE.J., FERGUSON.G.A. Atomic Safety and Licensing Board Panel. 2pp. 17560: 132. 24X Fiche: 50-338. B3/07/14.8307180019.

#### J. Insurance & indemnity information

8307130068 Forwards Endorsements 70,53,32 & 43 to NELIA & MAELU Policies NF-186. MF-57. MF-96 & NF-240. respectively. Endorsements 1-4 to NELIA Certificates N-27 & N-28 & Endorsements 1-3 to MAELU Certificates M-27 & M-28. PAINTER. B.F. Virginia Electric & Pawer Co. 83/07/05. DINITZ. I. Antitrust & Economic Analysis Branch (Utility Finance). 53pp. 19474: 150. 24X Fiche: 50-000.83/07/05. 6307130068.

- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563.116. 24X Fiche 90-000.83/06/03.
- 8307010090 Advises of changes to NPDES permit & state certification Section 401. Changes result from study to be done re impact of thermal discharges on blota in Lake Anna. List of interim actions for state water control board to initiate encl.

  STEWART.W L. Virginia Electric & Power Co. B3/06/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 19124-355 24X
  Fiche: 50-338,83/06/27.6307010090.
- 8307120302 Forwards suppl to proposed Tech Spec changes re 820624 application to amend Licenses NPF-4 % NPF-7 reflecting reorganization in 8A dept % addition of director emergency planning to nuclear operations dept STEWART.M.L. Virginia Electric % Power Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. CLARK, R.A. Operating Reactors Branch 3. 2pp. 19424:073. 24X Fiche: 50-338.83/07/01.8307120302.
- --8307120308 Proposed Tech Spec changes reflecting reorganization in GA dept & addition of director emergency planning to nuclear operations dept.

  \* Virginia Electric & Power Co. 83/07/01. 28pp. 19424:075. 24x Fiche: 50-338,83/07/01,8307120302
- 8307120561 Suppl to 820624 application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs re mgt reorganization % records of annual audits for emergency & security plans.
  STEMART, M. L. Virginia Electric & Power Co. 83/07/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Openating Reactors Branch 3. 2pp. 19433:098 24X Fiche: 50-338, 83/07/01, 8307120561.
- --8307120566 Suppl to 820624 application to amend Tech Specs to reflect mgt reorganization. \* Virginia Electric & Power Co. 83/07/01. 28pp 19433:100. 24X Fiche: 50-338,83/07/01,8307120561.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390-317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re survoillance intervals in STS. Svc list encl.
  EISENHUT. D. Q. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp 19649:254. 24X
  Ficha: 50-000.83/07/06.8307060329.
- 8307120268 Forwards supplemental info in response to 830509 & 0615 Core Performance Branch questions re 597.8 F.RCS temp, per application to amend Licenses NPF-4 & NPF-7. Tables re correlation limits & core condition provided.

  SIEWART, W. L. Virginia Electric & Power Co. 83/07/06. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK, R. A. Operating Reactors Branch 3. Spp. 19424:154. 24X Fiche: 50-338, 83/07/06, 8307120268.
- B307120356 Suppls info to B21230 application for amend to Licenses NPF-4 & NPF-7 allowing operation at RCS temp of 597.8 F,per NRC B30427 & 0621 questions.

  STEMART.W.L. Virginis Electric & Power Co. B3/07/06. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reactors Branch 3. 4pp. 19427:082. 24X Fiche: 50-338, 83/07/06, 8307120356.
- --8307120361 Proposed Tech Specs re RCS temp. \* Virginia Electric & Power Co. 83/07/06. 7pp 17427:086. 24X Fiche: 50-338.83/07/06.8307120396
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. G. Division of Licensing. 83/07/08 Consolidated Edison Co. of New York. Inc. 35pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.

- 8307180097 Suppl to 781230 application for amend to Licenses NPF~4 & NPF~7 allowing operation at RCS average temp of 587 8 F Info reflects results of containment LCCA reanalysis performed by SSM.
  SIEWART, M.L. Virginia Electric & Power Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. CLARK, R.A. Operating Reactors Branch 4. 16pp. 19556-340. 24X Fiche: 50-338,83/07/11,8307180097.
- 8307180100 Submits final resolution of open items identified in draft technical evaluation rept dtd 830282 demonstrating conformance to NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants," Phase I. SIEMART. W.L. Virginia Electric & Power Co. 83/07/12. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK, R. A. Operating Reactors Branch 3. 4pp. 19597:005. 24X Fiche: 50-338,83/07/12,8307(80100.
- G. Inspection reports, IE Bulletins & correspondence
- B307060160 Informs of NRC review of 770809.1216.781027.811229.820527 & O812 requests for relief from inservice insp requirements of ABME Boiler & Pressure Vessal Code.Encl SER delineates items for which relief granted.

  CLARK R. Derating Reactors Branch 3 83/06/20. STEHART. H. L. Virginia Electric & Power Co. 3pp. 19299:214. 24x

  Fiche: 50-338.83/06/20.8307060160.
- --8307060174 Notice of granting of reliaf from ASME Section XI inservice testing (Insp) requirements. CLARK.R.A. Operating Reactors Branch 3. 83/06/20. 2pp. 19299-217. 24X Fiche: 50-338.83/06/20.8307060160.
- --8307060176 Safety evaluation granting requests for relief from inservice insp requirements.

   Diffice of Nuclear Reactor Regulation, Director. 83/06/20. 9pp. 19279: 219. 24x Fiche: 50-338.83/06/20. 8307060160.
- --8209200358 "North Anna Power Station Unit 1 Inservice Insp Program," technical evaluation rept.

   Science Applications, Inc. NRC-03-82-096. SAI-186-028-29. 82/097/17. NRC No Detailed Affiliation Given. 35pp. 19299: 228. 24X Fiche: 30-338.83/06/20.8307060160.
- 8307060042 Requests written interpretation of 10CFR20.202(b)(2) & 20.203(b) re posting of radiation areas, in light of notice of violation recently issued to util.

  STEWART.W.L. Virginia Electric & Power Co. 83/06/27, DENTON, H. R. Office of Nuclear Reactor Regulation, Director, CLARK, R. A. Operating Reactors Branch 3. 3pp. 19251:049, 24X

  Fiche: 50-338,83/06/27,8307060042.
- 8307220214 Forwards IE Insp Repts 50-338/83-15 & 50-339/83-14 on 830531-0601 No noncompliance noted.

  DANCE, H. C. Division of Project & Resident Programs. 83/06/28.

  STEMART, W. L. Virginia Electric & Power Co. 2pp. 19673: 337. 24X Fiche: 50-338.83/06/28.8307220214
- --8307220220 IE Insp Regts 50-338/83-15 & 50-339/83-14 on 830531-0601 No noncompliance noted Major areas inspected licensee program for keeping radiation doses AttARA.
  HOSEY, C. M. WRAY, J. R. BARR, K. P. Region 2, Diffice of Director.
  83/06/24. 5pp. 19673: 339. 24x Fiche: 50-338, 83/06/28, 8307220214.
- 8307220224 Forwards IE Insp Repts 50-338/83-11 & 50-339/83-11 on 830406-0505 No noncompliance nuted. But the state of the
- --8307220267 IE [hsp Repts 50-338/83-11 to 50-339/83-11 on 830404-0505. No noncompliance noted Major areas inspected refueling, surveillance to maint activities.LERs.license conditions to plant operations.

  SHYMLOCK.M.B. Region 2. Office of Director. JULIAN.C. Division of Project to Resident Programs. 83/07/01. 10pp. 19684:183. 24x Fiche 50-338,83/07/01,8307220224.
- 830.6270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York. Inc. 154pp. 19563:273. 24X Fiche: 50-000,83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JURDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12 Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche 50-000,83/07/12.8306270404.

- B306270406 IE Info Notice 83-4B. "Gaseous Effluent Releases of Radioactive I-[25 & I-[31 in Excess of NRC Limits." Svc list encl.
  TANLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York. Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270046.
- 8307180106 Forwards insp fees for Unit 1 from Mar 1982 Mar 1983 & Unit 2 from Apr 1982 Apr 1983, STEWART.W.L. Virginia Electric & Power Co. 83/07/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BARRY.L. Division of Accounting. ip. 19596:212. 24X Fiche: 50-338, 83/07/14, 8307180106.
- 8307170041 Forwards IE Safeguards Insp Repts 50-338/83-16 & 50-338/83-15 on 830626-30. No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. 83/07/15. STEMART.W.L. Virginia Electric & Power Co. 2pp. 19635:138. 24X Fiche: 50-338, 83/07/15, 8307170041.
- --8307190060 IE Safeguards Insp Repts 50-338/83-16 & 50-339/83-15 on 830626-30. No noncompliance noted Major areas inspected: security mgt, repts & records maint, physical barriers & protected areas. Details mitheld (ref 10CFR73.21). HALL. R. E. Region 2. Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/07/14. ip. 19635:140. 24X Ficha: 50-338, 83/07/15, 8307190041.
- R. Periodic operating reports & related correspondence
- 8307220192 Monthly operating repts for May 1983 W/830615 ltr. SCHMITENDORF.G., STEWART.W.L. Virginia Electric & Power Co. 83/06/03. HALLER.N.M. Office of Resource Management. Director. 14pp. 19683:324. 24X Fiche:50-338,83/06/03,8307220192.
- 5. Reportable occurrences, LERs & related correspondence
- 8307120504 LER 83-034/03L-0: on 830525, during Mode 1, one header of control room bottled air pressurized sys had lower than required pressure. Probably caused by leak from B bank of air bottles. Header repressurized, W/830622 ltr.
  HARRELL.E.M. Virginia Electric & Power Co. 83/06/22. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 17425: 019. 24X Fiche: 50-338, 83/06/22, 8307120504.
- 8307120299 LER 83-031/03L-0: on 830614. w/unit at 100% power, Fire Door S54/5 from emergency switchgear room to cable vault would not latch. Fire watch posted immediately. Caused by misaligned strike. Door repaired within 1 h. W/830630 ltr. HARRELL.E.M. Virginia Electric & Power Co. 83/06/30. D'REILLY, J. P. Region 2, Dffce of Director. 2pp. 19424: 071. 24X Fiche: 50-338,83/06/30,8307120299.
- B307120562 LER 83-042/03L-0: on B30606; vital bus i-I momentarily demongried while trying to clear inverter trouble alarm. Caused by operator error. Bus energized. W/B306400 ltr. HARRELLE. W. Virginia Electric & Power Co. 83/06/30. O'REILLY, J. P. Region 2: Office of Director. 3pp. 19433: 12B. 24X Fiche: 50-338, 83/06/30, 8307120562.
- 8307110433 LER 83-038/03L-0: on 830606 & 07. intermediate range channels N36 & N35 high neutron flux reactor trip setpoints found higher than Tech Spec limits. Caused by administrative error. Intermediate range setpoints reduced W/830706 ltr. HARRELL.E.W. Virginia Electric & Power Co. 83/07/06. 0'REILLY, J. P. Region 2. Office of Director. 4pp. 19382: 241. 24X Fiche: 50-338.83/07/06.8307110435.
- 8307220048 LER 83-043/03L-0:on 830620, during steady-state operation, greater than 12 step disagreement noted between individual rod position indication for Rods J-13 & G-13, Caused by instrument drift. RPI channels recallbr.W/830713 ltr. HARRELL.E.W. Virginia Electric & Power Co. 83/07/13. 0'REILLY, J. P. Region 2. 0ffice of Director. 2pp. 19683:300. 24X Fiche: \$0-338,83/07/13,8307220048.
- 8307290171 LER 83-045/03L-0: on 830628, containment average temp exceeded 105 F twice for less than 4 h.First temp spike caused by mechanical chiller tripping on high lube oil temp & second caused by loss of bearing cooling to chiller W/830720 ltr. HARRELL.E.W. Virginia Electric & Power Co. 83/07/20. U'REILLY, J. P. Region 2. Office of Director. 2pp. 19821: 042. 24x Fiche: 50-338, 83/07/20, 8307290171.
- 8307270187 Updated LER Bi-D62/03X-2: on Bi0722, util notified that 15 block walls in fuel bldg did not meet design requirements of IE Bulletin 80-11. Caused by refinement in masonry wall design. Block walls to be replaced. W/B30720 ltr. HARRELL.E.W. Virginia Electric & Power Co. 83/07/20. 0'REILLY, J. P. Region 2. Office of Director. 4pp. 17821: 107. 24X Fiche: 50-338,83/07/20,8307290189.

- DOCKET 50-337 NORTH ANNA POWER STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8307140068 Ack receipt of 830216 ltr & Rev 5 to guard training & qualification plans. Revs acceptable per 10CFR30. 54(p). Mod implementation will be examined in forthcoming insp rept. LEWIS, R. C. Division of Project & Resident Programs. 83/04/22. STEMART. W. L. Virginia Electric & Power Co. 1p. 19514:090. 24x Fiche: 50-000.83/04/22.8307140068
- 8307140353 Ack receipt of 830318 ltr re emergency exercise scheduled during June 1983. Scenario under review. Addi comments on exercise details will be made by telephone.

  DANCE,H.C. Division of Project & Resident Programs. 83/06/15.

  STEMART,W.L. Virginia Electric & Power Co. 1p. 19525:232. 24X Fiche: 50-338, 83/06/15.8307140353.
- 8307110157 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. ip. 19386:014. 24X Fiche: 50-338,83/06/24, 8307110159.
- --B307110165 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-1. 01 re emergency manager controlling procedure & EPIP-3.02 re activation of technical support ctr. Receipt form encl. \* Virginia Electric & Power Co. B3/04/20. NRC No Detailed Affiliation Given. ip. 19386:015. 24X Fiche: 50-338,83/06/24, B307110159.
- --8307110169 Public version of revised emergency plan implementing procedures, including Procedures EPIP-1.01 re emergency manager controlling procedure & EPIP-3.02 re activation of technical support ctr.
  PAXTON.G.J. Virginia Electric & Power Co. 83/04/20. 100pp. 19386:016. 24X Fiche: 50-338,83/06/24,8307110159.
- 8307110179 Releases public version of revised corporate emergency response plan.
  FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19386: 001. 24X Fiche: 50-000, 83/06/24, 8307110179.
- --8307110184 Public version of Rev 3 to corporate emergency response plan.W/830614 ltr.
  8TEWART.W.L. Virginia Electric & Power Go. 83/05/15.
  0'RELLLY.J.P. Region 2. Office of Director. 6pp. 19386:002. 24X
  Fiche: 50-000.83/06/24.8307110179.
- B307120302 Forwards suppl to proposed Tech Spec changes re 820624 application to amend Licenses NPF-4 & NPF-7 reflecting reorganization in GA dept & addition of director emergency planning to nuclear operations dept.

  BTEWART.W.L. Virginia Electric & Power Co. B3/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 17424:073. 24X Fiche: 50-338, 83/07/01. 8307120302.
- --8307120308 Proposed Tech Spac changes reflecting reorganization in GA dept & addition of director emergency planning to nuclear operations dept.
  \* Virginia Electric & Power Co. 83/07/01. 28pp. 19424:075. 24x Fiche: 50-338, 83/07/01, 8307120302.
- 8307120386 Forwards procedures generation package for emergency operating procedures in response to NUREG-0737, Suppl 1 (Generic Ltr 82-33).
  STEMART.W.L. Virginia Electric & Power Co. 83/07/01. DENTON.H.R Office of Nuclear Reactor Regulation, Director. 13pp. 19426:209. 24X Fiche: 30-000, 83/07/01, 8307120386.
- B307120561 Suppl to B20624 application for amend to Licenses NPF-4 & NPF-7; changing Tech Specs re mgt reorganization & records of annual audits for emergency & security plans.

  STEWART, W. L. Virginia Electric & Power Co. 83/07/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19433:098. 24X Fiche: 50-338, 83/07/01, 8307120561.
- 8307190041 Forwards IE Safeguards Insp Repts 50-338/83-16 & 50-338/83-15 on 830626-30. No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. 83/07/15. STEWART.W.L. Virginia Electric & Power Co. 2pp. 19635:138. 24X Fiche: 50-338,83/07/15,8307190041.
- --8307190060 IE Safeguards insp Repts 50-338/83-16 & 50-339/83-15 on 830626-30. No noncompliance noted Major areas inspected: security mgt.repts & records maint physical barriers & protected areas. Details witheld (ref 10CFR73.21).

  HALL.B.L. Region 2. Office of Director. 83/07/14. 1p. 19635:140. 24X Fiche: 50-338.83/07/15.8307190041.

- 8307270289 Forwards response to 830322 comments re inconsistencies in Rev 8 to security plan & itr of understanding between util & NRC Encls withheld (ref 100FR2.790).

  STEWART.W L. Virginia Electric & Power Co. 83/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. lp 19768:358. 24: Fiche. 90-338.83/07/22.8307270289
- G Adjudicatory correspondence
- 8307120053 Advises of HJ McGurren reassignment from Hearing Div I to Hearing Div II % transfer of North Anna case from Hearing Div I to Hearing Div II.effective 830712. CHRISTERBURY.E. Hearings Division. 83/07/08. RUTBERG, J. Hearing Branch 2 TREBY.S. Hearing Branch 1 1p 19423:152 24X Fiche: 50-338,83/07/08,8307120053.
- 8307150299 Advises that Commission 830630 Memorandum & Order CLI-83-19 vacated ALAB-687 to extent inconsistent w/decision. ASLB cited ALAB-687 in 821203 & 830610 memoranda.

  WOLFE:8.J. Atomic Safety and Licensing Board Panel 83/07/14.

  MAUPIN.M.W. Hunton & Williams. MCOURREN.H.J. Hearing Branch 1.

  COLEMAN.J.M. Beveridge, Fairbanks & Diamond. 1p. 19538:304. 24X

  Fiche: 50-338,83/07/14,8307:50299.
- 8307180019 Responds to ASLB 830610 order for estimated dates of issuance of SERs & EIAs for proposed actions to receive & store Surry spent fuel at North Anna & expand capacity of North Anna fuel pool. Documents to be issued at end of yr. MCGURREN.H.J. Hearing Branch 1. 83/07/14. MDLFE.S.J. MLINE.J., FERGUSGIN.G.A. Atomic Safety and Licensing Board Panel. 2pp. 19560:152. 24X Fiche: 50-338.83/07/14,8307180019.
- J. Insurance & indemnity information
- 830713006B Forwards Endorsements 70.53.32 & 43 to NELIA & MAELU Policies NF-186.MF-57.MF-76 & NF-240. respectively. Endorsements 1-6 to NELIA Certificates N-27 & N-28 & Endorsements 1-3 to MAELU Certificates M-27 & M-28. PAINTER.B.F. Virginia Electric & Power Co. 83/07/05 DINITZ.C. Antitrust & Economic Analysis Branch (Utility Finance). 53pp. 19474:150. 24X Fiche: 50-280.83/07/05.8307130068.
- P Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs % holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list enci.
  EISENHUT, D. 9. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche:50-000,83/06/03.
- 8307050288 Responds to 830512 itr informing NRC that License Condition 2. C(21)(i)(iv) re containment high-range radiation monitors, satisfied per NUREG-0737, Item II.F. I. In-situ calibr of containment high-range monitors verified CLARK.R. A. Operating Reactors Branch 3. 83/06/15. STEWART, W. L. Virginia Electric & Power Co. 2pp. 19263.219. 24X Fiche: 50-339, 83/06/15. 8307050288.
- B30709027B Responds to B30519 itr informing NRC that License Conditions 2. C(15)(h)(2) & 2. C(15)(h)(4) re diese) generator reliability completed Verification of license conditions will be contained in forthcoming insp rept. CLARK, R. A. Operating Reactors Branch 3. B3/06/15. STEWART, W. L. Virginia Electric & Power Co. 2pp. 19263:227. 24X Fiche: 50-339, D3/06/15. 830705027B.
- 8307010090 Advises of changes to NPDES permit & state certification Section 401. Changes result from study to be done re impact of thermal discharges on biota in Lake Anna List of interim actions for state water control board to initiate encl STEWART. M. L. Virginia Electric & Power Co. 83/06/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 29p 19124:355. 24X Fiche: 50-338, 83/06/27, 8307010090
- 8307250451 "North Anna Unit 2.Cycle 3 Startup Physics Tost Rept." W/830719 ltr.
  STEWART.W L., MANN, B.D., RUFTY, S.J. Virginia Electric & Power Co-VEP-NOS-4. 83/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. 64pp. 19702:094. 24X Fiche: 50-339, 83/06/30. 8307250451.
- 8307120302 Forwards suppl to proposed Tach Spec changes re 820624 application to amend Licenses NPF-4 & NPF-7 reflecting reorganization in GA dept & addition of director ~ emergency planning to nuclear operations dept.

  STEWART.W.L. Virginia Electric & Power Co. 83/07/01. DENTON.H.R Office of Nuclear Reactor Regulation. Director CLARK.R.A. Operating Reactors Branch 3. 2pp. 19424.073. 24x Fiche. 50-338.83/07/01.8307120302.

- --8307120306 Proposed Tech Spec changes teflecting reorganization in GA dept & addition of director emergency planning to nuclear operations dept.

   Virginia Electric & Power Co. 83/07/01. 28pp. 19424:075. 24X Fiche 50-338.83/07/01.8307120302
- 6307120361 Suppl to 820624 application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs re mgt reorganization & records of annual audits for emergency & security plans.
  STEMARTH. L. Virginia Electric & Power Co. 83/07/01 DENTON.H.R. Office of Nuclear Reactor Regulation. Director CLARK.R. A. Operating Reactors Branch 3 2pp. 19433-098. 24X
  Fiche: 50-338.83/07/01.8307120561.
- --8307120566 Suppl to B20624 application to amend Tech Specs to reflect mgt reorganization. 4 Virginia Electric & Power Co. B3/07/01. 28pp. 19433:100. 24X Fishe. 50-03B, 83/07/01. 8307120561.
- 8305270397 Generic Ltr 83-25 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT.D.G. Division of Licensing 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24% Fiche. 50-000,83/07/05,8305270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669;254. 24X Fiche: 56-000.83/07/06.8307060329.
- B307120269 Forwards supplemental info in response to B30509 & 0615 Core Performance Branch questions re 587.8 F RCS temp.per application to amend Licenses NPF-4 & NPF-7. Tables recorrelation limits & core condition provided.

  SIEWART.W.L. Virginia Electric & Power Co. B3/07/06. DENTON.W.R. Office of Nuclear Reactor Regulation. Director. CLARK.R.A. Operating Reactors Branch 3. Spp. 19424:154. 24X Fiche: 50-338.83/07/06.8307120268.
- B307120356 Suppls info to 821230 application for amend to Licenses NPF-4 & NPF-7 allowing operation at RCS temp of 587.8 F.per NRC 830427 & 0621 questions.
  STEWART.W L. Virginia Electric & Power Co. 83/07/06. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. CLARK, R. A. Operating Reactors Branch 3. 4pp. 19429:082, 24X Fiche: 50-338.83/07/06.8307120356.
- --8307120351 Proposed Tech Specs re RCS temp.

  \* Virginia Electric & Power Co. 83/07/06. 9pp. 19429:086. 24X
  Fiche 50-338.83/07/06.8307120356.
- 8307120441 Requests deletion of proposed change to partial power multiplier on Fry & Issue O.3 FNH part power multiplier setpoints consistent w/582.8 F operation for facility.per 821208 application for amend to License NPF-7. STEHART.W.L. Virginia Electric & Powor Co. 83/07/06. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. Spp. 19425.333. 24X. Fichal 20-339, 82/07/06, 82/07/20441.
- #307096187 OF DELTA LET MG-06 to \$11 licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT. D G. Division of Licensing. #3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000-83/07/08.8307080169.
- 8307180097 Suppl to 781230 application for amend to Licenses NFF-4 & NFF-7 allowing operation at PCS average temp of 387.8 F info reflects results of containment LUGA reanalysis performed by StM.
  SIEWART.W L. Virginia Electric & Power Co. 83/07/11. DENTON.H.R. Office of Nuclear Reactor Regulation. Birector. CLARK.R. A. Operating Reactors Branch 4. 16pp. 19556:340. 24X
  Fiche: 50-338.83/07/11.8307180047.
- B307180100 Submits final resolution of open items identified in draft technical evaluation rept of 830222 demonstrating conformance to NURCG-0612, "Control of Heavy Loads at Nuclear Power Plants," Phase 1.

  STEMART.W.L. Virginia Electric & Power Co. 83/07/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reacturs Branch 3 4pp. 19557.005. 24X
  Fithe: 50-338.83/07/12.8307180100.

- Q. Inspection reports, IE Bulletins & correspondence
- 8307060042 Requests written interpretation of 10CFR20.202(b)(2) & 20.203(b) re-posting of radiation areas, in light of notice of violation recently issued to util.

  STEWART.W.L. Virginia Electric & Power Co. 83/06/27. DENTON, H. R. Office of Nuclear Reactors Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp. 19251:049, 24X
  Fiche: 50-338, 83/06/27, 8307060042.
- B307220214 Forwards IE Insp Repts 50-338/83-15 & 50-339/83-14 on B30831-0601. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. B3/06/28. STEWART. N. L. Virginia Electric & Power Co. 2pp. 19673: 337. Fiche: 50-338. B3/06/28. B307220214.
- --830722020 IE Insp Repts 50-338/83-15 & 50-339/83-14 on B30531-0601.No nancompliance noted Major areas inspected licensee program for keeping radiation doses ALARA. HOSEY.C.M., MRAY.J.R., BARR.K.P. Region 2, Office of Director. 83/06/24. 5pp. 19673:339. 24X Fiche:50-338.83/06/28.8307220214.
- 8307220224 Forwards IE Insp Repts 50-338/83-11 & 50-339/83-11 on B30406-0505. No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. 83/07/01.81EWART.W.L. Virginia Electric & Power Co. 2pp. 19684; 181. Fiche: 50-338, 83/07/01, 8307220224.
- --8307220267 IE Insp Repts 50-338/83-11 & 50-337/83-11 on 830406-0505. No noncompliance noted. Major areas inspected: refueling, surverilance & maint activities. LERs. license conditions & plant operations.

  SHYMLOCK. M. B. Region 2. Office of Director. JULIAN. C. Division of Project & Resident Programs. 83/07/01. 10pp. 19684: 183. 24% Fiche. 50-338, 83/07/01. 8307220224.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11.8306270401.
- B306270404 IE Info Notice B3-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl. TAYLOR, J. M. encl. TAYLOR, J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- 8307180106 Forwards insp fees for Unit 1 from Mar 1982 Mar 1983 & Unit 2 from Apr 1982 Apr 1983.
  STEWART.W.L. Virginia Electric & Power Co. 83/07/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BARRY, L. Division of Accounting. 1p. 19856:212. 24X Fiche: 50-338,83/07/14,
- 8307190041 Forwards IE Bafeguards Insp Repts 30-338/83-16 & 50-338/83-15 on 830626-30 No noncompliance noted. DANCE/M.C. Division of Project & Resident Programs. 83/07/1 STEMART.W.L. Virginia Electric & Power Co. 2pp. 19635:138. Fiche: 50-338,83/07/15,8307190041.
- -8307190060 IE Safeguards Insp. Repts 50-338/83-16 & 50-339/83-15 on 830626-30. No noncompliance noted Major areas inspected: security mpt. repts & records, maint, physical barriers & protected areas. Details withold (ref 100678.21).

  HALL, B. L. Region 2, Office of Director. McGUIRE, D. R. Division Emergency Preparedness & Materials Safety. 83/07/14. 1p. 19635:140. 24X Fiche: 50-338/83/07/15, 8307190041. Division of
- R. Periodic operating reports & related correspondence
- 8307220192 Monthly operating repts for May 1983 W/830615 ltr. SCHMITENDORF.Q., STEWART.W.L. Virginia Electric & Power Co. 83/06/03. HALLER.N.M. Office of Resource Management, Director. 14pp. 19683:324. 24X Fiche 50-338,83/06/03,8307220192.
- S. Reportable occurrences, LERs & related correspondence
- 8307290324 Forwards AEOD technical review rept, "Design Deficiency in Control Circuits of Feedwater Isolation Valves & BIT Recirculation Valves." No further AEOD actions contemplated. CHIRAMAL.M. Reactor Operations Analysis Branch. 83/06/13. SEYFRIT,K.V. Reactor Operations Analysis Branch. 1p. 19858:148. 24X Fiche: 50-339,83/06/13,8307290324.

- --8307290330 "Design Deficiency in Control Circuits of Feedwater Isolation Valves & BIT Recirculation Valves," AECD tachnical review rept. CHIRAMAL.M. Reactor Operations Analysis Branch. 83/06/13. 3pp 19859:149. 24X Fiche: 50-339,83/06/13,8307290324.
- 8307120254 LER 83-045/03L-0: on 830614. Fire Door S71-18, between Emergency Diesel Generator Room 2H & turbine bldg, would not latch & lock. Caused by stuck latch. Latch adjusted & lubricated. Door designs modified M/830622 ltr.

  MARRELL.E.M. Virginia Electric & Power Co. 83/06/22. 0'REI Region 2, Office of Director. 2pp. 19419: 358. 24X Fiche: 50-339, 83/06/22, 8307120254.
- 8307120491 LER 83-044/03L-0: on 830526, during Mode 3, one recirculation valve on each of two casing cooling pumps found open. Caused by procedure inadequacy, Valves closed immediately. Maint procedure will be revised. W/830623 ttr.
  HARRELL.E.W. Virginia Electric & Power Co. 83/06/23. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19425:025. 24X
  Fiche: 50-339, 83/06/23, 8307120491.
- 8307120074 LER 83-047/03L-0: on B30530, emergency diesel generator 2J tripped on high crankcase pressure during surveillance testing. Cause not determined. Diesel tosted satisfactorily. W/830628 ltr.
  HARRELL.E.W. Virginia Electric & Power Co. 83/06/28. O'REILLY, Region 2, Office of Director. 2pp. 19423:076. 24X Fiche: 50-339, 83/06/28, 8307120094. 83/06/28. D'RETLLY. J.P.
- B307110375 LER B3-04B/03L-0: on B30606 & 17. Intermediate range channels N35 & N36 high neutron flux reactor trip setpoints exceeded Tech Spec requirements. Caused by administrative error. Setpoints reduced, W/830706 ltr. HARRELL.E.M. Virginia Electric & Power Co. B3/07/06. O'REILLY, J. P. Region 2. Dffice of Director. 4pp. 19380: 331. 24% Fiche: 50-339, B3/07/06. B307110375.
- 8307220118 LER 83-043/03L-0: on 830620-27, during startup from Mode 3 & subsequent 100% power operation, 34 rod position indicators deviated greater than 12 steps from group demand position.

  Caused by temp variations. W/830707 ltr.

  HARRELL, E.W. Virginia Electric & Power Co. 83/07/07. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19684: 031. 24%

  Fiche: 50-339, 83/07/07, 8307220118.
- 3307220123 LER 83-050/03L-0: on 830613. w/unit at 100% power, emergency diesel generator 2J tripped during surveillance testing. Caused by high jacket coolant temp. Setpoint found lower than required. Setpoint recalifer satisfactorily. W/830707 ltr. HARRELL.E.W. Virginia Electric & Power Co. 83/07/07. G'REILLY, J. P. Region 2, Office of Director. 4pp. 19684:037. 24X Fiche: \$0-337, 83/07/07, 8307220123.
- 3307290058 LER 83-052/03L-0: on 830628, individual rod position indication for channels F-04, D-10 & M-04 deviated from group demand position by greater than 12 steps. Caused by instrument drift. Channels recatibr. W/830720 ltr.
  HARRELL.E.W. Virginia Electric & Power Co. 83/07/20. 0'REI Region 2. Office of Director. 2pp. 19821.076. 24X
  Fiche: 50-339, 83/07/20, 8307270058. 83/07/20. D'REILLY, J. P. 074. 24X
- 1307290073 Updated LER 83-038/03X-1: on 830303, RHR pump B suction lost during transfer of water from RCS to refueling storge tank.

  Caused by RCS being pumped below operating limit.RCS refilled & RHR pump suction restored.W/830720 ltr.

  HARRELL.E.W. Virginia Electric & Power Co 83/07/20. O'REILLY, J. F. Region 2, Dffice of Director. 3pp. 19822:172. 24X Fiche: 90-339,83/07/20,8307290073. O'REILLY, J. P.
- ISO7290187 LER 83-051/03L-0: on 830627 & 0702,RC8 subcoolant margin monitor A failed to operate correctly. Cause on 830627 due to failed low level data board & on 830702 due to failed computation board. Monitor will be relocated. W/830720 ltr. HARRELL.E.W. Virginia Electric & Power Co. 83/07/20. O'REILLY. Region 2, Uffice of Director. 2pp. 19821: 148. 24X Fiche: 50-339, 83/07/20, 8307290187. O'REILLY, J. P.
- OCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2 . Application/construction stage documents & correspondence
- 306270395 Generic Ltr 83-24 to all BWR applicants for QL & holders of QLs for Grand Gulf-LaSalle & Susquehama re TMI Yask Action Plan Item I.G. 1, "Special Low Power Testing & Training & Recommendations for BWRs." Svc list encl. EISENHUT. D.G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche:50-000.83/06/29, 8306270395.

- 8307010169 Forwards Amend 49 to application for OL & Amend 49 to PSAR LANDORAF,L.C. LeBoeuf, Lamb, Leiby 2 MacRee. 83/06/30. DENTON Office of Nuclear Reactor Regulation, Director. 1p. 19169:280. Fiche 50-341,83/06/30,8307010169. DENTON, H
- --8307010173 Amend 49 to application for OL.
  HEIDEL.C.M. Detroit Edison Co. 83/06/30 lp. 19169:281. 24X
  Fiche.50-341,83/06/30,8307010169
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp 19390.317. 24x Fiche: 90-000,83/07/05.8306270397
- 8307130301 Notification of B30707 meeting w/util in Bethesda.MD to discuss design criteria for instrumentation.control & power cables of standby liquid control sys. LYNCH.M.D. Licensing Branch 1. 83/07/05. YOUNGBLOOD.B.J. Licensing Branch 1. 3pp. 19525:352. 24X Fiche:50-341,83/07/05, 8307130301.
- 830704032? Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19649:254. 24x Fiche: 50-000.83/07/06.8307060329.
- 8307130297 Reissued notification of 830707 meeting w/util in Bethesda, MD to discuss design criteria for instrumentation control & power cables of standby liquid control sys Meeting time & location changed. LYNCH, M.D. Licensi Licensing Branch L. 8307130297. Licensing Branch L 83/( ranch L. 3pp. 19511:116
- 8307120239 Forwards Certificate of Svc indicating that Amend 49 to amended b substituted application for licenses served on listed persons.

  MATERS,B.R. Detroit Edison Co. 83/07/07 Office of Nuclear Reactor Regulation, Director. 3pp. 19423-197. 24X Fiche: 50-341,83/07/07,8307120239
- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York. Inc. 38pp 17669.269. 24X Ficha: 50-000.83/07/08.8307080169.
- 8307210028 Advises that methodology for establishing setpoints for Tech Specs will be provided by 830829. Methodology could be gameric Feasibility of response by Licensing Review Group to NRC 830414 thr under consideration.

  TAUBER, H. Detroit Edison Co. 83/07/15. YOUNGBLOOD, B. J. Licens Branch 1. 1p. 19668:348. 24X Fiche:50-341.83/07/15.8307210028.
- B307270493 Notification of B30721 meeting w/util in Bethesda.MD to discuss applicant proposal to form independent safety evaluation group.
  LYNCH.M.D. Licensing Branch 1 83/07/15 YOUNGBLOOD.B.J. Licensing Branch 1 8388:286. 24X Fiche:50-341.83/07/15.8307290493.
- B307270R07 Forwards "Environ Qualification of Safety-Related Electrical Equipment for Harsh Environ:" Vols 1-3.in response to NUREG-0588.NRC site verification visit expected in late Jul or Aug. Response to 10CFR30.49 will be provided. TAUBER.H. Detroit Edison Co. B3/07/19. YOUNGBLOOD, B. J. Licensing Branch 1. 1p. 19770:148. 24X Fiche: 50~341.83/07/19.8307270207.
- -8307270215 "Environ Qualification of Safety-Related Electrical Equipment for Harsh Environ," Vols 1-3. including program description & action plans, summary sheets & yestification for interim operation, in response to NUREG-0388. # Detroit Edison Co. 83/07/31. 1915pp 19770:149. 24X Fiche: 50-341,83/07/19,8307270207.
- 8307280487 Summary of B30707 meeting w/utils.GE & KMC.Inc in Bathesds.MD re standby liquid control sys. LYNCH.M.D. Licensing Branch 1. 83/07/19 Licensing Branch 1. 10pp. 19826:052. 24X Fiche: 50-341.83/07/19.8307280487

- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 9307120278 Forwards Rev O to "Enrico Fermi Atomic Power Plant, Unit 2: Evaluation of Safety Relief Valve Piping & Torus Attachment Piping for Effects of Site-Specific Earthquake," in response to SER.NNEGE-0798
  TAUBER. H. Detroit Edison Co. 83/07/08 YOUNGBLOOD, B. J. Licensing Branch 1 ip. 19424: 006. 24X Fiche: 90-341, 83/07/08, 8307120278.
- F. Security, medical, emergency & fire protection plans
- 8307050107 Forwards rev to physical security plan, describing temporary bldgs within security perimeter to be erected by fuel loading Rev withheld.

  TAUBER, H. Detroit Edison Co. 83/06/29. Office of Nuclear Reactor Regulation. Director. 1p. 19199:343. 24x Fiche: 50-341, 83/06/29, 8307050107.
- B307060099 Forwards final SALP Rept 50-341/83-13 for Oct 1981 Sept 1982. Positive performance noted in areas of preoperational test programs, bmergency preparadness to licensing activities.

  KEPPLER.J. G. Region 3. Office of Director. 83/06/29. WELLS.D.A. Datroit Edison Co. 1p. 19251:289. 24x Fiche: 50-341.83/06/29, 8307060099.
- ~-8307060106 Final SALP Rept 50~341/83~13 for Oct 1981 Sept 1982. \* Region J, Office of Director. 83/06/29. 31pp. 19251:290. 24X Fiche: 50~341,83/06/29,8307060099.
- --8307060116 Forwards summary of SALP Board findings & preliminary SALP rept for Oct 1981 Sept 1982, for comment within 20 days of SALP meeting scheduled for 830120 at Region III ofcs. W/o encl rept. HIND, J. A. Region 3, Office of Director. 83/01/14, WELLS, D. A. Detruit Edison Co. 4pp. 19251.317, 24X Fiche: 50-341, 83/06/29, 9307060099.
- B307060362 Provides addl info re alternate emergency operations facility, per NRC request Wayne/Monroe Div headquarters, located \$2.5 miles from site, selected for available communications & space.

  TAUDER, H. Detroit Edison Co. B3/06/29. YOUNGBLOOD, B. J. Licensing Branch 1. 1p. 19234:001. 24X Fiche: 90-341, 83/06/29, 8307060362.
- G. Adjudicatory correspondence
- 8307080302 Answer opposing Citizens for Employment & Energy 830622 petition for review of ASLAB 830602 decision ALAB-730, affirming ASLB 821027 Initial Decision LBP-82-95 re OL issuance. Petition should be denied Certificate of Svc encl. VOI07.H.H. Detroit Edison Co. VOI07.H.H. LeBoeuf, Lamb, Leiby & MacRae. 83/07/07. Commissioners. 13pp. 19350:168. 24X Piche: 50-341, 83/07/07.8307080302.
- 8307110047 Response opposing Citizens for Employment & Energy 830622 petition for Commission review of ALAB-730 affirming LBP-82-76 which ruled on emergency planning & late-filed contentions. Certificate of Svc encl. MODDHEAD, C. P. Hearing Branch 4, 93/07/07. Commissioners. 12pp. 19374: 325. 24X Fiche: 50-341.83/07/07, 8307110047.
- 8307130227 Forwards ASLAB decision ralemergency planning issues raised by Citizens for Energy & Employment Decision on Citizens 830622 petition for Commission review of ASLAB decision will be made available. W/o entl.
  WOODHEAD. C. P. Hearing Branch 4. 83/07/11. PERRY. S. Federal Energency Management Agency. 1a. 19474: 347. 24X
  Fiche: 50-341.83/07/11.8307130227.
- 8307250397 Order extending time until 830822 For Commission to act to review ALAB-730. CHILK, 8.J. Diffice of the Secretary of the Commission. 83/07/22. Commissioners. ip. 19703:242. 24X Piche: 50-341,83/07/22. 8307250357.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010167 Forwards Amend 49 to application for CL & Amend 49 to FBAR.
  LANDBRAF,L.C. LeBoeuf, Lamb, Leiby & MacRae. 83/06/30 DENTUN,H.
  Deffice of Nuclear Reactor Regulation, Director 1p. 19169:280. 24x
  Fiche:50-341,83/06/30,8307010169.

- --B307010173 Amend 49 to application for OL. HEIDEL.C.M. Detroit Edison Co. B3/06/30. lp. 19169:281. 24x Fiche: 50-341.83/06/30.8307010169.
- --8307010175 Amend 49 to FSAR.

  # Detroit Edison Co. -83/06/30. 161pp. 19169: 282. 24x
  Fiche: 50-341, 83/06/30, 8307010169.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307080286 Forwards IE Insp Rept 50-341/83-14 on 830531-0603 & notice of violation.
  LITTLE: W.S. Region 3, Office of Director. 83/06/24, WELLS, D. A. Batroit Edison Co. 2pp. 19351:193. 24X Fiche: 50-341, 83/06/24, 8307080286.
- --8307080289 Notice of violation from insp on 830531-0603. LITTLE,W.S. Region 3. Office of Director. 83/06/24. 2pp. 19351: 193. 24X Fiche: 50-341,83/06/24,8307080286.
- --8307080292 IE Insp Rept 50-341/83-14 on 830531-0603. Noncompliance noted: failure to comply w/ASME Code requirements during liquid penetrant exams.

  WARD, K. D., CILIMBERG. R. L., KEATING, D. E. Region 3, Office of Director. 83/06/24, 13pp. 19351:197. 24X Fiche: 90-341,83/06/24, 8307080286.
- 8307060099 Forwards final SALP Rept 50-341/83-13 for Oct 1981 Sept 1982. Positive performance noted in areas of preoperational test programs, emergency preparedness & licensing activities.

  KEPPLER J. G. Region 3, Office of Director. 83/06/29, WELLB, D. A. Detroit Edison Co. 1p. 19251: 289. 24X Fiche: 50-341, 83/06/29, 8307060099.
- --8307060106 Final SALP Rept 50-341/83-13 for Oct 1981 Sept 1982, \* Region 3, Office of Director. 83/06/29. 31pp. 19251:290. 24X Fiche: 50-341,83/06/29,8307060099.
- --8307060116 Forwards summary of SALP Board findings & proliminary SALP rept for Dct 1981 Sept 1982, for comment within 20 days of SALP meeting scheduled for 830120 at Region III afcs. W/o encl rept.
  HIND.J.A. Region 3. Office of Director. 83/01/14. WELLS, D. A. Detroit Edison Co. 4pp. 19251:317. 24x Fiche: 50-341, 83/06/29, 8307060099.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Rectrculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- B304270404 IE Info Notice B3-47, "Failure of Hydraulic Bnubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307280384 Forwards IE Insp Rept 50-341/83-07 on 830315-0503 & notice of violation.

  8PE58ARD, R. L. Division of Engineering, 83/07/13, WELLS, D. A. Detrait Edison Co. 2pp. 19794: 067. 24X Fiche: 50-341, 83/07/13, 83/07/13
- --8307280388 Notice of violation from insp on 830315-0503. SPESBARD.R.L. Division of Engineering. 83/07/13. 3pp. 19794:069. 24X Fiche: 50-341.83/07/13.8307280384.
- --B3072B0395 IE Insp Rept 50-341/83-07 on 830315-0503. Nancompliance noted: failure to take followup action to determine effectiveness of decision change distribution program & to follow procedure.

  BARRETT.P.A., NAIDU,K.R., MENDEZ.R. Region 3, Office of Director. 83/07/12. 27pp. 19796:072. 24X Fiche: 50-341,83/07/13,8307280384.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.

#### S. Reportable occurrences. LERs & related correspondence

- 8307060064 Final deficiency rept re Agastat relay bases remaining open when relays should be closed Initially reported on 791109. Caused by mounting base sockets being pushed away from misaligned relay pins. Relays replaced. WELLS, D. A. Detroit Edison Co. 83706/10. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19250.279. 24X Fiche: 50-341, 83/06/10, 82270/06/4 8307040064
- B307060016 Final Deficiency Rept Item 95 re Comsip. Inc post-LOCA containment gas monitoring sys. Initially reported on 830524. Item not reportable per 10CFR90. 55e since sys not in use at facility. Also reported per Part 21. WELLS, D.A. Detroit Edison Co. B3/06/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 19251: 035. 24X Fiche: 50-341, 83/06/24, 8307060016.
- 8307060137 Interim Deficiency Rept Item 84 re security sys & fire detection equipment mounted from block walls, contrary to IE Bulletin 80-11. Initially reported on 82:213. Architectural/civil group conducting final analysis of block walls. WELLS, D. A. Detroit Edison Co. 83/06/28. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19252:246. 24X Fiche: 50-341, 83/06/28, 8307060137.

#### DOCKET 50-344 TROJAN NUCLEAR PLANT

#### F. Security, medical, emergency & fire protection plans

- 8307060039 Submits addl info in support of 830427 fire protection examption request for 45-ft elevation of fuel & auxiliary bldgs. W/one oversize drawing. Aperture card is available in PDR.
  BROCHL. D. J. Portland General Electric Co. 83/06/30. CLARK. R. & Operating Reactors Branch 3. Upp. 19239: 246. 24X Fiche: 50-344, 83/06/30, 8307060039.
  - 83/06/30. CLARKIR.A. 46. 24X
- 8307180049 Forwards safety evaluation of NRC 830620-24 App R audit findings. Adequate fire protection features will be installed prior to Fuel Cycle 6. Further App R exemption requests forthcoming.

  BRUEHL, D. J. Portland General Electric Co. 83/07/08. MARTIN, J. B. Region 5. Office of Director. 28pp. 19556: 272. 24X Fiche: 50-344, 83/07/08, 8307180049.
- 8307270037 Forwards exemption from fire protection requirements for equipment important to safe shutdown. CLARK.R.A. Operating Reactors Branch 3, 83/07/08, WITHERS, B. D. Portland General Electric Co. 3pp. 19811: 248, 24X Fiche: 50-344,83/07/08,8307270037.
- --8307270042 Exemption from fire protection requirements for equipment important to safe shutdown.
  PURPLE.R. A. Division of Licensing. 83/07/08. Portland General Electric Co. App. 19811:231. 24X Fiche: 30-344,83/07/08,8307270037.
- 8307270267 Informs that 811203 evaluation of design plan for emergency response facilities based on NUREG-0814 not applicable per issuance of Suppl 1 to NUREG-0737.

  CLARK,R.A. Operating Reactors Branch 2. 83/07/11. WITHERS,B.D. Portland General Electric Co. 2pp. 19811:132. 24X

  Fiche: 50-344,83/07/11,8307270267.
- B307210223 Forwards fire protection exemption request re reactor coolant pump oil collection sys & addl technical justification for App R audit findings. BROEHLD. J. Portland General Electric Co. B3/07/15. CLARK.R. Operating Reactors Branch 3. 10pp. 19644:051. 24X Fichs: 50-344,83/07/15,8307210223. B3/07/15. CLARK, R. A.

## H. General correspondence

- 8307190489 Responds to 830620 itr & confirms 830627 telcon re writing style requirements.

  TRAMMELL.C.M. Operating Reactors Branch 3. 83/07/05. ROUSE, E. A. Portland General Electric Co. ip. 19651;354. 24X Fiche: 50-344, 83/07/05, 8307190485.
- J. Insurance & indemnity information
- 8307260400 Forwards Endorsement 61 to NELIA Policy NF-225.
  JOHANBEN,E. Portland General Electric Co. B3/07/19. SALTZMAN,J.
  Office of State Programs, Director. 2pp. 19731:346. 24X
  Fiche:30-344,83/07/19.8307260400.

## K. Utility Final Safety Analysis Report (FSAR) & amends

- 8307220085 Forwards Amend 1 to updated FSAR, including changes made to facility or procedures, safety evaluations supporting requested license amends & analyses of new safety issues. BROEHL. D. J. Portiand General Electric Co. 83/07/20. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17680:303. 24X Fiche: 50-344, 83/07/20, 8307220085.
- --B307220087 Forwards Amend 1 to updated FSAR. Ack of receipt requested.
  Description of changes encl.
  TODD. A. J. Portland General Electric Co. B3/07/20. Office of Nuclear Reactor Regulation. Director. 8pp. 19680: 305. 24X
  Fiche: 50-344.83/07/20.8307220085.
- --8307220091 Amend 1 to updated FSAR.

   Portland General Electric Co. 83/07/31, 976pp, 19680:313.
  24X Fiche:50-344,83/07/20,8307220085.
- P. Operating license stage documents & correspondence
- B30A0A0070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PWRs re safety avaluation of "Emergency Response Guidelines." Byo list encl.
  EISENHUT, D. G. Division of Licensing. 83/04/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, B3/04/03, B30A0070 Electric Co. 8306060070.
- 8307110616 Monthly notice of amends to OLs involving NSHC issued since 830523. CLARK, R. A. Operating Reactors Branch 3, 83/06/14, 26pp. 19391:152. 24X Fiche: 50-000, 83/06/14, 8307110616.
- B307060078 Bubmits schedule changes for NUREO-0737. Item II. B. 3,
  "Post-Accident Sampling Capability." Post-accident sampling
  sys will not be fully operational by B30701. Clarifications
  of util B21217 responses encl.
  BROEHL. D. J. Portland General Electric Co. B3/06/28. EISENHUT, D. Q.
  Division of Licensing. 5pp. 19238: 241. 24X Fiche: 50-344.83/06/28,
  B307060078.
- 8307ii0003 Forwards addl info re potential mudflows from hypothetical failure of Spirit Lake blockage, Based on results, max Columbia River flood levels will be below Elevation 39 ft mean sea level.

  BROEHL.D.J. Portland General Electric Co. 83/07/01. CLARK, R. A. dperating Reactors Branch 3. 13pp. 17974: 226. 24X Fiche: 50-344,83/07/01,8307110003.
- 8307110143 Forwards list of post-accident sampling sys items identified during functional tasting requiring resolution.per. NUREO-0737. Item II. B.3. Other aspects of sys acceptable. BROEHL, D. J. Portland General Electric Co. 83/07/01. EISENHUT, D. O. Division of Licensing. 3pp. 19375:028. 24X Fichs: 50-344:83/07/01. 8307110143.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, 8vc list enci. EIBENHUT.D.O. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs:50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT, D. O. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 1969:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- B307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EIBENHUT, D. Q. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307120027 Discusses continued problems in making control room ventilation sys operational per TMI Action Plan Item III.D.3.4.0mly one area radiation monitor necessary.per TMI Action Plan Item III.A.1.2.

  BROCELL.D.J. Portland General Electric Co. B3/07/08. EISENHUT.D.Q. Division of Licensing. 2pp. 19423:142. 24X Fiche: 50-344.B3/07/08.B307120029
- B307250041 Forwards Amend B1 to License NPF-1 & safety evaluation. Amend revises method for balancing flow for RCS cold leg injection lines from centrifugal charging & safety injection pumps. TRAMMELL.C.M. Operating Reactors Branch 3. B3/07/08. WITHERS.B.D. Portland General Electric Co. 2pp. 19723: 348. 24% Fiche: 50-344.83/07/08.8307250041.

- --8307250048 Amend 81 to License NPF-1, revising method for balencing flow for RCS cold leg injection lines from centrifugal charging & safety injection pumps & deleting flow balance test for hot leg injection.

  CLARK.R.A. Operating Reactors Branch 3. 83/07/08. 5pp. 19723:350. 24X Fiche:50-344.83/07/08.8307250041.
- --8307250052 Bafety evaluation supporting Amend 81 to License NPF-1.

   Office of Nuclear Reactor Regulation, Director. 83/07/08. 4pp 19723:355. 24X Fiche:50-344.83/07/08.8307250041.
- 8307250103 Forwards Amend 82 to License NPF-1 & safety evaluation. Amend authorizes operation w/22 fuel assemblies containing either three or five stainless steel rods in place of fuel rods for Fuel Cycle 6.

  CLARK.R.A. Operating Reactors Branch 3. 83/07/11. WITHERS, B. D. Portland General Electric Co. 2pp. 19725:328. 24X

  Fiche: 50-344, 83/07/11, 8307250103.
- ---8307250107 Amend 82 to License NPF-1, authorizing operation w/22 fuel assemblies containing either three or five stainless steel rods in place of fuel rods for Fuel Cycle 6.

  GLARK.R.A. Operating Reactors Branch 3. 83/07/11. 2pp. 19725:330. 24X Fiche: 50-344,83/07/11,8307250103.
- --8307250112 Bafety evaluation supporting Amend 82 to License NPF-1.
  \* Office of Nuclear Reactor Regulation, Director. 83/07/11.
  10pp. 19725:332. 24X Fiche:50-344,83/07/11,8307250103.
- B307190219 Forwards "Baismic & Dynamic Qualification of Pressurizer Relief Sys," in response to NUREG-0737, Item II.D. 1.
  "Reliability Engineering." Action item considered closed.
  BROCHL.D.J. Portland General Electric Co. 83/07/12. EISENHUT, D. G. Division of Licensing. 2pp. 19627:001. 24X Fiche: 50-344, 83/07/12, 8307190219.
- --83071902RI Requests ack of receipt of encl Topical Rept PGE-1039, "Seismic & Dynamic Qualification of Pressurizer Relief Sys."
  TODD: A.U. Portland General Electric Co. 83/07/11. EISENHUT. D. G. Division of Licensing. 1p. 19627:003. 24x Fiche: 50-344, 83/07/12, 8307190219.
- --8307190224 "Seismic & Dynamic Qualification of Pressurizer Relief Sys." TODD, A. J. Portland General Electric Co. PGE-1039. 83/07/31. 19ipp. 19627:004. 24X Fiche: 50-344, 83/07/12, 8307190219.
- 8307270466 Forwards safety evaluation of util responses to 801222 generic ltr re control of heavy loads, Phase I of issue resolved. Technical evaluation rept encl. CLARK.A. Operating Reactors Brench 3. 83/07/18. WITHERS, B.D. Portland General Electric Co. 2pp. 19859: 060. 24x Fichs: 30-344,83/07/18,8307270466.
- --8307290475 Safety evaluation of util responses to generic issue, "Control of Heavy Loads Near Spent Fuel." First response (Phase I) acceptable.

  # Operating Reactors Branch 5. 83/07/18. 2pp. 19859:062. 24X Fiche: 50-344, 83/07/18. 8307290466.
- --8306140436 "Control of Heavy Loads, Portland QE Go, Trujan Nuclear Plant," technical evaluation rapt.
  BOMBERGERIC. Franklin Institute/Franklin Research Genter.
  NRC-03-81-130. TER-C3506-398. 83/06/10. BINGH.A. NRC No
  Datailed Affiliation Given. 29pp. 19859: 064. 24X
  Fiche: 50-344.83/07/18,8307290466.
- G. Inspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Pailures Degrade Surry Recirculation Spray Subsystem." Svc list encl. URDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363;293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JRRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fichs: 30-000, 83/07/14, 8306270406.

- R. Periodic operating reports & related correspondence
- 8307180149 Monthly operating rept for June 1983. W/830712 ltr. BAIR.G.G., YUNDT.C.P. Portland General Electric Co. B3/07/12. Office of Resource Management, Director. Spp. 19556: 244. 24) Fiche: 50-344.83/07/12.8307180149.
- S. Reportable occurrences. LERs & related correspondence
- 8307120287 RD: on 830517, two triaxial time-history recording accelerographs, 8T-6336, on containment base slab & wall taken out of svc for calibr. Unit will be returned to svc by 830708 following integrated leak rate test.

  YUNDT, C. P. Portland General Electric Co. 83/06/27. MARTIN, J. B. Region 5, Office of Director. Ip. 19424:057. 24X Fiche: 50-344,83/06/27,8307120287.
- DOGKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8307060481 Advises that onsite & offsite emergency preparedness adequate & plans upgraded per NUREG-0737. Item III. A. 2. 1. Item complete.

  SYOLZ, J. F. Operating Reactors Branch 4. 83/06/17. CROUSE, R. P. Toledo Edison Co. 2pp. 19299; 124. 24X Fiche: 50-346, 83/06/17.
- 8307110174 Releases public version of rev to emergency plan supporting procedures rev index. FELTON, J.M. Division of Rules and Records, 83/06/24. Document Management Branch, 1p. 19385; 355. 24X Fiche: 50-346, 83/06/24, 8307110174.
- --8307110197 Public version of Rev 182 to emergency plan supporting procedures rev index. W/830608 ltr & receipt form.

  \* Toledo Edison Co. 83/06/30. Office of Nuclear Reactor Regulation, Director. 2pp. 19385:356. 24X Fiche: 50-346, 83/06/24, 8307110194.
- B3071B0300 Releases public version of revised amergency plan health physics procedure.
  FELTON, J. M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19566:119. 24X Fiche: 50-346, 83/06/24, 83/06/24,
- ---B307180304 Forwards public version of revised Emergency Plan Health Physics Procedures HP 1602.01 "External Personnel Radiation Exposure Monitoring" & HP 1604.01, "Personnel Decontamination." Receipt form encl.

  Toledo Edison Co. B3/05/26, NRC -- No Detailed Affiliation Given. 1p. 19366:120. 24X Fiche: 50-346,83/06/24,8307180300.
- --B307180306 Public version of revised Emergency Plan Health Physics Procedures HP 1602.01, "External Personnel Radiation Exposure Monitoring" & HP 1604.01, "Personnel Decontamination," MURRAY, T. D., BRIDEN, D. M., EVANS, J. Tuledo Edison Co. B3/05/24, S3pp. 19564:121, 24X Fiche: 50-346,83/06/24,8307180300.
- 8307080463 Advises that location of primary & backup emergency operations facilities acceptable. Approval of other features of facilities & other emergency response facilities will be determined during post-implementation appraisal. EISENNUT. D. G. Division of Licensing. 83/06/28. CROUSE, R. P. Toledi Edison Co. 2pp. 19365:071. 24X Fiche: 50-346, 83/06/28. B307080463.
- B307150091 Forwards schedule for completion of Suppl 1 to NUREG-0737 requirements for emergency response capability. Date of safety parameter display sys delayed 60 days. All other activities consistent w/orginal plan. CROUSE.R.P Toledo Edison Co. B3/07/11. EISENHUT.D.G. Division of Licensing. 2pp. 19336:111. 24X Fiche: 50-346.83/07/11.8307150091.
- B307250118 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. ip. 19738:059. 24X Fiche: 50-346, 83/07/19, 8307250118.
- ---B307250121 Forwards public version of revised emergency plan implementing procedures, including Procedures EI 1300.02 reunusual event, EI 1300.03 re alert & EI 1300.04 re site unergency.

  \* Toledo Edison Co. 83/06/21. NRC No Detailed Affiliation Given. 1p. 19738:060. 24X Fiche: 50-346,83/07/19,8307250118.

- --8307250125 Public version of revised emergency plan implementing procedures, including Procedures EI 1300.02 re unusual event. EI 1300.03 re alert & EI 1300.04 re site emergency Rev 29 to index encl. MURRAY, T. D. , BEYER, B. R. , WELLS, C. E. Toledo Edison Co. 83/06/15, 56pp. 19738:062. 24X Fiche.50-346,83/07/19,8307250118.
- 8307260316 Ack receipt of 830630 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-08.
  HIND, J. A. Division of Radiological & Materials Safety Programs.
  83/07/20. CROUNES, R.P. Toledo Edison Co. 1p. 19726:295. 24X
  Fiche: 50-346/83/07/20, 8307260316.
- --8307260321 Forwards response to NRC 830610 ltr re violations noted in IE Insp Rept 50-346/83-08. Response withheld (ref 10CFR73, 21).
  CROUSE.R.P. Toledo Edison Co. 83/06/30. KEPPLER.J.G. Region 3, Office of Director. 1p. 19726: 296. P4X Fiche: 50-346, 83/07/20, 8307260316.
- B307260533 Ack receipt of B30621 ltr informing NRC of steps taken to correct emergency planning exercise weaknesses noted in IE Insp Rept 50-346/B3-07.
  PAPERIELLO, C. J. Region 3, Office of Director. B3/07/21.
  CROUSE, R. P. Toledo Edison Co. ip. 19731:357. 24X
  Fiche: 50-346, B3/07/21, B307260533.
- --8307260537 Responds to NRC 830516 ltr re emergency planning exercise weaknesses noted in IE Insp Rept 50-346/83-07. Corrective actions: future scenarios will include more detailed in-plant radiation levels & offsite airborne radiation levels. CROUSE.R.P. Toledo Edison Co. 83/06/21. KEPPLER.J. G. Region 3. Office of Director. 6pp. 19731:358. 24X Fiche:50-346,83/07/21,8307260533.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307280201 Forwards Rev 1 to updated FSAR Replacement pages for typographical & grammatical errors identified in 830722 updated FSAR also encl. CROUSE, R. P. Toledo Edison Co. 83/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 19798:001. 24X Fiche: 50-346,83/07/22,8307280201.
- --8307280206 Rev 1 & errata to updated FSAR.

  \* Toledo Edison Co. 83/07/31. 105pp. 19798:002. 24X
  Fiche:50-346,83/07/22.8307280201.
- 8307220590 Notice of consideration of issuance of amend to License NPF-3 & proposed NSHC determination & opportunity for hearing re extension of surveillance test due date to 830917 for steam generator outlet steam pressure channels.

  8TOLZ.J.F. Operating Reactors Branch 4. 83/05/11. Spp. 19698:305. 24X Fiche: 50-346,83/05/11,8307220990.
- 8307220617 Forwards notice of consideration of issuance of amend to License NPF-3 & proposed NSHC determination & apportunity for hearing re 821014 application for revised Tech Spec setpoints.

  DEAQAZIO.A.W. Operating Reactors Branch 4. 83/06/13. CROUSE,R.P. Toledo Edison Co. 2pp. 19698:313. 24% Fiche:50-346,83/06/13. 8307220617.
- --B307220621 Notice of consideration of issuance of amend to License NPF-3 & proposed NSHC determination & opportunity for hearing re setpoints for pressurizer code safety valves. STOLZ1.J.F. Operating Reactors Branch 4. B3/06/13. 7pp. 19698:315. 24X Fiche: 50-346, B3/06/13, B307220617.
- B307180446 Forwards monthly FR notice of amends to OLs involving NSHC. # Office of Nuclear Reactor Regulation, Director. B3/06/15. UHRIG.R.E. Florida Pawer & Light Co. 2pp. 19641: 347. 24X Fiche: 50-000: B3/06/15: B307180446.
- --8307190001 Monthly notice of amends to OLs involving NSHC. CLARK.R.A. Operating Reactors Branch 3. 83/06/07. 15pp 19641:349. 24X Fiche:50-000.83/06/15.8307180446.
- 8307080611 Forwards Amend 59 to License NPF-3 & safety evaluation. Amend changes Tech Specs to permit one-time extension to 830917 for surveillance tests on certain instrumentation. DEAOAIIO.A.W. Operating Reactors Branch 4. 83/06/16. CROUSE.R.P. Toledo Edison Co. 1p. 19364:227. 24X Fiche: 50-346.83/06/16.8307080611.

- --8307080615 Requests FR publication of notice of issuance of Amerd 59 to License NPF-3, extending surveillance test due date to 830917.
  STOLZ.J.F. Operating Reactors Branch 4. 83/06/16. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19364:228 24X Fiche: 50-346.83/06/16.8307080611.
- --8307080620 Amend 59 to License NPF-3, changing Tech Spec to permit one-time extension to 830917 for surveillance tests on centain instrumentation.
  STOL7.J.F. Operating Reactors Branch 4 83/06/16 7pp.
  19364: 230. 24X Fiche: 50-346, 83/06/16, 8307080611.
- --8307080622 Safety evaluation supporting Amend 39 to License NPF-3.

   Office of Nuclear Reactor Regulation, Director. 83/06/16 Spp 19364:237. 24X Fithe: 50-346/83/06/16/8307080611
- 830707004) Requests extension until 830801 to submit revised Tech Specs for snubbers due to extensive internal review. CROUSE,R.P. Toledo Edison Co. 83706/28 STOLZ.J.F. Operating Reactors Branch 4. 1p 19293 253 24X Fiche: 50-346.83/06/28,
- 8307060226 Notifies of postponement of submittal of plans & schedules for resolution of TMI Action Item II. K 3.5. "Automatic Trip of Reactor Coolant Pump" (Generic Lit 83-10) until 830815, due to delay in receipt of generic rept from B&W. GROUSE.R.P. Toledo Edison Co. 83/06/30. STOLZ.J.F. Operating Reactors Branch 4. 1p. 19249:033. 24X Fiche: 50-346,83/06/30. 8307060226.
- 8307070178 Submits partial response to 821203 request re Generic Item 8-24 & NUREO-0737. Item II. E. 4.2 for proposed Iech Specs incorporating seal leakage test of containment purge & vent valves. Rev to license will be submitted by 830831. CROUSE.R. P. Toledo Edison Co 83706/30. 8TOLZ, J. F. Operating Reactors Branch 4. Ip. 19269: 335. 24X Fiche 50-346.83706/30, 8307070178.
- 8307110120 Forwards application for amend to License NPF-3, proposing changes to Tech Specs 3.0.3.4.0.3 & bases re safety sys aperability. Class II fee transmitted by 821105 ltr. CROUSER. P. Tuledo Edison Co. 83/07/01 STOLZ-J.F. Operating Reactors Branch 4. 1p. 19375:128 24X Fiche: 50-346,83/07/01.
- --8307110123 Application for amend to License NPF-3 proposing changes to Tech Specs 3.0.3.4.0.3 & bases re safety sys operability.
  Safety evaluation encl.
  CROUSE.R.P. Toledo Edison Co. 83/07/01 3pp. 19375:129. 24X
  Fiche: 50-346.83/07/01.8307110120.
- --8307110126 Proposed Tech Specs 3.0.3,4 0.3 & bases re safety sysoperability.
  Toledo Edison Co. 83/07/01. 6pp. 19375 132. 24X Fiche: 50-346,83/07/01,8307110120.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp 19390:317. 24% Fiche: 50-000. 83/07/05, 8306270397.
- 8307120228 Forwards application for amend to License NPF-3, revising Tech Specs re Cycle 4 reload. "Davis-Besse Nuclear Power Station Unit 1, Cycle 4 Reload Rept" also encl CROUSE, R. P. Toledo Edison Co. 83/07/05. 870LZ, J. F. Operating Reactors Branch 4. lp. 19425:132. 24X Ficher 50-346, 83/07/05, 8307120228.
- ---8307120237 Application for amend to License NPF-3, revising Tech Specs re Cycle 4 reload. MURRAY, T. D. Toledo Edison Co. 63/07/05 app. 19425:133, 24X Fiche: 50-346,83/07/05,8307120228,
- --8307120246 "Davis-Besse Nuclear Power Station Unit 1. Cycle 4 Reload Rept." \* Babcock & Wilcox Co. BAN-1783. 83/05/31. 69pp. 19425: 140. 24X Fiche: 50-346,83/07/05,8307120228.
- 8307060329 Generic Ltr 83-27 to all liconsees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT, D. G. Division of Licensing 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.

- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Sakem ATMS events Svc list encl. EISENHUT.D.e. Division of Licensing. 83/07/08. Cunsulidated Edison Co. of New York, Inc. 3Bpp. 1985:269. 24X Fichs: 50-000,83/07/08.8307080169.
- B307120411 Forwards application for amend to License NPF-3, changing Tech Specs 6.5.1.2,6.5.2.2. Figure 6.2-1.2 Figure 6.2-2 reutil reorganization. Fees previously submitted w/801226 amend request.
  CROUSE, R. P. Toledo Edison Co. B3/07/08. STOLZ, U.F. Operating Reactors Branch 4. (p. 19430: 132. 24X Fiche: 50-346, 83/07/08, 8307120411.
- --8307120413 Application for amend to License NPF-3, changing Tech Specs 6.5.1 2.6.5.2.2 Figure 6.2-1 & Figure 6.2-2 re util reorganization MRRAY.T.D. CROUSE.R.P. Toledo Edison Co. 83/07/08. 3pp. 19430:133. 24X Fiche: 50-346.83/07/08.8307120411.
- --8307120415 Proposed changes to Tech Specs 6.5.1.2.6.5.2.2.Figure 6.2-1 & Figure 6.2-2 re util reorganization.

  \* Toledo Edison Co. 83/07/08. 4pp. 19430:136. 24X
  ficha: 50-346.83/07/08.8307120411.
- 8307210302 Forwards application for amend to License NPF-3. Amend revises Tech Specs or operability requirements of DHR sys in Mode 3. revs to radiological effluent Fech Specs & rev to Table 4. fir-1 for consistency. CROUSE.R.P. Toledo Edison Co. 83/07/13. STQLZ.J.F. Operating Reactors Branch 4. 1p. 19665:045. 24X Fiche:50-346.83/07/13, 8307210302.
- --8307210309 Application for amend to License NPF-3, revising Tech Specs re operability requirements of DHR sys in Mode 3, revs to radiological effluent Tech Specs & rev to Table 4,11-1. CROUSE, R. P. Toledo Edison Co. 83/07/13. 4pp. 19665:046. 24X Fiche: 50-346,83/07/13,8307210302.
- --B307210314 Proposed changes to Tech Specs re operability of DHR sys in Mode 3, revs to radiological effluent Tech Specs & rev to Table 4, 11-1 to make notation consistent w/std radiological effluent Tech Specs.

  \* Tokedo Edison Co. B3/07/13, 14pp. 19655:050. 24X Fiche: 50-346.83/07/13,8307210302.
- 8307210167 Forwards "Disposal of Low Level Radioactively Contaminated Secondary-Bide Clean-up Resins in Onsite Settling Basins at Davis-Bessie Nuclear Power Station."
  CROUSE.R.P. Toledo Edison Co. 83/07/14. STOLZ.J.F. Operating Reactors Branch 4. lp. 17669:087. 24x Fiche:50-344.83/07/14.
- --B307210173 "Disposal of Low Level Radioactively Contaminated Secondary-Bide Clean-up Resins in Unsite Settling Basins at Davis-Beese Nuclear Power Station." # J. Stewart Bland Consulting. B3/05/31, 24pp. 19669:088. 24X Fiche. 50-346.83/07/14.8307210167.
- B307270294 Requests identification of specific valves which will be locked open as discussed in 830120 response to NUREO-0737. Item II. E.I. i. "Auxiliary Feedwater Bys Evaluation." Response requested by 830812. STOLZ-J.F. Operating Reactors Branch 4. 83/07/15. CROUSE.R.P. Toledo Edison Co. 2pp. 19812:045. 24X Fiche:50-346.83/07/15. 8307270294.
- B307260530 Submits status rept on ongoing activities towards developing & implementing integrated living schedule program for facility per B30510 ltr. Implementation schedule for FYB4 budget activities expected by B30701. CROUSE.R.P. Toledo Edison Co. 83/07/18. STOLZ.J.F. Operating Reactors Branch 4. 4pp. 19734:128. 24X Fiche:50-346.83/07/18. 8307260530.
- 8307280069 Forwards "Vegetation Survey for Effects of Cooling Tower Drift" & "Environ Noise Impact of Davis-Besse Nuclear Power Station." in response to NRC 821221 ltr re application to amend Tech Specs. CROUSE, R. P. Toledo Edison Co. 83/07/22. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19796: 325. 24X Fiche: 50-346, 83/07/22, 8307280069.
- --8307280071 "Vegetation Survey for Effects of Cooling Tower Drift." NASH.K. L.: SCOTT-WASILK.J. Toledo Edison Co. 83/07/31. 16pp. 19774: 327. 24X Fiche: 50-346.83/07/22.8307280069.
- --8307280079 "Environ Noise Impact of Davis-Besse Nuclear Power Station." \* Acoustic Technology, Inc. 83/06/30, 124pp. 19796:343, 24X Fiche 50-346,83/07/22,8307280069.

- G. Inspection reports, IE Bulletins & correspondence
- B307180177 Informs that B30429 commitment to procedure re verification & maint of drawing indices in response to IE Insp Rept 50-346/83-01 requires upgrading Separate procedure for index verification developed.

  CROUSE.R.P. Toledo Edison Co. 83/06/13. NORELIUS.C.E. Division of Engineering. 1p. 19555:067. 24X Fiche: 50-346,83/06/13,8307180177.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:273. 24X Fiche: 50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Cansolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Qaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list enci. TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:30-000.83/07/14,8308270406.
- 8307260316 Ark receipt of 830630 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-08.
  HIND, J.A. Division of Radiological & Materials Safety Programs.
  83/07/20. CROUSE, R.P. Toledo Edison Co. 1p. 19726: 295. 24X
  Fiche: 50-346, 83/07/20, 8307260316.
- --B30726032! Forwards response to NRC 830610 ltr re violations noted in IE Insp Rept 50-346/83-08. Response withheld (ref 10CFR73.21).
  CROUSE.R.P. Toledo Edison Co. 83/06/30. KEPPLER.J.O. Region 3, Office of Director. 1p. 19726:296. 24X Fiche: 50-346,83/07/20,8307260316.
- 8307260533 Ack receipt of B30621 ltr informing NRC of steps taken to correct emergency planning exercise weaknesses noted in IE Insp Rept 50-346/83-07.
  PAPERIELLO.C. J. Region 3. Office of Director. 83/07/21.
  CROUSE.R.P. Totedo Edison Co. 1p. 19731:357. 24X
  Fichs: 50-346, 83/07/21, 8307260533.
- R. Periodic operating reports & related correspondence
- B307220092 Monthly operating rept for May 1983. W/B30609 ltr.
  SARSDUR, D., MURRAY, T. D. Toledo Edison Co. 83/06/09. HALLER, N.
  Office of Resource Management, Director. 12pp. 19683: 302. 24x
  Fiche: 50-346, 83/06/09, 83072
- 8307180035 "Discharge Munitoring Rept for June 1983." W/830708 ltr. MURRAY.T.D. Toledo Edison Co. B3/07/01. DUNLAVY.8. Ohio. State of. 10pp. 19560:272. 24X Fiche: 50-346.83/07/01.8307180035.
- 8307180181 "Wastewater Rept for June 1983." W/830708 ltr. MURRAY, T. D. Toledo Edison Co. 83/07/08. Unio, State of, 9pp. 19555:053. 24X Fiche: 50-344, 83/07/08, 8307180181.
- S. Reportable occurrences, LEHs & related correspondence
- 8307050015 LER 83-026/03L-0: on 830524.one half channel trip in steam & feedwater rupture control sys (SFRCS) Channel 2 received.
  Caused by component failure. Input buffer replaced. W/830621 itr.
  YARGER,K., MURRAY,T. D. Toledo Edison Co. 83/04/21. KEPPLER, J. G. Region 3. Office of Director. 3pp. 19192:081. 24X
  Fiche: 50-346,83/06/21.8307050015.
- B307060220 LER 83-027/03L-0: on B30527 & 0607, emergency diesel generator tripped on dverspeed after startup. Caused by tachometer being out of calibr & incorrect setting described in Woodward Governor EGB-10C bulletin. W/830624 ltr. MELSTAD. K., MURRAY. T. D. Toledo Edison Co. B3/06/24. KEPPLER, J. G. Region 3, Office of Director. 4pp. 19248: 357. 24X Fiche: 50-346.83/06/24.8307060220.

0115 RO: on B30616, hatches associated w/negative pressure boundary re barrier removed. Notification satisfies 30-day irement. Written rept will be submitted by B30713.
AYT.D. Toledo Edison Co. B3/06/27. JACKIW.N. Region 3, ce of Director. 1p. 19251 276. 24X Fiche: 50-346, B3/06/27.

O482 LER 83-028/03L-0: on 830603 & 17 fuel handling area radiation tors RE8446 & 7 found deenergized Caused by blown ation monitoring cabinet fuse. Fuse replaced, W/830701

TZ, J., MURRAY, T. D. Toledo Edison Co B3/07/01. KEPPLER, J. O. on G. Office of Director 3pp. 19380-166. 24X p: 50-346-83/07/01, B307110482.

O127 LER B3-029/D3L-O: on B30612, main steam safety valve on steam rator 1-1 header actuated. Cause unknown. All main steam ty valves will be tested. W/B30712 ltr.
TLL, J., MURRAY, T. D. Toledo Edison Co. B3/07/12. KEPPLER, J. G. on 3, Diffice of Director. 3pp. 17666: 089. 24X e: 50-346, 83/07/12, 8307210129.

10228 LER 93-030/03L-0: on 830614, during change in ECC5 coil mbly 1, floor plugs forming part of negative pressure idary & fire barriers removed Caused by personnel error. If plugs reinstalled & new procedure written.

IPSON.T., MURRAY.T.D. Toledo Edison Co. 83/07/13, KEPPLER, J. G. on 3, Office of Director. App. 19684: 250. 24X

18: 50-346,83/07/13,8307220228.

#### igressional/Executive Correspondence

'OD47 Forwards monthly FR notice of consideration of issuance of ids to OLs involving NSHC determination & opportunity hearing.

ION,H.R. Office of Nuclear Reactor Regulation, Director.

36/22. STAFFORD,R.T. Senate, Environment & Public Works.

INGER,R.L. House of Rep., Energy & Commerce. 2pp. 19811:018.

Fiche: 50-000, 83/06/22, 8307270047.

7270030 Monthly notice of consideration of issuance of amends to OLs volving NBHC determination & opportunity for hearing. "ARK, R. A. Operating Reactors Branch 3. 83/06/07. 15pp. 7811: 020. 24X Fiche: 50-000, 83/06/22, 8307270047.

T 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1 curity, medical, emergency & fire protection plans

BO314 Releases public version of revised emergency plan lementing procedure.
TON.J.M. Division of Rules and Records. 83/06/24. Docum agement Branch. ip. 19566:090. 24X Fiche:50-348.83/06/24, 7180314. Document

7180319 Public Version of Rev 5 to Emergency Plan Implementing rocedure FNP-0-EIP-26, "Offsite Notification." W/830614 tr.transmittal form & procedure request form. DOM, J. E., HUDBPETH, J. B. Alabama Power Co. 83/06/10. Dffic uclear Reactor Regulation, Director. 5pp. 19566:091. 24X iche: 50-348,83/06/24,8307180314. Office of

20520 Ack receipt of 830705 ltr informing NRC of steps taken to rect violations noted in IE Insp Repts 50-348/83-15 & 344/83-13.

RELLI,D.M. Division of Project & Resident Programs. 83/07/13.

RNALD,R.P. Alabama Power Co. ip. 19685:031 24X he:50-348,83/07/13,8307220520.

7220530 Responds to NRC 830615 ltr re violations noted in IE lnsp epts 50-348/83-15 % 50-364/83-13 Corrective actions: p smoking signs posted on auxiliary feedwater pump room: personnel counseled re proper logging of entries. LAYTON, F. L. Alabama Power Co. 83/07/05. VERRELLI, D. M. Region: Office of Director. 3pp. 19685:032 24X Fiche: 50-34B. 13/07/13, 8307220520.

17220539 Notice of violation from insp on 830411-0510. : Region 2, Office of Director. 83/06/15. ip. 19685:037. 24% :iche: 50-348.83/07/13.8307220520.

17220549 IE Insp Repts 50-348/83-15 & 50-364/83-13 on 830411-0510. Noncompliance noted: violation of Tech Spec Section 6.8 reimsking in prohibited area in vicinity of auxiliary bidg. IRADFORD, W. H., RULAND, W. H. Region 2. Office of Director. ANTRELL, F. B. Division of Project & Resident Programs. 83/06/15. 3pp. 19485:038. 24X Fiche: 50-348, 83/07/13, 8307220520.

- 8307250696 Releases public version of revised emergency plan implementing procedure.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19720:151. 24X Fiche: 50-348,83/07/19,8307250696.
- --8307250699 Public version of Rev 2B to Emergency Plan Implementing Procedure FNP-0-EIP-8, "Notification Roster." W/830502 ltr. HUDSPETH. J. B. Alabama Power Co. B3/04/2B. Dffice of Nuclear Reactor Regulation, Director. 30pp. 19720:153. 24X Fiche: 50-348, 83/07/19, 8307250696.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307080402 Forwards Rev 1 to updated FSAR.Vol 2i,for JM Farley Nuclear Plant.Units 1 & 2.Rev reflects glant & procedure mods through B30101 & changes per 10CFR50, 59(b). CLAYTON.F.L. Alabama Power Co. B3/07/01. VARGA.S.A. Office of Nuclear Reactor Regulation, Director. 3pp. 19354:090. 24X Fiche: 50-348,83/07/01,8307080402.
- ---8307080405 Rev 1 to updated FSAR.Vol 21. for JM Farley Nuclear Plant, Units 1 & 2. \* Alabama Power Co. 83/07/31. 577pp. 19354:093. 24X Fiche: 50-348,83/07/01.8307080402.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Hestinghouse PHRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  ETSENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19363:116. 24X Fiche: 50-000,83/06/03.
- 8307070080 "Startup Test Rept, Unit 1. Cycle 5." W/830628 ltr. NESBITT.C. D., CLAYTON, F. L. Alabama Power Co. 83/06/23. VARQA, S. A. Office of Nuclear Reactor Regulation, Director. 23pp. 19273: 082. 24X Fiche: 50-348, 83/06/23, 8307070080.
- 8307010182 Forwards mod to "Conduct of Operations" re post-trip review.
  Permanent rev approval expected within 60 days.
  CLAYTON, F. L. Alabama Power Co. 83/06/28. VARGA, S. A. Office of
  Nuclear Reactor Regulation, Director. 1p. 19124: 287. 24X
  Fichs: 50-348, 83/06/28, 8307010182.
- --8307010187 "Temporary Procedure Change.Conduct of Operations -
  Operations Group."

  \* Alabama Power Co. 83/06/28. 7pp. 19124:288. 24X

  Fiche: 50-348.83/06/28,8307010182.
- 8307080479 Advises that util & DOE have executed DE-CR01-B3NE44361, "Contract for Disposal of Spent Nuclear Fuel &/or High Level Radwaste," per Nuclear Waste Policy Act of 1982 & Generic Ltr 83-07.
  CLAYTON.F.L. Alabama Power Co. 83/06/28. VARGA.S.A. Office of Nuclear Reactor Regulation, Director. 1p. 19346:322. 24X Fiche: 50-348,83/06/28,8307080479.
- 8307070104 Supplemental application to amend Licenses NPF-2 & NPF-8, requesting withdrawal of svc water portions of 830201 & 0620 Tech Specs Info re svc water batteries will be provided in Jul 1983 to support 831103 approval date. CLAYTON,F.L. Alabama Power Co. 83/06/29. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 19294:117. 24X Fiche: 50-348, 83/06/29, 8307070104.
- 8307080308 Forwards safety evaluation of 821116 Tech Spec change to reflect change in organization & mgt titles.in response to 830627 request. Change is administrative in mature. CLAYTON, F. L. Alabama Power Co. 83/06/29. VAROA, S. A. Office of Nuclear Reactor Regulation, Director. 2pp. 19350:163. 24X Fiche: 50-348,83/06/29,8307080308.
- B307190432 Forwards notice of consideration of B30527 application for amend to License NPF-3 & proposed NSHC determination & opportunity for hearing re turbine valve cycle tests.

  \* Division of Licensing B3706/27. CL47TON,F.L. Alabama Power Co. ip. 19540:198. 24X Fiche:50-348.B3/06/29.B307150432.
- --B307150437 Notice of consideration of issuance of amend to License NPF-3 & proposed NSHC determination & opportunity for hearing, per 830527 application re turbine valve cycle tests. W1001NTON, D. L., Operating Reactors Branch 1, 83/06/24, 7pp. 19540: 191. 24X Fiche: 50-34B, 83/06/29, 8307150432.

- 8307080272 Forwards design info for automatic shunt trip of reactor trip breakers & description of scope & objective of DS-416 undervoltage trip attachment confirmatory life testing program Info withheld (ref 10CFR2.79).

  CLAYTON.F.L. Alabama Power Co. 83/06/30. VARGA.S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 19349:307. 24x Fiche: 50-348,83/06/30,8307080272.
- B307120885 Notice of consideration of issuance of amends to Licenses NPF-2 & NPF-8 & proposed no significant hazards consideration determination & opportunity for hearing reflexibility in defining rod inoperability. VARGA.S.A. Operating Reactors Branch I. B3/06/30. 7pp. 19508:329. 24X Fiche: 50-348.83/06/30.8307120885.
- 8306270397 Opneric Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Ficha:50-000,83/07/05,8306270397.
- 8307130262 Forwards comments on SER rs util relief requests from inservice twating requirements. SERs should be revised by 830901 to ensure that Unit 2 outage will not be impacted. CLAYTON, F.L. Alabama Power Co. 83/07/05. VARGA.S.A. Office of Nuclear Reactor Regulation, Director. 8pp. 19508:238. 24X Fiche: 50-348, 83/07/05, 8307130262.
- B307060329 Coneric Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for yower reactors re surveillance intervals in STE. Svc list encl. EISENHUT.D. O. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000,83/07/06,8307060329.
- 8307120483 Submits info in response to request for changes to emergency operating procedures (EGP) for reactor trip & anticipated transient w/o trip (ATWT). Draft reactor trip EGP to be completed within 2 wks. ATWT EDP to be revised. CLAYTON F. L. Alabama Power Co. 83/07/06. VAROA, S. A. Office of Nuclear Reactor Regulation, Director. 2pp. 19425:060. 24X Fiche: 30-348, 83/07/06, 8307120483.
- B307140110 Forwards notice of consideration of issuance of amends to Licenses NPF-2 & NPF-8 & proposed no significant hazards consideration re testing & insp of river water sys.

  \* Division of Licensing. B3/07/06. CLAYTON.F.L. Alabama Power Co. ip. 19528:112. 24X Fiche: 50-348,83/07/04,8307140110.
- --B307140116 Notice of consideration of issuance of amends to Licenses NPF-2 & NPF-8 & proposed no significant hazards consideration determination. correcting administrative error in Tech Specs re testing & insp of river water sys. VARCA.S.A. Operating Reactors Branch 1. B3/07/06. 4pp. 19528:113. 24X Fiche: 50-348.83/07/06.8307140110.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24x Fiche: 30-000.83/07/08.8307080169.
- 8307150095 Submits add1 info re significant hazards consideration for 830617 proposed one-time Tech Spec change to extend visual insp of inaccessible hydraulic snubbers. Proposed changes involve no significant hazards.

  CLAYTON, F. L. Alabama Power Co. 83/07/08, VARCA, S. A. Office of Nuclear Reactor Regulation, Director. 4pp. 19536:122, 24X Fiche: 50-348, 83/07/08, 8307150095.
- 8307130097 Application to amend Licenses NPF-2 & NPF-8 changing Tech Specs re leak rate testing criteria. Proposed one-time amend for Unit 2 designated Class III. Permanent Tech Bpec change considered suppl to 820810 submittal.

  CLAYTON, F. L. Alabama Power Co. 83/07/08, VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 4pp. 19536:012. 24x Fiche: 50-348,83/07/08,8307150097.
- ~~B307150099 Proposed Tech Specs re leak rate testing criteria. \* Alabama Power Co. 83/07/08. 4pp. 19536:016. 24X Fiche: 30-348.83/07/08.8307150097.
- G. Inspection reports, IE Bulletins & correspondence
- B307140427 Requests that status of Inspector Followup Item 2 from IE Insp Rept 50-348/B1-05 re pressurizer inservice insp indications; be reviewed & rept corrected based on disposition of indications per util B30221 ltr. CLAYTON; F.L. Alabama Power Co. B3/04/05, D'REILLY, J.P. Region 2, Office of Director. 2pp. 19521: 183. 24X Fiche: 50-348, B3/04/05, B307140427.

- B307140054 Extends invitation to attend B30701 mgt meeting at Region II ofc to present findings of util investigation of transuranic matls in radwaste shipments.per B30607 telcon.

  LEWIS.R.C. Division of Project & Resident Programs. B3/06/10.

  MCDDNALD.R.P. Alabama Power Co. 2pp. 19514:143. 24X

  Fiche: 30-348,83/06/10,8307140054.
- 8307150095 Submits addl info re significant hazards consideration for 830617 proposed one-time Tech Spec change to extend visual insp of inaccessible hydraulic snubbers. Proposed changes involve he significant hazards.

  CLAYTON.F.L. Alabama Power Co. 83/07/08. VARGA.S.A. Office of Nuclear Reactor Regulation, Director. 4pp. 19834:122, 24X Fiche: 50-348,83/07/08,8307150095.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list ancl.
  JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 194pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list enci.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8307220820 Ack receipt of 830705 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-15 & 50-344/83-13.

  VERRELLI,D,M. Division of Project & Resident Programs. 83/07/13.

  MCDQNALD,R.P. Alabama Power Co. 1p. 17685:031. 24X

  Fiche: 50-348,83/07/13,8307220520.
- --8307220530 Responds to NRC B30615 ltr re violations noted in IE Insp. Repts 50-248/83-15 & 50-364/83-13. Corrective actions: no smoking signs posted on auxiliary feedwater pump room & personnel counseled re proper logging of entries. CLAYTON.F.L. Alabama Power Co. B3/07/05. VERRELLI, D.M. Region 2, Office of Director. 3pp. 19685:032. 24% Fiche: 50-348, B3/07/13, B307220520.
- --8307220534 Forwards IE Insp Repts 50-348/83-15 & 50-364/83-13 on 830411-0510 & notice of violation.

  VERRELLI, D. M. Division of Project & Resident Programs. 83/06/15. MCDOMALD, R. P. Alabama Power Ca. 2pp. 19685: 035. 24X Fiche: 50-348, 83/07/13, 8307220520.
- --8307220539 Notice of violation from insp on B30411-0510. \* Region 2, Office of Director. 83/06/15. ip. 17685:037. 24X fiche: 50-348, 83/07/13, 8307220520.
- --B307R20549 IE Insp Repts 50-348/83-15 & 50-364/83-13 on 830411-0510. Noncompliance noted violation of Tech Spec Section 6.8 resouting in prohibited area in vicinity of auxiliary bldg. BRADFORD, M.H., RULAND, W.H. Region 2. Office of Director. CANTRELL, F. B. Division of Project & Resident Programs. B3/06/15. Bpp. 19685:038. 24X Fiche: 50-348, 83/07/13, 8307220520.
- 8306270406 IE Info Notice 83~48, "Caseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl.

  TAYLOR.J.M. Division of QA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- R. Periodic operating reports & related correspondence
- 830719010B Monthly operating rept for June 1983. W/830712 ltr. HAIRSTON.W. 0. CLAYTON.F. L. Alabama Power Co. 83/07/06. Office of Resource Management. Director. 5pp. 19636:035. 24X Fiche: 50-348,83/07/06,830719010B.
- B307180095 Forwards status of licensing items requiring NRC approval as of B30708.

  CLAYTON,F.L. Alabama Power Co. B3/07/08. VARQA,S.A. Office of Nuclear Reactor Regulation, Director. 7pp. 19536:331. 24X Fiche: 30-348,83/07/08,8307180095.
- S. Reportable occurrences, LERs & related correspondence
- 8305100008 Forwards LER 83-016/03L-0. CLAYTON.F.L. Alabama Fower Co. 83/05/02. Region 2, Office of Director. 1p. 18377:181. 24X Fiche: 50-348,83/05/02,8305100008.
- --B305100010 LER B3-016/03L-0: on B30412, diesel generator iB declared inoperable due to start failure resulting in inoperability of train B due to loss of emergency power. Caused by mechanical binding of fuel filter constant vent check valve. HAIRSTON. M. Q. Alabama Power Co. 83/03/02. Region 2, Office of Director. 2pp. 18377: 182. 24X Fiche: 50-348, 83/05/02, 8305100008.

- 8307120576 Forwards LERs 83-025/03L-0 & 83-024/03L-0. CLAYTON, F. L. Alabama Power Co. 83/06/22. Region 2, Office of Director. 1p. 19433:079. 24X Fiche: 50-348, 83/06/22, 8307120576.
- --8307120590 LER 83~025/03L~0: on 830528, during Calibr Procedure FNP-2-8TP-612. O, reactor coolant pump 2A undervoltage relay 27-3 declared inoperable. Caused by setpoint drift. Relay setpoint adjusted.
  HAIRSTON, M. O. Alabama Power Co. 83/06/22. Region 2, Office of Director. ip. 17433:080. 24X Fiche: 50-348, 83/06/22, 8307120576.
- --8307120594 LER 83-024/03L-0: on 830525, following increased count rate on containment atmosphere particulate monitoring sys R-11, RGB unidentified leakage found above Tech Specs. Cause not stated. Loop B drain valve tightened.

  HAIRBTON.W.G. Alabama Power Co. B3/06/22. Region 2, Office of Director. 1p. 19433: OBI. 24X Fiche: 50-348, 83/06/22, 8307120576.
- 8307120286 LER 83-027/O3L-0: on 830507, during performance of FNP-1-8TP-43. O, train A penetration room filtration sus declared inoperable when exhaust fan damper 3357A would not open. Caused by comparator card failure. W/830530 ltr.

  HAIRSTON.W.O., CLAYTON.F.L. Alabama Power Co. 83/06/30. Region 2, Uffice of Director. 2pp. 19424:055. 24X Fiche: 50-348, 83/06/30, 8307120286.
- 8307150103 Forwards LERs 83-030/03L-0 & 83-031/03L-0. CLAYTON.F. L. Alabama Power Co. 83/07/07. Region 2. Office of Director. 1p. 19534: 130. 24X Fiche: 50-348. 83/07/07. 8307150103.
- --8307150105 LER 83-030/03L-0: on 830607, during administrative review, stroke time test for turbing driven auxiliary feedwater pump steam admission valve 32358 determined not performed after 830603 maint. Caused by personnel error.
  HAIRSTON.W. G. Alabama Power Co. 83/07/07. Region 2, Office of Diractor. 2pp. 19836:131. 24X Fiche: 50-348,83/07/07,8307150103.
- ---8307150109 LER 83-031/03L-0:on 830610, during solid state protection sysoperability test, loop 3 steam line differential pressure instrumentation channel declared inoperable. Caused by failure of universal card. Card replaced.

  HAIRBTON. W. O. Alabama Power Co. 83/07/07. Region 2. Office of Director. 1p. 19536:133. 24X Fiche: 50-348,83/07/07,8307150103.
- 8307220338 LER 83-035/03L-0: on 830610. vacuum pump tripped & containment atmosphere activity particulate monitor R-11 & gaseous monitor R-12 declared inoperable. Caused by failure of failure dinboard pump during maint on outboard pump. W/830708 ltr.

  MATRETON: W. G., CLAYTON: F. L. Alabama Power Co. 83/07/08. Region 2, Office of Director. 2pp. 17675:357. 24X Fiche: 50-348,83/07/08,8307220338.
- 8307220303 Forwards LERs 83-032/03L-0,83-033/03L-0,83-034/03L-0 & 83-037/03L-0. 83-037/03L-0. CLAYTON,F.L. Alabama Power Co. 83/07/15. Region 2, Office of birector. 1p. 19683:271. 24X Fiche: 50-348,83/07/15,8307220303.
- --B307220311 LER 83-032/03L-0: on B30617, train A containment spray sys declared inoperable due to failure of MOV 8926A to open fully. Cause not determined Valve stroked four times in succession. Surveillance frequency increased to monthly. HAIRBION; M. G. Alabama Power Co. B3/07/15, Ragion 2, Office of Director. 1p. 19483: 272. 24X Fiche: 50-348, 83/07/15, 8307220303.
- --8307220315 LER 83-033/03L-0: on 830615.RC8 average temp dropped below Tech Spec requirements during routine startup. Caused by personnel error requesting too large steam demand during main steam line warmup. Responsible operators counseled. HAIRSTON.H. G. Alabama Power Co. 83/07/15. Region 2. Office of Director. 1p. 19683:273. 24X Fiche: 90-348,83/07/15,8307220303.
- --8307220320 LER 83-034/03L-0: on 830616, pressurizer pressure dropped below Tech Spec limits during startup. Caused by personnel error. RCS boration. combined w/load increase, resulted in pressurizer pressure drop. Personnel counseled. HAIRSTON. H. G. Alabama Power Co. 83/07/15. Region 2, Office of Director. ip. 19683: 274. 24X Fiche: 50-348,83/07/15,8307220303.
- --8307220323 LER 83-037/03L-0: on B30617, containment isolation valve RC-MV-B028 did not meet required stroke time during miscallaneous valve Inservice Test FNP-1-BTP-47. O. Caused by faulty air solenoid valve. Valve repaired. HAIRBIDN.W. G. Alabama Power Co. B3/07/15, Region 2, Office or Director. 1p. 19683: 275. 24X Fiche: 50-348, 83/07/15, 8307220303.
- 8307290170 LER 83-036/03L-0: on 830629, steam generator iB wide-range level indicator on remote shutdown panel declared inoperable due to erratic readings. Caused by failure of printed circuit card. Card replaced. W/830721 ltr.
  HAIRBTON, W. O., CLAYTON, F. L. Alabama Power Co. 83/07/21. Region 2, Office of Director. 2pp. 19821: 160. 24X Fiche: 50-348, 83/07/21, 8307290170.

- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 8208060366 Board Natification 62-70 notifies of differing prof opinion resensitization of BHR stainless steel weldments.
  EISENHUT, D. G. Division of Licensing. 82/07/20. PALLADING, N. J. Commissioners. 4pp. 17043:001. 24X Fiche: 50-000, 82/07/20. 8208060366.
- --B302040562 Forwards request for add1 info re reactor internals mat1s.
  JUHNSTON.M.V. Assistant Director for Mat1s & Qualif. Engineering (Pre 830201). B2/05/14. TEDESCO.R.L. Assistant Director for Licensing. 2pp. 17043:089. 24X Fiche:50-000,82/07/20,8208060366.
- B307070556 Summary of B30608 meeting w/util:NUS, J Benjamin & Assoc.BNL & Structural Mechanics Assoc in Bethesda.MD re severe accident risk assessment.Viewgraphs encl. MARTIN.R.E. Licensing Branch 2. 166pp. 19344:125. 24X Fiche: 50-352, B3/06/27, B307070556.
- 8307080543 Forwards Equipment Qualification Branch request for add1 info re NUREG-0737, Item II. D. 1 re review of NEDE-24988-P. For specific safety/relief valves employed at plant, applicability of generic test results must be justified. SCHWENCER, A. Licensing Branch 2. 83/06/27. BAUER, E. 0. Philadelphia Electric Co. 4pp. 19365:043. 24X Fiche: 50-352, 83/06/27, 8307080543.
- 8307010093 Forwards response to Core Performance & Reactor Sys Branch telcon requests for addl info re differences in pressurization transient results between Limerick & other BHR plants of similar design.
  BRADLEY.E.J. Philadelphia Electric Co. 63/06/28. SCHWENCER.A. Licensing Branch 2. 3pp. 19124:217. 24X Fiche:50-352,83/06/28. 8307010093.
- 8307070549 Summary of 830623 meeting w/util.Bechtel.GE & Koch Process Sys:Inc re offgas sys explosion resistance.Meeting handouts encl. MARTIN.R.E. Licensing Branch 2. 83/06/28. Licensing Branch 2. 13pp. 19344:112. 24X Fiche:50-352.83/06/28.8307070549.
- B307130006 Provides statement of position re in-plant communication sys. Communication sys not seismically supported. Response requested in 7 days of Itr receipt.

  SCHWENCER. A. Licensing Branch 2. B3/06/28. BAUER. E. G. Philadelphia Electric Co. 3pp. 19525: 355. 24X

  Fiche: 50-352.83/06/28.8307130006.
- 8307130271 Forwards revised draft response & FSAR page changes to NRC Question 460.5 re air intake sys & addl info re ESF filter sys instrumentation, in response to 830524 & 0608 telcons.
  BRADLEY,E. J. Philadelphia Electric Co. 83/06/28. SCHHENCER,A. Licensing Branch 2. 23pp. 19508:256. 24X Fiche: 50-352,83/06/28,8307130271.
- 8307070037 Forwards draft rev to Page 11.5-39 of FSAR re gas analysis & core damage per 830628 request. Page will be incorporated in FSAR rev scheduled for Aug 1983.
  BRADLEY,E. J. Philadelphia Electric Co. 83/06/29. SCHMENCER, A. Litensing Branch 2. 4pp. 19293:247. 24X Fiche:50-352,83/06/29,8307070037.
- B307070286 Forwards draft rev to Request for Add1 Info 210.82 rebalance of plant supports designed to Subsection NF & related FSAR page changes.
  BRADLEY, E. J. Philadelphia Electric Co. B3/06/29. BCHMENCER, A. Licensing Branch 2. 5pp. 19269: 330. 24X Fiche: 50-352,83/06/29,8307070286.
- B307010185 Forwards Amend 52 to OL application consisting of Rev 21 page changes to FSAR per NRC 830308 & 0603 ltrs & Rev 4 page changes to design assessment rept.
  BRADLEY.E.J. Philadelphia Electric Co. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19186: 356. 24X Fiche: 50-352, 83/06/30, 8307010185.
- --8307010190 OL application consisting of Rev 21 page changes to FSAR & Rev 4 page changes to design assessment rept.
  BOYER, V. S. Philadelphia Electric Co. 63/06/27. App. 19186:359.
  24X Fiche: 50-352,83/06/30,8307010185.
- --8307010192 Rev 4 page changes to design assessment rept. \* Philadelphia Electric Co. 83/06/30. 49pp. 19187:003. 24X Fiche: 50-352, 83/06/30, 8307010185.

- 8307070167 Forwards Chapters 5.6 & B.App A to Chapter 5 & revised table of contents to "Severe Accident Risk Assessment." Chapter 7 will be provided in near future.
  BRADLEY.E.J. Philadelphia Electric Co. 83/07/01. SCHWENCER.A. Division of Licensing. 2pp. 19267:092. 24X Fiche: 50-352.83/07/01, 8307070167.
- --B307070170 Chapters 5.6 & 8.App A to Chapter 5 & revised table of contents to "Bevere Accident Risk Assessment."

  \* Philadelplás Electric Co. B3/07/01. 117pp. 19267:094. 24X Fiche:50-352,83/07/01,8307070167.
- 8307150389 Notification of 830708 meeting w/util & consultants in Newport Beach,CA to discuss seismic aspects of plant severe accident rist assessment.

  MARTIN.E. Licensing Branch 2, 83/07/01, SCHWENGER,A. Licensing Branch 2, 4pp. 17540:322, 24X Fiche:50~352,83/07/01,8307150389.
- 8306270397 Owneric Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05,8306270397.
- 8307080296 Forwards draft FSAR pages containing addl info re isolation of purge & vent valves on high radiation, per Containment Bys Branch request at 830615 meeting. Info will be incorporated into FSAR rev scheduled for Aug 1983. BRADLEY, E. J. Philadelphia Electric Co. 83/07/05. 8CHWENCER, A. Licensing Branch 2. 8pp. 19351:183. 24X Fiche: 30-352, 83/07/05, 8307080296.
- 8307080300 Advises that responses to QA Branch 830607 Requests for Add1 Info 260.36 & 260.37 will be provided by 830722. BRADLEYE, J. Philadelphia Electric Co. 83/07/05. SCHWENCER, A. Licensing Branch 2. 2pp. 19351:179. 24X Fiche: 50-352,83/07/05,8307080300.
- 8307080505 Forwards draft rev to Mechanical Equipment Branch Request for Add1 Info RAI 210.33 re operability of feedwater isolation check valves. Info will be incorporated into next FSAR rev, scheduled for Aug 1983.

  BRADLEY.E. J. Philadelphia Electric Co. 83/07/05. SCHNENCER.A. Licensing Branch 2. 6pp. 19346:338. 24X Fiche: 50-352.83/07/05, 8307080505.
- 8307150373 Notification of 830712 meeting w/util in Dathesda, MD to discuss outstanding items in Power Sys Branch review, including util appeal of NRC position on communications sys. MARTINR.E. Licensing Branch 2. 83/07/05. BCMMERGER.A. Licensing Branch 2. 4pp. 19540:337. 24X Fiche:30-352.83/07/05.8307150373.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors ra surveillance intervals in STS. Syc list and L. EISENHUT. D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307110272 Requests info re decision to conduct 830413-15 caseload forecast panel meeting & tour only at Unit 1.
  8UGARMAN.R.J. Sugarman. R.J. 83/07/06. HAUGHEY.M.F. Licensing Branch 2. ip. 19379:160. 24X Fiche: 50-352, 83/07/06, 8307110272.
- 8307110491 Forwards draft revs to responses to Guestions 410.10 & 410.12 re analysis for rotating components & tornado missile spectrum. Responses will be incorporated in FSAR rev scheduled for Aug 1983.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/06, SCHWENCER, A. Licensing Branch 2, 15pp. 19380:101, 24X Fiche: 50-352,83/07/06,8307110491.
- B307120484 Informs that util has elected to address chugging phenomenon by capping downcomers on which wetwell/drywell vacuum breakers are mounted. Pool swell phenomenon addressed by listed mods to vacuum breakers.

  KEMPER. J. B. Philadelphia Electric Co. B3/07/06. SCHWENCER, A. Licensing Branch 2. 3pp. 19425:076. 24% Fiche: 50-352,83/07/06, B307120484.
- B307110459 Forwards response to Structural Engineering Branch Question 220.22(b) re damping value for electrical raceway sys. Response will be incorporated into FSAR Rev 23 scheduled for Aug. 1983.
  BRADLEY, E. J. Philadelphia Electric Co. B3/07/07. BCHWENGER, A. Licensing Branch 2. 6pp. 19380: 124. 24x Fiche: 50-352, 83/07/07, 8307110459.

- 8307120330 Forwards response to Environ Qualification Branch & Containment Bys Branch requests for info re containment purge & vent valve operability. Encl draft FBAR pages to be incorporated in Aug 1983 rev. Seismic rept by 830801.
  BRADLEY.E. J. Philadelphia Electric Co. 83/07/07. SCHWENCER, A. Licensing Branch 2. 15pp. 19431:155. 24X Fiche: 50-352, 83/07/07, 8307120330.
- --8307120333 "Purge & Vent Valve Operability Qualification Analysis, Philadelphia Electric Co.Limerick Generating Station, Unit i."

  KRUEGER, J. E., SANSONE, R. C. CLOW Corp. 6-06-83. 83/06/30. 158pp. 19431:171. 24% Fichs: 50-352, 83/07/07. 8307120330.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fichs: 50-000,83/07/08,8307080169.
- 8307150075 Forwards NEDO-10678, "Seismic Qualification of Clase I Electrical Equipment," in response to R Martin 830609 request.

  BRADLEY, E. J. Philadelphia Electric Go. 83/07/12. SCHWENCER: A. Division of Licensing. 2pp. 19535:287. 24X Fiche: 50-352,83/07/12,8307130075.
- --8307150081 "Beismic Qualification of Class I Electric Equipment." TEST.L.D. General Electric Co. NEDD-10678. 72/11/30. 77pp. 19535: 289. 24% Fiche: 50-352, 83/07/12, 8307150075.
- 8307150300 Responds to 830630 ltr re failure to receive documents. Name added to NRC distribution list. NRC 830620 ltr to util, summariring NRC Caseload Forecast Panel 830413-15 sits visit & 830721 masting summary.encl.

  HDD0D0N.A.P. Hearing Branch 2. 83/07/13. BUSH.M.W. Bush. M.W. 21pp. 19532: 213. 24% Fiche: 50-352, 83/07/13, 8307150300.
- 8307190118 Forwards draft rev to Request for Add1 Info RAI 210.82 & related FSAR pages containing info requested by Mechanical Engineering Branch per 830701 telcon re balance of plant supports. Changes supersede info sent by 830429 ten. 8ADLEY,E.J. Philadelphia Electric Co. 83/07/13. SCHWENCER,A. Licensing Branch 2. 5pp. 19635:001. 24X Fiche: 50-352,83/07/19,8307/19018.
- B307190121 Forwards draft rev to FSAR Section 8.1.6.1.12.C & responses to Questions 430.57 & 430.62 re medium & lower voltage sys. Changes will be incorporated into FSAR rev scheduled for Aug 1983.
  BRADLEY.E.J. Philadelphia Electric Co. B3/07/15. SCHWENCER.A. Licensing Branch 2. 14pp. 19634:322. 24X Fiche:50-352,83/07/15. 8307190121.
- 8307190197 Forwards draft rev to response to FSAR Questions 220.2 re pressure transient caused by design basis tornado per 830624 telcon. Info will be incorporated into FSAR rev scheduled for Aug 1983.

  BRADLEY.E.J. Philadelphia Electric Co. 83/07/15. BCHWENCER.A. Licensing Branch 2. 8pp. 17630:130. 24X Fiche: 50-352,83/07/15,8307190197.
- 8307260406 Forwards marked-up FSAR pages, per Instrumentation & Control Sys Branch request during 830711 meeting. Info will be incorporated into FSAR rev scheduled for Aug 1983. Requested info inappropriate for incorporation into FSAR provided. KEMPER.J. 8. Philadelphia Electric Co. 83/07/18. 8CHWENCER.A. Licensing Branch 2. 31pp. 19733:210. 24X Fiche: 30-352,83/07/18,8307260406.
- B307230316 Advises that FBAR Figure 9.4-5 will be revised to show that hyrogen bottles now placed outside reactor bidg & number of bottles reduced. Next rev scheduled for August 1983. KEMPER, J. B. Philadelphia Electric Co. B3/07/20. BCHWENCER, A. Licensing Branch 2. 2pp. 19701:341. 24X Fiche: 50-352,83/07/20,8307280316.
- 8307260147 Forwards draft changes to FBAR Sections 1.13 & 6.2.4,3.1.2.
  1.1 re influent lines & feedwater lines, per Containment
  Sys Branch 830717 telcon. Changes will be incorporated into
  FBAR.
  BRADLEY, E. J. Philadelphia Electric Co. 83/07/20. SCHHENGER, A.
  Licensing Branch 2. 7pp. 19727:279. 24X Fiche: 50-352, 83/07/20,
  8307260147.
- 8307260350 Forwards revised response to 830411 Question 210.92 re RHR sys quality classification. Info will be incorporated in Augrev to FBAR.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/20, SCHWENCER, A. Licensing Branch 2. Spp. 19731:136. 24X Fiche: 50-352, 83/07/20, 8307260350.

- 8307260372 Forwards draft FSAR page change reflecting revised response to Question 430.62 re design basis seismic event.per 830719 telcon.Info will be incorporated into FSAR rev scheduled for Aug 1983.
  BRADLEY,E.J. Philadelphia Electric Co. 83/07/21. SCHWENCER.A. Licensing Branch 2. 4pp. 19733:057. 24X Fiche: 50-352.83/07/21, 8307260372.
- 8307260472 Submits info re components of program plan for Aug 1983 control room design review. Program will ref BWR Owners Group generic program plan & include qualifications & structure of review team.

  KEMPER, J. S. Philadelphia Electric Co. 83/07/21. 5CHWENCER, A. Licensing Branch 2. 3pp. 19734:165. 24X Fiche:50-352,83/07/21,8307260472.
- 8307280257 Forwards draft FBAR change to Section 6.2.4.3.1.3.2.3.per 830718 telcon w/Containment Sys Branch. Rev will be incorporated in FBAR amend scheduled for Aug 1983. BRADLEY, E. J. Philadelphia Electric Co. 83/07/22. SCHWENCER, A. Licensing Branch 2. 8pp. 19795: 280. 24X Fiche: 50-352, 63/07/22, 8307280257.
- B307280242 Forwards draft FSAR page changes addressing operator actions when entry level TRIP procedures met Changes will be incorporated into FSAR rev scheduled for Aug 1983.
  BRADLEY,E.J. Philadelphia Electric Co. 83/07/25. SCHWENCER,A. Licensing Branch 2. 4pp. 19790:161. 24X Fiche: 50-352.83/07/25. 8307280242.
- B307280294 Forwards response to Effluent Treatment Sys Branch 830718 request for add1 info re delta P recording across first HEPA filter of ESF cleanup sys.
  BRADLEY,E.J. Philadelphia Electric Co. 83/07/25. SCHWENCER,A. Licensing Branch 2. 5pp. 19789; 322. 24X Fiche: 50-352,83/07/25,8307280294.
- 8307280330 Forwards revised draft FSAR page change to TMI Item I.C. 8, "Pilot Monitoring of Selected Emergency Procedures for Near-Term OL Applicants."

  BRADLEY.E.J. Philadelphia Electric Co. 83/07/25, SCHWENCER.A. Licensing Branch 2. 4pp. 19790:057, 24X Fiche: 50-352, 83/07/25, 8307280330.
- B307280338 Forwards draft FSAR page change re availability of test procedures for fuel loading, initial startup testing & supporting activities. Info will be incorporated in Aug 1983 rev.

  BRADLEY, E. J. Philadelphia Electric Co. B3/07/25, BCHWENCER, A. Licensing Branch 2. 4pp. 19789:049, 24X Fiche: 50-352, 83/07/25, 8307280338.
- B307280420 Forwards add1 info re interlock setpoint value effect on ECCS analysis, in response to NRC B30713 request.Plant-unique calculations will be submitted in Feb 1784.
  BRADLEY,E.J. Philadelphia Electric Co. B3/07/28. SCHWENCER,A. Licensing Branch 2. 3pp. 19795:309. 24X Fiche:50-352,83/07/28,8307280420.
- B307270080 Forwards revised response to FSAR Question 430,47 re dc control relay & terminal box,per 830721 telcan. Info will be incorporated into FSAR rev schaduled for Aug 1983.
  BRADLEY,E.J. Philadelphia Electric Co. 83/07/26. SCHWENCER, A. Licensing Brench 2. 5pp. 19822:177. 24X Fiche: 50-352,83/07/26,8307290080.
- C. Utility Environmental Report (ER). amends & correspondence
- 8307190082 Forwards revised pages to Chapter 7 of "Severe Accident Risk Assessment" & "Impact of Flant Design Changes on Limerick Generating Station Severe Accident Risk Assessment (SARA)," per 830701 1tr re environ rept. Section 7.1. BRADLEY, E. J. Philadelphia Electric Co. 83/07/15, SCHWENCER, A. Division of Licensing, 2pp. 19635:249, 24X Fiche: 50-352, 83/07/15, 8307190082
- ---8307190072 Revised pages to Chapter 7 of "Severe Accident Risk Assessment." # Philadelphia Electric Co. 83/07/15. 136pp. 17635:251. 24X Fiche: 30-332.83/07/15.8307190082.
- ---8307190076 "Impact of Plant Design Changes on Limerick Generating Station Severe Accident Risk Assessment (SARA), " \* NUS Corp. 83/07/15. Bpp. 19636: 027. 24X Fiche: 50-352, 83/07/15, 8307190082.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- B307080500 Forwards FR notice of availability of DES (NUREQ-0974). BCHMENCER.A. Licensing Branch 2. 83/06/24. CHERRY.M. Cherry. M.M./Cherry. Flynn & Kanter. 4pp. 19365:051. 24x Fiche: 50-352.83/06/24.8307080500.

- --8307080510 Notice of availability of DES (NUREG-0974). BCHWENCER.A. Licensing Branch 2. 83/06/24. 3pp. 19365:055. 24X Fiche:50~352,83/06/24.8307080500.
- --8307080522 Forwards notice of availability of DES (NUREO-0974). Request for comments being sent to appropriate agencies. FES will be prepared after receipt of comments. SCHWENCER.A. Licensing Branch 2. 83/06/24. WILBON, K. Environmental Protection Agency. 19. 19365:058. 24X Fiche: 50-352,83/06/24,8307080500.
- --8307080525 Advises that DES issued Notice of availability encl.W/o DES. SCHWENCER, A. Licensing Branch 2. 83/06/24. BAUER, E. G. Philadelphia Electric Co. 4pp. 19365:089. 24X Fiche: 50-352,83/06/24,8307080500.
- --8307080527 Forwards DES (NUREO-0974) for review & comments. Comments are due within 45 days after FR publication. W/o encl.
  SCHWENCER.A. Licensing Branch 2. 83/06/24. WOOD, J. M. Commerce, Dept. of. Natl. Oceanographic & Atmospheric Administration. 5pp. 19365:063. 24X Fiche: 50-352,83/06/24,8307080500.
- 8307050479 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF LIMERICK GENERATING STATION, UNITS 1 AND 2, Docket Nos. 50-352 And 50-353. (Philadelphia Electric Company)

  \* Division of Licensing, NURS-0-074. 83/06/30. 331pp. 19261:035. 24X Fithe: 50-352,83/06/30,8307050479.
- B307200310 Concurs w/NRC conclusions re DES for facility, per NRC 830424 request. No detectable effects to Delaware River from facility operation expected.

  BARBIERI, N. J. Army, Dept. of. B3/07/15. Division of Licensing.

  1p. 1944B: 095. 24X Fiche: 50-352,83/07/15,8307200310.
- 8307260502 Advises of incorrect interpretation in DES of Delaware River Basin Commission water quality stds re mixing zone for discharge of constituents such as residual chlorine. HANSLER, O. M. Delaware River Basin Commission. 83/07/22. AULUCK, R. Office of Nuclear Reactor Regulation, Director. 1p. 19734:169. 24X Fiche: 50-352, 83/07/22, 8307260502.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307110641 Notification of 830711 meeting w/util in Bethesda, MD to discuss Instrumentation & Control Sys Branch SER open issues. Meeting agenda encl. ABELBON. H. Licensing Branch 2. 83/06/27. SCHWENCER, A. Licensing Branch 2. 8pp. 19434:055. 24X Fiche: 50-352, 83/06/27, 8307110641.
- B307060245 Forwards draft revised FBAR Sections 6.2.4 & 7.3 & Table 6.2-17, reflecting position on draft BER Item 15 re automatic isolation of containment isolation valves. Info will be included in FBAR rev scheduled for Jul 1983. BRADLEY, E. J. Philadelphia Electric Co. B3/07/01. BCHWENCER, A. Licensing Branch 2. 11pp. 19239:275. 24X Fiche: 50-352, 83/07/01, 8307060245.
- B307200449 Notification of B30707 meeting w/util in Bethesda.MD to discuss outstanding SER items in containment sys area; including potential for overpressurization of standby gas treatment sys duct work.

  MARTIN.R.E. Licensing Branch 2. B3/07/01. SCHWENCER.A. Licensing Branch 2. 4pp. 19672: 24B. 24X Fiche: 50-352, B3/07/01, B307200449.
- 8307150377 Notification of 830713 meeting w/util in Bethesda:MD to discuss status of development of SER & actions required to address all open issues: MARTIN:R.E. Licensing Branch 2. 83/07/09. SCHWENCER:A. Licensing Branch 2. 4pp. 17940: 324. 24X Fiche: 90-352,83/07/05.8307150377.
- 8307200384 Forwards request for add1 info re vibration monitoring program for all essential safety-related instrumentation lines per draft SER Section 3.9.2. Util 830404 ltr did not adequately address inaccessible instrumentation lines. SCHWENCER,A. Licensing Branch 2. 83/07/06. BAUER,E. G. Philadelphia Electric Co. 4pp. 19469:333. 24% Fiche: 50-352, 83/07/04, 8307.800384.
- B307120534 Forwards revised draft responses to draft SER Items 2,3,8 & 7 re fuel rod mechanical fracturing & fuel assembly structural damage. Responses will be incorporated into FSAR scheduled for release in Aug 1983.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/08. SCHWENCER, A. Licensing Branch 2. 7pp. 19433:322. 24X Fiche:50-352,83/07/08,8307120534.

- 8307150067 Forwards addl info re Item 6 of Radiological Assessment Branch draft SER concerning assignment of Taylor as special assistant to applied health physicist at Peach Bottom Atomic Power Station during Fall 1983 refueling outage. BRADLEY.E. J. Philadelphia Electric Co. 83/07/12. SCHWENCER.A. Licensing Branch 2. 3pp. 17548:185. 24X Fiche: 50-352,83/07/12-8307150067.
- G307150069 Forwards marked-up revised draft FSAR page changes per draft SER, resolving discrepancies & incorporating GESTAR II & ODYN analyses of pressurization transients into FSAR. BRADLEY, E. J. Philadelphia Electric Co. B3/07/12. SCHWENCER, A. Licensing Branch 2. 7pp. 19548:178. 24X Fiche: 50-352,83/07/12,8307150069.
- 8307150132 Forwards responses to Chemical Engineering Branch fire protection section, draft SER open review Items 17, 20, 22, 24 & 28. M/12 oversite drawings. Aperture cards are available in FDR.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/12. SCHWENCER, A. Licensing Branch 2, 27pp. 19536; 001. 24X Fiche: 50-352, 83/07/12, 8307150132.
- 8307180054 Forwards revised response to Core Performance Branch draft SER Item 10. "Post-Irradiation Burveillance." Fuel will be visually inspected at each refueling outage. Info will be incorporated into FSAR rev scheduled for Aug 1983. BRADLEY, E. J. Philadelphia Electric Co. 83/07/13. SCHMENCER, A. Licensing Brench 2. 3pp. 19560: 269. 24% Fiche: 50-352, 83/07/13, 8307180054.
- 6307250072 Summary of 630623 meeting w/util & Bechtel in Bethesda, MD re Auxiliary Sys Branch open SER issues. List of open SER issues encl. ABELSON. H. Licensing Branch 2. 83/07/15. Licensing Branch 2. 8pp. 19724: 086. 24X Fiche: 50-352, 83/07/15, 8307250072.
- 8307290483 Summary of 830711 meeting w/util.Bechtel & ANL in Bethesda. MD re Instrumentation & Control Sys Branch open SER issues. ABELBON.M. Licensing Branch 2. 83/07/20. Licensing Branch 2. 9ap. 19859: 092. 24X Fiche: 50-352, 83/07/20, 8307290483.
- F. Becurity, medical, emergency & fire protection plans
- 8307130232 Forwards Page 6-16 to Rev 2 to emergency plan, inadvertently not reproduced when amended Emergency plan will be corrected w/next amend. Related correspondence.

  METTERHANN,M. J. Conner & Wetberhahn. METTERHANN,M. J. Philadelphia Electric Co. 83/07/08. DRENNER,L., MORRIS.P.A., CDLE.R.F. Atomic Bafety and Licensing Board Panel. 2pp. 17465: 358. 24X

  Fiche: 50-352.63/07/08,8307130232.
- 8307150076 Forwards draft revised Pages 3-6,9-1 & 11-1 to security plan. Pages withheld (refs 10CFR2.790 & 10CFR73.21). Changes will be incorporated in security plan amend to be submitted in Aug 1783.

  8RADLEY, E. J. Philadelphia Electric Co. 83/07/12. SCHWENCER, A. Licensing Branch 2. 2pp. 17536:168. 24X Fiche: 50-352,83/07/12,8307150076.
- 8307150132 Forwards responses to Chemical Engineering Branch fire protection section, draft SER open review Items 17, 20, 22, 24 & 28, H/12 oversize grawings. Aperture cards are available in PDR.

  BRADLEY, U. J. Philadelphia Electric Co. 83/07/12, BCHMENCER, A. Litensing Branch 2, 27pp. 19538:001, 24X Fiche: 50-352, 83/07/12, 8307150132.
- O. Adjudicatory correspondence
- 8306030332 Order granting Commonwealth of PA 830526 motion for partial relief from ASLB requirements to coordinate filing of onsite emergency planning contentions. Commonwealth required to negotiate language of contentions.

  BRENNERIL. About Safety and Licensing Board Panel. 83/06/01.

  Pennsylvania. Commonwealth of. App. 18715: O3B. 24X

  Fichs: 50-352.83/06/01.8306030332.
- 8307060409 Answer opposing Del-Aware counsel 830616 ltr proposing new contention on use of supplemental cooling water from Point Pleasant diversion. ASLB does not have jurisdiction over issue Contificate of Byr encl.
  CONNER, T. B. Philadelphia Electric Co. CONNER, T. B. Conner & Watterhahn. 83706/30. Atomic Safety and Licensing Board Panel.
  App. 19234: 288. 24% Fiche: 50-352, 83/06/30, 8307060409.
- 8307070255 Answer opposing Limerick Ecology Action 830617 onsite emergency planning contentions. Contentions either lack requisite specificity & bases or fail to allege noncompliance wiregulations. Certificate of Svc encl. METTERHAMN, M. J. Philadelphia Electric Co. WETTERHAMN, M. J. Philadelphia Electric Co. WETTERHAMN, M. J. Conner & Metterhamn. 83/07/03. Atomic Bafety and Licensing Board Panel. 19267: 221. 24X Fiche: 50-352, 83/07/05, 8307070255.

- B307130194 Responds to telcon request re BNL review of util B30421 severe accident risk assessment BNL reviewers listed. HODDON, A.P. Hearing Branch 2. B3/07/08. DORSEY, J. A. Limerici Ecology Action. 2pp. 19465: 351. 24X Fiche: 50-352, 83/07/08. B307130196.
- B307130232 Forwards Page 6-16 to Rev 2 to emergency plan, inadvertently not reproduced when amended Emergency plan will be corrected w/next amend. Related correspondence.

  HETTERHAHN.M.J. Conner & Wetterhahn. METTERHAHN,M.J. Philadelphia Electric Co. B3/07/08. BRENNER.L., MORRIS.P.A., CDLE.R.F. Atomic Safety and Licensing Board Panel. 2pp. 19465:358. 24X

  Fiche: 50-352,83/07/08,8307130232.
- 8307180136 Forwards Limerick Ecology Action respecification of Contention I-42 per 830316 memorandum. Application did not show compliance w/830121 rule re environ qualification of electrical equipment.

  DDRSEY, J. A. Dorsey, J. A. DORSEY, J. A. Limerick Ecology Action.
  83/07/11. BRENNER, L., MORRIES, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel. ip. 19557:057. 24X Fiche: 50-352, 83/07/ii, 8307180136.
- --B3071B0142 Respecification of Contention I-42 re environ qualification of electrical equipment Certificate of Svc encl.

  \* Limerick Ecology Action. B3/07/11. App. 19557:058. 24X Fiche: 50-352,83/07/11,83071B0136.
- 8307140475 Response to Limerick Ecology Action 830617 onsite emergency planning contentions. Contentions VIII-3.4, 5, 6, 8, 9, 10 & 13 20 incomplete in whole or part due to unavailability of partinent details. W/Certificate of Svc. VOGLER.B.H. Hearing Branch 2. 83/07/12. Atomic Safety and Licensing Board Panel. 22pp. 19520:181. 24X Fiche: 50-352,83/07/12,8307140475.
- 8307150300 Responds to 830630 ltr re failure to receive documents. Name added to NRC distribution list. NRC 830620 ltr to util, summarizing NRC Caseload Forecast Panel 830413-15 site visit & 830721 meeting summary, encl.
  HDD00DN.A.P. Hearing Branch 2. 83/07/13. BUBH.M.W. Bush, M.W. 21pp. 17532:213. 24x Fiche: 50-352,83/07/13,8307150300.
- 8307180260 Memorandum & order rs Del-Aware 830616 ltr to ASLAB. Proposed contention denied. Contention vague & seems to address matters beyond ASLAB jurisdiction.

  BRENNER, L. Atomic Safety and Licensing Board Panel. 83/07/14.

  Del-Aware Unlimited, Inc. 3pp. 19356; 001. 24X

  Fiche: 50-352,83/07/14,8307180260.
- 8307190127 Second round of interrogatories re pressurized thermal shock. Related correspondence.
  LEWIS, M. Lewis, M. 83/07/15. Office of the Executive Legal Director. 2pp. 19636:051. 24X Fiche: 50~352,83/07/15,8307190127.
- 8307210230 Requests all available info responsive to 830603 first set of interrogatories & request for production of documents, including names, addresses & prof qualifications of all expert consultants & witnesses. Related correspondence.
  WETTERHAMN.M.J. Conner & Wetterhahn. METTERHAMN.M.J. Philadelphia Electric Co. 83/07/18. ANTHONY.R.L. Friends of the Earth. 2pp. 19469:059. 24X Fiche: 50-352, 83/07/18. 8307210230.
- 8307220364 Brief incorporating documents to avoid duplication.
  Cartificate of Bvc encl.
  SUGARMAN.R.J. Del-Aware Unlimited. Inc. BUGARMAN.R.J. Bugarman.
  R.J. 83/07/18. Atomic Safety and Licensing Appeal Panel. 3pp.
  19675:258. 24X Fiche: 50-352,83/07/18,8307220364.
- B30722037i Order striking Del-Aware Unlimited, Inc collection of documents purporting to constitute Del-Aware appellate brief supporting exceptions to ASLE B30308 & O601 decisions. Correct brief due by B30819.

  SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/07/20. Del-Aware Unlimited, Inc. 3pp. 19675; 271. 24X
  Fiche: 50-352,83/07/20,8307220371.
- B30729008B Forwards reply to NRC & util responses to desite emergency planning contentions & motion for extension of time to file contentions on Chapter 7 of environ rept OL stage.

  DORSEY.J.A. Dorsey. J.A. DORSEY.J.A. Limerick Ecology Action.
  B3/07/21. BRENNER.A., COLE,R.F., MORRIS,P.A. Atomic Safety and Licensing Board Panel. 1p. 19815:333. 24X Fiche:50-352,83/07/21,8307290088.
- ---B307290093 Reply to NRC & util responses to onsite emergency planning contentions, ABLB should admit contentions w/exceptions stated.

  DORSEY, J. A. Limerick Ecology Action. DORSEY, J. A. Dorsey, J. A. B3/07/21. Atomic Befety and Licensing Board Panel. 16pp. 19815: 334. 24X Fiche: 50-332, 83/07/21: B30729008B.

- --B307290079 Motion for extension until B30901 to file Chapter 7 environ rept OL contentions. Limerick Ecology Action consultant had not received suppl to supporting document as of B30719. Certificate of Bvc encl. DORSEY, J. A. Limerick Ecology Action. DORSEY, J. A. Dorsey, J. A. B3707/21. Atomic Safety and Licensing Board Panel. 4pp. 19815: 350. 24X Fiche: 50-352, B3/07/21. B30729008B.
- B307250152 Advises of placement in LPDR of portions of ACR6 Joint Bubcommittees on Indian Point Units 2 & 3 & Reliability & Probabilistic Assessment B30706 meeting discussing Limerick PRA.
  HODODON, A. P. Hearing Branch 2. B3/07/22. BRENNER, L., MORRIS, P. A., COLE, R.F. Atomic Safety and Licensing Board Panel. 1p. 19706:104. 24X Fiche: 50-352, B3/07/22, B307250152.
- 8307260375 Forwards A Love notice of appearance & DS Bronstein notice of withdrawal of appearance. Certificate of Svc encl. BRONSTEIN.D. S. Bronstein. D. S. BRONSTEIN.D. S. Graterford Prisoners. 83/07/22. BRENNER, L. Atomic Safety and Licensing Board Panel. 5pp. 19733:119. 24X Fiche: 50-352.83/07/22.8307260375.
- 8307280147 Hemorializes matters discussed on 830722. Documents recamburator icing to be sent to util. Resolution of discovery differences impossible.

  METTERHAHN.M.J. Conner & Wetterhahn. WETTERHAHN.M.J. Philadelphia Electric Co. 83/07/25. ROMAND.F. Romano.F. 2pp. 19792:045. 24X Fiche: 50-352.83/07/25. 8307280147.
- 8307280246 Objections to certain RL Anthony & Friends of the Earth in Delaware Valley 630714 Interrogatories & requests for documents. Interrogatories exceed scope of admitted contentions.
  WETTERHAHN.M. J. Philadelphia Electric Co. WETTERHAHN.M. J. Conner & Wetterhahn. 83/07/25. Anthony, R. L. 3pp. 19795: 288. 24X Fiche: 50-352.83/07/25,8307280246.
- --B307280254 Answer opposing admission of Limerick Ecology Action 830711 revised Contention I-42 re qualification of electric equipment exposed to harsh environs. Contention lacks specificity & basis or is premature. Certificate of Svc encl. METTERHAHN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn, B3/07/25. Atomic Safety and Licensing Doard Fanel. 1ipp. 19795:293. 24X Fiche: 50-352, 83/07/25, 8307280246.
- 8307280144 Second Special Prehearing Conference Order LBP-83-37 re 830509-11 prehearing conference in Philadelphia, PA on proposed contentions & further scheduling, Contentions I-8, I-15 & I-33M admitted Courtesy notification encl.

  BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel. 83/07/26. 44pp. 19792;001. 24X Fiche: 50-352,83/07/26,83/0280144.
- 8307280149 Informs of agreement in furtherance of memorandum & order confirming schedules established during 830516 prehearing conference. Draft emergency plans will be delivered to coursel for Limerick Ecology Action.

  HETTERHAHN.M.J. Conner & Wetterhahn. WETTERHAHN.M.J. Philadelphia Electric Co. 83/07/26. BRENNER.L., MORRIS, P.A., COLE, R.F. Atomic Safety and Licensing Board Pansl. 2pp. 19791: 361. 24X Fiche: 50-352, 83/07/26, 8307280169.

## H. General correspondence

- 8307050179 Requests replacement of WW Goode w/MW Bush on mailing list. BUSH:M.W. Philadelphia, PA. 83/06/29. SCHWENCER.A. Licensing Branch 2. 1p. 19199:186. 24X Fiche:50-352,83/06/29,8307050179.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010185 Forwards Amend 52 to OL application, consisting of Rev 21 page changes to FBAR per NRC 830308 & 0603 ltrs & Rev 4 page changes to design assessment rept.

  BRADLEY,E.J. Philadelphia Electric Co. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19186:356, 24% Fiche: 50-352, 83/06/30, 8307010185.
- --8307010190 DL application consisting of Rev 21 page changes to FSAR & Rev 4 page changes to design assessment rept.

  BUVER.V.S. Philadelphia Electric Co. B3/06/27. App. 19186:359.
  24% Fiche: 50-352, B3/06/30.8307010185.
- --8307010192 Rev 4 page changes to design assessment rept. \* Philadelphia Electric Co. 83/06/30. 49pp. 19187:003. 24X Fiche: 50-352, 83/06/30, 8307010185.
- ---8307010193 Rev 21 to FBAR. \* Philadelphia Electric Co. 83/06/30. 589pp. 19187:064. 24X Fiche: 50-352.83/06/30.8307010185.

- 8307280063 Forwards Affidavit of Svc re distribution of Rev 21 to FSAR, per 810706 1tr.
  BRADLEY,E.J. Philadelphia Electric Co. 83/07/20. DENTON.H.R.
  Office of Nuclear Reactor Regulation, Director. 3pp. 19791:201.
  24X Fiche: 50-352,83/07/20,8307280063.
- G. Inspection reports, IE Bulletins & correspondence
- 8307010152 Forwards IE Insp Repts 50-352/83-06 & 50-353/83-03 on 830516-20. No noncompliance noted.
  MARTIN.T.T. Division of Engineering & Technical Programs. 83/04/14. KEMPER.J.S. Philadelphia Electric Co. 2pp. 19175: 326. 24X Fiche: 50-352,83/06/14,8307010152.
- ---B307010161 IE Insp Repts 50-352/83-06 & 50-353/83-03 on B30516-20. No noncompliance noted. Major areas inspected installation of electrical/instrument components & sys in areas of receipt insp. matl qualification & insp. PADLIND.R. J. ANDERBON, C. J. Region 1, Office of Director. B3/06/07. Spp. 19175:328. 24X Fiche: 50-352,83/06/14,8307010152.
- 8307210070 Forwards IE Insp Repts 50-392/83-08 & 50-353/83-05 on 830529-0604 & notice of violation. STARDSTECKI.R. Division of Project & Resident Programs. 83/07/05. KEMPER, J. S. Philadelphia Electric Co. 2pp. 17668:250. 24X Fiche: 50-352,83/07/05,8307210070.
- --8307210073 Notice of violation from insp on 830527-0624.

  \* Division of Project & Resident Programs. 83/07/05. 1p. 19668: 252. 24% Fiche: 50-352, 83/07/05, 8307210070.
- --8307210078 IE Insp Repts 50-352/83-08 & 50-353/83-05 on B30529-0624.
  Noncompliance noted: failure to label harizontal shock
  arrestors GBB-102-H34 & HBB-118-H40 w/ "keep off" signs.
  GRANT.J.M. Division of Project & Resident Programs.
  CHAUDHARY.S.K., GONNER.E.L. Region 1, Office of Director.
  83/06/29. 9pp. 19468:253. 24X Fiche: 50-352,83/07/05,8307210070.
- 8307120503 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/83-05 & 50-353/83-02.

  8TARGSTECKI,R. Division of Project & Resident Programs. 83/07/06. KEMPER, J. S. Philadelphia Electric Co. 2pp. 19433:247. 24X Fiche: 50-352,83/07/06,8307120503.
- --8307120508 Responds to NRC 830526 ltr re violations noted in IE Insp Repts 50-352/83-05 & 50-353/83-02. Corrective actions: project QC Instruction E-2. O revised & Drawing FJ-44-18 revised to include steel barrier per Section 10.0 of M-830. KEMPER.J. S. Philadelphia Electric Co. 83/06/24. MURLEY.T.E. Region 1. Uffice of Director. App. 17433: 249. 24X Fiche: 50-352, 63/07/06, 6307120503.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Syc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8307180054 Forwards revised response to Core Performance Branch draft SER Item 10, "Post-Irradiation Surveillance." Fuel will be visually inspected at each refueling outage. Info will be incorporated into FSAR rev scheduled for Aug 1983.

  BRADLEY.E.J. Philadelphia Electric Co. 83/07/13. SCHWENCER.A. Licensing Branch 2. 3pp. 19560:269. 24X Fiche:50-352.83/07/13, 8307180054.
- 8306270406 IE Info Notice 83-48, "Cassous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguard: & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715; 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- B307280453 Forwards SALP rept for Jan-Dec 1982, conducted on B30418 & discussed on B30502. Overall performance in const area acceptable.

  MURLEY, T. E. Region i, Office of Director. B3/07/18. KEMPER, J. S. Philadelphia Electric Co. 3pp. 19797; 260. 24X
  Fiche: 50-352, 83/07/18, 8307280453.
- --B307280459 SALP rept for Jan-Dec 1982.

  \* Region i Office of Director. 83/04/18. 30pp. 19797:263. 24X Fiche: 50-352.83/07/18.8307280453.

- --830728046i Forwards SALP Board rept conducted on 830418 Meeting scheduled for 830502 to discuss performance assessment & any plans for improvement Written comments requested within 20 days of meeting M/o encl.
  8TAROSTECKI,R. Division of Project & Resident Programs. 83/04/28. KEMPER,J. S. Philadelphia Electric Co. lp. 19797: 293. 24X Fiche: 50-352, 83/07/18, 8307280453.
- --8307280463 Comments on B30502 SALP meeting GA engineer will be added to audit electrical work & reaudit program w/mmphasis on deficient areas.

  KEMPER. J. S. Philadelphia Electric Co. 83/05/19. ALLAN, J. M. Region i, Office of Director. 4pp. 19797:294. 24X

  Fiche: 50-352,83/07/18,8307280453.
- 8307280288 Responds to violations noted in IE lasp Repts 50-352/83-08 & 50-353/83-05 on 830529-0604. Corrective actions: pipe shock arrestors GBE-102-H34 & H8B-118-440 have been labeled as required. KEMPER, J. S. Philadelphia Electric Co. 83/07/25. MURLEY, T. E. Region i, Office of Director. 3pp. 19790: 054. 24X Fiche: 50-352, 83/07/25, 8307280288.
- S. Reportable occurrences, LERs & related correspondence
- 8307120216 Significant Deficiency Rept 74 re 4 kV switchgear supplied by Brown-Bover; Inc. Initially reported on 830225. Circuit breakers & ground trucks will have spring added to close hatch. Final rept will be provided by 830826.
  KEMPER, J. 5. Philadelphia Electric Co. 83/06/24. MURLEY, T. E. Region 1. Dffice of Director. 4pp. 19423:259. 24X Fiche: 50-352,83/06/24,8307120216.
- 8307110371 Final Deficiency Rept 83-03 re medium voltage circuit breakers of same type installed at Limerick which inadvertently closed after completion of spring charging due to slipped close latch, discussed in Brown Boveri 830524 ltr. SCHROEDER: C.W. Commonwealth Edison Co. 83/07/07. KEPPLER: J. G. Region 3. Office of Director. 5pp. 19380: 266. 24X Fiche: 50-000: 83/07/07, 8307110371.
- --8307i10377 Followup interim rept re potential deficiency in 5HX switchgear supplied by Brown Boveri. Circuit breaker inadvertently closed & tripped following spring charging. Light spring added to close latch.

  DVALL.D.D. Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.).

  83/04/28. STELLO.V. Director's Office. Office of Inspection and Enforcement. 2pp. 19380:271. 24X Fiche: 50-000.83/07/07, 830710371.
- 8307130015 Final Significant Deficiency Rept 84 re defect in motor operated valve tandem torque switches. One torque switch in each tandem assembly removed/reconfiguring switches to Limitorque std configuration.

  KEMPER. J. S. Philadelphia Electric Co. B3/07/08, HURLEY, T. E. Region I. Office of Director. 3pp. 19474: 209. 24X

  Fichs: 50-352, 83/07/08, 8307130015.
- DOCKET 50-953 LIMERICK GENERATING STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- B208060366 Board Notification B2-70:notifies of differing prof opinion resentitization of BNR stainless steel weldments.
  EISENMUT.D.O. Division of Licensing. B2/07/20. PALLADINO, N. J.
  Commissioners. 4pp. 17043:001. 24X Fiche: 50-000,82/07/20,8208060366.
- --B302040562 Forwards request for add1 info re reactor internals matls, JOHNSTON, M.V. Assistant Director for Matls & Qualif. Engineering (Pre B30201). 82/05/14. TEDESCO.R.L. Assistant Director for Licensing. 2pp. 17043:089. 24X Fiche:50-000.82/07/20.8208060366.
- B307070556 Summary of B3060B meeting w/util, NUS, J Benjamin & Assoc, BNL & Structural Mechanics Assoc in Bethesda, MD re severe accident risk assessment. Viewgraphs encl.

  MARTIN.R.E. Licensing Branch 2. 83/06/27. Licensing Branch 2. 166pp. 19344:125. 24X Fiche: 50-352, B3/06/27, 8307070556.
- 8307080543 Forwards Equipment Qualification Branch request for add1 info re NUREO-0737, Item II.D.1 re review of NEDE-24988-P. For specific safety/relief valves employed at plant, applicability of generic test results must be justified. SCHHENCER.A. Licensing Branch 2: 83/06/27, BAUER.E. 0. Philadelphia Electric Co. 4pp. 19365:043, 24X Fich=: 30-352,83/06/27,8307080543.

- 8307010093 Forwards response to Core Performance & Reactor Sys Branch telcon requests for addl info re differences in pressurization transient results between Limerick & other BMR plants of similar design.
  BRADLEY, E. J. Philadelphia Electric Co. 83/06/28. SCHWENCER, A. Licensing Branch 2. 3pp. 19124: 217. 24X Fiche: 50-352: 83/06/28. 8307010093.
- 8307070549 Summary of 830623 meeting w/util.Bechtel.GE & Koch Process Sys.Inc re offgas sys explosion resistance.Meeting handouts encl. MARTIN.R.E. Licensing Branch 2. 83/06/28. Licensing Branch 2. 13pp. 19344:112. 24X Fiche:50-352.83/06/28.8307070549.
- 8307130006 Provides statement of position re in-plant communication sys. Communication sys not seismically supported Response requested in 7 days of itr receipt.

  8CHWENCER, A. Licensing Branch 2. 83/06/28. BAUER, E. G. Philadelphia Electric Co. 3pp. 19525: 355. 24X

  Fiche: 30-352,83/06/28,8307130006.
- 8307130271 Forwards revised draft response & FBAR page changes to NRC Question 460,5 re air intake sys & addl info re EBF filter sys instrumentation in response to 830524 & 060B telcons. BRADLEY.E. J. Philadelphia Electric Co. B3/06/28. SCHWENCER.A. Licensing Brench 2, 23pp. 19508:256. 24X Fiche: 50-352:83/06/28. B307130271.
- 8307070037 Forwards draft rev to Page 11.5-39 of FBAR re gas analysis & core damage per 830628 request. Page will be incorporated in FBAR rev scheduled for Aug 1983.
  BRADLEY.E. J. Philadelphia Electric Co. 83/06/29. 8CHWENCER.A. Licensing Branch 2. 4pp. 19293:247. 24X Fiche: 50-352,83/06/29,8307070037.
- B307070286 Forwards draft rev to Request for Add1 Info 210.82 rebalance of plant supports designed to Subsection NF & related FSAR page changes.

  BRADLEY, E. J. Philadelphia Electric Co. B3/06/29. SCHWENGER, A. Licensing Brench 2. 5pp. 19267:330. 24X Fiche: 50-352, 83/06/29, 8307070286.
- 8307010185 Forwards Amend 52 to DL application.consisting of Rev 21 page changes to FBAR per NRC 830308 & 0403 ltrs & Rev 4 page changes to design assessment rept.

  BRADLEY.E.J. Philadelphia Electric Co. 83/04/30. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19186:356, 24X Fiche: 50-352, 83/04/30, 8307010185.
- --8307010170 OL application consisting of Rev 21 page changes to FBAR & Rev 4 page changes to design assessment rept.

  BOYER.V.S. Philadelphia Electric Co. 83/06/27. App. 19186:359.
  24X Fiche:50-352,83/06/30,8307010185.
- --8307010192 Rev 4 page changes to design assessment rept. \* Philadelphia Electric Co. 83/06/30. 49pp. 19187:003. 24X Fiche: 50-352, 83/06/30, 8307010185.
- 8307070167 Forwards Chapters 5.6 & B.App A to Chapter 5 & revised table of contents to "Bevere Accident Risk Assessment." Chapter 7 will be provided in near future. BRADLEY.E.J. Philadelphia Electric Go. B3/07/01. SCHWENCER.A. Division of Licensing. 2pp. 17267:072. 24X Fiche: 50-352, 83/07/01, 8307070167.
- --8307070170 Chapters 5,6 & 8,App A to Chapter 5 & revised table of contents to "Bavere Accident Risk Assessment."

  \* Philadelphie Electric Co. 83/07/01. 117pp. 19867:094, 24X Fiche: 50-352,83/07/01,8307070167.
- 8307150389 Notification of 830708 meeting w/util & consultants in Newport Beach, CA to discuss seismic aspects of plant severe accident risk assessment.

  MARTIN.R.E. Licensing Branch 2. 83/07/01. SCHWENCER, A. Licensing Branch 2. 4pp. 19540: 322. 24X Fiche: 50-352, 83/07/01, 8307150389.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity. Svc list encl. EIBENHUT, D. 9. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York: Inc. 16pp. 17390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- 8307080276 Forwards draft FSAR pages containing add1 info re isolation of purgs & vent valves on high radiation.per Containment Sys Branch request at 830615 mesting. Info will be incorporated into FSAR rev scheduled for Aug 1983.

  BRADLEY.E.J. Philadelphia Electric Co. 83/07/05. SCHWENCER.A. Licensing Branch 2. 8pp. 19351:183. 24X Fiche: 50-352,83/07/05,8307080276.

- 8307080300 Advises that responses to QA Branch 830407 Requests for Add1 Info 260.56 & 260.57 will be provided by 830722. BRADLEY, E. J. Philadelphia Electric Co. 83/07/05. SCHMENCER, A. Licensing Branch 2. 2pp. 19351:179. 24X Fiche: 50-352,83/07/05. B307080300.
- 8307080505 Forwards draft rev to Mechanical Equipment Branch Request for Add1 Info RAI 210.33 re operability of feedwater isolation check valves. Info will be incorporated into next FSAR rev.scheduled for Aug 1983.
  BRADLEY.E. J. Philadelphia Electric Co. 83/07/05. SCHHENCER.A. Licensing Branch 2. App. 19346:338. 24X Fiche:50-392.83/07/05, 8307080505.
- 8307150373 Notification of 830712 meeting w/util in Bethesda.MD to discuss outstanding items in Power Sys Branch review. including util appeal of NRC position on communications sys. MARTIN.R.E. Licensing Branch 2. 83/07/05. 8CHWENCER.A. Licensing Branch 2. 4pp. 19540:337. 24X Fichs:50-352.83/07/05.8307150373.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STB. 8vc list encl. EISENHUT. D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000. 83/07/06. 8307060329.
- B307110272 Requests info re decision to conduct B30413~15 caseload forecast panel meeting & tour only at Unit 1. BUGARMAN.R.J. Sugarman. R.J. B3/07/06. HAUGHEY.M.F. Licensing Branch 2. ip. 19379:140. 24X Fiche: 50-352:83/07/06:8307110272.
- B307110491 Forwards draft revs to responses to Questions 410.10 & 410.12 re analysis for rotating components & tornado missile spectrum.Responses will be incorporated in FBAR rev scheduled for Aug 1983.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/06. BCHWENCER, A. Licensing Branch 2. 15pp. 19380:151. 24X Fiche: 50-352, 83/07/06, 8307110491.
- B307120484 Informs that util has elected to address chugging phenomenon by capping downcomers on which wetwell/drywell vacuum breakers are mounted. Pool swell phenomenon addressed by listed mods to vacuum breakers.

  KEMPER.J. S. Philadelphia Electric Co. 83/07/06. SCHWENGER.A. Licensing Branch 2. 3pp. 19425:076. 24X Fiche: 50-352,83/07/06,8307120484.
- 8307110459 Forwards response to Structural Engineering Branch Guestion 220.82(b) re damping value for electrical raceway sys.
  Response will be incorporated into FSAR Rev 23 scheduled for Aug 1983.
  BRADLEY, E. J. Philadelphia Electric Co. 83/07/07. 8CHWENCER, A. Licensing Branch 2. 6pp. 19380:124. 24X Fiche: 50-352,83/07/07,8307110459.
- 8307120330 Forwards response to Environ Qualification Branch & Containment Bys Branch requests for info re containment purge & vent valve operability. Encl draft FBAR pages to be incorporated in Aug 1983 rev. Seismic rept by 830801.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/07. SCHWENCER, A. Licensing Branch 2. 13pp. 19431:155. 24X Fichs: 50-352, 83/07/07, 8307120330.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:267. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307150075 Forwards NEDD-10678, "Seismic Qualification of Class I Electrical Equipment," in response to R Martin 830609 request. BRADLEY, E. J. Philadelphia Electric Co. 83/07/12. SCHWENCER, A. Division of Licensing. 2pp. 19535:287, 24X Fiche: 50-352,83/07/12.
- 8307150300 Responds to 830630 ltr re failure to receive documents. Name added to NRC distribution list NRC 830620 ltr to util, summarizing NRC Caseload Forecast Panel 830413-15 site visit & 830721 meeting summary, encl.
  HDD0DDN.A.P. Hearing Branch 2. 83/07/13. BUSH, M.W. Bush, M.W. 21pp. 19532:213. 24X Fiche: 50-352,83/07/13.8307150300.
- B307190118 Forwards draft rev to Request for Add1 Info RAI 210,82 & related FSAR pages containing info requested by Machanical Engineering Branch per B30701 telcon re balance of plant supports. Changes supersede info sent by B30629 ltr.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/13. SCHWENCER, A. Licensing Branch 2. 5pp. 19635:001. 24X Fiche: 50-352,83/07/13,8307190118.

- B307190121 Forwards draft rev to FSAR Section 9.1.6.1.12.C & responses to Questions 430.57 & 430.62 re medium & lower voltage sys. Changes will be incorporated into FSAR rev scheduled for Avg 1983.

  BRADLEY.E.J. Philadelphia Electric Co. B3/07/15. BCHHENCER.A. Licensing Branch 2. 14pp. 19634:322. 24X Fiche: 50-352.83/07/15. B307190121.
- 830/7190197 Forwards draft rev to response to FSAR Questions 220.2 re pressure transient caused by design basis tornado per 830624 telcon. Info will be incorporated into FSAR rev scheduled for Aug 1983.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/15. SCHWENCER, A. Licensing Branch 2. 8pp. 19630:130. 24X Fiche: 50-352,83/07/15,820/190197
- 8307260406 Forwards marked-up FSAR pages, per Instrumentation & Control Bys Branch request during 830711 meeting. Info will be incorporated into FSAR rev scheduled for Aug 1983. Requested info inappropriate for incorporation into FSAR provided. KEMPER. J. S. Philadelphia Electric Co. 83/07/18. SCHMENCER. A. Licensing Branch 2. 31pp. 19733: 210. 24X Fiche: 50-352, 83/07/18. 8307260406.
- 8307250316 Advises that FSAR Figure 9.4-5 will be revised to show that hyrogen bottles now placed outside reactor bidg & number of bottles reduced. Next rev scheduled for August 1983.
  KEMPER, J. S. Philadelphia Electric Co. 83/07/20. 8CHMENCER, A. Licensing Branch 2. 2pp. 19701:341. 24X Fiche: 50-352,83/07/20,8307250316.
- 8307260147 Forwards draft changes to FBAR Sections 1.13 & 6.2.4.3.1.2.
  1.1 re influent lines & feedwater lines, per Containment
  Sys Branch 830717 telcon. Changes will be incorporated into
  FBAR.
  BRADLEY, E. J. Philadelphia Electric Co. 83/07/20, SCHWENCER, A.
  Licensing Branch 2. 7pp. 19727:279. 24X Fiche: 50-352,83/07/20,
  8307260147.
- B307260350 Forwards revised response to B30411 Question 210.92 re RHR sys quality classification. Info will be incorporated in Aug rev to FSAR.

  BRADLEY.E. J. Philadelphia Electric Co. B3/07/20. BCHMENCER. A. Licensing Branch 2. Bpp. 19731:136. 24X Fiche: 50-352,83/07/20. B307260330.
- B307260372 Forwards draft F9AR page change reflecting revised response to Question 430.62 re design basis seismic event, per B30719 telcon. Info will be incorporated into FSAR rev scheduled for Aug 1983.

  BRADLEY, E. J. Philadelphia Electric Co. B3/07/21. BCHWENCER, A. Licensing Branch 2. 4pp. 19733:057. 24X Fiche: 50-352, 83/07/21, 8307260372.
- B307260472 Bubmits info re components of program plan for Aug 1983 control room design review. Program will ref BWR Owners Group generic program plan & include qualifications & structure of review team.

  KEMPER.J. 5. Philadelphia Electric Co. 83/07/21. SCHWENCER.A. Licensing Branch 2. 3pp. 19734:165. 24X Fiche: 50-352,83/07/21,8307260472.
- 8307280257 Forwards draft FBAR change to Section 6, 2, 4, 3, 1, 3, 2, 3, per 830718 telcon w/Containment Sys Branch. Rev will be incorporated in FSAR amend scheduled for Aug 1983. IRADLEY,E. J. Philadelphia Electric Go. 83/07/22, 8CHWENCER,A. Licensing Branch 2, 8pp. 19795:280. 24X Fiche: 50~352,83/07/22,8307280257.
- 8307280242 Forwards draft FSAR page changes addressing operator actions when entry level TRIP procedures met. Changes will be incorporated into FSAR rev scheduled for Aug 1983. BRADLEY.E. J. Philadelphia Electric Co. 83/07/25. SCHWENGER, A. Licensing Branch 2. 4pp. 19790:161, 24X Fiche: 50-352,83/07/25,8307280242.
- B307280294 Forwards response to Effluent Treatment Sys Branch 830718 request for additinfo re delta P recording across first HEPA filter of EGF cleanup sys.
  BRADLEY,E.J. Philadelphia Electric Co. 83/07/25, SCHWENCER,A.
  Licensing Branch 2, 5pp. 19789:322, 24X Fiche: 50-352,83/07/25,8307280294,
- 8307280330 Forwards revised draft FBAR page change to TMI Item I.C.S. "Pilot Monitoring of Selected Emergency Procedures for Near-Term DL Applicants."

  BRADLEY,E.J. Philadelphia Electric Co. 89/07/25. BCHWENCER, A. Licensing Branch 2. 4pp. 17790:057. 24X Fiche: 50-352,83/07/25,830/28030.

- 8307280338 Forwards draft FSAR page change re availability of test procedures for fuel loading, initial startup testing & supporting activities. Info will be incorporated in Aug 1983 rev
  BRACLEV.E J. Philadelphia Electric Co. 83/07/25. SCHMENCER.A. Licensing Branch 2 4pp. 19789:049. 24X Fiche: 50-352,83/07/25,6307280338
- 8307280420 Forwards addl info re interlock setpoint value effect on ECCS analysis.in response to NRC 830715 request Plant-unique calculations will be submitted in Feb 1984.
  BRADLEV.E J Philadelphia Electric Co. 83/07/25. SCHMENCER.A. Licensing Branch 2. 3pp. 19795:309. 24% Fiche: 50-352,83/07/25,8307280420
- 8307290080 Forwards revised response to FSAR Question 430.47 re dc control relay & teroinal to:.per 830721 telcon. Info will be incorporated into FSAR rev scheduled for Aug 1983.
  BRADLEY.E J Philadelphia Electric Co. 83/07/26. 9CHMENCER.A. Licensing Branch 2. 5pp. 19822:177. 24X Fiche:50-352,83/07/26,8307290080.
- C Utility Environmental Report (ER), amends & correspondence
- B307190082 Forwards revised pages to Chapter 7 of "Severe Accident Risk Assessment" & "Impact of Plant Design Changes on Limerick Generating Station Severe Accident Risk Assessment (SARA): "per B30701 litr me environ rept-Section 7.1.

  BRADLEV.E. J. Philadelphia Electric Co. B3/07/15. BCHWENCER.A. Division of Licensing. 2pp. 17635:249. 24X Fiche: 50-352,83/07/15,8307190082.
- --8307190096 "Impact of Plant Design Changes on Limerick Generating Station Severe Accident Risk Assessment (SARA)." • NUS Corp. 83/07/15. 8pp. 19636:027. 24X Fichs: 50-352.83/07/15.8307190082.
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8307080500 Forwards FR notice of availability of DES (NUREO-0974). SCHWENCER:A Licensing Branch 2 83/06/24. CHERRY, M. Cherry. M. M. /Cherry. Flynn & Kanter. 4pp. 19365:051. 24X Fiche: 50-352:83/06/24.8307080500.
- --8307080510 Notice of availability of DES (NUREG-0974). SCHMENCER.A. Licensing Branch 2. 83/06/24. 3pp. 19365:055. 24X Fiche: 50-352.83/06/24.8307080500.
- --8307080522 Forwards notice of availability of DES (NUREO-0974). Request for comments being sent to appropriate agencies. FES will be prapared after receipt of comments. SCHMENGER.A. Licensing Branch 2. 83/06/24. WILSON, K. Environmental Protection Agency. 1p. 19365: 058. 24X Fiche: 30-332, 83/06/24, 8307080500.
- --8307080325 Advises that DES issued. Notice of availability encl. H/o DES.
  SCHWENCER. A Licensing Branch 2. 83/06/24. BAUER. E. G. Philadelphia Electric Co. 4pp. 19365: 059. 24X
  Fiche: 50-352, 83/06/24, 8307080500.
- --8307080527 Forwards DES (MUREO-0974) for review & comments.Comments are due within 45 days after FR publication.W/o encl.

  SCHWENCER.A. Licensing Branch 2. 83706/24. WDOD.J.M. Commerce. Dept. of, Natl. Oceanographic & Atmospheric Administration. 3pp. 19365-063 24x Fiche: 50-352,83/06/24,8307080500.
- B307050479 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF LIMENICK GENERATING STATION.UNITS 1 AND 2 Docket Nos. 50-352 And 50-353 (Philadelphia Electric Company) Division of Licensing. NUREQ-0974. 83/06/30. 331pp. 19261:035. 24X Fiche: 50-352-83/06/30.8307050479.
- B307200310 Concurs w/NRC conclusions re DES for facility.per NRC 830624 request No detectable effects to Delaware River from facility operation expected.

  BARBIERI.N. J. Aray. Dept. of. B3/07/15. Division of Licensing. ip. 19448:095. 24% Fiche: 50-352.83/07/15.8307200310.
- B307260502 Advises of incorrect interpretation in DES of Delaware River Basin Commission water quality stds re mixing zone for discharge of constituents such as residual chlorine.

  HANGLERO H. Delaware River Basin Commission. B3/07/22. AULUCK.R. Office of Nuclear Reactor Regulation. Director. ip. 19734:169. 24X Fiche 30-332.B3/07/22.B307260502.

- E. NRC Safety Evaluation Report (SER), supple & correspondence
- B307110641 Notification of B30711 meeting w/util In Bethesda, MD to discuss Instrumentation & Control Sys Branch SER open issues. Meeting agenda encl. ABELSON.H. Licensing Branch 2. 83/06/27. SCHWENCER.A. Licensing Branch 2. 8pp. 19434:055. 24X Fiche: 50-352, 83/06/27, 8307110641.
- 8307060245 Forwards draft revised FSAR Sections 6.2.4 & 7.3 & Table 6.2-17.reflecting position on draft SER Item 15 re automatic isolation of containment isolation valves. Info will be included in FSAR rev scheduled for Jul 1983. BRADLEY.E.J. Philadelphia Electric Co. 83/07/01. SCHWENCER.A. Licensing Branch 2. 11pp. 19239: 275. 24X Fiche: 50-352, 83/07/01, 8307060245.
- 8307200449 Notification of 830707 meeting w/util in Bethesda, MD to discuss outstanding SER items in containment sys area, including potential for overpressurization of standby gas treatment sys duct work.

  MARTIN.R.E. Licensing Branch 2. 83/07/01, SCHWENGER, A. Licensing Branch 2. 4pp. 19672:248. 24X Fiche: 50-352,83/07/01,8307200449.
- 8307150377 Notification of 830713 meeting w/util in Bethesda.MD to discuss status of development of SER & actions required to address all open issues. MARTIN.R.E. Licensing Branch 2. 83/07/05. 8CHWENCER.A. Licensing Branch 2. 4pp. 19540:326. 24X Fiche:50-352,83/07/05.8307150377.
- 8307200384 Forwards request for add1 info re vibration monitoring program for all assential safety-related instrumentation lines per draft SER Section 3. 9. 2. Util 830404 ltr did not adequately address inaccessible instrumentation lines. SCHWENCER. A. Licensing Branch 2. 83/07/06. BAUER. E. 0. Philadelphia Electric Co. 4pp. 17669: 333. 24X Ficha: 50-352.83/07/06.8307200384.
- 8307120534 Forwards revised draft responses to draft SER Items 2,3,8 & 9 re fuel rod machanical fracturing & fuel assembly structural damage. Responses will be incorporated into FSAR scheduled for release in Aug 1983.

  8RADLEY.E. J. Philadelphia Electric Co. 83/07/08. SCHWENCER.A. Licensing Branch 2. 7pp. 17433:322. 24X Fiche:50-352,83/07/08,8307120534.
- B307150047 Forwards add1 info re Itsm 6 of Radiological Assessment Branch draft SER concerning assignment of Taylor as special assistant to applied health physicist at Peach Bottom Atomic Power Station during Fall 1993 refueling outage.

  BRADLEY.E.J. Philadelphia Electric Co. 83/07/12, SCHHENCER.A. Licensing Branch 2. 3pp. 19548:185, 24X Fiche: 50-352,83/07/12,8307150067.
- 8307150069 Forwards marked-up revised draft FBAR page changes per draft SER:resolving discrepancies & incorporating GESTAR II & DDYN analyses of pressurization transfents into FBAR.
  BRADLEY.E. J. Philadelphia Electric Co. 83/07/12. BCHWENCER.A. Licensing Branch 2. 7pp. 19548:178. 24X Fichs:50-352,83/07/12,8307150069.
- B307150132 Forwards responses to Chemical Engineering Branch fire protection section, draft SER open review Items 17, 20, 22, 24 & 28. M/12 oversize drawings. Aperture cards are available in PDR.

  BRADLEY, E. J. Philadelphia Electric Co. 83/07/12. 8CHWENCER, A. Licensing Branch 2. 27pp. 19538: 001. 24X Fiche: 50-352, 83/07/12, 8307150132.
- 8307180054 Forwards revised response to Core Performance Branch draft SER Item 10, "Post-Irradiation Surveillance." Fuel will be visually inspected at each refueling outage. Info will be incorporated into FSAR rev scheduled for Aug 1983.

  BRADLEY.E. J. Philadelphia Electric Co. 83/07/13. BCHWENGER, A. Licensing Branch 2. 3pp. 19560; 269. 24X Fiche: 50-352, 83/07/19, 8307180054.
- 8307250072 Summary of 830623 meeting w/util & Bechtel in Bethesda, MD re Auxiliary Sys Branch open SER issues. List of open SER issues encl. ABELSON, H. Licensing Branch 2. 83/07/15. Licensing Branch 2. 8pp. 19724:086. 24X Fiche:50-352,83/07/15,8307250072.
- 8307290483 Summary of 830711 meeting w/util.Bachtel & ANL in Bethesda, MD re Instrumentation & Control Sys Branch open SER issues. ABELSON.H. Licensing Branch 2. 83/07/20. Licensing Branch 2. 9pp. 19859:092. 24X Fiche: 50-352,83/07/20,8307290483.

## F. Security, medical, emergency & fire protection plans

- B307150076 Forwards draft revised Pages 3-6,9-1 & 11-1 to security plan. Pages withheld (refs 10CFR2.790 & 10CFR73.21). Changes will be incorporated in security plan amend to be submitted in Aug 1983.
  BRADLEY.E. J. Philadelphia Electric Co. 83/07/12. SCHWENCER.A. Licensing Branch 2. 2pp. 19536:168. 24X Fiche: 50-352,83/07/12,8307150076.
- 8307150132 Forwards responses to Chemical Engineering Branch fire protection section, draft SER open review Items 17, 20, 22, 24 & 28, W/12 oversize drawings. Aperture cards are available in PDR.
  BRADLEY, E. J. Philadelphia Electric Co. 83/07/12. BCHWENCER, A. Licensing Branch 2, 27pp. 17538:001. 24X Fiche: 50-352, 83/07/12, 8307150132.

#### Q. Adjudicatory correspondence

- 8306030332 Order granting Commonwealth of PA 830526 motion for partial relief from ASLB requirements to coordinate filing of onsite emergency planning contentions. Commonwealth required to negotiate language of contentions.

  BRENNER, L. Atomic Safety and Licensing Board Panel. 83/06/01.

  Pennsylvania, Commonwealth of., Opp. 18715:038. 24X

  Fiche: 50-352,83/06/01,8306030332.
- B307060409 Answer opposing Ds1-Aware counsel B30616 ltr proposing new contention on use of supplemental cooling water from Point Pleasant diversion. ABLB does not have jurisdiction over issue. Certificate of Evc enci.
  CONNER.T.B. Philadelphia Electric Co. CONNER.T.B. Conner & Wetterhahn. 83/06/30. Atomic Bafety and Licensing Board Panel. 6pp. 19234:288. 24X Fiche: 50-352,83/06/30.8307060409.
- B307070255 Answer opposing Limerick Ecology Action B30617 onsite emergency planning contentions. Contentions either lack requisite specificity & bases or fail to allege noncompliance w/regulations. Certificate of Svc encl. WETTERHAHN.M. J. Philadelphia Electric Co. WETTERHAHN.M. J. Conner & Wetterhahn. B3/07/05. Atomic Bafety and Licensing Board Panel. 19267: 221. 24X Fiche: 50-352, 83/07/05, 8307070255.
- B307130196 Responds to telcon request re BNL review of util 830421 severe accident risk assessment.BNL reviewers listed. HDD0DDN.A.P. Hearing Branch 2. 83/07/08. DORBEY.J.A. Limeric Ecology Action. 2pp. 19465:351. 24X Fiche: 50-352,83/07/08, B307130196.
- 8307130232 Forwards Page 6-16 to Rev 2 to emergency plan, inadvertently not reproduced when amended Emergency plan will be corrected w/next amend Related correspondence.
  WETTERHANN, M. J. Conner & Wetterhahn. WETTERHANN, M. J. Philadelphia Electric Co. 93/07/08. BRENNER.L., MORRIS, F. A., COLE, R. F. Atomic Safety and Licensing Board Panel. 2pp. 19465:358. 24X Fiche: 50-352, 83/07/08, 8307130232.
- B307180136 Forwards Limerick Ecology Action respecification of Contention I-42 per 830516 memorandum. Application did not show compliance w/830121 rule re environ qualification of electrical squipment.

  DORREY.J.A. Dorsey.J.A. DORREY.J.A. Limerick Ecology Action.

  B3/07/11. BRENNER.L.: MDRRIS.P.A.: CULE.R.F. Atomic Safety and Licensing Board Panel. 1p. 19557:057. 24X Fiche: 80-352,83/07/11,8307180136.
- --8307180142 Respecification of Contention I-42 re environ qualification of electrical equipment Certificate of Svc encl.

  \* Limerick Ecology Action. 83/07/11. App. 19357:058. 24X
  Fiche: 50-352, 83/07/11, 8307180136.
- 8307140475 Response to Limerick Ecology Action 830617 onsite emergency planning contentions. Contentions VIII-3, 4, 5, 6, 8, 9, 10 & 13 20 incomplete in whole or part due to unavailability of pertinent details. W/Certificate of Svc. VOOLER, B. H. Hearing Branch 2. 83/07/12. Atomic Safety and Licensing Board Panel. 22pp. 19520:181. 24X Fiche: 50-352, 83/07/12, 8307140475.
- B307130300 Responds to B30630 ltr re failure to receive documents. Name added to NRC distribution list.NRC 830620 ltr to util, summarizing NRC Caseload Forecast Panel 830413-15 site visit & 830721 meeting summary, encl.
  HD09000N.A.P. Hearing Branch 2. B3/07/13, BUSH.M.W. Bush, M.W. 21pp. 19532:213. 24X Fiche: 50-352, B3/07/13, B307150300.
- 8307180260 Memorandum & order re Del-Aware 830616 ltr to ASLAB. Proposed contention denied. Contention vague & seems to address matters beyond ASLAB jurisdiction.

  BRENNER, L. Atomic Bafety and Licensing Board Panel. 83/07/14.

  Del-Aware Unlimited, Inc. 3pp. 19556:001. 24X

  Fiche: 50-352, 83/07/14, 8307180260.

- 8307170127 Second round of interrogatories re pressurized thermal shock. Related correspondence.

  LEWIS. M. Lewis. M. 83/07/15. Office of the Executive Legal Director. 2pp. 19636:051. 24X Fiche: 50-352.83/07/15.8307190127.
- 8307210230 Requests all available info responsive to 830603 first set of interrogatories & request for production of documents, including names, addresses & prof qualifications of all expert consultants & witnesses. Related correspondence. METTERHANN.M.J. Conner & Wetterhahn. WITTERHANN.M.J. Philadelphia Electric Co. 83/07/18. ANTHONY.R.L. Friends of the Earth. 2pp. 19669:039. 24% Fiche: 50-352,83/07/18,8307210230.
- 8307220364 Brief incorporating documents to avoid duplication.
  Certificate of Svc encl.
  SUGARMAN.R.J. Del-Aware Unlimited, Inc. SUGARMAN.R.J. Sugarman,
  R.J. 83/077/18. Atomic Safety and Licensing Appeal Panel. 3pp.
  19675: 258. 24X Fiche: 50-352,83/07/18,8307220364.
- B307220371 Order striking Del-Aware Unlimited, Inc collection of documents purporting to constitute Del-Aware appellate brief supporting exceptions to ASLB 830308 & 0401 decisions. Correct brief due by 830819.
  BHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 63/07/20. Del-Aware Unlimited, Inc. 3pp. 19675: 271. 24X Fiche: 50-352, 83/07/20, 8307220371.
- 830729008B Forwards reply to NRC & util responses to onsite emergency planning contentions & motion for extension of time to file contentions an Chapter 7 of environ rept OL stage.

  DDR6EY, J. A. Dorsey, J. A. DORSEY, J. A. Limerick Ecology Action.
  83/07/21. BRENNER, A., COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel. ip. 19815: 333. 24X Fiche: 50-352, 83/07/21, 8307290088.
- --B307290093 Reply to NRC & util responses to onsite emergency planning contentions. ASLB should admit contentions w/exceptions stated.

  DDRSEY, J. A. Limerick Ecology Action. DDRSEY, J. A. Dursey, J. A. B3707/21. Atomic Safety and Licensing Board Panel. 14pp. 19915: 334. 24X Fiche: 50-352.83/07/21. B307290088.
- --8307290099 Motion for extension until 830901 to file Chapter 7 environ rept OL contentions.Limerick Ecology Action consultant had not received suppl to supporting document as of 830719. Certificate of Svc encl. DORSEY.J.A. Limerick Ecology Action. DORSEY.J.A. Dorsey. J.A. 83707/21. Atomic Bafety and Licensing Board Panel. 4pp. 19815: 380. 24X Fiche: 50-352, 83/07/21, 8307290088.
- 8307250152 Advises of placement in LPDR of portions of ACRB Joint Subcommittees on Indian Point Units 2 & 3 & Reliability & Probabilistic Assessment 830706 meeting discussing Limerick PRA.
  HDDQDDN, A.P. Hearing Branch 2. 83/07/22. BRENNER, L., MDRRIS, P.A., COLE, R.F. Atomic Bafety and Licensing Board Panel. 1p. 19706:104. 24% Fiche: 50-352,83/07/22,8307250152.
- B307260395 Forwards A Love notice of appearance & DS Bronstein notice of withdrawal of appearance Certificate of Bvc encl. BRONSTEIN, D. S. Bronstein, D. S. BRONSTEIN, D. S. Graterford Prisoners. B3/07/22. BRENNER, L. Atomic Safety and Licensing Board Panel. 5pp. 19733:119. 24X Fiche: 50~352,83/07/22,8307260395.
- 8307280147 Memorializes matters discussed on 830722. Documents re carburator icing to be sent to util Resolution of discovery differences impossible. METTERHAHN.M.J. Conner & Wetterhahn. WETTERHAHN.M.J. Philadelphia Electric Co. 83/07/25. ROMAND.F. Romano.F. 2pp. 19792:045. 24X Fiche: 50-352,83/07/25,8307280147.
- 8307280246 Objections to certain RL Anthony & Friends of the Earth in Delaware Valley 830714 interrogatories & requests for documents. Interrogatories exceed scope of admitted contentions.

  METTERHANN.M. J. Philadelphia Electric Co. WETTERHANN.M.J. Conner & Wetterhann. 83/07/25. Anthony. R.L. 3pp. 19795:288. 24X Fiche: 50-332.83/07/25.8307280246.
- --B3072B0254 Answer opposing admission of Limerick Ecology Action 930711 revised Contention I-42 re qualification of electric equipment exposed to harsh environs. Contention lacks specificity & basis or is premature. Certificate of Svc encl. HETTERHAHN.M. J. Philadelphia Electric Co. HETTERHAHN.M. J. Conner & Wetterhahn. B3/07/25. Atomic Safety and Licensing Board Panel. 11pp. 19795: 293. 24X Fiche: 50-352, B3/07/25, 83072B0246.
- B307280144 Second Special Prehearing Conference Order LBP-83-39 re 830509-11 prehearing conference in Philadelphia, PA on proposed contentions & further scheduling. Contentions I-8, I-15 & I-33M, admitted. Courtesy notification entl. BRENNER, L., COLE, R.F., MORRIS, P.A. Atomic Safety and Licensing Board Panel. B3/07/26, 44pp. 19792:001. 24X Fiche: 50-352, 83/07/26, 8307280144.

- 8307280169 Informs of agreement in furtherance of memorandum & order confirming schedules established during 830516 prehearing confirming schedules established during 830516 prehearing confirmence. Braft emergency plans will be delivered to counsel for Limerick Ecology Action.

  METTERMAIN.M.J. Conner & Wetterhahn. WETTERMAIN.M.J. Philadelphia Electric Co. B3/07/26. BRENNER.L., MORRIS.P.A., COLE.R.F. Atomic Safety and Licensing Board Panel. 2pp. 19791:361. 24X Fiche: 50-352,83/07/26,8307280169.
- H General correspondence
- BD07050179 Requests replacement of HM Goods w/MM Bush on mailing list. BVBH.M. M. Philadelphis, PA. B3/06/29, SCHMENCER.A. Licensing Branch Z. 1p. 19199:186, 24x Fichs: 50-352, 83/06/29, 8307050179.
- M. Utility Final Safety Analysis Report (FSAR) & amends
- G307010185 Forwards Amen4 32 to OL application, consisting of Rev 21 page changes to FSAR per NRC 830308 & 0603 ltrs & Rev 4 page changes to design assessment rept.

  RRADLEY.E.J. Philadelphia Electric Co. 83/06/30. DENTON.H.R.
  Office of Nuclear Reactor Regulation. Director. 3pp. 19186:356.
  24X Ficha: 50-352.83/06/30.8307010185.
- --8307010193 Rev 21 to FSAR.
   Philadelphia Electric Co. 83/06/30. 589pp. 19187:064. 24X Fiche. 50-352:83/06/30:8307010185.
- 9307280063 Forwards Affidavit of Svc re distribution of Rev 21 to FSAR, per 810706 ltr.
  BRADLEY, E. J. Philadelphia Electric Co. B3/07/20. DENTON, H. R.
  Office of Nuclear Reactor Regulation. Director. 3pp. 19791: 201.
  24% Fiche: 50-352, 83/07/20, 8307280063.
- Q Inspection reports, IE Bulletins & correspondence
- B307010132 Forwards IE Insp Repts 50-332/83-06 & 50-333/83-03 on 830316-20. No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/14. KEMPER.J.S. Philadelphia Electric Co. 2pp. 19175: 326. 24X Fiche: 50-352,83/06/14,8307010152.
- --8307010161 IE Insp Repts 50-352/83-06 & 50-353/83-03 on B30516-20. No noncompliance noted Major areas inspected installation of electrical/instrument components & sys in areas of receipt insp. matl qualification & insp. PAOLING.R.J. ANDERSON.C.J. Region 1, Office of Director. 63/06/07. 5pp. 19175:328. 24X Fiche: 50-352,83/06/14,8307010152.
- #307210070 Forwards IE Insp Repts 50-352/83-08 & 50-353/83-05 on 830529-0604 & notice of violation. 574ROSTECKI,R. Division of Project & Resident Programs. 83/07/05. KEMPER,J.S. Philastephia Electric Co. 2pp. 17668:250. 24X Fiche: 50-352,83/07/05,8307210070.
- --8307210078 lE Insp Repts 50-352/83-08 & 50-353/83-05 on 830529-0524. Noncomplience noted: failure to label horizontal shock arrestors GB8-102-H34 & H8B-118-H40 w/ "keep off" signs. GRANT.J.H. Division of Project & Resident Programs. CHAUDHARY.S.K., CONNER.E.L. Region 1, Diffice of Director. B3/06/27. 9pp. 19668:253. 24X Fichs: 50-352/83/07/05/8307210070.
- 8307120503 Act receipt of 830624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/83-05 & 50-353/83-02 BTARDSTECKI.R. Division of Project & Resident Programs. 83/07/06. KEMPER.J.S. Philadelphia Electric Co. 2pp. 19433:247. 24X Fiche: 50-352,83/07/06.8307120503.
- --8307120508 Responds to NRC 830526 ltr re violations noted in IE lnsp Repts 50-352/83-05 & 50-353/83-02. Corrective actions: project OC Instruction E-2.0 revised & Drawing FJ-44-18 revised to include steel barrier per Section 10.0 of M-B30. KEMPER.J. S. Philadelphia Electric Co. 83706/24. MURLEY.T.E. Region 1. Office of Director. App. 19433: 249. 24X Fiche: 50-352, 83/07/06, 8307120503.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Suc list and.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York Inc. 134pp. 19363:293. 24X Fiche: 50-000,83/07/11,8306270401.
- B306270404 IE Info Notice 83-47, "Feilure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.

- B307180054 Forwards revised response to Core Performance Branch draft
  SER Item 10. "Post-Irradiation Surveillance." Fuel will be
  visually inspected at each refueling outage. Info will be
  incorporated into FSAR rev scheduled for Aug 1983.
  BRADLEY.E.J. Philadelphia Electric Co. 89/07/13. SCHWENCER.A.
  Licensing Branch 2. 3pp. 19560:269. 24X Fiche: 50-352,83/07/13,
  B307180054.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 930103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24% Fichs: 50-000, 83/07/14, 8306270406.
- B3072B0453 Forwards BALP rept for Jan-Dec 1982; conducted on 830418 & discussed on 830502. Gyerali performance in const area acceptable.

  MURLEY, T.E. Region 1, Office of Director. 83/07/18. KEMPER, J. 8. Philadelphia Electric Co. 3pp. 19797: 260. 24X Fichs: 50-352, 83/07/18, 83072B0453.
- --B307280459 BALP rept for Jan-Dec 1982, \* Region 1, Dffice of Director. B3/04/18. 30pp. 19797:263. 24X Fiche: 50-352,83/07/18,8307280453.
- --8307280461 Forwards SALP Board rept conducted on 830418. Meeting scheduled for 830502 to discuss performance assessment & any plans for improvement. Written comments requested within 20 days of meeting. W/o encl.

  8TAROSTECKI, R. Division of Project & Resident Programs, 83/04/28. KEMPER, J. S. Philadelphia Electric Co. ip. 19797:293. 24X Fiche: 50-352,83/07/18,8307280453.
- ---8307280463 Comments on 830502 SALP meeting QA engineer will be added to audit electrical work & resudit program w/emphasis on deficient areas.

  KEMPER, J. S. Philadelphia Electric Co. B3/05/19. ALLAN, J. M. Region I. Office of Director. App. 19797:294. 24X Fiche: 50-352, 83/07/18, 8307280453.
- 8307280288 Responds to violations noted in IE Insp Repts 50-352/83-08 & 50-353/83-05 on 830529-0604. Corrective actions: pipe shock arrestors GBB-102-M34 & MBB-118-440 have been labsied as required.

  KEMPER. J. S. Philadelphia Electric Co. 83/07/25. MURLEY, T. E. Region 1. Office of Director. 3pp. 19790:054. 24X Fiche: 50-352, 83/07/25, 8307280288.
- S. Reportable occurrences. LERs & related correspondence
- 8307120216 Significant Deficiency Rept 74 re 4 kV switchgear supplied by Brown-Boveri, Inc. Initially reported on 830226. Circuit breakers & ground trucks will have spring added to close hatch. Final rept will be provided by 830826. KEMPER. J. S. Philadelphia Electric Co. 83/06/24. MURLEY, T. E. Region I. Office of Director. 4pp. 19423: 259. 24X Fiche: 50-352.83/06/24, 8307120216.
- 830711037i Finel Deficiency Rept 83-03 rs medium voltage circuit breakers of same type installed at Limerick which inadvertently closed after completion of spring charging due to slipped close latch discussed in Brown Boveri 830324 ltr. SCHROEDER.C.W. Commonwealth Edison Co. 83/07/07. KEPPLER.J.G. Region 3, Office of Director. 3pp. 19380:266. 24X Fiche: 50-000.83/07/07.830711037i.
- --B307110377 Followup interim rept re potential deficiency in 5HK switchgear supplied by Brown Boveri Circuit breaker inadvertently closed & tripped following spring charging. Light spring added to close latch.

  DUVALL, D. D. Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.).

  B3/04/28. STELLO, V. Director's Office, Office of Inspection and Enforcement. 2pp. 19380; 271. 24X Fiche: 50-000,83/07/07, 8307110371.
- 8307130015 Final Significant Deficiency Rept 84 re defect in motor operated valve tandem torque switches. One torque switch in each tandem assembly removed reconfiguring switches to Limitorque std configuration.

  KEMPER. J. S. Philadelphia Electric Co. 83/07/08. MURLEY, T. E. Region I. Office of Director. 3pp. 19474: 209. 24X Fiche: 50-352, 83/07/08, 8307130015.

- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8307080684 Advises that OL application sufficiently complete for docketing. Concerns exist re ability to support licensing effort & mgt capability. Bases for confidence to start licensing activities should be documented & FEAR amended. EISENHUT, D. G. Division of Licensing. 83/06/23. MITTL.R. L. Public Bervice Electric & Oas Co. of New Jersey. 85pp. 19364: 020. 24x Fiche: 50~354,83/06/23,8307080684.
- 8307140145 Advises that util request for relief re RCPB component codes justified & acceptable. Two areas requiring upgrade include compliance w/NA-3260, "Review of Strees Rept" & fracture toughness requirements for older plants. SCHWENCER. A. Licensing Branch 2. 83/07/01. MITTL.R. L. Public Service Electric & Gas Co. of New Jersey. 2pp. 19529:343. 24) Fiche: 50-354,83/07/01,8307140145.
- 8306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- B307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATWB events. 8vc list encl. EISENHUT, D. G. Division of Licensing, B3/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 17669:267. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307130287 Responds to 830623 ltr forwarding acceptance review of OL application. Bechtel serves as AE & constructor. Hope Creek licensing activities will not detract from safe operation of Balem.
  MITTL.R.L. Public Service Electric & Oas Co. of New Jersey.
  83/07/08. SCHWENCER,A. Licensing Branch 2. 10pp. 19474:096. 24X
- 8307250032 Notification of 830727-28 environ site visit w/util in Salem.NJ to discuss environ concerns. HAGNER,D. Licensing Branch 2. 83/07/12. 8CHWENCER.A. Licensin, Branch 2. 5pp. 19723:299. 24X Fiche:50-354.83/07/12.8307250032.
- B307270164 Notifies of B30727 & 28 site visit to conduct environ site review. Agenda encl.

  SCHMENGER.A. Licensing Branch 2. 83/07/13. MITTL.R.L. Public Service Electric & Qas Co. of New Jersey. 6pp. 19811:140. 24X Fiche: 50-354,83/07/13,8307270164.
- 8307270251 Forwards newspaper notice of 830727 public site meeting re UL application to be published in area newspapers.

  8CHMENGER.A. Licensing Branch 2. 83/07/14. MITTL.R.L. Public Service Electric & Qas Co. of New Jersey. 3pp. 19811:173. 24X Fiche: 50-354,83/07/14.8307270251.
- C. Utility Environmental Report (ER), amends & correspondence
- B307130087 Forwards affidavit certifying updated distribution of general info, environ rept OL stage & FSAR.per 10CFR2.101 & Enci 1 to NRC 830623 acceptance review ltr.
  MITTL.R.L. Public Service Electric & Gas Co. of New Jersey.
  B3/07/08. BCHMENCER.A. Licensing Branch 2. 10pp. 19465:324. 24x
  Fiche: 50-354.83/07/08.8307130087.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8307200480 Extends invitation to attend NRC 830727-28 environ site visit. Public meeting will be held on evening of 830727. SCHURNGER: A. Licensing Branch 2. 83/07/12. QASTON.J. New Jersey, State of. 4pp. 19826:303. 24X Fiche: 50-354,83/07/12,8307200480.
- F. Security, medical, emergency & fire protection plans
- B307200134 Forwards request for addl info re security plans submitted B30304. Info should be provided within 45 days.
  BCHMENGER, A. Licensing Branch 2. B3/07/14. MITTL, R. L. Public Bervice Electric & Qas Co. of New Jersey. ip. 19651: 247. 24X Fiche: 50-354, 83/07/14, 8307200154.

#### Q. Adjudicatory correspondence

- B307210248 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC. BILBERG-J.E. Shaw. Pittman. Potts & Trowbridge. B3/07/13. PALLADINO.N.J. Commissioners. 1p. 19664:061. 24X Fiche: 50-000, 83/07/13, B307210248.
- --B307210251 Notifies of employment at law firm.VR Harding will not participate in any case pending before NRC.Svc list encl. HARDING.V.R. Shaw. Pittman. Patts & Troubridge. 83/07/13. PALLADING.N.J. Commissioners. Spp. 19664:062. 24X Fiche: 50-000.83/07/13.8307210248.
- J. Insurance & indemnity information
- B307130240 Forwards Endorsements 59 & 60 to NELIA Policy NF-230 & Endorsements 46 & 47 to MAELU Policy MF-90.
  GULDEN,M.P. Marsh & McLennan, Inc. B3/07/06. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 19474:352.
  24X Fiche:50-000,83/07/06,8307130240.
- K, Utility Final Bafety Analysis Report (FSAR) & amends
- 8307130087 Forwards affidavit certifying updated distribution of general info.environ rept OL stage & FSAR.per 100FR2.101 & Encl 1 to NRC 830623 acceptance review ltr.

  MITTL.R.L. Public Service Electric & Gas Co. of New Jersey.
  83/07/08. SGHWENCER.A. Licensing Branch 2. 10pp. 17465:324. 24X
  Fiche: 50-354, 83/07/08, 8307130087.
- G. Inspection reports, 1E Bulletins & correspondence
- B307140459 Forwards IE Insp Rept 50-354/B3-08 on B30418-0605 & notices of violation & deviation.
  STARDSTECKI,R. Region in Diffice of Director. B3/06/28. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 4pp. 19520:320.
  24X Fichs:50-354,83/06/28,8307140459.
- --8307140463 Natice of violation from insp on 830418-0405.

  \* Region 1, Office of Director. 83/04/28, 1p. 19520; 322. 24X Fiche: 50-354.83/04/28,8307140459.
- --8307140465 Natice of deviation from insp on 830418-0605.

  \* Region 1, Office of Director. 83/06/28. 1p. 17320:323. 24X Fiche: 50-354.63/06/28.8307140459.
- --B307140469 IE Insp Rept 50-334/83-0B on 830418-0605. Noncompliance noted: failure of QC insp to identify pipe support welding & installation discrepancies & QE valves designed & mfg per ASME Code, contrary to PSAR commitment.
  BATEMAN, W. H., MCCABE, E. C., Region I, Office of Director, 83/04/17, 14pp. 19520: 324. 24% Fiche: 50-354, 83/06/28, 8307140459.
- 8307280334 Forwards IE Insp Rept 50-354/83-07 on 830531-0603.No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/13.

  MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 2pp. 19790:095. 24X Fiche:50-354.83/07/13.8307280334.
- --8307280342 IE Insp Rept 50-354/83-07 on 830531-0603. No noncompliance noted Major areas inspected; work observation & document review of procurement activities; receipt insp.qualification & installation of electrical components/sys.
  PAOLIND.R.J., ANDERSON.C.J. Region 1. Office of Director.
  83/06/29. 7pp. 19790:097. 24X Fiche: 50-354:83/07/13:8307280334.
- 8307210172 Notifies that representative of Div of Ecological Svcs unable to attend site insp during wk of 830725. No federally listed or threatened species under DDI jurisdiction known to exist in project area. CHEZIK.M.T. Interior. Dept. of, Fish & Wildlife Service. 83/07/18. 83CHJEROKER.A. Licensing Brench 2. 2pp. 17666:058. 24X Fiche: 50-354,83/07/18. 8307210172.
- S. Reportable occurrences: LERs & related correspondence
- 8307150199 Interim deficiency rept re possible lack of heat treatment on stainless steel flanges mfg by Tube-Line Corp. Initially reported on 830A01. Affected flanges removed from svc.
  Bechtel providing analysis. Next rept by 830815.
  MARTIN,T. J. Public Service Electric & Cas Co. of New Jersey.
  B370A703. ALLAN.J.M. Region 1, Office of Director. 2pp.
  19530:240. 24X Fiche: 50-354,83/0A/30.8307150199.

#### V. Operator Examinations

- 8307250456 Submits rev to initial cold licensing exam & instructor certification exam schedules submitted on 830513 in response to Generic Ltr 83-01 due to further development of operator training & testing program.

  MITTLR.L. Public Service Electric & Gas Co. of New Jersey.
  83/07/14. SCHWENCER:A. Licensing Branch 2. ip. 19701:245. 24X Fiche:50-354:63/07/14.8307250456.
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

#### G. Adjudicatory correspondence

- B30721024B Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC. SILBERG, J. E. Shaw. Pittman. Potts & Trombridge. B3/07/13. PALLADINO.N. J. Commissioners. 1p. 1964:061. 24X Fich: 50-000.B3/07/13.B30721024B.
- -8307210251 Notifies of employment at law firm VR Harding will not participate in any case pending before NRC. Svc list and. HARDING. V. R. Shaw, Pittman, Potts & Troubridge. 83/07/13, PALLADING, V. Commissioners. Spp. 19664: 062. 24X Fiche: 50-000, 83/07/13, 8307210248.

#### J. Insurance & indemnity information

- 3307130240 Forwards Endorsements 59 & 60 to NELIA Policy NF-230 & Endorsements 46 & 47 to MAELU Policy MF-90.
  GOLDEN.M.P. Marsh & McLennan, Inc. 83/07/06. SALTIMAN, J. Assistant Director for Biste & Licensee Relations. 5pp. 19474:352.
  24X Fiche:50-000,83/07/06,8307130240.
- 3. Reportable occurrences, LERs & related correspondence
- 3307150199 Interim deficiency rept re possible tack of heat treatment on stainless steel flanges mfg by Tube-Line Corp. Initially reported on 830401. Affected flanges removed from svc. Bachtel providing analysis. Next rept by 830815. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 83704730. ALLAN.J.M. Region 1, Office of Director. 2pp. 19530: 240. 24X Fiche: 50-354,83/04/30,8307180199.
- DOCKET 50-356 UNIV. OF ILLINDIS COPRA RESEARCH REACTOR

#### . Operator Examinations

- 3307080427 Generic Ltr 83-12A to all monpower reactor licensees re issuance of NRC Form 398, "Personal Gualifications Statement Licensee." Syc list encl. EISEANUTO.G. Division of Licensing. 83/07/11. Michigen, Univ. of. 14pp. 19563:138. 24X Fiche:50-000,83/07/11,8307080427.
- OCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

## . Application/construction stage documents & correspondence

- 307130437 Forwards NUREO-0969, "Rept of NRC Evaluation Team on Quality of Const at Zimmer Nuclear Power Station" for proprietary review.
  SMIEZEK, J.H. Director's Office, Office of Inspection and Enforcement. 83/04/18. BORGMANN.E.A. Cincinnati Gas & Electric Co. 398pp. 19510;047, 24X Fiche: 50-358.83/04/18,8307130437.
- 306290356 Rev A.to "Program Plan for Independent Review of Zimmer Project Mgt." W/one oversize figure. Aperture card is available in PDR. \* Torrey Pines Technology. 83/05/31. 49pp. 66850:051. 24X Fiche: 50-358,83/05/31,8306290356.
- 306270395 Generic Ltr 83-24 to all BHR applicants for OL & holders of OLs for Grand Gulf, LaBalle & Susquehanna re TMI Task Action Plan Item I. G., "Special Low Fower Testing & Training & Recommendations for BMRs." Svc list enci.
  EISENHUT, D. G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, 83/06/29, 8306270395.
- 307130002 Forwards request for action under 10CFR2 206 from Miami Valley Power Project for transmittal to Dfc of FR for publication. Wo encl. AXELRAD. J. A. Enforcement Staff. 83/06/29. Docketing & Services Branch. 1p. 19465:356. 24X Fiche: 50-358.83/06/29,8307130002.

- 8307140125 Forwards request for add1 info for OL application re trip setpoint & EBF channel Application should be amended to comply w/encl requirements. Review schedule based on assumption that add1 info will be available by 831001. YOUNOBLOOD, B. J. Licensing Branch 1. 83/06/29. WILLIAMS, J. Cincinnati Gas & Electric Co. 7pp. 19539: 347. 24% Fiche: 50-358, 83/06/29, 8307140125.
- 8307080485 Requests Bechtel study draft rept & recent util proposals developed for consideration in final recommendation re independent review of facility project mgt.per 830526 meeting agreement.

  NEYLAN.A.J. Torrey Pines Technology. 83/07/01. DICXHONER, W. H. Cincinnati 8as & Electric Co. ip. 19346:356. 24X

  Fiche: 50-358, 83/07/01, 8307080485.
- 8306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. 9. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl.
  EISENHUT, D. G. Division of Licensing. B3/07/06. Consolid Edison Co. of New York, Inc. 16pp. 19669:254. 24X
  Fiche: 50-000, 83/07/06, 8307060329. Consolidated
- 8307130300 Forwards BER & request for add1 info re environ qualification of electric equipment important to safety & safety-related mechanical equipment. Schedule for submission of add1 info requested by 830815.
  YOUNGELOOD, B. J. Licensing Branch 1. 83/07/06. WILLIAMS, J. Cincinnett Oas & Electric Co. 20p. 19511:081. 24X Fich=: 50-358, 83/07/06, 8307130300.
- -8307130304 SER on environ qualification of electric equipment important to safety & safety-related mechanical equipment. Open items & request for addl info enci. # Office of Nuclear Reactor Regulation. Director. 83/07/06. 32pp. 19511:084. 24% Fiche: 50-358.83/07/06.8307130300.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. Q. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269, 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307180253 Forwards 830630 ltr to Torrey Pines Technology & ASME ltr to NJ Kaiser, Inc re ASME site renewal audit findings. WILLIAMB. J. Cincinnati Gas & Electric Co. 83/07/11, KEPPLER, J. G. Region 3, Office of Director. 32pp. 19556:020, 24X Fiche: 50-358, 83/07/11, 8307180253.
- 8307200233 Responds to 821021 request for review of Bargent & Lundy seismic design analyses of main steam piping between outboard MBIVs & turbine step valves.piping supports & partions of turbine bldg. Design acceptable.
  EISENHUT.D.G. Division of Licensing. 83/07/12. WARNICK, R. F. Region J. Office of Director. 7pp. 19670: 263. 24X Fiche: 50-358, 83/07/12. 8307200233.
- 8307210047 Revises 830706 1tr re Bechtel study draft rept on mgt of util Bechtel should retain rept & arrange meeting w/Torrey Pines Technology.

  COLE:0.F. Cincinnati Gas & Electric Co. 83/07/13. JONES, G. Bechtel Corp. 1p. 19648:303. 24X Fiche: 50-358:83/07/13.8307210047.
- 8307210109 Forwards HJ Kaiser, Inc response to ABME 830616 ltr re site renewal audit findings, Procedure FPE-1 revised to require inclusion of procurement std in purchase orders. All other deviations addressed.

  MILLIAMB. J. Cincinnati Gas & Electric Co. 83/07/13. KEPPLER, J. Q. Region J. Office of Director. 7pp. 19668; 212, 24X Fiche: 50-358, 83/07/13, 8307210109.
- 8307280486 Notification of 830727 meeting w/util in Moscow, OH to discuss applicant justifications for deviations from FBAR criteria for electrical cable separation.

  KINTNER, L. L. Licensing Branch i. 83/07/21. YDUNGBLODD, B. J. Licensing Branch i. 4pp. 19826:048. 24X Fiche: 50-358,83/07/21,8307280486.

#### Adjudicatory correspondence

- 8306160589 Advises that Appalachia-Science in Public Interest request to file amicus curiae brief or brief should not be refiled. Responses to request will be filed w/responses to Miami Vallay Power Project motion. FRYE.J.H. Atomic Bafety and Licensing Board Panel. 83/06/14. DAVIS.M. Affiliation Unknown. tp. 18872; 285. 24X Fiche: 50-358, 83/06/14, 8306160589.
- B307060495 Responds to B30617 telephone request re 10GFR 2.206 petition to suspend const filed by Miami Valley Power Project on B20820. Forwards two documents re petition. W/o encis. LEWIB.8. H. Region 3, Office of Director. B3/06/20. FROUG.J. Froug. J. 2pp. 19299:209. 24X Fiche: 50-358.83/06/20.8307060495.
- 8307130236 Responds to 830603 request to treat Miami Valley Power Project 830525 allegations as unauthorized submission or to permit util reply. Util reply should be sent to IE. Region III, intervenor & DELD.

  LIEBERMAN, J. Regional Operations & Enforcement Division. 83/06/27. CONNER, T. B. Conner & Wetterhahn. CONNER, T. B. Cincinnati Qas & Electric Co. ip. 19474:351. 24X Fiche: 50-358, 83/06/27, 8307130236.
- 8307050032 Motion for leave to file reply brief, by 830706, to NRC & util 830630 answers to Mismi Valley Power Project 830603 motion to reopen record to admit eight contentions on GA & util character & competence. Certificate of 8vc encl. DEVINE.T. Mismi Valley Power Project. DEVINE.T. Government Accountability Project. 83/06/29. Commissioners. 4pp. 19193:192. 24X Fiche: 50-358, 83/06/29, 8307030032.
- 8307060197 Requests info from 830607 interview re Ofc of Inspector & Auditor 1981 investigation be immediately reported to Commission & ABLB. Transcript requested for personal records. MCCARTEN.J. B. Affiliation Unknown. 83/06/29. HUYT.H.F. Atomic Bafety and Licensing Board Panel. 1p. 19249: 227. 24X Fiche: 30-338, 83/06/29, 8307060197.
- 8307060376 Answer opposing Miami Valley Power Project 830627 motion for leave to file reply brief to util & NRC answers to Project 830603 motion to reopen record. No purpose would be served by permitting redundant discussion. Certificate of Svc encl. WETTERHAHN, M. J. Cincinnati Gas & Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn. 83/07/01. Atomic Bafety and Licensing Board Panel. Spp. 19236:089. 24X Fiche: 30-358, 83/07/01, 8307060376.
- --8307060397 Responds to 1tr requesting removal of util from centrol of GA program by modifying Director's Decision DD-83-02 & Commission 821112 order to show cause & order immediately suspending const.tr to be treated as 10CFR2.206 petition. DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement. 83/06/27. DEVINE.T. Government Accountability Project. DEVINE.T. Hismi Valley Power Project. 1p. 19234:098. 24X Fiche: 50-358,83/07/01,8307040396.
- --B307060403 Notice of Miami Valley Power Project 10CFR2.206 petition. DEVOUND, R. G. Director's Office, Office of Inspection and Enforcement. B3/06/27. Zpp. 19236:099. 24X Ficha: 50-358, 83/07/01, 8307060396.
- 8307110331 Memorandum & order granting Miami Valley Power Project 830629 motion to file reply brief to NRC & util answers opposing Project 830603 motion to reopen record. Filings due on 830712.
  FRYELJ.H. Atomic Safety and Licensing Board Panel. 83/07/07. Miami Valley Power Project. 3pp. 19381: 288. 24X Fiche: 50-358, 83/07/07, 8307110331.
- B307080501 Response opposing Miami Valley Power Project B30629 motion to file reply brief to NRC & util B30620 briefs opposing Project B30603 request for reconsideration. No good cause shown for not including info in motion. W/Certificate of Syc. BARTH.C.A. Hearing Branch 1. B3/07/08. Atomic Safety and Licensing Board Panel. 4pp. 19346:344. 24X Fiche: 50-358,83/07/08. B307080501.
- 8307150312 Forwards Miami Valley Power Project 830502 original motion to reopen record for admission of eight contentions on GA & corporate character & competence, to complete Commission record.

  DEVINE, T. Government Accountability Project. DEVINE, T. Miami Valley Power Project. 83/07/12. Commissioners. ip. 19533:019. 24X Fiche: 50-358, 83/07/12, 8307150312.
- ---B307150317 Motion to reopen record for admission of eight contentions on GA & corporate character & competence, or alternatively, for ASLB to consider whether stds for 820715 exercise of sua sponte authority exists.

  DEVINE, T. Miami Valley Power Project. DEVINE, T. Government Accountability Project. 83/04/02. Atomic Safety and Licensing Board Panel. 224pp. 19533:020. 24X Fiche: 50-358, 83/07/12, 8307150312.

- B307150322 Forwards motions re reopening record to admit contentions on GA & corporate character & competence.

  DEVINE.T. Government Accountability Project. DEVINE.T. Miami Vallay Power Project. B3/07/12. Cammissioners. 1p. 19531:128. 24X Fiche: 50-358, 83/07/12. 8307150322.
- --8307150324 Reply brief supporting Miami Valley Power Project 830603 motion to reopen record for admission of eight contentions on GA & corporate character & competence & motion to compel discovery on contentions.

  DEVINE.T. Miami Valley Power Project. DEVINE.T. Government Accountability Project. 83/07/12. Atomic Safety and Licensing Board Panel. 52pp. 19531:129. 24X Fiche: 50-358, 83/07/12.
- --8307150327 Motion to reopen record for admission of eight contentions on GA & corporate character & competence. ASLAB has Jurisdiction even if ASLB lacks jurisdiction to reopen record.

  DEVINE, T. Miami Valley Power Project. DEVINE, T. Government Accountability Project. 83/07/12. Atomic Safety and Licensing Appeal Panel. 5pp. 19531:181. 24X Fiche: 50-358, 83/07/12.
- --8307150331 Hation to defer ruling on whether to review ALAB-727 until ABLB & ABLAB rule on Miami Valley Power Project 830603 & 0712 motions to reopen record to admit contentions on G& character & competence or alternatively, to reopen record. DEVINE.T. Miami Valley Power Project. DEVINE.T. Government Accountability Project. 83/07/12. Commissioners. 10gp. 19531:186. 24X Fiche:50-358,83/07/12,8307150322.
- --8307150338 Motion for protective order to shield identity of affiants providing portion of basis for Miami Valley Power Project eight proposed contentions. Certificate of Svc encl.

  DEVINE.T. Miami Valley Power Project. DEVINE.T. Government Accountability Project. 83/07/12. Atomic Safety and Licensing Board Panel. 336pp. 19531:196. 24X Fiche: 50-358, 83/07/12, 8307150322.
- B307190199 Motion for leave to respond by B30729 to Miami Valley Power Project (MVPP) reply brief re applicant opposition to eight GA contentions. MVPP reply distorts record & applicant position. Certificate of Svc encl. CONNER. T. B. Cincinnati Gas & Electric Co. CONNER. T. B. Conner & Wetterhahn. B3/07/15. Atomic Safety and Licensing Board Panel. 4pp. 19628: 285. 24% Fiche: 50-358, B3/07/15, B307190199.
- 8307250282 Response to applicant motion for leave to respond to Miami Valley Power Project reply brief. Applicant should respond only to substance of proposed contentions re GA program inadequacy. Certificate of Svc encl. DEVINE. T. Miami Valley Power Project. 83/07/21. Atomic Safety and Licensing Board Panel. 4pp. 19705: 324. 24% Fiche: 50-358, 83/07/21, 8307250282.
- G. Inspection reports. IE Bulletins & correspondence
- 8307220044 Add1 response to FOIA request for documents re IE Insp Rept 50-338/81-13. Forwards J McCarten file Portions of file & package addressing concerns reised at Commission meeting recriminal investigation withheld (ref FOIA Exemptions 5 & 7). FELTON, J. M. Division of Rules and Records. 83/05/18. DEVINE, T., ROSENTHAL, J. Government Accountability Project. 2pp. 19713:357. 24X Fiche: 50-338, 83/05/18, 8307220044.
- --8307220061 J McCarten file on facility.containing handwritten notes & various documents.

  \* NRC No Detailed Affiliation Given. 83/05/18. 405pp. 19714:001. 24% Fiche: 50-358,83/05/18,8307220044.
- 8307080278 Forwards 1E Mgt Meeting Rept 50-358/83-06 on 830526. No noncompliance noted.

  KEPPLER, J. G. Region 3, Office of Director. 83/06/23. WILLIAMS, J. Cincinnati 0as & Electric Co. 2pp. 19352; 128. 24X

  Fiche: 50-358,83/06/23,8307080278.
- --8307080284 IE Mgt Meeting Rept 50-358/83-06 on 830526. No noncompliance noted. Major areas discussed changes in independent design review program plan & Torrey Pines Technology independent review of project mgt.
  HUNTER, D. R. MARNICK, R. F. Region 3, Office of Director. 83/06/17, 3pp. 19352:130. 24X Fiche: 50-358, 83/06/23, 8307080278.
- 8307120574 Forwards IE Insp Rept 50-358/83-07 on 830117-21,0214-18 & 0411-15 & notice of violation.

  MARNICK.R.F. Region 3, Office of Director. 83/06/28. WILLIAMS, J. Cincinnati Oas & Electric Co. 2pp. 17433:178. 24X
  Fiche: 50-358,83/06/28,8307120874,

- --8307120580 Notice of violation from insp on 830117-21,0214-18 & 0411-15.

  WARNICK, R. F. Region 3, Office of Director. 83/06/28. 1p.
  19433:180. 24X Fiche: 50-358:83/06/28,8307120574.
- --8307120584 IE Insp Rept 50-358/83-07 on 830117-21,0214-18 & 0411-15.
  Noncompliance noted: inadequate 0A/QC of HPC8 & RHR pump & motor testing, per ASME Code.
  SCHEIBEHUT. C., GUSTAF80N,R. N., CHRISTIANSON,W. Region 3, Office of Director. 83/06/28, 12pp. 19433; 181. 24X
  Fiche: 50-358,83/06/28,8307120574.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Bubsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/07/11. Consolidated Edison Co. of New Yark, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11. 8306270401.
- B306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JURDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New Yort, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12,8306270404.
- B306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307210038 Responds to 830711 request for extension to respond to violation noted in IE Insp Rept 50-358/82-17. Extension to 830824 granted.
  WARNICK, R.F. Region 3. Office of Director. 83/07/15. WILLIAMS, J. Cincinnati Gas & Electric Co. 2pp. 19668; 322. 24X Fiche: 50-358, 83/07/15, 8307210038.
- --8307210044 Requests 45-day extension until B30824 for response to violation re welder qualification noted in IE Insp Rept 50-358/82-17.

  WILLIAMS.J. Cincinnati Gas & Electric Co. 83/07/11. KEPPLER.J.G. Region 3, Office of Director. 2pp. 19668:324. 24X Fiche: 50-358,83/07/15,8307210038.
- R. Periodic operating reports & related correspondence
- 8307200307 Forwards biweekly status rept on independent review of facility project mgt for B30618-0701.

  NEYLAN.A.J. Torrey Pines Technology. B3/07/12. DICKHONER, W. H. Cincinneti Gas & Elsctric Co. 3pp. 17648:065. 24X

  Fichs: 50-358:B3/07/12,8307200307.
- 8307280262 Forwards Biweekly Status Rept 6 on independent review of Zimmer project mgt for B30702-15.

  NEYLAN,A. J. Torrey Pines Technology. 83/07/22. DICKHONER, W. H. Cincinnet: 0as & Electric Co. 2pp. 19795:304. 24X

  Fiche: 50-358,83/07/22,8307280262.
- S. Reportable occurrences, LERs & related correspondence
- 8307060060 Suppl to final deficiency rept. ref QA-1595, dtd 820120 re
  Item M-31 concerning main steam relief valve solengid
  valves. Unqualified solenoid actuated valves will be replaced
  upon release from NRC 821112 show cause order.
  HILLIAMS.J., Cincinnati Qas & Electric Co. 83/06/27. KEPPLER, J. Q.
  Region 3. Office of Director. 2pp. 19251:331. 24X
  Fiche: 50-358, 83/06/27, 8307060060.
- 8307060297 Interim Deficiency Rept Item E-35 re nonconforming electrical panel foundation welding. Initially reported on 830104. Paint removal & insp will be completed by 830830. Next rept will be submitted by 831010. NLLLIAMS. J. Cincinnati Cas & Electric Cb. 83/06/28. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19238: 339. 24X Fiche: 50-358, 83/06/28, 8307060297.
- B307060327 Interim deficiency rept re Item E-16 on GE HFA relays. Corrective action for NBSS shutoff sys relays revised to require replacement of entire relay. Completion will be accomplished upon approval under NRC B21112 order, WILLIAMB.J. Cincinnati Gas & Electric Co. B3/06/28. KEPPLER.J.G. Region 3, Office of Director. 2pp. 19234:185. 24X Fiche: 50-358.83/06/28.8307060327.
- 8307080294 Suppl to final deficiency rept, Item M-44 re possible overpressuritation of piping. Initially reported on 820430. Revised schedule for completion of corrective actions will be submitted upon release from NRC 821112 order. WILLIAMS, J. Cincinnati Gas & Electric Co. 83/06/28. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19351:191. 24X Fiche: 50-358, 83/06/28, 8307080294.

- 8307080345 Interim deficiency rept, Item M-54, re inadequate qualification of hydraulic control units. Initially reported on BEO726. Remnalysis of units & limited scope operability testing will be performed. Next rept expected by 831130. WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/28. KEPPLER. J. Q. Region 3. Office of Director. 2pp. 19350: 313. 24X Fichs: 50-358.83/06/28.8307080345.
- 8307080327 Interim deficiency rept, Item M-87, re design control process inadequate to assure design output documents contain adequate eraction & insp criteria. Initially reported on 830313. Reportability per 100CR30. 55(e) not yet determined. WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/30. KEPPLER, J. Q. Region 3. Office of Director. 2pp. 19350:147. 24X Fiche: 50-358,83/06/30,8307080327.
- 8307080335 Final deficiency rept. Item E-44 re undersized wiring in 4.160/480-volt load ctrs supplied by I-T-E Imperial Corp. Cable replaced w/5-kV cable & vendor notified Wire replaced w/1/0 fierible wire.

  WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/30. KEPPLER, J. G. Region 3. Office of Director. 3pp. 19350: 137. 24X Fiche: 50-358,83/06/30,8307080335.
- 8307080428 Interim Deficiency Rept Item M-45 re Henry J Kaiser Co indeterminate welder qualifications. Initially reported on 820430. Program to identify welder qualification deficiencies being developed. Next rept by 831010.

  WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/30. KEPPLER. J. O. Region 3. Office of Director. 2pp. 19347:263. 24X Fiche: 30-358.83/06/30.8307080428.
- 8307080482 Followup Final Deficiency Rept, Item M-32, re incomplete hydraulic analysis of control rod drive piping. Sargent & Lundy Engineers evaluation determined piping to be within ABME Code allowables if installed per design drawings. WILLIAMS, U. Cincinnati Gas & Electric Co. 83/06/30. KEPPLER, J. Q. Region 3, Office of Director. 2pp. 19345: 354. 24X Fiche: 50-358, 83/06/30, 8307080482.
- 8307210186 Followup to 830806 final deficiency rept. Item M-14 re Rosemount 1151 pressure transmitters. Rosemount Model 1153 replacement program scheduled to begin on release of NRC 82112 order to show cause.
  WILLIAMS, J. Cincinnati Gas & Electric Co. 83/07/08. KEPPLER, J. Q. Region 3, Office of Director. 2pp. 19666:034. 24X Fiche: 50-358,83/07/08,8307210186.
- 8307210040 Interim deficiency rept Item M-14 re HVAC damper actuators. Initially reported on 800312. Projected schedule for corrective actions will be submitted following release of B21112 show cause order.

  MILLIAMS, J. Cincinnati Cas & Electric Co. 83/07/11. KEPPLER, J. G. Region 3. Office of Director. 2pp. 19668: 315. 24X
  Fiche: 50-358, 83/07/11, 8307210040.
- 8307210116 Interim Deficiency Rept Item M-88 re inadequate testing of forged flanges. Initially reported on 830616. Test to determine mechanical properties will be performed by approved lab & results evaluated.

  WICLIAMS. J. Cincinnati Gas & Electric Co. 83/07/14. KEPPLER, J. 0. Region J. 06fice of Director. 3pp. 17668: 204. 24X Fiche: 50-359, 83/07/14, 8307210116.
- 8307210002 Interim deficiency rept re Item M-33 use concerning use of high stress stamp on ASME fittings. Initially reported on 811229, Fittings will be blend grided & ultrasonic test for min wall violations conducted.

  MILLIAMS, J. Cincinnati Gas & Electric Co. 83/07/15. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17668: 190. 24% Fiche: 50-358,83/07/15,8307210002.
- B307210096 Interim deficiency rept Item E-29 re lack of insp records for Nelson studs. Initially reported on 820928. Const authorization request written. Projected schedule for work completion contingent upon relaxation of NRC 821112 order. WILLIAMS. J. Cincinnati Cas & Electric Co. 83/07/15. KEPPLER, J. O. Region 3. Office of Director. 2pp. 19668:236. 24% Fiche: 50-358, 83/07/15, 8307210096.
- B307260550 Interim deficiency rept, Item M-13 re svc water pump mod. Initially reported on 790810. Reinstallation of repaired equipment will be performed by HJ Kaiser Co by Jan 1984. Next rept by 840215.
  WILLIAMS, J. Cincinnati Gas & Electric Co. B3/07/18. KEPPLER, J. 0. Region 3. Office of Director. 2pp. 19734: 025. 24X Fiche: 50-358, 83/07/18, 8307260550.
- B307260556 Interim deficiency rept, Item 8-12 re Hergen-Paterson EA-3 pipe clamp incorrectly used in support design. Initially reported on B30620. Design or installation tolerances will be revised to within 6-degree allowable skew angle. WILLIAMS, J. Cincinnati Cas & Electric Co. B3/07/18. KEPPLER, J. G. Ragion 3, Office of Director. 2pp. 19732:025. 24X Fiche: 50-358, 83/07/18. 8307260556.

T. Hearing transcripts on non-antitrust matters

8307280134

- 8307280136 Informs of Commission determination releasing portions of transcript of Commission 821028 meeting & releasing whole transcripts of Commission 821108 & 12 meetings re plant investigations. lons. Office of the Sucretary of the Commission. 83/07/19. Jment Branch. 1p. 19812:062. 24X Fiche:30-358,83/07/19. CHILK, S. J. Public Document Branch.
- --8307280141 Advises that Commission does not object to release of transcripts of 821028,1108 & 12 meetings re plant transcripts of Balues, 1100 of in mesonand to provide investigations.
  CHILK, S. J. Office of the Secretary of the Commission. 83/07/12
  PLAINE, H. H. Office of the General Counsel. 1p. 19812:063. 24
  Fiche: 50-358, 83/07/19, 8307280136.
- --8307280160 Transcript of portions of Commission 821028 closed meeting in Washington, DC re status of plant investigation. Pp 1-69. Portion of Pages 48 & 49 withheld per Exemption 5. \* Commissioners. 82/10/28. 70pp. 19812:044. 24X Fiche: 50-358.83/07/19.8307280136.
- --B307280166 Transcript of Commission B2110B closed meeting in Washington DC re status of plant investigation Pp 1-103. \* Commissioners. B2/11/0B. 105pp. 19812:134. 24X Fiche: 50-358,83/07/19,8307280136.
- --8307280172 Transcript of Commission 821112 meeting in Washington, DC re Commission action on plant.Pp 1-60. \* Commissioners. 82/11/12. 62pp. 19812:237. 24X Fiche: 50-358, 83/07/19, 8307280136.
- DUCKET 50-361 BAN ONOFRE NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- B307060066 Forwards into re Orange County & Ban Clemente, CA plans for emergency planning zone. Into re Orange County Transit District emergency preparedness training also encl.

  BASKIN, R. P. Southern California Edison Ca. B3/07/01. KNIGHTON, G. Licensing Branch 3. 77pp. 19251:071. 24X Fiche: 50-361, B3/07/01, B3/07/01, B3/07/014 KNIGHTON, Q. W. Licensing Branch 3.
- 8307200385 Advises that plant identified for application of IAEA safeguards. Installation info should be prepared on encl IAEA design info questionnairs forms & submitted by 830822. W/o EISENHUT, D. G. Division of Licensing. 83/07/08, DIETCH, R. Southern California Edison Co. 2pp. 19667:325. 24X Fiche: 50-361.83/07/08, 8307200385.
- 8307200473 Comments on 830513 response to Generic Ltr 82-33 (NUREG-0737 Suppl 1) on detailed control room design & safety parameter display sys recview. Schedule for program plan or documentation describing processes & activities requested. KNIGHTON.G.W. Licensing Branch 3. 83/07/08. DIETCH.R. Southern California Edison Co. HDLCOMBEJ.J.C. San Diego Gas & Electric Co. 2pp. 17671:361. 24X Fiche:50-361.83/07/08.8307200473.
- 8307150215 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-206/83-10. 30-361/83-19 & 50-362/83-17. 81840P.T.W. Region 5. Office of Director. 83/07/11. PAPAY, L. T. Southern California Edison Co. ip. 17530:269. 24X Fichs: 50-206,83/07/11,8307150215.
- --8307150222 Responds to NRC 830516 ltr re violations noted in IE lnsp Repts 50-206/83-10,50-361/83-19 & 50-362/83-17. Corrective actions: fixed emergency lighting sys tested & instructions revised Six addi lights will be installed. PAPAY, L.T. Southern California Edison Co. 83/06/15, MARTIN, J. B. Region 5, Office of Director. 4pp. 19530: 270. 24X Fiche: 50-206, 83/07/11, 8307150215.
- B307270029 Forwards Rev 10 to physical security plan. Rev withheld (ref 100FR73, 21).
  BABKIN, P. Bouthern California Edison Co. 83/07/21. Division Licensing. ip. 19749:359. 24X Fiche: 50-206, 83/07/21, 8307270029.
- 8307260135 Discusses review of emergency operations facility (EOF) ventilation sys design. Potential problem w/air leakage from EOF equipment will be corrected.

  BASKIN, K. P. Southern California Edison Co. 83/07/22. EISENHUT, D. Q. Division of Licensing. ip. 19727: 289. 24X Fiche: 50-206, 83/07/22, 8307260135.

- G. Adjudicatory correspondence
- B30705004B Advises that time for Commission to review ALAB-717 expired. Commission declined review. Decision became final agency action on B30621.
  CHILK.6.J. Office of the Secretary of the Commission. B3/06/30. WHARTON.R.J. San Diego, Univ. of, San Diego, CA. ip. 19192: 163. 24X Fiche: 50-361, 83/06/30, 8307050048.
- 8307050055 Advises that time for Commission to review ALAB-717 expired. Commission declined review. Decision became final agency action on 830621. action on 830621. CHILK.8.J. Office of the Secretary of the Commission. 83/06/30. MCCLUNG.C.E. Flemming, Anderson, McClung & Finch. 1p. 19193:191. 24X Fiche:50-361.83/06/30.8307090055.
- P. Operating license stage documents & correspondence
- 8307110&16 Monthly notice of amends to OLs involving NSHC issued since 830523. CLARK.R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391: 152. 24% Fiche: 50-000, 83/06/14, 8307110616.
- B307150411 Forwards request for add1 info to complete NRC review of util submittal addressing NUREG-0737. Item II. D. 1, "Performance Testing of Relief & Safety Valves." Response requested within 30 days. KNIGHTON. O. W. Licensing Branch 3. 83/06/27. DIETCH.R. Southern California Edison Co. 10pp. 19540:166. 24X Fiche: 50-361.83/06/27. B307150411.
- B30711056B Forwards FR notice of consideration of issuance of amend to License NPF-10 & proposed NSHC determination & opportunity for hearing re 18-month surveillance requirements for ESF sys. ROOD, H. Licensing Branch 3. 83/06/28. DIETCH.R. Southern California Edison Co. HOLCOMBE.J.C. San Diego Gas & Electric Co. 3pp. 19391:332. 24X Fiche:50-361,83/06/28,8307110568.
- ---B307110573 Notice of consideration of issuance of amend to License NPF-10 & proposed NSHC determination & opportunity for hearing re 18-month surveillance requirements for ESF sys. NERSES.V. Licensing Branch 3. 83/06/16. Bpp. 19391:335. 24X Fiche:50-361,83/06/28,8307110568.
- 8307060091 Requests concurrence w/mods to post-fuel loading initial test program for FSAR Sections 14.2.10.2, "Initial Criticality" & 14.2.12.96, "Loss of Offsite Power Test."

  BASKIN, K. P. Bouthern California Edison Co. 83/06/29, KNIGHTON, G.W. Licensing Branch 3. 4pp. 19238:246. 24X Fiche: 50-361,83/06/29, 8307060091.
- B3070&0155 Forwards fees for 821119,1203.20 & 830107 proposed changes to Tech Specs re Unit 3 low water level refueling operations, turbine overspeed protection for Unit 2 & component cooling water loops for Units 2 & 3.

  BABKIN,K.P. Southern California Edison Co. 83/07/01. MILLER, H. C. License Fee Management Branch. 4pp. 19249:230. 24X

  Fiche: 50-361,83/07/01.8307060155.
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity, Svc list encl. EISENHUT, D. O. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05, B306270397.
- B307070164 Forwards Rev 5 to "Inservice Testing Program Plan, San Unofre Nuclear Generating Station, Unit 2." Rev incorporates changes discussed w/NRC on B30215. B08NAK.K.P. Bouthern California Edison Co. 83/07/05. KN10HTON, Q.W. Licensing Branch 3. 1p. 19294: 261. 24X Fiche: 50-361, 83/07/08, B307070164.
- --8307070166 Rev 5 to "Inservice Testing Program Plan, San Onofre Nuclear Generating Station, Unit 2." \* Southern California Edison Co. 83/07/05. 79pp. 19294: 262. 24X Fiche: 50-361, 83/07/05, 8307070164,
- 8307040329 Generic Ltr 83-27 to all licensus & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.8vc list encl. EISENHUT.D.C. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000.83/07/06.8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATHS events. Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:267. 24X Fiche: 50-000, 83/07/08, 8307080169.

- 8307180076 Forwards C-E Owners Group program description for resolving TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Fumps" & trip two/leave two strategy Schedule for generic operations-related info being developed.

  BASKIN.K.P. Bouthern California Edison Co. 83/07/14. KNIGHTON.G.W. Licensing Branch 3. App. 19356:357. 24X Fiche:50-361.83/07/14, B307180096.
- 8307180105 Responds to 830701 & 07 telcon requests to resvaluate 830307 core protection calculator (CPC) schedule & to implement CPC software corrections. Secondary calorimetric power & plant power differences clarified.

  BASKIN.K.F. Southern California Edison Co. 83/07/14. KNIOHTUN, G. W. Licensing Branch 3. 2pp. 19557:020. 24X Fiche: 50-361.83/07/14. 8307180105.
- 8307180236 Requests concurrent review & approval of 830106 & 25
  Proposed Changes NPF-10-33 & NPF-15-33, respectively. Proposed revised DNBR penalty factors partially restore operating margin removed by current rod bow penalty factors.

  BASKIN.K.P. Southern California Edison Co. 83/07/14. KNIGHTDN.G.W. Licensing Branch 3. 2pp. 19555: 229. 24X Fiche: 50-361, 83/07/14, 8307180236.
- B307200202 Forwards "Rept on Hydrogen Sensor Response to Dynamic Hydrogen Buildup for Southern California Edison Co," per util 830420 ltr. Results support acceptability of post-LUCA hydrogen monitoring sys. BABKIN.K.P. Southern California Edison Co. B3/07/18. KNIGHTON, G. W. Licensing Branch 3. 2pp. 17648:009. 24X Fiche: 50-361,83/07/18, B307200202.
- --B307200205 "Rept on Hydrogen Sensor Response to Dynamic Hydrogen Buildup for Southern California Edison Cp." HEVERLY.L. General Electric Co. PIR 1454-294. 83/04/27. 16pp. 19648:011. 24X Fiche: 50-361.83/07/18,8307200202.
- 8307210064 Informs that integrated sys demonstration of DNBR trip function requested on 830512 will be performed after warranty run & prior to completion of startup testing program Test performed W80% power natural circulation test.

  8ASKIN.K.P. Southern California Edison Co. 83/07/19. KNIGHTON, Q. W. Licensing Branch 3. 2pp. 19668:267. 24% Fiche: 50-361,83/07/19,8307210064.
- 8307270162 Discusses commitment to resolve design concerns re adequacy of fuel shoulder gap clearance to accommodate differences observed at Arkansas Nuclear One Unit 2 in fuel rod & guide tube axial growth.

  BASKIN.K.P. Southern California Edison Co. B3/07/25. KNIGHTON.O.W. Licensing Branch 3. 1p. 19749:340. 24X Fiche:50-361,83/07/25,8307270162.
- Inspection reports. IE Bulletins & correspondence
- 8307120340 Forwards IE Insp Repts 50-361/83-23 & 50-362/83-am B30509-13 & 0531-0603 No noncompliance noted BISHOP.T.M. Region 5. Office of Director. B3/06/27. PAPAY.L.T. Southern California Edison Ca. 2pp. 19434: 028. 24X Fiche: 50-361, 83/06/27, 8307120340.
- --B307120551 IE insp Repts 50-361/83-23 & 50-362/83-22 on 830509-13 & 0531-0603. No noncompliance noted. Major areas inspected: maint program onsite review committee meeting. Unit 2 control room & emergency lighting.

  ECKHART, J. H., KIRSCH, D. F. Region 5, Office of Director. B3/06/24.

  6pp. 19434:030. 24X Fiche:50-361,83/06/27,8307120540.
- B307050010 Responds to IE Bulletin B2-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants." Action Items 1,2 & 4. Required insps will be performed only when closures are opened for component maint.

  HAYNESIJ. G. Southern California Edison Co. B3/06/29. MARTIN. J. B. Region 5. Office of Director. 12pp. 19192:091. 24X Fichs: 30-361. B3/06/29, B307050010.
- 8306270401 IE Info Notice 83-44, "Common Mode Valve Failures Degrade Burry Rectroviation Spray Subsystem." Svc list encl. AGRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York: Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11,8306270401.
- B307150215 Ack receipt of B30615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-206/B3-10, 50-361/B3-17 & 50-362/B3-17.
  BISHOP.T.W. Region 5. Office of Director. B3/07/11. PAPAY.L.T. Southern California Edison Co. 1p. 19530:267. 24X
  Fiche: 50-206.83/07/11.8307150215.

- --8307150222 Responds to NRC 830516 ltr re violations noted in IE Insp. Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17. Corrective actions: fixed emergency lighting sys tested & instructions revised. Bix addi lights will be installed. PAPAY.L.T. Southern California Edison Co. 83/06/15, MARTIN.J.B. Region 5. Office of Director. 4pp. 17530: 270. 24X Fiche: 50-206, 83/07/11, 8307150215.
- 8306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN. E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153, 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- R. Periodic operating reports & related correspondence
- B3070B0392 "Annual Operating Rept of San Onofre Nuclear Generating Station, Unit 2 for 1982 Radiological Environ Monitoring Evaluation." #/830429 ltr.
  BASKIN, K.P. Southern California Edison Co. BASKIN, K.P. San Diego Oas & Electric Co. 83/04/29. MARTIN, J.B. Region 5. Defice of Director. 193pp. 19350:344. 24X Fiche: 50-361, 83/04/29, 8307080392.
- 8307220465 Monthly operating repts for May 1983.W/830615 ltr.
  MAYMEATHER.L., RAY.H.B. Southern California Edison Co. 83/06/15.
  Office of Resource Management, Director. 25pp. 19495;322. 24X
  Fiche: 50-361,83/06/15,8307220465.
- 8307130192 Submits second progress rept for post-accident sampling sys (PASS) as of B30701. Test verifying total gas capability completed Mod nutage for sys maint will be completed by 830820.

  BASKIN.K.P. Southern California Edison Co. B3/07/11. KNIGHTON, O. M. Licensing Branch 3. 3pp. 19469:347. 24X Fiche: 50-361,83/07/11.
- S. Reportable occurrences, LERs & related correspondence
- 8307060062 LER 83-053/03L-0: on B30519, containment atmosphere gaseous radioactivity monitors RI-7804C & RI-7807C inoperable. Caused by unidentified & unauthorized manipulation of setpoint controller. Setpoint recallbr. W/830620 ltr. RAY.H.B. Southern California Edison Co. B3/06/20. MARTIN, J. B. Region 3, Uffice of Director. 4pp. 19250: 281. 24X Fiche: 50-361, 83/06/20. B307060062.
- 8307060067 LER 83-057/03L-0: on 830522, fire computer alarms received for Fire Zones 22, 29, 30, 31, 32A, 32B & 53. Investigation disclosed Fire Panel 2/3 L203 inoperable. Caused by incorrectly rewired smoke detector. Detector rewired. M/830621 ltr. RAY.H.B. Southern California Edison Co. 83/06/21. MARTIN.J.B. Region 5, Office of Director. 3pp. 19251: 333. 24X Fiche: 50-361, 83/06/21, 8307060067.
- B307060214 LER 83-055/03L-0: on B30523, oxygen concentration in waste gas holdup sys exceeded Tech Spec limit. Caused by air inleakage into waste gas sample suction line Gas compressor & rectroulation sys will be repaired. W/830622 ltr. RAY.H.B. Southern California Edison Co. 83/06/22. MARTIN, J.B. Region 5, Office of Director. 4pp. 19238: 347. 24x Fiche: 30-361, 83/06/22, 8307060214.
- 8307060423 LER 83-054/83L-0; on 830326, control element assembly 64 slipped & dropped over 7 inches. Caused by slow operation of grippers. Assembly retrieved & placed at upper electrical limit. W/830623 ltr.
  RAY.H. B. Southern California Edison Co. 83/06/23. MARTIN, J. B. Region 5, Office of Director. 4pp. 17236; 345. 24x Fiche: 30-361, 83/06/23, 8307060423.
- B307060076 Updated LER B3-047/03X-1: on B30427, toxic gas isolation system in A declared inoperable. Caused by two simultaneous failures: discharged battery supply & misaligned alarm setpoint. Battery replaced. W/B30624 ltr. RAY.H.B. Southern California Edison Co. B3/06/24. MARTIN, J. B. Region 5, Office of Director. App. 17251: 285. 24x Fiche: 30-361, 83/06/24, 8307060076.
- 8307060080 Updated LER 83-048/03X-1: on 830424, pilot flames of Trains A & B toxic gas isolation sys butane/propane monitors experienced persistent flame-out after replacement of Ndrogen cylinder. W/830624 ltr. RAY. H. B. Southern California Edison Co. 83/06/24. MARTIN, J. B. Region 5, Office of Director. 4pp. 19251: 281. 24X Fiche: 30-361, 83/06/24, 8307060080.

- 9 ROs 83-063 & 83-039: on B30621:motor-driven auxiliary pr pumps 2P-141 & 3P-504 failed to complete 48 h; e test successfully. Initially reported an B30624, y improperly machined ail grooves. LERs forthcoming. Bouthern California Edison Co. B3/06/27, MARTIN, J. 9. Office of Director. 2PP. 17465: 337. 24X 9-361.83/06/27,8307130096.
- 5 LER 63-059/03L-0: on 83052B, inner motor bearing oil feeder component cooling water sys pump 2P-204
  a) broke. Caused by operator climbing in area to proper valve alignment. Line repaired. JM630627 ltr. Southern California Edison Co. 83/06/27. MARTIN, J. B. Pffice of Director. 3pp. 19474: 348. 24X >-361,83/06/27,8307130235.
- , LER 83-061/03L-0: on B30529, core protection calculator C declared inoperable Caused by loop 2A cold leg . istor to current converter 2TT-9179-3 out of '--cold loop recalibr. W/830628 ltr.
  Southern California Edison Co. 83/06/28. MARTIN, J. B. iy Office of Director. 4pp. 19507: 324. 24X

- LER B3-062/O3L-O: on B30601, review of chemistry surveillance mevealed that secondary coolant sys sampling & for specific activity per Tech Spec 4.7.1.4 not by B30531. Caused by personnel serior. W830701 ltr. Southern California Edison Co. B3/07/O1, MARTIN, J. B. Office of Director. 4pp. 19474:341. 24X —361.83/07/01,8307130081.
- LER 83-064/03L-0: on 830602, w/core operating limit
  OTY sys out of syc. Surveillance Test 5023-3-3.6
  O verify that DNBR was within acceptable limits.
  U conservative thermal power uncertainty bias.
  RAY.H.8. Southern California Edison Co. 83/07/05.
  B. Region 5. Office of Director. 4pp. 19557:053. 24x
  —361.83/07/05,830/180135.
- LER 83-049/03L-0: on 830607. w/plant in Mode 3. attempt to start auxiliary feedwater pump 2P504 failed. Caused re of control relay in start permissive control for pump. Relay replaced.

  Southern California Edison Co. 83/07/07, MARTIN, J. B. Uffice of Director. 4pp. 19556: 256. 24X—361.83/07/07,8307180146.
- Forwards LERs 83-063/01T-0 & 83-039/01T-0, 9outhern California Edison Co. 83/07/08. MARTIN, J. B. Effice of Director. 2pp. 17560; 246. 24X -361,83/07/08,8307180050
- 31 LER 83-043/01T-0: on 830621, motor-driven auxiliary feedwater 2-504 declared inoperable due to improperly machined over Properly machined bearings installed.

  3. Southern California Edison Co. 83/07/08. Region 5, of Director. 2pp. 17560:248. 24X Fiche: 50-361,83/07/08, JO50.
- 33 LER 83-039/017-0: on B30621, motor-driven auxiliary feedwater ?-504 declared inoperable following failure to := 48 h endurance run, Caused by failed outboard }. Bearings replaced.

  1. Southern California Edison Co. 83/07/08. Region 5, of Director. 2pp. 19360: 250. 24X Fiche: 50-361, 83/07/08, 3-050.
- #ROs 83-072 & 83-04i: on 830706, w/Unit 2 in Mode 5 & Unit 3 is marine fouling of inservice component cooling resulted in high differential pressure & reduced cooling flow. HXs realigned.

  Southern California Edison Co. 83/07/08. MARTIN, J. B. Office of Director. 2pp. 19556: 326. 24X
- LER 83-065/03L-0: on 830609, control element assembly (CEA) 57 Fore than 19 inches during group adjustment. Caused to tioning upper gripper on assembly. CEA coil stacks eplaced w/8ys 80 coils. W/830711 ltr. MOYALM.E. Southern Callfornia Edison Co. 83/07/11. B. Region 5, Offica of Director. 3pp. 19701:168. 24X 361.83/07/11.8307250462.

- 8307250490 LER 83-069/03L-0: on 830610, while in Mode 1, control element assembly calculator 1 declared inoperable due to erratic position indication. Caused by Faulty isolation amplifier card. Card replaced. W/830711 ltr. RAY. H. B. . MORGAN, H. E. Southern California Edison Co. 83/07/11. MARTIN. J. B. Region 5. Office of Director. 3pp. 19701: 230. 24x Fiche: 50-361, 83/07/11, 8307250490.
- 8307250472 LER 83-070/03L-0: an 830613, while in Mode 1, two steam leaks observed in line to turbine-driven auxiliary feedwater pump 2P-140. Caused by leaking plug on turbine stop valve & valve seating surfaces. Flug replaced. W/830712 itr.
  RAY: H. B. Southern California Edison Co. 83/07/12. MARTIN, J. B. Region 5. 04fice of Director. 3pp. 19702:082. 24X Fiche: 50-361, 83/07/12, 8307250472.
- 8307250474 Forwards LERs 83-068/01T-0 & 83-040/01T-0. RAY, H. B. Bouthern California Edison Co. 83/07/12. MARTIN, J. B. Region 5. Office of Director. 2pp. 19701:197. 24X Fiche: 50-361, 83/07/12, 8307250474.
- --8307250474 LER 83-068/01T-0: on B30628.C-E advised util of deficient RCB hot leg sampling norrie loads.Caused by design error. Shims installed to reduce norrie loads to acceptable limits. RAY.H.B. Southern California Edison Co. B3707712. Region 5. Office of Director. ip. 19701:197. 24X Fiche:50-361,83/07/12,8307230474.
- --B307250479 LER B3-040/01T-0: on B30628.C-E advised util of deficient RCS hot leg sampling nozzle loads.Caused by design error. Shims installed to reduce nozzle loads to acceptable limits. RAV-H.B. Southern California Edison Co. B3/07/12. Region 5, Office of Director. lp. 19701: 200. 24X Fiche: 50-361,83/07/12, R207286474
- 8307180284 Forwards turbine trip test results showing plant dynamic response per design requirements following 830616 turbine trip. Approval requested for proposed FSAR mod re power ascension testing sequence to support startup testing.

  BASKIN. K. P. Southern California Edison Co. 83/07/14. KNIOHTON. Q Licensing Branch G. 3pp. 19554:125. 24X Fiche: 50-361.83/07/14.8307160284.
- ---8307180286 "Assessment of Turbine Trip of 830616 for Satisfying FBAR Requirements,"

  \* Southern California Edison Co. 83/07/14. 34pp. 17596:128. 24X Fiche: 50-361,83/07/14.8307180284.
- 8307280491 RO 83-073; on 830714, while in Mode 1 at 50% power, Channels B & D contained nonconservative core protection for addressable constants. Caused by constants from previous channel test left in data base.

  RAY. H. B. Southern California Edison Co. 83/07/15. MARTIN, J. B. Region 5. Office of Director. 2pp. 19701: 218. 24% Fiche: 50-361,83/07/15,8307250491.
- DOCKET 50-362 SAN GNOFRE NUCLEAR STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 8307060329 Generic Ltr 83-27 to all liconsess & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.Svc list encl.
  EISENHUT, D. 0. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669; 254. 24x
  Fiche: 50-000.83/07/06,8307060329.
- F. Security, medical, emergency & fire protection plans
- 8307060066 Forwards info re Drange County & San Clemente, CA plans for emergency planning zone. Info re Orange County Transit District emergency preparedness training also encl. BASKIN, K. P. Bouthern California Edison Co. 93/07/01. KNIGHTON, G. W. Licensing Branch 3. 77pp. 19251:071. 24X Fiche: 50-361, 83/07/01, 8307060066.
- 8307060128 Forwards proposed change to License NPF-15, re License Condition 2. C(12)6, "Fire Protection," for review & approval. Formal request for amend will be submitted during wk of 830711.

  BASKIN.K.P. Southern California Edison Co. 83/07/01. KNIGHTDN.G.W. Licensing Branch 3. 5pp. 19238:250. 24X Fiche: 50-362,63/07/01,8307060128.
- 8307200473 Comments on 830513 response to Generic Ltr 82-33 (NUREQ-0737 Suppl 1) on detailed control room design & safety parameter display sys recview. Schedule for program plan or documentation describing processes & activities requested. KNIGHTGN: 9. W. Licensing Branch 3. 83/07/08. DIETCH.R. Southern California Edison Co. HOLCOMBE.J.C. San Diego 9as & Electric Co. 2pp. 19671:361. 24X Fiche: 50-361.83/07/08.8307200473.

- 8307150215 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17.
  81SH09.T.W. Region 5. Diffice of Director. 83/07/11. PAPAY, L. T. Southern California Edison Co. 1p. 19530:269, 24X Fiche:50-206.83/07/11, 8307150215.
- --8307150222 Responds to NRC 830516 1tr re violations noted in IE Insp. Repts 50-204/83-10, 50-361/83-19 & 50-362/83-17. Corrective actions: fixed emergency lighting systested & instructions revised. Six addl lights will be installed. PAPAYL. T. Southern California Edison Co. 83/04/15. MARTIN. J. B. Region 5, Office of Director. 4pp. 19530: 270. 24X Fiche: 50-204, 83/07/11, 8307150215.
- 8307270029 Forwards Rev 10 to physical security plan. Rev withheld (ref 100FR73.21).
  BASKINN.P. Southern California Edison Co. 83/07/21. Division of Licensing. 1p. 19749:359. 24X Fiche:50-206.83/07/21.8307270029.
- 8307260135 Discusses review of emergency operations facility (EDF) ventilation sys design. Potential problem w/air leakage from EOF equipment will be corrected.

  BASKIN.K.P. Southern California Edison Co. 83/07/22. EISENHUT, D. 0. Division of Licensing. 1p. 19727: 289. 24X Fiche: 50-206, 83/07/22, 8307260135.

### 9. Adjudicatory correspondence

- 830705004B Advises that time for Commission to review ALAB-717 expired. Commission declined review Decision became final agency action on 830621.
  CHILK, 8. J. Office of the Secretary of the Commission. 83/06/30. WHARTON, R. J. San Diego, Univ. of, San Diego, CA. ip. 19192:163. 24X Fiche: 50-361,83/06/30,8307050048.
- 8307050095 Advises that time for Commission to review ALAB-717 expired. Commission declined review Decision became final agency action on 830621.
  CHILK, B. J. Office of the Secretary of the Commission. B3/06/30. MCCLUNG. C.E. Flemming, Anderson, McClung & Finch. 1p. 19193:191. 24K Fiche: 50-361, 83/06/30. 8307050055.

## P. Operating license stage documents & correspondence

- 8307130411 Forwards request for add1 info to complete NRC review of util submittal addressing NUREG-0737. Item II. D. 1, "Performance Testing of Relief & Safety Valves." Response requested within 30 days. KNIGHTON.O.W. Licensing Branch 3. 83/06/27. DIETCH.R. Southern California Edison Co. 10pp. 19540: 146. 24X Fiche: 50-361,83/06/27, 8307150411.
- 8307060091 Requests concurrence w/mods to post-fuel loading initial test program for FSAR Sections 14.2.10.2, "Initial Criticality" & 14.2.12.96. "Loss of Offsite Power Test."

  BASKIN.K.P. Southern California Edison Co. 83/06/29. KNIOHTON.G.W. Licensing Branch 3. 4pp. 19238:246. 24X Fiche: 50-361.83/06/29, 8307060091.
- 8307060128 Forwards proposed change to License NPF-15, re License Condition 2.C(12)b, "Fire Protection," for review & approval.Formal request for amend will be submitted during who of 830711,

  BASKIN.K.P. Southern California Edison Co. 83/07/01, KNIGHTON, Q.W.
  Licensing Branch 3. 5pp. 19238:250, 24X Fiche:50-362,83/07/01,
  8307060128.
- 8307060155 Forwards fees for 821119,1203,20 & 830107 proposed changes to Tech Specs re Unit 3 low water level refueling operations, turbine overspeed protection for Unit 2 & component cooling water loops for Units 2 & 3.

  BASKIN,K.P. Southern California Edison Co. 83/07/01. MILLER, W. O. License Fee Management Branch. 4pp. 19249:230. 24X Fiche: 50-361,83/07/01,8307060155.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIBENNUTD. 9. Division of Litensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 3307070065 Forwards inservice insp & testing program plan. BASKIN, K.P. Southern California Edison Co. 83/07/05. KNIGHTON, G. H. Licensing Branch 3. ip. 19268:047. 24X Fiche:50-362,83/07/05, 8307070065.
- -8307070067 Inservice insp & testing program plan. \* Southern California Edison Co. 83/07/05. 25App. 19268:048. 24X Fiche:50-362.83/07/05.8307070065.

- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EIGENHUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307180096 Forwards C-E Owners Group program description for resolving TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps" & trip two/leavs two strategy. Bchedule for generic operations-related info being developed.

  BASKIN.K.P. Southern California Edison Co. B3/07/14, KNIGHTON, Q.W. Licensing Branch 3. App. 19556:357. 24X Fichs: 50-361,83/07/14, 8307180096.
- 8307180105 Responds to 830701 & 07 telcon requests to reevaluate 830307 core protection calculator (CPC) schedule & to implement CPC software corrections. Secondary calorimetric power & plant power differences clarified.

  BASKIN.K.P. Southern California Edison Co. 83/07/14. KNIGHTON, G. W. Licensing Branch 3. 2pp. 19557:020. 24X Fiche: 50-361.83/07/14.
- B307180121 Application for amend to License NPF-15, changing Tech Specs re auxiliary feedwater sys to permit entry into & operation in Mode 3 prior to initial criticality w/one motor-drayen auxiliary feedwater pump incoperable, W/Class III fee.

  BASKIN.K.P. Bouthern California Edison Co. B3/07/14. KNIGHTON, Q. W. Licensing Branch G. 2pp. 19556:260. 24X Fiche: 50-362, 83/07/14, B307180121.
- --8307180126 Proposed Tech Spec changes permitting entry into & operation in Mode 3 prior to initial criticality w/one motor-driven auxiliary feedwater pump inoperable.

  # Southern California Edison Co. 83/07/14. 4pp. 19556:262. 24X Fiche: 50-362,83/07/14.8307180121.
- B307180236 Requests concurrent review & approval of B30106 & 25 Proposed Changes NPF-10-33 & NPF-15-33, respectively. Proposed revised DNBR penalty factors partially restore operating margin removed by current rod bow penalty factors. BASKIN.K.P. Southern California Edison Co. 83/07/14. KNIGHTON, Q.W. Licensing Branch 3. 2pp. 19555:229. 24X Fiche: 50-361, 83/07/14, 8307180236.
- 8307200202 Forwards "Rept on Hydrogen Sensor Response to Dynamic Hydrogen Buildup for Sauthern California Edison Co." per util 830420 ltr.Results support acceptability of post-LDCA hydrogen monitoring sys.

  BASKIN.K.P. Southern California Edison Co. 83/07/18. KNIGHTON.Q.W. Licensing Branch J. 2pp. 19648:009. 24X Fiche: 50-361,83/07/18,8307200202.
- --B307200203 "Rept on Hydrogen Sensor Response to Dynamic Hydrogen Buildup for Southern California Edison Co." HEVERLY,L. General Electric Co. PIR 1454-294. B3/04/27. 16pp. 19448:011. 24X Fiche: 50-341, 83/07/18, 8307200202.
- 8307270162 Discusses commitment to resolve design concerns re adequacy of fuel shoulder gap clearance to accommodate differences observed as Arkansas Nuclear One Unit 2 in fuel rod & guide tube axial grouth.

  BASKIN.K.P. Southern Celifornia Edison Co. B3/07/25, KNIGHTON, Q. W. Licensing Branch 3. ip. 19749:340. 24X Fiche: 50-361, 83/07/25, B30/270162.

#### Q. Inspection reports. IE Bulletins & correspondence

- B307120340 Forwards IE Insp Repts 50-361/83-23 & 50-362/83-22 on 830509-13 & 0531-0603 No noncompliance noted.
  BISHOP,T.W. Region 5, Office of Director. 83/06/27. PAPAY,L.T. Southern California Edison Co. 2pp. 19434:028. 24X Fiche: 50-361,83706/27,8307120340.
- 8307050010 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PNR Plants," Action Items 1,2 & 4. Required insps will be performed only when closures are opened for component maint.

  HAYNES, J. Q. Southern California Edison Co. 83/06/29. MARTIN, J. B. Region 5, Office of Director. 12pp. 19192:091. 24% Fiche: 50-361, 83/06/29, 8307050010.
- 8307070065 Forwards inservice insp & tasting program plan.
  BASKIN, K.P., Southern California Edison Co. 83/07/05. KNIGHTON, O. W.
  Licensing Branch G. ip. 19268: 047. 24X Fiche: 50-362, 83/07/05,
  8307070065.

- --B307070067 Inservice insp & testing program plan.

  \* Southern California Edison Co. B3/07/05. 256pp. 19268:048.
  24X Fiche: 50-362,83/07/05,8307070065.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Bubsystem." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24% Fiche: 50-000, 83/07/11, 8306270401.
- 8307180215 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17.
  815H0P,T.W. Region 5, Office of Director. 83/07/11. PAPAY, L. T. Beuthern California Edison Co. 1p. 19530:269. 24% Fichs:50-206,83/07/11,8307150215.
- --8307150222 Responds to NRC 830516 ltr re violations noted in IE Insp Repts 50-206/83-10.50-361/83-17 & 50-362/83-17. Corrective actions: fixed emergency lighting eys tested & instructions revised. Bix addi lights will be installed. PAPAY.L.T. Southern California Edison Co. 83/06/15. MARTIN, J. B. Region 5, Office of Director. 4pp. 19530: 270. 24X Fiche: 50-206, 83/07/11, 8307150215.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Caseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307220465 Monthly operating repts for May 1983.W/830615 ltr.
  MAYNEATHER.L., RAV.H.B. Bouthern California Edison Co. 83/06/15.
  Uffice of Resource Management, Director. 25pp. 19685:322. 24X
  Fiche:50-361.83/06/15.8307220465.
- 8307130192 Submits second progress rept for post-accident sampling sys (PASS) as of 830701. Test verifying total gas capability completed Med outage for sys maint will be completed by 830820.

  BASKIN, K. P. Bouthern California Edison Co. 83/07/11. KNIGHTON, G. W. Licensing Branch 3. Spp. 19465: 347. 24X Fiche: 50-361, 83/07/11, B307130192.
- 8. Reportable occurrences, LERs & related correspondence
- 8307060387 Updated LER 83-029/01X-1: on 830325, vandor identified concern re valve position indication for Westinghouse gate valve. Caused by design defect. Instructions to visually & manually check valve instituted. W/830622 1tr. RAY.H. B. Southern California Edison Co. 83/06/22. MARTIN, J. B. Region 5. Office of Director. 3pp. 19236: 117. 24X Fiche: 30-362, 83/06/22, 8307060387.
- 8307060311 LER 83-034/01L-0: on 830527, potential for loss of indication during & after seismic event discovered during testing of qualified safety parameter display sys akin to installed sys. Gaused by loose lockwasher. H/830627 ltr. RAY.H.S. Southern California Edison Co. 83/06/27, MARTIN, J.B. Ragion 5. Dffice of Director. 3pp. 19239: 179, 24X Fiche: 50-362,83/06/27,8307060311.
- 8307130076 RDs 83-063 & 83-037: on 830621, motor-driven auxiliary feedwater pumps 2P-141 & 3P-504 failed to complete 48 h endurance test successfully. Initially reported on 830624. Caused by improperly machined oil grooves. LERs forthcoming. RAY.H.B. Southern California Edison Co. 83/06/27. MARTIN, J.B. Region 5. Office of Director. 2Pp. 19465: 339. 24X Fiche: 50-361, 83/06/27, 8307130076.
- 8307130275 RD: C-E has advised util that RCS hot leg sampling line noizle loads exceed stress limits. Acceptability of ASME requirements being evaluated Fourteen-day rept will be submitted by 830712.

  RAY.H.S. Southern California Edison Co. 83/06/29. MARTIN, J. B. Region 5, Office of Director. 2pp. 19508: 288. 24X Fiche: 50-361, 83/06/29, 8307130275.
- 8307180050 Forwards LERs 83-043/01T-0 & 83-037/01T-0. RAY.H.B. Bouthern California Edison Co. 83/07/08. MARTIN.J.B. Ragion 5. Office of Director. 2pp. 19560:246. 24X Fiche:50-361,83/07/08,8307180050.

- --8307180033 LER 63-039/01T-0: on 8306≥1, motor-driven auriliary feedwater pump 3P-504 declared inoperable following failure to complete 48 h endurance run. Caused by failed outboard bearing. Dearings replaced.

  RAY.H.B. Southern California Edison Co. 83/07/08. Region 5, Office of Director. 2pp. 19360:250. 24X Fiche: 50-361,83/07/08.
- B307180093 RDs B3-072 & B3-041: on B30706, w/Unit 2 in Mode 5 & Unit 3 in Mode 4. marine fouling of inservice component cooling water HXS resulted in high differential pressure & reduced saltwater cooling flow. HXS realigned.
  RAY.H.B. Southern California Edison Co. B3/07/08. MARTIN, J.B. Region 5. Office of Director. 2pp. 19556:326. 24X Fiche: 50-361, 83/07/08, 8307180093.
- B307250394 RD B3-043: nn B3070B, train B emergency chiller E-335 declared inoperable, rendering all equipment inoperable in rooms in both units where chilled water provided to root ambient air. Cause not stated. MORQAN.H.E. Southern California Edison Co. B3/07/11. MARTIN.J.B. Region 5, Office of Director. 2pp. 19701:326. 24% Fiche: 50-362,83/07/11,8307250394.
- --8307250477 LER 83-040/01T-0: on 830628; C-E advised util of deficient RCS hot leg sampling nottle loads Caused by design error. Shims installed to reduce nottle loads to acceptable limits. RAY.H.B. Southern California Edison Co. 83/07/12. Region 5, Office of Director. 1p. 19701: 200. 24X Fiche: 50-361, 83/07/12, 8307250474.
- 8307250298 RD 83-044: on 830711, during Mode 4, manual isolation valve MU-039 unlocked & opened in response to request for svc air. Caused by assistant control operator not recognizing Tech Spec requirement.
  RAY: H. B. Southern California Edison Co. 83/07/13, MARTIN, J. B. Region 5. Office of Director. 209. 19705: 320. 24% Fiche: 50-362, 83/07/13, 8307250298.
- 8307250426 LER 83-045/03L-0: on 830614, while performing QC insp of fire barrier penetration seals in Mode 5, five seals in diesel generator bldg damaged. Cause not determined. Fire watch in effect until seals repaired. H/830714 ltr. RAY,H. B. Southern California Edison Co. 83/07/14. MARTIN. J. B. Region 5, Office of Director. 2pp. 19701:262. 24X Fiche: 50-362.83/07/14.8307250426.
- B307250459 Updated LER 82-006/01X-1:on 821217, while in Mode 5.ESF actuation sys inadvertently activated Caused by simultaneous failure of two independent power supplies associated w/plant protection sys. Switch replaced W/830715 ltr. RAY, H. B. Southern California Edison Co. 83/07/15. MARTIN, J. B. Region 5. Dffice of Director. 4pp. 19701:246. 24X Fiche: 50-362,83/07/15,8307250437.
- DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307180314 Releases public version of revised emergency plan implementing procedure. FELTON.J.M. Division of Rules and Records. 83/06/24. Pocum Management Branch. 1p. 19366:090. 24X Fiche: 50-348,83/06/24,8307180314.
- --8307180319 Public Version of Rev 5 to Emergency Plan Implementing Procedure PNP-0-EIP-26, "Offsite Notification." W/830614 ttr. transmittal form & procedure request form. ODOM, J. E., HUDSPETH, J. B. Alabama Power Co. 83/06/10. Office Nuclear Reactor Regulation, Director. 5pp. 19366:091. 24x Fiche: 30-348, 83/06/24, 8307180314. Office of
- 8307220520 Ack receipt of 830705 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-348/83-15 & 50-364/83-13. VERRELLI.D.M. Division of Project & Resident Programs. 83/07/13. MCDONALD.R.P. Alabama Power Co. 1p. 19685:031. 24X Fiche: 50-348.83/07/13.8307220520.
- --B307220530 Responds to NRC 830615 ltr re violations noted in IE Insp. Repts 50-348/83-15 & 50-364/83-13. Corrective actions: no smoking signs posted on auxiliary feedwater pump room & personnel counseled re proper loging of entries. CLAYTON.F.L. Alabama Power Co. 83/07/05. VERRELLI.D.M. Region 2, Office of Director. 3pp. 17685:032. 24X Fiche: 50-348. 83/07/13,8307220520.

- --8307220537 Notice of violation from insp on 830461-0510. \* Region 2, Office of Director. 83/06/15. ip. 19685:037. 24X
- ~~B307220549 IE Insp Repts 50~348/83~15 & 50~364/83~13 on 830411~0510. Noncompliance noted:violation of Tech Spec Section 6.8 research in prohibited area in victinity of auxiliary bidg. 19685:038. 24x Fiche: 50~348, 93/07/13, 8307220520.
- 8307250696 Releases public version of revised emergency plan implementing procedure.
  FELTON J. M. Division of Rules and Records. 83/07/19. Docum Management Branch. ip. 19720:151. 24X Fiche: 50-348,83/07/19.
- --8307250699 Public Version of Rev 28 to Emergency Plan Implementing Procedure FNP-0-EIP-8, "Notification Roster." W/830502 ltr. Reactor Regulation, Director, 30PP. 19720:153, 24X
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307080402 Forwards Rev 1 to updated FSAR.Vol 21.for JM Farley Nuclear Flant.Units 1 & 2.Rev reflects plant & procedure mods through B30101 & changes per 10GFR30.37(b). Alabama Power Co. 83/07/01. VAROA.S.A. Office of Fiche: 50-348.83/07/01.8307080402.
- ---8307080405 Rev 1 to updated FSAR.Vol 21.for JM Farley Nuclear Plant. Units 1 & 2. \* Alabama Power Co. 83/07/31. 577pp. 19354:093. 24X Fichs:50-348.83/07/01.8307080402.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensess, applicants for OLs & holders of CPs for Nestinghouse PHRs as safety evaluation of "Emergency Response Quidelines."

  EISENHUT, D. O. Division of Licensing, 83/06/03, Yankee Atomic Blectric Co. 10pp. 19563:116, 24% Fiche:50-000,83/06/03,
- 8307010132 Remits fee for Amend 21 to License NPF-8 re masonry wall review.in response to 830526 ltr.
  CLAYTON.F.L. Alabama Power Co. 83/06/13. MILLER.W.O. License Fee 8307010132.
- B307010182 Forwards mod to "Conduct of Operations" re-post-trip review.

  Permanent rev approval expected within 60 days.

  GLAYTON, F. L. Alabama Power Co. B3/06/28. VARQA, S. A. Office of Nuclear Reactor Regulation, Director. 1p. 17124:287. 24X
- --8307010187 "Temporary Procedure Change, Conduct of Operations -Operations Oroup."

  \* Alabama Power Co. 83/06/28, 7pp. 19124:288, 24x
  Fiche: 50-348, 83/06/28, 8307010182.
- GO7080479 Advises that util & DDE have executed DE-CR01-B3NE44361.
  "Contract for Disposal of Spent Nuclear Fuel &/or High Level
  Ltr B3-07.
  Ltr B3-07.
  CLAYTON.F.L. Alahama Power Co. B3/06/2B. VARGA.S.A. Office of
  Nuclear Reactor Regulation, Director. ip. 19346: 322. 24X
- NOTOTOIO4 Supplemental application to amend Licenses NPF-2 & NPF-8, requesting withdrawal of every water portions of 830201 & 0620 Tech Specs. Info me syc water batteries will be provided CLAYION, F.L. Alebama Power Co. 83/06/29. VAR9A, S.A. Office of Fiche: 50-348, 83/06/29, 8307070104.
- 07080308 Forwards safety evaluation of B21116 Tech Spec change to reflect change in organization & mot titles, in response to B30629 request Change is administrative in nature. CLAYTON,F.L. Alebama Power Co. B3/06/29, VARQA,S.A. Office of Succession Regulation, Director. 2pp. 19330:163, 24X

- 8307080272 Forwards design info for automatic shunt trip of reactor trip breakers & description of scope & objective of DS-416 undervoltage trip attachment confirmatory life testing program. Info withheld (ref 10CR2.790).

  CLAYTON.F.L. Alabama Power Co. 83/06/30. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 19349:307. 24X Fiche: 50-348,83/06/30,8307080272.
- 8307120883 Notice of consideration of issuance of amends to Licenses NPF-2 & NPF-8 & proposed no significant hazards consideration determination & opportunity for hearing reflexibility in defining rod inoperability.

  VAROA.S. A. Operating Reactors Branch 1. 83/06/30. 7pp. 19508:329, 24X Fiche: 50-348,83/06/30,8307120885.
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Syc list encl. EISEMAUT.D. Q. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 179390:317. 24X Fiche: 50-000, B3/07/05, 8306270397.
- B307130262 Forwards comments on SER re util relief requests from inservice testing requirements. BERs should be revised by B30901 to ensure that Unit 2 outage will not be impacted. CLAYTON.F.L. Alabama Fower Co. B3/07/05. VARGA, B. A. Office of Nuclear Reactor Regulation, Director. Spp. 19308: 238. 24X Fiche: 50-348, B3/07/05, B307130262.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in BTS, Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/06. Consolidation Co. of New York, Inc. 16pp. 17669:254. 24x Fiche: 30-000, B3/07/06, 8307060329. Consolidated
- B307120483 Submits info in response to request for changes to emergency operating procedures (EOP) for reactor trip & anticipated transient w/o trip (ATHT). Draft reactor trip EOP to be completed within 2 wks. ATMT EOP to be revised. CLAYTON.F.L. Alabama Power Co. B3/07/06. VARQA.S.A. Office of Nuclear Reactor Regulation Director. 2pp. 19425:060. 24X Fiche: 50-348, 83/07/06, 8307120483.
- 8307140110 Forwards notice of consideration of issuance of amends to Licenses NPF-2 & NPF-8 & proposed no significant hazards consideration re testing & insp of river water sys.

  \* Division of Licensing, 83/07/06. CLAYTON,F. L. Alabama Power Co. ip. 19528:112. 24X Fiche:50-348,83/07/06,8307140110.
- ---B307140116 Notice of consideration of issuance of amends to Licenses NPF-2 & NPF-D & proposed no significant hazards consideration determination, correcting administrative error in Tech Specs re testing & insp of river water sys. VARGA: S.A. Operating Reactors Branch 1, B3/07/06, 4pp. 19528: 113. 24X Fiche: 50-348, 83/07/06, 8307140110.
- B307150402 Notification of B30713 appeal meeting w/util & Westinghouse in Bathesda: MD to discuss util requests to delete turbine valve testing from Tech Specs. REEVES, E. Operating Reactors Branch 1. B3/07/07. VARQA, S. Operating Reactors Branch 1. 2pp. 19540: 161. 24x Fiche: 50-364, 83/07/07, 8307190402.
- B307250567 Notification of date change for B30816 meeting w/util & Westinghouse in Bethesda, MD to discuss util requests to delete turbine valve testing from Tech Bpecs. Meeting originally scheduled on B30713, REEVES, E. Derating Reactors Branch 1. B3/07/07, VARGA, B. Operating Reactors Branch 1. 2pp. 19716:001. 24X Fiche: 50-364, 83/07/07, 8307250567.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHMUT. D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000.83/07/08.8307080169.
- 8307150097 Application to amend Licenses NPF-2 & NPF-B changing Tech Specs re leak rate testing criteria. Proposed one-time amend for Unit 2 designated Class III. Permanent Tech Spec change considered suppl to 820810 submittal. CLAYTON.F.L. Alabama Power Co. 83/07/08. VARQA.S.A. Office of Nuclear Reactor Regulation: Director. 4pp. 19536:012. 24X Fiche:50-348.83/07/08.8307150097.
- --8307150099 Proposed Tech Specs re leak rate testing criteria. \* Alabama Power Co. 83/07/08. 4pp. 19536:016. 24X Fiche: 30-348, 83/07/08, 8307150097.

- 8307190144 Application to amend License NPF-B requesting one-time Tech Spec change to permit foregoing turbine valve testing after 830729 by advancing approval date to 830718. Approval by 830718 requested.

  CLAYTON.F.L. Alabama Power Co. 83/07/13. VARGA.S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 19636:192. 24X Fiche: 50-364, 83/07/13, 8307190144.
- 8307200104 Supplis B30714 request for add1 info to support expedited review of B30523 application for one-time change to License NPF-B, to forego turbine valve testing until end of fuel cycle.

  CLAYTON F. L. Alabama Power Co. B3/07/15. VAROA, S. A. Office of Nuclear Reactor Regulation, Director. 3pp. 19447:141. 24X Fiche: 50-364, B3/07/15, B307200106.
- --B307200110 Revised proposed Tech Spec Pages 3/4 3-72 & 3/4 3-73, permitting one-time change to forego weekly turbine valve testing until end of fuel cycle.

  \* Alabama Power Co. B3/07/15. 2pp. 19647:144. 24X Fiche: 50-364, B3/07/15, B307200106.
- 8307290334 Notice of consideration of issuance of amend to License NPF-8 & proposed NBHC determination & apportunity for hearing re Cycle 2 refueling in area of pressure isolation valves leak rate test criteria.

  VARGA.S.A. Operating Reactors Branch 1. 83/07/22. 9pp. 19858:139. 24X Fiche: 50-364,83/07/22,8307290334.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140169 Forwards IE Insp Rept 50-364/82-25 on 821028-1102 & notice of violation. W/o notice of violation. LEWIG R. C. Division of Project & Resident Programs. 83/02/03. MCD0NALD, R. P. Alabama Power Co. 2pp. 19523: 167. 24X Fiche: 50-364, 83/02/03, 8307140169.
- --B307140184 IE Insp Rept 50-364/82-25 on 821028-1102. Noncompliance noted: containment spray sys inoperable for indefinite period of time prior to 821028. Enforcement meeting held on 821119. BRADFORD, M. H. Region 2, Office of Director. CANTRELL, F. S. Division of Project & Resident Fragrams, 83/02/02. 5pp. 19323:169. 24X Fiche: 50-364,83/02/03,8307140169.
- B307140054 Extends invitation to attend B30701 mgt meeting at Region II ofc to present findings of util investigation of transuranic matls in radwaste shipments, per B30607 telcon.
  LEWIB.R.C. Division of Project & Resident Programs. B3/06/10. MCDQNALD.R.P. Alabama Power Co. 2pp. 19514:143. 24X Fiche: 50-348, 83/06/10, 8307140054.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11.8306270401.
- B306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 14ipp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307220520 Ack receipt of 830705 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-15 & 50-348/83-13. VERRELLI, D.M. Division of Project & Resident Programs. 83/07/13. MCDUNALD, R. P. Alabama Power Co. 1p. 17485:031. 24X Fiche: 50-348, 83/07/13, 8307220520.
- --B307220530 Responds to NRC 830615 ltr re violations noted in 1E Insp Repts 50-348/83-15 & 50-344/83-13. Corrective actions: no smoking signs posted on auxiliary feedwater pump room & personnel counseled re proper logging of entries. CLAYTON,F.L. Alabama Power Co. 83/07/05, VERRELLI,D.M. Region 2, Office of Director. 3pp. 19685:032. 24X Fiche: 50-348, 83/07/13,8307220520.
- --8307220534 Forwards IE Insp Repts 50-348/83-15 & 50-344/83-13 on 830411-0510 & notice of violation. VERRELLID.M. Division of Project & Resident Programs. 83/04/15. MCDDNALD.R.P. Alabama Power Co. 2pp. 19685:035. 24X Fiche: 50-348,83/07/13,8307220520.
- --8307220539 Notice of violation from insp on 830411-0510. \* Region 2, Office of Director. 83/06/15. ip. 19685:037. 24X Fiche: 50-348,83/07/13,8307220520.

- --8307220549 IE insp Repts 50-348/83-15 % 50-364/83-13 on 830411-0510 Noncompliance noted: violation of Tech Spec Section 6.8 resmoking in prohibited area in vicinity of auxiliary bldg. BRADFORD, H. H., RULAND, W. H. Region 2, Office of Director. CANTRELL.F.S. Division of Project & Resident Programs. 83/06/15.8pp. 19685:038. 24% Fiche: 50-348.83/07/13,8307220320.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits" Syc list entl.

  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715.270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307190113 Monthly operating rept for June 1983.W/830712 ltr. HAKRSTON.W.G., CLAYTON.F.L. Alabama Power Co. 83/07/06. Office of Resource Management. Director. 5pp. 19636:040. 24X Fiche: 50-364,83/07/06.8307190113.
- B307180095 Forwards status of licensing items requiring NRC approval as of B30708.

  CLAYTON.F.L. Alabama Power Co. B3/07/08. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 9pp. 19596:331. 24X Fiche: 50-348
- S. Reportable occurrences, LERs & related correspondence
- 8307120576 Forwards LERs 83-025/03L-0 & 83-024/03L-0. CLAYTON.F. L. Alabama Power Co. 83/06/22. Region 2, Office of Director. 1p. 19433:079. 24X Fiche:50-348,83/06/22,8307120576.
- --B307120590 LER 83-025/03L-0: un B30528; during Calibr Procedure FNP-2-STP-612.0, reactor coolant pump 2A undervoltage relay 27-3 declared inoperable Caused by setpoint drift.Relay setpoint adjusted.
  HAIRSTON.W.O. Alabama Power Co. B3/06/22. Reginn 2, Dffice of Director. ip. 19433:080. 24X Fiche: 50-34B,83/06/22,8307120576.
- DOCKET 50-364 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8307140225 Forwards FEMA Region IV rept of observation results from 821208-09 emergency exercise & Georgia Emergency Mgt Agency response. Encourages continued work w/offsite agencies as necessary to resolve open issues.

  O'REILLY, J.P. Region 2: Office of Director. 83/03/25. KELLY, R. J. Georgia Power Co. 25pp. 19323:126. 24X Fiche: 50-321,83/03/25,8307140225.
- 8307060287 Furwards IE Safeguards Insp Repts 30-321/83-12 & 50-366/83-12 on 830424-28 & notice of violation.Notice of violation withheld (ref 100FR73.21).

  LEWIS, R. C. Division of Project & Resident Programs. 83/05/17.

  KELLY, R. J. Georgia Power Co. 2pp. 19238: 297. 24X

  Fiche: 50-321, 83/05/17, 8307060287.
- --9307060299 IE Safeguards Insp Repts 30-321/83-12 & 50-366/83-12 on 830424-28. Noncompliance noted in area of personnel access control. Details withheld (ref 100FR73.21)
  HALL,B.L. Region 2. Office of Directon 83/05/16. 1p. 19238:299. 24X Fiche: 50-321.83/05/17.8307060287.
- 8307110173 Releases public version of revised emergency plan cross-reference procedure. FELTON,J.M. Division of Rules and Records. 83/06/24. Document Management Branch. Ep. 19386:008. 24X Fiche:50-321,83/06/24, 8307110173.
- --8307110176 Public version of Rev 1 to Emergency Plan Cross-Reference Procedure OPND 13. Receipt form encl. GUCMA.L.T. Georgia Power Co. 83/05/10. Office of Nuclear Reactor Regulation, Director. 3pp. 19386:009, 24X Fiche: 30-321, 83/06/24, 8307110173.
- 8307180247 Releases public version of transmittal sheet notifying of change to emergency plan implementing procedure.
  FELTON, J. M. Division of Rules and Records, 83/06/24. Document Management Branch. 1p. 19567; 336. 24X Fiche: 90-321, 83/06/24, 8307180249.
- --8307180251 Forwards public version of transmittal sheet notifying of deletion of Emergency Plan Implementing Procedure HNP-8133. NIX-H.C. Georgia Power Co. 83/05/27. Office of Nuclear Reactor Regulation, Director. 2pp. 19567:337. 24X Fiche:50-321:83/06/24. 8307180249.

- B307140467 Ack receipt of B30616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/B3-13 & LEWIS, R.C. Division of Project & Resident Programs. B3/06/27, E1che: 50-321, B3/06/27, B307140467.
- --8307140472 Responds to NRC B30520 itr re violations noted in IE Insp. Repts 50-321/83-13 & 50-366/83-13. Corrective actions: carbon filter replaced & criteria for carbon filter testing being outly. T. Georgia Power Co. B3706/16. O'REILLY, J. P. Region 2. B307140467.
- ---8307140473 Forwards IE Insp Repts 30-321/83-13 & 50-366/83-13 on 830326-0423 & notice of violation.

  LENTS.R.C. Division of Project & Resident Programs. 83/05/20.

  KELLYR.J. Georgia Power Co. 2pp. 19520:206. 24X

  Fiche: 50-321, 83/06/27, 8307140467.
- 307060346 Ack receipt of 830616 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-321/83-12 & 50-366/83-12 Barbards Insp Repts DANCE.H. Division of Project & Resident Programs. 83/04/30. KELLY,R. J. Georgia Power Co. 1p. 19234:178. 24X Fiche: 50-321,83/04/30,8307060346.
- 8307060352 Responds to NRC B30517 ltr re violations noted in IE Safeguards Insp Repts 90-321/83-12 & 50-366/83-12 Corrective actions withheld (ref 10CfR73-21).

  GUCHA, L. T. Georgia Power Co. 83/06/16. D'REILLY, J. P. Region 2, Office of Director. Ip. 19234:179. 24x Fiche:50-321,83/06/30,8307060346.
- 07220501 Suppls response to Generic Ltr 82-33 re emergency response iapability, clarifying position re schedule for mplementation of guidance in Reg Guide 1.97, Rev 2. Schedule 10 be developed per NUREG-0737, Suppl 1. Georgia Power Co. B3/07/18. STOLZ, J.F. Operating actors Branch 4. 1p. 19685; 149. 24% Fiche: 50-321, 83/07/18, 307820501.
- 7290514 Releases public version of revised emergency plan aplementing procedures.

  ELION, J. N. Division of Rules and Records. 83/07/19. Document Branch. Ip. 19857; 174. 24x Fiche: 50-321, 83/07/19, 107290514.
- D7290523 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-4530 real electrons supervisor & HNP-6002 readiation approximately the second supervisor and supe
- 07290530 Public version of revised emergency plan implementing racedures, including Procedures HNP-4530 re alert perations supervisor & HNP-8002 re radiation exposure finits.

  IX.H.C., ROCERG, W. H. Georgia Power Co. 83/06/29, 49pp. 9857:177, 24X Fiche:50-321,83/07/19.8307290514.
- ility Final Safety Analysis Report (FSAR) & amends
- 0035 Forwards Rev 1 to updated FBAR for EI Hatch Nuclear Plant, is 1 & 2. HAM, J. T. Georgia Power Co. 83/07/22 STOLZ, J. F. Operating tors Branch 4. 2pp. 19775:264. 24X-Fiche:50-321,83/07/22, 270035.
- 270038 Rev 1 to updated FSAR for EI Hatch Nuclear Plant.Units 1 &
- Georgia Power Co. 83/07/31. £142pp. 19775: 266. 24X the:50-321,83/07/22,8307270035.
- ating license stage documents & correspondence
- 376 Ack receipt of 830202 itr advising of preliminary results of y relief valve test program & plans to continue ng. Adjustment of Unit I test frequency to be consistent t & acceptable.

  R.C. Division of Project & Resident Programs. 83/03/18.

  AMILJ 7. Georgia Power Co. ip. 19323:329. 24x
- 146 Forwards monthly FR notice of amends to OLs involving NSHC. Ice of Nuclear Reactor Regulation, Director. 83/06/15. R.E. Florida Power & Light Co. 2pp. 19641:347. 24X 50-000,83/06/15,8307180446.

- -8307190001 Monthly notice of amends to OLs involving NSHC. CLARK.R.A. Decrating Reactors Branch 3. 83/06/07. 15; 19641:349. 24X Fiche:50-000,83/06/15,8307180446.
- B307060487 Confirms B30621 or all authorization for one-time change in Tech Spec Tables 3.3.2.1 & 3.3.2.2-2 re shutdown cooling sys isolation low water level trip setpoint due to damaged feedwater sparger bracket. Marked-up SER encl. ALINAS, G. C. Assistant Director for Operating Reactors. B3/06/21. BCKHAM, J.T. Georgia Power Co. 6pp. 19299:200. 24X Fiche: 50-366, B3/06/21, B307060487.
- 8307070554 Forwards confirmatory order re commitment to install permanent stram discharge sys mods by 831231. Proposed model Tech Specs also enci.
  STOLZ, J.F. Operating Reactors Branch 4. 83/06/24. BECKHAM, J.T. Georgia Power Co. 2pp. 19300:267. 24X Fiche: 50~321,83/06/24,8307070554.
- ~8307070557 Order confirming licensee commitments to install mods to scram discharge sys by 831231.
  EISENHUT, D. D. Division of Licensing. 83/06/24. Georgia Power Co. 34pp. 19300:269. 24X Fiche: 50-321, 83/06/24, 8307070554.
- 8307140359 Approves B30606 request to delay submittal of QA program description until 830630.

  LEWIS,R. C. Division of Project & Resident Programs. B3/06/24.

  GUCMA.L. T. Georgia Power Co. ip. 19325: 227. 24X

  Fiche: 50-321, 83/06/24, B307140359.
- 8307C80553 Advises that requirements of TMI Item II.K.3.13, "HPCI/RCIC Initiation Level" met. Item resolved.

  SIGLZ, J. F. Operating Reacture Branch 4. 83/06/27. BECKHAM, J. T. Georgia Power Co. 4pp. 19365:035. 24X Fiche: 50-321, 83/06/27.
- 8307060270 Requests mod to NRC 830330 order confirming licenses commitments on post-TMI-related issues, allowing extension for implementation of NVREG-0737, Item II. B. 3, "Post-Accident Sampling:" to 830901.

  GUCHALI, Georgia Power Co. 83/06/28, STDLZ, J. F. Operating Reactors Branch 4, 2pp. 19239: 166, 24x Fiche: 50-321, 83/06/28, 8307060270.
- B307200357 Forwards Amend 33 to License NPF-5, safety evaluation & initial NSHC determination & noticing action. Amend provides add1 & revised trip setpoints to reflect design mods reducing containment transient loads.

  RIVENBARK. G. Operating Reactors Branch 4. 83/06/29. BECKHAM. J. T. 8307200357.
- -8307200358 Requests FR notice of issuance of Amend 33 to License NPF-5 providing addl & revised trip setpoints to reflect design mods reducing containment transient loads.

  STOLZ.J.F. Operating Reactors Branch 4. 83/06/27. CLARK.R.A. Operating Reactors Branch 3. 3pp. 17670:105. 24x

  Fiche: 50-366, 83/06/27, 8307200357.
- -B307200360 Amend 33 to License NPF-5, providing add1 & revised trip setpoints reflecting design mods to reduce containment loads from plant transients.
  STDL7.J.F. Operating Reactors Branch 4. B3/06/29. 51pp. 19670.10B. 24X Fiche: 50-366, B3/06/29, B307200357.
- --8307200361 Safety evaluation supporting Amend 33 to License NPF-5.

  + Office of Nuclear Reactor Regulation, Director. 83/06/29.
  19pp. 19670:159, 24X Fiche:50-366.83/06/29,8307200357.
- 8307120014 Advises that return piping for reactor water cleanup sys on both units rerouted via feedwater piping to feedwater nottles, per Section 4. 2 of NURSC-0619. Fracture mechanic analysis per Generic Lir 81-11 expected by 830729.

  BECKHAM. J. T. Georgia Power Co. 83/06/30. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19423:153. 24X Fiche: 50-321, 83/06/30.
- B307270170 Forwards revised B30330 order re commitments to implement NUREG-0737 items, extending completion date for Item II.B. 3, "Post-Accident Sampling," to B30901.
  STGLZ.J.F. Operating Reactors Branch 4, B3/07/01, BECKHAM, J. T. Georgia Power Co. 3pp. 19811:146. 24X Fiche: 50-321,83/07/01,
- --8307270179 Mod of order confirming licensee commitments on post-TMI-related issues, extending completion date for Item II.B.3, "Post-Accident Sampling," to 830901. EISENHUT.B. © Division of Licensing. 83/07/01. Georgia Power Co. 5pp. 19811:149. 24X Fiche:50-321,83/07/01,8307270170.

- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- ©307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors a surveillance intervals in STS 8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19667:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- B307140541 Notification of B30707 meeting w/util in Bethesda, MD to discuss pipe crack matters.

  PRIVENBARK, G. Operating Reactors Branch 4. 83/07/06. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19527: 358. 24X Fiche: 50-366, 83/07/06, 8307140541.
- © 7270048 Defers implementation of Tech Specs re operability of high water level trip & turbine bypass sys for 60 days following startup for Cycle 4 operation to allow time to discuss objections raised in 830526 ltr.

  © TOL2.J.F. Operating Reactors Branch 4. 83/07/06. BECKHAM.J.T. Georgia Power Co. 3pp. 19811:035. 24X Fiche: 50-366.83/07/06.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/09. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fichs: 50-000, 83/07/08, 8307080169.
- D307180101 Commits to add1 volumetric testing of welds to determine extent of intergranular stress corrosion cracking in recirculation sys & RHR sys piping.per 830707 meeting w/NRC. Proposed insp plan will be submitted by 830805.

  HEAD, G.F. Georgia Power Co. 83/07/08. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19557:009. 24X Fiche: 50-364, 83/07/08, 830/07/08.
- BG07210335 Forwards order confirming util 830325,0402,08 & 0708 commitments to repair ultrasonic indications on recirculation sys piping. Order authorizes plant restart.

  BT0LZ,J.F. Operating Reactors Branch 4. 83/07/08. BECKHAM.J.T. Georgia Puwer Co. 4pp. 19672:332. 24X Fiche: 50~366,83/07/08.
- G. Inspection reports, IE Bulletins & correspondence
- EIGO7140292 Requests that liquid samples spiked w/radionuclides be analyzed for tritium, Sr-89 & Sr-90 content within 60 days of traceipt of samples. Spiked samples will be sent annually as part of routine insp program.

  LEMIS.R.C. Division of Project & Resident Programs. 83/02/07. KELLY.R.J. Georgia Power Co. 1p. 17525: 134. 24X Fiche: 50-321, 83/02/07, 8307140292.
- □□○7060287 Forwards IE Safeguards Insp Repts 50-321/83-12 & □0-366/83-12 on 830424-28 & notice of violation Notice of violation withheld (ref 10CFR73.21).

  LEWIS.R.C. Division of Project & Resident Programs. 83/05/17.

  KELLY.R.J. Georgia Power Co. 2pp. 19238:297. 24X

  Fiche: 50-321, 83/05/17, 8307060287.
- SO7140058 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers." No cracking observed in spargers or in in-vessel P ining during 1983 maint/refueling outage insp. GUCWALLT. Ocorgia Power Co. 83/06/24. Q'REILLY, J. P. Region 2, Office of Director. ip. 19514:145. 24X Fiche: 50-366:83/06/24, E307140058.
- B307140243 Responds to IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at PWRs." High pressure relief Valve & high pressure alarm sys installed & dripwell P Reumatic sys pressure switches reset.

  BECKHAM. J. T. Georgia Power Ca. 83/06/24. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19523:061. 24X Fiche: 50-321,83/06/24, B307140243.

- 8307140467 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-13 & 50-326/83-13.

  LEWIS.R.C. Division of Project & Resident Programs. 83/06/27.

  KELLY.R.J. Georgia Power Co. 1p. 19520:203. 24X
  Fiche: 50-321.83/06/27.8307140467.
- --8307140472 Responds to NRC 830520 ltr re violations noted in IE Insp. Repts 50-321/83-13 & 50-366/83-13. Corrective actions: carbon filter replaced & criteria for carbon filter testing being evaluated Results & schedule will be available by 830714. GUCWA-L.T. Georgia Power Co. 83/06/16. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19520:204. 24X Fiche: 50-321, 83/06/27, 8307140467.
- ---8307140473 Forwards IE Insp Repts 50-321/83-13 & 50-366/83-13 on 830326-0423 & notice of violation.

  LEWIS.R.C. Division of Project & Resident Programs. 83/05/20.

  KELLY.R.J. Georgia Power Co. 2pp. 19520: 206. 24X

  Fiche: 50-321, 83/06/27, 8307140467.
- --8307140476 IE Insp Repts 50-321/83-13 & 50-366/83-13 on 830326-0423
  Noncompliance noted:halogenated hydrocarbon & carbon not
  sampled following extensive control room mods.
  CRLENJAK.R. V., HOLMES-RAY.J. Region 2, Office of Director.
  BROWNLEE, V. L. Division of Project & Resident Programs. 83/05/16.
  4pp. 19520:209. 24X Fiche: 50-321,83/06/27,8307140467.
- 8307060346 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-321/83-12 & 50-366/83-12.

  DANCE, H. C. Division of Project & Resident Programs. 83/06/30. KELLY, R. J. Georgia Power Co. 1p. 19234:178. 24X Fiche: 50-321,83/06/30,8307060346.
- --8307060352 Responds to NRC 830517 ltr re violations noted in IE Safeguards Insp Repts 50~321/83-12 & 50~366/83-12 Corrective actions withheld tref 10CFR73. 21).

  GUCMA-L. T. Georgia Power Co. 83/06/16. 0'REILLY, J. P. Region 2.

  Office of Director. 1p. 19234:179. 24X Fiche: 50-321, 83/06/30.
- B307180101 Commits to add1 volumetric testing of welds to determine extent of intergranular stress corrosion cracking in recirculation sys & RHR sys piping.per B30707 meeting w/NRC. Praposed insp. plan will be submitted by B30805.
  HEAD. G.F. Georgia Power Co. B3/07/08. STGLZ, J.F. Operating Reactors Dranch 4. 1p. 17557:009. 24X Fiche: 50-366.83/07/08. B307180101.
- 8307210335 Forwards order confirming util 830525,0602,08 & 0708 commitments to repair ultrasonic indications on recirculation sys piping. Order authorizes plant restart. STOLZ.J. F. Operating Reactors Branch 4. 83/07/08. BECKHAM, J. T. Georgie Power Co. 4pp. 19672:332. 24X Fiche:50-366.83/07/08, 8307210375.
- ---8307210339 Order confirming licensee commitments to repair recirculation pipe sys cracks & authorizing restart.
  PURPLE, R.A. Division of Licensing. 83/07/08. Georgia Power Co.
  8pp. 19672:336. 24X Fichs:50-366.83/07/08.8307210335.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Poet 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19863:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list anel. TAYLOR, J. M. Division of QA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 90-000.83/07/14.8306270406.
- R. Periodic operating reports & related correspondence
- B307170006 Monthly operating repts for June 1983.W/B30710 ltr. NIX/H.C., REDMANZ,F.J. Georgia Pawer Co., 83/07/10. Director's Office, Office of Inspection and Enforcement. 42pp. 19635:058. 24) Fiche:50-321.B3/07/10,B307190006.

- S. Reportable occurrences, LERs & releted correspondence
- 8305230439 Forwards LER 83-024/03L-0.

  NIX.H.C. Georgia Power Co. 83/05/09. D'REILLY, J.P. Region 2,

  Office of Director. ip. 18538:200. 24X Fiche: 50-366, 83/05/09,
- --8305230444 LER 83-024/03L-0: on 830411. during primary containment temp instrument Surveillance Procedure HNP-2-3879, primary containment temp containment temp recorder alarm setpoints found out of tolerance. Caused by setpoint drift. Setpoints adjusted. Director. 3pp. 18538: 201. 24X Fiche: 50-366. 83/03/09, 8305230439.
- 8307120098 LER 83-037/03L-0: on 830603, during performance of Procedure MNP-2-5622, personnel noted hydrogen recombiner controllers out of calian. Caused by setpoint drift due to miscellaneous failed parts. Controllers recalibr. LM830628 Ltr. 1PPS. B. B. NIX.H. C. Georgia Power Co. 83/06/28. 0'REILLY, J. P. Region 2. Office of Director. 4pp. 19423:072. 24X
- 8307120357 Confirms 830623 LER 50-366/283-46 re discovery of improper installation of certain pipe whip restraints & justification for continued operation. Stresses in piping would not be sufficient to lead to piping failures.

  GUCWA, L.T. Georgia Power Co. 83/06/28. U'REILLY, J.P. Region 2, 057120357. Spp. 19429:102. 24X Fiche: 50-366, 83/06/28.
- B307150064 LER B3-033/03L-D: on B30606, surveillance coordinator discovered Protedure HNP-2-3195, "Meekly Breater Alignment Checks," not performed by B30605 Caused by Personnel error. Procedure performed on B30606. W/B30628 Ly Personnel error. 1PPS.S.B., NIX.H.C. Georgia Power Co. B3/06/28. D'REILLY, J. P. Regian 2, Office of Director. 4pp. 19548: 176. 24x
- 8307150094 LER 83-032/03L-0: on 830A10, during surveillance procedure audit, verification of river stage discharge rating curve discovered not performed at required frequency Caused by personnel error. Proper testing will be tracted M/830628 Ltr. Region 2, Office of Director. 4pp. 1936: 118. 24x
- 8307150120 LER 83-038/03L-0: on 830605, reactor bldg exhaust vent radiation monitor D (2D11-K609D) failed upscale. Caused by sensor & converter unit (2D11-N010D) failing electronically. Unit replaced & calibr b/monitor W/830628 ltr 17P58.8 B. NIX.H.C Georgia Power Co. 83/06/28 D'REILLY, J. P. Region 2, Office of Director. 4pp. 19336: 228. 24x
- 8307130071 Updated LER 82-085/03X-1: on 820813.RHR svc water pumps A & C declared inoperable as result of failure to meet min flow requirements. Caused by broken & bent tubes on cavitrol trim.

  Insp procedure intriated W/830430 ltr.

  IIFPS.S.B. NIX.H.C. Georgia Power Co. 83/06/30. O'REILLY.J.P.

  Region 2, Office of Director. 3pp. 19535:266. 24X
- 8307150385 LER 83-026/03L-0: on 830610, diesel generator 2C failed to auto-start after manual trip. Caused by shutdown solenoid stuck in shutdown position. Solenoid cleaned. W/830630 ltr. 81/05/30, Big. NIX.H.C. Georgia Power Co. 83/06/30, D'REILLY, J. P. Fiche: 50-366, 83/06/30, 8307150385.
- 8307250096 LER 83-046/01T-0; on 830622. AE informed util that high energy line break restraints for control rod drive sys. reactor water cleanup sys.RCIC sys & auxiliary steam sys not properly (nstalled Caused by personnel error. M/830706 ltr. Region 2, Dffice of Director. Spp. 19706: 053. 24x Picke: 50-366, 83/07/06, 8307250096.
- 8307250166 LER 83-037/03L-0: on 830614, Procedure HNP-2-3901 re relief valve operability discovered erroneously revised. Caused by personnel erron Procedure re-revised M/830712 ltm. TIPPSS. B. NIX.H.C. Georgia Power Co. 83/07/12. D'REILLY, J. P. Region 2, Office of Director. 4pp. 19706:114. 24X
- 307250269 LER 83-047/03L-0:on 830621.vacuum breaker 2821-F1108 found stuci in open position. Caused by bent hinge pin. Breaker TIPPS. 8. B., NIX.H. C. Georgia Power Co. 83/07/14 G'REILLY, J. P. Region 2. Office of Director. App. 19705:271. 24X

- 8307250343 LER 83-036/03L-0: on 830620, temporary changes made to Weld Overlay Repair Procedure HNP-2-101 found not reviewed as procedure reviewed by personnel error. Temporary changes made to TIFPS, 8. B., NIX, M.C. Georgia Power Co. 8307714 ltr. Region 2, Office of Director 4pp. 19703: 271. 24X
- 8307250348 LER 83-043/03L-0: on 830620. A torus water level recorder (2T48-R607A red pen) failed to respond to increase in torus water. Caused by incorrect installation drawing. Hose line correctly reinstalled on 830701. W/830714 ttr.
  TiPPS, S. B. NIX.H. C. Occupia Power Co. 83/07/14. O'REILLY, J. P. Region 2, Office of Director. App. 19703: 255. 24X
- 8307280308 FNO-II-83-056: on 830722, operator found insulation smoldering on steam-driven feedwater pump in turbine bldg. Caused by presence of oil Insulation removed & burning extinguished by workers on scene. Unit reduced to 50% power. FEEDLES, T. A. BROWNLEE, V. L. Region 2. Office of Director. 83/07/22. 2pp. 19787: 211. 24% Fiche: 50-366, 83/07/22, 8307280308.
- U. Congressional/Executive Correspondence
- 8307270047 Forwards monthly FR notice of consideration of lesuance of amends to QLs involving NSHC determination & opportunity DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 33/06/22. STAFFDRD, R. T. Senate, Environment & Public Works, 2pp. 1981; 018. 24x Fiche: 50-000, 83/06/22, 8307270047.
- --8307270050 Monthly notice of consideration of issuance of amends to OL1 involving NSHC determination & opportunity for hearing. CLARK, R.A. Operating Reactors Branch 3. 83706/07. 15pp. 24X Fichs: 50-000, 83/06/22, 8307270047.
- V. Operator Examinations
- 8307140317 Informs that written, plant oral & simulator operator & senior operator licensing exams scheduled for wk of 830726. Approved ref mail required by 830726. Applications must be submitted 60 days prior to exam. BECKHAM, J.T. Georgia Power Co. Gpp. 19525:114. 24X
- DOCKET 50-367 BAILLY GENERATING STATION
- A. Application/construction stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. Edison Co. Division of Licensing. 83/07/05. Conselidated Ficha: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors to STS. Svc list encl.
  EISENHUT, D. Q. Olvision of Licensing. 83/07/06. Consolidated Fiche: 50-000, 83/07/06, 8307060329.
- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2
- F. Security, medical, emergency & fire protection plans
- B307120269 Notifies that Procedures 1405.16 & 2405.16 "Electrical Penetration Fire Barriers," revised per 830405 ltr. Procedures reflect insp requirements for barriers instituted ARBINALL, J. R. Arkansas Power & Light Co. 83/05/31. SEIDLE, W. C. Fiche: 50-313, 83/05/31, 8307120269.
- 8307050292 Requests submittal of listed info in order to resolve five fire protection-related licensing actions.

  GLARK.R.A. Operating Reactors Branch 3. 83/06/21, GRIFFIN, J. M. Arkanses Power & Light Co. 3pp. 19263: 221. 24X

  Fiche: 50~36B, 83/06/21, 8307050292.
- 8307040282 Forwards IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830518-22 No noncompliance noted. SEIDLE, W. C. Region 4, Office of Director. 83/06/27. GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 19238: 344. 24%

- --8307060291 IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830418-22. No noncompliance noted Major areas inspected security plan & implementing procedures & security program audit Safeguards info withheld (10CFR73.21).

  EVANS.C.A. Region 4, Office of Director. 83/06/23. ip. 19238:346. 24X Fiche:50-313.83/06/29.8307060282.
- B307060230 Informs that response to NRC B30621 ltr on five open items re fire protection & schedule for submitting info to resolve items will be submitted by B30730.

  MARBHALL, J. R. Arkansas Power & Light Co. B3/06/30. CLARK, R. A. Operating Reactors Branch 3. 1p. 19239: 286. 24X

  Fichm: 50-368, B3/06/30, B307060250.
- 8307190416 Advises that facility identified by IAEA for application of IAEA safeguerds. Encl design info questionnaire must be submitted to NRC by 830822. M/o encl. EISENHUT, D. O. Division of Licensing. 83/07/06. GRIFFIN, J. M. Arkansas Power & Light Co. 3pp. 19540:178. 24x Fiche: 30-368, 83/07/06. 8307180416.
- B307180079 Advises that util will cease further expedited efforts to provide schedule per request for exemption from App R rebarrier & suppression/detection sys & NRC 830617 ltr.pending receipt of add1 NRC clarification.

  MARSHALL.J.R. Arkansas Fower & Light Co. B3/07/12. STOLZ, J.F., CLARK, R.A. Operating Reactors Branch 4. 3pp. 19360: 263. 24% Fiche: 50-313,83/07/12,8307180079.
- 8307170135 Provides add1 info in support of 820727 schedular request for exemption from 10CFR50.App R.in order to complete proposed mods to redundant safe shutdown equipment in Fire Zones 2100-Z & 2101-AA.

  MARSHALL.J.R. Arkansas Power & Light Co. 83/07/13. STOLZ.J.F. Operating Reactors Branch 4. CLARK.R.A. Operating Reactors Branch 3. 2pp. 17636:232. 24X Fiche: 50-313.83/07/13.8307190155.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307250482 Forwards Amend 1 to updated FBARs.W/o Unit 2 rept. MARBHALL.J.R. Arkansas Power & Light Co. 83/07/15. NRC - No Datailed Affiliation Given. 1p. 19708:100. 24X Fiche: 50-313,83/07/15.8307250482.
- P. Operating license stage documents & correspondence
- 8307220310 Forwards Rev 6 to QA program topical rept, "QA Manual Operations." Rev deletes procedural refs throughout text & changes organization of energy supply dept.
  MARBHALL, J. R. Arkansas Power & Light Co. 83/06/10. COLLINS. J. T. Region 4. Diffice of Director. 3pp. 17674:081. 24X
  Fiche: 50-313,83/06/10,8307220310.
- --8307220314 Rev 6 to "QA Manual Operations." \* Arkansas Power & Light Co. 83766/10. 148pp. 19674:084. 24X Fiche: 50-313, 83/06/10, 8307820310.
- B307110616 Monthly notice of amends to OLs involving NSHC issued since B30323. CLARK,R.A. Operating Reactors Branch 3. B3/06/14. 24pp. 19391: 152. 24x Fiche: 50-000, B3/06/14. B307110616.
- 8307150403 Ack receipt of util 830526 ltr providing addl info to support util 830427 conclusion that eight Category II. B items qualified. Review of info concludes that items environmentally qualified. SER encl. CLARK.R.A. Operating Reactors Branch 3. 83/06/22. GRIFFIN.J.M. Arkansas Power & Light Co. 2pp. 17540:057. 24X Ficha: 50~368.83/06/22.8307150403.
- --8307150405 Safety evaluation concluding that Equipment Items 31,32,97, 98,101,102,104 & 105 environmentally qualified. Items designated Category I.A instead of II.B. No justification for continued operation required.

  # Office of Nuclear Reactor Regulation, Director. 83/06/22, 42pp. 19540:061. 24X Fiche: 50-368,83/06/22,8307150403.
- 8307060051 Responds to 830510 request for final submittals of radiological effluent Tech Specs.offsite dose calculation manual & process control program within 30 days. Response plan to be submitted by 830930 based on ongoing activities. MARSHALL.J.R. Arkansas Power & Light Co. 83/06/29. STOLZ.J.F. Operating Reactors Branch 4. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19250:340. 24X Fiche:50-313.83/06/29.8307060051.
- 8307050072 Application for amend to Licenses DPR-51 & NPF-6, revising Tech Specs to ref ANSI/ASME DM4-1982 guidelines for functional testing, per safety-related hydraulic shock snubber operability requirements.

  ORIFFIN.J.M. Arkansas Power & Light Co. 83/04/30. STDLZ, J.F. Dperating Reactors Branch 4. CLARK.R.A. Operating Reactors Branch 4. 3. 3pp. 19193:159. 24X Fiche:50-313,83/04/30,8307050072.

- --8307050079 Proposed Tech Specs referencing ANSI/ASME DM4-1982 guidelines for functional testing, per safety-related hydraulic shock snubber operability requirements. A Arkansas Power & Light Co. 83/06/30. 22pp. 19193:162. 24X Fiche 50-313.83/06/30.8307050072
- B307260546 Identifies precautionary measures to be taken re-shape annealing matrix (SAM) transposition, inadvertently omitted from B30603 Itr.Procedure mods planned to ensure SAM valves properly calculated.

  MARSHALL, J. R. Arkansas Power & Light Co. 83/06/30. SEIDLE, W. C. Region 4, Defice of Director 1p. 19731:295. 24X Fiche: 50-368, 83/06/30, 8307260346.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIBENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390.317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.Svc list ent. EISENHUT, D.G. Division of Licensing 83/07/06. Consolidates Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.
- 8307120306 Advises that based on review of 830126 & 0415 SERs re environ qualification, submittals do not require proprietary classification & may be made publicly available. MARSHALL J.R. Arkansas Power & Light Co. 83/07/07. 870L7. J.F. Operating Reactors Branch 4. CLARK.R.A. Operating Reactors Branch 3. 1p. 19424:103. 24X Fiche:50-313.83/07/07.8307120306.
- B307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307190098 Application for amend to License NPF-6, proposing Tech Specichanges re instrument in-core detectors Change defines in-core detector string operability withree out of five shodium detectors operable.

  ORIFFIN.J.M. Arkansas Power & Light Co. 83/07/12. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19634:274. 24X Fiche: 50-368.83/07/12.8307190098.
- --8307190101 Proposed Tech Spec changes re instrument in-core detectors \* Arkansas Power & Light Co. 83/07/12, 6pp. 19634:276. 24X Fiche: 50-268,83/07/12,8307190098.
- B307250544 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-51 & NPF-6 & proposed NBHC & opportunity for hearing re hydrogen/oxygen concentration limitations in radwaste gas sys.

  STOL7. J. F. Operating Reactors Branch 4. B3/07/13 CLARK, R. A. Operating Reactors Branch 4. B3/07/13 CLARK, R. A. Fiche: 50-313, 83/07/13, 8307250544.
- 8307250663 Forwards draft safety evaluation concluding that util meets Criteria 1 & 3-9 in Item II.8.3 of NUREC-0737. "Post-Accident Sampling Sqs." Addi info requested within 60 days on Criteria 2.10 & 11 to complete evaluation.

  CLARK.R.A. Operating Reactors Dranch 3. STDLZ.J.F. Operating Reactors Branch 4. 8307714. & GRIFFIN.J.M. Arkansas Power & Light Co. 17pp. 19718:291. 24X Fiche: 50-013.83/07/14.8307250663.
- B307210159 Advises of submittal of Amend 1 to updated FSAR on 830715. Brief description of safety evaluation for design changes made to fecility & completed during 1982 & early 1983 encl. MARSHALL, J. R. Arkansas Power & Light Co. 83707/15. STOLX, J. F. Operating Reactors Branch 4. 11pp. 19669:187. 24X Fiche: 50-313, 83/07/15, 8307210159.
- Q. Inspection reports, IE Builetins & correspondence
- B307120240 Forwards IE Insp Repts 50-313/83-10 & 50-348/83-10 on B30501-31 & notice of violation. SEIDLE, N. C. Region 4, Office of Director. 83/06/15, GRIFFIN, J. M. Ankansas Power & Light Co. 2pp. 19423:001, 24X Fiche:50-313,83/06/15,8307120240.
- ---8307120242 Notice of violation from insp on 830501-31. \* Region 4, Office of Director. 83/06/15. 3pp. 19423; 003. 24X Fiche: 50-313,83/06/15,8307120240.

- ---8307120247 IE Insp Repts 50-313/82-10 \$\nu\$ 50-368/83-10 on 830501-31.

  Noncompliance noted: failure to follow procedures for proper labeling of radwaste & use of inadequate procedure to perform monthly maint.

  CALLAN.L. J. CUMMINS, U.E., UDMNSON, M.D. Region 4, Office of Director. 83/06/14, 19pp. 19423:006. 24X Fiche: 50-313,83/06/15,8307120240.
- 8307140107 Forwards evaluation of util fuel insp results.per 820602 & 830330 submittals. Util responsive & thorough. Routine fuel surveillance recommended on periodic basis. One addl insp necessary to fulfill FSAR commitment.
  CLARK.R.A. Operating Reactors Branch 3. 93/06/24. GRIFFIN.J.M. Arkansas Power & Light Co. App. 19528: 117. 24X
  Fiche: 50-368.83/06/24.8307140107.
- 8307040282 Forwards IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830518-22. No noncompliance noted. SEIDLE.W. C. Region 4. Office of Director. 83/06/29. GRIFFIN, J. M. Arkansas Power & Light Co. Zpp. 19238: 344. 24X Fiche: 50-313, 83/06/29, 8307060282.
- --8307060291 IE Insp Repts 50-313/83-08 & 50-368/83-08 on 830418-22. No noncompliance noted. Major areas inspected: security plan & implementing procedures & security program audit. Safeguards info withheld (10CFR73. 21).

  EVANS-C. A. RELLY-J. A. JOHNSON, W. D. Region 4, Office of Director. 83/06/23. 1p. 19238: 346. 24X Fiche: 50-313,83/06/29,8307060282.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Dagrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Cunsolidated Edison. Co. of New York, Inc. 141pp. 19863:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." See list encl.

  TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307220560 Provides status & overview of waste gas sys upgrades per 821220 commitment in response to SALP rept.Mods include replacing large amount of carbon steel pipe w/stainless steel & rerouting to minimize low spots in sys. MARSHALL,J.R. Artaneas Power & Light Co. 83/07/18. STGLZ,J.F. Gperating Reactors Branch 4. GLARK.R.A. Operating Reactors Branch 3. 2pp. 19486:029. 24X Fiche: 50-313:83/07/18,8307220560.

#### R. Periodic operating reports & related correspondence

- 8307260180 Submits fifth monthly status rept on progress of regulatory response & commitment control program, for 830514-0614.
  Rept on passive commitment tracking expected by 830801.
  MARSHALL, J. R. Arkansas Power & Light Co. 83/06/14. COLLINS, J. T. Region 4. Office of Director. 2pp. 19727:102. 24X
  Fiche: 50-313,83/06/14,8307260180.
- 8307220305 Monthly operating rept for May 1983.W/83DAi5 ltr. BRANLETT.L.S.: MARSHALL, J.R. Arkansas Power & Light Co. 83/06/15 BASSETT.H.S. Division of Data Automation & Management Information. 7pp. 19683:279. 24X Fiche:50-368.83/06/15.8307220305.

### S. Reportable occurrences, LERs & related correspondence

- G307120191 LER G3-025/01T-0: on S30615, discovered that since G30517, BNBR power operating limit penalty not adequate for cold leg resistance temp detector response time. Caused by degradation of Never-Seez couplant W/830628 ltr.
  ROGERS, P. C. MARSHALL, J. R. Arkansas Power & Light Co. 63/06/28.
  SEIDLE: W. C. Region 4, Office of Director. 3pp. 17423: 354. 24x Fiche: 50-368, 83/06/28, 8307120191.

- B307260554 LER 83-026/03L-0: on B30620, deficient fire barrier penetration seals discovered between walls providing access to electrical equipment & cable spreading rooms. Cause not stated. Fire watch posted. Seals repaired. W/B30715 ltr. ROBERS.P.. MARSHALL.J.R. Arkansas Power & Light Co. B3/07/15. SEIDLE.W C. Region 4, Office of Director. 3pp. 19731: 326. 24X Fiche: 50-368, 83/07/15, 8307260554.
- 8307260075 LER 83-027/03L-0: on 830623.2CV-1511-i svc water inlet isolation valve to reactor bidg cooling loop 1 failed to open during surveillance test. Gaused by manual valve closing to prevent leakage which overtightened valve. M/830718 ltr. MADE.P.B. MARSHALL.J.R. Arkansas Power & Light Co. 83/07/18. SEIDLE.W.C. Region 4. Office ab Director. 2pp. 19727: 357. 24X Fiche: 50-368.83/07/18.8307260075.
- 8307260322 LER 83-029/03L-0: on 830703.control element assembly calculator I sensor failure lights came on for assemblies 64 & 72. Caused by failure of high level max card in calculator. Card replaced & calculator returned to svc. W/830718 ltr. ROGERS.P. MARSHALL.J.R. Arkansas Power & Light Co. 83/07/18. SEIDLE.W.C. Region 4. Office of Director. 2pp. 19726:087. 24X Fiche: \$0-368.83/07/18.8307260322.
- DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1
  F. Security, medical, smergency & fire protection plans
- 8307140312 Identifies personnel successfully completing comprehensive training course in generic aspects of radiation protection, emergency response & physical security. NRC personnel 830207 access ltr will be revised.

  MCGUIRE, D. R. Region 2. Office of Director. 83/02/10. TUCKER, H. B. Duke Power Co. ip. 19523: 307. 24X Fiche: 90-369, 83/02/10, 8307140312.
- 8307140257 Ack receipt of 830426 Rev 15 to physical security plan. Changes consistent w/100FR50, 54(p) & acceptable for inclusion in plan.

  LENIG.R.C. Division of Project & Resident Programs. 83/06/17. TUCKER, H. B. Duke Power Co. 2pp. 19523:007. 24X Fiche: 50-369, 83/06/17, 8307140257.
- B307140302 Ack receipt of B30414 & 0531 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-349/83-12 & 50-370/83-16.

  DANCE,H. C. Division of Project & Resident Programs. B3/06/24. TUCKER,H. B. Duke Power Co. Ip. 19521:007. 24X Fiche: 30-369, 83/06/24, 8307140302.
- --B307140305 Submits supplemental response to NRC B30314 ltr reviolations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16. Corrective actions: adequate shielding provided for Class IE equipment subj to water spray.

  TUCKER.H.B. Duke Power Co. B3/05/31. O'REILLY, J.P. Region 2, Office of Director. 2pp. 19521:008. 24X Fiche: 50-369.83/06/24, 8307140302.
- --B30714030B Ack receipt of B30414 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16.

  DANCE-H.C. Division of Project & Resident Programs. 83/05/17.

  TUCKER.H.B. Duke Power Co. 1p. 19521:010. 24X

  Fiche: 50-369.83/06/24.8307140302.
- --8307140310 Responds to NRC 830314 ltr re violations noted in IE Insp Repts 50-346/83-12 & 50-370/83-16. Corrective actions: automatic supervision & fire suppression automatic actuation circuits added. Fire protection review in progress. TUCKER: R B. Duke Power Co. 83/04/14. O'REILLY. J. P. Region 2. Office of Director. 8pp. 19521:011. 24X Fiche: 50-369, 83/06/24, 8307140302.
- 830714004B Forwards fees for amends to Licenses DPR-38, DPR-47, DPR-55 & NPF-9 re location of emergency operating facility & addition of license condition for verifying acceptability of Middel D2 steam generator design mod, respectively. RUTHERFORD.N.A. Duke Power Co. 83/07/08. DIGGS.R.M. License Fee Management Branch. 1p. 19514:227. 24X Fiche:50-000,83/07/08,8307140048.
- B307180076 Provides supplemental info supporting B30506 request for NRC approval of two deviations from NPPA 72D-1975 re local fire alarms. Fire protection review. Section E. 1. (a), Paragraph 2471 will be revised.
  TUCKER, H. B. Duke Power Co. 83/07/12. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. ADENSAM, E. G. Licensing Branch 4. 2pp. 19560: 201. 24X Fiche: 50-369, B3/07/12, B307180076.

- S307250084 Releases public version of revised emergency plan implementing procedures.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19724:140. 24X Fiche: 50-369, 83/07/19, 8307250084.

- ENGO7250101 Releases public version of revised crisis mgt plan for nuclear stations. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19737; 287. 24X Fiche: 50-000, 83/07/19. B307250101.
- B307290717 Releases public version of revised crisis mgt plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. ip. 19719:314. 24X Fiche: 50-000, 83/07/19. B307290717.
- ——8307250730 Forwards public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group.
  TUCKER, H. B. Duke Power Co. 63/05/02. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19719:315. 24X Fiche: 50-000, 83/07/19, 8307280717.
- ➡307270539 Releases public version of rev to emergency plan.
  FELTON.J.M. Division of Rules and Records. 83/07/19. Document
  Management Branch. ip. 19857:086. 24X Fiche: 50-369.83/07/19.
  8307290539.
- p. Operating license stage documents & correspondence
- □□07140218 Clarifies scheduling requirements for integrated leak rate tests (Type A tests), per 830309 request. Tests may be performed at end of current maint outage or during next refueling outage, scheduled for Oct-Dec 1983.

  LEWIS.R.C. Division of Project & Resident Programs. 83/03/16.

  TUCKER.H.B. Duke Power Co. 1p. 19523:166. 24X

  Fiche: 50-369,83/03/16,8307140218.
- D 306060070 Qeneric Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Quidelines." Byc list enci.
  EISENHUT.D.Q. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche:50-000,83/06/03,8306060070.
- P307050377 Ack receipt of 830609 ltr requesting proposed change in Tech Spec Figure 3.2-3 re rated thermal power & total RCS flow. Review of proposed 830609 request inappropriate. Check will be returned.

  ADENSAM: E. G. Licensing Branch 4. 83/06/22. TUCKER, H. B. Duke Power Co. ip. 19263:314. 24X Fiche: 50-369, 83/06/22, 8307050377.

- 8307130104 Forwards Amends 22 & 3 to Licenses NPF-9 & NPF-17, respectively & SER. Amends change Tech Specs to reduce measurement uncertainty for total RCS flow rate. ADENSAM E. G. Licensing Branch 4. 83/06/28. TUCKER H. B. Duke Power Co. 3pp. 19511:140. 24X Fiche: 50-369.83/06/28.8307130104.
- ---8307130112 Amends 22 & 3 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs to reduce measurement uncertainty for total RCS flow rate.

  ADENBAM E. 0. Licensing Branch 4. 83/06/28. 15pp. 19511: 143. 24X Fiche: 50-369, 83/06/28, 8307130104.
- ---B30713011B SER supporting Amends 22 & 3 to Licenses NPF-9 & NPF-17, respectively.

  \* Office of Nuclear Reactor Regulation, Director. 83/06/28, 10pp. 19511:138. 24X Fiche: 50-369.83/06/28,8307130104.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D.G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pg. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT.D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:294, 24X Fiche: 50-000.83/07/06.8307060329.
- 8307140118 Forwards 830609 feerreturned per NRC 830622 ltr concluding that application will not be reviewed.
  DIGOS.R.M. License Fee Management Branch. 83/07/06. TUCKER, H.B. Duke Power Co. ip. 19540:031. 24X Fiche: 50-369.83/07/06, 8307140118.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. 9. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:269. 24X Fiche: 50-000, 83/07/08, 8307080149.
- 8307140048 Forwards fews for amends to Licenses DPR-38.DPR-47.DPR-55 & NPF-9 re location of emergency operating facility & addition of license condition for verifying acceptability of Model D2 steam generator design mod
- 8307260526 Responds to unresolved items in EG Adensam 830610 ltr recontrol of heavy loads. Visual aids will be provided to assist crane operator in ensuring that designated safe load paths followed Listed lifting devices under evaluation. TUCKER.H.B. Duke Power Co. 83/07/15. DENTON.H.R. Defice of Nuclear Reactor Regulation, Director. ADENSAM.E.Q. Licensing Branch 4. 2pp. 19731:289. 24X Fiche: 50-369,83/07/15,8307260526.
- 8307280409 Forwards revised "Reactor Trip," "Unit Fast Recovery," & "Controlling Procedure for Unit Startup," requiring performance group evaluation be completed prior to restart. Addi changes will be provided per Generic Ltr 83-28, TUCKER.H.B. Duke Power Co. 83/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM.E.G. Licensing Branch 4. 1p. 19802:131. 24X Fiche: 50-369, 83/07/22, 8307280409.
- --8307280415 Changes O to 1 to Procedure AP/1/A/5500/01: "Reactor Trip. FIREBAUDH.L., SOMMER.S.J. Duke Power Co. 83/05/12. dpp. 19902: 192. 24X Fiche: 50-369, 83/07/22, 8307280409.
- ---8307280421 Changes O to 13 to Procedure CP/1/A/6100/05, "Unit Fast Recovery," MAYES,R., FIREBAUGH,L. Duke Power Co. 83/05/27, 11pp. 19802:138. 24% Fiche: 50-359,83/07/22,8307280409.
- --8307280427 Change 63 to Procedure OP/I/A/6100/D1, "Controlling Procedure for Unit Startup." MAYES.R. FIREBAUGHLL. HAMILTON.B. Duke Power Co. 83/05/17. Spp. 19802:149. 24X Fiche: 50-369.83/07/22.8307280409.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140336 Informs that liquid samples spiked w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Bamples should be analyzed for tritium, 8r-89 & 8r-90 content within 60 days.

  LEMIS.R.C. Division of Project & Resident Programs, 83/02/07, TUCKER.H. B. Duke Power Co. ip. 19325: 120, 24X Fiche: 50-000, 83/02/07, B307140336.

- 8307140189 Forwards IE Insp Repts 50-369/83-22 & 50-370/83-30 on 830503-06.No noncompliance nated. LENIS, R. C. Division of Project & Resident Programs. 63/06/16. TUCKER, H. B. Dute Power Co. 2pp. 19522:075. 24X Fiche: 50-369, 83/06/16.8307140189.
- --8307140195 IE Insp Repts 50-369/83-22 & 50-370/83-30 on 830503-06. No noncompliance noted. Major areas inspected: Licensed & nonlicensed operator training & requalification programs & on-shift/real-time training.

  BURGER.C., SCHNEIDER.G., SKINNER.P. Region 2. Office of Director. 83/06/16. 9pp. 19522:077. 24X Fiche: 50-369, 83/06/16, 8307140189.
- 8307140302 Ack receipt of 830414 & 0531 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16.

  DANCE.H.C. Division of Project & Resident Programs. 83/06/24. TUGKER.H.B. Duke Power Co. 1p. 19521:007. 24X Fiche: 50-369.83/06/24.8307140302.
- --9307140305 Submits supplemental response to NRC 830314 ltr reviolations noted in IE Insp Repts 50-369/83-12 & 50-370/83-14. Corrective actions: adequate shtelding provided for Class IE equipment subj to water spray.

  \*\*TUCKER.M.B.\*\* Buke Power Co. 83/05/31. D'REILLY, J.P. Region 2, 0ffice of Director. 2pp. 19521:008. 24X Fiche: 50-369, 83/06/24, 8307140302.
- --8307140308 Ack receipt of 830414 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16. Division of Project & Resident Programs. 83/05/17. TUCKER.H.B. Duke Power Co. ip. 19521:010. 24X Fiche:50-369,83/06/24,8307140302.
- --8307140310 Responds to NRC 830314 ltr re violations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16. Corrective actions: automatic supervision & fire suppression automatic actuation circuits added. Fire protection review in progress. TUCKER. H.B. Duke Power Co. 83/04/14. GREILLY. J. P. Region 2, Office of Director. 8pp. 19521:011. 24% Fiche: 50-369,83/06/24, 8307140302.
- --8304200521 Forwards IE Insp Repts 50-369/83-12 & 50-370/83-16 on 830214-18 & notice of deviation.

  DANCE, H. C. Division of Froject & Resident Programs. 83/03/14. TUCKER, H. B. Duke Power Co. 2pp. 19321:019. 24X Fiche: 50-369, 83/06/24, 8307140302.
- --8304200525 Notice of deviation from insp on 830214-18.

  \* Regian 2: Office of Director. 83/03/14. 2pp. 19521:021. 24x
  Fiche: 50-369.83/06/24.8307140302.
- --8304200527 IE Insp Repts 50-349/83-12 & 50-370/83-16 on 830214-18.
  Noncompliance noted: substandard automatic sprintler sys for reactor blidg annulus & failure to insp & test fire detection & actuation sys for diesel generator.
  MILLER, W.H., CONLON, T.E. Region 2, Office of Director. 83/03/09.
  lipp. 19521:023. 24X Fiche: 50-349, 83/06/24, 8307140302.
- 8307220431 Forwards IE Insp Repts 50-369/83-24 & 50-370/83-31 on 830420-0520. No noncompliance noted. DANCE-M.C. Division of Project & Resident Programs. B3/06/30. TUCKER. M. B. Dute Power Co. 2pp. 19686: 121. 24X Fichs: 50-369. 83/06/30. 8307220431.
- --8307220441 IE Insp Repts 50-369/83-24 & 50-370/83-31 on 830630.No noncompliance noted.Major areas inspected:operations, surveillance testing, maint activities & followup of unresolved (tems.

  ORDERS,W., BROHNLEE,V.L. Division of Project & Resident Programs, 83/06/30. 5pp. 19686:123. 24X Fiche:50-369.83/06/30.8307220431.
- 8305270401 IE Info Notice B3-45, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, inc. 134pp. 19363: 293. 24X Fiche: 30-000,83/07/11,8306270401.
- 9306270404 IE Info Notice B3-47, "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, B3/07/12, B306270404.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Piche: 50-000, B3/07/14, B306270406.

- R. Periodic operating reports & related correspondence
- B307190184 Forwards monthly operating repts for June 1983, including revised unit shotdowns & power reduction sheets for Unit 1 for Feb 1982.

  TUCKER, M. B. Duke Power Co. 83/07/15. Director's Office, Office of Inspection and Enforcement. Ip. 19641:308. 24X

  Fiche: 50-369, 83/07/15, 8307190184.
- --8307190188 Monthly operating repts for June 1983. REAVIS.J. A. Duke Power Co. 83/07/15. 9pp. 19641:309. 24X Fichs:50-369,83/07/15.8307190[84.
- --8307190309 Revised unit shutdowns & power reductions for monthly operating rept for Feb 1982. REAVIS.J.A. Duke Power Co. 82/06/13. 3pp. 17641:318. 24X Fiche:50-349,83/07/15,8307190184.
- S. Reportable occurrences, LERs & related correspondence
- B307120115 LER B3-030/01T-0: on B30926, discovered monthly test of containment pressure control sys failed to satisfy surveillance requirements to check permissive/termination setpoint accuracy. Alarm modules recalibr. W/B30627 ltr. NARDOCI.P.B., TUCKER.H.B., Duke Power Co., B3/06/27. O'REILLY, J.P. Region 2, Office of Director., Spp. 19423:057. 24X Fiche: 50-369.83/06/27,8307120115.
- 8307120583 LER 83-035/03L-0:on 830515, pressurizer heater group 18 failed to energize in manual & declared inoperable per Tech Spec 3.4.3. Caused by blown fose in heater contactor control circuit. Five replaced. M/830628 ltr.
  NARDDCI.F.B., TUCKER.H.B. Duke Pawer Co. 83/06/28, 0/REILLY, J.P. Region 2, Office of Director. 2pp. 19432:153. 24X fiche: 50-369,83/06/28,8307120383.
- 8307120897 Updated LER 83-002/03X-1: on 830f10, pressurizer heater group iB failed to energize in manual & declared inoperable. Heat damage found at heat dissipating resistor connections. Caused by design defect in contactor coil circuit. W/830628 ltr. NAR8DCI.P.B., TUCKER.H.B. Duke Power Co. 83/06/28. 0'REILLY, J. P. Region 2, Dffice of Director. 2pp. 19433: 077. 24X Fiche: 50-369.83/06/28.8307120897.
- B307150212 LER B3-039/03L-0: on B30606, control room ventilation systmain A failed control room pressurization test performed in response to control room door mod. Caused by out-of-position manual damper. W/B30706 ltr.

  NARDOCI.P.B., TUCKER.H.B. Duke Power Co. B3/07/06. O'REILLY, J.P. Region 2. Office of Director. 2pp. 19530:267. 24X
  Fiche: 50-369, B3/07/06, B307150212.
- 8307150234 LER 83-038/03L-0:on 830527, narrow-range levels of steam generators not verified within 4% of average value. On 830605, ice condenser monitoring sys & applicable instrument items missed. Caused by personnel error. 4/830706 ltr. NARDOCI.P.B., TUCKER.H.B. Duke Power Co. 83/07/06. D'REILLY, J. P. Region 2, Office of Director. 2pp. 19530: 210. 24X Fichs: 50-369, 83/07/06, 8307150234.
- 8307150253 LER 83-037/03L-0: on 830602, main steam code safety relief valve ISV-9 lifted. w/main steam pressure below acceptable lift setpoint range, during reactor of the transient. Caused by setpoint drift, probably due to vibration. W/830706 ltr. NARDDCI.P.D. TUCKER.H.B. Duke Power Co. 83/07/06. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19538: 250. 24x Fiche: 50-369, 83/07/06, 8307150253.
- 8307150108 LER 83-041/03L-0: on 830607, containment hydrogen monitor A hydrogen analyser gas flow found out-of-spec. Caused by partially blocked flow path. Monthly test performed again on 830610 & monitor declared operable. W/830707 ltr.
  NARDOCI.P.B., TUCKER.H.B. Duke Power Co. 83/07/07. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19536: 211. 24X
  Fiche: 50-369, 83/07/07. 8307150108.
- 8307180340 LER 83-040/03L-0: on 830604,06 & 28. Fire Detection Zones EFA 76.150 & 103 declared inoperable due to invalid alarms. Caused by spurious alarms & high dust concentration. Smake & fire ionization detectors replaced W/830707 ltr. NARDOCLP.B., TUCKER.H.B. Duke Power Co. 83/07/07. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 17538: 277. 24X Fiche: 50-367,83/07/07.8307130340.
- 8307220409 LER 63-042/03L-0: on 830609, diesel generator 18 declared inoperable when two unsuccessful attempts made to load generator. Caused by inaccurate timing. Test procedure revised to allow for 3 minute wait. W/800708 ltr. NARDOCI.P.B. Duke Power Co. 83/07/08. O'REILLY, J.P. Region 2, Office of Director. 2pp. 19691: 173. 24X Fiche: 50-369, 83/07/08, 8307220409.

- G307260558 Forwards LER 83-043/017-0 b 83-029/017-0. TUCKER.H.B. Duke Pawer Co. 83/07/14. O'REILLY, J.P. Region 2. Office of Director. 3pp. 19732: 334. 24X Fiche: 50-369, 83/07/14, 8307260558.
- --8307260567 LER 63-043/01T-0. on 830601. Westinghouse notified util that artended operation at lower power & subsequent escalation to power in same fuel cycle would result in heat flux hot channel factor limit violations to LOCA analysis.

  NARDOCI.P.B. Duke Power Co. 83/07/14. Region 2, Office of Director. 1p. 19732:338. 24X Fiche:50-369.83/07/14.8307260558.
- --B307260569 LER 83-029/01T-0: on B30601. Westinghouse notified util that extended operation at low power & subsequent escalation to power in same fuel cycle would result in heat flux hot channel factor limit violations for LOCA analysis.

  NARDOCI.P. B. Duke Power Co. 83/07/14. Region 2, Office of Director. 1p. 19732:339. 24X Fiche: 50-369.83/07/14.8307260558.
- 8307250202 LER 83-044/03L-0: on 830617, containment atmosphere gaseous radioactivity monitor EMF-39L declared inoperable while in Mode 1. Caused by failure of monitor to meet acceptance criteria due to lower detector voltage reading W/830715 ltr. NARDOCI.P. B., TUCKER.H. B. Duke Power Co. 83/07/15. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19705: 343. 24X Fiche: 50-369, 83/07/15, 8307250202.
- 8307260462 RD 369/83-46: on 830617, two independent control area ventilation sys inoperable, violating Tech Spec 3.7.6. Rept will be submitted by 830729.
  TUCKER, H. B. Duke Power Co. 83/07/15. D'REILLY, J. P. Region 2. D
- B307260535 LER B3-045/03L-0: on B30616, centrifugal charging pump 18 stopped due to high temp on motor inboard bearing. Caused by excess oil removed from bearing reservoir for sample analysis. Bearing, rotor & endbell replaced. W/B30715 ltr. NARDDCI.P. B., TUCKER.H. B. Duke Power Co. B3/07/15. O'REILLY, J. P. Region D. Dffice of Director. 2pp. 19731: 354. 24% Fiche: 50-369,83/07/15,8307260535.
- B307260495 Presents plan for satisfying intent of Part 21 in order to continue procurement of equipment from Nelson Electric Div of General Signal Co.in view of Nelson Electric refusal to accept purchase orders involving Part 21 requirements.

  TUCKER.H.B. Duke Power Co. 83/07/20 DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19739:350. 24X

  Fiche: 90-000.83/07/20.8307260495.
- DOCKET 50-370 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2

  A. Application/construction stage decuments % correspondence
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillence intervals in STS. Svc list encl. EIBENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- F. Security, medical, emergency & fire protection plans
- 8307140312 Identifies personnel successfully completing comprehensive training course in generic aspects of radiation protection, amergency response & physical security NRC personnel 830207 access thr will be revised.

  MCGUIRE, D. R. Region 2, Defice of Director. 83/02/10, TUCKER, H. B. Duke Power Co. 1p. 19323:307. 24x Fiche: 50-369, 83/02/10, 8307140312.
- 8307140257 Ack receipt of B30426 Rev 15 to physical security plan. Changes consistent w/10CFR50.54(p) & acceptable for inclusion in plan. LEWIS.R.C. Division of Project & Resident Programs. B3/06/17. TUCKER,H.B. Duke Power Co. 2pp. 19523:007. 24X Fiche: \$0-369, 83/06/17, 8307140257.
- 8307140302 Ack receipt of 830414 & 0531 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16.
  DANCE.H.C. Division of Project & Resident Programs. 83/06/24. TUCKER.H.B. Duke Power Co. 1p. 1952:007. 24X Fiche: 50-369, 83/06/24. 8307140302.
- --8307140305 Submits supplemental response to NRC 830314 ltr reviolations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16. Corrective actions: adequate shielding provided for Class IE equipment subj to water spray.
  TUCKER, H. B. Duke Power Co. 83/05/31. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19521:008. 24X Fiche: 50-369, 83/06/24, 8307140302.

- --8307140306 Ack receipt of 830414 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-369/83-12 & 50-370/83-16 DANCE.H C. Division of Project & Resident Programs. 83/05/17. TUCKER.H B. Duke Power Co. 1p. 19521:010 24X Fiche.50-369.83/06/24.8307140302
- --B307140310 Responds to NRC 830314 lith he violations noted in IE Insp. Repts 50-349/83-12 & 50-370/83-16. Corrective actions, automatic supervision & fire suppression automatic actuation circuits added Fire protection review in progress TUCKEP, H.B. Duke Power Co. 83/04/14. O'REILLY, J.P. Region 2. Office of Director. Opp. 19521-011 24X Fiche 50-369,93/06/24, 8307140302
- 8307180075 Provides supplemental info supporting 830506 request for NRC approval of two deviations from NFPA 72D-1975 re local fire alarms Fire protection review. Section E 1.(a), Paragraph 2471 will be revised.

  TUCKER, H B. Duke Power Co. 83/07/12. DENTON, H R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4 2pp. 19560:201. 24X Fiche:50-369,83/07/12,8307180076.
- 8307250084 Releases public version of revised emergency plan implementing procedures FELTON,J M. Division of Rules and Records 83/07/19. Document Management Branch. 1p. 19724.140. 24X Fiche: 50-369.83/07/19, 8307250084.
- --B3072500B7 Forwards public version of revised emergency plan implementing procedures, including Procedure HP/1/B/1009/15 re Unit i nuclear post-accident containment air sampling sys & Station Directive 3.8.2 re emergency organization. TUCXER.H.B. Duke Power Co. 83/05/17 DENTON.H.R. Office of Nuclear Reactor Regulation. Director. ABENSAM.E.G. Licensing Branch 4. Jpp. 19724:141. 24X Fiche: 50-369,83/07/19,8307250084.
- --8307250092 Public version of revised emergency plan implementing procedures, including Procedure HP/1/8/1009/15 re Unit 1 nuclear post-accident containment air sampling sys & Station Directive 3.8.2 re emergency organization.

  MCCONNELL, T., JOHNSON, M. K. Duke Power Co. 83/05/30. 81pp. 19724 144. 24X Fiche 50-369.83/07/19.8307250084.
- B307250101 Releases public version of revised crisis mgt plan for nuclear stations. FELTON,J.M. Division of Rules and Records 83/07/19. Document Management Branch. 1p. 19737:287 24X Fiche:50-000,83/07/19. 8307250101.
- --B307250110 Public version of Rev 9 to crisis mgt plan for nuclear stations. M/830630 ltr. VAUGHN. T.S. Duke Power Co. 83/06/15 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 127pp. 19737: 288. 24X Fiche. 50-000, 83/07/19, 8307250101
- 8307250717 Releases public version of revised crisis mgt plan implementing procedures FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19719:314. 24% fiche:50-000.83/07/19. 8307250717
- --8307250730 Forwards public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. TUCKER.H.B. Duke Power Co. 83/05/02. DENTON.H.R. Office of Nuclear Reactor Regulation, Director 2pp. 19719.315. 24X Ficha: 50-000.83/07/19.8307250717
- ---8307256744 Public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. \* Buke Power Co. 83/03/16 186pp 19719-317. 24X Fiche: 50-000.03/07/19.8307850717.
- 8307290937 Releases public version of rev to emergency plan. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Dranch. 1p. 19857:086. 24% Fiche.50-369,83/07/19, 8307290539.
- --8307290544 Public version of Rev 11 to smergency plan. 4/830630 ltr. MCINTOSH.M.D. Duke Power Co. 83/06/30. DENTON.H.R. Office of Nucleal Reactor Regulation. Director. ADENSAM.E.G. Licensing Branch 4. 67pp. 19857-087. 24X Fiche: 50-369.83/07/19.8307290539.

- P Operating license stage documents & correspondence
- 8307140224 Confirms that requirements constraining initial criticality completed & util may proceed to initial criticality per license conditions.

  3/RFILLYLY P. Region 2, Office of Director. 83/05/02. TUCKER, H. B. Duke Power Co. 1p. 19523:151. 24X Fiche: 50-370, 83/05/02, 8307140224.
- 8304040070 Generic Ltr B3-22 to all operating reactor licenses, applicants for OLS & holders of CPs for Westinghouse PHRs re safety evaluation of "Emergency Response Outdelines." Svc list onc!
  EISENHUT, D. G. Division of Licensing. B3/06/03. Yankea Atomic B306060070.
- 8307050377 Ack receipt of 830609 ltr requesting proposed change in Yech Spec Figure 3.2-3 re rated thermal power & total RCS flow Review of proposed 830609 request inappropriate.

  Check will be returned.

  ADENSAM.E. G. Licensing Branch 4. 83/06/22. TUCKER.H.B. Duke Power Co. 1p 19263:314. 24X Fiche: 50-369.83/06/22,8307050377.
- 8307130104 Forwards Amends 22 & 3 to Licenses NPF-9 & NPF-17, respectively & SER. Amends change Tech Specs to reduce measurement uncertainty for total RCS flow rate.
  ADENSAM, E. G. Licensing Branch 4. 83/06/28, TUCKER, H. B. Duke Power Co. 3pp 19511:140. 24X Fiche: 50-369, 83/06/28, 8307130104.
- --8307130112 Amends 22 & 3 to Licenses NFF-9 & NPF-17, respectively, changing Fech Specs to reduce measurement uncertainty for total RCS flow rate.

  ADENSAM.E.G. Licensing Branch 4. 83/06/28. 15pp. 17511:143. 24% Fische 50-369.83/06/28.8307130104.
- --8307130118 SER supporting Amends 22 % 3 to Licenses NPF-9 % NPF-17, respectively.

  \* Office of Nuclear Reactor Regulation, Director. 83/06/28, 10pp. 19511:158. 24X Fiche:50-369.83/06/28,8307130104.
- 8306270377 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. 9. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000, 83/07/05, 8306270397.
- 530714011B Forwards \$30609 fee returned per NRC 630622 ltr concluding that application will not be reviewed.
  DIGOS,R.M. License Fee Management Branch. 63/07/06. TUCKER,H.B. 630714011B.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT, D G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X
- 8307220636 Summary of 830608 appeal meeting w/utils & Bechtel restandby shutdown sys monitors for source range flux & steam generator pressure Viewgraphs encl.
  BIRKEL.R.A. Licensing Branch 4. 83/07/15. Licensing Branch 4. 32pp. 17697:045. 24X Fiche: 50-000, 83/07/15, 8307220636.
- 8307240526 Responds to unresolved items in EQ Adensam 830410 ltr recontrol of heavy loads. Visual aids will be provided to assist crane operator in ensuring that designated safe load paths followed. Listed lifting devices under evaluation. TUCKER.H. B. Duke Power Co. 83/07/15. DENTON.H.R. Defice of Nuclear Reactor Regulation. Director. ADENSAM.E.O. Licensing Branch 2. 2pp 19731: 289. 24X Fiche: 50-369, 83/07/15, 8307260526.
- 8307280409 Forwards revised "Reactor Trip," "Unit Fest Recovery," & "Controlling Procedure for Unit Startup," requiring performance group evaluation be completed prior to restart. Addi changes will be provided, per Generic Ltr 83-28.

  TUCKER.M. B. Duke Power Co. 83/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM.E. G. Licensing Branch 4. 1p. 19802.131. 24% Fithe: 50-369,83/07/22.8307280409.
- -9307280415 Changes O to 1 to Procedure AP/1/A/5500/01, "Reactor Trip." FIREBAUGH, L. , SOMMER, S. J. Duke Power Co. 83/05/12. App. 19802: 132. 24% Fiche: 50-369, 83/07/22, 8307280409.
- -2307280421 Changes 0 to 13 to Procedure OP/1/A/6100/05, "Unit Fast Recovery." MAYES.R., FIREBAUGH.L. Duke Power Co. 83/05/27, 11pp. 19802 138 24X Ficho: 50-369, 83/07/22, 8307280409.

- --8307280429 Change 63 to Procedure QP/1/A/6100/01, "Controlling Procedure for Unit Startup." MAYES.R., FIREBAUGH.L., HAMILTON,B. Duke Power Co. 83/05/19. Spp. 17802:149, 24X Fiche:50-369,83/07/22,8307280409.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140336 informs that liquid samples spiked w/radionuclides will be sent to facilities for radiochemical analyses as part of NRC confirmatory measurements program. Samples should be analyzed for tritium, Sr.-99 & Sr-90 content within 60 days.

  LEWIS.R.C. Division of Project & Resident Programs. 83/02/07. TUCKER, H. B. Duke Power Co. 1p. 19525: 120. 24X Fiche: 50-000, 83/02/07, 8307140336.
- 8307140189 Forwards IE Insp Repts 50-369/83-22 & 50-370/83-30 on 830503-06. No nancompliance noted.

  LEWIS.R.C. Division of Project & Resident Programs. 83/06/16. TUCKER, H. D. Duke Power Co. 2pp. 19522:075. 24X Fiche: 50-369, 83/06/16. 8307140189.
- --8307140195 IE Imsp Repts 50-369/B3-22 & 50-370/B3-30 on B30503-06. No noncompliance noted Major areas inspected: licensed & nonlicensed operator training & requalification programs & on-shift/real-time training.
  BURGER. C. . SCHNEIDER, G. , SKINNER, P. Region 2, Office of Director. B3/06/16. 7pp. 19322:077. 24X Fiche: 50-369, 83/06/16, 8307140189.
- 8307140302 Ack receipt of 830414 & 0531 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16. DANCE.H.C. Division of Project & Resident Programs. B3/06/24. TUCKER.H.B. Duke Power Co. 1p. 19521:007. 24X Fichs: 50-369.83/06/24.8307140302.
- ~-8307140305 Submits supplemental response to NRC 830314 ltr reviolations noted in IE Insp Repts 50-369/83-12 & 50-370/83-16. Corrective actions: adequate shielding provided for Class IE equipment subj to mater spray.

  TUCKER, H. B. Duke Power Co. 83/05/31. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19521:008. 24X Fiche: 50-369, 83/06/24, 8307140302.
- --B307140308 Ack receipt of 830414 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-12 & DANCE, H. C. Division of Project & Resident Programs. B3/05/17. TUCKER, H. B. Duke Power Co. ip. 19521:010. 24X Fiche: 50-369, 83/06/24, B307140302.
- ---8307140310 Responds to NRC 830314 ltr re violations noted in IE Insp. Repts 50-369/83-12 & 50-370/83-16. Corrective actions: automatic supervision & fire suppression automatic actuation circuits added. Fire protection review in progress.
  TUCKER.H.B. Duke Power Co. 83/04/14. 0'REILLY.J.P. Region 2, Office of Director. 8pp. 19521:011. 24X Fiche:50-369,83/06/24,
- --8304200321 Forwards IE Insp Repts 50-369/83-12 & 50-370/83-16 on B30214-18 & notice of deviation.
  DANCE, H. C. Division of Project & Resident Programs, 83/03/14, TUCKER, H. B. Duke Power Co. 2pp. 19521:019, 24X Fiche:50-349,83/04/24,8307140302.
- --8304200525 Notice of deviation from insp on 830214-18, \* Region 2, Office of Director. 83/03/14, 2pp. 19521:021, 24x Fiche: 50-369, 83/04/24, 8307140302.
- --8304200527 IE Insp Repts 50-369/83-12 & 50-370/83-16 on 830214-18. Noncompliance noted: substandard automatic sprinkler sys for reactor bldg annulus & failure to insp & test fire detection & actuation sys for diesel generator. MILLER, M. H. . COMLON, T. E. Region 2, Office of Director, 83/03/09, 11pp. 19521:023, 24X Fiche: 50-369, 83/06/24, 8307140302.
- B30722043! Forwards IE Insp Repts 50-369/83-24 & 50-370/83-31 on B30420-0520. No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. B3/06/30. TUCKER.H.B. Duke Power Co. 2pp. 19686:121. 24X Fiche: 50-369. B3/06/30. B307220431.
- --8307220441 IE Insp Repts 50-369/83-24 & 50-370/83-31 on 830630. No noncompliance noted Major areas inspected: operations, surveillance testing, maint activities & followup of unresolved items.

  ORDERS, W. BROWNLEE, V. L. Division of Project & Resident Programs. 83/06/30. 5pp. 19686; 123. 24% Fiche: 50-369, 83/06/30, 8307220431.

- 8306270401 IE Info Notice 83~46. "Common Mode Va)ve Fai)ures Degrade Surry Recirculation Spray Subsystem." Svc list enci. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11,8306270401.
- 8306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche:50-000.B3/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- R. Periodic operating reports & related correspondence
- 8307190184 Forwards monthly operating repts for June 1983, including revised unit shutdowns & power reduction sheets for Unit 1 for Feb 1982.
  TUCKER.H.B. Duke Power Co. 83/07/15. Director's Office of Inspection and Enforcement. 1p. 19641:308. 24X Fiche: 50-369, 83/07/15, 8307190184.
- --8307190188 Monthly operating repts for June 1983. REAVIS.J.A. Duke Power Co. 83/07/15. 9pp. 19641:309. 24X Fiche:50-369, 83/07/15.8307190184.
- S. Reportable occurrences, LERs & related correspondence
- 8307120200 LER 83-019/017-0: on B30526, containment pressure control sysmonthly test failed to satisfy surveillance requirements to check permissive/termination setpoint accuracy. Caused by out-of-tolerance instruments, Modules recalibr. W/B30627 ltr. NARDSCI.P.B., TUCKER.H.B. Duke Power Co. B3/06/27, D'REILLY, J. P. Region 2. Office of Director. 6pp. 19423:307. 24X Fiche: 50-370, B3/06/27, B307120200.
- B307150259 LER B3-024/03L-0: on B30526-0610. Fire Detection Zones EFA 179, 189, 182, 81, 102, 174 & 163 declared inoperable due to invalid alarms. Caused by dirt accumulation in Firemerk 9620 smoke detectors, W/B30706 ltr.
  NARDOCI.P. B., TUCKER.H. B. Duke Power Co. B3/07/06. O'REILLY, J. P. Region 2, Office of Director. 4pp. 19537: 359. 24X Fiche: 50-370, B3/07/06, B307150259.
- 8307150305 LER 83-025/03L-0: on 830605 digital rod position indication for control bank C rod F-6 declared inoperable due to ambiguous indication that rod was at both 228 & 204 steps from core bottom. Caused by failed display card. WF30707 ltr. NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/07/07, O'REILLY, J. P. Repion 2. Office of Director. 2pp. 19532: 309. 24X Fiche: 50-370, 83/07/07, 8307150305.
- 8307220221 LER 83-026/03L-0: on 830608, while in Mode 1, reactor coolant leakage calculation revealed excessive unidentified RCS leakage. Caused by valve 2MM-68 lifting at less than intended satpoint. Valve will be replaced. M/830707 ltm.
  NARDUCI.P.B., TUCKER, H.B. Dute Power Co. 83/07/07. O'RETLLY, J.P. Region 2. Office of Director. 4pp. 19674:001. 24X Fiche: 50-370, 83/07/07, 8307220221.
- B307220257 LER B3-028/03L-0:on B3060B; pressurizer heater group 2B declared inoperable when supply breaker found tripped open. Caused by damaged closed indicator lamp socket. Socket replaced. W/B3070B ltr NARDOCI.P.B., TUCKER, H.B. Duke Power Co. B3/07/0B. O'REILLY, J.B. Region 2. Office of Director. 2pp. 17684:228. 24X Fiche: 50-370,83/07/08,8307220257.
- 8307220499 Advises that RO-370/83-27 re violation of Tech Spec 3.6.3 concerning isolation times on 830609 will be submitted by 830722. Delay due to incomplete investigation & rept preparation.

  TUCKER.H.B. Duke Power Co. 83/07/08. O'REILLY, J.P. Region 2, Office of Director. Ip. 19685:225. 24X Fiche: 50-370,83/07/08, 8307220499.
- 8307240558 Forwards LER 83-043/01T-0 % 83-029/01T-0. TUCKER.H.B. Duke Power Co. 83/07/14. D'REILLY.J.P. Region 2. Office of Director. 3pp. 19732:334. 24x Fiche:50-369.83/07/14. 8307240558.

- --8307260569 LER 83-029/01T-0: on B30601, Westinghouse notified util that extended operation at low power & subsequent escalation to power in same fuel cycle would result in heat flux hot channel factor limit violations for LOCA analysis.

  NARDOCI.P.B. Duke Power Co. 83/07/14. Region 2. Diffice of Director. 1p. 19732:339. 24X Fiche: 50-369, 83/07/14, 8307260558.
- 8307260384 LER 83-027/03L-0: on 830609, following maint to actuator, valve 2CF-35 (S/O 2A feedwater containment isolation) exceeded stroke time of less than 5 s. Caused by solenoid failure of valve 2CF35. Solenoid replaced W/B3071B ltr.
  NARBOCT.P.B., TUCKER,H.B. Duke Power Co. 83/07/18. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19733:162. 24X Fiche: 50-370,83/07/18,8307260384.
- 8307260370 LER 83-030/03L-0: on 830618 & 20.ftre detection Zones EFA 100 & 170 declared inoperable due to invalid alarms. Caused by dirt accumulation in two Firemark 9620 ionization-type fire detectors. Detectors cleaned & returned to svc.W/830718 ltr. NARDOCI.P.B., TUCKER, H.B. Duke Power Co. 83/07/18. D'REILLY, J.P. Region 2, Office of Director. 2pp. 19733:164. 24X Fiche: 50-370,83/07/18.8307260370.
- B307260495 Presents plan for satisfying intent of Part 21 in order to continue procurement of equipment from Nelson Electric Div of General Signal Co. in view of Nelson Electric refusal to accept purchase orders involving Part 21 requirements.

  TUCKER. H. B. Duke Power Co. 83/07/20. DENTON. H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19733:350. 24X Fiche: 50-000. 83/07/20, 8307260495.
- DOCKET 90-373 LASALLE COUNTY STATION, UNIT (
  A. Application/construction stage documents & correspondence
- 8307120382 Forwards revised responses to NRC Questions 031.290 & 292 re-potential multiple control sys failures due to high energy line break events.per 830621 discussion. SCHROEDER.C. W. Commonwealth Edison Co. 83/07/04. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 9pp. 17429:030. 24X Fiche: 50-373.83/07/06.8307120382.
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8307260314 Forwards marked-up revised FSAR Table 14.2-123,per 830706 telcon & SER Section 14.deleting ref to measurement of relief valve capacity. Changes will be incorporated into FSAR Anend 64.

  BCHRUEDER.C. W. Commonwealth Edison Co. 83/07/21. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 5gp. 19726:297. 24X Fiche: 50-373,83/07/21.8307260314.
- F. Security, medical, emergency & fire protection plans
- 8307110411 Ack receipt of B30610 & 24 ltrs informing NRC of steps taken to correct violations noted in IE Inep Repts 50-373/92-54 & 30-374/82-22.

  BPESSARD,R.L. Division of Engineering. 83/07/06. REED.C. Commonwealth Edison Co. ip. 19382:021. 24X Fiche:50-373,83/07/06.8307110411.
- --8307110419 Responds to NRC 830428 ltr re violations noted in IE lnsp Repts 50-373/82-54 & 50-374/82-22. Corrective actions: response re fire endurance capability of US Gypsum cement firestops will be submitted by 830805.

  FARRARID.L. Commonwealth Edison Co. 83/06/10. KEPPLER, J. G. Region 3. Office of Director. 2pp. 19382:022. 24X Fiche: 50-373, 83/07/06, 8307110411.
- --8307110434 Responds to NRC B30428 ltr re violations noted in IE Insp Repts 50-373/82-34 & 50-374/82-22. Corrective actions: fire seal acceptable if seal contains no cracks, voids or separations greater than 3/8-inch wide. FARRAR, D. L. Commonwealth Edison Co. B3/06/24. KEPPLER, J. Q. Region 3, Office of Director. 202pp. 19382: 024. 24X Fiche: 50-373, 83/07/06, 8307110411.

- 8307120434 Forwards IE Safeguards Insp Rept 50-373/83-22 on 830523-25, 27 & 0601-03 No noncompliance noted. MILLER, J. R. Region 3, Office of Director. 83/07/07, REED, C. Commonwealth Edison Co. 2pp 19425:244 24x Fiche: 50-373,83/07/07, 8307120434.
- --8307120439 IE Safeguards Insp Rept 50-373/83-22 on 830523-25,27 & 0601-03.Ne noncompliance noted Major areas inspected security plan 5 implementing procedures & security organization.
  Safeguards info deleted tref 100FR73\_215.
  BELANDER.J.L.: MADEDA.T.J.: CHRISTOFFER.G. Region 3: Office of 0307120434.
- B307190410 Responds to B30615 request for acceptance of fire door test program Program acceptable. Acceptance of doors awaits review of rept on test results expected by B40401.

  SCHWENCER, A. Licansing Branch 2. B3/07/08. FARRAR, D. L. Commonwealth Edison Co. 2pp 19656:078. 24X Fiche: 50-373, 83/07/08, B307190410.
- 8307180062 Ack receipt of B30706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & SPESSARD, R.L. Division of Engineering. 83/07/11. REED.C. Commonwealth Edison Co. 1p. 19560:328. 24x Fiche:50-373.83/07/11, 8307180062.
- ---B307180063 Responds to NRC 830610 ltr re violations noted in IE Insp. Repts 50-373/82-54 & 50-374/82-22. Corrective actions: cable pan cleanliness surveillance frequency increased. FARRAR, D. L. Commonwealth Editson Co. B3/07/06. MEPPLER, J. G. Region 3, Office of Director. App. 19560: 327. 24x
  Fiche: 50-373, 83/07/11, 8307180062
- --8307180064 "Concrete Floor Fire-Stop Test of Nonqualified IEEE 383 Cable Penetrations Protected W/Firecode CT Gypsum & Thermafiber CT Felt." QUIGG,P.S., QRALS,D.L. US Gypsum Co. 80/03/14, 38pp. 19560:335. 24X Fiche:50-373,83/07/11,8307180062.
- --8307180065 "Fire-Stop Sys W/o Cable in 3 H Fire-Rated Wall." GUIGG.P S.: ORALS.D.L. US Gypsum Co. 79/09/06. 6pp. 19961:011. 24X Fiche: 50-373:83/07/11:8307180062.
- ---8307180066 "Firecode CT Gypsum Thermafiber Access Firestopping for Walls."

  GUIGG, P. S. ORALS, D. L. US Gypsum Co. 78/07/24, 17pp. 19561: 017. 24X Fiche: 50-373, 83/07/11, 8307180062.
- --8307180067 Transco Fire Test Rept TR-109, "Fire Hose Stream Tests of TCO-001 Cement,"

  JAROSZ.G.J. Transco, Inc. TR-109, 83/04/07, 86pp. 19541:034.
  24X Fiche: 50-373,83/07/11,8307180062.
- 8307280323 Forwards IE Insp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16. No noncomptionce noted. PAPERIELLO.C.J. Division of Emergency Preparedness & Operational Support 83/07/15. REED.C. Commonwealth Edison Co. 2pp. 19790:218 24x Fiche: 50-373,83/07/15,8307280323.
- --8307280329 IE lnsp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16 No noncompliance noted Major areas inspected state of emergency preparedness. Generic problem exists re inadequate documentation of emergency plan activities. PLOSKI, T., GLOERSEN, W., AXELSON, N.L. Region 3, Office of Director. 83/07/15, 9pp. 19790: 220. 24X Fiche: 50-373,83/07/15,8307280323.
- 8307250434 Ack receipt of 8307(1 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-12 & 50-374/83-10.

  SHAFER W D Region 3. Office of Director. 83/07/19. REED.C. Commonwealth Edison Co. 1p. 19701:182. 24X Fiche:50-373/83/07/19, 8307250434.
- -8307250435 Responds to NRC 830613 ltr re violations noted in IE Insp. Repts 50-373/63-12 & 50-374/83-10. Corrective actions: parsonnel briefed re proper classification & parameters to be considered when evaluating emergency plan. FARRAR, D. L. Commonwealth Edison Co. 83/07/11. KEPPLER, J. G. Region 3, Office of Director. 3pp. 19701:183. 24X Fichs 50-373, 83/07/19, 8307250434.
- B307260018 Submits supplemental response to NUREG-0737. Suppl 1 (Generic Ltr B2-33). Description of parameter selection criteria to be submitted by B31231. Human factors & safety parameter display says verification to be performed w/verification program. SHARTZ, E. D. Commonwealth Edison Co. 83/07/20 DENTUN, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727:177. 24X Fiche: 50-000, B3/07/20, 8307260018.

- 8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLO.C. J. Region 3. Office of Director. 83/07/26. REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24x Fiche:50-000. 83/07/26. B307280347.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- B307200022 Discusses NUREG-0808 "Mark II Containment Program Load Evaluation & Acceptance Criteria." Analysis methods adequate to assure structures will survive potential LUCA environ. ZUDANS, Z. Franklin Institute/Franklin Research Center. ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. 83/06/15. MCKINLEY, J. C. ACRS Advisory Committee on Reactor Safeguards. 7pp. 19670:357. 24X Fiche: 50-373, 83/06/15, 8307200022.
- P. Operating license stage documents & correspondence
- B307050273 Responds to B30531 ltr re conceptual design of guard pipe cooling sys to assure that flashing of level instrument refisg will not occur. Final design should be submitted for review prior to installation.

  SCHWENCER.A. Licensing Branch 2. 83/06/21. FARRAR.D.L. Commonwealth Edison Co. 2pp. 17263: 224. 24x Fiche: 50-373,83/06/21,8307050273.
- B307090393 Forwards draft technical evaluation rept, "Control of Heavy Loads at Nuclear Power Plants, LaSalle Units 1 & 2 (Phase III)." based on response to Section 5.1 of NUREO-0612. SCHMENCER.A. Licensing Branch 2. 83/06/21. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19262:007. 24x Fiche: 50-373, 83/06/21, 8307050333.
- --8306240037 "Control of Heavy Loads at Nuclear Power Plants, LaSalle Units 1 & 2 (Phase II), "draft technical evaluation rept. JENBEN, S. A., STICKLEY, T. H. E&&G. Inc. FIN A-6457, 83/05/31. NRC No Detailed Affiliation Given. 21pp. 19262:009, 24X Fiche: 50-373, 83/06/21, 8307050333.
- B305270395 Generic Ltr B3-24 to all BWR applicants for OL & holders of OLs for Grand Gulf, LaSalle & Susquehanna re TMI Task Action Plan Item I.G. i. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list encl. EISENHUT, D. G. Division of Licensing. B3/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, B3/06/29, B306270395.
- B307110114 Forwards discussions of detailed automatic depressurization sys logic implementation & plant-specific analysis justifying bypass timer setting per License Condition 3.C. (30). (1) & TMI Item II.K. 3.18. SCHROEDER.C. W. Commonwealth Edison Co. B3/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 19375;021. 24X Fiche: 50-373, B3/07/01, B307110114.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. 8vc list encl. EISEMHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.Svc list encl. EISENHUT.D. Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche:50-000,83/07/06,8307060329.
- 8307200253 Summary of 830621 meeting w/Comm Ed.Sargent & Lundy & Guadrer Corp in Bethesda.MD re multiple control sys failures resulting from high energy line breaks. Attendee list encl. BOURNIA.A. Licensing Branch 2. 83/07/06. Licensing Branch 2. 3pp. 19669: 302. 24X Fiche: 50-373, 83/07/06, 8307200253.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISEMMUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X fiche: 50-000.83/07/08.8307080169.
- 8307120431 Withdraus, w/o prejudice, 820918 request for amend to License NPF-18 & 830524 & 0403 requests for rev to organization chart to reflect project manager position. SCHROEDER, C. W. Commonwealth Edison Co. 83/07/08. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 1p. 19425: 239, 24% Fiche: 50~373, 83/07/08, 8307120431.

- 8307220375 Forwards revised response to NRC Questions 0301.290 & 031.292 re potential multiple control sys failures due to high energy line breaks.

  SCHROEDER, C. W. Commonwealth Edison Co. 83/07/19. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. Spp. 19675:274 24X Fiche: 50-373,83/07/19.8307220375.
- 8307110369 Forwards request for add1 info re fatigue evaluation methods to resolve concerns w/test & analysis programs. SCHHENGER,A. Licensing Branch 2. 83/07/28. FARRAR,D.L. Commonwealth Edison Co. 3pp. 19391:304. 24X Fiche:50-373,63/07/28,83071105549
- Q. Inspection reports, IE Bulletins & correspondence
- 8307050024 Ack receipt of B30622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-16 & 50-374/83-14. STREETER, J. F. Region 3. Office of Director. 83/06/28. REED. C. Commonwealth Edison Co. 19. 19220:280. 24X Fichs:50-373.83/06/28, 8307090024.
- --8307050033 Responds to NRC 830524 ltr re violations noted in IE Insp. Repts 50-373/83-16 & 50-374/83-14. Corrective actions: cable 2RH-363 removed from ESF Div 2 cable tray & into proper cable tray & cable pan cleanliness inspected. FARRAR, D. L. Commonwealth Edison Co. 83/06/22. KEPPLER, J. O. Region 3, Office of Director. 3pp. 19220: 281. 24X Fiche: 50-373,83/06/28,8307050024.
- 8307030259 Confirms 830630 enforcement conference in Glen EllynilL to discuss circumstances resulting in mispositioned drywell to suppression chamber vacuum breaker isolation valve.

  NORELIUB.C.E. Division of Project & Resident Programs. 83/06/28. REED.C. Commonwealth Edison Co. 1p. 19199:057. 24X Fiche: 50-373,83/06/28,8307050259.
- B307140179 Forwards IE Insp Rept 50-373/83-23 on 830601-03. No noncompliance noted.
  LITTLE.M.S. Region 3. Office of Director. 83/06/30. REED.C. Commonwealth Edison Co. 2pp. 19522:291. 24X Fiche: 50-373,83/06/30. 8307140175.
- --8307140182 IE Insp Rept 50-373/83-23 on 830401-03. No noncompliance noted. Major areas inspected: licensee action on previous insp findings & stone protection on cooling pond embankment. NORTON. J. F. , WILLIAMS. C. C. Region 3, Office of Director. 83/06/26. 4pp. 19522: 293. 24X Fiche: 50-373, 83/06/30, 8307140175.
- 8307180195 Forwards IE Enforcement Conference Rept 50-373/83-19 on 830512.No noncompliance noted.
  MGRELIUS:C.E. Division of Project & Resident Programs. 83/07/01.
  REED:C. Commonwealth Edison Co. 2pp. 19595:146. 24X
  Fiche: 50-373,83/07/01,8307180195.
- --8307180199 IE Enforcement Conference Rept 50-373/83-19 on 830512. No noncompliance noted Major areas discussed: licensee performance in surveillance program area & proposed corrective actions.

  MADISON.A. L., WALKER, R. D. Region 3, Office of Director. 83/06/30, 11pp. 19555:148. 24X Fiche: 50-373,83/07/01,8307180195.
- B3D7110411 Ack receipt of 830610 & 24 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-373/82-2.

  BFEBBARD.R. L. Division of Engineering. 83/07/06. REED, C. Commonwealth Edison Co. 1p. 19382:021. 24X Fiche: 50-373.83/07/06, 8307110411.
- --B307110419 Responds to NRC 830428 itr re violations noted in IE Insp. Repts 50-373/82-54 & 50-374/82-22. Corrective actions: response re fire endurance capability of US Gypsum cement firestops will be submitted by 830805.

  FARRAR.D.L. Commanwealth Edison Co. 83/06/10. KEPPLER, J. G. Region 3. Office of Director. 2pp. 19382:022. 24% fiche: 50-373,83/07/06.8307:10411.
- --8307110434 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22. Corrective actions: fire seal acceptable if seal contains no cracks, voids or separations greater than 3/8-inch wide. FARRAR, D. L. Commonwealth Edison Co. 83/06/24. KEPPLER, J. G. Region 3, Office of Director. 202pp. 19382: 024. 24X Fiche: 50-373: 83/07/06, 8307110411.
- 830712032! Advises that encl insp rept re Sargent & Lundy pipe design activities concerning preloaded clamps unresolved item. W/o encl. POTAPOVS.U. Division of Vendor & Technical Programs. 83/07/07. DANIELBON.D.H. Division of Engineering. 1p. 19429:287. 24X Fiche: 50-373, 83/07/07. 8307120321.

- 8307120434 Forwards IE Safeguards Insp Rept 50-373/83-22 on 830523-25, 27 % 0601-03. No noncompliance noted. MILLER, J. R. Region 3, Office of Director. 83/07/07. REED, C. Commonwealth Edison Co. 2pp. 19425: 244. 24X Fiche: 50-373, 83/07/07, 8307120434.
- --8307120439 IE Safeguards Insp Rept 50-373/83-22 on 830523-25,27 & 0601-O3.No noncompliance noted Major areas inspected security plan & implementing procedures & security organization. Safeguards info deleted (ref IOCFR73 21). BELANGER.J. L. MADEDA.T. J. CHRISTOFFER.G. Region G. Office of Director. 83/06/30. 2pp. 19425:246. 24X Fiche.50-373.83/07/07, 8307120434.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JURDANIE L. Division of Emergency Preparedness & Engineering
  Response (Post 830103) 83/07/11. Consolidated Edison Co. of New
  York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11,8306270401
- 8307180017 Ack receipt of 830603 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-373/83-14.

  NORBELIUS, C.E. Division of Project & Resident Programs. 83/07/11.

  REED. C. Commonwealth Edison Co. 2pp. 19560: 138. 24X

  Fiche: 50-373, 83/07/11, 8307180017.
- --8307180023 Responds to NRC 830506 ltr re violations noted in IE Insp. Rept 50-373/83-14. Corrective actions: Surveillance Testing Procedures LIG-RP-D1 & 02 revised to comply w/Tech Spec setpoints.
  FARRAR, D. L. Commonwealth Edison Co. 83/06/03. KEPPLER, J. G. Region 3, Office of Director. 8pp. 1956: 140. 24X Fiche: 50-373,83/07/11,8307180017.
- B307180062 Ack receipt of B30706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/B2-54 & 50-374/B2-22.

  BPESSARD.R.L. Division of Engineering. 83/07/IL REED.C. Commanwealth Edison Co. 1p. 19560:328. 24X Fiche:50-373.83/07/I1. B307180062.
- --B307180063 Responds to NRC 830610 ltr re-violations noted in IE Insp. Repts 50-373/82-54 & 50-374/82-22 Corrective actions:cable pan cleanliness surveillance frequency increased. FARRAR.D.L. Commonwealth Edisor Co. 83/07/06. KEPPLER, J. G. Rogion 3. Office of Director. 6pp. 19560:327. 24X Fiche: 50-373,83/07/11,8307180062.
- --8307180064 "Concrete Floor Fire-Stop Test of Nonqualified IEEE 383 Cable Penetrations Protected W/Firecode CT Gypsum & Thermafiber CT Felt." GUIGO,P. S., ORALS, D. L. US Gypsum Co. 80/03/14. 38pp. 19560:335. 24X Fiche: 50-373, 83/07/11, 8307180062.
- ---8307180065 "Fire-Stop Sys M/o Cable in 3 H Fire-Rated Hell."
  GUIGG, P. S. ORALS, D. L. US Gysum Co. 79/09/06. App. 19361:011.
  24X Fiche: 50-373, 83/07/11, 8307180062.
- --B307180066 "Firecode CT Gypsum Thermafiber Access Firestopping for Walls."

  QUIGG:P S.: ORALS:D.L. US Gypsum Co. 78/07/24. 17pp. 19561:017.
  24X Fiche: 50-373, B3/07/11, B307180062.
- --8307180067 Transco Fire Test Rept TR-107, "Fire Hose Stream Tests of TCO-001 Cement."

  JAR052.G.J. Transco, Inc. TR-109, 83/04/07, 86pp. 19561:034
  24X Fiche: 50-373.83/07/11,8307180062.
- B306270404 IE Info Notice B3-47, "Pailure of Hydraulic Snobbers as Result of Contaminated Hydraulic Fluid." Svc.list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. £7563:153. 24X Fiche: 50-000, B3/07/12, 8306270404.
- B306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl: TAYLOR, J.M. Division of QA. Safeguards & Inspection Programs (Post B30(03). B3/07/14. Consolidated Edison Co. of New York: Inc. 114pp. 19715: 270. 24X Fiche: 50-000.83/07/14. B306270404.
- 8307280323 Forwards IE Insp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16. No noncompliance noted. PAPERIELLO,C. J. Division of Emergency Preparedness & Operational Support. 83/07/15. REED,C. Commonwealth Edison Co. 2pp. 19790: 218. 24X Fiche: 50-373, 83/07/15, 8307280323.

- --B307280329 IE Insp Repts 50-373/83-21 & 50-374/83-21 on B30607-10 & 16.
  No moncompliance noted Major areas inspected: state of emergency preparadness. Generic problem exists re inadequate documentation of emergency plan activities.
  PLOSKI, T., GLOERSEN, W., AXELSON, W.L., Region 3, Dffice of Director, B3707/15, 9pp. 19790: 220. 24X Fiche: 90-373, 83/07/15, 8307280323.
- B307250434 Ack receipt of B30711 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-12 & 50-374/83-10.

  SHAFER. H. D. Region 3. Office of Director. 83/07/19. REED. C. Commonwealth Edison Co. 1p. 19701:182. 24% Fiche: 50-373.83/07/19. RECO. 2007.83/07/19.
- --8307250435 Responds to NRC 830413 ltr re violations noted in IE Insp. Repts 50-373/83-12 & 50-374/83-10. Corrective actions: personnel briefed re proper classification & parameters to be considered when evaluating emergency plan. FARRAR, D. L. Commonwealth Edison Co. 83/07/11. KEPPLER, J. G. Region 3, Office of Director. 3pp. 19701:183. 24X Fiche: 50-373, 83/07/19, 8307250434.
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util, per 830715 discussion. NDRELIUS, C.E. Division of Project & Resident Programs. 83/07/22. REED.C. Commonwealth Edison Co. 2pp. 19791; 169. 24X Fiche: 50-000, 83/07/22, 8307280084.
- --B307280102 Confirms request for NRC & util senior mgt meeting on B30726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.
  REED, C. Commonwealth Edison Co. B3/07/11. DAVIS, II A. Region 3, Office of Director. 1p. 19791:171. 24x Fiche: 50-000,83/07/22, B307280084.
- R. Periodic operating reports & related correspondence
- 8307220200 Monthly operating rept for May 1983. W/830609 ltr.
  LIN.D.t., DIEDERICH.G. J. Commonwealth Edison Co. 83/06/09
  Division of Data Automation & Management Information. 15pp
  19684: 101. 24X Fighe: 50-373, 83/06/09, 8307220200.
- B307050210 Forwards Stantup Test Rept 2.consisting of test procedures re-water level measurement, average power range monitor calibr.piping & recirculation sqs.
  SCHROEDER.C.W. Commonwealth Edison Co. B3/06/24. KEPFLER.J. 0. Region 3. Dffice of Director. 2pp. 19198:297. 24X
  Fiche: 50-373.83/06/24.8307050210.
- --B307050213 "Startup Test Procedure 9.Water Level Measurement." \* Commonwealth Edison Co. 83/06/24. 3pp. 19198:299. 24% Fiche: 50-373,83/06/24,8307050210.
- --8307050215 "Startup Test Procedure 12. Average Power Range Monitor Calibr." \* Commonwealth Edison Co. 83/06/24. [p. 19198: 302. 24X Fiche: 50-373, 83/06/24. 8307050210.
- --8307050218 "Startup Test Procedure 17.6ys Expansion." \* Commonwealth Edison Co. 83/06/24. 2pp. 19198:303. 24X Fiche:50-373.83/06/24.8307050210.
- --8307050220 "Startup Test Procedure 23A,Feedwater Control 8ys." \* Commonwealth Edison Co. 83/06/24. 2pp. 19198:305. 24X Fiche: 50-373,83/06/24,8307050210.
- --8307050223 "Startug Test Procedure 26.Relief Valves." • Commonwealth Edison Co. 83/06/24. 2pp. 19198:307. 24% Fiche: 50-373:83/06/24-8307050210.
- ---8307050225 "Btartup Test Procedure 29.Recirculation Flow Control Sys." a Commonwealth Edison Co. 83/06/24. Spp. 19198:309. 24X Fiche: 50-373.83/06/24.8307050210.
- --8307050229 "Startup Test Procedure 30.Recirculation 8ys," \* Commonwealth Edison Co. 83/06/24. 2pp. 19198:314. 24X Fiche: 90-373.83/06/24,8307050210.
- ---8307050233 "Btartup Test Procedure 33.Drywell Piping Vibration." a Commonwealth Edison Co. 83/06/24. ip. 19198:316. 24X Fiche: 50-373, 83/06/24, 8307050210...
- --8307050235 "Btartup Test Procedure 35.Recirculation Sys Flow Calibr." \* Commonwealth Edison Co. 83706/24. ip. 19198:317. 24X Fiche: 50-373.83/06/24.8397050210.

- --8307030239 "Gtantup Test Procedure 74.0ffgas Sys."

   Commonwealth Edison Co 03/06/24 2pp 19190:318, 24x

  Fiche, 30-973, 83/06/24, 8307030210
- B. Reportable occurrences, i.ERs & related correspondence
- G307050070 Updated LER G3-012/Cix-t on G30210.w/reactor in cold shutdown, setpoints for switches 1631-Ne12A/B found above fact Spec Limits. Cause unknown Buttches calibr W/030616 fts. WITTENBURG, K.C., DIEDERICH.G.J., Commonwealth Edison Co., 33/06/16 KEPPLER.J.G. Region 3. Office of Director. Jpp. 19193:186, 24X Fiche: 50-373/83/06/16/8307050070
- 8307080088 Updated LER 83-085/01X-1 on 830207. several temp switches mfg by Panalarm Div of Riley Co determined out of Yech Spec requirements caused by calibr between Riley modules & common indicator meter W/M30646 itr WITTENBURG.K., DIEDERRICH.G.J. Comminwealth Edison Co. 83/06/16 REPPLER.J.G. Region 3. Office of Director 6pp. 19220:014. 24x Fiche: 30-373.83/06/16.8307090088
- 8307030146 Updated LER 83-013/03X-1.on 830210, setpoints for switches 1831-N601A through K found above LCP Cause of instrument drift out found Bix of 10 switches replaced w/Unit 2 modules & switches callbr W/B30616 ltr WITTENBURG.K. DIEDERICH.O.J. Commonwealth Edison Co. 83/06/16 KEPPLER.J 0 Region 3, Office of Director 3pp 19220:063, 24x Fiche: 50-373:83/06/16-8307090146
- 8307060333 LER 83-0537038.-0 on 830320.diesel generator IA operability surveillance LOS-D9-M2 frequency exceeded Tech Specs by 18 days. Caused by personnel error Procedure change to LAP-1600-6 being implemented M/830616 ltr. MILSON 0. DIEDERICH Q. J. Commonwealth Edison Co. 93/04/16. REPPLER, J. 9. Region 3. Office of Director Gpp. 19236:250. 24X Fiche: 50-373, 93/06/16-8307060393
- 8307060331 LER B3-056703L-0 nn 830529. w/unit in Condition 2, rod 30-19 with to over-travel position while being withdrawn for startup. Possibly caused by excessive crud buildup 8/or undue force applied directly to inner filter W7630617 ltr. KALHON, K. J., DIEDERICH O. J. Consolidated Edison Co. of New York Inc. 83/06/17. KEPPLER J. O. Region G. OFFice of Director. 3pp. 19234:210 84X Fiche: 50-373, 83/06/17, 8307060331.
- B30721004B Updated LER U3-042/032/1 on G30423 inboard HDIVs 1821-F027A, BrC & D found leaking above Tech Upec limit Caused by imperfect seating of disc & seat surfaces Valves & discs lapped & reinstalled H/H30707 ltr
  HASTERGON, B. DIEDERICH, G. J. Commonwealth Edison Co. B3/06/21
  KEPPLER, J. G. Regins 3, Office of Director 4pp. 19668; 299. 24x
  Fichs: 50-373, U3/06/21, U307210048.
- B307060342 LER 83-055/03.-0 on 830325, monthly functional test on main steam leakage control temp instrumentation not performed since last caller on 820128. Caused by misunderstanding of responsibility. Test frequency revised W/830627 ltr. TRAINOR.A. DieDeRICH.Q.J. Commonwealth Edison Co. 83/06/27. KEPPLER.J.G. Region 3. Office of Director. 3pp. 19236:255. 24X Fiche: 30-378.83/06/27, 0307060342.
- B307060004 LER B3-057703L-0 on B30601, following reactor scram-operated decreased reactor pressure to 250 paig to allow condensate makeup to reactor to correct low RPV level. Moderator temp decreased faster than Tech Opec limit in 1 h M/830629 ltm. MITTENBURO.K. DIEDERICH.O.J. Commonwealth Edison Co. B3706/29. REPPLEALJ.G. Region 3. Office of Director Spp. 19250:344. 248 Fichs: 50-373, 63/706/29, 6307060054
- BJ07110400 LER EJ3-059/03.-0. on BJ0931, while in cold shutdown redwaste discharge line hi-hi radiation isolation valve CHLO67 failed to close Caused by coating of dirt on valve seat. Heat cleaned 5 reassembled W/8J06J0 ltr ARAND.J.J. DIEDERICH 6.2 Commonwealth Edison Co. BJ06/J0. REPPLER, J. G. Region D. Office of Director Spp. 19302: 280, 24x Fiche 50-373, 63/06/J0. BJ07110400
- G307110416 LER G3-058/01T-0: on D30621; primary containment vacuum breaker iPC001D isolation valve iPC003D found closed & unlocked Caused by shortfall in administrative control of equipment Equipment procedure revised M/830705 ltr. ATCHLEY, J. H. DEDERICH O. J. Commonwealth Edison Co. 83/07/05. KEPPLER, J. O. Region 3. Office of Director. 3pp. 19382: 272. 24 Fichs: 50-378 69/07/05, B307110416.
- 8307110488 LER B3-060703L-0: on B30606 following turbine trip & scrae due to high vibration on main turbine reactor recirculation breaker ill closed Cause undetermined Auxiliary contacts cleaned 47830705 ltr.
  RENNICKUJC: DIEDERICHIO J. Commonwealth Edison Co. 83/07/85 REPPLERJ O. Region 3, Office of Director. 3pp. 17380: 131. 241 Fichs: 50-373, 83/07/05, 8307110488

- 8307110371 Final Deficiency Rept 83-03 re medium voltage circuit breakers of same type installed at Limerick which inadvertently closed after completion of spring charging due to slipped close latch discussed in Brown Boveri 830524 ltr. SCHROEDER.C.W. Commonwealth Edison Co. 83/07/07. KEPPLER, J. C. Region 3, Office of Director. Spp. 19380:266. 24X Fiche: 30-000.83/07/07.8307110371.
- --B307110377 Followup interim rept re potential deficiency in SHK switchgear supplied by Brown Boveri.Circuit breaker inadvertently closed & tripped following spring charging. Light spring added to close latch.

  DUVALL.D.D. Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.).

  B3704/28. STELLO.V. Director's Dffice. Office of Inspection and Enforcement. 2pp. 19380:271. 24X Fiche: 90-000, 83/07/07.
- --B307i10381 Procedure IB-8307, "Instructions for Installation of Close Latch Anti-Shock Spring in HK Mechanism (Used in Breakers Less Than 1,000 MVA)." \* Brown Boveri Corp. (subs. Brown Boveri & Ca., Ltd.). 83/04/28. 3pp. 19380:273. 24X Fiche:50-000,83/07/07,8307110371.
- B307180191 LER B3-062/03L-0: on B30612, offges hydrogen analyser train A would not switch extensically put of calibr mode. Caused by contact failure within control switch. Work on analyser completed on B30623. W/B30711 ltr. HOUSTON.R.W., DIEDERICH.G.J. Commonwealth Edison Co. 83/07/11. KEPPLER.J.G. Region 3, Office of Director, 3pp. 19555:207. 24X Fiche: 50-373, B3/07/11, B307180191.
- 8307210001 LER 83-064/03L-0: on 830613. Div i post-LOCA oxygen monitor drifted downscale & declared inoperable. Caused by dust particles in matering valve at analyser cell. Dxygen monitor calibr per LIS-PC-07. W/830711 ltr.
  DUS. R., KALMAN, K., DIEDERICH, O. J., Commonwealth Edison Co. 83/07/11. KEPPLER. J. O. Region 3. Office of Director. 3pp. 19468:192. 24X Fiche: 50-373, 83/07/11, 8307210001.
- 8307210065 LER 83-045/03L-i: on 830615 & 13, Div 1 post-LOCA oxygen monitor began to drift downscale. Caused by leaking disphragm in vacuum pump & leaking O-rings of analyzer cell. Components replaced & monitor recalibr. W/830711 ltr.
  DUS.R., DIEDERICH.G. J. Commonwealth Edison Co. 83/07/11.
  KEPPLER.J.G. Region 3. Office of Director. 3pp. 19668: 264. 24X
  Fiche: 50-373,83/07/11.8307210065.
- 8307210148 LER 83-063/03L-0:on 830613, w/Div II post-LOCA hydrogen monitor out of svc.Div I hydrogen recorder read 1% & declared inoperable Caused by out of calibr hydrogen analyser cell.Div I monitor recalibr.W430711 ltr. DUS.R., KALMAN.K., DIEDERICH.G. J. Commonwealth Edison Co. 83/07/11. KEPPLER.J. O. Region 3, Office of Director. 3pp. 17668:338. 24% Fiche:50-373,83/07/11,8307210148.
- B307220201 LER B3-067/OGL-0: on B30617, HPCS testable check bypass valve IE22-F354 failed to close. Caused by insufficient spring tension of actuator assembly. Bpring tension to rack & gear assembly increased & inservice test revised. W/B30715 ltp. MASTERSON, V. V. DIEDERICH, G. J. Commonwealth Edison Co. B3/07/15. KEPPLER. J. G. Region 3, Office of Director. 4pp. 17684:340. 24X Fiche: 50-373,83/07/15.8307220201.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.

  LITKA.T.J. Elcen Metal Products Co. 83/07/15. KEPPLER, J. G. Region 3. Office of Director. 26pp. 17484:084. 24X Fiche: 50-000, 83/07/15, 8307220444.
- 8307220542 RB: on 830619, while DA diesel fire pump running, our to frequent autostart signal on low pressure, trouble light received. Caused by broken V-belt. Pump operability restored on 830629.

  DIEDERICH. O. J. Commonwealth Edison Co. 83/07/15. KEPPLER, J. G. Region 3. Office of Director. ip. 19686:037. 24X Fiche: 50-373, 83/07/15, 8307220542.
- 8307220193 LER B3-064/03L-0: on B30617, HPSC testable check valve IE22-F005 Failed to close Caused by failure of hypass valve. Work request generated & completed on 830703. Spring tension to rack & gear assembly increased W/B30715 ltr. MASTERSON, V. V. DIEDERICH, O. J. Commonwealth Edison Co. 83/07/17. KEPPLERIJG. Region 3, Office of Director. 4pp. 19484:089. 24X Fichs: 50-373, 83/07/17, 8307220193.
- 8307220187 Advises that on 830712. ENWL employee working at site left ascort to go to washroom. Situation warrants further action. BNML should be contacted to obtain firm commitment to meet security responsibilities at sites.
  CREED, J. R. Region 3, Office of Director. 83/07/18. AXELSON, W. L. Region 3, Office of Director. 19, 19683:346. 24X
  Fiche: 50-373, 83/07/18, 8307220187.

- 8307220531 PNG-III-83-063: on 830714, during monthly sorveillance testing of ECC5 actuation circuitry, one of two reactor water level switches failed to respond Caused by improperly connected wires in terminal panel. Panels will be sealed. MADISON.A., SHAFER.W. Region 3, Office of Director. 83/07/18. 1p 19685:008. 24x Fiche: 50-373,83/07/18,8307220531.
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8307050293 Responds to 83053) itr re-conceptual design of guard pipe cooling sys to assure that flashing of level instrument refileg will not occur. Final design should be submitted for review prior to installation.

  SCHWENCER. A. Licensing Branch 2. 83/06/21. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19263: 224. 24X Fiche: 30-373, 83/06/21, 8307050293.
- 8307050333 Forwards draft technical evaluation rept, "Control of Heavy Loads at Nuclear Power Plants. LaSalle Units 1 b 2 (Phase II)." based on response to Section 5.1 of NUREO-0612. SCHWENCER.A. Licensing Branch 2. 83706721. FARRAR.D. L. Commonwealth Edison Co. 2pp. 19262:007. 24X Fiche: 50-373.83706721. 8307050333.
- --8306240037 "Control of Heavy Loads at Nuclear Power Plants, LaSalle Units i & 2 (Phase II);" draft technical evaluation rept. JENSEN, S. A., 971CKLEY, T. H. EG&G, Inc. FIN A-6457. 83/05/31. NRC No Detailed Affiliation Given. 21pp. 19262:009. 24X Fiche: 50-373, 83/06/21, 8307050333.
- B306270395 Generic Ltr B3-24 to all BWR applicants for QL & holders of QLs for Grand Gulf.LaSalle & Susquehanna re TMI Task Action Plan Item I.G. 1. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list encl. EISENHUT.D.G. Division of Licensing. B3/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, B3/06/29. B306270395.
- 8307110114 Forwards discussions of detailed automatic depressurization sys logic implementation & plant-specific analysis justifying bypass timer setting per License Condition 3. C. (30). (1) & TMI Item II.K. 3. IB.

  8604RGEDER.C.W. Commonwealth Edison Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 7pp. 19375:021. 24X Fiche: 50-373.83/07/01.8307110114.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307120382 Forwards revised responses to NRC Questions 031.290 & 292 re potential multiple control sys failures due to high energy line break events.per 830621 discussion.

  SCHROEDER.C.W. Commonwealth Edison Co. 83/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 9pp. 19429:030. 24X Fiche: 50-373.83/07/06.8307120382.
- 8307200253 Summary of 830621 meeting e/Comm Ed.Sargent & Lundy & Guadrex Corp in Bethesda, MD ro multiple control sys Failures resulting from high energy line breaks. Attendee list encl. BOURNIA, A. Licensing Branch 2. 83/07/06. Licensing Branch 2. 3pp. 19669: 302. 24% Fiche: 50-373, 83/07/06, 8307200253.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list enct. EISENHUT, D. G. . Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:267. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307220375 Forwards revised response to NRC Questions 0301,270 % 031,272 re potential multiple control sys failures due to high energy line breaks. SCHROEDER.C.W. Commonwealth Edison Co. 93/07/19, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. Spp. 17675:274,24X Fiche: 50-373,83/07/19,8307220375.
- B307260301 Requests deferral of encl preoperational tests beyond fuel load. Delay due to design delivery & installation problems. Evaluation prior to fuel load will ensure sys & subsystem adequacy.

  REED.C. Commonwealth Edison Co. B3/07/21. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. Spp. 19726:109. 24X Fiche: 50-374, 83/07/21, 8307260301.

- 8307110369 Forwards request for add1 info re fatigue evaluation methods to resolve concerns w/test & analysis programs.

  SCHWENCER, A Licensing Branch 2. 83/07/28. FARRAR.D.L.
  Commonwealth Edison Co. 3pp. 19391.304. 24X Fiche: 50-373, 83/07/28, 8307110369.
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- 8307120524 Forwards response to Generic Ltr 82-33 (Suppl 1 to NUREO-0737) re detailed control room design review based on emergency response capability. Response supersedes Section C, App C to Suppl 1 to SER (NUREO-0519). SCHROEDER.C. H. Commonwealth Edison Co. B3/07/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 14pp. 19433:264.
- 8307260314 Forwards marked-up revised FSAR Table 14.2-123.per 830706 teleon & SER Section 14.deleting ref to measurement of relief valve capacity. Changes will be incorporated into FSAR SCHROEDER, C. W. Commonwealth Edis
- F. Security, medical, emergency & fire protection plans
- 8307110411 Ack receipt of 830610 & 24 ttrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22 SPESSARD.R.L. Division of Engineering. 83/07/06. REED.C. Commonwealth Edison Co. ip. 19382:021. 24X Fiche: 50-373,83/07/06,8307110411.
- --8307110419 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22. Corrective actions: response re fire endurance capability of US Gypsum cement firestops will be submitted by B3805. FARRAR, D. L. Commonwealth Edison Co. B3/06/10. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19382:022. 24X Fiche: 50-373, 83/07/06.8307110411.
- --8307110434 Responds to NRC 830428 ltm re violations noted in IE Insp. Repts 50-373/82-54 & 50-374/82-22. Corrective actions: fire seal acceptable if seal contains no cracks, voids or separations greater than 3/8-inch wide.

  FARRAR, D. L. Commonwealth Edison Co. 83/06/24. KEPPLER, J. G. Region 3. Office of Director. 202pp. 19382:024. 24%

  Fiche: 50-373, 83/07/06, 8307/10411.
- B307120324 Forwards response to Generic Ltr B2-33 (Supp) 1 to NUREC-0737) re detailed control room design review based on emergency response capability. Response supersedes Section C. App C to Supp! 1 to SER (NUREC-0519). SCHROEDER, C. W. Commonwealth Edison Co. B3/07/06. DENTON, H. R. Dffice of Nuclear Reactor Regulation. Director. 14pp. 19433:264. 24X Fiche: 50-374.83/07/06.8307120324.
- 8307180062 Ack receipt of 830706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-34 & 50-374/82-22.

  SPESSARD.R.L. Division of Engineering. 83/07/11. REED.C. Commonwealth Edison Co. ip. 19560:328. 24X Fiche:50-373,83/07/11,8307180062.
- --8307180063 Responds to NRC 830610 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22. Corrective actions: cable pan cleanliness surveillance frequency increased. FARRAR,D.L. Commonwealth Edison Co. 83/07/06. KEPPLER,J.O. Region 3, Diffice of Director. 6pp. 19560:329, 24X Fiche: 50-373,83/07/11/8307180062.
- 8307280323 Forwards IE Insp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16. No noncompliance noted. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/07/15. REED, C. Commonwealth Edison Co. 2pp. 19790:218. 24X Fiche: 50-373, 83/07/15, 8307280323.
- --8307280327 IE Insp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16. No noncompliance noted Major areas inspected state of amergency preparedness. Generic problem exists re inadequate documentation of emergency plan activities. PLOSKI, T. Region 3, Office of Director. 83/07/15. 9pp. 19790:220. 24X Fiche: 50-373, 83/07/15, 8307280323.
- B307250434 Ack receipt of B30711 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/B3-12 & SHAFER.W.D. Region 3, Office of Director. B3/07/17. REED, C. Commonwealth Edison Co. 1p. 19701:182. 24X Fiche: 50-373, 83/07/19, B307250434.

- --8307250435 Responds to NRC B30613 ltr re violations noted in IE Insp. Repts 50-373/83-12 & 50-374/83-10. Corrective actions: personnel briefed re proper classification & parameters to be considered when evaluating emergency plan. FARRAR, D. L. Commonwealth Edison Co. B3/07/11. KEPPLER, J. O. Region 3. Office of Director. 3pp. 19701: 183. 24X Fiche: 50-373, B3/07/19, B307250434.
- B30726001B Submits supplemental response to NUREG-0737. Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by B31231. Human factors & safety parameter display says verification to be performed w/verification program. SMARTZ.E.D. Commonwealth Edison Co. B3/07/20. DENTON.H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727:177. 24x
- 8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan.Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl.

  PAPERIELLO.C.J. Region 3, Office of Director. 83/07/26. REED.C. Gommonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 50-000, 83/07/26.8307280347.
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- B307200022 Discusses NUREG-0808 "Mark II Containment Program Load Evaluation & Acceptance Criteria." Analysis methods adequate to assure structures will survive potential LUCA environ. ZUDANS, Z. Franklin Institute/Franklin Research Center. ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. B3/06/15. MCKINLEY, J. C. ACRS Advisory Committee on Reactor Safeguards. 7pp. 19670:357. 24X Fiche: 50-373, B3/06/15, B307200022.
- P. Operating license stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390;317. 24x Fiche: 50-000,83/07/05,8306270397.
- G. Inspection reports, IE Bulletins & correspondence
- 8307050024 Ack receipt of 830622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-16 & 50-374/83-14.

  STREETER, J. F. Region J. Office of Director. 83/06/28. REED, C. Commonwealth Edison Co. 1p. 19220: 280. 24X Fiche: 50-373, 83/06/28, 8307050024.
- --8307050033 Responds to NRC 830524 ltr re violations noted in IE Insp. Repts 50-373/83-16 & 50-374/83-14. Corrective actions: cable 28ti-363 removed from ESF Div 2 cable tray & into proper cable tray & cable pan cleanliness inspected. FARRAR, D. L. Commonwealth Edison Co. 83/06/22. KEPPLER, J. G. Region 3. Office of Director. 3pp. 19220: 281. 24X Fiche: 50-373, 83/06/28, 8307050024.
- 8307080329 Ack receipt of B30523 & O614 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-374/83-11. Meeting will be arranged to discuss violation re improper cable segregation.
  LITILE: M.S. Region 3. Office of Director. 83/06/30. REED, C. Commonwealth Edison Co. ip. 19350:141. 24X Fiche: 50-374, 83/06/30. 8307080329.
- --8307080334 Responds to NRC 830426 ltr re violations noted in IE Insp. Rept 50-374/83-11. Corrective actions: Nonconformance Rept 626 initiated to record & resolve improper cable segregation & drawing for internal panel wiring will be developed. FARRAR.D.L. Commonwealth Edison Co. 83/05/23. KEPPLER, J. G. Region 3, Office of Director. 3pp. 19350:142. 24X Fiche: 50-374, 83/06/30, 8307080329.
- --8307080338 Suppls 830523 response to NRC 830426 ltr re violations noted in IE Insp Rept 50-374/83-11. Corrective actions: drawing for internal panel wiring will not be completed by 830615. Meeting requested to dispute violation. FARRAR, D. L. Commonwealth Edison Co. 83/06/14. KEPPLER, J. G. Region 3. Office of Director. 2pp. 19350:145, 24X Fiche: 50-374, 83/06/30, 8307080329.

- --8307140181 Natice of violation from insp on 830517-0617. STREETER, J. F. Region 3. Office of Director. 83/07/01. 1p. 19521:003. 24X Fiche: 50-374.83/07/01.8307140176.
- ---8307140422 IE Insp Repts 50-374/83-20 on 830517-0617. Noncompliance noted: failure to identify deficiencies in reactor circulation sys preoperational test procedure for jet pumps. LANKSBURY, R. D., DUPONT, S. Q., REYES, L. A. Region 3. Office of Director. 83706/30. 3pp. 19521:004. 24X Fiche: 30-374, 83/07/01, 8307140176.
- B307110411 Ack receipt of 830610 & 24 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22.
  SPESSARD.R.L. Division of Engineering. 83/07/06. REED.C. Commonwealth Edison Co. 1p. 19382:021. 24X Fiche: 50-373,83/07/06.
- --B307110419 Responds to NRC 830428 ltr re violations noted in lE Insp Repts 50-373/82-54 & 50-374/82-22. Corrective actions: response re fire endurance capability of US Gypsum coment firestops will be submitted by 830803. FARRAR.D.L. Commonwealth Edison Co. 83/06/10. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19382:022. 24X Fiche: 50-373, 83/07/06, 8307110411.
- --8307i10434 Responds to NRC 830428 ltr re violations noted in IE Insp. Repts 50-373/82-34 & 50-374/82-22. Corrective actions: fire seal acceptable if seal contains no cracks.voids or separations greater than 3/8-inch wide.

  FARRAR.D.L. Commonwealth Edison Co. 83/06/24. KEPPLER.J. G. Region 3. Office of Director. 202pp. 19382:024. 24X Fiche: 50-373,83/07/06,8307110411.
- 8307210147 Forwards IE Insp Rept 50-374/83-26 on 830621-22.No noncompliance noted.
  LITYLE,M.S. Region 3. Office of Director. 83/07/06. REED,C. Commonwealth Edison Co. 2pp. 19668:354. 24X Fiche: 50-374,83/07/06,8307210147.
- --8307210154 IE Insp Rept 30-374/83-26 on 830621-22. No noncompliance noted Major areas inspected review of procedure specs & test set-up for structural integrity test.
  NORTON, J.F., WILLLIAMS. C. C. Region 3, Office of Director.
  83/07/07. 2pp. 19668:356. 24x Fiche:50-374,83/07/06,8307210147.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Dagrade Surry Recirculation Spray Subsystem." Svc list encl.
  JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- 8307180062 Ack receipt of 830706 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-94 & 50-374/82-22.

  8PE8BARD.R.L. Division of Engineering. 83/07/11. REED.C. Commonwealth Edison Co. 1p. 19360: 328. 24X Fiche: 50-373, 83/07/11, 8307180062.
- ---B307180063 Responds to NRC B30610 ltr re violations noted in IE Insp. Repts 50-373/82-54 & 50-374/82-22. Corrective actions: cable pan cleanliness surveillance frequency increased. FARRAR, D. L. Commonwealth Edison Co. B3/07/06. KEPPLER, J. G. Region 3, Office of Director. App. 19560: 327. 24X Fiche: 50-373, 83/07/11, 8307180062.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR,J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14,8306270406.
- B307280142 Forwards IE Insp Rept 50-374/83-22 on 830516-0610. No noncompliance noted.
  LITTLE.W.S. Region 3, Office of Director. B3/07/14. REED.C. Commonwealth Edison Co. 2pp. 19791:300. 24X Fiche: 50-374. B3/07/14. B307280142.
- ---B307280156 IE Insp Rept 50-374/83-22 on 830516-0610 No noncompliance noted Major areas inspected corrective actions on previous items & observation & record review of instrumentation installation.

  AHMED, I., NAIDU, K. R., WILLIAMS, C. C. Region 3, Office of Director. 83/07/13. 6pp. 19791:302. 24X Fiche: 50-374, 83/07/14, 8307280142.

- 8307280323 Forwards If Insp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16. No mencompliance noted. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/07/15. REED, C. Commonwealth Edison Co. 2pp. 19790: 218. 24X Fiche: 50-373, 83/07/15, 8307280323.
- --8307280329 IE Insp Repts 50-373/83-21 & 50-374/83-21 on 830607-10 & 16.
  No noncompliance noted Major areas inspected: state of emergency preparedness. Generic problem exists re inadequate documentation of emergency plan activities.
  PLOBKI.T. GLOERSEN.H., AXELSON.H.L. Region 3, Office of Director.
  83/07/15 9pp. 19790:220 24X Fiche: 50-373, 83/07/15, B307280323.
- 8307250434 Ack receipt of 830711 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-12 t 50-374/83-10.

  SHAFER, M. D. Region 3. Office of Director. 83/07/19. REED, C. Commonwealth Edison Co. 1p. 19701:102. 24x Fiche: 90-373.83/07/19, 8307250434.
- --8307250435 Responds to NRC 830613 ltr re violations noted in IE Insp. Repts 50-373/83-12 & 50-374/83-10. Corrective actions: personnel briefed re proper classification & parameters to be considered when evaluating emergency plan. FARRAR.D. L. Commonwealth Edison Co. B3/07/11. KEPPLER, J. G. Region 3. Office of Director. 3pp. 19701:183. 24X Fiche: 50-373, 83/07/19, 8307250434.
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & utiliper 830715 discussion.
  NORELIUS.C.E. Division of Project & Resident Programs. 83/07/22.
  REED.C. Commonwealth Edison Co. 2pp. 19791:169. 24X
  Fiche: 50-000, 83/07/22, 8307280084.
- --8307280102 Confirms request for NRC & util senior mgt meeting on 830726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.

  REED, C. Commonwealth Edison Co. 83/07/11. DAVIS.B. A. Region 3, Office of Director. ip. 19791:171. 24X Fiche: 50-000,83/07/22, 8307280084.
- S. Reportable occurrences. LERs & related correspondence
- 8307110371 Final Deficiency Rept 83-03 re medium voltage circuit breakers of same type installed at Limerick which inadvertently closed after completion of spring charging due to slipped close latch discussed in Brown Boveri 830524 ltr. SCHROEDER, C. W. Commonwealth Edison Co. 83/07/07 KEPPLER, J. G. Region 3, Office of Director. Spp. 19380:266. 24X Fiche: 50-000, 83/07/07, 8307160371.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against suby products. Encl list of springs identified for Comm Ed only.

  LITKA.T.J. Elcen Metal Products Co. 83/07/15. KEPPLER.J.G. Region 3. Office of Director. 26pp. 19686:086. 24X Fiche: 50-900. 83/07/15. 8307220446.
- 8307220486 Final rept re potentially defective Figures 425,426 & 428 spring hangers mfg by Elcon Metal Products Co. Initially reported on 830617. Review revealed spring hanger installed at facility not type in question. Item closed. SCHROEDER.C.W. Commonwealth Edison Co. B3/07/15. KEPPLER, J Q. Region 3. Office of Director. 1p. 17685:103. 24X Fiche: 50-374. B3/07/15. B307220486.
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 8307260225 Forwards chart of util huclear operations dept w/functional responsibilities for NRC contacts.

  DRUMMOND, F.J. Louisiana Power & Light Co. 83/06/06. COLLINS, J. T. Region 4. Dffice of Director. 3pp. 19727:245. 24X
  Fiche: 50-382-83/06/06-8307260225.
- B307260229 Provides info re changes to GA program from PEAR description, for review & acceptance.

  GERRETS, T. F. Louisiana Power & Light Co. 83/06/09. CDLLINS, J. T. Region 4. Defice of Director. 9pp. 19726:346. 24X Fiche: 50-382, 83/06/09, 8307260229.
- --9307260247 Topical rept evaluation of ETR-1001,Rev 0, "Ebasco Nuclear QA Program." Rept acceptable. \* GA Branch. B3/06/09, 2pp. 19726:357. 24K Fiche: 50-382, 83/06/09, 8307260229.

- --8307260256 Advises that GA program described in Topical Rept CEMPO-210-A. Rev 3 being implemented satisfactorily. Conclusions of itr valid for 3 yrs. SEYFRIT.K.V. Region 4. Dallas. Office of the Director (81/03/01). 81/06/02. ETHERIDGE, M.R. Combustion Engineering, Inc. 3pp. 19726:359. 24% Fiche:50-382,83/06/09.8307260229.
- 8307070431 Requests list of all test rapts reviewed during equipment qualification site audit 830104-06. List of audited equipment items encl.

  NOVAK, T. M. Assistant Director for Licensing. 83/06/17. MAURIN, L. V. Louisiana Power & Light Co. 3pp. 19300:181. 24X

  Fiche: 50-382, 83/06/17, 8307070431.
- B307040251 Forwards responses to 14 questions submitted in NRC B20327 ltr re-depressurization & DHR capability. Results indicate existing capability adequate. W/o encls. BRUMHOND.F. J. Louisiana Power & Light Co. B3/04/29. KNIGHTON. Q. W. B307040251.
- 8307060314 Forwards matts received from Shell Oil & Chemical Co. consisting of itr of agreement affidavit & updated response to questionnaire re facility. Updated questionnaire response withhald (ref 10CFR2. 790).

  ORUMMOND. F. J. Louisiana Power & Light Go. 83/06/29. KNIGHTON. G. W. Elicensing Branch G. Spp. 19237: 052. 24x Fiche: 50-382.83/06/29, 8307060314.
- 8307060332 Responds to Core Performance Branch request for additinfore Guestion 12 on implementation & verification of core protection calculation sys constant changes originating from GE. Operational Procedure GP4-006 applicable.

  DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/29, KNIGHTON, G. & Licensing Branch 3. 2pp. 19234: 209. 24X Fiche: 50-382, 83/06/29, 8307060332. KNIGHTON, G. W.
- 8307080298 Notifies of deferral of installation of plant-specific simulator due to shortage of qualified manpower. Simulator will be operational by 87(23).
  DRUMHOND, F. J. Louisiana Power & Light Co. 83/07/01. KNIGHTON, G. W. Licensing Branch 3. 2pp. 1935(:18). 24x Fiche: 50-382, 83/07/01.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche:50-000,83/07/05. B306270397.
- 8307060329 Control Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Syc list encl. EISENNUT.D.G. Division of Licensing. 83/07/06. Consolidation Co. of New York. Inc. 16pp. 19649:254. 24X Fiche: 50-000,83/07/06,8307060329. Consolidated
- B307080169 Generic Ltr B3-28 to all licensess of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York: Inc. 38pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- B307220412 Forwards "Reactor Containment Bldg Integrated Leakage Rate Test:" final rept. DRUMMOND.F.J. Louisiana Power & Light Co. B3/07/19. KNIGHTON.G.W. Licensing Branch J. 1p. 19491:213. 24X Fiche:50-382,83/07/19, B307220412.
- --8307220419 "Reactor Containment Bldg Integrated Leakage Rate Test," 307220419 "Reactor Containment Bing Invegrated Costage Nave (e.f. final Pept. Final Pept. RUBIN.M , DILLON,P.B. Ebasco Services, Inc. (subs. of Enserch Corp.). KANE.J. Louisiana Power & Light Co. 83/03/01. 126p 19691:215. 24X Fiche:50-382,83/07/19,8307220412.
- B307260489 Forwards response to NRC B30510 itr requesting review of ESF actuation sys testing commitments against provisions of IEEE-338 & Reg Guide 1.22.List of ESF subgroup relays not testable during operation encl. DRUMMOND.F. J. Lauistane Power & Light Co. B3/07/21. KNIGHTON.G. W. Licensing Branch 3. 15pp. 19733:357. 24X Fiche: 50-382.83/07/21. B307260489.

- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307010019 Requests that SER, Section 7.5.4 be amended to reflect current NRC requirements & util commitments for proposed plant computer-based safety parameter display sys, per NUREG-0696 & NUREG-0737, Suppl 1.
  DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/27, KNIGHTON, Q. W. Licensing Branch 3. 1p. 19169:107. 24X Fiche: 50-382, 83/06/27, 8307010019.
- B307150139 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WATERFORD STEAM ELECTRIC STATION.UNIT 3. Docket No. 50-382. (Louisiana Power And Light Company) \* Division of Licensing. NUREO-0787 S05. 63/06/30. 120pp. 19596: 131. 24X Fiche: 50-382, 83/06/30, 8307150139.
- 8307200503 Forwards SER Suppl 5, NUREG-0787, W/o encl. KNICHTCN, G. W. Licensing Branch 3. 83/07/08. MAURIN, L.V. Louisiana Power & Light Co. 2pp. 19472:302. 24X Fiche: 50-382, 83/07/08,
- B307260470 Requests SER suppl be prepared to remove license condition re-secondary chemistry programs Program PND-CE-03 includes required provisions. Implementation will satisfy NRC DRUMMOND, F. J. Louisiana Power & Light Co. 83/07/21. KNIGHTON, G. H. Licensing Branch G. 1p. 19734:164. 24X Fiche: 50-382, 83/07/21, 8307260470. DRUMMOND & I
- B307260511 Identifies SER issue re monitoring nuclear plant island structure settlement which has been resolved. Requests that SER suppl be written to remove license condition. DRUMHOND.F. J. Louisiana Power & Light Co. B3/07/21. KNIGHTON.G.W. Licensing Branch 3. 1p. 19731:344. 24X Fiche: 50-382,83/07/21.
- 8307260518 Discusses post-accident sampling sys per Suppl 2 of SER. Bys will be tested every 6 months by obtaining RCS sample & comparing results w/concurrent RCS sample obtained by normal means.

  DRUMMOND, F. J. Louisiana Power & Light Co. 83/07/21. KNIOHI DRUMMOND,F.J. Louisiana Power & Light Co. 83/07/21. KNIOHTON, Q. M. Licensing Branch 3. ip. 19731:345. 24X Fiche:30-382,83/07/21. 8307260518.
- 8307260560 Requests that supplemental SER be written to remove license condition re LER on MW demand setter or reactor power cutback malfunctions. Procedure UNT-6-002 revised to require LER on noted malfunctions. DRUMMOND, F. J. Louisiana Power & Light Co. 83/07/21. KNIGHTON, O. W. B307260560.
- B307260562 Requests that supplemental BER be written to removal license condition re reevaluation of essential vs nonessential system for Rev 2 to Reg Guide 1.141 Review should commence when reg guide issued.

  DRUMMOND.F.J. Louisiana Power & Light Co. 83/07/21. KNIGHTON.G.W. Licensing Branch 3. ip. 19731:356. 24X Fiche: 50~382,83/07/21.
- 8307260568 Requests that BER suppl be written to delete license condition re ECCS preoperational testing.

  DRUMMOND, F. J. Lauisiana Power & Light Co. 83/07/21. KNIGHTON, G. H. Licensing Branch 3. lp. 19732:106. 24X Fiche: 50~382, 83/07/21, 8307260368.
- F. Security, medical, emergency & fire protection plans
- B307120042 Ruleases public version of rev to emergency plan implementing procedures.
  FELTON, J. M. Division of Rules and Records. 83/04/24. Document Management Branch. 1p. 19439: 233. 24X Fiche: 50-382, 83/06/24,
- --B307120046 Forwards public version of revised emergency plan implementing procedures, including Procedure EP-2.110 re man-caused emergencies, EP-2-120 re natural emergencies & EP-2-140 re reentry, BRUMMOND, F. J. Louisiana Power & Light Co. 83/06/01. Office of Nuclear Reactor Regulation, Director, 2pp. 17439:234, 24X Fiche: 50-382, 83/06/24, 8307120042.
- --8307120048 Public version of revised emergancy plan implementing procedures, including Procedure EP-2-110 re man-caused emergencies, EP-2-120 re natural emergencies & EP-2-140 re Pagnery.

  BARKHURST, R. P. , BAILEY, C. P. Louisiana Power & Light Co. 83/05/17, 104pp. 19439: 236. 24X Fiche: 50-382, 83/06/24, 8307120042.

- 8307140134 Responds to util 820106.11 & 28 ltrs re primary & backup emergency operations facility. Facility location acceptable. Approval of other features of facilities will be determined during post-implementation appraisal. EISENHUT. D. 9. Division of Licensing. 83/06/24. MAURIN. L. V. Louisiana Power & Light Co. 2pp. 19540:029. 24X Fiche: 50-382,83/06/24,8307140134.
- B307150408 Requests clarification re util B30311 evaluation of effect of Dec 1982 Union Carbide plant explosion on facility. Add1 emergency planning info needed to complete OL review. Response requested within 30 days. EISENHUT. D. 9. Division of Licensing. B3/O6/27. MAURIN, L. V. Lowisiana Power & Light Co. 3pp. 19540:143. 24X Fiche: 50-382, 83/06/27, 8307150408.
- B307110055 Submits updated schedule for completion of responses to NUREQ-0737 Suppl I on emergency response capability re safety parameter display sys. Update based on reevaluation of fuel load schedule.

  DRUMMOND.F.J. Louisiana Power & Light Co. 83/07/05. KNIGHTON, C.W. Licensing Branch 3. 2pp. 19375: 243. 24X Fiche: 50-382,83/07/05,8307110055.
- 8307080442 Forwards response to Reg Guide 1.97.Rev 2 "Instrumentation for Light-Water Cooled Nuclear Power Plants to Assess Plant & Environs During & Following Accident," per NURE9-0737, Suppl 1 re emergency response capability ORUMMOND.F.J. Louisiana Power & Light Co. 83/07/06. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 47pp. 19347:158. 24X Fiche: 50-382,83/07/06.8307080442.

#### G. Adjudicatory correspondence

- B307030077 Decision ALAB-732 affirming ASLB B21103 Partial Initial Decision LBP-82-100 as modified by LBP-82-112 If synergism occurs; enhancement effect nonexistent. BHOEMAKER.C.J. Atomic Safety and LIcensing Appeal Panel. B3/06/29. 69pp. 19193:088. 24X Fiche: 50-382, 83/06/29, 8307050077.
- 8307050128 Advises that notice of appearance should be filed & Commission rules of practice federal rules of civil procedure & NRC case law should be reviewed for guidance on reopening Contention 22.

  MOLFE S. J. Atomic Safety and Licensing Board Panel. 83/06/30. BURSTEIN.C.H. Affiliation Unknown. Ip. 19220: 212. 24X Fiche: 50-382, 83/06/30, 8307050128.
- B307070206 Order correcting errata in ASLB Partial Initial Decision LBP-83-27. WOLFE, B. J. Atomic Safety and Licensing Board Panel. 83/07/05. lp. 19269:314. 24X Fiche:50-382:83/07/05,8307070206.
- 8307080494 Notice of ASLAB reconstitution. CN Kohl, chairman & WR Johnson & HA Wilber, members.

  SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/07/06.

  1p. 17346: 337, 24% Fiche: 50-382, 83/07/06, 8307080494.
- B307150342 Forwards SER Suppl 5.NUREG-0787. W/o encl. TURK.S.E. Hearing Branch 1. B3/07/12. KOHL.C.N., JOHNSON.W.R., WILBER.H.A. Atomic Safety and Licensing Appeal Panel. 1p. 19538:327. 24X Fiche:50-382.83/07/12.8307150342.
- B30719026B Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  BLAKE.E.L. Bhaw, Pittman, Potts & Troubridge. B3/07/13. KOHL.C.N., JOHNSON.W.R., WILBER.H.A. Atomic Safety and Licensing Appeal Panel. 1p. 19628; 259. 24X Fiche: 50-382,83/07/13,830719026B.
- --8307190271 Notifies of employment at law firm. VR Harding will not participate in any case pending before NRC. Svc list encl. HARDING. V. R. Shaw. Pittman. Potts & Troubridge. 83/07/13. KOHL. C. N., JOHNSON, W. R., WILBER, H. A. Atomic Safety and Licensing Appeal Panel. 3pp. 19628: 260. 24X Fiche: 50-382, 83/07/13. 8307190268.
- 8307180145 Motion to associate author as co-counsel w/L Fontana for intervenors.
  BURSTEIN, C. H. Joint Intervenors-Waterford. BURSTEIN, C. H. Burstein.
  C. H. 83/07/15, Atomic Safety and Licensing Board Panel. 1p.
  19556: 217. 24X Fiche: 50-382, 83/07/15, 8307180145.
- --8307180153 Motion to reopen Contention 22 in light of newly discovered evidence. BURSTEIN.C.H. Joint Intervenors-Waterford. BURSTEIN.C.H. Burstein, C.H. 83/07/15. Atomic Safety and Licensing Board Panel. ip. 19556:218. 24X Fiche: 50-382,83/07/15,8307180145.

- --B307180160 Memorandum in support of motion to reopen Contention 22 re available info on slab cracks initially reported in 1977, reappearing on B30511 New hearing requested to re-review deficiencies in plant design.
  BURSTEIN.C. H. Joint Intervenors-Waterford. BURSTEIN.C H.
  Burstein, C. H. 83/07/15. Atomic Safety and Licensing Board Panel. 5pp. 19356: 219. 24X Fiche: 50-382,83/07/15.8307180145.
- 8307200120 Order rejecting, w/o prejudice, Joint Intervenors motion to reopen contention. Joint Intervenors may resubmit motion in proper form showing svc on all parties.

  SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/07/18. Joint Intervenors-Naterford. 3pp. 19647:069. 24X

  Fiche: 50-382, 83/07/18, 8307200120.
- 8307290032 Notice of appearance in proceeding. BURSTEIN.C.H. Joint Intervenors-Waterford. BURSTEIN.C.H. Burstein. C.H. 83/07/22. 1p. 19821:013. 24X Fiche:50-382.83/07/22. 8307290052.
- --8307290056 Motion to reopen Contention 22 in light of newly discovered evidence. BURSTEIN,C.H. Joint Intervenors-Waterford. BURSTEIN,C.H. Burstein, C.H. 83/07/22. Atomic Safety and Licensing Appeal Panel. 1p. 19821;014. 24X Fiche: 50-382,83/07/22,8307290052.
- ~~8307290067 Memorandum supporting motion to reopen Contention 22 recracks in plant foundation. Plant is sui generis. Safety implications re plant built w/o pilings on tracked slab unknown. Certificate of Svc encl.

  BURSTEIN.C.H. Joint Intervenors-Materford. BURSTEIN,C. H.
  Burstein.C. K. 83/07/22. Atomic Safety and Licensing Appeal Panel. 9pp. 19821:015. 24X Fiche: 50-382,83/07/22,8307290052.
- 8307290077 Order to show cause by 830808 why Joint Intervenors should not be found in default. Exceptions dismissed since A9LAB has not received Joint Intervenors brief on exceptions which was to be deposited in mail by 830711.
  SHOEMAKER.C.J. Atomic Safety and Liconsing Appeal Panel. 83/07/27.
  Joint Intervenors-Waterford. 2pp. 19822:175. 24X
  Fiche: 50-382.83/07/27.8307270077.

#### K. Utility Final Safety Analysis Report (FSAR) & amends

- 8307010119 Amend 32 to FSAR.W/830630 ltr. CAVANAUSH.W. Louisiana Power & Light Co. B3/06/30. Office of Nuclear Reactor Regulation, Director. 980pp. 19182:279. 24x Fiche:50-382.83/06/30.B307010119.
- 8307070045 Certifies syc of Amend 32 to FSAR on 830701.

  BANDING: Louisiana Power & Light Co. 63/07/01. 1p. 19293:254.
  24X Fiche: 50-382,83/07/01,8307070045.
- Q. Inspection reports, IE Bulleting & correspondence
- 8307120440 Forwards IE Insp Rept 50-382/83-10 on 830228-0303 No noncompliance noted. MADSEN/G.L. Region 4. Office of Director. 83/05/23. MAURIN.L.V. Louisiana Power & Light Co. 2pp. 19425:278. 24X Fiche:50-382,83/05/23,8307120440.
- --8307120447 IE Insp Rept 50-382/83-10 on 830228-0303. No noncompliance noted Major areas inspected preoperational insp of licensee chemistry/radiochemistry program, including organization, staffing & staff qualifications & training program.
  NICHQLAS.J.B., WISE.R., MURRAY.B. Region 4, Office of Director.
  83/05/11. 50pp. 19425:280. 24X Fiche:50-382,83/05/23,8307120440
- B307120425 Forwards IE Insp Rept 50-382/83-19 on B30428-30. No noncompliance noted.

  MADSEM.G.L. Region 4. Office of Director. 83/06/06. MAURIN, L. V. Louisiana Power & Light Co. 2pp. 19425: 226. 24x

  Fiche: 50-382, 83/06/06, 8307120425.
- --8307120430 IE Insp Rept 50-382/83-19 on 830428-30. No noncompliance noted Major areas inspected review & witnessing of containment integrated leakage rate test. TAPIA, J. I., HUNNICUIT, D. M., CROSSMAN, N. A. Region 4, Office of Director. 83/06/03. 3pp. 19425:228. 24X Fiche:50-382,83/06/06,8307120425.
- 8307040241 Ack receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/82-09.

  MADSEN/G.C. Region 4. Office of Director. 83/06/30. MAURIN, t. v. Lovisiana Power & Light Co. ip. 19239:316. 24X

  Fiche: 30-382/83/06/30. 8307060241.

- --8307060246 Responds to NRC 830504 ltr re violations nuted in IE Insp. Rept 50-382/82-09. Corrective actions: record search conducted to establish number of instruments affected by calibr by unqualified technician.

  DRUMMOND.F. J. Louisiana Power & Light Co. 83/06/06. MADSEN.G. L. Region 4. Office of Director. 3pp. 19239: 317. 24X
  Fiche: 50-382, 83/06/30, 8307060241.
- B307130281 Forwards IE Insp Rept 50-382/83-18 on B30501-31 & notice of violation.

  MADSEN, G.L. Region 4. Office of Director. B3/06/30. MAURIN, L. V. Louisiana Power & Light Co. 2pp. 19531:108. 24X
  Fiche: 30-382, 83/06/30, 8307150281.
- --8307190283 Notice of violation from insp on 830501-31.

  \* Region 4. Office of Director. 83/06/30. Ip. 19531:110. 24X
  Fishe: 50-382,83/06/30,8307150281.
- --8307150284 IE Insp Rept 50-382/83-18 on 830501-31 Noncompliance noted: failure to follow component cooling water, flow belance & pump performance procedures during startup testing.
  CONSTABLE, G. L., FLIPPO, T. A., CRUSSMAN, M. A. Region 4, Office of Director. B3/06/29. 6pp. 19531:111. 24X Fiche: 50-382, 83/06/30, 8307150281.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrado Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830603). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York. Inc. 141pp. 19563: 153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Qaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103), 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307280363 Notifies that due to unanticipated difficulties in rept preparation, preservice insp program will not be submitted by 830701.per 830404 commitment Preservice insp program requests for relief enci.

  DRUMHOND, F. J. Louisiana Power & Light Co. 83/07/25. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 146pp. 19796: 121. 24X Fiche: 50-382, 83/07/25, 8307280363.
- S. Reportable occurrences. LERs & related correspondence
- 8307050021 Interim rept of Significant Const Deficiency 32 re failure to perform stress analysis for welded pipe support attachments prior to fabrication. Corrective action complete & documentation under review. Final rept expected by 830831. DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/23. COLLINS, J. T. Region 4. Office of Director. 1p. 19193: 338. 24% Fiche: 50-382,83/06/23,8307050021.
- 8307050170 Final Significant Const Deficiency Rept 34 re tube steel laminations. All tube steel w/HT 16600 replaced w/acceptable matl & returned to Ebasco warehouse, per Nonconformance Rept W3-3304.

  BRUMMOND, F. J. Louisiana Power & Light Co. B3/06/23. COLLINS, J. T. Region 4. Office of Director. 2pp. 19199: 001. 24X Fiche: 50-382, 83/06/23, 8307050170.
- B307050204 Seventh interim rept re Significant Const Deficiency 55, "Holdup & Boric Acid Makeup Tank Incorrect Structural Calculations." Corrective action rescheduled for completion by 830715 Final rept will be submitted by 830805. DRUMMOND, F. J. Louisiana Power & Light Co. B3/06/23. COLLINS, J. T. Region 4, Office of Director. ip. 19199: 204. 24X Fiche: 50-382, 83/06/23, 8307050204.
- 8307120202 Seventh interim Significant Const Deficiency Rept 33 rechilled water piping supports. Corrective action, including DCN-MP-459, complete. Supporting documentation under review. Final rept will be submitted by 830729. DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/29. COLLINS, J. T. Region 4. Office of Director. [p. 19423:313, 24x Fiche: 50-382, 83/06/29. 8307120202.
- 8307120516 Third interim rept on Significant Const Deficiency &6 re GE-Type AKR breakers w/C-clips which may fall off Required matti received & corrective action to be completed by 830715. Final rept by 830805. DRUMMOND.F. J. Louisiana Power & Light Co. 83/06/29. COLLINS.J.T. Region 4. Defice of Director. 1p. 19433:084. 24x Fiche: 50-382, 83/06/29, 8307120516.

- 8307150289 Third Interim Const Deficiency Rept 77 re inadequate closure time & flow rate for containment purge valves. Corrective action completed Final rept will be submitted by 830729. DRUMKDN.F. J. Louisiana Power & Light Co. 83/07/05. COLLINS, J. T. Region 4, Office of Director. 1p. 19532:176. 24% Fiche: 50-382,83/07/05.8307150289.
- 8307150339 Fourth Significant Deficiency Rept 57 re inadequate instrumentation & control installation & turnover documentation. Initially reported on 830405. Corrective action complete.Review underway. Final rept by 830729.
  BRUMMOND,F. J. Louisiana Power & Light Co. 83/07/05. COLLINS, J. T. Region 4, Office of Director. 1p. 19538:333. 24X Fiche: 50-382,83/07/05.8307150339.
- 8307150388 Third interim Const Deficiency Rept 72 re radiation munitoring sys RM-23 control modules. Util awaiting receipt of six control modules shipped by vendor on 830617. Corrective action & final rept delayed until 830728. DRUMMOND,F. J. Louisiana Power & Light Co. 83/07/05. COLLINS, J. Y. Region 4, Office of Director. ip. 19839:149. 24X Fiche: 50-382,83/07/05,8307150389.
- 8307150261 Fourth interim rept re Significant Const Deficiency 29, concerning inadequate clearance between process piping sys & box-type pipe supports/restraints. Initially reported on 821015. Corrective actions completed. Final rept by 830831. DRUMMOND, F. J. Louisiana Power & Light Co. 83/07/11. COLLINS, J. T. Region 4. Diffice of Director. 1p. 19538:075. 24X Fiche: 50-382,83/07/11. 8307150261.
- B307260356 Second interim Bignificant Const Deficiency Rept 76 re damage to pressurizer heaters during hot functional testing. Thirty pressurizer heaters scheduled for replacement by B30815. Final rept will be submitted by B30915. DRUMMOND,F.J. Louisiana Power & Light Co. B3/07/13. COLLINS, J. T. Region 4, Office of Director. 1p. 19733:030. 24X Fiche: 50-382, B3/07/13, B307260356.
- 8307260114 Second rept on Significant Const Deficiency 81 re shelf life exceeded on cable splice & termination tape. Completion of corrective action delayed due to testing of volt terminations. Final rept will be provided by 830830.

  DRUMMOND.F. J. Laufsians Fower & Light Co. 83/07/15. COLLINS, J. T. Region 4, Office of Director. ip. 19727:292. 24X Fiche: 50-382,83/07/15.8307260114.
- 8307260126 Rept on Significant Const Deficiency 42 R-1 re HMA auxiliary relays. Completion of corrective action delayed due to testing. Three remaining coils will be installed during outage. Final rept will be provided by 830923.

  DRUMMOND, F. J. Louisiana Power & Light Co. 83/07/15. COLLINS, J. T. Region 4, Office of Director. 1p. 19727:290. 24X

  Fiche: 50-382, 83/07/15, 8307260126.
- B307260392 Fourth interim rept of Significant Const Deficiency 60 re turnover documentation & inadequate hanger weld problems T-B. Completion of corrective action & documentation review scheduled for B30B17. Final rept by B30916.
  DRUMMDND.F. J. Louisiana Power & Light Co. B3/07/15. COLLINS. J. T. Region 4. Office of Director. 1p. 19733:124. 24X Fiche: 50-382.83/07/15.8307260392.
- 8307290104 Seventh interim significant Deficiency Rept 35 re matl properties of tube track & welding fittings. Final rept will be delayed from 330720 to 830825. Util review expected to be completed by 830729.

  DRUMMOND, F. J. Louisiana Power & Light Co. 83/07/19. COLLINS, J. T. Region 4. Office of Director. 1p. 19820:332. 24X

  Fiche: 50-382, 83/07/19, 8307290104.
- V. Operator Examinations
- 8307260422 Forwards util 830411 itr to NRR providing estimated schedule & number of operator license & instructor certification exams necessary between present & Dec 1985 per Generic Ltr 83-01.
  MAURIN,L.V. Louisiana Power & Light Co. 83/04/21. CGLLINS.J.T. Region 4. Diffice of Director. 1p. 19733:171. 24X Fiche: 50-382,83/04/21,8307260422.

- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8307190173 Forwards evaluation rept of radiological emergency exercise conducted on 830323. Deficiencies cited in four areas that will require schedule of corrective actions. Extension until end of June to furnish schedule granted RRIMM.R.W. Federal Emergency Management Agency. 83/06/13. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 17634:172. 24X Fiche: 50-387, 83/06/13, 8307190173
- --B307190177 Evaluation of PArColumbia & Luzerne Counties & participating municipalities emorgency preparedness plan for Susquehanna Steam Electric Station.

  \* Federal Emergency Management Agency. 83/03/23. 66pp. 19634:175. 24X Fiche: 50-387,83/06/13,8307190172.
- 8307010055 Application to amend License NPF-14, consisting of Proposed Amend 25 to revise physical security plan to include Changes N.O. & P. & Changes A & B to security training & qualification plan. Change P withheld (ref 100FR73.21). CURTIS, N.W. Pennsylvania Power & Light Co. 83/06/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19168:152. 24X Fiche: 50-387, 83/06/27, 8307010055.
- 8307260076 Advises that rept on Reg Guide 1.97 expected by May 1984, per NRC request re response to Generic Ltr 82-33. Schedule for submittal of safety parameter display sys safety analysis remains 830930 due to resource limitations. CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/22. SCHWENCER.A. Litensing Granch 2. 1p. 19727:262. 24X Fiche: 50-387, 83/07/22. 8307260076.

#### H. General correspondence

- 8307220161 Requests that all nuclear plants be closely supervised, based on listed reasons. Knowledge about nuclear power insufficient to permit continued plant operation. MODD. 8. Affiliation Unknown. 83/07/14. DENTON. H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19684:079. 24X Fiche: 50-387.83/07/14.8307220161.
- P. Operating license stage documents & correspondence
- 8208060366 Board Notification 82-70: notifies of differing prof opinion resensitization of BWR stainless steel weldments.
  EIBENNUT, D. 9. Division of Licensing. 82/07/20. FALLADING, N. J. Commissioners. 4pp. 17043:001. 24X Ficha: 50-000, 82/07/20, 8208060366.
- --8302040362 Forwards request for add1 info re reactor internals matls: JOHNSTON.W.V. Assistant Director for Matls & Qualif. Engineering (Pre 830201), 82/03/14, TEDESCO.R.L. Assistant Director for Licensing, 2pp. 17043:089, 24X Fiche:30-000,82/07/20,8208060366.
- 8307010035 Application to amend License NPF-14, consisting of Proposed Amend 25 to revise physical security plan to include Changes N.O. & P. & Changes A. & B. to security training & qualification plan. Change P. withheld (ref. 100FR73.21).
  CURTIS.N.W. Pennsylvania Power & Light Co. 83/06/27. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19168: 152. 24X Fiche: 50-387, 83/06/27, 8307010035.
- 8307080471 Requests licensee provide conservative estimate of thermal load vital equipment due to delayed ignition of flammable gas plume resulting from rupture of proposed Transco 42-inch diameter pipeline.

  SCHWENCER,A. Licensing Branch 2. 83/04/28. CURTIS,N.W. Pennsylvania Power & Light Co. 2pp. 19345:049. 24X
  Fiche: 50-387, 83/04/28, 8307080471.
- 8306270395 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Gulf, LaSalle & Susquehanna re TMI Task Action Plan Item I.G. i. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list encl. EISENNUT, D. G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000.83/06/29. 8306270395.
- 8307070058 Summary of 830617 meeting w/util in Allentown PA re ECCS actuation instrumentation & implementation of applicable Tech Specs.List of attendess encl. PERCH, R.L. Licensing Branch 2. 83/06/29. Licensing Branch 2. 3pp. 19366:300. 24X Fiche:50-387,83/06/29,8307090058.
- --8307090061 Tech Specs re ECCS actuation instrumentation.

  \* Pennsylvania Power & Light Co. 83/06/29. 7pp. 19366:303. 24X
  Fiche: 50-387.83/06/29,8307090058.

- B307180008 Informs that separate independent design verification program not required on Unit 2 since design process essentially same as program applied to Unit 1 & incorporates improvements made per lessons learned on Unit 1. EISENHUT.D. 0. Division of Licensing. B3704/29 CURTIS.N. W. Pennsylvania Power & Light Co. 2pp. 19567:356. 24X Fiche: 50-387,83/06/29,8307180008.
- 8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl EISENHUT, D. G. Division of Licensing, 83/07/05. Consolidated Edison Co of New York, Inc. 16pp. 19390-317, 24X Fichs: 50-000/83/07/05/8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT. D. 0. Division of Licensing 83/07/06. Consolidated Edison Co. of New York, Inc. 18pp. 19669:254. 24X Fiche: 50-000.83/07/06.8307060329.
- 8307190494 Submits list of outstanding proposed changes to License NPF-14 to be held in abeyance until requested info or clarification provided.

  SCHMENCER: A. Licensing Branch 2. 83/07/06. CURTIS:N W. Pennsylvania Power & Light Co. 3pp. 19651:358. 24X
  Fiche: 50-387:83/07/06:8307190494.
- 8307110431 Advises that review conducted to identify power sources or sensors providing power or signals to two or more control sys, per License Condition 2. C. 25(a). No failures found which would result in consequences outside Chapter 15 analyses. CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/07. SCHWENCER, A Licensing Branch 2. 2pp. 19382:248. 24x Fiche: 50-387,83/07/07. 8307110431.
- 8307110439 Submits info re automatic depressuritation systimer setting & justification for setting. In response to NRC 830425 ltr on TMI Item II. K. 3. 18.
  CURTIS, N. W. Pennsylvania Power & Light Co. 83/07/07. SCHWENCER, A Licensing Branch 2. 3pp. 19382:235. 24X Fiche: 50-387, 83/07/07.
  8307110439.
- B3071i0466 Responds to B3062B itr relassessment bloomsequences of immediate or delayed gas cloud ignition resulting from rupture of Transco pipeline. Heat flux does not pose safety concern.

  CURTIS.N.W. Pennsylvania Power & Light Co. B3/07/07. SCHWENCER.A. Licensing Branch 2. 2pp. 19380:089. 24X Fiche: 50-387.B3/07/07, B307110466.
- 8307080149 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 8307190440 Informs that processing & issuance costs for CL exceeded max fee. No add1 fee required.
  MILLER, W. D. License Fee Management Branch. B3/07/08. CURTIS, N. W. Pennsylvania Power & Light Co. 1p. 19656:076. 24X
  Fiche: 50-387.83/07/08.8307190440.
- --B307190444 Forwards summary of review costs for processing & issuing OL.No add1 fee required for costs exceeding max fee paid. W/o encl.
  HOLLOWAY.C.J. License Fee Management Branch. 83/07/08. License fee Management Branch. ip. 17656: 077. 24X Fiche: 90-387.83/07/08. 83/07/08.
- 8307270478 Forwards notices of consideration of issuance of amends to License NPF-14 & proposed NSHC determination & opportunity for hearing re 830203,0415 & 27 submittals on alignment of particulate & gaseous radioactivity monitors.

  BCHWENCER. A. Licensing Branch 2. 83/07/18. CURTIS.N.W. Pennsylvania Power & Light Co. 2pp. 19788:336. 24X
  Fiche: 50-387.83/07/18.8307270478.
- --8307180369 Notice of consideration of issuance of amend to License NPF-14 re particulate & gaseous radioactivity monitors & proposed NSMC determination & apportunity for hearing. SCHMENCER.A. Licensing Branch 2. 83/07/01. 6pp. 19788:338. 24x Fiche:50-387.83/07/18.8307270478.
- ~~8307200050 Notice of consideration of issuance of amend to License NPF-14 & proposed NSHC determination & apportunity for hearing.

  8CHWENCER,A. Licensing Branch 2. 83/07/01. App. 19788: 344. 24x Fiche: 50-387, 83/07/18, 8307270478.

- --83071803B1 Notice of consideration of issuance of amend to License NPF-14 re safety parameter display sys & proposed NSHC determination & opportunity for hearing. SCHMENCER.A. Licensing Branch 2. 83/07/01 6pp 19788:350. 24X Fiche.50-387.83/07/18.830727047B.
- 8307260336 Forwards application for Amend 27 to License NPF-14, requesting relief from Tech Spec Tables 2.2.1-1 & 3.3.2-2 to increase main steam line radiation high trip setpoint of 3 times normal background.

  CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/22. SCHWENCER.A. Licensing Branch 2. 3pp. 19726:002. 24X Fiche: 50-387, 83/07/22, 8307260336.
- --8307260339 Application for Amend 27 to License NPF-14, requesting relief from Tech Spec Tables 2.2.1-1 & 3.3.2-2 to increase main steam line radiation high trip setpoint of 3 times normal background.

  CURTIS: N.W. Pennsylvania Power & Light Co. 83/07/22. 10. normal packground. CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/22. ip. 19726:005. 24% Fiche:50-387,83/07/22:8307260336.
- --8307260342 Proposed Tech Spec Tables 2.2.1-1 & 3.3.2-2 increasing main steam line radiation high trip setpoint. Table re offsite doses encl.
  - doses enc].

    \* Pennsylvania Power & Light Co. 83/07/22. 3pp. 19726:006. 24X
    Fiche:50-387,83/07/22,8307260336.

# G. Inspection reports, IE Bulletins & correspondence

- 6307010018 Ack receipt of 630617 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-11 & 50-388/83-04.
  STAROSTECKI.R. Division of Project & Resident Programs. 83/06/28.
  KENYON, B. D. Pennsylvania Power & Light Co. ip. 19169:103. 24x
  Fiche: 50-387.83/06/28.8307010018.
- --8307010023 Responds to NRC 830516 ltr re violations noted in 1E Insp Repts 50-387/83-11 & 30-388/83-04 Corrective actions: review of Panels 2C661 BR & 83 & 2C612 will be performed to ensure that lifted leads & fuses are properly controlled. KENYON.B.D. Pennsylvania Power & Light Co. 83/06/72. STAROBTECKI.R. Division of Project & Resident Programs. 3pp. 19169:104. 24X Fiche: 50-387,83/06/28,8307010018.
- 8307050084 Forwards Rev O to PPL-01-0207, "Inservice Insp Program," including applicable ASME Section XI relief requests & preliminary boundary classification drawings. CURTIS.N.M. Pennsylvania Power & Light Co. 83/06/30. SCHWENCER, A. Licensing Branch 2. lp. 19221:064. 24X Fiche 50-387,83/06/30, 8307050084.
- ---8307050094 Rev O to PPL-01-0207 "Inservice Insp Program." W/28 oversize drawings. Aperture cards are available in FDR. BEAULIEU.R.A., WHITEWAY,B.J., CLAUSS,J.M. NUTECH Engineers, Inc. B3/06/23. 54pp. 19221:065. 24X Fiche:50-387,83/06/30,8307050084.
- 8307080368 Forwards Rev 2 to inservice insp program for pumps & valves. Rev resolves comments generated from recent meeting w/NRC & includes valves required by IE Bulletin 83-03. CWRIGS.N.W. Pennsylvania Power & Light Co. 83/06/30. SCHWENCER.A. Licensing Branch 2. 1p. 19350:190. 24X Fiche: 50-387,83/06/30,8307080368.
- --8307080371 Rev 2 to inservice insp program for pumps 4 valves. \* Pennsylvania Power & Light Co. 83/06/30. 112pp. 19350:191. 24% Fiche: 50-387,83/06/30.8307080368.
- 8307120456 Act receipt of 830524 & 0622 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-02.

  KARTIN.T. Division of Engineering & Technical Programs. 83/07/01. KENYON.B.D. Pennsylvania Power & Light Co. tp. 19425:055. 24X Fiche: 50-387, 83/07/01, 8307120436.
- --8307120464 Responds to NRC 830520 ltr re violations noted in IE Insp. Rept 50-387/83-02 Corrective actions:review of specific procedures for effluent analyses cited in violations will be performed Reg Guide 1.32, Rev 2 does not apply. KENYON, B. D. Pennsylvania Power & Light Co. 83/05/24. MARTIN, T. T. Division of Engineering & Technical Programs. 3pp. 19425:056. 24X Fiche:50-387,83/07/01.8307120456.
- --B307120472 Supplements B3032B & 0524 responses to violations noted in IE Insp Rept 50-3B7/B3-02 Vendor procedures for performing gross alpha.tritium.iron & strontium analyses of effluent samples will be reviewed & approved.

  KENYON.B.D. Pennsylvania Power & Light Co. B3/06/22. MARTIN.T.T. Division of Engineering & Technical Programs. 1p. 19425:059.

  24X Fiche: 00-3B7, 83/07/01, B307120456.

- 8307150307 Forwards IE Insp Repts 50~387/83~15 & 50~388/83~07 on 830408-27. No noncompliance noted.
  STAROBTECKI, R. Division of Project & Resident Programs. 83/07/01. KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 19532; 312. 24% Fiche: 50~387, 83/07/01, 8307150307.
- --8307150313 IE Insp Repts 50-387/83-15 & 50-388/83-07 on 830608-27. No noncompliance noted. Major areas inspected preoperational test review, operational verification, maint observation, surveillance observation & preoperational test witnessing. RHDADS, G., MCCANN, J., NICHOLAS, M. Region 1, Dffice of Director, 83/06/30. 14pp. 19532:314. 24X Fiche:50-387,83/07/01.8307150307.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.

  JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 134pp. 17563: 273. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche:50-000,83/07/12,8306270404.
- 8307280332 Forwards IE Insp Repts 50-387/83-12 % 50-388/83-06 on 830504-0607 & notice of violation.

  STAROSTECKI,R. Division of Project & Resident Programs. 83/0:
  KENYON,B.D. Pennsylvania Power & Light Co. 2pp. 19790:061.

  Fiche: 50-387,83/07/12,8307280332.
- --8307280335 Notice of violation from insp on 830504-0607. \* Region i, Office of Director. 83/07/12. 3pp. 19790:063. 24X Fiche:50-387.83/07/12.8307280332.
- --8307280349 IE Insp Repts 50-387/83-12 & 50-388/83-06 on 830504-0607. Noncompliance noted: intermittent breaches of secondary containment, field change not implemented & use of unapproved handbook for acceptance of pipe supports. RHOADS.C., MACANN, J. Region i, Office of Director. MCCABE.E. C. Division of Project & Resident Programs. B3/06/13. 28pp. 19790: 066. 24X Fiche: 50-387,83/07/12,8307280332.
- 8307280336 Forwards IE Insp Repts 50~387/83-14 on 830608-15 & notice of violation. STARDSTECKI,R. Division of Project & Resident Programs. 83/4 KENYON, G.D. Pennsylvania Power & Light Co. 2pp. 19790:104. Fiche: 50-387, 83/07/12, 8307280336.
- --B307280340 Notice of violation from insp on B3060B-15. \* Region 1, Office of Director. 83/07/12 ip. 19790:106. 24X Fiche: 50-387, 83/07/12, 8307280336.
- -8307280346 IE Insp Rept 50-387/83-14 on 830408-15 Noncompliance noted: operating with mode switch in run position while high reactor vessel water level trip to main turbine bypassed. RHOADS.C. G., MCCABE.E.C. Division of Project & Resident Programs. 83/07/12, 4pp. 19790:107 24X Fishe:50-387,83/07/12,8307280336.
- 8306270406 IE Info Notice 83-48; "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR: J.M. Division of OA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8304270406.
- R. Periodic operating reports & related correspondence
- 8307220176 Monthly operating rept for May 1983 W/830615 ltr. KUCZYNSKI.L.A., KENYON, B. D. Pennsylvania Power & Light Co. 93/06/09. BEEDE.M.R. Management Information Branch. 5pp. 19684:026. 24x Fiche: 50-387, 83/06/09, 8307220176.
- 8. Reportable occurrences, LERs & related correspondence
- 8307010069 LER 83-075/01P-0: on 830515, interactions of chlorine detector in control room emergency autiside air supply sys noted following loss of power. Procedure changes instituted to provide operators w/appropriate corrective actions. KEISER.H.M. Pennsylvania Power & Light Co. 83/05/16. ALLAN, J. M. Region 1, Office of Director. 1p. 19124:337. 24X Fiche: 50-387, 83/05/16, 8307010069.
- 8307010099 Interim deficiency rept re defective GE HMA auxiliary relays. Insp program completion awaiting receipt of GE recommended corrective actions. Final rept scheduled for 830901. CURTIS N. W. CURTIS.N.W. Pennsylvania Power & Light Co. 83/06/09. ALLAN, J. M. Region 1. Office of Director. 2pp. 19168:155. 24X
  Fiche:50-387,83/06/09,8307010099.

- 8307010054 LER 83-083/03L-0: an 830520, during review of draft procedures; alarm check required by Tech Spec not included in chemistry surveillance procedures. Change made to surveillance procedures to include alarm check. W/830617 ltr. KUCZYNBKILL A., KEISER H. W. Pennsylvania Power & Light Co. 83/06/17. ALLAN, J.M. Region 1. Office of Director. 2pp. 19168: 333. 24X Fiche: 50-387,83/06/17,8307010054.
- 8307010031 LER 83-082/017-0: on 830607, main turbine trip on high reactor pressure vessel level bypassed to clear interlock. After outage, bypass discovered still installed. Caused by lack of clear requirement far bypass review. W/830621 ltr. MUCZYNBKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co. 83/06/21. ALLAN, J. M. Region 1. Defice of Director. 4pp. 19169: 196. 24X Fiche: 50-387, 83/06/21, 8307010031.
- 8307120443 LER 83-084/03L-0 on 830524, during surveillance testing, control room emergency outside air supply sys fan tripped. Caused by out of tolerance of time delay relay for heater differential temp. Relay resot. W/830623 ltr. PIEMONTESE, A. P., KEISER, H. W. Pennsylvania Power & Light Co. 83/06/23. ALLAN, J. M. Region i. Office of Director. 2pp. 19425: 335. 24X Fiche: 50-387, 83/06/23, 8307120443.
- 8307120296 LER 83-085/03L~0: an 830525, containment isolation valve for containment atmosphere control sample line failed to close. Cause not stated Maint personnel verified switch positioning & reconnected circuitry. W/830624 ltr.
  PIEMONTESE.A.P., KEISER.H.W. Pennsylvania Power & Light Co. 83/06/24. ALLAN.J.M. Region I. Office of Director. 2pp. 19419:338. 24X Fiche: 50-387,83/06/24,8307120256.
- 8307120273 LER 83-087/03L-0: on 830527, "A" Containment H2/02 analysers found to have erratic readings. Caused by pressure control valve & sample pump degradation to point where proper flow not maintained. Failed components replaced. W/830624 ltr. TODD, J. J. KEISER, H. W. Pennsylvania Power & Light Co. 83/06/24. ALLAN, J. M. Region 1. Office of Director. 3pp. 19424: 182. 24X Fiche: 50-387, 83/06/24, 8307120273.
- B307120442 LER 83-086/03L-0: on 830925, reactor bldg door opened while maint performed on turbine bldg side of air lock to reactor bldg. Caused by personnel error. Individual w/radio communication will be posted. W/B30624 ltr. PIEMONTESEA. P., KEISER. H. W. Pennsylvania Power & Light Co. 83/06/24. ALLAN, J. M. Region 1. Office of Director. 2pp. 19425: 234. 24% Fiche: 50-387, 83/06/24, 8307120442.
- B307010079 PNB-I-B3-069: on B30624, high reactor water level scram resulted from loss of offsite power. Caused by extensive damage to primary & secondary windings of startup transformer C phase. Evaluation underway.
  RHOADES G. MCCABE, E. Region 1. Office of Director. B3/06/27. 1p. 19169: 217. 24X Fiche: 50-387, 83/06/27, 8307010079.
- B307120436 LER B3-08B/03L-0: on B30530: RCIC pump discharge valve would not open. Caused by gap between breaker male & female stab clips. Female clips reworked to allow proper contact. W/430649 ltr.
  PIEMONTESS.A.P., KEISER, H. W. Pennsylvania Power & Light Co. B3/06/29. ALLAN.J. M. Region 1. Office of Director. 2pp. 19425: 275. 24X Fiche: 50-387,83/06/29.8307120436.
- 8307060069 RD re failurs of startup transformer Tio. Cause under investigation. Transformer will be disassembled for repair at which time evaluation of failurs will be conducted. Transformer windtomatic tap changer will be installed. KENYON, B.D. Pennsylvania Power & Light Co. 83/06/30. ALLAN, J. M. Region i. Office of Director. 3pp. 19251:001. 24X Fichs: 50-387, 83/06/30, 8307060069.
- 8307120387 Ack receipt of 830609 ltr Revised date of 830701 acceptable for submission of final deficiency rept re GE HMA relags. STAROSTECKI.R. Region i. Office of Director. 83706/30. CURTIS, N. H. Pennsylvania Power & Light Co. lp. 19426:005. 24X Fiche: 50-387, 83706/30. 8307120387.
- 8307110274 PNO-I-83-075: on 830705, reactor tripped from 95% power when MSIV closed. Caused by steam line isolation spike due to increase in condensate demineralizer resin. Water sample sent to Peach Bottom for analysis. RCIC being reevaluated. RHOADS, G., MCCABE, E., Region 1, Office of Director. 83/07/06. 2pp. 19379: 158. 24% Fiche: 50-387, 83/07/06, 8307110274.
- B307180230 LER B3-090/03L-0: on 830606, containment atmosphere hydrogen dioxide analyzer placed in svc from standby condition & exhibited erroneous readings. Analyzers declared inoperable. Caused by calibr gas in lines. Lines purged. W/B30706 ltr. KUCZYNSKI.L. A. KEISER.H.W. Pennsylvania Power & Light Co. 83/07/06. ALLAN.J. M. Region 1. Office of Director. 2pp. 19353: 227. 24X Fiche: 30-387.63/07/06.8307180230.

- 8307180264 LER 83-089703L-0 on 830606.during surveillance testing. Train 8 of standby gas treatment sys tripped shortly after starting. Caused by controls for outside Air makeup damper in closed instead of open position W/830706 ltr. PIEMGNTESEA. P., KEISER, H.W. Pennsylvania Power & Light Co. 83/07/06. ALLAN, J.M. Region 1, Office of Director. 2pp. 19556:018. 24% Fiche. 50-387. 83/07/06. 8307180264.
- 8307220459 LER 83-091/03L-0 on 830609, LPCI loop B of RMR discovered not full LPCI declared inoperable Caused by loose LPCI control disc valve. Tack weld on disc/stem assembly increased W/83070B ltr. RUCZYNSKI,LL.A., KEISER, H.W. Pennsylvania Power & Light Co. 83/07/08. ALLAN, J.M. Region 1, Office of Director. 3pp 19486:113. 24X Fiche: 50-387, 83/07/08, 8307220459
- 8307220312 LER B3-093/01T-0: on 830712, w/containment radiation monitor B out of svc, discovered that surveillance test period exceeded for monitor A. Cause not stated. Monitor A. tested satisfactorily.

  KEISER, H. W. Pennsylvania Power & Light Co. 83/07/12. ALLAN, J.M. Region 1. Office of Director. 1p. 19474:232. 24X Fiche: 50-387, 83/07/12, 8307220312.
- 8307220265 Final deficiency rept re detachment of ILSCO Corp Number 14 stranded wire from screw clamp detectors. Initially reported on 830524. Deficiency not reportable per 10CFR50. 55(e) for Unit 2. Item reportable per Part 2! for Unit 1. CURTISIN W. Pennsylvania Power & Light Co. 83/07/13. MURLEY.T. Region 1. Office of Director. 3pp. 19683:226. 24X Fiche: 50-387, 83/07/13, 8307220265.
- B307220319 LER B3-094/03L-0: on B30617, during cold-startup, average power range munitor flow biased screm trip setpoint less conservative than Tech Specs. Caused by low concentration of renon in core. Setpoint adjusted. W/830714 ltm. KUCZYNSKI,L. A., KEISER, H.W. Pennsylvania Power & Light Co. B3/07/14. ALLAN, J.M. Region 1, Office of Director. 2pp. 19675:095. 24X Fiche: 50-387,83/07/14,8307220319.
- 8307220279 RD: on 630628, review revealed reactor bidg station particulate indine & noble gas monitor out svc for more than 72 h during 820717-21 & 1201-14. Caused by need to work on sample probe & to replace pump.
  KEISER, H. W. Pennsylvania Power & Light Co. 83/07/15. ALLAN, J. M. Region I. Office of Director. 2pp. 19675:361. 24X Fiche: 50-387, 83/07/15, 8307220297.
- 8307220483 Second interim deficiency rept to inadequactes in Bechtel design verification of max circuit lengths of iom voltage power & control cables. Initially reported on 821215. Also reportable under Part 21. Next rept by 831031. CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/15. MURLEY.T. Region 1. Office of Director. 4pp. 17685: 185. 24X Fiche: 50-387. 83/07/15, 8307220483.
- 8307280281 LER 83-093/017-0 on 830711, during review of completion of surveillance tests discovered that 31-day functional test of containment radiation monitor A not performed from 830612-0711. Caused by personnel error M/830720 ltr. KUCZYNBKILL A. KEIEBER H. H. Pannsylvania Power & Light Co. 83/07/20. MURLEY, T.E. Region I. Dffice of Director. Spp. 19791:310. 24X Fiche: 30-387,83/07/20.8307280281.
- 8307280328 Part 23 rept re insufficient clearance on GE 250-volt documented ctrs. Initially reported on 830721. Corrective measures will be determined upon GE thisp completion. Separate rept per 100FR50. 55(a) forthcoming.

  MENYON, B. D. Pennsylvania Power & Light Co. 83/07/25. MURLEY, T. E. Region i. Office of Director. 2pp. 19789: 243. 24X

  Fiche: 50-387. 83/07/25, 8307280328.
- DOCKET 90-388 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 8208060366 Board Notification 82-70: notifies of differing prof opinion re sensitization of BWR stainless steel woldments. EISENHUT, D. G. Division of Licensing 82/07/20. PALLADING, N. J. Commissioners. 4pp. 17043.001. 24X Fiche: 50-000, 82/07/20, 82/8860366.
- 8307050286 Summary of Caseload Forecast Panel 830525-27 site visit & meeting w/util.PA Dept of Environ Resources & Bechtel refuel load date grojection. Applicant projects fuel load date of 840205.Panel projects date of late Second Guarter 1984. PERCH.R.L. Licensing Branch 2. 83/06/22. Licensing Branch 2. 88pp. 19263:136. 24X Fiche:50-388.83/06/22.8307030286.

- 8306270395 Generic Ltr 83-24 to all BWR applicants for UL & holders of GLs for Grand Gulf, LaSaile & Susquehanna re IMI lask Action & Recommendations for BWRs. "Svc list encl. EisEHHUT, D. G. Bivision of Licensing 83/66/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche 50-000, 83/06/29, B306270395.
- B306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENNUT.D. 6 Division of Licensing 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STE. Svc list encl. EISERNUT.D.O. Division of Licensing. 83/07/06. Consolidated Fiche: 50-000, 83/07/06, 83070600329.
- 8307110439 Submits info re automatic depressuritation systimer setting by Justification for setting. In response to NRC 830425 ltr on TMI Item II.K. 3.18.
  CURIIS.M.M. Pennsylvania Power & Light Co. 83/07/07. SCHHENCER, A. Licensing Branch 2. 3pp. 19382: 235. 24X Fiche: 50-387, 83/07/07, 8307110439.
- 8307110466 Responds to 830628 ltr re assessment & consequences of immediate or delayed gas cloud ignition resulting from rupture of Transco pipeline. Heat flux does not pose safety CONTISIN M. Pennsylvania Power & Light Co. 83/07/07. SCHWENCER, A. Licansing Branch 2. 20p. 19380:089. 24X Fiche: 50-387, 83/07/07, 8307110466.
- E NRC Safety Evoluation Report (SER), supply & correspondence
- 8307150180 Commits to correct 42 human engineering discrepancies in control room prior to fuel load, per App F to Suppl 5 to SER. design review submitted, per Generic Ltr 82-33.

  CURIIS, N. N. Fennsylvania Power & Light Co. 83/07/11. SCHWENCER, A Light Co. 83/07/11. SCHWENCER, A 8307130180.
- F. Security, medical, emergency & fire protection plans
- 8307190173 Forwards evaluation rept of radiological emergency exercise conducted on 830323. Deficiencies cited in four areas that will require schedule of corrective actions. Extension until RIMLR R. Federal Emergency Management Agency. 83/06/13. Response (Post 630103). 3pp. 19634:172. 24% fiche:50-387,83/06/13. 8307190173
- --8307190177 Evaluation of PA-Columbia & Luzorne Counties & participating municipalities emergency preparedness plan for Susquehanna Steam Electric Station.

  4 Februal Emergency Management Agency... 83/03/23. 66pp. 19624.175. 24X Fiche: 50-387, 83/06/13, 8307190173.
- B307150180 Commits to correct 42 human engineering discrepancies in control room prior to fuel load, per App F to Suppl 5 to SER. Schedule for secting requirements of detailed control room design requirements of the secting control room CURIIS, N. M. Pennsylvania Power & Light Co. 83/07/11. SCHWENCER, A. Licensing Branch 2. 1p. 19531-050 24x Ftche: 50-308,83/07/11.

- 8307260076 Advises that rept on Reg Guide 1.97 espected by May 1984,per NRC request re response to Generic Ltr 82-33. Schedule for submittal of safety parameter display sys safety analysis remains 830930 due to resource limitations. CURTIS,N.W. Pennsylvania Power & Light Co. 83/07/22. SCHNENCER,A. Licensing Branch 2. 1p. 19727:262. 24X Fiche: 50-387, 83/07/22, 8307260076.
- H. Ganeral correspondence
- 8307220161 Requests that all nuclear plants be closely supervised, based on listed reasons. Knowledge about nuclear power insofficient to permit continued plant uperation. WOOD, B. Affiliation Unknown. B3/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19684:079. 24X Fiche: 50-387, 83/07/14, 8307220161.
- Q. Inspection reports, IE Bulletins & correspondence
- 9307010018 Ack receipt of 830617 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-11 & 50-389/83-04.
  STARGSTECKI, R. Division of Project & Resident Programs. 83/06/28.
  KENYON, B. D. Pennsylvania Power & Light Co. 1p. 19169:103. 24X
  Fithe: 90-387, 83/06/28, 8307010018.
- --8307010023 Responds to NRC 830516 itr re violations noted in IE Insp. Repts 50-387/83-11 & 50-388/83-04. Corrective actions: review of Panels 20661 82 & 83 & 20612 will be performed to ensure that lifted leads & fuses are properly controlled. RENYON, B. D. Pennsylvania Power & Light Co. 83/06/17. STAROSTECKI.R. Division of Project & Resident Programs. 3pp. 19169: 104. 24X Fiche: 50-387,83/06/28,8307010018.
- 8307050084 Forwards Rev O to PPL-01-0207. "Inservice Insp Program," including applicable ASME Section XI relief requests & preliminary boundary classification drawings. CURIIS, N. W. Pennsylvania Power & Light Co. 83/06/30. SCHWENCER, A. Licensing Branch 2. tp. 19221:064. 24X Fiche: 50~387, 83/06/30, 8307050084.
- 8307150307 Forwards IE Insp Repts 50-387/83-15 & 30-388/83-07 on B30608-27. No noncompliance noted. BTAROSTECKI.R. Division of Project & Resident Programs. 83/07/01 KENYON.B.D. Pennsylvania Power & Light Co. 2pp. 19532:312. 24X Fiche: 50-387, 83/07/01, 8307150307.
- --B307150313 IE Insp Repts 50-387/83-15 & 50-388/83-07 on 830608-27. No noncompilance noted Major areas inspected preoperational test review, operational verification, maint observation, surveillance observation & preoperational test uttressing. RHOADS, G., MCCANN. J., NICHOLAS, H. Region in Diffice of Director. 83/06/30. 14pp. 19532:314 24X Fiche:50-387,83/07/01,8307150307.
- 8307210204 Forwards IE Insp Rept 50-388/83-08 on 830617-20. No noncomptiance noted.

  MARTIN, T. T. Division of Engineering & Technical Programs. 83/07/07. KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 19666; 347. 24X Fiche: 50-388, 83/07/07, 8307210204.
- --8307210212 IE Insp Rept 50-388/83-08 on 830617-20. No noncompliance noted Major areas inspected; hydrostatic testing of reactor pressure vessel & associated piping, including tours of containment repueling floor & reactor bldg.
  NICHOLS, H. H., BETTENHAUSEN, L. Region I, Office of Director.
  63/07/05, 7pp. 19666:349, 24X Fiche:50-388,83/07/07,8307210204.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Rectroulation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:273. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN, E. C. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12 Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307280332 Forwards IE Insp Repts 50-387/83-12 & 50-388/83-06 on 830504-0607 & notice of violation.

  STARGSTECKI, R. Division of Project & Resident Programs. 83/07/12 KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 19790: 061. 24x Fiche: 50-387, 83/07/12, 8307280332.
- --8307280335 Nutice of violation from insp on 830504-0607. \* Region 1, Office of Director. 83/07/12. 3pp. 19790:063. 24X Fichs 50-387, 83/07/12, 8307280332.

- --8307280349 IE Insp Repts 30-387/83-12 & 50-388/83-06 on 830504-0607. Noncompliance noted: intermittent breaches of secondary containment field change not implemented & use of unapproved handbook for acceptance of pipe supports. RHADADS G. MACANN. J. Region 1. Office of Director. MCCABE. E. C. Division of Project & Resident Programs. 83/06/13. 28pp. 19790:066. 24X Fiche: 50-387,83/07/12,8307280332.
- 8306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.63/07/14.8306270406.
- R. Periodic operating reports & related correspondence
- 8307260300 Forwards 6-month response to NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants." Procedures for overhead handling sys include precautions & guidelines to be observed while operating sys.
  CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/22. BCHMENCER.A. Licensing Branch 2. 17pp. 19726:092. 24X Fiche: 50-388, 83/07/22, 8307260300.
- S. Reportable occurrences: LERs & related correspondence
- B307010099 Interim deficiency rept re defective OE HMA auxiliary relays. Insp program completion awaiting receipt of GE recommended corrective actions. Final rept scheduled for B30901.

  CURTIS.N.W. Pennsylvania Power & Light Co. 83/06/09. ALLAN.J.M. Region i. Office of Director. 2pp. 19168:155. 24X Fiche: 50-387.83/06/09.8307010099.
- 8307220265 Final deficiency rept re detachment of ILSCO Corp Number 14 stranded wire from screw clamp detectors. Initially reported on 830524. Deficiency not reportable per 10CFR50. 55(e) for Unit 2. Item reportable per Part 21 for Unit 1. CURTIS.N.W. Pennsylvania Power & Light Co. 83/07/13. MURLEY, T. Region 1. Office of Director. 3pp. 19683: 226. 24X Fiche: 50-387, 83/07/13, 8307220265.
- B3072204B3 Second interim deficiency rept re inadequacies in Bechtel design verification of max circuit lengths of low voltage power & control cables. Initially reported on 821215. Also reportable under Part 21. Next rept by 831031. CURTISN. W. Pennsylvania Power & Light Co. 83/07/19. MURLEY, T. Region 1, Office of Director. 4pp. 19685:185. 24X Fiche: 50-387, 83/07/15, 83072204B3.

#### DOCKET 50-389 ST. LUCIE PLANT, UNIT 2

- A. Application/construction stage documents & correspondence
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT.D.O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 1969:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 830711024) Submits editorial changes to SER. Suppl 2. Section 9. 5. 1. Item 3 re control room fire detection coverage. Strategically replacing key sections of lay-in files will alkew flow of combustion where detectors installed.

  UHRIG.R.E. Florida Power & Light Co. 83/07/05. EISENHUT.D.G.
  DIVision of Licensing. 1p. 17379: 235. 24X Fiche: 50-389, 83/07/05. 8307110241.
- F. Security, medical, emergency & fire protection plans
- 8307140276 Ack receipt of 821227 ltr providing status of corrective actions re public info & educ programs NRC finding of adequacy will be based on mati, along w/FEMA review of emergency plan.during Jan 1938 exercise.

  O'REILLY, J.P. Region 2. Office of Director. 83/01/26. UHRIO, R.E. Florida Power & Light Co. ip. 19522:324. 24X Fiche: 50-335. 83/01/26, 8307140276.
- B307140420 Forwards FEMA evaluation rept of B30120-21 emergency exercise per IE Insp Repts 50-335/B3-04 & 50-389/B3-12. DANCE H.C. Division of Project & Resident Programs. 83/03/30. UHRIO, R.E. Florida Power & Light Co. 1p. 19520: 213. 24X Fiche: 50-335, B3/03/30, B307140420.

- --8307140424 "St Lucie Nuclear Power Plant Full-Scale Local Exercise Conducted on 830120," final evaluation rept. \* Federal Emergency Management Agency. 83/03/08. 36pp. 19520:214. 24X Fiche:50-335,83/03/30,8307140420.
- 8307140339 Discusses 1984 full-scale emergency exercise per 830426 meeting Exercise will extend over 3-day period Emergency operations facility will operate at reduced level after first day.

  D'REILLY, J. P. Region 2. Defice of Director. 83/05/26. UMRIG.R.E. Florida Power & Light Co. 2pp. 19523:325. 24X Fiche: 50-000.83/05/26.8307140339.
- 8307140278 Informs that Boise Interagency Fire Ctr contracted to perform surveys of radio frequency interference & electromagnetic interference. Assistance requested. VERRELLI.D.M. Division of Project & Resident Programs. 83/05/31. URRIG.R.E. Florida Power & Light Co. 22pp. 19522:297. 24X Fiche: 30-000, 63/05/31, 6307140278.
- 8307110241 Submits editorial changes to SER, Suppl 2, Section 9, 5, 1, Item 3 re control room fire detection coverage. Strategically replacing key sections of lay-in files will allow flow of combustion where detectors installed.

  UHRIG, R.E. Florida Power & Light Co. 83/07/05. EISENHUT, D. 0. Division of Licensing. ip. 19379:235. 24X Fiche: 50-389, 83/07/05, 8307110241.
- B307140152 Responds to util 830511 ltr re revs to Chapters 5 & 6 to security plan. Changes consistent w/10CFR50. 54(p) & acceptable.
  KMIGHTON-6-W. Licensing Branch 3. 83/07/06. UHRIG-R.E. Florida Power & Light Co. 2pp. 19540:049. 24X Fiche: 50-335,83/07/06. 8307140152.
- 8307270351 Forwards Rev 7 to physical security plan. Rev withheld (ref 10CFR73.21). UHRIG.R.E. Florida Power & Light Co. 83/07/07. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19767: 297. 24X Fiche: 50-335, 83/07/07, 8307270351.
- 8307150347 Forwards IE Sefeguards Insp Repts 50-333/83-25 & 30-389/83-50 on 830613-15. No noncompliance noted. DANCE H.C. Region 2, Office of Director. 83/07/12. UHRIO, R.E. Florida Power & Light Co. 2pp. 19538: 284. 24X Fiche: 50-335, 83/07/12, 8307190347.
- --8307150355 IE Safeguards Insp Repts 50-335/83-25 & 50-389/83-50 on 830613-15. No noncompliance noted Major areas inspected: physical security plan & implementing procedures re records & repts. Details withheld (ref 10CFR73.21).
  MODRE, D. E. Region 2, Office of Director. 83/07/11. 1p. 19538: 286. 24X Fiche: 50-335,83/07/12,8307150347.
- B307220326 Ack receipt of B30627 & 30 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/83-38.

  BANCE, H. C. Division of Project & Resident Programs. B3/07/15.

  UHRIG.R. E. Florida Power & Light Co. 1p. 19683:209. 24X

  Fiche: 50-389, 83/07/15, 8307220326.
- --8307220330 Responds to NRC 830525 ltr re violations noted in IE Insp Rept 50-389/83-39. Corrective actions: Insp performed on all completed fire barriers & process sheets revised to indicate holdpoint. UHRIO.R.E. Florida Power & Light Co. 83/06/30. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19683: 210. 24X Fiche: 50-389, 83/07/15, 8307220326.
- --8307220332 Ack receipt of IE Insp Rept 50-389/83-38. No proprietary info. Corrective actions: routing & processing of procedures reorganized & personnel instruction completed as of 830617. UHR10, R.E. Florida Power & Light Co. 83/06/27. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19683:212. 24X Fiche: 50-389, 83/07/15, 8307220326.
- --8307220335 Forwards IE Insp Rept 50-389/83-38 on 830503-16 & notices of violation & deviation.

  DANCE.H. C. Division of Project & Resident Programs. 83/03/25.

  UHRTO.R. E. Florida Power & Light Co. 2pp. 19683:214. 24X

  Fiche: 50-389,83/07/15,8307220324.
- --8307220337 Natice of violation from insp on 830303-06.
  \* Region 2, Office of Director. 83/05/25. ip. 19683:216. 24X
  Fiche: 50-389, 83/07/15, 8307220326.
- --8307220337 Notice of deviation from insp on 830503-96. \* Region 2, Office of Director. 83/05/25. ip. 19683:217. 24X Fiche: 50-389.83/07/15.8307220326.

- -B307220341 IE Insp Rept 50-3B9/83-38 an 830503-06. Noncompliance noted: failure to establish & implement procedures for fire fighting strategies & inadequate GA/GC program for const of fire barrier walls & shields.
  MILLER,W.H. Region 2. Office of Director. CONLON, T.E. Division of Engineering & Radiological Safety Programs. B3/05/20. Bpp. 19683:218. 24X Fiche: 50-3B9, B3/07/15, B307220326.
- 8307280051 Advises that Amend 14 to FSAR will not be issued until Nov 1983. Scope of amend revised to include rev of fire protection requirements & rev of piping & instrumentation diagram to reflect as-built conditions.

  UMRIG.R.E. Florida Pawer & Light Co. 83/07/22. EISENHUT. D. G. Division of Licensing. 1p. 19791:195. 24X Fiche: 50-389/83/07/22.
- 8307280237 Forwards Rev 2 to 820814 evaluation supporting requests for exemption from Section III-0 of App R to 10CFRSD re fire areas H.I & C.
  UHRIO.R.E. Florida Power & Light Co. 83/07/22. EISENHUT, D. C.
  Division of Licensing. App. 19795:238. 24X Fiche: 50-389:83/07/22.
  8307280237.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8307170327 Comments on reactor vessel thermal stress during cooldown in response to 830520 ltm. Concurs w/Taylor Ref 3 that large thermal gradients could have developed if no mixing of stagnant fluid at low temps occurred.

  ZUDANS, Z. Frantlin Institute/Franklin Research Center. ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. 83/05/31.

  MCXINLEY, J. C. ACRS Advisory Committee on Reactor Safeguards. 1p. 19656: 171. 24X Fiche: 50-335,83/05/31,8307190327.
- P. Operating license stage documents & correspondence
- 8307140136 Confirms that requirement constraining initial criticality complete & initial criticality may proceed.

  O'REILLY, J.P. Region 2: Office of Director. B3/05/27. UHRIG.R.E. Florida Power & Light Co. 1p. 19514:063. 24X Fiche: 50-389. 83/05/27. B307140136.
- 8307140168 Confirms that conditions for exceeding 5% rated power metrors License NPF-16 Attachment 1.Page 2 requirements. Util may escalate power once DL amend issued for full power operation.

  O'RETILLY, J.P. Region 2. Office of Director. 83/06/08. UHRIG.R.E. Florida Power & Light Co. 1p. 19523:207. 24X Fiche: 50-387. 83/06/08.8307140168.
- 8307150045 Forwards Amend 2 to License NPF-16, Suppl 4 to SER (NUREO-0843) & notice of issuance & availability. Amend authorizes operation at power levels up to 100% of full rated gower. W/o SER. NNIOHYTON, C. M. Licensing Brench 3. 83/04/10. UHRIO, R. E. Florida Power & Light Co. 2pp. 19562:313. 24X Fiche: 50-369.83/06/10. Power & Light Co. 2pp. 8307150045.
- -8307150048 Amend 2 to License NPF-16 authorizing operation at power levels up to 100% of full rated power. EISEMHUT, D. G. Division of Licensing. B3/06/10. 5pp. 19562: 313. 24% Fiche: 50-389, 83/06/10.8307130045.
- --8307150050 Notice of issuance & availability of Amend 2 to License MRTF-10. KNIGHTON 9. H. Licensing Branch 9. 83/06/10. 3pp. 19562: 320. 24% Fiche: 50-389,83/06/10,8307150045.
- B307180444 Forwards monthly FR notice of amends to OLs involving NSHC.

  \* Office of Nuclear Reactor Regulation, Director. B3/06/15.
  UHRIG.R.E. Florida Power & Light Co. 2pp. 19641:347. 24X
  Fiche: 50-000,83/06/15,8307180446.
- --8307190001 Monthly notice of amends to OLs involving NSHC.
  CLARK.R.A. Operating Reactors Branch 3, 83/06/07, 15;
  19641:349. 24X Fiche: 50-000; 83/06/15; 8307180446.
- 8307080646 Forwards "Control of Heavy Loads, 8t Lucie Plant, Unit 2 (Phase I)," technical evaluation rept.
  KNIGHTON 0.M. Licensing Branch 3. 83/06/17. UHRIG.R.E. Flor: Power & Light Co. 2pp. 19364: 180. 24X Fiche: 50-389.83/06/17.
- 8307140065 Concurs in 830516 request for extension until 830627 to submit call-in drills (staff augmentation/time saving measures).

  DANCE, H.C. Division of Project & Resident Programs. 83/06/20.

  UHRIG, R.E. Florida Power & Light Co. ip. 19514:091. 24X

  Fiche: 50-000, 83/06/20, 8307140065.

- 8307030456 Requests info on whether review panel implemented in Ragion II to inspect licensee documentation is utilized in other regions.

  NDVAK, T. M. Assistant Director for Licensing. B3/06/21. TAYLOR, J. M.

  Division of GA. Safeguards & Inspection Programs (Post B30103). tp.

  19262: 279. 24X Fiche: 50-389, 83/06/21, 8307030456.
- B307030126 Forwards safety analysis of 830606 proposed change to Tech Specs requesting that weakly testing of valves involved in turbine overspeed protection be extended to monthly schedule & Westinghouse ltr inadvertently omitted from 830606 ltr. UHRIG.R.E. Florida Power & Light Co. 83706/28. EISENHUT.D.G. Division of Licensing. 4pp. 19220:215. 24X Fiche: 50-389,83706/28,8307030126. 24X Fiche: 50-389, 83/06/28,
- 8307080667 Discusses accomplishments in meeting licensing schedule, NERSES,V. Licensing Branch 3. 83/06/28. KNIGHTON,Q. Licensing Branch 3. 2pp. 19364:123. 24X Fiche:50-389,83/06/28,8307080667.
- B307110634 Responds to Commissioner Ahearne B30613 request for info on vicinity population study. Revised resident & transient population estimate incorporated into SER Section 2. 1.2. DIRCKS, N. J. Office of the Executive Director for Operations. 83/06/28. PALLADINO, N. J. OILINSKY, V. AHEARNE, J. F. Commissioners. ip. 19371: 356. 24X Fiche: 50-389, 83/06/28, 8307110634.
- B307060265 Forwards "St Lucis Units 1 & 2. Turkey Point Units 3 & 4
  Detailed Control Room Design Reviews Program Plan," per util
  B30415 commitment re Suppl 1 to NUREO-0737.
  UHRIO,R. E. Florida Power & Light Co. 83/06/30. EISENHUT, D.G.
  Division of Licensing. 1p. 19237:184. 24X Fiche: 50-387,83/06/30,
  8307060265.
- 8307070077 Forwards description of C-E Owners Group program for resolving TMI Item II.K.3.5 "Automatic Trip of Reactor Comlant Pumps" & Generic Ltr 83-108. Program scheduled for completion by end of 1783.

  UHRIO, R.E. Florida Power & Light Co. 83/07/01. EISENHUT. D. 9.
  Division of Licensing. App. 19293:076. 24X Fiche: 50-335,83/07/01.8307070077.
- 8307120410 Forwards Class II & III amend fees for 830606 & 17 applications re turbine overspeed protection & steam generator pressure/temp limits.respectively. UHRIG, R.E. Florida Power & Light Co. 83/07/01. EISENHUT.D.C. Division of Licensing. 1p. 17430:140. 24X Fiche: 50-389, 83/07/01, 83271720410
- 8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of GPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. 0. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000, 83/07/05, 8306270397.
- 8307150231 Application for amend to License NPF-16, revising License Condition 2.C.7 re natural circulation cooldown & boron mixing test Bafety evaluation encl.
  UHRIO,R.E. Florida Power & Light Co. 83/07/07. EISENHUT, D. Q. Division of Licensing. 4pp. 19530:215. 24X Ficha: 50-389, 83/07/07, 8307150231.
- 8307080167 Generic Ltr 83-28 to all licensees of operating reactors, applicants for Oi. & holders of CPs re required actions based on generic implications of Salem ATMS events 8vc list encl. EISENHUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Ficha: 50-000, 83/07/08, 8307080169.
- 8307260353 Advises that post-reactor trip review procedures will be modified per NRC 830708 Generic Ltr 83-28 in lieu of util 830609 commitment.
  UHRIO, R. E. Florida Power & Light Co. 83/07/21. EISENHUT, D. O. Division of Licensing. ip. 19732; 361, 24% Fiche: 50-389, 83/07/21, 8307260353.
- 8307280051 Advises that Amend 14 to FSAR will not be issued until Nov 1983. Scope of amend revised to include rev of fire protection requirements & rev of piping & instrumentation diagram to reflect as-built conditions. UHRIO.R.E. Florida Power & Light Co. 83/07/22. EISENHUT, D. G. Division of Licensing. 1p. 19791: 195. 24X Fiche: 50-389, 83/07/22, 8307280051.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140227 Requests that liquid samples spiked w/radionuclides be analyzed for tritium.8r-89 & Sr-90 content within 60 days of receipt of spiked samples. Samples will be sent annually as part of routine insp program.

  LEWIS.R.C. Division of Project & Resident Programs. 83/02/07. UHRIG.R.E. Florida Power & Light Co. lp. 19524:060. 24X Fiche: 50-000,63/02/07,8307140229.

- 8307140112 Forwards IE Insp Rept 50-389/83-10 on 830118-21. No noncompliance noted. LEWIS.R.C. Division of Project & Resident Programs. 83/02/25 UKRIG.R.E. Florida Power & Light Co. 2pp. 19514:129. 24X Fiche: 50-389, 83/02/25, 8307140112.
- --8307140117 IE Insp Rept 30-389/83-10 on 830118-21. No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14).
  ANG.W.P., BLAKE.J.J. Region 2. Office of Director. 83/02/25.
  App. 19514:131. 24X Fiche: 50-389, 83/02/25, 8307140112.
- B307140420 Forwards FEMA evaluation rapt of 830120-21 emergency exercise per IE Insp Repts 50-335/83-04 & 50-389/83-12. DANCE H C. Division of Project & Resident Programs. 83/03/30. UHR10.RE Florida Power & Light Co. 1p. 19520: 213. 24X Fiche: 50-335,83/03/30,8307140420.
- 8307140147 Forwards IE Insp Repts 50-335/83+09 & 50-389/83-22 on 830311-0410. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/14. URRIG. R.E. Florida Power & Light Co. 2pp. 19514: 231. 24X Fiche: 50-335, 83/06/14, 8307140147.
- --8307140154 IE Insp Repts 50-335/83-07 & 50-389/83-22 on 830311-0410. No noncompliance noted Major areas inspected maint & surveillance observations, plant operations. IE buildtins, circulars & info notices. LERs & new fuel handling. ELROD, S. A., BIOB, H. E., Region 2, Office of Director. JULIAN, C. Division of Project & Resident Programs. 83/06/13. 14pp. 19514: 233. 24X Fiche: 50-335, 83/06/14, 8307140147.
- B307140097 Forwards IE Insp Rept 50-399/83-46 on 830525-27. No noncompliance noted.

  DANCE, H.C. Division of Project & Resident Programs. 83/06/24. URRIGR.E. Florida Power & Light Co. 2pp. 19514: 101. 24X Fiche: 50-389, 83/06/24, 8307140097.
- --B307140103 IE Insp Rept 50-389/83-46 on B30525-27. No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14) & pipe support baseplate designs using concrete expansion anchors. ANG. M.P., BLAKE, J. J. Region 2, Office of Director. B3/66/22 Spp. 19514:103. 24X Fiche: 50-389, 83/06/24, 8307140097.
- B307140394 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/83-12. DANCE H.C. Division of Project & Resident Programs. B3/06/27. UHRIGR.E. Florida Fower & Light Co. 1p. 17520: 166. 24X Fiche: 50-335. B3/06/27. B307140394.
- --8307140405 Forwards IE Insp Repts 50-335/83-12 & 50-389/83-32 on 830411-15 & notice of violation.

  DANCE.H.C. Division of Project & Resident Programs. 83/05/16. UHRIO.R.E. Flortid Power & Light Co. 2pp. 19520: 169. 24X Fiche: 50-335,83/06/27,8307140394.
- --B307140411 IE Insp Repts 30-335/83-12 & 50-389/83-32 on 830411-15.
  Nancompliance noted:failure to post specified documents per 10CFR19.11.
  WRAY, J.R. Region 2. Office of Director. BARR.K.P. Division of Engineering & Radiological Safety Programs. 83/05/11. 9pp. 19520:172. 24X Fiche:50-335,83/06/27,8307140394.
- B30722048B Forwards IE Insp Rept 50-387/83-49 on B3060B-10.No honcompliance noted. DANCE.H.C. Division of Project & Resident Programs. 83/06/28. UHRIG,R.E. Florida Pawer & Light Co. 2pp. 19685:091. 24X Fiche: 50-389, B3/06/28, B307220488.
- --B307220494 IE Insp Rept 50-389/83-49 on B30608-10. No noncompliance noted Major areas inspected: licensee action on previous enforcement matters.

  ANG.W.P. Region 2. Office of Director. BLAKE, J. Division of Engineering & Radiological Safety Programs. B3/06/27. 49p. 19685: 093. 24X Fiche: 50-389, 83/06/28, 8307220488.
- 8307140393 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/83-05.
  LEWIS.R.C. Division of Project & Resident Programs. 83/06/29.
  UHRIG.R.E. Florida Power & Light Co. ip. 19521:314. 24X
  Fiche:50-335.83/06/29.8307140393.
- --8307140408 Forwards IE Insp Repts 50-335/83-05 & 50-389/83-15 on 830211-0310 & notice of violation. LEWIS.R.C. Division of Project & Resident Programs. 83/04/21. UMRIG.R.E. Fiorida Power & Light Co. 2pp. 19521:317. 24X Fiche: 50-335,83/04/29,8307140393.

- ---B307140018 IE Insp Repts 30-335/83-05 & 50-389/83-15 on B30211-0310. Noncompliance noted:failure to follow refueling sequencing procedure during refueling operations. ELROD.S. A. BIBB.H. E. Region 2. Office of Director. JULIAN.C. A. Division of Project & Resident Programs. B3/04/21. 12pp. 19521: 320. 24% Fiche: 50-335, 83/04/29, 8307140393.
- 8307220028 Forwards IE Insp Rept 50-389/83-48 on 830530-0610.No noncompliance noted. DANCE, H.C. Division of Project & Resident Programs. 83/06/29. UHRIG. R.E. Florida Power & Light Co. Rpp. 19684:353. 24% Fiche: 50-389,83/06/29,8307220028.
- --8307220037 IE Insp Rept 50-389/83-48 on 830530-0610. No noncompliance noted. Major areas inspected: approach to & achievement of initial criticality, low power physics testing & raview of preoperational procedures re power accession test program. KRUG.H. Region 2, Gffice of Director. JAPE.F. Division of Engineering & Radiological Safety Programs. 83/06/28. Spp. 19684: 355. 24X Fiche: 50-389, 83/06/29, 8307220028.
- B307140274 Ack receipt of 830531 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-389783-29. DANCE, H. C. Division of Project & Resident Programs. 83/06/30. URRIGAR E. Florida Pouer & Light Co. 1p. 19525:126. 24X Fiche: 50-389.83/06/30.8307140274.
- --B307140282 Forwards response to IE Insp Rept 50-389/83-29. No proprietary info. Revised procedure posted. Full compliance achieved 830408.

  UHRIG.R.E. Florida Power & Light Co. 83/05/31. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19525: 124. 24X Fiche: 50-389, 83/06/30, 8307140274.
- --8307140283 Forwards IE Insp Rept 50-389/83-29 on 830405-08 & notice of violation.
  LEWIS,R.C. Division of Project & Resident Programs. 83/04/29.
  UHRIG.R.E. Florida Power & Light Co. 2pp. 19525:126. 24X
  Fiche:50-389,83/06/30,8307140274.
- --B307140287 Notice of violation from insp on B30408-08. \* Region 2. Office of Director. 93/04/29. ip. 19825:128. 24X Fiche: 50-389, 83/06/30, 8307140274.
- --B307140291 IE Insp Rept 50-389/83-29 on 830405-08.Noncompliance noted: failure to post revised procedures re control room inaccessibility.

  KRUG-E.P., JAPE-F. Region 2, Office of Director, 83/04/24, 5pp. 19525:129, 24X Fiche: 50-389, 83/04/30, 8307140274.
- 8307140227 Forwards summary of 830602 mgt meeting at Region II redisposition of util QC insprepts & status of 5% license conditions at facility.

  LEWIS: R. C. Region 2. Office of Director. 83/07/05. UHRIO, R. E. Florida Power & Light Co. 4pp. 19523: 121. 24X

  Fiche: 50-389, 83/07/05, 8307140227.
- 8307120278 Informs that 830425-27 insplat Neison Electric plant in Tulsa, OK found that identified damage to electrical supply panels resulted from gross mishandling during shipping or after receipt at site, AITS F02700270 closed.
  PDTAPOVS, U. Division of Vendor & Technical Programs. 83/07/07. LEWIS, R. L. Division of Project & Resident Programs. 19. 19424: 104. 24% Fiche: 50-389, 83/07/07, 8307120298.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 134pp. 19363:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8305270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 90-000,83/07/12.8306270404.
- 8307150347 Forwards IE Safeguards Insp Repts 50-335/83-25 & 50-387/83-50 on 830&13-15. No moncompliance noted. DANCE: H. C. Region 2. Office of Director. 83/07/12. UHRIO, R. E. Florida Pawer & Light Co. 2pp. 19538: 284. 24X Fiche: 50-335, 83/07/12, 8307150347.
- ---8307190355 IE Safeguards Insp Repts 50-335/83-25 & 50-389/83-50 on 830613-15. No noncompliance noted Major areas inspected: physical security plan & implementing procedures re records & repts. Debails withheld (ref 100FR73.21).
  MODRE, D. E. Region 2. Office of Director. MCOUIRE, D. R. Division of Emergency Preparadness & Materials Safety. 83/07/11. ip. 19538: 286. 24X Fiche: 50-335,83/07/12,8307150347.

- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- 8307220326 Ack receipt of 830627 & 30 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50~389/83-38.

  BANCE H C. Division of Project & Resident Programs. 83/07/15.

  UHRIO, R E. Florida Power & Light Co. 1p. 19683:209, 24X

  Fiche: 50~389, 83/07/15, 8307220326.
- --8307220330 Responds to NRC 830525 ltr re violations noted in IE Insp Rept 30-389/83-38. Corrective actions: insp performed on all completed fire barriers & process sheets revised to indicate holdpoint. UNRIG.R.E. Florida Power & Light Co. 93/06/30. O'REILLY, J. P. Region 2. Diffice of Director. 2pp. 19683: 210. 24X Fiche: 50-369, 83/07/15,8307220326.
- --8307220332 Ack receipt of IE Insp Rept 50-389/83-38. No proprietary info Corrective actions: routing & processing of procedures reorganized & personnel instruction completed as of 830617. UHRIG.R.E. Florida Power & Light Co. 83/06/27. U'REILLY, J. P. Region 2. Office of Director. 2pp. 19683: 212. 24X Fiche: 50-389, 83/07/15, 8307220326.
- --8307220335 Forwards IE Insp Rept 50-389/83-38 on 830503-16 & notices of violation & deviation.

  BANCE.H.C. Division of Project & Resident Programs. 83/05/25.

  UHRIG.R.E. Florida Power & Light Co. 2pp. 19683:214. 24X

  Fiche: 50-389, 83/07/15, 8307220326.
- --B307220337 Notice of violation from insp on 830503-06. \* Region 2, Office of Director. 83/05/25. ip. 17683:216. 24X Fiche: 50-389, 83/07/15, 8307220326.
- --8307220339 Notice of deviation from insp on 830503-06.
  4 Region 2. Office of Director. 83/05/25. 1p. 19483:217. 24X Fiche:50-389,83/07/15.8307220326.
- --8307220341 IE Insp Rept 50-389/83-38 on 830903-06. Noncompliance noted: failure to establish & implement procedures for fire fighting strategies & inadequate GA/GC program for const of fire barrier walls & shields.
  HILLER.W.H. Region 2. Office of Director. CONLON.T.E. Division of Engineering & Radiological Safety Programs. 83/05/20. 8pp. 19683.218. 24% Fiche: 50-389, 83/07/15, 8307220326.
- 8. Reportable occurrences, LERs & related correspondence
- 8307120428 Updated LER 83-006/017-1: on 830511.leak developed in weld on 1-inch drain line from RCS safety injection header 281. Caused by fetigue due to vibration. Drain line natural vibration frequency changed W/830624 ltr. BRANNIN.J.P. WILLIAMS.J.W. Florida Power & Light Co. 83/06/24. G'RETLLY.J.P. Region 2. Defice of Director. 3pp. 17434:001. 24x Fiche: 50-389, 63/06/24, 8307120428.
- 8307120134 LER 83-018/03L-0: on 830936 during initial startup inner equalizing valve of personnel air lock did not shut. Caused by broken valve operating linkage. Valve replaced & linkage repaired W/830630 ltr.

  WALLING.O.E. WILLIAMS.J.W. Florida Power & Light Co. 83/06/30.
  0'REILLY.J.P. Region 2. Office of Director. 2pp. 19423:169. 243
  Fiche: 50-389.83/06/30,8307120134.
- 8307120172 LER 83-019/03L-0 on 830803.position indication lights for PDRV 1475 discovered out Caused by failure of magnetic slug located on valve stem Slug replaced w/new magnet w/annealed metal M/830701 ltr.
  VALDES, S. A. WILLIAMS, J. W. Florida Power & Light Co. 83/07/03. O'REILLY, J. P. Region 2: Office of Director. 2pp. 19423:158. 24X Fichs: 50-389,83/07/03,8307120172.
- 8307110245 LER 83-021/03L-0: on 830602, waste gas decay tank oxygen level found out of Tech Specs Possibly raused by in-leakage Leaks corrected.

  BRANNIN J. P., WILLIAMS, J. W. Florida Power & Light Co. 83/07/05.

  O'REILLY, J. P. Region 2. Office of Director. 2pp. 19374:337. 24X

  Fiche: 50-387, 93/07/05, 8307110245.
- 8307110402 LER 83-025/03L-O: on 830616, while in Mode 2 startup & filling 2A2 safety injection tank relief valve on refueling water tank return header lifted resulting in loss of pressure in 2B2 Caused by open manual isolation valve. W/830705 ltr. BRANNIN.J.P., WILLIAMS.J.W. Florida Power & Light Co. 83/07/05. D'REILLY.J.P. Region 2, Office of Director. 2pp. 19380:307. 24X Fiche: 50-389,83/07/05.8307110402.

- B307120177 LER B3-020/03L-0: on B30606, safety injection tank 2A2 depressurized to 565 psig during filling. Caused by relief valve V-3466 lifting during filling & operator unaware of pressure restrictions. Operator reinstructed M/B30705 ltr. VALDES/S.A. WILLIAMS, J. W. Fiorida Power & Light Co. B3/07/05. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19423:149. 24X Fiche: 50-389, 83/07/05. B307120177.
- B307190205 LER B3-022/03L-D: on B30606, waste gas decay tank 2B contained explosive mixture. Caused by out-of-adjustment nitrogen regulators & slightly opened vent valve. Vent valve closed & nitrogen regulators adjusted. W/830706 ltr.
  ROTECLA-T.S., WILLIAMS, J. W. Florida Power & Light Co. B3/07/06, 0'REILLY, J.P. Region 2, Office of Director. 2pp. 19530: 235. 24x Fiche: 50-389, 83/07/06, 8307150205.
- B307150268 LER 83-027/03L-0: on B3060B, during power ascension testing, w/ one high radiation containment isolation sys channel in bypass another high radiation channel failed low. Caused by bistable driffting low. W/83707 ltr.
  VALOES, S. A., WILLIAMS, J. W. Florida Power & Light Co. 83/07/07. G'REILLY, J. P. Region 2, Office of Director. 2pp. 19538:094. 24x Fiche: 50-389, 83/07/07, 830715026B.
- 8307220427 LER 83-029/03L-0: on 830610, while performing power ascension testing auxiliary feedwater pump C failed to reach rated speed. Caused by erroneous electrical overspeed trips due to noise seen by AIR PAX Series 300 tachometer. W/830711 ltr. HALLING, G.E., WILLIAMS, J.W., Florida Power & Light Co. 83/07/11, O'REILLY, J.P. Region 2, Office of Director. 2pp. 17687:273. 24X Fiche: 50-389, 83/07/11, 8307220427.
- 8307220535 LER 83-030/03L-0: on 830610, channel D low component cooling water reactor coolant pumps spuriously started causing timing to trip. Caused by spikes from flow transmitter. Transmitter vented W/830711 ltr. WALLING.G.E., WILLIAMS, J.W. Florida Power & Light Co. 83/07/11. 0'REILLY, J.P. Region 2. Office of Director. 2pp. 19686:031. 24x Fiche: 50-389, 83/07/11, 8307220535.
- B307250182 LER 83-024/03L-0: on B30615; during power ascension testing. RCS inventory balance surveillance not performed. Caused by unstable conditions associated w/power ascension testing. Inventory balance subsequently performed W/830715 ltr. VALDES, S. A. WILLIAMS, J. W. Florida Power & Light Co. 83/07/15. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19705:358. 24x Fiche: 50-389, 83/07/15, 8307250182.
- 8307250209 LER 83-023/O3L-0: on 830617, during startup operations, control element assembly 45 slipped greater than 7 inches from group & dropped to bottom during withdrawal. Investigation conducted Cause unknown. W/830718 ltr.
  ROTELLA: T. S., WILLIAMS, J.W. Florida Power & Light Co. 83/07/18, O'RETLLY, J.P. Region 2, Office of Director. 2pp. 19705:341. 24x Fiche: 50-389, 83/07/18, 8307250209.
- U. Congressional/Executive Correspondence
- 8307270047 Forwards monthly FR notice of consideration of issuance of amends to DLs involving NBHC determination & opportunity for hearing.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

  83/06/22. STAFFGRD.R.T., SIMPSON.A. Senate, Environment & Public Horks. UDALL.M.K. House of Rep., Interior & Insular Affairs. 2pp. 19811:018. 24X Fiche: 50-000, 83/06/22, 8307270047.
- --8307270050 Monthly notice of consideration of issuance of amends to OL involving NSHC determination & opportunity for hearing. CLARK.R.A. Operating Reactors Branch 3. 83/06/07. 15pp. 19811:020. 24X Fiche: 50-000,83/06/22,8307270047.
- V. Operator Examinations
- 8307140300 Forwards list of personnel licensed to operate both units & of personnel licensed to operate only Unit 2 per 821129-1210,830124 & 0424 exams. Addl info re 820219 meeting request to lift separate license restriction needed.

  DANCE.H.C. Division of Project & Resident Programs. 83/04/16.

  UHRIGR.E. Florida Power & Light Co. 4pp. 19523:233. 24X

  Fiche: 50-935,83/06/16,8307140300.
- DUCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

  A. Application/construction stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensess, applicants for OLs & holders of CPs for Westinghouse PHRs re safety evaluation of "Emergency Response Guidelines," Svc list encl.
  EISENHUT, D. O. Division of Licensing, 83/06/03, Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03, 83060070

- 8307050226 Responds to Generic Ltrs 82-28 & 82-33 & NUREG-0737. Item II.F. 2 re detection on inadequate core cooling. Reactor vessel level instrumentation sys will be installed before fuel load for operator training & familiarization.

  MILLS.L.M. Tennessee Valley Authority. 83/06/29. ADENSAH.E. Licensing Branch 4. 2pp. 19198:333. 24% Fiche:50-370.83/06/29, 8307050226.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/05. Censolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000, 83/07/05, 8306270397.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche: 50-000,83/07/06,8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. 8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307260297 Forwards responses to NRC 830601 ltr re analysis of sheetpile walls & seismic analysis of buried pipes submitted per 820922-24 geotechnical audit.

  KAMMER, D. S. Tennesses Valley Authority. 83/07/21. ADENBAM.E. Licensing Branch 4. 16pp. 19726:214. 24X Fiche: 50-390, 83/07/21, 8307260297.
- 830729014B Forwards final response to NUREG-0737, Item II. D. 1, "Performance Testing of PWR Relief & Safety Valves."

  KAMMER, D. S. Tennessee Valley Authority. 83/07/22. ADENSAM, E. Licensing Branch 4. 8pp. 19821:053. 24X Fiche: 50-390, 83/07/22, 830729014B.
- 8307290151 Forwards proposed mods to NRC draft version of Tech Specs. Resolution of outstanding items & issuance of proof & review Tech Specs requested at earliest date possible. Unit 1 fuel load scheduled for Jan 1984. KAMMER, D. S. Tennessee Valley Authority. 83/07/27. ADENSAM.E. Q. Licensing Branch 4. 2pp. 19816:001. 24X Fiche: 50-390, 83/07/27, 8307290151.
- --8307290195 Proposed mods to draft Tech Specs.

  \* Tennessee Valley Authority. 83/07/27. 466pp. 19816:003. 24X Fiche: 50-390,83/07/27,8307290151.
- F. Security, medical, emergency & fire protection plans
- 8307030226 Responds to Generic Ltrs 82-28 & 82-33 & NUREO-0737, Item II.F.2 re detection on inadequate core cooling. Reactor vessel level instrumentation say will be installed before fuel load-for operator training & familiarization. MfLLS.L.M. Tennessee Valley Authority. 83/06/29. ADENSAM.E. Licenesing Branch 4. 2pp. 19198:333. 24x Fiche:50-390.83/06/29.
- 8307110054 Submits revised implementation schedule for prompt notification sys. All fixed strens installed & preoperationally tested. Revs due to rescheduled fuel load dates.

  MILLS.L.M. Tennessee Valley Authority. 83/07/01. ADENSAM.E. Licensing Branch 4. 2pp. 19375:018. 24X Fiche: 50-390, 83/07/01. 8307110054.
- B307140347 Corrects IE safeguards insp rept number from insp conducted on B30418-22. Rept number should be 50-370/83-11 instead of 50-370/83-12.
  VERRELLI, D. Division of Project & Resident Programs. B3/07/06. PARRIS, H. G. Tennessee Valley Authority. 2pp. 19323: 233. 24X fiche: 50-390, B3/07/06, B307140347.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010284 Amend 48 to FSAR. \* Tennessee Valley Authority. 83/07/01. 355pp. 19191:070. 24X Fiche: 50-390.83/07/01.8307010284.

- Q. Inspection reports, IE Bulletins & correspondence
- B307140064 Forwards 1E Insp Repts 50-390/83-18 & 50-391/83-14 on B30423-052k. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. B3/06/24 PARRIS.H. G. Tennessee Valley Authority. 2pp. 19514:108. 24X Fiche: 50-390, B3/06/24, B307140064.
- --8307140069 IE Insp Repts 50-390/83-18 % 50-391/83-14 on 830423-0521. No noncompliance noted. Major areas inspected: review of open 1 tems (IE bulletins, const deficiency repts, deviations & violations) & concrete placement & curing.

  HEATHERLY.T.L., SMAN. W. B. Region 2. Diffice of Director.

  GUICK, D. R. Division of Project & Resident Programs. 83/06/24.

  7pp. 19514:110. 24X Fiche: 50-390,83/06/24,8307140064.
- 8307220481 Forwards IE Insp Rept 50-390/83-21 on 830606-10. No noncompliance noted.

  VERRELLI.D.M. Division of Project & Resident Programs. 83/06/27. PARRISH G. Tennessee Valley Authority. 2pp. 17685:344. 24X Fiche:50-390.83/06/27.8307220481.
- --8307220493 IE insp Rept 90-390/83-21 on 830606-10 Nd noncompliance noted Major areas inspected preoperational review b test witnessing.

  THOMAS, M., MATHIS, J. L., Region 2. Diffice of Director. JAPE.F. Division of Engineering & Radiological Safety Programs. 83/06/23. 4pp. 19689:348. 24X Fiche: 90-390,83/06/27.8307220481.
- B307140347 Corrects IE safeguards inspirept number from inspiconducted on B30418-22. Rept number should be 50-390/83-11 instead of 50-390/83-12. VERRELLI, D. Division of Project & Resident Programs. B3/07/06. PARRIS,H. G. Tennessee Valley Authority. 2pp. 19525:233. 24X Ficha: 50-390, 83/07/06, 8307140347.
- 8307120481 Documents 830629-30 discussions w/NRC re preoperational tests for thermal expansion snubber movement exam & preservice inspirequirements on snubbors.per FSAR Question 112.39. Info documented in submittal prior to fuel load. MILLS.L.M. Tennessee Valley Authority. 83/07/07. ADENBAM.E. Licensing Branch 4. 3pp. 19425:064. 24X Fiche:50-390.83/07/07.8307120481.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Rectriculation Spray Subsystem." Svc list enci.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B301031), B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563: 293. 24X Fiche: 50-000, B3/07/11, B306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consulidated Edison Co. of New York, Inc. 141pp. 19563:133. 24X Fiche:30-000,83/07/12,8306270404.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000/83/07/14/8306270406.
- S. Reportable occurrances, LERs & related correspondence
- 8307120250 Second interim deficiency rept re nondivisional power received by transfer switches to auxiliary feedwater sys. Initially reported on 830202. Redundant circuits identical to existing design provided. Next rept expected by 830927. MILLS.L.M. Tennessee Valley Authority. 83704727. O'REILLY.J.P. Region 2. Office of Director. 3pp. 19423:035. 24% Fiche: 50-000.83706/27,8307120250.
- 8307120160 Final deficiency rept re cross-trained diesel generator HX inlet velves. Initially reported on 830531. Logic, schematic & connection drawings reviewed & checked against mechanical flow diagrams for compatibility.

  MILLS.L.M. Tennessee Valley Authority. 83/06/28. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19423:164. 24X Fiche: 50-390.83/06/28, 8307120160.
- 8307120180 Final deficiency rept re diesel generator room exhaust fans exhibiting higher than specified vibration amplitudes at initial startup. Initially reported on 810831. Rotational speed of fans increased by changing pitch of sheave. MILLS, L.M. Tennessee Valley Authority. 83/06/28. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19423:359. 24X Fiche: 50-390.83/06/28, 8307120180.

- 8307120569 Final deficiency rept re control of non-GA hex nuts. Initially reported on 821021. Nuts replaced Procedure revised to clarify responsibilities for review of arriving items. MILLS.L.M. Tennessee Valley Authority. 83/06/28. Q'REILLY, J. P. Region 2. Office of Director. 2pp. 19433:147. 24X Fiche: 50-390, 83/06/28, 8307120569.
- 8307120577 Final deficiency rept re loosening of yolk holddown nut mfg by Masokeilan Intl. Initially reported on 820601. Condition not reportable under 10CFR50.55(e).
  MILLG.L.M. Texnessee Valley Authority. 83/06/29. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19432:146. 24X Fiche: 50-390, 83/06/29, 8307120577.
- 8307110508 Final deficiency rept for Unit 1 & sixth interim deficiency rept for Unit 2 re thermal range for auxiliary feedwater sys incorrectly analyzed. Initially reported on 811022. Range corrected. Next rept for Unit 2 due 840109.
  MILLS.L.M. Tennessee Valley Authority. 83/06/30. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19380:091. 24X
  Fiche: 50-390.83/06/30.8307110508.
- 8307120179 Final deficiency tept re steam generator water level ref column error. Initially reported on 790706. Sensing lines will be thermally insulated & low-low water level setpoint will be adjusted. Also reportable under Part 21.
  MILLS.L.M. Tennessee Valley Authority. 83/06/30. Q'REILLY, J. P. Region 2. Office of Director. 3pp. 19424:001. 24X Fichs: 50-390, 83/06/30, 8307120179.
- 8307120598 Final deficiency rept re safety injection sys train B flow below required level. Initially reported on 800501. RHR HX outlet valves 1-FCV-74-16 & 28 will be operated at 79 degrees open.

  MILLS.L.M. Tennessee Valley Authority. 83/06/30. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19433:007. 24X Fiche: 50-390, 83/06/30, 8307120598.
- 8307150207 Sixth interim deficiency rept re containment spray miniflow valve design error. Initially reported on 820305. Engineering Change Notice 3420 under review for closure. Next rept will be provided by 830928. Also reportable per Part 21. MILLS, L. M. Tennessee Valley Authority. 83/07/06. O'REILLY, J. P. Region 2. Office of Director. ip. 19330:234. 24X Fiche: 50-390.83/07/06.8307150207.
- B307190236 Final deficiency rept re summation of loads in STRUDL Code. Initially reported on B30215. Defective code platform discovered in one program application corrected. Designers notified of correct computer commands.

  MILLG.L.M. Tennessee Valley Authority. B3/07/07. Q'REILLY, J. P. Region 2. Defice of Director. 2pp. 19530: 207. 24X Fiche: 50-390. B3/07/07. B307150236.
- 8307220554 Final Deficiency Rept 81-89 & sixth interim Deficiency Rept 81-83 re incorrect modeling of feedwater piping valves for Unit 1 & Unit 2. respectively. Initially reported on 811007. Next rept for Unit 2 will be submitted by 840917.
  MILLS.L.M. Tennessee Valley Authority. 83/07/13. D'REILLY, J. P. Région 2. Defice of Director. 4pp. 17484:059. 24% Fiche: 50-390,83/07/13.8307220554.
- 8307250272 Fourth interim deficiency rept re lact of evidence that auxiliary feedwater pump components meet code requirements. Initially reported on 820330. Cause under investigation. Components installed to Class C requirements. MILLS.L.M. Tennessee Valley Authority. 83/07/18. D'REILLY, J.P. Region 2. Defice of Director. 1p. 19705:313. 24x Fiche: 50-390.83/07/18.8307230292.
- 8307250375 First interim deficiency rept re high pressure fire protection piping water danger to shutdown board transformers. Initially reported on 830616. Piping will be supported to insure pressure boundary integrity.

  MiLLS-L.M. Townessee Valley Authority. 83/07/18. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19701:324. 24X Fiche: 50-390, 83/07/18, 8307250395.
- 8307250405 Final deficiency rept re cable separation in ERCW intake pumping station. Initially reported on Bii204. Drawing revised to add 1 h rated fire barrier protection for Train B syscables. Corrective actions will be completed by B30971. MILLS, L.M. Tennessee Valley Authority, 83/07/19. O'REILLY, J. P. Region 2. Diffice of Director. 2pp. 19703:213. 24X Fiche: 50-390,83/07/19,8307250405.
- B307240434 Third interim deficiency rept re use of digitized response spectra data. Initially reported on B20422. Util still in process of implementing Engineering Change Notice 3481. Next rept will be submitted by B30922.
  MILLS, L. M. Tennessee Valley Authority. B3/07/20. O'REILLY, J. P. Region 2. Office of Director. Ip. 19734. 177. 24X Fichs: 50-370. B3/07/20. 8307240434.

- B307290034 Final deficiency rept for Watts Bar & Items 2 & 4 of Bellefonte & Bixth Interim Deficiency Rept Item 3 for Bellefonte re engineering change review & handling. Initially reported on Bil215. Next Bellefonte rept by B31021. MILLS.L.M. Tennessee Valley Authority. B3/07/20. O'REILLY, J. P. Region 2. Office of Director. 7pp. 19822:142. 24X Fiche: 30-000, B3/07/20, B307290034.
- 8307240520 Suppl to 830428 Final Deficiency Repts 81-73 & 81-69 re diesel generator room exhaust fan mod Initially reported on 810831. Deficiency also reportable per Part 21.

  MILLS.L.M. Tennesses Valley Authority. 83/07/21. O'REILLY, J. P. Region 2. Defice of Director. 1p. 19731: 288. 24X Fiche: 50-390, 83/07/21, 8307260520.
- 8307290172 Third interim deficiency rept re lack of qualification for embedment plates identified during review of nonconformance concerning engineering change notices. Initially reported on 311215. Nonconformance rept under review. Next rept by 830729, MILLS.L.M. Tennessee Valley Authority. 83/07/22. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19821:044. 24X Fiche: 30-390.83/07/22.8307290172.
- 8307290176 First interim deficiency mept re sensing of pipe breaks in component cooling sys. Initially reported on 830624. Installation of flow differential measuring device being investigated. Next wept expected by 830915. MILLS, L. M. Tennessee Valley Authority. 83/07/22. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17821:136. 24X Fiche: 50-390, 83/07/22, 8307290176.
- DDCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Syc list encl.
  EISENHUT.D.O. Division of Licensing. 83/06/03. Yankee Atomic Elsetric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307030226 Responds to Generic Ltrs 82-28 & 82-33 & NUREO-0737. Item II.F.2 re detection on inadequate core cooling. Reactor vessel level instrumentation sys will be installed before fuel load for operator training & familiarization.
  MILLS.L.M. Tennessee Valley Authority. 83/06/29. ADENSAM.E. Licensing Dranch 4. 2pp. 19198:333. 24X Fiche:50-390,83/06/29,8307050226.
- 8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 14pp. 19669:234. 24X Fiche: 50-000:83/07/06:8307060329.
- B3070B0i69 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 1969: 269. 24X Fiche: 50-000, B3/07/08, B3070B0169.
- 8307260297 Forwards responses to NRC 830601 ltr re analysis of sheetpile walls & seismic analysis of buried pipes, submitted per 820922-24 geotechnical audit.

  KAMMER, D. S. Tennessee Valley Authority. 83/07/21. ADENSAM, E. Licensing Branch 4. 16pp. 19726:214. 24X Fiche: 50-390, 83/07/21, 8307260297.
- 8307290148 Forwards final response to NUREG-0737, Item II.D.1.
  "Performance Testing of PWR Relief & Safety Valves."
  KAMMER.D.S. Tennessee Valley Authority. 83/07/22. ADENSAM.E.
  Licensing Branch 4. 8pp. 19821:053. 24X Fiche:50-390,83/07/22.
  8307290148.
- B307290131 Forwards proposed mods to NRC draft version of Tech Specs.
  Resolution of outstanding items & issuance of proof &
  review Tech Specs requested at earliest date possible. Unit 1
  fuel load scheduled for Jan 1984.
  KAMMER.D.S. Tennessee Valley Authority. B3/07/27. ADENBAM.E.G.
  Licensing Branch 4. 2pp. 19816:001. 24X Fiche: 50-390, 83/07/27,
  B307290131.

- --8307270155 Proposed mods to draft Tech Specs. \* Tennessee Vailey Authority. 83/07/27. 466pp. 19816:003. 24X Fiche: 50-370,83/07/27,8307270151.
- F. Security, medical, emergency & fire protection plans
- 8307050226 Responds to Generic Ltrs 82-28 & 82-33 & NUREG-0737, Item II.F. 2 re detection on inadequate core cooling Reactor vessel level instrumentation sys will be installed before fuel load, for operator training & familiarization.
  MILLS, L.M. Tennessee Valley Authority. B3/06/29. ADENSAM. E. Licensing Branch 4. 2pp. 19198:333. 24x Fiche: 50-390.83/06/29, 8307050226.
- B307110054 Submits revised implementation schedule for prompt notification sys. All fixed sirens installed & preoperationally tested. Revs due to rescheduled fuel load dates.

  MILLS.L.M. Tennessee Valley Authority. B3/07/01. ADENSAM.E. Licensing Branch 4. 2pp. 19375:018. 24X Fiche: 50~390, 83/07/01, B307110054.
- N. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010284 Amend 48 to FSAR.

  \* Ternessee Valley Authority. 83/07/01. 355pp. 19191:070. 24X
  Fiche: 50-390.83/07/01.8307010284.
- O. Inspection reports, IE Bulletins & correspondence
- 8307140064 Forwards IE Insp Repts 50-390/83-18 & 50-391/83-14 on 830423-0521.No noncompliance noted. VERRELLI.D.M. Division of Project & Resident Programs. 83/06/24. PARRIS.H.Q. Tennessee Valley Authority. 2pp. 19514:108. 24X Fiche: 50-390.83/06/24.8307140064.
- --8307140069 IE Insp Repts 50-390/83-18 & 50-391/83-14 on B30423-0521. No noncompliance noted. Major areas inspected: review of open items (IE bulletins, const deficiency repts, deviations & violations) & concrete placement & curing.

  HEATHERLY, T. L., SMAN, W. B. Region 2, Office of Director.

  GUICK, D. R. Division of Project & Resident Programs. B3/06/24.

  7pp. 19514:110. 24X Fiche: 50-390, B3/06/24, B307140064.
- 8307120481 Documents 830429-30 discussions w/NRC re preoperational tests for thermal expansion snubber movement exam & preservice insp requirements on snubbers, per FSAR Question 112, 39. Info documented in submittal prior to fuel load.
  MILLS.L.M. Tennesses Valley Authority, 83/07/07. ADENBAM.E. Licensing Branch 4. 3pp. 19425:064. 24X Fiche: 50-390,83/07/07,8307120481.
- 8306270401 IE Info Notice 83-46, "Common Made Valve Failures Degrade Surry Recirculation Spray Subsystem." Evo list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11,8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14, Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- S. Reportable occurrences. LERs & related correspondence
- B307120250 Second interim deficiency rept re nondivisional power received by transfer switches to auxiliary feedwater sys. Initially reported on B30202. Redundant circuits identical to existing design provided. Next rept expected by B30927. MILLSL.H. Tennessee Valley Authority. B3/06/27. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19423:035. 24X Fiche: 50-000, B3/06/27, B307120250.
- 8307120160 Final deficiency rept re cross-trained diesel generator HX inlet valves. Initially reported on 830531. Logic. schematic & connection drawings reviewed & checked against mechanical flow diagrams for compatibility.

  MILLS.L.M. Tennessee Valley Authority. 83/06/28. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19423:144. 24X Fiche: 50-390, 83/06/28, 8307120160.

- 8307120180 Final deficiency rept me diesel generator noom exhaust fans exhibiting higher than specified vibration amplitudes at initial startup.Initially reported on 810831. Rotational speed of fans increased by changing pitch of sheave. MILLS.L.M. Tennessee Valley Authority. 83/06/28. DTREILLY.J.P. Region 2. Office of Director. 2pp. 19423:339. 24X Fiche: 50-390.83/06/28.8307120180.
- 8307120577 Final deficiency rept re loosening of yalk holddown nut mfg by Masoneilan Inti Initially reported on 820801 Condition not reportable under 100FR30, 55(e).
  MILLS,L.M. Tennessee Valley Authority, 83/06/29, 0'REILLY,J.P. Region 2, Office of Director. 2pp. 19432,166, 24X Fiche: 50-390,83/06/29,8307120577.
- B30711050B Final deficiency rept for Unit 1 & sixth interim deficiency rept for Unit 2 re thermal range for auxiliary feedwater sys incorrectly analyzed. Initially reported on 811022. Range corrected. Next rept for Unit 2 due 840109.
  MILLS.L.M. Tennessee Valley Authority. B3/06/30. O'REILLY.J.P. Region 2. Office of Director. 2pp. 19380:091. 24X Fiche: 90-390.83/06/30.830711050B.
- 8307120179 Final deficiency rept re steam generator water level ref column error. Initially reported on 790706. Sensing lines will be thermally insulated & low-low water level setpoint will be adjusted. Also reportable under Part 21. MILLS, L. M. Tennesses Valley Authority. 83/06/30. D'REILLY, J. P. Region 2. Dffice of Director. 3pp. 19424:001. 24X Fiche: 50-390.83/06/30.8307120179.
- 8307120398 Final deficiency rept re safety injection sys train B flow below required level. Initially reported on 800501. RHR HX sutlet valves 1-FCV-74-16 & 28 will be operated at 79 degrees open.

  MILLS, L. M. Tennessee Valley Authority. 83/06/30. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19433:007. 24X Fiche: 30-370.83/06/30, 8307120998.
- 8307150207 Sixth interim deficiency rept re containment spray miniflow valve design error. Initially reported on 820305. Engineering Change Notice 3420 under review for closure. Next rept will be provided by 830928. Also reportable per Part 21.
  MILLS, L. M. Tennessee Valley Authority. 83/07/06. D'REILLY, J. P. Region 2. Office of Director. 19. 19530: 234. 24X
  Fiche: 50-390, 83/07/06, 8307150207.
- 8307150236 Final deficiency rept re summation of loads in STRUDL Code. Initially reported on 830215. Defective code platform discovered in one program application corrected. Designers notified of correct computer commands.
  MILLS.L.M. Tennessee Valley Authority. 83/07/07. D'REILLY, J. P. Region 2. Office of Director. 2pp. 1930: 207. 24X
  Fiche: 50-390. 83/07/07. 8307150236.
- 8307220554 Final Deficiency Rept 81-87 & sixth interim Deficiency Rept 81-83 re incorrect modeling of Feedwater piping valves for Unit 1 & Unit 2 respectively. Initially reported on 811007. Next rept for Unit 2 will be submitted by 840917. MILLS,L.M. Tennessee Valley Authority. 83/07/13. O'REILLY,J.P. Region 2. Office of Director. 4pp. 19686:059. 24X Fiche: 50-390.83/07/13.8307220554.
- 8307250292 Fourth interim deficiency rept re lack of evidence that auxiliary feedwater pump components meet code requirements. Initially reported on 820330. Cause under investigation. Components installed to Class C requirements. MILLS, L. M. Tennessee Valley Authority. 83/07/18. 0'REILLY, J. P. Region 2. Office of Director. 1p. 19705:313. 24X Fiche: 50-390,83/07/18,8307250292.
- 8307250395 First interim deficiency rept re high pressure fire protection piping water danger to shutdown board transformers. Initially reported on 830616. Piping will be supported to insure pressure boundary integrity.

  MILLS,L.M. Tennessee Valley Authority. 83/07/18. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19701: 324. 24X
  Fiche: 50-390, 83/07/18, 8307250395.
- 8307250405 Final deficiency rept re cable separation in ERCW intake pumping station. Initially reported on 811204 Drawing revised to add 1 h rated fire barrier protection for Train 8 syscables. Corrective actions will be completed by 830901. MILLS.L.M. Tennessee Valley Authority. 83/07/19. 0'REILLY, J P. Region 2. DFfice of Director. 2pp. 19703:213. 24X Fiche: 50-390,83/07/19,8307250405.
- 8307260434 Third interim deficiency rept re use of digitized response spectra data. Initially reported on 820422. Util still in process of implementing Engineering Change Notice 3481. Nert rept will be submitted by 830922.

  MILLSI.M. Tennessee Valley Authority. 83/07/20. O'REILLY, J. P. Region 2. Office of Director. ip. 19734:177. 24X Fiche: 50-390, 83/07/20, 8307260434.

- 8307270034 Final deficiency rept for Watts Bar & Items 2 & 4 of Osileforte & Sixth Interim Deficiency Rept Item 3 for Belieforte re engineering change review & handling Initially reported on Bil215 Next Belieforte rept by B31021.

  MILLS: UM Tennessee Valley Authority. 83/07/20. 0/REILLY, J. P. Region 2. Office of Director. 7pp. 19822:142. 24X

  Fiche 50-003.83/07/20.8307290034.
- G307260520 Suppl to B30628 Final Deficiency Repts 81-73 & B1-69 re diesel generator room exhaust fan mod Initially reported on B10831 Deficiency also reportable per Part 21.
  MILLS.L M Tennessee Valley Authority, B3/07/21. O'REILLY, J. P. Region 2. Office of Director. 1p. 19731:288. 24X Fiche 50-390,63/07/21, B307260520.
- 8307290172 Third interim deficiency rept re lack of qualification for ambedment plates identified during review of nonconformance concerning angineering change notices: Initially reported on B11215 Nonconformance rept under review. Next rept by 830929. MILLS.L. H. Tennessee Valley Authority. 83/07/22. D'REJLLY, J. P. Region 2. Office of Director. 3pp. 19821:044. 24X Fiche 50-390,83/07/22,8307290172.
- 8307290176 First interim deficiency rept re sensing of pipe breaks in component cooling sys. Initially repurbed on 830624. Installation of flow differential measuring device being investigated. Next rept expected by 830915. MILLS-L H. Tennessee Valley Authority. 83/07/22. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19821:156. 24X Fiche 50-390.83/07/22.8307290176.
- DGCKET 50-395 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- G307140219 Ack receipt of B21228 itr re planned G30316 radiological electric Detailed scenario will be reviewed when received & any additionments will be discussed via telcon w/emergency preparedness coordinator.

  STOHR. J.P. Davision of Emergency Preparedness & Materials Safety.
  B3702709. DISGN.O.M. South Carolina Electric & Gas Co. 1p.
  19323: 165 24% Fiche: 50-395. B3702709, B307140219.
- 6307140188 Documents training & experience for NRC & contract personnel observing 830315-16 seergency exercise. Listed personnel had radiation protection training & previously observed seergency preparedness excercises.

  STOHR. J. P. Division of Emergency Preparedness & Materials Safety. B3703708 DIXON. O. W. South Carolina Electric & Gas Co. 2pp. 19522.086 24X Fiche: 50-395.83/03/08.8307140188.
- 9307140213 Responds to notice of violation in IE Insp Rept 30-395/83-05 Corrective action: operations personnel counseled on importance of controlled operations of safeguards equipment & Operating Procedure SOP-505 revised. DIXON.O M. South Carolina Electric & Gas Co. 83/05/04. O'REILLY.J.P. Region 2. Office of Director. Jpp. 19522:018. 24X Fichs. 50-395.83/05/04.8307140213.
- 8307220270 Approves issuance of SALP Rept 50-395/83-16 for Apr 1982 Feb 1983 O'REILLY, J P. Region 2, Office of Director. 83/07/12. DIXON, D. H. South Carolina Electric & Gas Co. 2pp. 19684:262. 24x Fiche: 50-395, 83/07/12.8307220270.
- --8307220273 Forwards SALP Rept 50-395/83-16 for Apr 1982 -- Feb 1983. LEWIS.R C. Division of Project & Resident Programs. 83/05/20. DIXON.O W. South Carolina Electric & Gas Co. 3pp. 19684:264. 244 Fiche 50-395.83/07/12.8307220270.
- --8307220275 SALP Rept 50-395/83-16 for Apr 1982 Feb 1983. \* Region 2, Office of Director. 83/05/20. 18pp. 19684:267. 24X
- --8307220283 Act receipt of SALP Rept 50-395/83-16 for Apr 1982 Feb 1983 No comments offered. DIXON O W South Carolina Electric & Gas Co. 83/06/16. O'REILLY, J.P. Region 2. Office of Director. 1p. 19684:285. 24X Fiche 30-395.83/07/12.8307220270.
- 8307270177 Releases public version of rev to radiation emergency plan. FELTON, J. B. Division of Rules and Records. B3/07/19. Document Management Branch. 1p. 19811:073. 24X Fiche: 50-395,83/07/19, 8307270177
- --8307270182 Public version of Rev 10 to Radiation Emergency Plan EP-100. N/B30630 ltr BEALE.K.E. KDDF.A.R. DIXON.D.W. South Carolina Electric & Gas Co. B3/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation, Director 29sp 19811:074. 24x Fiche:30-395.83/07/19.8307270177.

- B307260340 Updates B30415 response to Generic Ltr B2-33 (NUREG-0737, Suppl 1) re emergency response capability. Summary repts recontrol room design review. post-accident monitoring & emergency operating procedures will be submitted by B41230. DIXON.O.W. South Carolina Electric & Gas Co. B3/07/21. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19726:330, 24X Fiche: 50-395, B3/07/21, B307260340.
- H. General correspondence
- 8307190416 Advises that recipient status of NRC correspondence w/util re CL proceedings discontinued Documents will be made available in LPDR & significant events will be publicly announced.

  ADENSAM.E. C. Licensing Branch 4. 83/07/08. BURSEY, B. A. Bursey, B. ip. 19556:080. 24X Fiche: 50-395, 83/07/08, 8307190416.
- P. Operating license stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensess; applicants for DLs & holders of CPs for Westinghouse PWRs rs safety evaluation of "Emergency Response Guidelines." Svc list encl.
  E198NMUT.D.G. Division of Licensing. 83/06/03. Yankse Atomic E1ectric Co. 10pp. 19563:116. 24X Fiche: 50-000,83/06/03, 8306060070.
- 8307110616 Monthly notice of amends to OLs involving NBHC issued since 830523. CLARK,R.A. Operating Reactors Branch 3. 83/06/14. 26pp. 19391:152. 24X Fichs:50-000/83/06/14.8307110616.
- 8307140402 Forwards request for addl info re current QA program. Info required within 3D days to complete evaluation of proposed changes to program.

  LEMIS.R.C. Division of Project & Resident Programs. 83/06/16.

  DIXON, O. W. South Carolina Electric & Gas Co. 2pp. 19314: 046. 24X Fiche: 50-395, 83/06/16, 8307140402.
- 8307050209 Forwards, for review, safety analysis & details of mechanical relief valves in RHR sys for mitigating overpressurization during low temp operation.

  DIXON, D. M. South Carolina Electric & Gas Co. 83/06/29. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 9pp. 17198; 288. 24X Fiche: 50-375, 83/06/29, 8307050209.
- B307060272 Advises that life cycle program for reactor trip breakers scheduled to begin in early Jul & will require approx 2 months to complete. Commitment of B30608 to provide scope & schedule for life cycle program complete. DIXON.O.M. South Carolina Electric & Gas Co. B3/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19234: 206. 24X Fiche: 50-393, 83/06/30, 8307060272.
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc ltst encl.
  EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 17370:317. 24X
  Fiche: 50-000,83/07/05,8306270397.
- B307060329 Generic Ltr B3~27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STB. Svc list encl. EISEMHUT.D. Q. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50~000, 83/07/06, B307060329.
- 8307140111 Responds to 830620 request for review of applicability of License Condition 2.0(22) to startup tests scheduled for 100% power. Restriction in License Condition 2.0(22) does not apply to startup tests.

  NOVAK,T.M. Assistant Director for Licensing. 83/07/07. DIXON.O.W. South Carolina Electric & Gas Co. 2pp. 19528:110. 24X Fiche: 50-395, 83/07/07, 8307140111.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Bvc list encl. EISENWINT, D. G. Division of Licensins. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669; 269. 24x. Fich: 50-000, 83/07/08, B307080169.
- B307200537 Accepts process control program for solidification & packaging of wet solid wastes submitted on B30412. Program utilizes Chem Nuclear Sys, Inc cement solidification sys discussed in Topical Rept CNSI-2, 4313-01334-01. Rev 2. NDVAK, T. M. Assistant Director for Licensing. B3/07/12. DIXON, D. W. South Carolina Electric & Gas Co. 1p. 19671: 343. 24X Fiche: 30-395, 83/07/12, 830/200537.

- B307220380 Forwards noncontrolled versions of station emergency procedures for post-reactor trip reviews Addl revs may be necessary to meet requirements of Generic Ltr 83-28 re generic implications of Galem ATMS events.

  DIXON.O.M. South Carolina Electric & Gas Co. B3/07/15. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19686:132. iche: 50-395, 83/07/15, 8307220380
- --8307220383 Noncontrolled version of Rev 1 to Station Administration Procedure SAP-132. "Off-Normal Occurence Evaluation. Reporting & Resolution." \* South Carolina Electric & Gas Co. 83/07/14. 19pp. 19686:134. 24X Fiche: 50-395,83/07/15,8307220380.
- --8307220387 Noncontrolled version of Rev 6 to Emergency Operating Procedure EOP-5, "Recovery from Reactor Trip." WQDDWARD, K. W., WILLIAMS, B. C. South Carolina Electric & Gas Co. 83706/16, 15pp. 19686:153, 24X Fiche: 50-395, 83/07/15, 8307220380.
- --8307220413 Noncontrolled version of Rev 3 to Emergency Operating Procedure EGP-10, "Malfunction of Control Rud Sys." THIDAU, H.P., WOODWARD, K.W. South Carolina Electric & Gas Co. 82/12/27, 17pp. 19686:168. 24X Fiche:50-399,83/07/15,8307220360.
- 8307260394 Application to amend License NPF-12, changing Tech Specs to reflect installation & calibr of condensate demineralizer backwash effluent monitor RM-Li1 prior to startup after first refueling outage.

  DIXON, G. W. Bouth Carolina Electric & Gas Co. 83/07/22. DENTON, H. f. Office of Nuclear Reactor Regulation. Director. 2pp. 19733:125. 24X Fiche: 50-395,83/07/22,8307260394. DENTON, H. R.
- ---8307260399 Proposed Tech Spec changes reflecting installation & calibr of condensate demineralizer backwash effluent monitor RM-Lit. RM-L1t. \* South Carolina Electric & Qas Co. 83/07/22. 6pp. 19733:127. 24X Fiche: 50-395,83/07/22,8307260394.
- B307260461 Application for amend to License NPF-12 transferring Item (b) & (c) of Tech Spec Surveillance Requirement 4.7.4, "Svc Water Sys," to Surveillance Requirement 4.6.2.3 Item (b), "Reactor Bldg Cooling Sys." DIXON.O.W. South Carolina Electric & Oas Co. B3/07/22. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19734:012. 24X Fiche: 50-375,83/07/22,8307260461.
- --8307240463 Proposed Tech Spec changes re surveillance requirements. \* South Carolina Electric & Gas Co. 83/07/22. 3pp. 19734:014. 24X Fiche: 50-395,83/07/22,8307260461.
- 8307260465 Application for amend to License NPF-12, changing Tech Specs Tables 4,6-1a,4,6-1b & 4,6-2 re containment structural integrity.
  DIXON, O. W. South Carolina Electric & Qas Co. 83/07/22. DENTON, H
  Office of Nuclear Reactor Regulation, Director. 2pp. 19731: 164.
  24X Fiche: 50-395, 83/07/22, 8307260465. DENTON, H. R.
- --0307260469 Proposed Tach Spec changes re containment structural integrity. \* South Carolina Electric & Gas Co. 83/07/22. 3pp. 19731:166. 24X Fiche:50-395.83/07/22.8307260465.
- B307270006 Application to amend License NPF-12, changing Tech Specs re administrative controls to reflect upper mgt organizational changes.

  DIXON.O. H. Bouth Carolina Electric & Gas Co. 83/07/22, DENTON. H. R. Diffice of Nuclear Reactor Regulation, Director. 4pp. 19765; 236. 24X Fiche: 50-395, 83/07/22, 8307270006.
- --B307270013 Proposed changes to Tech Specs Chapter & re administrative controls. Resumes for DA Nauman, KW Nettles, DR Moore & DB Bradham encl.

  \* South Carolina Electric & Gas Co. 83/07/22. 28pp. 19765:240. 24X Fiche: 50-395,83/07/22.8307270006.
- B307270018 Application to amend License NPF-12, changing Tech Spec
  Table 2.2-1 re reactor trip sys instrumentation trip
  setpoints to correct error in time constants for lead-lag
  compensation of measured delta 1,7av 1 & Tav 2.
  DIXON,O.W. South Carolina Electric & Gas Co. 83/07/22. DENTON,H.R.
  Office of Nuclear Reactor Regulation, Director. 2pp. 19749:319.
  24X Fiche: 50-395,83/07/22,8307270018.
- --8307270020 Proposed Tech Bpsc Table 2.2-1 re reactor trip sys instrumentation trip setpoints. \* South Carolina Electric & Gas Co. 83/07/22. 3pp. 19749:321. 24X Fiche: 50-395,83/07/22,8307270018.

- B307270062 Forwards steam generator nozzle mod radiological dose companisons, per 830503 commitment Actual dose received distinctly lower than estimated dose.

  DIXON.D.W. South Carolina Electric & Gas Co. B3/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19749:343. 24X Fiche 50-395, B3/07/22, 8307270062.
- 8307270092 Advises that review of design change package, per 830608 commitment, will be provided for approval by 830901 % referenced in util formal response to Generic Ltr 83-28. DIXQN.O.W. South Carolina Electric & Gas Co. 83/07/25. DENTON, Office of Nuclear Reactor Regulation. Director. 1p. 19822:205. 24X Fiche:50-395.83/07/25.8307290092.
- 8307270085 Advises that contract executed on 830629 w/BOE for disposal of spent nuclear fuel &/or high level radwaste.per Nuclear Maste Police Act of 1982 & Generic Ltr 83-07.
  DIXON,O.W. South Carolina Electric & Gas Co. 83/07/26. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19822:204.
  24X Fiche:50-395,83/07/26,8307270085.
- Q. Inspection reports. IE Bulletins & correspondence
- 8307140273 Informs that project inspiresponsibilities within Region II for facility transferred to Div of Project & Resident Programs, effective 830314.

  LEWIS, R. C. Division of Project & Resident Programs. 83/04/12.

  DIXON, O. W. South Carolina Electric & Gas Co. 19. 19522:327. 24X Fiche: 50-395, 83/04/12, 8307140273.
- 8307140213 Responds to notice of violation in (E Insp Rept 50-395/83-05 Corrective action: operations personnel counseled on importance of controlled operations of safeguards equipment & Operating Procedure SOP-505 revised. DIXON O W South Carolina Electric & Gas Co. 83/05/04. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19522:018. 24X Fiche: 50-395, 83/05/04, 8307140213.
- 8307140250 Suppls 830422 ltr re IE Bulletin 8i-01 concerning inspresults for safety-related snubbers. Corrective actions implemented/completed u/exception of adding special caution to procedures for handling & abuse of snubbers.
  DIXON.O.M. South Carolina Electric & Gas Co. 83/06/30.
  O'REILLY.J.P. Region 2. Office of Director. 2pp. 19523.046.
  Fiche: 50-395.83/06/30.8307140250. 19523: 046. 24X
- B307210197 Forwards IE Insp Rept 50-395/83-20 on 830414-18.No oracion liance noted.

  VERRELLI,D.M. Division of Project & Resident Programs. 83/07/
  DIXUN,D.W. Bauth Carolina Electric & Gas Co. 2pp. 19669:062.

  Fiche: 50-395.83/07/01.8307210197.
- --B307210201 IE Insp Rept 50-395/B3-20 on 830514-18 No noncompliance noted Major areas inspected: startup test program & open item followsp.
  BURNETT,P.T. Region 2. Office of Director. JAPE.F. Division of Engineering & Radiological Safety Programs. 83/06/29. 5pp. 19669.064. 24X Fiche: 50-395,83/07/01,8307210197.
- 830627040) IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystam." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche: 50-000, 83/07/11, 8304270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JCRDAN.E.L. Division of Emergency Proparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8307220270 Approves issuance of SALP Rept 50-395/83-16 for Apr 1982 Feb 1983. O'REILLY, J.P. Region 2. Office of Director. 83/07/12. DIXON.O.W. Sauth Carolina Electric & Qas Co. 2pp. 19684:262. 24X Fiche: 50-395.83/07/12.8307220270.
- --8307220273 Forwards SALP Rept 50-395/83-16 for Apr 1982 Feb 1983. LEMIS.R.C. Division of Project & Resident Programs. 83/05/20. DIXON.O.W. Sauth Carolina Electric & Gas Co. 3pp. 19684: 264. 24X Fiche: 50-395, 83/07/12, 8307220270.
- --8307220276 SALP Rept 50-395/83-16 for Apr 1982 Feb 1983. # Region 2. Office of Director. 83/05/20. 18pp. 19684:267. 24X Fiche:50-395.83/07/12,8307220270.
- --8307220283 Ack receipt of SALP Rept 50-395/83-16 for Apr 1982 Feb 1983. No comments offered.

  DIXON.O.W. South Carolina Electric & Gas Co. 83/05/16.

  D'REILLY, U.P. Region 2. Office of Director. 1p. 19484:285. 24: Fiche. 50-395,83/07/12,8307220270. 83/06/16. 1p. 19684:285. 24X

- 8307220464 Ack receipt of 830629 request for add1 time to correct Violation C re operator training noted in IE Insp Rept 50-395/83-08. Interim corrective measures satisfactory. Completion date extended to 830812. LENIS.R C. Division of Project & Resident Programs. 83/07/13. DIXON.O.W. South Carolina Electric & Gas Co. 1p. 19685:100. 24: Fiche: 50-395, 83/07/13, 8307220464.
- --8307220473 Responds to NRC B30413 ltr re violations noted in IE Insp. Rept 50-395/83-08. Corrective actions: issuance of Training Procedure III. A. 4 expected by B30630. Extension of completion date to B30815 requested.

  DIXON.O.W. South Carolina Electric & Gas Co. B3/06/29.

  G'REILLY, J. P. Region 2, Office of Director. 2pp. 19685:101. 24X Fiche: 50-395,83/07/13.8307220464.
- 8307220548 Ack receipt of 830701 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-395/83-15.
  LEMIS.R.C. Division of Project & Resident Programs. 83/07/13.
  BIXON, D.W. South Carolina Electric & Gas Co. 1p. 19686:005. 24)
  Fichs: 50-395, 83/07/13, 8307220548.
- --8307220552 Responds to NRC 830630 ltr re violations noted in IE Insp. Rept 50-395/83-15. Corrective actions: all administrative procedures & changes reviewed & approved Technician counseled re deviations from procedures.

  DIXON.O. W. South Carollina Electric & Gas Co. 83/07/01.

  D'REILLY, J. P. Region 2, Office of Director. 9pp. 19686:006. 24X Fiche: 50-395, 83/07/13, 8307220548.
- ---B307220557 Forwards IE Insp Rept 50~395/83-t5 on B30401-0506 & notice of violation.

  LENIS,R.C. Division of Project & Resident Programs, B3/06/03. DIXON.O. W. Bouth Carelina Electric & Gas Co. 2pp. 19686:015. 24X Fiche: 50-395, B3/07/13, B307220548.
- --8307220559 Notice of violation from insp on 830401-0504. • Region 2. Office of Director. 83/06/03. 2pp. 19686:017. 24X Fiche. 50-395, 83/07/13, 8307220548.
- --B307220563 IE insp Rept 50-395/83-15 on B30401-0506. Noncompliance noted: failure to follow procedures, failure to perform plant safety review committee review & failure to perform 10CFR50. B9 safety evaluation. SKOLDS.J. L. Region 2. Office of Director. CANTRELL.F. S. Division of Project & Resident Programs. 83/06/02. 9pp. 19686:019. 24X Fiche: 50-395.83/07/13.8307220548.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Ercess of NRC Limits." Syc list ancl.

  TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24x Fiche: 50-000, 83/07/14, 8306270406.
- B307220099 Ack receipt of B30622 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-393/B3-09. Sys Operating Procedure S0P-201. "Main Steam Sys." re draining steam generator would be most appropriate procedure. LEMIS.R.C. Division of Project & Resident Programs. B3/07/14. DIXON.O.M. South Carolina Electric & Gas Co. 1p. 19674:031. 24x Fiche: 50-395, B3/07/14. B307220059.
- --8307220065 Responds to NRC 830523 ltr re violations noted on IE Insp. Rept 50-395/83-09. Corrective actions: Station Order 83-04 initiated on 830311 to record & track rotation of gas decay tanks & plant operator logs revised.

  PLXON. O. W. South Carolina Electric & Das Cu. 83/06/22.

  O'REILLY, J. P. Region 2, Office of Director, App. 17674: 032. 24X Fiche: 50-395, 83/07/14, 8307220059.
- --8307220068 Forwards IE Insp Rept 50-375/83-09 on 830305-0401 % notice of violation.

  LEWIS.R.C. Division of Project & Resident Programs. 83/05/23.

  DIXON.D.W. South Carolina Electric & Gas Co. 2pp. 19674:038.

  24X Fiche: 50-375, 83/07/14, 8307220059.
- --8307220070 Natice of violation from insp on 830305-0401. + Region 2, Office of Director. 83705/23. 2pp. 19674:040. 24x fiche: 50-395, 83/07/14:8307220059.
- --8307220078 IE Insp Rept 50-395/83-07 on 830305-0401.Noncompliance noted: failure to fullow gas decay tank procedure & failure to provide adequate procedure re removal of power to RHR SKOLDS, J. L. Region 2, Office of Director. CANTRELL, F. S. Division of Project & Resident Programs. 83/05/16. 9pp. 19674:042, 24X Fiche: 50-395, 83/07/£4,8307220059.

- A. Periodic operating reports & related correspondence
- 8307220172 Monthly operating rept for May 1983. W/830615 ltr.
  TAYLOR.O.J. DIXON.O.W. South Carolina Electric & Gas Co. B3/06/15.
  BARRY.L.W. Diffice of Resource Management. Director. 5pp.
  19684:084 24x Fiche: 30-395. B3/06/15. B307220172.
- S. Reportable occurrences, LERs & related correspondence
- B307270373 Forwards AEOD technical review rept, "Inadvertent Safety Injections Attributed to Personnel Error: "Rept addresses info contained in special rept dtd 830415 submitted by util. AEOD should perform suggested followup actions. ASHE, F. Reactor Operations Analysis Branch. B3/06/14. SEYFRIT, K. V. Reactor Operations Analysis Branch. 2pp. 17857:068. 24X Fiche: 50-375, 83/06/14, 8307270373.
- ~-8307290401 "Inadvertent Safety Injections Attributed to Personne? Error." AEDD technical review rept. ASHE,F. Reactor Operations Analysis Branch. 83/06/14. 3pp. 19837:070. 24X Fiche: 50-395, 83/06/14, 8307290393.
- B307120260 LER 83-051/03L-0:on B30524.control room evacuation panel pressurirer relief tank level indicator ILI-470A removed from svc due to low readings. Caused by instrument drift. Upgraded electronic cards installed. WH30622 ltr. KOLB, L. E. DIXON. O. M. Bouth Cardina Electric & Gas Co. B3/06/22. O'REILLY, J. P. Region 2, Office of Director. 4pp. 19419:334. 24) Fiche: 50-395, B3/06/22, B307120260.
- 8307120458 LER 83-54/03L-0: on 830601 plant auxiliary relay rack XPN-6034 balance declared inoperable due to power failure. Caused by loose fuse holder on power supply module grounding supply Module replaced W/830630 ltr. BOUKNIGHT.R.J., DIXON,O.W. South Carolina Electric & Oas Co. 83/06/30. D'REILLY,J.P. Region 2, Office of Director. 2pp. 19425:395. 24x Fiche: 50-395,83/06/30,8307120458.
- B3071200B1 LER 83-056/03L-0: on B30606, feedwater flow transmitter (FT-469) steam generator B failed low.Caused by failure of power supply card. Card replaced. W/830701 ltr. B3UKNIGHT,R.J., DIXUN.GL.W. Sauth Carolina Electric & Gas Co. B3/07/01. D'REILLY, J. P. Region 2, Office of Director. 2pp. 19423:044. 24X Fiche: 50-395, B3/07/01, B3071200B1.
- 9307120196 LER B3-057/03L-0: on B30606, nitrogen low pressure alarm on low pressure accumulator for PORV received in control room. Caused by valve position indicator lights not showing full actual position. Limit switches adjusted. W/B30701 ltr. WOLB-L. E., DIXON, O. W. South Carolina Electric & Gas Co. B3/07/01. D'REILLY, J. P. Region 2, Diffice of Director. 3pp. 17423:314. 24N Fiche: 30-395, B3/07/01, B307120196.
- 8307110210 LER 83~055/03L-D: on 830607 & 10, smoke detectors in control bidg Zone A failed Caused by welding in area.Fire watch patrol initiated & affected detectors & deluge resettled. W/830706 ltr.
  BOUKNIGHT.R.J., DIXON.O.W. South Carolina Electric & Gas Co. B3/07/06. D'REILLY, J. P. Region 2, Office of Director. 2pp. 19380: 078. 24X Fiche: 50-375, 83/07/06, 8307110210.
- 8307110262 Updated LER 83-054/03L-1: on 830601, power failure occurred, defeating one QPM leakage alarm for reactor bidg sump. Caused by loose power supply module fuse holder grounding power supply, Module replaced. W/830706 ltr.
  BOUKNIOHT.R. J. DIXON, D. W. South Carolina Electric & Qas Co. 83/07/06. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19379: 161. 24X Fiche: 50-395, 83/07/06, 8307110262.
- 8307110370 LER 83-058/03L-0: on 830607, smoke detector IXA-49930 failed to respond to simulated alarm. Caused by broken base assembly in detector due to open circuit preventing alarm condition. Component replaced. W/B30706 ltr.
  MCKINNEY, C. J., DIXON, D. W. South Carolina Electric & Oas Co. 83/07/06. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19380: 228. 24X Fiche: 50-395, 83/07/06, 8307110370.
- 8307220274 LER 83-059/03L-0: on 830609 & 0702, refueling water storage tank level transmitter failed high Caused by intermittent internal component breakdown when transmitter temp exceeds 100 F. Transmitter will be replaced W/830708 Itr. MCKINNEY, C. J. DIXON, C. W. South Carolina Electric & Gas Co. 83/07/08. 0'REILLY, J. P. Region 2, Office of Director. 4pp. 17684: 131. 24X Fiche: 50-395, 83/07/08, 8307220274.
- B307220284 LER B3-060/03L-0: on B30609, boron injection tank boron concentration fell below Tech Specs. Caused by overpressurized sus, resulting in relief valve actuation. Procedures revised M/B30708 ltr.
  BOUKNIGHT, R. J. DIXON, O. W. South Carolina Electric & Gas Co. 83/07/08. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19684: 154. 24X Fiche: 50-395, 83/07/08, 8307220284.

- 8307220454 LER 83-061/03L-0: on 830610, identified surveillance requirements for 6-inch containment purge supply & exhaust isolation valves not fully conducted Caused by procedural inadequacy. Procedure developed W/830708 ltr. FIELDS,H.C., DIXON.D.W. South Carolina Electric & Gas Co. 83/07/08 O'REILLY,J.P. Region 2, Office of Director. 3pp 19686:118. 24X Fiche: 50-395, 83/07/08, 8307220454.
- 8307220256 LER 83-062/03L-0: on B30611 % 12, reactor bldg purge exhaust radiation monitor sample pump overload protector tripped. Gaused by loose motor controller electrical connections & defective pump bearing, Bearing replaced. W/B30711 ltr. ROUS.L.E., DIXON.O.W. South Carolina Electric & Sas Co. 93/07/11. 0'RESILLY.J.P. Region 2, Office of Director. 3pp. 19694: 225. 24X Fiche: 50-395, 83/07/11, 8307220256.
- B307220252 Updated LER 83-039/03L-1: on B30506 electrical power lost to RMB train B. Caused by main power supply fuse blowing during extender module installation. Fuse replaced. M/830712 ltr. HCKINNEY, C.U., DIXON, D. W. South Carolina Electric & Gas Co. 83/07/12. D'REILLY, J. P. Region 2. Office of Director. 3pp. 19684: 199. 24X Fiche: 50-395, 83/07/12, 8307220252.
- B30723013B LER B3-063/03L-0: on B30616 & 27, turbine bldg sump radiation liquid effluent monitor RML-B declared inoperable due to low sample Flow Caused by accumulation of trash in sample manitor inlet isolation valve. Valve cleaned W/B30614 ltr. BJUKKNGHT,R.J., DIXON.O.W. South Carolina Electric & Gas Co. B3/07/14. D'REILLY,J.P. Region 2, Dffice of Director. 2pp. 19706:097. 24X Fiche: 50-395,83/07/14. B30725013B.
- B307250496 LER 83-065/03L-0: on B30616, while in Mode 1, 8HR snubber RHH-0211 declared inoperable due to bearing protruded from paddle plate. Caused by vibrational effects induced by sys operation. Snubber repaired. W/B30714 ltr.
  BOUKNIGHT, R. J., DIXON, O. W. South Carolina Electric & Gas Co. 83/07/14. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19701: 273. 24X Fiche: 50-395, 83/07/14, 8307250496.
- 9307250515 LER 93-064/03L-0: on 830616, while in Mode 1, snubber MK-CCH-306 declared inoperable due to misalignment. Caused by inappropriate maint activity. Infor re snubber handling & care provided to personnel, W/830714 itr.
  BUUKNIGHT.R. J., DIXON, O. W. South Carolina Electric & Gas Co. 83/07/14. 0/REILLY, J. P. Region 2, Office of Director. 3pp. 19701: 266. 24X Fiche: 50-395, 83/07/14, 8307250515.
- 8307250201 LER B3-066/03L-0: on 830666, fire barrier Kanwool Wrap on conduit SMC-B7C in svc water pump house found torn. Caused by high traffic on access ladder. Damaged area expeditiously repaired. W/830715 ltr.
  KOLB: L. E. DIXON: O. W. South Carolina Electric & Gas Co. 93/07/15. G/REILLY, J. P. Region 2. Office of Director. 3pp. 19705: 345. 24X Fiche: 50-395, 83/07/15, 8307250201.
- 8307240557 LER 83-047/03L-0: from 830401 to 19, reactor bldg sump inventory not performed contrary to Tech Spec Surveillance Requirement 4. 4.6.2.1.b. Caused by personnel failure to implement alternative inventory method. W/830718 ltr. BOUXNIGHT, R. J., DIXON, O. W. South Carolina Electric & Gas Co. 83/07/18. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19732: 021. 24X Fiche: 50-395, 83/07/18, 8307240557.
- B307290175 LER 83-068/03L-0: on 830620, snubber FWH-1109 (feedwater sys) declared importable due to bearing offset. Caused by maint activity in immediate area. Bearing centered, restaked, tested & declared operable on 830620. W/830720 ltr.
  BOUKNIGHT, R. J., DIXON, O. W. South Carolina Electric & Gas Co. 83/07/20. 0'8EILLY, J.P. Region 2. Office of Director. 2pp. 19821: 050. 24X Fiche: 50-395, 83/07/20, 8307290175.
- 8307270186 LER B3-067/03L-0: on 830620, snubber FNH-0265 declared inoperable due to misalignment & bent paddle plate. Caused by transient loading during startup. Snubber replaced w/unit modified to suit dimensional requirements. W/830720 ltr. 8DUKN16HT.R. J., BIXON, J.P. South Carolina Electric & Gas Co. 83/07/20. 0'78EILLY, J.P. Region 2. Office of Director. 3pp. 19821: 104. 24X Fiche: 30-375,83/07/20,6307270186.
- DUCKET 50-394 UNIV. OF VIRGINIA CAVALIER REACTOR

  F. Security, medical, emergency & fire protection plans
- 8307210344 Brants extension until 830915 to respond to NRC questions on emergency plan, per 830624 request.
  THOMAS.C. O. Standardization & Special Projects Branch.
  BRENIZER, J. S. Vinginia. Univ. of, Charlottesville, VA. 19.
  19672:325, 24X Fiche:50-062,83/07/13,8307210344.

- B307250514 Releases public version of licensee request for extension for responding to emergency plan review.
  FELTON.J.M. Division of Rules and Records 83/07/19. Document Management Branch ip. 19725:361. 24X Fiche: 50-062
- --B307230521 Forwards public version of request for 60-day extension for responding to emergency plan review Extension needed to allow rewriting, review & approval of SOPs to improve reactor operations.

  BRENIZER, J. S. Virginia, Univ. of, Charlottesville, VA. 83/06/24.

  THOMAS, C. D. Standardization & Special Projects Branch. 19
  19720-341. 24X Fishe: 50-082, 83/07/19, 8307250514

### V. Operator Examinations

- E307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 37B, "Personal Gualifications Statement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche.30-000.83/07/11,8307080427.
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

  A. Application/construction stage documents & correspondence
- 8307050001 Submits lowest svc metal temp values for most limiting pressure boundary components & table for theoretical min wail thickness for valves RFM-V-65A/B based on hydro test pressures per 6DC 51.

  BOUCHEY.G. D. Washington Public Power Supply System. 83/06/15.

  BCHMENCER.A. Licensing Branch 2. 7pp. 19192:133. 24X

  Fiche: 50-397, 83/06/15, 8307050001.
- 8307050022 Forwards response to request for supporting documentation & per Tech Spec second draft discussed during 830523-24 meetings. Tentative schedule for preparation of proof & review copy listed.

  BOUCHEY. O. D. Washington Public Power Supply System. 83/06/15.

  SCHMENCER. A. Licensing Branch 2. 39pp 19220: 241. 24X

  Fiche: 50-397.83/06/15.8307050022.
- B30705025B Notification of Caseload Forecast Panel 830712-14 site visit & meeting w/HPPSS in Richland. HA to review project const & prooperational testing schedule. Agenda encl. AULUCK, R. Licensing Branch 2. 83/06/20. SCHWENCER, A. Licensing Branch 2. 4pp. 19241:015. 24X Fiche. 50-397. 83/06/20. 8307050258.
- B306270395 Generic Ltr 83-24 to all BMR applicants for OL & holders of OLs for Grand Gulf, LaBalle & Susquehanna re TMI Task Action Plan Item I.G. 1, "Special Low Power Testing & Training & Recommendations for BMRs." Svc list encl EISENHUT, D. G. Division of Licensing. B3/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche:50-000.83/06/29. B306270375.
- 8307070006 Forwards revised Vols 1-3 to "Environ Equipment Qualification Rept for Bafety-Related Equipment." Rev provides response to concerns raised in Suppl 3 to SER (NUREO-0892).
  BOUCHEY.C. D. Washington Public Power Supply System. B3/06/30. SCHWENKER. A. Licensing Branch 2. 3pp. 19295:138. 24X Fiche: 50-397, 83/06/30. 8307070006.
- --B307070013 Revised Vols 1-3 to "Environ Equipment Qualification Rept for Safety-Related Equipment." # Washington Public Power Supply System. B3/07/31. 1220pp. 17293 141. 24K Fiche: 50-397/83/06/30/8307070006
- B306270397 Generic Ltr B3-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impority Svc list enci. EISENHUT, D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270377.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in B18.5vc list encl. EISENHUT.D.G. Division of Licensing. B3/07/06. Consolidated Eisen Co. of New York, Inc. 16pp. 1969:254. 24X Fiche: 50-000, B3/07/06, B307060329.
- B307150227 Revisus B30615 ltr re QDC 51.based on discussions & agreements reached at B30616 meeting Encl provides lowest svc metal temp values superseding values previously provided.
  BDUCHEY, G. D. Washington Public Power Supply System. B3/07/07. BCHWENCER, A. Licensing Branch 2. 8pp. 19538:044. 24X Fiche: 50-397.83/07/07,8307150227.

- 8307080169 Deneric Ltr 83-28 to all licensees of operating reactors, applicants for CL & holders of CPs re required actions based on generic implications of Balem ATMS events Svc list encl. 8188AMDTLS G Division of Elicensing. 83/07/08. Consolidated Estion Co of New York. Inc. 38pp. 19669:269—24X Fiche 50-030.63/07/08.8307080169
- 63071F0213 Forwards proposed snubber Tech Spec for review as followup to 820314 to 0524 telcons Changes will not lessen assurance of structural integrity & functionality of safety-melated sys fiel load scheduled for Sept 1983 8000HEV. 3 D. Washington Public Power Supply System. 83/07/08. 51MHEMORE A. Licensing Branch 2. 2pp 19829:187. 24X Fiche t0-097.82/07/08.8307190213
- --8337190215 Proposed snubber Tech Spec.
   Washington Public Power Supply System. 83/07/08. Bpp. 1927 187 284 Fiche 307-097.83/07/08.8307190219.
- --8307170717 "Component Support Insp & Test Program Plan." FRILES L. Washington Public Power Supply System. 83/03/14, 18pp. 19627-177 244 Fiche: 50-397.83/07/08.8307190213.
- 8307200386 Forwards request for add1 info re procedures generation package transmitted w/830323 ltr.Response requested by 830722 SCHMENGER.A. Licensing Branch 2. 63/07/08. FERGUSON, R.L. Hashington Public Power Supply System. 6pp. 19669:337. 24X Fiche 30-397, 83/07/08, 8307200386.
- 8307190457 Notification of 830715 meeting w/util in Bethesda.MD to discuss containment out-of-roundness.

  AULUCK.R Licensing Branch 2. 83/07/11. SCHWENCER.A. Licensing Branch 2. 3pp. 19656:070. 24X Fiche:50-397,83/07/11.8307190459.
- B307:53222 Forwards list of remaining open items requiring resolution before finding of readiness for operation can be endorsed. Items include preoperational testing & radiation protection. MAPTIN-J B. Region 5. Office of Director. B3/07/12. EISENHUT.D.G. Division of Licensing. 6pp. 19538.244. 24X Fiche:50-397,83/07/12.6307150252
- G307200142 Forwards response to Phase II of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Items discussed include step plugs.vessel cavity plugs.dryer separator pool step plugs.fueling slot plugs to auxiliary hoist. SOMENSEN G C Washington Public Power Supply System. B3/07/IG SCHMENGER.A Licensing Branch 2. 9pp. 19651-011. 24X Fiche 50-397.93/07/IG.8307200142.
- 8307280359 Forwards info re as-built Seismic Category I Guality Class II hangers, spec requirement & documentation relative to hold-down bolts for reactor vessel to assist in resolution of issues raised by const assessment team. CAPLISLE: C S Washington Public Power Supply System. 83/07/15. MARTIN. J B Region 5. Office of Director 138pp. 19789: 056. 24X Fichs 50-397, 83/07/15. 8307280359.
- C Utility Environmental Report (ER), amends & correspondence
- G307260523 Forwards list of dates for issuance & espiration of permits & permit numbers per E Chan telcon request for status of various permits & licenses noted in Table 12.1-1 of environ SUFFUSEN.C C Washington Public Power Supply System. 83/07/19. SCHWEMSER.A Licensing Branch 2. 4pp. 19731:271. 24X
- E NAC Serety Evaluation Report (SER), supply & correspondence
- GD0713C19b Advises that NRC B30316 proposed commitment re turbine maint reviewed Turbine sys maint program will be submitted for NRC approval within 3 yrs of obtaining OL SER Outstanding 1sue 4 considered confirmatory issue.

  B004FEV.G.D. Hashington Public Power Supply System. 83/06/15.

  SCHMENCER.A. Licensing Branch 2. 1p. 19199.238. 24X

  Fiche. 30-397.83/06/15.8307050196
- B307040045 Responds to SER Suppl 2 (NUREQ-0892) & TM1 Action Item II k 3 28 re surveillance requirements to ensure operability of back-up air supply sys Requirement on calibr of bottle 34ujes (unlested & not included to 5.6 Specs Supply System. B3/06/22. 19250: 338. 24%
  - 'es Seismic & Hydrodynamic System. B3/04/22. '7'143. 24%

- --8307120313 "WPPSS 2 Purge & Vont Valves Seismic & Hydrodynamic Analysis " \* Washington Public Power Supply System. 83/06/30. 359pp 19427:165. 24X Fiche: 30-397, 83/06/22, 8307120309.
- B307050136 Forwards procedures for post-accident sample analysis & core damage evaluation.per NUREG-0892 (SER). Item II.B. 3 & Section 9.3.2.4.GE interim dissolved gas analysis w/o kryptom tracer expected by end of June 1983.
  BDUCHEY.G. D. Washington Public Power Supply System. B3/06/23.
  SCHWENGER.A. Licensing Branch 2. 2pp. 19199:080. 24X
  Fiche: 50-397. B3/06/23. B307050136.
- --8307050141 Draft Procedure 9.3.30. "WNP-2 Core Damage Evaluation." # Washington Public Power Supply System. 83/06/23. 44pp. 19199.082. 24X Fiche: 50-397.83/06/23.8307050136.
- --B307050151 Rev O to Chemistry Procedure 12.10.2, "Post-Accident Sampling & Analysis, Small Vol Liquid Analysis." MARTIN.J. Washington Public Power Supply System. 83/06/21. 4pp. 19199:126. 24X Fiche:50-397,83/06/23,8307050136.
- --8307050156 Rev O to Chemistry Procedure 12.10.3, "Post-Accident Sampling & Analysis, Determination of Chiorides."

  MARTIN.J. Washington Public Power Bupply System. 83/06/21. 4pp. 19199: 130. 24X Fiche: 50-397, 83/06/23, 8307050136.
- --B307050160 Rev O to Chemistry Procedure 12. 10. 4, "Post-Accident Sampling & Analysis, Determination of Boron."

  MARTIN. J. Washington Public Power Supply System. B3/06/21. 4pp 19199: 134. 24X Fiche: 50-397, 83/06/23, 8307050136.
- --8307050165 Rev O to Chemistry Procedure 12.10.5, "Post-Accident Sampling & Analysis, Gas Sample Analysis."
  MARTIN.J. Washington Public Power Supply System. 83/06/21. Gpp 19199: 138. 24X Fiche: 50-397, 83/06/23, 8307050136.
- --8307050167 Rev O to Chemistry Procedure 12.10.6, "Post-Accident Sampling & Analysis, Iodine & Particulate Filter Analysis." MARTIN.J. Washington Public Power Supply System. 83/06/21, 2pp. 19199:146. 24X Fiche: 50-397,83/06/23,8307050136.
- --B307050173 Rev O to Chemistry Procedure 12.10.7, "Post-Accident Sampling & Analysis, pH of Post-Accident Sample." MARTIN.U. Washington Public Power Supply System. B3/06/21. Usp. 19199:148. 24X Fiche: 50-397, 83/06/23, 8307050136.
- 8307050004 Forwards final response to NRC Questions 031.135.031.137 & 031.138 re control sys failures.per SER Dutstanding issue 13. Responses will be incorportated into FBAR Amend 31. BOUCHEY.6 D. Washington Public Pawer Supply Bystem. 83/06/24. SCHWENCER.A. Licensing Branch 2. 200pp. 19193:339. 24X Fiche: 50-397, B3/06/24, B307050004.
- 8307070006 Forwards revised Vols 1-3 to "Environ Equipment Oualification Rept for Safety-Related Equipment." Ray provides response to concerns raised in Suppl 3 to SER (NUREG-0892).
  BOUCHEY, G. D. Washington Public Power Supply System. 83/06/30. SCHMENCER. A. Licensing Branch 2. 3pp. 19275:138. 24X Fiche: 50-397, B3/06/30. B307070006.
- --B307070013 Revised Vols 1-3 to "Environ Equipment Qualification Rept for Safety-Related Equipment." \* Washington Public Power Supply System. 83/07/31. 1220pp. 19295: 141. 24X Fiche: 50-397.83/06/30.8307070006.
- 8307110007 Responds to NRC request for add1 info re SER Confirmatory Issue 7. "Component Supports." Results of evaluation in Phase II indicate that 175 supports & 16 anchors acceptable. BOUCHEY.c.D. Washington Public Power Supply Bystem. 83/06/30. SCHWENCER.A. Licensing Branch 2. Tipp. 19374:214. 24X Fiche:50-397,83/06/30.8307110007.
- B307260519 Requests relief from SER License Condition B requiring completion due date for relocation of instrument panel from HPC5 diesel generator skid, per B30616 telcon. Completion prior to startup after first refueling outage requested. SORENSEN, C. C. Washington Public Power Supply System. B3/07/19. SCHMENCER. A. Licensing Branch 2. 2pp. 19734:161. 24X Fiche: 50-397, 83/07/19. 8307260519.
- F. Security, medical, emergency & fire protection plans
- B307110317 Releases public version of revised emergency preparedness plan.
  FELTON, J. M. Division of Rules and Records. 83/06/24. Document Management Branch. lp. 19384:257. 24X Fiche:50-397,83/06/24.
  B307110317.

- ,8307i1032i Public version of Rev 3 to emergency preparedness plan consisting of drawings of backup emergency operations facilities at util headquarters in Richland.WA.W/830616 ltr. BOUCHEY, G. D. Washington Public Power Supply System. 83/04/30. BOUCHEY, T. M. Assistant Director for Licensing. 4pp. 19384:258. 24x Fiche: 50-397,83/06/24,8307110317.
- | 07120537 Responds to fire protection site audit concerns noted in g30413 trip rept. Corrective actions: fire detectors installed, instryment racks will be encl w/concrete & use of automatic sprinkler sys reevaluated. gDUCHEY. G. D. Washington Public Power Supply System. 83/07/01.gCHWENCER. A. Licensing Branch 2. 10pp. 19433:333. 24X fiche: 50-397.83/07/01,8307120539.
- 107270452 Forwards rept on safety parameter display sys safety analysis, per 830415 commitment & response to Generic Ltr 82-33. Suppl 1 to NUREG-0737. "Requirements for Emergency Response Capability."

  BOUCHEY.G. D. Washington Public Power Supply System. 83/07/01. 

  BCHMENCER.A. Licensing Branch 2. 40pp. 19767: 138. 24X 
  Fiche: 50-397, 83/07/01, 8307270452.

#### Adjudicatory correspondence

307150320 Notice of appearance in proceeding Certificate of Syc encl. RYAN, K. M. Washington, State of . B3/07/08. 2pp. 19538:117. 24X Fiche: 50-397.83/07/08.8307150320.

#### General correspondence

- 307120545 Informs that D Mazur appointed new managing directoreffective 830516. 8DUCHEY, G. D. Washington Public Power Supply System. 83/07/06. 8CHMENCER.A. Licensing Branch 2. ip. 19433:347. 24X Fiche: 50-397,83/07/06
  - Inspection reports, 1E Bulletins & correspondence
- 306170412 Ack receipt of 830428 & 0520 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 80-397783-05.
  STERNBERG, D. M. Region 5, Office of Director. 83/06/13.
  CARLIBLE, C. S. Washington Public Power Supply System. 1p. 18879: 323. 24X Fiche: 50-397, 83/06/13, 8306170412.
- -8306170416 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-397/83-05.Corrective actions:missing documentation located & reviewed, Microfilm indexing sys sufficient. CARLIBLE, C. S. Washington Public Power Supply System B3/04/28. STERNBERG, D.M. Region 5, Office of Director. 3pp. 18879:324. 24X Fiche: 30-397.83/04/13,8306170412.
- -8306170422 Submits amended response to NRC 830329 ltr re violations noted in IE Insp Rept 50-397/83-05. Corrective actions: GA will issue nonconformance rept re missing welder qualifications, for engineering review.

  CARLISLE, C. S. Washington Public Pawer Supply Bystem. 83/05/20. STERNBERG, D. S. Region 5. Office of Director. 2pp. 18879: 327. 24X Fiche: 50-397, 83/06/13, 8306170412.
- 307030085 Responds to NRC 830608 telecopy requesting clarification of three areas of util preservice insp program. Clarification of preservice insp of scram discharge vol sys encl.
  80UCHEY, G. D. Washington Public Power Supply System. 83/06/15.
  80CHWENGER.A. Licensing Branch 2. 3pp. 17197:327. 24X
  Fiche: 50-397, 83/06/15, 8307050085.
- 307120532 Forwards IE Insp Rept 50-397/83-21 during May 1983. No noncompliance noted. STERNBERG.D.M. Region 5, Office of Director. 83/06/29. CARLISLE.C.S. Washington Public Power Supply System. 2pp. 19433: 310. 24X Fiche: 50-397,83/06/29,8307120532.
- "8307120537 IE insp Rept 50~397/83-21 during May 1983. No noncompliance noted. Major areas inspected; preoperational test procedure review & witnessing, fuel receipt, storage & independent inspeffort.
  FEIL,R.A. DODDS,R.T. Region 5. Office of Director. 83/06/28.
  5pp. 19433:312. 24X Fiche: 50-397.83/06/29,8397120332.
- 307190495 Forwards request for add1 info re preservice insp program & relief requests in response to 830503 ltr.Add1 info requested by 830722.

  8CHWENCER, A. Licensing Branch 2. 93/07/05. FERCUSON, R. L. Washington Public Power Supply System. App. 19451:252. 24X Fichs: 30-397,83/07/05,8307190495.

- 8307190213 Forwards proposed snubber Tech Spec for review as followup to 830314 & 0624 telcons. Changes will not lessen assurance of structural integrity & functionality of safety-related sys. Fuel load scheduled for Sept 1983.
  BOUCHEY, G. D. Washington Public Power Supply System. B3/07/08.
  SCHWENKER, A. Licensing Branch 2. 2pp. 19629:187. 24X
  Fiche: 50-397, 83/07/08, 8307190213.
- ---8307190217 "Component Support Insp & Test Program Plan."
  PRILES.L. Washington Public Power Supply System. 83/03/14. 18pp
  19629:197. 24X Fiche:50-397.83/07/08.8307190213.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem" Svc list encl.
  JORDAN.E. L. Division of Emergency Properedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24x Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid " Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- B306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- 8. Reportable occurrences, LERs & related correspondence
- B30715035B Part 21 Evaluation Rept B3-01 re section modulus error in ADLPIPE program. Initially reported on 830128. Error did not affect safety-related nuclear power plant piping sys. Deviation not reportable per Part 21.

  VERDERBER, J. J. Burns & Roe Co. B3/04/26. COLLING, J.P. Region 4, Office of Director. 3pp. 19539: 090. 24% Fiche: 50-397, 83/04/26, 830715035B.
- --8307150362 "Evaluation of ADLPIPE Error in Yee Element re Defect & Noncompliance Evaluation Rept 83-01.WPPSS Nuclear Power Plant 2."
  CHU.A.: STUDNICKA.Z., MICHEJDA.O. Burns & Roe Co 83/03/28.
  17pp. 19539:093. 24X Fiche:50-397.83/04/26.8307150358.
- 8307060228 Forwards deficiency repts re Condition 240.loss of ESF loads on undervoltage trip & Condition 258.RHR MX installation. CARLISLE.C.S. Washington Public Power Supply System. 83/06/24 MARTIN.J.B. Region 3. Office of Director. 1p. 19239:251. 24X Fiche:50~397.83/06/24.8307060228.
- --8307060232 Interim deficiency rept re Condition 240, loss of ESF loads on undervoltage trip. AE issued Project Engineering Directive PED 218-E-4618 on 830303 to delete seal-in circuit. Next rept will be submitted on 830921.

  \* Washington Public Power Supply System 83/06/24 Region 5. Office of Director. 2pp. 19239.252. 24X Fiche: 50-397, 83/06/24. 8307060228
- --8307060237 Interim deficiency rept re Condition 258.RHR HX installation, Burns & Roe issued PED 215-05-P531 to install new shear plates in lieu of shims. Extensive review of equipment installation being conducted \* Washington Public Power Supply System. 83/06/24. Region 5. Office of Director. 6pp. 19239-254. 24X Fiche: 50-397.83/06/24. 8307060228.
- 8307180027 Final deficiency rept Condition 246 re balance of plant Board G-2 design error.Initially reported on 830315.AE issued project engineering directive (FED-218-E-8375) to switch power supplies CARLISLE.C.S. Washington Public Power Supply System. 83/07/01. MARTIN.J.B. Region 5, Office of Director. 2pp. 19560:282. 24X Fiche: 50-397,83/07/01,8307180027.
- 8307180083 Interim deficiency rept re Reportable Condition 264, concerning improperly sized overcurrent devices Initially reported on 830607. Pump & valve operator motor fuses replaced. Fuse size verified. Next rept by 831003. CARLISE.C.S. Washington Public Power Supply System. 83/07/08. MARTIN.J. B. Region 5, Office of Director. App. 19560:001. 24) Fiche: 50-397,83/07/08,8307180083.

- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT : A. Application/construction stage documents & correspondence
- 8304040070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT.D.G. Division of Licensing. 83/06/03. Yantee Ato. Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307200231 Notification of 830707 meeting w/technical review committee in Bathesda, MD to discuss review of D4.D5 & E steam generator mods.

  MDPKINS J. B. Licensing Branch 4. 83/07/01. ADENSAM.E.G. Licensing Branch 4. 2pp. 19670:254. 24X Fiche: 50-000,83/07/01,8307200231.
- 8306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Int. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.5vc list encl. EISENHUT.D.G. Division of Licensing. 83/07/06. Consolidation Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: S0-000, 83/07/06, 8307060329. Consolidated
- 8307140251 Confirms schedule for B3070B mgt meeting at Raleigh-Durham Airport Raleigh.NC to discuss status of outstanding regulatory issues. Proposed meeting agenda encl. O'REILLY, J. P. Region 2. Office of Director. B3/07/06. UTLEY, E. Carolina Power & Light Co. 1p. 19523:044. 24X Fiche: 50-000,83/07/06,8307140251.
- B307080167 Generic Ltr B3-28 to all licensess of operating reactors, applicants for GL & holders of CPs re-required actions based on generic implications of Salem ATWS events Svc list encl. EISENHUT.D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:287, 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307140239 Advises that review of 830509 description of GA program in progress. LEWIG.R.C. Division of Project & Resident Programs. 83/07 MCDUFFIE.M.A. Carolina Power & Light Co. 1p. 19923:105. Fiche:50-400.83/07/08.8307140239.
- 8307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse 1/4, 05 & DE Steam Generators." Rept withheld (ref 10CFR2, 790).
  BUTTERFIELD.L. Steam Generator Owners Group. BUTTERFIELD.L.
  Commonwealth Edison Co. B3/07/18. EISENHUT.D.G. Division of Licensing. 3pp. 19664:114. 24X Fiche: 50~000, 83/07/18, 8307210300.
- 8307250124 Summary of 830707 meeting w/technical review committee in Bathesda, MD re Model D4/D5/E steam generator mod. Viewgraphs encl.

  HOPKING J. B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 26pp. 19738: 132. 24X Fiche: 50-000, 83/07/18, 8307250124.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- B307070094 Forwards comments on DES re operation of facilities (NUREO-0972). Opinions & calculations presented do not necessarily reflect Pennsylvania State Univ position. LOCHSTER, W. A. Pennsylvania State Univ B3/06/30. Division of Licensing. 5pp. 19293: 261. 24X Fiche: 30-400, 83/06/30, 8307070054.
- 8307040258 Comments on DES (NUREG-0972) re plant operation. Requesting public comments after decision supporting issuance of OL made inappropriate.

  LOTCHIN.P. Affiliation Unknown. 83/07/01. Division of Licensing. 3pp. 19239:303. 24X Fiche: 50-400,83/07/01,8307040258.
- 8307110258 Forwards comments on DES, Requests clarification of section re-chemical impacts of blowdown discharge on reservoir. Statement acceptable. MOGRES N. Environmental Protection Agency. 83/07/01. KADAMBI.P. Office of Nuclear Reactor Regulation, Director. 2pp. 19374: 866. 24X Fiche SO-400, 83/07/01, 8307110258

- 107070083 Forwards comments on DES NUREC-0972 Marked-up DES pages correcting typographical errors & containing minor comments encl. HURFORD.W.J. Carolina Power & Light Co. 83/07/05. EISENHUT,D.C. Division of Licensing. 20pp. 19293:138. 24X Fiche:50-400,83/07/05, Division of Licensing. 8307070083.
- B307130091 Forwards NC Dept of Natural Resources & Community
  Development comments on DES. Wildlife mgt plan for mitigation
  of land use impacts not yet received.
  BAGGETT.C. North Carolina. State of. 83/07/05. KNIGHTON, O. H.
  Licensing Branch 3. 2pp. 19465:334. 24X Fiche: 50-400, 83/07/05,
  8307130091.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307010053 Forwards responses to draft SER Open Items 103,106,116,118, 119,123,147 & 153.

  MCDUFFIE,M.A. Carolina Pawer & Light Co. 83/06/29. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. 18pp. 19168;314, 24X Fiche: 50-400,83/06/29,8307010053.
- 8307060111 Forwards responses to draft Chemical Engineering Branch BER Open Items 146 & 147 re schematics of sample lines & panels (per TMI Item II.B.3) re post-accident sampling sys. MCDUFFIE.M.A. Garolina Power & Light Co. B3/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. App. 19252:214. 24X Fiche: 50-400, 83/06/30, 8307060111.
- 8307060144 Forwards revised response to Accident Evaluation Branch draft SER Open Item 55 re containment spray sys design. Responses to remaining open Items forthcoming. MCDUFFIE,M.A. Carolina Power & Light Co. 83/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19249:360. 24X Fiche: 50-400.83/06/30.8307060144.
- B307060302 Forwards responses to Auxiliary Sys Branch draft SER Open Items 134,135 & 224,re removal of barrier in fuel cask pool, crane load block & protection of circulating water sys, respectively.

  MCDUFFIE,M.A. Garolina Power & Light Co. B3/06/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 19238:332. 24X Fiche: 50~400, B3/06/30, B307060302.
- 8307060095 Responds to Containment Sys Branch draft SER Open Item 68. Add1 failure alarm located within control room unnecessary. Continuous indication will be functioning within 30 minutes of safety injection initiation per TMI Item II.F.1. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19252:008. 24% Fiche: 50-400, 83/07/01, 8307060095.
- B307060114 Responds to draft SER Open Item 10 re meteorological instrumentation. Util will complete review of emergency plan during emergency preparedness implementation appraisal. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19252:219. 24X Fiche: 50-400, 83/07/01, 8307060114.
- B307060163 Forwards response to Maths Engineering Branch draft SER Open Item 36 re beltline math test requirements of 10CFR50.App 0. Paragraph III.C.2. MCDUFFIE, M.A. Carolina Power & Light Co. B3/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19250:270. 24X Fiche: 50-400.83/07/01.8307060163.
- 83070A0224 Forwards responses to Procedures & Sys Review Branch draft SER Open Items 194,195 & 217. Responses cover NSSS review of low-power testing.power ascension & emergency operating procedures per NUREO-0737.

  MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 4pp. 19239:356. 24X Fiche: 50-400,83/07/01,8307060234.
- 8307070085 Forwards response to Core Performance Branch draft SER Open Item 29 re visual exam of discharged fuel assemblies after refueling.

  MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19269;361. 24X Fiche: 50-400,83/07/01,8307070085.
- 8307080370 Forwards responses to draft BER open items. List of items, responsible NRC review branch & reviewer encl.
  MCDUFFIE,M.A. Carolina Power & Light Co. 83/07/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 166pp. 19349:330. 24X Fiche: 50-400,83/07/01,8307080390.

- 8307070125 Forwards responses to Auxiliary Sys Branch draft SER Open Items 129 through 131 & 137 re spent fuel pool drainage & storage. Applicable FSAR sections will be revised Responses to remaining open items forthcoming. MCDUFFIE,M.A. Carolina Power & Light Co. 83/07/05. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. App. 19269:338. 24% Ficha: 50-400, 83/07/05, 8307070125.
- B3070B0315 Forwards response to draft SER Open Item 209 re single failures assumed for accidents. MCDUFFIE,M.A. Carolina Power & Light Co. B3/07/05. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 12pp. 19350: 151. 24X Fiths: 50-400,83/07/05,83070B0315.
- B307140323 Forwards responses to Meteorological & Effluent Treatment Branch draft SER Open Items 198 & 186. Turbine gland sealing sys is non-nuclear nonseismic Category I sys. MCDUFFIE, M.A. Carolina Power & Light Co. 83/07/11. DENTON, H. R. Offfice of Nuclear Reactor Regulation. Director. 3pp. 19525:117. 24X Fiche: 50-400, 83/07/11, 8307140323.
- 8307270340 Forwards responses to draft SER open items & rev to 830701 response to Open Item 191.

  MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/15. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 346pp. 19748:001. 24X Fiche: 50-400, 83/07/15, 8307270340.
- 8307210146 Forwards responses to draft SER Open Items 172 & 173. Resumes of personnel to fill positions of environ & radiation control manager & radiation control supervisor will be added to FBAR when positions filled.

  MCDUFFIE,M.A. Carolina Power & Light Co. 83/07/18. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 5pp. 19648:349. 24% Fiche: 50-400,83/07/18,8307210146.
- B307280361 Forwards responses to Licensee Qualification Branch Questions 630.1 630.8 re personnel training program.per draft BER Open Items 316-323. Training for all license candidates completed prior to cold license etam.

  MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/25. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 25pp. 19796: 259. 24X Fiche: 50-400, 83/07/25, 8307280361.
- F. Security, medical, emergency & fire protection plans
- 8307140381 Forwards IE Insp Repts 50-400/83-19 & 50-401/83-19 on 830531-0602. No noncompliance noted. VERRELLI.D.M. Division of Project & Resident Programs. 83/06/22. UTLEY.E.E. Carolina Power & Light Co. 2pp. 19525:065. 24X Fiche: 50-400, 83/06/22, 8307140381.
- ---B3071403B5 IE Insp Repts 50-400/B3-19 % 50-401/B3-19 on 830531-0602. No noncompliance noted Major areas inspected: fire protection.

  MILLER. M. M. Region 2. Diffice of Director. CDNLON, T. E. Division of Engineering & Radiological Safety Programs. 83/06/20. Spp. 19525: 067. 24X Fiche: 50-400, B3/06/22, 8307140381.
- 8307060114 Responds to draft SER Open Item 10 re meteorological instrumentation. Util uill complete review of emergency plan during emergency preparedness implementation appraisal. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19252:219. 24X Fiche: 50-400,83/07/01.8307060114.
- B307220109 Notification of B30720 & 21 meetings w/util at site to review physical security plan per 10CFR73.21. LICITRA.E.A. Licensing Branch 3. 83/07/08. KNIGHTON, O. W. Licensing Branch 3. 3pp. 19692:339. 24X Fiche: 50-400, 83/07/08. B307220109.
- 8307150225 Forwards responses to Chemical Engineering Branch FSAR safety & acceptance review questions re fire protection. Draft safe shutdown analysis in case of fire transmitted on 830527. Final analysis to be transmitted by 830717. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1989. 19537: 332. 24X Fiche: 50-400, 83/07/11. 8307150225.
- 8307220333 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-400/83-16 & 50-401/83-16. LEHIS, R.C. Division of Project & Resident Programs. 83/07/12. UTLEY, E.E. Carolina Power & Light Co 1p. 19675:339. 24X Fiche: 50-400,83/07/12,8307220333.
- ---8307220336 Responds to NRC 830519 itr re violations noted in 1E Insp. Repts 50-400/83-16 & 50-401/83-16. Corrective actions: cable tray & cable tray support insp programs revised.

  PARSONS.R.M. Carolina Power & Light Co. 83/06/16. O'REILLY, J. P. Region 2, Office of Director. 3pp. 19675:340. 24X Fiche: 50-400, 83/07/12, 8307220333.

- --8307220340 Forwards [E Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420 & notice of violation. LEWIS.R C. Division of Project & Resident Programs. 83/05/19. UTLEY/E E. Carolina Power & Light Co. 2pp 19675:343 24X Ficha.50-400.83/07/12.8307220333.
- --B307220342 Notice of violation from insp on 830320-0420.

  \* Region 2. Office of Director. 83/05/19. ip. 19675:345. 24X Fithe:50-400,83/07/12,8307220333.
- --8307220344 IE Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420.

  Noncompliance noted: insp status of electrical raceway supports not completed prior to installation of cable trays.

  MAXWELL, G. F., PREVATTE, R. L. Region 2, Office of Director.

  BEMIS.P. Division of Project Resident Programs. 83/05/17. Spp. 19675:346. 24X Fiche: 50-400.83/07/12.8307220333.
- Q. Adjudicatory correspondence
- 8307050195 Advises that author cannot attend 830720-21 prehearing conference. Joint Intervenors will represent Kudzu Alliance position on issues.

  PAYNE, M.T. Edelstein & Payne. PAYNE, M.T. Kudzu Alliance.

  83706/27. KELLEY, T.L. BRIGHT, G. O., CARPENTER, J. H. Atomic Safety and Licensing Board Fanel. 2pp. 19197:211. 24X

  Fiche: 50-400/83/06/27,8307050195.
- 8307050198 Forwards revised joint interrogatories on Contentions IV,V & VI (first set). Related correspondence.
  PAYNE,M.T. Edelstein & Payne. 83/06/27. O'NEILL,J.H. Shaw, Pittman. Potts & Troubridge. 2pp. 19199:221. 24X
  Fiche: 50-400, 83/06/27, 8307050198.
- --8307050205 First set of Joint Intervenors interrogatories on Contentions IV.V & VI (first set). Certificate of Svc encl. PAYNE.M.T. Kudiu Alliance. PAYNE.M.T. Edulstein & Payne. 83/06/27. Carolina Power & Light Co. 15pp. 19199: 223. 24X Fiche: 50-400, 83/06/27, 8307050198.
- 8307060198 Third set of interrogetories & request for production of documents to joint intervenors. Certificate of Svc encl.

  BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trombridge S3706/30. Chapel Hill Anti-Nuclear Group Effort. 13pp. 19250:231. 24X Fische: 50-400, 83/06/30, 8307060198.
- 8307060383 Petition under iOCFR2.758 for waiver of rule barring issues re alternatives to & need for power from OL proceeding.

  Issues must be litigated since environmentally & economically superior alternatives exist.

  EDDLEMAN.W. Eddleman. W. 83/06/30. Atomic Safety and Licensing Board Panel. 2pp. 19234:302. 24X Fiche: 50-400.83/06/30.8307060383.
- --B307060386 Submission of Contention 15-AA that operating capacity factor of 55% in DES overestimated. Contention submitted per ABLB 830527 order.
  EDDLEMAN.W. Eddleman.W. 83/06/30. Atomic Safety and Licensing Board Panel. 2pp. 19234:304. 24X Fiche:50-400,83/06/30, 83/06/30.
- --B307060391 Affidavit of W Eddleman, summarizing economic & environ superiority of alternative to plant operation. Testimony of individuals before North Carolina Util Commission & portions of State of NC rept on need for power encl. EDDLEHAN. M. Eddleman, W. B3/06/30. 150pp. 19234:306. 24X Fiche:50-400,83/06/30.8307060383.
- --8307060406 "Bide Effects of Renewable Energy Sources," revised edition. MEDSKER,L. Addubon Society. EPRD 15. 82/12/31. 75pp. 19235:096. 24X Fiche: 50-400, 83/06/30, 8307060383.
- --B307060411 "Risk of Renewable Energy Sources: Critique of Inhaber Rept." Centificate of Svc encl.
  HOLDREN J.P., ANDERSON, K., GLEICK, P.H. California, Univ. of, Berkeley. ERG 79-3. 79/06/30. 55pp. 19236-001. 24X
  Fiche: 50-400, 83/06/30, 8307060383.
- 8307070022 Supplemental answers to interrogatories on Contentions 75 & B3/84. Cartificate of Svc encl. Related correspondence.
  CARROW.H. Carolina Power & Light Co. 83/06/30. EDDLEMAN.W.
  Eddleman. W. 7pp. 19293: 234. 24X Fiche: 50-400.83/06/30.8307070022
- 8307070025 Fourth set of interrogatories % request for production of documents. Certificate of Svr encl. Related correspondence.

  CARROW. H. Carolina Power & Light Co. 83/06/30 WILSON R. D.
  Wilson R. lipp. 17293: 334. 24X Fiche 50-400.83/06/30,8307070025.

- 8307070071 Fourth set of interrogatories & request for production of documents re Contentions 75 & 93/84. Certificate of Svc encl. Related correspondence.

  CARRON.H. Carolina Fower & Light Co. 83/06/30. EDDLEMAN.H. Eddleman. H. 13pp. 19293:115. 24X Fiche: 50-400.83/06/30. 8307070071.
- 8307070076 Interrogatories & request for production of documents. Contificate of Syc encl.Related correspondence. READ.D.F. Chapel Hill Anti-Nuclear Group Effort. 63/06/30. Carolina Power & Light Co. 9pp. 19293:128. 24X Fiche: 50-400.83/06/30.8307070076.
- 8307070092 Second set of interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
  CARRON.H. Carolina Power & Light Co CARRON.H. Shaw, Pittman. Potts & Trowbridge. 83706/30. Conservation Council of North Carolina. 16pp. 19274:001. 24X Fiche: 50-400.83/06/30.8307070092.
- 8307060173 Response to ASLB 830527 memorandum & order ruling on cost saving contentions, discovery disputes & scheduling matters. Commission assumed capacity factor of 55% considered conservative Certificate of Syc encl. O'NEILL.J.H. Carolina Power & Light Co. O'NEILL.J.H. Shaw, Pittman. Potts & Trombridge. 83/07/01. Spp. 19249:184. 24X Ficha: 50-400.83/07/01, 8307060173.
- 8307040159 Third set of general interrogatories & interrogatories on Contentions 75,80,83,84,64f & 67. EDDLEMAN,W. Eddleman, W. 83/07/02. Carolina Power & Light Co. 20pp. 19250:174. 24X Fiche: 50-400,83/07/02,8307040159.
- 8307060402 Response to util May 1983 DCRDR update, including revised & new contentions. Certificate of Svc encl.
  EDDLEMAN, W Eddleman, W. 83707702. Atomic Safety and Licensing Board Panel. 11pp. 19236: 069. 24X Fiche: 50-400. B3/07/02.
- 8307130242 Notice of withdrawal of D Greenblatt as intervenor counsel on security-related contentions. J Runkle will replace Greenblatt. Certificate of Svc encl.
  RUNKLE. J. Runkle. J. D. 83/07/07. 2pp. 19474:357. 24X
  Fiche: 50-400.83/07/07.8307130242.
- B307120077 Response to M Eddleman B30624 response to NRC Apr 1983 DES. DES contains no new info previously unavailable in public domain upon which new contentions could be based. Notice of appearance & Certificate of Svc enc!.

  BARTH.C.A. Hearing Branch 1. 83/07/08. [8pp. 19423:089. 24X Fiche: 50-400, 83/07/08, 8307120077.
- 9307130231 Advises that util considered Commission 830630 Memorandum & Order CLI-83-19 in each filings Certificate of Svc enci.
  BAXTER.T.A. Shaw, Pittman, Potts & Trowbridge. BAXTER.T.A.
  Carolina Power & Light Co. 83/07/08. KELLEY.J.L., BRIGHT.G.D.,
  CARFENTER.J.H. Atomic Safety and Licensing Board Panel. Spp.
  19473: 290. 24X Fiche: 50-400, 63/07/08, 8307130231.
- --8307130241 Response to W Eddleman 830520 contentions. No objectio raised to admission of portions of Contention BF. Remaining, deferred & new contentions re DES should be rejected. O'NEILL, J. H. Carolina Power & Light Co. O'NEILL, J. H. Shaw, Fittman. Potts & Troubridge. 83/07/08. Atomic Safety and Licensing Board Panel. 4pp. 19473: 295. 24X Fiche: 50-400, 83/07/08.8307130231.
- --8307130253 Motion for dismissal of Conservation Council of North Carolina Contention 4 & Chapel Hill Anti-Nuclear Group Effort Contention of 8 response to W Eddleman 830620 contention on spent field transportation.

  O'NEILL-J.A. Carolina Power & Light Co. D'NEILL-J.A. Shaw, Pittman. Potts & Troubridge. B3/07/06. Atomic Safety and Licensing Board Panel. 25pp. 19473:341. 24X
  Fiche: 50-400, 83/07/08, 8307130231.
- --8307130261 Affidavit of LM Martin re shipment of spent fuel Shipment of spent fuel from Robinson M/or Brunswick to Harris will be considered Shipment will be made so environ impacts fall within 10CFRS1 20. Table S-4. values.

  MARTIN.L H. Carolina Power & Light Co. 83/07/06. 2pp. 19474:004. 24X Fiche: 50-400.83/07/08.8307130231.
- 8307130244 Forwards protective order governing access to security info & proposed affidavit of nondisclosure for security plan phase of proceedings. Appropriate notice of appointment as counsel to intervenors required Related correspondence. CARROW, M. Carolina Power & Light Co. 83/07/08 RUNKLE, J. D. Runkle, J. D. 19474: 359. 24x Fiche 50-400, 83/07/08, 8307130244.

- 8307130067 Response to W Eddleman 830502 contentions re applicant onsite emergency plan. Contentions 150, 153, 154, 155, 156, 158, 159 & 160 should be denied. Contentions 151, 152 & 157 should be deferred. Certificate of Svc encl.

  BARTH. C A. Hearing Branch 1. B3/07/11. Atomic Safety and Licensing Board Panel. 10pp. 19474: 217. 24X Fiche: 50-400, 83/07/[[, 8307130067]]
- B307140435 Notice of appearance in proceeding. Certificate of Svc encl. RIDGMAY.D.A. Carolina Power & Light Co. RIDGMAY.D.A. Shaw, pittnan. Potts & Trowbridge. B3/07/11. 4pp. 19320:162. 24x Fiche: 50-400. B3/07/11. B307140435.
- 8307140437 Response to 830523 request for suppl to 830510 answers to interrogatories. Certificate of Svc enc.l. Related correspondence. FLYNN.S.F. Carolina Power & Light Co. 83/07/[1, Wilson, R. 49pp. 19521:034. 24X Fiche: 50-400, 83/07/[1,8307140437.
- B307140440 Forwards Pages 43 & 44 to util B30708 response to W Eddleman contentions re DEB, inadvertently omitted.

  O'NEILL.J.H. Shaw, Pittman, Potts & Troubridge, O'NEILL.J.H. Carolina Power & Light Co. B3/07/11. KELLEY.J.L., CARPENTER.J.H., BRIGHT.G.D. Atomic Safety and Licensing Board Panel. ip. 19321:256. 24X Fiche: 50-400, 83/07/11, B307140440.
- --8307140445 Pages 43 & 44 to util 830708 response to W Eddleman contentions re DES, inadvertently ommitted Svc list encl. \* Carolina Power & Light Co. 83/07/11. Atomic Safety and Licensing Board Panel. 4pp. 19321:257. 24X Fiche: 50-400, 83/07/11, B307140440.
- 8307140454 Response to W Eddleman 830502 proposed contentions re amergency plan. Opposes Contentions 150/2, 150/29, 150/30, 150/55, 150/57, 150/63, 150/97, 150/99, 150/100, 130/117, 150/118, 150/124 & 151 160. Certificate of Svc encl. RIDGNAY, D. A. Carolina Power & Light Co. RIDGNAY, D. A. Shaw, Pittman. Potts & Trowbridge. 83/07/11. Atomic Safety and Licensing Board Penel. 35pp. 19521: 204. 24X Fiche: 50-400, 83/07/11.
- B307140438 Extends invitation to participate in 830721 site tour. Svc list encl. FLYNN, S.F. Carolina Power & Light Co. 83/07/11. BARTH, C. Hearing Branch 1. EDDLEMAN, W. Eddleman, W. PAYNE, M. T. Edelstein & Payne, 2pp. 19521: 196. 24X Fiche: 50-400, B3/07/11, B307140458,
- 8307150188 Motion to compel discovery re Eddleman 29,378,75 & B3/84 per applicants objections. Certificate of Svc.centificate of negotiations & notice of negotiations encl. EDDLEMAN.W. Eddleman.W. B3/07/11. BRIGHT, G.D., CARPENTER, J. H., KELLEY, J. L. Atomic Safety and Licensing Board Panel. 19pp. 19530:342. 24X Fiche: 50-400,83/07/11.8307150188.
- 8307140443 Answer to W Eddleman 830626 motion for extension to file second round interrogatories & to file interrogatories on Contentions 29 & 378 until 830720 Agrees w/second request & apposes first request M/Certificate of Svc.

  BAXTER, T. A. Carolina Power & Light Co. BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge. 83/07/12. Atomic Safety and Licensing Board Panel. 10pp. 19521:261. 24X Fiche: 50-400, 83/07/12, 8307140443.
- 8307140451 Requests input on alleged economics & alleged technology set forth in W Eddleman 10CFR2.758 petition to litigate need for power & alternatives to plant.Logic & coherence of Eddleman scenarios bear close scruting.

  BARTH.C.A. Hearing Branch 1. 83/07/12. KNIGHTON, G. Licensing Branch 3. 1p. 19521:243. 24X Fiche: 50-400, 83/07/12, 8307140451.
- 8307140464 Forwards Commission 830701 order on issue of late filed contentions & NUREG-0794, "Protection of Unclassified Safeguards Info," W/o NUREG. BARTH, C.A. Hearing Branch 1. 83/07/12, FLYNN.S. Carolina Power & Light Co. Ip. 17521:134, 24X Fiche: 50-400, 83/07/12, 8307140466.
- 8307150201 Informs that applicants considering filing second motion to compel discovery on Interrogatory 2 per unsuccessful negotiations w/Eddleman. Discusses Eddleman B30625 response. BAXTER.T.A. Shaw. Pittman. Potts & Trowbridge. BAXTER.T.A. Carolina Power & Light Co. 83/07/12 KELLEY.U.L. BRIGHT.G.C., CARPENTER.J.H. Atomic Safety and Licensing Board Panel. 4pp. 19530: 242. 24X Fiche: 50-400.83/07/12,8307150201.
- B307190283 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  BAXTER.T.A. Shaw, Fittman, Potts & Trowbridge. BAXTER.T.A.
  Carolina Power & Light Co. B3/07/13. KELLEY.J.L., BRIGHT.G.C., CARPENTER.J.H. Atomic Safety and Licensing Board Panel. ip. 19628: 034. 24X Fiche: 50-400, 83/07/13, 8307190283.

- --83071902BB Notifies of employment at law firm VR Harding will not participate in any case pending before NRC Svc list encl.

  HARDING, V. R. Shaw, Pittman, Potts & Trowbridge 83/07/13.

  KELLEY, J. L., BRIGHT, G. O., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 3pp. 19628:035. 24X Fiche: 30-400, Licensing Board Panel. 83/07/13,8307190283.
- 8307210281 Response to fourth set of interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
  WILSON, R. Wilson, R. 83/07/14. Carolina Power & Light Co. 4pp. 1964: 198. 24X Fiche: 50-400.83/07/14.8307210281
- B307190262 Memorandum & order memorializing 830714 telcon re postponement of upcoming prehearing conference & related matters. Atomic Safety and Licensing Board Panel. 83/07/15. 243. 24X Fiche: 50-400.83/07/15,8307190242. 19428 241
- 8307210171 Forwards modified draft protection order & affidavit of nundisclosure & submits summary of unresolved issues discussed on B30713. Draft incorporates NRC & intervenor suggestions. Certificate of Svc encl. FLYNN. S.F. Carolina Power & Light Co. B3/07/15. KELLEY, J. L., BRIGHT, G. D., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 11pp. 19666:047. 24X Fiche: 50-400, B3/07/15, B307210171.
- 8307210203 Confirms 830718 telcon re agreement concerning intervenor 830630 request for production & interrogatories Applicants will respond to discovery requests on Contention 44 by 830812. 830812. BAXTER.T.A. Shaw, Pittman, Potts & Trowbridge. BAXTER.T.A. Carolina Power & Light Co. 83/07/19. REED.D.F. Chapel Hill Anti-Nuclear Group Effort. 4pp. 19669:043. 24X Fithe: 30-400.83/07/19.8307210203.
- 8307240281 Notice of amend to W Eddleman third set of interrogatories to utils Page 8 should not be included Certificate of Svc encl.
  - MAN.W. Eddleman. W. 83/07/19. Carolina Power & Light Co. 19726: 206. 24X Fiche: 50-400.83/07/19.8307260281. EDDLEMAN W.
- B307250247 Forwards RH Odegaarden, P Bemis, WC Seidle, F Hawkins & T Mo signatures to complete NRC 830624 responses to interrogatories. BARTH, C.A. Hearing Branch 1. B3/07/20. EDDLEMAN, W. Eddleman, W. Bpg. 19705: 328. 24X Fiche: 50-400, 83/07/20, 8307250247.
- B307250346 Response opposing admission of W Eddleman proposed Contention 15-AA re NEPA cost-benefit balance Eddleman fails to plead litigable contention w/adequate basis % specificity.

  G'NEILL, J. H. Carolina Power & Light Co. O'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge. B3/07/20. Atomic Safety and Licensing Board Panel. 7pp. 19702:004. 24X Fiche: 50-400, 83/07/20, 8307250346.
- --8307250350 Fifth set of interrogatories & request for production of documents re Eddleman Contentions 29/30 & 378. Certificates of 8vc encl.

  BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge. B3/07/20. Eddleman, W. 30pp. 19702:011. 24X Fiche: 50-400, B3/07/20, B307250346.
- 8307240341 Answer to applicant response to motion for extension of time re-second round interrogatories on environ contentions. EDDLEMAN, W. Eddleman, W. 83/07/20, 2pp. 19726: 332. 24X Fiche: 50-400, 83/07/20, 8307240341.
- 8307250285 Amend to svc list. MILLER,R.G. Atomic Safety and Licensing Board Panel. 83/07/21. ip. 19705:305. 24X Fiche:50-400.83/07/21,8307250285.
- B307250337 Advises that during B30721 telephone conference, applicants & NRC did not modify positions taken in written response to proposed contentions. W Eddleman will reflect changes in written reply to applicant & NRC written responses.

  BAXTER.T. A. Shaw, Pittman, Potts & Trowbridge, BAXTER.T.A.
  Carolina Power & Light Co. B3/07/21. KELLEY, J.L., BRIGHT, G.D., CAPERNTER, J.M. Atomic Safety and Licensing Board Panel. 4pp. 19703:007. 24x Fiche: 50-400, 83/07/21, 8307250337.
- 8307260360 Advises that util does not accept W Eddleman 830625 reply as conforming to ASLB 830527 holdings on General Interrogatory 2 re identification of experts or witnesses. Svc list and Related correspondence. BYC list onci. Related correspondence.

  BAXTER, J. A. Bhaw, Pittman. Potts & Trowbridge. BAXTER, J. A.
  Carolina Power & Light Co. B3/07/22. KELLEY, J. L., BRIGHF, C
  CARPENTER, J. H. Atomic Safety and Licensing Board Panel. Sp
  19733: 031. 24X Fiche: 50-400.83/07/22,8307260360. BRIGHT G. D.

- 8307260483 Dhyections to applicant 830711 draft affidevit of mondisclosure & protective order governing access to security plan info Proposed restricted time schedule makes proper review difficult Certificate of Eva encl. RUMKLEJD Joint Intervenors-Shearch Harris 83/07/22. Safety and Licensing Board Panel 1thp 19731 145 24X RUNKLE, J D. Joint Intervenors-Sh Safety and Licensing Board Panel Fiche: 90-400, 83/07/22, 8307260483.
- B307260248 Fourth set of general interrogatories & interrogatories on Contentions 29 & 370 EDDLEMAN, N. Eddleman, W. 83/07/25 Carolina Power & Light Co 31pp. 19727: 007 24% Fiche: 50-400, 83/07/25, 8307260248
- B307280163 Requests response to 830630 interrogatories on Joint Contention II or request for extension Early response important due to 830701 deadline for motion for summary disposition. See 1st encl.

  BAXTER.T.A. Shaw, Pittman, Potts & Troubridge RAXTER.T.A.

  Carolina Power & Light Co. 83/07/25 PAYME,M T. Edelstein & Payne.

  3pp. 19792.076 24X Fiche 50-400,83/07/25,8307280163.
- 8307290185 Answer opposing W Eddleman 830711 motion to compel discovery re-applicant response to W Eddleman general interrogatories & interrogatories on Contentions 29 & 378. Certificate of Svc encl.Related correspondence BAUSER.D.D. Carolina Power & Light Co. BAUSER.D.B. Shaw, Pittman Potts & Trowbridge. B3/07/26. Atomic Safety and Licensing Board Panel. 21pp. 19791: 268. 24X Fiche.50-400.83/07/26.8307280185
- 8307280167 Comments on util 830715 transmittal to ASLB & Runkle 830722 comments. Clearer statement re not removing safeguards papers needed in affidavit of nondisclosure Site visit would be more meaningful at later stage of const BARTHLC A. Hearing Branch 1 83/07/27. KELLEY, J. L., CARPENTER.J. H., BRIGHT. 0.0 Abomic Safety and Licensing Board Panel. 2pp 19791: 293. 24X Fiche 50-400.83/07/27.8307280167.
- B307290142 Advises that second round discovery requests on Contentions 29 % 378 will be treated as having been served an B30725.

  Original copy lost in mail Svc list encl. Related correspondence.

  BAXTER.T. A. Shaw, Pittman, Potts & Trowbridge B3/07/27.

  EDDLEPMAN.W. Eddleman.W. 3pp. 19821-056 24X

  Fiche: 50-400, 83/07/27, 8307290142.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307060121 Forwards Amend 7 to FSAR, in teaponse to draft SER Open Items 132, 136, 157, 178, 199, 203, 204 & 207.

  MCDUFFIE.M.A. Carolina Power & Light Co. 83/06/30 DENTON, H.R.

  Office of Nuclear Reactor Regulation, Director. 299 17251: 197.

  24X Fichs 50-400, 83/06/30, 8307060121.
- --8307060127 Amend 7 to FSAR.

  4 Carolina Power & Light Co 83/06/30 56pp. 19251:199. 24X
  Fiche 50-400/83/06/30/8307060121
- 8307140267 Advises that Amend 7 to FSAR distributed to encl list of individuals.
  ZIMMERMAN, S.R. Carolina Power & Light Co. 83/07/02. EISENHUT, D. C. BUYLSTON, OF Licensing. 4pp. 19522: 335. 24X Fishe, 50-400, 83/07/07. G307140267.
- --8307270060 Amend 8 to FSAR.

  \* Carolina Pawer & Light Co 83/07/22, 79pp. 19765:003. 24X Fiche:50-400.83/07/22,8307270057
- io/200355 Forwards Affidavit of Svc & revised distribution list for Amend B to FSAR. ZIMMERMAN.S.R. Carolina Power & Light Co. 83/07/25. EISENHUT.D.G. Division of Licensing. 4pp. 19789.001. R4x Fichor50-400.83/07/25. 8307280355. 8307280355 Forwards Affidavit of Svc & revised distribution list for
- G. Inspection reports, IE Bulletins b correspondence
- B30714038| Forwards IE Insp Repts 50-400/83-19 & 50-401/83-19 on B30531-0602 No noncompliance noted VERRELLI.D.M. Division of Project & Resident Programs B3/06/22 UTLEVIE E Carolina Power & Light Co. 2pp. 19925.065. 24X Fiche: 50-400, 83/06/22, 8307140381.

- --B307140365 IE Insp Repts 50-400/83-19 % 50-401/83-19 on 830531-0402.No noncompliance noted Major areas inspected fire protection.

  MILLERIAH Region 2. Office of Director COMLONIT E. Division of Engineering & Radiological Safety Programs 83/06/20. Spp. 19525 047 24% Fiche 50-400.83/05/22.8307140381.
- 830-27040: IE Info Notice 83-46. "Common Mode Valve Failures Degrade
  Eurry Recirculation Spray Subsystem." Svc list encl.
  JORDANLE L. Division of Emergency Prepaiedness & Engineering
  Response (Post 830103) 83/07/11 Consolidated Edison Co. of New
  York. Inc. 154pp 19563 293 243 Fiche. 50-000. 83/07/11. 8306270401.
- 8305270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. UGREAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/12 Consolidated Edison Co. of New York, Inc. 141pp. 19563.153 24X Fiche: 50-000.83/07/12,8306270404.
- 8307220333 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-16 & 50-401/83-16 LEHTS.P C Division of Project & Resident Programs. 83/07/12. UTLEY.E E Carolina Power & Light Co. 1p. 19675.339, 24X Fiche: 50-400.83/07/12.8307220333
- --830722033c Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-400/83-16 & 50-401/83-16. Corrective actions: cable tray & cable tray support insp programs revised. PARSONS.R M Carolina Power & Light Co 83/06/16. O'REILLY, J. P. Region 2. Office of Director 3pp 19675: 340 24X Fiche 50-400. 83/07/12, 8307220333
- --8397220340 Forwards IE Insp Repts 50-400/83-16 \$ 50-401/83-16 on 830320-0420 \$ notice of violation.

  LEMIS.R C Division of Project & Resident Programs. 83/05/19. UTLEV.E E Carolina Power & Light Co 2pp. 19675:343. 24X Fiche 50-400.83/07/12.8307220333
- --8307220342 Natice of violation from insp on 830320-0420. \* Region 2. Office of Director. 83/05/19. lp. 19675:345. 24X Fiche 50-400.83/07/12.8307220333.
- --8307220344 IE Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420. Mancapliance noted insp status of electrical raceway supposts not completed prior to installation of cable trays MAXWELL GF, PREVATE/R.L. Region 2, Office of Director. BEMIS.P. Division of Project & Resident Programs. 83/05/17. 5pp. 19675-346. 24x Fiche: 50-460.83/07/12.8307220333.
- 8305270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive 1-125 & 1-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR. J. M. Division of QA. Safeguards & Inspection Programs (Post 830103) 83/67/14 Consolidated Edison Co. of New York, Inc. 1149p. 19715 270 24x Fiche: 50-000, 83/07/14, 8306270406.
- 8307220130 Ack receipt of 830430 & 0701 itrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-40783-18. 50-401/83-18. VERNELLY, PM Division of Project & Resident Programs. 83/07/15. UTLEY, E.E. Carolina Power & Light Co. 1p 19684:035. 24X Fiche 50-409.83/07/15.8307220130.
- --8307220137 Forwards IE insp Repts 50-400/83-18 % 50-401/83-18 on 830425-0528 & notice of violation VERRELLI, D. M. Division of Project & Resident Programs. 83/06/10. UTLEY. E. E. Carolina Power & Light Co. 2pp. 19684:056. 24X Fiche 50-400,83/07/15,8307220130
- --8207220135 Notice of violation from Insp on 830420~0520.
   Region 1. Office of Director 83/06/10. lp. 19684:058. 24X
- --B307220141 IE Insp Repts 50-400/83-18 t 50-401/B3-18 on B30420-0520. Nancompliance noted failure to document completion of training programs in electrical training to welding. Arc strikes noted in heat affected zone to be metal. PREVATTE.R. MAYMELL. 6. Region 2. Office of Director. BEMIS.P. Division of Project to Resident Programs. B3/06/10. 6pp. 19884-039 24X Fiche: 50-400.83/07/15,6307220130
- --8307220143 Responds to NRC B30610 ltr re violation noted in IE Insp Rept 50-400/83-18 Corrective actions Deficiency & Disposition Rept 1553 generated OC ptps welding inspectors trained in identifying arc strikes PARSONS R M. Carolina Power & Light Co. B3/07/07 O'REILLY, J. P. Region 2. Office of Director 3pp. 19684-065 24X

- --8307220148 Responds to NRC 830610 ltr re violation noted in IE Insp Rept 50-400/83-18. Corrective actions, extensive audit of procedural reading assignments conducted 830303. All overdue requirements resubmitted. PARSONS, R. M. Carolina Power & Light Co. 83/06/30. D'REILLY, J. P. Region 2. Office of Director. 3pp. 19684: 068. 24x Fiche: 50-400.83/07/13.8307220130.
- R. Periodic operating reports  $\boldsymbol{z}$  related correspondence
- 8307260363 "Quarterly Data Rept Seismic Monitoring Program, Shearon Harris Nuclear Power Plant.Apr-June 1983." W/830721 ltr. ZIMHERMAN.S.R. Carolina Power & Light Co. 83/07/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19733:038. 24X Fiche: 50-400, 83/07/21, 8307260363.
- S. Reportable occurrences, LERs & related correspondence
- 8307120395 Interim deficiency rept re receipt of 34 Ruskin Mfg Cobackdraft dampers w/one counterbalance arm assembly in lieu of required two. Wyle Labs test results expected by 830715. Extension requested until 830808 for submittal of rept. PARSONS.R M. Carolina Power & Light Co. 83/06/29. D'REILLY, J. P. Region 2. Office of Director. 1p. 19430:197. 24X Fiche: 50-400.83/06/29, 8307120395.
- 8307190005 Interim deficiency rept re receipt of 34 backdraft dampers w/one counterbalance arm assembly instead of required two. Initially reported on 830602 Extension for rept on reportability until 830808 requested.
  PARSONS.R.M. Carolina Power & Light Co. 83/06/29. D'REILLY, J. P. Region 2, Office of Director. 1p. 19635: 015. 24X Fiche: 50-400, 83/06/29, 8307190005.
- 8307110338 Final deficiency rept Item 132 re removal of expansion anchors after insp. Initially reported on 830601. Hanger base plate in fuel handling bldg reinstalled, torqued & accepted by const insp. Insp. Procedure TP-39. Rev 5 revised. PARSDNS.R.M. Carolina Power & Light Co. 83/07/01. 0'REILLY, J. P. Region 2, Office of Director. 4pp. 19381:301. 24x Fiche: 50-400, 83/07/01, 8307110338.
- B307110440 Interim deficiency rept on Item 135 re insufficient Nuclear Energy Svcs reactor vessel preservice insp waveforms for pulsers. Initially reported on 830603. Condition not reportable per IOCFRBO, 55(e), per B30701 telcon. CHIANGI, N. J. Carolina Power & Light Co. 63/07/01. 0'REILLY, J. P. Region 2. Office of Director. 1p. 19380: 185. 24x Fiche: 50-400, 83/07/01, 8307110440.
- 8307120207 Interim deficiency rept re Items 95 & 72 concerning shop welding in Bergen-Paterson seismic I pipe hangers & undersize skewed fillet welds Initially reported on 820813 & 1105. Final rept by 831003. Also reported per Part 21. PARSONS,R.M. Carolina Power & Light Co. 83/07/01. D'REILLY, J.P. Region 2. Office of Director. Spp. 19423:284. 24X Fiche: 50-400.83/07/01.8307120207.
- 8307120316 Interim deficiency rept Item 96 re defective field welds on Bergen-Paterson pipe hangers previously accepted by QC welding inspectors & Item 72 re undersize skewed tee fillet welds on seismic I pipe hangers. Final rept by 831003. PARSONS,R M. Carolina Power & Light Co. 83/07/01. D'REILLY, J. P. Region 2, Office of Director. Spp. 19429:168. 24X Fiche: 50-400, 83/07/01, 8307120316.
- B307150380 Final deficiency rept re Item 136 on pipe hanger frame base metal reduction. Initially reported on 830606, Frame C-1-175 will be refabricated w/certified matl & will be welded onsite. Also reported per Part 21.

  PARBONS, R. M. Carolina Power & Light Co. 83/07/05. 0'REILLY, J. P. Region 2, Office of Director. 3pp. 19539:156. 24X Fiche: 50-400, 83/07/05, 8307190380.
- 8307220145 Interim deficiency rept Item 129 re weld deficiencies on ITE Gould Class IE 480-volt motor control ctrs. Initially reported on 830408 Extension of submittal of rept on reportability requested to 830831. Also reported per Part 21. PARSONS, R. M. Carolina Power & Light Co. 83/07/13. G'REILLY, J. P. Region 2. Office of Director. 1p. 19684:075. 24X Fiche: 50-400, 83/07/13, 8307220145.
- 830725039? Advises that Potentially Reportable Item 137 re Seismic Class I SA-36 carbon steel pipe hanger math, mfg by Bergan-Paterson, initially reported on 830614, not reportable per 10CFR50, 55(e) & Part 21. CHIANGI, N. J. Carolina Power & Light Co. 83/07/14. D'REILLY, J. P. Region 2, Office of Director. ip. 19703:153. 24X Fiche: 30-400, 83/07/14, 8307250399.

0404 Fourth interim deficiency rept. Item 61 re defective valve 195 on diesel engines mfg by Transamerica Delaval. 1411y reported on 810828. Final rept will be submitted by 166. Also reportable under Part 21. 1085. R.M. Carolina Power & Light Co. 83/07/14. 0'REILLY, J.P. 197. 2, Office of Director. 4pp. 19703: 209. 24X 1: 50-400, 83/07/14, 8307250404.

1485 Interim rept re welding deficiencies in main steam/feedwater int frames. Initially reported on 830715. Support frames asted. Item considered not reportable under 10CFR50. 55(e) t 21.

161.N.J. Carolina Power & Light Co. 83/07/15. O'REILLY, J.P. in 2. Office of Director. ip. 19734:168. 24X; 50-400,83/07/15.8307260485.

50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2 ication/construction stage documents & correspondence

070 Generic Ltr 83-22 to all operating reactor licensees, cants for OLs & helders of CPs for Westinghouse PWRs fety evaluation of "Emergency Response Quidelines." ist encl. RUT,D.G. Division of Licensing. 83/06/03. Yankee Atomic ric Co. 10pp. 19563:116. 24X Fiche:50-000,83/06/03,60070.

231 Notification of 830707 meeting w/technical review committee thesda,MD to discuss review of D4,D3 & E steam ator mods NG.J.B. Licensing Branch 4. 83/07/01. ADENBAM,E.G. Licensin

.mods 1.8. Licensing Branch 4. B3/07/01. ADENBAM,E.Q. Licensing 2pp. 19670:234. 24% Fiche:30-000,83/07/01.8307200231.

397 Generic Ltr 83-26 to all applicants for DLs & holders of or power reactors re clarification of surveillance rements for diesel fuel impurity Svc list encl. HUT.D.O. Division of Licensing, 83/07/05. Consolidated n Co. of New York, Inc. 16pp. 19390:317. 24X:50-000,83/07/05.8306270397.

329 Generic Ltr 83-27 to all licensees & applicants for ting power reactors & holders of CPs for power reactors rveillance intervals in STS 8vc list encl. HUT, D. G. Division of Licensing. 83/07/06. Consolidated in Co. of New York, Inc. 16pp. 19649:254. 24X:50-000.83/07/06.8307060327.

291 Confirms schedule for 830708 mgt meeting at Raleigh-Durham rt,Raleigh.NC to discuss status of outstanding abory issues. Proposed meeting agenda encl. LLY,J.P. Region 2: Office of Director. 83/07/06. UTLEY,E.E. ina Power & Light Co. 1p. 19523:044. 24X :90-000,83/07/06,8307140291.

i69 Generic Ltr 83-28 to all licensees of operating reactors, cants for GL & holders of CPs re required actions based nevic implications of Salem ATMS events. Svc list encl. HUT, D. G. Division of Licensing. 83/07/08. Consolidated in Co. of New York, Inc. 38pp. 19649: 269. 24X: 50-000, 83/07/08, 8307080169.

239 Advises that review of 830509 description of QA program in ess. R.C. Division of Project & Resident Programs. 83/07/08. \*IE.M.A. Carolina Power & Light Co. 1p. 19523:105. 24 50-400,83/07/08.8307140239.

300 Forwards proprietary "Independent Evaluation of Proposed to Westinghouse D4,D5 & DE Steam Generators." Rept 21d (ref 10CFR2.790). RTELD.L. Steam Generator Cuners Group. BUTTERFIELD.L. wealth Edison Co. 83/07/18. EISENHUT.D.G. Division of sing. 3pp. 19444:114. 24X Fiche:50-000,83/07/18,8307210300.

124 Summary of 830707 meeting w/technical review committee in ada.MD re Model D4/D5/E steam generator mod.Viewgraphs

45, J.B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 19738: 132. 24X Fiche: 50-000, 83/07/18: 8307250124.

Praft/Final Environmental Statements, suppls & correspondence

054 Forwards comments on DES re operation of facilities 0-0972). Opinions & calculations presented do not agrily reflect Pennsylvania State Univ position. ETT.W.A. Pennsylvania State Univ. 83/06/30. Division of sing. 5pp. 17273:261. 24X Fiche:50-400.83/06/30.8307070054.

8307060258 Comments on DES (NUREC-0972) re plant operation. Requesting public comments after decision supporting issuance of OL made inappropriate.

LOTCHIN.P. Affiliation Unknown. 83/07/01. Division of Licensing. 3pp. 19239: 303. 24X Fiche: 50-400, 83/07/01, 8307060258.

8307110258 Forwards comments on DES. Requests clarification of section re chemical impacts of bloudown discharge on reservoir. Statement acceptable.

MODRE, S. N. Environmental Protection Agency. 83/07/01. KADAMBI.P. Office of Nuclear Reactor Regulation. Director. 2pp. 19374:266. 24X Fiche:50-400.83/07/01.8307110258.

8307070083 Forwards comments on DES, NUREC-0972 Marked-up DEB pages correcting typographical errors & containing minor comments enci. HURFORD, W. J. Carolina Power & Light Co. 83/07/05. EISENHUT, D. Q. Division of Licensing. 20pp. 19293; i38. 24X Fiche: 50-400,83/07/05. 8307070083.

8307t30091 Forwards NC Dept of Natural Resources & Community
Development comments on DES. Wildlife mgt plan for mitigation
of land use impacts not yet received,
BAGGETT.C. North Carolina, State of, 83/07/05, KNIGHTON.O.W.
Licensing Branch 3. 2pp. 19465:334. 24X Fiche: 50-400, 83/07/05,
8307130091.

E. NRC Safety Evaluation Report (SER), supply & correspondence

8307010053 Forwards responses to draft SER Open Items 103,106,114,118, 119,123,149 & 153.

MCDUFFIE.M.A. Carolina Power & Light Co. B3/06/27, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 18pp. 19168:314, 24X Fiche: 50-400,83/06/29,8307010053.

8307060111 Forwards responses to draft Chemical Engineering Branch SER Open Items 146 & 147 re schematics of sample lines & panels (per TMI Item II. B. 3) re post-accident sampling sys. MCDUFFIE, M.A. Carolina Power & Light Co. B3/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 17252; 214. 24X Fiche: 50-400, 83/06/30, B307060111.

8307060144 Forwards revised response to Accident Evaluation Branch draft SER Open Item 55 re containment spray sys design. Responses to remaining open items forthcoming. MCBUFFIE.M.A. Carolina Power & Light Co. 83/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19247:360. 24X Fiche:50-400,83/06/30.8307060144.

8307060302 Forwards responses to Auxiliary Sys Branch draft SER Open Items 134,135 & 224,re removal of barrier in fuel cask pool, crane load block & protection of circulating water sys. crane to ab stock a procession of the process of the pectively.

MCDUFFIE, M.A. Carolina Power & Light Co. 83/06/30. DENTON, H. R.

Office of Nuclear Reactor Regulation, Director. 7pp. 19238: 332.

24X Fiche: 50-400, 83/06/30, 8307060302.

8307040095 Responds to Containment Sys Branch draft SER Open Item &B. Addl failure alarm located within control room unnecessary. Continuous indication will be functioning within 30 minutes of safety injection initiation per TMI Item II.F. i. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 17252:008. 24X Fiche: 50-400.83/07/01.8307040095.

8307060114 Responds to draft SER Open Item 10 re meteorological instrumentation. Util will complete review of emergency plan during emergency preparedness implementation appraisal. MCDUFFIE, M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19252:219. 24X Fiche: 50-400, 83/07/01, 8307060114.

8307060163 Forwards response to Matis Engineering Branch draft SER Open Item 36 re beltline mati test requirements of 10CFR50, App G, Paragraph III.C.2. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19250:270. 24X Fiche: 50-400, 83/07/01, 8307060163.

8307040234 Forwards responses to Procedures & Sys Review Branch draft SER Open Items 194,195 & 217. Responses cover NGSS review of low-power testing, power ascension & emergency operating procedures per NUREO-0737.

MCDUFFIE. M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19239: 356. 24X Fiche: 50-400, 83/07/01, 8307040234.

8307070085 Forwards response to Core Performance Branch draft SER Open Item 29 re visual exam of discharged fuel assemblies after refueling.

MCDUFFIE, M.A. Carolina Power & Light Co. 83/07/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19269:361, 24X Fiche: 50-400, 83/07/01, 8307070085.

- 8307080390 Forwards responses to draft SER open items. List of items. responsible NRC review branch & reviewer encl. MCDUFFIE.M.A. Carolina Power & Light Co. 83/07/01. DENTON. H. R. Office of Nuclear Reactor Regulation. Director. 166pp. 19349: 330, 24X Fiche: 50-400, 83/07/01, 8307080390.
- 8307070125 Forwards responses to Auxiliary Sys Branch draft SER Open Items 129 through 131 & 137 re spent fuel pool drainage & storage. Applicable FSAR sections will be revised Responses to remaining open items forthcoming.

  MCBUFFIE.M.A. Carolina Power & Light Co. 83/07/05. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 6pp. 19269:338. 24X Fiche: 50-400.83/07/05.8307070125.
- 8307080315 Forwards response to draft BER Open Item 209 re single failures assumed for accidents.

  MCDUFFIE.H.A. Carolina Power & Light Co. 83/07/05. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 12pp. 15350:151. 24X Fiche: 50-400, 83/07/05, 8307080315.
- 8307140323 Forwards responses to Meteorological & Effluent Treatment Branch draft SER Open Items 15B & 186. Turbine gland sealing sys is non-nuclear nonseismic Category I sys. RCDUFFIE, M.A. Carolina Power & Light Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19525:117. 24X Fiche: 50-400, 83/07/11, 8307140323.
- 8307270340 Forwards responses to draft SER open items & rev to 830701 response to Open Item 151.

  MCDUFFIE,M.A. Carolina Power & Light Co. 83/07/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 346pp. 19768:001. 24X Fiche: 50-400, 83/07/15, 8307270340.
- 8307210146 Forwards responses to draft SER Dpen Items 172 & 173. Resumes of personnel to fill positions of environ & radiation control manager & radiation control supervisor will be added to FSAR when positions filled.

  MCDDFFIE.M.A. Carolina Power & Light Co. 83/07/18, DENTGN.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19668:349, 24X Fiche: 50-400,83/07/18,8307210146.
- 9307280361 Forwards responses to Licensee Qualification Branch Questions 630.1 630.8 re personnel training program.per draft SER Open Items 316-323. Training for all license candidates completed prior to cold license exam. MCDUFFIE.M. A. Carolina Power & Light Co. 63/07/25. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2Spp. 19776:259. 24X Fiche: 50-400.83/07/25.8307280361.
- F. Security, medical, emergency & fire protection plans
- 8307140381 Forwards IE Insp Repts 50-400/83-19 & 50-401/83-19 on 830531-0602. No noncompliance noted.

  VERRELLI, D. N. Division of Project & Resident Programs. 83/06/22. UTLEV.E. E. Carolina Power & Light Co. 2pp. 19525:065. 24X Fiche: 50-400.83/06/22,8307140381.
- --8307140383 IE Insp Repts 50-400/83-19 & 50-401/83-19 on 830531-0602 No hencompliance noted Major areas inspected fire protection. MILLER W. H. Region 2. Office of Director. B3/06/20. 5pp. 19525:067. 24X Fiche: 50-400. B3/06/22. 8307140381.
- 8307060114 Responds to draft SER Open Item 10 re meteorological instrumentation. Util will complete review of emergency plan during emergency preparedness implementation appraisal. MCDUFFIE,K.A. Carolina Power & Light Co. B3/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19252:220.24X Fiche:50-400,83/07/01.8307040114.
- 8307220109 Notification of 830720 & 21 meetings w/util at site to review physical security plan per IOCFR73.21. LICITRA E.A. Licensing Branch 3. 83/07/08. KNIGHTON, O. W. Licensing Branch 3. 17692: 339. 24X Fiche: 30-400, 83/07/08, 8307220109.
- 8307150225 Forwards responses to Chemical Engineering Branch FSAR safety & acceptance review questions re fire protection. Draft safe shutdown analysis in case of fire transmitted on 830527. Final analysis to be transmitted by 830717.

  KCDUFFIE.M.A. Carolina Power & Light Co. 83/07/11. DENTON.H.R. Defice of Nuclear Reactor Regulation. Director. 19pp. 19537: 332 24X Ficha: 50-400.83/07/11.8307150225.
- B307220333 Ack receipt of B30616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-400/B3-16 & 30-401/B3-16.

  LEWIS R. C. Division of Project & Resident Programs. 83/07/12.

  UTLEY. E. C. Carolina Power & Light Co. 1a. 19675:339. 24X

  Fiche: 80-400.83/07/12, B307220333.

- --B307220340 Forwards IE Insp Repts 50-400/B3-16 & 50-401/B3-16 on B30320-0420 & notice of violation.

  LEMIS.R.C. Division of Project & Resident Programs. B3/05/19.

  UTLEY.E.E. Carolina Power & Light Co. 2pp. 19675:343. 24X Fiche:50-400.83/07/12,8307220333.
- --8307220344 IE Insp Repts 50-400/B3-16 & 50-401/B3-16 on 830320-0420. Noncomptiance noted insp status of electrical raceway supports not completed prior to installation of cable trays.

  MAXNELL, G. F. Region 2, Office of Director. 83/05/17. Spp. 19679:346. 24X Fiche: 80-400.83/07/12.8307220333.
- G. Adjudicatory correspondence
- 8307050195 Advises that author cannot attend 830720-21 prehearing conference. Joint Intervenors will represent Kudzu Alliance position on issues.

  FAYNELM.T. Edelstein & Payne. PAYNELM.T. Kudzu Alliance.

  83/05/27. KELLEY.T. L., BRIGHT.G.G., CARPENTER.J.H. Atomic Safety and Licensing Board Panel. 2pp. 19197:211. 24X

  Fiche: 50-400, 83/06/27, 8307050195.
- 830705017B Forwards revised joint interrogatories on Contentions IV.V & VI (Pirst set). Related correspondence.
  PAYNE, M.T. Edelstein & Payne. 83/06/27. O'NEILL, J. H. Shaw, Pittman, Potts & Troubbridge. 2pp. 19199: 221. 24X
  Fiche: 50-400, 83/06/27, 8307050178.
- --8307050205 First set of Joint Intervenors interrogatories on Contentions IV.V & VI (first set). Certificate of Svc encl. PAYNE.M.T. Kudzu Alliance. PAYNE.M.T. Edelstein & Payne. 83706/27. Carolina Power & Light Co. 15pp. 19199: 223. 24x Fiche: 50-400. 83/06/27, 8307050198.
- 8307060198 Third set of interrogatories & request for production of documents to joint intervenors Certificate of Svc encl.
  BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Troubridge. 83706/30, Chapel Hill Anti-Nuclear Group Effort. 13pp. 19250:231. 24X Fiche:50-400,83/06/30,8307060198.
- 8307060383 Petition under 10CFR2.758 for waiver of rule barring issues re alternatives to & need for power.from CL proceeding.

  Issues must be litigated since environmentally & sconomically superior alternatives exist.

  EDDLEMAN.W. Eddleman.W. 83/06/30. Atomic Safety and Licansing Board Panel. 2pp. 19234:302. 24X Fiche:50-400.83/06/30.8307060393.
- --8307060386 Submission of Contention 15-AA that operating capacity factor of 55% in DES overestimated Contention submitted per ASLB 830527 order.
  EDDLEMAN.M. Eddleman, W. 63/06/30. Atomic Safety and Licensing Board Panel. 2pp. 19234:304. 24% Fiche: 50-400,83/06/30,83/06/30,
- --B307060391 Affidavit of W Eddleman summarizing economic & environ superiority of alternative to plant operation. Testimony of individuals before North Carolina Util Commission & portions of State of NC rept on need for power encl. EDBLEMAN.W. Eddleman W. B3/06/30. 190pp. 19234:306. 24X Fiche: 50-400,83/06/30. B307060383.
- B307070022 Supplemental answers to interrogatories on Contentions 75 & B3/B4. Certificate of Svc encl.Related correspondence.

  CARROW, H. Carolina Power & Light Co. 83/06/30. EDDLEMAN. W. Eddleman. W. 7pp. 19293:234. 24X Fiche: 50-400, B3/06/30, B307070022.
- 8307070025 Fourth set of interrogatories & request for production of documents, Centificate of Svc encl. Related correspondence.
  CARROW, H. Carolina Power & Light Co. 83/06/30. WILSON, R. D. Wilson, R. 1ipp. 19273: 334. 24X Fiche: 50-400, 83/06/30, 8307070025.
- 8307070071 Fourth set of interrogatories & request for production of documents re Contentions 75 & 83/84. Certificate of Svc encl. Related correspondence. CARROW. H. Carolina Fower & Light Co. 83/06/30. EDDLEMAN, W. Eddleman, W. 13pp. 19273:115. 24X Fiche: 50-400, 83/06/30, 8307070071.
- 8307070076 Interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
  READ.D.F. Chapel Hill Anti-Nuclear Group Effort. 83/06/30.
  Carolina Power & Light Co. 9pp. 19293:128. 24X
  Fiche: 50-400.83/06/30.8307070076.
- 8307070092 Second set of interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
  CARROW.H. Carolina Power & Light Co. CARROW.H. Shaw, Pittman., Potts & Trowbridge. 83/06/30. Conservation Council of North Carolina. 16pp. 19294:001. 24x Fiche: 50-400, 83/06/30, 8307070092.

- B307060173 Response to ASLB 830527 memorandum & order ruling on cost saving contentions, discovery disputes & scheduling matters. Commission assumed capacity factor of 59% considered conservative. Certificate of Svc encl.

  O'NEILL, J. H. Carolina Power & Light Co. O'NEILL, J. H. Shaw, Pittman, Potts & Troubridge. 83/07/01. Spp. 19249:184. 24X Fiche: 50~400,83/07/01,8307060173.
- 8307060159 Third set of general interrogatories & interrogatories on Contentions 75.80,83,84,646 & 67. EDDLEMAN,W. Eddleman, W. 83/07/02. Carolina Power & Light Co. 20pp. 19280:174. 24X Fiche:50-400,83/07/02,8307060159.
- 8307060402 Response to util May 1983 DCRDR update, including revised & new contentions. Certificate of Svc encl.
  EDDLEMAN, W. Eddleman, W. 83/07/02. Atomic Safety and Licensing Board Panel. 11pp. 19236:069. 24X Fiche: 50-400, 83/07/02, 8307060402.
- B307i30242 Notice of withdrawal of D Greenblatt as intervenor counsel on security-related contentions. J Runkle will replace Greenblatt. Certificate of Svc encl. RUNKLE. J. Runkle, J. D. B3/07/07. 2pp. 19474:357. 24X Fiche: 50-400. B3/07/07. B307i30242.
- 8307120077 Response to W Eddleman 830624 response to NRC Apr 1983 DES. DES contains no new info previously unavailable in public domain upon which new contentions could be based. Notice of appearance & Certificate of Svc encl.

  BARTH-C.A. Hearing Branch 1. 83/07/08. 18pp. 19423:089. 24X

  Fiche: 50-400, 83/07/08, 8307120077.
- B307130231 Advises that util considered Commission 830630 Memorandum & Order CLI-83-19 in encl filings Certificate of Svc encl.
  BAXTER.T.A. Shaw, Pittman. Petts & Trowbridge. BAXTER.T.A.
  Carolina Power & Light Co. B3/07/08. KELLEY, J.L., BRIGHT.Q.O., CARPENTER.J.H. Atomic Safety and Licensing Board Panel. Spp. 19473:270. 24X Fiche: 30-400, 83/07/08, 8307130231.
- --B307130253 Motion for dismissal of Conservation Council of North Carolina Contention 4 & Chapel Hill Anti-Nuclear Group Effort Contention 7 & response to W Eddleman 830620 contention on spent fuel transportation. O'NEILL. J. A. Carolina Power & Light Co. O'NEILL. J. A. Shaw, Pittman, Potts & Trowbridge. B3/07/08. Atomic Safety and Licensing Board Panel. 25pp. 19473:341. 24% Fiche: 50-400,83/07/08.B307130231.
- --83071302&1 Affidavit of LH Martin re shipment of spent fuel. Shipment of spent fuel from Robinson &/or Brunswick to Harris will be considered. Shipments will be made so environ impacts fall within 10CFR51.20, Table S-4, values.

  MARTIN.L.H. Carolina Power & Light Co. 83/07/06. 2pp. 19474:004. 24X Fiche: 50~400, 83/07/08, 8307130231.
- B307130244 Forwards protective order governing access to security info & proposed affidavit of nondisclosure for security plan phase of proceedings. Appropriate notice of appointment as counsel to intervenors required Related correspondence. CARROW, H. Carolina Power & Light Co. B3/07/08. RUNKLE, J. D. Runkle, J. D. 1p. 19474: 359. 24X Fiche: 50-400, B3/07/08, B307130244.
- 8307130047 Response to W Eddleman 830502 contentions re applicant onsite emergency plan. Contentions 150,153,154,155,156,158, 159 & 150 should be denied Contentions 151,152 & 157 should be deferred. Centificate of Svc encl.

  BARTH.C.A. Hearing Branch 1. 83/07/11. Atomic Safety and Licensing Board Panel. 10pp. 19474:217. 24X Fiche: 50-400,83/07/11,8307130047.
- B307140435 Notice of appearance in proceeding Certificate of Svc encl. RIDGWAY, D. A. Carolina Power & Light Co. RIDGWAY, D. A. Shaw. Pittman, Potts & Trowbridge. B3/07/11. 4pp. 19520:162. 24X Fiche: 50-400.83/07/11.6307140435.
- B307140437 Response to B30523 request for suppl to B30510 answers to interrogatories. Certificate of Svc encl. Related correspondence.
  FLYNN: S.F. Garolina Power & Light Co. 83/07/11. Wilson: R. 49gp. 19821:034. 24% Fiche: 50-400:83/07/11:8307140437.

- 8307140440 Forwards Pages 43 & 44 to util 830708 response to H Eddleman contentions re DES, inadvertently omitted.

  O'MEILL, J. H. Shaw, Pittman, Patts & Troubridge, O'MEILL, J. H. Caralina Power & Light Co. 83/07/11, KELLEY, J. L., CARPENTER, J. H., BRIGHT, G. O. Atomic Safety and Licensing Board Panel. 1p. 19521, 256. 24X Fiche: 30-400, 83/07/11, 8307140440.
- --8307140445 Pages 43 & 44 to util 830708 response to W Eddleman contentions re DES. Inadvertently ommitted. Svc list encl.

  \* Carolina Power & Light Co. 83/07/11. Atomic Safety and Licensing Board Panel. 4pp. 19521: 257. 24% Fiche: 50-400, 83/07/11, 8307140440.
- 8307140454 Response to W Eddleman 830502 proposed contentions reemergericy plan. Opposes Contentions 150/2, 150/29, 150/30, 150/55, 150/57, 150/63, 150/97, 150/97, 150/100, 150/117, 150/118, 150/124 & 151 160. Certificate of Svc encl.
  RIDOWAY.D.A. Carolina Power & Light Co. RIDOWAY.D.A. Shaw, Pittman, Patts & Trowbridge. 83/07/11. Atomic Safety and Licensing Board Panel. 35pp. 19521: 204. 24X Fiche: 50-400, 83/07/11, 8307140454.
- 8307140458 Extends invitation to participate in 830721 site tour Svc list encl. FLYNN, S.F. Carolina Power & Light Co. 83/07/11. BARTH.C. Hearing Branch I. EDDLEMAN.W. Eddleman, W. PAYNE, M. T. Eddlstein & Payne, 2pp. 19521:196. 24X Fiche: 50-400, 83/07/11, 8307140458.
- 830715018B Motion to compel discovery re Eddleman 29,378,75 & 83/84 per applicants objections. Certificate of Svc. certificate of negotiations & notice of negotiations encl. EDDLEMAN.W. Eddleman. W. B3/07/11. BRIGHT.O. CARFENTER, J. H. KELLEY, J. L. Atomic Safety and Licensing Board Panel. 19pp. 19530:342. 24X Fiche:50-400.83/07/11.8307150188.
- 8307140443 Answer to W Eddleman 830626 motion for extension to file second round interrogatories & to file interrogatories on Contentions 27 & 378 until 830720. Agrees w/second request & opposes first request M/Certificate of Svc.

  BAXTER, T. A. Carolina Power & Light Co. BAXTER, T. A. Shaw, Pittman, Potts & Troubridge. 83/07/12. Atomic Safety and Licensing Board Panel. 10pp. 19521: 261. 24X Fiche: 50-400,83/07/12,8307140443.
- 8307140451 Requests input un alleged economics & alleged technology set forth in W Eddleman (OCFR2, 758 petition to litigate need for power & alternatives to plant Logic & coherence of Eddleman scenarios bear close scrutiny.

  BARTH. C.A. Hearing Branch 1. 83/07/12. KNIGHTON, 9. Licensing Branch 3. 1p. 17521: 243. 24X Fiche: 50-400, 83/07/12, 8307140451.
- 8307140466 Forwards Commission 830701 order on issue of late filed contentions & NUREG-0794, "Protection of Unclassified Safeguards Info," W/a NUREG. BARTH, C.A. Hearing Branch 1. 83/07/12. FLYNN.S. Carolina Power & Light Co. 1p. 19521:134. 24X Fiche: 50-400,83/07/12.8307140466.
- B307150201 Informs that applicants considering filing second motion to compel discovery on Interrogatory 2 per unsuccessful negotiations w/Eddleman. Discusses Eddleman B30625 response. BAXTER.T.A. Shaw, Pittman. Potts & Trowbridge. BAXTER.T.A. Carolina Power & Light Co. 83/07/12. KELLEY.J.L., BRIGHT, G.O., CARPENTER.J.H. Atomic Safety and Liconsing Board Panel. 4pp. 19530: 242. 24X Fiche: 50-400.83/07/12.8307150201.
- B3071902B3 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  BAXTER.T.A. Shaw. Pittman. Potts & Trowbridge. BAXTER.T.A.
  Carolina Power & Light Co. B3/07/13. KELLEY.J.L., BRIGHT.G.D., CARPENTER.J.H. Atomic Safety and Licensing Board Panel. 1p. 1962B:034. 24% Fiche: 50-400, B3/07/13, B3071902B3.
- --8307190288 Notifies of employment at law firm VR Harding will not participate in any case pending before NRC, Svc list encl. HARDING, V. R. Shaw, Pittman, Potts & Trowbridge. 83/07/13. KELLEY, J.L., BRIGHT, G. D., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 3pp. 19628:035. 24% Fiche: 50-400, 83/07/13,8307190283.
- 8307210281 Response to fourth set of interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
  MILSON.R. Wilson, R. 83/07/14. Carolina Power & Light Co. App. 19464: 198. 24X Fiche: 50-400, 83/07/14, 8307210281.
- 8307190262 Memorandum & order memorializing 830714 telcon re postponement of upcoming prehearing conference & related matters. KELLEY.J.L. Atomic Safety and Licensing Board Panel. 83/07/15. 4pp. 19628: 263. 24X Fiche: 50-400.83/07/15.8307190262.

- 8307210171 Forwards modified draft protection order & affidavit of nondisclosure & submits summary of unresolved issues discussed on 830713. Draft incorporates NRC & intervenor suggestions. Certificate of Svc enct. FLYNN, S. F. Carolina Power & Light Co. B3/07/15. KELLEY, J. L., BRIGHT, C. O., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 11pp. 19666:047. 24X Fiche: 50-400, 83/07/15, 8307210171.
- 8307210203 Confirms 830718 telcan re agreement concerning intervenor 830630 request for production & interregatories Applicants will respond to discovery requests on Contention 44 by 830812.

  BAXTER.T.A. Shaw, Pittman, Potts & Trowbridge. BAXTER.T.A. Carolina Power & Light Co. 83707/19. REED, D. F. Chapel Hill Anti-Nuclear Group Effort. 4pp. 19609:043. 24X
  Fiche: 50-400, 83/07/19. 8307210203.
- 8307260281 Notice of amend to W Eddleman third set of interrogatories to utils. Page 8 should not be included. Certificate of Svc encl.
  EDDLEMAN. M. Eddleman, W. 83/07/19. Caroline Power & Light Co. 2pp. 19726: 206. 24X Fiche: 50-400,83/07/19,8307260281.
- 8307250247 Forwards RH Odegaarden.P Bemis.HC Scidle.F Hawkins & T Mo signatures to complete NRC 830624 responses to interrogatories. BARTH.C.A. Hearing Branch 1. 83/07/20. EDDLEMAN.H. Eddleman. H. 8pp. 19705:328. 24X Fiche:50-400,83/07/20.6307250247.
- 8307250346 Response upposing admission of W Eddieman proposed Contention 15-AA Te NEPA cost-benefit balance.Eddieman fails to plead litigable contention w/adequate basis & specificity.

  O'NEILL.J.H. Carolina Power & Light Co. D'NEILL.J.H. Shaw. Pittman. Potts & Trowbridge. 83/07/20. Atomic Safety and Licensing Board Panel. 7pp. 19702:004. 24X Fiche: 50-400. 83/07/20.
- --8307230330 Fifth set of interrogatories & request for production of documents re Eddleman Contentions 29/30 & 378. Certificates of Syc encl.

  BAVSER.D.B. Carolina Power & Light Co. BAVSER.D.B. Shaw. Fittman, Potts & Troubridge. 83/07/20. Eddleman, W. 30pp. 19702:011. 24X Fiche: 50~400,83/07/20.8307250346.
- B307260341 Answer to applicant response to motion for extension of time re-second round interrogatories on environ contentions. EDDLEMAN. W. Eddleman. W. 83/07/20. 2ps. 19726:332. 24X Fithe: \$0-400.83/07/20.8307260341.
- 8307250285 Amend to svc list.
  MILLER.R.G. Atomic Safety and Licensing Goard Panel. 83/07/21. 1p. 19705:305. 24X Fiche: 50-400,83/07/21,8307250285.
- 8307250337 Advises that during 830721 telephone conference, applicants & NRC did not modify positions taken in written response to proposed contentions. H Eddleman will reflect changes in written reply to applicant & NRC written responses.

  BAXIER, T.A. Shaw, Pittman, Potts & Trowbridge. BAXIER, T.A. Carolina Power & Light Co. B3/07/21. KELLEY, J.L., BRIGHT, G.C., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 4pp. 19703:007. 24X Fiche: 50-400, 83/07/21, 8307250337.
- B307260360 Advises that util does not accept H Eddleman 830625 reply as conforming to ASLB 830527 holdings on General Interrogatory 2 re identification of experts or witnesses. Svc list encl. Related correspondence. BAXTER.J. A. Shaw, Pittman, Potts & Trowbridge, BAXTER.J. A. Carolina Power & Light Co. 83/07/22. KELLEY.J. L., BRIGHT.G.O., CARPENIER.J. H. Atomic Safety and Licensing Board Panel. 3pp. 17733.031. 24X Fiche: 50-400, 83/07/22.8307260360.
- 8307260483 Objections to applicant 830711 draft affidavit of nondisclosure & protective order governing access to security plan info, Proposed restricted time schedule makes proper review difficult Cartificate of Svc encl. RUNKLE, J. D. Joint Intervenors-Shearon Harris. 83/07/22. Atomic Safety and Licensing Board Panel. 11pp. 19731:145. 24X Fiche: 50-400, 83/07/22, 8307260483.
- 8307260248 Fourth set of general interrogatories & interrogatories on Contentions 27 & 378. EDDLEMAN.W. Eddleman, W. 83/07/25. Carolina Power & Light Co. 31pp. 19727:007. 24X Fiche: 50-400.83/07/25,8307260248.
- 8307280163 Requests response to 830630 interrogatories on Joint Contention II or request for extension. Early response important due to 830901 deadline for motion for summary disposition Svc list encl.

  BAXTER.T. A. Bhaw. Pittman. Potts & Trowbridge. BAXTER.T. A. Carolina Power & Light Co. 83/07/25. PAYNE.M.T. Edelstein & Payne. 3pp. 19792:076. 24x Fiche: 50-400.83/07/23,8307280163.

- 8307280183 Answer opposing W Eddleman 830711 motion to compel #istim re applicant response to W Eddleman general interrogatories & interrogatories on Contentions 29 % 378 Certificate of Svc encl. Related correspondence.

  8AUSER, D.B. Carolina Power & Light Co. BAUSER, D.B. Shaw, Pittay, Potts & Troubridge. 83/07/26. Atomic Safety and Licensing Span Panel. 21pp. 19791:268. 24X Fiche: 30-400,83/07/26.8307280183.
- B307280167 Comments on util B30715 transmittal to ASLB & Runile B3072 comments. Clearer statement re not removing safeguards papers needed in affidavit of nondisclosure. Site visit would be more meaningful at later stage of const. BARTH.C.A. Hearing Branch 1. 83/07/27. KELLEY.J.L., CARPENTER.J.H., BRIGHT.O.D. Atomic Safety and Licensing Board Famil 2pp. 19791: 293. 24X Fichs: 50-400, 83/07/27, 8307280167.
- 8307290142 Advises that second round discovery requests on Contenting 27 & 378 will be treated as having been served on 630723, Original copy lost in mail Svc list encl. Related correspondence.

  8AXTER, T. A. Shaw, Pittman, Potts & Trombridge, 83/07/27, EDDLEMAN, W. Eddleman, H. 3pp. 19821:058, 24X Fiche: 50-400, 83/07/27, 8307290142.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307060121 Forwards Amend 7 to FSAR, in response to draft SER Opin lim 132, 136, 137, 198, 199, 203, 204 & 207, MCDUFFIE, M. A. Carolina Fower & Light Co. B3/06/30. DENYON, M. R. Office of Nuclear Reactor Regulation, Director. 2pp. 1925: 197, 24X Fiche: 50-400, 83/06/30, 8307060121.
- --8307040127 Amend 7 to FSAR. \* Carolina Power & Light Co. 83/06/30. 56pp. 19251:199. 24 Fiche: 50-400, 83/06/30, 8307060121.
- 9307140267 Advises that Amend 7 to FSAR distributed to encl lift of individuals.

  ZIMMERMAN, S.R. Carolina Power & Light Co. B3/07/07. EIBEMNILD:
  Division of Licensing. 4pp. 19522:335. 24X Fiche: 50-400, 83/07/07.
- 8307270057 Forwards Amend 8 to FSAR. in response to draft BER Open Items 58.61.65, 113 & 202. MCDUFFIE. M. A. Carolina Power & Light Co. 83/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19765:001. 24X Fiche: 50-400.83/07/22.8307270057.
- --8307270060 Amend B to FSAR.

  \* Caroline Power & Light Co. 83/07/22. 79pp. 19765:003. 24I
  Fiche: 50-400.83/07/22,8307270057.
- 8307280355 Forwards Affidavit of Svc & revised distribution list for Amend 8 to FSAR. ZIMMERMAN, B. R. Carolina Power & Light Co. 83/07/25. EIBEMULD: Division of Licensing. 4pp. 19789:001. 24X Fiche: 50-400,83/07/25. 8307280355.
- G. Inspection reports, IE Bulletins & correspondence
- B3071403B1 Forwards IE Insp Repts 50-400/83-19 & 50-401/83-19 on B30531-0602. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. B3/06/22. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19525:065. 24X Fiche: 50-400, B3/06/22, B3071403B1.
- --8307140385 IE Insp Repts 50-400/83-19 & 50-401/83-19 on 830511-0602k noncompliance noted Major areas inspected: fire protection. MILLER, M. M. Region 2, Office of Director. COMLON-TE. Division of Engineering & Radiological Safety Programs. 83/06/20. 5pp. 19525: 067. 24X Fiche: 50-400.83/06/22, 8307140381.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrate Surry Recirculation Spray Subsystem." Svc list encl. JORBAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:293. 24X Fiche: 50-000,83/07/11,83062754M
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers et Result of Contaminated Hydraulic Fluid." Syc list encl. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. et Nes York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,83062795X
- B307220333 Ack receipt of B30616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-16 & 50-401/83-16. LEWIS.R.C. Division of Project & Resident Programs. 83/07/12. UTLEY.E.E. Carolina Power & Light Co. 1p. 19675:339. 24X Fiche: 50-400, 83/07/12, 8307220333.

-B307220336 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-400/83-16 & 50-401/83-16 Corrective actions:cable tray & cable tray support insp programs revised. PARSONS.R.M. Carolina Power & Light Co. 83/06/16. O'REILLY, J. P. Region 2, Office of Director. 3pp. 19675:340. 24X Fiche: 50-400,83/07/12,8307220333.

#307220340 Forwards IE Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420 & notice of violation.

LEWIS.R.C. Division of Project & Resident Programs. 83/05/19.

UTLEY.E.E. Carolina Power & Light Co. 2pp. 19675:343. 24X

Fiche: 50-400,83/07/12.8307220333.

#307220344 IE Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420.
Noncompliance noted: insp status of electrical raceway supports not completed prior to installation of cable

MAXWELL, C. F., PREVATTE, R. L. Region 2, Office of Director.

BENIS, P. Division of Project & Resident Programs. 83/05/17. 5pp.
19675: 346. 24X Fiche: 50-400, 83/07/12, 8307220333.

D&270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
TAYLOR, J. M. Division of GA: Safeguards & Inspection Programs (Post #30103). B3/07/14. Consolidated Edison Co. of New York, Inc.
114pp. 19715:270. 24X Fiche: 50-000.83/07/14,8306270406.

O722013O Ack receipt of 830630 & O701 itrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-18 & 50-401/83-18.
VERRELLI.D.M. Division of Project & Resident Programs. 83/07/15.
UTLEY.E.E. Carolina Power & Light Co. 1p. 19484:035. 24X
Fiche: 50-400,83/07/15,8307220130.

#307220133 Forwards IE Insp Repts 50-400/83-18 & 50-401/83-18 on 830420-0520 & notice of violation.

VERRELLI, D.M. Division of Project & Relident Programs. 83/06/10.

UTLEY, E.E. Carolina Power & Light Co. 2pp. 17684:056, 24X

Fiche: 50-400,83/07/15,8307220130.

B307220141 IE Insp Repts 50-400/83-18 & 50-401/83-18 on 830420-0520. Noncompliance noted:failure to document compliation of training programs in electrical training & welding Arc strikes noted in heat affected zone & base metal. PREVATTE.R. MAXWELL,O. Region 2, Office of Director. BEMIS.P. Division of Project & Resident Programs. 83/06/10. App. 19684:059. 24X Fichs:50-400.83/07/15.8307220130.

Periodic operating reports & related correspondence

07260363 "Quarterly Data Rept Beismic Monitoring Program.Shearon Harris Nuclear Power Plant,Apr~June 1983." W/830721 ltr. ZIMMERMAN.S.R. Carolina Power & Light Co. 83/07/21. DENTON.H.R. □ffice of Nuclear Reactor Regulation. Director. 2pp. 19733:038. ☑4X Fiche: 90-400,83/07/21,8307260363.

Reportable occurrences. LERs & related correspondence

O7120395 Interim deficiency rept re receipt of 34 Ruskin Mfg Co backdraft dampers w/one counterbalance arm assembly, in lieu of required two. Myle Labs test results expected by 830715. Extension requested until 830808 for submittal of rept. PARSONS.R.M. Carolina Power & Light Co. 83/06/29. O'REILLY, J. P. Region 2. Office of Director. ip. 19430:197. 24X Fiche: 50-400,83/06/29,8307120395.

O711033B Final deficiency rept Item 132 re removal of expansion manchors after insp. Initially reported on 830401. Hanger base plate in fuel handling bldg reinstalled torqued & accepted by const insp. Insp Procedurs TP-39.Rev 5 revised.
PARBONS.R.M. Carolina Power & Light Co. 83/07/01. O'REILLY, J.P. Region 2, Office of Director. 4pp. 19381:301. 24X Fiche: 50-400,83/07/01,830711033B.

Of120207 Interim deficiency rept re Items 95 & 72 concerning shop welding in Bergen-Paterson seismic I pipe hangers & undersize skewed fillet welds. Initially reported on 820813 & 1 105. Final rept by 831003. Also reported per Part 21.
PARBONS.R.M. Carolina Power & Light Co. 83/07/01. 0'REILLY, J.P. Region 2. Office of Director. 5pp. 17423: 284. 24X
Fiche: 50-400.83/07/01.8307120207.

O7150380 Final deficiency rept re Item 136 on pips hanger frame base metal reduction. Initially reported on 830606. Frame C-1-195 will be refabricated w/certified math & will be welded onsite. Also reported per Part 21.

ARBONS.R. M. Carolina Power & Light Co. 83/07/05. O'REILLY, J.P. degion 2. Office of Director. 3pp. 19539: 196. 24X

Fiche: 50~400,83/07/05,8307150380.

8307220145 Interim deficiency rept Item 129 re weld deficiencies on ITE Gould Class IE 480-volt motor control ctrs. Initially reported on 830408. Extension of submittal of rept on reportability requested to 830831. Also reported per Part 21. PARSONS.R.M. Carolina Power & Light Co. 83/07/13. D'REILLY, J. P. Region 2. Office of Director. 1p. 19884: 075. 24% Fiche: 50-400. 83/07/13. 8307220145.

DOCKET 50-406 TUSKEGEE INST. RESEARCH REACTOR V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.0. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000, 83/07/11, 8307080427.

DOCKET 50-407 UNIV. OF UTAH RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8307200393 Requests assistance in review of licenses 830308 physical security plan as part of application for renewal of Licenses R-126. Encls withheld (ref 100FR2. 790).
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13.
BROWN.W.B. Fuel Facility Safeguards Licensing Branch. 1p.
19672: 264. 24X Fiche: 50-407,83/07/13,8307200393.

8307250418 Requests review of encl emergency plan submitted w/830308 application to renew License R-126. W/o encl.
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13.
PAGANO.F.C. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 19716:362. 24X Fiche:50-407.83/07/13, 8307250418.

#### I. Financial information

8307250586 Forwards univ financial info rept for 1982 re 830308 application to renew License R-126. Review should determine if applicant is financially qualified to operate reactor facility for 20-yr renewal, per 10CFR50. THOMAS.C.D. Standardization & Special Projects Branch. 83/07 NASH.D.A. Assistant Director for State & Licensee Relations. 19718:091. 24X Fiche: 50-407.83/07/13.8307250586. 83/07/13. \*!ons, 15pp.

# P. Operating license stage documents & correspondence

8307130307 Forwards notice of consideration of application for renewal of License R-124 for TRIGA reactor.
THOMAS.C.O. Standardization & Special Projects Branch. 83/07/07.
Utah. Univ. of. 2pp. 19525:346. 24x Fiche: 50-407.83/07/07.
8307130307.

--8307130310 Notice of consideration of application for renewal of License R-126 for TRIGA reactor. THOMAS.C.D. Btandardfration & Special Projects Branch. 83/07/07. 4pp. 19525:348. 24X Fiche:50-407.83/07/07.8307130307.

# V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nunpower reactor licensees re issuance of NRC Form 37B, "Personal Qualifications Statement - Licensee." Svc list encl. ETSENHUT.D.O. Division of Licensing. 83/07/1(, Michigan, Univ. of. 14pp. 19563:138. 24X Fichs:50-000,83/07/11,8307080427.

8307270173 Requests review of entl 830308 operator requalification plan for License R-126 renewal.W/o encl. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13. BOOHER.H.R. Licensee Qualifications Branch. 1p. 19811:154. 24X Fiche: 50-407.83/07/13.8307270173.

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F. Security, medical, emergency & fire protection plans

B307110559 Releases public version of revised emergency plan implementing procedure.
FELTON.J.M. Division of Rules and Records. B3/06/24. Docum Management Branch. 1p. 19390:336. 24X Fiche: 50-409, B3/06/24, B307110559.

- 8307210171 Forwards modified draft protection order & affidavit of nondisclosure & submits summary of unresolved issues discussed on 830713 Draft incorporates NRC & intervenor suggestions. Certificate of Svc encl. FLYNN.5.F. Carolina Power & Light Co. 83/07/15. KELLEY, J. L., BRIGHT, G. D., CARPENTER, J. H. Atomic Safety and Licensing Board Panel. 11pp. 19666:047. 24X Fiche: 50-400, 83/07/15, 8307210171.
- 8307210203 Confirms 830718 telcon re agreement concerning intervenor 830630 request for production & interrogatories. Applicants will respond to discovery requests on Contention 44 by 830812.

  BAXTER.T.A. Shaw, Pittman, Potts & Troubridge, BAXTER.T.A. Carolina Power & Light Co. 83/07/19, REED, D. F. Chapel Hill Anti-Nuclear Group Effort. 4pp. 17669:043. 24X Fiche: 30-400,83/07/19,8307210203.
- 8307240281 Notice of amend to W Eddleman third set of interrogatories to utils. Page 8 should not be included. Certificate of Svc encl.

  EDDLEMAN. W. Eddleman. W. 83/07/19. Carolina Power & Light Co. 2pp. 19726: 206. 24X Fiche: 50-400.83/07/19.8307260281.
- 8307250247 Forwards RH Odegaarden,P Bemis.WC Seidle.F Hawkins & T Mo signatures to complete NRC 830624 responses to interrogatories. 8ARTH.C.A. Hearing Branch 1. 83/07/20. EDDLEMAN.W. Eddleman. W. 8pp. 19705: 328. 24X Fiche: 50-400, 83/07/20. 8307250247.
- 8307250346 Response opposing admission of W Eddleman proposed Contention 15-AA re NEPA cost-benefit balance. Eddleman fails to plead litigable contention w/adequate basis & specificity.

  G'NEILL, J. H. Carolina Power & Light Co. D'NEILL, J. H. Shaw, Pittman, Potts & Troubridge. 83/07/20. Atomic Safety and Licensing Board Panel. 7pp. 19702:004. 24X Fiche: 50-400,83/07/20, 8307250346.
- --B307250350 Fifth set of interrogatories & request for production of documents re Eddleman Contentions 29/30 & 378. Certificates of Svc encl.
  BAUSER D. B. Carolina Power & Light Co. BAUSER D. B. Shaw, Pittman. Putts & Yrowbridge. B3/07/20. Eddleman, W. 30pp. 19702:011. 24x Fiche: 50-400, B3/07/20, B307250346.
- B307260341 Answer to applicant response to motion for extension of time re second round interrogatories on environ contentions. EDDLEMAN. W. Eddleman. W. B3/07/20. 2pp. 19726:332. 24X Fiche: 50-400.83/07/20.8307260341.
- 8307250285 Amend to svc list. MILLER,R.C. Atomic Safety and Licensing Board Panel. 83/07/21. ip. 19705:305. 24X Fiche:50-400,83/07/21,8307250285.
- 8307250337 Advises that during 830721 telephone conference, applicants & NRC did not modify positions taken in written response to proposed contentions. W Eddleman will reflect changes in written reply to applicant & NRC written responses.

  BAXTER.T.A. Bhaw, Pittman, Potts & Trombridge. BAXTER.T.A. Carolina Power & Light Co. 83/07/21. KELLEY. J.L., BRIGHT.G.G., CARPENTER.J.H. Atomic Safety and Licensing Board Panel. 4pp. 19703:007. 24X Fichs: 50-400, 83/07/21, 8307230337.
- B307260360 Advises that util does not accept W Eddleman 830625 reply as conforming to ASLB 830527 holdings on General Interrogatory 2 re identification of experts or witnesses. Svc list encl. Related correspondence.
  BAXTER.J.A. Shaw, Pittman, Potts & Trowbridge. BAXTER.J.A. Carolina Power & Light Co. 83/07/22. RELLEY, J.L., BRIGHT, O.D., CARPENTER.J.H. Atomic Safety and Licensing Buard Panel. 5pp. 19733: 031. 24X Fiche: 50-400, 83/07/22, 8307260360.
- 8307260483 Objections to applicant 830711 draft affidavit of nondisclosure & protective order governing access to security plan info. Proposed restricted time schedule makes proper review difficult. Certificate of Evc encl.
  RUNKLE, J. D. Joint Intervenors-Shearon Harris. 83/07/22. Atomic Safety and Licensing Board Panel. 11pp. 19731:145. 24X Fiche: 50-400.83/07/22.8307260483.
- 830726024B Fourth set of general interrogatories & interrogatories on Contentions 29 & 37B. EDDLEMAN W. Eddleman, W. B3/07/25. Carolina Power & Light Co. 31pp. 19727:007. 24X Fiche: 50-400, 83/07/25, 830726024B.
- B307280163 Requests response to B30630 interrogatories on Joint Contention II or request for extension Early response important due to B30901 deadline for motion for summary disposition Svc list encl.

  BAXTER.T.A. Bhaw, Fittman, Potts & Trowbridge. BAXTER.T.A. Carolina Power & Light Co. B3/07/25, PAYNE, M.T. Edelstein & Payne, 3pp. 19792:076. 24X Fiche: 50-400, B3/07/25, B307280163.

- 8307280185 Answer opposing W Eddleman 830711 motion to compel discovery re applicant response to W Eddleman general interrogatories & interrogatories on Contentions 29 & 378. Certificate of Svc encl. Related correspondence.

  BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Bhaw, Pittman, Potts & Trowbridge. 83/07/26. Atomic Safety and Licensing Board Panel. 21pp. 19791:268, 24X Fiche: 50-400, 83/07/26, 8307280185.
- 8307280167 Comments on util 830715 transmittal to ASLB & Runkle 830722 comments. Clearer statement re not removing safeguards papers needed in affidavit of nondisclosure. Site visit would be more meaningful at later stage of const.

  BARTH.C.A. Hearing Branch 1. 83/07/27. KELLEY, U.L., CARPENTER.J.H., BRIGHT.O.O. Atomic Safety and Licensing Board Panel. 2pp. 19791: 293. 24X Fiche: 50-400, 83/07/27, 8307280167.
- 8307290142 Advises that second round discovery requests on Contentions 29 & 37B will be treated as having been served on 830725. Original copy lost in mail. Bvc list encl. Related correspondence.

  BAXTERIT. A. Shaw, Pittman, Potts & Trowbridge. B3/07/27. EDDLEMAN M. Eddleman, W. 3pp. 19821:05B. 24X Fiche: 50~400, 83/07/27, 8307290142.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307060121 Forwards Amend 7 to F8AR. in response to draft BER Dpen Items 132.156.157.198,199,203.204 & 207.
  MCDUFFIE.H.A. Carolina Power & Light Co. 83/06/30. DENTON, H. R.
  Office of Nuclear Reactor Regulation, Director. 2pp. 19251:197.
  24X Fiche: 50-400,83/06/30,8307060121.
- --8307060127 Amend 7 to FSAR.

  \* Caroling Power & Light Co. 83/06/30, 56pp. 19251:199. 24X
  Fichs:50-400,83/06/30,8307060121.
- B307140267 Advises that Amend 7 to FBAR distributed to encl list of individuals.
  ZIMMERMAN, S.R. Carolina Power & Light Co. B3/07/07. EIBENHUT, D. G. Division of Licensing. 4pp. 19522:335. 24X Fiche: 50~400, B3/07/07, B307140267.
- 8307270057 Forwards Amend 8 to FSAR, in response to draft SER Open Items 58,61,65,113 & 202.

  MCDUFFIE, M.A. Carolina Power & Light Co. B3/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19765:001. 24X Fiche: 50-400, 83/07/22, 8307270057.
- ---8307270060 Amend 8 to FBAR.

  \* Carolina Power & Light Co. 83/07/22. 79pp. 19765:003, 24X Fiche: 50-400, 83/07/22, 8307270057.
- B307280355 Forwards Affidavit of Syc & revised distribution list for Amend 8 to FSAR.
  ZIMMERMAN, S.R. Carolina Power & Light Co. B3/07/25. EISENHUT, D. O. Division of Licensing. App. 19789:001. 24X Fiche: 50-400, 83/07/25, 8307280355.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140381 Forwards IE Insp Repts 50-400/83-19 & 50-401/83-19 on 830331-0602 No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. 83/06/22. UTLEV.E.E. Carolina Power & Light Co. 2pp. 19325:065. 24X Fiche: 50-400, 83/06/22, 8307140381.
- --B307140385 IE Insp Repts 50-400/83-19 & 50-401/83-19 on 830531-0602. No noncompliance noted Major areas inspected fire protection. MILLER, M.H. Region 2. Office of Director. CONLON, T.E. Division of Engineering & Radiological Safety Programs. 83/06/20. 5pp. 19525:067. 24X Fiche: 50-400,83/06/22,8307140381.
- B304270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:273. 24X Fiche:50-000,83/07/11,8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103), B3/07/12, Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 50-000, B3/07/12, B306270404,
- B307220333 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-400/83-16 & 50-401/83-16.

  LEWIS,R.C. Division of Project & Resident Programs. 83/07/12.

  UTLEY,E.E. Carolina Power & Light Co. 1p. 19675:339. 24X

  Fiche: 30-400, 83/07/12, 8307220333.

- --6307220336 Responds to NRC 830519 ltr re violations noted in IE Insp. Repts 30-400/83-16 & 50-401/83-16. Corrective actions: cable tray & cable tray support insp. programs revised. PARSONS:R.M. Carolina Power & Light Co. 83/06/16. O'REILLY, J. P. Region 2: Office of Director. 3pp. 19675: 340. 24X Fiche: 50-400, 83/07/12, 8307220333.
- ---8307220340 Forwards IE Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420 & notice of violation. LEWIS, R.C. Division of Project & Resident Programs. 83/05/19. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19675: 343. 24X Fiche: 50-400, 83/07/12, 8307220333.
- --8307220344 IE Insp Repts 50-400/83-16 & 50-401/83-16 on 830320-0420. Noncompilance noted: insp status of electrical raceway supports not completed prior to installation of cable trays.

  MAXWELL, G. F., PREVATTE, R. L. Region 2, Office of Director. BEMIS.P. Division of Project & Resident Programs. B3/05/17. Spp. 19675:346. 24X Fiche:50-400,83/07/12,8307220333.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, B3/07/14, B306270406.
- B307220130 Ack receipt of B30630 & 0701 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/B3-18 & 50-401/B3-18. VERRELLI,D.M. Division of Project & Resident Programs. B3/07/15. UTLEY,E.E. Carolina Power & Light Co. ip. 19684:055. 24X Fiche: 50-400, 83/07/15, 8307220130.
- --B307220133 Forwards IE Insp Repts 50-400/B3-18 & 50-401/B3-18 on B30420-0520 & notice of violation. VERRELLI.D.M. Division of Project & Rekident Programs. B3/06/10. UTLEY.E.E. Carolina Power & Light Co. 2pp. 19684:056. 24X Fiche: 50-400, 83/07/15, 8307220130.
- --8307220141 IE Inap Repts 50-400/83-18 & 50-401/83-18 on 830420-0520. Noncompliance noted: failure to document completion of training programs in electrical training & welding. Arc strikes noted in heat affected zone & base metal. PREVATTE, R., MAXHELL, Q. Region 2, Office of Director. BEMIS. P. Division of Project & Resident Programs. 83/06/10. App. 19684: 059. 24X Fiche: 50-400, 83/07/15, 8307220130.
- R. Periodic operating reports & related correspondence
- 8307260363 "Quarterly Data Rept Seismic Monitoring Program, Shearon Harrts Nuclear Power Plant, Apr-June 1983." W/830721 ltr.
  ZIMMERMAN, S.R. Carolina Power & Light Co. 83/07/21. DENTON, H.R.
  Office of Nuclear Reactor Regulation, Director. 2pp. 19733:038.
  24X Fichs: 50-400, 83/07/21, 8307260363.
- 9. Reportable occurrences, LERs & related correspondence
- 8307120395 Interim deficiency rept re receipt of 34 Ruskin Mfg Cobackdraft dampers w/one counterbalance arm assembly, in lieu of required two. Wyle Labs test results expected by 830715. Extension requested until 830808 for submittal of rept. PARSONS.R.M. Carolina Power & Light Co. 83/06/29. 0'REILLY, J. P. Region 2, Office of Director. ip. 19430:197. 24X Fiche: 50-400, 83/06/29, 8307120375.
- B307110338 Final deficiency rept Item 132 re removal of expansion anchors after insp. Initially reported on 830601. Hanger base plate in fuel handling bldg reinstalled torqued & accepted by const insp. Insp Procedure TP-37. Rev 5 revised. PARBUNS R. M. Carolina Power & Light Co. B3/07/01. O'REILLY, J. P. Ragion 2. Dffice of Director. 4pp. 19381:301. 24X Fiche: 50-400, B3/07/01, B307110338.
- 3307120207 Interim deficiency rept re Items 95 & 72 concerning shop welding in Bergen-Paterson seismic I pipe hangers & undersize skewed fillet welds. Initially reported on 820813 & 1105. Final rept by 831003. Also reported per Part 21. PARSUNG.R.M. Carolina Power & Light Co. 83/07/01. O'REILLY, J. P. Region 2, Office of Director. Spp. 19423:284, 24X Fiche: 50-400.83/07/01, 8307120207.
- 3307150380 Final deficiency rept re Item 136 on pipe hanger frame base metal raduction. Initially reported on 830606.Frame C-1-195 will be repabricated w/certified matl & will be walded onsite. Also reported per Part 21.
  PAREGNS, R. M. Carolina Power & Light Co. 83/07/05. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19539: 156. 24X Fiche: 50-400,83/07/05,8307150380.

8307220145 Interim deficiency rept Item 129 re weld deficiencies on ITE Gould Class IE 480-volt motor control ctrs. Initially reported on 830408 Extension of submittal of rept on reportability requested to 830831. Also reported per Part 21. PARSIONS.R.M. Carolina Power & Light Co. 83/07/13. D'REILLY, J. P. Region 2. Office of Director. 1p. 19684:075. 24X Fiche: 50-400.83/07/13.8307220145.

DOCKET 50-404 TUSKEGEE INST. RESEARCH REACTOR
V. Operator Examinations

8307080427 Generic Ltr 83-12A to all nonpower reactor licensess re issuance of NRC Form 39B, "Personal Qualifications Statement - Licensee." Svc list enci. EISENMUT, D. G. Division of Licenseing. 83/07/11. Michigan, Univ. of. 14pp. 19563:13B. 24X Fiche:50-000,83/07/11,8307080427.

DOCKET 50-407 UNIV. OF UTAH RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

- B307200393 Requests assistance in review of licensee B30308 physical security plan as part of application for renewal of License R-126. Encis withheld (ref 10CFR2.790).

  HD0MAS.C.O. Standardization & Special Projects Branch.

  BROWN, W. B. Fuel Facility Safeguards Licensing Branch. 1p.

  19672: 264. 24X Fiche: 30-407, 83/07/13, 8307200393.
- 8307290618 Requests review of encl emergency plan submitted w/830308 application to renew License R-126.W/m encl.
  THOMAS.C.D. Standardization & Special Projects Branch. 83/07/13.
  PAGAND.F.G. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 19716:362. 24X Fiche: 50-407.83/07/13.8307250618.
- 1. Financial information
- B307250586 Forwards univ financial info rept for 1982 re 830308 application to renew License R-126 Review should determine if applicant is financially qualified to operate reactor facility for 20-yr renewal.per IOCFR30. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13. NASH.D.A. Assistant Director for State & Licensee Relations. 15pp 19718: 091. 24X Fiche: 50-407.83/07/13,8307250586.
- P. Operating license stage documents & correspondence
- B307130307 Forwards notice of consideration of application for renewal of License R-126 for TRIGA reactor.
  THOMAS,C.O. Standardization & Special Projects Branch. 83/07/07.
  Utah. Univ. of. 2pp. 19525:346. 24X Fiche: 50-407, 83/07/07, 8307130307.
- --B307130310 Notice of consideration of application for rengwal of License R-126 for TRIGA reactor. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/07. 4pp. 19525:348. 24X Fiche:50-407,83/07/07,8307130307.
- V. Operator Examinations
- B307080427 Generic Ltr 83-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Btatement - Licensee." Svc list encl. EISENHUT.D.G. Division of Licensing. B3/07/il. Michigan, Univ. of. 14pp. 19543:138. 24X Fiche:50-000.83/07/il.8307080427.
- 8307270173 Requests review of encl 830308 operator requalification plan for License R-126 renewal. W/o encl. THOMAS.C.O. Standardization & Special Projects Branch. 83/07/13. 800HER.H.R. Licensee Qualifications Branch. 1p. 19811:154. 24X Fiche: 50~407, 83/07/13, 8307270173.

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F. Security, medical, emergency & fire protection plans

B307110559 Releases public version of revised emergency plan implementing procedure. FELTON.J.M. Division of Rules and Records. B3/06/24. Document Management Branch. 1p. 19390:336. 24X Fiche:50-409.83/06/24. 8307110559.

- --8307110563 Public version of Issue 6 to Emergency Plan Implementing Procedure EPP-1, "Emergency Conditions & Response." W/B30506 1tr % receipt form.
  SHAFER, P. M., LINDER, F. Dairyland Power Cooperative. 83/04/13.
  CRUTCHFIELD, D. Operating Reactors Branch 5. 34pp. 19390:337.
  24X Fiche: 50-409, 83/06/24, 8307110559.
- 8307120612 Releases public version of revised emergency plan. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. ip. 19438:038. 24% Fiche:50-409.83/06/24. 8307120612.
- --8307120624 Public version of Rev 4 to emergency plan. H/830601 ltrs. LINDER, F. Dairyland Power Cooperative. B3/05/31. CRUTCHFIELD, D Operating Reactors Branch 5. HIND, J. A. Region 3. Office of Director. 191pp. 19438:040. 24X Fiche: 50-409, 83/06/24, 8307120612.
- 8307140296 Forwards request for add1 info re 830408 response to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re emergency response capability requirements. Response requested within 30 days. CRUICHFIELD, D. Operating Reactors Branch 5. B3/07/12. LINDER, F. Dairyland Power Cooperative. 4pp. 19523: 311. 24X Fiche: 30-409, 83/07/12, 9307140296.
- B307140419 Forwards FR notice of exemption from IOCFR50.App R. Sections III.A & III.9 requirements for fire protection in diesel fire water gump crib house & fire protection SER. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/07/12. LINDER.F. Dairyland Power Cooperative. 3pp. 19520:230. 24X Fiche: 50-409.83/07/12.8307140419.
- ~~8307140429 Exemption from 10CFR50. App R. Section III. A & III. O requirements for fire protection in diesel fire water pump crib house. Alternate fire protection configuration acceptable.

  PURPLE.R. A. Division of Licensing. 83/07/12. Dairyland Power Cooperative. Bpp. 19320:233. 24X Fiche: 50-409,83/07/12.
- --B307140432 Safety evaluation of fire protection SER Open Itams 3.1.5.3.1.22(2) & 3.1.29 re heat detector circuit supervision.protection for electrical equipment room & signaling sys. tems acceptable.

   Office of Nuclear Reactor Regulation, Director. B3/07/12. 4pp. 19520:261. 24% Fiche: 50-409. B3/07/12, B307140419.
- 8307270455 Informs that evaluation of design plan for emergency response facilities using NUREC-0814-per NRC 811120 ltr.nut applicable to facility in view of issuance of Suppl 1 to NUREC-0737-per 821217 submittal. CHUTCHFIELD, D. Operating Reactors Branch 5. 83/07/26. LINDER.F. Dairyland Power Cooperative. 2pp. 19767:178. 24X Fichs: 50-409,83/07/26,8307270455.

# Q. Adjudicatory correspondence

- 8307140438 Decision ALAB-733.affirming LBP-82-58.LBP-81-7 & LBP-83-23. Sua sponte review disclosed no error warranting review. SHOEMAKER.C.J. Atomic Safety and Licensing Appeal Panel. 83/07/13.2pp. 19321:252. 24X Fiche:30-409.83/07/13.830714043B.
- P. Operating license stage documents & correspondence
- 8307220564 Submits evaluation of SPING-4 as iodine sampler per NUREG-0737. Item II. F. 1. 2. B. 2. Methodology & details of determination re use of SPING-4 found in Technical Rept LAC-TR-116.
  SHAFER. P. H. Dairyland Power Cooperative. 83/06/30. PAUL. R. Region 3, Office of Director. 2pp. 19685:360. 24X Fiche: 50-409, 83/06/30, 8307220564.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENNUT.D. Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: \$0-000.83/07/05.8306270397.
- 830704032? Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENHUT.D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000.83/07/06/8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS ovents. Svc list enc.] EISEMHUT. D. 9. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X
  Fiche: SO-000, 83/07/08, 8307080169.

# G. [nspection reports, IE Bulletins & correspondence

- B30705002B Advises of actions taken re-potential matl-false statement documented in IE Insp Rept 50-409/83-05. Discrepancy involving response to SEP Topic III-4.C occurred due to lack of understanding by employee.

  JACKIM, I. N. Region 3, Office of Director. 83/06/29. NGRELIUS, C. E. Division of Project & Resident Programs. Ip. 19220: 284. 24X Fiche: 50-409.83/06/29.8307050028.
- 8307080518 Updates status of in-vivo analyses program per 830314 ltr & IE Insp Rept 50-409/82-08 outlining time table milestones. Whole body counter expected to be modified & operational by 830715. 830715. SHAFER,P.H. Dairyland Power Cooperative. 83/06/30. GREOER,L.R. Region 3, Office of Director. ≥pp. 19345:356. 24X Fiche:50-409,83/06/30,8307080518.
- ### 8307080015 Forwards addendum to IE Insp Rept 50-409/82-17.closing Open Items 409/81-17-03.409/82-17-02 & 409/82-17-03 re Cs-137 disagreements.

  #### APPENIELLO,C. J. Region 3. Office of Director. ### 83/07/05.

  LINDER,F. W. Dairyland Power Cooperative. 2pp. 19351:217. 24X Fiche: 50-409, 83/07/05, 8307080015.
- --8307080019 Addendum to IE Insp Rept 50-409/82-17 re confirmatory measurements program. Tables II & III.

  \* Region 3. Office of Director. 83/07/05. 2pp. 19351:219. 24X Fiche: 50-409,83/07/05.8307080015.
- 8306270401 IE Info Notice 83-46. "Common Hode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDANIE. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293, 24X Fiche: 50-000, 83/07/11, 8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Bvc list encl. JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 50-000, B3/07/12, B306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits," Svc list encl.
  TAYLOR. J. M. Division of QA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York. Inc. 114pp. 19715: 270. 24% Fiche: 50-000: 83/07/14. 8306270406.
- 8307210249 Ack receipt of 830708 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-05.
  SHAFER, W. D. Region 3, Office of Director. 83/07/15, LINDER, F. W. Dairyland Power Cooperative. 1p. 19664:160. 24X
  Fiche: 50-409, 83/07/15, 8307210249.
- -8307210253 Responds to NRC 830617 ltr re violations noted in IE Insp. Rept 50-409/83-05. Corrective actions: IE Procedure 74-06 remaint insp. of 480-volt breakers, revised to include check of transformer polarity before installing breaker.

  LINDER, F. Dairyland Power Cooperative. 83/07/08. KEPPLER, J. G. Region 3. Office of Director. Jpp. 19664: 161. 24x

  Ficha: 50-409, 83/07/15, 8307210249.
- R. Periodic operating reports & related correspondence
- 8307220222 "LACBUR Annual Rept 1982 " W/830217 ltr. LINDER,F. Dairyland Power Cooperative. 83/02/17. N Region 3. Office of Director. Tipp. 19674:005. 24X Fiche: 50-409, 83/02/17, 8307220222. KEPPLER, J. G.
- 8307220225 Monthly operating rept for May 1983 W/830608 ltr. GDODMAN. L. S., LINDER, F. Dairyland Power Cooperative. 83/06/07. Office of Resource Management, Director. 12pp. 19674:016. 24) Fiche: 50-409.83/06/07.8307220225.
- S. Reportable occurrences, LERs & related correspondence
- 8307110127 LER 83-004/03L-0:on 830531.during power escalation following shutdown water level safety Channel 3 indicated approx 5 inches high. Caused by physical differences in sensing lines. Channel 3 adjusted W/83D829 ltr. 600DMAN, L.S., LINDER, F. Dairyland Power Cooperative, 83/06/29, KEPPLER, J. 0. Region 3. Office of Director. 4pp. 19375:014. 24X Fiche: 50-409,83/06/29,8307110127.

- B307200264 LER B3-005/01T-0: on B30708, personnel airlock failed Type B leak test due to out of adjustment of outer door sealing mechanisms. During retest, inner door gasket came out of seat & airlock leakage exceeded acceptance criteria. W/B30711 ltr. Q00DMAN.L.S., LINDER.F. Dairyland Power Cooperative. 83/07/11. KEPPLER.J.G. Region 3. Office of Director. 3pp. 19651:241. 24X Fiche: 50-409, 83/07/11, 8307200264.
- B307220401 PNO-III-B3-062: on B3071B. reactor tripped from 93% power due to loss of forced circulating water pumps. Pumps tripped due to leak in seal injection sys. Caused by failed gasket on flow indicator. Reactor in cold shutdown.

  JACKIW, I. SHAFER. W. Region 3. Office of Director. 83/07/18. ip. 19685:001. 24% Fiche: 50-409. 83/07/18. 8307220401.
- 8307240574 PNO-III-83-062A: on 830716, 15, 000 gallons radioactively contaminated water leaked from sual injection sys into reactor containment subbasement. Caused by gasket failure, due to overpressurization. Water pumped out.

  JACKIW, I., SHAFER, M. Region 3, Office of Director. 83/07/20. 1p. 19732:090. 24X Fichs: 50-409, 83/07/20, 8307260574.
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8307060425 Summary of Caseload Forecast Panel 830222-24 site meetings w/util re resource needs for licensing activities, design review & const progress.

  HAUGHEY, M. Licensing Branch 2. B3/06/24, Licensing Branch 2. 14pp. 17279: 335. 24X Fiche: 50-410,83/06/24,8307060425.
- 8306270395 Generic Ltr 83-24 to all BMR applicants for OL & holders of OLs for Orand Guif, LaBalle & Susquehanna re TMI Task Action Plan Item I. G. 1, "Special Low Power Testing & Training & Recommendations for BMRs." Svc list encl. EIGENHUT. D. G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000,83/06/29, 8306270395.
- 8304270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. 0. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in ST8.8vc list encl. EISENHUT, D. O. Division of Licensing, 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/08, Consolidated Edison Co. of New York, Inc. 3Bpp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307200374 Assures that reviews of Tech Spucs & security plan proceeding on schedules compatible w/approved review schedule, in response to 830707 memo.

  THOMAS.C.O. Standardization & Special Projects Branch. 83/07/08. BCHWENCER, A. W. Licensing Branch I. ip. 19656: 362. 24X Fiche: 50-410, 83/07/08. 8307200374.
- B307220407 Submits clarification of weld design for pipe supports. Clarification will be reflected in amend to FSAR scheduled for submittal during Third Guarter 1983.
  RHODE, G. K. Niegara Mohawk Power Corp. B3/07/18. BCHWENGER, A. Licensing Branch 2. ip. 19687:361. 24X Fiche: 50-410, 83/07/18.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8307200538 Forwards notification & agenda for 830802-03 environ site visit & 830802 public meeting in Oswego, NY to review issues for preparation of EIS OL stage.

  SCHWENCER, A. Licensing Branch 2. 83/07/13. RHODE, G.K. Niagara Mohawk Power Corp. 2pp. 19672: 291. 24X Fiche: 50~410, 83/07/13, 8307200538,
- --8307200543 Notification of 830802-03 environ site visit & 830802 public meeting in Oswego, NY to review issues for preparation of EIS OL stage. HAVOHEY, M. Licensing Branch 2. 83/07/13. 8CHWENCER.A. Licensing Branch 2. 5pp. 19826;276. 24X Fiche: 50-410, 83/07/13. 8307200938.

- 6307280187 Forwards newspaper notice of 630802 public meeting in Oswego,NY to discuss environ concerns for EIS. SCHMENCER.A. Licensing Branch 2. 83/07/20. RHODE.G.K. Niagara Mohawk Power Corp. 3pp. 19826:265. 24X Fiche:50-410,83/07/20, 8307280187.
- F. Security, medical, emergency & fire protection plans
- 8307200374 Assures that reviews of Tech Specs & security plan proceeding on schedules compatible w/approved review schedule: in response to 830707 memo.

  THOMAS. C.O. Standardization & Special Projects Branch. 83/07/08. SCHNENCER.A.W. Licensing Branch 1. ip. 19696:362. 24X Fiche: 50-410.83/07/08.8307200374.
- Q. Adjudicatory correspondence
- 8307140461 Advises that if Multiple Intervenors expect to withdraw 830614 patition to intervene, notice of withdrawal should be filed within 2 wks.

  MARQULIES.M.B. Atomic Safety and Licensing Board Panel. 83/07/12.

  WHITE.A.F. DeGraff, Foy, Conway & Holt-Harris. 1p. 17521:241. 24X Fiche: 50-410, 83/07/12, 8307140461.
- B307190191 Requests filing of Multiple Intervenor withdrawal of petition; per 830623 ltr.

  CONNER, T. B. Niagara Mohawk Power Corp. CONNER, T. B. Conner & Metterhahn.

  B3707714. WHITE, A.F. DeGraff, Foy. Conway & Holt-Harris.

  1p. 19630:141. 24X Fiche: 50-410.83/07/14.8307190191.
- Q. Inspection reports, IE Bulletins & correspondence
- B307010002 Forwards IE Mgt Meeting Rept 50-410/83-09 on B30523, BTARDSTECKI,R. Division of Project & Resident Programs. B3/06/14, RHODE,O.K. Niagara Mohawk Power Corp. 2pp. 19169.081, 24X Fiche: 50-410, B3/06/14, B307010002.
- --8307010005 IE Mgt Meeting Rept 50-410/83-09 on 830523. Major areas discussed: util overview of contractor performance at const site.

  KISTER, H. B., KEIMIG, R. R. Region I. Office of Director. 83/06/13. 2pp. 19169: 083. 24X Fiche: 50-410.83/06/14.8307010002.
- 8307010029 Forwards IE Insp Rept 50-410/83-05 on 830425-0527 & notice of violation.
  STARGSTECKI/R. Division of Project & Resident Programs. 83/06/15. RHODE. Q. K. Niagara Mohawk Power Corp. 2pp. 17169:177. 24x Fiche: 50-410.83/06/15.8307010029.
- --8307010032 Natice of violation from insp on 830425-0527.
  \* Region 1, Office of Director. 83/06/15. 2pp. 19169:179. 24X Fiche: 50-410, 83/06/15, 8307010029.
- --8307010036 IE Insp Rept 50-410/83-05 on B30425-0527. Noncompliance noted: failure to identify nonconforming trends for casual indications & take subsequent corrective action. SCRULZ.R.D., GRAMM.R.A., KISTER.H.B. Region I. Office of Director. 83/06/10. 11pp. 19169: 181. 24X Fiche: 50-410, 83/06/13, 8307010029.
- B3070700A2 Responds to NRC B3042A ltr re notice of violation & proposed imposition of civil penalty. Corrective actions: all trainees required to meet educ & esperience requirements of GAD 2.5, as well as demonstrate proficiency, prior to certification. RHODE, G. K. Niagara Mohawk Power Corp. B3/06/30. Director's Office, Office of Inspection and Enforcement. App. 19293: 203. 24X Fiche: 50-410, 83/06/30, 8307070062.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid, " Svc list encl. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000,83/07/12,8306270404.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of QA, Bafeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: S0-000. B3/07/14. B306270406.

- S. Reportable occurrences, LERs & related correspondence
- 8307190151 Interim deficiency rept re discrepancies in WJ Woolley Co GA documentation. Initially reported on 830504. Records reviewed for compliance w/Irwin Steel Co GA manual. Final rept expected by 830915.

  MANNO, S. F. Niagara Mohawk Power Corp. 83/04/03. STARDSTECKI. rept expected by 0:30713.
  MANNO,S.F. Niagara Mohawk Power Corp. 83/06/03. STARDS1
  Division of Project & Resident Programs. 2pp. 19636:206.
  Fiche: 50-410.83/06/03.8307190151. STAROSTECKI, R.
- 8307210059 Interim deficiency rept re environ & seismic qualification documentation of certain control room aquipment. Initially reported on 820921. Itams 1-13 qualified. Itams 14 & 15 placed in qualification program & Itams 16 & 17 will be qualified. DISE.D.P. Niagara Mohauk Power Corp. 83/07/11. STARDSTECKI.R. Division of Prograt & Resident Programs. 2pp. 19668:267. 24X Fiche:50-410.83/07/11.8307210059.
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2 A. Application/construction stage documents & correspondence
- 830606070 Generic Ltr 83-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT, D. O. Division of Licensing. 83/06/03, Yankee Atomic Electric Co. 10pp. 17563:116. 24X Fiche: 50-000,83/06/03, 23006070 Electric Co. 8304060070.
- 8307070036 Responds to 830615 request for info re presence of federally listed or proposed endangered & threatened species within plant impact area. Compilation of federally listed endangered & threatened species in State of PA encl.

  KULP.C. J. Interior, Dept. of, Fish & Wildlife Bervice. 83/06/30.

  KNIOHTOM.G. Licensing Branch 3. 5pp. 19293:242. 24X

  Fiche: 50-412.83/06/30.8307070036.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity. Svc list enci. EISENHUT.D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24x Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT.O.O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 17669:254. 24X Fiche:50-000.83/07/06.8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATW8 events. Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24x Fiche: 50-000, 83/07/08, 8307080169.
- 8307220043 Requests priority review of SRP differences to evaluate util justification for deviation. Review results requested by 830729.

  LAZO, L. Licensing Branch 3. 83/07/08. TERAO, D., LEU, K. C., PICHUMANI, R. NRC No Detailed Affiliation Given. 2pp. 19491: 358. 24X Fiche: 50-412, 83/07/08. B307220043.
- 8307220046 Summary of 830607 meeting w/util in Bethesda.MD re OL application.List of attendees encl.
  LAZO.L. Licensing Branch 3. 83/07/11. Licensing Branch 3. 40pp. 19692:082. 24X Fiche:50-412.83/07/11.8307220046.
- 8307280367 Forwards responses to 830304 acceptance review questions re safety-related structures, sys & components, GA program, fracture prevention of containment pressure boundary & inadequate core cooling.

  HODLEVER.E.J. Duquesne Light Co. 83/07/14. DENTON, H. R. Office Nuclear Reactor Regulation, Director. 11pp. 19796: 107. 24X Fiche: 30-412, 83/07/14, 8307280367. Office of
- C. Utility Environmental Report (ER), amends & correspondence
- 8307180201 Forwards Amend 1 to environ rept QL stage consisting of responses to NRC acceptance questions contained in Encl 3 to DO Eisenhut 830504 1tr.8&W request for ack of amend receipt
  - MIGULEVER, E. J. Duquesne Light Co. 83/07/14. DENTON, H. R. Di Nuclear Reactor Regulation, Director. 4pp. 19561; 120. 24X Fiche: 50-412, 83/07/14, 8307180201.

- --8307i80206 Amend i to environ rept OL stage.

  \* Duquesne Light Co. 83/07/31. 237pp. 19561:125. 24X
  Fiche: 50-412,83/07/14,8307i80201.
- 8307290100 Forwards Certificate of Svc re distribution of Amend 1 to environ rept. WOOLEVER.E.J. Duquesne Light Co. 83/07/22, DENTON.H.R. C Nuclear Reactor Regulation, Director. App. 17822:210. 24X Fiche: 50-412,83/07/22,8307290100. Office of
- 8307280360 Submits listing of refs.permits & maps per 830504 request concerning environ rept acceptance review of OL application. MODLEVER,E. J. Duquesne Light Co. 83077/25. DENTON.H.R., KNIOHTON.G. Office of Nuclear Reactor Regulation, Director. 3pp. 19796:283. 24X Fiche: 50-412,83/07/25,8307280340.
- Q. Adjudicatory correspondence
- 8307050057 Forwards OB White petition to intervene in OL hearings. WHITE.G. S. Affiliation Unknown. B3/06/27. Office of the Bacretary of the Commission. 1p. 19172:140. 24X Fiche: 50-412.83/06/27.8307050057.
- --8307030063 Petition of GB White for laws to intervene in OL hearings. WHITE, G. S. Affiliation Unknown, 83/06/27. Commissioners. 6pp. 19192:141. 24X Fiche: 50-412.83/06/27.8307050057.
- 8307050099 Petition of Environ Coalition on Nuclear Power for leave to intervene & request for hearing. Certificate of Svc encl.
  JOHNSRUD, J. H. Environmental Coalition on Nuclear Power. 83/06/30.
  Commissioners, 2pp. 19193:336. 24X Fiche: 50-412,83/06/30,
- 8307070205 Patition of RF Halker for leave to intervene.
  WALKER, R.F. Affilation Unknown. 83/06/30. Commissioners. 5pp.
  19269:322. 24X Fiche: 50-412, 83/06/30, 8307070205.
- B307060395 Petition for leave to participate as interested state. Notices of appearance & Certificate of Bvc encl. THORMBURGH. D. Pennsylvania, Commonwealth of. . 83/07/01. Commissioners. 6pp. 19236:083. 24X Ficha: 50-412, 83/07/01, 8307060375.
- 8307070202 Petition of Ohio Citizens for Responsible Energy for leave to intervene & request for hearing Certificate of Svc encl. HIATT.S.C. Ohio Citizens for Responsible Energy. 83/07/01. Atomic Safety and Licensing Board Panel, 3pp. 19269:327. 24X Fiche:50-412.83/07/01.8307070202.
- B307070204 Putition for leave to participate as interested state. Notices of appearance & Certificate of Byc encl. THORNBURGH.D. Pennsylvania, Commonwealth of. 83/07/01. Commissioners. 6pp. 19293:349. 24X Fiche: 50-412,83/07/01,8307070204.
- 8307130287 Responds to Commonwealth of PA 830701 petition for leave to participate as interested state. Util does not object to Commonwealth participation if hearing held. Certificate of Svc encl.

  BILBERG, J. E. Duquesne Light Co. BILBERG, J. E. Shaw, Pittman, Potts & Troubridge. B3/07/03. Atomic Safety and Licensing Board Panel.

  4pp. 19532:172. 24X Fiche: 50-412,83/07/03,8307150287.
- 8307110043 Notice of ABLB constitution, MB Margulies, chairman & EE Hill & PM Purdom, members.
  COTTER, B. P. Atomic Bafety and Licensing Board Panel. 83/07/07, 2pp. 19375:253. 24X Fiche: 50-412, 83/07/07, 8307110043.
- 8307150343 Response opposing RF Walker 830630 request to intervene. Granting of intervenor status unmerited. Certificate of 8vc encl. SILBERG, J. E. Duquesne Light Co. BILBERG, J. E. Shaw, Pittman, Potts & Trowbridge. 83/07/13. Atomic Safety and Licensing Board Panel. 5pp. 19538: 328. 24X Fiche: 50-412,83/07/13,8307150343.
- 8307150350 Answer apposing Ohio Citizens for Responsible Energy 830701 petition to intervene & request for hearing Petition fails to meet requirements since no individual w/requisite standing identified. Certificate of Svc encl.

  81.BERG. J. E. Duquesne Light Co. SILBERG. J. E. Shaw, Pittman, Potts & Troubridge. 83/07/13. Atomic Bafety and Licensing Spard Panel. 4pp. 17938: 280. 24X Fiche: 50-412, 83/07/13, 8307150350.
- 8307180225 Answer opposing Environ Coalition on Nuclear Power 830630 request for hearing & petition to intervene. Requisite showing of interest not met. Petitioner fails to identify nature of member interests. Certificate of Svc encl.
  SILBERO.J.E. Duquesne Light Co. SILBERO.J.E. Shaw, Pittman, Potts & Troubridge. 83/07/14. Atomic Safety and Licensing Board Panel.
  Spp. 19555:096. 24X Fiche: 50-412, 83/07/14, 8307180225.

- 8307190284 Answer to GS White 830627 petition to intervene. White set forth adequate interest. Judgment reserved on whether intervention should be granted pending filing of petition suppl. Certificate of SVc encl.
  8LLBERG.J.E. Duquesne Light Co. BILBERG.J.E. Shaw, Pittman, Potts & Trowbridge. 83/07/15. Atomic Safety and Licensing Board Panel. 4pp. 19632:100. 24X Fiche: 50-412,83/07/15,8307190284.
- B307220414 Response to petitions to intervene & requests for hearing. Environ Coalition on Nuclear Power Ohio Citizens for Responsible Energy & RF Walker petitions should be denied & GS White petition granted Certificate of Svc encl. PERLIS.R. G. Hearing Branch 3. 83/07/20. Atomic Safety and Licensing Board Panel. i3pp. 19687:215. 24X Fiche: 50-412,83/07/20,8307220414.
- 8307270298 Discusses petition to intervene & forwards newspaper articles. Individuals living inside nuclear complex should be allowed to speak.

  WHITE.G. S. Affiliation Unknown. 83/07/20. Docketing & Services Branch. 8pp. 19769:01B. 24X Fiche: 50-412, 83/07/20, 8307270298.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- B307290103 Forwards Certificate of Svc re distribution of Amend 2 to FBAR. MODLEVER, E. J. Duquesne Light Co. B3/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19820:333. 24X Fiche: 50-412,83/07/22,8307290103.
- 8307180279 Amend 2 to FBAR W/830714 ltr. WOOLEVER Duquesne Light Co. 83/07/31. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 828pp. 19546:001. 24x Fiche: 50-412,83/07/31.8307180279.
- Q. Inspection reports, IE Bulletins & correspondence
- B307110285 Ack receipt of B30620 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-04. Confirms use of temporary supports to prevent overstressing from dead weight to be applied to installed piping.

  BTAROBTECKI.R. Division of Project & Resident Programs. 83/07/01. MODLEVER.E.J. Doquesne Light Co. 2pp. 19379:175. 24X Fiche: 50-412.83/07/01.8307110285.
- --8307110272 Responds to NRC 830408 ltr re violations noted in IE Insp Rept 50-412/83-04. Corrective actions: procedures issued to provide temporary piping supports during const. MODLEVER, E. J. Duquesne Light Co. 83/06/20. STAROSTECKI, R. Division of Project & Resident-Programs. 3pp. 19379: 177. 24X Fiche: 50-412, 83/07/01, 8307110285.
- 8307210213 Forwards IE Insp Rept 50-412/83-05 on 830411-29 & notices of violation & deviation.

  MARTIN.T. T. Division of Engineering & Technical Programs. 83/07/06.

  WOOLEVER.E. J. Duqueene Light Co. 2pp. 19666:302. 24X

  Fiche: 50-412,83/07/06,8307210213.
- --B307210215 Notice of violation from insp on B30411-29. \* Ragion 1, Office of Director. B3/07/06. ip. 19666:304. 24X Fiche: 50-412,83/07/06,8307210213.
- --8307210217 Notice of deviation from insp on 830411-27. \* Region 1, Office of Director, 83/07/06. 3pp. 19666:305. 24X Fiche: 50-412,83/07/06,8307210213.
- --8307210226 IE Insp Rept 50-412/83-05 on 830411-29 Noncompliance noted: violation involving failure to calibr torque whench within required date & deviation involving failure to comply w/ANBI-N45.2.11 for design control.

  BLUMBERG.N., FINKEL.A., GRANT.J. Region 1, Office of Director. 83/06/30. 37pp. 19466:308. 24X Fiche: 50-412,83/07/06.8307210213.
- 8306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Syc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Cansolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, B3/07/11, B306270401.
- B306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Conteminated Hydraulic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparadness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19569:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA. Bafeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.

- S. Reportable occurrences, LERs & related correspondence
- B307150275 Interim Significant Deficiency Rept 83-04 re unacceptable Bergen Paterson welded clevises on pipe rupture restraints. Initially reported on 830531 Program for remig of clevises implemented. Next rept will be submitted by B30720. MODLEVER.E. J. Duquesne Light Co. 83/06/29, MURLEY.T.E. Region 1, Office of Director. 4pp. 19538:109. 24X Fiche: 50-412,83/06/29, B307150275.
- 8307220287 Interim Deficiency Rept 83-02 re significant breakdown in QA program. Initially reported on 830318. Unsatisfactory items found during reinsp program will become new reportable significant deficiencies.
  WOOLEVER, E. J. Duquesne Light Co. 83/07/06. MURLEY, T. E. Region 1, Office of Director. 2pp. 19683:361. 24X Fiche: 50-412.83/07/06. 8307220287.
- DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- B307070053 Comments on B10924 meeting re discharge monitoring at facilities. No biological or physical studies conducted on Lake Mylie. Dept has only one monitoring station ω/minimal capabilities.

  PEACOCK B. Bouth Carolina, State of 81/10/02. LEHR, J. Environmental Engineering Branch. 2pp. 19293: 259. 24X Fiche: 30-413,81/10/02,8307070053.
- 8307070139 Forwards info re water quality stds for State of SC industry.per 820401 discussion. No thermal plume studies required for facilities.Projected flow rate of cooling tower blowdown not environmentally harmful.
  PEACOCK.B. Bouth Carolina, State of. 82/04/02. LEHR, J. Environmental Engineering Branch. 1p. 19274:220. 24X Fiche: 50-413, 82/04/02, 8307070139.
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Bvc list encl.
  EISENHUT.D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000.83/06/03.
- 6307110033 Responds to B30531 ltr transmitting draft technical evaluation rept re-control of heavy loads. Comparison of Westinghouse spec for manipulator cranes w/AN31 B30.2 released Sevices meet both specs.

  TUCKER.H. B. Duke Power Co. B3/06/28. DENTUN.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAME.G. Licensing Branch 4. 2pp. 19375:245. 24X Fighe: 50-413, B3/06/28, B307110053.
- 8307090081 Staff requirements memo re 830628 affirmation/discussion & vote in Washington,DC re SECY-83-190A. "Commission Review of ALAB-687."
  CHILK, 8. J. Office of the Secretary of the Commission. 83/06/3D. PLAINE, H. H. E. Office of the General Counsel. 2pp. 19366:310. 24X Fiche: 50-413,83/06/30,8307090081.
- 8306270397 Deneric Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24% Fiche: 50-000, 83/07/05, 8306270397.
- 8307040327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STB. Svc list encl. EISENVHUT.D. Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19649:254. 24X Fichs: 30-000,83/07/06,8307060329.
- B3070B0169 Generic Ltr B3-2B to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EIBENHUTLD.Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307250027 Notification of 830727-28 meetings w/util in York County, SC to discuss completion status & schedule & to tour site & observe const progress.

  JABBOURK M. Licensing Branch 4, 83/07/13, ADENSAM, E. C. Licensin Branch 4, 3pp. 19723:304, 24X Fiche: 50-413,83/07/13,8307250029.

- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8307270011 Provides add1 info not addressed in FES to clarify bases for NRC assessments on matters re aquatic resources effects, in response to 830307 comments.

  ADENSAM, E. 9. Licensing Branch 4. B3/07/13. BLANCHARD, B. Interior, Dept. of. 5pp. 19811:006. 24X Fiche: 50-413, B3/07/13, B307270011.
- B307280099 Forwards DDI B30309 & 0713 ltrs re potential biotic impacts of intake & discharge structures & thermal discharge compliance w/water quality stds.

  ADENSAM, E. G. Licensing Branch 4. 83/07/13. TURNER, L.E. South Carolina, State of. 3pp. 19812:355. 24X Fiche: 50-413, 83/07/13, 8307280099.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8307050368 Forwards licensing position re lockout of manual control by load sequencer. Open Item 10 in Section 1.7 of SER.

  Affirmative response to resolve issue requested by 830715.

  NOVAK.T.M. Assistant Director for Licensing. 83/06/21. TUCKER. H. B. Duke Power Co. 3pp. 19263:311. 24X Fiche: 50-413.83/06/21.

  8307050368.
- 8307130249 Forwards Directive 3.1.10(0P), "Control Room Access & Control." in response to SER Section 13.5.
  TUCKER,H.B. Dute Power Co. 83/06/29. DENTON,H.R. Diffice of Nuclear Reactor Regulation, Director. ADENSAM.E.Q. Licensing Branch 4. 4pp. 19507:328. 24X Fiche: 50-413,83/06/29,8307130249.
- 8307i10383 Forwards info on SER Open Itom 10 re safe shutdown analysis & standby shutdown sys confirming safety-related batteries in station control complex not required for hot standby condition per App R to iOCFR50.
  TUCKER.H.B. Duke Power Co. 83/07/05. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 34pp. 19381:005. 24X Fiche: 50-413, 83/07/05, 8307110383.
- 8307190085 Confirms separation of each channel of containment pressure control sys,per Section 7.3.2.10 of SER Confirmatory Issue 28.

  TUCKER, H. B. Duke Power Co. 83/07/08. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. ADENSAM.E. G. Licensing Branch 4. 2pp. 19635:173. 24X Fiche: 50-413,83/07/08,8307190085.
- 8307190218 Forwards revised response to FBAR Question 440, 48, in response to SER Confirmatory Item 36 re flooding of electrical equipment as result of LOCA. TUCKER, H.B. Duke Power Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 5pp. 19629: 217. 24% Fiche: 50-413,83/07/11,8307190218.
- 8307250372 Forwards proposed resolution to SER Open Item 10, "Lockout of Manual Control by Load Sequencer." Appropriate procedures will be revised to provide operator w/specific guidance as to when & how action should be taken. TUCKER.H.B. Duke Power Co. B3/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM.E.G. Licensing Branch 4. 2pp. 19704:008. 24% Fiche: 50-413.83/07/14,8307250372.
- 8307250435 Forwards revised response to FSAR Question 430, 110 re 100% load rejection capability per SER Confirmatory Item 38. Based on test parameters, brief transient not expected to have adverse effect or impact on equipment operation.

  TUCKER, H. B. Duke Power Co. 83/07/14, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 3pp. 19701: 250, 24% Fiche: 50-413, 83/07/14, 8307250455.
- 8307250537 Notification of 830809-12 meetings w/util & BioTechnology, Inc in Charlotte & York County, SC to discuss preimplementation audit of detailed control room design review summary rept (SER Open litem 18), JABBOUR, K. N. Licensing Branch 4. 83/07/19. ADENSAM, E. Q. Licensing Branch 4. 3pp. 19739; 281. 24X Fiche: 50-413,83/07/19.8307250537.
- F. Security, medical, emergency & fire protection plans
- 8307010015 Forwards Rev 4 to security plan. Rev withheld (ref 10CFR73, 21).
  TUCKER. H. B. Duke Power Co. B3/06/20. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19169: 203. 24X Fiche: 30-413, B3/06/20, 8307010015.
- 8307110383 Forwards info on SER Open Item 10 re safe shutdown analysis a standby shutdown sys confirming safety-related batteries in station control complex not required for hot standby consistion per App R to 100FR50.

  TUCKER.H.B. Duke Power Co. 83/07/05. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 34pp. 19381:005. 24X Fiche: 50-413, 83/07/05, 8307110383.

- 8307250101 Releases public version of ravisad crisis mgt plan for nuclear stations. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19737: 287. 24X Fiche: 50-000, 83/07/19, 8307250101.
- --8307250110 Public version of Rev 9 to trisis mgt plan for nuclear stations. H/830630 ltr.
  VAUDHNIT.S. Duke Power Co. 83/06/15. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 127pp. 19737: 288. 24X Fiche: 50-000, 83/07/19, 8307250101.
- 8307250620 Releases public version of rev to emergency plan. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. ip. 19717:001. 24% Fiche: 50-413,83/07/19, 8307250620.
- --8307250625 Public version of Rev 3 to emergency plan. W/830706 ltr.
  HAMPTON, J. H., TUCKER, H. B. Duke Power Co. 83/06/30. DENTON, H. R.
  Office of Nuclear Reactor Regulation, Director. ADENSAM, E. Q.
  Licensing Branch 4. 159pp. 19717:002. 24X Fiche: 50-413, 83/07/19,
  8307250620.
- B307250717 Releases public version of revised crisis mpt plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/07/19. Document Management Branch. ip. 19719:314. 24X Fiche:50-000,83/07/19,8307250717.
- --8307250730 Forwards public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group.

  TUCKER.H.B. Duke Power Co. 83/05/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17719:315. 24X Fiche:50-000,83/07/19,8307250717.
- --8307230744 Public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. \* Duke Power Co. 83/03/16. 186pp. 19719:317. 24X Fiche:50-000,83/07/19.8307250717.
- Q. Adjudicatory correspondence
- B307050250 Comments on ASLB B30620 memorandum & order re tentative revised schedule. Schedule will not accommodate issuance of initial decision on issues prior to const completion. Proposed schedule & Certificate of Syc encl. QIBBON,R.L. Duke Power Go. B3706/28. 15pp. 19197:144. 24X Fiche: 50-413, 83/06/28, 8307050250.
- 8307050186 Memorandum & Order CLI-83-19 delineating criteria for accepting late-filed contentions based on info contained in licensing-related documents. Document unavailability not good cause when Pacts available. Addl views encl. CHILK. 8. J. Office of the Secretary of the Commission. 83/06/30. 24pp. 19197:030. 24X Fiche: 50-413, 83/06/30, 8307050186.
- 8307070196 Advises that util employees receiving notices of deposition will be available for deposition between 830701 & 15. Related correspondence.

  GIBBON.R.L. Duke Power Co. 83/07/01. GUILD.R. Guild. R. GUILD.R. Palmetto Alliance. 2pp. 19293:355. 24X Fiche:50-413.83/07/01.8307070196.
- B307110291 Advises of availability of welding inspector supervisors to be deposed. Written notices of deposition must be served. Related correspondence. G1880N.R.L. Duke Power Co. B3/07/06. GUILD, R. Guild. R. 1p. 19375:009. 24X Fiche: 50-413, B3/07/06. B307110291.
- 8307110296 Motion for summary disposition of Palmetto Alliance Contention 16 re storage of irradiated fuel assemblies. No genuine issue of mati fact exists & NRC entitled to favorable decision. Statement of mati facts encl. JOHNBON. 9. E. Hearing Branch 4, 83/07/08. Atomic Safety and Licensing Board Panel, 12pp. 19375:313. 24X Fiche: 50-413,83/07/08,8307110256.
- --8307110260 Affidavit of A Bingh & KN Jabbour supporting NRC motion for summary disposition of Palmetto Alliance Contention 16. Public health will not be endangered from storing cooling & handling Ocones & McGulre fuel assemblies at Catawba. SINGH, A. Auxiliary Systems Branch. JABBOUR.K.N. Licensing Branch 4. 83/07/07. 16pp. 19375:325. 24X Fiche: 50-413,83/07/08,8307110256.

- --8307110264 Motion for summary disposition of DES Contention 19 re anviron costs of storage facility for spent fuel. No genuine issue of matl fact exists & NRC entitled to favorable decision. Statement of matl facts encl. JOHNSON. G. E. Hearing Branch 4. 83/07/06. Atomic Safety and Licensing Board Panel. 16pp. 19375: 341. 24X Fiche: 50-413, 83/07/08, 8307110256.
- --B307110270 Affidavit of JS Boegli.EF Branagan & RJ Serbu supporting NRC motion for summary disposition of DES Contention 19. Dose commitments both onsite & offsite from spent fuel storage facility discussed. Prof qualifications encl.
  BUEGLI.J.S. Effluent Treatment Systems Branch. BRANAGAN, E. F., SERBU, R. J. Radiological Assessment Branch. B3/06/23. 20pp. 19375: 357. 24X Fiche: 50-413, B3/07/08, B307110254.
- --8307110273 Motion for summary disposition of DES Contention 17 re environ impacts. No genuine issue of matl facts exists & NRC entitled to favorable decision. Statement of matl facts encl. JOHNSON, O. E. Hearing Branch 4. 83/07/07. Atomic Safety and Licensing Board Panel. 10pp. 19376:015. 24X Fiche: 50-413, 83/07/08, 8307110256.
- ~-B307110279 Affidavit of JA Mitchell.KC Dempsey & JE Fairobent supporting NRC motion for summary disposition of DES Contention 17. Discusses NRC consideration of meteorological conditions for design basis & severe accidents. MITCHELL, J. A., DEMPSEY, K. G. Accident Evaluation Branch. FAIROBENT, J.E. Effluent Treatment Systems Branch. B3/07/07. 13pp. 19376:025. 24X Fiche: 50~413,83/07/08.8307110256.
- --8307i10289 Motion for summary disposition of Carolina Environ Study Oroup Contention iB.Palmetto 44 re reactor degradation. No genuine issue of matl fact exists & Group entitled to favorable decision. Statement of matl facts encl. JOHNSON. G.E. Hearing Branch 4. 83/07/OB. Atomic Safety and Licensing Board Panel. 8pp. 19376:038. 24X Fiche: 50-413. 83/07/OB.8307110256.
- --8307110293 Affidavit of BJ Elliot supporting NRC motion for summary disposition of Carolina Environ Study Group Contention 18, Palmetto 44. Amount of reactor matl degradation for reactor vessels can be accurately measured. ELLIOT. B. J. Materials Engineering Branch. 83/07/01. 39pp. 19376: 046. 24X Fiche: 50-413, 83/07/08, 8307110256.
- --8307110297 Motion for summary disposition of Palmetto Alliance Contention 27 re reading gamma radiation levels. No genuine issue of matl fact exists & NRC entitled to favorable decision. Statement of matl facts encl.

  JOHNBUN. 0. E. Hearing Branch 4. 83/07/08. Atomic Safety and Licensing Board Panel. 7pp. 19376:085. 24X Fiche: 50-413, 83/07/08, 8307110256.
- --8307110302 Affidavit of OE Simonds & EF Branagan supporting NRC motion for summary disposition of Palmetto Alliance Contention 27.

  Util plans for accident assassment & protective action decisionmaking adequate. Centificate of Svc encl.

  SIMONDS.O.E. Emergency Preparedness Branch. BRANAGAN, E.F.
  Radiological Assessment Branch. 83/06/29. 15pp. 19376:092. 24X

  Fiche: 50-413,83/07/08,8307110856.
- 830713019B Forwards motion for summary disposition of Palmetto Alliance Contentions 16,27 & 44 & DEB Contentions 17 & 19. Related correspondence.

  CARR.A.V. Duke Power Co. 83/07/08. KELLEY.J.L., CALLIHAN.A.D., FOSTER.R.F. Atomic Bafety and Licensing Board Panel. 2pp. 19508:068. 24X Fiche: 50-413,83/07/08.8307130198.
- --8307130202 Motion for summary disposition of Palmetto Alliance Contentions 16,27 & 44. Carolina Environ Study Group Contentions 18 & DES Contentions 17 & 19. No genuine issue of matl fact exists. Related correspondence.

  CARR.A.V. Duke Power Co. 83/07/08. Atomic Safety and Licensing Board Panel. 24pp. 19508:070. 24X Fiche: 50-413,83/07/08, 8307130198.
- --8307130205 Affidavit of AL Snow re Palmetto Alliance Contention 16 on spent fuel storage facility cooling & criticality control capability.Plant sys comply w/GDC 44. Prof qualifications encl.

  BNOW.A.L. Duke Power Co. 83/07/08. 15pp. 17508:074. 24X Fiche: 50-413.83/07/08.8307130178.
- --8307130213 Affidavit of MC Green rs Palmetto Alliance Contention 16.

  Spent fuel liner would not rupturs if temp exceeds 150 F.

  Spent fuel cask cannot be dropped into spent fuel pool. Rails will be relocated so cask will not be over fuel pool area.

  GREEN.M.C. North Carolina, State of. 83/07/08. 42pp. 19508:109.

  24X Fiche: 50-413,83/07/08,8307130198.

- --B307130224 Affidavit of AL Snow re Palmetto Alliance/Carolina Environ Study Group Alliance Contention 19. Environ impact of McGuire & Oconee spent fuel at Catawba insignificant.Prof qualifications & Certificate of Svc encl. SNDW.A.C. Duke Power Co. 63/07/08. 7pp. 19908:151. 24X Fiche: 50-413,83/07/08.8307130198.
- B307190237 Suppl to petitions to intervene re emergency plans. Issuance of DL would contravene NEPA, Section 4332, wherein environ costs outweigh economic, technical & other benefits. Certificate of Svc enci.
  RILEY, J. L. Carolina Environmental Study Group. GUILD, R. Palmetto Allíance. B3/07/11. Atomic Bafety and Licensing Board Panel. 26pp. 19630:055. 24X Fiche: 50-413,83/07/11,8307190239.
- 8307180089 Memorandum & order approving 830623 stipulation between applicants & Charlotte-Mecklenburg Environ Coalition (CMEC).

  CMEC dismissed as party.

  KELLEY, J.L. Atomic Safety and Licensing Board Panel. 83/07/14.

  Charlotte-Mecklenberg Environmental Coalition. 2pp. 19556:242. 24X

  Fiche: 50-413,83/07/14,8307180089.
- 8307210269 Motion for partial summary disposition of Palmetto Alliance Contention 6. No genuine issue of matl fact exists & applicants entitled to favorable decision. Argument & documentation supporting motion encl. Related correspondence. CARR. A. V. Dute Power Co. CARR. A. V. Debevoise & Liberman. 83/07/15. Atomic Safety and Licensing Board Panel. 47pp. 19644: 289. 24X Fiche: 30-413.83/07/15.8307210269.
- --8307210272 Affidavit of LR Davidson re Palmetto Alliance Contention 6. Concrete pours on wall above interior doghouse of Unit 1 containment found acceptable Rain leakage did not damage control room boards. Prof qualifications encl.

  DAVIDSON.L.R. Duke Power Co. 83/07/15. 8pp. 19664:336. 24X Fiche: 50-413.83/07/15.8307210269.
- ---8307210274 Affidavit of JC Rogers re Palmetto Alliance Contention 6.
  Green water in UHI bldg is not unsafe. Contact of carbon steel & stainless steel will not compromise matl integrity.
  Prof qualifications & Certificate of Svc encl.
  RODERS.J. C. Duke Power Co. 83/07/15. 9pp. 19644:344 24X
  Fiche: 30-413,83/07/15,8307210269.
- B307220358 Memorandum & order adopting schedule leading to hearing, if necessary, on all issues except emergency planning.
  KELLEY, J. L. Atomic Safety and Licensing Board Panel. B3/07/20.
  3pp. 19675: 174. 24X Fiche: 50-413, 83/07/20, B307220358.
- 8307280032 Motion for extension until 830805 to file affidavit supporting util motion for partial summary disposition of Palmetto Alliance Contention 6. Time necessary due to illness of individual. Certificate of Svc encl.

  JOHNSON. 9. E. Hearing Branch 4. 83/07/27. Atomic Safety and Licensing Board Panel. 5pp. 19791:185. 24X Fiche: 50-413.83/07/27, 8307280032.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140140 Ack receipt of IE Insp Repts 50~413/83-07 & 50~414/83-07. No proprietary info.
  TUCKER.H. B. Duke Pawer Co. 83/06/22. O'REILLY, J. P. Region 2, Office of Director. 1p. 19514: 228. 24X Fiche: 50~413, 83/06/22, 8307140140.
- 8307140070 Forwards IE Insp Rept 50~413/83-13 on 830531~0604. No noncompliance noted. DANCE,H.C. Division of Project & Resident Programs. 83/06/23. TUCKER,H.B. Duke Power Co. 2pp. 19514: 092. 24X Fiche: 50~413,83/06/23,8307140070.
- --8307140073 IE Insp Rept 50-413/83-13 on B30531-0604 No noncompliance noted Major areas inspected: cold hydrostatic test of RCS & plant tour.
  TAYLOR,P.A., JAPE,F. Region 2, Office of Director. 83/06/20.
  3pp. 19514:094. 24X Fiche: 50-413,83/06/23,8307140070.
- 8307140127 Ferwards IE Insp Repts 50-413/83-11 & 50-414/83-11 on 830531-0603. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/23. TUCKER, H. B. Duke Power Co. 2pp. 19514: 146. 24X Fiche: 50-413,83/06/23,8307140129.
- --8307140133 IE Insp Repts 50-413/83-11 & 50-414/83-11 on 830531-0603. No noncompliance noted, Major areas inspected; instrumentation installation & records & GA/GC procedures.

  HUNT,M.D. Region 2, Office of Director, CONLON,T.E. Division of Engineering & Radiological Eafety Programs. 83/06/20. 5pp. 19514:148. 24X Fiche: 50-413,83/06/23,8307140129.

- B307220470 Ack receipt of IE Insp Repts 50-413/83-10 & 50-414/83-10. No proprietary info.
  TUCKER. (f. B. Dute Power Co. B3/07/01, 0'REILLY, J. P. Region 2, 0ffice of Director. 1p. 17685: 004. 24X Fiche: 50-413, 83/07/01, 8307220470.
- B307220504 Ack receipt of IE Insp Repts 50-413/83-09 & 50-414/83-09. No proprietary info.
  TUCKER.H.B. Dute Power Co. 83/07/01 D'REILLY, J. P. Region 2, Office of Director. ip. 19685: 180. 24X Fiche: 50-413, 83/07/01, 830
- 8307220007 Ack receipt of 1E. Insp. Repts 50-413/83-08 & 50-414/83-08. No proprietary info. TUCKER.H.B. Duke Power Co. B3/07/06. D'REILLY, J. P. Region 2. Office of Director. 1p. 19674: 030. 24X Fiche: 50-413, 83/07/06. 8307220007.
- 8306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Burry Recirculation Epray Subsystem." Svc list encl.
  JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Past 830103). B3/07/11. Consolidate Edison Co. of New York, Inc. 154pp. 17563: 293. 24X Fiche: 50-000, 83/07/11. 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Syc list encl. JORDAN, E. L. Division of Emergency Preparefness & Engineering Response (Post 830103). 837/07/12. Consolidate Edison Co. of New York, Inc. 141pp. 19563: 153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14,8306270406.
- 8. Reportable occurrences, LERs & related correspondence
- B307120349 Suppl to Significant Deficiency Rept SD 413/414/82-26 dtd B30117 Te repair 6/or replacement of defective piston skirts by B30601. Mork on Unit 1 diesels complete. Work on Unit 2 diesels scheduled for completion by B30801. TUCKER. H. B. Duke Power Co. B3/06/22. O'REILLY, J. P. Region 2, Office of Director. 1p. 19425: 121. 24X Fiche: 50-413, 83/06/22, 8307120349.
- B307120371 Suppl to Significant Deficiency Rept SD 413-414/82-01 dtd B20218 re resolution of NCI 13.808. Work will be completed by B30715 pather than B30301 dise to unavailability of valves in sys undergoing testing.

  TUCKER.H. B. Duke Power Co. 83/06/22. 0'REILLY.J.P. Region 2. Office of Director. ip. 19429: 101. 24X Fiche: 50-413.83/06/22. G307120371.
- 8307120398 Interim Bignificant Deficiency Rept 8D 413/83-07 re vent installation error. Initially reported on 830513.RCB cold hydro completed & vent installation error scheduled for correction by 830701.

  TUCKER-H. B. Duke Power Co. 83/04/22. 0'REILLY, J. P. Region 2, Office of Director. ip. 19430: 218. 24X Fiche: 50-413,83/04/22, 8307120398.
- B307260426 Updates Deficiency Regt BD-413-414/81-25 dtd B11113.8A1 relay mod kits to be ordered & installed by 830101, returned instead to Hestinghouse for repair. Installation now expected to be completed by 830801.
  TUCKER. M. B. Duke Power Co. B3/07/12. 0'REILLY. J. P. Region 2, Office of Director. 1p. 19731: 280. 24X Fiche: 50-413, 83/07/12, B307260426.
- B307260495 Presents plan for satisfying intent of Part 21 in order to continue procurement of equipment from Nelson Electric Div of General Bignal Co. in view of Nelson Electric refusal to accept purchase orders involving Part 21 requirements.

  TUCKER.H. B. Duke Power Co. B3/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19733:350. 24%

  Fiche: 50-000.83/07/20.8307260495.
- DUCKET 50-464 CATAMBA NUCLEAR STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 8307070033 Comments on 810924 meeting re discharge monitoring at facilities. No biological or physical studies conducted on Lake Wulle. Dept has only one monitoring station w/minimal capabilities.

  PEACOCK. N. South Carolina, State of, 81/10/02, LEHR, J. Environmental Engineering Branch. 2pp. 19293:259, 24x Fiche: 50-413.01/10/02, 8307070053.

- 8307070139 Forwards info re water quality stds for State of SC industry, per 820401 discussion. No thermal plums studies required for facilities. Projected flow rate of cooling tower blowdown not environmentally harmful.

  PEACOCK, B. South Carolina: State of. 82/04/02. LEHR, J. Environmental Engineering Branch. 1p. 19294: 220. 24X Fiche: 50-413, 82/04/02, 8307070139.
- B306060070 Generic Ltr B3-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Byc list enci.
  EIBENRUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19363:116. 24% Fichs: 50-000, 83/06/03, 830660070.
- B307110053 Responds to B30531 ltr transmitting draft technical evaluation rept re control of heavy loads. Comparison of Hestinghouse spac for manipulator cranes w/ANSI B30. 2 releaved devices meet both spacs.
  TUCKER.H.B. Duke Power Co. B3/06/28, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM.E.G. Licensing Branch 4. 2pp. 19375:245. 24X Fiche: 50-413.83/06/28,8307110053.
- B3070900B1 Staff requirements memo re B3062B affirmation/discussion & vote in Washington, DC re BECY-B3-190A, "Commission Review of ALAD-697."

  CHILK, B. J. Diffice of the Secretary of the Commission, B3/06/30, PLAINE, H. H. E. Office of the General Counsel. 2pp. 17366:310, 24 Fiche: 30-413, B3/06/30, B3070900B1.
- B30720023i Notification of B30707 meeting w/technical review committee in Bethesda, MD to discuss review of D4, D5 & E steam generator mods. HOPKINSJ. B. Licensing Branch 4. 83/07/01. ADENSAM, E. Q. Licensing Branch 4. 83/07/01. ADENSAM, E. Q. Licensing Branch 4. 2pp. 19670:234. 24X Fiche: 30-000, 83/07/01, 8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Bvc list encl. EIGENHUT, D. O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390: 317. 24X Fiche: 50-000, 83/07/03, 8306270397.
- 8307060329 Oeneric Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 8TS.8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19667:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Oeneric Ltr 83-28 to all licensees of operating reactors; applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D. 9. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19869:269. 24X Fiche: 50-000:83/07/08.8307080169.
- 8307250029 Notification of 830727-28 meetings w/util in York County, BC to discuss completion status & schedule & to tour site & observe const progress.
  JABBOUR, K. N. Licensing Branch 4. 83/07/13. ADENBAM. E. Q. Licensing Branch 4. 3pp. 19723:304. 24X Fiche: 50-413, 83/07/13, 8307250029.
- 8307250124 Summary of 630707 meeting w/technical review committee in Bethesda,MD re Model D4/D5/E steam generator mod. Viewgraphs encl. MOPKING.J.D. Licensing Branch 4. 83/07/18. Licensing Branch 4. 26pp. 19738: 132. 24X Fiche: 50-000, 63/07/18, 8307250124.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 8307270011 Provides add1 info not addressed in FEB to clarify bases for NRC assessments on matters re aquatic resources effects, in response to 830309 comments.

  ADENBAM, E. O. Licensing Branch 4, 83/07/13, BLANCHARD, B. Interior, Dept. of, 5pp. 19811:006, 24X Fiche: 50-413, 83/07/13, 8307270011.
- 8307280099 Forwards DDI 830309 & 0713 ltrs re-potential biotic impacts of intake & discharge structures & thermal discharge compliance w/water quality stds.

  ADENSAM.E. Q. Licensing Branch 4. 83/07/13. TURNER, L. E. South Carolina, State of. 3pp. 19812:355. 24X Fiche: 50-413,83/07/13,8307280099.

- E. NRC Safety Evaluation Report (SER), supply & correspondence
- 8307050368 Forwards licensing position re lockout of manual control by load sequencer. Open Item 10 in Section 1.7 of SER. Affirmative response to resolve issue requested by B30715. NOVAK, T. M. Assistant Director for Licensing. B3/06/21. TUCKER, H. B. Duke Power Co. 3pp. 19263: 311. 24X Fiche: 50-413, 83/06/21. B307050368.
- 8307130249 Forwards Directive 3.1.10(OP), "Control Room Access & Control," in response to SER Section 13.5.
  TUCKER.H. B. Duke Power Co. 83/06/29, DENTON,H.R. Office of Nuclear Reactor Regulation, Director, ADENGAM,E.G. Licensing Branch 4. 4pp. 19507:328. 24X Fiche: 50-413, 83/06/29, 8307130249.
- 8307110383 Forwards info on SER Open Item 10 re safe shutdown analysis & standby shutdown sys confirming safety-related batteries in station control complex not required for hot standby condition per App R to 10CFR80.

  TUCKER.H.B. Duke Power Co. 83/07/05. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM.E.G. Licensing Branch 4. 34pp. 19381:005. 24X Fiche: 50-413, 83/07/05.8307110383.
- 8307190085 Confirms separation of each channel of containment pressure control sys.per Section 7.3.2.10 of BER Confirmatory Issue 28. TUCKER, H. B. Duke Power Co. B3/07/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. Q. Licensing Branch 4. 2pp. 19435:173, 24X Fiche: 50-413, 83/07/08. B307190085.
- 8307190218 Forwards revised response to FBAR Question 440.48, in response to SER Confirmatory Item 36 re flooding of electrical equipment as result of LOCA.
  TUCKER, H. B. Duke Power Co. 83/07/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. Q. Licensing Branch 4. 5pp. 19629; 217. 24X Fiche; 50-413, 83/07/11, 8307190218.
- 8307230372 Forwards proposed resolution to SER Open Item 10. "Lockout of Manual Control by Load Sequencer." Appropriate procedures will be revised to provide operator w/specific guidance as to when & how action should be taken.
  TUCKER.H. 8. Duke Power Co. 83/07/14. DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director. ADENSAM.E.O. Licensing Branch 4. 2pp. 19704:00B. 24X Fiche: 50-413, 83/07/14, 8307250372.
- 8307250455 Forwards revised response to FBAR Question 430.110 re 100% 10ad rejection capability per BER Confirmatory Item 38. Based on test parameters, brief transient not expected to have adverse affect or impact on equipment operation. TUCKER.H.B. Duke Power Co. 83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. ADENBAM.E.G. Licensing Branch 4. 3pp. 19701:250. 24X Fiche: 50-413, 83/07/14.8307250455.
- 8307250537 Notification of 830809-12 meetings w/util & BioTechnology, Inc in Charlotte & York County.8C to discuss preimplementation audit of detailed control room design review summary rept (BER Open Item 18).

  VABBOUR,K. N. Licensing Branch 4, 83/07/19, ADENSAM.E. G. Licensi Branch 4, 3pp. 19739:281. 24X Fiche: 50-413,83/07/19,8307250537.
- F. Security, medical, emergency & fire protection plans
- 8307010015 Forwards Rev 4 to security plan. Rev withheld (ref 100FR73.21). TUCKER, H. B. Duke Power Co. 83/06/20. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19169: 203. 24X Fiche: 50-413: 83/06/20,
- 8307110383 Forwards info on SER Open Item 10 re safe shutdown analysis & standby shutdown sys confirming safety-related batteries in station control complex not required for hot standby condition per App R to 10CFR50.
  TUCKER.H.B. Duke Power Co. 83/07/05. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 34pp. 19381:005. 24X Fiche: 50-413, 83/07/05, 8307110383.
- 8307250101 Releases public version of revised crisis mgt plan for nuclear stations. FELTON, J. M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19737: 287. 24X Fiche: 50-000, 83/07/19, 8307250101.
- --8307250110 Public version of Rev 9 to crisis mgt plan for nuclear stations W/830630 ltr. VAUGHN, T.S. Dute Power Co. 83/06/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 127pp. 19737:288. 24X Fiche: 50-000, 83/07/19, 8307250101.
- 8307250620 Releases public version of rev to amergency plan. FELTON, J. M. Division of Rules and Records. 83/07/19. Document Management Branch. 1p. 19717:001. 24X Fiche: 50-413,83/07/19,8307250620.

- --8307250625 Public version of Rev 3 to emergency plan H/830706 ltr. HAMPTON.J.M., TUCKER.H.B. Duke Power Co. 83/06/30, DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM.E.G. Licensing Branch 4. 159pp. 19717:002. 24X Fiche: 50-413,83/07/19,8307250620.
- 8307250717 Releases public version of revised crisis mgt plan implementing procedures. FELTON.J.M. Division of Rules and Records. B3/07/19. Document Management Branch. 1p. 19719:314. 24X Fiche:50-000:83/07/19. 8307250717.
- --B307250730 Forwards public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group.

  TUCKER.H.B. Duke Power Co. 83/05/02. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19719:315. 24X Fiche:50-000,83/07/19,8307250717.
- --B307250744 Public version of Rev 1 to Crisis Mgt Plan Implementing Procedure 5.3.2 re crisis news group plan & Rev 5 to Procedure 5.3.3 re administrative & logistics support group. \* Duke Power Co. B3/03/16. 186pp. 19719:317. 24X Fiche: 50-000, 83/07/19, 8307250717.

## G. Adjudicatory correspondence

- 8307050250 Comments on ASLB 830620 memorandum & order re tentative revised schedule. Schedule will not accommodate issuance of initial decision on issues prior to const completion. Proposed schedule & Certificate of Svc encl. 01860N.R.L. Duke Power Co. 83/06/28. 15pp. 19197:144. 24X Fiche: 50-413.83/06/28.8307050250.
- 8307030186 Memorandum & Order CLI-83-19 delineating criteria for accepting late-filed contentions based on info contained in licensing-related documents. Document unavailability not good cause when facts available. Addl views encl. CHILK, 8. J. Office of the Secretary of the Commission. 83/06/30.24pp. 19199.030. 24X Fiche: 50-413, 83/06/30, 8307050186.
- 8307070196 Advises that util employees receiving notices of deposition will be available for deposition between 830701 & 15.Related correspondence.

  OIBBON,R.L. Duke Power Co. 83/07/01. GUILD,R. Guild, R. GUILD,R. Palmetto Alliance. 2pp. 19293:355. 24X Fiche: 50-413,83/07/01,8307070196.
- B307110291 Advises of availability of welding inspector supervisors to be deposed. Written notices of deposition must be served. Related correspondence. 01BB0N.R.L. Duke Power Co. 83/07/06. OVILD.R. Guild, R. 1p. 19375:009. 24X Fiche: 50-413.83/07/06.8307110291.
- B307110256 Motion for summary disposition of Palmetto Alliance Contention 16 re storage of irradiated fuel assemblies. No genuine issue of matl fact exists & NRC entitled to favorable decision. Btatement of matl facts encl. JOHNSON. G. E. Hearing Branch 4. B3/07/08. Atomic Bafety and Licensing Board Panel. 12pp. 19375:313. 24X Fiche: 50-413, B3/07/08, B307110256.
- --8307110260 Affidavit of A Singh & KN Jabbour supporting NRC motion for summary disposition of Palmetto Alliance Contention 14.

  Public health will not be endangered from storing cooling & handling Oconee & McQuire fuel assemblies at Catauba.

  BINGH.A. Auxiliary Systems Branch. JABBOUR, K. N. Litensing Branch 4. 83/07/07. 16pp. 19375:325. 24X Fiche:50-413,83/07/08.
- --B307110264 Motion for summary disposition of DES Contention 19 re moviron costs of storage facility for spent fuel. No genuine issue of matl fact exists & NRC entitled to favorable decision. Statement of matl facts encl. JOHNSON, G.E. Hearing Branch 4. B3/07/06. Atomic Safety and Licensing Board Panel. 16pp. 19375:341. 24X Fiche: 50-413, 83/07/08, 8307110256.
- --B307i10270 Affidavit of JB Boegli, EF Branagan & RJ Serbu supporting NRC motion for summary disposition of DES Contention 19. Dose commitments both onsite & offsite from spent fuel storage facility discussed. Prof qualifications encl.
  BDGCLI, J. S. Effluent Treatment Systems Branch. BRANAGAN. E. F., SERBU. R. J. Radiological Assessment Branch. 83/06/23, 20pp. 19375: 357. 24x Fiche: 50-413, 83/07/08, 8307110256.
- ---B307110273 Motion for summary disposition of DEB Contention 17 re environ impacts. No genuine issue of mat1 facts exists & NRC entitled to favorable decision. Statement of mat1 facts enc1. JOHNSON, O. E. Hearing Branch 4. B3/07/07. Atomic Safety and Licensing Soard Panel. 10pp. 19376:015. 24X Fiche: 50-413, 83/07/08, 8307110256.

- --8307110279 Affidavit of JA Mitchell.KC Dempsey & JE Fairobent supporting NRC motion for summary disposition of DEB Contention 17. Discusses NRC consideration of meteorological conditions for design basis & severe accidents.

  MITCHELL.J.A., DEMPSEY.K.C. Accident Evaluation Branch. FAIROBENT.J.E. Effluent Treatment Systems Branch. 83/07/07. 13pp. 19376:025. 24X Fiche: 30-413.83/07/08.8307110256.
- --B307110287 Motion for summary disposition of Carolina Environ Study Group Contention 18.Palmetto 44 re reactor degradation. No genuine issue of matl fact exists & Group entitled to favorable decision. Statement of matl facts encl. JOHNBON.O.E. Hearing Branch 4. B3/07/08. Atomic Safety and Licensing Board Panel. Bpp. 19376:03B. 24X Fiche: 50~413. B3/07/08.B307110256.
- --8307110293 Affidavit of BJ Elliot supporting NRC motion for summary disposition of Carolina Environ Study Group Contention 18, Palmatto 44. Amount of reactor matl degradation for reactor vessels can be accurately measured.

  ELLIDT, B. J. Materials Engineering Branch. 83/07/01. 39pp. 19376: 046. 24X Fiche: 30-413, 83/07/08, 8307110256.
- --8307110297 Motion for summary disposition of Palmetto Alliance Contention 27 re reading gamma radiation levels. No ganuine issue of matl fact exists & NRC entitled to favorable decision. Statement of matl facts enci.

  JOHNSON G. E. Hearing Branch 4. 83/07/08. Atomic Safety and Licensing Board Panel. 7pp. 19376:085. 24x Fiche: 50-413.
- --8307110302 Affidavit of OE Simonds & EF Branagan supporting NRC motion for summary disposition of Palmetto Alliance Contention 27. Util plans for accident assessment & protective action decisionmaking adequate. Certificate of Syc encl. SIMONDS, G. E. Emergency Preparedness Branch. BRANAGAN, E.F. Radiological Assessment Branch. 83/06/27. 15pp. 19376:092. 24X Fiche: 50-413, 83/07/08, 8307110256.
- 8307130198 Forwards motion for summary disposition of Palmetto Alliance Contentions 16,27 & 44 & DEB Contentions 17 & 19. Related correspondence.

  GARR.A.V. Duke Power Co. 83/07/08. KELLEY, J. L., CALLIHAN, A. D., FOSTER, R. F. Atomic Safety and Licensing Board Panel. 2pp. 19508:068. 24K Fichs: 50-413,83/07/08,8307130198.
- --8307130202 Motion for summery disposition of Palmetto Alliance Contentions 16,27 & 44, Carolina Environ Study Group Contention 18 to DES Contentions 17 & 19. No genuing issue of mat1 fact exists. Related correspondence.

  CARR. A. V. Duie Power Co. B3/07/08. Atomic Safety and Licensing Board Panel. 24pp. 19508;070. 24x Fiche: 50-413, B3/07/08, B307130198.
- --8307130206 Affidavit of AL Snow re Palmetto Alliance Contention 16 on spent fuel storage facility cooling & criticality control capability. Plant sys comply w/ODC 44. Prof qualifications enci.

  SNOW, A. L. Duke Power Co. 83/07/08. 15pp. 17508:074. 24X Fiche: 50-413,83/07/08,8307130178.
- --B307130213 Affidavit of MC Orsen re Palmetto Alliance Contention 16.

  Spent fuel liner would not rupture if temp exceeds 150 F.

  Spent fuel cask cannot be dropped into spent fuel pool.Rails will be relocated so cask will not be over fuel pool area.

  OREEN.M.C. North Carolina. State of. 83/07/08. 42pp. 19508: 109.

  24X Fiche: 50-413.83/07/08.8307130198.
- --8307130224 Affidavit of AL Show re Palmetto Alliance/Caroline Environ Study Group Alliance Contention 19. Environ impact of McGuire & Oconee spent fuel at Catawba insignificant. Prof qualifications & Certificate of Bvc encl. SNOW, A. C. Duke Power Co. 83/07/08. 7pp. 19508:151. 24X Fiche: 50-413, 83/07/08, 8307130178.
- 8307190239 Suppl to patitions to intervens re emergency plans. Issuance of GL would contravene NEPA, Section 4332, wherein environ costs outweigh aconomic, technical & other benefits.

  Certificate of Svc encl.

  RILEY, J. L. Carolina Environmental Study Group. GUILD, R. Palmetto Alliance. 83/07/ii. Atomic Safety and Licensing Board Panel. 26pp. 19430:055. 24X Fiche: 50-413,83/07/ii,8307190239.
- 8307180089 Memorandum & order approving 830623 stipulation between applicants & Charlotte-Mecklenburg Environ Coalition (CMEC). CMEC dismissed as party. KELLEY, U.L. Atomic Safety and Licensing Board Panel. 83/07/14. Charlotte-Mecklenberg Environmental Coalition. 2pp. 19556:242. 24x Fiche: 50-413, 83/07/14, 8307180089.

- 8307210267 Motion for partial summary disposition of Palmetto Alliance Contention 6. No genuine issue of matl fact exists & applicants entitled to favorable decision. Argument & documentation supporting motion encl. Related correspondence. CARR.A. V. Duke Power Co. CARR.A. V. Debvoise & Liberman. 83/07/15. Atomic Safety and Licensing Board Panel. 47pp. 19664: 289. 24X Fiche: 50-413,83/07/15,8307210269.
- --B307210272 Affidavit of LR Davidson re Palmetto Alliance Contention 6. Concrete pours on wall above interior deghouse of Unit 1 containment found acceptable. Rain leakage did not damage control room boards. Prof qualifications encl. DAVIDSON, L. R. Duke Power Co. B3/07/13. 8pp. 19664: 336. 24X Fiche: 50-413, 83/07/15, 8307210269.
- --B307210274 Affidavit of JC Rogers re Palmetto Alliance Contention 6. Green water in UHI bldg is not unsafe. Contact of carbon steel & stainless steel will not compromise matl integrity. Prof qualifications & Certificate of Svc encl. ROGERS, J. C. Duke Power Co. B3/07/15. 7pp. 17664:344. 24X Fiche:50-413,83/07/15,8307210269.
- B307220358 Memorandum & order adopting schedule leading to hearing, if necessary, on all issues except emergency planning. KELLEY, J.L. Atomic Safety and Licensing Board Panel. B3/07/20. 3pp. 19675:174. 24X Fiche: 30-413
- 8307280032 Motion for extension until 830805 to file affidavit supporting util motion for partial summary disposition of Palmetto Alliance Contention 6. Time necessary due to illness of individual. Cartificate of Svc encl.
  JOHNSON.O.E. Hearing Branch 4. 83/07/27. Atomic Safety and Licensing Board Panel. 5pp. 19791:195. 24X Fiche: 50-413.83/07/27, 8307280032.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140140 Ack receipt of IE Insp Repts 50-413/83-07 & 50-414/83-07. No proprietary info.
  TUCKER.H.B. Dute Power Co. 83/06/22. O'REILLY, J. P. Region 2.
  Office of Director. Ip. 19514: 228. 24X Fiche: 50-413,83/06/22, 8307140140.
- 8307140127 Forwards IE Insp Repts 50-413/83-11 & 50-414/83-11 on 830531-0603. No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. 83/06/23. TUCKER.H.B. Duke Power Co. 2pp. 19514:146. 24X Fiche: 30-413, 83/06/23, 8307140129.
- --B307140133 IE Insp Repts 50-413/83-11 & 50-414/83-11 on 830531-0603. No noncompliance noted Major areas inspected instrumentation installation & records electrical component installation & records & 0A/06 procedures.

  HUNTIM D. Region 2, Office of Director. CONLON.T.E. Division of Engineering & Radiological Safety Programs. 83/06/20. 5pp. 19514:148. 24X Fiche: 50-413:83/06/23,8307140129.
- 8307220470 Ack receipt of IE Insp Repts 50-413/83-10 & 50-414/83-10. No proprietary info.
  TUCKER.M.B. Duke Power Co. 83/07/01. O'REILLY, J. P. Region 2, Office of Director. 1p. 19685:004. 24X Fiche: 50-413, 83/07/01, 8307220470.
- 8307220504 Ack receipt of IE Insp Repts 50-413/83-09 & 50-414/83-09. No proprietary info.
  TUCKER: H.B. Duke Pawer Co. 83/07/01. 0'REILLY, J. P. Region 2, Office of Director. ip. 19685:180. 24X Fiche: 50-413,83/07/01: 8307220504.
- B307220007 Ack receipt of 1E Insp Repts 50-413/83-08 & 50-414/83-08 No proprietary info.
  TUCKER, H. B., Duke Power Co. 83/07/06. D'REILLY, J. P. Region 2, Office of Director. ip. 19674:030. 24X Fiche: 50-413, 83/07/06, 8307220007.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Byc list ancl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Past B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8304270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list enci. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19343:153. 24X Fiche: 30-000,83/07/12.8306270404.

- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLORJ.M. Division of GA, Safeguards & Inspection Program
  - TAYLOR, J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- 8. Reportable occurrences, LERs & related correspondence
- B307120349 Suppl to Bignificant Deficiency Rept SD 413/414/82-26 dtd B30117 re repair &/or replacement of defective piston stirts by B30601. Hork on Unit 1 dissels complete. Nork on Unit 2 dissels scheduled for completion by B30801.
  TUCKER.H.D. Duke Power Co. B3/06/22. D'REILLY.J.P. Region 2. Office of Director. 1p. 19425:121. 24x Fiche: 50-413.B3/06/22. B307120349.
- 8307120371 Suppl to Significant Deficiency Rept SD 413-414/82-01 dtd 820218 re resolution of NCI 13,808. Mork will be completed by 830715 rather than 830301 due to unavailability of valves in sys undergoing testing.
  TUCKER. M. B. Duke Power Co. 83/06/22. D'REILLY, J. P. Region 2: 0ffice of Director. 1p. 19429: 101. 24X Fiche: 50-413,83/06/22,8307120371.
- 9307120427 Final Significant Deficiency Rept SD 414/82-16 re arc strike on valve 2NI162A. Encl Borg-Warner evaluation concludes that arc strike not made at vendor facility. Arc strike occurred during installation. Item datermined not reportable. TUCKER, H. B. Duke Power Co. 83/06/30. D'REILLY, J. P. Region 2. Office of Director. Spp. 19425; 231. 24X Fiche: 50-414, 83/06/30, 8307120427.
- 8307220269 Final Bignificant Deficiency Rept SD 414/83-D8 Te tack weld on shaft/rotor assembly of Limitorque operator motor mfg by Reliance Electric installed on Class i Kerotast valve. Initially reported on 80415. Rotor & shaft replaced. TUCKER. H. B. Duke Power Co. 83/07/08. O'REILLY, J. P. Region 2. Office of Director. 3pp. 17684:172. 24X Fiche: 50-414, 83/07/08, 830720269.
- B307260426 Updates Deficiency Rept SD-413-414/81-25 dtd 811113 SA1 relay mod kits to be ordered & installed by B30101.returned instead to Mestinghouse for repair. Installation now expected to be completed by B30801.

  TUCKER.H.B. Duke Power Co. B3/07/12. O'REILLY, J. P. Region 2, Office of Director. 1p. 19731:280. 24X Fiche: 50-413, B3/07/12, B307260426.
- 8307260495 Presents plan for satisfying intent of Part 21 in order to continue procurement of equipment from Nelson Electric Div of General Signal Co.in view of Nelson Electric refusal to accept purchase orders involving Part 21 requirements. TUCKER.H.B. Duke Power Co. 83/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19733:350. 24X Fiche:50-000.83/07/20.8307260495.
- DOCKET 50-416 GRAND QULF NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Syc list encl. EISENHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-900, 83/07/05, 8306270397.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Balem ATMS events. Evc list encl. EISENMUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24x Fichs: 30-000,83/07/08,8307080169.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307220368 Provides formal documentation of analyses performed per SER Saction 6.2.8 to determine min design thickness of main steam line & feedwater line Flued heads. Info re design ability to maintain see metal temp also encl.

  DALE, L.F. Mississippi Power & Light Co. 83/07/20. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 19475: 234. 24X Fiche: 50-416, 83/07/20, 8307220368.

- F. Becurity, medical, emergency & fire protection plans
- B307140040 Discusses B3012B briefing in Jackson,MS re util drug & alcohol abuse program.

  D'REILLY, J.P. Region 2, Office of Director. B3/02/03.

  STAMPLEY, N.L. Mississippi Power & Light Co. ip. 19514: 219. 24X

  Fiche: 50-414, 83/02/03, 8307140040.
- B306140204 Requests review of 10CFR30.54(p) change to physical security plan. Rev 7. Change involved access authorization program.
  BTOHR, J. P. Division of Emergency Preparedness (Pre B30103).
  B3/05/03. MIRAOLIA,F. J. Standardization & Special Projects Dranch.
  1p. 18832: 261. 24X Fiche: 50-416.83/05/03.8306140204.
- B3070100B1 Forwards Rev B replacement pages to physical security plan. Pages withheld (ref 10CFR2.790).

  DALELLF. Mississippi Power & Light Co. 83/06/10. O'REILLY, J.P. Region 2. Office of Director. 2pp. 19124:340. 24X

  Fiche: 50-416.83/06/10.8307010081.
- B30705013B Ack receipt of B30617 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 30-416/B3-18. LEWIG.R.C. Division of Project & Resident Programs. B3/06/29. RICHARD.J.B. Mississippi Pawer & Light Co. 1p. 19199:181. 24X Fiche: 50-416.83/06/29.830708013E.
- --8307050166 Responds to NRC 830517 ltr re violations noted in IE Safeguards Insp Rept 50-416/83-18. Corrective actions withheld (ref 10CFR73, 21) HCGAUGHY, J.P. Mississippi Power & Light Co. 83/06/14. O'REILLY, J.P. Region 2, Office of Director. 1p. 19199:192. 24X Fiche: 50-416,83/06/29,8307050158.
- --8307050175 Forwards IE Safeguards Insp Rept 50-446/83-18 on 830421 & 0503-04 & notice of violation. Notice of violation withheld (ref 10CFR73, 21).

  LEMIS.R.C. Division of Project & Resident Programs. B3/05/17.

  RICHARDS, J. B. Mississippi Power & Light Co. 2pp. 17179:183. 24X Fiche: 50-446,83/04/27,8307050158.
- --8307050181 IE Safeguards Insp Rept 50-416/83-18 on 830421 & 0503-04. Noncompliance noted: failure to maintain positive control of escented employee. Details withheld (ref 10CR73.21). TILLMAN.A. HAGNER.A. Region 2, Office of Director. MCGUIRE.D.R. Division of Emergency Preparedness & Materials Safety. 83/05/16. 19. 19199: 185. 24X Fiche: 50-416.83/06/29.8307050158.
- B307140093 Forwards summary of B30602 meeting in Region II off re proposed physical security plan mods at facility. List of attendees also encl. LEWIS.R.C. Division of Project & Resident Programs. 83/07/01. RICHARD.J.B. Mississippi Power & Light\_Co. 4pp. 19514:086. 24 Fiche: 30-416.83/07/01.8307140093.
- B307080447 Notifies that centain changes in B30315 Rev 7 to physical specurity plan.decrease effectiveness of plan & are inconsistent w/IOCFR90. 54. Previously approved plan will be implemented. Encl withheld (ref IOCFR73. 21).
  BCHMENCER.A. Licensing Branch 2. 83/07/05. MCGAUGHY.J.P. Mississippi Power & Light Co. 1p. 19346:159. 24%
  Fiche: 90-416.83/07/05.8307080447.
- 8307220491 Ack receipt of 830311 & 0606 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-78.

  O'REILLY J. P. Region 2. Office of Director. 83/07/11. RICHARD, J. R. Mississippi Power & Light Co. 1p. 19685: 196. 24X Fiche: 50-416-83/07/11, 8307220491.
- --8307220500 Submits supplemental response to NRC 830209 ltr reviolations noted in IE Insp Rept 50-416/82-78. Corrective actions: security post established to conduct insp of control room cabinets every 4 h & all activities logged. MCOAUCHY.J.P. Mississippi Power & Light Co. 83/06/06. O'REILLY.J.P. Region 2. Dffice of Director. Spp. 19685: 197. 24X Fiche: 50-416,83/07/11,8307220491.
- --8307220505 Forwards response to NRC B30207 ltr re violations noted in IE Insp Rept 50-416/82-78. Corrective actions: surveillance conducted on B21125, w/independent verification. Valves positioned & locked per instructions. Training scheduled. MCOAUGHY, J. P. Mississippi Power & Light Co. 83/03/11. 078EILLY, J. P. Region 2. Office of Director. 4pp. 19685; 200. 24X Fiche: 50-416, 83/07/11, 8307220491.
- --8307220516 IE Insp Rept 50-416/82-78 on 821116-1215.Noncompliance noted: failure to follow maint procedures, failure to conduct training & failure to lock cabinets.

  WAGNER, A. O., SCOTT, D. E., CANTRELL, F. S. Region 2, Office of Director. 83/01/26, 10pp. 17685:210. 24X Fiche: 50-416,83/07/11,8307220491.

- 8307210177 Application to amend License NPF-13, revising Tech Specs re fire detection instrumentation. Changes necessary to enhance clarity & provide consistency w/plant design & operation. BALE/L.F. Mississippi Power & Light Co. 83/07/19. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19669:069. 24X Fiche: 50-416.83/07/19.8307210177.
- --B307210181 Proposed Tech Spec changes re fire detection instrumentation. \* Mississippi Power & Light Co. B3/07/19. 15pp. 19669:071. 24X Fiche:50-416.B3/07/19.B307210177.

#### f. Financial information

- B307060101 Forwards Annual Financial Repts & certified financial statements for 1982.

  DALE-L.F. Hississippi Power & Light Co. B3/06/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 13pp. 19237: 172. 24X Fiche: 50-416, B3/06/30, B307060101.
- ---8307060110 Annual Financial Rept 1982.

  \* South Mississippi Electric Power Association. 83/06/30. 27pp. 19237: 185. 24X Fiche: 50-416, 83/06/30, 8307060101.
- --8307060113 Annual Financial Rept 1982. \* Mississippi Power & Light Co. 83/06/30. 27pp. 19237:212. 24X Fiche: 50-416.83/06/30.8307060101.

### M. Antitrust correspondence

- B307210216 Forwards interconnection agreement between util & FERC to resolve violations of antitrust license conditions.
  Resolutions to other issues also provided.
  MCDIARMID,R.C. Spiegel & McDiarmid. 83/07/19. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 143pp. 19667:101, 24X Fiche: 30-416,83/07/19,8307210216.
- P. Operating license stage documents & correspondence
- 8307140367 Concurs w/interim interpretation of Tech Specs re operability of source range monitor. Interpretation should be corrected when permanent change to Tech Specs requested & accepted.

  LEMIS.R. C. Division of Project & Resident Programs. 83/01/13. 9371412EV, N.L. Nississippi Power & Light Co. ip. 19523:327. 24X Fiche: 50-416, 83/01/13, 8307140367.
- 8306270375 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Guif, LaSalle & Susquehanna re TMI Task Action Plan Item 1.0.1. "Special Low Power Testing & Training & Recommendations for BWRs." Syc list encl. EIBENNUT.D. G. Division of Licensing. 83/06/27. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, 83/06/27, B306270375.
- B307010026 Forwards, for NRC review & approval, proposed changes to Tech Specs, enhancing clarity & providing consistency w/plant design & application. Marked-up Tech Spec Justification for determination encl.

  DALE: L.F. Mississippi Power & Light Co. 83/06/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 66pp. 19169:111. 24X Fiche: 50-416, 83/06/29, 8307010026.
- B307140266 Discusses insps of revised surveillance test program scheduled for wk of B30620-24 & operational readiness evaluation scheduled for wk of B30627-0701. NRC canceling plans until implementation of improved programs. LEMIS.R.C. Division of Project & Resident Programs. B3/06/30. MCCAUCHY.J.P. Mississippi Power & Light Co. 2pp. 19322:333. 24X Fichs: 50-416.83/06/30.8307140266.
- 8907150044 Forwards Amend 7 to License NPF-13, safety evaluation & notice of issuance & availability. Amend grants administrative changes to Tech Spacs to correct editorial & nomenclature errors.

  SCHWENCER.A. Licensing Branch 2. 83/07/01. MCGAUGHY, J. P. Mississippi Power & Light Co. 3pp. 19562:338. 24% Fiche: 50-416, 83/07/01.8307130044.
- --8307130046 Amend 7 to License NPF-13 granting administrative changes to Tech Specs to correct editorial & nomenclature errors & to achieve consistency w/as-built plant conditions.

  SCHWEMCER.A. Licensing Branch 2. 83/07/01. 3pp. 19362:341. 24X Fiche: 50-416,83/07/01,8307130044.

- --8307150051 Notice of issuance & availability of Amend 7 to License NPF-13. SPENDER, A. Licensing Branch 2. 83/07/01. 4pp. 19563:055. 24X SPENDER: 50-416, 83/07/01, 8307150044.
- 8307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307180247 Forwards add1 info to support requests for changes to Tech Specs.per 830630 meeting w/NRC.W/14 oversize drawings. Aperture cards are available in PDR.

  DALE,L.F. Mississippi Power & Light Co. 83/07/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 30pp. 19348:147. 24X Fiche: 50-416, 83/07/08, 8307180247.
- 8307190073 Forwards proposed changes to Tech Specs, enhancing clarity or providing consistency w/plant design & operation.per 821014 confirmation of action ltm. Changes involve NSHC. Justification for determination encl. DALE, L.F. Mississippi Fower & Light Co. 83/07/11. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 4pp. 19635:183. 24X Fiche: 50-416, 83/07/11, 8307190073.
- --8307190079 Proposed changes to Tech Specs, enchancing clarity or providing consistency w/plant design & operation.

  \* Mississippi Power & Light Co. 83/07/11. 40pp. 19635:187. 24X Fiche: 50-416,83/07/11,8307190073.
- 8307180175 Informs that design change package to remove automatic containment isolation signal from RHR jockey pumps will be implemented before next criticality. Description of package submitted in 830623 itr proposing Tech Spac change.

  DALE,L.F. Mississippi Power & Light Co. 83/07/14. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. ip. 19555:062. 24X Fiche: 50-416.83/07/14.8307180175.
- 8307190106 Comments on changes to Tech Specs (NUREO-0926) proposed by util on 830629 Requirement for noble gas activity monitor w/alarm to be continuously operable at either offgas post-treatment or radwaste ventilation point recommended, COBB.A.B. Mississippi, State of, 83/07/14, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19634:248. 24X Fiche:50-416,83/07/14,8307190106.
- 8307250534 Summary of 830629 meeting w/Mark III BWR Dwners Group in Bethesda, MD re hydrogen control research program. Need & technical basis for reduced hydrogen source term in BWR discussed. Viewgraphs encl.
  HOUSTON, M. D. Licensing Branch 2. 83/07/15. 8CHWENCER, A. Licensing Branch 2. 120pp. 19739:287. 24x Fiche: 50-416.83/07/15.8307250534.
- 8307210177 Application to amend License NPF-13, revising Tech Specs re fire detection instrumentation Changes becessary to enhance clarity & provide consistency w/plant design & operation. DALE-L.F. Mississippi Power & Light Co. 83/07/19. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19669:069. 24X Fiche: 50-416, 83/07/19, 8307210177.
- --8307210181 Proposed Tech Spec changes re fire detection instrumentation.

  # Mississippi Power & Light Co. 83/07/19. 15pp. 19669:071. 24X Fiche: 50-416, 83/07/19, 8307210177.
- 8307210193 Forwards addl info to support Tech Spec changes re tolerance associated w/relief function of safety relief valves discussed during 830630 meeting. DALELLF. Mississippi Power & Light Co. 83/07/19. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19665:176. 24X Fiche: 50-416,83/07/19.8307210195.
- B307250225 Forwards revs to Chapter 14 of FBAR, correcting info restartup test procedures & program. Info will be incorporated in future rev to updated FBAR. DALE.L.F. Mississippi Power & Light Co. 83/07/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 27pp. 19706: 001. 24X Fiche: 50-416,83/07/21,8307250225.
- G. Inspection reports, IE Bulletins & correspondence
- 8307140230 Responds to IE Bulletin 82-01, Rev i to bulletin & Suppl 1 to Rev i to bulletin re Associated Piping & Engineering alteration of piping subassembly weld radiographs. No alterations of penetrameter T holes indicated.

  MCGAUGHY, J. P. Mississippi Power & Light G. 83/06/20, O'REILLY, J. P. Region 2, Office of Director. 3pp. 17523; i18, 24X Fiche: 30-416, 83/06/20, 8307140230.

- 8307140120 Forwards IE Insp Rept 50-416/83-21 on 830523-27. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. 83/0. RICHARD. J. B. Mississippi Power & Light Co. 2pp. 19514: 135. Fiche: 50-416 83/06/21
- --8307140124 IE Insp Rept 50-416/83-21 on 830523-27. No noncompliance noted Major areas inspected: licensee identified items. GIBBONS T. D. , CONLON, T. E. Region 2. Office of Director. 83/06/20. 4pp. 19514:137. 24X Fiche: 50-416.83/06/21,8307140120.
- 8307220498 Forwards IE Insp Rept 90-416/83-23 on 830606-10. No noncompliance noted.

  VERRELLI,D.M. Division of Project & Resident Programs. 83/06/27 RICHARD,J.B. Mississippi Power & Light Co. 2pp. 19685: 122. 24 Fiche: 50-416,83/06/27,8307220498.
- --8307220502 IE Insp Rept 50-416/83-23 on 830606-10. No noncompliance noted, Major areas inspected: actions on previous enforcement matters, personnel qualification program, procurement & storage & handling of equipment & matls programs.

  DEBBAGE, A. 9. Region 2, Office of Director. UPRIGHT, C. M. Division of Engineering & Radiological Safety Programs. 83/06/24. Bpp. 19685:124. 24X Fiche: 50-416, 83/06/27, 8307220478.
- B30705015B Ack receipt of B30617 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-416/83-18.

  LEWIB.R.C. Division of Project & Resident Programs. B3/06/29. RICHARD, J. B. Mississippi Power & Light Co. 1p. 17197:181. 24X Fiche: 50-416,83/06/29. B30705015B.
- --B307050166 Responds to NRC 830517 1tr re violations noted in IE Bafeguards Insp Rept 50-416/83-18. Corrective actions withheld (ref 100FR73. 21)
  MCGAUGHY, J. P. Mississippi Power & Light Co. B3/06/16.
  O'REILLY, J. P. Region 2, Office of Director. 1p. 19199: 182.
  Fiche: 50-416, 83/06/29, 8307050158. 19199: 182. 24X
- --8307050175 Forwards IE Safeguards Insp Rept 50-416/83-18 on 830421 & 0503-04 & notice of violation. Notice of violation withhold (ref 10CFR73, 21).

  LEWIS, R. C. Division of Project & Resident Programs. 83/05/17.

  RICHARDB. J. B. Mississippi Power & Light Co. 2pp. 19199:183. 24)

  Fiche: 50-416, 83/06/29, 8307050158. 83/05/17.
- --8307050181 IE Safeguards Insp Rept 50-416/83-18 on 830421 & 0503-04.
  Noncompliance noted: failure to maintain positive control of escorted employee. Details withheld (ref 10CFR73. 21).
  TILLMAN.A., WAGNER.A. Region 2, Office of Director. MCGUIRE.D.R. Division of Emergency Preparedness & Materials Safety. 83/03/16.
  1p. 19199:185. 24X Fiche: 50-416,83/06/29,8307050158.
- B307140266 Discusses inspa of revised surveillance test program scheduled for wk of B30620-24 & operational readiness evaluation scheduled for wk of B30627-0701 NRC canceling plans until implementation of improved programs. LEWIS.R.C. Division of Project & Resident Programs. B3/06/30, MCGAUGHY, J. P. Mississippi Pawer & Light Co. 2pp. 19522: 333. Fiche: 50-416, 83/06/30, 8307140266.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDANIE. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Cancildated Edison Co. of New York, Inc. 154pp. 17563:273. 24X Fiche: 50-000.83/07/11.8306270401.
- 8307220491 Ack receipt of 830311 & 0606 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-78.

  O'REILLY, J. P. Region 2, Office of Director. 83/07/11. RICHARD, J. R. Mississippi Power & Light Co. ip. 17685: 176. 24X Fiche: 50-416, 83/07/11, 8307220471.
- --8307220500 Submits supplemental response to NRC 830209 ltr re violations noted in IE Insp Rept 50-416/82-79. Corrective actions: security post established to conduct insps of control room cabinets every 4 h & all activities logged. MCGAUGHY.J.P. Mississippi Power & Light Co. 83/06/06. O'REILLY.J.P. Region 2. Office of Director. 3pp. 19685: 1976: 19685: 1976: 19685: 1976: 19685: 1976: 19685: 1976: 19685: 1976: 19685: 1976: 19685: 1976: 19685: 1976: 19 19685: 197. 24X
- --8307220505 Forwards response to NRC 830209 ltr re violations noted in IE Insp Rept 50-416/82-78. Corrective actions: surveillance conducted on 821125, w/independent verification. Valves positioned & locked per instructions. Training scheduled. MCGAUGHY. J.P. Mississippi Power & Light Co. 83/03/11. O'REILLY, J.P. Region 2. Office of Director. 4pp. 19685: 200. 24X Fiche: 30-416, 83/07/11, 8307220491.

- --8307220507 Forwards IE lnsp Rept 50-416/82-78 on 821116-1215 & notices of violation % deviation.

  O'REILLY, J. P. Region 2. Office of Director. 83/02/09.

  STAMPLEY, N. L. Mississippi Power & Light Co. 3pp. 19685:204. 24X Fiche: 50-416.83/07/11.8307220491.
- -8307220510 Notice of violation from insp on 821116-1215 \* Region 2, Office of Director. 83/02/09. 2pp. 19. Fiche: 50-416,83/07/11,8307220491. 19485.207. 24x
- --8307220513 Notice of deviation from insp on 821116-1215. \* Region 2, Office of Director. 83/02/09. tp. 19685:209. 24x Fiche: 50-416.83/07/11.8307220491.
- --8307220516 IE Insp Rept 50-416/82-78 on 821116-1215. Noncompliance noted: failure to follow maint procedures, failure to conduct training & failure to lock cabinets.

  WACNER, A. G. . SCOTT, D. E. . CANTRELL, F. S. Region 2. Office of Director 83/01/26. 10pp. 19685:210. 24% Fiche: 50-416, 83/07/11, 8307220491.
- B308270404 IE Info Notice B3-47. "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN.E.L. Division of Emergency Proparedness & Engineering Response (Post B30103). B3/07/12. Comsolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: \$0-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gascous Effluent Releases of Radioactive 1-125 & 1-131 in Excess of NRC Limits." Syc list TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- R. Periodic operating reports & related correspondence
- 8307260324 Monthly operating rept for June 1983.W/830715 ltr.
  RICHARDSON.J.D., DALE.L.F. Mississippi Power & Light Co. 83/07/14.
  DEYQUNG.R.C. Director's Office, Office of Inspection and
  Enforcement. 2pp. 19726:306. 24X Fiche:30-416.83/07/14.8307260324.
- 5. Reportable occurrences. LERs & related correspondence
- 8307290284 Forward AEOD technical review rept. "Turbine Trip Bypass Delay." No further evaluation necessary.

  8ALAH.B. Reactor Operations Analysis Branch. 83/06/17.

  8EVFRIT.K.V. Reactor Operations Analysis Branch. 1p.

  24X Fiche: 50-416.83/06/17.8307290284. 19824: 322
- --8307290287 "Turbine Trip Bypass Delay." AEOD technical review rept. SALAH. 9. Reactor Operations Analysis Branch. 83/06/17. 2pp. 17826: 323. 24X Fiche: 50-416.83/06/17.8307290284.
- G307120275 RO B3-047/0; on G30508 & ii, fire protection halon sys for two control room back panels failed surveillances. Caused by inability to meet tolerance specified for full charge pressure. Surveillance procedure revised.

  MCGAUGHY. J. F. Mississippi Power & Light Co. B3/06/22.

  G'REILLY. J. P. Region 2, Office of Director. 2pp. 17423:361. 24
  Fiche: 50-416.83/06/22,8307120275. 19423:361 24X
- 8307120509 LER 83-069/03L-0: on B30323, during attempt to reenergize Div II motor operated valves, shutdown cooling mode of RHR sys & reactor water cleanup sys isolated. Caused by failure to install power fuses. Fuses installed. W/830622 ltr. ROHRER.M. V., MCOAUGHY, J. P. Mississippi Power & Light Co. 83/06/22. 0'REILLY, J. P. Region 2, Defice of Director. 3pp. 19433:244. 24X Fiche: 50-416,83/06/22,8307120509.
- 8307120109 LER 83-070/03L-0:on 830525, reactor water cleanup sys-isolated when standby liquid control pump B breaker closed. Caused by personnal error. Isolation signal reset. W/830624 ltr. ROHRER,M.V., MCGAUGHY,J.P. Mississippi Power & Light Co. B3/ O'REILLY,J.P. Region 2, Office of Director. 3pp. 19423:062. Fiche:50-414:83/06/24:8307120109.
- B307120473 RD B3-049/0: on B30526, halon buttle 2 in panel P936 discharged until empty. Hourly fire watch established pending bottle replacement. Limiting condition for operation to be maintained. Next rept will be submitted by B30731.

  MCGAUGHY, J. P. Mississippi Power & Light Co. B3/06/24.

  G'REILLY, J. P. Region 2. Office of Director. 2pp. 17425:052. 24X Fiche: 50-416.83/06/24, 8307120473.

- 107120526 RO 83-050/0: on 830519, floor penetration CE-376 in control hidg upper cable room opened to rework cable tray hanger. Fire watch established until penetration sealed on 830603. Seven-day limiting condition for operation exceeded. HCGAUGHV. J. P. Mississippi Power & Light Co. 83/06/24. D'REILLY, J. P. Region 2, Office of Director. Ip. 19433: 280. 24X Fiche: 50-416, 83/06/24, 8307120526.
- 07120459 Updated RO 83-027/1: on 830321, during seismic monitoring sysfunctional test, operation of chart recorders & spectrum analyses unacceptable. Caused by faulty circuit card. Card replaced. Sys restored on 830519.

  MCGAUGHY, J. P. Mississippi Power & Light Co. 83/06/27.

  O'REILLY, J. P. Region 2, Office of Director. 2pp. 19425:357. 24X Fiche: 50-416, 83/06/27, 8307120459.
- 07120525 RD 83-052/0: on 830523. Listed fire rated penetrations opened to implement design change packages. Hourly fire watches established & will be maintained until penetrations resealed by 830801.
  100AUGHY.J.P. Hississippi Power & Light Co. 83/06/27.
  17REILLY.J.P. Region 2, Office of Director. 2pp. 19433:278. 24X
- 07120392 LER 83-071/03L-0: an 830607.RHR shutdown cooling mode solated when valve E12-F009 closed.Caused by blown fuse. Tuse replaced.H/830627 ltr. LACKU.D. MCGAUGHY.J.P. Mississippi Pawer & Light Co. 83/06/27. \*REILLY.J.P. Region 2: Office of Birector. 2pp. 19433:082. a iche:50-416.83/06/27.8307120592.
- 7120102 LER 83-072/01T-0: on 830613 operations shift supervisor iscovered some continuous fire watches not performed on 30614.Causad by personnel error.Personnel reinstructed not o pull fire watch w/o approval W/830627 ltr.
  YRD.R., MCGAUGHY, J. P. Mississippi Power & Light Co. 83/06/29.
  'REILLY, J. P. Region 2. Office of Director. 3pp. 19423:025. 24x iche: 50-416,83/06/29,8307120102.
- 7120433 Final deficiency rept for Unit 1 & interim deficiency rept or Unit 2 re incorrect wipe setting on normally closed ontacts converted from normally open contacts on MFA slays. Also reportable under Part 21 for Unit 1.

  19406HY, J. P. Mississippi Power & Light Co. 83/07/01.

  19418 REILLY, J. P. Region 2, Office of Director. 4pp. 19425: 240. 24x iche: 50-416, 83/07/01, 83/07/20133.
- '120452 Final deficiency rept for Unit I & interim deficiency rept ir Unit 2 re PRD-82/14 concerning sheared bolts on diesel nerator rear crankcase cover. Initially reported on 820322. it I bolts adequate. Also reported per Part 21. GAUGHY, J. P. Mississippi Power & Light Co. 83/07/05. REILLY, J. P. Region 2, Office of Director. 6pp. 17425: 349. 24X che: 50-416,83/07/05,8307120452.
- 150239 Final Deificiency Rept PRD-82-38 re Nelson stud failures on badded plates. Initially reported on 821221. Condition not portable per Part 21 for Unit 2 Failure unique to Type plate. Helds will be redesigned.
  GAUCHY.J.P. Mississippi Pawer & Light Co. 83/07/05.
  REILLY.J.P. Region 2, Office of Director. App. 19531:097. 24x che: 50-416.83/07/05.8307150239.

- 20296 LER 83-074/03L-0: on 830506, Div 1 bus breaker, ITE Tupe 350, tripped during LPCS pump startup for monthly veillance. Cause not determined during maint estigation. W/830706 ltr. D.R., MCOAUGHY, J.P. Mississippi Power & Light Co. 83/07/06 EILLY, J.P. Region 2, Office of Director. 3pp. 19683:229. he: 50-416,83/07/06,8307220276.
- 50092 Final Deficiency Rept PRD-B1/44 re valves & actuators not under QA program. Initially reported on B11029, Seals, ricants & coating on pins & rollers upgraded. Corrective ion completed. Item not reportable per 100FR50, 55(e). AUGHY, J. P. Hissistippi Power & Light Co. B3/07/08. EILLY, J. P. Region 2: Office of Director. 5pp. 19536:113. 249 he: 50-416, 83/07/08, 8307150092.
- 50113 LER 83-076/03L-0: on 830610, two of four channels for tainment & drywell ventilation exhaust radiation monitor led monthly functional surveillance & declared perable. Cause under investigation M/830708 ltr. SER.M.V., MCGAUGHY, J.P. Mississippi Power & Light Co. 83/07/08. EILLY, J.P. Region 2, Office of Director. 3pp. 19536:215. 24% section 83/07/08, 8307150113.

- 8307i30144 Updated RO 83-023/1: on 830312, two smoke detectors in standby gas treatment filter train room (Zone 2-17) covered while conducting welding activities. Fire watches established.

  Detectors should be operable by 830701.

  MCGAUGHY. J. P. Mississippi Power & Light Co. 83/07/08.

  O'REILLY. J. P. Region 2, Office of Director. 2pp. 19535:231. 24X

  Fiche: 50-416, 83/07/08, 8307150144.
- 8307150274 Updated RO B3-014/1:on 830301, fire-rated penetration TE-148 (elevation 113 ft. turbine bldg) opened to install raceway, per design change package. Hourly fire watch established. Penetration not sealed within 7-day time limit. MCGAUGHY. J. P. Mississippi Power & Light Co. 83/07/08. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19538:107. 24X Fiche: 50-414, 83/07/08, 8307130274.
- 8307220482 RD 83-051/0: on B30526, PQCC Halon fire protection sys removed from syc to correct differences between design documents & as-built configuration. All hardware mods completed. Limited condition of operation exceeded 14-day time limit. MCGAUGHY, J. P. Mississippi Power & Light Co. B3/07/08. 0'RETILLY, J. P. Region 2, Office of Director. Ip. 17685:097. 24X Fiche: 50-416,83/07/08,8307220482.
- B307250164 Updated LER B2-106/01X-2: on B21104, discovered that action statement entered per Tech Spec 3.7.7 on B20730 due to incomplete installation of fire-rated barriers on safety-related cables & required rapt not filed W/B30712 ltr. ROHRER.M. V. MCGAUGHY, J. P. Mississippi Power & Light Co. B3/07/12 O'REILLY, J. P. Region 2, Office of Director, 4pp. 19706: 110, 24X Fiche: 50-416, 83/07/12, 8307250164.
- 8307290193 Upfate 2 to LER 82-172/99X-2:on 821210, penetration AE154C in auxiliary bldg opened. Caused by planned maint activity. Hourly fire watch established. Penetration to be resealed by 830910 M/830712 ltr. RORRER.M. V. MCQAUGHY.J.P. Mississippi Power & Light Co. 83/07/12, 0'REILLY, J. P. Region 2, Office of Director. 2pp. 17705:348. 24X Fiche: 50-416,83/07/12,8307250193.
- B307250289 Updated LER 82-060/01X-2: on 820910, during image areas containing safety-related cable in auxiliary bldg identified w/no smoke detectors. Caused by omission in original plant design. W/830712 ltr.
  ROWRER: M.V. MOGAUGHY, J. P. Mississippi Power & Light Co. 83/07/12.
  O'REILLY, J. P. Region 2: Office of Director. 3pp. 19705: 275. 24x Fiche: 30-416, 83/07/12, 8307250289.
- 8307250473 Updated LER 83-053/97X-1: on 830201, two electrical penetrations (AE138C & CE-7E) opened to allow performance of planned maint activity, Caused by conduit routing, Work to be completed by 830830, W/830712 ltr.
  ROHRER, M. V., MCGAUGHY, J. P. Mississippi Power & Light Co. 83/07/12. 0'REILLY, J. P. Region 2, Office of Director. 3pp. 19701:297. 24X Fiche: 50-416, 83/07/12, 8307250473.
- B307260464 LER B3-075/03L-0: on B30623, design deficiency noted in standby syc water sys following makeup evolution to standby syc water tower basins. Caused by design error. Water level raised & design change request submitted W/B30718 Itr. ROHRER.M.V. MCGAUGHY, J.P. Mississippi Power & Light Co. B3/07/18. O'REILLY, J.P. Region 2. Office of Director. 3pp. 19733:347. 24X Fiche: 50-416, B3/07/18, B307260464.
- 8307290128 LER 83-077/03L~D; on 830622; while performing control room standby fresh air Unit A monthly surveillance, unit heater failed to operate, Caused by malfunctioning control relay. Relay replaced. BYRD, R. . MCGAUGHY, J. P. Mississippi Pawer & Light Co. 83/07/18. O'REBLLY, J. P. Region 2, Office of Director. 2pp. 19822:151. 24X Fiche: 50-416, 83/07/18, 8307290128.
- B30729023B Updated LER 83-070/03L-1:on 830525, reactor water cleanup system isolated when stansby liquid control pump breaker B closed. Gaused by procedural inadequacy. Standby liquid control operating instruction revised. W/83071B ltr. ROHRER, M. V. MCGAUGHY, J. P. Mississippi Power & Light Co. 83/07/18. B'REILLY, J. P. Region 2, Office of Director. 4pp. 19822:031. 24x Fiche: 50-416.83/07/18.830729023B.
- 8307250335 Part 21 rept re potential defect in high pressure fuel injection line of DSR or DSRV standby diesel generator. Removal of random sample of lines to be internally borescope inspected recommended. BOYER, R.E. Transamerica Delaval, Inc. 83/07/20. Director's Office, Office of Inspection and Enforcement. 2pp. 19703:011. 24X Fiche: 50-000, 83/07/20, 8307250335.

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

#### A. Application/construction stage documents & correspondence

- 8307140367 Concurs w/interim interpretation of Eech Specs re operability of source range monitor. Interpretation should be corrected when permanent change to Tech Specs requested & accepted. LEWIS R. C. Division of Project & Resident Programs. 83/01/13. STAMPLEY.N.L. Mississippi Pawer & Light Co. 1p. 19523:327. 24% Fiche: 30-416,83/01/13,8307140367.
- B306270395 Generic Ltr B3-24 to all BWR applicants for CL & holders of CLs for Grand Gulf-LaBalle & Susquehanna re TMI Task Action Plan Item I.G.i, "Special Low Power Testing & Training & Recommendations for BWRs: " Svc list encl.
  EISENNUT.D. G. Division of Licensing. B3/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000,83/06/29, 8306270395.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D.G. Division of Licensing. 83/07/09. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 8vc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669: 254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- #307080169 Generic Ltr #3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATW8 events. Svc list encl. EISENHUT.D.G. Division of Licensing. #33/07/08. Consolidated Edison Co. of New York. Inc. 3Bpp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307180247 Forwards add1 info to support requests for changes to Tech Specs, per 830630 meeting w/NRC.W/14 oversize drawings. Aperture cards are available in PDR.

  DALE, L.F. Mississippi Power & Light Co. 83/07/08. DENYON, H. R.
  Office of Nuclear Reactor Regulation. Director. 30pp. 19548: 147.
  24X Fiche: 50-416,83/07/08,8307180247.

### E. NRC Safety Evaluation Report (BER), supply & correspondence

- 8307220368 Provides formal documentation of analyses performed per SER Section 6.2.8 to determine min design thickness of main steam line & feedwater line flued heads. Info re design ability to maintain svc metal temp also encl.

  DALE.L.F. Mississippi Power & Light Co. 83/07/20. DENTON.H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 19675:234. 24X Fiche: 50-416, 83/07/20, 8307220368.
- F. Security, medical, emergency & fire protection plans
- 8307140040 Discusses 830128 brinfing in Jackson, MS re util drug & alcohol abuse program.

  O'REILLY, J. P. Region 2, Office of Director. 83/02/03.

  STAMPLEY, N. L. Mississippi Power & Light Co. ip. 19514:219. 24X

  Fiche: 50-416.83/02/03,8307140040.
- 8306140204 Requests review of iOCFR30.54(p) change to physical security plan. Rev 7. Change involved access authorization program.

  870HR. J. P. Division of Emergency Preparedness (Pre 830103).

  83/05/03. MIRAQIIA,F. J. Standardization & Special Projects Branch.

  1p. 18832: 261. 24X Fiche: 50-416.83/05/03.8306140204.
- 8307010081 Forwards Rev 8 replacement pages to physical security plan. Pages withheld (ref 10CFR2.790).

  DALE, L. F. Mississippi Power & Light Ca. 83/06/10. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19124: 340. 24X Fiche: 50-416, 83/06/10, 8307010081.
- 8307140093 Forwards summary of 830602 meeting in Region II ofc re proposed physical security plan mods at facility.List of attendees also encl. LEHIS.R.C. Division of Project & Resident Programs. 83/07/01. RICHARD.J.B. Mississippi Power & Light Co. 4pp. 19514:086. 24X Fiche: 50-416,83/07/01,8307140093.

B3070B0447 Nutifies that certain changes in B30315 Rev 7 to physical security plan decrease effectiveness of plan & are inconsistent w/10CFR50. 34. Previously approved plan will be implemented. Encl withheld (ref 10CFR73. 21).
BCHMENGER.A. Licensing Branch 2. B3/07/05. MCGAUGHY.J. P. Mississippi Power & Light Co. 1p. 19346:139. 24X
Fiche: 50-416.83/07/05.8307080447.

#### I. Financial information

- 8307060101 Forwards Annual Financial Repts & certified financial statements for 1982. DALE-L.F. Mississippi Power & Light Co. 83/06/30. DENTON-H.R. Office of Nuclear Reactor Regulation. Director. 13pp. 19237:172. 24X Fiche: 50-416, 83/06/30, 8307060101.
- --8307060110 Annual Financial Rept 1982. \* Bouth Mississippi Electric Power Association. 63/06/30. 29pp. 19237: 185. 24X Fiche: 50-416, 83/06/30, 8307060101.
- --8307060113 Annual Financial Rept 1982. \* Mississippi Power & Light Co. 83/06/30, 27pp. 19237:212. 24X Fiche: 50-414,83/06/30,8307040101.

#### M. Antitrust correspondence

- 8307210216 Forwards interconnection agreement between util & FERC to resolve violations of antitrust license conditions.
  Resolutions to other issues also provided.
  MCDIARMID.R.C. Spiegel & McDiarmid. 83/07/19. DENTON.H.R. Dffice of Nuclear Reactor Regulation, Director. 145pp. 19667:101. 24X Fiche: 30-416, 83/07/19, 8307210216.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307140230 Responds to IE Bulletin B2-01.Rev 1 to bulletin & Suppl 1 to Rev 1 to bulletin re Associated Piping & Engineering alteration of piping subassembly weld radiographs. No alterations of genetrameter T holes indicated.

  MCQAUGHY. J.P. Mississippi Power & Light Co. B3/06/20.

  0'REILLY. J.P. Region 2. Office of Director. 3pp. 19523:118. 24X Fiche: 50-416, 83/06/20, 8307140230.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade
  Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering
  Response (Post 830103), 83/07/11. Consolidated Edison Co. of New
  York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & [-131 in Excess of NRC Limits," Svc list encl. TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.

# S. Reportable occurrences. LERs & related correspondence

- B307120433 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re incorrect wipe setting on normally closed contacts converted from normally open contacts on MFA relays. Also reportable under Part 21 for Unit 1. MCGAUGHY, J. P. Mississippi Power & Light Co. 83/07/01. 0 /REILLY, J. P. Region 2, Office of Director. 4pp. 17425:240, 24X Fiche: 50-416,83/07/01,8307120433.
- 8307120452 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re PRD-82/14 concerning sheared bolts on diesel generator rear crankcase cover. Initially reported on 820322. Unit i bolts adequate. Also reported per Part 21. MCGAUGHY, J. P. Mississippi Power & Light Co. 83/07/05. 0 REILLY, J. P. Region 2. Defice of Director. App. 19425:349. 24X Fiche: 50-416:83/07/05,8307120452.
- 8307150237 Final Deificiency Rept PRD-82-38 re Nelson stud failures on ambedded plates. Initially reported on 82122i. Condition not reportable per Part 21 for Unit 2.Failure unique to Type 86 plate, Welds will be redesigned. MCGAUGHY. J. P. Mississippi Pawer & Light Co. 83/07/05, 0'RETLLY, J. P. Region 2. Office of Director. 6pp. 19531:097. 24X Fiche: 50-416, 83/07/05, 8307150239.

- 8307150367 Final/interim Deficiency Rept PRD-82/14 for Units 1/2, respectively re sheared bolts on rear crankcase cover of Delaval diesel generators. Unit 1 bolts not defective. Unit 2 rept due on 850130. Also reportable per Part 21. MCOAUGHY. J. P. Mississippi Power & Light Co. 83/07/05. 07.REILLY. J. P. Region 2. Office of Director. 6pp. 19539: 084. 24% Fiche: 50-416, 83/07/05, 8307150369.
- B307130092 Final Deficiency Rept PRD-B1/44 re valves & actuators not afg under QA program. Initially reported on B11029. Seals, lubricants & coating on pins & rollers upgraded Corrective action completed. Item not reportable per 100FR50. 55(e). MCOAUGHY. J. P. Mississippi Power & Light Co. B3/07/08. 0'REILLY. J. P. Region 2. Office of Director. 5pp. 19536:113. 24X Fiche: 50-416, B3/07/08, B307150092.
- B307250335 Part 21 rept re potential defect in high pressure fuel injection line of DSR or DSRV standby diesel generator.

  Removal of random sample of lines to be internally borescope inspected recommended.

  BDYER.R.E. Transamerica Delaval, Inc. 83/07/20. Director's Office. Office of Inspection and Enforcement. 2pp. 19703:011. 24X Fiche: 50-000, 83/07/20, 8307250335.
- OOCKET 90-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

  A. Application/construction stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Byc list encl.
  EISENMUT.D.9. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03, 830660070.
- 8307060494 Notification of B30720 & 21 meetings w/util at site to discuss info for environ review Meeting & site tour agenda encl.

  DOCLITILE, E. L. Licensing Branch 1. 83/06/24, YOUNGBLOOD, B. J. Licensing Branch 1. 5pp. 17297:110. 24X Fiche: 50-423, 83/06/24, 8307080494.
- 8307140519 Advises of 830720-21 site visit as part of review process for preparing environ statement re OL application. YQUNGBLODE, J. Licansing Branch 1. 83/06/27. COUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 19527:350. 24x Fiche: 50-423.83/06/27.8307140519.
- B307140522 Forwards Procedures & Sys Review Branch request for additinfo re OL application. Response within 90 days requested.
  YOUNGBLOOD, B. J. Licensing Branch 1. B3/06/29. COUNSIL.W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 17pp 19527: 322. 24X Fiche: 50-423, 83/06/29, 8307140522.
- B3070B0319 Requests amend to summary of B30512 DL application docksting meeting to clarify plans re-submittal & presentation of probabilistic safety study.

  COUNSIL.M.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.M.Q. Northeast Utilities. B3/06/30. YOUNGBLOOD,B.J. Licensing Branch i. Ip. 19350:150. 24X Fiche: 50-423, B3/06/30, B3070B0319.
- 8307140174 Forwards "Const Project Evaluation of Millstone Station 3 (Observations)" & "Const Project Evaluation of Millstone Station 3." Repts prepared using INPO performance objectives & criteria.

  BRUNNER, E. J. Division of Project & Resident Programs. 83/06/30. TAYLOR.J.M. Division of Reactor Programs (Pre 830103); ip. 19322:091. 24X Fiche: 50-423.83/06/30.8307140174.
- --8307140179 "Const Project Evaluation of Milistone Station 3 (Observations)."

  # Management Analysis Co. 82/12/21. 34pp. 19522:095. 24X Fiche: 50-423.83/06/30.8307140174.
- --8307140183 "Const Project Evaluation of Millstone Station 3." \* Management Analysis Co. 82/12/21. 166pp. 19522:125. 24X Fiche: 30-423, 83/06/30.8307140174.
- 8306270397 Ceneric Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Syc list encl. EISEMHUT. D.C. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 30-000, 83/07/05, 8306270397.

- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list and. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Ca. of New York, Inc. 16pp. 19669:254. 24% fiche: 50-000, 83/07/06, 8307060329.
- 8307140271 Responds to 830503 request for add1 meteorological info.Data tape provided.Data format description encl.
  COUNBIL.W. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W. 9. SEARS.C.F. Northeast Utilities. 83/07/07. YOUNGBLOOD.B.U. Licensing Branch 1. 4pp. 19520:359. 24X Fiche: 50-423,83/07/07,9307140271.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. 8vc list encl. EISENHUT.D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 30-000, 83/07/08, 8307080169.
- 8307240197 Responds to NRC 830503 select requests for add1 info.Final revised FSAR pages will be forwarded 830801. Amend 3 to FSAR will be submitted by 830901.

  COUNSIL.W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W. O. Northeast Utilities. B3/07/22.

  YOUNGBLOOD, B. J. Licensing Branch 1. 262pp. 19728:001. 24X Fiche: 50-423,83/07/22,8307260197.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8307150156 Requests participation in NRC 830720-21 site visit to review process for preparing EIS re facility operation. Input identifying any specific item of environ interest solicited. YOUNGBLOUD, B. J. Licensing Branch 1. 83/06/27. Commerce: Dept. of: Natl. Oceanographic & Atmospheric Administration. 3pp. 19574:356. 24X Fiche: 50-423, 83/06/29, 8307150156.
- F. Security, medical, emergency & fire protection plans
- 8307140271 Responds to 830503 request for add1 meteorological info.Data tape provided.Data format description encl. COUNSIL.W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W. Q. SEARS, C.F. Northeast Utilities. 83/07/07. YOUNGBLOOD, B. J. Licensing Branch 1. 4pp. 17520:359, 24X Fiche: 50-423,83/07/07.8307140271.
- H. General correspondence
- 8307270110 Forwards 830721 ltr to State of CT Legislature.Energy & Public Utils Committee.Hearings should be held locally. Plant cost is prohibitive & future problem exists re final disposition of waste.

  SMITH.M.P. Affiliation Unknown. 83/07/21. NRC No Detailed Affiliation Given. 4pp. 19749:347. 24X Fiche:50-423,83/07/21, 8307270110.
- G. Inspection reports, IE Bulletins & correspondence
- 8307010010 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No assemblies mfg by Bunker-Ramo Co in svc or planned to be placed in svc at plant. COUNSIL.W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W.G. Northeast Utilities. 63/06/17. MURLEY.T.E. Region 1. Office of Director. 2pp. 19169:206. 24X Fiche: 30-423, 83/06/17, 8307010010.
- 8307040182 Forwards "Overpressure Protection Rept" & Rev 1 to preservice insp plan.per 830331 commitment to provide add1 info. in response to NRC acceptance review of OL application. COUNSIL.W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities. COUNBIL.W. O. Northeast Utilities. 83706/30. YOUNGELOOP, B. J. Licensing Branch 1. 3pp. 17232:248. 24X Fiche: 50-423, 83/06/30, 8307060182.
- --8307060183 "Overpressure Protection Rept."
  FORCHT.K. A. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/31. 10pp. 19252:251. 24X
  Fiche: 50-423, 83/06/30, 8307060182.
- --B307060185 Rev 1 to PSI 2.01 "Preservice Insp Plan." Oversize drawings and.
  PERKINS, O. R., BCHMIDT, R. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/06/15, 377pp. 19252:261. 24X
  Fiche: 50-423,83/06/30,8307060182.

- 8307210033 Forwards IE Insp Rept 50-423/83-08 on 830406-09 No
  - noncompliance noted.

    MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/0:
    COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast
    Utilities). 2pp. 19668:336. 24X Fiche:50~423,83/07/05,8307210033. 83/07/05.
- -8307210036 IE Insp Rept 50-423/83-D8 on 830606-09 No moncompliance noted Major areas inspected safety-related piping, containment liner repair, svc water pump castings, welder qualification & weld insp, including radiography GRAY,E.H., DURR, J.P. Region i, Deffice of Director, KG, J.D. Korea, Democratic Peoples Republic (North Korea), 83/06/23, Sp; 17668:338, 24X Fiche: 50-423, 83/07/05,8307210033. . KO, J. D. 83/06/23. 5pp.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem," Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000. B3/07/11, B306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN/E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19543:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Ercess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- 5. Reportable occurrences. LERs & related correspondence
- 8306200396 Final Significant Deficiency Rept SD-25 re failure of pinion gear shear keys in Limitorque Mode SB-0 motor operated valves. Initially reported on 820703. Hestinghouse will replace pinion keys on all SB-0 series motor operators. COUNSIL-M.9. Northeast Nuclear Energy Co. (aubs. of Northeast Utilities). COUNSIL-M.0. Northeast Utilities. B3/06/10. MURLEY, T. E. Region 1. Office of Director. 2pp. 18719: 217. 24X Fiche: 50-423, 83/06/10, 8306200376.
- 8307010148 Interim deficiency rept re cracks in containment crane wall near embedments. Initially reported on 821207. Evaluation incomplete. Next rept due by 830901.

  GDUNSIL.W.Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). GDUNSIL.W.Q. Northeast Utilities. 83/06/16.

  MCRLEV.T.E. Region 1. Office of Director. 1p. 19175:337. 24X

  Fiche: 50-423.83/06/16.8307010148.
- B307010133 Interim deficiency rept re containment liner stud anchor spacing exceeding ASME Code, Section III spec. Initially reported on B30519. Engineering evaluation being conducted. Next rept to be filed by 631201.

  COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W.O. Northeast Utilities. B3/06/17.

  MURLEY, T. E. Region 1. Diffice of Director. 2pp. 19169: 274. 24X Ficha: 50-423, 83/06/17, 8307010133.
- B307050201 PNB-I-B3-017: on B30428. S&M craft worker discovered 20 severed cables in unfinished control bldg between control bldg & intake structure. Cause under investigation. MCKEOMN, ODDY, MARTIN, T. Region I. Office of Director. B3/06/29. 1p. 19199: 220. 24X Fiche: 50-423, 83/06/29, 8307050201.
- B307110370 Final deficiency rept re potential problems w/loop power supply card heat sinks of Westinghouse 7300 process protection sys (BD-40). Initially reported on 830602. Concurs w/Westinghouse hardware changes. Also reportable per Part 21. COUNBIL W. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNBIL W. 9. Northeast Utilities. 83/07/01. MURLEY, T. E. Region i. Office of Director. 3pp. 17380:284. 24% Fiche: 50-423.83/07/01,8307110370.
- 8307120588 Final Bignificant Deficiency Rept 8D-35 re design & const of pull-apart terminal blocks in Gould motor control ctrs. Initially reported on B30428. Brackets developed to firmly secure blocks.

  COUNSIL W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL W. O. Northeast Utilities. B3/07/01. MURLEY, T. E. Region 1. Office of Director. 2pp. 19432:142. 24X Fiche: 50-423, 83/07/01.8307120588.
- 8307150208 Final Significant Deficiency Rept SD-39 re potential problems w/temp channel test (NYC) cand relays. Initially reported on 830602 Relay replaced prior to operation. Also reported per Part 21 by Westinghouse.

  COUNSIL, W. G., SEARS, C. F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G., Northeast Utilities, 83/07/06. MURLEY, T.E. Region in Office of Director. 4pp. 19530: 221. 24X Fiche: 50-423, 83/07/06, 8307150208.

- B307150240 Interim Significant Deficiency Rept SD-34 re interference & possible binding of ITT Grinnell mechanical snubbers.
  Initially reported on B30304 Extension for submittal of final rept until B30801 requested.
  COUNSIL.W.G., SEARS.C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W.G. Northeast Utilities. B3/07/07. MURLEY.T.E. Region i. Office of Director. 1p. 19538:349, 24X Fiche: 90-423, 83/07/07, 8307150240.
- 8307140241 Interim Deficiency Rept SD-41 repotential failure of Gould Type HE 4 breakers to close Initially reported on 830608. Cause not yet determined Discussions unvendor initiated. COUNSILM G. SEARS. C.F. Northeast Utilities. 83/07/08, MURLEY. T.E. Region 1. Defice of Director. 1p. 19523:063. 24X Fiche: 30-423.83/07/08, 8307140241.
- DOCKET 50-424 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 1 A. Application/construction stage documents & correspondence
- B307140234 Comments on B30504 ltr re proposed changes to existing field change control program to provide further clarification & understanding of specific areas. Proposed field change control program mod acceptable.

  LEMIS.R.C. Division of Project & Resident Programs. 63/06/02.

  KELLY.R.J. Georgia Power Co. 2pp. 19523:038. 24X

  Fiche: 50-424.63/06/02.6307140254.
- B306060070 Generic Ltr B3-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Mestinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT.D.G. Division of Licensing. B3/06//03. Yankee Atomic Electric Co. 10pp. 17563:116. 24X Fiche: 50-000, 83/06/03, B306060070.
- B307010166 Forwards application for OL, for Vogtle Electric Generating Plant, Units 1 & 2, FOBTER, D. D. Georgia Power Co. B3/06/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19570: DOI: 24X Fiche: 50-424, B3/06/22, B307010166.
- --8307010174 Application for QL, for Vogtle Electric Generating Plant, Units 1 & 2. FOSTER, D. G. Georgia Power Co. 83/06/22. 22pp. 19370:003. 24X Fiche: 50-424,83/06/22,8307010166.
- B306270397 Peneric Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390;317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. O. Division of Licensing. B3/07/06. Consolidation Co. of New York, Inc. 16pp. 19667:254. 24X Fiche: 50-000, 83/07/06, B307060329. Consolidated
- B307120412 Provides summary of events surrounding discovery of prehistoric whale approx 45 to 50 million yes old during const activity. Excavations of fossil remains completed B30610. Info will be included in environ rept OL stage. FOSTER, D. D. Georgia Power Co. B3/07/07. ADENSAM, E. Q. Licensing Branch 4. 2pp. 17425: 090. 24X Fiche: 50-424, B3/07/07, B307120412.
- 8307120513 Discusses possible existence of shortnose sturgeon larvae in Savannah River. Sampling programs conducted by util show no evidence of endangered species. Environ rept will provide addl info. FOSTER.D.O. Georgia Power Co. 83/07/07. ADENSAM.E.Q. Licensing Branch 4. 2pp. 19433:216. 24X Fiche:50-424.83/07/07.8307120913.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. ETESHMUT. D. G. Division of Licensing. 83/07708. Consolidated Edison Ca. of New York, Inc. 38pp. 17669:269. 24x Fiche: 50-000, 83/07708, 8307080169.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307010166 Forwards FSAR, application for OL (filed in PDR Category A) & advolvios rorwards Park, application for UL (filed in PDR Catego" geologic & soils borings logs, for Voytle Electric Generating Plant, Units 1 & 2. Environ rept. emergency response plan & antitrust info due by 830701.
  FOSTER, D.O. Georgia Power Co. 83/06/22. DENTON, H.R. Office Nuclear Reactor Regulation, Director. 2pp. 19570:001. 24X Fiche: 50-424. 83/06/22. 8307010166.

- ~-8307010183 Vogtle Electric Generating Plant,Units 1 & 2.FBAR,Chapters
  - 1-18. # Georgia Power Co. 83/06/22. 7,201pp. 19597:001. 24X Fiche: 50-424,83/06/22,8307010166.
- --8307010189 Chapter 1 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Introduction & General Description of Plant." \* Georgia Power Co. 83/06/22, 450pp. 19597:032, 24X Fiche: 50-424, 83/06/22, 8307010166.
- --8307010191 Chapter 2 to Vogtle Electric Generating Plant.Units 1 & 2, FSAR, "Site Characteristics."

  \* Georgia Power Co. 83/06/22, 1,002pp. 19598:129. 24X
  Fiche: 50-424,83/06/22,8307010166.
- ---8307010194 App 2A to Vogtle Electric Generating Plant,Units 1 & 2,FSAR,
  "Population Distribution Methodology."

  \* Georgia Power Co. 83/06/22. 5pp. 19601:051. 24X
  Fiche:50-424,83/06/22,8307010166.
- --8307010197 App 28 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Geology,"

  \* Georgia Power Co. 83/06/22, 62pp. 17601:056. 24X
  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010204 Chapter 3 to Vogtle Electric Generating Plant, Units 1 & 2, FBAR, "Design of Structures, Components, Equipment & Sys." # Georgia Power Co. 83/06/22, 1,444pp. 19601:117. 24X Fiche: 50-424,83/06/22,8307010166.
- --8307010205 App 3A to Vogtle Electric Generating Plant, Units 1 & 2. F8AR. "Conformance W/Reg Guides." # Georgia Power Co. B3/06/22. 1p. 17605:121. 24X Fiche: 50-424, 83/06/22, 8307010166.
- --8307010209 App 38 to Vogtle Electric Generating Plant, Units 1 & 2, F5AR, "Computer Programs Used for Structural, Seismic & Geotechnical Analyses."

  \* Georgia Power Co. 83/06/22, 11pp. 19605:122, 24X
  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010210 Chapter II to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Radwaste Mgt."

  \* Georgia Power Co. 83/06/22, 336pp. 17621:006, 24X
  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010213 App 17A to Vogtle Electric Generating Plant, Units 1 & 2, FBAR, "Bechtel Guality Program."

  \* Bechtel Corp. 83/06/22, 69pp. 19626:035, 24X
  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010214 App 3C to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Design of Structures for Tornado Missile Impact." # Georgia Power Co. 83/06/22, 8pp. 19605:133. 24X Fiche: 50-424,83/06/22,8307010166.
- --8307010215 App 15A to Vogtle Electric Generating Plant, Units 1 & 2, F5AR, "Accident Analysis Radiological Consequences Evaluation Models & Parameters."

  4 Georgia Power Co. 83/06/22, 20pp. 19625:243. 24X
  Fiche: 50-424,83/06/22,8307010166.
- ---5307010216 Chapter 12 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Radiation Protection."

  # Georgia Power Co. B3/06/22, 481pp. 17621:342, 24X
  Fiche: 50-424, B3/06/22, B307010166.
- --8307010217 App 178 to Vogtle Electric Generating Plant, Units 1 % 2, FBAR. "Westinghouse Water Reactor Div 6A Plan."

  \* Westinghouse Electric Corp. 83/06/22. Ip. 19626:113. 24X Fiche: 50-424,83/06/22,8307010166.
- ---B307010219 App 3D to Vogtle Electric Generating Plant.Units 1 & 2. FSAR, "Seismic Response Spectra." \* Georgia Power Co. B3/06/22. 79pp. 19605:141. 24X Fiche: 50-424,83/06/22,8307010166.
- ---B307010220 App 17C to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Southern Co Svcs, Inc, Auditing & Supplier Surveillance Insp. Functions." \* Southern Co. Services, Inc. 83/06/22, 8pp. 19626:114, 24x
- --B307010221 Chapter 13 to Vogtle Electric Generating Plant.Units 1 & 2. FSAR. "Conduct of Operations." # Georgia Power Co. B3/06/22, 50pp. 19623:103. 24X Fiche: 50-424. B3/06/22, B307010166.

- -8307010222 Chapter 16 to Vogtle Electric Generating Plant.Units 1 & 2, FBAR, "Tech Spacs."

  # Georgia Power Co. 83/06/22. 4pp. 19625:263, 24%
  Fiche: 50-424,83/06/22,8307010166.
- -8307010223 Chapter 18 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Human Factors Engineering."

  \* Georgia Power Co. 83/06/22, 63pp. 19626:122. 24X

  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010225 Chapter 14 to Vogtle Electric Generating Plant.Units 1 & 2, FSAR, "Initial Test Program."

   Georgia Power Co. 83/06/22, 177pp. 19623:187. 24X
  Fiche: 50-424,83/06/22,8307010166.
- --8307010226 App 3E to Voytle Electric Generating Plant, Units 1 & 2, FSAR, "Impedance Functions for Layered Medium." # Georgia Power Co. 83/06/22. 1p. 19605:220. 24X Fiche: 50-424,83/06/22,8307010166.
- --8307010227 Chapter 15 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR. "Accident Analyses."

  \* Georgia Power Co. 83/06/22, 597pp. 17624:004. 24X
  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010228 App GF to Vogtle Electric Generating Plant.Units 1 & 2, FSAR, "Hazards Analysis." \* Gaorgía Power Co. 83/06/22, 142pp. 19605:253, 24X Fíche:50-424,83/06/22,8307010166.
- --8307010230 Chapter 9 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Auxiliary Sys."

  \* Georgia Power Co. 83/06/22. 332pp. 19616:269. 24X
  Fiche: 50-424,83/06/22,8307010166.
- --8307010231 Chapter 4 to Vogtle Electric Generating Plant, Units 1 & 2, F5AR. "Reactor." \* Georgia Power Co. 83/06/22. 300pp. 19606:039. 24x Fiche: 50-424, 83/06/22, 8307010166.
- --8307010233 App 9A to Vogtle Electric Generating Plant, Units I & 2. FSAR, "Fire Hazards Analysis."

  \* Georgia Power Co. 83/06/22. 752pp. 19617:241. 24X
  Fiche: 50-424,83/06/22.8307010166.
- --8307010234 Chapter 5 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "RCS & Connected Sus."

  \* Georgia Power Co. 83/06/22, 253pp. 19606:335, 24x
  Fiche:50-424,83/06/22,8307010166.
- --8307010235 App 98 to Vogtle Electric Generating Plant, Units 1 & 2, F5AR. "Comparison of Vogtle Units 1 & 2 W/Requirements of Branch Technical Position CMER 9.5-1."

  \* Georgia Power Co. 83/06/22, 74pp. 19619:273. 24x
  Fiche: 50-424,83/06/22,8307010166.
- --8307010237 Chapter 17 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR. "GA" ### Georgia Power Co. 83/06/22, 128pp. 19625: 267, 24X Fiche: 50-424, 83/06/22, 8307010166.
- --8307010238 Chapter 6 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "ESF." FSAR, "ESF." \* Georgia Power Co. 83/06/22. 1,315pp. 19607:228. 24X Fiche:50-424,83/06/22,8307010166.
- --8307010239 Chapter 10 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Steam & Power Conversion Sys."

  \* Georgia Power Co. 83/06/22, 316pp. 19619;347. 24X
  Fiche: 50-424,83/06/22,8307010166.
- --8307010241 Chapter 7 to Vogtle Electric Generating Flant, Units 1 & 2, FSAR, "Instrumentation & Controls."

  \* Georgia Power Co. 83/06/22. 676pp. 19611:103. 24X
  Ficha: 50-424,83/06/22.8307010166.
- --8307010242 App 10A to Vogtle Electric Generating Plant.Units 1 & 2, FSAR, "Vogtle Auxiliary Feedwater Sys Reliability Analysis." # Georgia Power Co. 83/06/22. 65pp. 19620:303. 24X Fiche:50-424,83/06/22,8307010166.
- -8307010244 Chapter 8 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Electric Power." \* Georgia Power Co. B3/06/22, 210pp. 19613:059, 24X Fiche: 30-424, 83/06/22, 8307010166.

#### Q. Inspection reports, IE Bulletins & correspondence

- B307140177 Forwards IE Insp Repts 50-424/B3-10 & 50-425/83-10 on B30413-0510 No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. B3/06/20 KELLYR.J. Georgia Power Co. 2pp. 19522:089. 24X Fiche:50-424,83/06/20,8307140177.
- --8307140185 IE Insp Repts 50-424/83-10 & 50-425/83-10 on 830413-0510. No noncompliance noted Major areas inspected: primary containment lifting & setting primary done-welding primary coolant pipe, concrete pouring & stored in-place equipment. SANDERS. W. F. Region 2, Office of Director. BROWNLEE.V. L. Division of Project & Resident Programs. B3/06/20. 3pp. 19522:071. 24X Fiche: 50-424, 83/06/20, 8307140177.
- 8307140249 Forwards IE Insp Repts 50~424/83-11 & 50~425/83-11 on 830524-27. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/23. KELLYR J. Georgia Power Co. 2pp. 19523:052. 24X Fiche: 50-424-83/06/23.8307140245.
- --8307140249 lE Insp Repts 50-424/83-11 & 30-425/83-11 on 830524-27. No noncompliance noted Major areas inspected: previous enforcement matters, structural steel & concrete & previously identified inspector followup item.

  HARRIS, J. R., CONLON, T. E. Region 2, Office of Director. 83/06/21, 5pp. 19523:054. 24X Fiche: 50-424, 83/06/23, 8307140245.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid," Svc list encl. JORDAN/E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list enci.
  TAYLOR, J. M. Division of QA, Safeguerds & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.

#### S. Reportable occurrences, LERs & related correspondence

- 8307120358 Final deficiency rept re quality of welds & radiographs mfg by Pullman Power Products. Deficiency nonexistent, Detailed engineering evaluation determined quality of welds sufficient to withstand any potential accident.
  FOSTER.D. D. Georgia Power Co. FOSTER.D. D. Southern Co. Services. Inc. 83706/24, 07REILLY, J.P. Region 2, Office of Director. 1p. 19429:167. 24X Fiche: 50-424, 83/06/24, 8307120358.
- B307110453 Interim deficiency rept re lack of anchor bolt thread engagement for embeds. Initially reported on B20426. Seven embed plates classified void & 75 plates dispositioned useras-is. Followup audits by QA & QC being performed.
  FOSTER.D. D. Georgia Power Co. FOSTER.D. D. Southern Co. Services, Inc. B3/07/01. D/REILLY, J.P. Region 2, Office of Director. 10pp. 19380:112. 24X Fiche: 50-424,83/07/01.8307110453.
- 8307220195 Interim deficiency rept re possible use of defective weld wire for stainless steel carbon steel welds. Initially reported on 830709. Metallungical tests continuing. Next rept will be submitted by 831014.

  CGNKAY.R.E. Georgia Power Co. 83/07/11. D'REILLY, J. P. Region 2. Office of Director. 1p. 19684:093. 24X Fiche: 50-424,83/07/11,8307220195.
- B307220324 Interim deficiency rept re failure in embed plate base metal. Initially reported on B30606. Caused by lamellar tearing due to large shrinkage stresses from heavy welding.

  Next rept will be submitted by B31216.

  CONMAY.R.E. Georgia Power Co. B3/07/11. D'REILLY, J. P. Region 2, Office of Director. 4pp. 19675: 120. 24X Fiche: 50-424, B3/07/11, B307220324.

# V. Operator Examinations

B307140253 Requests submittal of ref matl discussed in B30617 telcon re instructor certification exams scheduled for B30725. Requirements for administration of operator licensing written exams encl. DANCE, H. C. Division of Project & Resident Programs. B3/06/20. BECKHAM. J. T. Georgia Power Co. 3pp. 17523: 040. 24X Fiche: 50-424. B3/06/20. B307140253.

- DOCKET 50-425 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- B307140234 Comments on B30304 itr re proposed changes to existing field change control program to provide further clarification & understanding of specific areas. Proposed field change control program mod acceptable. LEWIS.R.C. Division of Project & Rewident Programs. B3/06/02. WELLY.R.J. Georgia Power Co. 2pp. 19323:038. 24X Fiche: 50-424,83/06/02,8307140234.
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for DLs & holders of CPs for Wastinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03, 830600070.
- B307010166 Forwards application for OL, for Vogtle Electric Generating Plant-Units 1 & 2.
  FOSTER.D.O. Georgia Power Co. 83/06/22. DENTON.H.R. Office of Nuclear Reaction Regulation, Director. 2pp. 19570:001. 24X Fiche: 30-424, 83/06/22, 8307010166.
- --8307010174 Application for OL. for Vogtle Electric Generating Plant, Units 1 & 2. FOSTER, D. O. Georgia Power Co. 83/06/22. 22pp. 19570:003. 24X Fiche: 50-424, 83/06/22, 8307010166.
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Bvc list encl. EISENHUT, D.G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, B3/07/05, B306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list enci.
  EISENHUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York Inc. 16pp. 17669:254. 24x
  Fiche: 50-000,83/07/06,8307060329.
- B307120412 Provides summary of events surrounding discovery of prehistoric whate approx 45 to 50 million yrs old during const activity Excavations of Possil remains completed 830610. Info will be included in environ rept OL stage. FOSTER. D. D. Georgia Power Co. B3/07/07. ADENSAM. E. G. Licensing Branch 4. 2pp. 17425:090. 24X Fiche: 50-424.83/07/07,8307120412.
- B307120513 Discusses possible existence of shortnose sturgeon larvae in Bavannah River. Bampling programs conducted by util show no evidence of endangered species. Environ rept will provide addl info.
  FDSTER. D. D. Georgia Power Co. B3/07/07. ADENSAM. E. O. Licensing Branch 4. 2pp. 19433:216. 24% Fiche: SO-424, B3/07/07, B307120513.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT.D.O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X Fiche: 50-000.83/07/08.8307080169.

#### K. Utility Final Safety Analysis Report (FSAR) & amends

- B307010166 Forwards FSAR, application for OL (filed in PDR Category A) & geologic & soils borings logs, for Vogtle Electric Generating Plant, Units i & 2. Environ rept, emergency response plan & antitrust info due by 830901.
  FOSTER, D. O. Georgia Power Co. 83/06/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19570:001. 24X Fiche: 50-424,83/06/22,8307010166.
- --8307010183 Vogtle Electric Generating Plant, Units 1 & 2, FBAR, Chapters 1-18. \* Georgia Power Co. 83/06/22, 7, 201pp. 19397: 001. 24X Fiche: 30-424, 83/06/22, 8307010166.
- --8307010189 Chapter i to Vogtle Electric Generating Plant,Units 1 & 2, FSAR. "Introduction & General Description of Plant."

  \* Georgia Power Co. 83/06/22, 430pp. 19597:032. 24X
  Fiche: 50-424, 83/06/22, 8307010166,
- --8307010191 Chapter 2 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Site Characteristics." \* Georgia Power Co. 83/06/22. 1,002pp. 19598:129. 24X Fiche: 50-424,83/06/22,8307010166.

- --B307010194 App 2A to Vogtim Electric Generating Plant, Units 1 & 2,FSAR,
  "Population Distribution Methodology."

   Georgia Power Co. B3/06/22. 5pp. 19601:051. 24X
  Fichm: 50-424,83/06/22, B307010166.
- --8307010197 App 2B to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Geology."

  9 Georgia Power Co. 83/06/22, 62pp. 19601; 036. 24X Fiche: 50-424, 83/06/22, 8307010166.
- --8307010204 Chapter 3 to Vogtle Electric Generating Plant, Units 1 & 2. FSAR. "Design of Structures, Components, Equipment & Sys."

   Georgia Power Co. 83/06/22, 1,444pp. 19601:117. 24X Fiche: 50-424,63/06/22,8307010166.
- --B307010205 App 3A to Vogtle Electric Generating Plant, Units 1 & 2, FBAR, "Conformance W/Reg Ouides."

  Georgia Power Co. B3/06/22. ip. 19605:121. 24X
  Fiche: 50-424, 83/06/22. 8307010166.
- --B307010209 App 3B to Vogtle Electric Generating Plant,Units 1 & 2, FBAR. "Computer Programs Used for Structural, Seismic & Geotechnical Analyses."

  \* Georgia Power Co. 83/06/22. lipp. 19605:122. 24X
  Fichs: 30-424,83/06/22,8307010166.
- --8307010210 Chapter 11 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR: "Radurate Mgt."

  \* Georgia Power Co. 83/06/22. 336pp. 19621:006. 24X
  Fiche: 50-424.83/06/22.8307010166.
- --8307010213 App 17A to Vogtle Electric Generating Plant, Units 1 & 2, F8AR, "Bechtel Quality Program."

  \* Bechtel Corp. 83/05/22, 69pp. 19626:035. 24X
  Fiche: 30-424,83/06/22,8307010166.
- --8307010214 App 3C to Vogtle Electric Generating Plant,Units 1 & 2, FBAR. "Design of Structures for Tornado Missile Impact."

  Georgia Power Co. 83/06/22 8pp. 19605:133. 24X Fichs: 50-424,63/06/22.8307010166.
- --8307010215 App 15A to Vogtle Electric Generating Plant, Units 1 & 2, FSAR: "Accident Analysis Radiological Consequences Evaluation Models & Parameters:" \* Georgia Power Co. 83/06/22. 20pp. 19625:243. 24X Fiche: 50-424,83/06/22,8307010166.
- --8307010216 Chapter 12 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Radiation Protection."

   Georgia Power Co. 83/06/22, 481pp. 17621:342. 24X
  Fiche: 50-424,83/06/28,8307010166.
- --8307010217 App 17B to Vogtle Electric Generating Plant,Units 1 & 2, FBAR, "Mestinghouse Water Reactor Div GA Plan."

  \* Mestinghouse Electric Corp. 83/06/22. ip. 19626:113. 24X Fiche: 50-424,63/06/22.8307010166.
- --8307010219 App 3D to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Spismic Response Spectra."

  \* Georgia Power Co. 83/06/22, 79pp. 19605:141. 24X Fiche: 50-424, 83/06/22, 8307010166.
- --8307010220 App 17C to Vugtle Electric Generating Plant.Units 1 & 2. FBAR. "Bouthern Co Sycs, Inc. Auditing & Supplier Surveillance Insp Functions."

  \* Southern Co. Services, Inc. 83/06/22. 8pp. 19626:114. 24X Fiche: 50-424.83/06/22.8307010166.
- --8307010221 Chapter 13 to Vogtle Electric Generating Plant.Units 1 & 2. FSAR. "Conduct of Operations." \* Georgie Power Co. 83/06/22. 50pp. 19623:103. 24X Fiche: 50-424.83/06/22.8307010166.
- --8307010222 Chapter 16 to Vogtle Electric Cenerating Plant, Units 1 & 2, FBAR, "Tech Specs."

  4 Caorgia Power Co. 83/06/22, 4pp. 19625:263. 24X
  Ficha: 50-424,83/06/22,8307010166.
- --8307010223 Chapter 18 to Vogtle Electric Generating Plant, Units 1 & 2, FBAR. "Muman Factors Engineering."

  Georgia Power Co. 83/06/22. 63pp. 19626:122. 24X Fiche: 50-424.83/06/22.8307010166.
- --8307010225 Chapter 14 to Vogtle Electric Cenerating Plant, Units 1 & 2. FSAR. "Initial Test Program."

  \* Georgie Power Co. 83/05/22. 177pp. 19623:187. 24X
  Fiche: 50-424.83/06/22.8307010166.

- --8307010226 App 3E to Voytle Electric Generating Plant, Units 1 & 2, FSAR, "Impedance Functions for Layered Medium." # Georgia Power Co. 83/06/22, 1p. 19605:220. 24% Fiche: 50-424,83/06/22,8307010166.
- ---8307010227 Chapter 15 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Accident Analyses."

  \* Georgia Power Co. 63/06/22, 599pp. 19624:004. 24X
  Fiche: 50-424,83/06/22,8307010166.
- --8307010228 App 3F to Vogtle Electric Generating Plant.Units 1 & 2, FSAR. "Hazards Analysis." \* Georgia Power Co. 83706/22. 142pp. 19605:253. 24X Fiche:30-424.83/06/22,8307010166.
- --8307010230 Chapter 9 to Vogtle Electric Generating Plant.Units 1 & 2, FSAR, "Auxiliary Sys." \* Georgia Power Co. 83/06/22, 332pp. 19616:269, 24X Fichs: 50-424, 83/06/22, 8307010166,
- --8307010231 Chapter 4 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Reactor."

  \* Qeorgia Power Co. 83/06/22, 300pp. 19606:039. 24X
  Fiche: 50-424,83/06/22,8307010166.
- --8307010233 App 9A to Vogtle Electric Generating Plant, Units 1 & 2, FBAR. "Fire Harands Analysis." Woorgia Power Co. 83/06/22. 752pp. 19617:241. 24X Fiche: 50-824, 83/06/22.8307010166.
- --B307010234 Chapter 5 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "RGS & Connected Bys."

  w Georgia Power Co. B3/06/22, 253pp. 19606:335. 24X
  Fiche: 50-424,83/06/22,8307010166.
- ---B307010235 App 98 to Vogtle Electric Generating Plant.Units 1 & 2, FBAR, "Comparison of Vogtle Units 1 & 2 W/Requirements of Branch Technical Position CMEB 9.5-1."

  \* Georgia Power Co. 83/06/22, 74pp. 19619:273. 24X
  Fiche: 50-424, 83/06/22, 8307010166.
- --8307010237 Chapter 17 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "GA" # Georgia Power Co. 83/06/22, 128pp. 19625:267. 24X Fiche: 50-424, 83/06/22, 8307010166.
- --8307010238 Chapter 6 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "ESF."

  \* Georgia Power Co. 83/06/22. 1,315pp. 19607: 228. 24X
  fichs: 50-424,83/06/22,8307010166.
- --8307010239 Chapter 10 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR. "Bteam & Power Conversion Sys." \* Georgia Power Co. 83/06/22. 316pp. 19619:347. 24X Fiche: 50-424, 83/06/22, 8307010166.
- --B307010241 Chapter 7 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Instrumentation & Controls." \* Georgia Power Co. B3/06/22. 676pp. 19611:103. 24X Fiche: 50-424, 83/06/22.8307010166.
- --8307010242 App 10A to Vogtle Electric Generating Plant.Units 1 & 2. FSAR. "Vogtle Auxiliary Feedwater Sys Reliability Analysis." \* Georgia Power Co. 83/06/22. 65pp. 19620;303. 24X Fiche: 50-424,83/06/22.8307010166.
- --8307010244 Chapter 8 to Vogtle Electric Generating Plant, Units 1 & 2, FSAR, "Electric Power."

  \* Georgia Power Co. 83/06/22, 210pp. 19613:059, 24X fiche: 50-424,83/06/22,8307010166.
- Q. Inspection reports, IE Bulletins & carrespondence
- 8307140177 Forwards IE Insp Repts 50-424/83-10 & 50-425/83-10 on 830413-0510. No noncompliance noted. DANCE, H. C. Division of Project & Resident Programs. 83/06/20. KELLY, R. J. Georgia Power Co. 2pp. 19522:089. 24X Fiche:50-424,83/06/20.8307140177.
- --B307140185 IE Insp Repts 50-424/83-10 & 30-425/83-10 on B30413-0510.No noncompliance noted Major areas inspected:primary containment lifting & setting primary dome.welding primary coolant pipe, concrete pouring & stored in-place equipment. SANDERS, W.F. Region 2, Office of Director. BRANNEE, V.L. Division of Project & Resident Programs. B3/06/20. 3pp. 19522:091. 24X Fiche: 50-424, B3/06/20. B307140177.

- 8307140245 Forwards IE Insp Repts 50-424/83-11 & 50-425/83-11 on 830324-27. No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs. 83/06/23. KELLY.R.J. Georgia Power Co. 2pp. 17923:032. 24X Fiche: 50-424.83/06/23.8307140245.
- --8307140249 IE Insp Repts 50-424/83-11 & 50-425/83-11 on 830524-27. No noncompliance noted Major areas inspected: previous enforcement matters, structural steel & concrete & previously identified inspector followup item.

  HARRIS, J.R.: CONLON, T.E. Region 2. Office of Director. 83/06/21. 5pp. 19523:054. 24X Fiche: 50-424:83/06/23:8307140245.
- 8304270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc. list encl.

  UCRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563; 293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Efficient Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Go. of New York, Inc. 114pp. 19715:270. 24X Fiche: 30-000, 83/07/14, 8306270406.
- S. Reportable occurrences. LERs & related correspondence
- 8307120358 Final deficiency rept re quality of welds & radiographs mfg by Pullman Power Products. Deficiency nonexistent. Detailed engineering evaluation determined quality of welds sufficient to withstand any patential accident. FOSTER.D. D. Georgia Power Co. FOSTER.D. D. Bouthern Co. Services. Inc. 83/06/24. 0/REILLY.J.P. Region 2. Office of Director. 1p. 19429:167. 24X Fiche: 50-424.83/06/24.8307120358.
- 8307110433 Interim deficiency rept re lack of anchor bolt thread engagement for embeds. Initially reported on 820426. Seven embed plates classified void & 75 plates dispositioned useras-is. Followup audits by 9A & 9C being performed.
  FOSTER.D.O. Georgia Power Co. FOSTER.D.O. Bouthern Co. Services. Inc. 83/07/01. 0/REILLY, J.P. Region 2. Office of Director. 10pp. 19380:112. 24X Fiche: 50-424, 83/07/01. 8307110453.
- 8307220195 Interim deficiency mept me possible use of defective weld wire for stainless steel cambon steel welds. Initially reported on 830709. Metallungical tests continuing. Next rept will be submitted by 831014.

  CONMAY.R.E. Georgia Power Co. 83/07/11. D'REILLY.J.P. Region 2. Office of Director. 1p. 19484:093. 24X Fiche: 80-424.83/07/11. 8307220195.
- 8307220324 Interim deficiency rept re failure in embed plate base metal. Initially reported on 830606. Caused by lamellar tearing due to large shrinkage stresses from heavy welding.

  Next rept will be submitted by 831216.

  CONMAY.R.E. Georgia Power Co. 83/07/11. O'REILLY.J.P. Region 2. Office of Director. 4pp. 19675: 120. 24X Fiche: 50-424, 83/07/11. 8307220324.

#### V. Operator Examinations

B307140253 Requests submittal of ref matl discussed in B30617 telcon re instructor certification exams scheduled for B30725. Requirements for administration of operator licensing unitten exams encl.
DANCE, H. C. Division of Project & Resident Programs. B3/06/20. BECKHAH, J. T. Georgia Power Co. 3pp. 17523:040. 24X Fiche: 50-424,83/06/20,8307140253.

# DOCKET 50~433 UC-SANTA BARBARA RESEARCH REACTOR

# V. Operator Examinations

B3070B0427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT.D.Q. Division of Licensing. 83/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche: 50-000, 83/07/11, 83070B0427.

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A. Application/construction stage documents & correspondence
- B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. O. Division of Licensing. 83/07/09. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669: 234. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. 8vc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:249. 24X fiche: 50-000.83/07/08, 8307080169.
- 8307190489 Informs that costs for processing & issuance of license exceed max fee. No addl fee required.
  MILLER.W. O. License Fee Management Branch. B3/07/08. COLLIER.A.R. Offshore Power Systems (subs. of Westinghouse Electric Corp.). 1p. 19651:355. 24X Fiche: 50-437.83/07/08.8307190489.
- --B307190491 Forwards summary of review costs for issuance of mfg license. Max fee paid & no add1 fee required. HOLLOWAY.C.J. License Fee Management Branch. B3/07/08. License Fee Management Branch. 2pp. 19651:356. 24X Fiche:50-437, B3/07/08/B307190489.
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 830707009B Responds to 830615 ltr re Endangered Species Act. Plant site & associated transmission line corridors in plant area possibly occupied by several listed species. NRC surveys recommended.

  JURDAN, D. B. Interior, Dept. of, Fish & Wildlife Service. 83/06/2B. ADENSAM, E. Licensing Branch 4. 1p. 19295: 133. 24X
  Fiche: 50-438, 83/06/28, 8307070098.
- 8306270397 Ceneric Ltr 83-26 to all applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list enci. EISENKUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Byc list encl. EIBENHUT, D. G. Division of Licensing. 83707706. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events, 8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pg. 19659: 269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- Q. Inspection reports, IE Bulletins & correspondence
- B307220242 Forwards 1E Insp Repts 50-438/B3-14 & 50-439/B3-14 on B30531-0603. No noncompliance noted. VERRELLI, D.M. Division of Project & Resident Programs. B3/07/01. PARRISH. O. Tennessee Valley Authority. 2pp. 19684: 230. 24X Fiche: 50-438, B3/07/01. B307220242.
- --8307220247 IE Insp Repts 50-438/83-14 & 50-439/83-14 on 83053i-0603. No noncompliance noted. Major areas inspected: electrical components & sys observation of work & work activities, instrumentation cables & terminations. RUFF, A. B., CONLON, T. E. Region 2, Office of Director. B3/06/27. 6pp. 17484: 232. 24X Fiche: 50-438/83/07/01/8307220242.
- B306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.B3/07/11.8306270401.

- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- 8307220522 Ack receipt of 830627 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-11 & 50-439/83-11. Violation A will not be withdrawn. Rev 4 to Procedure BNP-0CP-10.29 conforms to Generic Ltr 81-01. 0'REILLY.J.P. Region 2. Defice of Director. 83/07/12. PARRIS. H. C. Tennessee Valley Authority. 2pp. 17685:150. 24X Fiche: 50-438,83/07/12,8307220522.
- --6307220526 Responds to NRC 830527 ltr re violations noted in IE Insp Repts 50-438/83-i1 & 30-437/83-i1 Corrective actions:motor sperated valves & auxillary feedwater pumps cleaned. Violation A re & inspector educ & experience disputed. MILLS.L.M. Tennessee Valley Authority. 83/06/27. O'REILLY, J. P. Region 2. Office of Director. 7pp. 19683:152. 24X Fiche: 50-438,83/07/12,8307220522.
- --8307220522 Forwards IE Insp Repts 50-438/83-11 & 50-439/83-11 on 830425-29 & notice of violation.

  LEWIS.R.C. Division of Project & Resident Programs. B3/05/27. PARRIS.H.O. Tennessee Valley Authority. 2pp. 19685: 159. 24X Ficha: 50-438, 83/07/12, 8307220522.
- --8307220336 Notice of violation from insp on 830425-29.
  \* Region 2. Office of Director. 83/05/27. 2pp. 17685:161. 24X Fiche:50-438,83/07/12.8307220522.
- --8307220541 IE insp Repts 50-438/11 & 50-439/83-11 on 830525-29. Noncompliance noted: Rev 3 to Procedure BNP-GCP-10.29 did not define GC inspector educ & experience requirements & nonconformance rept re in-core monitoring sys not initiated. WRIGHT, R.W. Region 2. Office of Director. UPRIGHT, C.M. Division of Engineering & Radiological Safety Programs. 83/05/25. 13pp. 19685:163. 24X Fiche: 50-438,83/07/12.8307820322.
- 8306270406 IE Info Natice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fische: 50-000, 83/07/14.8306270406.
- 8307270176 Requests expeditious review of 800909 request for exemption from inservice insp of welds for main steam & feedwater piping encl in guard pipe inside main steam valve rooms & forwards Rev 2 to CEB-76-163 including venting relief paths. KAMMER.D.S. Tennessee Valley Authority. 83/07/22. ADENBAM.E. Licensing Branch 4. 2pp. 19749:260. 24X Fiche:50-438.83/07/22, 8307270176.
- ~-B307270180 Rev 2 to "Break Exclusion Position From Complying W/APCBB 3-1 & MEB 3-1.8ellefonte Nuclear Plant Units 1 & 2."
  NEELY.B.B., EVANS, P.A., ENCLIBH, W.A. Tennessee Valley Authority. CEB-76-13 RO2. 77/09/28. 44pp. 19749:262. 24x
  Fiche: 50-438,83/07/22,8307270176.
- R. Periodic operating reports & related correspondence
- 8307140045 Informs that scheduled fuel load date remains May 1985. Any schedule changes will be included in next quarterly update until SER issuance.
  MILLS.L.M. Tennessee Valley Authority.
  Division of Licensing. ip. 19514:191. 24X Fiche: 50-438, 83/07/08, 83/07/08, 83/07/08, 83/07/08,
- 8. Reportable occurrences, LERs & related correspondence
- 8307120167 Sixth interim deficiency rept re RCB support & restraint bolt torques. Initially reported on 810824, EPRI funding raceived for NDE & corrosion research re high strength fasteners. Also reportable per Part 21.

  MILLIS.L.M. Tennessee Valley Authority. 83/06/29. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19423:160. 24X

  Fichs: 50-438, 83/06/29, 8307120167.
- 8307120210 Second interim deficiency rept re improper handling of design change repts. Initially reported on 821221 BLP-EP 44.76 revised & evaluation of 100 design change repts in progress. Next rept will be submitted by 831222.

  MILLS-L.M. Tennessee Valley Authority. 83/07/01. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19423:282. 24X Fiche: 50-438, 83/07/01. 8307120210.

- 8307150166 Second interim deficiency rept re relief valves violating ASME Code on use of stop valves between relief device & equipment being protected. Initially reported on 821223.

  Analysis & Jesign drawing revs underway. Next rept by 841102.

  MILLE, L.M. Tennessee Valley Authority. 83/07/05. 0'REILLY, J.P. Region 2, Office of Director. 2pp. 19537:210. 24X

  Fiche: 50-438.83/07/05.8307150166.
- 8307150267 First interim deficiency rept re breaking welded studs on seismic conduit supports. Initially reported on 830606.

  Corrective action will involve specifying max allowable torque on bolts. Next rept expected by 831219,

  MILLS,L.M. Tennessee Valley Authority. 83/07/05. O'REILLY, J. P. Region 2, Office of Director. 3pp. 19338:091. 24X

  Fiche: 30-438,83/07/05,8307150267.
- 8307220302 First Interim Deficiency Rept 50-438/83-39 re water damage to reactor bldg normal sump isolation valve motor operator. Initially reported on 830609. Motor operator refurbished. Preventive actions investigated. Next rept due by 831026. MLLS, L.M. Tennessee Valley Authority. 83/07/08. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19683:269. 24% Fiche: 50-438, 83/07/08, 8307220302.
- 8307220321 Supplemental Final Deficiency Rept 50-438/82-40 re overpressurization of makeup & purification piping & valves. Initially reported on 820528. Valve VIBB-439-A will reworked & retested by 831014.

  MILLS.L.M. Tennessee Valley Authority. 83/07/08. O'REILLY, J. P. Region 2, Office of Director. ip. 19675:097. 24x Fiche: 50-438,83/07/08,8307220321.
- 8307220080 Second interim deficiency rept re Johnson Machine Works welds on auxiliary feedwater pump room doors. Initially reported on 830210. Doors returned to vendor for rework. Next. rept expected by 840117, Also reported per Part 21. MILLS, L.M. Tennessee Valley Authority. 83/07/12. O'REILLY, J. P. Region 2, Office of Director. 1p. 19674:074. 24X Fiche: 50-438, 83/07/12, 8307220080.
- 8307220169 Eighth interim deficiency rept re failure of Chettanooga Bolt & Screw nuts & Challenge Enterprises bolts to meet ASTM specs. Initially reported on 810924. Results of bolting matl analysis under review. Also reportable per Part 21. MILLS, L. M. Tennessee Valley Authority. 83/07/14. D'REILLY, J. P. Region 2, Office of Director. 2pp. 19684:082. 24X Fiche: 50-438, 83/07/14, 8307220169.
- 8307220304 First interim deficiency rept re inability of ITE Imperial Corp safety-related electrical switchgear panel welds to meet QA criteria. Initially reported on 830415. Next rept will be submitted by 831130.
  MILLS,L.M. Tennessee Valley Authority. 83/07/14. D'REILLY, J. P. Region 2, Office of Director. 3pp. 19683:276, 24X Fiche: 50-438,83/07/14,8307220304.
- 8307220437 First interim deficiency rept re field cables not properly terminated in penetrations. Initially reported on 830614. Craft personnel & inspectors will be retrained in proper application of termination procedures. MILLB.L.M. Tennessee Valley Authority. 83/07/14. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19687:332. 24X Fiche: 50-438,83/07/14,8307220437.
- B307250464 Tenth interim deficiency rapt re failurs of main steam lines due to main feedwater overfill. Initially reported on B00319. Final analysis & verification of main steam line piping overfill event not compiste. Also reportable under Part 21. MILLS.L.M. Tennesses Valley Authority. B3/07/14. 0'REILLY, J. P. Region 2. Dffice of Director. 2pp. 19701:166. 24X Fiche: 50-438, 83/07/14, 8307250464.
- 8307250230 Final deficiency rept re Westinghouse low voltage switchgear. Initially reported on 820823. Fuse blocks will be matchmarked w/fuses in on position. Corrective actions will be completed by 830831.

  MILLS, L. M. Tennessee Valley Authority. 83/07/15. D'REILLY, J. P. Region 2, Defice of Director. 2pp. 19706:039. 24X
  Fiche: 50-438, 83/07/15, 8307250230.
- 8307250408 Second interim deficiency rept re snubber interference from rear brackets mfg by ITT Grinnell. Initially reported on 830126. Review of ITT Grinnell test results underway. Also reportable under Part 21. Next rept by 840125.
  MILLB.L.M. Tennessee Valley Authority. 83/07/15. 0'REILLY, J. P. Region 2. Office of Director. 2pp. 19704:013. 24X Fiche: 50-438, 83/07/15. 8307250408.
- 8307260503 Sixth Interim Deficiency Repts 81-30 & 81-33 re generic implications of failure to implement design criteria in design drawings. Initially reported on 810401. Review of functional control logic diagrams complete. Next rept 831021. MILLS, L.M. Tennessee Valley Authority. 83/07/19. 0'REILLY, J. P. Region 2. Office of Director. 1p. 19734:170. 24X Fiche: 50-438,83/07/19.8307260503.

- 8307260419 First interim deficiency rept re makeup/high pressure injection pump vibration. Initially reported on 830622. B&W requested to advise of corrective actions. Next rept expected by 831202. Also reported per Part 21. MILLS, L.M. Tennessee Valley Authority. 83/07/20. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19733:177. 24X Fiche: 50-438,83/07/20,8307260419.
- B307290034 Final deficiency rept for Watts Bar & Items 2 & 4 of Bellefonte & Sixth Interim Deficiency Rept Item 3 for Bellefonte re engineering change review & handling. Initially reported on Bil215. Next Bellefonte rept by B31021.
  MILLS.L.M. Tennessee Valley Authority. B3/07/20. O'REILLY, J. P. Region 2. Office of Director. 7pp. 19822:142. 24X
  Fiche: 50-000, 83/07/20, 8307290034.
- 8307260555 Final deficiency rept re failure to have proper review of functional control logic diagrams. Initially reported on 821027. Revs to diagrams identified & squadchecked. All electrical personnel advised of requirements. MILLS.L.M. Tennessee Valley Authority. 83/07/21. O'REILLY.J.P. Region 2. Dffice of Director. 2pp. 19731: 286. 24X Fiche: 50-438.83/07/21.8307260555.
- 8307290135 First interim deficiency rept re reactor bldg sump pH valves. Initially reported on 830623. Util studying extent of problem to determine resolution. Next rept expected by 840117.
  MILLS, L. M. Tennessee Valley Authority. 83/07/21. D'REILLY, J. P. Region 2. Office of Director. 2pp. 19822:043. 24X
  Fiche: 50-438, 83/07/21, 8307290135.
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 830707009B Responds to 830615 ltr re Endangered Species Act.Plant site & associated transmission line corridors in plant area possibly occupied by several listed species.NRC surveys recommended.

  JORDAN, D. B. Interior, Dept. of, Fish & Wildlife Service. 83/06/28. ADENSAM, E. Licensing Branch 4. lp. 19295:133. 24X Fiche: 50-438.83/06/28.8307070098.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York: Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS, Byc list encl. EISENHUT, D. 9. Division of Licensing, 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254, 24X Fiche: 50-000, 83/07/06, 8307060329.
- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS svents. Svc list encl. EIBENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Ficha: 30-000, B3/07/08, 8307080169.
- G. Inspection reports, IE Bulletins & correspondence
- 8307220242 Forwards IE Insp Repts 50-438/83-14 & 50-439/83-14 on 830531-0603.No noncompliance noted. VERRELLI, D. M. Division of Project & Resident Programs. 83/07/01. PARRIE.H. G. Tennessee Valley Authority. 2pp. 19684:230. 24X Fiche: 50-438,83/07/01.8307220242.
- --8307220247 IE Insp Repts 50-438/83-14 & 50-439/83-14 on 830831-0603. No noncompliance noted Major areas inspected: electrical components & sys observation of work & work activities, instrumentation cables & terminations.

  RUFF.A. B., CONLON, T. E., Region 2, Office of Director, 83/06/27.

  6pp. 19684: 232. 24% Fiche: 50-438, 83/07/01, 8307220242.
- 8306270401 IE Info Notice 83~46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Bubsystem." Svc list encl. JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293, 24X Fiche:50-000,83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 50-000,83/07/12,8306270404.

- 8307220522 Ack receipt of 830627 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-11 & 50-439/83-11. Violation A will not be withdrawn. Rev 4 to Procedure BNP-0CP-10. 29 conforms to Generic Ltr 81-01. 0'REILLY.J.P. Region 2. Office of Director. 83/07/12. PARRIS.H.G. Tannessee Valley Authority. 2pp. 19685:150. 24X Fiche: 50-438,83/07/12,8307220522.
- --8307220526 Respands to NRC 830527 ltr re violations noted in IE Insp Repts 50-438/83-11 & 30-439/83-11. Corrective actions:motor operated valves & auxiliary feedwater pumps cleaned. Violation A re GC inspector educ & experience disputed. MILLS.L.M. Tennessee Valley Authority. 83/06/27. 0'REILLY, J.P. Region 2. Office of Director. 7pp. 19685:132. 24X Fiche: 50-438, 83/07/12, 8307220522.
- --8307220532 Forwards IE Insp Repts 50-438/83-11 & 50-439/83-11 on 830425-29 & notice of violation. LEWIS.R.C. Division of Project & Resident Programs. 83/05/27. PARRIS.H.Q. Tennessee Valley Authority. 2pp. 19685:139. 24X Fiche: 50-438,83/07/12,8307220522.
- --8307220536 Notice of violation from insp on 830425-29. \* Region 2: Office of Director. 83/05/27. 2pp. 17685:161. 24X Fiche: 50-438, 83/07/12:8307220522.
- --8307220341 IE Insp Repts 30-438/11 & 50-439/83-11 on 830525-29.

  Noncompliance noted:Rev 3 to Procedure BNP-GCP-IO. 29 did not define GC inspector educ & experionce requirements & nanconformance rept re in-core monitoring sys not initiated. WRIGHT.R.W. Region 2. Office of Director. UPRIGHT.C.M. Division of Engineering & Radiological Safety Programs. 83/05/25. I3pp. 19685:163. 24X Fiche: 50-438.83/07/12.8307220522.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J. M. Division of GA. Safeguards & Inspection Programs (Post 830103) B3/07/14. Cansalidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- B307270176 Requests expeditious review of 800909 request for exemption from inservice insp of welds for main steam & feedwater piping encl in guard pipe inside main steam valve rooms & forwards Rev 2 to CEB-76-13 including venting relief paths. KAMMER.D. S. Tennessee Valley Authority. 83/07/22. ADENSAM.E. Licensing Branch 4. 2pp. 19749:260. 24X Fiche:50-438,83/07/22,8307270176.
- ---8307270180 Rev 2 to "Break Exclusion Position From Complying W/APCSB 3-1 & MEB 3-1, Bellefonte Nuclear Plant Units 1 & 2."

  NEELY, B. B., EVANS, P. A., ENGLISH, W. A. Tennessee Valley Authority, CEB-76-13 ROZ. 77/09/2B. 44pp. 19749: 262. 24X

  Fiche: 50-438, 83/07/22, 8307270176.
- S. Reportable occurrences, LERs & related correspondence
- 8307120167 Sixth interim deficiency rept re RCS support & restraint bolt torques. Initially reported on 810824. EPRI funding received for NDE & corrosion research re high strength fasteners. Also reportable per Part 21.

  MILLS.L.M. Tennessee Valley Authority. 83/06/29. 0'REILLY, J. P. Region 2. 0ffice of Director. 2pp. 19423:160. 24X

  Fiche: 50-438,83/06/29,8307120167.
- 8307120210 Second interim deficiency rept re improper handling of design change repts. Initially reported on 821221. BLP-EP 44.76 revised & evaluation of 100 design change repts in progress. Next rept will be submitted by 831222. MILLS,L.M. Tennessee Valley Authority. B3/07/01. G'REILLY,J.P. Region 2. Office of Director. 2pp. 19423: 282. 24% Fiche: 50-438,83/07/01.8307120210.
- 8307130166 Second interim deficiency rept re relief valves violating ABME Code on use of stop valves between relief device & equipment being protected. Initially reported on 821223. Analysis & design drawing revs underway. Next rept by 841102. MILLS, L. M. Tennessee Valley Authority. 83/07/05. O'REILLY, J. P. Ragion 2. Office of Director. 2pp. 19537:210. 24X Fiche: 50-438, 83/07/05, 8307150166.
- 8307130247 First interim deficiency rept re breaking weided studs an weismic conduit supports. Initially reported an 830606. Corrective action will involve specifying max allowable torque on buits. Next rept expected by 831217. MILLS, L. M. Tennessee Valley Authority. 83707705. O'REILLY, J. P. Region 2. Dffice of Director. 3pp. 19538:091. 24X Fiche: 50-438, 83707705. 8307150267.

- 8307220080 Second interim deficiency rept re Johnson Machine Works welds on auxiliary feedwater pump room doors. Initially reported on B30210. Doors returned to vendor for rework. Next rept expected by 840117. Also reported per Part 21. MILLS, L.M. Tennessee Valley Authority. B3/07/12. 0'REILLY, J. P. Region 2. Office of Director. Ip. 19674:074. 24X Fiche: 50-438.83/07/12.8307220080.
- 8307220169 Eighth interim deficiency rept re Failure of Chattanooga Bolt & Screw nuts & Challenge Enterprises bolts to meet ASTM specs. Initially reported on 810924. Results of bolting matl analysis under review. Also reportable per Part 21. MILLS, L.M. Tennessee Valley Authority. 87/07/14. 0'REILLY, J. P. Region 2. 0ffice of Director. 2pp. 19684: 082. 24x Fiche: 50-438, 83/07/14, 8307220169.
- 8307220304 First interim deficiency rept re inability of ITE Imperial Corp safety-related electrical switchgear panel welds to meet GA criteria. Initially reported on 830615. Next rept will be submitted by 83130.
  MILLS.L.M. Tennessee Valley Authority. 83/07/14. 0'REILLY, J. P. Region 2. Dffice of Director. 3pp. 19683: 276. 24X Fiche: 50-438, 83/07/14, 8307220304.
- 8307220422 Third interim rept re deficient pipe supports. Initially reported on 81i215. Support design load drawings revised to identify supports w/thermal movements equaling or exceeding 1/16-inch in unrestrained directions.

  MILLS.L.M. Tennesse Valley Authority. 83/07/14. O'REILLY, J. P. Region 2, Office of Director. 2pp. 19687:265. 24X Fiche: 50-439,83/07/14,8307220422.
- 8307220437 First interim deficiency rept re field cables not properly terminated in penetrations. Initially reported on 830614. Craft personnel & inspectors will be retrained in proper application of termination procedures.

  MILLS, L.M. Tennessee Valley Authority, 83/07/14, 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19687: 332. 24X Fiche: 50-438, 83/07/14, 8307220437.
- 8307250464 Tenth interim deficiency rept re failure of main steam lines due to main feedwater overfill Initially reported on 800319.

  Final analysis & verification of main steam line piping overfill event not complete. Also reportable under Part 21.

  MILLS.L.M. Tennessee Valley Authority. 83070714. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19701:166. 24X

  Fiche: 50-438, 83/07/14, 8307250464.
- 8307230408 Second interim deficiency rept re snubber interference from rear brackets mfg by ITT Grinnell Initially reported on 830126. Review of ITT Grinnell test results underway. Also reportable under Part 21. Next rept by 840125.
  MILLS.L.M. Tennessee Valley Authority. 83/07/15. © 'REILLY, J. P. Region 2. Office of Director. 2pp. 19704:013. 24X Fiche: 30-438, 83/07/15, 8307250408.
- B307260503 Sixth Interim Deficiency Repts 81-30 & 81-33 re generic implications of failure to implement design criteria in design drawings. Initially reported on B10401. Review of functional control logic diagrams complete. Next rept B31021. MILLS, L.M. Tennessee Valley Authority. 83/07/17. 0/REILLY, J.P. Region 2. Qffice of Director. 1p. 19734:170. 24X Fiche: 50-438, 83/07/19, 8307260503.
- 8307290034 Final deficiency rept for Watts Bar & Items 2 & 4 of Bellefonte & Sixth Interim Deficiency Rept Item 3 for Bellefonte re engineering change review & handling Initially reported on Bii215. Next Bellefonte rept by 831021. MILLS, L.M. Tennessae Valley Authority. 83/07/20. 0/REILLY, J. P. Region 2, Office of Director. 7pp. 19822:142. 24% Fiche: 50-000, 83/07/20, 8307270034.
- 8307260555 Final deficiency rept re failure to have proper review of functional control logic diagrams. Initially reported on 821027. Revs to diagrams identified & squadchecked. All electrical personnel advised of requirements. MILLS, L.M. Tennessee Valley Authority. 83/07/21. 0'REILLY, J. P. Region 2, Office of Director. 2pp. 19731:286. 24X Fiche: 30-438, 83/07/21, 8307260555.
- 8307290135 First interim deficiency rept re reactor bldg sump pH valves Initially reported on 830623. Util studying extent of problem to determine resolution Next rept expected by 840117.

  MILLS.L.H. Tennessee Valley Authority. 83/07/21. D'REILLY.J.P. Region 2. Office of Director. 2pp. 19822:043. 24X Fiche: 30-438. 83/07/21. 8307290135.

- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- B307050202 Summarizes status of concrete annulus fill & containment radiograph issues to permit continued const in annulus area. Deviation from ASME Code requirements for inaccessible welds requested.

  EDELMAN.M.R. Cleveland Electric Illuminating Co. B3/06/22. YOUNGBLOOD, B. Licensing Branch 1. 2pp. 19198: 285. 24X Fiche: 50-440, 83/06/22, 8307050202.
- 8306270395 Generic Ltr 83-24 to all BWR applicants for GL & holders of GLs for Grand Gulf, LeBalle & Susquehanna re TMI Task Action Plan Item I. G. I, "Special Low Power Testing & Training & Recommendations for BMRs." Svc 11st encl. EISENHUT, D. G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fichs: 50-000, 83/06/29, 8306270375.
- B306270397 Qeneric Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIBENHUT, D. Q. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 30-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS 8vc list encl. EISENMUT.D.Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche:50-000.83/07/06.8307060329.
- B3070B0169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISEN-MIT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 1969:269. 24X Fiche: 50-000, 83/07/08, 83070B0169.
- 8307250367 Submits summary status of issues being addressed by Licensing Review Group II.per 830502 request. Four issues require further action prior to NRC closeout. Post-accident sampling requires procedural upgrading. HOLTZSCHER, D. L. Licensing Review Group II. HOLTZSCHER, D. L. Illinois Power Co. 83/07/15. STEFANG. J. J. Licensing Branch 1. 12pp. 19705: 203. 24X Fiche: 50-000, 83/07/15. 8307250367.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8307060277 Forwards revised rept providing addl info in response to SER Confirmatory Issue 21 re suppression pool temp limits. Rapt addresses plant-specific info, analyses & assumptions to meet requirements & criteria given in NUREG-0783. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/06/29. YOUNOBLOOD.B.J. Licensing Branch 1. 15pp. 19234:191. 24X Fiche: 50-440, 83/06/29, 8307060277.
- 8307060278 Responds to 830427 ltr re proposed mode to automatic depressurization sys logic (TMI Item II. K. 3.18) per SER Confirmatory Item 25. Util will implement BMR Owners Group option for removal of high drywell pressure trip. EDELHAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. YOUNGBLOOD.B. J. Licensing Branch 1. 2pp. 19234:187. 24X Fiche: 50-440,83/07/01.8307060278.
- G. Adjudicatory correspondence
- 8307070144 Amended 830623 response to NRC 830531 motion for summary disposition of Issue 13. Reasonable opportunity should be afforded Ohio Citizens for Responsible Energy to support opposition through further discovery. Related correspondence. HIATT, S. L. Ohio Citizens for Responsible Energy. 83/06/27. NRC No Detailed Affiliation Given. 3pp. 19274:162. 24X Fichs: 50-440, 83/06/27, 8307070144.
- --8307070154 Affidavit of SL Hiatt, providing justification for add1 time needed to respond properly to NRC motion for summmary disposition of Issue i3. Certificate of Svc encl. HIATT, S. L. Dito Citizens for Responsible Energy. 83/06/29. 3pp. 19294:167. 24X Fiche: 50-440, 83/06/29, 8307070144.
- 8307070225 Motion to strike portions of applicant 830627 answer supporting NRC motion for summary disposition of Issue 13, Certificate of Svc snc1.Related correspondence. HIATT, S.L. Ohio Citizens for Responsible Energy, 83/06/30, Atomic Safety and Licensing Board Panel. 4pp. 19269;308. 24X Fiche: 50-440,83/06/30,8307070225.

- 8307060339 Forwards proposed finding of fact & conclusions of law in form of partial initial decision.

  SILBERG J. E. Shaw, Pittman, Potts & Trowbridge. SILBERG, J. E. Cleveland Electric Illuminating Co. 83/07/01. BLOCH, P. B., KLINE, J. R., BRIGHT, O. O. Atomic Safety and Licensing Board Panel. ip. 19234: 051. 24X Fiche: 50-440, 83/07/01, 8307060339.
- B307110310 Reply opposing util & NRC responses apposing Ohio Citizens for Responsible Energy B30510 motion to file contentions on SNM license application. Certificate of Svc encl. HIATT.S.L. Ohio Citizens for Responsible Energy. B3/07/05. Atomic Safety and Licensing Board Panel. 15pp. 19380:344. 24X Fiche: 50-440, B3/07/05, B307110310.
- B30708046B Serves parties w/KR Naidu 830629 ltr clarifying testimony at May 1983 hearing. WOODHEAD,C.P. Hearing Branch 4. B3/07/06. BLOCH,P.B., BRIGHT,Q.D., KLINE,J.R. Atomic Bafety and Licensing Board Panel. 1p. 19346:354. 24X Fiche: 50-440,83/07/06.830708046B.
- --8307080473 Clarifies testimony of Region III witnesses on crossexamination & ASLB questioning. NAIDU.K.R. Region 3, Office of Director. 83/06/29. BLOCH.P.B., BRIOHT.Q.O., KLINE, J.R. Atomic Safety and Licensing Board Panel. 1p. 19346:355. 24X Fiche:50-440,83/07/06,8307080468.
- 8307150325 Motion for extension, until 830721, to file proposed findings of fact & conclusions of law w/supporting citations & argument. Certificate of Svc encl.
  LODGE, T. J. Bunflower Alliance. LODGE, T. J. Lodge, T. J. 83/07/11.
  Atomic Safety and Licensing Board Panel. 2pp. 19838: 252. 24X
  Fiche: 50-440,83/07/11,8307150325.
- 8307190114 Proposed findings of fact & conclusions of law for Issue 3 re adequacy of GA program & control of const contractors. Applicant failed to resolve issue at 830524-27 public hearing. Certificate of 8vc enci.
  MIATT.9.L. Uhio Citizens for Responsible Energy. 83/07/11. 36pp. 19634:286. 24X Fiche: 50-440,83/07/11,8307190114.
- 8307140430 Memorandum & order denying admission of Ohio Citizens for Responsible Energy 830510 contentions to block util receipt of unirradiated reactor fuel & associated matls. Late-filed requirements not met.

  BLOCH.P. B., KLINE, J. R., BRIGHT, G. D. Atomic Safety and Licensing 80ard Panel. 83/07/12, 7pp. 19821:169. 24X Fiche: 50-440,83/07/12,8307140430,
- B307150316 Answer opposing Ohio Citizens for Responsible Energy B30630 motion to strike portions of applicant B30627 answer in support of NRC motion for summary disposition of Issue 13. Motion has no basis. Certificate of Bvc encl.

  BNIGER, M. A. Cleveland Electric Illuminating Co. SWIGER, M. A. Shaw, Pittman, Potts & Troubridge. B3/07/12. Atomic Safety and Licensing Board Panel. 7pp. 19533:011. 24X Fiche: 50-440, 83/07/12, 8307150316.
- 8307190186 Motion to reopen record on Issue 3 re const QA. Motion based on recently received documents obtained through FOIA which indicate QA deficiencies are much worse than recent hearing revealed. Certificate of 8vc encl. HIATT, S. L. Ohio Citizens for Responsible Energy. 83/07/13. Atomic Safety and Licensing Board Panel. 24pp. 19630:144. 24X Fiche: 50-440, 83/07/13, 8307190186.
- B307190222 Response opposing applicant B30627 answer supporting NRC motion for summary disposition of Issue 13. NRC must abide by SRP & Reg Quide 1. 115. Regulatory policy changes cannot be made merely for convenience. Certificate of Svc snc1.
  HIATT.B. L. Dhio Citizens for Responsible Energy. B3/07/13. Atomic Safety and Licensing Board Panel. 3pp. 19629:222, 24x Fiche: 50-440, 83/07/13, 8307190222.
- B307270287 Notifies of VR Harding employment at law firm. Harding will not participate in any case currently pending before NRC. BILBERG.J.E. Shaw. Pittman. Potts & Trowbridge. 83/07/13. BLOCH.P.B., KLINE.J.R., BRIGHT.G.O. Atomic Safety and Licensing Board Panel. 1p. 19747:198. 24X Fiche: 30-440.83/07/13.8307270287.
- --B307270477 Notifies of employment at law firm. VR Harding will not participate in any case pending before NRC. Svc list encl. HARDINO, V. R. Bhaw, Pittman, Potts & Trombridge. B3/07/13. BLOCH. P. B., KLINE, J. R., BRIGHT, O. O. Atomic Safety and Licensing Board Panel. 2pp. 19767: 199. 24X Fiche: 50-440, 83/07/13, 8307270287.

- B307190203 Motion for leave to file answer to Dhio Citizens for Responsible Energy B30629 amended response to NRC motion for summary disposition of Issue 13.per ASLB B21006 memorandum & order.

  SILBERO, J. E. Cleveland Electric Illuminating Co. SILBERO, J. E. Shaw, Pittman, Potts & Troubridge. B3/07/14. Atomic Bafety and Licensing Board Panel. 2pp. 19628: 289. 24X Fiche: 50-440, 83/07/14, 8307190203.
- --B307190208 Answer to Ohio Citizens for Responsible Energy (OCRE) B30629 amended response to NRC motion for summary disposition of Issue 13. OCRE request for continuance is frivolous & should be denied. Certificate of Svc encl.

  SitBERG.J.E. Cleveland Electric Illuminating Co. SILBERG.J.E. Shaw, Pittman, Potts & Troubridge. B3/07/14. 13pp. 19628: 291. 24X Fiche: 50-440, B3/07/14. 8307190203.
- 8307190084 Response to ASLB 830509 telcon questions re declaration of sua sponte issues. Encl AF Silatoski affidavit responds to ASLB inquiries.

  BILBERG, J. E. Cleveland Electric Illuminating Co. SILBERG, J. E. Bhaw. Pittman, Potts & Troubridge. 83/07/15, 1p. 19635:175. 24X Fiche: 50-440,83/07/15,8307190084.
- --8307190104 Affidavit of AF Silakoski in response to ASLB sua sponte questions. Simulator operator training includes comparing & contrasting indications of all related instrument types & ranges. W/Certificate of Evc.

  SILAKOSKI.A.F. Cleveland Electric Illuminating Co. 83/07/14.

  7pp. 19635:176. 24X Fiche: 50-440, 83/07/15, 8307190084.
- B307200214 Proposed findings of fact & conclusions of law.Certificate of Bvc encl. LODGE, T. J. Sunflower Alliance. LODGE, T. J. Ladge, T. J. B3/07/15. 19pp. 1964B: 033. 24X Fiche: 50-440. 83/07/15. B307200214.
- 8307210179 Answer to applicant 830714 motion for leave to file answer to intervenor amended response to NRC motion for summary disposition of Issue 13 Rules allow for no fourther response. Certificate of Svc ancl. Related correspondence. HIATT, 8. L. Ohio Citizens for Responsible Energy. 83/07/18. Atomic Safety and Licensing Board Panel. 2pp. 19666:040. 24% Fiche: 50-440, 83/07/18, 8307210179.
- B307210305 Answer opposing Ohio Citizens for Responsible Energy B30630 motion to strike portions of applicant B30627 answer supporting NRC B30531 motion for summary disposition of Issue 19. Certificate of 8vc encl. CUTCHIN. J. M. Hearing Branch 4, B3/07/20. Atomic Safety and Licensing Board Panel. 5pp. 19664:353. 24X Fiche:50-440,83/07/20,8307210305.
- 8307260294 Memorandum in support of Ohio Citizens for Responsible Energy B30713 motion to reopen record on Issue 3 re GA. Cartificate of Svc encl. LODOE, J. L. Bunflower Alliance. LODOE, J. L. Wilt, D. D. 83/07/21. Atomic Safety and Licensing Board Fanel. 4pp. 19811:002. 24X Fiche: 50-440,83/07/21,8307260294.
- 8307250340 Proposed findings of fact & conclusions of law on Issue 3 re GA. Certificate of Svc encl. CUTCHIN.J.M. Hearing Branch 4. 83/07/22. 23pp. 19703:215. 24X Fiche: 50-440,83/07/22,8307250360.
- 8307270246 Answer supporting util 830714 motion for leave to file answer to Ohio Citizens for Responsible Energy 830629 amended response to NRC 830531 motion for summary disposition of Issue 13. Certificate of Svc encl.

  CUTCHIN.J.M. Hearing Branch 4. 83/07/26. Atomic 8afety and Licensing Board Panel. 5pp. 19767:106. 24X Fiche: 50-440.83/07/26, 8307270246.
- 8307270250 Answer opposing Dhio Cititens for Responsible Energy B30713 motion to reopen record on Issue 3. Citizens fail to demonstrate motion timely, raises significant safety issue or is likely to change result Centificate of Svc encl. CUTCHIN.J.M. Hearing Branch 4, B3/07/26, Atomic Safety and Licensing Board Panel. Spp. 19749:306. 24X Fiche:50-440,B3/07/26,B307270250.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307210077 Forwards Amend 12 to FBAR. Amend incorporates previously submitted response to GA branch questions & revises mechanical sys & components, conduct of operations & GA. EDELMAN.N.R. Cleveland Electric Illuminating Co. B3/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. Spp. 17660: 273. 24X Fiche: 50-440, B3/07/19, B307210077.
- --B307210081 Amend 12 to F8AR. \* Cleveland Electric Illuminating Co. 83/07/19. 380pp. 19640: 276. 24X Fiche: 30-440.83/07/19.8307210077.

# G. Inspection reports: IE Bulletins & correspondence

- 8307080448 Ack receipt of 830628 ltr informing NRC of steps taken to correct violations moted in IE Insp Repts 50-440/83-12 & 50-441/83-11.
  LITTLE-M.S. Region 3, Office of Director. 83/07/05. EDELMAN, M.R. Cleveland Electric 111uminating Co. ip. 19347: 225, 24X Fiche: 30-440,83/07/05,8307080448.
- --8307080451 Responds to NRC 830603 ltr re violations noted in IE Insp Repts 30-440/83-12 & 50-441/83-11. Corrective actions: Johnson Controls, Inc reindoctrinated affected personnel in GC procedures required for insp & documentation. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/06/28. KEPPLER.J. C. Region 3, Office of Director. 2pp. 19347: 226. 24x Fiche: 50-440, 83/07/05, 8307080448.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Stray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, B3/07/11, B306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Syc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-125 & I-13i in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14, Consolidated Edison Ca. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, B3/07/14, B306270406.
- 8307280247 Forwards IE insp Repts 50-440/83-19 & 50-441/83-1B on B30620-24 & notice of violation.
  LITTLE.W.S. Region 3. Office of Director. B3/07/15. EDELMAN.M.R. Cleveland Electric Illuminating Co. 2pp. 19791:211. 24X Fiche: 50-440,83/07/15,8307280247.
- --8307280253 Notice of violation from insp on 830620-24. LITTLE,W.B. Region 3. Office of Director. 83/07/15. ip. 19791:213. 24X Fiche: 50-440,83/07/15,8307280247.
- --8307280264 IE Insp Rept 50-440/83-19 % 50-441/83-18 on 830620-24.

  Noncompliance noted: safety-related instrument panel
  1H22-P015 removed w/o rework procedure.

  MERRIMEATHER, N. Region 2, Office of Director. CONLON, T. E.
  Division of Engineering & Radiological Safety Programs. 83/07/11.

  6pp. 19791:214. 24X Fiche:50-440,83/07/15,8307280247.
- 8307280437 Forwards IE Insp Repts 50-440/83-13 & 50-441/83-12 on 830404-0615 & notice of violation.
  STREETER, J. F. Region 3, Office of Director. 83/07/25. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 19796:286. 24X Fiche: 50-440,83/07/25,8307280437.
- --8307280437 Notice of violation from insp on 830404-0615. 8TREETER, J. F. Region 3. Office of Director. 83/07/25. 1p. 19796:288. 24X Fiche: 50-440, 83/07/25, 8307280437.
- --8307280442 IE Insp Repts 50-440/83-13 & 50-441/83-12 on 830404-0615. Noncompliance noted: failure to periodically assess adequacy of program. KISH.J.N. MAXWELL, Q.F., VANDEL, T.E. Region 3, Office of Director. 83/07/25. 11pp. 19776:289. 24X Fiche: 50-440,83/07/25,8307280437.

### 8. Reportable occurrences, LERs & related correspondence

- 8307060065 Interim deficiency rept re Johnson Controls, Inc failure to adequately verify acceptability of Unistrut Corp GA program. Initially reported on 830329, Corrective Action Request 83-03 issued. Final rept by 830730.
  EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/06/24, KEPPLER, U. Q. Region 3, Office of Director. 2pp. 19250:359, 24X Fiche: 30-440,83/06/24,8307060065.
- B307070001 Part 21 rept re lack of automatic restart capabilities of P-47 chillers after loss of offsite power Initially reported on B30429. Evaluation continuing.

  BARKER, R. Oilbert/Commonumealth Cos. B3/06/30. DEYGUNG, R. C. Director's Offsice, Offsice of Inspection and Enforcement. 1p. 19293:158. 24X Fiche: 50-440, B3/06/30, B307070001.

- 8307070282 Part 21 rept to RCIC pump turbine which could operate w/o adequate room cooling. Initially reported on 830427. Automatic cooling water provided to pump room cooling unit when RCIC turbine starts.

  BARKER, N.R. Oilbert/Commonwealth Cos. 83/06/30. DEYOUNG, R.C. Director's Office. Office of Inspection and Enforcement. 1p. 19294:091. 24X Fiche: 50-440, 83/06/30, 8307070282.
- 8307110134 Second interim deficiency rept re violation of spec requirements during installation of adjacent Hilti Kutk bolts. Initially reported on 830207. Spec SP108/208 revised. Final rept by 830930. EDELHAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J. G. Region 3. Office of Director. 2pp. 19375:126. 24X Fiche: 30-440,83/07/01,8307110134.
- 8307110316 Final deficiency rept re ABME Code Section III, Class 3 piping supports supplied by Transamerica Delaval, Inc. Initially reported on 830223. Revised drawings detailing mode supplied by Delaval.

  EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J.G. Region 3. Office of Director. 2pp. 19380:361. 24X Fiche: 50-440, 83/07/01, 8307110316.
- 8307110382 Third interim Significant Deficiency Rept RDC 64(83) re linear indications in bracket welds for main steam & recirculation sys pipe whip restraints. Initially reported on 821228. Completion of corrective actions by 841215. EDELMAN.J.O. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J.O. Region 3. Office of Director. 2pp. 19380:338. 24X Fiche: 50-440,83/07/01,8307110382.
- B307190038 Interim Deficiency Rept RDC 24(B1) re defect in lubricating oil sys standyby diesel generators. Installation of replacement parts will begin upon completion of code piping weld repairs & will be completed by Feb 1984.

  EDELMAN.M.R. Cleveland Electric Illuminating Co. B3/07/01.

  KEPPLER.J. Q. Region 3. Office of Director. 1p. 19635:047. 24X

  Fiche: 50-440, 83/07/01. 8307190038.
- 8307190136 Interim deficiency rept re relocation of Governor lube oil coolers/standby diesel generator. Governors returned to Transamerica DeLaval. Corrective actions on coolers will not be complete until Nov 1983 for Unit 1 & Jan 1984 for Unit 2. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J.G. Region 3. Office of Director. 1p. 19636:105. 24X Fiche: 30-440.83/07/01.8307190136.
- 8307190176 Suppl to 821215 final deficiency rept re standby diesel generators. Model DSRIVI6, starting air sys check valve. Valves returned to Transamerica DeLaval remfg of internal components. Mods will be completed by Dec 1783. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J.G. Region 3, Office of Director. 1p. 17632:114. 24X Fichs: 50-440, 83/07/01, 8307190176.
- B307190204 Interim Deficiency Rept RDC 52(B2) re discrepancies in documentation package used to track repair work for skid-mounted piping. Correction of discrepancies expected to be completed by B31201.
  EDELMAN.M.R. Cleveland Electric Illuminating Co. B3/07/01.
  KEPPLER, J. O. Repion 3, Office of Director. ip. 19628:317, 24X Fiche: 50-440,83/07/01,8307190204.
- 8307180031 Interim deficiency rapt re partial blockage found in porous concrete pipes & weepholes associated w/pumping drain sys portion of pressure relief underdrain sys. Initially reported on 830610. Investigation underway. Final rept due 831101. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/08. KEPPLER.J. G. Region 3, Office of Director. 2pp. 19360:207. 24X Fiche: 50-440.83/07/08.8307180031.
- 8307200289 Interim Deficiency Rept RDC 73(83) re Borg-Warner valve radiographs. Forty-four valves selected as representative sample reradiographed by Magnaflux Corp. Radiographs submitted to Borg-Warner for review. Final rapt by 830831. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/11. KEPPLER, J. O. Region 3, Office of Director. 1p. 19648: 064, 24X Fiche: 50-440, 83/07/11, 8307200289.
- B307220434 Interim deficiency rept re HPCS diesel generator electrical panels supplied by GE. Initially reported on B30615. Ring lug terminations will be replaced. Next rept will be submitted by B40406.
  EDBLMAN.M.R. Cleveland Electric Illuminating Co. B3/07/15.
  KEPPLER,J. O., Region 3, Office of Director. 2pp. 19687:327. 24X
  Fiche: 50-440, 83/07/15, 8307220434.

#### T. Hearing transcripts on non-antitrust matters

8307040238 Proposed corrections to 830527 hearing transcript.
Certificate of Svc encl.
BILBERG J.E. Cleveland Electric Illuminating Co. SILBERG J.E.
Shaw, Pittman, Potts & Troubridge. 93/07/01. 8pp. 19239: 266. 24X
Fiche: 50-440.83/07/01.8307060238.

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

B307050202 Summarizes status of concrete annulus fill & containment radiograph issues to permit continued const in annulus area. Deviation from ABME Code requirements for inaccessible welds requested. EDELMAN.M.R. Cleveland Electric Illuminating Co. 93/06/22. YOUNOBLOODS.B. Licensing Branch 1. 2pp. 19198:285. 24X Fiche: 50-440,83/06/22,8307050202.

8306270395 Generic Ltr 83-24 to all BWR applicants for GL & holders of OLs for Grand Gulf.LoSalle & Susquehanna re TMI Task Action Plan Item I.G.1. "Special Low Power Tosting & Training & Recommendations for BWRs." Svc list encl. EISENHUT.D. G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche:50-000.83/06/29, 8306270395.

8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for diasel fuel impurity, Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000,83/07/05,8306270397.

8307060329 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISEN-WITD.O. Division of Licensing. 93/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.

B307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Balem ATW8 events. Svc list encl. EISENHUT.D. 9. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.

E. NRC Safety Evaluation Report (SER), supple & correspondence

B307060277 Forwards revised rept providing addl info in response to BER Confirmatory Issue 21 re suppression pool temp limits. Rept addresses plant-specific info analyses & assumptions to meet requirements & criteria given in NUREO-0783. EDELMAN.M.R. Cleveland Electric Illuminating Co. B3/06/29. YOUNOBLOOD, B. J. Licensing Branch 1. 13pp. 19234:191. 24X Fichs: 50-440. B3/06/29. B307060277.

B30708027B Responds to B30427 ltr re proposed mods to automatic depressurization sys logic (TMI Item II.K.3.18) per SER Canfirmatory Item 25. Util will implement BWR Owners Group option for removal of high drywell pressure trip. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. YOUNGBLOOD, B. J. Licensing Branch 1. 2pp. 19234:187. 24X Fichs: 50-440.83/07/01,8307060278.

# G. Adjudicatory correspondence

8307070144 Amended 830629 response to NRC 830531 motion for summary disposition of Issue 13. Reasonable opportunity should be afforded Dhio Citizens for Responsible Energy to support opposition through further discovery, Related correspondence, HIATT, S. L. Ohio Citizens for Responsible Energy, 83/06/29, NRC - No Detailed Affiliation Given, 5pp. 19294:162. 24X Fichs: 50-440.83/06/29,8307070144.

---B307070154 Affidavit of SL Hiatt, providing justification for add1 time needed to respond properly to NRC motion for summary disposition of Issue 13. Certificate of Svc encl. HIATT.B.L. Ohio Cititiens for Responsible Energy. B3/06/29. 3pp. 19294:167. 24X Fiche: 50-440, B3/06/29, B307070144.

B307070225 Motion to strike portions of applicant B30627 answer supporting NRC motion for summary disposition of Issue (3. Certificate of Svc encl. Related correspondence. HIATT, S. L. Ohio Citizens for Responsible Energy. B3/06/30. Atomic Safety and Licensing Board Panel. 4pp. 19269:308. 24) Fiche: 50-440, B3/06/30, B307070225.

B307060339 Forwards proposed finding of fact & conclusions of law in form of partial initial decision.
SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge. SILBERG, J. E. Cleveland Electric Illuminating Co. B3/07/01. BLOCK, P. B., KLINE, J. R., BRIGHT, G. D. Atomic Safety and Licensing Board Panel. ip. 19234:051. 24X Fiche: 50~440.83/07/01.8307060339.

--B307060344 Proposed findings of fact & conclusions of law in form of partial initial decision. Certificate of Svc encl.
BLLBERG, J. E. Cleveland Electric Illuminating Co. SILBERG, J. E. Shaw, Pittman, Potts & Troubridge. B3/07/01. 72pp. 19234:052. 24X Fiche: 50-440, 83/07/01, 8307060339.

8307110310 Reply apposing util & NRC responses apposing Dhio Citizens for Responsible Energy 830510 motion to file contentions on SNM license application. Certificate of Svc encl. HIATY, S. L. Ohio Citizens for Responsible Energy. 83/07/05. Atomic Safety and Licensing Board Panel. 15pp. 19380:346. 24X Fiche: 50-440,83/07/05,8307110310.

8307080468 Serves parties w/KR Naidu 830629 ltr clarifying testimony at May 1983 hearing. WDODHEAD,C.P. Hearing Branch 4. B3/07/06. BLOCH,P.B., BRIGHT, Q.D., KLINE,J.R. Atomic Safety and Licensing Board Panel. 1p. 19346:354. 24X Fiche:50-440,83/07/06.8307080468.

--B307080473 Clarifies testimony of Region III witnesses on crossexamination & ABLD questioning. NAIDU,K.R. Region 3. Office of Director. B3/06/29. BLOCH.P.B., BRIGHT,G.O., KLINE, J.R. Atomic Safety and Licensing Board Panel. 1p. 19346: 355. 24X Fiche: 50-440,83/07/06,8307080468.

8307190325 Motion for extension, until 830721, to file proposed findings of fact & conclusions of law w/supporting citations & argument. Certificate of Svc encl.

LODGE, T. J. Bunflower Alliance. LODGE, T. J. Lodge, T. J. 83/07/11.

Atomic Safety and Licensing Board Panel. 2pp. 19538:252. 24X

Fiche: 50-440,83/07/11,8307150325.

B307190114 Proposed findings of fact & conclusions of law for Issue 3 re adequacy of GA program & control of const contractors. Applicant failed to resolve issue at 830524-27 public hearing. Certificate of Svc encl. HIATT, S. L. Dhio Citizens for Responsible Energy. 83/07/11. 36pp. 19634: 286. 24X Fiche: 50-440, 83/07/11, 8307190114.

B307140430 Memorandum & order denying admission of Ohio Citizens for Responsible Energy B30510 contentions to block util receipt of unirradiated reactor fuel & associated matls.Late-filed requirements not met.
BLOCH.P. B. KLINE.J.R., BRIGHT.G.O. Atomic Safety and Licensing Board Panel. 83/07/12. 7pp. 19521:169. 24X Fiche: 50-440,83/07/12. 8307140430.

8307150316 Answer opposing Ohio Citizens for Responsible Energy 830630 motion to strike portions of applicant 830627 answer in support of NRC motion for summary disposition of Issue 13. Motion has no basis. Certificate of Svc encl.
SWIGER.M. A. Cleveland Electric Illuminating Co. SWIGER.M. A. Shaw. Pittman. Potts & Trombridge. 83/07/12. Atomic Safety and Licensing Board Panel. 7pp. 19533:011. 24X Fiche: 50-440, 83/07/12, 8307150316.

8307190186 Motion to reopen record on Issue 3 rs const QA.Motion based on recently received documents obtained through FOIA which indicate QA deficiencies are much worse than recent hearing revealed. Certificate of Svc encl.

HIATT, S. L. Ohio Citizens for Responsible Energy. 83/07/13.

Atomic Safety and Licensing Board Panol. 24pp. 19630:144. 24X

Fiche: 50-440,83/07/13,8307190186.

8307190222 Response opposing applicant B30627 answer supporting NRC motion for summary disposition of Issue 13.NRC must abide by SRP & Rog Guide 1.115. Regulatory policy changes cannot be made merely for convenience. Certificate of Svc encl. HIATT.5. L. Dhio Citizens for Responsible Energy. B3/07/13. Atomic Safety and Licensing Board Panel. 3pp. 19629:222. 24X Fiche: 50~440.83/07/13.8307190222.

8307270287 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
BILBERGO, J. E. Shaw, Pittman, Potts & Trowbridge. B3/07/13.
BLOCH, P. B., KLINE, J. R., BRIGHT, G. D. Atomic Safety and Licensing Board Panel. 1p. 19767:178. 24X Fiche: 50-440, 83/07/13, 8307270287.

- --B307270477 Notifies of employment at law firm VR Harding will not participate in any case pending before NRC Svc list encl. HARDING, V. R. Shaw. Pittmen, Potts & Troubridge. 83/07/13. BLOCH, P. B., KLINE, J. R., BRIOHT, O. D. Atomic Safety and Licensing Board Panel. 2pp. 19767:199. 24X Fiche: 50-440, B3/07/13, B307270287.
- 8307190203 Motion for leave to file answer to Ohio Citizens for Responsible Energy 830829 amended response to NRC motion for summary disposition of Issue 13,per ASLB 821006 memorandum & order.

  81LBERG, J. E. Cleveland Electric Illuminating Co. SILBERG, J. E. Bhaw, Pittman, Potts & Trambridge. 83/07/14. Atomic Safety and Licensing Board Panel. 2pp. 19828:289. 24% Fiche: 50-440,83/07/14,8307190203.
- --B307190208 Answer to Ohio Citizens for Responsible Energy (OCRE) 830629 amended response to NRC motion for summary disposition of Issue 13.0CRE request for continuance is frivolous & should be denied. Certificate of Svc encl.
  SILBERG.J.E. Cleveland Electric Illuminating Co. SILBERG.J.E. Shaw, Pittman, Potts & Trowbridge. 83/07/14. 13pp. 19628:271. 24X Fiche: 50-440, 83/07/14, 8307190203.
- 8307190084 Response to ASLB 830509 telcon questions re declaration of sua sponte issues. Encl AF Silakoski affidavit responds to ASLB inquirtes. SILBERG, J. E. Cleveland Electric Illuminating Co. SILBERG, J. E. Shaw, Pittman, Potts & Trombridge. 83/07/15. lp. 19635:175. 24X Fiche: 50-440.83/07/15,8307190084.
- --B307190104 Affidavit of AF Silakoski in response to ASLB sua sponte questions. Simulator operator training includes comparing & contrasting indications of all related instrument types & ranges. W/Certificate of Svc.
  SILAKOSKI, A.F. Cleveland Electric Illuminating Co. 83/07/14.
  7pp. 19635:176. 24X Fiche: 50-440, 83/07/19, 8307190084.
- 8307200214 Proposed findings of fact & conclusions of law Certificate of Bvc encl.
  LODGE-T.J. Sunflower Alliance. LODGE-T.J. Lodge, T.J. 83/07/15, 17pp. 17648: 033. 24X Fiche: 50-440, 83/07/15, 8307200214.
- B307210179 Answer to applicant 830714 motion for leave to file answer to intervenor amended response to NRC motion for summary disposition of Issue 13. Rules allow for no further response. Certificate of Svc encl. Related correspondence. HIATT.S.L. Ohio Citizens for Responsible Energy. B3/07/18. Atonic Safety and Licensing Board Panel. 2pp. 19666:040. 24X Fiche: 50-440, 83/07/18.8307210179.
- B307210305 Answer opposing Dhio Citizens for Responsible Energy B30630 motion to strike portions of applicant B30627 answer supporting NRC B30531 motion for summary disposition of Issue 13. Certificate of Svc anci. CUTCHIN.J.M. Hearing Branch 4. B3/07/20. Atomic Safety and Licensing Board Panel. 5pp. 19664:353. 24X Fiche: 50-440.83/07/20.8307210305.
- B307260294 Memorandum in support of Ohio Citizens for Responsible Energy B30713 motion to reopen record on Issue 3 re QA. Certificate of Svc encl. LODGE.J.L. Buflower Alliance. LODGE.J.L. Wilt, D.D. 83/07/21. Atomic Bafety and Licensing Board Panel. 4pp. 19811:002. 24X Fiche: 30-440, B3/07/21, B307260294.
- 8307230360 Proposed findings of fact & conclusions of law on Issue 3 re QA. Certificate of Svc encl. CUTCHIN.J.M. Hearing Branch 4. 83/07/22. 23pp. 19703:215. 24X Fiche: 50-440,83/07/22,8307250360.
- B307270246 Answer supporting util 830714 motion for leave to file answer to Ohio Citizens for Responsible Energy B30629 amended response to NRC B30531 motion for summary disposition of Issue 13. Certificate of Svc encl. CUTCHIN.J.M. Hearing Branch 4. S3/07/26. Atomic Safety and Licensing Board Panel. Spp. 19767:106. 24X Fiche: 50-440, 83/07/26, 8307270246.
- 8307270250 Answer opposing Ohio Citizens for Responsible Energy 830713 motion to reopen record on Issue 3. Citizens fail to demonstrate motion timely ratises significant safety issue or is likely to change result. Certificate of 8tc encl. CUTCHIN. J.M. Hearing Branch 4. 83/07/26. Atomic Safety and Licensing Board Panel. Spp. 19749:306. 24X Fiche: 50-440, 83/07/26, 8307270250.

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307210077 Forwards Amend 12 to FSAR. Amend incorporates previously submitted response to GA branch questions & revises mechanical sys & components, conduct of operations & GA, EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/07/19, EDENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19660:273. 24X Fiche: 50-440, 83/07/19, 8307210077.
- --8307210081 Amend 12 to FBAR. # Cleveland Electric Illuminating Co. 83/07/19. 380pp 19640:276. 24X Fiche:50-440,83/07/19.8307210077.
- Q. Inspection reports, IE Bulletins & correspondence
- B30708044B Ack receipt of 830628 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-12 & 50-441/83-11.

  LITTLE: W. S. Region 3, Office of Director. B3/07/05. EDELMAN, M. R. Cleveland Electric Illuminating Co. 1p. 19347: 225. 24X Fiche: 50-440, B3/07/05, B30708044B.
- ---B3070B0451 Responds to NRC B30603 ltr re violations noted in IE Imap Repts 50-440/83-12 & 50-441/83-11. Corrective actions: Johnson Controls, Inc reindoctrinated affected personnel in GC procedures required for insp & documentation. EDELMAN, M. R. Cleveland Electric Illuminating Co. B3/06/28. KEPPLER, J. G. Region S. Office of Director. 2pp. 19347: 226. 24X Fiche: 50-440, 89/07/05, 8307080448.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list enci.
  JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Ficha: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORBAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Cassous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- 8307280247 Forwards IE Insp Repts 50-440/83-19 & 50-441/83-18 on 830620-24 & notice of violation.
  LITTLE:W.S. Region 3, Office of Director. 83/07/15. EDELMAN:M.R. Cleveland Electric illuminating Co. 2pp. 19791:211. 24X
  Fichs: 50-440,83/07/15,8307280247.
- --8307280253 Notice of violation from insp on 830620-24. LITTLE.W.S. Region 3. Office of Director. 83/07/15. ip. 19791:213. 24X Fiche: 50-440.83/07/15.8307280247.
- --8307280264 IE Insp Rept 50-440/83-19 & 50-441/83-18 on 830620-24.

  Noncompliance noted:safety-related instrument panel

  IM22-P015 removad w/o rework procedure.

  MERRIMEATHER, N. Region 2, Office of Director. CONLON, T.E.

  Division of Engineering & Radiological Safety Programs. 83/07/11.

  6pg. 19791:214. 24X Fichs:50-440,83/07/15,8307280247.
- 8307280437 Forwards IE Insp Repts 50-440/83-13 & 50-441/83-12 on 830404-0615 & notice of violation.
  STREETER.J.F. Region 3, Office of Director. 83/07/25, EDELMAN.M.R. Cleveland Electric Illuminating Go. 2pp. 19796: 286. 24X
  Fiche: 50-440.83/07/25.8307280437.
- --8307280439 Notice of violation from insp on 830404-0615. STREETER, J. F. Region 3, Office of Director. 83/07/25. 1p. 19776: 288. 24X Fiche: 50-440, 83/07/25, 8307280437.
- --8307280442 IE Insp Repts 50-440/83-13 & 50-441/83-12 on 830404-0615.

  Noncompliance noted: failure to periodically assess adequacy of program.

  KISH, J. N., MAXWELL, Q. F., VANDEL, T. E. Region 3, Office of Director, 83/07/25, 11pp. 19796: 289. 24X Fiche: 50-440, 83/07/25, 8307280437.

1. - MHZ

- S. Reportable occurrences, LERs & related correspondence
- 8307060045 Interim deficiency rept re Johnson Controls, Inc failure to adequately verify acceptability of Unistrut Corp GA program. Initially reported on B30327 Corrective Action Request B3-03 issued. Final rept by B30730.

  EDELMAN.M.R. Cleveland Electric Illuminating Co. B3/06/24.

  KEPPLER, J. G. Region 3, Office of Director. 2pp. 17250: 357. 24X

  Fiche: 50-440, 83/06/24, 8307060065.
- 8307070001 Part 21 rept re lack of automatic restart capabilities of P-47 chillers after loss of offsite power. Initially reported on 830429. Evaluation continuing.

  BARKER, N. R. 011bert/Commonwealth Cos. 83/06/30. DEYOUNG. R. C. Director's Office. Office of Inspection and Enforcement. 1p. 17273:158. 247 Fiche: 50-440.83/06/30.8307070001.
- 8307110134 Second interim deficiency rept re violation of spec requirements during installation of adjacent Hilti Kwik bolts. Initially reported on 830207. Spec SP108/208 revised. Final rept by 830930. EDELMAN. M. R. Clevaland Electric Illuminating Co. 83/07/01. KEPPLER. J. G. Region 3, Office of Director. 2pp. 19375: 126. 24X Fiche: 50-440, 83/07/01, 8307110134.
- 8307110316 Final deficiency rept re ASME Code Section III, Class 3 piping supports supplied by Transamerica Delaval, Inc. Initially reported on 8302823. Revised drawings detailing mods supplied by Delaval, EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19380: 361. 24X Fiche: 50-440,83/07/01,8307110316.
- 8307110382 Third interim Significant Deficiency Rept RDC 64(83) re linear indications in bracket welds for main steam & recirculation sys pipe whip restraints. Initially reported on 821228. Completion of corrective actions by 841215. EDELMAN, J. O. Clevaland Electric Illuminating Co. 83/07/01. KEPPLER, J. O. Region 3, Offics of Director. 2pp. 19380:338. 24X Fiche: 50-440,83/07/01,8307110382.
- 8307190038 Interim Deficiency Rept RDC 24(81) re defect in lubricating oil sys standyby diesel generators. Installation of replacement parts will begin upon completion of code piping weid repairs & will be completed by Feb 1984. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J. G. Region 3, Office of Director. 1p. 19635:047. 24X Fiche: 50-440.83/07/01,8307190038.
- 8307190136 Interim deficiency rept re relocation of Qovernor lube oil coolers/standby diesel generator. Oovernors returned to Transamerica DeLaval. Corrective actions on coolers will not be complete until Nov 1983 for Unit 1 & Jan 1984 for Unit 2. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/01. KEPPLER.J.G. Region 3, Office of Director. 1p. 19636:105, 24X Fiche: 50-440.83/07/01.8307190136.
- 8307190176 Suppl to 821215 final deficiency rept re standby diesel generators. Model DSRIVI6. starting air sys check valve. Valves returned to Transamerica DeLaval remfg of internal components. Mode will be completed by Dec 1983.

  EDELMAN. M. R. Cleveland Electric Illuminating Co. 83/07/01.

  KEPPLER. J. Q. Region 3, Office of Director. 1p. 19632:114. 24X Fiche: 50-440.83/07/01.8307190176.
- B307190204 Interim Deficiency Rept RDC 52(82) re discrepancies in documentation package used to track repair work for skid-mounted piping. Correction of discrepancies expected to be completed by B31201.

  EDELMAN. M.R. Cleveland Electric Illuminating Co. B3/07/01, KEPPLER. J.G. Region 3, Office of Director. ip. 19628:317. 24X Fiche: 50-440, 83/07/01, 8307190204.
- 8307180031 Interim deficiency rept re partial blockage found in porous concrete pipes & weepholes associated w/pumping drain sys portion of pressure relief underdrain sys. Initially reported on 830610. Investigation underway. Final rept due 831101. EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/08. KEPPLER.J.O. Region 3, Office of Director. 2pp. 19560:207. 24X Fiche: 50-440,83/07/08,8307180031.
- 8307200289 Interim Deficiency Rept RDC 73(83) re Borg-Warner valve radiographs. Forty-four valves selected as representative sample reradiographed by Magnaflux Corp. Radiographs submitted to Borg-Warner for review. Final rept by 830831. EDELMAN. M. R. Cleveland Electric Illuminating Co. B3/07/11. KEPPLERIJ. G. Region 3, Office of Director. 1p. 19648:064. 24X Fiche: 50-440, 83/07/11, 8307200289.

- 8307220434 Interim deficiency rept re HPCS diesel generator electrical panels supplied by GE. Initially reported on B30615. Ring lug terminations will be replaced. Next rept will be submitted by B40406.

  EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/07/15.

  KEPPLER.J.G. Region 3. Office of Director. 2pp. 19687: 327. 24X

  Fiche: 30-440, 83/07/15, 8307220434.
- T. Hearing transcripts on non-antitrust matters
- 830706023B Proposed corrections to 830527 hearing transcript.

  Certificate of Svc encl.

  SILBERG, J. E. Cleveland Electric Illuminating Co. 8ILBERG, J. E.

  8haw. Pittman, Potts & Trombridge. 83/07/01. 8pp. 19239: 266. 24X

  Fiche: 50-440.83/07/01.8307060238.
- DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for QLs & holders of CPs for Mestinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT.D. G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- B307040035 Forwards "Evaluation of Cost & Schedule Estimate of Seabrook Nuclear Project." DEVINCENTIS, J. Yanker Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. B3/06/21. KNIGHTON, G.W. Licensing Branch 3. ip. 17250: 270. 24X Fiche: 50~443, B3/06/21, 8307060035.
- --8307060043 "Evaluation of Cost & Schedule Estimate of Seabrook Nuclear Project." \* Management Analysis Co. 83/05/24, 44pp. 19250; 291, 24X Fiche: 50-443, 83/06/21, 8307060035.
- 8307140149 Discusses facility const completion date as result of site visit & mgt meeting re present activities. Unit will be ready for fuel loading during First Guarter 1986.
  EIBENHUT, D. G. Division of Licensing. 83/06/24. HARRISON, R. J. Public Service Co. of New Hampshire. 3pp. 19840:026. 24X Fiche: 50-443,83/06/24,8307140149.
- 8306270397 Oeneric Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, 8vc list enci. EISENHUT, D. Q. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270377.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Evc list encl. EISENHUT. D. Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24x Fichs: 50-000,83/07/06,8307060329.
- B307200550 Notification of B30712 meeting w/util in Bethesda.MD to discuss Dayton Bar-Grip method of splicing reinforcing bars for future application at facility.
  VIETTI.A. Licensing Branch 3. B3/07/06. KNIGHTON.G.W. Licensing Branch 3. 4pp. 17672:278. 24X Fiche: 50-443,83/07/06,8307200550.
- B307220027 Notification of B30713 meeting w/util in Bethesda, MD to discuss alternative designs for stone revetment. VIETTI.A. Licensing Branch 3. 83/07/06. KNIGHTON, G. W. Licensing Branch 3. 4pp. 17672:127. 24X Fiche: 30-443, B3/07/06, B307220027.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl. EIBENHUT.D. 9. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 19669:269. 24x Fiche: 30-000, 83/07/08. 8307080169.
- 8307200498 Forwards request for add1 info re util request for authorization to use Dayton Bar Grip sys. Questions will provide framework for discussions at 830712 meetings. KNIGHTON, G. H. Licensing Branch 3. 83/07/08. HARRISON, R. J. Public Service Co. of New Hampshire. 6pp. 19671:350. 24X Fiche: 50-443, 83/07/08, 8307200498.
- 8307130142 Application for amend to CPPR-135 & CPPR-136, consisting of Amend 49 to FSAR.

  JUNSON, W.P. Public Service Co. of New Hampshire. B3/07/11.

  KNIGHTON, G.W. Licensing Branch 3. 3pp. 19533:244. 24X

  Ficha: 50-443

- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307130448 Forwards Suppl 2 to SER for concurrence Requests concurrence by signing mean & returning to NRC no later than 830624. H/o and l
  - anci, NOVAK,T.M. Assistant Director for Licensing. 83/06/23. KNIGHT,J.P. Assistant Director for Comp. & Structures Engineering (Post 830201). MULLER.D.R. Assistant Director for Radiation Protection. LESSY,R.P. Office of the Executive Legal Director. 1p. 19340:224. 24X Fiche: 50-443,83/06/23,8307150448.
- 8307060127 Forwards revised response to SER Outstanding Issue 1 re meteorological conditions considered in auxiliary sys & component design-reflecting 830518 discussions. Response will be incorporated in Amend 49 to OL application.

  DEVINCENTIS. J. Yankes Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. B3/06/24. KNIGHTON, G. N. Licensing Branch 3. 12pp. 19252: 227. 24X Fiche: 50-443, 83/06/24, 8307060129.
- 8307040090 Responds to Suppl 1 to SER & Generic Ltr 82-33, Suppl 1 to NUREO-0737 re emergency classification sys. Encl Section 5.0 will be incorporated in Amend 49 to OL application. DEVINCENTIS.J. Yankes Atomic Electric Ca. DEVINCENTIS.J. Public Service Co. of New Hampshire. 83/06/27. KNIGHTON.O.W. Licensing Branch 3. 18pp. 19251:149. 24X Fiche: 50-443, 83/06/27, 8307060090.
- B307190446 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION.UNITS 1 AND 2 Dockets No. 50-443 And 50-444. (Public Service Company of New Hampshire et al.)

  # Division of Licensing. NUREO-0876 S02. B3/06/30. 18pp. Available at NRC. \$3.25. 19569:285. 24X Fiche:50-444,83/06/30. B307190446.
- 9307120312 Forwards "Seabrook Station Control Room Design Review," per NUREO-0737: Item I.D. 1 & Suppl 1 to NUREO-0737 (Generic Ltr 82-33) re emergency response & SER (NUREO-0896) Gutstanding Item 19 Section 18.

  DEVINCENTIS, J. Yankes Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/07/07. KNIGHTUN, O. H. Licensing Branch 3. 140pp. 19430: 268. 24X Fiche: 50-443, 83/07/07, 8307120312.
- 8307250098 Forwards Suppl 2 to SER (NUREG-0896) re application for OL. W/o enci. KNIGHTON, C.H. Licensing Branch 3. 83/07/13. HARRISON, R.J. Public Service Co. of New Hampshire. 4pp. 19738: 055. 24X Fiche: 50-443, 83/07/13, 8307250098.
- F. Security, medical, emergency & fire protection plans
- 8307060127 Forwards revised response to SER Outstanding Issue 1 remeteorological conditions considered in auxiliary sys & component design reflecting 830518 discussions Response will be incorporated in Amend 49 to OL. application.

  BEVINCENTIS.J. Yankee Atomic Electric Co. DEVINCENTIS.J. Public Service Co. of New Hampshire. 83/06/24. KNIGHTON.C.W. Licensing Branch 3. 12pp. 19252:227. 24X Fiche: 50-443.63/06/24.8307040127.
- 8307060090 Responds to Suppl 1 to SER & Generic Ltr 82-33, Suppl 1 to MUREO-0737 re energency classification sys. Encl Section 5.0 will be incorporated in Amend 49 to OL application DEVINCENTIS.J. Yankbe Atomic Electric Co. DEVINCENTIS.J. Public Service Co. of New Hampshire. 83/06/27. KNIGHTON.G. W. Licensing Branch 3. ISpp. 19251:149. 24X Fiche: 50-443,83/06/27,8307060090.
- 8307120312 Forwards "Seabrook Station Control Room Design Review," per NUREO-0737. Item I.D. 1 & Suppl I to NUREO-0737 (Generic Ltr 82-33) re emergency response & SER (NUREO-0876) Outstanding Item 19 Section 18.

  DEVINCENTIS, J. Yankee Atomic Electric Co. BEVINCENTIS, J. Public Service Co. of New Hampshire. 83/07/07. KNIGHTON. 0. W. Licensing Branch 3. 140pp. 19420:268. 24X Fiche: 50-443.83/07/07,8307120312.
- 8307210185 Forwards applicant direct Testimony 1. Exhibit 3 qualifications of DA Maidrand will be served by 830719. Certificate of Svc encl. GAD.R. R. Ropes & Gray. GAD.R. R. Public Service Co. of New Hampshire. 83/07/15. Office of the Secretary of the Commission. ip. 19665: 241. 24X Fiche: 50-443, 83/07/15, 8307210185.
- --8307210200 "Evacuation Clear Time Estimates for Areas Near Seabrook Station." \* HMM Associates: Inc. 83/07/31, 92pp. 19665:285, 24X Fiche: 50-443,83/07/15,8307210185.
- G. Adjudicatory correspondence
- B307220373 Advises that more work needed before draft smargancy response plan can be submitted to federal authorities.

  MACGREGOR.N.: STEVENS, G. P., WATERHOUSE, G. A. Merrimac, MA. B3/06/27.

  LOMASNEY, M. Costello, Lomasney & deNapoli, Inc. 2pp. 17686:186.

  24X Fiche: 50-443, 83/06/27, 8307220373.

- 8307050203 Motion to defer hearing on evacuation time estimates, Contentions III.12 & III.13, until hearing on offsite emergency planning. Delay necessary to provide ASLB w/testimony on all contentions. Certificate of Svc encl. SHOTMELL.J.A. Massachusetts, Commonwealth of, 83/06/28, Safety and Licensing Board Panel. 7pp. 19198:278. 24x Fiche: 50-443, 83/06/28, 8307050203. Atomic
- 8307060162 Answers to motion to defer hearing on evacuation time estimates & motion for time extension to file rebuttal testimony on evacuation time estimate contentions. Opposes deferral motion. Certificate of Svc encl.

  GAD.R.K. Public Service Co. of New Hampshire. GAD.R.K. Ropes & Gray. 83706/30. Atomic Safety and Licensing Board Panel. 14pp. 19249: 190. 24X Fiche: 50-440.83/06/30,8307060162.
- 8307060203 Supplemental response to Interrogatory 30. Certificate of SVC enc). JOHNSON, W. P. JOHNSON, N.P. Public Service Co. of New Hampshire. 83/00 England Coalition on Nuclear Pollution. Sap. 19250:218. Fiche: 50-443, 83/06/30, 8307060203. 83/04/30
- 8307060394 Memorandum & order granting portion of util 830214 21st motion for summary disposition. Util 830214 seventh motion for summary disposition granted. New England Coalition on Nuclear Pollution Contentions III. 12 & III. 13 dismissed. HOYT.H.F. Atomic Safety and Licensing Soard Panel. 83/06/30. Public Service Co. of New Hampshire. 16pp. 19236:101. 24X Fiche: 50-443, 83/06/30, 8307060394.
- 8307060421 Advises that Commission decision to review ALAB-687 should be considered in addressing ASLB 830620 memorandum & order, second question, at 830713 oral argument. SHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 83/06/30. CURRAN.D. Harmon & Weiss. GAD.R.K. Ropes & Gray. LE88Y.R.P. Hearing Branch 3. ip. 19239:336. 24X Fiche: 50-443,83/06/30,8307060421.
- 8307070174 Advises that Town of Amesbury draft radiological emergency plan seriously deficient. Emergency response organization violates current chain of command. Public alert sys info unclear. Related correspondence.

  BROWN.R.B. Amesbury, MA. 83/06/30, LOMASNEY, M. Costello, Lomasne debugging in the command of the comm
- 8307070214 Advises that author will represent New England Coalition on Nuclear Pollution at 830713 oral argument re Goalition patition for directed certification. Related correspondence. CURRAN, D. Harmon & Weiss. CURRAN, D. New England Coalition on Nuclear Pollution. 83/07/01. TOMPKINS, B.A. Atomic Safety and Licensing Appeal Panel. 1p. 19267:313. 24X Fiche: 50-443,83/07/01,8307070214.
- 8307070016 Advises that RP Lessy will present NRC oral argument re New England Coalition on Nuclear Pollution petition for directed certification. LESSY, R.P. Hearing Branch 3. B3/07/05. RGSENTHAL, A. S., EDLES, O. J., WILBER, H. A. Atomic Safety and Licensing Appeal Panel. 2pp. 19293: 228. 24X Fiche: 50-443,83/07/05,8307070016.
- B307120444 Response to Seacoast Anti-Pollution League contentions on State of NH radiological emergency response plan No objections made to Contentions 3, 5, 6 & 8. Certificate of Syc encl. enci. DigNAN,T.G., GAD,R.K. Public Service Co. of New Hampshire. DigNAN,T.G. Ropes & Gray. 83/07/05. Atomic Safety and Licensing Board Panel. 6pp. 19425:337. 24X Fiche:50-443,83/07/05,8307120444.
- 8307080456 Memorandum & order denying State of NH 830526 objections to ASLB 830511 memorandum & order granting summary disposition of State of NH Contentions 9 & 13.
  HOYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/06. New Hampshire, State of, 9pp. 19347:228. 24X Fiche: 50-443,83/07/06.
- 8307120379 Response to New England Coalition on Nuclear Pollution contentions on State of NN radiological emergency response plan. No objections made to Contentions 2,4-9 or 12-13. Certificate of Svc encl.
  DIGNAN.T. G., GAD.R.K. Public Service Co. of New Hampshire.
  DIGNAN.T. G., Ropes & Gray. 83/07/11. Atomic Safety and Licensing Board Panel. 7gp. 19429:007. 24X Fiche: 50-443.83/07/11,8307120379.
- 8307120363 Response to State of NH 030623 contentions re emergency planning for state. State of MA has no standing to raise contentions. Certificate of Svc encl. DIQNAN.T.G., DIONAN.T.G. Public Service Ca. of New Hampshire. CAD.R.K. Ropes & Oray, 83/07/11. Atomic Safety and Licensing 8307120383.

- B307130201 Memorandum forwarding final schedule for Aug 1983 hearings.
  Hearings commence on B30817 & limited appearance session
  rescheduled for B30831. Last wk of hearings eliminated.
  HOYT. H. F. Atomic Bafety and Licensing Board Panel. 83/07/i1. 2pp.
  19465:354. 24X Fiche: 50-443,83/07/i1,8307130201.
- B307130250 Notice of B30817-19, 23-26 & 30-0902 first phase hearings in Dover, NH. Limited appearances will be taken on 830820, 23, 26 & 31.

  HDYT.H.F. Atomic Bafety and Licensing Board Panel. 83/07/11. 5pp. 19507: 332. 24X Fiche: 50-443, 83/07/11, 8307130250.
- 8307130283 Response to State of MA. Seacoast Anti-Pollution League & New England Coalition on Nuclear Pollution 830622. 23 & 27 contentions, respectively re State of NH radiological emergency response plan. Certificate of Svc encl. PERLIS.R. 9. PATTERSON. M. F. Hearing Branch 3. 83/07/12. Atomic Safety and Licensing Board Panel. 24pp. 19508:214. 24x Fiche: 50-443,83/07/12,8307130283.
- 8307200220 Requests extension of 830714 deadline to submit draft Newburyport. MA radiological emergency response plan to FEMA or NRC. Plan incomplete. Routos, evacuation time estimates or guidelines not received. Related correspondence. BROAT.L. B. Newburyport: MA. 83/07/13. Costello, Lomasney & deNapoli, Inc. ip. 19648:052. 24X Fiche: 50-443,83/07/13, 8307200220.
- B307190150 Response opposing Commonwealth of MA B30628 motion to defer litigation of New England Coalition on Nuclear Pollution Contentions III. 12 & III. 13 re evacuation time estimates. Hearing deferral unnecessary. Certificate of Svc encl. PERLIS.R.O., LESSY.R.P. Hearing Branch 3, 83/07/15. Atomic Safety and Licensing Board Panel. 9pp. 19636:197. 24X Fiche: 50-443,83/07/15,8307190130.
- B307190212 Answer to applicant response to Commonwealth of MA 830623 contentions on emergency planning Commonwealth has standing as full party. Issues are within ABLB subj matter jurisdiction.

  SHOTMELL, J. A. Massachusetts, Commonwealth of. B3/07/15. Atomic Safety and Licensing Board Panel. 19pp. 19629:080. 24X Fiche: 30-443, 83/07/15. B307190212.
- --8307190214 Petition for directed certification to ASLB of 830630 memorandum & drder summarily dismissing New England Coalition on Nuclear Pollution Contentions III. 12 & 13 re evacuation time estimates.

  SHOTHELL.J.A. Massachusetts: Commonwealth of. 83/07/15, Atomic Safety and Licensing Appeal Panel. 36pp. 19629:099. 24X Fiche: 50-443, 83/07/15, 8307190212.
- --8307170220 Contention on applicant evacuation time estimates for beach areas.

  8HOTHELL.J.A. Massachusetts, Commonwealth of, 83/07/15.

  Atomic Bafety and Licensing Board Panel. 5pp. 19629: 135. 24X

  Fiche: 50-443, 83/07/15, 8307170212.
- ---8307190225 Testimony of R Mark re New England Coalition on Nuclear Pollution Contentions III.12 & III.13 Discusses concerns re evacuation of beach area. MARK.R. Massachusetts, Commonwealth of . MARK.R. Hampton, NH. 83/07/15. 10pp. 19627:140. 24X Fiche: 50-443, 83/07/15, 8307190212.
- --8307190241 Testimony of PB Herr re New England Coalition on Nuclear Pollution Contentions III.12 & III.13. Necessity of analyzing adverse weather conditions of summer explained. HERR, P. B. Massachusetts. Commonwealth oft. 83/07/15. 22pp. 19427:150. 24X Fiche: 50-443.83/07/15.8307190212.
- --8307190247 Testimony of A Kuncho re New England Coalition on Nuclear Pollution Contentions III. 12 & III. 13 Concerns re evacuation of beach people discussed Certificate of Svc encl. KUNCHO, A. Massachusetts, Commonwealth of, KUNCHO, A. Hampton, NH. 83/07/15. 9pp. 19629:173. 24X Fiche: 50-443, 83/07/15, 8307190212.
- --8307190254 Testimony of RJ Shahen re New England Coalition on Nuclear Pollution Contentions III.12 & III.13.Night life of Balisbury Beach discussed Certificate of Byc encl. BHAHEN.R.J. Massachusetts, Commonwealth of, 83/07/15. App. 19629:181. 24X Fiche:50-443,83/07/15.8307190212.
- B307200208 Informs that New England Coalition on Nuclear Pollution will not file direct testimony on Contentions I.B.2.III.12 or III.13.

  CURRAN, D. Harmon & Weiss. CURRAN, D. New England Coalition on Nuclear Pollution. B3/07/15. HOYT. H.F., CUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 1p. 19648.027. 24X Fiche: 30-443,83/07/15,8307200208.

- 8307200107 Order denying Commonwealth of MA 830628 motion for deferral of hearings on New England Coalition Against Nuclear Pollution Contentions III. 12 & III. 13. Grants Commonwealth 830628 motion for extension to file rebuttal testimony.
  HOYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/18. 3pp. 19647: 072. 24X Fiche; 50-443, 83/07/18, 8307200107.
- B307200112 Forwards SER, Suppl 2, including ACRS rept W/o encl.
  PATTERSON.W. F. Kearing Branch 3. B3/07/19 HDYT.R., LUEBKE, E. A.,
  HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp.
  17647: O64. 24x Fiche: 50-443, 83/07/19, B307200112.
- 8307210250 Memorandum & Order ALAB-734, denying New England Coalition on Nuclear Pollution petition for directed certification of portion of ASLB 830511 memorandum & order granting summary disposition of Contention II.B.4.

  8/ODEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 83/07/19. New England Coalition on Nuclear Pollution. 13pp. 19644:147. 24X Fiche: 50-443-83/07/19. 8307210250.
- 8307220360 Order directing parties to address Commonwealth of MA 830715 & New England Coalition on Nuclear Pollution 830722 patitions for directed certification of portions of ASLB 830630 order in single response. BHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 83/07/20, 25p. 19676:076. 24% Fiche: 50-443.83/07/20, 8307220340.
- B307220363 Order requesting further filings from Seacoast
  Anti-Pallution League Commonwealth of MA & New England
  Coalition Against Nuclear Pollution allowing redrafting of
  contentions. Filings due within 10 days of svc of order.
  HOYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/20. 2pp.
  19676: 074. 24X Fiche: 50-443, 83/07/20, 8307220363.
- 8307260337 Petition for directed certification of ASLB summary disposition of intervener Contention III.12 re evacuation time estimates. Certification should restore language of contention. Certificate of Svc encl.

  CURRAN, D., JORDAN, W.S. New England Coalition on Nuclear Pollution.

  CURRAN, D. Harmon & Weiss. 83/07/21. Atomic Safety and Licensing Appeal Panel. 16pp. 19726:314. 24X Fiche:50-443,83/07/21, 8307260337.
- 8307260338 Answer to NRC 830712 response to Communwealth of MA Contentions I-V on State of NH radiological emergency response plan. Certificate of Svc encl.

  8HOTHELL, J. A. Massachusetts, Commonwealth of ... 83/07/21. Atomic Safety and Licensing Board Panel. 11pp. 19733:006. 24X Fiche: 50-443, 83/07/21, 8307260358.
- 9307260395 Forwards New England Coalition on Nuclear Poliution response to applicant & NRC objections to contention on State of NH emergency plan. Coalition will negotiate wording of four contentions w/NRC & applicant.

  JORDAN, M. S. Harmon & Weiss. JORDAN, M. S. New England Coalition on Nuclear Pollution. 83/07/22. HOYT, H. F., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 19733.028. 24X Fiche: 50-443, 83/07/22, 8307240395.
- 8307240538 Response to util & NRC objections to New England Coalition on Nuclear Pollution contentions on State of NH state plan.

  All contentions should be admitted.

  JORDAN, M. S., CURRAN, D. New England Coalition on Nuclear Pollution.

  JORDAN, M. S. Harmon & Weiss. 83/07/22. Atomic Safety and

  Licensing Board Panel. 5pp. 19734:119. 24X Fiche: 50-443.83/07/22,
  8307260538.
- 8307260246 Order directing New England Coalition on Nuclear Pollution to Inform ABLB & parties immediately whether Coalition intends to file rebuttal testimony. Procedures for filing testimony listed.

  HOYTH.F. Atomic Safety and Licensing Board Panel. 83/07/25. 2pp. 19727:005. 24X Fiche: 50-443,83/07/25,8307260246.
- 8307260259 Notice of appearance in proceeding Certificate of Svc encl. SNEIDER.C.S. Massachusetts, Commonwealth of, B3/07/25, ip. 19727:039. 24X Fiche: 50-443,83/07/25,B307260259.
- 8307290066 Amend to ASLB 830711 notice of hearing changing place of limited appearance statement to be given on 830826. HOYT.N.F. Atomic Safety and Licensing Board Panel. 83/07/27. 2pp. 19820:360. 24X Fiche: 50-443,83/07/27,8307270066.
- 8307290190 Memorandum amending 830711 hearing schedule. Third limited appearance session will be held in Dover, not Hampton, NH. HOYT. H. F. Atomic Safety and Licensing Board Panel. 83/07/27. 2pp. 19821: 036. 24X Fiche: 50-443, 83/07/27, 8307290150.

#### H. General correspondence

- 8307080429 Advises that draft radiological emergency response plans for Town of Amesbury deficient. Plans should be tailored to town needs & contain detailed info on training. Deficiencies outlined.

  BROWN.R.B. Amesbury, MA. 83/06/30. LOMASNEY.M. Costello, Lomasney & deNapoli, Inc. 2pp. 19347:265. 24X Fiche: 50-443,83/06/30,8307080429.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307130142 Application for amend to CPPR-135 & CPPR-136, consisting of Amend 49 to FSAR.

  JOHNSON.M.P. Public Service Co. of New Hampshire. B3/07/11.

  KN10HTUN.C.W. Licensing Branch 3. 3pp. 19533:244. 24X

  Fiche: 50-443,83/07/11.8307150142.
- --8307150145 Amend 49 to FSAR.

  \* Public Service Co. of New Hampshire. 83/05/31. 484pp.
  19333:247. 24X Fithe: 50-443,83/07/11,8307150142.
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B307070075 Summarizes 276th ACRS meetings on B30414-16 w/utils to review request for OL.Agenda for B30512-14 meetings encl. EBERBOLE, J. ACRS Advisory Committee on Reactor Safeguards, B3704/29. PALLADING, N. J. Commitssioners. 3pp. 19366:038. 24X Fiche: 80-000, B3/04/29, B3070700095.
- G. Inspection reports, IE Bulletins & correspondence
- 8307110422 Forwards IE Mgt Meeting Repts 50~443/83-10 & 50~444/83-07 on 830607. No noncompliance noted Requests high level of mgt attention be devoted to NDE surface exams.
  STAROSTECKI, R. Division of Project & Resident Programs. 83/06/22. HARRISON, R. J. Public Service Co. of New Hampshire. 2pp. 17382:230, 24X Fiche: 50-443, 83/06/22, 8307110422.
- 8307210121 Forwards IE Insp Rept 50-443/83-07 on 830523-27 & notice of violation.

  MARTINIT.T. Division of Engineering & Technical Programs. 83/07/07.

  HARRISON.R.J. Public Service Co. of New Hampshire. 2pp. 19666:068. 24X Fiche:50-443.83/07/07.8307210121.
- --8307210126 Natice of violation from insp on 830523-27.

  \* Region 1: Office of Director. B3/07/07. 2pp. 19666:070. 24X Fiche: 50-443.83/07/07.8307210121.
- --8307210133 IE Insp Rept 50-443/83-07 on 830523-27. Noncompliance noted: failure to perform reactor internals per procedures, to issue process control sheet w/procedure change & to maintain proper storage of reactor internals.

  GRAY.E. H., VARELA.A. A. Region I. Office of Director. 83/06/27.

  7pp. 17666:072. 24X Fiche:50-443,83/07/07.8307210121.
- 8306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:273. 24X Fiche:50-000,83/07/11.B306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JDRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563: 153. 24X Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Ercess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000.83/07/14.8306270406.

#### 8. Reportable occurrences, LERs & related correspondence

- 8307150096 Interim deficiency rept re Westinghouse 7300 process protection sys NLP card heat sinks & NTC card relays. Initially reported on 830216 & 0617. Heat sink replacements to be supplied by vendor. Next rept by 840105.

  DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/07/01. STARGSTECKI, R. Division of Project & Resident Programs. 4pp. 19536:139. 24X

  Fiche: 50-443,83/07/01,8307150096.
- 8307180318 Interim deficiency rept re solid state protection sys power surge. Initially reported on 820805. Westinghouse will supply field kits for permanent hardware mods. Next rept expected by 840105.

  DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Bervice Co. of New Hampshire. 83/07/01. STAROSTECKI.R. Division of Project & Rosident Programs. 4pp. 19356:032. 24X
  Fiche: 50-443,83/07/01.8307180318.
- B307150285 Interim deficiency rept re suspect NDE exams.Pullman-Higgins reexam program evaluation expected by B30730. Next interim rept will be submitted by B30803.

  DEVINCENTIS.J. Yankee Atomic Electric Co. DEVINCENTIS.J. Public Service Co. of New Hampshire. B3/07/05. STAROSTECKI.R. Division of Project & Resident Programs. 3pp. 19531:125. 24X Fiche: 30-443,83/07/05,8307150285.
- 8307140222 Interim deficiency rept re Class IE hydrogen analyzer catalyst contamination by fission-fragment iodine. Initially reported on 830608.84d configuration catalyst bed upgraded as recommended by Comsip. Inc. Next rapt expected by 840120. DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/07/08. 8TAROSTECKI.R. Division of Project & Resident Programs. 3pp. 19523:152. 24X Fiche: 50-443, 83/07/08, 8307140222.
- B307220572 Interim deficiency rept re tornado missile shields for fuel storage bldg. Initially reported on B21110. Probability analyses underway to determine if any potential missile "windows" could be disregarded on basis of low probability. DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. B3/07/14. BTARDSTECKI.R. Division of Project & Resident Programs. 2pp. 19684:305. 24X Fiche: 30-443, B3/07/14, B307220572.
- B307220279 Interim deficiency rept re greater than allowable transverse sheer stresses in concrete beam/cooling tower wall. Initially reported on 830301 Mods to strengthen wall completed final rept by 830613.

  DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. B3/07/15. STAROSTECK1.R. Division of Project & Resident Programs. 2pp. 19675:357. 24X Fiche: 50-443,83/07/15,8307220279.
- 8307220547 Interim deficiency rept re cold pulling of pipe. Initially reported on 821110. Pullman-Higgins continuing review of isometrics. Weld process sheets for determination of closure welds completed. Next rept expected by 831215.

  DEVINCENTIB, J. Yankee Atomic Electric Co. 83/07/15. STARDBTECKI, R. Division of Project & Resident Programs. 2pp. 19684:307. 24X Fiche: 50-443,83/07/15,8307220567.
- T. Hearing transcripts on non-antitrust matters
- 8307130085 Transcript of 830713 oral argument in Bethesda, MD. Pp 1-74. \* Atomic Safety and Licensing Appeal Panel. 83/07/13, 75pp. 19536: 021. 24X Fiche: 50-443, 83/07/13, 8307130085.
- 8307190212 Answer to applicant response to Commonwealth of MA 830623 contentions on emergency planning Commonwealth has standing as full party. Issues are within ABLB subj matter jurisdiction.

  8HOTMELL, J. A. Messachusetts, Commonwealth of, 83/07/15. Atomi Safety and Licensing Board Panel. 19pp. 19629:080. 24X Fiche: 50-443,83/07/15,8307190212.
- --8307190225 Testimony of R Mark re New England Coalition on Nuclear Pollution Contentions III.12 & III.13. Discusses concerns re evacuation of beach area. MARK.R. Hassachusetts. Commonwealth of. MARK.R. Hampton, NH. 83/07/15. 10pp. 19629:140. 24X Fiche: 50-443,83/07/15,8307190212.
- --8307190241 Testimony of PB Herr re New England Coalition on Nuclear Pollution Contentions III.12 & III.19. Necessity of analyzing adverse weather conditions of summer explained. HERR.P. B. Massachusetts, Commonwealth of. 83/07/15. 22pp. 19629.150. 24X Fiche: 50-443,83/07/15,8307190212.

- -8307190247 Testimony of A Kuncho re New England Coalition on Nuclear Pollution Contentions III.12 ½ III.13 Concerns re evacuation of beach people discussed.Certificate of Svc encl. KUNCHO,A. Massachusetts, Commonwealth of. KUNCHO,A. Hampton, NH. 83/07/15. 9pp. 19629:172. 24X Fiche:50-443.83/07/15,
- -- ### --
- ➡307190276 Fawards testimony of JR Sears on Contention NH-20, R9 LaGrange & H Walker on Contention NECNP I. B. 2 & T Urbanik on restated Contention NECNP III. 12/III. 13. LESBY, R.P. Hearing Branch 3. 83/07/15. HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 19632: 079. 24X Fiche: 50-443, 83/07/15, 8307190276.
- ---B307190279 Testimony of JR Sears on Emergency Planning Contention NH-20. Resume encl. SEARS.J.R. Emergency Preparedness Branch. 83/07/15. App. 19432:081. 24X Fiche: 50-443,83/07/15.8307190276.
- - -8307190285 Testimony of T Urbanik on restated Contention NECNP III.12/III.13 re evacuation time estimates.Prof qualifications encl. URBANIK.T. NRC No Detailed Affiliation Given. URBANIK.T. Texas A&M Univ., College Station, TX. 83/07/15. 4pp. 19632:094. 24X Fiche:50-443,83/07/15,8307190276.
- ➡307210185 Forwards applicant direct Testimony 1. Exhibit 3 qualifications of DA Maidrand will be served by 930719. Certificate of Svc encl. GAD.R.K. Ropes & Gray. GAD.R.K. Public Service Co. of New Hampshire. 83/07/15. Office of the Secretary of the Commission. 1p. 19665: 241. 24X Fiche: 30-443, 83/07/15, 8307210185.
  - -8307210191 Direct Testimony ( re environ qualification equipment classification % evacuation time estimates.

    MERRILL, D.N., THOMAS, G.S., DEVINCENTIS, J. Public Service Co. of New Hampshire, 83/07/15, 43pp. 19665:242. 24X

    Fiche: 50-443,83/07/15,8307210165.
- -8307210200 "Evacuation Clear Time Estimates for Areas Near Scattrook Btation." \* HMM Associates, Inc. 83/07/31, 92pp. 19665-285, 24x Fiche: 50-443, 83/07/15, 8307210185,
- #307230374 Forwards Exhibit 3 to applicant 830713 Direct Testimony 1. OAD,R.K. Ropes & Gray. GAD,R.K. Public Service Co. of New Hampshire. 83/07/18. Office of the Secretary of the Commission. 1p. 19705:199. 24% Fiche: 50-443,83/07/18,8307250376.
- CKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2 . Application/construction stage documents & correspondence
- □ O6060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT.D. G. Division of Licensing. 83/04/03. Yankee Atomic EIsethic Co. 10pp. 19563:116. 24X Fiche: 50-000.83/04/03. ⊟306060070.
- 307060035 Forwards "Evaluation of Cost & Schedule Estimate of Beabrook Nuclear Project."
  DEVINCENTIS,J. Yankee Atomic Electric Co. DEVINCENTIS,J. Public Services Co. of New Hampshire. 83/06/21. KNIGHTGN.G.N. Licenting Branch 3. 1p. 17250:270. 24X Fiche:50-443,83/06/21.8307060035.
- \*8307040043 "Evaluation of Cost & Schedule Estimate of Seabrook Nuclear Project." \* Management Analysis Co. 83/05/24. 44pp. 19250:291. 24X Fiche:50-443,83/06/21,8307060035.

- 8306270397 Generic Ltr 83-26 to all applicants for DLs & helders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390.317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees % applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. 5vc list encl.
  EISENNEUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X
  Fiche: 50-000,83/07/06,8307060329.
- 8307200550 Notification of 830712 meeting w/util in Bethesda.MD to discuss Dayton Bar-Grip method of splicing reinforcing bars for future application at facility. VIETTIA. Licensing Branch 3. 83/07/06. KNIGHTON, 0. W. Licensing Branch 3. 4pp. 19672:298. 24X Fiche:50-443,83/07/06.8307200550.
- 8307220027 Notification of 830713 meeting w/util in Bethesda,MD to discuss alternative designs for stone revetment. VIETTI.A. Licensing Branch 3. 83/07/06. KNIGHTON,G.W. Licensing Branch 3. 4pp. 19692:129. 24X Fiche:50-443,83/07/06.8307220027.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 6307200498 Forwards request for add1 info re util request for authorization to use Dayton Bar Grip sys. Questions will provide framework for discussions at 830712 meetings. KNIOHTON.G.W. Licensing Branch 3. 83/07/08. HARRISON.R.J. Public Service Co. of New Hampshire. 6pp. 19671:350. 24X Fiche: 50-443,83/07/08,8307200498.
- 8307150142 Application for amend to CPPR-135 & CPPR-136.consisting of Amend 49 to FSAR.

  JOHNSON, W.P. Public Service Co. of New Hampshire. 83/07/11.

  KNIGHTON, G.W. Licensing Branch 3. 3pp. 19533:244. 24X

  Ficha: 50-443,83/07/11,8307150142.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8307150448 Forwards Suppl 2 to SER for concurrence Requests concurrence by signing memo & returning to NRC no later than 830624.4/o encl. ancl.
  NDVAK.T.M. Assistant Director for Licensing. 83/06/23. KNIGHT.J.P.
  Assistant Director for Comp. & Structures Engineering (Post 830201).
  MULLER.D.R. Assistant Director for Radiation Protection.
  LESSY.R.P. Office of the Executive Legal Director. 1p. 19540:224.
  24X Fiche: 50-443,83/06/23,8307150448.
- 8307060127 Forwards revised response to SER Outstanding Issue 1 re meteorological conditions considered in auxiliary sys & component design, reflecting B30518 discussions. Response will be incorporated in Amend 47 to OL application. DEVINCENTIS, J. Public BEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83706/24. KNIGHTON, G. W. Licensing Branch 3. 12pp. 19252:227. 24X Fiche: 50-443.83/06/24,8307060129.
- 8307060090 Responds to Suppl 1 to SER & Generic Ltr 82-33, Suppl 1 to NUREG-0737 re emergency classification sys. Encl Section 5.0 will be incorporated in Amond 47 to O. application. DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/06/27. KNIGHTON, G. M. Licensing Branch 3. 18pp. 19251:149. 24X Fiche: 50-443.83/06/27,8307060090.
- 8307190446 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION. UNITS I AND 2. Dockets No. 50-443 And 30-444. (Public Service Company of New Hampshire, et al.)

  \* Division of Licensing. NUREG-0876 S02. 83/06/30. 18pp. Available at NRC. \$3.25. 19569:285. 24x Fiche: 50-444,83/06/30,8307190446.
- 8307120312 Forwards "Seabrook Station Control Room Design Review," per NUREO-0737, Item 1. D. 1 & Suppl ! to NUREO-0737 (Generic Ltr 82-33) re emergency response & SER (NUREO-0896) Outstanding Item 19 Section 18, DEVINCENTIS, J. Vankee Atomic Electric Co DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/07/07, KNIGHTON, G. W. Licensing Branch 3. 140pp. 17430:268. 24X Fiche 50-443,83/07/07,8307120312.
- 8307250098 Forwards Suppl 2 to SER (NUREG-0896) re application for OL. N/o encl. RNIGHTON, G. M. Licensing Branch 3. 83/07/13, HARRIGON, R. J. Public Service Co. of New Hampshire. 4pp. 19738-055. 24X Fiche: 50-443, 83/07/13, 8307250098.

- F. Security, medical, emergency & fire protection plans
- 8307060129 Forwards revised response to SER Dutstanding Issue 1 re meteorological conditions considered in auxiliary sys & component design, reflecting 830518 discussions. Response will be incorporated in Amend 49 to DL application. DEVINCENTIS, U. Yankee Atomic Electric Co. 83/06/24, KNIGHTON, G. W. Licensing Branch 3, 12pp. 19252:227. 24X Fiche: 50-443, 83/06/24, 83307060129.
- B307060090 Responds to Suppl 1 to SER & Generic Ltr B2-33, Suppl 1 to NUREO-0737 re emergency classification sys. Encl Section 5.0 will be incorporated in Amend 49 to DL application. DEVINCENTIS. J. Yankee Atomic Electric Co. B3/06/27. KNICHTUN. C. W Licensing Branch 3. 18pp. 19251:149. 24X Fiche: 50-443,83/06/27, 8307060090.
- 8307120312 Forwards "Seabrook Station Control Room Design Review," per NUREO-0737, Item I. D. 1 & Suppl 1 to NUREO-0737 (Generic Ltr 82-33) re emergency response & SER (NUREO-0896) Outstanding Item 17, Section 18.

  DEVINCENTIS, J. Yankee Atomic Electric Co. 83/07/07, KNIGHTON, G. W. Licensing Branch 3. 140pp. 19430:268. 24X Fiche: 50-443, 83/07/07, 8307120312.
- 8307210185 Forwards applicant direct Testimony 1.Exhibit 3 qualifications of DA Maidrand will be served by 830719.

  Certificate of Svc encl.

  GAD.R.K. Ropes & Gray. 83/07/15. Office of the Secretary of the Commission. 1p. 19465: 241. 24X Fiche: 50-443, 83/07/15, 8307210185.
- --8307210200 "Evacuation Clear Time Estimates for Areas Near Seabrook Station." % HMM Associates.Inc. 83/07/31. 92pp. 19665:285. 24X Fiche:50-443.83/07/15.8307210185.
- Q. Adjudicatory correspondence
- 8307220373 Advises that more work needed before draft emergancy response plan can be submitted to federal authorities.

  MACGREODR.N., STEVENS, G.P., WATERHOUSE, G.A. Merrimac, MA. 83/06/27.

  LOMASNEY, M. Costello, Lomasney & deNapoli, Inc. 2pp. 17686:186.

  24% Fiche: 50-443, 83/06/27, 8307220373.
- 8307050203 Motion to defer hearing on evacuation time estimates.
  Contentions III. 12 & III. 13. until hearing on offsite emergency planning. Delay necessary to provide ASLB w/testimony on all contentions. Certificate of Svc encl.
  SHOTMELL.J.A. Massachusetts. Commonwealth of. 83/06/28. Atomic Safety and Licensing Board Panel. 7pp. 19198:278. 24X
  Fiche: 50-443.83/06/28.8307050203.
- B307060162 Answers to motion to defer hearing on evacuation time estimates & motion for time extension to file rebuttal testimony on evacuation time estimate contentions. Opposes deferral motion. Certificate of Svc encl.

  GAD.R.K. Public Service Co. of New Hampshire. GAD.R.K. Ropes & Gray. B3706/30. Atomic Safety and Licensing Board Panel. 14pp 19249: 190. 24X Fiche: 50-443.83/06/30.8307060162.
- 8307060203 Supplemental response to Interrogatory 30. Certificate of Svc encl.
  JDFN800N.H.P. Public Service Co. of New Hampshire. 83/06/30. New England Coalition on Nuclear Pollution. Spp. 19230 218. 24X Fiche: 30-443
- 8307040394 Memorandum & order granting portion of util 830214 21st motion for summary disposition. Util 830214 seventh motion for summary disposition granted. New England Coalition on Nuclear Pollution Contentions III. 12 & III. 13 dismissed. HOYT. H. F. Atomic Safety and Licensing Board Panel. 83/06/30. Public Service Co. of New Hampshire. 14pp. 19236:101. 24X Fiche: 50-443, 83/06/30, 8307060394.
- 8307060421 Advises that Commission decision to review ALAB-687 should be considered in addressing ASLB 830620 memorandum & order, second question at 830713 oral argument. 840EMAKER.C.J. Atomic Safety and Licensing Appeal Panel. 83/06/30. CURRAN.D. Harmon & Weiss. GAD.R.K. Ropes & Gray. LESSY.R.P. Hearing Branch 3. ip. 19239:336. 24X Fiche:50-443.83/06/30, 8307060421.
- B307070194 Advises that Town of Amesbury draft radiological emergency plan seriously deficient Emergency response organization violates current chain of command Public alert sys infounciear Related correspondence.

  BROWN R. B. Amesbury, MA. 83/06/30. LOMASNEY, M. Costello, Lomasney & Jennyoli, Inc. 2pp. 19269: 336. 24X Fiche: 50-443,83/06/30, B307070194.

- B307070214 Advises that author will represent New England Coalition on Nuclear Pollution at B30713 oral argument re Coalition petition for directed certification. Related correspondence. CURRAN. D. Harmon & Weiss. CURRAN. D. New England Coalition on Nuclear Pollution. B3/07/01. TOMPKINS. B. A. Atomic Safety and Licensing Appeal Panel. 1p. 19269:313. 24x Fiche: 50-443.83/07/01. B307070214.
- B307070016 Advises that RP Lessy will present NRC oral argument re New England Coalition on Nuclear Pollution petition for directed certification.
  LESSY.R.P. Hearing Branch 3. 83/07/05. ROSENTHAL, A. S., EDLES, G. J., WILBER, H. A. Atomic Safety and Licensing Appeal Panel. 2pp. 19273: 228. 24x Fiche: 50-443, 83/07/05, 8307070016.
- 8307120444 Response to Seacoast Anti-Pollution League contentions on State of NH radiological emergency response plan. No objections made to Contentions 3,5,6 & B. Cartificate of Svc encl.
  DIONAN, T. G., GAD, R. K. Public Sprvice Co. of New Hampshire.
  DIONAN, T. G., Ropes & Gray. 83/07/05. Atomic Safety and Licensing Board Panel. 6pp. 19425:337. 24X Fiche: 50-443,83/07/05,8307120444.
- 8307080456 Memorandum & order denying State of NH 830526 objections to ASLB 830511 memorandum & order granting summary disposition of State of NH Contentions 9 & 13.

  HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/07/06. New Hampshire, State of, 9pp. 19347:228. 24X Fiche: 50-443, 83/07/06, 8307080435.
- B307120379 Response to New England Coalition on Nuclear Pollution contentions on State of NH radiological emergency response plan. No objections made to Contentions 2.4-9 or 12-13. Certificate of Syc encl. DIGNAN.T.G., GAD, R.K. Public Service Co. of New Hampshire. DIGNAN.T.G. Ropes & Gray. B3/07/11. Atomic Safety and Licensing Board Panel. 7pp. 19429:007. 24X Fiche: 50-443, B3/07/11, B307120379.
- 8307120383 Response to State of NH 830623 contentions re emergency planning for state. State of MA has no standing to raise contentions. Certificate of Svc encl.
  DIGNANAT.G., DIGNANAT.G. Public Service Co. of New Hampshire.
  QAD.R.K. Ropes & Gray.
  83/07/11. Atomic Safety and Licensing Board Panel. 16pp. 19429:014. 24X Fiche: 50-443,83/07/11.
- B307130201 Memorandum forwarding final schedule for Aug 1783 hearings. Hearings commence on B30817 & limited appearance session rescheduled for B30831. Last wk of hearings eliminated. HOYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/11. 2pp. 17465: 334. 24X Fiche: 50-443, 83/07/11, 8307130201.
- 8307130250 Notice of 830817-19,23-26 & 30-0902 first phase hearings in Dover, NH. Limited appearances will be taken on 830820,23,26 & 31.

  HDYT, H. F. Atomic Safety and Licensing Board Panel. 83/07/11, 5pp. 19507:332. 24X Fiche: 50-443,83/07/11,8307130250.
- 8307130283 Response to State of MA. Seacoast Anti-Pollution League & New England Coalition on Nuclear Pollution 830622, 23 & 27 contentions, respectively re State of NH radiological emergency response plan. Certificate of Svc encl. PERLIS.R. O. PATTERSON. W.F. Hearing Branch 3. 83/07/12. Atomic Safety and Licensing Board Panel. 24pp. 19508:214. 24x Fiche: 50-443, 83/07/12, 8307130283.
- 8307200220 Requests extension of 830714 deadline to submit draft Newburyport. MA radiological emergency response plan to FEMA or NRC. Plan incomplete. Routes, evacuation time estimates or guidelines not received. Related correspondence. BROAT.L. B. Newburyport, MA. B3/07/13. Costello, Lomasney & deNapoli, Inc. 1p. 19648:052. 24X Fiche: 50-443, 83/07/13, 8307200220.
- 9307190150 Response opposing Commonwealth of MA 830628 motion to defer litigation of New England Coalition on Nuclear Pollution Contentions III. 12 & III. 13 re evacuation time estimates. Hearing deferral unnecessary. Certificate of Svc encl. PERLIS-R. G., LESSY, R.P. Hearing Branch J. 83/07/15. Atomic Safety and Licensing Board Panel. 7pp. 17636:197. 24X Fiche: 30-443,83/07/15,8307190150.
- B307190212 Answer to applicant response to Commonwealth of MA B30623 contentions on emergency planning Commonwealth has standing as full party. Issues are within ASLB subj matter jurisdiction.
  SHOTWELL, J. A. Massachusetts, Commonwealth of, 83/07/15. Atomi Safety and Licensing Board Panel. 19pp. 19629:080. 24X Fiche:50~443.83/07/15.8307190212.

- --8307190216 Petition for directed certification to ASLB of B30630 memorandum & order summarily dismissing New England Coalition on Nuclear Pollution Contentions III.12 & 13 re evacuation time estimates.

  SHOTMELL.J.A. Massachusetts, Commonwealth of, 83/07/15.
  Atomic Safety and Licensing Appeal Panel. 36pp. 19629:079. 24x Fichs: 50-443, 83/07/15, 8307190212.
- --B307190220 Contention on applicant evacuation time estimates for beach areas.
  SHOTMELL.J.A. Massachusetts, Commonwealth of,. B3/07/15.
  Atomic Safety and Licensing Board Panel. 5pp. 19629:135. 24X
  Fiche: 50-443.B3/07/15,B307190212.
- 8307200208 Informs that New England Coalition on Nuclear Pollution will not file direct testimony on Contentions I.B.2.III.12 or III.13.

  CURRAN.D. Harmon & Weiss. CURRAN.D. New England Coalition on Nuclear Pollution. 83/07/15. HOYT.H.F., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 1p. 19648:027. 24X Fiche: 30-443,83/07/15,8307200209.
- 8307200107 Order denying Commonwealth of MA 830628 motion for deferral of hearings on New England Coalition Against Nuclear Pollution Contentions III. 12 & III. 13 Grants Commonwealth 830628 motion for extension to file rebuttal testimony. HOYT.H.F. Atomic Safety and Licensing Board Panel, 63/07/18, 3pp. 19647:072. 24X Fiche: 50-443, 83/07/18, 8307200107.
- 8307200112 Forwards SER, Suppl 2, including ACRS rept. W/o encl.
  PATTERSON, W. F. Hearing Branch 3. 83/07/19. HOYT, H., LUEBKE, E. A.,
  HARBOUR, J. Atomic Safety and Licensing Beard Panel. 2pp.
  19647:064. 24% Fiche: 50-443
- 8307210250 Memorandum & Order ALAB-734, denying New England Coalition on Nuclear Pollution petition for directed certification of portion of ASLB 830511 memorandum & order granting summary disposition of Contention II.B.4.

  SHOEMAKER.C. J. Atomic Bafety and Licensing Appeal Panel. 93/07/19.

  New England Coalition on Nuclear Pollution. 13pp. 17664; 147. 24X Fiche: 50-443, 83/07/19, 8307210250.
- 8307220360 Order directing parties to address Commonwealth of MA 830715 & New England Coalition on Nuclear Pollution 830722 petitions for directed certification of portions of ASLB 830630 order in single response.

  8HOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel, 83/07/20. 2pp. 17676: 076. 24X Fiche: 50-443, 83/07/20, 8307220360.
- 8307220363 Order requesting further filings from Seacoast
  Anti-Pollution League.Commonwealth of MA & New England
  Coalition Against Nuclear Pollution allowing redrafting of
  contentions.Filings due within 10 days of svc of order.
  HDYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/20. 2pp.
  19676:074. 24X Fiche:50-443.83/07/20.8307220363.
- 8307260337 Petition for directed certification of AGLB summary disposition of intervenor Contention III.12 re evacuation time estimates. Certification should restore language of contention. Certificate of Svc encl.

  CURRAN, D. JÜRDAN, M. S. New England Coalition on Nuclear Pollution.

  CURRAN, D. Harmon & Weiss. 83/07/21. Atomic Safety and Licensing Appeal Panel, 16pp. 19726: 314. 24X Fiche: 50-443, 83/07/21, 8307260337.
- 8307260358 Answer to NRC 830712 response to Commonwealth of MA Contentions I-V on State of NH radiological emergency response plan, Certificate of Svc encl. BHOTNELL.J.A. Massachusetts, Commonwealth of. 83/07/21. Atomic Safety and Licensing Board Panel. 11pp. 19733:006. 24X Fiche: 30-443,83/07/21,8307260358.
- 8307260355 Forwards New England Coalition on Nuclear Pollution response to applicant & NRC objections to contention on State of NH emergency plan Coalition will negotiate wording of four contentions w/NRC & applicant.

  URDAN, W. S. Harmon & Weiss. JORDAN, W. S. New England Coalition on Nuclear Pollution. 83/07/22. HOYT. M. F., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 19733:028. 24X Pichs: 50-443, 83/07/22, 8307260355.
- 8307260538 Response to util & NRC objections to New England Coalition on Nuclear Pollution contentions on State of NH state plan.
  All contentions should be admitted.
  JORDANIM.S., CURRANID. New England Coalition on Nuclear Pollution.
  JORDANIM.S. Harmon & Weiss. 83/07/22. Atomic Safety and
  Licensing Board Panel. 5pp. 19734: 119. 24X Fiche: 30-443,83/07/22,
  B307260538.

- 8307260246 Order directing New England Coalition on Nuclear Pollution to inform ASLB & parties immediately whether Coalition intends to file rebuttal testimony. Procedures for filing testimony listed.
  HOYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/25. 2pp. 19727:005. 24X Fiche: 50-443,83/07/25,8307260246.
- 8307260259 Notice of appearance in proceeding Certificate of Svc encl. SNEIDER.C.S. Massachusetts, Commonwealth of., 83/07/25, 1p. 19727:039. 24X Ficha: 50-443,83/07/25,8307260259.
- 8307290066 Amend to ASLB B30711 notice of hearing changing place of limited appearance statement to be given on 830826. HOYT.H.F. Atomic Safety and Licensing Board Panel. 83/07/27. 2pp. 19820:360. 24X Fiche:50-443.83/07/27.8307290066.
- 8307290150 Memorandum amending 830711 hearing schedule. Third limited appearance session will be held in Dover not Hampton NH. HOYT-M.F. Abomic Safety and Licensing Board Panel. 83/07/27. 2pp. 19821:036. 24X Fiche: 50-443
- H. General correspondence
- 8307080429 Advises that draft radiological emergency response plans for Youn of Amesbury deficient. Plans should be tailored to town needs & contain detailed info on training. Deficiencies outlined.

  BROWN R. D. Amesbury, MA. 83/06/30. LOMASNEY, M. Costello, Lomasney & deNapoli, Inc. 2pp. 19347; 265. 24X Fiche: 50~443, 83/06/30. 8307080429.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 6307150142 Application for amend to CPPR-135 & CPPR-136, consisting of Amend 49 to FSAR.

  JORNSON, M.P. Public Service Co. of New Hampshire. B3/07/11.

  KNIGHTON, 9. M. Licensing Branch 3. 3pp. 19533: 244. 24X

  Fiche: 50-443, 83/07/11, 8307150142.
- --8307190145 Amend 49 to FSAR. \* Public Service Co. of New Hampshire. 83/09/31. 686pp. 19533: 247. 24% Fiche: 50-443,83/07/11.8307150142.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- G307090095 Summarizes 276th ACRS meetings on B30414-16 w/utils to review request for OL. Agenda for B30512-14 meetings encl. EBERSOLE, J. ACRS Advisory Committee on Reactor Safeguards. B3/04/29. PALLADING, N. J. Commissioners. 3pp. 17366:058. 24X Fiche:50-000, B3/04/29, B307090095.
- Q. Inspection reports, IE Builetins & correspondence
- 8307110422 Forwards IE Mgt Meeting Repts 50-443/83-10 & 50-444/83-07 on 830607. No noncompliance moted Requests high level of mgt attention be devoted to NDE surface exams.

  8TAROSTECKI, R. Division of Project & Resident Programs. 83/06/22.

  HARRISON, R. J. Public Service Co. of New Hampshire. 2pp. 19382:230. 24X Fiche: 50-443,83/06/22,8307110422.
- --8307110426 IE Mgt Meeting Repts 50-443/83-10 & 50-444/83-07 on 830607. No noncompliance noted Major areas discussed corrent & proposed licensee actions in response to NRC concerns requestionable conduct of NDE exams by Pullman-Higgins. CERNE, A. C., GRAMN, R. A. Region 1, Office of Director. GALLD, R. M. Division of Project & Resident Programs. 83/06/17. 3pp. 19382:232. 24X Fiche: 50-443,83/06/22,8307110422.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JURDAN.E.C. Division of Emergency Preparedness & Engineering Response (Post, 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC timits." Svc list encl. TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14,8306870406.

- S. Reportable occurrences, LERs & related correspondence
- B307150094 Interim deficiency rept re Westinghouse 7300 process protection sys NLP card heat sinks & NTC card relays. Initially reported on B30216 & 0617. Heat sink replacements to be supplied by vendor. Next rept by B40105. DEVINCENTIS. J. Yantee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. B3/07/01. STAROSTECKI.R. Division of Project & Resident Programs. 4pp. 17536:159. 24X Fiche: 50-443. B3/07/01. B307150096.
- 8307180318 Interim deficiency rept re solid state protection sys power surge. Initially reported on 820805. Westinghouse will supply field kits for permanent hardware mods. Next rept expected by 840105. DEVINCENTIS. J. Yantee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. 83/07/01. STARDSTECKI.R. Division of Project & Resident Programs. 4pp. 19556:052. 24X Fiche: 30-443, 83/07/01, 8307180318.
- 8307150285 Interim deficiency rept re suspect NDE exams Pullman-Higgins regram program evaluation expected by B30730. Next interim rept will be submitted by B30803.

  DEVINCENTIS.J. Yankse Atomic Electric Ca. DEVINCENTIS.J. Public Service Co. of New Hampshire. B3/07/05. STAROSTECKI.R. Division of Project & Resident Programs. 3pp. 17331:125. 24X Fichs: 30-443.83/07/05.8307150285.
- 8307140222 Interim deficiency rept re Class IE hydrogen analyzer catalyst contamination by fission-fragment iodine. Initially reported on 830608. Std configuration catalyst bed upgraded as recommended by Comsip. Inc. Next rept expected by 840120.

  DEVINCENTIS. J. Yantee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/07/08. STAROSTECKI.R. Division of Project & Resident Programs. 3pp. 1923: 152. 24X

  Piche: 30-443.83/07/08.8307140222.
- B307220572 Interim deficiency rept re tornado missile shields for fuel storage bldg. Initially reported on B21110. Probability analyses underway to determine if any potential missile "undows" could be disregarded on basis of low probability. DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. B3/07/14. STARDSTECKI.R. Division of Project & Resident Programs. 2pp. 19684:305. 24X Fiche:30-443:83/07/14.B307220572.
- 8307220279 Interim deficiency rept rs greater than allowable transverse sheer stresses in concrete beam/cooling tower wall. Initially reported on 830301. Mods to strengthen wall completed. Final rept by 830613.

  DEVINCENTIS. J. Yantee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. 83/07/15. STAROSTECKI.R. Division of Project & Resident Programs. 2pp. 19675:357. 24x

  Fiche: 50-443.83/07/15,8307220279.
- 8307220567 Interim deficiency rept re cold pulling of pipe. Initially reported on 821110. Pullman-Higgins continuing review of isometrics. Held process sheets for determination of closure welds completed. Next rept expected by 831215.

  DEVINCENTIS.J. Yankee Atomic Electric Co. 63/07/15. STAROSTECKI.R. Division of Project & Resident Programs. 2pp. 19684:307. 24X Fiche: 30-443,83/07/15.8307220367.
- T. Hearing transcripts on non-antitrust matters
- 8307150085 Transcript of 830713 oral argument in Bethesda, MD. Pp 1-74.

  \* Atomic Safety and Licensing Appeal Panel. 83/07/13. 75pp.
  19536: 021. 24x Fiche: 50-443, 83/07/13, 8307150085.
- B307190212 Answer to applicant response to Commonwealth of MA B30623 contentions on emergency planning.Commonwealth has standing as full party. Issues are within ASLB subj matter jurisdiction.
  SHOTHELL.J.A. Hassachusetts, Commonwealth of, B3/07/15. Atomic S4fety and Licensing Board Panel. 19pp. 19629:080. 24X Fiche: 50-443, B3/07/15, B307190212.
- --8307190225 Testimony of R Mark re New England Coalition on Nuclear Pollution Contentions III. 12 & III. 13. Discusses concerns re evacuation of beach area.

  MARK.R. Massachusetts, Commonwealth of, MARK.R. Hampton, NH. 83/07/15, 10pp. 19629:140. 24X Fiche: 50-443,83/07/15,8307190212.
- --8307190241 Testimony of PB Herr re New England Coalition on Nuclear Poliution Contentions III.12 & III.13. Necessity of analyzing adverse weather conditions of summer explained.

  HERR.P. 8. Hassachusetts, Commonwealth of, 83/07/15. 22pp. 19629:150. 24X Fiche: 50-443.83/07/15.8307190212.

- --8307190247 Testimony of A Kuncho re New England Coalition on Nuclear Pollution Contentions III. 12 & III. 19. Concerns re evacuation of beach people discussed Certificate of Svc encl. KUNCHO. A. Massachusetts, Commonwealth of. KUNCHO. A. Hampton, NH. 83/07/15, 9pp. 19629:172, 24X Fiche: 50-443,83/07/15,8307190212.
- --B307190254 Testimony of RJ Shahen re New England Coalition on Nuclear Pollution Contentions III.12 & III.13. Night life of Salisbury Beach discussed. Gertificate of Svc encl. SHAMEN.R.J. Massachusetts, Commonwealth of. 83/07/15. 6pp. 19629: 181. 24X Fiche: 50-443, 83/07/15, 8307190212.
- 8307190276 Fowards testimony of JR Bears on Contention NH-20, RO Lagrange & H Walker on Contention NECNP I.B. 2 & T Urbanik on restated Contention NECNP III. 12/III. 13. LESSY, R.P. Hearing Branch 3. 83/07/15. HQYT, H., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 19632:079. 24X Fiche: 50-443, 83/07/15, 8307190276.
- --8307190279 Testimony of JR Spars on Emergency Planning Contention NH-20. Resume encl. SEARS.J.R. Emergency Preparedness Branch. B3/07/15. App. 19632: 081. 24X Fiche: 50-443,83/07/15,8307190276.
- --8307190281 Testimony of RG LaGrange & H Walker on Contention NECNP I.B.2. Prof qualifications encl.
  LAORANGE.R.O., MALKER, H. Equipment Qualification Branch.
  83/07/15, 7pp. 19632:087. 24X Fiche: 90-443, 83/07/15, 8307190274.
- --8307190285 Testimony of T Urbanik on restated Contention NECNP III. 12/III. 13 rs syacuation time estimates. Prof qualifications encl. URBANIK.T. NRC - No Detailed Affiliation Given. URBANIK.T. Texas A&M Univ., College Station, TX. 83/07/15, 4pp. 19432:094. 24x Fiche: 50-443, 83/07/15, 8307190276.
- 8307210185 Forwards applicant direct Testimony 1. Exhibit 3 qualifications of DA Haidrand will be served by 830719. Certificate of Svc encl. GAD.R.K. Ropes & Gray. GAD.R.K. Public Service Co. of New Hampshire. 83/07/15. Office of the Secretary of the Commission. 19. 19645:241. 24X Fiche: 50-443, 83/07/19, 8307210185.
- --B307210191 Direct Testimony 1 re soviron qualification equipment classification & evacuation time estimates.

  MERRILL, D.N., THOMAS, G.S., DEVINGENTIS, J. Public Service Co. of New Hampshire. B3/07/15, 43pp. 19665:242, 24X

  Fiche: 50-443, 83/07/15, 8307210185.
- 8307250376 Forwards Exhibit 3 to applicant 830715 Direct Testimony 1. GAD.R.K. Ropes & Oray. GAD.R.K. Public Service Co. of New Hampshire. 83/07/18. Office of the Secretary of the Commission. 1p. 19705: 199. 24X Fiche: 50-443, 83/07/18, 8307250376.
- --8307250378 Exhibit 3 to applicant 830715 Direct Testimony 1 consisting of DA Maidrand prof qualifications. Certificate of 8vc encl. \* Public Service Co. of New Hampshire. 83/07/18. 3pp. 19705:200. 24X Fiche: 50-443, 83/07/18, 8307250376.
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA..UNIT 1

  A. Application/construction stage documents & correspondence
- 8305230578 Disagrees w/current enforcement policy allowing assessment of monetary penalties for Severity Levol IV or V violations, per 821221 ltr re regulatory reform.

  RRITTAIN,P.O. Texas Utilities Generating Co. 83/03/18, TOURTELLOTTE. J. Regulatory Reform Task Force. 2pp. 18541:312. 24X Fiche: 50-445,83/03/18,8305230578.
- B306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Ouidelines."
  Svc list encl.
  E18ENHUT, D. G. Division of Licensing. 83/04/03. Yankee Atomic Electric Co. 10pp. 19363:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307120631 Forwards "Independent Assessment Program," per agresment reached at 830518 meeting.
  SCHMIDT.H.C. Texas Utilities Services, Inc. B3/06/10.
  EISENHUT, D. G. Division of Licensing. 2pp. 19432:168. 24X
  Fichs: 50~445,83/06/10,8307120631.
- --8307120637 "Independent Assessment Program." \* Cygna Energy Services. 883-12C. 83/06/03. 98pp. 19432:170. 24X Fiche: 50-445,83/06/10,8307120631.

- 8307050064 Advises that environ qualification program for safety—related electrical equipment will be completed prior to fuel load. Util in compliance w/10CFR50. 49 & committed to remain so even though design grandfathered.
  88HHIDT.H.C. Texas Utilities Services, Inc. 83/06/28.
  YUUNOBLOOD, B. J. Licensing Branch 1. 3pp. 19192:149. 24X
  Fiche: 50-445,83/06/28,8307050064.
- B30707008B Forwards App A Tech Specs for proof & review.Response requested by B30805.W/o encl.
  THOMAS.C.O. Standardization & Special Projects Branch. B3/07/01.
  YOUNOBLOOD, B. J. Licensing Branch 1. IPPOLITO.T.A. Operating Reactors Assessment Branch. LIAM.B.D. Mechanical Engineering Branch. 2pp. 19364:312. 24X Fiche: 50-445, 83/07/01, 830709008B.
- 8307110282 Submits responses to 811112-14 requests at ACRS 259th meeting re containment hydrogen purge sys filters & control room occupancy vs containment leakage rate.

  8CHMIDT.H.C. Teras Utilities Generating Co. 83/07/01. BURNELL.S.B. NRC No Detailed Affiliation Given. 3pp. 19374:242. 24X

  Fichs: 30-445,83/07/01,8307110282.
- 8307200231 Notification of 830707 mesting w/technical review committee in Bethesda, MD to discuss review of D4, D5 & E steam generator mods.

  HOPKING J. B. Licensing Branch 4, 83/07/01. ADENSAM, E. Q. Licensing Branch 4. 2pp. 19670:234. 24X Fiche: 50-000, 83/07/01, 8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/09. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060327 Generic Ltr 83-27 to all licenses & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 878. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- 8307130294 Confirms plans for 830712-14 site visit to review & resolve enci questions on pump & valve inservice testing program. YOUNOBLOOD, B. J. Licensing Branch I. B3/07/07. GARY, R. J. Texas Utilities Generating Co. 13pp. 19511; 119. 24X Fiche: 50-445, 83/07/07, 8307130294.
- 8307140526 Forwards B Brink document produced at hearing re cold weather concrete curing. ROTHSCHILD, H. U. Office of the Executive Legal Director. 83/07/07 ELLIS, J. Case Consulting Laboratories, Inc. 1p. 17526:360. 24X Fiche: 50-445,83/07/07,8307140526.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EIBENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307210117 Forwards description of B30711 FSAR Amend 41. HARBHALL, J. S. Texas Utilities Generating Co. B3/07/11. BURWELL, S. B. Division of Licensing. 7pp. 19668:197. 24: Fiche: 50-445, B3/07/11/B307210117.
- 8307200228 Informs that applicants rescheduled fuel load date from Sept 1983 to Dec 1983, Region 4.NRC counsel & project manager advised of schedular change in 830708 telcon. BURWELL, S. B. Licensing Branch 1. 83/07/12. DENTON, H.R., CASE, E.G., CARTER, J. Office of Nuclear Reactor Regulation, Director. 1p. 19670: 289. 24X Fiche: 50~445, 83/07/12, 8307200228.
- 8307250124 Summary of 830707 meeting w/technical review committee in Bethesda, MD re Model D4/D5/E steam generator mod. Viewgraphs encl.
  HOPKINS, J. B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 25pp. 19738: 132. 24X Fichs: 50~000, 83/07/18, 8307250124.
- B307290500 Notification of B30720 meeting w/util in Bethesa.MD to discuss applicant plans for independent assessment program. BURNELL, B. B. Licensing Branch 1. 83/07/18. YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 19858:289. 24X Fiche: 50-443.83/07/18, 8307290500.
- 8307250256 Forwards addendum to preoperational integrated leak rate test rept.submitted on 830506.

  8CHHIDT.H.C. Texas Utilities Services, Inc. 83/07/19, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 19, 19705:282. 24X Fiche: 50-445,83/07/19,8307250256.

- --8307250260 Addendum to preoperational integrated leak rate test.

  \* Texas Utilities Services, Inc. 83/07/31. 4pp. 19705; 283. 24:
  Fiche: 50-445, 83/07/19, 8307250256.
- B307250370 Submits add1 info re FSAR submittal concerning D4/D5 steam generator tube vibration fix. Existing Chapter 15 accident analyses envelop all changes in parameters resulting from vibration fix.
  SCHMIDT.H.C. Texas Utilities Services, Inc. 83/07/19.
  YOUNGBLOOD, B. J. NRC No Detailed Affiliation Given. 1p. 19704:001. 24X Fiche: 50-445,83/07/19,8307250370.
- 8307280070 Responds to NRC B30706 position that RCS cold leg temp & source range neutron flux indicators must be included in alternate shutdown design. Expeditious consideration of dasign requested. Review affects fuel load date.

  GARY.R.J. Texas Utilities Generating Co. B3/07/22. YOUNGBLOOD, B. J. Licensing Branch i. 20pp. 19790: 229. 24x Fiche: 50-445, B3/07/22, B307280070.
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307230079 SAFETY EVALUATION REPORT RELATED TO THE DPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION.UNITS 1 AND 2. Docket Nos. 50-445 And 50-446. (Texas Utilities Generating Company, et al.)

  \* Office of Nuclear Reactor Regulation, Director. NUREO-0797 803. B3/03/31. 62pp. Aveilable at NRC. \$5.00. 19739:088. 24X Fiche: 50-445, B3/03/31, B307280079.
- B307110350 Outlines low power test program per SER (NUREC-0797) Open Item I.O.1, which includes loss of offsite power test, comparable facility test data utilization & training on validated simulator. Program will be incorporated in FSAR. BCHMIDT. H.C. Texas Utilities Services, Inc. B3/07/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19381:306. 24X Fiche:50-445.83/07/07.8307110350.
- F. Security, medical, emergency & fire protection plans
- 8306240435 Responds to NRC request re disposition of three unresolved areas based on FEMA testimony at ASLB 820917 hearing in Forth Worth, TX.

  RRIMM, R. W. Federal Emergency Management Agency. 83/03/22.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103).

  19. 19530: 252. 24X Fiche: 50-445, 83/03/22, 8306240435.
- B307050351 Responds to 821008.1206 & B30214 ltrs submitting changes to physical security, security training & qualification & safeguards contingency plans. Changes approved. YOUNOBLOOD, B. J. Licensing Branch 1. 83/06/23. GARY.R. J. Texas Utilities Generating Co. 2pp. 17263:273. 24X Fiche: 50-445, 83/06/23.8307050351.
- B307130097 Confirms plans for B30718 & 19 site visit to review installation of security equipment & commitments made in physical security plan against requirements of 10CFR73. 55. YOUNOBLOOD, B. J. Licensing Branch 1. B3/07/06. GARY.R. J. Texas Utilities Generating Co. 2pp. 19511:294. 24X Fiche:30-445. B3/07/06.8307130057.
- B307130316 Forwards interim safety evaluation of alternate safe shutdown capability from auxiliary sys standpoint Review of design in meeting fire protection requirements of App R to 10CFR50 incomplete.

  YDUNOBLOUD, B. J. Licensing Branch 1. B3/07/06. GARY, R. J. Texas Utilities Generating Co. 3pp. 19510:011. 24X Fiche: 30-445, B3/07/06, B307130316.
- ---B307130319 Bafety evaluation of alternate safe shutdown capability from auxiliary sys standpoint.

  \* Office of Nuclear Reactor Regulation, Director. B3/07/06. Bpp. 19510:014. 24X Fichs: 50~445, 83/07/06, 8307130316.
- 8307290099 Forwards Human Factors Engineering Branch audit rept of control room design review from 830404-08 per Generic Ltr B2-33. Responses to unsatisfied conditions should be provided 60 days prior to expected licensing date. YOUNOBLOOD, B. J. Licensing Branch 1. 83/07/08. GARY, R. J. Texas Utilities Generating Co. 34pp. 19723:309. 24X Fiche: 50-445, 83/07/08, 8307250059.
- B307270172 Forwards request to amend Rev 4 to physical security plan.
  Request withheld (ref 10CFR2.790 & 73.21).
  OARY, R. J. Texas Utilities Generating Co. 83/07/15. DENTON, H. R.
  Office of Nuclear Reactor Regulation, Director. 1p. 19749:318. 24X
  Fichs: 50-445, B3/07/15, 8307270172.

# Adjudicatory correspondence

- B305200618 Forwards addl Citizens Assoc for Sound Energy exhibits to be used during cross-examination on SIT rept. Stipulation re authenticity requested.

  ELLIS, J. Citizens Association for Sound Energy. 83/05/13. BROWN, B. Region 4, Office of Director. WADE, D. Texas Utilities Generating Co. 2pp. 18514:087. 24X Fiche: 50-445, 83/05/16.8305200618.
- B307050139 Order CLI-B3-18 granting NRC petition for review of ALAB-714 requiring NRC to disclose informant (dentities Issues will be deferred pending completion of generic review of informant confidentiality issues Separate views enci. CHILM.S. J. Office of the Secretary of the Commission, 83/06/30, 69pp. 19220:154. 24X Fiche: 50-445,83/06/30,8307050139.
- B307080201 Response to Commission B30630 Order CLI-83-18 Allegations re plant defects must be answered in rigorous fashion. Record incomplete on welding allegations. BLOCH.P.B. Atomic Safety and Licensing Board Panel. B3/07/06. 6pp. 19351: 344. 24% Fiche: 50-445, B3/07/06, B307080201.
- 8307080461 Memorandum & order directing that Secretary of Dept of Labor findings in Atchison vs Brown & Root binding in proceeding.based on collateral sstoppel doctrine.

  BLOCH.P.B., JURDAN.K.H., MCCOLLON,K.A. Atomic Safety and Licensing Board Panel. 83/07/06. Spp. 19347:237. 24X Fiche: 50-445, 83/07/06, 8307080461.
- B307080466 Memorandum & order re definition of thermal stresses in pipe supports. Reg Guide 1.124 & ASME Code do not require applicant to analyze thermal stresses in pipe design. BLOCH, P. B. Atomic Safety and Licensing Board Panel. 83/07/06. 12pp. 19346: 306. 24X Fiche: 50-445, 83/07/06, 8307080466.
- 830711004B Notice of continuation of evidentiary hearings on 830801-05 in Fort Worth, TX to receive evidence of nonconformances or const deficiencies.

  BLOCH, P. B. Atomic Safety and Licensing Board Panel. 83/07/07. 1p. 19375: 251. 24X Fiche: 50-445, 83/07/07, 8307110048.
- B3071203B5 Advises that fuel loading for Unit 1 rescheduled from Sept to Dec 1983. Related correspondence.
  REYNOLOS, N. B. Debevoise & Liberman. REYNOLOS, N. S. Texas Utilities Generating Co. B3/07/OB. BLOCH, P. B. , JORDAN, M. H. , MCCOLLOM, K. A. Atomit Safety and Licensing Board Panel. ip. 19432:155. 24X
  Fiche: 50-445, B3/07/OB, B3071205B5.
- 8307220346 Expresses shock & amazement re ASLB comments in recent hearings in Fort Worth, TX. Population numbers within 10-mile zone around plant should have no effect on adequacy of emergency plan.

  CRUMP, G.R. Somervell County, TX. 83/07/12. BLOCH, P.B. Atomic Safety and Licensing Board Panel.

  Spp. 19675: 297. 24X

  Fiche: 50-445, 83/07/12, 8307220346.
- B307180015 Responds to request for add1 evidence on whether practice exists of discouraging preparation of GC deficiency repts at plant. NRC may have info to offer into evidence by Sept 1983 re const appraisal team repts.

  SCINTO.J.F. Hearings Division. 83/07/14. BLOCH.P.B., JORDAN.W.H., MCCOLLON,K.A. Atomic Safety and Licensing Board Panel. 2pp. 19560:150. 24X Fiche: 50-445,83/07/14,8307180015.
- B307190228 Summary of record re weave & downhill welding Allegations re weave welding w/o merit & founded on erroneous beliefs concerning applicable codes, procedures & instructions. Downhill welding allegations limited to cover passes. REYNOLDS, N. S., HORIN, M. A. Texas Utilities Generating Co. REYNOLDS, N. S. Debevoise & Libernan. B3/07/15. 14pp. 19629:256. 24X Fiche: 50-445,83/07/15,8307190228.
- ---8307190233 Affidavit of CT Brandt supporting summary of record re weave & downhill welding Certificate of Svc encl. BRANDT.C.T. Texas Utilities Generating Co. 83/07/15, 5pp. 19629: 270. 24X Fiche: 50-443, 83/07/15, 8307190228.
- 8307200211 Motion for reconsideration of ASLB 830706 memorandum & order that thermal stresses within pipe support need not be considered in pipe support design. ABME Code. App XVII, not considered in order. Certificate of Svc encl. ELLIS. J. Citizens Association for Sound Energy. 83/07/15. Atomic Safety and Licensing Roard Panel. 14pp. 19648:105. 24X
- B307280351 Notice canceling B30801-05 hearing by agreement of parties:
  No evidence exists to be heard since witness interviews
  conducted by Btate of TX did not produce substantial adverse
  evidence re GA program.
  BLOCH, P. B. Atomic Safety and Licensing Board Panel. 83/07/21. 1p.
  19703:245. 24X Fiche: 50-445,83/07/21.8307250351.

- B307250356 Forwards original signature page to util 830715 summary of record re weave & downhill welding. Related correspondence. HORIN.W.A. Debavoise & Liberman. HORIN.W.A. Texas Utilities Generating Co. 83/07/21. STUCKY.S.W. Docketing & Services Branch. 1p. 19703;243. 24X Fiche: 50-445, 83/07/21, 8307250356.
- --8307250359 Driginal signature page to util 830715 summary of record re weave & downhill welding. BRANDT.C.T. Texas Utilities Generating Co. 83/07/15. ip. 19703:244. 24X Fiche:50-445,83/07/21,8307250356.
- B3072B0140 Responds to B30712 ltr.All relevant factors will be considered when ASLB decides whether FEMA review is important safety issue.
  BLOCH,P.B. Atomic Safety and Licensing Board Panel. B3/07/2 GRUMP,Q.R. Somervell County, TX. 2pp. 19791:308. 24X Fiche: 50-445, B3/07/25, B3072B0140. 83/07/25

### H. General correspondence

- 8307120272 Requests that BR Clements receive all correspondence originating from Region IV & IE Headquarters. GARY.R.J. Texas Utilities Generating Co. 83/06/16. GOLLING. Region 4. Office of Director. 1p. 19424:181. 24X Fiche: 30-445,83/06/16,8307120272. rs. 83/06/16. GOLLINB.J.T. 181. 24%
- I. Financial information
- B306280576 Forwards Annual Financial Repts 1982.

  ORRY, R. J. Texas Utilities Generating Co. 83/06/13. DENTON, H. R

  Office of Nuclear Reactor Regulation, Director. 1p. 19016:090. DENTON, H. R. 24X
- --83042805B0 Annual Financial Rept 1982. PARKER, M. G., MCCASKILL.R.E. Boston Edison Co. 19016:091. 24X Fiche: 50-445, B3/06/15, 8306280576. 83/06/15. 40pp.
- --8306280588 Annual Financial Rept 1982. MATTHEWS, C. R. Texas Municipal Power Agency. 83/06/15. 16pp. 19016:130. 24X Fiche: 50-445, 83/06/15, 8306280576.
- --8306280593 Annual Financial Rept 1982. MARGUARDT, W. G. Texas Electric Service Co. 83/03/31. 37pp. 19016:147. 24X Fiche: 50-445, 83/04/15, 8306280576.
- --8306280600 Annual Financial Rept 1982. FARRINGTON, J. Dallas Power & Light Co. 83/06/13 19016:183. 24X Fiche: 50-445, 83/06/15, 8306280576. 83/06/15. 34pp.
- --8306280603 Annual Financial Rept 1982. CAMPBELL,R.K. Teras Power & Light Co. 83/03/31. 34pp. 17016:218. 24X Fiche:50~445,83/06/15,8306280576.
- --8306280607 Annual Financial Rept 1982. BRITTAIN,F.G., AUSTIN,T.L. Texas Utilities Co. 83/03/25. 38pp. 19016:233. 24X Fiche: 50~445,83/06/15,8306280576.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- B307210152 Forwards Amend 41 to FBAR. CLEMENTS,B.R. Texas Utilities Generating Co. B3/07/1 Office of Nuclear Reactor Regulation, Director. 2pp. 24X Fiche: 50-445, 83/07/18, 8307210152. 93/07/18, DENTON, N 9np. 19438: 232, DENTON, H. R.
- -8307210161 Amend 41 to F5AR. \* Texas Utilities Generating Co. 8: 24X Fiche: 50-445,83/07/18,8307210152. 83/07/11. 757pp. 19458: 234.
- 8307260548 Forwards Affidavit of Svc re Amend 41 to FSAR. 8CHMIDT.H.C. Texas Utilities Services, Inc. 83/07/19. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19734:027. 24X Fiche: 50-445, 83/07/19, 8307260548.
- Q. Inspection reports, IE Bulletins & correspondence
- B307210192 Forwards IE Insp Repts 50-445/83-16 & 50-446/83-10 on 830411-15. No noncomplicance noted. MADSEN, G.L. Region 4. Office of Director. B3/06/09. GARY, R. J. Texas Utilities Generating Co. 2pp. 1965: 205. 24X Fiche: 50-445, B3/06/09, B307210192.

- ---B307210202 IE Insp Repts 50-445/83-16 & 50-446/83-10 on 830411-15.No noncompliance noted Major areas inspected: planned radiation protection program, including onsite & offsite organizations, qualifications & experience & training. CHANEY.H.D., MURRAY.B., WESTERHAN.T.F. Region 4, Office of Director. 83/06/03. 34pp. 19665:207. 24X Fiche: 30-445,83/06/09,8307210192.
- © 307260405 Forwards final response to IE Bulletin 82-04 re Bunker Ramo electrical penetrations. Required tests, insps & evaluations complete. All Bunker Ramo termination lugs replaced.

  GARY, R. J. Texas Utilities Generating Co. B3/06/14. COLLINS, J. T. Ragion 4, Office of Director. Spp. 19733: 202. 24X Fiche: 50-445, B3/06/14, B307260405.
- © 307050132 Forwards IE Insp Rept 50-495/83-26 on 830501-31. No noncompliance noted.

  MADSEN.9. L. Region 4. Office of Director. 83/06/15. GARY, R. J. Texas Utilities Generating Co. 2pp. 19220:199. 24X Fiche: 50-445.83/06/15.8307050132.
- □307060145 Ack receipt of B30525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/83-08.

  MADBEN.G.L. Region 4, Office of Director. B3/06/30, QARY,R.J. Texas Utilities Generating Co. ip. 19250: 213. 24X Fiche: 50-445,83/06/30,8307060145.
- S306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363:293. 24X Fiche:50-000.83/07/11.8306270401.
- BC307190304 Ack receipt of 830628 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-445/83-18 & 50-446/83-12.

  MADSEN.G.L. Region 4. Office of Director. 83/07/11. QARY,R.J. Texas Utilities Generating Co. ip. 19532: 298. 24% Fichs: 50-445/83/07/11,8307190304.
- BC306270404 IE Info Notice 83-47, "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133, 24X Fiche:50-000.83/07/12.8306270404.
- □□06270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list ancl.

  TAYLOR.J.M. Division of QA. Bafeguards & Inspection Programs {Post ⊕30103}. B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24% Fiche:50-000,63/07/14.8306270404.
- 🖴. Reportable occurrences. LERs & related correspondence
- GIGO7260391 Interim deficiency rept re new fuel storage racks. Initially reported verbally on 630310. Evaluation will be completed by 830401.

  CLEMENTS, B. R. Texas Utilities Generating Co. 83/04/07. MADSEN, C. L.
  - DV 83-001. CLEMENTS, B. R. Texas Utilities Generating Co. 83/04/07. MADSEN, G. L. Region 4. Dffice of Director. 1p. 19733:168. 24X Fiche: 30-445, 83/04/07, 8307260391.
- BEO7150273 Part 21 rept re potential defect in component cooling water sys. Initially reported on 830523. Loss of pressure integrity of equipment could result in loss of function of component cooling water sys. reducing degree of protection.

  DERIENZO.P.P. Oibbs & Hill. Inc. (subs. of Drave Corp.). 83/06/28, POTAPOVS-U. Region 4. Office of Director. 4pp. 19538:103. 24X Fiche: 50-445.83/06/28,8307150273.

- 8307150100 Interim Deficiency Rept SDAR-106 re HVAC hangers fabricated at variance w/design documents. Initially reported on 830301.
  Evaluation continuing w/completion expected by 830801.
  OARY, R. J. Texas Utilities Generating Co. 83/07/04. MADSEN, G. L.
  Ragion 4. Office of Director. 1p. 19536:126. 24X
  Fiche: 50-445,83/07/04,8307150100.
- B307130274 Interim deficiency rept re letdown HX anchors. Initially reported on B30506. Anchor bolts found bound in end of slotted holes prohibiting movement. Mounting configuration revised.

  QARY, R. J. Texas Utilities Generating Co. B3/07/07. MADSEN, G. L. Region 4. Office of Director. 2pp. 19532:203. 24X Fiche: 50-445, B3/07/07, 8307150294.
- 8307220259 Deficiency rept re boiting mati used for cable tray clamps. Structural drawings specify high strength bolting matls. Bolts used were mild steel type Design change issued. Rework performed as required. SPENCE.M.D. Texas Utilities Generating Co. 83/07/12. MADBEN.G.L. Region 4, Office of Director. 2pp. 19684:211. 24X Fiche: 50-445,83/07/12,8307220259.
- T. Hearing transcripts on non-antitrust matters
- 8307080002 Transcript of 830705 telephone conference in Bethesda, MD. Pp 8,620-8,683. \* Atomic Safety and Licensing Board Panel. 83/07/05. 63pp. 19351;247. 24% Fiche: 50-445,83/07/05.8307080002.
- B307220489 Transcript of 830720 telephone conference in Washington, DC. Pp B. 684-8.721.

  \* Atomic Safety and Licensing Board Panel. B3/07/20. 39pp. 19683:281. 24% Fiche: 80-445.83/07/20.8307220489.
- 8307290110 Motion for correction to transcript of 830720 telcon. Cartificate of Svc encl. HORIN.M.A. Texas Utilities Generating Co. HORIN.W.A. Debaydise & Liberman. 83/07/27. Atomic Safety and Licensing Board Panel. 3pp. 19822:153. 24X Fichs:50-445,83/07/27,8307290110.
- V. Operator Examinations
- 8307200504 Forwards evaluation of Rev 1 to licensed operator requalification training program, Procedure TRA-201. Changes detailed in encl evaluation necessary in order for procedure to satisfy 10CFR55.App A. requirements.
  YOUNOBLOOD, B. J. Licensing Branch 1. B3/07/12, 9ARY.R. J. Texas Utilities Generating Co. 4pp. 19672:082. 24X Fiche: 50-445, 83/07/12,8307200504.
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 2
  A. Application/construction stage documents & correspondence
- 8305230578 Disagrees w/current enforcement policy allowing assessment of monetary penalties for Severity Level IV or V violations, per 821221 ltr re regulatory reform.
  BRITTAIN,P.O. Texas Utilities Generating Co. 83/03/18.
  TOURTELLOTTE,J. Regulatory Reform Task Force. 2pp. 18541:312. 24X Fiche: 50-445,83/03/18,8305230578.
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Ouidelines." Svc list encl.
  EISENHUT.D. 9. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000, 83/06/03. B306060070.
- 8307120631 Forwards "Independent Assessment Program," per agreement reached at 830518 meeting.

  8CHMIDT.H.C. Texas Utilities Services, Inc. 83/06/10.

  EISENHUT.D.9. Division of Licensing. 2pp. 19432:168. 24X

  Fiche: 50-445,83/06/10,8307120631.
- --8307120637 "Independent Assessment Program." \* Cygna Energy Services. 883-12C, 83/06/03. 98pp. 19432:170. 24X Fiche: 50-445.83/06/10,8307120631.
- 8307050064 Advises that environ qualification program for safety-related electrical equipment will be completed prior to fuel load. Util in compliance w/10CFR50. 49 % committed to remain so even though deeign grandfathered.

  8CHMIDT.H.C. Texas Utilities Services, Inc. 83/06/28.

  YOUNOBLOQD, B. J. Licensing Branch i. 3pp. 19192:149. 24X Fiche: 50-445, 63/06/28, 8307050064.

- #307110292 Submits responses to #11112 14 requests at ACRS 259th meeting re-instalment hydrogen purge sys filters & control room occupanty vs containment leakage rate #CRMIDIAN C Terms Utilities Generating Co #82/07/01 #BURWELL-6 B NRC No Detailed Affiliation Given 3pp 19374 242 24X
- 8207200231 Notification of B30707 meeting w/technical review committee in Bethevda.MD to discuss review of D4:05 & E steam generator mode MOPRINS.J B. Lirensing Branch 4. 83707701. ADENSAMJE Q. Licensing Branch 4. 839—19670-254—24X Fiche 50-080-83707701-8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs 5 holders of CPs for power reactors re-clarification of surveillance requirements for diesel fuel impurity Svc list encl EISENHULD & Division of Licensing 83/07/05 Consolidated Edison Co of New York, Inc. 16pp 17390 317 24X Fiche 50-000.83/07/05.8306270397
- B307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in ST5 Svc list encl EISENHUT.D G Division of Licensing B3/07/06 Consolidated Edison Co of New York, Inc. 16pp 19669-254. 24X Fiche 50-000.83/07/06.8307060329
- 0307140526 Forwards B Brink document produced at hearing re cold weather concrete curing ROTHSCHILD: HV Office of the Executive Legal Director. 83/07/07 ELLIG.J Case Consulting Laboratories, Inc. 1p. 19526:360. 24X Fiche:50~445.83/07/07.8307140526.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669, 269. 24X Fiche: 30-000.83/07/08.8307080169.
- B307210117 Forwards description of B30711 FSAR Amend 41.
  MARSHALL.J.S. Texas Utilities Generating Co. 83/07/11.
  BURNELL.S B. Division of Licensing. 7pp. 19668:197. 24X
  Fiche: 30-445.83/07/11.8307210117.
- B307250124 Summary of B30707 meeting w/technical review committee in Bethesda.MD re Model D4/D5/E steam generator mod.Viewgraphs encl.
  HOPKINS.J.B. Licensing Branch 4. B3/07/18. Licensing Branch 4. 26pp. 1973B: I32. 24X Fiche: 50-000.83/07/18.8307250124.
- 8307250370 Submits add1 info re FSAR submittal concerning D4/D5 steam generator tube vibration fix. Existing Chapter 15 accident analyses envelop all changes in parameters resulting from vibration fix.

  SCHMIDT.H.C. Texas Utilities Services, Inc. 83/07/19.

  YOUNGBLOOD.B. J. NRC No Detailed Affiliation Given. 1p.
  19704:001. 24X Fiche: 50-445, 83/07/19, 8307250370.
- 8307280070 Responds to NRC 830706 position that RCS cold leg temp & source range neutron flux indicators must be included in alternate shutdown design. Expeditious consideration of design requested. Review affects fuel load date.

  OARY, R. J. Texas Utilities Generating Co. 83/07/22. YDUNOBLOOD, B. J. Licensing Branch 1. 20pp. 19790:229. 24X Fiche: 30-445, 83/07/22, 8307280070.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307250079 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2. Docket Nos. 30-445 And 50-446 (Toxes Utilities Generating Company, et al.)

  4 Office of Nuclear Reactor Regulation, Director. NUREO-0797 SO3. 83/03/31. 62pp. Available at NRC. \$5,00. 19739:08B. 24X Fiche: 50-445,83/03/31,8307250079.
- 8307110350 Outlines low power test program per SER (NUREG-0797) Open Item I. G. Liwhich includes loss of affsite power test, comparable facility test data utilization & training on validated simulator. Program will be incorporated in FSAR. SCHMIDT, H. C. Texas Utilities Services, Inc. 83/07/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19381:306. 24X Fiche: 50-445,83/07/07,8307110350.

- F Security, medical, emergency & fire protection plans
- B306240435 Responds to NRC request re disposition of three unresolved areas based on FEMA testimony at ABLB B20917 hearing in Forth Morth.TX KRIMM.P W Federal Emergency Management Agency B3/03/22. JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Pust B30103) 1p 19530-252 24X Fiche 50-445.B3/03/22, B306240435
- B307050351 Responds to 821008.1206 % 830214 ltrs submitting changes to physical security, security training % qualification % safeguards contingancy plans Changes approved YOUNGBLOOD. II J Licensing Branch 1 83/06/23 GARY. R J Texas Utilities Generating Co 2pp 19263 293 24X Fiche 50-445, 83/06/23.8307050351
- B307130057 Confirms plans for B30718 % 19 site visit to review installation of security equipment % commitments made in physical security plan against requirements of 10CFR73.55. YQUNGBLODD, B. J. Licensing Branch | B3/07/06 GARY, R. J. Texas Utilities Generating Co. 2pp. 19511 294. 24X Fiche: 50-445, 83/07/06.8307130057.
- B307130316 Forwards interim safety evaluation of alternate safe shutdown capability from auxillary sys standpoint Review of design in meeting fire protection requirements of App R to IOCRESO incomplete.
  YOUNOBLOOD B. J. Licensing Branch I B3/07/06 CARY, R J. Texas Utilities Generating Co. 3pp 19510 011 24X Fiche: 50-445, B3/07/06.B307130316.
- --8307130319 Safety evaluation of alternate safe shutdown capability from auxiliary sys standpoint auxiliary sys standpoint 90ffice of Nuclear Reactor Regulation, Director 83/07/06. Bpp. 19510:014. 24X Fiche:50-445.83/07/06.8307130316
- 8307250059 Forwards Human Factors Engineering Branch audit rept of control room design review from 830404-08 per Generic Ltr 82-33. Responses to unsatisfied conditions should be provided 60 days prior to expected licensing date YOUNOBLODD. B. J. Licensing Branch 1. 83/07/08 GARY, R J. Texas Utilities Generating Co. 34pp. 19723:309 24X Fiche: 30-445,83/07/08,8307250039
- 8307270172 Forwards request to amend Rev 4 to physical security plan.
  Request withheld (ref 10CFR2.790 & 73.21)
  GARY, R J Teras Utilities Generating Co. 83/07/15. DENTON, H. R.
  Office of Nuclear Reactor Regulation, Director 1p 19749: 318. 24X
  Fiche: 50-445: 83/07/15, 8307270172.

#### G Adjudicatory correspondence

- 8305200618 Forwards add) Citizens Assoc for Sound Energy exhibits to be used during cross-ecamination on SIT rept Stipulation re authenticity requested.
  ELLIS.J. Citizens Association for Sound Energy 83/05/13. BROWN.B. Region 4. Office of Director. WADE.D. Texas Utilities Generating Co. 2pp. 18514:087. 24X Fiche: 50-445.83/05/16.8303200618.
- 8307050139 Order CLI-83-18, granting NRC petition for review of ALAB-714 requiring NRC to disclose informant identities lasues will be deferred pending completion of generic review of informant canfidentiality issues Beparate views enci CHILK: S. J. Office of the Secretary of the Commission. 83/06/30. 6pp 19220:154. 24X Fiche: 50-445, 83/06/30, 8307050139.
- B307080201 Response to Commission B30630 Order CLI-B3-iB Allegations re plant defects must be answered in rigorous fashion. Record incomplete on welding allegations. BLOCK, P. B. Atomic Safety and Licensing Board Panel 83/07/06 app. 19351:344. 24X Fiche: 50-445, 83/07/06, 8307080201
- 8307080461 Memorandum & order directing that Secretary of Dept of Labor findings in Atchison vs Brown & Root binding in proceeding, based on collateral estappel doctrine BLOCH, P.B., UDRDAN, H.H., MCCQLLOM, K.A. Atomic Safety and Licensing Board Panel. 83/07/06. 6pp. 19347 237 24X Fiche 50-445,83/07/06.
- 8307080466 Memorandum & order re definition of thermal stresses in pipe supports Rog Quide 1.124 & ASME Code do not require applicant to analyze thermal stresses in pipe design BLOCH.P.B. Atomic Safety and Licensing Board Panel 83/07/06 12pp. 19346.306 24X Fiche: 50-445.83/07/06.8307080466.
- B30711004B Notice of continuation of evidentiary nearings on 830801-05 in Fort Worth, TX to receive evidence of nonconformances or const deficiencies.

  BLOCH, P. B. Atomic Safety and Licenting Board Panel 83/07/07 ip 19375:251 24X Fiche 50-445,83/07/07,8307110048

- B307120585 Advises that fuel loading for Unit 1 rescheduled from Sept to Dec 1983. Related correspondence.
  REYNOLDS.N.S. Debevoise & Liberman. REYNOLDS.N.S. Texas Utilities Generating Co. 83/07/08. BLOCH.P.B., JORDAN.W.H., MCCOLLOM.K.A. Atomic Safety and Licensing Board Penel. 1p. 19432:155. 24X Fiche: 50-445.83/07/08.8307120585.
- 8307220346 Expresses shock & amazement re ASLB comments in recent hearings in Fort Worth, TX. Population numbers within 10-mile ione around plant should have no effect on adequacy of emergency plan.

  CRUMP, G. R. Bomervell County, TX. 83/07/12. BLOCH, P. B. Atomic Safety and Licensing Board Panel. 3pp. 19675: 297. 24X Fiche: 50-445, 83/07/12, 8307220346.
- 8307180015 Responds to request for add1 evidence on whether practice sxists of discouraging preparation of GC deficiency repts at plant. NRC may have info to offer into evidence by Sept 1983 re const appraisal team repts.

  SCINTO.J.F. Hearings Division. 83/07/14. BLOCH.P.B., JORDAN.W.H., MCCOLLOM.K.A. Atomic Safety and Licensing Board Panel. 2pp. 19560:150. 24X Fiche: 50-445, 83/07/14, 8307180015.
- 8307190228 Summary of record re weave & downhill welding. Allegations re weave welding w/o merit & founded on erroneous beliefs concerning applicable codes, procedures & instructions. Downhill welding allegations limited to cover passes. REYNOLDS, N. S., HORIN, M. A. Texas Utilities Generating Co. REYNOLDS, N. S. Debevoite & Liberman. 83/07/15. 14pp. 19629:256. 24X Fiche:50-445,83/07/15,6307190228.
- --8307190233 Affidavit of CT Brandt supporting summary of record re weave & downhill welding. Cartificate of Svc encl. BRANDT, C.T. Texas Utilities Generating Co. 83/07/15. Spp. 19629: 270. 24X Fiche: 50-443.63/07/15.8307190228.
- B307200211 Motion for reconsideration of ASLB 830706 memorandum & order that thermal stresses within pipe support used not be considered in pipe support design. ASME Code. App XVII. not considered in order. Certificate of Svc encl. ELLIS. J. Citizens Association for Sound Energy. B3/07/15. Atomic 8afety and Licensing Board Panel. 14pp. 19648:105. 24X Fiche: 50-445.83/07/15,8307200211.
- 8307250351 Notice canceling 830801-05 hearing by agreement of parties. No evidence exists to be heard since witness interviews conducted by State of TX did not produce substantial adverse evidence re OA program.

  8LOGCH.P.B. Atomic 8afety and Licensing Board Panel. 83/07/21. 1p. 19703:245. 24X Fiche: 50-445, 83/07/21, 8307250351.
- 8307250356 Forwards original signature page to util 830715 summary of record re weave & downhill welding Related correspondence. HORIN. M. A. Debevoise & Liberman. HORIN. W. A. Texas Utilities Generating Co. 83/07/21. STUCKY, S. W. Docketing & Services Branch. ip. 19703:243. 24X Fiche: 50-445,83/07/21,8307250356.
- --8307250359 Driginal signature page to util 830715 summary of record re weave & downill welding. BRANDT,C.T. Texas Utilities Generating Co. 83/07/15. 1p. 19703:244. 24X Fiche:50-445,83/07/21,8307250356.
- 8307280140 Responds to 830712 ltr. All relevant factors will be considered when ABLB decides whether FEMA review is important safety issue.

  BLOCH.P.B. Atomic Safety and Licensing Board Panel.

  GRUMP.G.R. Somervell County

### H. Qeneral correspondence

- 8307120272 Requests that BR Clements receive all correspondence originating from Region IV & IE Headquarters. GARV.R.J. Texas Utilities Generating Co. 83/06/16. CDLLINB.J.T. Region 4. Office of Director. ip. 19424; 181. 24X Fiche: 50-445.83/06/16.8307120272.
- I. Financial information
- 8306280576 Forwards Annual Financial Repts 1982. OARY/R.J. Texas Utilities Generating Co. 83/06/15. DENTON.H.R. Office of Nuclear Reactor Regulation Director. 1p. 19016:090. 24X Fiche: 50-445, 83/06/15. 8306280575.
- --8306280580 Annual Financial Rept 1982.
  PARKER, H. O., MCCABKILL, R. E. Boston Edison Co. 83/06/15. 40pp. 19016:091. 24X Fiche: 50-445, 83/06/15, 8306280576.
- --B306280388 Annual Financial Rept 1982. MATTHEMB, C. R. Texas Municipal Power Agency. 83/06/15. 16pp. 19016:130. 24X Fiche: 50-445, 83/06/15, 8306280576.

- --8306280593 Annual Financial Rept 1982.
  MARQUARDT.N. C. Teras Electric Service Co. 83/03/31. 37pp. 19016: 147. 24X Fiche: 50-445.83/06/15.8306280576.
- --8306280600 Annual Financial Rept 1982. FARRINGTON, J. Dallas Power & Light Co. 83/06/15. 34pp. 19016:183. 24X Fiche: 50-445.83/06/15.8306280576.
- --8306280603 Annual Financial Rept 1982. CAMPBELL, R. K. Texas Fower & Light Co. 83/03/31. 34pp. 19016: 218. 24X Fiche: 50-445, 83/06/15, 8306280376.
- --8306280607 Annual Financial Rept 1982. BRITTAIN, P. G., AUSTIN, T. L. Taxas Utilities Co. 83/03/25. 38pp. 19016. 253. 24X Fiche: 50-445, 83/06/15, 8306280576.
- K. Utility Fina! Safety Analysis Report (FSAR) & amends
- 8307210132 Forwards Amend 41 to FBAR. CLEMENTS.B.R. Texas Utilities Generating Co. 83/07/18. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19458: 232. 24X Fiche: 50-445.83/07/18.8307210152.
- --8307210161 Amend 41 to FSAR.

  \* Texas Utilities Generating Co. 83/07/11. 759pp. 19658:234.
  24% Fiche: 50-445,83/07/18.8307210152.
- 830726054B Forwards Affidavit of Svc re Amend 41 to FSAR. 8CHMIDT.H.C. Texas Utilities Services, Inc. 83/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19734: 027. 24X Fiche: 50-445.83/07/19.830726054B.
- Q. Inspection reports. IE Bulletins & correspondence
- 8307210192 Forwards IE Insp Repts 50-445/83-16 & 50-446/83-10 on B30411-15. No noncomplicance noted. MADSEN,G. L. Region 4. Office of Director. B3/06/09. GARY,R.J. Texas Utilities Generating Co. 2pp. 19665: 205. 24X Fiche: 50-443.83/06/09.8307210192.
- --8307210202 IE Insp Repts S0-445/83-16 & 50-446/83-10 on 830411-15. No noncompliance noted Major areas inspected: planned radiation protection program, including onsite & offsite organizations, qualifications & experience & training. CHANEY.H. D. MURRAY.B., WESTERMAN.T.F. Region 4, Office of Director. 83/06/03. 34pp. 17645:207. 24X Fiche: 50-445,83/06/07,8307210172.
- 8307260405 Forwards final response to IE Bulletin 82-04 re Bunker Ramo electrical penetrations. Required tests, insps & evaluations complete. All Bunker Ramo termination lugs replaced. GARY, R. J. Teras Utilities Generating Co. 83/06/14. COLLINS, J. T. Region 4. Office of Director. 8pg. 19733: 202. 24X Fichs: 50-445, 83/06/14, 8307260405.
- B3D6270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade
  Burry Recirculation Spray Subsystam." Svc list encl.
  JORDAN,E.L. Division of Emergency Preparedness & Engineering
  Response (Post B30103). B3/07/11. Consolidated Edison Co. of New
  York, Inc. 154pp. 19563: 293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8307130304 Ack receipt of 830628 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-18 & 50-446/83-1R.

  MADBEN, G. L. Region 4, Office of Director. 83/07/11. GARY, R. J. Texas Utilities Generating Co. 1p. 19532: 298. 24X Fiche: 50-445, 83/07/11, 8307150304.
- --8307150311 Responds to NRC 830531 ltr re violations noted in IE lnsp Repts 30-445/83-18 & 50-446/83-12. Corrective actions: spec & const installation procedures for mechanical equipment revised & reinsp program instituted. GARY,R. J. Texas Utilities Generating Co. 83/06/28. MADSEN, G. L. Region 4, Office of Director. 10pp. 19532:299. 24X Fichs: 50-445,83/07/11,8307150304.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York: Inc. 141pp. 19363:153. 24X Fiche: 50-000.83/07/12.8306270404.
- B306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of QA: Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.

- S. Reportable occurrences, LERs & related correspondence
- 8307260391 Interim deficiency rapt re new fuel storage racks. Initially reported verbally on 830310. Evaluation will be completed by 830601.

  CLEMENTS, B. R. Texas Utilities Generating Co. 83/04/07. MADSEN, G. L. Region 4. Office of Director. (p. 19733:168. 24X Fiche: 30-443, 83/04/07, 8307260391.
- B307150273 Part 21 rept re potential defect in component cooling water sys. Initially reported on 830523. Loss of pressure integrity of aquipment could result in loss of function of component cooling water sys, reducing degree of protection.

  DERIENZO,P. P. Gibbs & Hill. Inc. (subs. of Dravo Corp.). 83/06/28. PDTAPDVS, U. Region 4. Office of Director. 4pp. 1938:103. 24X Fiche: 50~445,83/06/28. 8307150273.
- 8307150100 Interim Deficiency Rept SDAR-106 to HVAC hangers fabricated at variance w/design documents. Initially reported on 830301. Evaluation continuing w/completion expected by 830801. GARY, R. J. Teras Utilities Generating Co. 83/07/04. MADSEN, G. L. Region 4. Defice of Director. ip. 19536:126. 24X Fichs: 50-445,83/07/04,8307150100.
- 8307130294 Interim deficiency rept re letdown HX anchors. Initially reported on 830506. Anchor bolts found bound in end of slotted holes prohibiting movement. Mounting configuration revised.

  OARY, R. J. Texas Utilities Generating Co. 83/07/07. MADSEN, Q. L. Region 4, Office of Director. 2pp. 19532: 203. 24X Fichs: 50-445, 83/07/07, 8307150294.
- 8307220239 Deficiency rept re bolting matl used for cable tray clamps.

  Structural drawings specify high strength bolting matls.

  Bolts used were mild steel type Design change issued.

  Rework performed as required.

  SPENCE,M.D. Texas Utilities Generating Co. 83/07/12. MADSEN, G. L.

  Region 4, Diffice of Director. 2pp. 19684:211. 24%

  Fiche: 50-445, 83/07/12, 8307220259.
- T. Hearing transcripts on non-antitrust matters
- 8307080002 Transcript of 830705 telephone conference in Bethesda, MD. Pp 8, 620-8, 683.

  \* Atomic Safety and Licensing Board Panel. 83/07/05. 63pp. 19351: 247. 24X Fiche: 50-445, 83/07/05, 8307080002.
- 8307220489 Transcript of 830720 telephone conference in Washington, DC. Pp 8,684-8,721. \* Atomic Safety and Licensing Board Panel. 83/07/20. 39pp. 19885;281. 24X Fiche: 50-445,83/07/20.8307220489.
- 8307290110 Motion for correction to transcript of 830720 telcon. Certificate of Byc encl. MORIN.M.A. Texas Utilities Generating Co. HORIN.W.A. Debevoise & Liberman. B3/07/27. Atomic Safety and Licensing Board Panel. 3pp. 19822:153. 24X Fiche: 50-445,83/07/27,8307290110.
- V. Operator Examinations
- B307200504 Forwards evaluation of Rev 1 to licensed operator requalification training program, Procedure TRA-201. Changes detailed in encl evaluation necessary in order for procedure to satisfy 100FR953-App A, requirements.
  YOUNGBLOOD, B. J. Licensing Branch 1. 83/07/12. GARY, R. J. Texas Utilities Generating Co. 4pp. 19672; 082. 24X Fiche: 50-445, 83/07/12, 8307200504.
- DOCKET STN-50-447 GESSAR-238
- A. Application/construction stage documents & correspondence
- B21103014B Forwards "Draft Yechnical Evaluation Rept on Mark III LOCA-Related Hydrodynamic Load Definition, Generic Technical Activity B-10." Evaluation based on info contained in App 3B of GEGSAR-II. Final rept will be issued by Jan 1983. SBRIS.T.P. Assistant Director for Reactor Safety. B2/10/08. PFEFFERLEN.H. General Electric Co. 2pp. 19390:193. 24X Fiche: 50-447, 82/10/08, B211030148.
- --8304140613 "Draft Technical Evaluation Rept on Mark III LUCA-Related Hydrodynamic Load Definition, Generic Technical Activity B-10." Proposed load definitions acceptable. 8 Containment Systems Branch. FIN A-3320. 83/03/31. 117pp. 19390: 197. 24X Fiche: 50-447, 82/10/08, 8211030148.

- 8307010180 Forwards marked-up proposed rev to response to CP/ML rule (10CFR30.34(f)) re hydrogen control. Amend to be formally filed in early Jul 1983.
  SHERNOOD, G.O. General Electric Co. 83/06/28. EISENHUT, D. Q. Division of Licensing. 7pp. 19169:227. 24x Fiche: 50-447, 83/06/28, 8307010180.
- B307130394 Notification of B30707-08 meetings w/GE & BNL in Long Island:NY to conduct technical review of GEBSAR-11 PRA. SCALETTI.D.C. Standardization & Special Projects Branch. B3/07/01. THOMAS.C.O. Standardization & Special Projects Branch. 2pp. 19340:300. 24X Fiche: 50-447, 83/07/01, 8307130394.
- 8307110470 Ack receipt of ACRS B30613 ltr re completion of review of OESBAR-II application for final design approval of BWR/6 Mark III design. No items remain as outstanding issues. SHERRHOOD, G. G. General Electric Co. B3/07/05. THOMAS.C.O. Standardization & Special Projects Branch. 9pp. 19380:173. 24X Fiche: 50-447, 83/07/05, 8307110470.
- 8307250367 Submits summary status of issues being addressed by Licensing Review Group II.per 830302 request Four issues require further action prior to NRC clossout Post-accident sampling requires procedural upgrading.

  HOLTZGCHER, D. L. Licensing Review Group II. 83/07/15. STEFANO, J. J. Licensing Branch 1. 12pp. 19705:203. 24X Fiche: 50-000, 83/07/15, 8307250367.
- 8307290131 Forwards QESSAR-II responses to action plan for resolving containment design issues in response to 820810 ltr.
  Affidavit for withholding proprietary info encl. Portions withheld.
  SHERNDOD, G. G. General Electric Co. 83/07/26. EISENHUT, D. G. Division of Licensing. 86pp. 19815: 182. 24X Fiche: 50-447, 83/07/26, 8307290131.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 830727018B Forwards Suppl i to SER for GESSAR-II (NUREG-0979). W/o encl. THOMAB, C. O. Standardization & Special Projects Branch. 83/07/20. SHERWOOD, G. G. General Electric Co. 2pp. 19811:155. 24X Fiche: 50-447, 83/07/20, 830727018B.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307250377 Forwards Amend iB to GESSAR-23B, incorporating B30428 ltr re gost-accident monitoring instrumentation, B30615 ltr re Question 410, 24 of NRC B20815 request for add1 info & summary of measures to avoid stress corrosion cracking.

  BHERHODD, G. G. General Electric Co. B3/07/1B. EISENHUT. D. G. Division of Licensing. 2pp. 19704: 232. 24X Fiche: 50-447, 63/07/1B, B307250377.
- --8307250382 Amend 18 to GESSAR-23B. SHERHOOD, G. O. General Electric Co. 83/07/18. 86pp. 19704:234. 24X Fiche: 50-447, 83/07/18, 8307250377.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8307200390 Advises that ACRB comments on GE application for final design approval for SHR/6 nuclear island design, GESSAR-II, will be included in first SER supplito be issued in Jul 1963.
  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
  B3/07/08. RAY, J.J. ACRB Advisory Committee on Reactor Safeguards.
  4pp. 19656: 324. 24X Fiche: 50-447, 83/07/08, 8307200390.
- --8306240426 Summarites ACRS 278th meeting on B30607-11 re GESBAR-II final design approval Approval recommended subj to listed comments & approval of balance-of-plant design. RAY.J.J. ACRS Advisory Committee on Reactor Bafeguards. 83/06/15. PALLADING.N.J. Commissioners. 8pp. 19656:328. 24X Fiche:50-447.83/07/08.8307200390.
- DOCKET STN-50-454 BYRON STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8305310033 Summary of 830518 meeting w/util, Westinghouse & OE in Bathesda, MD re Tach Spac requirements concerning outage times for redundant safety-related equipment. Viewgraphs encl.

  OLSHAN, L. N. Licensing Branch 1. 83/05/19, Licensing Branch 1. 29pp. 18663:099. 24X Fiche: 20~454,83/05/19,8305310033.

- 8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl. EISENMUT.D. 9. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116. 24X Fiche: 50-000.83/06/03, B30660070.
- 8306230264 Forwards advance revised pages to FSAR necessary to reclassify spent fuel pool liner from safety Category I structure to Category II. Info will be incorporated into next amend to FSAR.

  TRAMM, T.R. Commonwealth Edison Co. 83/06/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 18745:076. 24X Fiche: 50-000, 83/06/20, 8306230264.
- S3D7200231 Notification of 830707 meeting w/technical review committee in Bethesda. MD to discuss review of D4.D5 & E steam generator mods.

  HDPKINS.J.B. Licensing Branch 4. 83/07/01. ADENSAM.E. G. Licensing Branch 4. 2pp. 19670:254. 24X Fiche: 50-000.83/07/01.8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesal fuel impurity. Svc list encl. EIBENHUT, D. 9. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors resurveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329.
- 8307120281 Requests add1 exemption from Type C testing requirements for containment sump isolation valves MOVS18811A & B per 830419 Ltr concerning containment leak rate testing. Justification provided.

  LENTINE.F.O. Commonwealth Edison Co. 83/07/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19424:114. 24X Fiche: 50-000, 83/07/07, 8307120281.
- 8307130309 Forwards responses to SORT & pump & valve operability review team audits & responses to add1 items discussed at B30513 meeting w/NRC in Bethesda.MD.

  SWARTZ.E.D. Commonwealth Edison Co. B3/07/07. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 17466:127. 24X

  Fiche: 50~000, 83/07/07, 8307130309.
- --8307130313 Procedure X-604, "Qualification Testing of Joy Azivene Fan & Reliance Electric Motor for Class I Svc for Nuclear Containment per IEEE 334-1974."

  BISSETT.T.A., ZEIGLER, J. T., MURPHY, J. A. Joy Manufacturing Co. 80/03/20. 1107pp. 19466:141. 24X Fiche: 50-000, 83/07/07, 8307130309.
- --8307130317 Rev O to "Auditable Link Document for Byren Unit 1." PETRONIE A.D., JELOVICH, J.J., HAUZE, G.L., Commonwealth Edison Co. EGAL-CAE ROD. 83/07/07, 17pp. 19469: 168. 24X Fiche: 50-000, 83/07/07, 8307130309.
- --8307130322 Rev O to "Environ Qualification of Mechanical Equipment for Comm Ed Byron Units 1 & 2. Braidwood Units 1 & 2 Component Pacific Safety Injection Pump Model 3-Inch 10 Stage JHF."

  ZECAR.M.J., WALKER, L. I. Commonwealth Edison Co. EG&T-EGT-204 ROD. 83/06/20. 84pp. 19469:185. 24X Fiche: 50-000,83/07/07,8307130309.
- ---B307130325 "Byron Pump & Valve Operability Bummary."

  KAMENIC,M., SNIDER,J.M. Westinghouse Electric Corp. CAE-05-01.

  B3/06/10. 40pp. 19469:270. 24X Fiche:50-000,83/07/07,8307130309.
- --8307130328 Vol 1 to "Nuclear Environ Qualification Program on Lead Acid Storage Batteries." MINADED, R., JORDAN, H., KIMBRELL, M. Wyle Laboratories. 44681-2 VOl. 81/10/27. 200pp. 19469:310. 24X Fiche: 50-000,83/07/07, 8307130309.
- --8307130330 Vol 2 to "Nuclear Environ Qualification Program on Lead Acid Storage Batteries." \* Wyle Laboratories. 44681-2 VO2. 81/10/27. 710pp. 19470:147. 24X Fichs: 50-000, 83/07/07, 8307130309.
- --8307130331 "Seismic Simulation Test Rept." PINKERTON, B., JORDAN, H., KIMBRELL, M. Wyle Laboratories. 44681-1. 81/05/15. 200pp. 19471:307. 24X Fiche:50-000,83/07/07, 8307130309.

- --8307130333 "Environ Qualification for Class IE Lead Acid Storage Batteries." HDPENELLAR.W. DESAI.R.H. Gould, Inc. 83/07/07. 188pp. 19472:137. 24X Fiche: 50-009.83/07/07.8307130309.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24% Fiche: 30-000, 83/07/08, 8307080169.
- 8307260516 Forwards memo describing actions taken to resolve JH Conran differing prof opinion re sys interaction (Unresolved Bafety Issue A-17) & safety classification.

  DENTON,H.R. Office of Nuclear Reactor Regulation, Director.

  83/07/11. CONRAN.J.H. Reliability & Risk Assessment Branch. 2pp.
  19782: 241. 24X Fiche: 50-000,83/07/11,8307260516.
- --8305080369 Forwards comments on mgt views & positions on systhetraction per differing prof opinion in response to 830418 & 0505 memos. Excerpts from Suffolk County 830509 submittal & proposed request for addl infore Byron/Braidwood encl. CONRAN. J. H. Reliability & Risk Assessment Branch. 83/05/25. RUSSELL. W. T. Systematic Evaluation Program Branch. 74pp. 19783:033. 24X Fiche: 50-000.83/07/11.8307260516.
- 8307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4,D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).

  8UTTERFIELD, L. Steam Generator Cuners Group. BUTTERFIELD, L. Gommonwealth Edison Co. B3/07/18, EISENHUT, D. G. Division of Licensing. 3pp. 17464:114. 24X Fiche: 50-000, 83/07/18, 8307210300.
- 8307250124 Summary of 830707 meeting w/technical review committee in Bethesda MD re Model D4/D5/E steam generator mod. Viewgraphs encl.

  HOPKINS.J.B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 24pp. 19738: 132. 24X Fiche: 50-000.83/07/18.8307250124.
- 8307270430 Forwards SER addressing environ qualification program for electrical equipment important to safety & safety-related equipment. Dutstanding info identified in Sections 3.11.3 & 3.11.4 should be provided by 830730.
  YOUNOBLOOD, B. J. Licensing Branch 1. 63/07/20. FARRAR, D. L. Commonwealth Edison Co. 2pp. 17838:001. 24X Fiche: 50-454, 63/07/20, 8307270430.
- --8307290437 SER identifying outstanding info in Sections 3.11.3 & 3.11.4. "Environ Qualification Program for Electrical Equipment Important to Safety & Safety-Related Mechanical Equipment."

  \* Equipment Qualification Branch. 83/07/20. t6pp. 19858:003. 24X Fiche: 50-494,83/07/20.8307270430.
- 8307290047 Advises that energy absorbing matl used in pipe whip restraint design not properly qualified for design applications used at facilities. Recommended position to resolve issue encl.
  YOUNGBLOOD, B. J. Licensing Branch 1. 83/07/21. FARRAR, D. L. Commonwealth Edison Co. 1p. 19857:026. 24X Fiche: 30-000, 83/07/21, 8307290047.
- --8307290072 Trip rept of B30511-12 visit to Region III ofc.Byron site & Sargent & Lundy Chicago. It. ofc re design.installation & testing of pipe restraints using energy absorbing matl. TERAO.D. Mechanical Engineering Branch. 83/05/26. BOSNAK.R.J. Mechanical Engineering Branch. 4pp. 19857:033. 24X Fiche: 50-000,83/07/21,8307290047.
- F. Security, medical, emergency & fire protection plans
- 8307220546 Forwards IE Insp Repts 90-494/83-27 % 50-455/83-20 on B30619.No noncompitance noted. PAPERIELLO, C. J. Region 3, Office of Director. 83/07/08. REED, C. Commonwealth Edison Co. 2pp. 19686:041. 24X Fiche: 50-454,83/07/08, 8307220046.
- 8307260018 Submits supplemental response to NUREG-0737, Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display sys verification to be performed w/verification program. GMARTZ.E.D. Commonwealth Edison Co. 83/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19727: 177. 24X Fiche: 50-000, 83/07/20, 8307260018.

- 8307280347 Forwards review of draft Rev 4 to generic portion of generating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions encl. PAPERIELLO.C.J. Region 3, Office of Director. 83/07/24. REED.C. Commonwealth Edison Co. 10pp. 19789:018. 24x Fiche: 50-000, 83/07/26, 8307280347.
- G. Adjudicatory correspondence
- B307050003 Forwards NRC Press Release 83-44 re proposed imposition of \$150,000 in civil penalties for alleged shutdown regulation violations. Intervenors will seek to admit press release & associated insprepts into evidence. Svc list encl. WHICHER, J. M. Businessmen for the Public Interest. 83/06/29. BMITH, J. W., CALLAHAN, A. D., COLE, F. Atomic Safety and Licensing Board Panel. 4pp. 19192:117. 24X Fiche: 50-454. B3/06/29. B307050003.
- B307050011 Forwards stipulation re recent fine imposed on util & agreement to delete portions of JH Hughes deposition. MHICHER, J. M. Businessmen for the Public Interest. B3/06/29. SMITH, I. N., CALLAHAN, A. D., COLE, R. F. Atomic Safety and Licensing Board Panel. 2pp. 19192:084. 24X Fiche: 50-434,83/06/29,8307050011.
- --8307050020 Stipulation on deletion of portions of util witness
  JH Hughes 830519 deposition.
  GOLDBERG: S. C. Hearing Branch 4. MILLER, M. Commonwealth Edison
  Co. WHICHER, J. M. League of Nomen Votors of Rockford, IL.
  83/05/31. 2pp. 19192:086. 24X Fiche: 50-454, 83/06/29, 8307050011.
- --8307050032 Stipulation re recent fine imposed on util for failure to maintain operability of one of two instrument channels in trip sys 8.5vc list encl.
  GOLDBERG, S. Hearing Branch 4. BICKER, B.D. Commonwealth Edison Co. WHICHER, J.M. League of Women Voters of Rockford, IL.
  83/06/20. 3pp. 19192:088. 24X Fiche: 50-454, 83/06/27, 8307050011.
- 8307050227 Motion to suppl closed GA/GC record w/info on preoperational testing. Exhibits show evidence of severe deficiencies in preoperational testing program. Certificate of Svc enci. HHICHER.J.M. League of Homen Voters of Rockford, IL. WHICHER.J.M. Dakalb Area Alliance for Responsible Energy. WHICHER.J.M. Sinnissippl Alliance for the Environment (SAFE). 83/06/29. Atomic Safety and Licensing Board Fanel. 39pp. 19199:239. 24X Fiche: 50-454:83/06/29.8307050227.
- B307060355 Reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re ALARA Certificate of Svc encl.
  MILLER.M.I.: HERRIN.M.G. Commonwealth Edison Co. MILLER.M.I. Isham, Lincoln & Beals. B3/06/30. 16pp. 19234:147. 24X Fiche: 50-454.83/06/30.8307060355.
- 8307060375 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on Class 9 accidents & liquid pathway releases. Certificate of Svc encl. RAMSON.R.J. Hearing Branch 3, 83/07/01, 96pp. 19236:122, 24% Fichs: 50-454, 83/07/01, 8307060375.
- 8307040400 Memorandum & order directing NRC to present evidence on cited portion of Region III testimony re ongoing NRC insps & investigations. NRC fails to discuss why protective procedures inapplicable.

  BMITH.I.W. Atomic Safety and Licensing Board Panel. 83/07/01.
  Office of the Executive Legal Director. 4pp. 19234:294. 24X
  Fiche: 50-454.83/07/01,8307040400.
- 8307070207 Proposed findings of fact & conclusions of law re Class 9 accidents. Certificate of Svc encl.

  9ALLO.J., HERRIN.M.G. Commonwealth Edison Co. GALLO.J. Isham, Lincoln & Beale. 83/07/01. 53pp. 19269: 106. 24X
  Fiche: 50-454, 83/07/01. 8307070207.
- B307070207 Proposed findings of fact & conclusions of law re liquid pathway & Class 9 accidents. Certificate of Svc encl. THOMAS, D.C. League of Women Voters of Rockford, IL. B3/07/01. 23pp. 19269: 200. 24X Fiche: 50-454, 83/07/01, 8307070209.
- B307110037 Proposed findings of fact & conclusions of law re steam generator tube integrity.

  # League of Women Voters of Rockford, IL. B3/07/01. Atomic Bafety and Licensing Board Panel. 107pp. 19375:144. 24X Fiche: 50-454, 83/07/01. 8307110037.
- 8307080488 Presents info proving Hughes allegations intimately connected w/noncompliance noted in IE Insp Rept 50-454/82-05. Item 19 re reinsp program. WHICHER, J.M. Businessmen for the Public Interest, 83/07/05. BMITH, I.W.; COLE, R.F.; CALLAHAN, A.D. Atomic Bafety and Licensing Board Panel. 6pp., 19346: 328, 24X Fiche: 50-454,83/07/05.8307080488.

- B307110324 Memorandum & order modifying & clarifying scope of ASLB 830721 order re evidentiary presentation on Region III IE
  Insp Repts 50-454/82-05 Item 19 & 50-455/82-04 Item 19.
  SMITH, I. H. Atomic Safety and Licensing Board Panel. 83/07/07. 3pp. 19381:283. 24% Fiche: 50-454,83/07/07,8307110324.
- 8307120578 Advises of agreement between intervenors.NRC & util re inclusion.in evidentiary record.of portions of J Hughes 830926 ASLB-supervised deposition. Svc list encl. HHICHER.J.M. Businessmen for the Public Interest. HHICHER.J.M. League of Women Voters of Rockford. IL. HHICHER.J.M. Sinnissippi Alliance for the Environment (8AFE). 83/07/07. SMITH.I.H.. COLE.R.F., CALLAHAN.A.D. Atomic Safety and Licensing Board Panel. 5pp. 17432:161. 24X Fiche: 50-454.03/07/07, 8307120578.
- B307110051 Motion to extend, until B30805, filing of proposed findings of fact & conclusions of law on GA/GC issues. Contention 1A.

  Counsel workload heavy. Certificate of Svc encl.

  YDUNG, M. A. Hearing Branch 4. 83/07/08. Atomic Safety and Licensing Board Panel. 4pp. 19375:247. 24X Fiche: 50-454, 83/07/08, 8307110051.
- 8307120066 Notice of appeal of & list of exceptions to ABLB 830701 memorandum & order requiring NRC to present testimony at 830809 hearing on allegations re electrical contractor GA program-noted in ongoing investigation. W/Centificate of Bvc. YUUNG, M. A. Hearing Branch 4. B3/07/08. Atomic Safety and Licensing Appeal Panel. 7pp. 19423:107. 24X Fiche: 30-454, 83/07/08, 8307120066.
- 8307120072 Motion for directed certification of ASLB 830701 ruling requiring NRC to present testimony on & to produce documents re allegations noted in ongoing insp & investigations of contractor 9A program. Certificate of Svc encl.
  YOUNG, M. A., GOLDBERG, S. C. Hearing Branch 4. B3/07/OB. Atomic 8afety and Licensing Appeal Panel. 27pp. 19423:115. 24X Fiche: 30-454, 83/07/OB, 8307120072.
- 8307140433 Motion to extend, until 830305, time for filing proposed findings of fact & conclusions of law on GA/GC issues. Contention iA. Counsel workload heavy. Motion granted on 630708 by ABLB.
  YOUND, M. A. Hearing Branch 4. 83/07/08. Atomic Safety and Licensing Board Panel. 2pp. 19521; 250. 24X Fiche: 50-454, 83/07/08, 8307140433.
- B307130070 Order directing filing, by B30719, of responses to NRC B30708 motion for directed certification of ABLB B30701 order. SHOEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel. B3/07/11. 19. 19469:361. 24X Fiche: 50-454/83/07/11, B307130070.
- 8307130233 Application for stay of ASLB 830701 memorandum & order, pending ASLAB decision on NRC appeal & motion for directed certification. Objects to providing testimony re allegations until investigation complete. Certificate of Svc encl. YOUNO. M. A. Hearing Branch 4. 83/07/11. Atomic Safety and Licensing Board Panel. 11pp. 19507:313. 24X Fiche: 50-454, 83/07/11, 8307130233.
- 8307130280 Forwards amended Certificate of Svc to NRC 830708 motion for directed certification & notice of appeal & list of exceptions to ABLB 830701 memorandum & order. Amended Page 15 to directed certification motion also encl. YOUNO, M. A. Hearing Branch 4. 83/07/11. ELLPERIN, S.F., GOYCHY, R.L., KOHL, C.N. Atomic Safety and Licensing Appeal Panel. 1p. 19508:203. 24X Fiche: 50-454, 83/07/11, 8307130280.
- --8307130284 Amended Certificate of Svc to NRC 830708 notice of appeal & list of exceptions to ABLB 830701 memorandum & order.

  \*\* NRC No Detailed Affiliation Given. 83/07/11. Atomic Bafety and Licensing Appeal Panel. 2pp. 19508:204. 24X Fiche: 50-494,83/07/11,8307130280.
- --B307130270 Amended Certificate of Svc & Page 15 to NRC B3070B motion for directed certification. \* NRC - No Detailed Affiliation Given. B3/07/11. Atomic Bafety and Licensing Appeal Panel. 3pp. 19508: 206. 24X Ficha: 50-454,B3/07/11,B307130280.
- 8307130234 Forwards Page 51 to NRC 830701 proposed findings on Class 9 accidents & liquid pathways; inadvertently omitted from 830701 filing.
  RAW80N.R.J. Hearing Branch 3. 83/07/12. SMITH.J.W., COLE.R.F., CALLIHAN.A.D. Atomic 8efety and Licensing Board Panel. 1p. 19507:337. 24X Fiche: 50-454,83/07/12,8307130254.
- --8307130260 Page 51 to NRC 830701 proposed findings on Class 7 accidents & liquid pathways, inadvertently emitted from 830701 filing.

  \* NRC No Detailed Affiliation Given 83/07/12, 1p. 19507:338.
  24% Fichs: 50-454,83/07/12,8307130254.

- 8307150187 Memorandum announcing appointment of author to task force exploring procedures re cooperation w/0% of Investigations in licensing hearings. Future meetings will be limited to general principles of info transfer & protection.

  BMITH, I. W. Atomic Safety and Licensing Board Panel. 83/07/12, ip. 19531:067. 24X Fiche: 50-454:83/07/12,8307150187.
- B307200201 Forwards util B30603 deficiency rept re Westinghouse Model DB-416 reactor trip breaker, for info. New & redesigned undervoltage attachments in all DB-416 switchgear will be installed & tested before fuel load. Related correspondence. BLOOM. J. G. Isham. Lincoln & Beale. B3/07/12. SMITH. I. W., COLE. R. F., CALLIHAN. A. D. Atomic Safety and Licensing Board Panel. Spp. 19651: 159. 24X Fiche: 50-454,83/07/12.8307200201.
- 8307190122 Opposition to intervenor motion to suppl GA/GC record re preoperational testing. Motion deals w/matters tangential & immaterial to GA issues. Certificate of Svc encl.
  MILLER.M. I. Commonwealth Edison Co. MILLER.M. I. Isham, Lincoln & Beale. B3/07/13. Atomic Safety and Licensing Board Panel. 27pp. 19634: 337. 24X Fiche: 50-454, B3/07/13, B307190122.
- 8307150293 Memorandum & order ruling on admissibility of J Hughes testimony.

  BHITH, I.W. Atomic Safety and Licensing Board Ponel. 83/07/14. 6pp. 19532:197. 24X Fiche: 50-454,83/07/14.8307150293.
- 8307150302 Forwards Congressional Subcommittee on Oversight & Investigations 830617 memo, cited in NRC 830708 motion for directed ceptification.
  YOUNG.M.A. Hearing Branch 4. 83/07/14. ROSENTHAL, A.S., KOHL, C.N., GOTCHY, R.L. Atomic 8afety and Licensing Appeal Panel. 40pp. 19332:247. 24X Fiche: 50-454.83/07/14.8307150302.
- 8307190111 Memorandum of B30713 oral motion for extension until B30726 to file reply findings to Rockford League of Momen Voters proposed findings of fact & conclusions of law re steam generator tube integrity. Certificate of Svc encl.

  GOLDFEIN.M.R. Commonwealth Edison Co. GOLDFEIN.M.R. Isham, Lincoln & Beale. B3/07/14. App. 19634:282. 24X Fiche: 50-454,83/07/14, 8307190111.
- 8307190126 Reply to Dekalb Area Alliance for Responsible Energy/ Sinnissippi Alliance for Environ & Rockford League of Women Voters findings of fact & conclusions of law re emergency planning, Certificate of Svc encl. BIELAWSKI, A.P., COPELAND, V.Q. Commonwealth Edison Co. BIELAWSKI, A.P., Isham, Lincoln & Beale, 83/07/15, 19pp. 19635:230. 24X Fiche: 50-454,83/07/15,8307190126.
- B307200087 Forwards NRC reply to Rockford League of Women Voters proposed findings of fact & conclusions of law ro liquid pathway & Class 9 accidents.

  RAWBON.R. J. Hearing Branch 4. 83/07/18. SMITH. I.W., COLE, R.F., CALLIHAN, A.D. Atomic Bafety and Licensing Board Panel. 1p. 19647:163. 24X Fiche: 50-454, 83/07/18, 8307200087.
- --8307200093 Reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re liquid pathway & Class 9 accidents. Certificate of Bvc encl.
  RAMSON.R.J. Hearing Branch 4. 83/07/18. 9pp, 19647:164. 24X
  Fiche: 50-454.83/07/18.8307200087.
- 8307200109 Response opposing Joint Intervenors 830629 motion to suppl GA/QC record re preoperational testing. Deficiencies do not raise significant safety issue. Likelihood that different record on Contention 14 will be developed minimal. YOUNO, M. A. Hearing Branch 4. 83/07/19. Atomic Safety and Licensing Board Panel. 6pp. 19647:052. 24X Fiche: 50-434,83/07/18,8307200109.
- --8307200116 Affidavit of WL Forney re safety significance of noncompliances in insp repts attached to Joint Intervenors 830629 motion to suppl GA/GC record re preoperational testing. Prof qualifications encl.
  FORNEY.W. L. Region 3. Office of Director. 83/07/15. 6pp. 19647:058. 24X Fiche: 50-454.83/07/18.8307200109.
- 8307210236 Response apposing Rockford League of Wamen Voters proposed findings of fact & conclusions of law re liquid pathway. Proposed findings misstate record. Centificate of Svc encl. GALLO.J.: FURBE.M. C. Commonwealth Edison Co. GALLO.J.' Isham: Lincoln & Beale. 83/07/18. 8pp. 19664:184. 24X Fiche: 50-454,83/07/18.8307210236.
- 8307220417 Response opposing NRC motion for directed certification of ABLB 830621 & 0701 orders directing NRC to provide info. No valid reason presented to allow NRC to refuse to provide info. Certificate of Svc encl.
  HHIGHER.J.M. League of Women Voters of Rockford, IL. WHICHER.J.M. DEKAID Area Alliance for Responsible Energy. WHIGHER.J.M. Binnissippi Alliance for the Environment (BAFE). 83/07/18. Atomi 8afety and Licensing Appeal Panel. 23pp. 19687:240. 24X Fiche: 50-454,83/07/18.8307220417.

- 8307210211 Forwards response to NRC motion for directed certification, OALLO.J. Isham, Lincoln & Beale. GALLO.J. Commonwealth Edison Co. 83/07/19. ROSENTHAL.A.S., KOHL.C.N., COTCHY.R.L. Atomic Safety and Licensing Appeal Panel. 1p. 19666:356. 24X Fiche: 50-454,83/07/19,8307210211.
- --B307210217 Response supporting NRC B3070B motion for directed certification of issue of disclosure of detailed info re allegations subj. to ongoing insps & investigations. Notices of appearance & Certificate of Svc encl.

  OALLO, J., FITZ01BBDNS, R., STYLES, L. C. Commonwealth Edison Co B3/07/19. Atomic Safety and Licensing Appeal Panel. 39pp. 19666: 357. 24X Fiche: 50-454. 83/07/19. 8307210211
- 8307220354 Motion for leave to file amicus curiae brief re NRC refusal to provide info re allegations which are subj of ongoing investigations. Govt Accountability Project has substantial experience w/Region III.

  DEVINE.T., GARDE.B. Government Accountability Project. 83/07/19.

  Atomic Safety and Licensing Appeal Panel. 5pp. 19675:301, 24X

  Fiche: 30-454,83/07/19,8307220354.
- ---9307220355 Amicus curiae brief re NRC refusal to provide info re allegations which are subj of ongoing investigations NRC has no valid legal excuse to withhold evidence in dispute. NRC violated legal duty to disclose info. M/Certificate of Svc. DEVINE. T. GARDE, B. P. Government Accountability Project. 83/07/19. Atomic Safety and Licensing Appeal Panel. 22pp. 19475: 306. 24X Fiche: 50-454.83/07/19.8307220354.
- 830722034B Advises of error on Page 26 of applicant 830719 response to NRC motion for directed certification.

  STYLES.L.C. Isham, Lincoln & Beale. STYLES.L.C. Commonwealth Edison Co. 83/07/20. RDBENTHALLA.S., KCHL.C.N., GOTCHY.R.L. Atomic Bafety and Licensing Appeal Panel. ip. 19675:300. 24X
  Fiche: 50-454.83/07/20,830722034B.
- 8307220361 Memorandum & order reminding counsel & parties of confidentiality of certain info in J Hughes deposition.

  BMITH, I. W. Atomic Safety and Licensing Board Panel, 83/07/20, 1p. 19675; 233. 24X Fiche: 50-454,83/07/20,8307220361.
- 8307260258 Revised findings of fact & opinion on Rockford League of Women Voters Contention 22 & Dekalb Area Alliance for Responsible Energy/Binnissippi Alliance for Environ Contention 9(c). Certificate of Svc encl.

  \* League of Women Voters of Rockford, 1L. \* Dekalb Area Alliance for Responsible Energy. \* Sinnissippi Alliance for the Environment (BAFE). B3/07/20. 47pp. 19727:040. 24X Fiche:50-454,83/07/20, B307260208.
- B3072402BB Response opposing NRC B30711 application for stay of effectiveness of B30621 & 0701 orders re withholding evidence. Requisite showing to support stay not established. Certificate of EVC encl.
  WHICHER.J.M. Dekalb Area Alliance for Responsible Energy.
  WHICHER.J.M. Whicher, J.M. 83/07/21. Atomic Safety and Licensing Board Panel. 5pp. 19726: 208. 24X Fiche: 50-454, B3/07/21: 8307240288.
- 8307260309 Forwards revised findings of fact & opinion on Rockford League of Women Voters Contention 22 & DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 9 re steam generators. W/o encls.

  JOHNSON. B. League of Homen Voters of Rockford, IL. 83/07/21.

  SMITH. I. W., COLE. R. F., CALLIHAN. A. D. Atomic Safety and Licensing Board Panei. 1p. 19726: 292. 24X Fiche: 50-494, 83/07/21, 8307260309.
- 8307260425 Response supporting intervenor motion to suppl GA/GC record on preoperational testing.per 830721 telcon. GA/GC concerns arise out of entire scope of Region III insps & cannot be separated from preoperational testing.

  WHICHER, J.M. League of Homen Voters of Rockford, it. WHICHER, J.M. DeKalb Area Alliance for Responsible Energy. WHICHER, J.M. Whicher, J.M. 82/07/21. Atomic Safety and Licensing Board Panel. 6pp. 19734:033. 24% Fiche: 50-454,83/07/21,8307260425.
- 8307230345 Response apposing NRC application for stay of ASLB 830701 memorandum & order memorializing 830427 & 30 conference call rulings NRC showing of irreparable harm insufficient. Certificate of 8vc encl. OALLO, J. FITZGIBBONS.R. Commonwealth Edison Co. OALLO, J. Isham. Lincoln & Beals. 83/07/22. Atomic Safety and Licensing Board Panel. 9pp. 19703:355. 24X Fiche: 50-454,83/07/22,8307250365.
- B307260042 Response to Govt Accountability Project 830719 motion to file amicus curiae brief. NRC does not object despite doubts about brief value to decisional process. NRC categorically rejects validity of Project reasoning. W/Certificate of Svc. GOLDBERG. S. C. Hearing Branch 4. B3/07/22. Atomic Safety and Licensing Appeal Panel. App. 19727:345. 24X Fiche: 50-454.83/07/22, 8307260042.

- 8307260310 Response opposing Boyt Accountability Project motion for leave to file amicus curiae brief re NRC 830708 certification motion. Project interest ill-founded & arguments immaterial Certificate of Syc encl.

  GALLO, J. Commonwealth Edison Co. GALLO, J. Isham, Lincoln & Beale. 83/07/22. Atomic Safety and Licensing Appeal Panel. 4pp. 19726:077. 24X Fiche: 50-454,83/07/22,8307260310.
- 8307280232 Memorandum & order denying NRC 8307t1 motion for stay of ASLB 830701 memorandum & order re evidentiary hearing on Region III & Ofc of Investigation investigations of Hatfield Electric GA program.
  SMITH, I. W. Atomic Safety and Licensing Board Panel. 83/07/26. Office of the Elecutive Legal Director. 13pp. 19794:149. 24X Fiche: 50-454,83/07/26,8307280232.
- G307290102 Forwards reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re steam generator twhe integrity.

  GOLDFEIN, M.R. Isham, Lincoln & Beale, GOLDFEIN, M.R. Commonwealth Edison Co. B3/07/26, SMITH.I.W. COLE.R.F., CALLIHAN.A.D. Atomic Bafety and Licensing Board Panel. 1p. 19820: 336. 24X Fichs: 50-434,83/07/26,8307290102.
- --8307290105 Reply opposing Rockford League of Women Voters proposed findings of fact & conclusions of law re steam generator tube integrity. Certificate of Svc encl.
  GALLO.J. OCDFEIN.M.R. Commonwealth Edison Co. GALLO.J. Isham, Lincoln & Deale. 83/07/26. 20pp. 19820:337. 24X
  Fiche: 50-454,83/07/26,8307290102.
- 8307280194 Memorandum & Order ALAB-735 denying & dismissing NRC motion for directed certification & appeal, respectively re ASLB 830701 memorandum & order reopening record on GA issues. NRC may file motion for reconsideration.

  SHORMAKER.C.J. Atomic Safety and Licensing Appeal Panel. 83/07/27. Office of the Executive Legal Director. 12pg. 19792:047. 24X Fiche: 50-454, 83/07/27, 8307280154.
- G. Inspection reports, 1E Bulletins & correspondence
- 830708000? Forwards IE Insp Regts 50-454/83-20 & 50-455/83-17 on 830503-04 & 09-12 & notice of violation. SPESSARD, R. L. Region 3. Office of Director. 83/06/22. REED. C. Commonwealth Edison Co. 2pp. 19351: 224. 24X Fiche: 50-454,83/06/22,8307080009.
- --8307080012 Notice of violation from insp on 830503-04 & 09-12. SPESSARD.R.L. Region 3. Office of Director. 83/06/22. 4pp. 19351:226. 24X Fiche:50-454.83/06/22.8307080009.
- --8307080014 IE Insp Repts 50-454/83-20 & 50-455/83-17 on 830503-04 & 09-12 Noncompliance noted inadequate GC for whip restraint installation inadequate audit of site whip restraint activities & lack of adequate prevention for snubber damage. YIN I.T., DANIELSON, D. H. Region 3. Office of Director. 83/06/22, 11pp. 19351:230. 24% Fiche:50-454.83/06/22, 8307080009.
- B307180003 Forwards IE insp Reptw 50-454/83-26 & 50-455/83-19 on B30607-10. No noncompliance noted. KNDP.R. C. Region 3. Office of Director. 83/06/28. REED.C. Commonwealth Edison Co. 2pp. 20078:271. 24X Fiche: 50-454, 83/06/28, 8307180003.
- --8307180007 IE Insp Repts 50-454/83-26 & 50-455/83-19 on 830607-10. No noncompliance noted. Major areas inspected status of reinsp program & status of program for key contractors per IE Insp Repts 50-454/82-05 & 50-455/82-05. HAYES, D. H., HINDS, J. M., KNOP, R. C. Region 3, Office of Director. 83/06/27. 16pp. 20078:273. 24X Ficha: 50-494,83/06/28.8307180003.
- 8307140071 Forwards IE Insp Rept 50-454/83-25 on 830607-10 No noncompliance noted.
  LITTLE.W.S. Region 3. Office of Director. 83/07/01. REED.C. Commonwealth Edison Co. 2pp. 19514:074. 24% Fiche: 50-454, 83/07/01. 8307140071.
- --8307140074 IE Insp Rept 50-454/83-25 on 830607-10. No noncompliance noted Major areas inspected observation of electrical component & instrument component work activities & review of records.

  MENDEZ.R. WILLIAMS.C.C. Region 3: Office of Director. 83/06/30, 8pp. 19314:078. 24X Fiche:50-454,83/07/01.8307140071.
- 8307200200 Forwards IE Insp Rept 50-454/83-24 on 830505-0610 No noncompliance noted.

  STREETER, J. F. Region 3, Office of Director. 83/07/05. REED. C. Commonwealth Edison Co. 2pp. 19648:001 24x Fiche: 50-454,83/07/05,8307200200.

- --8307200204 IE Insp Rept 50-454/83-24 on 830505-0610.No noncompliance noted Major areas inspected preoperational test procedures, performance of preoperational testing & review of preoperational testing QA.

  REYES, L. A., RING, M. A., CHOULES, N. C. Region 3, Office of Director, 83/07/05. 6pp. 19648:003. 24X Fiche: 50-454,83/07/05,8307200200.
- 8307110139 Ack receipt of 830627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/83-16.
  LITTLE.W.S. Region 3. Office of Director. 83/07/06. REED.C. Commonwealth Edison Co. ip. 19377: 200. 24X Fiche: 50-454.83/07/06.8307110139.
- --8307110146 Responds to NRC 830931 ltr re violations noted in IE Insp. Rept 50-454/83-16. Corrective actions: interim lead auditor concept discontinued & request submitted to ASME/ANSI requesting other provisions be provided in std. FARRAN, D. L. Commonwealth Edison Co. 83/06/27. KEPPLER, J. 0. Region 3. Office of Director. 3pp. 19377:201. 24% Fiche: 50-454, 83/07/06, 8307110139.
- 8307180016 Forwards IE Insp Repts 50-454/83-28 & 50-455/83-21 on 830621-23 & 29. No noncompliance noted. PAPERIELLO.C. J. Region 3, Office of Director. 83/07/07. REED.C. Commonwealth Edison Co. 2pp. 19560:284. 24X Fiche:50-454/83/07/07, 8307180014
- --8307180018 IE Insp Repts 50-454/83-28 & 50-455/83-21 on 830621-23 & 29. No noncompliance noted Major areas inspected environ protection, review of chemistry & radiochemistry program & procedures & review of actions on previous open items.

  DESTMANN, M. J. , SCHUMACHER, M. G. Region 3, Office of Director.

  83/07/06. App. 19360: 286. 24X Fiche: 50-454, 83/07/07, 8307180016.
- B307220546 Forwards IE Insp Repts 50-454/B3-27 & 50-455/B3-20 on B30613.No noncompliance noted. PAPERIELLO.C.J. Region 3, Office of Director. B3/07/08. REED.C. Commonwealth Edison Co. 2pp. 19686:041. 24X Fiche: 50-454, 83/07/08, 8307220546.
- --8307220553 IE Insp Repts 50-454/83-27 & 50-455/83-20 on B30615. No noncompliance noted Major areas inspected emergency medical drill. GLOERBON, W. , SMITH, M. , AXELSON, W.L. Region 3, Office of Director. 83/07/07. 8pp. 19686:043. 24X Fiche: 30-454,83/07/08,8307220546.
- B306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153, 24X Fiche: 50-000,83/07/12,8306270404.
- B307190145 Ack receipt of B30506 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50~454/B3-07 & 50~455/B3-07.
  NDRELIUS.C.E. Division of Project & Resident Programs. 83/07/I3.
  REED.C. Commonwealth Edison Co. 2pp. 19636:177. 24X
  Fiche: 50-454,83/07/I3,8307190145.
- --8307190147 Responds to NRC 830404 ltr re violations noted in IE Insp. Repts 50-454/83-07 & 50-455/83-07. Corrective actions: Level III GA manager appointed on 830324 & all contractors requested to notify util of changes in GC inspectors. FARRAR.D.L. Commonwealth Edison Co. 83/05/06 KEPPLER.J.O. Region 3. Office of Director. 10pp. 19636: 179. 24% Fiche: 50-454, 83/07/13: 8307170145.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl. TAYLOR, J. M. Division of QA. Bafeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19713:270. 24X Fiche: 30-000:83/07/14.8306270406.
- 8306270415 Board Notification 83-097: forwards draft SALP rept for Jan-Dec 1982 & util 830712 response. NOVAK, T. M. Assistant Director for Licensing. 83/07/22. Atomic Safety and Licensing 80ard Panel. 3pp. 19767:043. 24X Fiche: 50-454, 83/07/22, 8306270415.
- --8307270453 Forwards preliminary BALP rept for Jan-Dec 1982, for review prior to 830613 meeting to discuss observations & findings.
  HIND, J.A. Division of Radiological & Materials Safety Programs, 83706708. REED. C. Commonwealth Edison Co. 32pp. 19767:046. 24X Fiche: 50-454, 83/07/22, 8306270415.

- --8307270454 Forwards comments on SALP rept based on discussion at 830613 public meeting. Evaluation distressing, since NRC prepared testimony in licensing proceedings stating that util had implemented acceptable GA program.

  STIEDE.W.L. Commonwealth Edison Co. 83/07/12. KEPPLER, J. G. Region 3, Defice of Director. 28pp. 19767:078. 24X
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util.per 830715 discussion.

  NORELIUS.C.E. Division of Project & Resident Programs. 83/07/22, REED.C. Commonwealth Edison Co. 2pp. 19791: 169, 24X Fiche: 50-000, 83/07/22, 8307280084.
- --8307280102 Confirms request for NRC & util senior mgt meeting on 830726 in Chicago IL to discuss licensee regulatory performance & relationship w/NRC.

  REED.C. Commonwealth Edison Co. 83/07/11. DAVIS, B. A. Region 3, Office of Director. 1p. 19791:171. 24X Fiche:50-000.83/07/22, 8307290884

#### 8. Reportable occurrences, LERs & related correspondence

- 8307180099 RO: on 830630, during (nsp of spent fuel rack, five propane gas cylinders found in spent fuel pool area. Caused by personnel error. Cylinders will be stored outside fuel handling bldg. Signs re combustible matl will be posted. QUERIO.R. E., CHOMACKE. A. C. Commonwealth Edison Co. 83/07/08. KEPPLER. J. G. Region 3. Office of Director. 2pp. 19557:003. 24X Fiche: 50-454,83/07/08,8307180099.
- 8307200201 Forwards util 830603 deficiency rept re Westinghouse Model DB-416 reactor trip breaker-for info. New & redesigned undervoltage attachments in all DB-416 switchgear will be installed & tested before fuel load. Related correspondence. BLOOM, J. G. Isham, Lincoln & Beale. B3/07/12. SMITH, I. W., COLE, R. F., CALLIMAN, A. D. Atomic Safety and Licensing Board Panel. Spp. 19651:139. 24X Fiche: 50-454, 83/07/12. 8307200201.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.
  LITKA: T. J. Elcen Metal Products Co. 83/07/15. KEPPLER, J. Q. Region 3, Office of Director. 26pp. 19686:086. 24X Fiche: 50-000, 83/07/15, 8307220446.
- B307250432 Interim deficiency rept re excess carbon content in spring hangers supplied by Elcen Metal Products. Initially reported on B30617. Approx 40 hangers at each site being evaluated. Final rept expected within 90 days.

  TRAMM.T.R. Commonwealth Edison Co. B3/07/18. KEPPLER.J. Q. Region 3, Office of Director. 2pp. 19702:168. 24X Fiche: 50-000.B3/07/18.B307250432.

#### V. Operator Examinations

- 8307130305 Daily highlights memo on results of written exam administered to cold license candidates. Next written exam scheduled for wk of 831027.

  OLBHAN, L.N. Licensing Branch 1. 83/07/07 DENTON, H. R., CASE, E. Office of Nuclear Reactor Regulation. Director. EISENHUT, D. Division of Licensing. 1p. 19511:362. 24X Fiche: 50-454, 83/07/07, 8307130305.
- DOCKET STN-50~455 BYRON STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8305310033 Summary of 83051B meeting w/util.Westinghouse & GE in Bethesda-MD re Tech Spec requirements concerning outage times for redundant safety-related equipment.Viewgraphs enct. DLSHAN.L.N. Licensing Branch 1. 83/05/19. Eicensing Branch 1. 29pp. 18463:099. 24X Fiche:50-454,83/03/19.8305310033.
- 8304040070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Byc list encl.
  EISENHUT.D.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 17563:116. 24X Fiche: 50-000,83/06/03. B306060070.
- B306230264 Forwards advance revised pages to FBAR necessary to reclassify spent fuel pool liner from safety Category I structure to Category II. Info will be incorporated into next amend to FBAR.

  TRAMM.T.R. Commonwealth Edison Co. 83/06/20. DENION,H.R. Office of Nuclear Reactor Regulation. Director. 7pp. 18745:076. 24X Fiche: 50-000.83/06/20.8306230264.

- 8307200231 Notification of 830707 meeting w/technical review committee in Bethesda.MD to discuss review of D4,D5 /r E steam generator mods.

  HDPKINS.U. B. Licensing Branch 4. 83/07/01. ADENSAM.E.G. Licensin: Branch 4. 2pp. 19670:254. 24X Fiche: 50-000.83/07/01.8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for GLs & holders of GPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/05. Conspidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- B307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc list encl. EISENNUT.D.C. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000.83/07/06, 8307060329.
- 8307120281 Requests add1 examption from Type C testing requirements for containment sump isolation valves MOVSI8811A & B per 830419. It concerning containment leak rate testing Justification provided.

  LENTINE, F. G. Commonwealth Edison Co. 83/07/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19424:114. 24X Fiche: 50-000, 83/07/07, 8307120281.
- 8307130309 Forwards responses to SGRT & pump & valve operability review team audits & responses to addlitems discussed at 830513 meeting w/NRC in Bethesda.MD.
  8WARTZ.E.D. Commonwealth Edison Co. 83/07/07. DENTON, H. R. D
- --8307130322 Rev O to "Environ Qualification of Mechanical Equipment for Comm Ed Byron Units 1 & 2. Braidwood Units 1 & 2. Component Pacific Safety Injection Pump Model 3-Inch 10 Stage JHF."

  ZEGAR, M. J., WALKER, L. I. Commonwealth Edison Co. EG&T-EQT-204 ROO. B3/06/20. 84pp. 19469:185. 24X Fiche: 50-000, B3/07/07, B307130309.
- --8307130325 "Ryron Pump & Valve Operability Summary."

  KAMENIC, M., SNIDER, J. M. Hestinghouse Electric Corp. CAE-05-01.

  83/06/10. 40pp. 19469:270. 24X Ficha: 50-000,83/07/07,8307130309.
- --8307130333 "Environ Qualification for Class IE Lead Acid Storage Batteries." HOPEMELL.R.W. DESALR.H. Gould, Inc. 83/07/07. 188pp. 19472:137. 24X Fiche:50-000.83/07/07.8307130309.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307260516 Forwards memo describing actions taken to resolve UH Conran differing prof opinion re sys interaction (Unresolved Safety Issue A-17) & safety classification.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
  83/07/11. CONRAN.J.H. Reliability & Risk Assessment Branch. 2pp. 19782:241. 24X Fiche: 50-000.83/07/11.8307260516.
- ---B306080367 Forwards comments on mgt views & positions on sys interaction per differing prof opinion in response to 830418 & 0305 memos. Excerpts from Suffolk County 830509 submittal & proposed request for add) info re Byron/Braidwood enci.
  CONRAN. J. H. Reliability & Risk Assessment Branch. 83/05/25. RUSSELL: W. T. Systematis Evaluation Program Branch. 74pp. 19783: 033. 24% Fiche: 50-000. B3/07/11, 8307260516.
- 8307250124 Summary of 830707 meeting w/technical review committee in Bethesda.MD re Model D4/D5/E steam generator mod.Viewgraphs eacl.
  HOPKINS, J. B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 26pp. 19738: 132. 24X Fiche: 50-000/83/07/18, 8307250124.
- 8307290430 Forwards SER addressing environ qualification program for electrical equipment important to safety & safety-related equipment. Outstanding info identified in Sections 3.11.3 & 3.11.4 should be provided by 830930. YOUNGBLOOD, B. J. Licensing Branch 1. 83/07/20. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19858:001. 24X Fiche: 50~454,83/07/20,8307290430.

- --8307290437 SER identifying outstanding info in Sections 3.11.3 & 3.11.4, "Environ Qualification Program for Electrical Equipment Important to Safety & Safety-Related Mechanical Equipment."

  \* Equipment Qualification Branch. 83/07/20. idpp. 19858:003.24% Fichs: 50-454,83/07/20. 8307290430.
- 8307290047 Advises that energy absorbing math used in pipe whip restraint design not properly qualified for design applications used at facilities. Recommended position to resolve issue entl.
  YOUNGBLOOD B. J. Licensing Branch 1. 83/07/21. FARRAR, D. L. Commonwealth Edison Co. 1p. 19857:026. 24X Fiche: 50-000, 83/07/21, 8307290047.
- --8307290072 Trip rept of 830511-12 visit to Region III ofc.Byron site & Sargent & Lundy Chicago. IL ofc re design, installation & testing of pipe restraints using energy absorbing matl.

  TERAO.D. Hechanical Engineering Branch. 83/05/26. BOSNAK.R.J. Hechanical Engineering Branch. 4pp. 19857:033. 24X

  Ficha: 50-000,83/07/21,8307290047.
- F. Security, medical, emergency & fire protection plans
- B307220546 Forwards IE Insp Reg ts 50-454/83-27 & 50-455/83-20 on 830615. No noncompliance noted.
  PAPERIELLO, C. J. Region 3, Office of Director. 83/07/08. REED, C. Commonwealth Edison Co. 2pp. 17686: 041. 24X Fiche: 50-454, 83/07/08, 8307220546.
- 8307260018 Submits supplemental response to NUREG-0737. Suppl I (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display sys verification to be performed w/verification program. SWARTZ-E.D. Commonwealth Edison Co. 83/07/20. DENTON. H. R. Dffice of Nuclear Reactor Regulation. Director. 2gp. 19727:177. 24X Fichs: 30-000.83/07/20.8307260018.
- 8307280347 Forwards review of draft Rev 4 to generic portion of gamerating station emergency plan. Plan deficiencies marked. Flow chart for general emergency offsite protective decisions enci. PAPERIELLO.C.J. Region 3, Office of Director. 83/07/26. REED.C Commonwealth Edison Co. 10pp. 19789:018. 24X Fiche: 50-000.83/07/26.8307280347.
- Adjudícatory correspondence
- 83070530003 Forwards NRC Press Release 83-44 re proposed imposition of \$150,000 in civil penalties for alleged shutdown regulation violations. Intervenors will seek to admit press release & associated inspirepts into evidence. Svc list encl. MHICHER, J. H. Businessmen for the Public Interest. 83/06/29. SMITH. I. W., CALLAHAN, A. D., CULE, F. Atomic Safety and Licensing Board Panel. 4pp. 19192:117. 24X Fiche: 50-454.83/06/29,8307050003.
- B307050011 Forwards stipulation re recent fine imposed on util & agreement to delete portions of JH Hughes deposition. B3/06/29. WHICHER, J. M. Businessmen for the Public Interest. B3/06/29. SMITH. I.W. CALLAHAN, A. D., COLE. R.F. Atomic Safety and Licensing Board Panel. 2pp. 19192:084. 24X Fiche: 50-454.83/06/29.8307050011.
- --8307050020 Stipulation on deletion of portions of util witness
  JH Hughes 830519 deposition.
  GBLBBERG.S.C. Hearing Branch 4. HILLER.M. Commonwealth Edison
  Co. HHICHER.J.M. League of Women Voters of Rockford, IL.
  83/05/31. 2pp. 19192:086. 24X Fiche:50-454-63/06/29,8307050011.
- --B307030032 Stipulation re recent fine imposed on util for failure to maintain operability of one of two instrument channels in trip sys B. Svc list encl.

  OOLDBERG, S. Hearing Branch 4. BICKER, B.D. Commonwealth Edison Co. HHICHER, J.M. League of Women Voters of Roctford, IL.

  B3/06/20. Spp. 19192:088. 24X Fiche: 50-454, 83/06/29, 8307050011.
- 8307050227 Notion to suppl closed GA/QC record w/info on preoperational testing Exhibits show evidence of severe deficiencies in preoperational testing program Certificate of Svc encl. WHICHER, J. M. Lague of Homen Voters of Rockford, 11. WHICHER, J. M. DeKalb Area Alliance for Responsible Energy. WHICHER, J. M. Sinnissippi Alliance for the Environment (SAFE). 83/06/29. Atomic SaFety and Licensing Board Panel. 39pp. 19197:237. 24X Fiche: 50-454,83/06/29,8307050227.
- B307060355 Reply to Rockford League of Homen Voters proposed findings of fact & conclusions of law re ALARA. Certificate of Sycents.

  MRIJER M. L. MEGGIN M. O. Consequently Sychology Co. MINER M. L.
- Willer, M. I., HERRIN, M. O. Commonwealth Edison Co. MILLER, M. I. Isham, Lincoln & Beale, 83/06/30, [app. 19234:147, 24X Fiche: 50-454,83/06/30,8307060355.

- 8307060375 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on Class 7 accidents & liquid pathway releases. Certificate of Svc encl. RAHSON.R.J. Hearing Branch 3. 83/07/01. 95pp. 19236:122. 24X Fiche: 50-454.83/07/01.8307060375.
- 8307040400 Memorandum & order directing NRC to present evidence on cited portion of Region III testimony re ongoing NRC insps & investigations. NRC fails to discuss why protective procedures inapplicable.

  SMITH. I. W. Atomic Safety and Licensing Board Panel. 83/07/01.

  Office of the Executive Legal Director. 49p. 19234:294. 24X Fiche:30-454.83/07/01.8307040400.
- 8307070207 Proposed findings of fact & conclusions of law re Class 9 accidents. Certificate of Svc vncl.

  GALLO, J., HERRIN, M. G. Commonwealth Edison Co. GALLO, J. Isham, Lincoln & Beale. 83/07/01. 53pp. 19269:106. 24X

  Fiche: 50-454, 83/07/01. 8307070207.
- B307070209 Proposed findings of fact & conclusions of law re liquid pathway & Class 9 accidents. Certificate of Svc encl.
  THOMAS.D.C. League of Women Voters of Rockford, IL. B3/07/01.
  23pp. 19269: 200. 24X Fiche: 50-454.B3/07/01.B307070209.
- B307110057 Proposed findings of fact & conclusions of law re steam generator tube integrity. \* League of Women Voters of Rockford, IL. 83/07/01. Atomic Safety and Licensing Board Panel. 107pp. 19375:144. 24X Fiche: 50-454, 83/07/01, 8307110057.
- 8307080488 Presents info proving Hughes allegations intimately connected w/noncompliance noted in IE Insp Rept 50-434/82-05, Item 19 re reinsp program. WHICHER, J. M. Businessmen for the Public Interest. 83/07/05. SHITM. I. W., COLE, R. F., CALLAHAN, A. D. Atomic Safety and Licensing Board Panel. 6pp. 19346: 328. 24X Fiche: 50-454.83/07/05,8307080488.
- 8307110324 Memorandum & order modifying & clarifying scope of ASL8 830721 order re evidentiary presentation on Region III IE Insp Repts 50-454/82-05 Item 19 & 50-455/82-04 Item 19. 8MITM.I.W. Atomic Safety and Licensing Board Panel. 83/07/07. 3pp. 19381:283. 24X Fiche: 50-454-83/07/07.8307110324.
- 8307120578 Advises of agreement between intervenors, NRC & util reinclusion, in evidentiary record, of portions of J Hughes 830526 ASLS-supervised deposition. Svc list and. WHICHER, J.M. Businessmen for the Public Interest. WHICHER, J.M. League of Homen Voters of Rockford, IL. WHICHER, J.M. Sinnissippi Allience for the Environment (SAFE). 83/07/07, SMITH, I.W., COLER, F., CALLAHAN, A.D. Atomic Safety and Licensing Board Panel, 5pp. 19432:161. 24X Fiche: 50-454, 83/07/07, 8307120578.
- 8307110051 Motion to extend, until 830805, filing of proposed findings of fact & conclusions of law on GA/OC issues, Contention 1A. Counsel workload heavy. Certificate of Svc encl. YOUNG, M.A. Hearing Branch 4. 83/07/08. Atomic Safety and Licensing Board Panel. 4pp. 17375:247. 24X Fiche: 50-454, 83/07/08, 8307110051.
- 8307120066 Notice of appeal of & list of exceptions to ABLB B30701 memorandum & order requiring NRC to present testimony at 830807 hearing on allegations re electrical contractor QA program.noted in ongoing investigation. W/Certificate of Svc. YOUNO.M.A. Hearing Branch 4. 83/07/08. Atomic Safety and Licensing Appeal Panel. 7pp. 19423:107. 24X Fiche: 50-454.83/07/08, 8307120066.
- 8307120072 Motion for directed certification of ASLB 830701 ruling requiring NRC to present testimony on & to produce documents re allegations noted in ongoing insp & investigations of contractor GA program. Certificate of Svc encl.
  YOUNG-M.A., GOLDBERG-S.C. Hearing Branch 4. B3/07/08. Atomic Safety and Licensing Appeal Panel. 27pp. 19423:115. 24X Fiche: 50-454,83/07/08,8307120072.
- B307140433 Motion to extend, until 830305, time for filing proposed findings of fact & conclusions of law on GA/GC issues, Contention IA. Counsel workload heavy Motion granted on 830708 by ASLB.
  YOUND, M. A. Hearing Branch 4. B3/07/0B. Atomic Safety and Licensing Board Panel. 2pp. 19821:250. 24X Fiche:50-454,83/07/0B,8307140433.
- B3071300/0 Order directing filing, by B30719, of responses to NRC B30708 motion for directed certification of ASLB B30701 order. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. B3/07/11. p. 17465:361. 24X Fiche: 50-454, B3/07/11, B307130070.

- B307130233 Application for stay of ASLB 830701 memorandum & order, pending ASLAB decision on NRC appeal & motion for directed certification. Dbjects to providing testimony re allegations until investigation complete. Certificate of Svc encl. YOUNG.M.A. Hearing Branch 4. 83/07/11. Atomic Safety and Licensing Board Panel. 11pp. 19507:313. 24X Fiche: 50-454, 83/07/11, 8307130233.
- B307130280 Forwards amended Certificate of Svc to NRC B30708 motion for directed certification & notice of appeal & list of exceptions to ASLB 830701 memorandum & order Amended Page 15 to directed certification motion also encl.
  YOUNG.M.A. Hearing Branch 4. 83/07/11. EILPERIN.S.F., ODTCHY.R.L., KDML.C.N. Atomic Safety and Licensing Appeal Panel. 1p. 17508:203. 24X Fiche: 50-454.83/07/11.8307130280.
- --8307130284 Amended Certificate of Svc to NRC B30708 notice of appeal & list of exceptions to ASLB B30701 memorandum & order.

  NRC No Detailed Affiliation Given. B3/07/11. Atomic Safety and Licensing Appeal Panel. 2pp. 19508: 204. 24X Fiche: 50-454, B3/07/11, B307130280.
- ---8307130270 Amended Certificate of Svc & Page 15 to NRC 830708 motion for directed certification.

  \* NRC No Detailed Affiliation Given. 83/07/11. Atomic Safety and Licensing Appeal Panel. 3pp. 19508:206. 24% Fiche: 50-454,83/07/11,8307130280.
- B307130234 Forwards Page 31 to NRC B30701 proposed findings on Class 9 accidents & liquid pathways inadvertently omitted from 830701 filing.
  RAMSON.R.J. Hearing Branch 3. 83/07/12. SMITH.J.W., COLE.R.F., CALLIHAN.A.D. Atomic Safety and Licensing Board Panel. 1p. 19507:337. 24X Fiche: 50-454.83/07/12.8307130254.
- --8307130260 Page 51 to NRC 830701 proposed findings on Class 9 accidents & liquid pathways inadvertently untitled from 830701 filing. \* NRC - No Detailed Affiliation Given. 83/07/12. 1p. 19507:338. 24X Fiche: 50-454,83/07/12,8307130254.
- ### B307150187 Memorandum announcing appointment of author to task force exploring procedures re cooperation w/Ofc of Investigations in licensing hearings. Future meetings will be limited to general principles of info transfer & protection.

  SMITH.I.W. Atomic Safety and Licensing Board Panel. 83/07/12. 1p. 19831:067. 24X Fiche: 50-454. 83/07/12. 8307190187.
- EG07200201 Forwards util B30603 deficiency rept re Westinghouse Model D9-416 reactor trip breaker, for info. New & redesigned undervoltage attachments in all D8-416 switchgear will be installed & tested before fuel load. Related correspondence. BLOOM.J. G. Isham. Lincoln & Beals. 83/07/12. SMITH.I.W., COLE, R.F., CALLIHAN.A.D. Atomic Bafety and Licensing Board Panel. 3pp. 19651:159. 24X Fiche: \$0-454.83/07/12.8307200201.
- #3307190122 Opposition to intervenor motion to suppl GA/GC record represperational testing Motion deals w/matters tangential & immaterial to GA issues. Certificate of Svc enci.

  MILLER, M. I. Commonwealth Edison Co. MILLER, M. I. Isham, Lincoln & Beals. #3707/13. Atomic Safety and Liconsing Board Panel. 27pp. 19634:337. 24X Fiche: 50-454,83/07/13,8307190122.
- 8307150273 Memorandum & order ruling on admissibility of J Hughes testimony.
  8MITH.I.W. Atomic Safety and Licensing Board Panel. 83/07/14. 6pp. 19532:197. 24X Fiche: 50-454,83/07/14,8307150293.
- B307150302 Forwards Congressional Subcommittee on Oversight & Investigations 830417 memo.cited in NRC 830708 motion for directed certification.
  YOUNO.M.A. Hearing Branch 4. 83/07/14. ROSENTHAL.A.S., KOHL.C.N., OUTCHY.R.L. Atomic Safety and Licensing Appeal Panel. 40pp. 19532:247. 24X Fiche: 50-454, 83/07/14, 8307150302.
- #3907190111 Memorandum of 830713 oral motion for extension until 830726 to file reply findings to Rockford League of Women Voters proposed findings of fact & conclusions of law re steam generator tube integrity. Centificate of Svc encl.

  OOLDFEIN.M.R. Commonwealth Edison Co. GOLDFEIN.M.R. Isham, Lincoln & Beale. 83/07/14. 4pp. 19634:282. 24X Fiche: 50-454.83/07/14.
- ##307170126 Reply to Dekalb Area Alliance for Responsible Energy/
  Sinnissippi Alliance for Environ & Rockford League of Women
  Vaters findings of fact & conclusions of law re emergency
  planning. Certificate of Eve encl.

  BIELAWSKI.A.P. COPELAND.V.O. Commonwealth Edison Co.
  BIELAWSKI.A.P. Isham. Lincoln & Beale. 83/07/15. 17pp. 19635: 230.

  24X Fiche: 50-454, 83/07/15, 8307190126.

- 8307200087 Forwards NRC reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re liquid pathway & Class 9 accidents.

  RANSON,R. J. Hearing Branch 4 83/07/18. SMITH, I. N., COLE, R. F., CALLIHAN, A. D. Atomic Safety and Licensing Board Panel. | Ip. 19647: 163. 24x Fiche: 50-454, 83/07/18, 8307200087.
- --8307200093 Reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re liquid pathway & Class 9 accidents. Cortificate of Svc encl.

  RAWSON R J. Hearing Branch 4, 83/07/18 9pp. 19647:164. 24X Fiche: 50-454,83/07/18,8307200087.
- 8307200107 Response opposing Joint Intervenors 830627 motion to suppl QA/QC record re-preoperational testing. Deficiencies do not raise significant safety issue. Likelihood that different record on Contention 1A will be developed minimal. YOUNG, M.A. Hearing Branch 4. 83/07/18 Atomic Safety and Licensing Board Panel. 6pp. 17647:052. 24X Fiche: 50-454, 83/07/18, 830720109
- --B307200116 Affidavit of WL Formey re safety significance of noncompliances in inspirepts attached to Joint Intervenors 830629 motion to suppl QA/QC record re preoperational testing. Prof qualifications encl. FORNEY, W. L. Region 3, Office of Director, B3/07/15, App. 19447:058. 24X Fiche: 50-454, B3/07/18, B307200109.
- 8307210236 Response apposing Rackford League of Homen Voters proposed findings of fact & conclusions of law re liquid pathway.

  Proposed findings misstate record Certificate of Svc encl.

  GALLO, J. FURSE, M. C. Commonwealth Edison Co. GALLO, J. Isham,
  Linceln & Beale. 83/07/18. 8pp. 19664:184. 24X

  Fiche: 50-454,83/07/18,8307210236.
- 8307220417 Response opposing NRC motion for directed certification of ASLB 830621 & 0701 orders directing NRC to provide info No valid reason presented to allow NRC to refuse to provide info. Certificate of Svc encl.
  WHICHER, J. M. League of Women Voters of Rockford, IL. WHICHER, J. M. DeKalb Area Alliance for Responsible Energy. WHICHER, J. M. Sinnissippi Alliance for the Environment (8AFE). 83/07/18. Atomic Safety and Licensing Appeal Panel. 23pp. 19697:240. 24X Fiche: 50-459, 93/07/18. 8307220417.
- 8307210211 Forwards response to NRC motion for directed certification. QALLO, J. Isham, Lincoln & Beate. GALLO, J. Commonwealth Edison Co. B3/07/19. ROSENTHAL, A. S. & KDHL, C. N. , GOTCHY, R. L. Atomic Safety and Licensing Appeal Panel. 1p. 19666:356 24% Fiche: 50-454, 83/07/19, B307210211.
- --8307210217 Response supporting NRC B30708 motion for directed certification of issue of disclosure of detailed info re allegations subj to angoing insps & investigations. Notices of appearance & Certificate of Svc encl. GALLO.J., FITZ01880NS.R., STYLES.L.C. Commonwealth Edison Co. 83/07/19. Atomic Bafety and Licensing Appeal Panel. 39pp. 19666:357. 24X Fiche: 50-454.83/07/19.8307210211.
- 8307220354 Motion for leave to file amicus curiae brief re NRC refusal to provide info re allegations which are subj of ongoing investigations. Govt Accountability Project has substantial experience w/Region III.

  DEVING.T., GARDE.B. Government Accountability Project. 83/07/19. Atomic Safety and Licensing Appeal Panel. 5pp. 19675:301. 24x Fiche: 50-454.83/07/19.\$307220354.
- --8307220355 Amicus curiae brief re NRC refusal to provide info re allegations which are subj of ongoing investigations. NRC has no valid legal excuse to withhold evidence in dispute NRC violated legal duty to disclose info. W/Certificate of Svc. DEVINE. T. GARDE. B. P. Government Accountability Froject. 83/07/19. Atomic Safety and Licensing Appeal Panel. 22pp. 19675: 306. 24x Fiche: 50-454.83/07/19.8307220354.
- 830.7220348 Advises of error on Page 26 of applicant 830719 response to NRC motion for directed certification STYLES.L.C. Isham, Lincoln & Beale. BTYLES.L.C. Commonwealth Edison Co. B3/07/20, RDSENTHAL.A.S., KOHL.C.N., GOTCHY.R.L. Atomic Bafety and Licensing Appeal Panel. 1p. 19679:300. 24X Fiche: 50-434.83/07/20, B307220348.
- B307220361 Memorandum & order reminding counsel & parties of confidentiality of certain info in J Hughes deposition. SMITH:I.W. Atomic Safety and Licensing Board Panel. 83/07/20. 1p. 19679:233. 24X Fiche:50-454.83/07/20.8307220361

- 8307260258 Revised findings of fact & opinion on Rockford League of Momen Voters Contention 22 & DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 9(c). Certificate of Svc encl.

  \* League of Women Voters of Rockford, IL. \* DeKalb Area Alliance for Responsible Energy. \* Sinnissippi Alliance for the Environment (SAFE). 83/07/20, 47pp. 19727:040. 24X Fiche: 50-454, 83/07/20, 8307260258.
- B30726028B Response opposing NRC B30711 application for stay of effectiveness of B30621 & 0701 orders re withholding evidence. Requisite showing to support stay not established. Certificate of Svc encl.
  WHICHER.J.M. Dekalb Area Alliance for Responsible Energy.
  WHICHER.J.M. Micher. J.M. B3/07/21. Atomic Safety and Licensing Board Panel. 5pp. 19726:208. 24x Fiche: 50-454.83/07/21.830726028B.
- 8307260309 Forwards revised findings of fact & opinion on Rockford League of Homen Voters Contention 22 & DeKalb Area Alliance for Respunsible Energy/Sinnissippi Alliance for Environ Contention 9 re steam generators. W/o encis.

  JOMNSON.B. League of Women Voters of Rockford, IL. 83/07/21.

  SMITH.I.W., COLE.R.F., CALLIHAN.A.D. Atomic Safety and Licensing Board Panel. 1p. 19726.292. 24X Fiche: 50-454, 83/07/21, 8307260309.
- B307240425 Response supporting intervenor motion to suppl QA/QC record on preoperational testing.per B30721 teleon. GA/QC concerns arise out of entire scope of Region III insps & cannot be separated from preoperational testing.

  MHICHER.J.M. League of Homen Voters of Rockford, IL. WHICHER,J.M. DeKalb Area Alliance for Responsible Energy. WHICHER,J.M. Whicher, J.M. B3/07/21. Atomic Safety and Licensing Board Panel. 6pp. 19734:033. 24X Fiche: 50-454, 83/07/21. 8307260425.
- B307250365 Response opposing NRC application for stay of ASLB B30701 memorandum & order-memorializing B30629 & 30 conference call rulings.NRC showing of irreparable harm insufficient. Certificate of Svc encl. GALLO, J. FITTGIBBONS, R. Commonwealth Edison Co. GALLO, J. Isham. Lincoln & Beale. B3/07/22. Atomic Safety and Licensing Board Panel. 9pp. 19703:355. 24X Fiche: 50-454, B3/07/22, B307250365.
- 8307260042 Response to Govt Accountability Project 830719 motion to file amicus curiae brief. NRC does not object despite doubts about britsf value to decisional process. NRC categorically rejects validity of Project reasoning. W/Certificate of 8vc. GOLDBERG. S. C. Hearing Branch 4. 83/07/22. Atomic 8afety and Licensing Appeal Panel. 6pp. 19727: 345. 24% Fiche: 50-454,83/07/22,8307260042.
- 8307260310 Response opposing Govt Accountability Project motion for leave to file anizus curiae brief re NRC 830708 certification motion. Project interest ill-founded & arguments immaterial. Certificate of 5vc encl. OALLO.J. Commonwealth Edison Co. GALLO.J. Isham, Lincoln & Beale, 83/07/22. Atomic 8afety and Licensing Appeal Panel. 4pp. 19726: 077. 24X Fiche: 50-494, 83/07/22, 8307260310.
- 8307280232 Memorandum & order denying NRC 830711 motion for stay of ASLB 830701 memorandum & order re evidentiary hearing on Region III & Ofc of Investigation investigations of Hatfield Electric GA program.
  SMITH, I. W. Atomic Safety and Licensing Board Panel. 83/07/26. Office of the Executive Legal Director. 13pp. 19794:148. 24x Fiche: 50-454.83/07/26.8307280232.
- 8307290102 Forwards reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re steam generator tube integrity.

  GOLDFEIN,M.R. Isham, Lincoln & Beale. GOLDFEIN,M.R. Commonwealth Edison Co. B3/07/26. SMITH.I.W., COLE, R.F., CALLIHAN,A.D. Atomic Safety and Licensing Board Panel. ip. 19820:336. 24X Fiche: 50-454,83/07/26,8307290102.
- --8307290105 Reply opposing Rockford League of Women Vaters proposed findings of fact & conclusions of law re steam generator tube integrity. Certificate of Svc encl. GALLO.J. GOLDFEIN.M.R. Commonwealth Edison Co. GALLO.J. Isham. Lincoln & Beale. 83/07/26. 20pp. 19820:337. 24X Fiche: 50-454, 83/07/26, 8307270102.
- B307280154 Nemorandum & Order ALAB-735 denying & dismissing NRC motion for directed certification & appeal, respectively re ASLB B30701 memorandum & order reopening record on OA issues. NRC may file motion for reconsideration.

  SHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 83/07/27. Office of the Executive Legal Director. 12pp. 19792:047. 24x Fiche: 50-454, 83/07/27, 8307280154.

- Q. Inspection reports, IE Bulletins & correspondence
- 9307080009 Forwards IE Insp Repts 50-454/83-20 & 50-455/83-17 on 830503-04 & 09-12 & notice of violation. SPESSARD, R.L. Region 3, Office of Director. 83/06/22. REED, C. Commonwealth Edison Co. 2pp. 19351:224. 24X Fiche: 50-454, 83/06/22, 8307080009.
- --8307080012 Notice of violation from insp on 830803-04 & 09-12. SPESSARD.R.L. Region 3. Office of Director. 83/06/22. 4pp. 19351:226. 24X Fiche: 30-454.83/06/22.8307080009.
- --8307080014 IE Insp Repts 50-454/83-20 & 50-455/83-17 on 830503-04 & 09-12 Noncompliance noted: inadequate GC for whip restraint installation, inadequate audit of site whip restraint activities & lack of adequate prevention for snubber damage. YIN, I. T., DANIELSON, D. H. Region 3, Office of Director. 83/06/22. 11pp. 19351:230. 24X Fiche: 50-454,83/06/22,8307080007.
- 8307180003 Forwards IE Insp Repts 50-454/83-26 & 50-455/83-19 on 830607-10. No noncompliance noted. KNDP.R.C. Region 3, Office of Director. 83/06/28, REED,C. Commonwealth Edison Co. 2pp. 20078:271. 24X Fiche: 50-454,83/06/28,8307180003.
- --8307180007 IE Insp Repts 50-454/83-26 & 50-455/83-19 on 830607-10. No noncompliance noted. Major areas inspected: status of reinsp program & status of program for key contractors per IE Insp Repts 50-454/82-05 & 50-455/82-05. HAYES, D. H., HINDS, J. M., KNDP.R. C. Region 3, Office of Director. 83/06/27, 16pp. 20078: 273. 24X Fiche: 50-454,83/06/28,8307180003.
- 8307180016 Forwards IE Insp Repts 50-454/83-28 & 50-455/83-21 on 830621-23 & 27. No noncompliance noted. PAPERIELLO, C. J. Region 3, Office of Director. B3/07/07. REED, C. Commonwealth Edison Co. 2pp. 19560: 284. 24X Fiche: 50-454, 83/07/07, 8307180016.
- ---B307180018 IE Insp Repts 50-454/83-28 & 50-455/83-21 on 830621-23 & 29. No noncompliance noted Major areas inspected environ protection review of chemistry & radiochemistry program & procedures & review of actions on previous open items.

  OESTMANN.M.J. SCHUMACHER.M.C. Region 3, Office of Director. 83/07/06. 6pp. 19560:286. 24X Fiche: 50-454,83/07/07,8307180016.
- B307220546 Forwards IE Insp Repts 50-454/83-27 % 50-455/83-20 on B30615 No noncompliance noted. PAPERIELLO, C. J. Region 3, Office of Director. B3/07/08, REED, C. Commonwealth Edison Co. 2pp. 19686:041. 24X Fiche: 50-454, 83/07/08, B307220546.
- --B307220553 IE Insp Repts 50-454/83-27 & 50-455/83-20 on B30615.No noncompliance noted. Major areas inspected; emergency medical drill.
  GLOERBON, M., BMITH, M., AXELSON, W. L. Region 3, Office of Director, B3/07/07. 8pp. 19686:043. 24X Fiche: 50-454,83/07/08,8307220546.
- 8306270401 IE Info Notice 83-46, "Common Hode Valve Failures Degrade Surry Recirculation Byray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:133. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307190145 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-454/83-07 & 50-455/83-07.

  NORELIUS, C. E. Division of Project & Resident Programs. B3/07/13.

  REED, C. Commonwealth Edison Co. 2pp. 19636:177. 24X

  Fiche: 50-454, 83/07/13, 8307190145.
- --8307190147 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-454/83-09 % 30-455/83-07. Corrective actions: Level III GA manager appointed on 830324 % all contractors requested to notify util of changes in GC inspectors. FARRAR, D. L. Commonwealth Edison Co. 83/05/06. KEPPLER, J. G. Region 3, Office of Director. 10pp. 19636: 179. 24X Fiche: 50-454, 83/07/13, 8307190145.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.

- 8306270415 Board Notification 83-097 forwards draft SALP rept for Jan-Dec 1982 & util B30712 response. NGVAK.T.M. Assistant Director for Licensing. 83/07/22. Atom 8afety and Licensing Board Panel. 3pp. 19767:043. 24X Fiche: 50-454.83/07/22,8306270415.
- --8307270493 Forwards preliminary SALP rept for Jan-Dec 1982, for review prior to 830613 meeting to discuss observations & findings.
  HIND.J.A. Division of Radiological & Materials Safety Programs.
  83706/09. REED.C. Commonwealth Edison Co. 32pp. 19767:046. 24X
  Fiche: 50-454,83707/22,8306270415.
- --B307270454 Forwards comments on SALP rept based on discussion at 830613 public meeting Evaluation distressing, since NRC prepared testimony in licensing proceedings stating that util had implemented acceptable QA program.

  STIEDE,W.L. Commonwealth Edison Co. 83/07/12. KEPPLER, J. Q. Region 3, Office of Director. 28pp. 19767:078. 24X Fiche: 50-454, 83/07/22, 8305270415
- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util.per 830715 discussion.

  NDRELIUB, C. E. Division of Project & Resident Programs. 83/07/22. REED, C. Commonwealth Edison Co. 2pp. 19791:169. 24X Fiche: 30-000:83/07/22.8307280084.
- --8307280102 Confirms request for NRC & util senior mgt meeting on 830726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.
  REED, C. Commonuealth Edison Co. 83/07/11. DAVIS, B.A. Region 3, Office of Director. ip. 19791:171. 24% Fiche: 50-000,83/07/22.
- S. Reportable occurrences, LERs & related correspondence
- 8307200201 Forwards util 830603 deficiency rept re Westinghouse Model DS-416 reactor trip breaker, for info. New & redesigned undervoltage attachments in all DB-416 switchgear will be installed & tested before fuel load. Related correspondence. 8LODM, J. G. Isham, Lincoln & Beale. 83/07/12. SMITH, I. W. Atomic Safety and Licensing Board Panel. Spp. 17651:159. 24X Fiche: 50-454, 83/07/12, 8307200201.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only. LITKA: T. J. Elcen Metal Products Co. 83/07/15, KEPPLER, J. G. Region 3, Office of Director. 26pp. 19686: 086. 24X Fiche: 50-000,83/07/15,8307220446.
- 8307250432 Interim deficiency rept re excess carbon content in spring hangers supplied by Elcen Metal Products. Initially reported on 830617. Approx 40 hangers at each site being evaluated. Final rept expected within 90 days.

  TRAMM.T.R. Commonwealth Edison Co. 83/07/18. KEPPLER, J. G. Region 9, Office of Director. 2pp. 19702: 168. 24X Fiche: 50-000, 83/07/18. 8307250432.
- DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- B306060070 Generic Ltr B3-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENNUT.D. G. Division of Licensing. B3/06/03. Yankee Ato Electric Co. 10pp. 19563:116. 24X Fiche: 50-000. B3/06/03. B306060070.
  - Division of Licensing. 83/06/03. Yankee Atomic 10pp. 19563:116. 24X Fiche:50-000.83/06/03.
- B306230264 Forwards advance revised pages to FBAR necessary to reclassify spent fuel pool liner from safety Category I structure to Category II. Info will be incorporated into next amend to FBAR.

  TRAMM.T.R. Commonwealth Edison Co. B3/06/20. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 7pp. 18945:076. 24X Fiche: 50-000, 83/06/20, 8306230264.
- 8307200231 Notification of 830707 meeting w/technical review committee in Bethesda, MD to discuss review of D4, D5 & E steam generator mods.

  HOPKINS J. 8, Licensing Branch 4, 83/07/01, ADENSAM, E. Q. Licensing Branch 4, 2pp, 19670: 254, 24X Fiche: 50~000, 83/07/01, 8307200231.

- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT, D. G. Division of Licensing B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensess & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS Svc 1)st encl. EISENHUT.D. G. Division of Licensing. 83/07/06. Consolid Edison Ca. of New Yark. Inc. 16pp. 19669-254. 24X Fiche: 30-000.83/07/06.8307060329. Consolidated
- 8307120281 Requests add1 exemption from Type C testing requirements for containment sump isolation valves MOVSIBBIIA & B per 630419 ltr concerning containment leak rate testing Justification provided. LENTINE,F. 9. Commonwealth Edison Co. 83/07/07 of Nuclear Reactor Regulation. Director. 2pp. Fiche: 50-000.83/07/07.8307120281. 83/07/07. DENTON:1 DENTON, H. R. Office
- 8307130309 Forwards responses to SGRT % pump & valve operability review team audits & responses to add1 items discussed at 830513 meeting w/NRC in Bethesda.MD.
  SWARTZ.E.D. Commonwealth Edison Co. 83/07/07. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 19466:127. 24% Fichs: 50-000,83/07/07,8307130309.
- --8307130322 Rev O to "Environ Qualification of Mechanical Equipment for Comm Ed Byron Units 1 & 2.Braidwood Units 1 & 2 Component Pacific Safety Injection Pump Model 3-Inch 10 Stage JHF." Stage JHF. "
  ZEOAR.M.J. WALKER.L.I. Commonwealth Edison Co. EG&T-EGT-204 ROD.
  83/06/20. 84pp. 19469:185. 24X Fiche: 50-000.83/07/07,
  8307130309.
- --8307130333 "Environ Qualification for Class IE Lead Acid Storage Batteries." HOPEWELL.R.W. DESAI.R.H. Gould, Inc. 83/07/07. 188pp. 19472:137. 24X Fichs:50-000.83/07/07.8307130309.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENNUT.D.G. Division of Licensing. 83707708. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24x Fiche: 50-000.83707708.8307080169.
- 8307260516 Forwards memo describing actions taken to resolve JH Conran differing prof opinion re sys interaction (Unresolved Safety Issue A-17) & safety classification.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
  83/07/11. CONRAN,J.H. Reliability & Risk Assessment Branch. 2pp. 19782:241. 24X Fiche: 50-000, 83/07/11. 8307260516.
- --8306080369 forwards comments on mgt views & positions on sysinteraction per differing prof upinion, in response to 8304(8 & 0505 memos. Excepts from Suffolk County 830509 submittal & proposed request for addition for Byron/Braidwood encl. CONRAN. J. H. Reliability & Risk Assessment Branch. 83/05/25. RUSSELL. M. T. Systematic Evaluation Program Branch. 74pp. 19783:033. 24X Fiche: 50-000,83/07/11,8307260516.
- 8307210188 Forwards response to FSAR Questions 330.3 ½ 330.4. Info discusses location of pipelines & frequency of shipments of explosive matl to & from Juliet Army Ammunition Plant on IL Central Guif Railroad.
  SWARTZ.E.D. Commonwealth Edison Co. B3/07/15. DENTON.H.R. Of of Nuclear Reactor Regulation, Director. 18pp. 17466:016. 24X Fiche: 30-434,63/07/15,8307210188. Office
- 8307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4.D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
  BUTTERFIELD, L. Steam Generator Owners Group, 83/07/18.
  EISENHUY, D. G. Division of Licensing. 3pp. 17464:114. 24X
  Fiche: 30-000.B3/07/18.8307210300.
- B307290124 Summary of B30707 meeting w/technical review committee in Bethesda,MD re Model D4/D5/E steam generator mod Viewgraphs encl. 9.J.B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 19738:132. 24% Fiche:50-000.83/07/18.8307250124. HOPKINS, J. B.
- B307290047 Advises that energy absorbing matl used in pipe whip restraint design not properly qualified for design applications used at facilities. Recommended position to resolve issue encl.
  YOUNOBLOOD, B. J. Licensing Branch 1. 83/07/21. FARRAR, D. L. Commenue atth Edison Co. 1p. 19857:026. 24X Fiche: 30-000, 83/07/21, 8307290047.

- --B307290072 Trip rept of B30511-12 visit to Region III ofc.Byron site & Sargent & Lundy Chicago. IL ofc re design, installation & testing of pipe restraints using energy absorbing matl. TERAO. D. Mechanical Engineering Branch. 83/05/26. BOSNAK, R. J. Mechanical Engineering Branch. 4pp. 19857:033. 24X fiche: 50-000, B3/07/21, B307290047.
- C. Utility Environmental Report (ER), amends & correspondence
- B307200121 Forwards Amend 2 to environ rept OL stage, including site & environ interfaces, environ effects of station operation, summary of cost-benefit analysis & efficent & environ measurements & monitoring programs.

  SWARTZ.E.D. Commonwealth Edison Co. B3/07/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19645:001. 24X

  Fiche: 50-456, 83/07/15, 8307200121.
- ~-B307200125 Amend 2 to environ rept OL stage. \* Commonwealth Edison Co. B3/07/31. 200pp. 19645:003. 24X Fiche: 50-456, 83/07/15, B307200121.
- B307270042 Forwards request for add1 info based on B30503-05 environ site visit & review of environ rept OL stage. Response requested by B30831.

  YDUNOBLODD, B. J. Licensing Branch 1. B3/07/22. FARRAR, D. L. Commonwealth Edison Co. App. 19857: 020. 24X Fiche: 50-455, 83/07/22. B307270042.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B307040446 Forwards input for Section 16.0 of SER re Tech Specs prepared for facilities.per B30411 request. MIRAGLIA.F.U. Assistant Director for Safety Assessment. B3/06/24. NDVAK.T.M. Assistant Director for Licensing. 2pp. 19300:158. 243 Fiche: 50-436, 83/06/24. B307060446.
- F. Security, medical, emergency & fire protection plans
- 8307260018 Submits supplemental response to NUREG-0737, Suppl I (Generic Lee B2-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display says verification to be performed w/verification program. SHARTZ, E. D. Commonwealth Edison Co. 83/07/20. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 2pp. 19727:177. 24X Fiche: 50-000, 83/07/20, 8307260018.
- G. Inspection reports, IE Bulletins & correspondence
- B307050501 Ack receipt of B30A04 ltr in response to notice of violation & proposed imposition of civil penalties. No sufficient basis exists for mitigation of App Item III re steam generator bolting problems.

  DEYQUNG.R.C. Director's Office. Office of Inspection and Enforcement. 83/06/27. 0'CQNNOR.J.J. Commonwealth Edison Co. 1p. 19262:153. 24X Fiche: 50-454, 83/06/27, 8307030501.
- --8307050505 Order imposing civil monetary penalties in amount of \$100,000 for failure to take corrective actions after experiencing steam generator bolting problems. DEYQUNG:R.C. Director's Office, Office of Inspection and Enforcement. 83/06/27. Commonwealth Edison Co. 10pp. 19262: 154. 24X Fiche: 50-456, 83/06/27, 8307050901.
- B307130194 Forwards B30627 order imposing civil monetary penalties for FR publication. H/o encl.

  AXELRAD, J. A. Director's Office, Office of Inspection and Enforcement. B3/06/29. Docketing & Services Branch. 1p. 19465: 350. 24X Fiche: 50-456. B3/06/29. B307130194.
- 8306270401 lE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 17563:153. 24X Fiche: 30-000, 83/07/12, 8306270404.
- B306270406 IE Info Notice B3-48, "Caseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Bvc list encl.
  TAYLOR.J.M. Division of GA. Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 30-000, 83/07/14, 8306270406.

- 8307280084 Confirms 830726 mgt meeting in Chicago, IL to discuss licensee regulatory performance & communication problems between NRC & util, per 830715 discussion.

  NORELIUS, C.E. Division of Project & Resident Programs. 83/07/22. REED, C. Commonwealth Edison Co. 2pp. 19791:169. 24X Fiche: 30-000, 83/07/22, 8307280084.
- --B307280102 Confirms request for NRC & util senior mgt meeting on B30726 in Chicago, IL to discuss licensee regulatory performance & relationship w/NRC.

  REED. C. Commonwealth Edison Co. B3/07/11. DAVIB.B. A. Region 3, Office of Director. 1p. 19791:171. 24X Fiche: 50-000, B3/07/22, B3072800B4.
- S. Reportable occurrences, LERs & related correspondence
- 8306280432 EN-B3-005A: on 830128, notice of violation & proposed imposition of civil penalty in amount of \$100,000 issued. Violation based on failure to implement adequate GA program for safety-related equipment. KLINGLER.G., AXELRAD.J. Director's Office, Office of Inspection and Enforcement. 83/06/27. Ip. 19020:327. 24X Fiche: 50-456,83/06/27,8306280432.
- B307110056 Interim Deficiency Rept B2-10 re inadequate QA provisions in structural steel installation inspirecords. Initially reported on B21119, Reinspicontinuing, Final rept will be issued by B40201.

  SHARTZ.E.D. Commonwealth Edison Ca. B3/07/01. KEPPLER, J. Q. Region 3, Office of Director. 2pp. 19375; 241. 24X Fiche: 50-456, 83/07/01, 830/110056.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.

  LITKA, T. J. Elcen Metal Products Co. 83/07/15. KEPPLER, J. O. Region 3, Office of Director. 26pp. 19686:086. 24X Fiche: 50-000, 83/07/15, 8307220446.
- 8307250432 Interim deficiency rept re excess carbon content in spring hangers supplied by Elcen Metal Products. Initially reported on 83047. Approx 40 hangers at each site being evaluated. Final rept expected within 90 days.

  TRAMM.T.R. Commonwealth Edison Co. 83/07/18. KEPPLER, J. Q. Region 3. Office of Director. 2pp. 19702: 168. 24X Fiche: 50-000, 83/07/18, 8307250432.
- DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- B306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT, D. G. Division of Licensing. B3/06/03. Yankee Atomi Electric Co. 10pp. 19563:116. 24% Fiche: 50-000, B3/06/03, B306060070.
- 8306230264 Forwards advance revised pages to FSAR necessary to reclassify spent fuel pool liner from safety Category I structure to Category II. Info will be incorporated into next amend to FSAR.

  TRAMM.T.R. Commonwealth Edison Co. 83/06/20. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 18945:076. 24X Fiche: 50-000.83/06/20.8306230264.
- 8307200231 Notification of 830707 meeting w/technical review committee in Bethesda, MD to discuss review of D4, D5 & E steam generator mods.

  HOPKINS, J. B. Licensing Branch 4, B3/07/01, ADENSAM, E. Q. Licensing Branch 4, 2pp. 19670: 254, 24X Fiche: 50-000, 83/07/01, 8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISEMHUT.D.O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, 83/07/05, 9306270397.
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list enci. EISENHUT, D. Ø. Division of Licenseing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254, 24X Fiche: 50-000, 83/07/06, 8307060329.

- 3307120281 Requests add1 exemption from Type C testing requirements for containment sump isolation valves MDVS18811A & B per 830419

  1tr concerning containment leak rate testing Justification provided.

  LENTINE, F. G. Commonwealth Edison Co. 83/07/07. DENTON, H.R. Office
  - CENTINE, F. G. Commonwealth Edison Co. 83/07/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19424:114. 24X Ficha: 50-000,83/07/07,8307120281.
- IG071G-0309 Forwards responses to SQRT & pump & valve operability review team audits & responses to add1 items discussed at 830513 meating w/NRC in Bethesda: MD.
  SWART7:E.D. Commonwealth Edison Co. 83/07/07. DENION,H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 19466:127. 24X Fiche: 50-000-83/07/07.8307130309.
- -8307130322 Rev O to "Environ Gualification of Mechanical Equipment for Comm Ed Byron Units 1 & 2. Braidwood Units 1 & 2 Component Pacific Safety Injection Pump Model 3-Inch 10 Stage JHF." ZEGAR.M.J. Commonwealth Edison Co. EG&T-EOT-204 ROD. 83/06/20. 84pp. 19469;185. 24X Fiche: 50-000,83/07/07,8307130309.
- -8307130333 "Environ Qualification for Class IE Lead Acid Storage Batteries."

  HGPEWELL.R.W Gould, Inc. 83/07/07. 188pp. 19472:137. 24X

  Fich: 50-000,83/07/07,8307130309.
- 307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for OL & holders of CPs re required actions based on gwnsric implications of Salem ATMS events. Svc list encl. EISENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 3Spp. 19669: 269. 24X Fiche: 30-000, 83/07/08, 8307080169.
- 307240516 Forwards memo describing actions taken to resolve JH Conran differing prof opinion re sys interaction (Unresolved Safety Issue A-17) & safety classification. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 89/07/11. CONRAN, J.H. Reliability & Risk Assessment Branch. 2pp. 19782:241. 24X Fiche: 50-000, 83/07/11, 8307260516.
- -8306080369 Forwards comments on mgt views & positions on sys interaction per differing prof opinion, in response to 830418 & 0505 memos. Excerpts from Suffolk County 830509 submittel & proposed request for addlinfo re Byron/Braidwood enci. CONRAN.J.H. Reliability & Risk Assessment Branch. 83/05/25. RUSSELL, W.T. Systematic Evaluation Program Branch. 74pp. 19783:033. 24X Fiche: 50-000, 83/07/11, 8307260516.
- 307210188 Forwards response to FSAR Questions 330.3 & 330.4, Info discusses location of pipelines & frequency of shipments of maplestive math to & from Jollet Army Ammunition Plant on IL Central Gulf Railroad.

  BMARTZJE.D. Commonwealth Edison Co. B3/07/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 18pp. 19666:016. 24X Fiche: 50-456, 83/07/15, 8307210188.
- 307210300 Forwards proprietary "Independent Evaluation of Proposed Mode to Westinghouse D4.D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
  BUTTERFIELD.L. Steam Generator Owners Group. 83/07/18.
  EISENHUT.D. 9. Division of Licensing. 3pp. 17664:114. 24X
  Fiche: 50-000, 83/07/18, 8307210300.
- 307250124 Summary of 830707 meeting w/technical review committee in Bethesda.MD re Model D4/D5/E steam generator mod.Viewgraphs
- HOPKINS J. B. 6.J.B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 19738:132. 24X Fiche:50-000,83/07/18,8307250124.
- IO7290047 Advises that energy absorbing mat1 used in pipe whip restraint design not properly qualified for design applications used at facilities. Recommended position to resolve issue encl.
  YOUNGBLOOD, B. J. Licensing Branch 1. 83/07/21. FARRAR, D. L. Commonwealth Edison Co. 1p. 19857:026. 24X Fiche: 50-000, 83/07/21, 8307290047.
- #307290072 Trip rept of 830511-12 visit to Region III ofc, Byron site & Sargent & Lundy Chicago, IL ofc re design, installation & testing of pipe restraints using energy absorbing mati.
  TERAG, D. Mechanical Engineering Branch. 83/05/26. BOBNAK, R. J. Mechanical Engineering Branch. 4pp. 19857:033. 24X
  Fiche: 50-000, 83/07/21, 8307290047.

- C. Utility Environmental Report (ER), amends & correspondence
- B307200121 Forwards Amend 2 to environ rept CL stage, including site & environ interfaces, environ effects of station operation, summary of cost-benefit analysis & effluent & environ measurements & monitoring programs.
  SWARTZ.E.D. Commonwealth Edison Co. B3/07/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19645:001. 24X Fiche: 30-456.83/07/15.8307200121.
- --8307200125 Amend 2 to environ rept OL stage.

  \* Commanwealth Edison Co. 83/07/31. 200pp. 19645:003. 24X
  Fiche: 50-456,83/07/15,8307200121.
- 8307290042 Forwards request for addi info based on 830903-05 environ site visit & review of environ rept CL stage. Response requested by 830831.
  YOUN0BLCODD B. J. Licensing Branch 1. 83/07/22. FARRAR, D. L. Commonwealth Edison Co. App. 19897: 020. 24X Fithe: 50-456.83/07/22.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307060446 Forwards input for Section 16.0 of SER re Tech Specs prepared for facilities.per 830411 request.
  MIRAGLIA.F. J. Assistant Director for Safety Assessment. 83/06/24.
  NDVAK.T.M. Assistant Director for Licensing. 2pp. 19300:158. 24X
  Fiche: 50-456.83/06/24,8307060446.
- F. Security, medical, emergency & fire protection plans
- 8307240018 Submits supplemental response to NUREG-0737, Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display sys verification to be performed w/verification program. SWARTZ.E.D. Commonwealth Edison Co. 83/07/20. DETTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19727:177. 24X Fiche: 30-000.83/07/20.8307260018.
- G. Inspection reports. IE Bulletins & correspondence
- 8307030501 Atk receipt of 830404 ltr in response to notice of violation & proposed imposition of civil penalties. No sufficient basis exists for mitigation of App Item III re steam generator bolting problems.

  DEYQUNG.R.C. Director's Office, Office of Inspection and Enforcement. 83706/27. 0'CONNOR.J.J. Commonwealth Edison Co. 1p. 19262: 153. 24X Fiche: 50-456, 83/06/27, 8307050501.
- --8307080505 Order imposing civil monetary penalties in amount of \$100.000 for failure to take corrective actions after experiencing steam generator bolking problems.

  DEYOUNG, R. C. Director's Office. Office of Inspection and Enforcement. 83/06/27. Commonwealth Edison Co. 10pp. 17262:154. 24X Fiche: 50-456,83/06/27,8307050501.
- B307130194 Forwards 830627 order imposing civil monetary penalties for FR publication. W/o encl.
  AXELRAD.J.A. Director's Office, Office of Inspection and Enforcement. B3706/29, Docketing & Services Branch. 1p. 19465: 350. 24X Fiche: 50-456, 83/06/29, 8307130194.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000.83/07/12,8306270404.
- 8304270404 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list enci.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Cansolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8304270406.
- 8307280084 Confirms 830726 mgt meeting in Chicago II. to discuss licensee regulatory performance & communication problems between NRC & utiliper 830715 discussion.
  NORELIUS, C. E. Division of Project & Resident Programs. 83/07/22.
  REED, C. Commonwealth Edison Co. 2pp. 19791;169. 24X
  Fiche: 50-000, 83/07/22, 8307280084.

- --0307280102 Confirms request for NRC & util senior mgt meeting on 030726 in Chicago IL to discuss licensee regulatory performance & relationship w/NRC.

  REED.C. Commonwealth Edison Co. 03/07/11. DAVIS.B.A. Region 3. Office of Director. 1p. 19791:171. 24X Fiche: 50-000.83/07/22. 0307280084.
- S. Reportable occurrences, LERs & related correspondence
- 8306280432 EN-63-005A: on 83012B, notice of violation & proposed imposition of civil penalty in amount of \$100,000 issued. Violation based on failure to implement adequate GA program for safety-related equipment. KLINGLER,G., AXELRAD,J. Director's Office, Office of Inspection and Enforcement. 83/06/27. 1p. 19020.327. 24X Fiche: 50-456,83/06/27,8304280432.
- 8307110056 Interim Deficiency Rept 82-10 re inadequate OA provisions in structural steel installation insp records. Initially reported on 821119. Reinsp continuing. Final rept will be issued by 840201. SMARTZ.E.D. Commonwealth Edison Co. 83/07/01. KEPPLER, J. Q. Region 3. Office of Director. 2pp. 19375: 241. 24X Fiche: 50-456.83/07/01. 8307110056.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbuckle & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.
  LITKA, T. J. Elcen Metal Products Co. 83/07/15. KEPPLER, J. G. Region 3, Office of Director. 26pp. 19686:086. 24X Fiche: 80-000, 83/07/15, 8307220446.
- 8307230432 Interim deficiency rept re excess carbon content in spring hangers supplied by Elcen Metal Products. Initially reported on 830617. Approx 40 hangers at each site being evaluated. Final rept expected within 90 days.

  TRANM.T.R. Commonwealth Edison Co. 83/07/18. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19702:148. 24X Fiche: 50-000, 83/07/18. 8307250432.
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- B307260003 Forwards const QA program identifying changes to program since issuance of CP.W/o encl.
  BOOKER.J.E. Gulf States Utilities Co. 83/06/10. COLLINS, J. T. Region 4. Office of Director. 1p. 19727:186. 24X
  Fiche: 50-458.83/08/10.8307260003.
- 8307060431 Summary of Caseload Forecast Panel 830330-31 meeting & site visit w/util.56H & atty general in Parrish.LA re current status of const & observation of in-progress activities.

  MEINKAM.E.J. Licensing Branch 2. 83706/23. Licensing Branch 2. 68pp. 19300:085. 24X Fiche:50-458,83/06/23.8307060431.
- B307070050 Responds to NRC B30615 ltr re Endangered Species Act.
  Endangered red-cockaded woodpecker may occur in project
  area. Proposed areas should be inspected for presence of
  woodpacter. Requests notification of insp results.
  JGRDAN.D. B. Interior. Dept. of, Fish & Wildlife Service, 83/06/28.
  ADENSAM.E. Licensing Branch 4. 2pp. 19293:256. 24X
  Fichs: 50-458.83/06/28.8307070050.
- 8306270395 Generic Ltr 83-24 to all BWR applicants for DL & holders of OLs for Grand Oulf, LaSalle & Susquehanne re TMI Task Action Plan Item 1.0.1. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list encl. EISENHUT.D.G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, 83/06/29, 8306270395.
- 8307060017 Forwards set of transparent overlays used in imagery associated w/Questions 231.4 & .7 inadvertently omitted from 830422 submittal. Info responds to NRC 811231 & 820605 1trs & will be referenced in Future FSAR amend. BOCKER.J.E. Gulf States Utilities Co. 83/07/01. SCHWENCER.A. Licensing Branch 2. 19pp. 19249:012. 24X Fiche: 50-458.83/07/01, 8307060017.
- 8307140167 Summary of 830621 meeting w/util & S&W in Bethesda, MD re Georgiences Branch open items, specifically, dealing w/interprotations of seismic reflection profiles. List of attendees enci. PERCH, R. L. Licensing Branch 2. 83/07/01. Licensing Branch 2. 4pp. 19539: 358. 24X Fiche: 50-458, 83/07/01, 8307140167.

.

- 8305270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000:83/07/05:8306270397.
- 8307080169 Generic Ltr 83-28 to all licensers of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. SVc list encl. EISENHUT, D. 9. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669: 269. 24X Fiche: 30-000. B3/07/08.8307080169.
- 8307200383 Forwards request for add1 info re terrestrial resources, including map of site identifying prime farmland & farmland of statewide importance. Schedule for response requested. SCHMENCER, A. Licensing Branch 2. 83/07/08. CAHILL. W. J. Qulf States Utilities Co. 4pp. 19669: 347. 24X Fiche: 50-458, 83/07/08, 8307200383.
- 8307220142 Notification of 830720 & 21 meetings w/util & S&W in Cherry Hill, NJ to discuss Power Sys Branch items for facilities.

  WEINKAM,E.J. Licensing Branch 2. 83/07/14. SCHWENCER, A. Licensing Branch 2. 3pp. 19692:264. 24X Fiche: 50-458,83/07/14,8307220142.
- 8307220889 Advises of NRC position requiring redundant ammonia & chloride detectors in control room normal vantilation sysintakes. Response to position requested by 830901.

  8CHHENGER: A. Licensing Branch 2, 83/07/15. CAHILL. W. J. Guif States Utilities Co. 3pp. 19712:088. 24X Fiche: 50-458,83/07/15,830720589.
- B307250367 Submits summary status of issues being addressed by Licensing Review Oroup II,per B30502 request. Four issues require further action prior to NRC closeout. Post-accident sampling requires procedural upgrading.

  HOLTISCHER.D. L. Licensing Review Group II. 83/07/15. BYEFAND, J. J. Licensing Branch 1. 12pp. 19705: 203. 24X Fiche: 50-000, 83/07/15, 8307250367.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8306090249 Forwards draft 8ER (NUREO-0989), for review. Detailed agenda to resolve 8ER open items requested. Draft responses raquested prior to recommended util & NRC meeting.

  NGVAK.T.M. Assistant Director for Licensing. 83/06/01. CAHILL.H.J., Gulf States Utilities Co. 683pp. 18799:201. 24X

  Fiche: 50-458, 83/06/01, 8306090249.
- 8307190463 Notification of 830719 meeting w/util & 8&W Engineering Corp in Bethesda, MD to discuss structural engineering draft SER open items. WEINKAN, E. J. Licensing Branch 2. 83/07/11, SCHWENCER, A. Licensing Branch 2. 3pp. 19656:073. 24X Fiche: 50~458, 83/07/11, 8307190463.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307190265 Amend 9 to FSAR.W/830615 ltr. CAHILL.W.J. Quif States Utilities Co. 83/07/31. EISENHUT, D. Q. Division of Licensing. 317pp. 19644:001. 24X Fiche: 50-458, 83/07/31,8307190265.
- P. Operating license stage documents & correspondence
- 8307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS, Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669; 254. 24X Fiche: 50-000, 83/07/06, 8307060329.
- G. Inspection reports, IE Bulletins & correspondence
- B307120486 Forwards IE Insp Rept 50~458/83-03 on 830228-0304. No noncompliance noted.

  MADBEN, G. L. Region 4. Office of Director. B3/05/16. CAHILL, W. Quif Blates Utilities Co. 2pp. 19424:210. 24X

  Fiche: 50-458/83/05/16
- --8307120505 IE Insp Rept 50-458/83-03 on 830228-0304. No noncompliance noted Major areas inspected organization & administration, audits training, procedures & preoperational & planned operational nonradiological & radiological programs.
  BAER, R. E., MURRAY, B., CROSSMAN, W. A. Region 5, Office of Director. 83/05/10. 21pp. 19424: 212. 24X Fiche: 50-458, 83/05/16, 8307120486.

- 8307150334 Forwards IE Imsp Rept 50-458/83-11 on 830501-0602. No noncompliance noted.
  MADSEN, O. L. Region 4. Office of Director. 83/06/24. CAHILL, W. J. 0vif States Utilities Co. 2pp. 19538:261. 24X
  Fiche: 50-458:83/06/24
- --8307150341 IE Insp Rept 50-458/83-11 on 830501-0602. No noncompliance noted Major areas inspected: followup of licensee identified const deficiencies per 10CFR50. 55(e): IE builtetins, safety-related pipe installation & welding & RCPB pipe welding. BROWN, R. L., CROSSMAN, M. A. Region 4. Office of Director. B3/06/20. 11pp. 19538:263, 24X Fiche: 50-458, 83/06/24, 8307150334.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19543:293. 24X Fiche: 50~000, 83/07/11. 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York: Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12. 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of GA. Safaguards & Inspection Programs (Post 830103). 83/07/14. Consulidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000:83/07/14:8306270406.
- 8. Reportable occurrences, LERs & related correspondence
- 8307030127 Supplemental interim Deficiency Rept DR-30 re Interpretation of radiographs performed by BF Shaw Co. Welds indicated as defective by rejectable radiographs evaluated by AE. Next rept expected by 830727. BOOKER.J.E. Gulf States Utilities Co. 83/06/24, COLLINB.J.T. Region 4. Office of Director. ip. 19220:211. 24X Fiche: 50-458,83/06/24,8307050127.
- 8307050144 Interim Deficiency Rept DR-98 re potential failure of 8BM control switches mfg by 0E between Aug & Oct 1982. Initially reported on 830217, Addl info awaited from GE. Interim or final rept will be submitted by 830816.

  800KER.J. E. 901f States Utilities Co. 83/06/24. COLLINS, J. T. Region 4. Office of Director. 1p. 19220:046. 24X Fiche: 50-458,83/06/24,8307050144.
- 8307050208 Interim Deficiency Rept DR-97 re clearance between armature tail piece & molded posts of HMA auxiliary relays mfg by QE in 1974. Initially reported on 830217. AE awaiting adding from QE. Next rept will be provided by 830316.
  800KER.J.E. Gulf States Utilities Co. 83/06/24. CDLLING.J.T. Region 4. Office of Director. 1p. 19199:278. 24X
  Fiche: 50-458.83/06/24.8307050208.
- B307050R3B Final Deficiency Rept DR-104 re overturning of Transilift crans while lifting reactor shield bldg dome. Initially reported on B30323. Damaged concrete framing assembly replaced & dome will be erected in place.

  BOOKER, J. E. Gulf States Utilities Co. B3/06/24. COLLINS, J. T. Region 4. Office of Director. 2pp. 1919B: S49. 24X

  Fiche: 50-458.83/06/24, B307050238.
- 8307130334 Forwards IE Insp Rept 50-458/83-11 on 830501-0602. No noncompliance noted.
  MADBEN.G.L. Region 4. Office of Director. 83/06/24. CAHILL.W.J. 001f States Utilities Co. 2pp. 19538: 261. 24X
  Fiche: 50-458, 83/06/24, 8307150334.
- --8307150341 IE Insp Rept 50-458/83-11 on 830501-0602. No noncompliance noted. Major areas inspected: followup of licensee identified const deficiencies per 10CFR50. 55(e), IE bulletins, safety-related pipe installation & welding & RCPH pipe welding. BROWN, R. L., CROSSMAN, M. A. Region 4, Office of Director. 83/06/20. 11pp. 19538:263. 24% Fiche: 50-458,83/06/24,8307130334.
- 8307030206 Interim Deficiency Rept DR-120 rs improper storage & subsequent deterioration of four standby switchyear circuit breakers. Initially reported on 830527. Investigation continuing. Interim or final rept will be provided by 830803. BOOKER. J. E. Gulf States Utilities Co. 83/06/27. COLLINS, J. T. Region 4. Office of Director. ip. 19198: 287. 24X Fiche: 50-458, 83/06/27, 8307030206.

- B307050216 Interim Deficiency Rept DR-92 re PYCO Inc & subsupplier documentation for Category I stainless steel thermowells. Initially reported on B30114. Suppliers not ASME III Guality Sys certificate holders. Next rept by B30817.
  BBDKER-J.E. Gulf States Utilities Co. B3/06/27. COLLINS. J. T. Region 4. Defice of Director. Ip. 19197:278. 24X Fiche: 50-458.83/06/27.8307050216.
- 8307080336 Interim Deficiency Rept DR-112 re power cables supplied by Power Conversion Products, used to terminate factory installed AMO 2 internal wiring. Initially reported on 830419. Util awaiting addi info. Next rept by 830822. 800MER. J. E. Oulf States Utilities Co. 83/06/28. COLLINS, J. T. Region 4, Office of Director. 1p. 19350:136. 24X Fiche: 50-458,83/06/28,8307080336.
- 8307080332 Interim Deficiency Rept DR-113 re misapplication of in-line cable splices on electrical connections for hydrogen igniter assemblies. Initially reported on 830419. Evaluation continuing. Next rept will be provided by 830720.

  BDDKER. J. E. Quif States Utilities Co. 83706729. COLLINS, J. T. Region 4, Defice of Director. ip. 19350:140. 24X
  Fiche: 50-458.83/06/29,8307080302.
- 8307080415 Interim Deficiency Rept DR-114 re weld defects in radial rebar anchor ring for shield bldg roof. Initially reported on 830419. Util awaiting addl info from AE. Next rept will be submitted by 830726.

  800KER.J. E. Quif Scates Utilities Co. 83/06/30. COLLINS. J. T. Region 4. Office of Director. ip. 19347:274. 24X Fiche: 50-458.83/06/30.8307080415.
- 8307080374 Interim Deficiency Rept DR-96 re linear indications found in Bergen-Patterson tube steel. Initially reported on 830217. AE awaiting addi info from vendor. Next rept will be submitted by 830826.
  BOOKER, J. E. Guif States Utilities Co. 83/07/01. COLLINS, J. J. Region 4. Office of Director. 1p. 19350:189. 24X
  Fiche: 50-458, 83/07/01, 8307080374.
- B307150378 Interim Deficiency Rept DR-103 re electrical separation of reactor protection sgs wiring from NBSE shutoff wiring within power generation control complex Initially reported on B30327. Info from GE awaited Next rept due by B30913.
  B00KER.J.E. Gulf States Utilities Co. B3/07/01. COLLINS.J.T. Region 4. Office of Director. 1p. 19539:142, 24X Fiche: 50-438.83/07/01.8307150378.
- 8307150173 Interim Deficiency Rept DR-89 re potential malfunction of primary knife-type disconnect mfg by RTE Delta Corp & used in diesel generators. Util awaiting addl info from AE. Next rept will be submitted by B30803.
  BOOKER. J. E. Gulf States Utilities Co. 83/07/06. COLLINS, J. T. Region 4. Office of Director. 1p. 19531:009. 24X Fiche: 50-458, B3/07/06, B307150173.
- 8307150326 Interim Deficiency Rept DR-104 re Interstate Steel & Hub. Inc & Regal & Welded Tube of America documentation for Class 1, Grade B. steel. Initially reported on 830404 AE info awaited. Next rept will be submitted by 830815.

  BOOKER.J.E. Gulf States Utilities Co. 83/07/07. COLLINS, J.T. Region 4, Office of Director. 1p. 19538:335: 24X Fiche: 50-458, 83/07/07, 8307150326.
- 8307190179 Interim Deficiency Rept DR-93 re documentation & code stamping of interconnecting piping between reactor water cleanup HXs. Info awaited from Atlas Industrial Mfg Co. Next rept will be submitted by 830012.

  BO
- 8307250284 Final Deficiency Rept DR-100 re Category I mutor control ctr motor operated valve feeder breakers supplied by Gould-Brown Boveri. Initially reported on B30222. Deficiency not reportable per 10CFR50. 55(e) due to unfinished sys design. BOUKER.J. E. Gulf States Utilities Co. 83/07/13. COLLINS.J. T. Region 4. Dffice of Director. 1p. 19705: 278. 24X Fiche: 50-458, 83/07/13, 8307250284.
- 8307250447 Final Deficiency Rept DR-111 re dimensional discrepancy on two small bore pipe support design drawings. Initially reported on 830412, Discrepancies isolated case, Item not reportable under 100FR90, 55(e).

  BDOKER.J. E. Guif States Utilities Co. 83/07/14, COLLINS, J. T. Region 4, Office of Director. ip. 19701:178, 24X Fiche: 50-458, 83/07/14, 8307250447,
- 8307250466 Final Deficiency Rept 116 re gaps larger than specified in joints connecting RHR HX supports. Initially reported on 830511. Support structure loads examined item not reportable per 10CFR50.55(e).

  80CKER.J. E. Oulf States Utilities Co. 83/07/15 COLLING, J. T. Region 4. Office of Director. 1p. 19701:320. 24X Fiche: 50-459, 83/07/15, 8307250466.

- 8307260056 Final Deficiency Rept BR-i15 re tackwelding of heavy hex nuts. Initially reported on 830510 Condition not reportable per 10CFR50.55(e). BOOKER.J.E. Gulf States Utilities Co. 83/07/18. COLLINS.J.T. Region 4. Office of Director. 1p. 19727:355. 24X Fiche: 50-458.83/07/18.8307260056.
- 8307260414 Interim Deficiency Rept DR-107 re Category I air circuit breaters withip coils of higher-than-bill-of-matls range. Initially reported on 830404.AE info awaited.Next rept will be submitted by 830823. BOOKER.J.E. Gulf States Utilities Co. 83/07/17. COLLINS.J.T. Region 4. Dffice of Director. lp. 19733:160. 24X Fiche: 50~458.83/07/19.8307260414.

### DUCKET 50-459 RIVER BEND STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- B307070050 Responds to NRC 830613 ltr re Endangered Species Act.
  Endangered red-coctaded woodpecker may occur in project
  area.Proposed areas should be inspected for presence of
  woodpecker.Requests notification of insp results.
  JORDAN.D. B. Interior. Dept. of, Fish & Wildlife Service.
  B3/06/28.
  ADENSAM.E. Licensing Branch 4. 2pp. 19293:256. 24X
  Fiche: 50-458.B3/06/28.B307070050.
- 8306270395 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Guif.LaSalle & Susquehanna re TMI Task Action Plan Item 1.6.1. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list enct. EISENHUT.D.G. Division of Licensing. 83/05/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000,83/06/29,8306270395.
- 8307060017 Forwards set of transparent overlays used in imagery associated w/Guestions 231.4 & .7 inadvertently omitted from 830422 submittal. Info responds to NRC 811231 & 820605 ltrs & will be referenced in future FSAR amend. 800KER. J E. Gulf States Utilities Co. 83/07/01. SCHWENCER. A. Licansing Branch 2. 19pp. 19249:012. 24X Fiche: 50-458.83/07/01, 8307060017.
- B306270397 Generic Ltr B3-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl.
  EISENHUT.D.O. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X
  Fiche: 30-000.83/07/05.8366270397.
- 8307080169 Generic Ltr 83-28 to all licensess of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Syc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669: 269. 24x Fiche: 30-000, 83/07/08, 8307080169.
- B3072003B3 Forwards request for add1 info re terrestrial resources, including map of site identifying prime farmland & farmland of statewide importance. Schedule for response requested.
  SCHMENCER.A. Licensing Branch 2. B3/07/08. CAHILL, H. J. Gulf States Utilities Co. 4pp. 17669:347. 24X Fiche:50-458,83/07/08,83072003B3.
- B307220142 Notification of B30720 & 21 meetings w/util & S&W in Cherry Hill,NJ to discuss Power Sys Branch items for facilities.

  MEINKANE. J. Licensing Branch 2. 83/07/14. SCHWENCER,A. Licensing Branch 2. 3pp. 19692: 264. 24X Fiche: 50-458,83/07/14,8307220142.
- 8307220589 Advises of NRC position requiring redundant ammonia & chloride detectors in control room normal ventilation sysintakes. Response to position requested by 800901.

  SCHMENCER. A. Licensing Branch 2. 83/07/15. CAHILL, M. J. Qulf States Utilities Co. 3pp. 19712:088. 24X Fiche:30-458,83/07/15,8307220589.
- 8307250367 Submits summary status of issues being addressed by Licensing Review Group II, per 830502 request. Four issues require further action prior to NRC closeout Post-accident sampling requires procedural upgrading.
  HOLTZSCHER, D.L. Licensing Review Group II, 83/07/15. STEFANO, J. J. Licensing Branch i. 12pp. 19705:203. 24x Fiche: 50-000, 83/07/15, 8307250367.

- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8306090247 Forwards draft SER (NUREO-0987), for review. Detailed agenda to resolve SER open items requested. Draft responses requested prior to recommended util & NRC meeting.

  NDVAK, T.M. Assistant Director for Licensing. 83/06/01. CAHILL, W. J., Oulf States Utilities Co. 683pp. 18797:201. 24X

  Fiche: 30-458, 83/06/01, 8306090249.
- 8307190463 Notification of 830719 meeting w/util & 8&W Engineering Corp in Bethesda,MD to discuss structural engineering draft SER open items. WEINKAM,E.J. Licensing Branch 2. 83/07/11. SCHWENCER,A. Licensing Branch 2. 3pp. 19656:073. 24X Fiche:50-458.83/07/11.8307190463.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307190265 Amend 9 to FBAR.W/830615 ltr. CAHILL.W.J. Oulf States Utilities Co. 83/07/31. EISENHUT, D.Q. Division of Licensing. 317pp. 19644:001. 24X Fiche: 50-458, 83/07/31.8307190265.
- P. Operating license stage documents & correspondence
- 8307040329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 8TS. 8vc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 80-000, 83/07/06, 8307060329.
- G. Inspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46, "Common Mods Valve Failures Degrade Surry Recirculation Spray Subsystem," Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Bnubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche:50-000,83/07/12,8306270404.
- B306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list encl. TAYLOR,J.M. Division of GA, Safeguerds & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of Naw York, Inc. 114pp. 19715:270. 24% Fiche: 30-000, B3/07/14, B306270406.

### DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

- A. Application/construction stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Syc list encl, EISENHUT.D. 9. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000, 83/07/05, 8306270397.
- B307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Bvc list encl. EIBENHUT.D.G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307290177 Advises that plan & schedule for resolution of reactor coolant pump trip issue, per TMI Action Item II.K. 3.5, will be delayed until const restart. Concurs w/Generic Ltr B3-10E that applicant work through owners groups for solutions.

  BORENSEN, 9.C. Washington Public Power Supply System. 83/07/22.

  EISENHUT. D. 9. Division of Licensing. 1p. 19821:052. 24X

  Fichs: 50-460, 83/07/22, 8307290177.
- F. Security, medical, emergency & fire protection plans
- 8307110317 Releases public version of revised emergency preparedness plan. FELTON.J.M. Division of Rules and Records. 83/06/24. Document Management Branch. ip. 19384:237. 24X Fiche:50-397,83/06/24, 8307110317.

[30711032] Public version of Rev 3 to emergency preparedness plan consisting of drawings of backup emergency operations facilities at util headquarters in Richland, WA. W/B30616 ltr. BGUCHEY, G. D. Washington Public Power Supply System. B3/04/30. NOVAK.T.M. Assistant Director for Licensing. 4pp. 19384:258. 24X Fiche: 50-397, B3/06/24, B307110317.

#### Adjudicatory correspondence

7030172 Response to 830409 first set of interrogatories. Certificate # Svc & prof qualifications encl.
#ONER.M.E. YOUNG.M.A. Hearing Branch 4. 83/06/30. Coalition or 8afe Power. 25pp. 19199:003. 24X Fiche: 50-460.83/06/30, 207050172.

705017B Memorandum & order denying util 830607 motion to compet urther answers from Coalition for Safe Power to util 830503 jrst set of interrogatories Motion mout since Coalition jled response on 830622. ROSBMAN.H. Atomic Safety and Licensing Board Panel. 83/07/01. astington Public Power Supply System. 2pp. 19199:187. 24X jche:50-460.83/07/01.830705017B.

7120556 Order establishing further schedule re discovery,motions or summery disposition.prefiled testimony & hearing.
GOSBMAN.H. Atomic Bafety and Licensing Board Panel. 83/07/11.
pp. 19432:065. 24X Fiche: 50-460.83/07/11.8307120896.

7200126 Third set of interrogatories. Related correspondence. ELL.N. Coalition for Bafe Power. 83/07/13. Washington Public ower Bupply System. 7pp. 19648:137. 24X Fiche: 50-460,83/07/13, 307200126.

307200131 Motion to compel answers from util to second set of interrogatories. Interrogatories concern issues properly discoverable. Related correspondence.

BELL,N. Coalition for Safe Power. 83/07/13. Atomic Safety and Licensing Board Panel. 3pp. 17648:144. 24X Fiche: 50-460, 83/07/13, 8307200126.

307200134 Updated responses to first set of interropatories. Related respondence. L.N. Coalition for Safe Power. 83/07/13. 4pp. 19648:147. Fiche:50-460:83/07/13:8307200126.

307200138 Second updated responses to first set of interrogatories.
Certificate of Svc encl.Related correspondence.
BELL,N. Coalition for Safe Power. 83/07/13. Washington Public Power Supply System. 4pp. 19648:151. 24X Fiche: 50-460.83/07/13.8307200126.

7260298 Forwards N Bell affidavit re varacity of statements in 30426 ltr to ABLB re disclosure of Coalition for Safe Power amber identity. ELL.N. Coalition for Bafe Power. 83/07/21. HARTMAN, 8. Debevo Liberman. 2pp. 19726:230. 24X Ficha:50-460,83/07/21,83072602

Operating license stage documents & correspondence

7060327 Generic Ltr 83-27 to all licensees & applicants for perating power reactors & holders of CPs for power reactors & surveillance intervals in STS. Svc list encl.
ISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated dison Co. of New York, Inc. 16pp. 19669: 254. 24X iche: 50-000, 83/07/06, 8307060329.

## Inspection reports, IE Bulletins & correspondence

6270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Urry Recirculation Spray Subsystem." Svc list encl. DRDAM.E.L. Division of Emergency Preparedness & Engineering Seponse (Post B30103). 83/07/11. Consolidated Edison Co. of New Ork, Inc. 154pp. 19563:293. 24% Fiche: 50-000,83/07/11.8306270401.

6270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as wault of Contaminated Hydraulic Fluid." Svc list encl.
DRDAN, E.L. Division of Emergency Preparadness & Engineering
\*\*sponce (Post 830103). 83/07/12. Consolidated Edison Co. of New Ork, Inc. 141pp. 19563:153. 24% Fiche: 50-000, 83/07/12, 8306270404.

\$270405 IE Info Notice 83-48. "Gaseous Effluent Releases of Middle India Notice 83-48. "Gaseous Effluent Releases of MRC Limits." Svc list Nel. Aylor, J. H. AYLOR.J.H. Division of GA, Bafeguards & Inspection Programs (Post 30103). 83/07/14. Consolidated Edison Co. of New York, Inc. 14pp. 19715:270. 24X Fiche:50-000.83/07/14.8306270406.

- 5. Reportable occurrences. LERs & related correspondence
- B307120497 Interim deficiency rept re emergency diesel generator starting air valve assembly mfg by Transamerica Delavai. Initially reported on B20618 Capscrew design revised Next rept by const restart. Also reportable per Part 21. DE LORENZO, R. A. Washington Public Power Bupply System. 83/06 STERNBERG, D. M. Region 5, Office of Director. 2pp. 19425:021. Fiche: 50-460: B3/06/29, B307120497. 19425 021
- B307180034 Interim Deficiency Rept 2 re deformation in conductor insulation in Okonite cable. Sixteen 7/C-#12 cables will be removed & replaced. Bix cables installed in raceway will be abandoned in place & replaced. Final rept by const restart. DE LORENZO.R. A Washington Fublic Power Supply System. 83/07/STERNBERG.D.M. Region 5. Office of Director. 3pp. 17560:131 Fiche: 50-460.83/07/01.8307180034. 17560: 131.
- 8307180144 Interim deficiency rept re problem w/top cover gaskets on NAMCO Model EA180 series switches. Problem traced to over-impregnated & insufficiently heat cured top cover gaskets. Also reported per Part 21.

  DE LORENZO, R. A. Washington Public Power Supply System. 83/07/01.
  STERNBERG, D. M. Region 5. Diffice of Director. 3pp. 19557: 046. 24 Fiche: 50-460, 83/07/01, 8307180144.
- B307280297 Interim deficiency rept re emergency diesel generator current transformers. Initially reported on 811113. Norlake Mfg Co current transformer. Model CD 1408, selected to replace Westinghouse current transformer. DE LORENZO,R. Washington Public Power Supply System. B3/07/14. STERNBERG, D. M. Region 5. Office of Director. 3pp. 19790:118. 24% Fiche: 50-460. B3/07/14, B307280299.
- 8307280345 Final deficiency rept re Buffalo Forge fan housing missile protection. Initially reported on 810824, Unit 1 fans shipped to manufacturer for rework. Unit 4 fans not being modified. Nonconformance rept written.

  DE LORENZO. R. A. Washington Public Power Supply System. 83/07/18. STERNBERG. D. M. Region 5. Office of Director. 3pp. 19789: 028. 24) Fiche: 50-460.83/07/18.8307280345.

## DOCKET 90-461 CLINTON POWER STATION, UNIT 1

A. Application/construction stage documents & correspondence

- B307080259 Forwards backfit cost figures for addl seven utils per original B30208 request. Cost figures for 20 utils transmitted B30411.
  TOURTELLOTTE, J. Regulatory Reform Task Force. B3/06/22.
  PALLADING, N. Commissioners. 2pp. 19363:313. 24X
  Fichs: 50-000, B3/06/22, B307080259.
- --8307080031 Informs of inability to respond to NRC 830208 request re impact of regulatory backfit cost since util has no operating plant to use as baseline for comparison. Support expressed for backfit evaluation effort.

  HALL,D.P. Illinois Power Co. 83/04/09. TOURTELLOTTE, J. Regulatory Reform Task Force. ip. 19363:320. 24X Fiche: 50-000.83/06/22.8307080289.
- 8307060020 Requests review of util actions & concurrence in lifting 8top Work Order 16 issued on 820628 re electrical conduit installation. Necessary portions of recovery plan completed HACLID.P. Illinois Power Co. 83706/24. KEPPLER.J. 9. Region 3. Office of Director. 1p. 19251:041. 24X Fiche: 50-461, 83/06/24.
- B307060073 Requests review of util actions to correct deficiencies re electrical cable tray & tray attachment installation. Also requests concurrence in lifting B20118 Stop Work Order 7. HALL. D.P. Illinois Power Co. 83/06/24, KEPPLER, J.G. Region 3, Office of Director. 2pp. 19251; 321. 24X Fiche: 50-461,83/06/24, B307060073
- B306270395 Generic Ltr 83-24 to all BMR applicants for OL & holders of OLs for Grand GulfiLaSalla & Susquehanna re TMI Task Action Plan Item I.O. 1, "Special Low Power Testing & Training & Recommendations for BMRs." Evc list enci. EIBENHUT.D.G. Division of Licensing. B3/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000.83/06/29. EISENHUT, D. G. Divi Lighting Co. 26pp. 8306270395.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of GPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24% Fiche: 50-000, B3/07/05, B306270397.

- 8307110532 Ack receipt of 830615 ltr requesting concurrence in plans for lifting Stop Work Order 017 on structural steel.
  Appropriate procedures & instructions revised to accomplish lessons learned training Concurs w/lifting stop work order.
  KEPPLER, J. G. Region 3, Office of Director. 83/07/06. GERSTNER, W. C. Illinois Power Co. 1p. 19380:142. 24X Fiche: 50-461,83/07/06, 8307110532.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fichs: 50-000.83/07/08,8307080169.
- 8307220379 Revises commitments made in response to NRC 820127 confirmation of action ltr re increased util GA & const mgt involvement in contractor const mgt 8A/GC program. GERSTNER.W.C. Illinois Power Co. 83/07/13. KEPPLER.J. 9. Region 3. Diffice of Director. 3pp. 19675:230. 24X Fiche: 50-461.83/07/13.8307220379.
- B307250367 Submits summary status of issues being addressed by Licensing Review Group II.pur B30502 request. Four issues require further action prior to NRC closeout. Post-accident sampling requires procedural upgrading.
  HOLTISCHER. D. L. Licensing Review Group II. B3/07/15. STEFAND, J. J. Licensing Branch 1. 12pp. 19705:203. 24X Fiche: 50-000, B3/07/15, B307250367.
- 8307270049 Forwards evaluation of B21022 submittal re operability of containment purge & vent valves under combined LDCA/seismic loadings. Further justification required for 24 & 36-inch valves.

  SCHMENCER: A. Licensing Branch 2. B3/07/20. WULLER, Q. Illinois Power Co. 7pp. 19811:038. 24% Fiche: 30-461, B3/07/20, B307270049.
- 8307280322 Concurs w/830624 decision to lift Stop Work Order 7 on electrical coble tray & tray attachments. Continued compliance w/8A requirements assumed.

  KEPPLER. J. C. Region 3, Diffice of Director. 83/07/22. GERSTNER, W. C. 111nois Power Co. 2pp. 19789: 245. 24X Fiche: 50-461, 83/07/22. 8307280322.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B307120376 Forwards listing of docteted sources of documentation per NUREG-0802 criteria & comparison of plant w/Kuosheng.Grand Oulf & Perry per NUREG-0763 to resolve SER Outstanding Issue 7.
  - 9. WULLER, G. E. Illinois Power Co. 83/07/08. SCHWENCER, A. Licensing Branch 2. 20pp. 19430:198. 24X Fiche: 50-461, 83/07/08, 8307120396.
- 8307260154 Forwards summary update to info previously submitted by 821215 ltr re electrical & mechanical seismic & dynamic equipment qualification.per Supplemental SER 2. Installation of 593 piaces of equipment complete.

  HULLER, G. E. Illinois Power Co. 83/07/26. SCHWENCER, A. Licensing Branch 2. 2pp. 19727:309. 24X Fiche: 50-461, 83/07/26, 8307260154.
- F. Security, medical, emergency & fire protection plans
- B307110228 Forwards revised emergency response capability implementation plan schedule & submittals to reflect new submittal dates of B30101 for control room review program plan & B30701 for summary rept per Supp 1 to NUREG-0737. WULLER.G.E. Illinois Power Co. B3/07/05. SCHWENCER.A. Licensing Branch 2. 5pp. 19376:107. 24X Fiche: 50-461, 83/07/05, 8307110228.
- 8307190230 Clarifies info on Fire Zones D. 3.2 & D. 3.6, in response to 821216 ltr re update of safe shutdown analysis for fire protection & request for exemptions from 10CFR50, App R. Two cable conduits embedded in concrete. WULLER.G.E. Illinois Power Co. 83/07/14. SCHWENCER.A. Licensing Branch 2. 2pp. 19630:104. 24% Fiche: 50-461.83/07/14.8307190230.
- Q. Adjudicatory correspondence
- B307120591 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.
  NEUHAN,R.W. Illinois: State of. 83/07/08. 3pp. 19432:148. 24X
  Fiche: 50-461:83/07/08,8307120581.

## H. General correspondence

- 8307180086 Advises of reassignment of training organization to vice president rather than Baldwin Assoc Quality & Technical Svcs. Change necessary since QA workload detracts from available mpt attention to QA matters.

  HALL.D.P. Illinois Power Co. 83/07/08. KEPPLER, J. Q. Region 3, Office of Director. 1p. 19556:250. 24X Fiche: 50-461,83/07/08. B307180086.
- P. Operating license stage documents & correspondence
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Syc list encl. EISENHUT, D. G. Division of Licensing, 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19469:294. 24X Fiche: 50-000, 83/07/04, 8307060329.
- G. Inspection reports, IE Bulletins & correspondence
- 8307110031 Forwards revs to overinsp checklists & instructions to be used in overinsp program.

  HALL.D.P. Illinois Power Co. 83/06/27. KEPPLER, J. C. Region 3, Office of Director. 17pp. 19374:181. 24X Fiche: 50-461, 83/06/27, 8307110031
- 8307080283 Ack receipt of 830628 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/83-02. LITLE.W.S. Region 3. Office of Director. 83/07/05. GERSTNER.W.C. Illinois Power Co. ip. 19351:210. 24X Fiche: 50-461.83/07/05. 8307080283.
- --8307080290 Responds to NRC 830516 ltr re violations noted in IE Insp. Rept 50-461/83-02. Corrective actions: all superseded electrical hanger travelers identified by site search transmitted to document records ctr for storage. HALL.D.P. Illinois Power Go. 83/06/28. KEPPLER.J.Q. Region 3, Office of Director. 5pp. 19351:211. 24X Fiche: 50-461,83/07/05,8307080283.
- B307110268 Forwards IE Insp Rept 50-461/83-08 on 830621-25.No noncomplience noted. KNOP.R.C. Region 3, Office of Director. 83/07/06. GERSTNER, W.C. Illinois Power Co. 2pp. 19374:258. 24X Fiche: 50-461,83/07/06, 8307110268.
- --8307i10276 IE Insp Rept 50-461/83-08 on 830621-25. No noncompliance noted Major areas inspected review of licensee assessment of record verification program "dry run," progress w/Standing Mork Order 007 & action on open items. JABLONSKI.F. J., BERGOREN, J. S., HAYES. D. W. Region 3, Office of Director. 83/07/02. 3pp. 19374: 260. 24X Fiche: 50-461, 83/07/06, 8307110268.
- 8307210139 Forwards IE Insp Rept 50-461/83-07 on 830615-17. No noncompliance noted.
  LITTLE.M.S. Region 3, Office of Director. 83/07/08. GERBTNER.W.C. Illinois Power Co. 2pp. 17666:112. 24X Fiche: 50-461,83/07/08,8307210139.
- --8307210149 IE Insp Rept 50-461/83-07 on 830613-17. No noncompliance noted Major areas inspected training procedures & testing program requirements for personnel involved w/8top Work Order 019 & 0A records & associated documents.

  KEATING, D.E., CILIMBERG, R.L., DANIELSON, D.H. Region 3, Office of Director, 83/07/08, 6pp. 17666:114. 24X Fiche: 50-461, 83/07/08, 8307210139.
- R. Periodic operating reports & related correspondence
- 8307280065 Provides quarterly const schedule updates in response to 810529 request. Next rept will be submitted in Oct 1983. HALL, D.P. Illinois Power Co. 83/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ip. 19791:204. 24X Fiche: 30-461,83/07/22,8307280065.
- S. Reportable occurrences, LERs & related correspondence
- B307130263 Part 21 rept re indeterminate weld quality due to surface irregularities that may mask defects. Initially reported on B30622. Piping subassemblies containing welded angular branch connections w/pad reinforcement reviewed.

  MOERKE.N.H., BORNES,R.P. Southwest Fabricating & Welding Co. (subs. of IV International Corp.), 83/06/24. PDTAPOVS; U. Region 4, Office of Director. 3pp. 19538: 080. 24X Fiche: 30-461, 83/06/24, 8307150263.

- 8307110322 Finel Deficiency Rept 82-13 re fabrication & detailing of structural steel connection drawings provided by Bristol Steel & Iron. Initially reported on 821115. Vendor surveillance dept reorganized to increase effectiveness. HALL.D.P. Illinois Power Co. 83/07/05. KEPPLER.J. G. Region 3. Office of Director. Spp. 19381:278. 24x Fiche:50-441.83/07/05.8307110322.
- 8307180009 Interim Deficiency Rept 82-09 re small/bore instrumentation piping & conduit support design calculations. Initially reported on 820902. Sargent & Lundy procedures for small bore/instrumentation support design enhanced.

  HALL, D. P. Illinois Power Co. 83/07/06. KEPPLER, J. G. Region 3, Office of Director. 7pp. 19560:301. 24x Fiche: 50-461,83/07/06,8307180009.
- 8307180036 Interim Deficiency Rept 83-04 re document control of QE design change documents. Initially reported on 830215. Investigation results & corrective actions listed Final rept to be sent in 90 days. HALL.D.P. Illinois Power Co. 83/07/06. KEPPLER.J. 9. Region 3. Office of Director. App. 19360: 209. 24X Fiche: 30-461, 83/07/06, 8307180036

# V. Operator Examinations

- 8307150344 Supplemental response to Generic Ltr 83-01 re licensed operator exams. Approx 25 candidates will be examined in each June & Sept 1985 session. WULLER, G.E. Illinois Power Co. 83/07/08, 8CHWENCER, A. Licensing Branch 2. 1p. 19538:279. 24X Fiche: 50-461,83/07/08,8307150344.
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8307080259 Forwards backfit cost figures for add1 seven utils per original 830208 request. Cost figures for 20 utils transmitted 830411.
  TOURTELLOTTE, J. Regulatory Reform Task Force. 83/06/22.
  PALLADING, N. Commissioners. 2pp. 19363:313, 24X
  Fiche: 50-000, 83/06/22, 8307080259.
- --830708033i Informs of inability to respond to NRC 830208 request re impact of regulatory backfit cost since util has no operating plant to use as baseline for comparison. Support expressed for backfit evaluation effort.

  HALL, D. P. Illinois Power Co. 83704708. YOURTELLOTTE, J. Regulatory Reform Task Force. 1p. 19363:320. 24X

  Fiche: 50-000, 83706722, 8307080259.
- 8306270395 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Gulf.LaSalle & Susquehama re TMI Task Action Plan Item I.Q. i. "Special Low Power Testing & Training & Recommendations for BWRs." Syc list encl.
  EISENHUT.D.G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000.83/06/29. 8306270395.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Byo list encl. EISENHUT.D.G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000, B3/07/05, B306270397.
- 8307060329 Generic Ltr 83-27 to all licensess & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS, Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254, 24x Fiche: 50-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- B307250367 Submits summary status of issues being addressed by Licensing Review Oroup II.per 830502 request. Four issues require further action prior to NRC closeout. Post-accident sampling requires procedural upgrading. HOLTZBCHER. D. L. Licensing Review Group II. B3/07/15. STEFANO, J. J. Licensing Branch 1. 12pp. 19705:203. 24X Fiche: 50-000. B3/07/15, 8307250367.

- S. Reportable occurrences, LERs & related correspondence
- 8307180009 Interim Deficiency Rept 82-09 re small/bore instrumentation piping & conduit support design calculations. Initially reported on 820702 Sargent & Lundy procedures for small bore/instrumentation support design enhanced.

  HALL, D. P. Illinois Power Co. 83/07/06. KEPPLER, J. G. Region 3, Office of Director. 7pp. 19360:301. 24X Fiche: 50-461,83/07/06,8307180009.
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- B307200409 Informs of Salance due for review of CP application, withdrawn on B21006. Invoice to cover Commission review costs will be issued.

  MILLER, W.O. License Fee Management Branch. B3/07/11. OPREA, Q. W. Houston Lighting & Power Co. 1p. 19472: 254. 24X

  Fiche: 30-466, 83/07/11, 8307200409.
- --8307200412 Discusses max assessment of fees for CP application & withdrawal reviews.Util will be billed for balance due. HOLLEMAY.C.J. License Fee Management Branch. 83/07/11, License Fee Management Branch. 2pp. 19672:255. 24X Fiche: 50-466, 83/07/11,8307200409.
- --B307200417 Confirms 760907 telcon re reactivation of Unit 1 const on modified schedule.Plans for Unit 2 canceled.Ltr describing design changes discussed at 760923 meeting will be submitted in mid-Nov 1976.

  OPREA.O.H. Houston Lighting & Power Co. 76/10/07. RUSCHE,B.C. Office of Nuclear Reactor Regulation, Director. 19. 19672:257. 24X Fiche: 50-466:83/07/11:8307200409.
- DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8307200409 Informs of balance due for review of CP application, withdrawn on 821004. Invoice to cover Commission review costs will be issued.

  MILLER, M. O. License Fee Management Branch. 83/07/11. OPREA, Q. W. Houston Lighting & Power Co. ip. 19672: 254. 24X

  Fiche: 50-466, 83/07/11, 8307200409.
- --8307200412 Discusses may assessment of fees for CP application & withdrawal reviews. Util will be billed for balance due.
  HOLLOWAY.C.J. License Fee Management Branch. 83/07/11. License Fee Management Branch. 83/07/11. 8
- --8307200417 Confirms 760907 telcon re reactivation of Unit 1 const on modified schedule. Plans for Unit 2 canceled. Ltr describing design changes discussed at 760923 meeting will be submitted in mid-Nov 1976.

  OPREA. G. W. Houston Lighting & Power Co. 76/10/07. RUSCHE, B. C. Office of Nuclear Reactor Regulation. Director. 1p. 19672: 297, 24X Fiche: 50-466.83/07/11,8307200409.
- DOCKET STN-50-470 CESSAR SYSTEM 80
- A. Application/construction stage documents & correspondence
- 8307010172 Forwards "Depressurization & DHR.Response to NRC Questions." Recommends NRC base cost/benefit analysis in existing Sys 80 plants on possible design change. BCHERER.A.E. Combustion Engineering, Inc. 83/06/29. EISENHUT.D.O. Division of Licensing. 59pp. 19171:127. 24X Fiche: 50-470.83/06/29, 8307010172.
- --8307010184 "Depressurization & DHR.Response to NRC Questions."

  Executive summary included.


  \* Combustion Engineering. Inc. CEN-239. 83/06/30. 433pp. 19171:186. 24% Fiche: 90-470.83/06/29.8307010172.
- 8307150160 Outlines & approves 830411 & 26 requests to withhold listed info from public disclosure per 10CFR2.790.

  THOMAS.C.O. Standardiretion & Special Projects Branch. B3/06/30.

  SCHERER.A.E. Combustion Engineering, Inc. 3pp. 19540:355. 24X

  Fiche: 50-470.83/06/30.8307150160.
- 8307150170 Outlines & approves 830228.0426 & 0510 requests for withholding listed info from public disclosure per 10CFR2.790.

  THOMAS.C.O. Standardization & Special Projects Branch. 83/06/30. 8CHERER.A.E. Combustion Engineering, Inc. 4pp. 17540:358. 24X Fiche: 50-470.83/06/30.8307150170.



- B307210241 Submits list of expert witnesses to be called Counsel for other parties have no objection.
  SILBERG, J.E. Shaw. Pittman, Potts & Trowbridge. SILBERG, J.E. Kansas Gas & Electric Co. 83/07/19. LAURENSON, J. A., ANDERSON, G. C., PAXTON, H. C. Atomic Safety and Licensing Board Panel. 2pp. 19664:165. 24X Fiche: 50-482, 83/07/19, 8307210241.
- G. Inspection reports, IE Bulletins & correspondence
- 8307120010 Forwards IE Insp Rept 50~482/83-13 on 830416-0515 & notice of violation.
  8EIDLE.W. C. Region 4, Office of Director. 83/06/14. KDESTER, G. L. Kanass Gas & Electric Co. 2pp. 19425:122. 24X
  Fiche: 50-482,83/06/14,8307120010.
- --8307120011 Notice of violation from insp on 830416-0515.

  \* Region 4: Office of Director. 83/06/14. 2pp. 19425:124. 24X Fiche: 50-482,83/06/14,8307120010.
- --8307120013 IE Insp Rept 50-482/83-13 on 830414-0515. Noncompliance noted: lack of training & qualification for anchor bolt torque verification & rejectable indications on moisture separator welds in steam generator 1.

  ROBERDS.H. H. JURNSON. M. D. Region 4. Office of Director.

  83/06/14. 5pp. 19425: 126. 24X Fiche: 50-482, 83/06/14, 8307120010.
- 8307120488 Forwards IE Insp Rept 50-482/83-14 on 830501-31 & notice of violation.
  8EIDLE, M. C. Region 4, Office of Director. 83/06/15. KOESTER, G. L. Kaness Gas & Electric Co. 2pp. 19425:029. 24X
  Fiche: 50-482,83/06/15,8307120488.
- --8307120494 Notice of violation from insp on 830501-31.

  \* Region 4, Office of Director. 83/06/15. 1p. 19425:031. 24X Fiche: 50-482,83/06/15,8307120488.
- --8307120498 IE Insp Rept 50-482/83-14 on 830501-31. Noncompliance noted: failure to provide procedure for realignment of (NK) 125-volt dc Class IE electrical sys to support vendor rework on battery chargers.

  SCHUM, W. S., JUHNSON, M. D. Region 4, Office of Director. 83/06/14.

  8pp. 19425:032. 24% Fiche: 50-482,83/06/15,8307120488.
- 8307050114 EN-83-015A: on B30630, order imposing civil penalty in amount of \$40,000 issued, based on licensee failure to ensure complete QA sys turnover. Licensee may pay civil penalty within 30 days or request hearing.

  KLINOLER, O. AXELRADJ. Director's Office. Office of Inspection and Enforcement. 83/06/30. 1p. 17197:362. 24X Fiche: 50-482,83/06/30,830/78014
- 8307050212 Responds to 830421 ltr re notice of violation & proposed imposition of civil penalties issued on 830323. Order imposing civil monetary penalty & evaluation & conclusion supporting actions encl.
  DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 63/06/30. KUESTER, G. L. Kansas Cas & Electric Co. 2pp. 19198: 320, 24X Fiche: 50-482, 83/06/30, 8307050212.
- --8307050217 Order imposing civil monetary penalty in amount of \$40,000 based on licensee failure to adequately control activities affecting quality of safety-related work,per IE Insp Rept 30-482/83-02.

  DEYOUNG.R.C. Director's Office. Office of Inspection and Enforcement. 83/06/30. Kansas Oas & Electric Co. 7pp. 19198:322. 24X Fiche: 50-482,63/06/30,8307050212.
- 8307130061 Forwards, for transmittal to Off. of FR. order imposing civil monetary penalty, issued to util on 830630. W/o encl. AXELRAD. J. A. Office of International Programs, Director. 83/06/30. Docketing & Services Branch. ip. 19474: 216. 24X Fiche: 50-482, 63/06/30, 6307130061.
- 8307120471 Ack receipt of 830421 & 0617 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-04.

  SEIDLE.W.C. Region 4, Office of Director. 83/07/01. KOESTER.G.L. Kansas Oas & Electric Co. 1p. 17424:185. 24X Fiche:30-482, 83/07/01,8307120471.
- --B30712047& Responds to NRC B30325 ltr re violations noted in IE lnsp Rapt 50-482/83-04.Corrective actions: GC Procedures GCP-VI-200 & GCP-VI-201 revised on B30512 to assure that vessels & equipment turned over acceptably clean. KOESTER.O.L. Kansas Gas & Electric Co. B3/06/17. SEIDLE, W. C. Region 4, Office of Director. 2pp. 19424: 186. 24X Fiche: 50-482, 83/07/01, 8307120471.

- B306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York: Inc. 154pp. 19563:293. 24X Fiche: 50-000. B3/07/11, B306270401.
- 8306270404 IE Info Notice B3-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:133. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307180261 Ack receipt of 830624 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-482/83-10.

  SEIDLE.W. C. Region 4, Office of Director 83/07/13. KOESTER, G. L. Kansas Gas & Electric Co. 1p. 17355: 359. 24X Fiche: 50-482, 83/07/13, 8307180261.
- --B307180278 Responds to NRC 830506 ltr re violations noted in IE Insp. Rept 50-482/83-10. Corrective actions: all future intermittent fillet welds will require weld increment at ends of dimensioned length.

  KDESTER.O.L. Kansas Qas & Electric Co. 83/06/24. SEIDLE, W. C. Region 4, Office of Director. 3pp. 19355: 360. 24X

  Fiche: 50-482, 83/07/13, 8307180261.
- B306270406 IE Info Notice B3-4B, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Byo list encl.
  TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.B3/07/14, B306270406.
- 8307220480 Ack receipt of B30617 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-11.
  8EIOLE, M. C. Region 4. Office of Director. 83/07/18. K0E8TER, G. L. Kansas Oas & Electric Co. 1p. 19685: 192. 24X Fiche: 50-482, 83/07/18, 8307220480.
- --8307220487 Responds to NRC 830520 ltr re violations noted in IE Insp. Rept 50-482/83-11. Corrective actions: AE contacted to verify that diamond figures adjacent to travel bar satisfy specs. KOE8TER, O. L. Kansas Gas & Electric Co. 83/06/17. SEIDLE, W. C. Region 4. Office of Director. 3pp. 19685: 193. 24X Fiche: 50-482, 83/07/18, 8307220480.
- S. Reportable occurrences, LERs & related correspondence
- B3070500B7 Interim deficiency rept re documentation & hardware discrepancies in borated refueling water sys. Initially reported on B30121. Discrepancies evaluated. No effect on safety of operation noted Next rept spected by 830930. KOESTER. G. L. Kansas Gas & Electric Co. 83/06/24. SEIDLE, W. C. Region 4, Office of Director. ip. 19193: 184. 24X Fichs: 50-482,83/06/24,8307050087.
- B307030113 Final deficiency rept re discrepancy between piping stool piece matl & matl specs of installed piping stool piece in feedwater sys. Safety not adversely affected. Condition not reportable per 10CFR50.551e).

  KUESTER: O. L. Kansas Gas & Electric Co. 83/06/24. SEIDLE: W. C. Region 4. Office of Director. 2pp. 19220: 023. 24X
  Fiche: 50-482.83/06/24, B307050113.
- 8307050219 Final deficiency rept re impruperly torqued bolt on instrument mounts. Initially reported on 830222. Bolts will be replaced & torqued per designer specs. Corrective action due in approx 2 months. Also reported per Part 21.

  KDESTER. G. L. Kansas Gas & Electric Co. 83/06/24. SEIDLE. W. C. Region 4. Defice of Director. App. 19198: 329. 24X

  Ficha: 50-482,83/06/24,8307050219.
- 8307060280 Forwards Significant Deficiency Repts 83-01,83-03 & 83-01 re EMD gate valve position & U-bolt restraints, inadvertently omitted from transmittal to Washington, DC ofc.

  SEIKEN, S. J. Standardized Nuclear Unit Power Plant System. 83/06/30. DEYOUNG, R. Director's Office of Inspection and Enforcement. 1p. 19239:027. 24X Fiche: 50-000,83/06/30,8307060280.
- --8307060288 Final Significant Deficiency Rept 83-03 re design & installation of U-bolt restraints. Initially reported on 830127. Analysis revealed absence of locknots on piping. Double nut locking mechanism installed.

  SEIKEN, S. J. Standardized Nuclear Unit Power Plant System. 83/02/18. KEPPLER, J. G. Region 3. Defice of Director. COLLING, J. T. Region 4. Office of Director. Bpp. 19239:032. 24X Fiche: 50-000,83/06/30,8307060280.

- B307110244 Part 21 rept re deficiency in Bechtel design of ac & dc control circuits for facilities Design changes to affected motor controller & power circuit breater compartments initiated. Also reported per 10CRESO. 55(\*\*) by SNUPPS MEYERS, B. L. Bechtel Corp. B3706/30 KEPPLER. J. G. Region 3, Office of Director. SEYRRIY. K. Region 4, Office of Director. Spp. 19374: 339. 24% Fiche: 50-000. 83/06/30. 8307t10244.
- 8307120515 Final deficiency rept re potential errors in reactor coolant wide range pressure instruments during post-accident conditions initially reported on 820504. Transmitters PT403 & PT405 will be relocated outside containment.

  KDEBTER, G. L. Kansas Gas & Electric Co. 83/07/01. SEIDLE.H. C. Region 4. Office of Director. 2pp. 19433:200. 24X Fiche: 50-482.83/07/01.8307120515.
- 8307230315 Interim deficiency rept re nonconforming nuclear coatings in reactor bldg. Phase 1 of test program developed to evaluate acceptability of coatings completed & Phase 2 scheduled to begin in Jul Test status will be provided by 831202. MCGETER, G. L. Kansas Gas & Electric Co. 83/07/01. 1p. 19701:343. 24X Fiche: 50-482-83/07/01.8307250315.
- 8307210221 Forwards 830621 Part 21 rept re valve seat defects.
  QALLD.R M: Region i. Office of Director. 83/07/05. KISTER.H.B.
  Region 1. Office of Director. 1p. 19666: 290. 24X
  Fiche: 50-000.83/07/05.8307210221.
- ~-8307210229 Part 21 rept re valve seat defect. Initially reported on 830620. Risk of seat cracking could occur under torque. Backbel analysis underway.

  BARCLAY. J. F. Yarway Corp. 83/06/21. GALLO. R. Repion 1. Office of Director. 11pp. 19666: 291. 24X Fiche: 50-000. 83/07/05. 8307210221.
- 8307150241 Final deficiency rept re failure of battery on backup diesel fire pump. Initially reported on 830610. Battery not safety-related. Item not reportable per 10CFR50. 55(e).

  KOESTER.G. L. Kansas Gas & Electric Co. 83/07/08. SEIDLE, H. C. Region 4. Office of Director. ip. 19531:092. 24X
  Fiche: 50-482,83/07/08,8307150241.
- 8307150243 Interim deficiency rept re push button switches installed in main control panels. Initially reported on 830609. Matter under investigation by AE & Cutler-Hammer. Evaluation & resolution expected by 830790.

  KOEBTER. G L. Xansas Gas & Electric Co. 83/07/08. SEIDLE, W. C. Region 4. DEfice of Director [p. 19538: 348. 24X Fiche: 50-482, 83/07/08, 8307150243.
- 8307190110 Interim deficiency rept re miscellaneous component failures in safety-related battery chargers. Initially reported on 830309. Power Conversion Products. Inc currently testing chargers & making corrections. Next rept by 831003.
  KOESTER. G. L. Kansas Gas & Electric Co. 83/07/11. SEIDLE, W. C. Region 4, Office of Director. 1p. 19635:007. 24X
  Fiche: 30-482,83/07/11,8307190110.
- B307250322 Interim deficiency rept re linear indications on base metal on Guyon 1/2-inch socket couplings Initially reported on B30617. Investigation continuing. Next rept will be submitted by B31014.

  KOESTER. C. L. Kansas Cas & Electric Co. 83/07/15. SEIDLE, W. C. Ragion 4. Office of Director. 1p. 19701:360. 24X Fiche. 50-482, 83/07/15. 8307250322.
- 8307250390 Interim deficiency rept re questionable matls supplied by Ray Miller Corp used in safety-related applications. Initially reported on 830218 Investigation continuing Next rept will be provided by 840130. MOESTER. G. L. Kansas Gas & Electric Co. 83/07/15. SEIDLE, H. C. Region 4. Office of Director. 1p. 19701:331. 24X Fiche: 30-482,83/07/15,8307250380.
- 8307230453 Interim deficiency rept re laminations in three weld beam attachments. Initially reported on 830617. Problem under evaluation by AE & Bergen-Paterson. Next rept will be submitted by 831028
  KDESTER.G. L. Kansas Gas & Electric Co. 83/07/15. SEIDLE, W. C. Region 4, Office of Director. 19. 19701:171. 24X
  Fiche: 50-482, 83/07/15, 8307250453.
- B307260382 Interim potential deficiency rept re welds on Bergen-Faterson sway struts. Initially reported on B30224. Last three struts being inspected Evaluation will be completed upon disposition of nonconformance repts. Next rept by B31021. KDESTER. 6 L. Kansas Qas & Electric Co. 83/07/18. SEIDLE, W. C. Region 4: Office of Director. ip. 19733: 161. 24X Fiche: 50-482, 83/07/18, B307260382.

- B307290178 Interim deficiency rept re installation of Vulkene Supreme cable. Initially reported on B30620. Evaluation in progress.

  Next rept will be provided by B30930.

  KDESTER. 9. L. Kansas Gas & Electric Co. 83/07/20. SEIDLE. W. C. Region 4. Office of Director. ip. 1982:042. 24X

  Fiche: 50-482,83/07/20,8307290178.
- 8307290352 Interim deficiency rept re OE AKR breakers. Initially reported on 830620 Matter still under evaluation. Status of evaluation will be reported by 831007.
  KOESTER, G. L. Kansas Gas & Electric Co. 83/07/20. SEIDLE, W. C. Region 4. Office of Director. 1p. 17826:311. 24X
  Ficha: 50-482,83/07/20,8307290352.

### V. Operator Examinations

- 8307060077 Provides revised info re operator licensing exams,per Generic Ltr 83-01.8chadule changes based on fuel load date advanced to 840815. KOESTER.G.L. Kansas Gas & Electric Co. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 17251:278, 24X Fiche:50-482,83/07/01,8307060077.
- DOCKET STN-50-489 CALLAWAY PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8304040070 Generic Ltr 83-22 to all operating reactor licenses, applicants for ULs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines," Svc list enci. EISENHUT. D. O. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19543:116. 24X Fiche: 50-000, 83/06/03, 8304040070.
- B307060034 Requests determination of NRC ofc responsible for review of Tech Spec Section 6.0 re administrative controls,per STS (NUREQ-0452),by 830715. Jul meeting w/reviewers requested to effect tentative agreement by B30915. SCHWELL,D.F. Union Electric Co. 83/06/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19251:148. 24X Fiche: 50-483,83/06/30,8307060034.
- 8307110257 Submits proposed schedule for completing Tech Spec review & issuance. Issuance of Tech Spec Sections 1-5 expected prior to fuel load date of 840402.

  8CHNELL D.F. Union Electric Co. 83/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19374: 268. 24X Fiche: 50-483, 83/06/30, 8307110257.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders, of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. 8vc list encl. EISENHUT, D. O. Division of Licensing. 83/07/05. Gonsolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X fiche: 50-000,83/07/05,8306270397.
- 8307130292 Summary of 830617 meeting w/util ½ SNUPPS in Bethesda.MD re GA program for operations.List of attendees encl. EDISON.O.E. Licensing Branch 1. 83/07/06. Licensing Branch 1. 5pp. 19511:132. 24% Fiche:50~483.83/07/06.8307130292.
- 8307130312 Advises that use of Paragraph NF-4427 from Winter 1782 Addenda to Section III of ASME Boiler & Pressure Vessel Code re fillet welds acceptable (POUNOBLOOD, B. J. Licensing Branch 1. 83/07/06. KOESTER, O. L. Kansas Gas & Electric Co. 3pp. 17508:359. 24X Fiche: 50-482,83/07/06.
- B307080169 Generic Ltr B3-2B to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York. Inc. 3Bpp. 19669:269. 24X Fiche: 30-000.83/07/08.8307080169.
- 8307290037 Notification of 830801 meeting w/utils, Westinghouse & ENUPPB in Bethesda, MD to discuss plasma display sys for inadequate core cooling data.
  EDISON, O. E., HOLONICH, J. J. Licensing Branch 1. 83/07/18.
  YOUNGBLOOD, B. J. Licensing Branch 1. 5pp. 19837: 015. 24X
  Fiche: 30-000, 83/07/18, 8307270037.
- 8307250309 Forwards to WP Haass,Rev 7 to QA program for design & const of Callaway & Wolf Creek sites.Callaway site addendum reflects changes in organizational updating in effect prior to 8303if rulemaking date. W/o encl.

  SEIKEN.S.J. Standardized Nuclear Unit Power Plant System. 83/07/21.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19701:347. 24X Fiche:50-000,83/07/21,8307250309.

# E. NRC Safety Evaluation Report (SER), suppls & correspondence

- 8307110076 Forwards two copies of Suppl 2 to SER (NUREG-0830, Suppl 2). W/o encl. VDUN0BLOOD, B. J. Licensing Branch 1. 83/06/28. SCHNELL, D. F. Union Electric Co. 3pp. 19386: 297. 24% Fiche: 50-483, 83/06/28, 8307110076
- 8307150141 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CALLAMAY FLANT, UNIT NO. 1. bockst No. 50-483. (Union Electric Company)

  \* Division of Licensing. NUREG-0830 SO2. 83/06/30. 65pp. 19562:155. 24X Fiche: 50-483, 83/06/30, 8307150141.
- 8307130050 Forwards Suppl 2 to SER (NUREC-0830). W/o encl. YOUNGBLOOD, B. J. Licensing Branch 1. 83/07/06. SCHNELL, D. F. Union Electric Co., 3pp. 19511:297. 24X Fiche: 50-483, 83/07/06, 8307130050.
- B30713026B Forwards revised marked-up Tech Bpecs discussed at B30203 meeting Requests confirmatory issues & license conditions listed in SERs (NUREQ-0830 & 0881) be removed from SER & responsibility transferred to NRC for review.

  PETRICK. N. A. Standardized Nuclear Unit Power Plant System.
  B3/07/08. DENTON, H. R. Defice of Nuclear Reactor Regulation, Director. 436pp. 19506:237. 24X Fiche: 50-000,83/07/08,8307130268.
- F. Security, medical, emergency & fire protection plans
- 8307060257 Forwards "Detailed Control Room Design Review Program Plan for SNUPPS," in response to Generic Ltr 82-33. Suppl 1 to NUREQ-0737. "Requirements for Emergency Response Capability." PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 83/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19238:263. 24X Fiche: 50-000.83/06/30.8307060257.
- --8307060264 "Detailed Control Room Design Review Program Plan for BNUPPS." \* Standardized Nuclear Unit Power Plant System. 83/06/30. 17pp. 19238:264. 24X Fiche:50-000,83/06/30,8307060257.
- 8307110352 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~483/82-14.
  LITTLE W. B. Region 3, Office of Director. 83/07/06. SCHNELL D.F. Union Electric Co. 1p. 17382:268. 24X Fiche: 50~483,83/07/06,8307110352.
- --8307110334 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-483/82-14. Corrective actions: Doors 4/23 & 5/23 in fire pump house will be installed by 831101. 8CHNELL, D. F. Union Electric Co. 83/07/01. LITTLE, W. S. Region 3, Office of Director. ip. 19382: 269. 24X Fiche: 50-483, 83/07/06, 8307110352.

# O. Adjudicatory correspondence

- 8307070060 Summarizes 830623 meeting of parties in Fulton, MO to resolve Reed Contentions 4, ii & 15. Reed agreed to withdraw contentions based on commitments in encl settlement agreement. Draft order encl.

  PERLISE.R. 9. Hearing Branch 3. 83/06/30. GLEASON, J. P., KLINE, J. R., BRIGHT, O. O. Atomic Safety and Licensing Board Panel. 3pp. 19294:330. 24X Fiche: 50-483,83/06/30,8307070060.
- --8307070063 Settlement agreement re disposition of J Reed Contentions 4, if & 15. Reed will withdraw contentions based on outlined commitments. PERLIS, R. O. Hearing Branch 3, 83/06/30, 9pp. 19294:353, 24X Fiche: 50-483, 83/06/30, 8307070060.
- 8307080375 Forwards util executed settlement agreement re disposition of Reed contentions. Svc list encl.

  BAXTER.T. A. Shaw. Pittman, Potts & Trowbridge. BAXTER.T. A. Union Electric Co. B3/07/05. OLEABON, J.P., BRIGHT, O. C., KLINE, J.R. Atomic Bafety and Licensing Board Panel. 3pp. 19349:324. 24X Fiche: 50-483, 83/07/05, 8307080375.
- --8307080383 Stipulation re disposition of Reed Contentions 4.11 & 15. Contentions will be withdrawn based on listed commitments. BAXTER, T. A. Union Electric Co. 83/07/05. 3pp. 19349:327. 24X Fiche: 50-483,83/07/05,8307080375.
- B307180263 Settlement agreement re disposition of J Reed Contentions 4, 11 & 15. Certificate of Bvc encl. REED. J. Reed, J. O. 83/07/12. 4pp. 19555: 355. 24X Fiche: 50-483, 83/07/12, 8307180263.

- 8307190250 Notifies of VR Harding employment at law firm Harding will not participate in any case currently pending before NRC.
  BAXTER.T.A. Shaw. Pittman. Potts & Troubridge. BAXTER.T.A. Union Electric Co. 83/07/13. GLEASON, J.P., BRIGHT.G.Q., KLINE, J.R. Atomic Safety and Licensing Board Panel. 1p. 19628:281. 24X Fiche: 50-483, 83/07/13, 8307190250.
- --8307190255 Notifies of employment at law firm VR Harding will not participate in any case pending before NRC. Svc list encl. HARDING: V.R. Show, Pittman, Potts & Trowbridge, B3/07/13. GLEASON, J.P., BRIGHT. G.O., KLINE, J.R. Atomic Safety and Licensing Board Panel. 3pp. 19628:282. 24X Fiche: 50-483,83/07/13,8307190250.
- B3072503B1 Forwards SER Suppl 2.W/o encl.
  PERLIS.R.G. Hearing Branch 3. B3/07/22. ROBENTHAL,A B.,
  EDLES.G.J., OLEASON.J.P. Atomic Safety and Licensing Appeal Panel.
  2pp. 19701:332. 24X Fiche:50-403.83/07/22,83072503B1.
- B3072B0225 Order ratifying settlement agreement between NRC/FEMA, util & JG Reed Reed Contentions 4:11 & 15 dismissed Hearing on two remaining contentions to be held on 830913 Written testimony & expert witness identification by B30824.
  BRIGHT.G.O. KLINE.J.R., GLEASON.J.P. Atomic Safety and Licensing Board Panel. B3/07/27. 5pp. 19794:138. 24X Fiche:50-483,83/07/27,8307280225.
- J. Insurance & indemnity information
- B307200099 Forwards MAELU & NELIA Certificates of Insurance M-95 & N-95 (secondary financial protection), respectively.
  BUCKLEB. J. A. Marsh & McLennan, Inc. B3/07/ii. SALTZMAN, J.
  Assistant Director for State & Licensee Relations. 14pp. 17646:049.
  24X Fiche: 50-483, B3/07/ii, B307200099.
- Inspection reports, IE Bulletins & correspondence
- 8307120302 Forwards IE Insp Rept 50-483/83-10 on 830524-27. No noncompliance noted. PAPERIELLO.C.J. Region 3. Office of Director. 83/06/22. SCHNELL.D.F. Union Electric Co. 2pp. 17433:253. 24X Fiche: 50-483,83/06/22,8307120502.
- --8307120506 IE Insp Rept 50-483/83-10 on 830524-27. No noncompliance noted Major areas inspected radiation protection program, including organization, training, radiation protection procedures, facilities & equipment & previous insp findings. LGVENDALE, P. C., GREGER, L. R. Region 4, Diffice of Director. 83/06/22, 7pp. 17433; 255. 24X Fiche: 50-483, 83/06/22, 8307120502.
- 8307140075 Forwards IE Insp Rept 50-483/83-12 on 830607-08.No noncompliance noted. LITTLE: M. S. Region 3, Office of Director. 83/06/30. SCHNELL, D. F. Union Electric Co. 2pp. 19514: 168. 24X Fiche: 50~483, 83/06/30, 8307140075.
- --8307140080 IE Insp Rept 50~483/83-12 on 830607-08. No noncompliance noted Major areas inspected pipe whip restraint design control installation & GC insp activities & review of upgraded site hanger GC insp program
  YIN.I.T., DANIELSON, D. H. Region 3, Office of Director, 83/06/28, 9pp. 19514:170, 24X Fiche: 50~483,83/06/30,8307140075.
- 8307180132 Forwards IE Insp Rept 50-483/83-13 on 830614-17. No noncompliance noted, KNDP.R.C. Region 3. Office of Director. 83/06/30. SCHNELL.D.F. Union Electric Co. 2pp. 19557:068. 24X Fiche: 50-483.83/06/30.8307180132.
- --8307180137 IE Insp Rept 50-483/83-13 on 830614-17. No noncompliance noted Major areas inspected 10CFR50. 55(e) repts IE bulleting & review of previous inspected findings.
  WESCOTT, H. M., RONKEIN, J. E. Region 3, Office of Director.
  83/06/29. App. 19557:070. 24X Fiche: 50-483,83/06/30,8307180132.
- 8307110352 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-14.
  LITTLE, M. B. Region 3. Office of Director. 83/07/04. 9CHNELL, D. F. Union Electric Co. 1p. 19382: 268. 24X Fichs: 50-483,83/07/06,8307110352.
- --B307110354 Responds to NRC B30329 ltr re violations noted in IE Insp Rept 50-483/82-14 Corrective actions: Doors 4/23 & 5/23 in fire pump house will be installed by B31101. BCHNELL, D. F. Union Electric Co. B3/07/01 LITTLE, M. S. Region 3, Office of Director. 1p. 19382:269. 24X Fiche: 50-483, 83/07/06, B307110352.

- 8307i10360 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/83-21.
  Corrective actions re cable sidewall pressure issue appears adequate.
  LITTLE.W S. Region 3, Office of Director. B3/07/06. SCHNELL.D.F. Union Electric Co. 1p. 19380:234. 24X Fiche:50-483,83/07/06,830710360.
- ~~8307110364 Responds to NRC B30308 ltr re violations noted in IE Insp. Rept 50-483/83-21. Corrective actions: AE issued guidelines via E-01013(Q)-7-4, consisting of visual exam & physical testing of cables. Addi cables identified & tested. SCHNELL. D.F. Union Electric Co. 83/07/01. LITTLE. M. S. Region 3, Office of Director. 3pp. 19380.235. 24x Fiche: 50-483, 83/07/04, 8307110360.
- B306270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JURDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000, B3/07/11, B306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice B3-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.

  TAYLOR.J. M. Division of QA. Bafeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14.8306270406.
- 8307260205 Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-22. NORELIUS-C. E. Division of Project & Resident Programs. 83/07/21. SCHNELLD.F. Union Electric Co. 1p. (9727:190. 24x Fichs: 50-483.83/07/21.8307260205.
- --8307260214 Responds to NRC 830404 ltr re violations noted in IE Insp. Rept 50-483/82-22. Improvements to internal design interface processes described. Selsmic classification of pump turbine exhaust pipe concerns addressed. SGHMELL.D F. Union Electric Co. 83/06/15. KEPPLER.J.C. Region 3. Office of Director. 51pp. 19727:191. 24X Fiche: 30-483,83/07/21,8307260205.
- 8307280392 Ack receipt of 830718 ltr informing NRC of steps taken to correct violations noted in FE Insp Rept 50-483/83-11.

  KNOP.R.C. Region 3, Office of Director. 83/07/22. SCHNELL.D.F. Union Electric Co. 1p. 19796:063. 24x Fiche: 50-483.83/07/22, 8307280392.
- --8307280401 Responds to NRC 830617 ltr re violations noted in 1E Insp. Rept 30-483/83-11. Corrective actions: craft & supervision advised that severe disciplinary actions will be taken against individuals tampering w/hardware following insp. SCHNELL D.F. Union Electric Co. 83/07/18. KNOP.R.C. Region 3, Office of Director. Spp. 19796:064. 24X Fiche: 90-483, 83/07/22, 8307280392.
- R. Periodic operating reports & related correspondence
- 8307120477 Submits quarterly followup response to NRC 810527 ltr reconst progress. Schedule remains unchanged. Fuel load scheduled for Apr 1984.

  DOUGHERTY.C.J. Union Electric Co. 83/06/30. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 1p. 19432:267. 24X

  Fiche:50-483.83/06/30,8307120477.
- S. Reportable occurrences. LERs & related correspondence
- 8307030096 Final Deficiency Rept U-35 Te Rubertshaw thermostatic flow control valves. Castellated not & cutter pin installed & valve body O-ring eliminated preventing valve stem from disengaging. Also reported per Part 21 SCHNELL.D.F. Union Electric Co. B3/06/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 19199:337. 24X Fiche: 30-483, 83/06/24, 8307050096.
- B307060280 Forwards Significant Deficiency Repts B3-01, B3-03 & B3-01 re EMD gate valve position & U-bolt restraints, inadvertently omitted from transmittal to Washington. DC ofc. SEIKEN.S.J. Standardized Nuclear Unit Power Plant System B3/06/30. DEYOUNG.R. Director's Office of Inspection and Enforcement. 1p. 19239: 027. 24x Fiche: 50-000, B3/06/30, B307060280.

- --8307040288 Final Significant Deficiency Rept 83-03 re design & installation of U-bolt restraints. Initially reported on 830127. Analysis revealed absence of locknuts on piping. Double nut locking mechanism installed. GEIKEN, S. J. Standardized Nuclear Unit Power Plant Bystem. 83/02/18. KEPPLER, J. G. Region 3. Office of Director. CULLINS. J. T. Region 4. Office of Director. Spp. 19237: 032. 24X Fiche: 50-000, 83/04/30, 8307040280.
- 8307110244 Part 21 rept re deficiency in Bechtel design of ac & dc control circuits for facilities. Design changes to affected motor controller & power circuit breaker compartments initiated. Also reported per 100FR50. 55(e) by SNUPPS. MEYERS, B. L. Bechtel Corp. 83/06/30. KEPPLER, J. Q. Region 3. Office of Director. SEYFRIT, K. Region 4. Office of Director. 5pp. 19374:339. 24X Fiche: 50-000,83/06/30.8307110244.
- 8307110301 Final Deficiency Rept U-40 re inaccuracy of wide-range RCS pressure transmitters during post-accident conditions inside containment. Transmitters will be relocated from inside to outside containment. FSAR will be revised.

  SCHNELL, D.F. Union Electric Co. 83/06/30, KEPPLER, J. Q. Region 3, Office of Director. ip. 19374: 344. 24X Fiche: 50-483, 83/06/30, 8307110301.
- 8307110231 Final Deficiency Rept U-56 & Part 21 rept re metal belious flexible hose assembly w/60 degree instead of 90 degree fitting at discharge of reactor coolant pump B motor. Initially reported on 830602.All assemblies inspected. SCHNELL, D.F. Union Electric Co. 83/07/01. KEPPLER, J. G. Region 3, Office of Director. 2pp. 19380:031. 24X Fiche: 50-483, 83/07/01, 830710231.
- 8307210221 Forwards 830621 Part 21 rept re valve seat defects. GALLO,R. M. Region i, Office of Director. 83/07/05. KISTER. H. B. Region i, Office of Director. ip. 19666:290. 24X Fiche: 50-000,83/07/05,8307210221.
- --8307210229 Part 21 rept re valve seat defect. Initially reported on 830620. Risk of seat cracking could occur under torque.

  Bachtel analysis underway.

  BARCLAY, J. F. Yarway Corp. 83/06/21. GALLO, R. Region i. Office of Director. [1pp. 17666:291. 24X Fiche: 50-000, 83/07/05, 8307210221.
- DOCKET 30-496 MONTAQUE NUCLEAR POWER STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENAUT. D. O. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19370:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISCANUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New Yorks Inc. 16pp. 19669:254. 24X Fiche: 30-000:83/07/06;8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISEMHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- G. Inspection reports. IE Bulletins & correspondence
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3707/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Bnubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York: Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715; 270. 24X Fiche: 50-000, 83/07/14, 8306270406.

- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for CLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D. 9. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390: 317. 24X Fig. 1che: 50-000.83/07/05.8306270397.
- BSOPOA0329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors resourcellance intervals in STS. 8vc list encl.

  EIBENHUT, D. 0. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19649: 254. 24x

  Fiche: 30-000, 83/07/06, 8307060329.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EIBENHUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17669: 269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- G. Imspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JORDANIE.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- B3D&270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48. "Caseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list ensc 1.
  FAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York. Inc. 114pp. 19715:270. 24X Fiche: 80-000.83/07/14.8306270406.
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A. Application/construction stage documents & correspondence
- B3D7220394 Forwards list detailing status of commitments for corrective actions made prior to transition of engineering work on project.
  RICE:M.M. Brown & Root Corp. (subs. of Halliburton Corp.).
  B2/02/08. SEYFRIT.K. Region 4. Defice of Director. 2pp.
  19475:255. 24X Fiche: 50-498. B2/02/08. G307220394.
- 8307040118 Forwards response to Structural Engineering Branch (SEB)
  Question 220, 34 requesting addl info in form of completed
  structural design audit forms SEB audit requested after June
  1983. Bechtel reviewing stress analysis. W/o encl.
  GOLDBERGJ.H. Houston Lighting & Power Co. 83/06/30. NGVAK.T.M.
  Assistant Director for Licensing. 2pp. 19252:221. 24X
  Fiche: 50-498.83/06/30,8307060118.
- 8307060170 Forwards response to NRC Question 440.1 re deletion of smergency boration sys. Response will be included in Amend 33 to FSAR, scheduled for Sept 1983.

  QOLDBERG, J. H. Houston Lighting & Power Co. 83/06/30. NOVAK, T. M. Astistant Director for Licensing. 14pp. 19230:160. 24X Fiche: 50-498, 83/06/30, 8307060170.
- B307⊋00231 Notification of B30707 meeting u/technical review committee in Bethesda, MD to discuss review of D4, D3 & E steam generator mods.

  HOPKING, J. B. Licensing Branch 4. B3/07/01. ADENSAM, E. Q. Licensing Branch 4. 2pp. 19670: 234. 24X Fiche: 50-000, B3/07/01, B307200231.

- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT, D. G. Division of Licensing B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000. B3/07/05, B306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 878. Svc list encl. EIGENHUT. D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche: 50-000, 83/07/06, 830/7060329
- 8307080169 Generic Ltr 83-28 to all licenses of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:269. 24X Fiche: 50-000, 83/07/08, 8307080169.
- 8307250242 Notification of contract execution, Mod 4 to "Expert Consultation & Witness Svc for South Texas Project Hearings." Contractor: W Hubacek.
  PERLMAN. J. Administrative Contracts Branch. FIN B-B506. 83/07/14 COLLINS. J. T., CROSSMAN. W. Region 4. Office of Director. 1p. 19721:063. 24X Fiche: 50-498, 83/07/14, 8307250242.
- --8307250250 Mod 4, extending period of performance to 831231 & adding add1 funds, to "Expert Consultation & Witness Svc for South Texas Project Hearings."
  HUBACEK, M. O. Hubacek, W. O. SMITH, P. A. Division of Contracts. FIN 8-8506, 83/07/14, 1p. 19721:064, 24X Fiche: 50-498,83/07/14, 8307250242.
- B307250468 Provides schedule for submittal of responses to Reactor Sys Branch review questions, in response to 830512 ltr. QOLDBERG, J.H. Houston Lighting & Power Co. 83/07/15. MOVAK, T. M. Assistant Director for Licensing. 2pp. 19701: 271. 24X Fiche: 50-498, 83/07/15, 8307250468.
- B307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4, D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
  BUTTERFIELD.L. Steam Generator Owners Group. B3/07/18.
  EISENHUT, D. G. Division of Licensing. 3pp. 19664:114. 24X Fiche: 50-000, B3/07/18, B307210300.
- 8307250124 Summary of 830707 meeting w/technical review committee in Bethesda, MD re Model D4/D5/E steam generator mod. Viewgraphs encl.
  HDPKINB, J. D. Licensing Branch 4. 83/07/18. Licensing Branch 4. 26pp. 1973B: 132. 24% Fiche: 50-000. 83/07/18, 8307230124.
- F. Security, medical, emergency & fire protection plans
- 8307070134 Informs that encl to util 830517 ltr contained schedule for implementation of prompt notification sys. Schedule will be confirmed or rescheduled by June 1984.

  GOLDBERG, J. H. Houston Lighting & Power Co. 83/06/30. JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103). 2pp. 19294:218. 24X Fiche 50-498,83/06/30,8307070134.
- 8307220030 Notification of 830714 meeting w/util in Bethesda,MD to discuss fire protection issues affecting near-term design decision, isolation valve cubicle PRA & pipe break program. Aganda encl. VIETTI.A. Licensing Branch 3, 83/07/05, KNIGHTON, C. W. Licensing Branch 3, 5pp. 19692:124, 24X Fiche: 50-498,83/07/05,8307220030.
- G. Adjudicatory correspondence
- 8307190256 Memorandum & Order LBP 83-37 denying Citizens Concerned About Nuclear Power 830318 motion to admit new contention refinancial qualifications. Unusual circumstances do not exist to waive financial qualifications rule.

  BECHIDEFER.C. Atomic Safety and Licensing Board Panel. 83/07/14.

  Citizens Concerned About Nuclear Power, Inc. 13pp. 19628:268. 24X Fiche: 50-498.83/07/14.8307190256.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307210008 Forwards Amend 32 to FSAR Affidavit encl. GOLDBERG, J. H. Houston Lighting & Power Co. 83/07/19, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19657:001. 24X Fiche: 50-498, 83/07/19, 8307210008.
- --8307210010 Amend 32 to FSAR. \* Houston Lighting & Power Co. 83/07/19, 587pp. 19657:005. 24X Fiche: 50-498, 83/07/19, 8307210008.

- 8307260349 Certifies svc of Amend 32 to FSAR on 830719. QUINN.V.M. Houston Lighting & Power Co. 83/07/19. 2pp. 19732:359. 24% Fiche.50-498.83/07/19.8307260349
- Q. Inspection reports, IE Bulletins & correspondence
- 8307120520 Forwards IE Insp Repts 50-498/83-10 & 50-499/83-10 on 830516-20 No noncompliance noted MADSEN.G L. Region 4. Diffice of Director. 83/06/09. OPREA.G.W. Houston Lighting & Power Co. 2pp. 19434:004. 24X Fiche: 50-498.83/06/09.8307120520.
- --8307120531 IE Insp Repts 50-498/83-10 & 50-499/83-10 on B30516-20. No noncompliance noted Major areas inspected; procedure review & welding of safety-related piping.
  GILBERTIL. D. CROSSMAN. H. A. , HUNNICUTT, D. M. Region 4. Office of Director. 83/06/02. 5pp. 19434:006. 24x Fiche: 50-498,83/06/09,8307120520.
- B307150122 Forwards IE Insp Repts 50-498/B3-07 & 50-499/B3-07 on B30401-0314. No noncompliance noted. MADSEN,G.L. Region 4. Office of Director. B3/06/30. OPREA,G.W. Houston Lighting & Power Co. 2pp. 19536:236. 24X Fiche: 90-498.83/06/30.8307150122.
- --B30715014B IE Insp Repts 50-498/83-07 & 50-499/83-07 on 830401-0514. No noncompliance noted. Major areas inspected: equipment storage & maint. site tours: nonconformance repts. structural concrete & steel, electrical installations & soil test. HLL.-H. H., CROSSMAN. M. A. Region 4, Office of Director. 83/06/27. 11pp. 19336: 23B. 24X Fiche: 50-498.83/06/30.8307150122.
- B306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list ancl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563.293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydrautic Snubbers as Result of Contaminated Hydraulic Fluid." Svc 11st encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche:50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 93-49, "Caseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR.J.M. Division of OA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fichs.80-000.83/07/14.8306270406.
- 8307220285 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-478/83-02 & 30-497/83-02. Supplemental info requested within 30 days. MADSEN. G. L. Region 4. Office of Director. 83/07/18. OPREA, G. W. Houston Lighting & Power Co. 3pp. 17684:142. 24X Fiche: 50-498, 83/07/18, 8307220285.
- --8307220292 Responds to NRC 830518 ltr re violations noted in IE Insp Repts 50-498/83-02 & 50-499/83-02. Corrective actions: hardness test data sheets & personnel training records retrieved & available at site. OPREA.O.N. Houston Lighting & Power Co. 83/06/16. COLLINS, J. T. Region 4. Office of Director. 6pp. 19684:145. 24X Fiche:50-498,83/07/18,8307220285.
- S. Reportable occurrences, LERs & related correspondence
- 8307060269 Final deficiency rept re voltage requiation problem for ESF 4160/480-volt Class IE load ctr transformers. Initially reported on 830419. Transformers will be replaced w/new transformers w/lower impedance based on sys requirements. OPREA.G.W. Houston Lighting & Power Co. 83/06/29. COLLINS, J. T. Region 4. Dffice of Director. 4pp. 19238:281. 24X Fiche:50-498.83/06/29.8307060268
- 8307080476 Final deficiency rept re triaxial cable mfg by Rockbestas used in electrical penetrations supplied by Westinghouse. Initially reported on 811026, Cable RSS-6-108 will be used as replacement. Also reported per Part 21.

  OPREA G.W. Houston Lighting & Power Co. 83/06/30. COLLINS, J. T. Region 4. Office of Director. 3pp. 19346:325. 24X

  Fiche: 30-478, 83/06/30, 8307080476.
- 8307230465 Final deficiency rept re flashovers/failures of nonsafety-related insulators. Initially reported on 830616. Insulators either coated w/grease or replaced Insulators will be replaced w/different design.

  OPREA.C.W. Houston Lighting & Power Co. 83/07/13. COLLINS, J. T. Region 4. Office of Director. 4pp. 19701:241. 24X
  Fiche: 50~498, 83/07/13, 8307250465.

- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

  A. Application/construction stage documents & correspondence
- 8307220394 Forwards list detailing status of commitments for corrective actions made prior to transition of engineering work on project.
  RICE.W.M. Brown & Root Corp. (subs. of Halliburton Corp.).
  B2/02/08. SEYFRIT,K. Region 4, Office of Director. 2pp.
  19675:255. 24X Fiche:50-498,82/02/08,8307220394.
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.
  EISENHUT, D. G. Division of Licensing. 83/06/03. Yankee Atomi Electric Co. 10pp. 19363:116. 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307060118 Forwards response to Structural Engineering Brench (REB) Question R20. 34 requesting add1 info in form of completed structural design audit forms. SEB audit requested after June 1983. Bechtel reviewing stress analysis. W/o encl. QOLDBERG, J. H. Houston Lighting & Power Co. 83/06/30. NOVAK, T. H. Assistant Director for Licensing. 2pp. 19232: 221. 24X Fiche: 50-498, 83/06/30, 8307040118.
- 8307060170 Forwards response to NRC Question 440.1 re deletion of emergency boration sys. Response will be included in Amend 33 to FSAR, scheduled for Sept 1983. GULDBERG, J. H. Houston Lighting & Power Co. 83/06/30. NOVAK, T. M. Assistant Director for Licensing. 14pp. 19250:160. 24X Fichs: 50-498, 83/06/30. 8307060170.
- B30720023I Notification of 830707 meeting w/technical review committee in Bethesda, MD to discuss review of D4, D5 & E steam generator mods.

  HDPKINB.J.B. Licensing Branch 4. 83/07/01. ADENSAM, E.Q. Licensing Branch 4. 2p. 19670:254. 24X Fiche:50~000,83/07/01.8307200231.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19370:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 830706032? Generic Ltr 83~27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 818. 8vc list encl. EIBENHUT.D.O. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000, 83/07/06, 8307060327.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT.D.G. Division of Licensing 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fichs: 50-000,83/07/08,8307080169.
- B307250242 Notification of contract execution Mod 4 to "Expert Consultation & Witness Syc for South Texas Project Hearings." Contractor: W Hubacek.
  PERLMAN. J. Administrative Contracts Branch. FIN B-8506. 83/07/14.
  COLLINS. J. T., CROSSMAN. W. Region 4. Office of Director. 1p.
  19721:063. 24X Fiche: 50-478.83/07/14.8307250242.
- --8307250250 Mod 4.extending period of performance to 831231 & adding addi funds, to "Expert Consultation & Witness Svc for Bouth Texas Project Hearings."
  HUBACEK. W. O. Hubacek. W. O. SMITH. P. A. Division of Contracts. FIN 8-8506. 83/07/14. tp. 19721:064. 24X Fiche:50-498,83/07/14,8307250242.
- 8307290468 Provides schedule for submittal of responses to Reactor Sys Branch review questions, in response to 830512 ltr. GDLDBERG, J.H. Houston Lighting & Power Co. 83/07/15, NOVAK, T.M. Assistant Director for Licensing. 2pp. 19701:271, 24X Fiche: 50-498,83/07/15,8307250468.
- B307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4,D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
  BUTTERFIELD, L. Steam Generator Owners Group. B3/07/18.
  EISENHUT,D. G. Division of Licensing. 3pp. 19664:114. 24X
  Fiche: 50-000, B3/07/18, B307210300.

- 8307250124 Summary of B30707 meeting w/technical review committee in Bathesda, MD re Model D4/D5/E steam generator mod. Viewgraphs enci.

  MOPKING J. B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 24pp. 19738:132. 24X Fiche: 50-000:83/07/18, 8307250124.
- F. Security, medical, emergency & fire protection plans
- 8307070134 Informs that encl to util 830517 ltr contained schedule for implementation of prompt notification sys. Schedule will be confirmed or rescheduled by June 1984.

  QOLDBERG, J. H. Houston Lighting & Power Co. 83/06/30. JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 19294:218. 24X Fiche: 50-498,83/06/30,8307070134.
- B307220030 Notification of B30714 meeting w/util in Bethesda, MD to discuss fire protection issues affecting near-term design decision, isolation valve cubicle PRA & pipe break program.
  - Agenda encl. VIETTI.A. Licensing Branch 3. 83/07/05. KNIGHTON.G.W. Licensing Branch 3. 5pp. 19692:124. 24X Fiche:50-498,83/07/05.8307220030.
- G. Adjudicatory correspondence
- 8307190256 Memorandum & Order LBP 83-37 denying Citizens Concerned About Nuclear Power 830318 motion to admit new contention refinancial qualifications. Unusual circumstances do not exist to waive financial qualifications rule.

  BECHHOLEER, C. Atomic Safety and Licensing Board Panel. 83/07/14. Citizens Concerned About Nuclear Power, Inc. 13pp. 19628: 268. 2 Fiche: 50-498, 83/07/14, 8307190256.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B307210008 Forwards Amend 32 to FSAR. Affidavit encl. GOLDBERG, J. H. Hauston Lighting & Power Co. 83/07/19. DENTON, H. 19657:001. GOLDBERG, J. H. Houston Lighting & Power Co. 83/ Office of Nuclear Reactor Regulation, Director. 24X Fiche: 30-498,83/07/19,8307210008. DENTON, H. R.
- --8307210010 Amend 32 to FBAR.

  \* Houston Lighting & Power Co. 83/07/19. 587pp
  Fiche: 50-498, 83/07/19, 8307210008. 19657: 005. 24x
- 8307260349 Certifies svc of Amend 32 to FSAR on 830719. GUINN,V.M. Houston Lighting & Power Co. 83/07/19. 2pp. 19732:359. 24X Fiche: 50-498,83/07/19,8307260349.
- G. Inspection reports: IE Bulletins & correspondence
- B307120520 Forwards IE Insp Repts 50-498/83-10 & 50-499/83-10 on B30516-20. No noncompliance noted. MADSEN.G.L. Region 4. Office of Director. 83/06/09. OPREA.G.W. Houston Lighting & Power Co. 2pp. 19434:004. 24X Fiche: 50-498.83/06/09.8307120520.
- --8307120531 IE Insp Repts 50-498/83-10 & 50-499/83-10 on 830516-20. No noncompliance noted Major areas inspected: procedure review & welding of safety-related piping.

  GLIBERTIL D., CROSSMAN. M.A.: HUNNICUIT, D. M. Region 4, Office of Director. 83/06/02. Spp. 19434:006. 24X Fiche: 50-498, 83/06/09, 3007106870 uirector. 83/06/02. 83/06/02.
- 8307150122 Forwards IE Insp Repts 50-498/83-07 % 50-499/83-07 on 830401-0514. No noncompliance noted.

  MADSEN.G. L. Region 4, Office of Director. 83/06/30. OPREA, G. W. Houston Lighting & Power Co. 2pp. 19536-236. 24X Fiche: 50-498.83/06/30,8307150122.
- ---830715014B IE Insp Repts 50-498/83-07 % 50-499/83-07 on 830401-0514. No noncompliance noted Major areas inspected equipment storage & maint, site tours, nonconformance repts, structural concrete & steel, electrical installations & soil test.
  HILL.W.M., CROSSMAN.W.A. Region 4, Office of Director. 83/06/27, 11pp. 19536: 238. 24X Fiche: 50-498, 83/06/30, 8307150122.
- 8304270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc. list encl.
  JURDAN/E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 17563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- B306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.

- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & 1-131 in Excess of NRC Limits," Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103) 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- B307220285 Ack receipt of B30616 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-498/83-02 & 50-499/83-02 Supplemental info requested within 30 days.

  MADSEN.G.L. Region 4. Office of Director. B3/07/18 OPREA.G.W. Houston Lighting & Power Co. 3pp. 19684:142 24X

  Fiche: 50-498/83/07/18/8307220285.
- --8307220392 Responds to NRC 830518 ltr re violations noted in IE lnsp Repts 50-498/63-02 & 50-499/83-02 Corrective actions: hardness test data sheets & personnel training records retrieved & available at site. DPREA.G.W. Houston Lighting & Power Co 83/06/16. COLLINS.J.T. Region 4, Diffice of Director. &pp 19684:145. 24X Fiche: 50-498, 83/07/18, 8307220285.
- S. Reportable occurrences, LERs & related correspondence
- 8307060268 Final deficiency rept re voltage requiation problem for ESF 4160/480-volt Class IE load ctr transformers. Initially reported on 830419. Transformers will be replaced w/new transformers wildower impedance based on sys requirements. OPREA. G. W. Houston Lighting & Pawer Co. 83/06/29. COLLINS, J. T. Region 4. Dffice of Director. 4pp. 19238:281. 24X Fiche: 50-498,83/06/29,8307060268.
- B307080476 Final deficiency rept re triaxial cable mfg by Rockbestos used in electrical penetrations supplied by Westinghouse. Initially reported on Bi1026. Cable R55-6-108 will be used as replacement. Also reported per Part 21. OPREA.6.W. Houston Lighting & Power Co. B3/06/30. COLLINS. J. T. Region 4. Office of Director. 3pp. 19346:325. 24x Fiche: 50-498.83/06/30.8307080476.
- B307250465 Final deficiency rept re flashovers/failures of nonsafety-related insulators. Initially reported on B30616. Insulators either coated w/grease or replaced. Insulators will be replaced w/different design.

  OPREA.G.W. Houston Lighting & Power Co. B3/07/13. COLLINS.J.T. Region 4. Office of Director. 4pp. 19701.241. 24X
  Fiche: 50-498.83/07/13.8307250465.
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNII 3 A. Application/construction stage documents & correspondence
- B307040255 Forwards responses to NRC B30404 Questions 210.14-20 re use of ITT Grinnell pipe clamps.
  BCUCHEY, G. D. Washington Public Power Supply System. B3/04/15.
  KNIOHTON, G. W. Licensing Branch 3. 9pp. 19248.001. 24X
  Fiche: 50-508, B3/04/15, B307040255.
- --8307060260 "Testing of Size 2A Figure 215 Stiff Clamp Oven-Heated to 870 F. B. Strang of Street, 1996 E. Strangs of Street, 1997 E. Strangs of Strangs of Street, 1997 E. Strangs of Strangs of
- 8307050270 Forwards marked-up FSAR pages for incorporation into amend to show conformance w/SRP (NUREG-0800).
  BOUCHEY. G. D. Washington Public Power Supply System. B3/06/16.
  KNIGHTON, G. W. Licensing Branch 3. lipp 19199.
- 8307080324 Requests formal approval of provisions of Subarticle NE-5230 of Winter 1982 addenda of ASME Boiler & Pressure Vessel Code. Section III re exam of inacressible welds attaching electrical assemblies to vessel nozzles BOUCHEY. 6.D. Washington Public Power Supply System. 83/06/28 KNIGHTON, G.W. Licensing Branch 3. Ip. 19330:149. 24X Fichs: 50-508.83/06/28,8307080324. 83/06/28
- B306270397 Generic Ltr 83-26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05.8306270397.
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl.

  EISENHUT. D. G. Division of Licensing 83/07/06. Consolidated Edison Co. of New York Inc. 16pp. 19669.254 24%

  Fiche: 50-000,83/07/06,8307060329.

- B30721021B Forwards game harvest data, list of species, bald eagle sitings, acoustic tracking program. NPDES permit. FES CP suppl. Grays Harbor fisheries mgt program fisheries harvest/stocking data & sport fishing regulations. W/o encl. MILLSM.E. Washington. State of 83/07/07. VIETTI.A. Licensing Branch 3: 2pp 19669:047. 24X Fiche: 50-508. 83/07/07, 830721021B.
- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. ETSENMUT.D. G. Division of License. B3/07/08 Consolidated Edison Co of New York, Inc. 38pp 19269-269. 24x Fiche: 50-000, B3/07/08, B307080169.
- 8307190390 Notification of 830719 meeting w/util in Bethesda.MD to discuss status of licensing ectivities. VIETTLA Licensing Branch 3. 83/07/08. MNIGHTON.G.W. Licensing Branch 3. 3pp. 19643:360. 24x Fiche:50-508.83/07/08.8307190390.
- 8307140464 Forwards util recent telecopy to NRC advising of immediate coast delay until assured source of funding for continued coast obtained.

  REYNOLDS: N.S. Debevoise & Liberman. REYNOLDS: N.S. Hashington Public Power Supply System. 83/07/12. MARGULIES: M., CARPENTER. J. H., SHON. F. J. Atomic Safety and Licensing Board Panel. 1p. 19521-239. 24x Fiche: 30-508, 83/07/12. 8307140464.
- 8307180059 Advises of 30-day const slowdown until assured source of funding obtained. Detailed implementation plan expected by 830801. SORENSEN.G.C. Washington Public Power Supply System. 83/07/12. DENTON.H.R. Division of
- 8307280356 Discusses util erecutive board 830708 vote to implement immediate extended const delay of facility due to financial difficulties. Plan being developed to assure delay activities conform w/NRC requirements & licensee conditions.

  DOBSIGN, D. E. Washington Public Power Supply System. 83/07/13.

  STERNSERG, D.M. Region 5, Office of Director 1p. 19790:117. 24X

  Fiche: 50-508.83/07/13,8307280356.
- 8307250135 Forwards update to 830615 response to NRC B30404 request for addt info re use of ITT Grinnell pipe clamps. Results indicate localized pipe wall stresses reduced. B300CHEV.G.D. Washington Public Power Supply System. 83/07/19. KNICHTON.G.W. Licensing Branch 3. 2pp. 19706:095. 24X Fiche: 50-508.83/07/19.8307250135
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B307220115 Forwards request for add1 info on safety review of hydrologic engineering Draft SER will be prepared following review of responses to support closeout of open items. Responses requested by B30812.
  KMIGHTON.G.W. Licensing Branch 3. 83/07/08. MAZUR.D.W. Washington Public Power Supply System. 9pp. 19692:330. 24x
  Fichs: 50-508,83/07/08,8307220115.
- 8307220415 Forwards responses to NRC safety evaluation of OL application. W/17 oversize drawings Aperture cards are available in PDR. SORENSBON. 6. C. Washington Public Power Supply System. 83/07/15. KN19HTON. 6. W. Licensing Branch 3. 361pp. 19686: 214. 24X Fiche: 50-508.83/07/15.8307220415.
- F. Security, medical, emergency & fire protection plans
- 8307110317 Releases public version of revised emargency preparedness plan. FELTON, J. M. Division of Rules and Records. 83/06/24. Document Management Branch. 1p. 19384:257 24x Fiche: 50-397,83/06/24. 8307110317.
- --8307110321 Public version of Rev 3 to emergency preparedness plan consisting of drawings of backup emergency operations facilities at util headquarters in Richland MA M/830616 ltr. BOUCHEY.O.D. Mashington Public Power Supply System. 83/04/30. NOVAK.T.M. Assistant Director for Licensing. 4pp. 19384:258. 24X Fiche: 50-397.83/06/24.8307110317.
- B307130310 Forwards "Control Room Design Review Program Plan for WPPSS Nuclear Project 3," per Generic Ltr B2-33 (NUREG-0737, Suppl 1) re emergency response capability, NUREG-0700 & NUREG-0801.
  BBUCKEY, G B. Washington Public Power Supply System. B3/07/12.
  KNIGHTUN.G W. Licensing Branch 3. 1p 19538:121. 24X
  Fiche: 50-508, B3/07/12, B307150310.
- --B307180318 Procedure WMM-025 "Control Room Design Review Program Plan For WPPSS Nuclear Project 3." \* Washington Public Power Supply System 83/07/12. 117pp 19538-122. 24X Fiche 50-508,83/07/12,8307150310.

## G. Adjudicatory correspondence

- B305100420 Submits schedule for submission of proposed contentions by petitioner & subsequent responsive filings of other parties & time & place for holding special prehearing conference. Montesano. HA recommended Certificate of Svc encl REYNOLDS, N. S. Washington Public Power Supply System. REYNOLDS, N. S. Debevoise & Liberman. B3/05/05. Spp. 18410:316. 24X Fiche: 50-508, 83/05/05, 8305100420.
- B307080437 Response opposing Coalition for Safe Power suppl to petition to intervene & request for hearing.Contentions fail to specify bases Certain contentions impormissibly vague. Certificate of Svc enci.
  REYNOLDS, N. S. Washington Public Power Supply System. REYNOLDS, N. S. Debevoise & Liberman. 83/07/06. Atomic Safety and Licensing Board Panel. 140pp. 19347:018. 24X Fiche: 50-508, B3/07/06, 8307080437.
- 8307110236 Response opposing Coalition for Safe Power contentions in supplemental petition to intervene. Intervenor status should be denied Certificate of Svc encl.
  REYNOLDS,N.S. Washington Public Power Supply System. REYNOLDS,N.S. Debevoise & Liberman. 83/07/06. Atomic Safety and Licensing Board Panel. 140pp. 19379:238. 24% Fiche: 50-508,83/07/06,8307110236.
- 8307130085 Response to Coalition for Safe Power B30615 supplemental petition to intervene delineating contentions. Opposes admission of Contentions 1, 2, 3, 3, 6, 8, 9, 10, 11, 14, 15 & 16, Notices of appearance & Certificate of Svc encl. ROTHSCHILD, M. U., BACHMANN, R. G. Hearing Branch 1. B3/07/11. Atomic Safety and Licensing Board Panel. 24pp. 19507:352, 24X Fiche: 50-508, 83/07/11, 8307130085.
- 8307140464 Forwards util recent telecopy to NRC advising of immediate const delay until assured source of funding for continued const obtained.

  REYNOLDS, N. S. Debevoise & Liberman. REYNOLDS, N. S. Hashington Public Power Supply System. B3/07/12. MARGULIES, M., CARPENTER, J. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 1p. 19521: 239. 24X Fiche: 30-508, 83/07/12, 8307140464.
- G. Inspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JGRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- B306270404 IE Info Notice B3-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8307130198 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-04.
  STERNBERG, D. M. Region 5, Office of Director. 83/07/12.
  LEDDICK, R. S. Washington Public Power Supply System. 2pp. 19530: 237. 24X Fiche: 50-508, 83/07/12, 8307150198.
- --8307150203 Responds to NRC 820413 ltr re violations noted in IE Insp. Rept 30-508/82-04. Corrective actions: Certificate of Conformance provided on 830418 & FSAR Table 3.2-1 re quality Class & items revised.

  LEDDICK.R.S. Washington Public Power Supply System. 83/06/08. STERNBERG.D.M. Region 5, Office of Director. 2pp. 19530:238. 24X Fiche: 50-508, 83/07/12, 8307150198.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 90-000, 83/07/14, 8306270406.
- DOCKET STN-30-509 WPPSS NUCLEAR PROJECT, UNIT 5

  E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8307220415 Forwards responses to NRC safety evaluation of OL application. W/17 oversize drawings. Aperture cards are available in PDR.
  SORENSON, G. C. Washington Public Power Supply System. 83/07/15.
  KNICHTON, G. W. Licensing Branch 3. 361pp. 19686: 214. 24X
  Fiche: 50-508, 83/07/15, 8307220415.

- DUCKET 30-513 WPPSS NUCLEAR PROJECT, UNIT 4
- Reportable occurrences. LERs & related correspondence
- 8307120241 Interim deficiency rept re Rockbestos cable. Initially reported on 820421. Further updates will be deferred until const completion schedule established or until const
  - restant Completion screenie established or until const restant De LORENZO, R. A. Washington Public Power Supply System. 83/06/29. STERNBERG, D. M. Region 5, Office of Director. 2pp. 19423:195. 24X fiche: 50-513,83/06/29,8307120241.
- 3307120499 Interim deficiency rept re emergency diesel generator starting air valve assembly mfg by Transamerica Delaval. Initially reported on 820618. Capscrew design revised. Next rept by const restart. Also reportable per Part 21. DE LORENZO, R.A. Washington Public Power Supply System. 83/06/29. STERNBERG, D. M. Region 5. Defice of Director. 2pp. 19425:021. 2 Fich &: 30-460.83/06/29.8307120499.
- 3307180034 Interim Deficiency Rept 2 re deformation in conductor insulation in Okonite cable. Sixteen 7/C-#12 cables will be removed & replaced. Six cables installed in raceway will be aband oned in place & replaced. Final rept by const restart. DE LOTENDURA. A Washington Public Power Supply System. 83/07/BTERNBERG.D.M. Region 5, Office of Director. 3pp. 19560:131 Fich 6: 50-460,83/07/01.8307180034.
- |307180144 Interim deficiency rept re problem w/top cover gaskets on NAMCO Model EA180 series switches. Problem traced to over—impregnated & insufficiently heat cured top cover gask ets. Also reported per Part 21.

  DE LORENZO, R. A. Washington Public Power Supply System. 83/07/01.

  STERNBERG, D. M. Region 5. Office of Director. 3pp. 17557:046. 24 83/07/01, 24X
- 307280297 Interim deficiency rept re emergency diesel generator current transformers. Initially reported on Biiii3, Norlake Mfg Co current transformer, Model CD 1408, selected to replace Westinghouse current transformer.

  DE LORENZO, R. Washington Public Power Supply System. 83/07/14.

  STERNBERG, D. M. Ragion 5, Office of Director. 3pp. 19790:118. 24X Fich #: 50-460, 83/07/14, 8307280299.
- 307280345 Final deficiency rept re Buffalo Forge fan housing missile protection. Initially reported on Bi0824. Unit 1 fans shipped to manufacturer for rework. Unit 4 fans not being modified.

  Nonconformance rept written.

  DE LORENZO, R.A. Washington Public Power Supply System. 83/07/18.

  STERNBERG, D.M. Region 5. Dffice of Director. 3pp. 19789:028. 24) Fiche: 30-460.83/07/18.8307280345.
- DCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1
- . App 1 1 cation/construction stage documents & correspondence
- 306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIBENH-UT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 30708O149 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649: 267. 24X Fiche: 30-000, 83/07/08, 8307080169.
  - Inspection reports. IE Bulletins & correspondence
- 306270401 IE Info Notice 83-46. "Common Mode Valve Failures Deprade Surry Recirculation Spray Subsystem." Svc list enci.
  JORDAN-E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York. Inc. 154pp. 19563:293. 24X Fiche: 50-000, 83/07/11. 8306270401.
- 106270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/07/12. Consolidated Edison Co. of New York. Inc. 14ipp. 19563:153. 24X Fithe: 50-000,83/07/12.8306270404.
- NO6270406 IE Info Notice 83-48, "Gaseous Effluent Releases o Radioactive I-125 & I-131 in Excess of NRC Limits." Syc lis encl. TAYLOR: J. M. enci. TAYLDR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.

- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x Fiche: 50-000,83/07/05,8306270397.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269 24x Fiche: 50-000.83/07/08.8307080169.
- Q. Inspection reports, IE Bulletins & correspondence
- 8304270401 IE Info Notice B3-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 1,54pp. 19563:293. 24X Fiche:50-000.83/07/11.8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B301031. 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83~48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Symptomics enc 1. TAYLOR: J. M. TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000,83/07/14,8306270406.
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- B306270395 Generic Ltr 83-24 to all BHR applicants for GL & holders of GLs for Grand Gulf, LaSalle & Susquebanna re TMI Task Action Plan Itom I.O.1, "Special Low Power Testing & Training & Recommendations for BHRs." Svc list encl EISENHUT, D. Q. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, 83/06/29. EISENHUT, D. Q. Divis Lighting Co. 26pp. 8306270395.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity. Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 14pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- S. Reportable occurrences, LERs & related correspondence
- B307120250 Second interim deficiency rept re nondivisional power received by transfer switches to auxiliary feedwater sys. Initially reported on B30202. Redundant circuits identical to existing design provided. Next rept expected by B30727. MLLS.L.M. Tennessee Valley Authority. B3706/27. 0'REILLY, J. P. flegion 2. Office of Director. 3pp. 19423:035. 24X Fiche: 50-000, B3706/27, B307120250.
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- S. Reportable occurrences. LERs & related correspondence
- B307120250 Second interim deficiency rept to nondivisional power received by transfer switches to auxiliary feedwater sys. Initially reported on B30202. Redundant circuits identical to existing design provided. Next rept expected by B30727. MILLS.C. M. Tennessee Valley Authority. B3/06/27. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19423:035. 24X Fiche: 50-000, 83/06/27, 8307120250.

- DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1 A. Application/construction stage documents & correspondence
- 8306270395 Ceneric Ltr B3-24 to all BMR applicants for OL & holders of OLs for Grand Gulf.LaSalle & Susquehanna re TMI Task Action Plan Item I.0.1. "Special Low Power Testing & Training & Recommendations for BMRs." Svc list encl. EISENHUT.D. 9. Division of Licensing. 83/06/29. Long Island Lighting Co. 24pp. 19384:115. 24X Fiche: 50-000.83/06/29. & Recommendations f EISENHUT, D. G. Divi Lighting Co. 24pp. 8306270375.
- 8306270397 Generic Ltr 83-26 to all applicants for CLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT.D.G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000,83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re survaillance intervals in STS Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidation Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060329. Consolidated
- B3070B0169 Generic Ltr B3-2B to all licensees of operating reactors, applicants for DL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 19669: 267. 24X Fiche: 50-000, 83/07/08, B3070B0169.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8307060482 Advises that schedule for issuance of FES will be made after choice of alternative licensing efforts or after prehearing schedule reestablished.
  EISENHUT.D.Q. Division of Licensing. 83/06/24. MYERS.R.V. Puget Sound Power & Light Co. 3pp. 19299:129. 24X Fiche: 50-522,83/06/24,8307060482.
- B3070B0342 Comments on proposed rule 10CFR30 re NRC policy statements on severe accidents & related views on nuclear reactor regulation.

  JIM.R. Yakima Indian Nation. B3/06/30. CHILK, S. J. Office of the regulation. JTM.R. Yakima Indian Nation. 83/06/30. CHILK.S.J. Office of the Secretary of the Commission. 2pp. 19350:327, 24X Fiche:50-522.83/06/30.8307080342.
- --B307080350 Comments on DES for Skapit/Hanford Nuclear Plant. EIS flawed in scope & content & fails to recognize existence of Yatima Indian Nation. No significant adverse impact addressed. Comment may not be used in proceeding.

  JIM.R. Yatima Indian Nation. B2/08/30. BLACK.R. NRC No Detailed Affiliation Given. 1p. 19350:343. 24X
  Fiche: 50-322.83/06/30,8307080342.
- 8307080435 Comments on proposed rules 10CFR50 & 51 re requirements for licensee actions on disposition of spent fuel upon expiration of DLs.

  JIM.R. Yakima Indian Nation. 83/06/30. CHILK.S. J. Office of the Secretary of the Commission. RATHBURN.D., MATTSDN.R.J. NRC No Detailed Affiliation Given. 2pp. 19347:001. 24X
  Fiche: 50-522, 83/06/30, 8307080435.

- --8307080440 Comments on DES for Skagit/Hanford Nuclear Plant.EIS flawed in scope & content & fails to recognize existence of Yakima Indian Nation. No significant adverse impact addressed Comment may not be used in proceedings.

  JIH.R. Yakima Indian Nation. 83/06/30. BLACK.R. NRC No Detailed Affiliation Given. 1p. 19347:017. 24X

  Fichs: 90-522,83/06/30,8307080435.
- 8307080445 Comments on NRC policy statement on evaluation plan for safety goal development program.

  JIM.R. Yatima Indian Nation. B3/06/30. CHILK, S. J. Office of the Secretary of the Commission. 2pp. 19347:205. 24X
  Fiche: 50-522,83/06/30,8307080445.
- --8307080452 Comments on DES for Skagit/Hanford Nuclear Plant. EIS flawed in scope & content & fails to recognize existence of Yatima Indian Nation. No significant adverse impact addressed. Comment may not be used in proceedings.

  JIM.R. Yakima Indian Nation. 83/06/30. BLACK.R. NRC No Detailed Affiliation Given. 1p. 19347:221. 24X

  Fiche: 50-522, 83/06/30, 8307080445.

- 8307190182 Concurs w/830624 proposal re issuance of FES. Schedule should be determined following selection of licensing alternative or after prehearing schedule reestablished. Svc list encl. MYERS.R.V. Puget Saund Power & Light Co. 83/07/12. EISENHUT.D. Q. Division of Licensing. 4pp. 19630:168. 24X Fiche: 30-522,83/07/12,8307190182.
- 8307210303 Concurs w/proposal in 830424 ltr re issuance of FE6. Schedule should be determined following selection of licensing alternative or after prehearing schedule reestablished. Svc list encl. Related correspondence.

  MYERG.R.V. Puget Sound Power & Light Co. 83/07/12, EISENHUT, D. Q. Division of Licensing. 4pp. 19665:064. 24X Fiche: 50-522, 83/07/12, 8307210303.
- Q. Inspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Proparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 194pp. 19963:273. 24X Fiche:50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid," Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:133. 24X Fiche: 50-000,83/07/12,8306270404. 141pp.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list ents. TAYLDR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of Naw York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2 A. Application/construction stage documents & correspondence
- 8306270395 Opneric Ltr 83-24 to all BMR applicants for OL & holders of OLs for Grand Gulf, LaSalle & Busquehanna re TMI Task Action Plan Item 1.9. i, "Special Low Power Testing & Training & Recommendations for BMRs." Sec list encl. EISEMHUY, D. O. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 30-000.83/06/29, 8306270395.
- 8306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of survaillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 17370:317. 24X Fiche: 50-000, 83/07/05, 8306270397.
- 8307040327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STB. Svc list encl. EISENHUT. D. G. Division of Licensing, 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24X Fiche: 50-000,83/07/06,8307060327.
- 8307080167 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Sec list encl. EIBENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 17649:267. 24X Fiche: 50-000, 83/07/08, 8307080169.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 8307060482 Advises that schedule for issuance of FES will be made after choice of alternative licensing efforts or after prehearing schedule restablished.

  EISENHUT, D. G. Division of Licensing. 83/06/24. MYERB, R. V. Puget Sound Power & Light Co. 3pp. 19299: 129. 24X Fiche: 30-522, 83/06/24, 8307060482.
- B307080342 Comments on proposed rule 10CFR30 rs NRC policy statements on severe accidents & related views on nuclear reactor regulation.

  JIK.R. Yakima Indian Nation. 83/06/30. CHILK.S.J. Office of the Secretary of the Commission. 2pp. 19350:327. 24X

  Fichs: 50-522,83/06/30.8307080342.

- 7080350 Comments on DES for Skagit/Hanford Nuclear Plant EIS flawed in scope & content & fails to recognize existence of waiting Indian Nation. No significant adverse impact addressed Comment may not be used in proceeding.

  JIM.R. Yakima Indian Nation. 82/08/30. BLACK.R. NRC No petalled Affillation Given. 1p. 19350: 343. 24X piche: 50-522,83/06/30.8307080342.
- B3070#30435 Comments on proposed rules 10CFR50 & 51 re requirements for 1 c ensure actions on disposition of spent fuel upon x p ration of CLs.

  \*\*X p ration of CLs.

  \*\*X p ration of the Commission. B3/06/30. CHILK, B. J. Office of the Secretary of the Commission. 2pp. 19347:001. 24X

  \*\*E retary of the Commission. 2pp. 19347:001. 24X

  \*\*Fiche: 50-522, B3/06/30. B3070B0435.
- 7080440 Comments on DES for Skagit/Hanford Nuclear Plant EIS flawed in scope & content & fails to recognize existence of wakima Indian Nation. No significant adverse impact dessed Comment may not be used in proceedings.

  JIM.R. Yakima Indian Nation. B3/06/30. BLACK.R. NRC No patailed Affillation Given. ip. 19347:017. 24X
- 8307080445 Comments on NRC policy statement on evaluation plan for sefecty goal development program.
  JIM. R. Yakima Indian Nation. 83/06/30. CHILK.S.J. Office of the Section of the Commission. 2pp. 19347:205. 24X Fiche: 50-522.83/06/30.8307080445.
- TO DESCRIPTION OF THE PROPERTY OF THE PROPERTY
- B30フ1 90182 Concurs w/830624 proposal re issuance of FES. Schedule should be determined following selection of licensing alternative or after prehearing schedule reestablished. Svc list encl. MYERS.R.V. Puget Sound Power & Light Co. 83/07/12. EISENHUT.D.O. Division of Licensing. 4pp. 19630:148. 24X Fiche: 30-322,83/07/12,8307170182.
- 8307210303 Concurs w/proposal in 830624 ltr re issuance of FEB. Schedule should be determined following selection of licensing allternatives or after prehearing schedule reestablished. 8vc list encl. Related correspondence.

  MYERS.R.V. Puget Bound Power & Light Co. 83/07/12. EISENHUT.D.O. Division of Licensing. 4pp. 19665:064. 24X Fiche: 50-522,83/07/12, B307210303.
- Q. In spection reports, IE Bulletins & correspondence
- 830&270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York。Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11.8306270401.
- 830もなアの404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.
  JORDAN,E.L. Division of Emergency Proparedness & Engineering Response (Post 930103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24x Fiche: 50-000,83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list #I-121 TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

  A. APPlication/construction stage documents & correspondence
- 8307070427 Requests add1 quantitative analysis to support 821230 conclusions refailure of E-NNN-D11 panel. Transient semarios bounded by FSAR Chapter 15 analyses. Notification Planned submittal date requested.

  NIOHTON. 9. W. Licensing Branch 3. 83/06/17. VAN BRUNT. E. E. Arizona Public Service Co. 3pp. 19300:178. 24X Fiche: 50-528.83/06/17.8307070427.
- B307070437 Forwards request for info on Tech Spec setpoint methodology.
  NO tification of planned response date requested.
  KHIGHTON.C.W. Licensing Branch 3. 83/06/20. VAN BRUNT.E.E.
  ATIZONA Public Service Co. 4pp. 19300:184. 24X
  FICH 8: 50-528.83/06/20.8307070437.

- B307070226 Comments on B30502 proposed revs to FSAR re component classification & scope of augmented inservice insp. Revs acceptable.

  KNIGHTON, G. H. Licensing Branch 3. B3/06/21. VAN BRUNT, E. E. Arizona Public Service Co. 3pp. 19344:351. 24X

  Fiche: 50-528.83/06/21, B307070226.
- 8307060012 Forwards proposed rev to FSAR.Section 1.8 re exceptions to Reg Quide 1.88 covering level concrete floor & roof in records storage facility.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/06/24. STERNBERG.D.M. Region 5. Office of Director. 7pp. 19238:235. 24X Fiche: 50-328.83/06/24.8307060012.
- 8307050026 Forwards response to 830415 request for addl info re solid waste process control program. Package waste will be segregated by container activity level into high level or low level storage area.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. XNIGHTON, G. Licensing Branch 3. 17pp. 19220:134. 24X Fiche: 50-528, 83/06/30, 8307050026.
- 8307050133 Advises that accelerated schedule date of 830731 for submittal of specific info re depressurization & DHR capabilities by 830731 supports NRC needs.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. KNIGHTON, G. Licensing Dranch 3. 2pp. 19220: 219. 24X Fiche: 50-528, 83/06/30, 8307050133.
- 8307050179 Responds to Generic Ltr 83-10A re resolution of TMI Action Item II.K. 3.5, "Automatic Trip of Reactor Coolant Pumps."
  Description for resolving item & plan & schedule for plant-specific activities encl.
  VAN BRUNT.E.E. Arizona Public Service Co. 83/06/30, KNIGHTON.G. Licensing Branch 3. 14pp. 19199:205. 24x Fiche: 50-528,83/06/30,8307050197.
- B306270397 Generic Ltr B3-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity Svc list encl. EISENHUT, D. Q. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000,83/07/05,8306270397.
- 8307060327 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 17669:254. 24X Fiche: 50-000, 83/07/06, 8307060327.
- B307150238 Forwards supplemental rept re piping sys design review as part of independent QA evaluation of facilities in response to questions resulting from B30602 meeting.

  SIMON.W.A. Torrey Pines Technology. B3/07/06. LICITRA.E. NRC No Detailed Affiliation Given. 17pp. 19539: 067. 24X

  Fiche: 50-528,83/07/06,8307150238.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl. EISENHUT, D. 0. Division of Licensing, 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19649:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 8307290183 Advises that barring unforeseen delays, Unit 1 should be ready for fuel loading by Nov 1983.

  VAN BRUNT. E.E. Artiona Public Service Co. 83/07/22. LICITRA, E.A. Licensing Branch 3. 2pp. 1982: 150. 24X Fiche: 50-528, 83/07/22, 8307290183.
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- 8307080637 Forwards request for add1 info & comments on SER Suppl 4 re revised emergency plan. Notification of submittal date requested. KNIGHTON, G. W. Licensing Branch 3. B3/06/20. VAN BRUNT, E. E. Anizona Public Service Co. App. 19364: 213. 24X Fiche: 50-528,83/06/20,8307080637.
- 8307050211 Responds to Nov 1981 SER, subsequent suppl & correspondence & Generic Ltr 82-33, Suppl 1 to NUREG-0737 requirements for amergency response capabilities. Human factors study & status rept re historical earthquake data encl.

  VAN DRUNT, E.E. Arizona Public Service Co. 83/06/30. KNIGHTON. G. Licensing Branch 3. 5pp. 19174:183. 24X Fiche:50-528,83/06/30,8307050211.
- --8307050228 Suppl 1 to QA-C16398 "Palo Verde Nuclear Generating Station Control Room Human Factors Study Executive Summary Rept."

  \* Torrey Pines Technology GA-C16398 S01 83/06/30 70pp.
  19194:189. 24X Fiche:30-528.83/06/30.8307050211.

- 830706036B Forwards responses to NRC findings of Power Sys site audit conducted on 830406-07.per SER.NUREO-0857.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/07/01. KNIGHTON.G. Licensing Branch 3. 11pp. 19236:228. 24X Fiche:50~528.83/07/01. B307060368.
- 8307110012 Forwards response to SER Section 7.7.2.Question 222.03 requalification of control sys.Response closes open item in Section 7.7.2 & will be incorporated into upcoming FSAR amend.

  VAN BRUNT.E.E. Artiona Public Service Co. 83/07/01. KNIGHTON.G. Licensing Branch 3. App. 19374:205. 24X Fiche:50-528.83/07/01.8307110012.
- 8307150363 Forwards corrected mag identifying reception & care ctrs. per 830615 request & Suppl 4 to SER re emergency plan. VAN BRUNTLE. Arizona Public Service Co. 83/07/08, KNIGHTON, C. Licensing Branch 3. 3pp. 17538:350. 24% Fiche:50-528,83/07/08,8307150363.
- 8307140374 Responds to Har 1983 SER (NUREG-0857) request for add1 info re emergency plan, External ltrs of agreement ancl. Info adequately responds to request. VAN BRUNT, E. E. Arizona Public Service Co. 83/07/12. KNIGHTON, Q. Licensing Branch 3. 19pp. 19523: 335. 24X Fiche: 50-528, 83/07/12, 8307140374.
- F. Security, medical, emergency & fire protection plans
- 8307050498 Notification of 830622 meeting w/util & NUSAC in Silver Spring.MD to discuss proposed substitute security plan. LICITRA.E.A. Licensing Branch 3. 83706/20. KNIGHTON.G.W. Licensing Branch 3. 3pp. 19262:276, 24X Fiche:50-528.83/06/20.8307050498.
- B307080637 Forwards request for add1 info & comments on SER Suppl 4 re revised emergency plan. Notification of submittal date requested. KNIGHTON, O. M. Licensing Branch 3. B3/06/20. VAN BRUNT, E. E. Arizana Public Service Co. 6pp. 19364:213. 24X Fiche:30-328.83/06/20.8307089637.
- B307050211 Responds to Nov 1981 SER, subsequent suppl & correspondence & Genetic Ltt B2-33, Suppl 1 to NUREO-0737 requirements for emergency response capabilities. Human factors study & status rept re historical earthquake data encl.
  VAN BRUNT.E. E. Arizona Public Service Co. B3/06/30, KNIOHYON, G. Licensing Branch 2, 5pp. 19194:183, 24x Fiche: 50-52B, 83/06/30, B307050211.
- 8307190363 Forwards corrected map identifying reception & care ctrs, per 830615 request & Suppl 4 to SER re emergency plan. VAN BRUNTLE. Arizona Public Service Co. 83/07/08. KNIGHTON, G. Licensing Branch 3. 3pp. 19538:350. 24X Fiche:50-528,83/07/08,8307150363.
- 9307140374 Responds to Mar 1983 SER (NUREG-0857) request for add1 infors emergency plan. External litrs of agreement enci. Info adequately responds to request. VAN BRUNT.E.E. Arizona Public Servica Co. 83/07/12. KNIGHYON, O. Licensing Branch 3. 19pp. 19523:335. 24% Fiche: 50-528,83/07/12. 8307140374.
- 8307200117 Summarizes tignificant changes being incorporated in Rev 3 to emergency plan, including organizational control of emergencies, emergency conditions & emergency facilities & equipment. Rev 3 will be submitted by 830815.
  VAN SRUTT.E.E. Arizona Public Service Co. 83/07/14. KNIQHTON, G. Licensing Branch 3. 7pp. 19647: 156. 24% Fiche: 50-528, 83/07/14, 8307200117.
- 3307190190 Forwards "Emergency Procedure Generation Package," per requirements of Suppl 1 to NUREG-0737. VAN BRUNT,E.E. Arizona Public Service Co. 83/07/15. KNIOHTON.O, Litensing Branch 3. 2pp. 19630:192. 24X Fiche:50-528.83/07/15. 8307190190.
- --8307190194 "Emergency Procedure Generation Package." \* Arizona Public Service Co. 83/07/15. 211pp. 19631:001. 24X Fiche:50-528,83/07/15,8307190190.
- Utility Final Safety Analysis Report (FSAR) & amends
- 3307190223 Forwards Proof of Svc of Amend 11 to FSAR.

  VAN BRUNTIE.E. Arizona Public Service Co. 83/07/15. KNIGHTON.G.W.
  Licensing Branch 3. 3pp. 19629: 225. 24X Fiche: 50-528.83/07/15,
  8307190223.

- G. Inspection reports: IE Bulletins & correspondence
- 8307120558 Forwards IE Insp Repts 50-528/83-22, 50-529/83-12 & 50-530/83-09 on 830523-07. No noncompliance moted. STERNBERG, D. M. Region 5. Office of Director. 83/06/20. VAN BRUNT, E.E. Arizona Public Service Co. 2pp. 19431: 329. 24X Fiche: 50-528, 83/06/20, 8307120558.
- --8307120568 IE Insp Repts 50-528/83-22,50-529/83-12 & 50-530/83-09 on 830583-27. No noncompliance noted Major areas inspected: allegations re electrical activities & tendon prestressing activities & action on previous insp findings.
  NARBUT.P.P. BURDDIN.J.F. YOUNG.T. Region 4: Office of Director, 83/06/17. 16pp. 19431:331. 24x Fiche:50-528,83/06/20,8307120558.
- 8307070226 Comments on 830502 proposed rovs to FSAR re component classification & scope of augmented inservice insp. Revs acceptable.

  KNIGHTON G. W. Licensing Branch 3. 83/06/21. VAN BRUNT, E. E., Arizona Public Service Co. 3pp. 19344:351. 24X
  Fiche: 50-528, 83/06/21, 83070707226.
- 8307120560 Forwards IE Insp Rept 50-528/83-13 on 830503-06 & 10-13 & notice of violation.
  STERNBERG, D. M. Region 5, Office of Director. 83/06/23, ANDBONINI, G. C. Artrona Public Service Co. 2pp. 19433:088. 24X Fiche: 50-528, 83/06/23, 8307120560.
- --9307120564 Notice of violation from insp on 830503-06 & 10-13, YOUNG,T. Region 5, Office of Director. 83/06/23. ip, 19433:090, 24X Fiche: 50-528, 83/06/23, 8307120560.
- --8307120570 IE Insp Rept 50-528/83-15 on 830503-06 & 10-13.Noncompliance noted:issuance of Administrative Procedure 70AC-07202 delayed until 830505.

  JOHNBON.P. H., YOUNG. T. Region 5, Office of Director. 83/06/22.

  7pp. 19433:091. 24X Fiche:50-528,83/06/23,8307120560.
- 8307120541 Forwards IE Insp Repts 50-528/83-23,50-529/83-13 & 50-530/83-10 on 830502-0603. No noncompliance noted. STERNBERG. D. M. Region 5. Office of Director. 83/06/27. VAN BRUNT. E.E. Arizona Public Service Co.: 2pp. 19433:348. 24% Fiche: 50-528,83/06/27,8307120541.
- ---8307120549 IE Insp Repts 50-528/83-23,50-529/83-13 & 50-530/83-10 on 830502-0603. No noncompliance noted. Major areas inspected: const activities re followup of allegations of unacceptable electrical work & followup of previous insp items. VORDERBRUEGOEN, YOUNG-T. Region 5, Office of Director. 83/06/22. Spp. 19433:350. 24X Fiche:30-528,83/06/27.8307120541.
- 8307260291 Informs that final response to 830525 notice of noncompliance from insp on 830301-0430 will be delayed until 830725 due to extensive investigation & evaluation required. VAN BRUNT, E. E. Arizona Public Service Co. 83/06/27. STERNBERO, D. M. Region 5, Office of Director. ip. 19726; 213. 24X Fiche: 50-528, 83/06/27, 8307260291.
- 9307060408 Forwards IE Mgt Meeting & SALP Repts 50-528/83-16; 50-529/83-09 & 50-530/83-07 on 830525. No noncompliance noted. MARTIN, J. B. Region 5, Office of Director. 83/06/30. HOODS: T. C. Aritone Public Service Co. 2pp. 19237:010, 24X Fichs: 50-528, 83/06/30, 8307060408.
- --8307060416 IE Mgt Meeting Repts 50-528/83-16,50-529/83-07 & 50-530/83-07 on 830525. No noncompliance noted Major areas discussed: results of Region V assessment of licensee performance for Jul 1981 Feb 1983.

  JOHNSON, P. H., YOUNO, T. Region 5. Office of Director. 83/06/24, 2pp. 19237:012. 24X Fiche: 50-528,83/06/30,8307060408.
- --8307060420 BALP Repts 80-528/83-16,50-529/83-07 & 50-530/83-07 for Jul 1961 Feb 1983 Overall performance acceptable.
  \* Region 5. Office of Director. 83/04/30. 32pp. 19237:014. 24X Fiche: 50-528.83/04/30,8307060408.
- --8307060426 Confirms comments on SALP repts for Jul 1981 Feb 1983.per 830525 meeting to review program results. Onal comments listed & discussed Mgt & GA activities will be amphasized to assure that electrical equipments meets FBAR criteria. WQDDS.T.G. Arizona Public Service Co. 83/06/10. MARTIN.J.B. Region 5. Office of Director. 4pp. 19237:047. 24X Fiche: 50-528.83/06/30.8307060408.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDANE L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563: 293. 24X Fiche: 50-000, 83/07/11, 8306270401.

Sec.

- B306270404 IE Info Notice B3-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:193. 24X Fiche: 50-000, B3/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 % I-131 in Excess of NRC Limits." Svc list encl. TAYLOR, J. M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Ficha: 50-000,83/07/14,8306270406.
- 8. Reportable occurrences, LERs & related correspondence
- 8307060323 Final Deficiency Rept DER 83-11 re potential oxide battery leak or corrosion at terminals due to cracked plastic seals/covers. Initially reported on 830228. Batteries will be repaired. Deficiency not reportable per 100FR95. 55(e). VAN BRUNT, E. E. Arizona Public Service Co. 83/06/14. STERNBERG, D. M. Region 5, Office of Director. 9pp. 19239:168. 24X Ficha: 50-528. 83/06/14. 8307060323.
- 8307060013 Final Deficiency Rept DER 82-50 re flexible conduit couplings between auxiliary & control bidgs which may be damaged if seismic event exceeds 3/4-inch movement. Item determined not reportable under 105FR30. 55(e) requirements. VAN BRUNTLE E. Arizona Public Service Co. 83/06/17. STERNDERO, D. P. Region 5. Dffice of Director. 3pp. 19250:001. 24X Fiche: 50-528, 63/06/17, 8307060013.
- ---8307060025 "Evaluation of Electrical Conduit Connections Between Auxiliary & Control Bidgs for Arizona Public Svc Palo Verde Nuclear Generating Station."
  WILBON, S. W., PAZARGADI, S., BAUSCH, H. P. Wyle Laboratories, 26406-1. 83/03/31. 134pp. 17230:004. 24X Fiche: 50-528,83/06/17,8307060013.
- 8307060046 Interim Deficiency Rept DER 83-32 re use of dissimilar metal socket welds in steam generator process piping. Initially reported on 830525. Final rept expected by 830807.

  VAN BRUNT, E. E. Arizona Public Service Co. 83706/24. STERNBERG, D. M. Region 5. Office of Director. 4pp. 17250: 286. 24X

  Fiche: 30-528,83706/24,8307060046.
- B307060379 Interim Deficiency Rept DER 82-96 re scaling-down condensate storage tank design w/o new calculations. Initially reported on 821015 Submittal of final rept extended to 830727.

  VAN BRUNT, E. E. Arizona Public Service Co. B3/06/27. STERNBERG, D. M. Region 5. Office of Director. 2pp. 19236: 062. 24X

  Fiche: 50-528, 83/06/27, 8307060379.
- B307120366 Final Deficiency Rapt DER 82-63 re design calculation error in refueling water tank seismic response. Initially reported on B21026. Deficiency not reportable per iOCFR50. 35(e). Bechtel independent analysis of calculations encl. VAN BRUNT.E.E. Arizona Public Service Co. B3/06/27. STERNBERO, D. M. Region 5. Office of Director. 32pp. 17429:048. 24X Fiche: 50-528.83/06/27.8307120366.
- --8307120377 Rev 1 to "Engineering Evaluation for Design of Condensate Water Storage Tank & Refueling Water Tank, Palo Verde Nuclear Generating Station," for Deficiency Evaluation Repts 82-56 & 82-63.
  LIMAYE, G.S., HUGHES, M.R., BERGGUIST, S. H. Bechtel Corp. 83/05/31.
  28pp. 19429:052. 24X Fichs: 50-528, 83/06/27, 8307120366.
- 8307120530 Interim Deficiency Rept DER 82-53 re failed Joy fan blade causing 2-inch penetration of containment liner plate. Initially reported on 820724. Final rept delayed until 830827, pending extensive investigation.

  VAN BRUNT.E.E. Arizona Public Bervice Co. 93/06/29. STERNBERG, D. M. Region 3, Office of Director. 2pp. 19433:308. 24X Fiche: 50-528, 83/06/29, 8307120530.
- 8307180221 Interim Deficiency Rept DER 83-25 re instrumentation tubing not having required boundary class break Initially reported on 830421 Due to extensive investigation & evaluation, completed repts expected by 830817.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/07/01. STERNBERG, D. M. Region 5, Office of Director. 2pp. 19555:225. 24X Fiche: 50-528,83/07/01,8307180221.
- 8307280313 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pipe line failure in essential cooling water sys Initially reported on 820910. No new info or change to interim rept. Final rept will be submitted by 830816. VAN BRUNT, E. E. Arizona Public Service Co. 83/07/06. STERNBERG, D. M. Region 5. Office of Director. 2pp. 19789:215. 24X Fiche: 50-528,83/07/06,8307280313.

- 8307280348 Interim Deficiency Rept DER 83-35 re Elgar inverters producing voltage spikes on dc supply bus Initially reported on 830607. Add1 inverter tests requested to reduce or eliminate voltage spikes. Final rept by 831031.

  VAN BRUNT.E.E. Ariona Public Service Co. 83/07/07. STERNBERO, D. M. Region 5. Office of Director. 3pp. 19789.015. 24X Fiche: 50-528.83/07/07.8307280348.
- 8307180081 Part 21 rapt clarifying position re equipment failures during C-E qualification testing of Target Rock solenoid activated valves per T Lee 830620 request Valve design conforms to NUREG-0588. Retrofit program supported PATTARINI.D. M. Target Rock Corp. 83/07/11. DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement. 1p. 19560:007. 24% Fiche:50-528.83/07/11.8307180081.
- 8307280306 PND-V-83-027: on B30718; during preparation for repairs on reactor contant pumps 1A & 1B; three bolts which hold diffusor clamp ring discovered missing & all bolts toose & 15% of impeller vanes missing. FIDRELLI, G., YOUNG, T. Region 5, Office of Director, 83/07/19, 19789: 210. 24% Fiche: 50-528; 83/07/19; 8307280306.
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- B307070427 Requests add1 quantitative analysis to support 821230 conclusions re failure of E-NNN-D11 panel. Transient scenarios bounded by FSAR Chapter 15 analyses. Notification of planned submittal date requested.
  KNIOHTON, G.W. Licensing Branch 3. 83/06/17. VAN BRUNT, E.E. Arisona Public Service Co. 3pp. 19300:178. 24X
  Fichs: 50-528,83/06/17,8307070427.
- 8307070437 Forwards request for info on Tech Spec setpoint methodology. Notification of planned response date requested. KNIGHTON, G. M. Licensing Branch 3. 83706/20. VAN BRUNT, E. E. Arizona Public Service Co. 4pp. 19300: 184. 24X Fiche: 50-528, 83/06/20, 8307070437.
- B307070226 Comments on B30502 proposed revs to FSAR re component classification & scope of augmented inservice insp. Revs acceptable.

  KNIGHTON, G. W. Licensing Branch 3. B3706/21. VAN BRUNT, E. E. Arizona Public Bervice Co. 3pp. 19344: 351. 24X
  Fiche: 50-528, B3706/21, B307070226.
- 8307060012 Forwards proposed rev to FSAR, Section 1. B re exceptions to Reg Ouide 1.88 covering level concrete floor & roof in records storage facility.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/24. STERNBERG, D. M. Region 5. Office of Director. 7pp. 19238: 255. 24X Fiche: 50-528, 83/06/24, 8307060012.
- 8307050026 Forwards response to 830415 request for add1 info re solid waste process control program. Package waste will be segregated by container activity level into high level or low level storage area.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. XNIGHTON, O. Licensing Branch 3. 17pp. 19220:134. 24X Fiche: 50-528, 83/06/30, 8307050026.
- B307050133 Advises that accelerated schedule date of B30731 for submittal of specific info re depressuritation & DHR capabilities by B30731 supports NRC needs. VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. KNIGHTON, G. Licensing Branch 3. 2pp. 19220; 219. 24X Fiche: 50-528, B3/06/30, B307050133.
- 8307050199 Responds to Generic Ltr 83-10A re resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps."

  Description for resolving item & plan & schedule for plantspecific activities encl.

  VAN ORUNT, E. E. Arizona Public Service Co. 83/06/30. KNIGHYON, G. Licensing Branch 3. 14pp. 19199:205. 24X Fiche:50-328,83/06/30, 8307050199.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for dissel fuel impurity, Svc list encl. EIBENHUT, D.G. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50~000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS.8vc list encl. EISENMUT.D. 0. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York, Inc. 16pp. 19669: 254. 24X Fiche: 50-000, 83/07/06, 8307060329.

- 830715023B Forwards supplemental rept re piping sys design review as part of independent QA evaluation of facilities in response to questions resulting from 830602 meeting.

  SIMON,W.A. Torrey Pines Technology, 83/07/06. LICITRA,E. NRC No Detailed Affiliation Given. 17pp. 19539:067. 24X

  Fiche: 50-528,83/07/06,8307150238.
- B3070B0169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENMUT. D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 3Bpp. 19669:269. 24X Fiche: 30-000, 83/07/08, 8307080169.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B307080637 Forwards request for add1 info & comments on SER Suppl 4 re revised emergency plan. Notification of submittal date requested.

  XNIOHTON, G. W. Licensing Branch 3. 83/06/20. VAN BRUNT, E. E. Arisona Public Service Co. 6pp. 19364:213. 24X Fiche: 30-528, 83/06/20, 8307080637.
- 8307050211 Responds to Nov 1981 SER, subsequent suppl & correspondence & Generic Ltr 82-33. Suppl I to NUREG-0737 requirements for emergency response capabilities. Human factors study & status rept re historical earthquake data encl.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/06/30. KNIGHTON, G. Licensing Branch 3. Spp. 19194: 183. 24X Fiche: 50-528, 83/06/30, 8307050211.
- --8307030228 Suppl 1 to 0A-C16398 "Palo Verds Nuclear Generating Station Control Room Human Factors Study, Executive Summary Rept." \* Yorrey Pines Technology. GA-C16398 S01. 83/06/30. 70pp. 19194:189. 24X Fiche: 50-528, 83/06/30, 8307050211.
- B30706036B Forwards responses to NRC findings of Power Sys site audit conducted on B30406-07.per SER, NUREO-0857.

  VAN BRUNT, E. E. Arizona Public Service Co. B3/07/01. KNIOHTDN, O. Licensing Branch 3. 11pp. 19236: 228. 24X Fiche: 50-528, B3/07/01, B307060368.
- 8307110012 Forwards response to SER Section 7.7.2, Question 222.03 requalification of control sys.Response closes open item in Section 7.7.2 & will be incorporated into upcoming FSAR amend.

  VAN BRUNT, E. E. Artiona Public Service Co. 83/07/01. KNIGHTDN, G. Licensing Branch 3, 6pp. 19374:205. 24X Fiche:50-528,83/07/01,8307110012.
- 8307190363 Forwards corrected map identifying reception & care ctrs, per 830615 request & Suppl 4 to SER re emergency plan.

  VAN BRUNT.E. Arizona Public Service Co. 83/07/08. KNIGHTON.G. Licensing Branch 3. 3pp. 19538:350. 24X Fiche: 50-528,83/07/08,8307150363.
- B307140374 Responds to Mar 1983 SER (NUREG-0887) request for add1 info re emergency plan. External ltrs of agreement encl. Info adequately responds to request. VAN BRUNT, E. E. Arizona Public Service Co. B3/07/12. KNIOHTON, G. Licensing Branch 3. 19pp. 19523:335. 24X Fiche: 50-528, B3/07/12, B307140374.
- F. Security, medical, emergency & fire protection plans
- B307050498 Notification of B30622 meeting w/util % NUSAC in Silver Spring.MD to discuss proposed substitute security plan. LICITRA.E.A. Licensing Branch 3. 83/06/20. KNICHTON.O.W. Licensing Branch 3. 3pp. 19262:276. 24X Fiche: 50-528.83/06/20. 8307050498.
- B3070B0637 Forwards request for add1 info & comments on BER Suppl 4 re revised emergency plan. Notification of submittal date requested. KRIOHTON, G. W. Licensing Branch 3. 83/06/20. VAN BRUNT, E. E. Arizona Public Service Co. App. 19364:213. 24X Fiche:30-328,83/06/20,83070B0637.
- B307030211 Responds to Nov 1981 BER, subsequent suppl & correspondence & Generic Ltr 82-33, Suppl 1 to NUREO-0737 requirements for amergency response capabilities. Human factors study & status rept re historical earthqueke data encl.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. KNIGHTON, G. Licensing Branch 3. 5pp. 19194: 183. 24X Fiche: 50-528, 83/06/30, 8307050211.
- B307150363 Forwards corrected map identifying reception & care ctrs, per B30615 request & Suppl 4 to SER re emergency plan.

  VAN BRUNT. E. Arizona Public Service Co. B3/07/08. KNIGHTON. G. Licensing Branch J. 3pp. 19538:350. 24X Fiche:50-528,83/07/08, B307150363.

- 8307140374 Responds to Mar 1983 SER (NUREG-0857) request for addl info re emergency plan External ltrs of agreement encl. Info adequately responds to request. VAN BRUNT.E.E. Arizona Public Service Co. 83/07/12. KNIGHTON, Q. Licensing Branch 3. 19pp. 19523:335. 24X Fiche: 50-528,83/07/12, 8307140374.
- 8307200117 Summarizes significant changes being incorporated in Rev 3 to emergency plan including organizational control of amergencies, remergency conditions & emergency facilities & equipment Rev 3 will be submitted by 830815.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/07/14. KNIGHTON, O. Licensing Branch 3. 7pp. 19647:156. 24X Fiche: 50-528,83/07/14,8307200117.
- B307190190 Forwards "Emergency Procedure Opnoration Package," per requirements of Suppl I to NUREG-0737. VAN BRUNTIE.E. Aritons Public Service Co. B3/07/15. KNIGHTON.G. Licensing Branch 3. 2pp. 19630:192. 24X Fiche:50-528,83/07/15, B307190190.
- --8307190194 "Emergency Procedure Generation Package." \* Arizona Public Service Co. 83/07/15. 211pp. 19631:001. 24X Fiche: 50-528,83/07/15,8307190190.
- Adjudicatory correspondence
- 8307050244 Supplemental answers to interrogatories.
  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  83/06/29. Arisona Public Service Co. 10pp. 17199:061. 24X
  Fiche:30-327.83/06/29.8307050244.
- --8307050247 Motion for protective order against Joint Applicants & NRC interrogatories requesting info on West Valley Agricultural Protection Council, Inc members, acreage, crop yields & profits.

  BERLIN, K. West Valley Agricultural Protection Council, Inc. 83/06/29. Atomic Safety and Licensing Board Panel. 2pp. 19199:072. 24X Fiche: 50-529, 83/06/29, 8307050244.
- --8307050251 Memorandum supporting West Valley Agricultural Protection Council motion for protective order Guestion relates to potential salt damage to area crops not Council member crops Certificate of Svc encl.

  BERLIN.K. West Valley Agricultural Protection Council, Inc. 83/06/29. Atomic Safety and Licensing Board Panel. 6pp. 19199: 074. 24X Fiche: 50-529, 83/06/29, 8307050244.
- 8307060151 Responses to Wast Valley Agricultural Improvement Council, Inc requests for production of documents. Certificate of Svc encl.
  CRAMFORD, V. A. Joint Applicants-Palo Verde. CRAWFORD, V. A. Snell & Wilmer. 83/07/10. West Valley Agricultural Protection Council, Inc. 4pp. 19230:201. 24X Fiche: 50-527,83/07/01,8307060151.
- 8307060156 Supplemental response to West Valley first & second sets of interrogatories. Certificate of Svc encl. CRAWFORD, V.A. Joint Applicants-Palo Verde. CRAWFORD, V.A. Snell & Wilner. 83/07/01. West Valley Apricultural Protection Council, Inc. 4pp. 19250:156. 24x Fiche: 50-529, 83/07/01, 8307060156.
- 8307120572 Memorandum & order denying West Valley Agricultural Protection Council B30202 & 0506 motions for declaration that NEPA analysis inadequate & for continuance. PL Hourihan B30223 motion for leave to file reply denied.

  LAZO,R.M. Atomic Safety and Licensing Board Panel. B3/07/12. Hest Valley Agricultural Protection Council, Inc. 9pp. 19433:147. 24X Fiche: 50-529,83/07/11.8307120572.
- 8307190076 Motion to compel responses to second set of Interrogatories 2-4.7 & 9. Legitimacy of Joint Applicant objection may be resolved by identifying each document specifically.

  BERLIN.K. West Valley Agricultural Probection Council, Inc.

  BERLIN.K. Berlin, Roisman, Kessler & Cashdan, 83/07/15. Atomic Safety and Licensing Board Panel. 2pp. 19635:119. 24X

  Fiche: 50-529, 83/07/15, 8307190076.
- --8307190081 Memorandum in support of motion to compel responses to second set of Interrogatories 2-4,7 & 9. Objections are overbroad. Confidentiality waived re FOQ model since model used in proceeding. Certificate of Svc encl.

  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  BERLIN.K. Berlin, Roisman, Kessler & Cashdan, 83/07/15. Atomic Safety and Licensing Board Panel. 5pp. 19635:121, 24X
  Fiche: 50-529, 83/07/15, 8307190076.
- 8307190157 Response to request for production of documents, Request 1.
  M/o documents.
  BIBCHOFF, C. A. Joint Applicants-Palo Verde. BIBCHOFF, C. A. Snell & Wilmer. B3/07/15. BERLIN, K. West Valley Agricultural Protection Council, Inc. BERLIN, K. Berlin, Roisman, Kessler & Cashdan. 11pp. 19636:234. 24X Fiche: 50-529, B3/07/15, B307190157.

- B307190227 Answer opposing West Valley Agricultural Protection Council, Inc (West Valley) B30627 motion for protective order. Order unnecessary since no motion to compel interrogatory response filed.

  BISCHOFF, C. A. Arizona Public Service Co. BISCHOFF, C. A. Snell &
  - filed.

    BISCHOFF, C. A. Arizona Public Service Co. BISCHOFF, C. A. Snell & Wilmer. 83/07/15. Atomic Safety and Licensing Board Panel. 7pp. 19629: 236. 24X Fiche: 50-529, 83/07/15, 8307190227.
- --B307190232 Motion to compel Hest Valley Agricultural Protection Council, Inc to answer interrogatories. Interrogatories relevant or will lead to discovery of admissible evidence. Certificate of Svc encl. BISCHOFF, C. A. Arizona Public Service Co. BISCHOFF, C. A. Bnæll & Wilmer, B3/07/15, Atomic Bafety and Licensing Board Panel. 13pp. 19629:243. 24X Fiche: 50-529,83/07/15,8307190227.
- 8307210039 Answer to West Valley Agricultural Protection Council.Inc 830629 motion for protective order re discovery info on membership, farm acreage, crop yields & profits. ASLB should defer ruling due to snot stipulation.

  DEWEY, L. S. Hearing Branch 3. 83/07/19. Atomic Safety and Licensing Board Panel. 2pp. 19668:317. 24X Fiche: 50-529,83/07/19,8307210039.
- --B307210041 Stipulation that NRC agrees to attempt to obtain info requested in NRC Interrogatory 1.in B30427 second set of interrogatories to West Valley Agricultural Protection Gouncil.from publicly aveilable matis. W/Gertificate of Byc. DEWEY.L.S. Hearing Branch 3. BERLIN.K. West Valley Agricultura Protection Council. Inc. B3/07/11. 3pp. 19668:317. 24X Fiche:50-527,83/07/19,8307210037.
- 8307210276 Updates chart of specific portions of IE insp repts applicable to allegations raised by former plant const workers.

  DEMEY.L. B. Hearing Branch 3. 83/07/20. LAZG.R. M., CALLIHAN.D., CDLE.R.F. Atomic Bafety and Licensing Board Panel. 2pp. 19664: 287. 24X Fiche: 50-529, 83/07/20, 8307210276.
- 8307260243 Response to request for production of documents. Certificate of Svc enci.
  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  83/07/21. Joint Applicants-Palo Verde. 4pp. 19727:001. 24X
  Fiche: 50-529, 83/07/21, 8307260243.
- 8307240251 Response to request for production of documents. West Valley Agricultural Protection Council has not decided upon which documents to be used as exhibits or to be used during cross-examination. Certificate of Svc encl.

  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  83/07/21. Office of the Executive Legal Director. 3pp.
  19727:091. 24X Fiche: 50-529,63/07/21,8307260251.
- 8307260367 Requests authorization of appeal of ASLB 830711 decision denying NEPA motion. Prompt decision necessary to prevent detriment to public interest & unusual delay & expense. Certificate of Svc encl.

  BERLIN,K. Berlin, Roisman, Kessler & Cashdan, BERLIN,K. West Valley Agricultural Protection Council, Inc. 83/07/21, LAZG.R.M., CDLE.R.F., CALLIHAN,D. Atomic Safety and Licensing Board Panel.

  3pp. 19733:048, 24X Fiche: 50-527,83/07/21,8307260367.
- 9307260403 Motion seeking stay of ASLB 830711 decision permitting hearing to proceed w/inadequate EIS Certification of appeal & completion of adequate EIS requested.
  BERLIN,K. West Valley Agricultural Protection Council, Inc.
  BERLIN,K. Berlin, Roisman, Kessler & Cashdan. 83/07/22. Atomic Safety and Licensing Appeal Panel. 3pp. 19733:063. 24X
  Fiche: 50-529,83/07/22,8307260403.
- --8307260407 Memorendum in support of motion seeking stay of ABLB 830711 decision permitting hearing to proceed w/inadequate EIS.
  Exhibits & Certificate of Svc ancl.
  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  BERLIN.K. Berlin, Roisman, Kessler & Cashdan. 83/07/22. Atomic
  Safety and Licensing Board Panel. 3Bpp. 19733:067. 24X
  Fiche: 50-529,83/07/22,8307260403.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307190223 Forwards Proof of Svc of Amend 11 to FSAR.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/07/15, KNIOHTON, Q. W.

  Licensing Branch 3. 3pp. 19629: 225, 24X Fiche: 50-528: 83/07/15,
  8307190223.
- Q. Inspection reports, IE Bulletins & correspondence
- 8307120558 Forwards IE Insp Repts 50-528/83-22,50-529/83-12 & 50-530/83-09 on 830523-07. No noncompliance noted. 8TERNBERG, D. M. Region 5, Office of Director. 83/06/20. VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 19431:329. 24X Fiche:50-528,83/06/20,8307120558.

- --8307120568 IE Insp Repts 50-528/83-22.50-529/83-12 & 50-530/83-09 on 830523-27. No noncompliance noted Major areas inspected: allegations re electrical activities & tendon prestressing activities & action on previous insp findings.

  NARBUT.P.P. BURDDIN.J.F., YOUNG.T. Region 4. Office of Director. 83/06/17. 16pp. 19431:331. 24X Fiche:50-528.83/06/20.8307120558.
- 8307070226 Comments on 830502 proposed revs to FSAR re component classification & scope of augmented inservice insp. Revs acceptable.

  KNIGHTON.G W. Licensing Branch 3, 83/06/21. VAN BRUNT, E. E. Aritona Public Service Co. 3pp. 19344:351. 24X
  Fiche:30-928.83/06/21.8307070226.
- 8307120541 Forwards IE Insp Repts 50-528/83-23,50-529/83-13 & 50-530/83-10 on 830502-0603 No noncompliance noted. 8TERNBERG, D. M. Region 5. Office of Director. 83/06/27. VAN BRUNT, E. E. Artona Public Service Co. 2pp. 19433:348. 24X Fiche: 50-528,83/06/27,8307120541.
- --8307120549 IE Insp Repts 50-528/83-23.50-529/83-13 & 50-530/83-10 on 830502-0603. No noncompliance noted. Major areas inspected: const activities re followup of allegations of unacceptable electrical work & followup of previous insp items.
  VURDERBRUEGGEN. YDUNG.T. Region 5, Office of Director. 83/06/22.
  8pp. 19433:350. 24X Fiche:50-528.83/06/27.8307120541.
- B307260291 Informs that final response to B30525 notice of noncompliance from insp on B30301-D430 will be delayed until B30725 due to extensive investigation & evaluation required. VAN BRUNT, E. E. Arizona Public Service Co. B3/06/27. STERNBERG, D. M. Region 5, Office of Director. 1p. 19726:213. 24X Fiche: 50-528, 83/06/27, 8307260291.
- B30706040B Forwards IE Hgt Meeting & SALP Repts 50-528/B3-16, 50-527/B3-09 & 50-530/B3-07 on B30525.No noncompliance noted.

  MARTIN.J.B. Region 5. Office of Director. B3/06/30. WOODS, T. G. Arizona Public Service Co. 2pp. 19237:010. 24X Fiche: 50-528, B3/06/30, B307060408.
- ---B307060416 IE Mgt Meeting Repts 30-528/83-16, 50-529/83-09 & 50-530/83-07 on 830525. No noncompliance noted. Major areas discussed: results of Region V assessment of licensee performance for Jul 1981 Feb 1983.

  JUNNSON, P. H. , YOUNGO, T. Region 5, Office of Director. 83/04/24.

  2pp. 19237: 012. 24X Fiche: 50-528,83/04/30,8307040408.
- --8307060420 SALP Repts 50-528/83-16.50-527/83-09 % 50-530/83-07 for Jul 1981 Feb 1983 Overall performance acceptable.

  \*\* Region 5. Office of Director. 83/04/30. 32pp. 19237:014. 24X Fiche: 50-52B.63/06/30.630706040B.
- --8307060426 Confirms comments on SALP repts for Jul 1981 Feb 1983, per 830825 meeting to review program results. Oral comments listed & discussed Mgt & QA activities will be emphasized to assure that electrical equipments meets FSAR criteria. WUDDS.T.G. Arizona Public Stry(ce Co. 83/06/10. MARTIN.J.B. Region 5, Office of Director. 4pp. 19237:047. 24X Fiche: 50-528,83/06/30,8307060408.
- 8306270401 IE Info Notice 83-46. "Common Made Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000.83/07/12.8306270404.
- B306270406 IE Info Notice B3-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR, J. M. Division of QA, Safeguards & Inspection Programs (Post B30103). B3/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, B3/07/14, B306270406.
- 5. Reportable occurrences, LERs & related correspondence
- 8305130239 Interim Deficiency Rept 83-17 re fire protection switches mfg by ITE Gould failure to meet requirements of TMI Task 18A. Initially reported on 830304. Bechtel & Brown Boveri Electric evaluating condition. Next rept by 830519.

  VAN BRUNT, E. E. Aritona Public Service Co. 83/04/21. STERNBERG, D. & Region 5, Office of Director. 3pp. 18439:185. 24X Fiche: 50-529, 83/04/21, 8305130239.

- 8307040323 Final Deficiency Rept DER 83-11 re potential oxide battery leak or corrosion at terminals due to cracked plastic seals/covers. Initially reported on 830228. Batteries will be repaired. Deficiency not reportable per 10CFR50. 55(e). VAN BRUNT.E.E. Arizona Public Service Co. 83/06/14. STERNBERG.D.M. Region 5. Office of Director. 9pp. 19239:168. 24X Fiche: 50-528, 83/06/14, 8307060323.
- 8307060013 Final Deficiency Rept DER 82-50 re flerible conduit couplings between auxiliary & control bldgs which may be damaged if seismic event exceeds 3/4-inch movement. Item determined not reportable under 10CFR50. 55(e) requirements, VAN BRUNT.E.E. Arizona Public Service Co. 83/06/17. 8TERNI Region 5. Defice of Director. 3pp. 19250:001. 24X Fiche: 50-528.83/06/17, 8307060013. STERNBERG D. M.
- --8307060025 "Evaluation of Electrical Conduit Connections Between Auxiliary & Control Bidgs for Arizona Public Svc Palo Verde Nuclear Generating Station."

  WILSON, 5. W. PAZAROADI, S., BAUSCH, H. P. Wyle Laboratories, 24404-1. 83/03/31. 154pp. 19250:004. 24X Fiche: 50-528, 83/06/17, 8307060013.
- 8307040379 Interim Deficiency Rept DER 82-56 rm scaling-down condensate storage tank design w/o new calculations. Initially reported on 821015. Submittal of final rept extended to 830727.

  VAN BRUNTLE.E. Artiona Public Service Co. B3/06/27. STERNBERG, D. M. Region 5, Office of Director. 2pp. 19236:062. 24X Fiche: 30-528, 83/06/27, 8307060379.
- 8307120195 Interim Deficiency Rept 83-34 re surface cracks on Bechtel welds to embed plates of C-E containment instrument racks. Initially reported on 830527. Bechtel examining defective welds. Final rept expected by 830920.

  VAN BRUNT. E. E. Arizona Public Service Co. 83/06/27. STERNBERG, D. M. Region 5. Dffice of Director. 3pp. 19425: 213. 24% Fiche: 50-529, 83/06/27, 8307120195.
- 8307120366 Finel Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response. Initially reported on 821026. Deficiency not reportable per 10CFR30. 53(e). Bechtel independent analysis of calculations encl. VAN BRUNT.E. E. Arizona Public Service Co. 83/06/27. STERNBERG, D. M. Region 5. Office of Director. 32pp. 19429:048. 24x Fiche: 50-328.83/06/27.8307120366.
- -9307120377 Rev 1 to "Engineering Evaluation for Design of Condensate Water Storage Tank & Refueling Water Tank,Palo Verde Nuclear Generating Station," for Deficiency Evaluation Repts 82-56 & 00-47 LIMAYE, G.S., HUGHES, W.R., BERGGUIST, S.H. Bechtel Corp. 28pp. 19429:052. 24% Fiche: 50-528,83/06/27,8307120366.
- B307120296 Final Deficiency Rept DER B2-72 re concrete void in containment exterior wall. Initially reported on B21124. Orouting program conducted to fill leak paths in wall & to seal off leaks in tendon sheaths.

  VAN BRUNT.E.E. Arizona Public Service Co. B3/06/30. STERNBERG, D. M. Region 5, Office of Director. 4pp. 19431:048. 24X Fiche: S0-529, 83/06/30, 8307120296.
- ---B307120303 "Engineering Evaluation Rept: Investigation & Grouting of Leaks Associated W/Tendon Sheaths H32-007 & H32-011, Unit 2 Containment Bidg."
  WDLFF: M., BINGHAM, W. O. Bechtel Corp. 83/06/30. 103pp. 17431:052. 24X Fiche: 50-529, 83/06/30, 8307120296.
- 830718022! Interim Deficiency Rept DER 83-25 re instrumentation tubing not having required boundary class break. Initially reported on 83042!. Due to extensive investigation & evaluation, completed repts expected by 830B19.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/07/01. STERNBERG, D. M. Region 5. Office of Director. 2pp. 19555: 225. 24X

  Fiche: 50-528, 83/07/01, 8307180221.
- 8307280348 Interim Deficiency Rept DER 83-35 re Elgar inverters producing voltage spikes on dc supply bus. Initially reported on 830807. Addl inverter tests requested to reduce or eliminate voltage spikes. Final rept by 831031.

  VAN BRUNT. E. E. Arizona Public Service Co. 83/07/07. STERNBERG, D. M. Region 5. Office of Director. 3pp. 19789:015. 24X Fiche: 50-528, 83/07/07, 8307280348.
- 8307180081 Part 21 rept clarifying position re equipment failures during C-E qualification testing of Target Rock solenoid activated valves per T Lee 830620 request Valve design conforms to NUREG-0588 Retrofit program supported. PATTARINI, D. M. Target Rock Corp. 83/07/11. DEVOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p. 19360:007. 24x Fiche: 50-528, 83/07/11. 8307180081.

- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3 A. Application/construction stage documents & correspondence
- B307070427 Requests add1 quantitative analysis to support 821230 conclusions re failure of E-NNN-D11 panel. Transient scenarios bounded by FSAR Chapter 15 analyses. Notification of planned submittal date requested.
  KN10HTON, O. W. Licensing Branch 3. 83/06/17. VAN BRUNT, E. E. Aritona Public Service Co. 3pp. 19300:178. 24X
  Fiche: 50-528,83/06/17,8307070427.
- 8307070437 Forwards request for info on Tech Spec setpoint methodology. Notification of planned response date requested. XNIGHTON, O.W. Licensing Branch 3. 83/06/20. VAN BRUNT, E. E. Arizona Public Service Co. 4pp. 19300:184. 24X Fiche: 50-528,83/06/20,8307070437.
- 8307070226 Commants on 830502 proposed revs to FBAR re component classification & scope of augmented inservice insp. Revs classification & scope of augmented inservice insp.Revs acceptable. KNIGHTON.G.W. Licensing Branch G. 83/06/21. VAN BRUNT, E.E. Arizona Public Service Co. 3pp. 19344:351. 24X Fiche: 50-528,83/06/21,8307070226.
- B30706/0012 Forwards proposed rev to FSAR, Section 1.8 re exceptions to Reg Guide 1.88 covering level concrete floor & roof in records storage facility. VAN BRUNT-E.E. Arizona Public Service Co. B3/06/24, STERNBERG, D. M. Region 3, Office of Director. 7pp. 19238: 255. 24X Fiche: 50-528, B3/06/24, B307060012.
- 8307280413 Revised final Deficiency Rept DER 83-33 re GE AKR-50 breaker w/EC-1 trips which may have generic defect. Initially reported on 820429. Defects will be corrected prior to fuel load. Also reportable per Part 21.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/24. STERNBERO, D. M. Region 5. Office of Director. 5pp. 19802: 107. 24X Fiche: 50-530, 83/06/24, 8307280413.
- B307050026 Forwards response to B30415 request for add1 info re solid waste process control program. Package waste will be segregated by container activity level into high level or low level storage area.

  VAN BRUNTLE.E. Arizone Public Service Co. B3/06/30. KNIGHTON, C. Licensing Branch 3. 17pp. 19220: 134. 24X Fiche: 50-528, 83/06/30, 8307030026.
- 8307050133 Advises that accelerated schedule data of 830731 for submittal of specific info re depressurization & DHR capabilities by 830731 supports NRC needs.

  VAN BRUNT.E.E. Aritiona Public Service Co. 83/06/30, KNIGHTON, G. Licensing Branch 3, 2pp. 19220:219, 24X Fiche: 50-528, 83/06/30, 83070780132
- 8307050199 Responds to Generic Ltr 83-10A re resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps."
  Description for resolving item & plan & schedule for plant-specific activities encl.
  VAN BRUNT.E.E. Arizona Public Service Co. 83/06/30, KNIGHTON, O. Licensing Branch 3, 14pp. 19199:205. 24X Fiche: 50-528, 83/06/30, 8307050199.
- B306270397 Generic Ltr B3~26 to all applicants for QLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT. D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24x. Fiche: 50~000, 83/07/05, 8306270397.
- 8307060329 Generic Ltr B3-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/07/06. Consolidated Edison Co. of New York. Inc. 16pp. 19669:254. 24X Fiche: 50-000.83/07/06.8307060329.
- 830713023B Forwards supplemental rept re piping sys design review as part of independent GA evaluation of facilities in response to questions resulting from 830602 meeting.

  SIMON.W.A. Torrey Pines Technology. 83/07/06. LIGITRA.E. NRC No Detailed Affiliation Given. 17pp. 19539:067. 24X

  Fiche: 30-528, 83/07/06, 8307130238.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATMS events 8vc list encl. EISENHVI.D.G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.

- E. NRC Safety Evaluation Report (SER), supple & correspondence
- \$307080637 Forwards request for add1 info & comments on SER Suppl 4 re revised emergency plan. Notification of submittal date requested.

  KNIOHTON, O. H. Licensing Branch 3. 83/06/20. VAN BRUNT, E. E. Arizona Public Service Co. 6pp. 19364: 213. 24x

  Fiche: 50-528, 83/06/20, 8307080637.
- E307050211 Responds to Nov 1981 SER, subsequent suppl & carrespondence & Generic Ltr 82-33, Suppl 1 to NUREG-0737 requirements for amergency response capabilities. Human factors study & status rept re historical earthquake data encl.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. KNIGHTON, Q. Licensing Branch 3. 5pp. 19194:183. 24X Fiche:50-528,83/06/30, 8307050211.
- --8307050228 Suppl 1 to GA-C16398 "Palo Verde Nuclear Generating Station Control Room Human Factors Study, Executive Summary Rept. # Torrey Pines Technology. GA-C16378 S01. B3/06/30. 19194:189. 24X Fine: 30-528, B3/06/30, B3/000211.
- B30706036B Forwards responses to NRC findings of Power Sys site audit conducted on 830406-07.per SER, NUREG-0857.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/07/01. KNIGHTON, O. Licensing Branch 3. lipp. 19236:228. 24X Fiche: 50-528,83/07/01,830706036B.
- 3307110012 Forwards response to SER Section 7, 7, 2, Question 222, 03 re qualification of control sys. Response closes open item in Section 7.7.2 & will be incorporated into upcoming FBAR amend
  - VAN BRUNT, E. E. Arizona Public Bervice Co. 83/07/01. KNIGHTON, G. Licensing Brench 3. App. 19374; 205. 24X Fiche: 50-528, 83/07/01. 8307110012.
- 3dD7150363 Forwards corrected map identifying reception & care ctrs.
  per 830613 request & Suppl 4 to SER re emergency plan.
  VAN BRUNT, E. Arizona Public Service Co. 83/07/08. KNIGHTON, G.
  Licensing Branch 3. 3pp. 19538:330. 24% Fiche:50-328.83/07/08.
  8307150363.
- ₹307140374 Responds to Mar 1983 SER (NUREG-0857) request for add1 info re emergency plan. External ltrs of agreement encl. Info adequately responds to request. VAN BRUNT, E. E. Arizona Public Service Co. 83/07/12. KNIGHTON, O. Litensing Branch 3. 19pp. 19923:335. 24X Fiche: 50-528,83/07/12, 8307140374,
- Security, medical, emergency & fire protection plans
- \*307050498 Notification of 830422 meeting w/util & NUBAC in Silver Spring, MD to discuss proposed substitute security plan.
  LICITRA.E.A. Licensing Branch 3. 83/06/20. KNIGHTON, G. W.
  Licensing Branch 3. 3pp. 19262: 276. 24X Fiche: 50-528, 83/06/20, 8307050498.
- IBO7080637 Forwards request for add1 info & comments on SER Suppl 4 re revised emergency plan. Notification of submittal date requested.

  KNIGHTON.G.W. Licensing Branch 3. 83/06/20. VAN BRUNT.E.E. Arizona Public Service Co. 6pp. 17364:213. 24X

  Fiche: 50-528, 83/06/20, 8307080637.
- 307050211 Responds to Nov 1981 GER, subsequent suppl % correspondence & Generic Let 82-33, Suppl 1 to NUREO-0737 requirements for emergency response capabilities. Human factors study & status rept re historical earthquake data encl.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/06/30. KNIGHTON, G. Licensin Branch 3. 3pp. 19194: 183. 24X Fiche: 50-528, 83/06/30, 8307050211.
- 307150363 Forwards corrected map identifying reception & care ctrs, per 830613 request & Suppl 4 to SER re emergency plan. VAN BRUNT, E. Arizona Public Service Co. 83/07/08. KNIGHTON, 0, Licensing Branch 3. 3pp. 19538:350. 24X Fiche: 50-528, 83/07/08, 8307150363.
- 307140374 Responds to Mar 1983 SER (NUREG-0857) request for add1 info re emergency plan. External ltrs of agreement encl. Info adequately responds to request.

  VAN BRUNT, E. E. Arizona Public Service Co. 83/07/12. KNIGHTON, 6, Licensing Branch 3, 19pp. 19523: 335. 24X Fiche: 50-528, 83/07/12, 8307140374.
- 307200117 Summarizes significant changes being incorporated in Rev 3 to emergency plan.including organizational control of ammrgencies, emergency conditions & emergency facilities & equipment Rev 3 will be submitted by 830815.

  VAN BRUNT, E.E. Arizona Public Service Co. 83/07/14. KNIGHTON, C. Licensing Branch 3. 7pp. 19647:156. 24X Fiche: 50-528, 83/07/14. 8307200117.

- 8307190190 Forwards "Emergency Procedure Generation Package," per requirements of Suppl 1 to NUREO-0737 VAN BRUNT, E.E. Arizona Public Service Co. 83/07/15. KNIGHTON.G. Licensing Branch 3. 2pp. 19630:192. 24X Fiche: 50-528
- --8307190194 "Emergency Procedure Generation Package." \* Arizona Public Service Co. 83/07/15. 211pp. 19631:001. 24X Fiche. 50-528, 83/07/15, 8307190190.
- O. Adjudicatory correspondence
- 8307050244 Supplemental answers to interrogatories.

  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  83/06/29. Arizona Public Service Co. 10pp. 19199:061. 24X
  Fiche: 80-529.83/06/29.8307050244.
- -8307050247 Motion for protective order against Joint Applicants & NRC interrogatories requesting info on West Valley Agricultural Protection Council, Inc members, acreage, crop yields & profits
  BERLIN.K. West Valley Agricultural Protection Council,
  B3/06/27. Atomic Safety and Licensing Board Panel, 2
  19199: 072. 24X Fiche: 50-529, 83/06/29, 8307050244.
- --B307050251 Memorandum supporting West Valley Agricultural Protection Council motion for prodective order Guestion relates to potential salt damage to area crops, not Council member crops. Certificate of Svc encl. BERLINK. West Valley Agricultural Protection Council, Inc. B3706/29. Atomic Safety and Licensing Board Panel. App. 19199: 074. 24X Fiche: 50-529, 83706/29, 8307050244.
- 830706013: Responses to West Valley Agricultural Improvement Council, Inc requests for production of documents Certificate of Svc encl. BVC enci. CRAMFORD,V.A. Joint Applicants-Palo Verde. CRAWFORD,V.A. 9 Wilmer. 83/07/10. West Valley Agricultural Protection Co. Inc. 4pp. 19230:201. 24X Fiche: 50-529,83/07/01,8307060151. RAW. Hilmer. ... 4pp.
- 8307040136 Supplemental response to West Valley first & second sets of interrogatories. Certificate of Svc encl. CRAWFORD. V.A. Joint Applicants-Palo Verde. CRAWFORD. V.A. Snell & Wilmer. 83/07/01. West Valley Agricultural Protection Council, Inc. 4pp. 19250: 156. 24X Fiche: 50-529.83/07/01.8307060136.
- 8307120572 Memorandum & order denying West Valley Agricultural Protection Council 830202 & 0506 motions for declaration that NEPA analysis inadequate & for continuance.PL Hourihan 830223 motion for leave to file reply denied. LAZO.R.M. Atomic Safety and Licensing Board Panel. 83/07/12 West Valley Agricultural Protection Council. Inc. 9pp. 194524X Fiche: 50-529, 83/07/11, 8307120572.
- 8307190076 Motion to compel responses to second set of interrogatories 2-4,7 & 9. Legitimacy of Joint Applicant objection may be resolved by identifying each document specifically.

  BERLIN.K. West Valley Agricultural Protection Council, Inc. BERLIN.K. Berlin, Roisman, Kessler & Cashdan, 83/07/15. Atomic Safety and Licensing Board Panel. 2pp. 19635-119. 24X Fiche: 50-529, 83/07/15, 8307190076.
- --B307190081 Memorandum in support of motion to compel responses to second set of Interrogatories 2-4.7 & 9. Objections are overbroad. Confidentiality waived re FDO model since model used in proceeding. Certificate of Syc enci.

  BERLIN.K. West Valley Agricultural Protection Council, Inc. BERLIN.K. Berlin. Roisman. Ressier & Cashdan. B3/07/15. Att Safety and Liconsing Board Panel. Spp. 19635:121. 24X Fiche: 50-529, B3/07/15, B307190076.
- 8307190197 Response to request for production of documents, Request 1. W/o documents, C.A. Joint Applicants-Palo Verde. BISCHOFF, C.A. Sneil & Wilher. 83/07/15. BERLIN, K. West Valley Agricultural Protection Council. Inc. BERLIN, K. Berlin. Roisman, Kessler & Cashdan. 11pp. 19636:234. 24X Fiche: 50-529, 83/07/15, 8307190197.
- 8307190227 Answer opposing West Valley Agricultural Protection Council, Inc (West Valley) 830629 motion for protective order Order Unnecessary since no motion to compel interrogatory response Filed.
  BISCHOFF, C. A. Arizona Public Service Co. BISCHOFF, C. A. Snell & Wilmer. B3/07/15. Atomic Safety and Licensing Board Panel. 7pp. 19629: 236. 24% Fiche: 50-529, 83/07/15, 8307190227.
- --8307190P32 Motion to compel West Valley Agricultural Protection Council, Inc to answer interrogatories. Interrogatories relevant or will lead to discovery of admissible evidence, Certificate of Svc encl. BISCHOFF, C.A. Arizona Public Service Co. BISCHOFF, C.A. Snell & Wilmer. 83/07/15. Atomic Safety and Licensing Board Panel. 13pp. 19629: 243. 24X Fiche: 50-529, 83/07/15, 8307190227.

- 8307210039 Answer to West Valley Agricultural Protection Council, Inc 830629 motion for protective order re discovery info on membership, form acreage, crop yields & profits. ASLB should defer ruling due to encl stipulation.

  BEWEY, L. S. Hearing Branch 3. 83/07/19. Atomic Safety and Licensing Board Panel. 2pp. 19668.317. 24X Fiche: 50-329, 83/07/19, 8307210039.
- --8307210041 Stipulation that NRC agrees to attempt to obtain inforequested in NRC Interrogatory 1, in 830429 second set of interrogatories to West Valley Agricultural Protection Council, from publicly available matls. W/Certificate of Svc. DEWEY, L. S. Hearing Branch 3. BERLIN.K. West Valley Agricultural Protection Council, Inc. 83/07/11. 3pp. 19668:319. 24% Fiche: 50-529, 83/07/19, 8307210039.
- 8307210276 Updates chart of specific portions of IE insp repts applicable to allegations raised by former plant const workers.

  DENEY,L. 5. Hearing Branch 3. 83/07/20. LAZO,R.M., CALLIHAN,D., COLE,R.F. Atomic Safety and Licensing Board Panel. 2pp. 17664:287. 24X Fiche: 50-529, 83/07/20, 8307210276.
- B307260243 Response to request for production of documents. Certificate of Bvc encl.
  BERLIN.K. West Valley Agricultural Protection Council, Inc.
  B3/07/21. Joint Applicants-Palo Verde. 4pp. 19727:001. 24X
  Fiche: 50-529, 83/07/21. B307260243.
- 8307260251 Response to request for production of documents. West Valley Agricultural Protection Council has not decided upon which documents to be used as exhibits or to be used during cross-examination. Certificate of Svc encl.

  82RR.I.N.K. West Valley Agricultural Protection Council, Inc.
  83/07/21. Office of the Executive Legal Director. 3pp.
  19727:091. 24X Fiche: 50-529, 83/07/21, 8307260251.
- 8307260367 Requests authorization of appeal of ABLB 830711 decision denying NEPA motion. Prompt decision necessary to prevent detriment to public interest & unusual delay & expense. Certificate of Svc encl.

  BERLIN.K. Berlin. Roisman. Kessler & Cashdan. BERLIN.K. West Valley Agricultural Protection Council, Inc. 83/07/21. LAZO.R.M., COLE.R.F., CALLIMAN.D. Atomic Safety and Licensing Board Panel. 3pp. 19733:048. 24X Fiche: 50-529.83/07/21.8307260367.
- 8307260403 Motion seeking stay of ASLB 830711 decision permitting hearing to proceed w/inadequate EIS.Certification of appeal & completion of adequate EIS requested.

  BERLIN.K. Hest Valley Agricultural Protection Council, Inc. BERLIN.K. Berlin. Roisman. Kessler & Cashdan. 83/07/22. Atomic 8afety and Licensing Appeal Panel. 3pp. 19733:063. 24X Fiche: 50-529,83/07/22,8307260403.
- --8307260407 Memorandum in support of mution seeking stay of ASLB 830711 decision permitting hearing to proceed w/inadequate EIS. Exhibits & Certificate of Svc encl. ERLINIK. West Valley Agricultural Protection Council. Inc. BERLINIK. Berlin. Roisman. Kessler & Cashdan. 83/07/22. Atomic Safety and Licensing Board Panel. 38pp. 19733:067. 24X Fiche: 50-529.83/07/22,8307260403.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8307190223 Forwards Proof of Svc of Amend 11 to FSAR.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/07/15. KNIGHTON, Q. W.
  Licensing Branch 3. 3pp. 19629: 225. 24X Fiche: 50-528,83/07/15,8307190223.
- G. Inspection reports, IE Bulletins & correspondence
- 8307120358 Forwards IE Insp Regts 50-526/83-22,50-529/83-12 & 50-530/83-07 on 830523-07. No noncompliance noted.
  STERNBERG, 0 M. Region 5. Office of Director. 83/06/20. VAN BRUNT. E. E. Antrona Public Service Co. 2pp. 19431:327. 24X Fiche: 50-528,83/06/20,8307120558.
- --830712056B IE Insp Repts 50-528/83-22.50-529/83-12 & 50-530/83-09 on 830523-27.No noncompliance noted Major areas inspected: allegations re electrical activities & tendon prestressing activities & action on previous insp findings.
  NARBUT.P.P., BURDOIN.J.F., YOUNG.T. Region 4, Office of Director. 83/06/17. 16pp. 19431:331. 24X Fiche:50-52B,83/06/20.8307120558.
- 8307070226 Comments on 830502 proposed revs to FSAR re component classification & scope of augmented inservice insp.Revs acceptable.

  KNIOHTONIO. H. Licensing Branch 3. 83/06/21. VAN BRUNT, E. E. Arizona Public Service Co. 3pp. 19344:331. 24X

  Fiche: 50-528.83/06/21.8307070226.

- B307120541 Forwards IE Insp Repts 50-528/83-23, 90-529/83-13 & 50-530/83-10 on 830502-0603. No nancompliance noted. STERNBERG, D. M. Region 5, Office of Director. B3/06/27, VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 19433: 348. 24X Fiche: 50-528, B3/06/27, 8307120541.
- --8307120549 IE Insp Repta 50-528/83-23, 50-529/83-13 & 50-530/83-10 on 830502-0603. No noncompliance noted Major areas inspected: const activities re followup of allegations of unacceptable electrical work & followup of previous insp items.

  VORDERBRUEOGEN, YOUNG, T. Region 5, Office of Director. 83/06/22, 8pp. 19433:350. 24X Fiche: 50-528,83/06/27,8307120541.
- 8307240291 Informs that final response to 830925 notice of noncompliance from insp on 830301-0430 will be delayed until 830725 due to extensive investigation & evaluation required. VAN BRUNT.E.E. Arisona Public Service Co. 83/06/27. STERNBERG.D.M. Region 5. Office of Director. 1p. 19726:213. 24X Fiche:30-528.83/06/27.8307260291.
- 8307060408 Forwards IE Mgt Meeting & SALP Repts 50-528/83-16, 30-529/83-09 & 30-530/83-07 on 830525.No noncompliance noted. MARTIN.J. B. Region 5, Office of Director. 83/06/30. WOODS, T. Q. Arizona Public Service Co. 2pp. 19237:010, 24X Fiche: 50-528.83/06/30.8307060408.
- --B307060416 IE Mgt Meeting Repts 50-528/83-14,50-529/83-09 & 50-530/83-07 on 830525. No noncompliance noted Major areas discussed: results of Region V assessment of licensee performance for Jul 1981 Feb 1983.

  JOHNSON, P. H., YOUNG, T. Region 5, Office of Director. 83/06/24, 2pp. 19237:012. 24X Fiche: 50-528,83/06/30,8307060408.
- --8307060420 SALP Repts 50-528/83-16,50-529/83-09 & 50-530/83-07 for Jul 1981 Feb 1983 Overall performance acceptable.

  \* Region 5. Office of Director. 83/04/30. 32pp. 19237:014. 24x Fiche: 50-528,83/06/30,8307060408.
- --B307060426 Confirms comments on SALP repts for Jul 1981 Feb 1983, per B30525 meeting to review program results. Oral comments listed & discussed Mgt & QA activities will be emphasized to assure that electrical equipments meets FSAR criteria. WOODS.T.O. Arizona Public Service Co. B3/06/10. MARTIN, J.B. Region 5, Office of Director. 4pp. 19237:047. 24X Fiche: SO-528, B3/06/30, B307060408.
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list enci.
  JORDANE.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000.83/07/11.8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Byc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche:50-000,83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR,J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270, 24X Fiche: 50-000,83/07/14,8306270406.
- S. Reportable occurrences, LER's & related correspondence
- 8307060013 Final Deficiency Rept DER 82-50 re flexible conduit couplings between auxiliary & control bidgs which may be damaged if seismic event exceeds 3/4-inch movement. Item determined not reportable under 10CFR50. 55(e) requirements. VAN BRUNT.E.E. Arizona Public Service Co. 83/06/17. STERNBERG.D.M. Region 5. Office of Director. 3pp. 19250:001. 24X Ficha: 50-528.83/06/17.8307060013.
- --8307060025 "Evaluation of Electrical Conduit Connections Between Auxiliary & Control Bidgs for Arizona Public Svc Palo Verde Nuclear Generating Station."
  WILSON,B.W., PAZAROADI,S., BAUSCH,H.P. Wyle Laboratories.
  24405-1. 83/03/31. 154pp. 19250:004. 24X Fiche:50-528,83/06/17,8307060013.
- 8307120529 Final deficiency Rept DER 83-33 re GE Model AKR-50 breakers w/EC-1 trips which may have generic defect. Initially reported on 830429. Bechtel will correct defects prior to fuel load. Also reportable per Part 21.

  VAN BRUNTI E. E. Arizona Public Service Co. 83/06/24. STERNBERG, D. M. Region 5, Office of Director. 11pp. 19433: 295, 24x

  Fiche: 50-530,83/06/24,8307120529.

- O 70 60379 Interim Deficiency Rept DER 82-56 re scaling-down condensate errage tank design w/o new calculations. Initially reported 821015 Submittal of final rept extended to 830727.

  ON BRUNT, E. E. Arizona Public Service Co. B3/06/27. STERNBERG, D. M. Pagian 5. Office of Director. 2pp. 19236:062. 24X
- B307120366 Final Deficiency Rept DER 82-63 re design calculation error refueling water tank seismic response. Initially reported 921026. Deficiency not reportable per 10CFR50, 55(e). The lindependent analysis of calculations encl. BAN BRUNT, E.E. Aritona Public Service Co. B3/06/27. STERNBERG, D. M. Ragion 5, Office of Director. 32pp. 19429:048. 24X Fiche: 50-52B: 83/06/27, 8307120366.
- O7120377 Rev 1 to "Engineering Evaluation for Design of Condensate Hater Storage Tank & Refueling Water Tank, Palo Verde Nuclear Generating Station," for Deficiency Evaluation Repts 82-56 & 82-63.

  LIMAYE, G. S., HUGHES, W. R., BERGGUIST, S. H. Bechtel Corp. 83/05/31.

  28pp. 19429:032. 24X Fiche: 50-528, 83/06/27, 8307120366.

- 8307180221 Interim Deficiency Rept DER 83-25 re instrumentation tubing not having required boundary class break Initially reported on 830421. Due to extensive investigation & evaluation. Completed repts expected by 930819.

  VAN BRUNT, E. E. Aritona Public Service Co. 83/07/01. STERNBERG, D. M. Region 5. Office at Director. 2pp. 19555: 225. 24X piche: 50-528, 83/07/01. 8307180221.
- 8307280348 Interim Deficiency Rept DER 83-35 Te Elgar inverters producing voltage spikes on dc supply bus. Initially reported on 830407. Addi inverter tests requested to reduce or 11 minate voltage spikes. Final rept by 831031.

  VAN BRUNT.E.E. Arizona Public Service Co. 83/07/07. STERNBE gagion 5, Office of Director. 3pp. 19789:015. 24X pt. 6:50-528,83/07/07,8307280348. '07. STERNSERG, D. M. 24X
- 8307180081 Part 21 rept clarifying position re equipment failures
  during C-E qualification testing of Tanget Rock solenoid
  activated valves per T Lee 830620 request Valve design
  conforms to NUREG-0588. Retrofit program supported.
  pATTARINI.D.M. Target Rock Corp. 83/07/11. DEYOUNG.R.C.
  Director's Office. Office of Inspection and Enforcement. 1p.
  19560:007. 24X Fiche: 50-528,63/07/11,8307160081.
- DOCKET 50-597 CLINCH RIVER BREEDER REACTOR
- App 1ication/construction stage documents & correspondence
- 8307220126 Appeals denial of FOIA request for transcript of Commisssion B30105 meeting re exemption request for CRBR transcript.

  GREENBERG, E. V. Galloway & Greenberg. GREENBERG, E. V. Natural Resources Defense Council. GREENBERG, E. V. Sierra Club. B3/03/21.

  Office of the Secretary of the Commission. Bpp. 19692:283. 24X Fiche: 50-537,83/03/21,8307220126.
- 8307220119 Responds to appeal re-denial of FOIA request for transcript of Commission 830105 meeting re-remand proceeding on CRBR. Document withheld per Bunshine Act Exemption 10.
  CHILK.S.J. Office of the Secretary of the Commission. 83/05/19.
  GREENBERG, E. V. Galloway & Greenberg. 6pp. 17692:277. 24X
  Fiche: 50-537, 83/05/19, 8307220119.
- 8305270397 Oeneric Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISENHUT, D. G. Division of Licensing, 83/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fich e:50-000.83/07/05,8306270397.
- 8307060329 Generic Ltr 83-27 to all licensees & applicants for operating power reactors & holders of CPs for power reactors resurveillance intervals in STS.Svc list encl. EISENHUT.D.9. Division of Licensing. 83/07/06. Consolid. Editor Co. of New York. Inc. 16pp. 19669: 254. 24X Fiche: 50-000, 83/07/06.8307060329. Consolidated
- B30707 0086 Forwards add1 info per request at 830610 meeting on programmatic objectives re fuel burnup.FFTF operates w/peak burnup of over 61,000 megawatt day/MT. Burnup occurred under temp & power conditions similar to CROR conditions.

  CNGENECKERJ, Energy, Dept. of, Clinch River Breeder Reactor Plant. B3707/06. GRACE.J.N. Clinch River Breeder Reactor Program Office. 19293; 105. 24X Fiche: 30-537. B3/07/06. B307070086.
- ## 2070 O 102 Forwards Rev 6 to Vol 2 to CRBRP-3, "Assessment of Thermal LONG ENECKER. J. Energy, Dept. of, Clinch River Breeder Reactor Plant. 19295: 019. 24x Fiche: 50-537,83/07/06,8307070102.

- --B307070105 Rev 2 to Vol 2 to CRDRP-3, "Assessment of Thermal Margin Beyond Design Base (TMBDB)." \* Energy, Dept. of. Clinch River Breeder Reactor Plant. CRBRP-3 VO2 R06. B3/07/04. 89pp. 19295.020. 24% Fiche:50-537,83/07/06. 8307070102
- B307120345 Informs that auxiliary feedwater sys evaluation.ger PSAR App C.Bection C.6.4 & App H.Section IJ.E.L.1.scheduled for completion by mid-1985. LONGEMECKERJ. Energy. Dept. of, Clinch River Breeder Reactor Pla og miluti983. J. Enengy, Dept. of, Clinch River Breeder Reactor Plant. GRACE, J. N. Clinch River Breeder Reactor Program Office. DB1. 24X Fiche: 50-537.83/07/08.8307120345. יאט 19429: 081.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- B307200187 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER PLANT ERRATA DOCKET NO. 50-537. CUS DEPARTMENT OF EMPEROY, TENNESSEE VALLEY AUTHORITY AND PROJECT MANAGEMENT CORPORATION).

  \* Office of Nuclear Reactor Regulation, Director. NUREG-0968 V01 ERR. 83/07/11. 2pp. 19647:308. 24X Fiche: 50-537, B3/07/11, B307200187.
- G. Adjudicatory correspondence
- 8307150321 Notice of postponement of 830718 evidentiary hearing in Dak Ridge. TN. Postponement necessary due to serious illness in ASLB member family.

  MILLER.M.E. Atomic Safety and Licensing Board Panel. 83/07/13. ip. 19538: 119. 24X Fiche: 50-537.83/07/13.8307150321.
- 8307180266 Forwards applicant proposed exhibit list for CP hearings, for review. Stipulation as to authenticity & admissibility requested. Certificate of Svc encl.

  EDGAR, G. L. Morgan, Lewis & Bocktus. EDGAR, G. L. Joint Applicants-Clinch River Breeder Reactor. 83/07/15. TURK, 6. E. Hearing Branch 1. 12pp. 19556:006. 24X Fiche: 50-537, 83/07/15, 8307180266.
- 8307220350 Advises of incorrectly cited ref on Page 1 of Attachment B & on Page 2 of Attachment C to 830708 ltr.Certificate of EDOAR O.L. Morgan, Lewis & Bockius. EDGAR, G.L. Project Hanage Corp. 83/07/19. MILLER, M.E., HAND, C.H., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 5pp. 19676: 083. 24X Fiche: 30-537, 83/07/19. 8307220350. Project Management
- 8307250363 Response opposing intervenor 830518 exceptions to ASLB 830228 partial initial decision on LWA ASLAB should affirm ASLB decision. Site suitability arguments incongroous.

  Gertificate of Svc encl.

  EDGAR. 9. C. Project Management Corp. LUCK, M. D. Energy, Dept. of. 83/07/22. Atomic Safety and Licensing Appeal Penel. 80pp. 19703:275. 24X Fiche: 50-537, 83/07/22, 8307250363.
- 8307260369 Advises of unission in applicant 830722 response re CP evidentiary hearings. Hearings did not commence on 830718 but were postponed per 830713 order. Order of 830717 rescheduled hearings for 830808-12. Certificate of 5vc encl.

  EDGAR.G.L. Morgan, Leuis & Bockius. EDGAR.G.L. Project Management Corp. 83/07/25. EDLES.G.V., JOHNSON, W.R., WILBER.H.A. Atomic Safety and Licensing Appeal Panel. 4pp. 19733:001. 24X Fiche: 50-537.83/07/25.8307260369.
- B307270227 Forwards final NUREG/CR-3224 which will be offered into evidence by NRC. No substantive mode, additions or deletions made. W/o encl.
  TURK, S.E. Hearing Branch 1. 83/07/25. MILLER, M., HAND, C. H.,
  LINENBERGER, G. Atomic Safety and Licensing Board Panel. 1p.
  19749: 315. 24X Fiche: 50-537, 83/07/25, 8307270227.
- 8307280178 Forwards proposed seismic margin exhibit, per ASLB 830513 & 0629 requests for NRC conclusions re seismic qualification of small diameter piping. W/o entl.
  TURK.S.E. Hearing Branch 1. 83/07/27. MILLER, M., HAND, C. H., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 2pp. 19792: 259. 24X Fiche: 50-537, 83/07/27, 8307280178.
- H. General correspondence
- 9307290092 Opposes plant const since little prior experience exists w/breader reactor design.

  DCHERTY, J.F. B3/07/20, MILLER, M.E. Atomic Safety
  and Licensing Board Panel. | p. 19815:354, 24X

  Fiche: 50-537,83/07/20,8307290882.

- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8307090095 Summarites 276th ACRS meetings on 830414-16 w/utils to review request for OL. Agenda for 830512-14 meetings encl. EBERSOLE. J. ACRS Advisory Committee on Reactor Safeguards. 83/04/29. FALLADINO.N. J. Commissioners. 3pp. 19366:058. 24X Fiche: 50-000: 83/04/29. 8307090095.
- Q. Inspection reports. IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Burry Recirculation Spray Subsystem." Svc list encl. JORDAN.E. L. Bivision of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000,83/07/11,8306270401.
- 8305270404 IE Info Notice 83-47, "Failure of Hydraulic Shubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 630103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19363:153. 24X Fiche: 50-000, 83/07/12, 8306270404.
- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR,J.M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715: 270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- T. Hearing transcripts on mon-antitrust matters
- 8307010159 Transcript of B30629 conference in Bethesda, MD. Pp 7, 298-7, 354.

  a Atomic Safety and Licensing Board Panel. 83/06/29. 59pp. 19174:120. 24x Fiche: 50-537, 83/06/29, 8307010159.
- 8307070200 Forwards transcript of 830629 conference w/counsel. TURK S.E. Hearing Branch 1. 83/07/03. Joint Applicants-Clinch River Breeder Reactor. 1p. 19294:017. 24X Fiche: 50-537, 83/07/05, 8307070200.
- 8307110142 Forwards testimony on whether hypothetical core disruptive accidents (HCDA) should be treated as DBAs, on HCDA analysis, on ASLB interest re emergency planning & on ASLB Questions 5 & 6. Certificate of Byc encl.

  EDGAR.O.L. Morgan, Lewis & Bockiys. EDGAR.G.L. Project Management Corp. 83/07/09 MILLER.M.E. Atomic Safety and Licensing Board Panel. 21pp. 19377: 204. 24X Fiche: 50-537.83/07/08.8307110142.
- --8307110149 Testimony of GH Clare, RE Hottel, AL Schwallie, HP Planchon & LE Strawbridge on whether hypothetical core disruptive accidents should be treated as BBAs. Certificate of Svc encl. CLARE, O. H. HOTTEL, R. E. SCHWALLIE, A. L. Joint Applicants-Glinch River Breeder Reactor. 83/07/05. 198pp. 19377:253. 24X Fiche: 50-537, 83/07/08, 8307110142.
- --8307t10158 Testimony of LW Deitrich, H Fauske, L Strawbridge & TW Ball re hypothetical core disruptive accident (HCDA) analyses. GRBR designed so HCDAs beyond DBA. Prof qualifications & Certificate of Svc encl.

  DEITRICH, L.W., FAUSKE, H.K., STRAWBRIDGE, L. Joint Applicants-Clinch River Breeder Reactor. 83/07/05. 166ep. 19378:091. 24X
  Fiche: 50-537, 83/07/08, 8307110142.
- --8307i10164 Testimony of HW Hibbitts.EK Sliger & LE Strawbridge re ASLB areas of interest related to emergency planning CRBR radioactive releases could contain sodium oxides & hydroxide aerosols.Prof qualifications & Certificate of Svc encl. HIBBITTS.H.W. SLICER.E.K., STRAMBRIDGE.L. Joint Applicants-Clinch River Breeder Reactor. 83/07/08. 32pp. 19378:237. 24X Fiche: 50-537, 83/07/08, 8307110142.
- --8307110168 Testimony of VD Hedges, JW Anderson & JE Karr responding to ASLB Areas of Interest 3 & 6. Owners mgt organization described Westinghouse, GE, Atomics Intl. S&W & Burns & Roe are project contractors. Certificate of Svc encl.

  HEDOES, V. D., ANDERSON, J. W., KARR, J. E. Joint Applicants-Clinch River Breeder Reactor. 83/07/08. 40pp. 19378: 289. 24X

  Fiche: 50-537, 83/07/08, 8307110142.
- B307120136 Forwards NRC testimpny on DBA spectrum, core disruptive accident analyses & ASLB Questions 4, 6, 7, 10, 12, 13 & 14, NRC & applicant joint proposed order of testimong listed.

  TURK. S.E., MIZUNO, O. S. Hearing Branch 1, B3/07/08. MILLER, M., HAND, C. H., LINENBERGER, G. Atomic Safety and Licensing Board Panel.

  4pp. 19419.001. 24X Fiche: 50-537, 83/07/08, 8307120156.

- --830712016B Testimony of RA Becker, HC Garg, S Hou, TL King, B Morris, CE Rossi, R Schemel, JJ Swift, AK Agrawal, JE Hanson & ET Rumble re adequacy of DBA spectrum. Core disruptive accidents may be excluded from DBA spectrum for CRDR. MyProf qualifications. BECKER. R. A. Clinch River Breeder Reactor Program Office, GARO, H. C. Equipment Qualification Branch. HQU. S. Mechanical Engineering Branch. B3/07/08. B3pp. 19419:005. 24X Fiche: 50-537, 83/07/08, 8307120156.
- ---B307120176 Testimony of CL Allen, LW Bell, HB Holz, LQ Hulman, JK Long, B Morris, JJ Swift, CR Bell, TA Butler, ET Rumble, D Swanson & TG Theofanous re analyses of core disruptive accidents. Prof qualifications encl.

  ALLEN, C. L., HOLZ, H. B. Clinch River Breeder Reactor Program Office.

  BELL, LW. Accident Evaluation Branch. B3/07/08. 171pp.

  19419:086. 24X Fiche: 50-537, 83/07/08, 8307120156.
- ---8307120188 Testimony of TL King on ABLB Question 4 re natural convective circulation. NRC accepts natural convective circulation in CRBR as viable mechanism for DHR Prof qualifications encl.

  KING.T.L. Clinch River Breeder Reactor Program Office. 83/07/08, 6pp. 19419:257. 24X Fiche:50-537,83/07/08,8307120156.
- --8307120193 Testimony of JQ Bpraul & AJ Ignatonis re ASLB Question & on GA. NRC considers GC responsibilities & activities integral part of GA. NRC will monitor GA & GC activities throughout CRBR const. Prof qualifications encl.

  SPRAUL.J. G. GA Branch. IGNATONIS.A. J. Region 2, Office of Director. 83/07/08. 8pp. 19419: 263. 24X Fiche: 50-537, 83/07/08.
- --8307120197 Testimony of LO Hulman, EF Branagan & DJ Perrotti on ABLB Question 9 re protective action guides. No rev to protective action guides necessary for CRIR. If guides revised, NRC will consider applicability at OL stage. Prof qualifications encl. HULMAN. L. O. Accident Evaluation Branch. BRANAGAN, E. F. Radiological Assessment Branch. PEROTTI. D. J. Emergency Preparedness Branch. 83/07/08. 21pp. 19419:271. 24X Fiche: 50-537, 83/07/08, 8307120156.
- --8307120203 Testimony of RJ Dube re ABLB Question 10 on mat1 control & accountability. R&D activities on measurement capabilities for mat1 control & accounting unnecessary for continued fuel safeguards. Prof qualifications encl.

  DUBE.R.J. Fuel Facility Safeguards Licensing Branch. 83/07/08.

  Spp. 19419: 292. 24X Fiche: 50-537. 83/07/08, 8307120136.
- --B307120211 Testimony of TL King & RM Stark re ASLB Question 12 on items identified for resolution at OL stage.NRC & applicants developing program & schedule to review & resolve items, to minimize impacts on final design & const.

  KING.T.L., STARK,R.M. Clinch River Braeder Reactor Program Office.
  B3/07/08. Spp. 19419:297. 24X Fiche: 50-537, B3/07/08, B307120156.
- --8307120220 Testimony of TL King re ASLB Question 13 on fuel sys fallback positions.Lists possible impacts on CRBR programmatic objectives from implementing NRC positions. Prof qualifications encl. KING, T. L. Clinch River Breeder Reactor Program Office. 83/07/08. 25pp. 19419:305. 24X Fiche: 50-537,83/07/08,8307120156.
- ---8307120232 Testimony of TL King on ASLE Question 14 re operation w/
  leaking fuel pins. Bodium entry into fuel pin may cause
  increased pellet-to-clad gap conductance, but would not
  adversely affect fuel performance. Prof qualifications encl.
  KINO. T. L. Clinch River Breeder Reactor Program Deffice. 83/07/08,
  4pp. 17419:330. 24X Fiche: 50-537,83/07/08,8307120136.
- B307120557 Limited appearance statement of TB Cochran re issues raised in CP proceeding Discusses radiological consequences of CRBR core disruptive accident & site suitability Certificate of Svc encl.

  CUCHRAN. T. B. Natural Resources Defense Council. CUCHRAN, T. B. Sierra Club. B3/07/08. SOpp. 19431:347. 24X Fiche: 50-537, B3/07/08, B307120557.
- 8307130211 Forwards Pp 53 & 54 to testimony of TL King & ET Rumble re adequacy of DBA spectrum.inadvertently omitted from 830708 filing.

  TURK.S.E. Hearing Branch 1. 83/07/11, MILLER.M., HAND, C. H., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 1p. 17508:065 24X Fiche: 50-537, 83/07/11, 8307130211.
- --B307130215 Pages 53 & 54 to testimony of TL King & ET Rumble readequacy of DBA spectrum.

  KING.T.L. Clinch River Breeder Reactor Program Office.

  RUMBLE.E.T. NRC No Detailed Affiliation Given. 83/07/11. 2pp.
  19508: 066. 24X Fiche: 50-537, 83/07/11, 8307130211.

DOCKET 50-538 MEMPHIS STATE UNIV. RESEARCH REACTOR
V. Operator Examinations

B307080427 Generic Ltr B3-12A to all nonpower reactor licensees re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/11. Michigan, Univ. of. 14pp. 19563:138. 24X Fiche:50-000.B3/07/11.B307080427.

DOCKET STN-50-546 MARDLE HILL NUCLEAR STATION, UNIT I

A. Application/construction stage documents & correspondence

8306060070 Generic Ltr 83-22 to all operating reactor licenses, applicants for OLs & holders of CPs for Westinghouse PMRs re safety evaluation of "Emergency Response Guidelines." Svc list encl.

EISENNUT, D. G. Division of Licensing, 83/06/03. Yankee Atomic Electric Co. 10pp 19563:116. 24X Fiche: 50-000, 83/06/03, 830660070.

8307070037 Advises that IN State Board of Health plans on evaluating environ radioactive contamination from plant operation. Water samples split & arrangements made to split milk & other liquid samples.

PICKARD.R.C. Indiana, State of. 83/06/30, YDUNGBLOOD.B.J. Licensing Branch 1. 1p. 19293:252. 24X Fiche:50-546.83/06/30, 8307070039.

B307090126 Notification of B30711-13 site meetings w/util for preliminary discussion of info re environ review & site tour. Proposed meeting agenda encl.

O'CONNOR, P. W. Licensing Branch 1 83/06/30. YOUNGBLOOD, B. J. Licensing Branch 1. 8pp. 19366:353. 24X Fiche: 50-946.83/06/30, B307090126.

8307070051 Responds to 830608 request for review of proposal re plant operation. Proposed project will not adversely affect any area or jurisdiction of Natl Park Svc POPE. R.B. Interior. Dept. of. National Park Service. 83/07/01. YUUNOBLOOD. B. J. Licensing Branch 1. lp. 19293:258. 24X Fiche: 30-546.83/07/01.8307070051.

8307200231 Notification of 830707 meeting w/technical review committee in Bethesda, MD to discuss review of D4, D5 % E steam generator mods.

HDPKINS.J.B. Licensing Branch 4. B3/07/01 ADENSAM, E. Q. Licensing Branch 4. 2pp. 19670:254 24X Fiche: 50-000, 83/07/01, 8307200231.

B306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EIGENHUT, D. 9. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fichs: 50-000, 83/07/05, 8306270397.

8307060329 Generic Ltr 83-27 to all licenseus & applicants for operating power reactors & holders of CPs for power reactors re surveillance intervals in 875. Byc list encl. EISENHUT. D. G. Division of Licensing. 83/07/06 Consolidated Edison Co. of New York, Inc. 16pp. 19669:254. 24x Fiche: 50-000, 83/07/06, 8307060329.

8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for QL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list enci. EISENHUT, D. G. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669-269 24X Fiche: 30-000, 83/07/08, 8307080169.

B307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4.05 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
BUTTERFIELD.L. Steam Generator Owners Group. B3/07/18
EISENHUT, D. G. Division of Licensing. 3pp. 1964:114. 24X
Fiche: 90-000, 83/07/18, 8307210300.

8307250124 Summary of 830707 meeting w/technical review committee in Bethesda,MD re Model D4/D5/E steam generator mod.Viewgraphs encl. HOPKINS,J.B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 26pp. 19738:132. 24X Fiche:50-000,83/07/18,8307250124. C. Utility Environmental Report (ER), amends & correspondence

B307210035 Comments on B30712 public meeting re environ concerns for application for OLs. Util should present analyses of environ risks associated w/more severe types of very low probability accidents in environ rept.

FREY. D. G. Audubon Society. B3/07/12. YOUN9BLOOD, B. J. Licensing Branch 1. App. 1966B: 330. 24X Fiche: 50-546, 83/07/12, 8307210035.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

B307130359 Discusses arrangements for B30711-13 environ site visit associated w/EIS & B30712 environ review public meeting in Madison. IN. Agenda encl.

NOVAN, T. M. Assistant Director for Licensing. B3/07/01. TODD, T.R. Jefferson County, IN. 3pp. 1950B:356. 24X Fiche:50-546,63/07/01. B307130359.

f. Security, medical, emergency & fire protection plans

8307110424 Forwards IE Insp Repts 50-946/83-08 & 90-547/83-08 on B30613-17.No noncompliance noted. KNOP.R.C. Region 3. Office of Director. 83/06/27. SHIELDS, S. W. Public Service Co. of Indiana, Inc. 2pp. 19382: 221. 24X Fiche: 50-546,83/06/27,8307110424.

--8307110430 IE Insp Repts 50-546/83-08 & 50-547/83-08 on 830613-17. No noncompliance noted Major areas inspected licensee actions on previous insp findings. IOCFR30. 55(e) items: IE bulletins & circulars & fire prevention, protection & suppression. PELKE, P. R., KONKLIN, J. E. Region 3. Office of Director. 83/06/24, 7pp. 19382. 223. 24X Fiche: 50-546, 83/06/27, 8307110424.

B307190209 Forwards detailed control room design review per requirements of Generic Ltr B2-33, "Suppl 1 to NUREO-0737 Requirements for Emergency Response Capability." Reg Guide 1.97 implementation rept will be submitted by B31101. SHIELDS.S.W. Public Service Co. of Indiana, Inc. B3/07/15, E15ENHVT.D.G. Division of Licensing. 113pp. 19628:322. 24) Fiche: 50-546, 83/07/15, 8307190209.

### Q. Adjudicatory correspondence

830705016B Memorandum & order denying Sassafras Sot & Valley Watch 830416 & 19 respective petitions to intervene. Petitioners may amend petitions within 30 days of order. Save the Valley petition to intervene granted. LINEMBERGER. G., PARIS. O. H., SMITH, I. W. Atomic Safety and Licensing 80 ard Panel. 83/06/30. 10pp. 19199:171. 24X Fiche: 50-546, 83/06/30.8307050168.

8307060204 Notices of appearance in proceeding Contificate of Svc encl. NDLAND.J. D., POPE.J. R., KRUSE.L. M. Public Service Co. of Indiana. Inc. 83/07/01. 3pp. 19250:226. 24X Fiche: 50-546.83/07/01.

830726026B Amend to petition to intervene in OL hearing Petitioner makes requisite showing that members have standing & have authorized petitioner to represent interests Contentions to be litigated identified Certificate of Svc encl.

LYNCH. H. P. Sassafras Audubon Society. 83/07/21. Atomic Safety and Licensing Board Panel. 12pp. 19726:114. 24x
Ficho: 50-546,83/07/21,8307260268.

8307260366 Requests correspondence re util be sent to author address.

MODDY.M.K. Sassafras Audubon Society 83/07/25. NRC - No Detailed Affiliation Given. 1p. 19733-040. 24X Fiche: 50-546, 83/07/25, 8307260366.

# I. Financial information

B307190140 Forwards Annual Financial Repts 1982 for Public 8vc Co of Indiana Inc. & Wabash Valley Power Assoc.Inc.

SHIELDS.S.W. Public Service Co. of Indiana, Inc.
BENTON, H.R. Office of Nuclear Regulation, Director. 1p.
19636:109. 24x Fiche: 50-544, B3/07/14, B307190140.

---8307190142 Annual Financial Rept 1782 BARKER.H.A., MENSCER.D.V. Public Service Co. of Indiana, Inc. 83/01/28 43pp. 17636:110. 24X Fiche: 50-546:83/07/14:8307190140.

---8307190143 Annual Financial Rept 1982. LOY.C. Wabash Valley Power Association, Inc. 83/07/14. 23pp 19636:153. 24X Fiche:50-546.83/07/14.8307190140.

- $\mathbf{Q}_{r}$  Inspection reports. IE Bulletins  $\boldsymbol{\ell}$  correspondence
- B307060010 Requests assignment of inspector to verify program for improved control over electrical const program beginning B30613.per meeting prerequisites outlined in B30202 confirmatory action ltr.
  SHIELDS.5 W. Public Service Co. of Indiana. Inc. B3/06/10. MEPPLER J G. Region J. Office of Director. Ip. 19251:015. 24X Fiche: 50-546, 83/06/10, 8307060010.
- 8307110424 Forwards IE Insp Repts 50-546/83-08 & 50-547/83-08 on B30613-17.No noncompliance noted. KNOP.R.C. Region 3. Office of Director. 83/06/27. SHIELDS.S.H. Public Service Co. of Indiana. Inc. 2pp. 19382:221. 24X Fiche:50-546:83/06/27.8307110424.
- --8307110430 IE Insp Repts 50-546/83-08 & 50-547/83-08 on 830613-17. No noncompliance noted. Major areas inspected: licensee actions on previous insp findings. 10CFR50. 55(e) items. IE builetins & circulars & fire prevention.protection & suppression. PELKE.P.R. & KONKLIN. J. E. Region 3. Office of Director. B3/06/24. 7pp. 19382:223. 24X Fiche: 50-546.83/06/27.8307110424.
- 8307140221 Forwards IE Insp Repts 50-546/B3-07 & 50-547/83-07 on B30607-10.No noncompliance noted.

  LITTLE:M.S. Region 3, Office of Director. B3/06/30. SHIELDS:S.W. Public Service Co. of Indiana. Inc. 2pp. 19523:155. 24X

  Fiche: 50-546:83/06/30:8307140221.
- --B307140226 IE Insp Repts 50-546/83-07 & 50-547/83-07 on B30607-10. No noncompliance noted Major areas inspected procedures, work activities & record review for structural steel & supports & for safety-related components & supports.

  KEATING.D.E., CILIMBERO.R.L., DANIELSON.D.H. Region 3. Office of Director. B3/06/30. 7pp. 19523:157. 24X Fiche: 50-546.83/06/30, 8307140221.
- B307190210 Requests assignment of inspector beginning B30707, to verify adequacy of program for improved control over electrical cable tray installation.

  BHIELDS W. Public Service Co. of Indiana, Inc. 83/07/01.

  KEPPLER, J. G. Region 3, Office of Director. Ip. 19629:079. 24X

  Fiche: 30-546, 83/07/01, 8307190210.
- B307190172 Informs that completion date for Item II of B30415 ltr rg cable tray hanger insp extended to B30805 Corrective actions for procedures & nonconformances created delay.

  BHIELDS.S.W. Public Service Co. of Indians, Inc. 83/07/06.

  KEPPLER.J.G. Region 3, Office of Director. 2pp. 19634:170. 24X Fichs: 50-546:83/07/06,8307190172.
- B306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem " Svc list encl.
  JURDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563.293. 24X Fiche: 50-000, B3/07/11, B306270401.
- 8307180073 Verifies that program addressing 830202 confirmatory action ltr (CAL) Items 2-6.adequate for resumption of electrical work.per util 830415 & 0701 ltrs. CAL closed. KEPPLER.J. G. Region 3, Office of Director. 83/07/11. SHIELDS.S.W. Public Service Co. of Indiana, Inc. 2pp. 19560:199. 24X Fiche: 50-546.83/07/11,8307180073.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24x Fiche 50-000.83/07/12,8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list encl. TAYLOR J.M. Division of QA. Safeguards & Inspection Programs (Post 8301031. 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000,83/07/14,8306270406.
- S. Reportable occurrences, LERs & related correspondence
- 8307030174 Interim deficiency rept re possible Southwest Steel Fabricator nunconforming QA program for structural steel used in safety-related areas Initially reported on 830524. Review continuing. Next rept due by 830916. SHIELDBS. W. Public Service Co. of Indiana, Inc. 83/06/22. KEPPLER. J. G. Region 3, Office of Director 1p. 19199:028. 24X Fiche: 50-546.83/06/22,8307050174.
- 8307110424 Forwards IE Insp Repts 50-546/83-08 % 50-547/83-08 un B30613-17. No noncompliance noted. 
  KNOP.R.C. Region 3, Office of Director 83/06/27. SHIELDS, S. W. Public Service Co. of Indiana. Inc. 2pp. 19382: 221 24X Fiche: 30-546, 83/06/27, 8307110424.

- --8307110430 IE Insp Repts 50-546/83-08 & 50-547/83-08 on B30613-17. No noncompliance noted Major areas inspected incenses actions on previous insp findings. IOCFRSO. 55(e) items. IE bulletins & circulars & fire prevention, protection & suppression. PELKE.P.R. Region 3. Office of Director. B3/06/24. 7pp. 19382:223. 24X Fiche: 50-546.83/06/27.8307110424
- B307110306 Final deficiency rept re heat sink failures on loop power supply cards & contact bounce in mercury relay utilized on temp channel test cards of Westinghouse 7300 process protection sys. Initially reported on B30603.

  SHIELDS.S. W. Public Servico Co. of Indiana. Inc. B3/06/30.

  KEPPLER.J. G. Region 3. Office of Director 2pp. 19375:007. 24X Fiche: 30-546.83/06/30.8307110306.
- B307190261 Interim deficiency rept relack of QA involvement in fabrication of seismic Category I HVAC duct work not serving safety-related function. Initially reported on B30607 Next rept expected by B31104.
  SHIELDS.S.W. Public Service Co. of Indiana. Inc. B3/07/06.
  KEPPLER, J. G. Region 3, Office of Director. 1p. 19628.267. 24X Fiche: 50-346.83/07/06.B307190261.
- 8307190039 PNO-111-83-059 licensee authorized to resume remaining electrical safety-related const. GA site managers replaced, insp procedures revised & personnel retrained. WILLIAMS, C., LITTLE, M., SPESSARD, R. Region G. Office of Director. 63/07/11. 1p. 19635:149. 24X Fiche. 50-546,83/07/11,8307190039.
- 8307220490 Interim deficiency rept resix sheared pinion keys in Limitarque Model SB-O valve motor operators installed by Westinghouse: Initially reported on 820805. Item not reportable per 10CFR50. 55(e). SHIELDS, SW. Public Bervice Co. of Judiana. Inc. 83/07/13. KEPPLER.J. G. Region 3, Office of Director 2pp. 19685:097—24X Fiche: 50-546.83/07/13.8307220490.
- B307220460 Interim deficiency rept re welding techniques not covered by Brown-Boveri Electric. Inc GA program Initially reported on B30925. Brown-Boveri revised procedures to include controls on welding activities. Next rept expected by B31021. SHIELDS.S.W. Public Service Co. of Indiana. Inc. B3707714. KEPPLER.J.O. Region 3. Office of Director. 2pp. 19686:116. 24X Fiche: 50-546.83707714.8307220460.
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION. UNIT 2

  A. Application/construction stage documents & correspondence
- 8306060070 Generic Ltr 83-22 to all operating reactor licensees, applicants for OLs & holders of CPs for Westinghouse PWRs re-safety evaluation of "Emergency Response Guidelines."

  Byc list encl.
  EISENHUT, B.G. Division of Licensing. 83/06/03. Yankee Atomic Electric Co. 10pp. 19563:116 24X Fiche: 50-000, 83/06/03, 8306060070.
- 8307070039 Advises that IN State Board of Health plans on evaluating environ radioactive contamination from plant operation. Water samples split & arrangements made to split milk & other liquid samples.

  PICKARD.R C. Indiana, State of 83/06/30 YOUNGBLOOD, B. J. Licensing Branch 1. 1p. 19293 252. 24X Fiche 30-546,83/06/30,8307070039.
- 8307090126 Notification of 830711-13 site meetings w/util for preliminary discussion of lafe re environ review & site tour. Proposed meeting agenda encl.

  G'CONNOR.P.W. Licensing Branch 1. 83/06/30. YOUNGBLOOD.B.J. Licensing Branch 1. 89p. 19366:353 24x Fiche 50-546,83/06/30.830790126.
- B307070051 Responds to B30608 request for review of proposal re plant operation Proposed project will not adversely affect any area or juvisdiction of Natl Park Svc.
  POPE,R.R. Interior, Dept. of, National Park Service B3/07/01.
  YOUNDBLOOD,B.J. Licensing Branch 1. ip. 19293.258 24X
  Fiche: 50-546,83/07/01,8307070051
- B307200231 Notification of B30707 meeting w/technical review committee in Bethesda,MD to discuss review of D4.D3 % E steam generator mods HOPKINS,J.B. Licensing Branch 4. B3/07/01. ADENSAM, E.G. Licensing Branch 4. 2pp. 19670:254. 24X Fiche: 50-000, 83/07/01, 8307200231.
- 9306270397 Generic Ltr 83-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl EISENHUT. D.O. Division of Licensing. 83/07/05 Consolidated Edison Co. of New York, Inc. 16pp. 19390-317 24x Fiche: 50-000.83/07/05.8306270397

- 8307060327 Generic Ltr 83-27 to all licensees & applicants for aperating power reactors & holders of CPs for power reactors re surveillance intervals in STS. Svc list encl. EISENHUT, D. G. Division of Licensing 83/07/04. Consolidated Edison Co. of New York, Inc. 16pp. 19669-254. 24x Fiche: 50-000, 83/07/06, 8307060329.
- 9307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events Svc list encl EISENHUT, D. G. Division of Licensing 83/07/08. Consolidated Edison Co. of New York. Inc. 38pp. 19669:269. 24X Fiche: 50-000,83/07/08,8307080169.
- 3307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4,D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
  BUTTERFIELD.L. Steam Generator Owners Group. 83/07/18.
  EISENHUT,D.G. Division of Licensing. 3pp. 19664:114. 24X
  Fichs: 50~000,83/07/18,8307210300.
- 3307250124 Summary of B30707 meeting w/technical review committee in Bethesde, MD re Model D4/D5/E steam generator mod. Viewgraphs encl.

  HOPKINE J B. Licensing Branch 4. 83/07/18. Licensing Branch 4. 26pp. 19738: 132. 24% Fiche: 50-000, 83/07/18. 8307250124.
- 1. Utility Environmental Report (ER), amends & correspondence
- 3307210035 Comments on 830712 public meeting re environ concerns for application for OLs. Util should present analyses of environ risks associated w/more severe types of very law probability accidents in environ rept.

  FREY. D. G. Audubon Society. 83/07/12. YOUNGBLOOD, B. J. Licensing Branch I. 6pp 19668:330. 24% Fiche: 50-546,83/07/12,8307210035.
- ). NRC Draft/Final Environmental Statements, suppls & correspondence
- 3307130359 Discusses arrangements for 830711-13 environ site visit associated w/EIS & 830712 environ review public meeting in Madison. IN. Agenda encl.
  NOVAK.T.M. Assistant Director for Licensing. 83/07/01. TUDD.T.R. Jefferson County. IN. 3pp. 19508.356. 24X Fiche: 50-546.83/07/01.
- T. Security, medical, emergency & fire protection plans
- 3307110424 Forwards IE Insp Repts 50-546/83-08 & 90-547/83-08 on B30613-17 No noncompliance noted KNOP, R.C. Region 3, Office of Director 83/06/27, SHIELDS, S. W. Public Service Co. of Indiana, Inc. 2pp. 19382:221 24X Fiche: 50-546,83/06/27,8307110424.
- --8307110430 IE Insp Repts 50-346/83-08 % 90-547/83-08 on 830613-17. No noncompliance nated Major areas inspected: licensee actions on previous insp findings. 1007R780. 55(e) items. IE bulletins & circulars & fire prevention, protection & suppression. PELKE.P R. Region 3. Office of Director 83/06/24. 7pp. 19382 823. 24X Fiche: 30-846.83/06/27.8307110424.
- 1307190209 Forwards detailed control room design review per requirements of Generic Ltr. 82-33. "Suppl I to NUREG-0737 Requirements for Emergency Response Capability." Reg Guida 1 97 implementation rept will be submitted by 83101. SHIELDS.S.W. Public Service Co. of Indiana, Inc. 83/07/15. EISEMUNT.D.O. Division of Licensing 113pp. 19628:322. 24X Fiche: 50-546,83/07/15,8307190209

# >. Adjudicatory correspondence

- 1307050168 Memorandum & order denying Bassafras Soc & Valley Watch 830416 & 19 respective petitions to intervene Petitioners may amond petitions within 30 days of order Bave the Valley petition to intervene granted.

  LINENBERGER. 0., PARIS, O. H., SMITH, I. W. Atomic Safety and Licensing Board Panel. 83/06/30. 10pp. 19199.171. 24X Fiche: 50-546, 83/06/30,8307050168.
- 1307060204 Notices of appearance in proceeding Certificate of Svc enct. NOLAND.J.D., POPE.J.R., KRUSE.L.M. Public Service Co. of Indiana. Inc. 83/07/01. 3pp. 19250: 226. 24x Fiche: 50~546.83/07/01. 8307060204.
- I307260268 Amend to petition to intervene in OL hearing. Petitioner makes requisite showing that members have standing & have authorized petitioner to represent interests. Contentions to be litigated identified. Certificate of Svc encl. LYNCH. M.P. Sassafras Audubon Society. 83/07/21. Atomic Safety and Licensing Board Panel. 12pp. 19726:114. 24X. Fiche: 50-546.83/07/21.8307260268.

- 8307260366 Requests correspondence re util be sent to author address MCODY,M.K. Sassafras Audubon Society. B3/07/25. NRC - No Detailed Affiliation Given. 1p. 19733:040, 24X Fiche: 50-546.83/07/25,8307260366.
- I. Financial information
- 8307190140 Forwards Annual Financial Repts 1982 for Public Evc Co of Indiana, Inc. & Wabash Valley Power Assoc, Inc. 8HIELDS.S.W. Public Service Co of Indiana, Inc. 83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19636:109. 24X Fiche: 50-546.83/07/14.8307190140.
- --8307190142 Annual Financial Rept 1982. BARKER, H. A., MENSCER, D. V. Public Service Co. of Indiana, Inc. 83/01/28. 43pp. 19636:110. 24X Fiche: 50-546,83/07/14,8307190140.
- --8307190143 Annual Financial Rept 1982. LOY,C. Wabash Valley Power Association, Inc. 83/07/14. 23pp. 19636: 153. 24X Fiche: 50-546,83/07/14,8307190140.
- G. Inspection reports, IE Bulletins & correspondence
- 8307060010 Requests assignment of inspector to verify program for improved control over electrical const program beginning 830613,ppr meeting prerequisites outlined in 830202 confirmatory action ltr. 841ELDS.8.W. Public Service Co. of Indiana, Inc. 83/06/10. KEPPLER.J.C. Region 3, Office of Director. 1p. 19251:015. 24X Fiche: 50-546,83/06/10.8307060010.
- B307110424 Forwards IE Insp Repts 50-546/83-08 % 50-547/83-08 on 830613-17. No noncompliance noted. KNDP.R.C. Region 3, Office of Director. 83/06/27. SHIELDS, S.W. Public Service Co. of Indiana, Inc. 2pp. 19382: 221. 24X Fiche: 50-546.83/06/27, 8307110424.
- --8307110430 IE Insp Repts 30-546/83-08 & 50-547/83-08 on 830613-17. No noncompliance noted Mayor areas inspected: licensee actions on previous insp findings. IOCFR50. 55(e) items. IE bulletins & circulars & fire prevention. protection & suppression. PELKE. P. R. KONKLIN. J. E. Region 3. Office of Director. 83/06/24. 7pp. 19382: 223. 24X Fiche: 50-546.83/06/27.8307110424.
- 8307140221 Forwards IE Insp Repts 50-546/83-07 % 50-547/83-07 on 830607-10. No noncompliance noted.
  LITLE W.S. Region 3, Office of Director. 83/06/30. SHIELDS, S. W. Public Service Co. of Indiana, Inc. 2pp. 19323:155. 24X
  Fiche: 30-546/83/06/30/8307140221.
- --8307140226 IE Insp Repts 50-546/83-07 % 50-547/83-07 on 830607-10. No noncompliance noted Major areas inspected:procedures, work activities & record review for structural steel & supports & for safety-related components & supports.

  MEATINO. D. E. C. CILIMBERG. R. L. DANIELSON. D. H. Region 3, Office of Director. 83/06/30. 7pp. 19523:157. 24X Fiche: 50-546,83/06/30,8307140221.
- 8307190210 Requests assignment of inspector beginning 830707 to verify adequacy of program for improved control over electrical cable tray installation.

  SHIELDS, S. W. Public Service Co. of Indiana, Inc. 83/07/01.

  KEPPLER, J. G. Region 3, Office of Director. 1p. 19629:079. 24X

  Fiche: 50-546,83/07/01,8307190210.
- 8307190172 Informs that completion date for Item II of 830415 itr recable tray hanger insplextended to 830805.Corrective actions for procedures & nonconformances created delay.

  SHIELDS.S.W. Public Service Co. of Indiana, Inc. 83/07/06.

  KEPPLER.J.O. Region 3. Office of Director. 2pp. 19634:170. 24x

  Fiche: 50-546.83/07/06.8307190172.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche:50-000.83/07/11.8306270401.
- 8307180073 Verifies that program addressing 830202 confirmatory action ltr (CAL) Items 2-6. adequate for resumption of electrical work, per util 830415 & 0701 ltrs. CAL closed.

  KEPPLER, J. G. Region 3. Office of Director. 83/07/11. SHIELDS. S. W. Public Service Co. of Indiana. Inc. 2pp. 17360: 197. 24X

  Fiche: 50-546.83/07/11.8307180073.
- 8306270404 JE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche: 50-000, 83/07/12, 8306270404.

- 8306270406 IE Info Notice 83-48. "Gaseous Effluent Releases of Radioactive I-125 & [-131 in Ercess of NRC Limits." Svc list encl.
  TAYLDR, J. M. Division of GA. Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche:50-000.83/07/14.8306270406.
- 8. Reportable occurrences. LERs & related correspondence
- B307030174 Interim deficiency rept re possible Southwest Steel Fabricator nonconforming QA program for structural steel used in safety-related areas. Initially reported on 830524. Review continuing, Nert rept due by 830716. SHIELDS.S.W. Public Service Co. of Indiana, Inc. B3/06/22. KEPPLER.J.G. Region 3, Office of Director. ip. 19199: 028. 24x Fiche: 50-546,83/06/22,8307050174.
- 8307110424 Forwards IE Insp Repts 30-546/83-08 & 50-547/83-08 on 830663-17. No noncompliance noted. RNGP, R. C. Région 3. Office of Director. 83/06/27. SHIELDS, S. W. Public Service Go. of Indiana. Inc. 2pp. 19382: 221. 24X Fiche: 50-546. 83/06/27, 8307110424.
- --8307110430 IE Insp Repts 50-546/83-08 & 50-547/83-08 on 830613-17. No noncompliance noted Major areas inspected:licensee actions on previous insp findings. 10CFR50. 55(e) items. IE bulletins & circulars & fire prevention, protection & suppression. PELKE.P.R. Region 3. Office of Director. 83/06/24. 7pp. 19382: 223. 24X Fiche: 50-546, 83/06/27, 8307110424.
- 8307110306 Final deficiency rept re heat sink failures on loop power supply cards & contact bounce in mercury relay utilized on temp channel test cards of Hestinghouse 7300 process protection sys. Initially reported on 830603.
  SHIELDS, S. H. Public Service Co. of Indians, Inc. 83/06/30.
  KEPPLER, J. C. Region 3, Office of Director. 2pp. 19375:007. 24X Fiche: 50-546,83/06/30,8307110306.
- 8307190261 Interim deficiency rept re lack of QA involvement in fabrication of sedsmic Category I HVAC duct work not serving safety-related function. Initially reported on 830607. Next rept expected by 831104.
  SHIELDS.S.W. Public Service Co. of Indiana, Inc. 83/07/06.
  KEPPLER.J.O. Region 3. Office of Director. 1p. 19628:267. 24X Fichs: 50-546.83/07/06.8307190261.
- 8307190039 PNO-III-83-059: licensee authorized to resume remaining electrical safety-related const. GA site managers replaced, insp procedures revised & personnel retrained. HILLIAMS.C., LITILE, W. BPESSARD, R. Region 3, Office of Director 83/07/11. 1p. 19635:149. 24X Fiche: 50-546.83/07/11.8307190039.
- 8307220490 Interim deficiency rept re six sheared pinion keys in Limitorque Hodel 88-D valve motor operators installed by Hestinghouse. Initially reported on 920805. Item not reportable per 100FR90. 55(e).
  BHIELDS, S. M. Public Service Co. of Indiana. Inc. 83/07/13. KEFPLER. J. G. Region 3, Office of Director 2pp. 19885: 097. 24X Fiche: 50-546, 83/07/13, 8307220490.
- 8307220460 Interim deficiency rept re welding techniques not covered by Brown-Boveri Electric. Inc 8A program Initially reported on B30528. Brown-Boveri revised procedures to include controls on welding activities. Next rept expected by 831021. BHIELDS, G. H. Public Service Co. of Indiana. Inc. 63/07/14. KEPPLER, J. G. Region 3. Office of Director. 2pp. 19685: 116. 24x Fiche: 30-546, 83/07/14, B307220460.
- DOCKET SIN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 8306270395 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Gulf, LaSalle & Susquehanna re TMI Task Action Plan Item 1.9.1, "Special Low Power Testing & Training & Recommendations for BMRs." Swc list ent.
  EISENHUT, D. 9. Division of Licensing. 33/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, 83/06/27, 8306270395.
- DOCKET SYN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 8306270395 Generic Ltr 83-24 to all DMR applicants for Di. & holders of Dis for Grand Gulf, LaSalle & Susquehanna re IMI Task Action Plan Item I.Q.i. "Special low Power Testing & Training & Recommendations for BMRs." Swc list encl. EISENHUT, D.Q. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche:50-000.63/06/29. B306270395.

- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8306270395 Generic Ltr 83~24 to all BWR applicants for OL & holders of OLs for Grand Gulf.LaSaile & Susquehanna re IMI Task Action Plan Item I. G. i. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list enci. EISENHUT.D. G. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115 24x Fiche: 50-000, 83/06/29, 8306270395.
- 8306270397 Generic Ltr 83-26 to all applicants for DLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity. Svc list encl. EISEMINIT.D.Q. Division of Licensing 83/07/05. Consolidated Edison Co. of New York. Inc. 16pp. 19390-317. 24x Fiche: 50-000, 83/07/05, 8306270397.
- 8307080169 Generic Ltr 83-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATMS events Svc list encl. EISEM-MUT, D. Q. Division of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669-269. 24x Fiche: 50-000, 83/07/08, 8307080169.
- G. Inspection reports, IE Bulletins & correspondence
- B30427040) IE info Notice B3-46. "Common Made Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JURDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24x Fiche:50~000.83/07/11.8306270401.
- 8304270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JURNOAM.E.L. Division of Emergency Preparedness & Englineering Response (Post 930103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24X Fiche 50-000.83/07/12.8306270404.
- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list encl.
  TAYLOR.J.M. Division of GA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19715:270. 24X Fiche: 50-000, 83/07/14, 8306270406.
- DOCKET SIN-50-557 BLACK FOX STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 8306270395 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Gulf-LaSelle & Susquehanna re TMI Task Action Plan Item 1.0.1. "Special Low Power Testing & Training & Recommendations for BWRs." Svr list bent!. EISENHUT.D. 6. Division of Licensing. 83/06/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche:50-000,83/06/29.
- B306270397 Generic Ltr B3-26 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for diesel fuel impurity, Svc list encl. EISENHUT, D. G. Division of Licensing. B3/07/05. Consolidated Edison Co. of New York, Inc. 16pp. 19390:317. 24X Fiche: 50-000.83/07/05, 8306270397.
- 8307080169 Generic Ltr 83-28 to all licenses of operating reactors, applicants for GL & holders of CPs re required actions based on generic implications of Salem ATMS events. Svc list encl. EISENHUID, B. Obivision of Licensing. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:267. 24X Fishe: 50-000,83/07/08,8307080169.
- G. Inspection reports, IE Bulletins & correspondence
- 8306270401 IE Info Notice 83-46, "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl. JURDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11 Consolidated Edison Co. of New York, Inc. 154pp. 19563:293. 24X Fiche: 50-000,83/07/11,8306270401.
- 8306270404 IE Info Notice 83-47. "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:153. 24% Fiche 50-000.83/07/12.8306270404.

8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Svc list

encl.
TAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). B3/07/14. Consolidated Edison Co. of New York. Inc. 114pp. 19715:270. 24X Fiche:30-000.83/07/14.B306270406.

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

S. Reportable occurrences, LERs & related correspondence

8307120250 Second interim deficiency rept re nondivisional power received by transfer switches to auxiliary feedwater sys. Initially reported on 830202.Redundant circuits identical to existing design provided. Next rept expected by 830927. MILLS.L.M. Tennessee Valley Authority. 83/06/27. D'REILLY, J. P. Region 2. Office of Director. 3pp. 19423:035 24X Fichs: 50-000, 83/06/27, 8307120250.

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2 S. Reportable occurrences, LERs & related correspondence

8307120250 Second interim deficiency rept re nondivisional power received by transfer switches to auxiliary feedwater sys. Initially reperted on 830202. Redundant circuits identical to existing design provided. Next rept expected by 830927. MILLS. L. M. Tennessee Valley Authority. 63/06/27. O'REILLY, J. P. Region 2. Office of Director. 3pp. 19423:035. 24X Fiche: 50-000, 83/06/27, 8307120250.

#### DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANDQA PARK, CA

8307110648 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matis stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13 REMLEY.M.E. Rockwell International Corp. 2pp. 19434:106.

8307050081 Responds to 830612 ltr re license renewal application.
Commission 830602 order, addressing requests for hearings & procedures for filing intervention or limited appearance statements, encl. W/o encl,
HANCHETT, J. 9. Region 5, Office of Director. 83/06/28. BELKNAP, L. Affiliation Unknown. 1p. 19220:192.

--8307080089 Requests date, location & time of hearing on application for license renewal. BELKNAP.L. Affiliation Unknown. 83/06/12. Commissioners, 1p. 1920: 153.

9307120467 Package of eight citizen requests for informal hearing re effects of licensed reactor on community. MINEOURA,K., MINELAND,B., JACKSON,K. Affiliation Unknown. 83/06/28. PAGE,R.G. Uranium Fuel Licensing Branch. 8pp. 19424:197.

8307280184 Memorandum & order directing licensee to answer petitions to intervene within 10 days after svc of order NRC may answer petitions within 13 days after svc of order if NRC decides to appear.

LAZO.R.M. Atomic Safety and Licensing Board Panel. 83/07/26. Rockwell International Corp. 4pp. 19791:289.

DOCKET 70-0027 BABCOCK & WILCOX CO. , LYNCHBURG, VA

8307110596 Advises that proposal to extend completion of approved interim security measures described in 820813 ltr by 830228 acceptablesper 821201 request. 8MITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/10. REGAN.N. Bebcock & Wilcox Co. 1p. 19391:312.

8307110649 Advises that Matls & Plant Protection Amend MPP-1 to License 8MM-42 revised, amending License Condition 2.1 to update measurement std lists in fundamental nuclear matl control plan. Submittal of new std calibr data summary requested. RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch. 83/01/24. CORDANI, R. A. Babcock & Wilcox Co. 2pp. 19434:053.

8307110551 Advises that unnumbered license condition to Amend MPP-1 to License BNM-42 issued, approving discards in response to 820920 ltr ra use of DOE/NRC Forms 741,742 & 742C & DOE Rept M-742.

SMITH, C. N. Fuel Facility Safeguards Licensing Branch. 93/02/04. CORDANI, R. A. Babcock & Wilcox Co. 2pp 19434:110.

B307110666 Advises that revised pages to physical security plan acceptable. NRC withholding approval of security personnel qualification training & equipment plan pending submittal of pages inadvertently omitted from 830119 ltr.
SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/02/04. REGAN.N. Babcock & Wilcor Co. 1p 19434.071

8307110630 Advises that Matis & Plant Protection Amend MPP-1 to License SNM-42 amended revising Section 9.1.0 set forth in encl.per 830203 transmittal of three pages to security personnel qualification training & equipment plan BROWN.W.B. Fuel Facility Safeguards Licensing Branch. 83/02/09. REGAN.N. Babcock & Wilcox Co. 2pp. 19434:117.

8307220282 Forwards IE Safeguards Insp Rept 70-0027/83-12 on 830624-28. No noncomptiance hoted Rept withheld (ref 100FR2.790).

870HR, J. P. Division of Emergency Preparedness & Materials Safety.

83/07/13 ECKERT, J. P. Babcock & Wilcor Co. 2pp. 19891:342.

DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT

B30709009B Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid 7 solid waste math stored onsite. Appropriate revs to fundamental nuclear math control submitted.
SMITH.C.N. Fuel Facility Safeguards Licensing Branch. B3/01/13. ESKRIDGE.H. Combustion Engineering, Inc. 2pp. 17366:325.

8307200825 "Occupational Radiation Exposures,1981-82," W/830708 ltr. EBKRIDGE,H.E. Combustion Engineering, Inc. 83/07/08. CROW.W.T. Uranium Fuel Licensing Branch. 6pp. 19672:265.

8307200372 Lists beta sampling results obtained during telcon.Licensee pians no further action on Tc beta analysis. BIDINOER.O.H. Uranium Fuel Licensing Branch. 83/07/13. CROW.W.T. Uranium Fuel Licensing Branch. 1p. 17672:263.

8307280321 Forwards IE Safeguards Insp Rept 70-0036/83-02 on 830620-23. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/07/26. LICHTENBERGER Combustion Engineering, Inc. 2pp. 19789: 240.

--8307280325 1E Safeguards Insp Rept 70-0036/83-02 on 830620-23 No moncompliance noted Major areas inspected matt control & accountability, Details withheld Cref 10CFR2,7701, MADEDALT J., PATTERSON, J. P., CREED, J. R. Region 3, Office of Director. 83/07/25 ip 19789: 242.

DOCKET 70-0044 STANFORD UNIV. . STANFORD, CA

8307150151 IE Insp Findings & Licensee Ack dtd 830303 of License SNM-56. Insp Findings:no violations observed.

\* Region 9. Office of Director. 83/03/03. 1p. 19535:233.

DOCKET 70-0115 WASHINGTON, UNIV. QF. SEATTLE, WA

8307180244 Ack receipt of 830701 ltr informing NRC of steps taken to correct violations noted in IE insp of License SNM-108 on 830517.

BOOK.H.E. Region 5. Office of Director: 83/07/13. MILLER.W.P. Washington. Univ. of

~~8307180245 Responds to NRC 830607 ltr re violations noted in IE insp of License SNM-108 on 830517. Corrective actions: tests scheduled on shorter cycle than 5 months.per License Condition 13. A. 1. MILLER.N.P. Washington, Univ. of, Seattle, WA. 83/07/01. SGARAND.R.A. Division of Radiological Safety & Safeguards Program. 1p. 19595: 232.

DOCKET 70-0135 BABCOCK & WILCOX CO. . APOLLO, PA

8307110609 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13 AUSTIN:M.A. Babcock & Wilcox Co. 2pp. 19434:100.

8307110662 Forwards revised Sections 1-8 of Matls & Plant Protection Amend MPP-1 to License SNM-145, deleting obsolete conditions. & changing refs to fundamental nuclear matl control plan for low enriched U operations, in response to 820618 submittal. BMITH.C.N Fuel Facility Safoguards Licensing Branch. 83/02/04. AUSTIN, M.A. Babcock & Wilcox Co. 4pp. 19434:067.

- BR07110日で Pevises Safeguards Arend MPP-I to License SNM-145, effective immediately regress usight measurements on U hexafluoride cylinders, in response to BR0200 ltr BSHRETT, F F Division of Safeguards 83/02/18 AUSTIN, M. A. Babcot ち Wilcox Co Ip. 19434, 120
- 8307110515 Application to renew License SNM-145 to complete phaseout of U mFg operations at Apollo.PA
  AUSTIN M A Babcock & Hilcor Co 83/05/26 PAGE.R G. Uranium Fuel Licensing Branch 1p. 19384:192
- --B307:10318 Responds to 830526 application to renew License SNM-145.
  Amend to license will be issued changing expiration date.
  Payment of fee requested.
  MEISG: D. License Fee Management Branch 83/06/09 AUSTIN.M.A.
  Babcock & Milcox Co. 2pp. 19384-193
- E337140143 Application to amend Spec I B.1 of License SNM-145 per anti-revised pages to permit storage of low specific activity waste in decontamination facility at Apollo site.

  AUSTIN.M A. Babcock & Wilco: Co. 63/06/08. PAGE.R.G. Uranium Fuel Licensing Branch. 6pp. 19529-345
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, IN
- E3071106E5 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid 5 solid waste matls stored at site. Request for exception from 100FR70.51 should be submitted for storage of holding account waste discards. SMITH.C N. Fuel Facility Safeguards Licensing Branch. B3701/13. HENSLEY.M. D. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.). 2pp. 17434.115
- G307110592 Revises License Condition 2 1 to Amend MPP-1 to License SMM-124, granting approval to begin matl control & accounting operations per G21107 & 1229 ltrs. SMITH.C N Fuel Facility Safeguards Licensing Branch. B3/01/14. MENZLEY.K D Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.). 2pp 17371:346
- 6307110517 Advises that Rev 10 to physical safeguards plan transmitted by 621225 ltr acceptable Section 9 0 of Amend MPP-1 to License SNM-124 will be reissued to incorporate plan revs, per 105FR70.32 SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/14. BOOTH.R. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). jp.
- G307110557 Issues license condition to Amend MPP-1 to License SNM-124, effective immediately granting 30-day extension to complete receiver measurements in response to B3013 ltr. BURNETIER F. Division of Safeguards 83/01/24. HENSLEY, K. D. Nuclear Fuel Services. Inc. (subs. of Getty Dil Co.). 1p. 19391 302
- 8307180057 Advises that 831105 Rev 2 to safeguards contingency plan acceptable. License Condition 9.1.8 revised per ICCFR70 J2(g) RENTSCHLER.R.R. Evel Facility Safeguards (1998) MLER.R. Fuel Facility Sefeguards Licensing Branch. 25. BOOTH.R. Nuclear Fuel Services, Inc. (subs. of Getty Oil 27. 19566:315.
- 8397110570 Denies request for exemption from License Condition 2.11 for current inventory period in response to 830125 ltr.
  SMITH C N Fuel Facility Safeguards Licensing Branch. 83/01/31.
  HENSLEY.K D Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
  19. 19391-343
- 8307:10545 Confirms conversations between J Buck & E Sparks re use of DDE/NRC Form 741. "Nuclear Mat! Transfer Receipt," replacing

- 8307:10655 Grants request to have two designated individuals act as MBA-6 custodians per shift. w/one in lab & other in production area, in response to 830:128 ltr. License Condition 2.5 to Amend MPP-1 to License SNM-124 revised.

  BROWN, W. B. Fuel Facility Safeguards Licensing Branch. 83/02/17.
  MENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) ch. 03/02/17. Getty Oil Co.).
- 8307140423 Forwards IE Insp Rept 70-0143/83-14 on 830307-11 & notice of violation.
  STOMR.J.P. Division of Emergency Preparedness & Materials Safety.
  83/04/01. MANSER.W.C. Nuclear Fuel Services, Inc. (subs. of Getty
  Dil Co.). 2pp. 19521:161.
- --B307140426 Notice of violation from insp on B30307-11 \* Region 2, Office of Director. B3/04/01. 1p. 1 19521 163
- --8307140428 IE Insp Rept 70-0143/83-14 on 830307-11. Noncompliance nated: proportional detectors performance tests unacceptable per Procedure NFS-HS-A4.

  EVANS, C. D. Region 2, Office of Director. MONTGOMERY, D. M.
  Division of Emergency Preparedness & Materials Safety. 83/03/31.

  5pp. 17521:164.
- 8307200010 Add1 response to FDIA request for repts re inventory differences at NFS. App A documents partially withheld (ref FDIA Exemptions 1.3 & 4). Forwards nonexempt portions of documents. Review of remaining 13 documents in progress. FELTON.J.M. Division of Rules and Records. 83/04/28. BARLETT.D.L. Philadelphia Inquirer. 6pp. 19671:001.
- --8307200014 Forwards detailed rept on current & planned projects designed to improve facility accountability sys & associated inventory difference results. Safeguards info deleted (ref 10CFR2.790).

  TAYLOR.C.W. Nuclear Fuel Services, Inc. (subs. of Octty Oll (79/10/23). BURNETT, R. F. Division of Safeguards. 13pp. 1967. oy, M. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) BURNETT,R.F. Division of Safeguards, 13pp. 19671:00
- --8307200019 Forwards matl balances for inventory period 790512-0618.
  Safeguards info deleted (ref 10CFR2,790).
  HENBLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
  79/07/04. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 3pp.
- --8307200025 Forwards matl balances for inventory period 790309-0507 for highly enriched U & Pu. Safeguards info deleted (ref 10CFR2.790).
  HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/06/26. KENNA, W.B. Region 2, Atlanta, Safeguards Branch. 4pp. 19671:028.
- ~-8307200029 Forwards mat1 balances for inventory period 790109-0309 for highly enriched U & Pu Safeguards info deleted (ref 10CFR2 790).
  HENSLEY.K. D. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.). 79704709. KENNA.W. B. Region 2. Atlanta, Safeguards Branch. App. 19671:032.
- --8307200032 Forwards mati balances for inventory period 781110-790109 for highly enriched U & Pu. Safeguards info deleted (ref. 100FR2.790).
  HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). 79/02/09. KENNA.W.B. Region 2. Atlanta. Safeguards Branch. Spp.
- --8307200034 Forwards mati balances for inventory period 790618-0814.
  Safeguards info deleted (ref 10CFR2 790).
  HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
  79/09/24. KENNA, W. B. Region 2. Atlanta, Safeguards Branch. 3pp.
- --8307200039 Forwards matl balances for inventory period 790814-1004.
  Safeguards info deleted (ref 10CFR2.790).
  HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  79/12/03. KENNA.W.D. Region 2. Atlanta. Safeguards Branch. Spp.
- --8307200042 Forwards mat1 balances for inventory period 791004-1212.
  Safeguards info deleted (ref 10CFR2.790).
  HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
  80/01/31, KENNA,W.B. Region 2, Atlanta, Safeguards Branch. Epp.
  19671:053.
- --8307200045 Forwards mati balances for inventory period 791212-800325.
  Safeguards info deleted (ref 10CFR2. 790).
  HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  80/05/08. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 3pp.

- --9307200049 Forwards matl balance sheets for inventory period 791212-800329 inadvertently omitted from correspondence. Safeguards info deleted (ref 10CFR2. 790) HENSLEY.K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 80703/12. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 3pp. 19671: 064.
- --8307200051 Forwards matl balances for high enriched U for physical inventory period 800325-0527. Safeguards info deleted (ref 10CFR2.790).

  HENBLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). 80/07/08. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 4pp. 19671:067.
- --9307200053 Forwards matl balances for inventory period May-Aug 1980 Safeguards info deleted (ref 10CFR2.790). HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/09/24. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. Spp 19671:071.
- ---8307200056 Forwards mat) balances for inventory period 800801-0926. Safeguards info deleted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services: Inc. (subs. of Getty Dij Co.). B0/11/10. KENNA.W.B. Region 2. Atlanta, Safeguards Branch. 5pp. 19671:076.
- --8307200058 Forwards matl balances for inventory period Sept-Nov 1980. Safeguards info deleted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services: Inc. (subs. of Gatty Dil Co.). 80/12/23. KENNA, W. B. Region 2. Atlanta. Office of the Director (81/03/01). 5pp. 19671:081.
- --8307200059 Forwards matl balances for 801120-810121 operating period. 8afeguards info deleted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). 81/02/24. LEWIS.R.C. Division of Resident & Reactor Project Inspection. 6pp. 19671:086.
- --8307200062 Forwards matl balances for 810121-0325 operating period. Safeguards info deleted (ref 10CFR2.790). HEMSLEY,K.D. Nuclear Fuel Services: Inc. (subs. of Gatty Dil Co.). 81/05/01. LEWIS,R.C. Division of Resident & Reactor Project Inspection. 7pp. 19671:092.
- --B307200069 Forwards matl balance for B10927-0729 operating period.
  Revised sheet for B10323-0527 period for Matl Balance Areas
  5 & 6 contained in B10709 matl balance rept Safeguards info
  deleted (ref 10CFR2.790).
  HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  B1/09/10. LEWIS,R.C. Division of Resident & Reactor Project
  Inspection. 6pp. 17671:098.
- -8307200072 Forwards matl balances for 810325-0527 operating period. Safeguards info deleted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services. Inc. (subs. of Getty Dil Co.). 81/07/09. LENIS,R.C. Division of Resident & Reactor Project Inspection. 7pp. 19671:105.
- -8307200075 Forwards matl balances for Jul-Sept 1981 operating period. Safeguards info deleted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 81/11/11. LEWIS.R.C. Division of Resident & Reactor Praject Inspection. 7pp. 19671:112.
- --8307200077 Forwards matl balances for Sept-Dec 1981 operating period. Bafeguards info deleted (ref 10CFR2.790). HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). B2/01/13. O'REILLY, J.P. Region 2. Atlanta, Office of the Director (81/03/01). 7pp. 19671:119.
- -8307200080 Forwards matl balances for Dec 1981 Feb 1982 operating period. Safeguards info deleted (ref 10CFR2.790).
  HENBLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  82/03/05, D'REILLY, J. P. Region 2, Office of Director. 7pp.
  19471:125.
- --8307200083 Forwards mat1 balances for Feb-Apr 1982 operating period. Safeguards info deleted (ref 10CFR2.790).
  HENGLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
  82/05/07. O'REILLY, J.P. Region 2. Office of Director. 8pp.
  19671:132.
- ---8307200086 Forwards matl balances for Apr-June 1982 operating period. Safeguards info deleted (ref 10CFR2.790). HENGLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). 82/07/13. D'REILLY,J.F. Region 2. Office of Director. 7pp. 19671: 140.

- --8307200391 Forwards Region II proposed license conditions to be imposed on NFS if startup approved to Div of Sys Integration comments Add1 inspectfor may result in more recommendations.

  STELLO.V. Office of Inspection to Enforcement, Office of the Director 79/12/07. BURNETIAR.F. Division of Safeguards. 1p. 19671 147.
- --8307200096 Forwards Region II recommendations for license conditions to be imposed on NFS if startup approved. Specific safety recommendations having impact on safeguards sys included Safeguards into deleted.

  O'REILLY, J.P. Region 2. Atlanta. Office of the Director.
  79/11/21. DURNETT, R. F. Division of Safeguards 11pp. 19671:148.
- 8307080648 Ack receipt of 830407 ltr to NFS re proposed groundwater monitoring program for waste lagouns on NFS property. City of Erwin. TN still plans to consider Banner Spring, adjacent to NFS holding lagouns, for water source.

  REAGAN.S. Tennessee, State of, 83/05/02 WYNGARDEN.S. Uranium Fuel Licensing Branch. 2pp. 19364:177.
- B307150449 Transcript of B30511 Commission meeting re review of NFS-Erwin settlement.Exemptions ( & 10 in Washington.DC.Pp 1-46.SJ Chilk B30706 memo releasing transcript encl. \* Commissioners. B3/05/11. 70pp. 19540:225.
- 8307080629 Forwards response to IE Insp Rept 70-0143/83-17 % notice of violation. Program initiated to perform detailed contamination surveys of processing facilities to locate contamination sources.

  GUINN, F. K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).

  83/06/24. STOHR, J.P. Division of Emergency Preparedness & Materials Safety. 4pp. 19364:221.
- 8307140193 Forwards IE Safeguards Insp Rept 70-0143/83-21 on 830517-20. No noncompliance noted. STONR, J. P. Division of Emergency Preparedness & Materials Safety. 83/06/28. GUINN, F. K. Nuclear Fuel Services. Inc. (subs. of Getty Gil Co.). 2pp. 19514:060.
- ~-B307140179 IE Safeguards Insp Rept 70-0143/83-21 on B30517-20 No noncompliance noted Major areas inspected measurements & statistical controls, independent insp effort & following on previous insp findings. Details withheld (ref 100FR2,770). BATES, J W., RICHARDS, B.L. Region 2, Office of Director. MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety, 83/06/28, lp. 19514:062.
- 8307140205 Ack receipt of 830217 ltr re Rev 52 to fundamental nuclear mat1 control plan.Changes consistent w/provisions of 10CFR70.32(c) & acceptable.

  8TOMR.J.P. Division of Emergency Preparedness & Materials Safety.
  83/06/29. GUINN.F.K. Nuclear Fuel Services: Inc. (subs. of Getty Oil Co.). 1p. 19522:044.
- 8307140261 Ack receipt of 830216 Rev 51 to fundamental nuclear math control plan. Changes consistent w/10CFR70.32(c) & acceptable.

  STOHR, J. P. Division of Emergency Preparedness & Materials Safety.
  83/06/27. GUINN.F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1p. 19523:001.
- 8307080455 Forwards IE Safeguards Insp Rept 70-0143/83-24 on 830607-09. No noncompliance noted. STOHR.J.P. Division of Emergency Preparedness & Materials Safety. 83/07/01. GUINN,F.K. Nuclear Fuel Services. Inc. (subs. of Getty Dil Co.). 2pp. 19347:243.
- MCGUIRE D. R
- 8307140247 Ack receipt of B30216 & 17 ltrs transmitting Revs 48 & 49 to fundamental nuclear mat1 control plan Revs consistent w/10CFR70.32(c) & acceptable.

  STOHR, J P Division of Emergency Preparedness & Materials Safety.
  B3/07/01. GUINN.F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) ip. 19523:050.
- 8307200462 Application for amend to License SNM-124, superseding 810328 application by revising organization to administration chart.

  OUINN,F.K. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  83/07/06. PAGE,R.G. Uranium Fuel Licensing Branch 24pp.
  19672:208.

- 8307180420 Forwards proposed mods to license conditions for License SNM-124 scheduled for submittal in Jan 1984.License condition section should be upgraded to include suggested mods.

  500NG.A.L. Uranium Fuel Licensing Branch. 83/07/12. IDEMER.R. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 4pp. 19556: 335
- 8307280135 Forwards "Daily Summary of Stack Monitoring" for airborne radioactivity concentrations during June 1983.

  GUINN.F.K. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).

  83/07/13. O'REILLY.J.P. Region 2. Office of Director. 1p.
  19824: 028.
- --8307280150 "Daily Summary of Stack Monitoring" for airborne radioactivity concentrations during June 1983.

  \* Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 83/07/13. 2pp. 19826:029.
- 8307260492 PNO-II-83-055: an 830720, during maint on demister in shutdown ventilation sys, hydrogen flashback occurred at entrance to furnace in Bldg 300 complex. No internal personnel contamination or release to environ detected.

  CORYELL. 6. F.. BARR. K.P. Region 2, Office of Director. 83/07/21, 2pp. 19734:010.
- DOCKET 70-0168 NUCLIDE CORP., STATE COLLEGE, PA
- B307280173 IE Insp Findings & Licensee Ack dtd 830629 of License SNM-188. Insp findings:no violations observed. LADUM.R.H. Region 1. Office of Director. B3/06/29, 1p. 19792:092.
- DOCKET 70-0223 CALIFORNIA, UNIV. OF, LOS ANGELES, CA
- 8307260521 Forwards IE Insp Repts 50-142/83-02 & 70-0223/83-01 on 830628. No noncompliance noted.
  NGRDERHAUG.L.R. Region 5. Office of Director. 83/07/08. O'NEIL.R. California, Univ. of. Los Angeles. 2pp. 19734:156. 24X Fiche: 50-142,83/07/08,8307260521.
- --8307260528 IE Insp Rests 50-142/83-02 & 70-0223/83-01 on 830628.
  No noncompliance noted Major areas inspected: SSMM inventory.
  NELSON.G. B., NORDERHAUG, L. R. Region 5; Office of Director.
  83/07/08. 3pp. 19734: 158. 24X Fiche: 50-142, 83/07/08, 8307260521.
- 8307260442 Forwards modified Page R to IE lnsp Repts 50-142/83-02 & 70-0223/83-01 summarizing SNM physical inventory.
  NGRDERHAUG.L.R. Region 5, Office of Director. 83/07/20. D'NEIL,R. California, Univ. of, Los Angeles. 1p. 19731:284. 24X Fiche:50-142,83/07/20,8307260442.
- --8307260444 Modified Page 2 to 1E Insp Repts 50-142/83-02 & 70-0223/83-01 on 830628.

  Reglan 5, Office of Director. 83/07/20. 1p. 19731:285. 24X Fiche:50-142,83/07/20.8307260442.
- B307290134 Forwards IE Insp Repts 50-142/83-02 & 70-0223/83-01 re recent SNM inventory. WOQOHEAD, C. P. Hearing Branch 4. 83/07/28, FRYE, J. H., BRIGHT, Q. D., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. App. 19822:134. 24% Fiche: 50-142,83/07/28,8307290134.
- DOCKET 70-0364 BABCOCK & WILCOX CO., APOLLO, PA
- 8307110605 Advises that Matis & Plant Protection Amend MPP-1 to License SNM-414 amended-revising License Condition 9, 1 re Parks Township security plan for safeguarding SNM of moderate strategic significance as contained in encl. RENTSCHLER.R.R. Fuel Facility Safeguards Licensing Branch. 83/01/27. AUSTIN.M.A. Battock & Wilcox Co. 2pp. 19391:319.
- 8307010128 Responds to 830307 ltr re cancellation of Category II security plan for safeguarding SNM of moderate strategic significance. Change acceptable.
  MARTIN, T. T. Division of Engineering & Technical Programs. 83/06/17.
  COLEMAN. W. L. Babcock & Wilcox Co. 2pp. 19175:321.
- 8307140277 Forwards IE Safeguards Insp Rept 70-0364/83-04 on 830604-10. No noncompliance noted. MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/27, COLEMAN.W.L. Babcock & Wilcox Co. 2pp. 19522:320.
- --8307140281 IE Safeguards Insp Rept 70-0364/83-04 on 830606-10. No nancompliance noted Major areas inspected: holdup measurements during decommissioning.
  ZIBULSKY.H., WOLTNER, E. F., DeLLA RATTA.A. Region 1: Office of Director. 83/06/24. 2pp. 19522:322.

- 8307130445 Advises that all future applications & fees for licensing actions related correspondence & inquiries should be sent to Region I as stated in enc1 FR notice. Safeguards info should be sent to Div of Safeguards.

  ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 83/07/01. AUSTIN, M. A. Babcock & Wilcox Co. 8pp. 19510:039.
- 8307130107 Ack receipt of 830522 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/83-02. STAROSIECKI.R. Division of Project & Resident Programs. 83/07/11. COLEMAN.W.L. Babcock & Wilcox Co. 1p. 19536:195.
- --8307180112 Responds to NRC 830523 ltr re violations noted in IE Insp Rept 70-0364/83-02. Corrective actions: pressure sensing devices of increased sensitivity installed. Addl ventilation sys reactivated by 830617. AUSTIN-M.A. Babcock & Wilcox Co. 83/06/22. 8TAROSTECKI.R. Division of Project & Resident Programs. 3pp. 19336:156.
- 8307220120 Advises that lead case studies re status & disposition of low level radwaste disposal area at B&W Parks Township site will not be transferred to Region I ofc as discussed during B30412 meeting.
  ROUSE.L.C. Advanced Fuel & Bpent Fuel Licensing Branch. 83/07/14.
  STAROSIECKI.R. Division of Project & Resident Programs. 1p.
- DOCKET 70-0371 UNC NAVAL PRODUCTS, INC., UNCABVILLE, CT
- 8307110647 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matls stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13 KIRK.W.F. United Nuclear Corp. 2pp. 19434:123.
- 8307180005 Orants 830112 request for extension to complete receiver measurements for receipt of BNM.License condition permitting extension to 830128 & 0203 added to 8afeguards Amend MPP-1 to License SNM-36B.

  BURNETT,R.F. Fuel Facility 8afeguards Licensing Branch. 83/01/24.

  KIRK,W.F. United Nuclear Corp. 1p. 19367:339.
- 8307110571 Advises that revised Ref 29 to physical protection plan transmitted by 830131 ltr acceptable. SMITH.G.N. Fuel Facility Safeguards Licensing Branch. 83/02/04. KIRK.M.F. United Nuclear Corp. 1p. 19434:112.
- 8307110524 Application to amend Licenses SNM-368 & 06-06884-01 changing name of licensee to UNC Naval Products. CUNNINGHAM.K.A. United Nuclear Corp. 83/05/02, PAGE.R.G. Uranium Fuel Licensing Branch. 4pp. 17434:125.
- --8307110526 Responds to 830502 application to amend Licenses BNM-368 & O6-06884-01 changing name of licenses Payment of few requested.

  WEISB D. License Fee Management Branch. 83/06/03. AMY, G. G. United Nuclear Corp. 2pp. 19434:129.
- 8307110162 Requests six copies of App Arref in vendor 830502 application & revised pages to Part I & Part II to be inserted in application for License SMM-368, Review will be continued upon receipt of addl info.

  BIDINGER, G. H. Uranium Fuel Licensing Branch. 83/06/28, AMY, G. O. United Nuclear Corp. 2pp. 19386:012.
- 8307120253 Ack receipt of 830531 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/83-02. Corrective actions withheld (ref 10CFR2.770). MARTINIT. T. Division of Engineering & Technical Programs. 83/06/29, AMY, 0.0. United Nuclear Corp. 2pp. 19429:004.
- 8307220635 Forwards Exhibit A omitted from 830502 ltr.W/o encl. KIRK.W.F. United Nuclear Corp. 83/06/29. CROW.W.T. Uranium Recovery Licensing Branch. ip. 19697:078.
- B307130030 Advises that License SNM-36B amended changing name of licensee & transferring control from United Nuclear Corp.UNC Naval Products.Div of UNC Naval Products.Div of UNC Resources.Inc., per B30502 application & B30629 suppl. PAGE.R.G. Uranium Fuel Licensing Branch. B3/06/30. AMY, O. G. United Nuclear Corp. ip. 19562:323.
- 8307200440 Confirms 830525 telcon. Nuclear criticality safety portion of license renewal should be approved as is. Complete rev to plant controls not achieved due to devotion of resources to criticality studies, license amends & control of operations. KIRK.W.F. United Nuclear Corp. 83/07/01. CROW.W.T. Uranium Fuel Licensing Branch. 2pp. 17672:245.

- B307210086 Forwards IE Insp Rept 70-0371/83-04 on B30404-07 & notice of violation. Corrective actions stated in B20112 ltr not fully effective. Mgt emphasis on corrective actions stressed. BTAROSTECKI, R. Division of Project & Resident Programs. B3/07/07. AMY, O. Q. United Nuclear Corp. 2pp. 19668: 238.
- --8307210089 Notice of violation from insp on 830404-07.
  \* Region 1. Office of Director. 83/07/07. 2pp. 19468:240.
- --8307210095 IE Insp Rept 70-0371/83-04 on 830404-07. Noncompliance noted: failure to park fuel-bearing carts in authorized locations & to evaluate in-plant & stack air samples exceeding limits. Inadequate level of raschig rings in waste receivers. ROTH.U. ELSASBER.T.C. Region 1. Office of Director. 83/06/15. 8pp. 19668:242.

#### DOCKET 70-0378 ARMY, DEPT. OF, ADELPHI, MD

- 8307210054 Addl response to FOIA request for documents re Harry Diamond Lab.from 1965 to present Forwards requested documents. Info partially withheld (ref FOIA Exemption 6). FELTON.J.M. Division of Rules and Records. 83/03/07. SIMPBON.C. Affiliation Unknown. 2pp. 19783:315.
- --8307210330 Insp Repts 70-0378/81-01,30-12435/81-01,30-12436/81-01 & 30-12436/81-01 on 810616. No noncompliance noted. \* Region 1, Philadelphia, Office of the Director. 81/05/23. 8pp. 19784:338.
- --B307210341 Discusses Insp Repts 70-0378/78-01.30-12438/78-01. 30-12475/78-01.30-12435/78-01.30-12436/78-01 & 30-12840/78-01 on 780208. No noncompliance noted. MCCLINTOCK.R.O. Region 1. Philadelphia. Office of the Director. 79/02/27. RAMSDEN.J. Army, Dept. of. 2pp. 19785:006.
- --8307210347 IE Insp Rapts 70-0378/78-02, 30-12435/78-02, 30-12436/78-02 to 30-12436/78-02 on 781128 & 27. No noncompliance issued. MGCLINTOCK, R. O. Region 1: Philadelphia: Office of the Director. 787/12/07. 7pp. 19785:008.
- ---8307210358 IE Insp Repts 70-0378/78-01,30-12435/78-01,30-12436/78-01,30-12436/78-01,30-12436/78-01,30-12436/78-01,30-12436/78-01 & 30-12475/78-01 on 780208, No noncompliance noted. COSTELLO, D., MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 78/02/15. 9pp. 19785:015.

### DOCKET 70-0398 COMMERCE, DEPT. OF, WASHINGTON, DC

- B307i10623 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored at site. Request for exception from IOCFR70, 51 should be submitted for storage of holding account waste discards. BMITH, C, N. Fuel Facility Bafeguards Licensing Branch. B3/01/13. HOBBS.T.O. Commerce, Dept. of, National Bureau of Standards. 2pp. 17434:102.
- B307110691 Withdraws License Conditions 6.4 & 6.5 from Safeguards Amend MPP-3 to License BNM-362 requiring reporting of intentional discards & inventory differences on monthly bases.NUREO/BR-0006 instructions should be followed. RENTBCHLER, R. R. Fuel Facility Safeguards Licensing Branch. B3/01/24. H0BBB,T.Q. Commerce, Dept. of, National Bureau of Standards. 1p. 19434:073.
- 8307270445 Advises that radiological contingency plan required to be submitted by licensee per Commission 810211 order reviewed & meets requirements. BER encl. Requests amend to License BNM-342 be processed.
  FISHER: F.D. Uranium Fuel Licensing Branch. 83/07/18. CROW, W. T. Uranium Fuel Licensing Branch. 19. 19802: 327.
- ---B307270447 BER supporting radiological contingency plan required by licensee per Commission order B10211. FISHER,F. D. Uranium Fuel Licensing Branch. B3/07/18. 4pp. 19802: 328.

# DOCKET 70-0572 MONSANTO RESEARCH CORP., DAYTON, OH

8307050018 Part Ri evaluation rept re mismarking of ten 1,000 mCi Am-241 sources as 1,000 uCi. GC insp procedure changed, requiring that markings be recorded on insp form. HOADLEY, S. D. Monsanto Co. 83/06/20. Region 3, Office of Director. 5pp. 19220:058.

- DOCKET 70-0697 UNION CARBIDE CORP. . TUXEDO, NY
- 8307110628 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH, C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13. MCGOVERN, J. J. Union Carbide Corp. 2pp. 19434:104.
- 8307010013 Forwards physical security plan for facility, updated through Rev 3.Plan withheld. VOTH.M.H. Union Carbide Corp. B3/04/21. CARLSON.D. Office of Nuclear Material Safety & Safeguards.Director. 1p. 19124:362. 24X Fiche:50-054.B3/04/21.8307010013.
- 8307190264 Informs of plans for spent reactor fuel shipment to DOE Chemical Processing Plant at Idaho Falls.ID in early Sept 1983. Battelle BMI-f shipping cask will contain 24 MTR type elements. Route approved in Dec 1982 will be used.

  HART. H. C. Union Carbide Corp. 83/06/20. HILLMAN. C. Physical Becurity Licensing Branch. 2pp. 19656:210.
- 8307140099 Forwards IE Insp Rept 70-0687/83-02 on 830531-0603. No noncompliance noted. STARBSTECKI, R. Division of Project & Resident Programs. 83/06/27. MCGOVERN.J.J. Union Carbide Corp. 2pp. 19923:216.
- --B307140106 IE Insp Rept 70-0687/B3-02 on B30531-0603. No noncompliance noted Major areas inspected organization facility changes & mods safety committees operations review & nuclear criticality safety.

  ROTH, J. Region 1. Office of Director. ELBASSER, F. C. Division of Project & Resident Programs. B3/06/24. 9pp. 19523:218.
- DOCKET 70-0498 WESTINGHOUSE ELECTRIC CORP. , PITTSBURGH, PA
- 8307010125 Ack receipt of 830607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0698/83-01. MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/24. NARDI,A.J. Westinghouse Electric Corp. 1p. 19168:335.
- --9307010131 Responds to NRC 830530 itr re violations noted in IE Insp Rept 70-0678/83-01 Corrective actions:drums filled w/low level contaminated soil inspected & mixed w/cement to bind moisture. GALM.D.T. Hestinghouse Electric Corp. 83/06/07. MARTIN.T.T. Division of Engineering & Technical Programs. 2pp. 19168:336.

#### DOCKET 70-0734 GA TECHNOLOGIES, INC., SAN DIEGO, CA

- 8307110613 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matis stored at site Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards.

  BMITH.C.N. Fuel Facility Safeguards Licensing Branch. B3/01/13. MUNRY, W.R. GA Technologies. Inc./General Atomic Co. 2pp. 19434-098.
- 8307110601 Advises that Sections 1-8 of Matis & Plant Protection Amend MPP-1 to License BNM-696 revised in entirety as contained in entl re HTGR fuel fabrication operations.
  BROWN, W.B. Fuel Facility Safeguards Licensing Branch. 83/02/09.
  MURRY, W.R. OA Technologies, Inc./General Atomic Co. 6pp.
- B307i10695 Approves request for extension of schedule for completing physical protection mods & procedures contained in 830222 ltr.provided compensatory measures implemented to reposition guard to maintain surveillance.

  BROWN.W.B. Fuel Facility Safeguards Licensing Branch. 83/02/25.

  MOWRY.W.R. OA Technologies: Inc./General Atomic Co. 19. 19434:074.
- B307030470 ENVIRONMENTAL IMPACT APPRAISAL RELATED TO SPECIAL NUCLEAR MATERIALS LICENSE NO. 8NM-696. Docket No. 74-734. (QA Technologies, Inc.)

  # Division of Fuel Cycle & Material Safety. NUREG-0974. B3/06/30. 67pp. 19264:122.
- 830/120384 Discusses IE Safeguards Insp Rept 70-0734/83-06 conducted on 830615.16 & 20. No noncompliance noted. Major areas inspected: program for safeguarding SMM under 10CFR73 & approved security plan. Rept withheld (ref 10CFR73.21).

  NORDERHAUG, L. R. Region 5. Office of Director. 83/07/06. PARKER, J. M. OA Technologies. Inc. /General Atomic Co. 2pp. 19429:079.

B307120106 Discusses IE Safeguards Insp Rept 70-0734/83-09 conducted on B30613-17. No noncompliance noted Major areas inspected: program for control & accounting of SNM. Insp rept withheld (ref 10CFR2.770).

NORDERHAUG. L. R. Region 5, Office of Director. B3/07/08. PARKER, J. W. GA Technologies, Inc./General Atomic Co. 2pp. 19423: 070.

#### DOCKET 70-0754 GENERAL ELECTRIC CO., PLEASANTON, CA

8307110702 Clarifies safeguards licensing policy re-inventory requirements of SNM contained in liquid & solid waste matis stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH. C. N Fuel Facility Safeguards Licensing Branch. 83/01/13. CUNNINGHAM. G. E. General Electric Co. 2pp. 19434:077.

#### DOCKET 70-0801 OHIO STATE UNIV. . COLUMBUS, OH

- 8307280452 Forwards IE Safeguards Insp Repts 50-150/83-01.70-0801/83-01 & 70-0966/83-01 on 830412-13 & notice of violation. Encis withheld (ref 10CFR2.790).

  MILLER, J. R. Region 3. Office of Director. 83/05/09. REDMOND.R.F. Ohio State Univ. 2pp. 19797:258. 24x Fiche: 50-150.83/05/09. 8307280452.
- B3070600B5 Ack receipt of B30607 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-150/83-01, 70-0801/83-01 & 70-0966/83-01. Response withheld (ref 10CFR2, 790).

  MILLER, J. R. Region 3, Office of Director. B3/06/30. CRAMBLETT, H. G. Ohio State Univ. 1p. 19237:240. 24X Fiche: 50-150, B3/06/30. B307060B5.

#### DOCKET 70-0820 UNITED NUCLEAR CORP. . WOOD RIVER JUNCTION, RI

- B30705028) Forwards new survey data sheets for insertion into final survey rept. Section I. HELGEBON, K.A. United Nuclear Corp. 83/06/02. GROW, W.T. Office of Nuclear Material Safety & Safeguards, Director. 200pp. 19260:171.
- 8307090102 Application to amend License SNM-777, releasing third floor cailing of Columns Tower for unrestricted use, based on application of ALARA concept to areas containing residual contamination in excess of NRC decontamination guidelines.

  HELGEBON.K.A. United Nuclear Corp. 83/06/06. CROW.W.T. Office of Nuclear Material Safety & Safeguards, Director. 6pp. 19366:051.
- 8307150375 Quarterly status rept re investigation of radioactive contaminants at facility.

  MARNER,D. L. Don L. Warner, Inc. NRC-02-80-076. 83/06/24.

  MYNOARDEN,S. D. Office of Nuclear Material Safety & Safeguards. Director. 20p. 19596: 357.
- 8307150349 Forwards United Nuclear Corp Recovery Sys 930606 application requesting release of third floor of Wood River Junction facility & WRC guidalines for decontamination. Comments requested within 60 days. W/o encls.

  CROW-W.T. Uranium Fuel Licensing Branch. 83/06/30. HICKEY, J. E. Rhode Island, State of. 1p. 19540:346.
- 8307190011 Forwards well summary sheets & analyses for MariApr & May 1983. HELGESON, K. A. United Nuclear Corp. 83/07/01. CROH. W. T. Office of Nuclear Meterial Gafety & Safeguards Director. 1p. 19569:306.
- --9307190019 Well summary sheets & analyses for Mar.Apr & May 1983. MULLER, J.J., MENDES, T. Controls for Environmental Pollution, Inc. 83/07/01. 25pp. 19569:307.
- 8307220147 Forwards resurvey data sheets for walls & floors for insertion into Section 1 vols of final survey rept Addicopies transmitted under separate cover. HELOEBON.K.A. United Notlear Corp. 83/07/07. CROW,W.T. Office of Nuclear Material Safety & Safeguards, Director. 14pp. 17692:267.
- 8307250517 Advises that no action required on 8204R8 request to terminate sampling of leak detection sys associated w/500,000 gallon storage tank, as tank & piping sys removed. PAGE,R.G. Uranium Fuel Licensing Branch. 83/07/14. GREGG,R.J. United Nuclear Corp. 1p. f9740:180.
- 8307280318 Ack receipt of 830316 Itr requesting withdrawal of two violations noted in IE Insp Rept 70-0820/83-01. Violations not withdrawm. Std work permit not issued to cover removal of contaminated floor. Alpha survey meter required.

  8TAROSTECKI.R. Division of Project & Resident Programs. 83/07/20. AMY. J. G. United Nuclear Corp. 2pp. 19789:234.

--8307280319 Responds to NRC 830304 ltr re violations noted in IE Insp Rept 70-0820/83-01. Corrective actions: generic std work permits put in place covering nonroutine operations & survey meter provided. Requests withdrawal of violations. GREGO:R. J. United Nuclear Corp. 83/03/16. MARTIN:T. T. Division of Engineering & Technical Programs. 3pp. 19789:236.

#### DOCKET 70-0824 BABCOCK & WILCOX CO., LYNCHBURG, VA

- 8307110454 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matis stored at site. Request for exception from lOCFR70. 51 should be submitted for storage of holding account waste discards. BMITH, C.N. Fuel Facility Safeguards Licensing Branch. B3/01/13. OLSEN, A.F. Babcock & Wilcox Co. 2pp. 19434:063.
- 8307190013 Forwards replacement page to 830615 application to amend License SNM-778. No change in possession limit of irradiated fuel requested. OLSEN.A.F. Babcock & Wilcox Co. 83/07/01. GROW.W.T. Uranium Fuel Licensing Branch. 2pp. 19656:048.
- 8307290140 Ack receipt of B30621 ltr informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-0824/83-02.
  8TGHR.J.P. Division of Emergency Preparedness & Materials Safety.
  83/07/08. ENGELDER.T.C. Babcock & Wilcox Co. 1p. 19815:361.
- --B307270143 Responds to NRC B30527 itr re violation noted in IE Bafeguards Insp Rept 70-0824/83-02. Corrective actions withheld (ref 10CFR2.770). ENGELDER.T.C. Babcock & Wilcox Co. 83/04/24. STOHR.J.P. Division of Emergency Preparedness & Materials Bafety. 1p. 17915:362.

#### DOCKET 70-0966 DHID STATE UNIV., COLUMBUS, OH

- 8307280452 Forwards IE Safeguards Insp Repts 50-150/83-01.70-0801/83-01 & 70-0966/83-01 on 830412-13 & notice of violation Encls withheld (ref 100FR2,790).

  MILLER, J. R. Region 3, Office of Director. 83/05/09. REDMOND, R. F. Ohio State Univ. 2pp. 19797:258. 24X Fiche: 50-150,83/05/09,8307280452.
- 8307060085 Ack receipt of 830607 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-150/83-01, 70-0801/83-01 & 70-0966/83-01. Response withheld (ref 10CFR2, 790).
  MILLER, J. R. Region 3, Office of Director. 83/06/30. CRAMBLETT, H. Q. Ohio State Univ. 1p. 19237;240, 24X Fiche: 50-150, 83/06/30, 830706085

#### DUCKET 70-1007 GENERAL ELECTRIC CO., SAN JUSE, CA

- 8307260478 Forwards IE Insp Rept 70-1007/83-01 on 830512-18.No noncompliance noted. BOOK.H.E. Region 5. Office of Director. 83/07/19. DARMITZEL,R.W. General Electric Co. 1p. 19732:342.
- --8307260482 IE Insp Rept 70-1007/83-01 on 830512-18. No noncompliance noted Major areas inspected:confirmatory survey of Bldg J to establish that bldg can be released for unrestricted use. BROCK, B.L. ZURAKOHEKI, P.R., PANG, J.F. Region 5, Office of Director. 83/07/07. 16pp. 19732:343.
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8307110658 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored at site Request for exception from 10CFR70.51 should be submitted for storage of holding account waste discards. SNITH, C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13. LICHTENBERGER Combustion Engineering, Inc. 2pp. 17434:065.
- B307250507 Forwards matls re implementation of UB/IAEA safeguards agreement program under 10CFR75. Completed design info questionnaire requested by B30B22. W/o encis. BURNETIR. F. Division of Safeguards. B3/06/28. LICHTENBERGER Combustion Engineering, Inc. 3pp. 19720:352.
- 8307040338 Responds to 830204 ltr re changes to C-E fundamental nuclear mati control plan. Two sections not acceptable, due to decreased effectiveness of mati control & accounting program Revs requested within 30 days.

  MARTIN.T.T. Division of Engineering & Technical Programs, 83/06/30, LICHTENBERGER Combustion Engineering, Inc. 3pp. 19234:144.

- 8307290314 Advises that submission date for IAEA design info questionaire extended. Every effort should be expended to complete questionnaire as soon as possible or by 830806. BURNETT.R.F. Division of Safeguards. 83/07/21. LICHTENBERGER Combustion Engineering, Inc. 1p. 19858:196.
- DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NC
- B307110584 Advises that License Condition 2.1 to Amend MPP-3 to License SNM-1097 revised, incorporating revs to fundamental nuclear matl control plansper 821210 & 23 ltrs.
  SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/10. VAUGHAN.C.M. General Electric Co. 1p. 19391:310.
- B307i10556 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored at site. Request for exception from 10CFR70.51 should be submitted for storage of holding account waste discards. BMITH.C.N. Fuel Facility Safeguards Licensing Branch. B3/01/13. VAUGHAN.C. General Electric Co. 2pp. 19391:323.
- B307110671 Advises that License Condition 2.1 of Amend MPP-3 to License SNM-1097 amended, adding second paragraph inadvertently omitted from NRC B30110 ltr re fundamental nuclear matl control plan.
  BNITH, C. N. Fuel Facility Safeguards Licensing Branch. B3/02/01. VAUGHAN, C. M. General Electric Co. 1p. 19434:072.
- 8307070048 Forwards reve to fundamental nuclear matl control plan for fuel fabrication facility in Wilmington, NC, per 10CFR70, 32(c). Revs withheld (ref 10CFR2. 790). VAUGHAN, C. M. General Electric Co. 83/06/17. D'REILLY, J. P. Region 2. Office of Director. 1p. 19273: 255.
- B307140324 Forwards IE Safeguards Insp Rept 70-1113/83-15 on B30531-0603. No noncompliance noted. STQHR.J.P. Division of Emergency Preparedness & Materials Safety. B3/06/29. LDNo.J.A. General Electric Go. 2pp. 19514:037.
- --B307140330 IE Safeguards Insp Rept 70-1113/83-15 on 830531-0603. No noncompliance noted. Major areas inspected: verification of export shipment & measurement control program. Details withheld (ref 10CFR2.790).

  BATES, J. M. Region 2. Office of Director. MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety. 83/06/28. ip. 19514:059.
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP. , PITTSBURGH, PA
- 8307110678 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13. NARDI.A.J. Westinghouse Electric Corp. 2pp. 17434:075.
- B307120213 Ack receipt of 830624 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1143/83-01.
  BTAROSTECKI,R. Division of Project & Resident Programs. B3/06/30.
  JACOBI,W.M. Westinghouse Electric Corp. 1p. 19423:269.
- --8307120224 Responds to NRC 830606 ltr re violations noted in IE Insp Rept 70-1143/83-01. Corrective actions: special air investigations of Stacks 77,72 & 76 initiated & Procedures C8-IH-0301 & C9-IH-0202 revised. JACOBI.W. M. Westinghouse Electric Corp. 83/06/24. STAROBTECKI.R. Division of Project & Resident Programs. 2pp. 19423:270.
- 8307130436 Advises that all future applications & fees for licensing actions, related correspondence & inquiries w/exception of safeguards licensing matters should be sent to Region I as stated in encl FR notice.

  ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch.

  NARDI, A. J. Westinghouse Electric Corp. 7pp. 19510:027.
- 8307220120 Advises that lead case studies re status & disposition of low level radwaste disposal area at B&W Parks Township site will not be transferred to Region I ofc as discussed during 830412 meeting.
  RDUSE.L.C. Advanced Fuel & Spent Fuel Licensing Branch. 83/07/14. 8TAROSTECKIR. Division of Project & Resident Programs. 1p. 19492:329.

- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA
- B307110590 Confirms agreement that B20910 request for one time exemption from requirement of 10CFR70.51(a)(5) not needed. No further action taken.

  SMITH.C.N. Fuel Facility Bafeguards Licensing Branch. 83/01/12. NARDI.A.J. Westinghouse Electric Corp. 1p. 19391:311.
- 8307110698 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matls stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH, C. N. Fuel Facility Safeguards Licensing Branch. B3/01/13. NARDI, A. J. Westinghouse Electric Corp. 2pp. 19434:075.
- 8307110574 Forwards new license conditions to Amend MPP-1 of License SNM-1107.granting 820427 request for exemptions from Items 2.3 & 4 of 10CFR70.57(b). No exemption needed for Item 1. Fundamental nuclear matl control plan needs to be expanded. BURNETI.R.F. Division of Safeguards. 83/01/17. NARDI.A. J. Westinghouse Electric Corp. 2pp. 19391:307.
- 8307110181 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/83-05.
  810HRJ.P. Division of Emergency Preparedness & Materials Safety.
  83/05/25. BRITTON.W.H. Westinghouse Electric Corp. 1p. 19374:082.
- --8307110187 Responds to NRC 830406 ltr re violations noted in IE Insp Rept 70-1151/83-05. Corrective actions withheld (ref 10CPR2, 790). BRITTON, H. H. Hestinghouse Electric Corp. 83/04/21. O'REILLY, J. P. Region 2, Office of Director. 1p. 19374:083.
- B307140047 Extends invitation to attend B30624 enforcement conference at site to discuss mgt control & accountability,per B30610 telcon.
  BTORR, J. P. Division of Emergency Preparadness & Materials Safety.
  B3/06/15. BRITTON, W. H. Westinghouse Electric Corp. 1p. 19314: 226.
- 8307140456 Forwards IE Insp Rept 70-1151/83-07 on 830516-20. No noncompliance noted. STOHR, J. P. Division of Emergency Preparedness & Materials Safety. 83/06/24. BRITTON, W. H. Westinghouse Electric Corp. 2pp. 19521:198.
- ---8307140460 IE insp Rept 70-1151/83-07 on 830516-20. No noncompliance noted Major areas inspected: organization, internal review & audit, training, safety committees, facility mods, operations & previous insp findings.

  CORYELL, O. P. Region 2. Office of Director. MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety. 83/06/23, 4pp. 17521:200.
- 8307140325 Forwards IE Safeguards Insp Rept 70-1151/83-09 on 830523-27. No noncompliance noted: STORR, J.P. Division of Emergency Preparedness & Materials Safety. 83/06/28. BRITTON, W. H. General Electric Co. 2pp. 19514:054.
- --8307140327 IE Safeguards Insp Rapt 70-1151/83-09 on 830523-27. No noncompliance noted, Major areas inspected:measurement control & statistical & inventory (measurement) varification. Details withheld (ref 100FRZ.790).

  SABADDS, J. H. Region 2, Office of Director, MCALPINE.E. J. Division of Emergency Preparedness & Materials Safety, 83/06/27.

  1p. 17514:056.
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP. . OKLAHOMA CITY, OK
- B307110624 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matls stored onsite. Appropriate revs to fundamental nuclear matls control plan should be submitted.
  BMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13.
  BHELLEY.M.J. Kerr-McGes Nuclear Corp. 2pp. 19434:131.
- 8307110583 Advises that Section 9.0 of Matis & Plant Protection Amend MPP-3 to License SNM-1174 amended, revising License Condition 9.1. Incorporating 821111 revs to standby physical security plan for Cimarron Pu Plant. DUBE, R. J. Fuel Facility Safeguards Licensing Branch. 83/01/21. SHELLEY, W. J. Kerr-McGee Nuclear Corp. 1p. 19391: 322.
- B307140497 Advises that all future applications for licensing actions, related correspondence & inquiries, excluding safeguards licensing matters, should be sent to Region III ofc. as stated in encl FR notice.

  ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 83/07/01.

  SHELLEY, W. J. Kerr-McGee Nuclear Corp. 8pp. 19326:036.

- 8307220076 Notifies that official doctet & NRC working files for License SNH-1174 transferred to Region III ofc per regional licensing program. No pending licensing actions in progress at time of transfer.

  ROUSE,L.C. Advanced Fuel & Spent Fuel Licensing Branch. B3/07/14.

  HIND,J.A. Division of Radiological & Materials Safety Programs. 1p. 19691:345.
- DOCKET 70-1201 BABCOCK & WILCOX CO., LYNCHBURG, VA
- 8307110760 Clerifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matts stored onsite. Appropriate revs to fundamental nuclear matts control plan should be submitted.

  SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13.
  FORD.J.T. Babcock & Wilcox Co. 2pp. 19434:140.
- 8307110645 Advises that Bafeguards Amend MPP-2 to License SNM-1168 revised changing License Conditions 2.1 & 5.1 & adding new Condition 4.12 as contained in entlyper 821124 ltr & request for partial exemption from 10CFR70.57(6)(ii).

  BURNETITR.F. Division of Safeguards. 83/02/07. FORD, J. T. Babcock Wilcox Co. 2pp. 19391:360.
- 8307010003 IE Safeguards Insp Rept 70-1201/83-03 on 820228-830304. Noncompliance noted; failure to review audit all aspects of measurement programs on annual basis. Details withheld (ref 100FR2.790).

  CLAY, E.L. Region 2, Office of Director, MCALPINE, E.J. Division of Emergency Preparedness & Materials Safety, 83/04/27. 1p. 19173:350.
- B307010140 Forwards notice of violation from 1E Safeguards Insp Rept 70-1201/83-03 on 830228-0304. Notice withheld (ref 100FR2.790). 870MRJ.U.P. Division of Emergency Preparedness & Materials Safety. 83/04/27. ALTO,R.A. Babcock & Wilcox Co. 2pp. 19173:348.
- 8307010061 Ack receipt of 830527 itr informing NRC of steps taken to correct violations noted in IE Insp Rapt 70-1201/83-03.
  8TOHM.J.P. Division of Emergency Preparedness & Materials Safety.
  83/06/17. ALTD.R.A. Babcock & Wilcox Co. ip. 19173:346.
- ---B307010064 Responds to NRC B30427 ltr re violations noted in IE Insp Rept 70-1201/B3-03. Corrective actions withheld (ref 10CFR2, 790). ZEFF,D. W. Babcock & Wilcox Co. B3/05/27. STORR,J.P. Division of Emergency Preparedness & Materials Safety. 1p. 19173:347.
- 8307140364 Forwards IE Safeguards Insp Rept 70-1201/83-09 on 830531-0603, No noncompilance noted. 8TOHM.J.P. Division of Emergency Preparadness & Materials Safety. 83/06/23. ALTO-R.A. Babtock & Wilcox Co. 2pp. 19514:048.
- --B307140377 IE Bafeguards Insp Rept 70-1201/B3-08 on 830331-0603. No noncompliance noted Major areas inspected: internal control, shipping & receiving & followup on previous insp findings. Details withheld (ref 10CFR2.790).

  JONES D. W. RICHARDS B.L. Region 2. Office of Director.

  MGALPINE, E. J. Division of Emergency Preparedness & Materials Safety. 83/06/28. ip, 19514:050.
- 8307140279 Forwards IE Bafeguards Insp Rept 70-1201/83-07 on 830516-20. No noncompliance noted. 8TOHR.J.P. Division of Emergency Preparedness & Materials Safety. 83/06/28. ALTO.R.A. Bebcock & Wilcox Co. 2pp. 19514:051.
- --8307140283 IE Bafeguards Insp Rept 70-1201/83-07 on 830314-20. No noncompliance noted. Hajor areas inspected: NG-852128 physical inventory observation & MC-852138 physical inventory verification. Details withheld (ref 10CFR2, 790). CLAY.E. L. Region 2. Office of Director. MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety. 83/06/28. 1p. 19314:033.
- 8307/110063 Forwards renewed Matis License SNM-1168. Requests for amend should be submitted in form of replacement pages to conditions sections. License expires on 880531.

  PAGE.R.O. Uranjum Fuel Licensing Branch. 83/06/29. FORD, J. T. Babcock & Wilcox Co. 1p. 19386:305.
- ---8307110067 Renewed Matis License SNM-1168 for B&W, authorizing storage of U hexafluoride; fabrication of U disside & possession & use of sealed sources (Fu & Ca) & possession of unitradiated reactor fuel at other sites in US. GROW-W.T. Division of Fuel Cycle & Material Safety. 83/06/29, 4pp. 17386:306.
- ---8307110070 SER supporting issuance of renewed Hatls License SNM--1168. KOSLA, B. M., KETZLACH, N., CROW, W. T. Division of Fuel Cycle & Haterial Safety, 83/03/10. 51pp, 19386:312.

- DOCKET 70-1257 EXXON NUCLEAR CO. , INC. , RICHLAND, WA
- 8307110643 Clarifies safeguards licensing policy re inventory requirements of SNM contained in liquid & solid waste matls stored at site. Request for exception from 10CFR70. 51 should be submitted for storage of holding account waste discards. SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/13. SCHNEIDER.R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 2pp. 19434:121.
- 8307110594 Advises that 821202 Rev 4 to Figure 1-2 to physical protection plan for matl of low strategic significance acceptable. Revised drawing reflects expansion of protected area boundary to encl addl storage lagoon. RENTSCHLER. R. Fuel Facility Safeguards Licensing Branch. 83/01/28. MALODY.C.W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 19. 19434:097.
- 8307110582 Disapproves request for annual physical inventory due to conflict of interest w/IAEA regulations. Chapters 1,2 & 3 should be revised to conform w/comments. Comments re sections of Rev 13 dreft encl.

  8HITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/02/01.

  8CHNEIDER.R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). ip. 1939: 244
- 8307200513 Rev 12 to XN-NF-32A, "Emergency & Radiological Contingency Plan: "Part 1. BROWN,C.O., MILES,R.L., DAVIS,T.L. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 83/02/18. 9pp. 19672:281.
- B307180110 Forwards IE Insp Rept 70-1257/83-02 on 830418-22 No noncompliance noted, BOOK,H.E. Region 5, Office of Director. B3/06/28. MALODY,C.W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 2pp. 19557:031.
- --8307180117 IE Insp Rept 70-1257/83-02 on 830418-22. No noncompliance noted Major areas inspected: Part 21 reporting, organization, facility changes & mods, internal review & audit, procedure control, maint, radiation protection & operation review. BROCK, B. L., THOMAS, R. D., BOCK, H. E. Region 5, Office of Director. 83/06/28. 13pp. 19557:033.
- 8307110384 Forwards IE Safaguards Insp Rept 70~1257/83-04 on 830423. No noncompliance noted. NORDERHAVG.L.R. Region 5. Office of Director. 83/07/01. NILBON,R. Excon Nuclear Co., Inc. (subs. of Exxon Corp.). 2pp. 19381:312.
- --8307i1037i IE Safeguards Insp Rapt 70-i257/83-04 on 830423. No noncompliance noted Major areas inspected:general requirements for SNM of low strategic significance & independent effort. Details withheld (ref 10CFR2. 790). SCHWAN, C. A., NORDERHAUG, L. R. Region 5, Office of Director. 83/07/01. 1p. 19381:314.
- DOCKET 70-1308 GENERAL ELECTRIC CO., SAN JOSE, CA
- 8307110587 Advises that changes to physical security plan acceptable. Plan format changed by including contingency plan, guard training plan & final transportation security plan per 10CFR72. Bi. License Conditions 9.1. & \$9.1.8 amended.

  8MITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/14. DAW80N,D.M. Qeneral Electric Co. ip. 19391;345.
- 8307280038 Advises that editorial errors found in Rev 7 to NEDO-20776, "SF80/GEUMCO GA Plan." New rev being prepared, DAMBON.D.M. General Electric Uranium Management Corp. 83/07/08. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 1p. 19826:016.

1

- DOCKET 70-1353 DEACONESS HOSP., MILWAUKEE, WI
- 8307210031 Discusses IE insp of Licenses BNM-1367 & 48-00988-04 on B30512-16. No noncompliance noted. Major areas inspected; procedures & records, observations, independent measurements & interviews w/personnel. Amend to License GNM-1367 required. WIEDEMAN.D.Q. Region 3, Office of Director. 83/05/31. KAGNER, J.R. Good Samaritin Medical Center, Milwaukse, WI (formerly Deaconess Hosp.), 1p. 17468:347.
- DOCKET 70-1359 IRT CORP. , BAN DIEGO, CA
- 8307120076 Forwards IE Insp Rept 70-1357/83-01 on 830519. No noncompliance noted. BOOK.H.E. Region 5. Office of Director. 83/07/08. CROSBIE, K.L. IRT Corp. 1p. 19423:028.

- THE GOVERNMENT OF THE PROPERTY OF THE PROPERTY
- DOCKET 70-1406 VETERANS ADMIN. HOSP., NEW ORLEANS, LA
- 日日の7260188 Advises of expiration of License SNM-1376 & discusses actions to be taken by licensee. BROWN,G.D. Region 4. Office of Director. 83/07/20. DILLENKOFFER,R. Vet. Admin. Hosp. New Orleans,LA. 2pp. 19727:343.
- DOCKET 70-1486 BUTTERWORTH HOSP. , GRAND RAPIDS, MI
- □□07110045 IE Insp Findings & Licensee Ack dtd 830630 of License

   □NM-1432 Insp findings:no violations observed. Steps taken

   to correct violations noted in previous insp verified.

   ★ Region 3, Office of Director. 83/06/30. ip. 19373:252.
- DOCKET 70-1703 EASTMAN KODAK CO., ROCHESTER, NY
- 19307110351 Forwards IE Safeguards Insp Rept 70-1703/83-01 on 830602. No noncompliance noted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/06/22.

  HARTUR.E.B. Eastman Kodak Co. 2pp. 19381: 308.
- DOCKET 70-1779 AMERICAN STEEL FOUNDRIES, EAST CHICAGO, IN
- S307220101 IE Insp Findings & Licensee Ack dtd 830714 of License SNM-1509. Insp findings: date of birth, social security number & Individual name not provided on exposure records per 1 OCR820, 401(a).
  SLAWINGKI, W. J. Region 3, Office of Director. 83/07/14. 1p. 19683:345.
- DOCKET 70-2204 BLODGETT MEMORIAL MEDICAL CENTER, GRAND RAPIDS, MI
- ⊕307220321 Discusses IE insp of Licenses 21-01424-03 & SNM-1614 on B30627 & forwards notice of violation. BRENIAWSKI.D.J. Region 3. Office of Director. 83/07/19. VANLOPIK.M. Blodgett Nemorial Hosp. Grand Rapids.MI. 2pp. VANLOPIK.W. 19685: 027.
- 19499-029
- DOCKET 70-2319 OUR LADY OF LOURDES HOSP. CAMDEN, NJ
- B307250116 Discusses IE Insp Rept 70-2319/83-01 on 830513 Noncompliance noted; possession of SNM u/o valid license. Application for new license must be submitted.

  MARTIN.T.T. Division of Engineering & Technical Programs. 83/07/19.

  PETERS.A. Dur Lady of the Lourdes Hosp. Camden.NJ. 2pp. PETERS, A. 19706; 069.
- DOCKET 70-2609 COMMONWEALTH EDISON CO. . CHICAGO, IL
- ©307110578 Advises that "Security Plan for SNM for Comm Ed, LaSalle County Station," no longer applicable since station received OL on 820417. Physical security plan submitted per 10CFR73. 35 replaces physical protection requirements:

  BROWN. W. B. Fuel Facility Safeguards Licensing Branch. 83/02/07.

  DUKE, W. L. Commonwealth Edison Co. 1p. 19391: 348.

- DOCKET 70-2885 COMMONWEALTH EDISON CO., CHICAGO, IL
- 8307110598 Advises that "Security Plan for SNM for Comm Ed.LaSalle County Station," no longer applicable since station received OL on 820417. Physical security plan submitted per 10CFR73. 55 replaces physical protection requirements.

  BROWN.W.B. Fuel Facility Safeguards Licensing Branch. 63/02/09. DUKE.W.L. Commonwealth Edison Co. 1p. 19391:348.
- DOCKET 70-2926 DETROIT EDISON CO. DETROIT, HI
- 8307190023 Forwards executed Amends 24 ½ 25 to Indemnity Agreement B-20. effective 830531, per 830931 memo 9CHUERMAN.L. E. Detroit Edison Co. 83/06/27. PAGE.R.G. Uranium Fuel Licensing Branch 4pp. 19369:346.
- 8307190330 Corrects statement in SER for License SNM-1915. Statement in Section V. D that fuel bundles handled by reactor operators was taken from FSAR Statement applies to fuel after irradiation.not initial fuel receipt. TAUBER, M. Detroit Edison Co. 83/07/07. KETZLACH, N. Division of Fuel Cycle & Material Safety. 1p. 19644: 350.
- DOCKET 70-2945 UNION ELECTRIC CO. , ST. LGUIS, MO
- B307190024 Advises that Amend 2 to License SNM-1901 issued authorizing use of crames in vicinity of fuel bldg & use of cask handling crame over spent fuel storage pool subj to Condition 17.per B30516 application & B30617 suppl. PAOE, R. G. Uranium Fuel Licensing Branch. B3/06/30. SCHNELL, D. F. Union Electric Co. 2pp. 19569: 340.
- --8307190026 SER re licensee 830516 application & 830617 suppl for amend to License SNM-1901, requesting use of crames in vicinity of fuel bidg & use of cask handling crame over spent fuel pool. Issuance of amend recommended.

  KETZLACH.N., CROW.W. T. Uranium Fuel Licensing Branch. 83/06/30. KETZLACH, N., CR 4pp. 19569: 342
- DOCKET 70-2946 LOUISIANA POHER & LIGHT CO., NEW ORLEANS, LA
- 8307050406 Forwards Endorsements 10 & 11 to NELIA Policy NF-263. DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/15. Office Nuclear Material Safety & Safeguards, Director. Spp. 17263:307
- 8307290302 Advises that no licensing action necessary re 830712 ltr on plans to correct orientation of poison assemblies as long as only one poison assembly removed from fuel racks at any given time.

  SERINI.B.L. Uranium Fuel Licensing Branch. 83/07/20. WILKENS.R. Louisiana Power & Light Co. 1p. 19898:348.
- DOCKET 70-2947 ILLINOIS POWER & LIGHT CO. DECATURE IL
- 8307280134 Responds to 9 Serini verbal request for info re procedures for handling of neutron calibr sources. Info to be used in review of 930425 request for amend to License 9MM-1986. WULLER.G.E. Illinois Power Co. 83/07/08 CUNNINGHAM.R.E. Division of Fuel Cycle & Material Safety. 2pp. 19826:033.
- DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA
- R307110140 Advises that License SNM-1890 amended authorizing receipt, possession, assembly into source holders & installation in reactor vessel of total of 14 antimony-beryllium sealed sources containing max 3,000 curies/source. PAGE.R.O. Uranium Fuel Licensing Branch. 83/06/29. BOUCHEY.G.D. Washington Public Power Supply System. 1p. 19386:127.
- --8307110147 Safety evaluation supporting issuance of amend to License SNM-1870 re receipt possession, assembly into source holders & installation into reactor vessel of 14 antimony-beryllium sealed sources. KETZLACH.N. Uranium Fuel Licensing Branch, 83/06/29. Spp.
- 830720045B Responds to Mar 1983 request for add1 info re SER Confirmatory Issue 7. component supports. Predicted primary stress combination w/s!1 support loads resulting from normal piping thermal expansion loss than allowable stress. BOUCHEY. O. D. Mashington Public Power Supply System. 83/06 BCHWENGER. A. Licensing Branch 2. 11pp. 19672: 233. 83/06/30.

B307120529 Forwards IE Safeguards Insp Rept 70-2950/83-01 on B30620-22. No noncompliance noted Rept withheld (10CFR2.790). NORDERHAUG, L. R. Region 5. Office of Director B3/07/07. BOUCHEY, C. D. Washington Public Power Supply System. 2pp.

DOCKET 70-2957 FLORIDA PONER & LIGHT CD . MIAMI. FL

8307050338 Requests change in annual indemnity fee for Amend 10 to License SNM-1209 License terminated. DINITZ, I. Assistant Director for State & Licensee Relations. 83/06/28. PUBLISE A.S. Division of Accounting. 1p. 17263:257.

DOCKET 70-2960 KANSAS GAS & ELECTRIC CO., WICHITA, KS

8307110565 Advises that 820706 "Molf Creek Generating Station Interim Security Plan for Protection of SNM of Low Strategic Significance," meets requirements of IOCFR73 67(f) & (g). Approved plan must be implemented by fuel receipt date. RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch. 83/01/23. KOESTER, G. L. Kansas Gas & Electric Co. 1p. 19391:303.

DOCKET 70-2973 COMMONWEALTH EDISON CO. , CHICAGO, IL

8306230264 Forwards advance revised pages to FSAR necessary to reclassify spent fuel pool liner from safety Category I structure to Category II. Info will be incorporated into next amend to FSAR. TRAMM, T.R. Commonwealth Edison Co. 83/06/20. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 18745:076. 24X Fiche: 50-000,83/06/20,8306230264.

8307050282 Application for amend to License SNM-1917 authorizing receipt 90585510m & storage of unirradiated fuel assemblies in amount necessary for operation of Byron Units 1 & 2. TRAMM, T. R. Commonwealth Edison Co. 83/06/20. DAVIS.J. G. Office of Nuclear Material Safety & Safeguards.Director. 2pp. 19263:127.

DOCKET 70-2974 NORTH KANSAS CITY MEMORIAL HOSP., NORTH KANSAS CITY, MD

8307050193 Discusses 1E insp of Licenses 24-18428-01 & SNM-1910 on 830607 & forwards natice of violation.
WIEDEMAN, D.G. Region 3, Office of Director. 83/06/28. HAYMONS, North Kansas City, MO. 1p. 19199: 054 HAYMONS, L.

--8307050197 Notice of violation from insp on 830607 Noncompliance noted: Failure to repair dose calibrator during 820601-830607 & failure to perform Gaily surveys of preparation & injection areas since 800806.

HIEDEMAN.D. G. Region 3, Office of Director. 63/06/27. 2pp. 19199-1951

DOCKET 70-2982 ROCHESTER, UNIV. OF, ROCHESTER, NY

8307180006 Advises that submittal of physical security plan not needed for possession of U-235 under License SNM-1918, per License Condition 11.

COOL. D. A. Uranium Fuel Licensing Branch. B3/06/30. GREGORY, W. D. Rochester, Univ. of.. 1p. 19567: 358.

DOCKET 70-2983 PENNSYLVANIA POWER & LIGHT CO , ALLENTONN, PA

8307140105 Forwards response to request for add1 info on SNM license application for new fuel storage & receipt Application exampt from licenseing fees.

CURTIS.M.W. Pennsylvania Power & Light Co. 83/06/20. Office of Nuclear Material Safety & Safeguards Director. 178pp. 19528:123. Office of

8307180415 Forwards 830620 application for SNM license for receipt & storage of new fuel. W/o ancl. KETZLACH.N. Uranium Fuel Licensing Branch. 83/07/12. CUTCHIN.J.M. Office of the Elecutive Legal Director. 1p. 19366:357.

8307180416 Forwards 830620 application for SNM license for receipt to storage of new fuel. (470 encl. KETZLACH.N. Unanium Fuel Licensing Branch. 83/07/12. PERCH.R.L. Licensing Branch 2. 1p. 19566.956.

DOCKET 70-2988 PHILADELPHIA ELECTRIC CO., PHILADELPHIA, PA

B307290317 Forwards application for SNM, requesting authorization to receive possess & store fuel assemblies for initial core at facility & certain nuclear instrumentation.

BRADLEY, E. J. Philadelphia Electric Co. 83/06/01. DAVIS, J. G. Division of Safeguards. 4pp. 19859:001.

---8307290329 Application for SNM license authorizing receipt, possession & storage of fuel assemblies for initial core at facility & certain nuclear instrumentation. W/two oversize figures.

Aperture cards are available in PDR.

BAUER, E. G., BRADLEY, E. J. Philadelphia Electric Co. 83/06/01.

36pp. 19859:005.

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0004 GENERAL ELECTRIC CO.

8307270355 Advises of rev to NEDO-20776, "BFSO/GE U Mgt Corp GA Plan." Rev B will be forwarded upon completion. DAMSON.D.M. General Electric Co. 83/07/08. ROUSE,L.C. Advanced Fuel & Spent Fuel Licensing Branch. 2pp. 17858:102.

DOCKET 71-0037 NAVY, DEPT. OF

B307220020 Forwards Rev 1 to Svc School Command QA program for transportation packaging of radioactive matl per 10CFR71.51. MORRIS.W.J. Navy, Dept. of. B3/07/OS. Transportation Branch. 3pp. 19692:135.

--B307220024 Rev 1 to Bvc School Command QA plan for transportation packaging of radioactive matl per 10GFR71.51.

SCHLEICHER.R. J. Navy, Dept. of. 83/06/03. 10pp. 19692:137.

DOCKET 71-0210 GULF NUCLEAR, INC.

B307200466 Forwards revised QA program for mfg of components used in radiography & oil industry.per B30613 request. HDPCRAFT.C.P. Quif Nuclear, Inc. B3/07/08. MACDUNALD.C.E. Transportation Branch. 1p. 19672:188.

--8307200467 GA program for mfg of components used in radiography & oil industry. \* Gulf Nuclear: Inc. 83/06/15. 19pp. 19672:190.

8307290577 Forwards QA program approval for Radioactive Matl Pactage 0210, Rev 1.

MACDONALD, C. E. Transportation Branch. 83/07/14. HQPCRAFT, C. P.

Gulf Nuclear, Inc. 1p. 19716; 345.

--8307250582 GA program approval for Radioactive Matl Package 0210, MACDQNALD,C.E. Transportation Branch. 83/07/14. 1p. 19716:346.

DOCKET 71-0231 CHEM-NUCLEAR SYSTEMS, INC.

B30729038! Procedure TR-DP-005, "Gasket/Seal/O-ring Replacement/Repair Procedure for CNSI Cask Fleet." POPPE, L. K. Chem-Nuclear Systems, Inc. B3/07/08. MACDONALD.C. E. Transportation Branch. 26pp. 19858:019.

DOCKET 71-0318 MARATHON GIL CO.

8307290380 Advises that request for specific documents should be made to PDR in Washington,DC in response to 830718 request for info or copies of Docket File 71-0318.

MACDUNALD.C.E. Transportation Branch. 83/07/22. OSBORNE,A. Marathon Oil Co. 1p. 19857:398.

DOCKET 71-0496 NUS CORF.

8307060359 Forwards QA program per requirements of iOCFR71.Revised program consists of expanded version of original submittal dtd 830302.Rev addresses shipping cask design & fabrication.

MOTL.G.P. NUS Corp. B3/06/20. MACDONALD.C. Transportation Branch. 19299: 277

- /-8307060366 Rev A to "GA Program Plan for Design:Fabrication. Procurement Use, Maint & Repair of Packaging Used in Transport of Radioactive Matl." \* NUS Corp. 83/06/17. 32pp. 19299 278
- #307130315 Forwards request for addl info re 830630 application for approval of Rev A to GA Plan GA-014.

  MACDONALD.C.E. Transportation Branch 83/07/07. MGTL.G.P. NUS Corp. 2pp. 19510:022.
- 307290369 Forwards QA-014.Rev B. "QA Program Plant for Design. Fabrication.Procurement.Use.Maint & Repair of Packaging Used in Transport of Radioactive Matl." Plan revised to address issues in NRC 830707 ltr.
  MOTL.G.P. NUS Corp. 83/07/12. MACDONALD.C.E. Transportation Branch. 1p. 19838:295.
- y-8307290375 Rev B to "GA Program Plan for Design, Fabrication, Procurement, Use, Maint & Repair of Packaging Used in Transport of Radioactive Matl." RIVERIA.J.A., CASELLIA.E., MOTL, G.P. NUS Corp. GA-014 RB. 83/07/19. 91pp. 19858: 276.
- **₽**ОСКЕТ 71-0499 КОКОМО ТОВЕ СО.
- @307130039 Forwards QA program approval for Radioactive Matl Package 0447, Nev O. MACDUNALD, C. E. Transportation Branch. 83/06/29. SMITH, R. Kokomo Tuba Co. ip. 19511:306.
- →B307130045 QA program approval for Radioactive Matl Package 0499,Rev 0. MACDQNALD, C. E. Transportation Branch. B3/04/29. 1p. 19511:307.
- DOCKET 71-0500 E. I. DU PONT DE NEMOURS & CO. . INC.
- 8307090034 Requests permission to package & ship radioactive matls containing more than Type A quantity. Approval of encl GA program also requested.

  SIMONA.C. E.1. du Pont de Nemours & Co., Inc. 83/06/09. GDRDUN, L. Transportation Branch. 1p. 19384:103.
- --B30709003B GA program for packaging matls in excess of Type A E I, du Pont de Nemours & Co. . Inc. 83/06/13. 3pp. 19384.104.
- 8307130030 Forwards OA program approval for Radioactive Matl Package USUGATEV D. MACGONALD, C.E. Transportation Branch. 83/07/07. SIMON, A.C. E.I. du Pont de Nemours & Co., Inc. ip. 19511:312.
- --8307130036 9A program approval for Radioactive Matl Package 0500,Rev 0. MACDONALD,C.E. Transportation Branch. 83/07/07. 1p. 19511:313.
- DOCKET 71-0501 SCIENTIFIC INSPECTION TECHNOLOGY, INC
- SIGO7190235 Forwards QA program for transportation/packing of radioactive math. Registration as user of Gamma Industries Models 100. 100A, Century S & SA, Universal S & SA, C-B & 6717B & Tech Ops Models 715.660.680 & 650 requested.
  COX.D.L. Scientific Inspection Technology, Inc. 83/05/03. MACDONALD, C.E. Transportation Branch. 7pp. 19659:020.
  - `8307190244 GA program for transportation/packing of radioactive matl.
    # Scientific Inspection Technology, Inc. 83/05/03. 9pg.
    19455:027.
- ~8307190246 Procedure RGPM-1, "Radiographic Safety Procedure Manual." \* Scientific Inspection Technology, Inc. 83/05/03. 328pp. 19655:037.
- DOCKET 71-0502 VERMONT YANKEE NUCLEAR POWER CORP.
- O7250519 Requests exemption from lOCFR71 provisions inconsistent w/revised hazardous matis regulations & adoption of recent DOT final rules re shipment of radioactive mati. HEIDER.L.H. Vermont Yankee Nuclear Power Corp. 83/07/07. DAVIS.J.G. Office of Nuclear Material Safety & Safeguards.Director. 2pp. 19740:177.

- DOCKET 71-4909 MODEL: GE 21PF-1, GENERAL ELECTRIC CO
- 8307080374 Summary of 830527 meeting w/Westinghouse in Silver Spring, MD re-stainless steel overpack for 30-inch U herafluoride re manuses cylinders. ODEGAARDEN.R.H Transportation Branch 83/06/29 Branch 2pp. 19364: 293. Transportation
- DOCKET 71-5026 MODEL CNS 14-190, CHEM-NUCLEAR SYSTEMS, INC
- B307150442 Application to amend Certificate of Compliance 5026 for Model CNS 14-190 to incorporate use of ASTM-A-515 Grade 70 or Atcor approved equivalent stee!
  PDPPEL K Chem-Nuclear Systems, Inc. B3/06/17. MACDDNALD.C.E. Transportation Branch. Spp. 19540:217
- B307250569 Forwards Rev 8 to Certificate of Compliance 5026 for Model CNS 14-190. MACBONALD.C.E. Transportation Branch. 83/07/14. DEAL.R. Chem-Nuclear Systems. Inc. 3pp. 19715-356.
- --8307250573 Certificate of Compliance 3026.Rev 8 for Model CNS 14-190. MACDONALD, C. E. Transportation Branch 83/07/14, 4pp. 19715:339
- DOCKET 71-5450 MODEL: RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP.
- B3071B0025 Application for amend to Certificate of Compliance 5450 for Model RCC. Amend permits shipment of higher enrichment fuels.

  NARDI.A.J. Westinghouse Electric Corp. B3/06/14. MACDONALD.C.E. Transportation Branch. 64pp. 19641:138
- B307290411 Forwards Rev 16 to Certificate of Compliance 5450 for Models RCC,RCC-1,RCC-2,RCC-3 & RCC-4 HACDDNALD,C E. Transportation Branch B3/07/22 NARDLA.J. Wastinghouse Electric Corg. 2pp. 19858-046.
- --8307290422 Certificate of Compliance 5450 Rev 16 for Models RCC.RCC-1, RCC-2.RCC-3 & RCC-4. MACDONALD, C. E. Transportation Branch. 83/07/22 6pp. 19858.048.
- DOCKET 71-5552 MODEL: GAS CYLINDER FIRE IMPACT SHIELD, ENERGY, DEPT.
- B307190030 Forwards SAR & Certificate of Compliance 5552.Rev 4.for Model ORNL gas~cylinder fire impact shield FRICHARD.R.P. Energy. Dept. of 83/06/29 MACBONALD.C E Transportation Branch. 1p. 19656:264.
- --8307190032 Certificate of Compliance 5552.Rev 4.for Model ORNL.gas cylinder fire impact shield. TRAVIS.W.H. Energy, Dept. of. 83/05/13. 2pp. 19656:265.
- --8307190035 "SAR for Packaging ORNL Gas-Cylinder Fire & Impact Shield." EVANS.J.H.: LEVINE.D.L.: EVERSOLE.R.E. Oak Ridge National Laboratory. ORNL/ENG-TM-5/RI. 83/06/29. 113pp. 19569:171.
- 8307280218 Advises of inadvertent umission of Procedure 16A, "Bidg 3033, Krypton & Tritium Facility, Procedure for Leak Testing Loaded Tritium Cylinders for Shipment," from Rept DRNL/ENG/TM-5, Rev 1, App C. TRAVIS, W. H. Energy, Dept. u6. 83/07/04. MACDDNALD, C. E. Transportation Branch. 1p. 19826:070
- --B307280223 Procedure 16A, "Bldg 3033 Krypton & Tritium Facility Procedure for Leak Testing Loaded Tritium Cylinders for Shipment." \* Dak Ridge National Laboratory. 78/10/11. 2pp. 19826:071.
- B3D7250557 Forwards Rev O to Certificate of Compliance 5952 for Model Gas Cylinder Fire Empact Shield MACDUNALD.C.E. Transportation Branch. 63/07/13. PRICHARD.R.P. Energy. Dept. pf. 1p. 19716-003.
- --8307250562 Certificate of Compliance 5552 Rev 0 for Model Gas Cylinder Fire Impact Shield. MACDUNALD, C. E. Transportation Branch. 83/07/13, 5pp. 19716:004.

- DOCKET 71-5641 MODEL: UNC-2500, UNITED NUCLEAR CORP.
- 8307130017 Forwards Rev 5 to Certificate of Compliance 3641 for Model UNC-2500 MACDDNALD.C.E. Transportation Branch 89/06/27 KIRK.W.F. United Nuclear Corp. 1p. 19511:357.
- ~-8307130022 Certificate of Compliance 5641, Rev 5, for Model UNC-2500. MACDONALD, C. E. Transportation Branch. 83/06/29. 4pp. 19511:358.
- DOCKET 71-5787 MODEL: D-28, ENERGY, DEPT. OF
- 8307190275 Requests registration as user of Model ORNL D-38. MOHRY, H. R. GA Technologies, Inc./General Atomic Co. 83/06/27. MACDONALD, C. E. Transportation Branch. ip. 19636: 205.
- BOCKET 71-5805 MODEL: CNS-3-55, CHEM-NUCLEAR SYSTEMS, INC.
- 8307280023 Requests registration as user of Model CNS 3-55 shipping cask. NEAL, T.P. Consumers Power Co. 83/07/15. MACDONALD.C.E. Transportation Branch. Ip. 19826.020.
- 8307290372 Forwards request for additinfo re 820429 request for Rev 0 to Certificate of Compliance 5805 for Model CN6 3-55.
  MACDDNALD, C. E. Transportation Branch. 83/07/22. DEAL, R. Chem-Nuclear Systems, Inc. 3pp. 19857: 359.
- DOCKET 71-5828 MODEL: TREAT, ENERGY, DEPT. OF
- B307220641 Requests registration of Union Carbide Corp as user of Model TREAT. WEINTRAUB, A.A. Energy, Dept. of. B3/07/07. MAGDONALD, C.E. Transportation Branch. 1p. 19697: 040.
- DOCKET 71-5874 MODEL: WAPD-40. ENERGY. DEPT. OF
- 8307110085 Forwards request for add1 info re 820420 application, supplemented on 830301, requesting amend to Model MAPD-40. Submittal schedule requested within 30 days of ltr receipt. MACDONALD.C.E. Transportation Branch. 83/04/23. ENGEL.W.P. Energy, Dept. of. 3pp. 19386:287.
- DOCKET 71-5957 MODEL: BMI-1, BATTELLE COLUMBUS LABORATORY
- 8307050326 Application for rev to Certificate of Compliance 3957 withdrawing PULSAR fuel from list of contents.
  BURIAN, R. J. Battelle Memorial Institute, Columbus Laboratories, 837067(3. MACDONALD, C.E. Transportation Branch. Spp. 19221: 188.
- --8307050327 Rev D to "SAR for Model BMI-1 Shipping Cask." \* Battelle Hemorial Institute, Columbus Laboratories. 83/11/23. 104pp. 19221:194.
- B307130066 Notification of registration as user of Model BMI-1 in response to B30430 request. MACDONALD, C.E. Transportation Branch. 83/07/07. WETHY, C.M. Florida Power & Light Co. 1p. 19526:002.
- 8307190392 Notification of registration as user of Model BHI-1 in response to 830513 request. MACDONALD.C.E. Transportation Branch. 83/07/08. DEIGEL.H.J. Texas A&M Univ.. College Station. TX. 1p. 19644:362.
- DOCKET 71-5971 MODEL: GE-200, GENERAL ELECTRIC CO.
- B307130042 Notification of registration as user of Model GE-200 in response to B30508 request. MACDANALD, C.E. Transportation Branch. 83/07/07. MILLER, R. I. Sacramento Municipal Utility District. ip. 19511:305.
- B307280004 Forwards revised Model 200 certification drawings per B30504 request. CUNNINGHAM.G.E. General Electric Co. B3/07/18. MACDONALD.C.E. Transportation Branch 10pp. 19826:286.

- DOCKET 71-6078 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC.
- 8307080623 Notification of registration as user of Models 927A1 & 627C1 in response to 830325 request.
  MACDDNALD, C. E. Transportation Branch. 83/06/27. ANDOGNINI. G. C. Arizona Public Service Co. 1p. 19364: 226.
- DOCKET 71-4272 MODEL: 6272, U.S. ECOLOGY, INC.
- 8307270273 Forwards one oversize drawing in support of 830415 application to amend Certificates of Compliance 6400 & 6272, in response to NRC request Aperture card available in PDR. MOSERR M. Energy Dept. of. 83/07/12. MACDONALD.C.E. Transportation Branch. 1p. 19858:169.
- 8307250576 Forwards Rev 4 to Certificate of Compliance 4272 for Model 6272. MACODONALD.C.E. Transportation Branch. 83/07/15. MOSER,R.M. Energy, Dept. of. 3pp. 19716:337.
- B307290581 Certificate of Compliance 6272, Rev 4, for Model 6272, MACDDNALD, C. E. Transportation Branch. 83/07/15. 5pp. 19716: 340.
- DOCKET 71-6286 MODEL: CMB-11, ENERGY, DEPT. OF.
- B307120034 Advises that Rev O to Certificate of Compliance 6286, for Model CHB-il expired on 830531.

  MACDDNALD, C. E. Transportation Branch. B3/06/28. BARRACLAUGH, E. Energy, Dept. of. 1p. 19435:361.
- DOCKET 71-6346 MODEL: FSV-1, GENERAL ATOMIC CO.
- 8307220130 Requests registration as user of Model FSV-19. MANOAN.C.V. Niagara Mohawk Power Corp. 83/07/06. DAVIB.J.G. Office of Nuclear Material Safety & Bafeguards, Director. 1p. 19692:357.
- 8307270335 Advises that use of FSV-1 shipping cask will commence Jul 1983 approved under Certificate of Compliance 6346.dtd 800828. MURPHY.W.P. Vermont Yankes Nuclear Power Corp. 83/07/18. Office of Nuclear Material Safety & Safeguards, Director. 1p. 19858:137.
- DOCKET 71-6400 MODEL: 6400, WESTINGHOUSE ELECTRIC CORP.
- 8307290361 Forwards "BAR for Packaging Super Tiger Shipping Container as Adapted for Small Numbers of LWBR Type Fuel Rods (LWBR Development Program)."

  ENGEL, M. P. Energy, Dept. of. 83/07/08. MACDONALD, C. E. Transportation Branch. 2pp. 19858:034.
- --8307290367 "SAR for Packaging Super Tiger Shipping Container as Adapted for Small Numbers of LWBR Type Fuel Rods (LWBR Development Program)."
  PLUMMER, D. E. Energy, Dept. of. WAPD-LP(CE)-256, 83/05/31, 2ipp. 19858:036.
- ~-B307290370 Rev 1 to "Min Critical Numbers of LWBR Rods & Pellets. LAUDE, L. Energy, Dept. of. WAPD-RS(CC) R01. 72/04/30. 21pp. 1985B:077.
- ---B307290374 Certificate of Compliance 6400, Rev 3.for Model BAPL 5910. \* Energy, Dept. of. 83/07/08. 2pp. 19858:098.
- 8307290273 Forwards one oversize drawing in support of 830415 application to amend Certificates of Compliance 6400 & 6272, in response to NRC request Apenture card available in PDR. MOSER, R. H. Energy, Dept. of. 83/07/12. MACDONALD, C. E. Transportation Branch. 1p. 17858:169.
- 8307250603 Forwards Rev 13 to Certificate of Compliance 6400 for Model 6400. MACDDNALD.C.E. Transportation Branch. 83/07/14. MOSER.R.M. Energy, Dept. of. 3pp. 19718:057.
- --8307250609 Certificate of Compliance 6400 Rev 13 for Model 6400. MACDONALD.C.E. Transportation Branch. 83/07/14. 7pp. 19718:060.
- 8307270386 Discusses 801014 application re repairs to Model 6400 packaging Licensing action closed.
  MACDONALD, C.E. Transportation Branch. 83/07/22. SCOVILLE, J. J. UB Ecology, Inc. (formerly Nuclear Engineering). 1p. 17857:357.

DOCKET 71-6406 MODEL: NONE, ENERGY, DEPT. OF

B307080657 Forwards Rev 3 to Certificate of Compliance 6406 for shipping unirradiated fuel assemblies, MACDDNALD.C.E. Transportation Branch. 83/06/23. ENGEL,W.P. Energy, Dept. of. 1p. 19364:131.

--8307080469 Certificate of Compliance 6406 Rev 3 for shipping unirradiated fuel assemblies.
MACDONALD.C.E. Transportation Branch 83/06/23. 5pp. 19364:132.

DOCKET 71-6495 MODEL: PADUCAH DEMONSTRATION CASK, ENERGY

8306240429 Advises that NRC 830506 request for add1 info re Paducah demonstration cask has been forwarded to field ofc for review. Amended DOE Certificate of Compliance 6495 re fuel return encl. W/one oversize drawing. Aperture card is in PDR. PRICHARD.R.P. Energy, Dept. of. 83/06/13. MACDDNALD.C.E. Transportation Branch. 1p. 18999:102.

DOCKET 71-6550 MODEL: 6-08-1, ENERGY, DEPT. OF

B307210367 Forwards LBL-2168, "Analysis of Neutron Shipping Container 6-98-1" & seven oversize drawings in response to NRC B30608 request. Prompt recertification of Certificate of Compliance 6550 requested for Model 6-09-1.

PRICHARD.R.P. Energy, Dept. of, 83/07/01. MACDUNALD.C.E. Transportation Branch. Ip. 19688:001.

--B307210373 "Analysis of Neutron Shipping Container 6-GS-1."
WIQLE, Q. L., DRINGHAM, P. S. Laurence Berkeley Laboratory. LBL-216B.
74/02/2B. Atomic Energy Commission. 91pp. 19688:002.

8307250553 Forwards Rev O to Certificate of Compliance 5650 for Model 6-08-1.
MACDONALD, C. E. Transportation Branch. 83/07/14. JACKSON, C. D. Energy, Dept. of. 2pp. 19740:181.

--B307250575 Certificate of Compliance 6550, Rev O.for Model 6-08-1. MACDONALD.C.E. Transportation Branch. 83/07/14. 3pp. 19740:183.

DOCKET 71-6601 MODEL: CNB 8-120, CHEM-NUCLEAR SYSTEMS, INC.

B307190027 Forwards Rev 1 to SAR for Model CNS B-120. PDPPE.L.K. Chem-Nuclear Systems, Inc. B3/06/29. MACDDNALD,C.c. Transportation Branch. 3pp. 19369:334.

8307280125 Delineates corrective actions to determine cause & prevent recurrence of defective primary lid bolts found on CNS 8-120 shipping cask. Encl procurement spec implemented. PDPPELL.K. Chem-Nuclear Systems, Inc. 83/07/18. MACDONALD, C. E. Transportation Branch. (3pp. 19812:332.

DOCKET 71-6679 MODEL: 6679, U.S. ECOLOGY, INC.

8307130033 Forwards application for renewal of Certificate of Compliance 6679 authorizing use of Half Super Tiger overpack for Type B quantities of radioactive metl. Supporting repts encl. W/o application for Certificate of Compliance 6679.

HALLER, W. K. US Ecology, Inc. (formerly Nuclear Engineering).
83706/30. MACDUNALD, C. E. Transportation Branch. 1p. 19362:003.

--8307150035 "8AR for Packaging (SARP) Helf Super Tiger." W/two oversize drawings & two procedures Aperture cards are available in PDR. US Ecology, Inc. (formerly Nuclear Engineering). 83/06/20. 37pp.

--B307150038 Rev 1 to G-103, "Operational Insp Procedures for DDT Spec Containers 6400 & 6679.

# UB Ecology, Inc. (formerly Nuclear Engineering). 92/01/31. 5pp. 19562:041.

---8307150040 Rev O to G-113, "Torquing Procedure for DOT Spec Container \*\* US Ecology, Inc. (formerly Nuclear Engineering). 81/11/30. 2pp. 19562:046.

--8307150042 "Engineering Evaluation of Super Tiger Overpack Designed for Shipment of Large Quantities of Hazardous Matls." HANSEN.L.J., HAELSIG.R.T. Mechanics Research, Inc. C2378. 70/05/04. 106pp. 19362:048.

DOCKET 71-6698 MODEL: NFS-4, NUCLEAR FUEL SERVICES, INC.

B307080588 Summary of B30628 meeting w/TMI personnel in Silver Spring, MD re shipment of reactor core fuel mat(s.List of attendees & meeting agenda encl.

GDEGARDEN, R.H. Transportation Branch. 83/06/29. Transportation Branch. 6pp. 19364-283.

B307150391 Requests interpretation of Section (5(a) re cask cavity measurements for spent fuel shipments per Certificate of Compliance 6699, Rev 15 by B30815.
TUCKER, B. Duke Power Co. B3/06/30. MACDONALD.C.E.
Transportation Branch. 1p. 19540.320.

DOCKET 71-6708 MODEL: C-6, ENERGY, DEPT OF

B30713002B Notifies that Rev O to Certificate of Compliance 670B for Model C-6 expired on 821031.

MACDDNALD, C. E. Transportation Branch 83/06/28 PETERSON, J. M. Energy, Dept. of. 1p. 19511:315.

DOCKET 71-6771 MODEL: SN-1, METROPOLITAN EDISON CO.

8307190017 Requests that 820118 application for amend to Certificate of Compliance 6771 for Model SN-1 be withdrawn Shield insert no longer needed due to operational changes within EPICOR shipping program. shipping program. KANGA:B.K. General Public Utilities - GPU Service Corp. 83/06/27. MACDONALD:C.E. Transportation Branch. 1p. 19636:047.

8307290105 Ack receipt of 630627 ltr withdrawing 820118 application. Application for Model SN-1 deleted from review.per 820118 request. MACDUNALD.C.E. Transportation Branch. 83/07/12 KANGA.B.K. MACDONALD.C.E. Transportation Branch. 83/07/12 KANGA.B.K. General Public Utilities - GPU Service Corp. 1p. 19725:347.

DOCKET 71-9006 MODEL: 500-SU, AUTOMATION INDUSTRIES, INC.

B307270270 Forwards one oversize revised drawing re B30519 request to add shielding plates to several Automation Industries Model 500-8U Ir-192 source changer Aperture card is available in PING. MAYBERRY, G. B. Automation Industries, Inc. 83/07/14. MACDONALD.C.E. Transportation Branch. 1p. 19859.101.

DOCKET 71-9010 MODEL: NLI-1/2, NL INDUSTRIES, INC.

B30719001B Requests registration as user of Model NLI-1/2.
FAY, C. W. Wisconsin Electric Power Co. 83/06/27. MACDONALD, C. E. Transportation Branch. 1p. 19569: 360.

B307080588 Summary of B30628 meeting w/TMI personnel in Silver Spring, MD re shipment of reactor core fuel matls. List of attendees & meeting agenda encl.

DBEGARREN, R.H. Transportation Branch. 83/06/29 Transportation Branch. App. 19364: 283.

8307280433 Application for amend to Certificate of Compliance 9010, to authorize shipment of PWR fuel w/max average burnup to 40,000 MMD/MTU w/o borated fluid in neutron shield tank. JOHNBON.C.R. Nuclear Assurence Corp. 83/06/29. MACDONALD.C.E. Transportation Branch. 4pp. 19826:062

8307190415 Forwards Rev 11 to Certificate of Compliance 9010 for MACDONALD.C.E. Transportation Branch 83/07/12. JOHNSON.C.R. Nuclear Assurance Corp. 3pp. 19656.034.

--8307190420 Certificate of Compliance 9010. Rev 11. for Model NLI-1/2. MACDONALD. C. E. Transportation Branch 83/07/12. 6pp. 19656: 037.

DOCKET 71-9029 MODEL: 676 & 676E, TECHNICAL OPERATIONS, INC.

8307280149 Requests registration as user of Models 650,660,676,680 & 771. PETERSON.B.H. Morrison-Knudsen Co., Inc. 83/07/06. MACOGNALD.C.E. Transportation Branch. 1p. 19826:038

- DOCKET 71-9032 MODEL. 650. TECHNICAL OPERATIONS: INC
- 8307190236 Forwards GA program for transportation/packing of radioactive mati Registration as user of Gamma Industries Models 100.100A.Century S & SA.Universal S & SA.C-8 & 67178 & Tech Ops Models 715.660.680 & 650 requested. COX.D.L. Scientific Inspection Technology Inc. B3/05/03. MACDONALD.C.E. Transportation Branch. 7pp. 19655:020.
- 9307280149 Requests registration as user of Models 690,660,676,680 & 771.
  PETERSON, B. H. Morrison-Knudsen Co., Inc. 93/07/06. MACDONALD. C. E. Transportation Branch. 1p. 19826-038
- DOCKET 71-9033 MODEL: 660 & 660E, TECHNICAL OPERATIONS, INC.
- 8307:90236 Forwards QA program for transportation/packing of radioactive matl Registration as user of Gamma Industries Models 100:100A.Century S & SA.Universal S & SA.C-8 & 67:78 & Tech Ops Models 715.660.680 & 650 requested. COX.D.L. Scientific Inspection Technology. Inc. 83/05/03. MACDQNALD.C.E. Transportation Branch. 7pp. 19655:020.
- 8307280149 Requests registration as user of Models 650,660,676,680 & 771. PETERSON, B.H. Morrison-Knudsen Co., Inc. 83/07/06. MACDONALD.C.E. Transportation Branch. 1p. 19826:038
- 8307130034 Notification of registration as user of Models 600 & 600E in response to 830526 request. MACDONALD.C.E. Transportation Branch. 83/07/07. NEAL.T.P. Consumers Power Co. 1p. 19311:311.
- DOCKET 71-9035 MODEL: 680 & 680E, TECHNICAL OPERATIONS, INC.
- 8307190236 Forwards GA program for transportation/packing of radioactive matl Registration as user of Gamma Industries Models 100:100A, Century S & SA, Universal S & SA, C-8 & 67178 & Tech Ops Models 715, 660, 680 & 650 requested. COX.D. L. Scientific Inspection Technology. Inc. 83/05/03. MACDONALD.C.E. Transportation Branch. 7pp. 19655:020.
- 8307280149 Requests registration as user of Models 650,660,676,680 & & 771.
  PETERSON, B. H. Morrison-Knudsen Co., Inc. 83/07/06. MACDONALD, C. E. Transportation Branch. 1p. 19826:038.
- DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC.
- 8307190236 Forwards QA program for transportation/packing of radioactive mati. Registration as user of Gamma Industries Models 100.100A, Century 5 & SA. Universal S & SA. C-8 & 67178 & Tech Ups Models 719.660.680 & 650 requested.

  CDX. D. L. Scientific Inspection Technology. Inc. 83/05/03. MACDONALD, C. E. Transportation Branch. 7pp. 19655:020.
- DOCKET 71-9044 MODEL: GE-1600, GENERAL ELECTRIC CO.
- B307130029 Notification of registration as user of Model GE-1600 in response to 830331 request. MACDONALD.C.E. Transportation Branch. 83/07/07 JONES.W.C. Omaha Public Power District. 1p 19511:314.
- DOCKET 71-9049 MODEL: GE-500, GENERAL ELECTRIC CD
- 8307280214 Requests registration as user of Model GE-500. WEINTRAUB, A. A. Energy, Dept. of 83/07/06. MACDONALD, C. E. Transportation Branch. tp. 19826.068.
- DOCKET 71-9070 MODEL: N-55, ENERGY, DEPT. OF
- 8307190434 Natification of registration as user of Model N-55 in response to 830310 request. MACDDNALD.C.E. Transportation Branch 83/07/08. ANSELMO.A.A. EG&O. Inc. ip 19656:049.
- 8307220105 Responds to 830408 ltr requesting registration as package user. Approved GA program per IOCFR71 must be obtained prior to registration as user.

  MACDDNALD, C.E. Transportation Branch 83/07/12. GUIH, J. H. Kraft, Inc. 1p. 17691:344.

- DOCKET 71-9071 MODEL: AP-101, AMERCO, INC.
- 8307150431 Application for amend to Certificate of Compliance 9071 for Model AP-101, to include borosilicate & other silicate solid waste forms as contents.

  MURPHY, J. D. Anefro, Inc. 83/04/05. ODEGARDEN, R. Transportation Branch, 2pp. 19540:189.
- DUCKET 71-9079 MUDEL: HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR
- 8307150445 Requests registration as user of Model HN-100 Series 2. CUNNINOHAM G.E. General Electric Co. 83/06/22. MACDONALD, C.E. Transportation Branch. 1p. 19540:223.
- DOCKET 71-9080 MODEL: 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 8307130052 Notification of registration as user of Model 9080 in response to 830421 request.
  MACDONALD, C. E. Transportation Branch. 93/07/07. MIS, F. J. Rochester Gas & Electric Corp. ip. 19511:300.
- DOCKET 71-9088 MODEL: NLS-RF, SCHLUMBERGER WELL SERVICES
- B307120030 Advises that Rev 1 to Certificate of Compliance 9088 for Models NLS-RF, NLS-LM expired 830531. MACDONALD,C.E. Transportation Branch, B3/06/28. RACSTER, C.E. Schlumberger Hell Services. 1p. 19439:342.
- DOCKET 71-9089 MODEL: HN-1005, HITTMAN NUCLEAR & DEVELOP, CORP.
- 8307110071 Forwards request for addl info re 830516 application for renewal of Certificate of Compliance 9089 for Model HN-1008. Info required within 60 days of ltr receipt. MACDDNALDO, C.E. Transportation Branch. 83/06/23. MALLORY, C.W. Hittman Nuclear & Development Corp. (subs. Hittman Corp.). 3pp. 19386:302.
- B307190428 Informs that Rev 3 to Certificate of Compliance 9089 for Model NN-1005 will not expire until final determination made by NRC.

  MACDUNALD, C. E. Transportation Branch, B3/07/11, ROWE, B. S. Hittman Nuclear & Development Corp. (subs. Hittman Corp.), 3pp. 17636:168.
- DDCKET 71-9096 MODEL: CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC.
- 8307080404 Forwards Rev 2 to "CNS1 21-300 Type A Radwaste Shipping Cask SAR." App 1.describing & evaluating new load distribution pallet.auxiliary shield, thermal analysis & revised operating procedure. Rev supersedes 830228 version. POPPE, L K. Chem-Nuclear Systems, Inc. 83/06/28. MACDONALD, C. E. Transportation Branch. 10pp. 19362:245.
- --8307080407 Rev 2 to "CNSI 21-300 Type A Radwaste Shipping Cask SAR," App 1. \* Chem-Nuclear Systems, Inc. 83/06/30. 66pp. 19362:247.
- 8307250595 Forwards Rev 5 to Certificate of Compliance 9096 for Model CNS 21-300. MACDDNALD.C.E. Transportation Branch. B3/07/18. DEAL,R. Chem-Nuclear Systems, Inc. 3pp. 19718:073.
- DOCKET 71-9098 MODEL: UCC-20WC-2 & 2A, UNION CARBIDE CORP.
- B307250559 Forwards Rev 4 to Certificate of Compliance 909B for Models UCC-2-0WC-2 & UCC-20WC-2A. MACDDNALD.C.E. Transportation Branch. 83/07/18. MCGOVERN, J. J. Union Carbide Corp. 1p. 19715;352.
- --8307250570 Certificate of Compliance 9098, Rev 4, for Models UCC-20WC-2 & UCC-20WC-2A, MACDDNALD, C. E. Transportation Branch. 83/07/18. 3pp. 19715:353.

DOCKET 71-9107 MODEL: 771, TECHNICAL OPERATIONS, INC.

B307280149 Requests registration as user of Models 650,660,676,680 & & 771.
PETERSON, B. H. Morrison-Knudsen Co., Inc. 83/07/06 MACDONALD, C. E. Transportation Branch. 1p. 19826.038

DOCKET 71-9108 MODEL: CNS 6-75, CHEM-NUCLEAR SYSTEMS, INC.

B307250023 Forwards requests for addl info re 830531 application for renewal of Certificate of Compliance 9108 for Model CNS 6-75. Addl info should be submitted in form of revised pages within 60 days from date of ltr.

MACDDNALD.C.E. Transportation Branch. 83/07/14. DEAL,R.
Chem-Nuclear Systems, Inc. 3pp. 19721:001.

DOCKET 71-9111 MODEL: CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC.

B307190266 Forwards responses to B30525 questions re amend request for Model CNS 4-B0-2 package. O-ring seals will be bonded w/light coating of RTV adhesive. Leak test will be performed on cask prior to acceptance.
POPPE, L. K. Chem-Nuclear Systems, Inc. B3/06/29. MACDONAL, D. C. E. Transportation Branch. 1p. 19556:207.

B307200364 Application for renewal of Certificate of Compliance 9111 for Model CNS 6-80-2. PDPPE, L. K. Chem-Nuclear Systems, Inc. B3/06/29. MACDUNALD, C. E. Transportation Branch. 4pp. 19656:272.

--8307200369 "BAR for Chem-Nuclear Sys.inc Model CNS 6-80-2 Type A Radwaste Shipping Cask." \* Chem-Nuclear Systems: Inc. 83/06/29. 97pp. 19656:277.

B307250091 Requests registration as user of Model CNS 6-80-2. LUNDVALL,A.E. Baltimore Gas & Electric Co B3/06/30. MAGDONALD, C. E. Transportation Branch. 1p 19720: 333.

DOCKET 71-9127 MODEL: 100, 100A, 200, 200A, GAMMA INDUSTRIES

8307190236 Forwards 9A program for transportation/packing of radioactive matl. Registration as user of Gamma Industries Models 100.100A. Century 8 & SA. Universal 5 & SA. C-8 & 67178 & Tech Ops Models 715,660.680 & 650 requested.
COX.D. L. Scientific Inspection Technology. Inc. 83/05/03. MACDONALD. C. E. Transportation Branch. 7pp. 19655:020.

DOCKET 71-9128 MODEL: C-8, GAMMA INDUSTRIES

8307190236 Forwards GA program for transportation/packing of radioactive matl. Registration as user of Gamma Industries Models 100.100A. Century 5 & SA. Universal S & SA. C-8 & 67178 & Tech Ops Models 715.660.680 & 650 requested. CDX.D.L. Scientific Inspection Tachnology. Inc. 83/05/03. MACDONALD.C.E. Transportation Branch 7pp. 19655:020.

DOCKET 71-9132 MODEL: T-3, ENERGY, DEPT. OF

8307130048 Summary of 830629 meeting w/NUPAC & Westinghouse-Hasford in Silver Spring.MD re shipment of sodium contaminated fuel & increased heat load in Model T-3. GDEOARDEN.R.H. Transportation Branch. 83/07/07. Transportation Branch. 2pp. 19511:301.

8307290340 Forwards add1 info in response to NRC 830215 request reapplication for amend to Model T-3 shipping cask. HANSEN,L.J. Nuclear Packaging, Inc. 83/07/19. MACDDNALD.C.E. Transportation Branch. 27pp. 19858:107.

DOCKET 71-7135 MODEL: CENTURY S & SA. CEN. UNIV. S & SA. GAMMMA IND.

8307190236 Forwards QA program for transportation/packing of radioactive matl.Registration as user of Gamma Industries Models 100:100A:Century S & SA.Universal S & SA.C-8 & 6717B & Tech Ops Models 715,660.680 & 650 requested. COX.D.L. Scientific Inspection Technology, Inc. 83/05/03 MACDONALD.C.E. Transportation Branch, 7pp. 17655:020. 8307130311 Notification of registration as user of Models Century S. Century SA. Century UNIV S. Century UNIV SA. IR-50 % IR-100 in response to 830606 request MACDOMALD.C.E. Transportation Branch 83/07/07 CORBESIA.D.M. Cherne Contracting Corp. 1p 19508 362

DOCKET 71-9151 MODEL. HN-100, SERIES 3, HITTMAN NUCLEAR & DEV. CORP.

8305030261 Requests correction to NRC 830509 ltr referencing Model CNS 14-170 package instead of 100 Series 3 MUSDLF,D Northern States Power Co. 83/05/23. MACDDNALD,C.E Transportation Branch. Ip 18795.356.

8307250039 Application for amend to Certificate of Compliance 9151 to include NUS 14-170 Series I package for shipment of radioactive matt. W/four oversize drawings Aporture cards are available in PDR. Four procedures encl RUSSELL, T.A. NUS Corp. 83/06/29, MACDONALD.C Transportation Branch. 3pp. 19724:001.

--8307250040 Rev A to Procedure WM-011. "Soap Bubble Leak Test NUS Process Sycs Shipping Casks." \* NUS Corp. 83/06/28. 7pp. 19724 005

--8307250042 Rev A to Procedure WM-012: "NUS-14-170. Series 1 Maint " \* NUS Corp. 83/06/28. 8pg. 19724 012

--8307250045 Rev A to Procedure WM-013, "Gamma Scanning of Lead Shielding for NUS Type Casks." \* NUS Corp 83/06/28. 6pp 19724 020

--8307250047 Rev A to Procedure WM-014. "Operating Instructions for Loading & Unloading NUS-14-170 Series 1 Casks " \* NUS Corp. 83/06/28. 17pp 17724 026.

B307220637 Advises that actual requester of revito Certificate of Compliance 9151 is NUS Process Sycs Corp. Revishould be changed accordingly.
ANDERSON,H M. NUS Corp. B3/07/06 MACDUNALD.C Transportation Branch. 1p. 19697.042

8307130037 Notification of registration as user of Models HN-100 Series 3 & CNS 14-170 in response to 830224 request HACODONALD.C.E. Transportation Branch 83/07/07 MIDURA.H. J Public Service Electric & Gas Co of New Jersey ip 19511 308

DOCKET 71-9156 MODEL: 18-50: INDUSTRIAL NUCLEAR CO.

8307130311 Notification of registration as user of Models Century S. Century SA. Century UNIV S. Century UNIV SA. IR-50 & IR-100 in response to 830606 request.

MACDDNALD.C.E. Transportation Branch 83/07/07 CORRESIA.D M Cherne Contracting Corp. 1p. 19508:362

8307280034 Requests registration as user of Model [R-50 shipping package. BRACKEN.K.W. Energy, Dept. of 83/07/12 MACDONALD.C.E Transportation Branch. 1p. 19826.018

DOCKET 71-9157 MODEL: IR-100, INDUSTRIAL NUCLEAR CO.

B307130311 Notification of registration as user of Models Century S. Century SA. Century UNIV S. Century UNIV SA. IR-50 & IR-100 in response to 830606 request MACDOMALD.C.E. Transportation Branch 83/07/07 CORBESIA, D M Cherne Contracting Corp. 1p. 19508-382

DOCKET 71-9142 MODEL. GNM-20, GULF NUCLEAR, INC

B307070467 Forwards Rev 1 to Model GNM-20 Certification requested HCPCRAFT,C.P. Gulf Nuclear, Inc. 83/06/24 MACDONALD.C E Transportation Branch. 34pp 19344.291

DOCKET 71-9143 MGDEL: GNG-20, GULF NUCLEAR, INC.

B307150392 Application for IAEA certificate of competent authority for GNG-20 source shield. HOPCRAFT.C.P. Gulf 011 Corp. B3/06/09 RAWL.R Transportation, Dept. of. 1p. 19540:318.

- Discrete of the contractors where the temperature of Compliance F163 For Model
- umunul. Harigens, C.E. Erajesportative Erarin HGZCorry HOFCRAFT+C P Guila P. Lawe (In. 18 1955) 347
- Aprilips Algertificate of compliance Field Re. 0 for Model GNG-20 eachtrach de Frankportalion Scantt 63/05/29 8pp 1965/:346
- Pulzisidas intuines that Cersificate of Compliance F163 meets equipments for Type Bith parkages Approval should be productioned to require sensity, numbered lead usine seal in compliance prolosers establishment for productions of the mathematic Barone B3/07/07 RANLIR R independential Ceat of 10 1785m 168
- CONSERT OF STAN MICH. MUPAC 14-21CL & 14/21EM. MUCLEAR PACKAGING, INC.
- Opinio of Notification of registration as user of Models NUPAC 141210H to STOTIO STATE TO STOTIO STATE TO STOTIO STATE TO STATE TO STATE TO STATE TO STA
- CHORRET IN SIDE MOTEL BOOKST ANTEMATION INDUSTRIES. INC.
- issociation: Forwards Rev C to Cartificate of Compliance 9180 for Hisman 5-100-9 MALIDMAN TO S Transportation Branch H3-06/27 MAYERRAY.G B Alignmethin Industries: Inc. 1p. 19354-185
- 는 NEW TORST IN GENERAL AND ACTION OF A CONTROL OF A CONT

- B307110092 Approves Automation Industries Inc 830227 request that Model 5005U-OP be issued IAEA certificate of competent authority.u/listed condition.
  MACDONALD.C.E. Transportation Branch. 83/06/27. RAUL.R.R. Transportation. Dept. of. ip. 19386:286.
- DOCKET 71-9505 MODEL: HPG MOD-3 RTG, ENERGY, DEPT. OF
- 8307120028 Advises that Rev to Certificate of Compliance 9505, for Model HPG MDD-3 RTG expired on 830531.

  MACDDNALD.C.E. Transportation Branch. 83/06/28. BARRACLAUGH, E. Energy, Dept. of. 1p. 19439:343.

#### LICENSING OF INDEPENDENT SPENT FUEL STORAGE

- DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.
- 8307110587 Advises that changes to physical security plan acceptable. Plan format changed by including contingency plan, guard training plan & final transportation security plan per 10CFR72.81.License Conditions 9.1.4 & 9.1.8 amended. SMITH.C.N. Fuel Facility Safeguards Licensing Branch. 83/01/14. DAWSON,D M General Electric Co. 1p. 19391:345.
- 8307280038 Advises that editorial errors found in Rev 7 to NEDD-20776, "SFSD/GEUNCO GA Plan." New rev being prepared.
  DAWSUN.D.M. General Electric Uranium Management Corp. 83/07/08.
  ROUSE.L.C. Advanced Fuel & Spent Fuel Licensing Branch. 1p. 19826:016.

#### 10CFR COMMISSION MEETING RECORDS

- B307050423 Transcript of Commission B30628 meeting in Washington, DC rediscussion & possible vote un final rule 10CFR50.73 concerning LER sys. Pp. 1-71. Supporting documentation encl. # Commissioners. B3/06/28. 84pp. 19263.001.
- 8307050440 Transcript of Commission 830628 affirmation/discussion & vote in Washington, DC re SECY-82-170A on review of ALAB-687 & SECY-82-215A on low-power OL for Shoreham. Pp. 1-7. Commissioners. ALAB-687. 83/06/28. 10pp. 19262:336. 24X Fiche: 50-322.83/06/28.8307050440.
- 8307060325 Staff requirements memo re B30617 brisfing on impending strike by util employees. Commission requested that Region I datermine if personnal that util intends to use in control room meet regulatory requirements.

  CHILK, B. J. Defice of the Secretary of the Commission. M9306178. 83/06/27.

  Uffice of the Secretary of the Commission. 1p. 19299: 276. 24X Fiche: 50-247, 83/06/27, 8307060325.
- 8307070553 Staff requirements memo on 830615 briefing in Washington, DC re NRC certification in restart proceeding. Final no significant hazards consideration determination will be proposed for concurrence by end of June.

  CHILM.S.J. Office of the Secretary of the Cummission. M830615A.
  83/06/22. DIRCKS.W.J. Office of the Executive Director for Operations. 1p. 17362: 226. 24X Fiche: 50-287, 83/06/22, 8307070553.
- 8307080558 Transcript of Commission 830621 public meeting in Washington, DC re completion of restart review, Pp 1-72, \* Commissioners. 83/06/21, 87pp. 19364:307. 24x Fiche: 50-287, 83/06/21, 8307080558.
- 8307080361 Transcript of Commission 830630 affirmation, discusion & vote in Washington, DC re SECY-83-259A on low power OL for Shoreham & ALAB-714, Pp 1-8.

  \* Commissioners. ALAB-714. 83/06/30. 12pp. 19364:295. 24x Fiche: 50-322,83/06/30,8307080561.
- 8307090081 Staff requirements memo re 830428 affirmation/discussion & vote in Washington.DC re 8ECY-83-190A, "Commission Review of ALAB-687." of ALAB-dd7.

  Office of the Secretary of the Commission. MB30628B.

  83/06/30. PLAINE, H. H. E. Office of the General Counsel. 2pp.

  19366:310. 24X Fiche: 50-413, 83/06/30, 8307090081.
- B307090090 Staff requirements memo re 830517 discussion in Washington, DC re NRC required resources to fulfill requirements of Nuclear Waste Policy Act.
  CHILK, S. J. Office of the Secretary of the Commission. M830517A.
  83/06/29, Office of the Secretary of the Commission. 1p.
  19366:331.
- 8307090130 Staff requirements memo re 830623 discussion & possible vote in Washington, DC on Final rule 10CFR50.73, "LER Sys." CMILK, S. J. Defice of the Secretary of the Commission. M830628A. 83706/30. DIRCKS, M. J. Defice of the Executive Director for Operations. 1p. 19366:352.
- B307ii0106 Transcript of Commission B30705 meeting re evaluation of implication of Salem event (Part II) in Washington.DC.Pp 1-B2. Supporting documentation encl. # Commissioners. B3/07/05. 100pp. 19386:137. 24X Fiche: 50-272. 83/07/05. 8307110106.
- 8307110555 Discusses staff requirements memo re 830615 briefing on OA deficiency status Deficiencies resulted in safety-related work stoppage on 821203 & resulted from work performed subsequent to Aug 1980 reorganization.

  DIRCKS.W.J. Office of the Executive Director for Operations. 83/06/29. CHILK.S.J. Office of the Secretary of the Commission. 1p. 19434:138. 24X Fiche: 50-329,83/06/29,8307110555.

- --B307110564 Staff requirements memo re 830615 briefing in Washington.DC on GA problems. Commissioner Gilinsky requested info whether deficiencies involved const completed before or after Aug 1980 0A dept formation.
  CHILK.S.J. Office of the Secretary of the Commission M8306158 B3/06/20 DIRCKS.W.J. Office of the Executive Director for Operations 1p. 19434 137 24X Fiche 50-327.83/06/29.8307110555.
- 8307140924 Transcript of Commission 830707 public hearing in Washington, DC re-discussion of Regulatory Reform Task Force administrative proposals backfit rule Pp 1-37. Supporting documentation encl # Commissioners. 83/07/07 55pp. 19563-059
- B307150449 Transcript of B30511 Commission meeting re review of NFS-Erwin settlement, Exemptions 1 & 10 in Washington, DC Pp 1-64. SJ Chilk B30706 memo releasing transcript encl # Commissioners. B3/05/11 70pp. 19540 225.
- 8307180291 Staff requirements memo re 830705 briefing in Washington, DC on evaluation of implications of Salem event. Commission concurred in proposed ltrs to licensees, revised to include rept on status of compliance CHILKLS J. Office of the Secretary of the Commission. M830705. 83707711. DIRCKS, W. J. Office of the Erecutive Director For Operations. 1p. 19366: 163. 24X Fiche 50-272, 83707711, 8307180271.
- 8307180299 Staff requirements memo re 830708 moeting w/ACRS in Washington DC concerning proposed safety research program, FY85 & 86 budget & seismic design margins CHILK-S J Office of the Secretary of the Commission. M83070: 83/07/11. FRALEY.R.F. ACRS Advisory Committee on Reactor Safeguards. DIRCKS,W.J. Office of the Ejecutive Director for Operations 1p. 19546.155
- 8307200137 Transcript of Commission 830713 public meeting in Washington, DC re-continuation of evaluation of implications of Salem event. Pp. 1-79. Supporting documentation encl \* Commissioners. 83/07/13 91pp. 19671:251 24X Fiche: 50-272, 83/07/13, 8307200137
- 8307200175 Transcript of Commission 830713 open meeting in Washington. DC re regulatory reform task force administrative proposals revs to Part 2.Pp 1-89 \* Commissioners. 83/07/13 92pp 19671 199
- B307200186 Staff requirements momu re 830707 discussion of administrative proposals of Hegulatory Reform Task Force on backfit rule in Washington.DC CHILM, 5.7 Office of the Secretary of the Commission MB30707A B3/07/08. DIRCKS.W.J. Office of the Executive Director for Operations TOURTELLOTTE.J. Regulatory Reform Task Force | Ip. 19470-313
- 8307200373 Transcript of Commission 830708 meeting w/ACRS in Washington.DC to FY85 & 86 RES audget & seismic design margins Pp 1-72 \* Commissioners. \* ACRS Advisory Committee on Reactor Safeguards 83/07/08, 75pp 19670:177
- 8307220055 Forwards Commission determination statement releasing portions of 830406 transcript of discussions on rulemaking petition & entire transcript of B30411 discussions CHILK(S.J. Office of the Secretary of the Commission B3/07/07 Public Document Branch 1p. 19712.093

- --B307220060 Commission determination statement releasing portions of transcript of 830406 discussions on rulemaking petition & 830411 discussions in Washington.BC. Pp. 1-17 & 1-37, respectively CHILK, S. J. Defice of the Secretary of the Commission. 83/07/07, 77pp. 19712.094.
- 8307220428 Transcript of Commission 830714 briefing in Washington DC replace tracks in BMRs.Pp 1-83. Supporting documentation encl. 8207/14. 97pp. 19712:173.
- 8307250082 Trenscript of 830714 affirmation/discussion & vote in Mashington.DC re SECY 83-240 on Suffolk County motion on energency planning & SECY 83-232 on 100FR71.

  \*\*Gammissioners.\*\* 83/07/14. App. 19720:320. 24X
  Fichs: 50-322, 83/07/14. B307250082.
- 8307250327 Memorandum on status of NRC TMI-1 restart review per ASLAB 830816 & 0706 orders Completion of NRC review of open issues & formulation of NRC position on mat integrity on the first status of the status
- --8307250352 Staff requirements memo re 830621 discussion of guidance to NRC on restart pending immediate effectiveness decision on restart. Certificate of Eve encl.

  Office of the Secretary of the Commission. 83/06/28.

  19703: 036. 24X Fiche: 50-289, 83/07/21, 8307230327.
- 8307250523 Transcript of Commission 830715 meeting w/BWR Owners Group re-pipe tracking in BWRs in Washington DC. Pp 1-103.

  Supporting documentation encl.
  Commissioners. 83/07/15. 120pp. 19740:045.
- 8307250678 Forwards Commission determination statement releasing transcript of 830519 briefing on enforcement matter. CHILK,S. J. Office of the Secretary of the Commission. 83/07/19. Public Document Branch. 2pp. 19718:106. 24X Fiche: 50-247, 83/07/19, 8307250678.
- --83072506BI Transcript of Commission 830519 closed meeting re enforcement actions based on emergency planning deficiencies in Washington, DC. Pp. 1-30, % Commissioners. 83/07/19. 31pp. 19718:108. 24X Fiche: 50-247, 83/07/19, 8307250478.
- 8307260096 Staff requirements memo re 830714 affirmation/discussion & vote approving rev to 10CFR71 & order dismissing Suffolk County motton for Commission to reject licensee emergency
- Councy motion for commission to reject itemstee emergency plan.

  CHILK, B. J. Office of the Secretary of the Commission. MB30714B.
  B3/07/1B. B1RCKS, W. J. Office of the Executive Director for Department. PLAINE. H. H. Office of the General Goursel.
  FOUCHARD, J. J. Office of Public Affairs. 2pp. 19786: 219. 24X
  Fiche: 30-322, B3/07/1B, B307260096.
- B30728011B Informs of Commission determination to withhold transcript of B30415 closed Commission meeting from public disclosure.

  CHILK, B. J. Office of the Secretary of the Commission. B3/07/20. Public Document Branch. 1p. 19812:346. 24X Fiche: 50-322,83/07/20, B307280118.
- --8307280122 Advises that Commission has not objected to proposed be released. Be released. CHILKS. U. Office of the Secretary of the Commission. 83/05/PLAINE.H.H. Office of the General Counsel. 1p. 19812:347. 83/05/23
- 8307280136 informs of Commission determination releasing portions of transcripts of Commission 821028 meeting & releasing whole investigations.

  CHILK.8 J. Office of the Secretary of the Commission of the Secretary of the Secre
  - investigations.
    CHILKS J. Office of the Secretary of the Commission. 83/07/19.
    Public Document Branch. ip. 19812:062. 24X Fiche: 50-358, 83/07/19,
- --8307280141 Advises that Commission does not object to release of transcripts of 921028, 1108 & 12 meetings re plant (investigations. CHILK. 8 J. Office of the Secretary of the Commission. 83/07/12. PLAINE, H. H. Office of the General Counsel. 1p. 17812:063. 24X
- --8307280160 Transcript of portions of Commission 821028 closed meeting in Washington.DC re status of plant investigation.Pp 1-68. Portion of Pages 48 & 49 withheld per Exemption 5. Commissioners. 82/10/29. 70pp. 17812:064. 24x Fiche: 50-358,83/07/19,8307280136.

- --8307280166 Transcript of Commission 821108 closed meeting in Washington.DC re status of plant investigation.Pp 1-103. # Commissioners. 82/11/08. 103pp. 19812:134. 24X Fiche: 50-358,83/07/19,8307280136.
- ~8307280172 Transcript of Commission 821112 meeting in Washington, DC re-Commission action on plant.Pp 1-60. \* Commissioners. 82/11/12. 62pp. 19812:239. 24x Fiche: 50-358,83/07/19,8307280136.
- 8307280468 Informs of Commission determination re public disclosure of 830405 briefing Transcript should be withhold.

  CHILK, S. J. Office of the Secretary of the Commission. 83/07/20, Public Document Branch. 1p. 19826:044. 24X Fiche: 50-322, 83/07/20,
- ---8307280469 Advises that Commission has not objected to proposed withholding of 830403 meeting transcript. Transcript will not be released.

  CHILK.S.J. Office of the Secretary of the Commission. 83/05/PLAINE.H.H. Office of the General Counsel. 1p. 17826:045, Fiche: 50-322, 83/07/20, 8307280468. sion. 83/05/23, 19826: 045, 24
- 8307290216 Advises of Commission determination to withhold transcript of 830303 closed Commission meeting re possible enforcement action from public disclosure.
  CHILK.8.J. Office of the Sacretary of the Commission. 83/07/22.
  Public Document Branch. 1p. 19826;316.
- 8307290244 Staff requirements memo re Commission discussion of regulatory reform task force & role of NRC in hearing regulatory reform task ronce & role or NRC in hearing process.
  CHILK.S. J. Office of the Secretary of the Commission. ?
  63/07/21. DIRCKS.M. J. Office of the Executive Director
  Operations. 1p. 19826: 321.
- ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
- B307010042 Transcript of ACRS Subcommittee on AC/DC Power Sys Reliability B30629 meeting in Bethesda.HD.Pp 1-106. # ACRS Advisory Committee on Reactor Bafeguards. 83/06/29. 129pp. 19173: 351.
- 8307090183 Transcript of ACRS Subcommittee on Human Factors 830630 meating in Washington, BC. Pp 1-244. Supporting documentation encl. 1. ACRS - Advisory Committee on Reactor Safeguards. 83/06/30. pp. 19196:036.
- B307050316 Summarizes ACRS 277th meeting on 830512-14 Subcommittee activities & tentative future adgenda schedule listed.
  B3705/27. PALLADING, N. Commissioners. 4pp. 17263: 247.
- 8307050361 Forwards comments on review of prioritization of generic issues. Written responses to comments requested. FRALEY.R.F. ACRS Advisory Committee on Reactor Safeguards. 83/06/20. DIRCKS.H.J. Office of the Executive Director for Operations. 24pp. 19263:267.
- 8307080287 Transcript of ACRB Combined Subcommittees on Indian Point & Reliability & Probabilistic Assessment 830706 meeting in Washington. DC. Pp 1-283. Supporting documentation encl. # ACRS Advisory Committee on Reactor Safeguards. 83/07/06. 328pp. 19353; 122. 24X Fiche: 50-247,83/07/06,8307080287.
- 8307070095 Summarises 274th ACRS meetings on 830414-16 w/utils to review request for OL. Agenda for 830512-14 meetings encl. EBERSDLE.J. ACRS Advisory Committee on Reactor Safeguards. 83704/29. PALLADINO.N.J. Commissioners. 3pp. 17366:058. 24X Fichs: 50-000, 83/04/29, 8307070095.
- 8307110155 Transcript of ACRS 279th general meeting on 830707 in Washington, DC. Pp 1~332. Supporting documentation encl.

  \* ACRS Advisory Committee on Reactor Safeguards. 83/07/07. 400pp. 19376:112.
- 8307150152 Transcript of ACRS 279th general meeting on 830708 in Washington, DC. Pg. 333-514. Supporting documentation encl. ACRS Advisory Committee on Reactor Safeguards. 83/07/08. 321pp. 17536: 249.
- 8307170323 Comments on ACRS Subcommittee on ATWS 830527 meeting.
  Uncertainty bounds for probability results are extremely
  important & can provide almost as much info & perspective as
  point value estimate.
  DAVIS.P.R. Affiliation Unknown. DAVIS.P.R. ACRS Advisory
  Committee on Reactor Safeguards. 83/06/18. KERR, W. ACRS Advisory
  Committee on Reactor Safeguards. 2pp. 19656:172.

- B307190327 Comments on reactor vessel thermal stress during cooldown, in response to B30520 ltr. Concurs w/Taylor Raf 3 that large thermal gradients could have developed if no mixing of stagnant fluid at low temps occurred.

  ZUDANS, Z. Franklin Institute/Franklin Research Center. ZUDANS, Z. ACR8 Advisory Committee on Reactor Safeguards. B3/03/31.

  MCKINLEY, J. C. ACRS Advisory Committee on Reactor Safeguards. 1p. 17656:171. 24X Fiche: 50~335, 83/05/31. 8307190327.
- B307190345 Comments on ACRS ECCS Subcommittee B30524-29 meetings. Significant progress made in pressurized thermal shock (PTS) issue. Computer input decks partially completed for 18 plants subj to PTB analysis. ZUDANS, Z. Franklin Institute/Franklin Research Center. ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. 83/05/31. BOEHNERT, P. A. ACRS Advisory Committee on Reactor Safeguards. 4pp. 19444:352.
- 8307200022 Discusses NUREG-OBOS "Mark II Containment Program Load Evaluation & Acceptance Criteria." Analysis methods adequate to assure structures will survive potential LOCA environ.

  ZUDANS, Z. Franklin Institute/Franklin Research Center. ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. 83/06/15. MCKINLEY, J. C. ACRS Advisory Committee on Reactor Safeguards. 7pp. 17670:357. 24X Fiche: 50-373, 83/06/15. 8307200022.
- B307200026 Comments on ACRS Metal Components Subcommittee B30615 meeting. Plant operators should be prepared to cope w/potential pressurized thermal shock or other unexpected conditions. Diagnostic training should be provided.
  BINFORD.F.T. Oak Ridge National Laboratory. BINFORD.F.T. ACRS Advisory Committee on Reactor Safeguards. B3/06/16. IONE.E.G. ACRS Advisory Committee on Reactor Safeguards. B3pp. 17670:354.
- 8307200030 Comments on ACRS Subcommittee on ATWS 830526-27 meetings.
  Reliability assessment program should include discussion of reactor scram sys hardware.
  MUELLER, C. J. Argonne National Laboratory. MUELLER, C. J. ACRS Advisory Committee on Reactor Safeguards. 83706/06. KERR, W. ACRS Advisory Committee on Reactor Safeguards. 3pp. 19670:346.
- 8307200033 Comments on Charleston area earthquake workshop. Current saismicity of Charleston region is not part of aftershock sequence of 1886 event, but indicative of semiuniqueness of area.

  POMEROY, P. W. Rondout Associates. POMEROY, P. W. ACRS Advisory Committee on Reactor Safeguards. 83/06/13. OKRENT, D. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19670:344.
- 8307200038 Comments on ACRS subcommittee 830527 meeting. Attention to & better understanding of existing sys by plant personnel can accomplish more than equipment add-ons.

  DITTO.S.J. Affiliation Unknown. DITTO.S.J. ACRS Advisory Committee on Reactor Safeguards. B3/06/07. BDEHNERT, P. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19670:342.
- B307200043 Comments on Pressurized Thermal Shock (PTS) Task Action Plan A-49. Guidance to plant mgt & improvement in instrumentation & control sys offer best method to prevent PTS. #INFORD.F.T. Oak Ridge National Laboratory. BINFORD.F.T. ACRS Advisory Committee on Reactor Safeguards. 83/05/31. IONE.E.G. ACRS Advisory Committee on Reactor Safeguards. 4pp. 17670; 338.
- 8307200088 Transcript of ACRS Joint Subcommittee on Reactor Radiological Effects & Site Evaluation 830718 meeting in Washington, DC. Pp. 1-246. Supporting documentation encl. \* ACRS - Advisory Committee on Reactor Safeguards. 83/07/18. 339pp. 19446:063.
- B307200149 Transcript of ACRS Subcommittee on GA During Const 830718 meeting in Washington, DC. Pp 1-144. Supporting documentation encl.

  \* ACRS Advisory Committee on Reactor Safeguards. 83/07/18.
  175pp. 19450: 194.
- 8307200342 Comments on NRC licensing guidance for enhancing reliability of dc power sys & diesel generators. Info exchange program should be implemented for diesel generator reliability.
  LIPINBKI.W.C. Argonne National Laboratory. LIPINBKI.W.C. ACRS Advisory Committee on Reactor Safeguards. 83/06/22. KERR.W. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19649:327.
- B307200347 Discusses proposed NRC rule on ATWS Rule should state that reliability analysis should be performed for original scram sys & new diverse scram sys.

  LIPINSKI,W.C. Argonne National Laboratory. LIPINSKI,W.C. ACRS Advisory Committee on Reactor Safeguards. B3/06/22. KERR,W. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19669:329.

- 8307200352 Comments of ACRS ECCS Subcommittee 830524-28 meetings.
  Clmited NRC research having adverse effect NRC needs more definite plan to clarify issue of sensitivity of BMR transient evolution to CCFL correlation.
  SCHROCK.V E. California, Univ of, Berkeley. SCHROCK.V.E. ACRS = Advisory Committee on Reactor Safeguards 83/06/24. MARD.D. ACRS = Advisory Committee on Reactor Safeguards 2pp. 19669.331.
- 8307200373 Transcript of Commission 830708 meeting w/ACRS in Washington, DC re FYB5 & 86 RES budget & seismic design margins Pp 1-72 \* Commissioners. \* ACRS - Advisory Committee on Peactor Safeguards 83/07/08. 75pp 19670.177
- G307200474 Comments on 830927 session of ACRS Joint Metal Components/ Reactor Fuels Subcommittee 830526-27 meetings re bolting problems. Corrections should be made to underestimate of strain-to-failure at high temp in described in NUREG-0630. SOLOMON: A A Purdue Univ. SOLOMON: A. A. ACRS - Advisory Committee on Reactor Safeguards. 83/06/01. SHEMMAN: P. ACRS - Advisory Committee on Reactor Safeguards. 2pp 19672:173
- B307200475 Comments favorably on Task Action Plan A-49 re pressurized thermal shock (PTS). Projected App K changes, w/potential for reduction of flux seen by reactor vessel walls, represents best apportunity for ultimate resolution of PTS.

  ZUDANS, Z. Franklin Institute/Franklin Research Center ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. 83/06/03.

  IGNE, E. G. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19672:175.
- 8307200487 Comments on ACRS ECCS Subcommittee 830524-25 meetings in Denver.CO re LOFT program, separate effects area data bank program, nuclear plant analyzer, ReLAP5 status, TRAC-BHR & TRAC-PWR status, code assessment, FIST & MIST GATTON: L. ACRS Advisory Committee on Reactor Safeguards. 83705/31. BDEHNERT.P. ACRS Advisory Committee on Reactor Safeguards. 5pp. 19671:336.
- 8307200493 Comments on technical matl presented at ACRS Subcommittee on Human Factors 830519 meeting, including info reprioritization of generic items research program educ training & nuclear data link.

  DEBONS.A. ACRS Advisory Committee on Reactor Safeguards.
  83/05/27. WARD.D. ACRS Advisory Committee on Reactor Safeguards.
  3pp. 19672: 276
- B307200506 Comments on ACRS Metal Components Subcommittee 820930 meeting re pressurized thermal shock (Task Action Plan Item A-49). Procedure for screening PRRs acceptable CATTON I. ACRS Advisory Committee on Reactor Safeguards. B3706705 IGNE E. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19672: 279.
- 8307200529 Comments on ACRS Joint Metal Components/Reactor Fuels Subcommittee 830526 meeting re BNR large diameter pipe cracking Detection & sixing of defects difficult due to choice of original design & matl.

  BERGER.H Industrial Quality. Inc. DERGER.H ACRS Advisory Committee on Reactor Safeguards. 83/05/31. SHEWHON.P Ohio State Univ. 2pp. 19672:252.
- 8307200532 Provides additingutine ACRS Human Factors Subcommittee meeting.including astimates of elementary probability of human error, educational incentives for human factors personnel & mechanism for human factors plan.
  BUCK.J. lowa, Univ. of. BUCK.J. ACRS Advisory Committee on Reactor Safeguards. 83706/03. WARD.D. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19672:272.
- 8307200548 Comments on Human Factors Subcommittee 830519 meeting in Washington: BC re PRA, BMR emergency procedure guidelines & nuclear data link. Human factors areas underfunded. CATTON: I. ACRS Advisory Committee on Reactor Safeguards. 83705731. FISCHER.D. ACRS Advisory Committee on Reactor Safeguards. 1p 19672:270.
- B307210004 Transcript of ACRS Joint Subcommittee on Reactor Radiological Effects & Site Evaluation 830719 meeting in Mashington.UC fp 247-500. Supporting documentation encl. \* ACRS - Advisory Committee on Reactor Safeguards. 83/07/19 297pp. 19667: 246.
- 8307220018 Comments on ATWS proposals discussed at Electrical Sys & ATWS Subcommittees 830526 & 27 meetings Superior program, arresting transient development & terminating transients w/o plant shutdown must be developed to reduce risk. EPLER.E.P. Epler. E.P. EPLER.E.P. ACRS Advisory Committee on Reactor Safeguards. 83/06/03. KERR.W. ACRS Advisory Committee on Reactor Safeguards. 22pp. 19692:147.

- 8307220032 Comments on ACRS Electrical Sys Subcommittee 830526 meeting re diverse scram sys for Westinghouse reactors. New study of sys reliability & careful review of operator ability recommended DIVTO.S. J. Ditto. S. J. DiTTO.S. J. ACRS Advisory Committee on Reactor Safeguards. 83704/07. SAVIO.R. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19692:122.
- B307220034 Submits comments on proposed Task Action Plan A-49 repressurized thermal shock Recommends procedures contained in App E to SECY-82-469 be included in Reg Guide 1.99 earlier than 1986 GALL-W.R. Gall, W.R. GALL-W.R. ACRS Advisory Committee on Reactor Safeguards. B3/06/03. IGNE, E.G. ACRS Advisory Committee on Reactor Safeguards. 1p. 19712:092.
- 8307220035 Comments on ACRS ATMS Subcommitted 830527 meeting reproposed rule requiring supplementary scram sys for Mestinghouse reactors. Improvements in scram sys & reducing chalitenge frequencies of reactor protection sys recommended. LEE, J. C., LEE, J. C., Michigan, Univ. of. 83706/06. BOEHNERT, P. A. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19491:360.
- B307220643 Summarises concerns raised at ACRS Human Factors
  Subcommittee 830719 meeting. Human factors budget should be
  doubled & 20% of budget should be appropriated for research
  at univs.

  BALVENDY, G. Purdue Univ, SALVENDY, G. ACRS Advisory Committee on
  Reactor Safeguards. B3/05/23. FISCHER, D. ACRS Advisory Committee
  on Reactor Safeguards. 1p. 19697:038.
- 9307250081 Summarites ACRS ECCS Subcommittee 830310 meeting in Washington. DC re B&W feedwater spray work. GE adder concept in revised ECCS methodology & B&W multiloop integral systest scaling.

  TIEN.C.L. California, Univ. of, Berkeley. TIEN.C.L. ACRB Advisory Committee on Reactor Safeguards. 83705747. BOEHNERT, P. ACRS Advisory Committee on Reactor Safeguards. 1p. 19720:328.
- B307250535 Forwards comments on ACRS Subcommittee on Human Factors
  B30519 meeting. Human factors research plan presented at
  meeting was reasonable & consistent w/provious discussions.
  KEYSERLING. M. M. Keyserling. H. M. KEYSERLING, H. M. ACRS Advisory
  Committee on Reactor Safeguards. B3/05/25. WARD, D. ACRS Advisory
  Committee on Reactor Safeguards. B3/05/25. WARD, D. ACRS Advisory
- 8307270004 Transcript of ACRS Subcommittee on ECCS 830717 meeting in Alliance: GH. Pp. 1-345. Supporting documentation encl. \* ACRS Advisory Committee on Reactor Safeguards. 83/07/19. 514pp. 19747: 056.
- 8307280175 Transcript of ACRS Subcommittee on Transportation of Radioactive Matls 830726 meeting in Washington.DC.Pp 1-157. \* ACRS - Advisory Committee on Reactor Safeguards. 83/07/26. 163pp. 19792:093.

# ADVCM NRC ADVISORY COMMITTEE

- 8307150172 Forwards B Garde 830620 itr requesting review of mishandling of NRC insp/investigation of allegations of generic welding defects at San Onofre Ltr discusses prerequisites for alleger interview.

  LEVI.R.P. Rights of Licensee Employees Under Investigation.

  83/06/30. SILBERT.E.J. Schwaib, Donnenfeld, Bray & Silbert.

  RUEBHAUSEN.D.M. Debevoise & Plimpton. SCGVI.J.B. Kator, Scott & Heiler. [p. 19574:318.
- --B307150175 Requests Commission review analysis of serious mishandling of NRC (nap/investigation of allegations raised re both specific & generic welding flaws at Gechtel constructed plants. GARDE.B.P. Government Accountability Project. B3/06/20. PALLADINO.N.J., ASSELSTINE.J.K., AHEARNE.J.F. Commissioners. 27pp. 19574:319.
- 8307200274 Responds to 830325 ltr re investigation procedures NRC seaking autside input prior to deciding policy content. PLAINE.H.E. Office of the General Counsel, 83/06/24. GREENSPUN.J.S. Justice, Dept. of. ip. 17669:305.
- --8307200275 Confirms agreements reached at 830321 meeting re investigative procedures to be amployed by NRC & DDJ. Appointment of advisory panel to provide guideline for NRC investigations detracts from revitalizing program. GREENSPUN.U.S. Justice: Dept. of. 83/03/25. HAYES.B.B. NRC - No Datailed Affiliation Given. Spp. 17669:306.

#### COMMISSION NRC COMMISSIONERS

- 8307060439 Informs that five lists of documents re TMI-2 accident will be compiled per 830607 request.
  PALLADING.N.J. Commissioners. CR-83-103. 83/06/24. UDALL.M.K. House of Rep., Interior & Insular Affairs. 4pp. 19300:153. 24x Fiche: 50-289.83/06/24.8307060439.
- --B307060443 Ack receipt of NRC 830826 itr responding to B30427 request for info re forthcoming decision on TMI-1 restant & B&W vs GPU trial record. Commission majority response to B30427 ltr inappropriate.

  UDALL.M X. House of Rep., Interior & Insular Affairs, B3/06/07. PALLAHING,N. J. Commissioners. 1p. 19300:137. 24X Fiche: 50-289, 83/06/24, 8307060439.
- 8307090092 Weekly info rept for wk anding 830617. REHM.T.A. Office of the Executive Director for Operations. 83/06/24. 37pp. 19366:061.
- 8307090118 Weekly info rept for wk ending 830624. REHM.T.A. Office of the Executive Director for Operations. 83/06/30. 47pp. 19366:098.
- B307140121 Responds to B30601 ltr expressing concerns re NRC decision to permit facility operation in light of serious incidents occurring in Feb 1983. NRC instituted augmented insp program to monitor activities. Plant can be operated safely. DIRCKS.M. J. Office of the Executive Director for Operations. 83/07/01. CASTLE.M.N. Delaware, State of. 2pp. 19539:354, 24X Fiche: 50-272,83/07/01. B307140121.
- ---B307140127 Submits comments on behalf of concerned citizens reoperation of facility.Plant should be shut down due to
  gross mismanagement causing serious health & safety risk.
  NRC should carefully scrutinize operations.
  CABTLE, M. N. Delaware, State of. 83/06/01. PALLADING, N. J.
  Commissioners. 2pp. 19539:356, 24X Fiche:50-272,83/07/01,
  8307140121.
- 8307i90057 Responds to 830503 request for NRC views on Nuclear Nonproliferation Policy Act of 1983, HR 1417 Titles I, IV & VI do not affect NRC activities. PALLADINO.N.J. Commissioners. 83/06/28. ZABLOCKI.C.J. House of Rep., Foreign Affairs. 5pp. 19656:223.
- ~-8307190059 Requests comments on encl H.R.1417 re promotion of US nuclear mangraliferation policies.

  IABLOCKI.C.J. House of Rep., Foreign Affairs, 83/05/03, PALLADIND.N.J. Commissioners, 18pp. 19656:232.
- 8307190403 Weekly info rept for wk ending 830701. REHM T.A. Office of the Executive Director for Operations, 83/07/08. 64pp. 19656:081.
- 8307190443 Weekly info rept for wk ending 830708. REHM.T.A. Office of the Executive Director for Operations. 83/07/14. 37pp. 19451:307.
- 8307200243 Informs that addl resources needed to fulfill requirements of Nuclear Haste Mgt Policy Act of 1982, approved by Commission. Congress requested to appropriate addl funds. PALLADING, N. J. Commissioners. 83/06/17. DITINGER, R. L. House of Rep., Energy & Commerce. 3pp. 19470:260.
- B307200247 Recommends extension of Commission authority to issue temporary OLs to 841231 in response to Subcommittee B30603 quastions. Authority will be exercised sparingly. PALLADINO, N.J. Commissioners. 83/06/15. OTTINOER, R. L. House of Rep. Finergy & Commerce. 2pp. 19670:258.
- B30720024B Responds to inquiry during B3060B hearing re addl resources needed to fulfill requirements of Nuclear Waste Mgt Policy Act of 1982. Decision on estimate of addl resources unresolved. Estimates encl. PALLADING. N. J. Commissioners. B3706/16. OTTINGER, R. L. House of Rep., Energy & Commerce. 2pp. 19670:256.
- 8307200257 Advises that 11 full-time employee positions will be reallocated to Ofc of Investigations to investigate allegations of urongolong by non-NRC employees or contractors.

  PALLADINO:N.J. Commissioners. 83/06/16. BEVILL:T. House of Rep., Appropriations. HATFIELD.M.C. Senate, Appropriations. 2pp. 17656:338.

- 8307200320 Informs that Commission providing 24 SECY papers covering variety of regulatory topics over last 1-1/2 yrs. Access to documents should be restricted to subcommittee members & staff.
  PALLADINO.N.J. Commissioners. 83/06/24. MARKEY.E. House of Rep., Interior & Insular Affairs. 3pp. 19636.332.
- 8307200367 Forwards proposed amend to Section 8 of H.R.2510, enabling avaluation program to demonstrate decentralizing concept, to assess safety effects, to develop detailed descriptions & to analyze comments, H/o entl.
  ROBERTS.T.M. Commissioners. 83/06/14. HATFIELD.M. House of Rep., Appropriations. 2pp. 19669:351.
- --8307200369 Forwards proposed amend to Section 8 of H.R. 2510, enabling evaluation program to demonstrate decentralizing concept to assess safety effects to develop detailed descriptions & to analyze comments. W/o entl. ROBERTS,T.M. Commissioners. 83/06/14. OTTINGER.R.L. House of Rep., Energy & Commerce. 2pp. 19669:353.
- --8307200372 Forwards proposed amend to Section 8 of H. R. 2510, enabling evaluation program to demonstrate decentralizing concept to assess safety effects, to develop detailed descriptions & to analyze comments. W/o enci.
  ROBERTS, T. M. Commissioners. 83/06/14. SIMPSON, A. House of Rep., Environment & Public Works. 2pp. 17667:355.
- --8307200376 Forwards proposed amend to Section 8 of H.R. 2510, enabling evaluation program to demonstrate decentralizing concept to assess safety effects, to develop detailed descriptions & to analyze comments. W/o encl.
  ROBERTS, T. H. Commissioners. 83/06/14. BEVILL. T. House of Rep., Appropriations. 2pp. 19669:357.
- ---8307200379 Forwards proposed amend to Section 8 of H. R. 2510, enabling evaluation program to demonstrate decentralizing concept & to assess safety effects, to develop detailed descriptions & to analyze comments. Commissioner Asselstine views encl.

  ROBERTS.T.M. Commissioners. 83/06/14, UDALL.M.K. House of Rep., Interior & Ingular Affairs. 5pp. 19669:359.
- 8307250513 Weekly info rept for wk ending 830715. REHM.T.A. Diffice of the Executive Director for Operations. 83/07/20. 46pp. 19721:167.
- 8307260111 Responds to FOIA request for documents re recent experiences w/illegal export of sensitive items through use of bogus invoices & Commissioner Oilinsky travel schedules & itineraries for past 2 yrs.Forwards App A documents. FELTON.J.M. Division of Rules and Records. 83/05/11. KAMENAR.P.D. Washington Legal Foundation. 4pp. 19744:100.
- --8307260123 Speech entitled "First Step in Solving Nuclear Waste Problem:Providing Adequate Spent Fuel Storage," presented at Waste Mgt '83 Symposium in Tucson.AZ on 830228. QTLINSKY.V. Commissioners. 83/02/28. 13pp. 19744:104.
- --8307260130 Speech entitled "Nuclear Safety: Dealing W/Conflicts of Interest:" presented at East-West Ctr. Honolulu: HI on 830121. GILINSKY, V. Commissioners. 83/01/21. 17pp. 19744: 117.
- --8307260149 Discusses four repts re recent attempts to circumvent US export control laws, Bupporting documentation encl. QILINSKY, V. Commissioners. 83/04/13. RUDD, E. House of Rep. 24pp. 19744: 153.

#### CONTRACT NRC CONTRACTS AND MODIFICATIONS

- B305120547 Notification of contract execution, Mod 1 to "Bafety Aspects of Industrial Radiography Courses." Contractor: Gamma Industries.

  OILDENHORN, A. J. Administrative Contracts Branch. NRC-05-B2-251.
  B3/03/09. BLAHA, J.L. Program Support Branch. HASSELBERG, R. NRC No Detailed Affiliation Given. 1p. 18443:122.
- --8305120551 Mod 1, specifying date of Course 2 & deleting & substituting certain course requirements, to "Barety Aspects of Industrial Radiography Courses."
  RIDDLE, D. H. Nuclear System. HAGAN, T. F. Division of Contracts, NRC-05-82-251, 83/05/09, 2pp. 18443:123.
- B307050284 Notification of contract execution.Mod 1 to "Purchase & Installation of Six Teleprinters." Contractor: Extel Comp/Warner Assoc. Inc.
  DDRBEY.M. BMITH.P.A. Administrative Contracts Branch.
  NRC-10-80-692. B3/05/06. DDRIE, W.M. Office of Administration.
  MELVILLE.T. NRC No Detailed Affiliation Given. 1p. 19263:214.

- --8307050285 Mod 1.deobligating balance of funds to "Purchase & Installation of Six Teleprinters."

  COFFEY,E.C. Extal Corp./Warner Associates Inc SMITH, P. A. Division of Contracts, NRC-10-80-692, 83/05/06, 1p. 19263: 215.
- 8307050317 Notification of contract execution. Mod 3 to "Keypunching & Verifying Sycs." Contractor: SBA. Subcontractor: Intl Business Sycs. Inc.
  DDRSEY.M. SMITH.P.A. Administrative Contracts Branch.
  NRC-10-79-393. 83/04/23. DDRIE.M.M. Office of Administration.
  OLIVER.D. NRC No Detailed Affiliation Given. 1p 19263:251.
- --8307050321 Mod 3,deobligating balance of funds,to "Keypunching & Verifying 8vcs."

  BERODOLLT.E. Small Business Administration. \* International Business Bervices, Inc. HAGAN.T. Division of Contracts.

  NRC-10-79-393. B3/04/23. 2gp. 19263:252.
- 8307050324 Notification of contract execution Mod 17 to "PDR Micrographic Storage & Retrieval Sys." Contractor: Access Corp. PERLMAN. J. Administrative Contracts Branch. FIN B-8153. NRC-17-79-449. 83706/20. CHILK.S. J. Office of the Secretary of the Commission. BCATTOLINI.L. NRC No Detailed Affiliation Given. 1p. 19263: 234.
- --B307050328 Mod 17.authorizing installation of addit equipment, to "PDR Micrographic Storage & Retrieval Bys."
  BAKER.N.D. Access Corp. SMITH.P.A. Division of Contracts. FIN B-8153. NRC-17-79-449. B3/06/20. 2pp. 19263:255.
- B307050495 Notification of contract execution Mod 5 to "Licensing Technical Assistance." Contractor: Science Applications, Inc. FLYNN.M. Technical Assistance Contracts Branch. FIN B-7394-3. NRC-02-83-035. B3/06/03. DAVIS.J. Office of Nuclear Material Safety & Safeguards, Director. LOYSEN.P. NRC No Detailed Affiliation Given. 1p. 19262:166.
- --8307050496 Mod 5, issuing fully definitized task order & increasing Amount obligated, to "Licensing Technical Assistance." FINDLEY, D. E. Science Applications, Inc. GUSTAVE.R.P. Technical Assistance Contracts Branch. FIN B-7394-3. NRC-02-83-035. 83/06/03. 4pp. 19262:167.
- B307070480 Notification of contract execution Mod 1 to "Info Mgt Sys for NRC Operation Ctr." Contractor: Phoenix Assoc. OILDENHORN, A. J. Administrative Contracts Branch. FIN B-8709. NRC-09-83-218. B3/06/24. MUIR.A.P. Program Support Branch. HIMES, J. NRC - No Detailed Affiliation Given. 1p. 19300: 230.
- --8307070484 Mod i.extending period of performance to B30910.to "Info Mgt Sys for NRC Operation Ctr." # Phoenix Associates, Inc. HAGAN.T.F. Division of Contracts. FIN B-8709. NRC-05-83-218. 83/06/24. ip. 19300:231.
- 8307070488 Notification of contract execution, Mod 11 to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2." Contractor:Franklin Inst.Franklin Research Ctr. FLYNN.M. Technical Assistance Contracts Branch. FIN B-6891. NRC-03-B1-130. 83/06/27. EISENHUT.D.G. Division of Licensing. CARRINGTON.M. NRC No Detailed Affiliation Given. 1p. 19300: 232.
- --8307070490 Mod ii.providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2."

  \* Franklin Institute/Franklin Research Center. GUSTAVE.R.P. Division of Contracts. FIN 8-6891. NRC-03-81-130. 83/06/27 2pp. 19300:233.
- 8307070503 Notification of contract execution, Mod 1 to "Technical Assistance for Design Review." Contractor: Engineers Inti, Inc.
  FLEENOR.C. Technical Assistance Contracts Branch. FIN B-7928.
  RRC-02-B2-030. 83/06/08. DAVIS.J. Office of Nuclear Material Barety & Safeguards, Director. SEAMANS, T. NRC No Detailed Affiliation Given. 1p. 19300:310.
- --B307070506 Mod 1, providing incremental funds, revising contractor address & incorporating updated version of NRC Manual Chapter 3202, to "Technical Assistance for Design Review." \* Engineers International, Inc. GUSTAVE, R.P. Division of Contracts. FIN 8-7328. NRC-02-82-030. B3/06/08. 2pp. 19300:311.
- B3070B0547 Notification of contract execution, Mod 5 to "Seismic Qualification of Nuclear Plant Mechanical & Electrical Equipment." Contractor: BMRI. MOLLETT.S. Technical Assistance Contracts Branch. FIN 8-7087. NRC-04-BI-185. B3706/27. FOREMAND.W. Office of Nuclear Regulatory Research. Director. CAMPBELL.W.E. NRC No Detailed Affiliation Given. Ip. 19365:040.

- --B307080551 Mod 5.providing addl funding for travel & attendance at two previously unscheduled meetings.to "Solemic Qualification of Nuclear Plant Mechanical & Electrical Equipment.
  BIROEL.S.H. Southwest Research Institute. GUSTAVE.R.P. Division of Contracts. FIN B-7087. NRC-04-81-185. 83/06/27. ≥pp. 19365.041.
- 8307080557 Notification of contract execution. Mod 1 to "Subscriptions to Following Publications: Inside Energy/W/Fedoral Lands, Inside FERC, Inside NRC, Nuclear Fuel, Nucleonics Wk."
  Contractor: McGraw-Hill. Inc.
  SMITH, P. A. Division of Contracts. NRC-10-83-321. 83/06/27.
  BESAM, M. J. Division of Technical Information & Document Control.
  CONYNGMAM, M. NRC No Detailed Affiliation Given. 1p. 17365:032.
- ~-8307080963 Mod 1.providing two addl 7-month subscriptions to Inside Energy/W/Federal Lands & adding one 7-month subscription to Nucleonics Mt. to "Subscriptions to Following Publications: Inside Energy/W Federal Lands...."

  FERRANTE.J. McGraw-Hill Publications Co. SMITH.P. A. Division of Contracts. NRC-10-83-321. 83/06/27. 2pp. 19365:033.
- 8307080583 Notification of contract execution, Mod 5 to "Research Study Entitled 'Study of Regional Tectonics & Seismicity for Idwa.'" Contractor: Idwa Geological Survey.

  SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-6312.

  NRC-04-78-220. 83706/27. BATSON.U. Diffice of Nuclear Regulatory Research, Director. STEUER, N. NRC No Detailed Affiliation Given.

  1p. 19364:289.
- --8307080595 Mod 5, deobligating funds, to "Research Study Entitled 'Study of Regional Tectonics & Belsmicity for Iowa.'"

  VAN ECK.O. J. Iowa Geological Survey. OUSTAVE.R.P. Division of Contracts. FIN B-6312. NRC-04-78-228. 83/06/27. 1p. 19364:290
- 8307140115 Notification of contract execution: "Word Processing Svcs," awarded to Keyboard Communications, Inc.
  DORSEY, M. BAZIN, J. P. Administrative Contracts Branch.
  NRC-10-83-296. B2/12/01. STEELE, M. Division of Technical Information & Document Control. JDHANSEN, J. Cress Branch. 1p. 19528: 001.
- --8307140119 Solicitation, offer & award of "Word Processing Byc" to Keyboard Communications, Inc. # Keyboard Communications, Inc. MATTIA, M. J. Division of Contracts. NRC-10-83-296. 82/12/01. 102pp. 19528:002.
- 8307140481 Notification of contract suscution: "Basic Ordering Agreement Entitled 'Technical Assistance in Hydrogeology'," awarded to Entec Western Inc.
  HIGGINS.E. Technical Assistance Contracts Branch. FLEENOR.C. Division of Contracts. NRC-02-82-028-07. 83/06/16. BROWN.R.S. Program Support Branch. JOHNSON.B. Office of Nuclear Material Safety & Safeguards, Director. ip. 19527:284.
- \*\*-B307140483 Contract: "Basic Ordering Agreement Entitled 'Technical Assistance in Hydrogeology', " awarded to Entec Western, Inc. YOUNG, G. T. Entec, Inc. \* Division of Contracts. NRC-02-82-028-07. 83/06/16. 37pp. 19527:285.
- 8307140487 Notification of contract execution, Mod 1 to "Radioactive Matts Transportation Surveillance Program." Contractor: State of MD.
  SMITH, P. A. Division of Contracts. FIN B-1327. NRC-06-80-679.
  83/07/01. KERR, O. W. Office of State Programs. Director. JANINEK, M. NRC ~ No Detailed Affiliation Given. 1p. 19327: 341.
- --8307140493 Mod 1, deobligated remaining unliquidated balance, to "Radigactive Matis Transportation Surveillance Program." EICHBAUM, W. M. Moryland, State of. SMITH.P.A. Division of Contracts. FIN 8-1327. NRC-06-80-679. 83/07/01. 1p. 19527:342.
- 8307140508 Notification of contract execution: "Severa Accident Core/ Vessel/Containment Interactions," awarded to Purdue Research Foundation.Purdue Univ. HIGGINS.E. Technical Assistance Contracts Branch. FIELDS.J. Division of Contracts. FIN 8-8634. NRC-03-83-093. 83/06/16. MATISON.R.J. Division of Systems Integration (post 811005). HARDIN.W. NRC ~ No Detailed Affiliation Given. 1p. 19326:044.
- --B307(40517 Contract: "Severe Accident Core/Vessel/Containment Interactions," awarded to Purdue Research Foundation Purdue Univ. HENISCHEL, H.F. Purdue Research Foundation. MCRTON, K. V. Division of Contracts. FIN B-8634. NRC-03-83-093. 83/06/16. 21pp.

- B307140523 Notification of contract execution: "Programming, Training, Testing, Conversion & Implementation of Facility Control Sys (FACS)," awarded to Boeing Computer Svcs Co.
  DCRSEY,M. Administrative Contracts Branch. FIN B-8848.
  NRC-33-83-438. 83/06/16. BASSETT. H. S. Office of Resource Management, Director. WRIGHT. G. NRC No Detailed Affiliation Given. 1p. 19326:066.
- --8307140528 Contract: "Programming, Training, Testing, Conversion & Implementation of Facility Control Sys (FACS)," awarded to Bosing Computer Syss Co.
  HUPKINS, H.R. Bosing Computer Services, Inc. (subs. of Bosing Co.), MATTIA, M.J. Division of Contracts, FIN B-8848, NRC-33-83-458, B3/06/16. 65pp. 19526:067.
- 8307150009 Notification of contract execution: "Examine Facts in Employee Grievance, Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Hritten Rept." awarded to DE Matthews.
  MURPHY.L. G. Administrative Contracts Branch. NRC-10-83-367.
  B3/07/01. BIRD, P. E. Division of Organization and Parsonnel.
  MDHRWINKEL. C. NRC No Detailed Affiliation Given. 1p. 19562:330.
- --B307150016 Contract: "Examine Facts in Employee Grievance, Hold Hearing Including Taking Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." awarded to DE Matthews.

  MATTHEMS, D. E. Matthews, D. E. REBELLO, J. E. Division of Contracts, NRC-10-83-367. 83/07/01. 6pp. 17562;331.
- 8307150054 Notification of contract execution.Mod 1 to "Classified Waste Paper Destruction Project." Contractor: Simkins Industries, Inc.
  MCLEAREN.T. Administrative Contracts Branch. NRC-10-82-403.
  83706/27. BRADY.R.J. Division of Security. BURNSIDE, W. NRC No Detailed Affiliation Given. 1p. 17576:360.
- --8307130056 Mod 1.extending period of performance to 840407, to "Classified Waste Paper Destruction Project." RUSSELL.V. Simkens Industries, Inc. SMITH.P.A. Division of Contracts. NRC-10-82-403. 83/06/27. 1p. 19596:361.
- 8307150364 Notification of contract execution, Mod 1 to "State Legislative Reporting Sycs." Contractor: Public Affairs Info. Inc. PERLMAN, J. Administrative Contracts Branch. FIN B-1592. NRC-06-B3-R6. 83/07/01. KERR, G. M. Office of State Programs, Director. LANDAU, M. NRC - No Detailed Affiliation Given. 1p. 19540: 343.
- --B307150367 Mod 1,adding quarterly payments,to "State Legislative Reporting Bycs."

  \* Public Affairs Information, Inc. SMITH,P.A. Division of Contracts. FIN B-1392. NRC-06-83-266. B3/07/01. 2pp. 19340:344.
- 8307150374 Notification of contract execution Mod 4 to "Maint of Data General Computers & Peripheral Equipment." Contractor: Data Consultants, Inc.
  PERLMAN. J. Administrative Contracts Branch. FIN B-1663.
  NRC-29-B2-311. 83/06/23. BASSET, H. R. Office of Resource Management. Director. JOHNSON, C. R. NRC No Datailed Affiliation Given. 1p. 19540: 334.
- ---8307150376 Mod 4.extending period of performance to 840526, to "Maint of Data General Computers & Peripheral Equipment."

  BONNES.O. Data Consultants, Inc. SMITH.P.A. Division of Contracts. FIN 8-1463. NRC-25-82-311. 83/04/23. 2pp.
- B307150413 Notification of contract execution, Mod 3 to "Maint & Operation of LPDRs." Contractor: State Library of PA. MCLEAREN.T. Administrative Contracts Branch. NRC-10-82-696. B3/06/29. FELTON.J.M. Office of Administration. SCUDER.J. NRC No Detailed Affiliation Given. 1p. 19540: 183.
- --8307150417 Mod 3.extending period of performance to 840630 & increasing funds, to "Maint & Operation of LPDRs."

  SHELKRET.E. L. Pennsylvania, Commonwealth of, SMITH, P.A.

  Division of Contracts. NRC-10-82-676. 83/06/29. 1p. 17540:184.
- B307150420 Notification of contract execution, Mod 3 to "Multiple Award Task Order Contract for ADP Devalopment." Contractor: Boeing Computer Svcs Co.
  PERLMAN, J. Administrative Contracts Branch. FIN B-B166.
  NRC-33-83-452. B3/07/07. BASSET, H. S., HARVES, J. Office of Resource Management, Director. 1p. 19540: 181.
- --8307150422 Mod 3.changing cost of money rates, to "Multiple Award Task Order Contract for ADP Development."

  \* Boeing Computer Services, Inc. (subs. of Boeing Co.), SMITH.P.A. Division of Contracts. FIN B-8166. NRC-33-83-452, 83/07/07. 1p. 19540:182.

- #307150427 Notification of contract execution Mod 1 to "Listing of High Technology 8(a) Firms." Contractor: Miranda Associates, Inc. BROMBERO, B. J. Administrative Contracts Branch. NRC-27-83-446. 83706/99. KERR, W. Dfc of Small & Disadvantaged Bus. Utilization & Civil Rights. COLEMAN, M. NRC No Detailed Affiliation Given. 1p. 19340:185.
- ---8307150430 Mod 1.allowing partial payments when sample submitted.to
  "Listing of High Technology 8(a) Firms."

  # Miranda Associates. Inc. SMITH.P.A. Division of Contracts.
  NRC-27-83-444. 83706/09. 3pp. 19540:186.
- B307150433 Notification of contract execution, Mod 2 to "Provide Expert Technical Consulting Svcs to DCS on Task Order Basis."

  Contractor: Dept of Air Force.

  BROMBERG, 8-J. Administrative Contracts Branch. NRC-10-82-404.

  83707705. NORRY, P. G., LUNDY, J. Office of Administration. 1p.
  19540: 199.
- ---8307150435 Mod 2, extending period of performance to 831230, to "Provide Expert Technical Consulting Svcs to DCS on Task Order Basis."

  \* Air Force, Dept. of. SHITH.P.A. Division of Contracts.
  NRC-10-82-404. 83/07/05. 2pp. 19540:200.
- E307150453 Notification of contract execution, Mod 5 to "Conversion, Programming, Implementation, Documentation & Acceptance Processing of IFMIS." Contractor: SBA. Subcontractor: Technassociates.

  GILDENHORN, A. J. Administrative Contracts Branch. FIN B-81/2.

  NRC-10-81-359. 83/06/12. DORIE, W. Office of Administration.

  WRIGHT, G. NRC No Detailed Affiliation Given. 1p. 19540: 295.

- ---8307180328 Mod i.extending period of performance to 830727 at no additionable of the cost to "Binassays Using Resonance Innization Spectroscopy."

  ECHMITT.H.W. Atom Sciences Inc. GUSTAVE.R.P. Division of Contracts. FIN B-8122. NRC-04-82-021. 83/07/02. 1p. 19566:089.
- B307180429 Notification of contract execution, Mod i to "Cataloging Support Svcs." Contractor: Informatics, Inc.
  BMITH.P.A. Division of Contracts. NRC-10-79-362. B3/07/05.
  BEGAM, M.J. Division of Technical Information & Document Control.
  WISE,R. NRC No Detailed Affiliation Given. ip. 19566:346.
- --8307180431 Mod i,increasing amount of contract to allow for indirect rate adjustment to "Cataloging Support Svcs." SLOMLY.L. Informatics, Inc. SHITH.P.A. Division of Contracts. NRC-10-79-362. 83/07/05. ip. 19566:347.
- 8307180434 Notification of contract execution, Mod 1 to "Examine Facts in Employee Grievance, Hold Hearing Including Taking of Testimony & Acceptance of Eyidentiary Hatl & Make Final Written Rept." Contractor: DE Hatthews.
  MURPHY.L. O. Administrative Contracts Branch. NRC-10-83-367.
  83706/30. BIRD, P.E. Division of Organization and Personnel.
  MOHRWINKEL, C. NRC No Detailed Affiliation Given. ip. 19366:342.
- ---8307180436 Mod i.extending period of performance to 830708 to "Examine Facts in Employee Grievance Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Hritten Rept."

  MATTHEMS.D.E. Matthews, D.E. REBELLO, J.E. Division of Contracts.
  NRC-10-83-367. 83/06/30. ip. 19566:343.
- 8307190107 Notification of contract execution Mod 11 to "Structural Integrity of Water Reactor Boundry Components." Contractor: ENSA.Inc. WOLLETT.S. Technical Assistance Contracts Branch. FIN 8-8133. NRC-04-82-013. 83/07/01. FOREMAND.W. Office of Nuclear Regulatory Research, Director. VACINS, M. NRC No Detailed Affiliation Given. ip. 19656:213.
- ---8307190112 Mod 11, providing add1 work & funding & extending period of performance to 831115, to "Structural Integrity of Water Reactor Boundry Components."
  HAAS, M. N. ENSA, Inc. GUSTAVE, R. P. Division of Contracts.
  NRC-04-82-013. 83/07/01. 9pp. 17656:214.

- 8307190307 Notification of contract execution. "Monthly Update of NRC Rules & Regulations," awarded to BBA. Subcontractor Metrotec.

  JACOBS. A. Administrative Contracts Branch. NRC-10-83-350.

  83706/10 FELTON.J.M. Office of Administration PHILLIPS.J. NRC No Detailed Affiliation Given. 1p. 19636:007
- ---8307190313 Contract: "Monthly Update of NRC Rules & Regulations,"
  awarded to SBA Subcontractor: Netrotec.
  \* Small Business Administration. NELSON, J. E. Metrotec. Inc.
  DENNISTON, S. F. Division of Contracts NRC-10-83-350. 83/06/10
  23ap. 19656-008.
- B307190335 Notification of contract execution, Mod 3 to "Shuttle Bus Svc." Contractor: Capital City Coach, Inc. DDR8EY, M., PERLMAN, J. Administrative Contracts Branch. NRC-10-B2-362, B3/07/07, CORLEY, J. H., GRANT, L. NRC - No Detailed Affiliation Given. 1p. 19454: 047.
- --8307190339 Mod 3, establishing termination settlement costs, to
  "Shuttle Bus Syc."
  RYANJ, S. Capital City Coach. SMITH, P. A. Division of Contracts.
  NRC-10-82-362. 83/07/07. 2pp. 19654:048.
- B307190411 Notification of contract execution, Mod 4 to "ADP Sys Support." Contractor: BBA: Subcontractor: Technassociates.
  GILDENHORN: A. J. Administrative Contracts Branch. FIN 8-0664.
  NRC-25-83-315. B3706/27. BARRY, L. W. Office of Resource Management.
  Director. BURTON: J. NRC No Detailed Affiliation Given. 1p.
  17656: 145.
- --B307190418 Mod 4, extending period of performance to 840616, increasing ceiling & obligated amount, adding option changing labor hourly rates, changing security provisions & adding key personnel to "ADP Sys Support."

  HILL.D. Small Business Administration. OFFCRD, J.C.
  Technessociates, Inc. HAGAN.T.F. Division of Contracts. FIN B-1664. NRC-25-82-315. B3/06/29. 7pp. 19656:146.
- B307190430 Notification of contract execution. Mod 4 to "On Call Maint for NRC Computer Paripheral Equipment." Contractor. Computer Bys Support Corp., PERLHAN. J. Administrative Contracts Branch. FIN 8-8174. NRC-33-B3-451. B3/07/14. BASSETT. H. S. Division of Data Automation & Management Information. JOHNSON. C. NRC No Detailed Affiliation Given. 1p. 19656:155.
- ---8307190435 Mod 4, adding addl equipment, to "On Call Maint for NRC Computer Peripheral Equipment."

  ROOT.L. E. Computer Systems Support Corp. SMITH.P.A. Division of Contracts. FIN B-8174. NRC-33-83-451. 83/07/14. 2pp.
- B307190453 Notification of contract execution: "Photographic Reproduction Syc," awarded to SBA.Subcontractor:Domus Design Studios.Inc.
  BAZIN.J.P. Administrative Contracts Branch. NRC-10-83-322.
  B3/07/07. BEBAN, W. J. Division of Technical Information & Document Control. DEHN, D. NRC No Detailed Affiliation Given. lp. 19643:313.
- --B307190438 Contract: "Photographic Reproduction Svc." awarded to SBA. Subcontractor: Domus Design Studios. Inc. Subcontractor contract encl.

  4 Small Business Administration. BERODOLL.T.E. Domus Design Studios. Inc. MATTIA.M.J. Division of Contracts NRC-10-83-322. 83/07/07. Sipp. 19443:314.
- B307200153 Notification of contract execution Mod 7 to "Geotechnical Engineering Casework Review II." Contractor: US Army Corps of Engineers. FIELDS: J.A. Technical Assistance Contracts Branch. FIN B-8027. NRC-03-82-102.
- --8307200157 Mod 7, increasing funds obligated for technical svcs & deobligating funds for FV82 travel to "Geotechnical Engineering Casework Review II."

  RYAN,R.H. Army, Dept. of Corps of Engineers. GUSTAVE.R.P. Division of Contracts. FIN B-8027. NRC-03-82-102. 83/07/06. 2pp. 19670:336.
- B307200159 Notification of contract execution, Mod 7 to "MCLAMS Mod." Contractor: NUSAC, Inc. FIELDS.J.A. Technical Assistance Contracts Branch. NRC-02-B2-034. B3/07/05. DAVIS.J. Office of Nuclear Material Safety & Safeguards. Director. MILLER.M. NRC - No Detailed Affiliation Given. 1p. 19470: 333.
- --B307200142 Mod 7, mpdifying statement of work authorizing use of PL/I, to "MCLAMS Mod."

  PEVENSTEIN.J.E. NUSAC, Inc. GUSTAVE.R.P. Division of Contracts. NRC-02-82-034. 83/07/05. ip. 19670:334.

- --8307080551 Mod 5, providing addl funding for travel & attendance at two previously unscheduled meetings, to "Seismic Qualification of Nuclear Plant Mechanical & Electrical Equipment.

  BIRGEL,S. H Southwest Research Institute GUSTAVE.R.P. Division of Contracts FIN D-7087. NRC-04-81-185. 83/06/27. 2pp.
- B307080557 Notification of contract execution. Mod i to "Subscriptions to Following Publications Inside Energy/W/Federal Lands.
  Inside FERC. Inside NRC. Nuclear Fuel. Nucleonics We."
  Contractor McGraw-Hill. Inc.
  SMITH.P. A. Division of Contracts. NRC-10-B3-321. B3/06/27.
  BESAW. W. J. Division of Technical Information & Document Control.
  CONYNOMAM. M. NRC No Detailed Affiliation Given. 1p. 19365:032.
- --B3070B0563 Mod 1,providing two addl 7-month subscriptions to Inside Energy/H/Federal Lands & adding one 7-month subscriptions to Inside Nucleonics Ht. to "Subscriptions to Following Publications: Inside Energy/H Federal Lands..."
  FERRANJE.J. McGraw-Hill Publications Co. SMITH,P. A. Division of Contracts. NRC-10-B3-321. B3/06/27. 2pp. 19365:033.
- 8307080583 Notification of contract execution Mod 5 to "Research Study Entitled 'Study of Regional Tectonics & Seismicity for Iowa '" Contractor: Iowa Geological Survey.

  SILVIS.R M. Technical Assistance Contracts Branch. FIN 0-6312.

  NRC-04-78-228. 83/06/27. BATSON.W. Office of Nuclear Regulatory Research. Director. STEUER.N. NRC No Detailed Affiliation Given.

  Ip. 19364: 289.
- --B307080595 Mod 5.deobligating funds to "Research Study Entitled 'Study of Regional Tectonics & Seismicity for lows.' 'Division of VAN ECK.D.J. Ioua Geological Survey. GUSTAVE.R.P. Division of Contracts. FIN B-6312. NRC-04-78-228. 83/06/27. Ip. 19364:290.
- 8307140115 Notification of contract execution: "Word Processing Svcs," awarded to Keyboard Communications, Inc. DURSEY,M., BAZIN,J.P. Administrative Contracts Branch. NRC-10-83-276. 82/12/01. STEELE,M. Division of Technical Information & Document Control. JOHANSEN,J. Cress Branch. 1p. 19528:001.
- --8307140119 Solicitation, offer & award of "Word Processing Svc" to Keyboard Communications, Inc. \* Keyboard Communications, Inc. MAITIA.M.J. Division of Contracts. NRC-10-83-296. 82/12/01. 102pp. 19328:002.
- 8307140481 Notification of contract execution: "Basic Ordering Agreement Entitled 'Technical Assistance in Hydrogeology'," awarded to Ertec Western, Inc.
  WIGGINS, E. Technical Assistance Contracts Branch. FLEENOR, C. Division of Contracts. NRC-02-82-028-07. 83/06/16. BRDWN, R.S. Program Support Branch. JOHNSON, B. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17527: 284.
- -8307140483 Contract: "Basic Ordering Agreement Entitled Technical Assistance in Hydrogeology", " awarded to Ertec Western Inc. YOUNG G 7. Ertec, Inc. Division of Contracts. NRC-02-82-028-07. 83/06/14. 37pp. 19527:285.
- 03071404B7 Notification of contract execution. Mod I to "Radioactive Matis Transportation Surveillance Program." Contractor: State of MD.
  State of MD.
  SMITH,PA. Division of Contracts. FIN B-1327. NRC-06-80-679.
  B3/07/01. KERR. G.W. Office of State Programs. Director. JANINEK,M.
  NRC No Detailed Affiliation Given. Ip. 19527:341.
- -8307140493 Mod 1,deobligated remaining unliquidated balance,to "Radioactive Matis Transportation Surveillance Program." EICHBAUM, W. M. Maryland, State of, SMITH, P. A. Division of Contracts. FIN B-1327, NRC-06-80-679, 83/07/01, 1p. 19527:342.
- 307140508 Notification of contract execution: "Severe Accident Core/ Vessel/Containment Interactions," awarded to Purdue Research Foundation, Purdue Univ. WiGoINS, E. Technical Assistance Contracts Branch. FIELDS, J. Division of Contracts. FIN B-8634. NRC-03-83-093. 93/06/16. MATTSON, R. J. Division of Systems Integration (post Bi1005). HARDIN, W. NRC No Betailed Affiliation Given. 1p. 19526:044.
- 9307140517 Contract: "Severe Accident Core/Vessel/Containment Interactions," awarded to Purdue Research Foundation,Purdue
- MORTON, K
  of Contracts. FIN B-8634. NRC-03-83-093. 83/06/16. MORTON, K. V. D: 83/06/16. 21pp. Division

- B307140523 Notification of contract execution: "Programming, Training, Testing, Conversion & Implementation of Facility Control Sys (FACS), " awarded to Doeing Computer Sycs Co. DORSEY.M. Administrative Contracts Branch. FIN B-8848. NRC-33-83-458. B3706/16. BASSETT.M.S. Office of Resource Management. Director. WRIGHT.G. NRC No Detailed Affiliation Given. 1p. 17526:O66.
- --8307140528 Contract: "Programming, Training, Testing, Conversion & Implementation of Facility Control Sys (FACS)," awarded to Bosing Computer Sycs Co.
  HOPKINS: H.R. Bosing Computer Services, Inc. (subs. of Bosing Co.).
  MATTIA: M.J. Division of Contracts. FIN 8-8848. NRC-33-83-458.
- 8307150009 Notification of contract execution: "Examine Facts in Employee Grievance-Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." awarded to DE Matthews.
  HURPHY.L.G. Administrative Contracts Brench. NRC-10-83-367.
  B3/07/01. DIRD.P.E. Division of Organization and Personnel.
  MOHRWINKEL, C. NRC No Detailed Affiliation Given. 1p. 19562:330.
- --8307150016 Contract: "Examine Facts in Employee Orievance Hold Hearing Including Taking Testimony & Acceptance of Evidentiary Mat1 & Make Final Written Rept." awarded to DE Matthews.

  MATTHEWS D. E. Matthews. D. E. REBELLO. J. E. Division of Contracts.

  NRC-10-83-367. 83/07/01. 6pp. 19562:331.
- 9307150094 Notification of contract execution, Mod 1 to "Classified Maste Paper Destruction Project." Contractor: Simking Industries, Inc.
  MCLEAREN, T. Administrative Contracts Branch. NRC-10-82-403. 83706/27. BRADY, R. J. Division of Security. BURNSIDE, W. NRC Detailed Affiliation Given. 1p. 19896: 360. NRC - No
- --B307150056 Mad i, extending period of performance to B40407, to "Classified Waste Paper Destruction Project."

  RUSSELL.V. Sinkens Industries, Inc. SMITH, P. A. Division of Contracts. NRC-10-82-403. B3/06/27. [p. 19576:361.
- 8307150364 Notification of contract execution.Mod 1 to "State Legislative Reporting Svcs." Contractor:Public Affairs Info Inc. PERLMAN, J. PERLMAN. J. Administrative Contracts Branch. FIN 8-1592. NRC-06-83-266. 83/07/01. KERR. G. H. Office of State Programs. Director. LANDAU. H. NRC - No Detailed Affiliation Given. Ip.
- --B307150347 Mod 1, adding quarterly payments, to "State Legislative PV.15046/ Mod 1.adding quarterly payments,to "State Legislati Reporting Svcs." Public Affairs Information, Inc. SMITH.P.A. Division of Contracts. FIN 8-1592. NRC-06-83-266. 83/07/01. 2pp.
- B307150374 Notification of contract execution Mod 4 to "Maint of Data General Computers & Peripheral Equipment." Contractor: Data Consultants, Inc.
  PERLMAN.J. Administrative Contracts Branch. FIN B-1663.
  NRC-25-82-311. 83/06/23. BASSET, H. R. Defice of Resource Management, Director. JUHNSON, C. R. NRC No Detailed Affiliation Given. 1p. 19540: 334.
- --8307150376 Mod 4.extending period of performance to 840526, to "Maint of Data General Computers & Peripheral Equipment," BUNNES, G. Data Consultants, Inc. SMITH, P. A. Division of 17540:335. FIN 8-1663. NRC-25-82-311. 83/06/23. 2pp.
- B307150413 Notification of contract execution, Mod 3 to "Maint & Operation of LPDRs." Contractor: State Library of PA. MCLEAREN.T. Administrative Contracts Branch. NRC~10~82~696. 83/04/29. FELTON, J. M. Office of Administration. SOUDER, J. NRC No Detailed Affiliation Given. 1p. 19540: 183.
- --8307150417 Mad 3, extending period of performance to 840630 & increasing funds, to "Maint & Operation of LPDRs."

  SHELKRET, E. L. Pennsylvania, Commonwealth of, SMITH, P. A.
  Division of Contracts. NRC-10-82-696. 83/06/29. 1p. 19540:184. SMITH, P. A. 15. 19540: 184.
- 8307150420 Notification of contract execution, Mod 3 to "Multiple Award Task Order Contract for ADP Development." Contractor: Boeing Computer Svcs Co.
  PERLMAN. J. Administrative Contracts Branch. FIN B-8166, NRC-93-983-683-687-07-07.
  BASSET, H. S., HARVES, J. Office of Resource Management, Director. 1p. 19540: 181.
- --8307150422 Mod 3, changing cost of money rates, to "Multiple Award Task Order Contract for ADP Development."

  \* Boeing Computer Services, Inc. (subs. of Boeing Co.), SMITH.P.A. Division of Contracts. FIN B-8166. NRC-33-83-452.

- 8307150427 Notification of contract execution.Mod 1 to "Listing of High Technology 8(a) Firms." Contractor:Miranda Associates. Inc. BROMBERG.B. J. Administrative Contracts Branch. NRC-27-83-446. 83/06/09. KERR.M. Ofc of Small & Disadvantaged Bus. Utilization & Civil Rights. COLEMAN.H. NRC No Detailed Affiliation Given. 1p. 19540:185.
- --B307150430 Mod 1,allowing partial payments when sample submitted to "Listing of High Technology 8(a) Firms." \* Miranda Associates Inc. SMITH.P.A. Division of Contracts. NRC-27-B3-446. B3/96/09. 3pp. 19540:186.
- B307150433 Notification of contract execution, Mod 2 to "Provide Expert Technical Consulting Sycs to DCS on Task Order Basis."

  Contractor: Dept of Air Force.

  BROMBERG. B. J. Administrative Contracts Branch. NRC-10-82-404.
  B3/07/05. NORRY, P. G., LUNDY, J. Office of Administration. ip.
  19340:197.
- --B307150435 Mod 2.extending period of performance to B31230.to "Provide Expert Technical Consulting Bvcs to DCS on Task Order Basis."

  \* Air Force, Dept. of. SMITH.P.A. Division of Contracts.
  NRC-10-82~404. B3/07/05. 2pp. 19540:200.
- 8307130453 Notification of contract execution Mod 5 to "Conversion, Programming, Implementation, Documentation 5 Acceptance Processing of IFMIB." Contractor: SBA. Subcontractor: Technassociates.
  GILDENHURN, A. J. Administrative Contracts Branch. FIN B-8172.
  NRC-10-081-339, 83/06/12. DORIEL N. Office of Administration.
  HRIGHT, O. NRC No Detailed Affiliation Given. 1p. 19540: 295.
- ---B307150454 Mod 5, producing new program specs, increasing fixed fee & altering deliverable dates, to "Conversion, Programming, Implementation, Documentation & Acceptance Processing of IFM15." HILL, D. Small Business Administration. OFFORD, J. C. Technassociates, Inc. SMITH, P. H. Division of Contracts. FIN B-B172. NRC-10-B1-359. B3/06/12. 4pp. 19540: 296.
- B307180325 Notification of contract execution Mod 1 to "Bioassays Using Resonance Ionization Spectroscopy." Contractor:
  Atom Sciences. Inc.
  DELDATCH.V. Technical Assistance Contracts Branch. FIN B-8122.
  NRC-04-82-021. B3/07/02. FDREHAND.W. Diffice of Nuclear Regulatory Research. Director. NEEL.R. NRC No Detailed Affiliation Given.
- --8307180328 Mod 1.extending period of performance to 830727 at no add1 cost.to "Bioassays Using Resonance Ionization Spectroscopy."

  BCHHITT.H. Atom Bciences, Inc. GUSTAVE.R.P. Division of Contracts. FIN B-8122. NRC-04-82-021. 83/07/02. 1p. 19366:089.
- 8307180429 Notification of contract execution Mod 1 to "Cataloging Support Svcs." Contractor: Informatics: Inc.
  8M1TH: P. A. Division of Contracts. NRC-10-79-362. 83/07/05.
  BESAL: W. J. Division of Technical Information & Document Control.
  WISE.R. NRC No Detailed Affiliation Given. 1p. 19366: 346.
- --8307180431 Mod i,increasing amount of contract to allow for indirect rate adjustment, to "Cataloging Support Svcs."
  SLOHLY,L. Informatics, Inc. BMITH,P.A. Division of Contracts.
  NRC-10-79-362. 83/07/05. 1p. 19566:347.
- 8307180434 Notification of contract execution Mod 1 to "Examine Facts in Employee Grievance. Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Hritten Rept." Contractor: DE Matthews.
  MURPHY.L. Q. Administrative Contracts Branch. NRC-10~83-367.
  83706/30. BIRD, P.E. Division of Organization and Personnel.
  MORRHINKEL, C. NRC No Detailed Affiliation Given. 1p. 19366: 342.
- --8307180436 Mod 1.extending period of performance to 830708, to "Examine Facts in Employee Grisvance, Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept."

  MATTHEWS: D. E. Matthews, D. E. REBELLO, J. E. Division of Contracts. NRC-10-83-367. 83/06/30. 1p. 19566:343.
- B307190107 Notification of contract execution, Mod | 1 to "Btructural Integrity of Water Reactor Boundry Components." Contractor: ENSA, Inc. WOLLETT, B. Technical Assistance Contracts Branch. FIN B-8133. NRC-04-82-013. B3/07/01. FOREHAND, W. Office of Nuclear Regulatory Research, Director. VAGINS, M. NRC No Detailed Affiliation Given. 1p. 19636: 213.
- --B307190112 Mod 11, providing addl work & funding & extending period of performance to 831115.to "Structural Integrity of Water Reactor Boundry Components."
  HA65.H.N. ENSA: Inc. GUSTAVE.R.P. Division of Contracts.
  NRC-04-82-013. 83/07/01, 9pp. 17656:214.

- 8307190307 Notification of contract elecution "Monthly Update of NRC Rules & Regulations." awarded to SBA Subcontractor Metrotec. JACOBS.A Administrative Contracts Branch. NRC-10-83-330. 83/06/10 FELTON.JM. Office of Administration PHILLIPS.J. NRC No Detailed Affiliation Given. 1p 19456:007.
- ---8307190313 Contract: "Monthly Update of NRC Rules & Regulations,"
  awarded to SBA. Subcontractor. Metrotec.
  \* Small Business Administration. NELSON, J.E. Metrotec, Inc.
  BENNISTON, 8.F. Division of Contracts NRC-10-83-350. 83/06/10
  23pp. 19656:008.
- B307190335 Notification of contract execution.Mod 3 to "Shuttle Bus Svc." Contractor:Capital City Coach.Inc. DDRSEY.M., FERLMAN.J. Administrative Contracts Branch. NRC-10-DB2-362 B3/07/07. CDREY.J.H., GRANT.L NRC - No Detailed Affiliation Given. 1p. 19654:047.
- --8307190339 Mod 3,establishing termination settlement costs,to
  "Shuttle Bus Svc."
  RYAN.J.S. Capital City Coath. SMITH.P.A. Division of Contracts.
  NRC-10-82-362. 83/07/07. 2pp. 19654:048.
- B307190411 Notification of contract execution.Mod 4 to "ADP Sys Support." Contractor: SBA Subcontractor: Technassociates.
  G1LDENHORN.A.J. Administrative Contracts Branch. FIN 8-0664.
  NRC-23-B3-315. B3/06/29. BARRY, L. W. Office of Resource Management, Director. BURTON, J. NRC No Detailed Affiliation Given. 1p. 19656: 145.
- ---B307190418 Mod 4.extending period of performance to 840616, increasing ceiling & obligated amount, adding option, changing labor hourly rates, changing security provisions & adding key personnel, to "ADP Bys Support."

  HILL.D. Small Business Administration. OFFORD, J. C.
  Technassociates, Inc. HAGAN, T. F. Division of Contracts. FIN B-1664. NRC-25-82-315. B3/06/29, 7pp. 19656:146.
- 8307190430 Notification of contract execution. Mod 4 to "On Call Maint for NRC Computer Peripheral Equipment " Contractor: Computer Sys Support Corp. PERLMAN. J. Administrative Contracts Branch. FIN 8-8174. NRC-33-83-451. 83/07/14. BASSETT. H. S. Division of Data Automation & Management [ reformation. JQHNSON, C. NRC No Detailed Affiliation Given. 19. 19656: 155.
- --8307190435 Mod 4, adding addl equipment; to "On Call Maint for NRC Computer Peripheral Equipment."

  ROOT.L.E. Computer Systems Support Corp. SMITH.P.A. Division of Contracts. FIN B-8174. NRC-33-83-451. 83/07/14. 2pp. 19686-156.
- 8307190433 Notification of contract execution: "Photographic Reproduction Svc," awarded to SBA Subcontractor: Domus Design Btudios. Inc. BAZIN, J.P. Administrative Contracts Branch. NRC-10-83-322. B3/07/07. BESAW, W. J. Division of Tachnical Information & Document Control. DEHN, D. NRC - No Detailed Affiliation Given. 1p. 19643: 313.
- --B307190458 Contract: "Photographic Reproduction Svc." awarded to SBA.
  Subcontractor: Domus Design Studios. Inc. Subcontractor
  contract encl.
  \* Small Dusiness Administration. RERGODUL.T.E. Domus Design
  Studios. Inc. MATTIA.M.J. Division of Contracts. NRC-10-83-322.
  B3/07/07. Sipp. 19643: 314.
- 8307200133 Notification of contract execution, Mod 7 to "Geotechnical Engineering Casework Review II." Contractor: US Army Corps of Engineers.
  FIELDS.J. Technical Assistance Contracts Branch. FIN 9-8027.
  NRC-03-82-102 83/07/06. VOLLMER.R.H. Division of Engineering.
  LEAR.G. NRC No Detailed Affiliation Given. 1p. 19670: 335.
- --8307200157 Mod 7. increasing funds obligated for technical svcs & deobligating funds for FY82 travel, to "Deotechnical Engineering Casework Review II."
  RYAN,R.H. Army, Dept. of, Corps of Engineers. GUSTAVE,R.P. Division of Contracts. FIN B-8027. NRC-03-82-102. B3/07/06. Rpp. 19670:336.
- BB07200159 Notification of contract execution Mod 7 to "MCLAMS Mod."
  Contractor: NUSAC: Inc.
  FIELDS.J.A. Technical Assistance Contracts Branch. NRC-02-02-034.
  B3/07/05. DAVIS.J. Office of Nuclear Material Safety &
  Bafeguards: Director. MILLER.M. NRC No Detailed Affiliation Given.
  1p. 19670: 333.
- ---8307200162 Mod 7, modifying statement of work authorizing use of PL/I, to "MCLAMS Mod."

  PEVENSTEIN, J.E. NUBAC, Inc. GUSTAVE.R.P. Division of Contracts.

  NRC-02-82-034. 83/07/05. 1p. 19670:334.

- --830708055I Mod 5, providing add1 funding for travel & attendance at two praviously unscheduled meetings, to "Seismic Qualification of Nuclear Plant Mechanical & Electrical Equipment.
  BIRGEL, S. H. Southwest Research Institute GUSTAVE, R. P. Division of Contracts. FIN 8-7087. NRC-04-81-185. 83/06/27. 2pp.
- B307080557 Natification of contract execution.Mod 1 to "Subscriptions to Following Publications: Inside Energy-W/Fedoral Lands, Inside FERC, Inside NRC, Nuclear Fuel, Nucleonics Wk."

  Contractor: McGraw-Hill, Inc.

  SMITH, P. A. Division of Contracts. NRC-10-83-321. 83/06/27.

  BESAW, W. J. Division of Technical Information & Document Control. CONYNGHAM, M. NRC No Detailed Affiliation Given. 1p. 19365:032.
- --8307080563 Mod i, providing two addl 7-month subscriptions to Inside Energy/W/Federal Lands & adding one 7-month subscription to Nucleonics Wi, to "Subscriptions to Following Publications: Inside Energy/W Federal Lands..."
  FERRANTE, J. McGraw-Hill Publications Co. SMITH, P. A. Division of Contracts. NRC-10-83-321. 83/06/27. 2pp. 19365:033.
- 8307080583 Notification of contract erecution, Mod 5 to "Research Study Entitled 'Study of Regional Tectonics & Selamicity for Iowa.'" Contractor: Iowa Geological Survey.
  SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-6312.
  NRC-04-78-228. 83/06/27. BATSON.W. Office of Nuclear Regulatory Research. Director. STEUER:N. NRC No Detailed Affiliation Given.
  19. 19364:289.
- -8307080595 Mod 5, deabligating funds, to "Research Study Entitled 'Study of Regional Tectonics & Saismicity for Iowa.'"

  VAN ECK, O. J. Iowa Geological Survey. GUSTAVE, R. P. Division of Contracts. FIN 8-6312. NRC-04-78-228. 83/06/27. 1p. 19364
- 307140115 Notification of contract execution: "Word Processing Svcs," awarded to Keyboard Communications.inc.
  DORSEY, M., BAZIN, J.P. Administrative Contracts Branch.
  NRC-10-82-394 82/12/01. STEELE, M. Division of Technical Information & Document Control. JUHANSEN, J. Cress Branch. ip. 19528:001.
- -B307140119 Solicitation.offer & award of "Word Processing Svc" to Keyboard Communications. Inc. ★ Keyboard Communications. Inc. MATTIA.M.J. Division of Contracts. NRC-10-83-296. 82/12/01. 102pp. 19528:002.
- O7140481 Notification of contract execution: "Basic Ordering Agreement Entitled 'Technical Assistance in Hydrogeology';" awarded to Entec Mestern. Inc.
  WIGOINS. E. Technical Assistance Contracts Branch. FLEENOR.C.
  Division of Contracts. NRC-02-82-028-07. 83/06/16. BROWN, R.S.
  Program Support Branch. JOHNSON.B. Office of Nuclear Material
  Safety & Safeguards, Director. 1p. 19527: 284.
- 9307140483 Contract: "Basic Ordering Agreement Entitled 'Technical Assistance in Hydrogeology': "awarded to Ertec Western.Inc. YOUND, G. T. Ertec, Inc. \* Division of Contracts. NRC-02-82-028-07. 83/06/16. 37pp. 19527:285.
- 071404B7 Notification of contract execution.Mod 1 to "Radioactive latis Transportation Surveillance Program." Contractor: MITH.P.A. Division of Contracts. FIN B-t327. NRC-06-80-679. 3/07/01. KERR.G.W. Defice of State Programs. Director. JANINER NRC No Detailed Affiliation Given. 1p. 19527:341.
- 307140493 Mod 1.deobligated remaining unliquidated balance, to "Radicactive Matls Transportation Surveillance Program." EICHBAUM.W.M. Maryland, State of SMITH.P.A. Division of Contracts. FIN B-1327. NRC-04-80-679. 83/07/01. 1p. 19327:342.
- P140508 Notification of contract execution: "Severe Accident Core/
  essel/Containment Interactions," awarded to Purdue Research
  sundation.Purdue Univ.
  (GOINS.E. Technical Assistance Contracts Branch, FIELDS, J.
  vision of Contracts. FIN B-8634. NRC-03-83-093. 83/06/16.
  HTSON.R.J. Division of Systems Integration (post 81005).
  RDIN.W. NRC No Detailed Affiliation Given. Ip. 19526:044.
- 07140517 Contract: "Severe Accident Core/Vessel/Containment Interactions," awarded to Purdue Research Foundation,Purdue
- Interactions," awarded to Purdue Resparch Foundation,Purdue Univ. HENISCHEL,W.F. Purdue Research Foundation. MORTON,K.V. Di of Contracts. FIN 8-8634. NRC-03-83-093. 83/06/16. Zipp. 19526:045. Division

- B307140523 Notification of contract execution: "Programming Training Testing Conversion & Implementation of Facility Control Sys (FACS): "awarded to Boeing Computer Svss Co. DORSEY M. Administrative Contracts Branch. FIN B-8848. NRC-33-83-438 B3706/16. BASSETT, H.S. Office of Resource Management. Director. WRIGHT. G. NRC No Detailed Affiliation Given. 1p. 17326:066.
- --B307140528 Contract: "Programming, Training, Testing, Conversion & Implementation of Facility Control Sys (FACS)," awarded to Boeing Computer Sycs Co.
  HDPKINS:H.R. Boeing Computer Services, Inc. (subs. of Boeing Co.).
  MATTIA:M.J. Division of Contracts. FIN B-8848. NRC-33-83-458.
- 8307150009 Notification of contract execution: "Examine Facts in Employee Grievance, Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Hritten Rept," awarded to DE Matthews.
  MURPHY, L. G. Administrative Contracts Branch. NRC-10-83-367.
  83/07/01. BIRD, P. E. Division of Organization and Personnel.
  MOHRWINKEL, C. NRC No Detailed Affiliation Given. 1p. 19562:330.
- --8307159016 Contract: "Examine Facts in Employee Orievance, Hold Hearing Including Taking Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept," awarded to DE Matthews.

  MATTHEWS.D.E. Matthews. D.E. REBELLD.J.E. Division of Contracts.

  NRC-10-83-367. 83/07/01. 6pp. 19562:331.
- 8307150054 Notification of contract execution, Mod 1 to "Classified Waste Paper Destruction Project." Contractor: Simkins Industries, Inc.
  MCLEAREN, T. Administrative Contracts Branch. NRC-10-82-403, 83/06/27. BRADY, R. J. Division of Security. BURNSIDE, W. NRC No Detailed Affiliation Given. 1p. 17596:360.
- --8307150056 Mod 1 extending period of performance to 840407, to "Classified Waste Paper Destruction Project." RUSSELL.V. Simtens Industries, Inc. 9MITH/P.A. Division of Contracts. NRC-10-82-403. 83/06/27. ip. 19596:361.
- 8307150364 Notification of contract execution, Mod 1 to "State Legislative Reporting Svcs." Contractor: Public Affairs Info. Inc. Inc.
  PERLMAN, J. Administrative Contracts Branch. FIN B-1592.
  NRC-06-83-266. 83/07/01. KERR.G.W. Dffice of State Programs.
  Director. LANDAU, M. NRC - No Detailed Affiliation Given. ip.
- ~-8307150367 Mod 1, adding quarterly payments, to "State Legislative Reporting Svcs."

  \* Public Affairs Information, Inc. SMITH, P. A. Division of Contracts. FIN B-1592. NRC-06-83-266. 83/07/01. 2pp.
- B307150374 Notification of contract execution. Mod 4 to "Maint of Data General Computers & Peripheral Equipment." Contractor: Data Consultants, Inc.
  PERLMAN.J. Administrative Contracts Branch. FIN B-1663.
  NRC-25-82-311. B3705/23. BASSET, H. R. Office of Resource Management, Director. JDHNBON, C. R. NRC ~ No Detailed Affiliation Given. 1p. 19540: 334.
- --8307150376 Mod 4.extending period of performance to 840526.to "Maint of Data General Computers & Peripheral Equipment."

  BONNES.C. Data Consultants. Inc. SMITH.P.A. Division of Contracts. FIN 8-1663. NRC-25-82-311. 83/06/23. 2pp.
- 8307150413 Notification of contract execution.Mod 3 to "Maint & Operation of LPDRs." Contractor: State Library of PA. MCLEAREN.T. Administrative Contracts Branch. NRC-10-82-696. 83/06/29. FELTON, J. M. Office of Administration. SOUDER, J. NRC No Detailed Affiliation Given. 1p. 17540: 183.
- --8307150417 Mod 3, extending period of performance to 840630 & increasing funds, to "Maint & Operation of LPDRs."
  SHELKRET, E. L. Pennsylvania, Commonwealth of, SMITH, P. A.
  Division of Contracts, NRC-10-82-676, 83/06/29, Ip. 19340:184.
- 8307150420 Notification of contract execution, Mod 3 to "Multiple Award Task Order Contract for ADP Development." Contractor: Boeing Computer Svis Co.
  PERLMAN, J. Administrative Contracts Branch. FIN B-8166.
  NRC-33-83-452. B3/07/07. BASSET, H. S., HARVES, J. Office of Resource Management, Director. 1p. 19540: 181.
- --8307150422 Mod 3, changing cost of money rates, to "Multiple Award Task Order Contract for ADP Development."

  \*\*Boeing Computer Services Inc. (subs. of Boeing Co.).

  SMITH, P. A. Division of Contracts. FIN B-8166. NRC-33-83-452.

  83/07/07. 1p. 19540:182.

- B307i50427 Notification of contract execution.Mod 1 to "Listing of High Technology B(a) Firms." Contractor:Miranda Associates, Inc. BROMBERG.B. J. Administrative Contracts Branch. NRC-27-63-446. B3/D6/09. KERR.H. Dfc of Small & Disadvantaged Rus. Utilitation & Civil Rights. COLEMAN.H. NRC No Detailed Affiliation Given. ip.
- --8307150430 Mod 1,allowing partial payments when sample submitted to "Listing of High Technology 8(a) Firms." # Miranda Associates, Inc. SMITH.P A. Division of Contracts. NRC-27-83-446, 83/06/09. 3pp. 19540.186.
- B307150433 Notification of contract execution, Mod 2 to "Provide Expert Technical Consulting Svcs to DCS on Task Order Basis."

  Contractor: Dept of Air Force.
  BROMBERG, B. J. Administrative Contracts Branch. NRC-10-82-404.
  B3/07/05. NORRY, P. G., LUNDY, J. Office of Administration. 1p.
  19540:199.
- ---8307150435 Mod 2, extending period of performance to 831230, to "Provide Expert Technical Consulting Sycs to DCS on Task Order Basis."

  \* Air Force, Dept. of. SMITH, P.A. Division of Contracts.
  NRC-10-82-404. 83/07/05. 2pp. 19540:200.
- 8307150453 Notification of contract execution. Mod 5 to "Conversion, Programming, Implementation, Documentation & Acceptance Processing of IFMIS." Contractor: SBA. Subcontractor: Technassociates.
  - OILDENHORN.A.J. Administrative Contracts Branch. FIN B-8172. NRC-10-81-357. 83/06/12. DDRIE.W. Office of Administration. WRIGHT, G. NRC No Detailed Affiliation Given. ip. 19540:295.
- --8307130454 Mod 5, producing new program specs, increasing fixed fee & altering deliverable dates to "Conversion, Programming, Implementation, Documentation & Acceptance Processing of HTMLS."

  HTMLS."

  HTML.D. Small Business Administration. DFFORD.J.C.

  Technosociates, Inc. SHITH.P.H. Division of Contracts. FIN

  B-8172. NRC-10-81-359. 83/06/12. 4pp. 19540:296.
- 8307180325 Notification of contract execution.Mod 1 to "Bioassays Using Resonance Ionization Spectroscopy." Contractor:
  Atom Sciences:Inc.
  DELOATCH.V. Technical Assistance Contracts Branch. FIN B-8122.
  NRC-04-82-021. B3/07/02. FOREHAND.W. Office of Nuclear Regulatory Research. Director. NEEL.R. NRC -- No Detailed Affiliation Given.
  19. 19366:087.
- --8307180328 Mod 1.extending period of performance to 830727 at no add1 cost.to "Bioassays Using Resonance Ionization Spectroscopy."

  SCHMITT.H.W. Atom Sciences, Inc. GUSTAVE, R.P. Division of Contracts. FIN B-8122. NRC-04-82-021. 83/07/02. 1p. 179566:087.
- B307180429 Notification of contract execution Mod i to "Cataloging Support Svcs." Contractor:Informatics.Inc. BMITH.P.A. Division of Contracts. NRC-10-79-362. B3/07/05. BEBALW.W. Division of Technical Information & Document Control WISE.R. NRC No Detailed Affiliation Given. 1p. 19366:346.
- --8307180431 Mod i.increasing amount of contract to allow for indirect rate adjustment.to "Cataloging Support Svcs." SLDMLY.L. Informatics, Inc. SHITM.P.A. Division of Contracts. NRC-10-79-362. 83/07/05. ip. 19566:347.
- 8307180434 Notification of contract execution, Mod 1 to "Examine Facts in Employee Grievance. Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." Contractor: DE Matthews.
  MURPHY.L. G. Administrative Contracts Branch. NRC~10-83-347.
  83706/30. BIRD.P.E. Division of Organization and Personnel.
  MOHRWINKEL.C. NRC No Detailed Affiliation Given. ip. 19566: 342.
- --8307180436 Mod 1.extending period of performance to 830708,to "Examine Facts in Employee Grievance, Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept."

  MATTHEWS, D. E. Matthews, D. E. REBELLO, J. E. Division of Contracts, NRC-10-83-367, 83/06/30, 1p. 17566:343.
- 8307190107 Notification of contract execution, Mod 11 to "Structural Integrity of Water Reactor Boundry Components." Contractor: ENSA: Inc.

  MOLLETT: S. Technical Assistance Contracts Branch. FIN 8-8133.

  NRC-04-82-013. 83/07/01. FOREHAND.W. Office of Nuclear Regulatory Research. Director. VAGINS.M. NRC No Detailed Affiliation Given.

  1p. 19656:213.
- --8307190112 Mod 11, providing add1 work & funding & extending period of performance to 831115, to "Structural Integrity of Water Reactor Boundry Components."

  HAAS.M.N. ENSA: Inc. GUSTAVE.R.P. Division of Contracts.

  NRC-04-82-013. 83/07/01. 9pp. 17656:214.

- 8307190307 Notification of contract execution "Monthly Updat Rules % Regulations," awarded to SBA Subcontractor Metrotec JACOBS. A Administrative Contracts Branch. NRC-10-83-350. B3706/10 FELTON.J.M. Office of Administration PHILLIPS No Detailed Affiliation Given. 1p 19696:007. "Monthly Update of NRC
- ---B307190313 Cuntract: "Monthly Update of NRC Rules & Regulations,"
  awarded to SBA. Subcontractor: Metrotec.
  \* Small Business Administration. NELSON, J. E. Metrotec, Inc.
  DENNISTON: S. F. Division of Contracts NRC-10-83-350. 83/06/10
  23pp. 19656:008.
- 8307190339 Notification of contract execution, Mod 3 to "Shuttle Bus Byc." Contractor:Capital City Coach, Inc DCRSEY, M. PERLMAN, J. Administrative Contracts Brench NRC-10-82-362 B3/07/07. CORLEY, J. H., GRANT, L. NRC No Detailed Affiliation Given. 1p. 19654:047.
- --8307190337 Mod 3,establishing termination settlement costs,to
  "Shuttle Bus Svc."
  RYAN.J.S. Capital City Coach. SMITH.P.A. Division of Contracts.
  NRC-10-82-342. 83/07/07. 2pp. 19654:048.
- B307190411 Notification of contract execution, Mod 4 to "ADP Sys Support." Contractor: 80A. Subcontractor: Technassociates. GILDENHORN, A. J. Administrative Contracts Branch. Fin B-0664. NRC-25-89-315. B3/06/29. BARRY.L.W. Office of Resource Management, Director. BURTON, J. NRC No Detailed Affiliation Given. 1p. Director. BURTON, J. 19656: 145.
- --8307190418 Mod 4.extending pariod of performance to 840616.increasing ceiling & obligated amount, adding option.changing labor hourly rates.changing security provisions & adding key personnel.to "ADP Sys Buppart."
  HILL.D. Smail Business Administration OFFORD.J.C.
  Technassociates. Inc. HAGAN.T.F. Division of Contracts. FIN 8-1664. NRC-29-82-315. 83/06/27. 7pp. 19656:146.
- B307190430 Notification of contract execution.Mod 4 to "On Call Maint for NRC Computer Peripheral Equipment " Contractor: Computer Sys Support Corp. PERLMAN.U. Administrative Contracts Branch. FIN 8-8174. NRC-33-83-451. B3/07/14. BASETIT.M.S. Division of Data Automation & Management Information. JOHNSON.C. NRC No Detailed Affiliation Given. 1p. 19456:135.
- --8307190435 Mod 4.adding addl equipment.to "On Call Maint for NRC Computer Peripheral Equipment."

  ROOT.L.E. Computer Systems Support Corp. BMITH.P.A. Division Contracts. FIN B-8174. NRC-33-83-451. 83/07/14. 2pp. 19656:156.
- B307190453 Notification of contract execution: "Photographic Reproduction Syc," awarded to SBA. Subcontractor: Domus Design Studios. Inc.
  BAZIN.J.P. Administrative Contracts Branch. NRC-10-83-322.
  B3707/07. BESAN.W.J. Division of Technical Information & Document Control. BEHN.D. NRC No Detailed Affiliation Given. ip. 19643:313.
- --8307190498 Contract: "Photographic Reproduction Svc." awarded to SBA.
  Subcontractor:Domus Design Studios, Inc. Subcontractor
  contract encl.

  \* Small Business Administration. BERGDOLL..T.E. Domus Design
  Studius: Inc. MATTIA.M.J. Division of Contracts. NRC-10-83-322.
  83/07/07. 31pp. 19443:314.
- 8307200153 Notification of contract execution Mod 7 to "Geotechnical Engineering Casework Review II." Contractor: US Army Corps of Engineers FIELDS.J.A. Technical Assistance Contracts Branch. FIN 0-8027. NRC-03-82-102. 83/07/06. VOLLMER.R.H. Division of Engineering. LEAR.G. NRC - No Detailed Affiliation Given 1p. 19670:335.
- ~-8307200157 Mod 7, increasing funds obligated for technical sycs & deobligating funds for FY82 travel, to "Geotechnical Engineering Casework Review II."

  RYAN,R.H. Army, Dept. of, Corps of Engineers. GUSTAVE,R.P. Division of Contracts. FIN B-8027. NRC-03-82-102. 83/07/06. 2pp. 19670:336.
- 8307200159 Notification of contract execution, Mod 7 to "MCLAMS Mod."
  Contractor: NUSAC, Inc.
  FIELDS.J.A. Technical Assistance Contracts Branch. NRC-02-82-034.
  83/07705. DAVIS, J. Office of Nuclear Material Safety &
  Safeguards, Director. MILLER.M. NRC No Detailed Affiliation Given.
  19. 19470: 333.
- --B307200162 Mod 7,modifying statement of work authorizing use of PL/I, to "MCLAMS Mod."

  PEVENSTEIN.J.E. NUSAC, Inc. GUSTAVE,R.P. Division of Contracts. NRC-02-82-034. B3/07/05. Ip. 19670:334.

- ob Notification of contract elecution, Mod 4 to "Survey on Snow on Nuclear Power Plant Structures." Contractor: NBS.

  R.M. Technical Assistance Contracts Branch. FIN 8-1087.

  79-009. B3/06/27. BATSON.W. Office of Nuclear Regulatory h, Director. KORNABIEWICZ.R. NRC No Detailed Affiliation | p. 19670: 228.
- 0170 Mod 4.deabligating remaining balance of funds under Fact, to "Survey on Snow Loads on Nuclear Power Plant (tures." (Br.D.B. Commerce, Dept. of, National Bureau of Standards. (VE.R.B. Division of Contracts. FIN B-1087. NRC-01-79-009. 1/27. ip. 19470:329.
- 2 Notification of grant execution.Mod 2 to "Thermal-Hydraulic nts Behavior of Coolant in Simulated Reactor Coop."

  Univ of Maryland.

  77.D. Technical Assistance Contracts Branch. FIN 9-1043.
  4-82-013. 83/06/30. BATSON.H. Office of Nuclear Regulatory
  h. Director. YOUNG.M. NRC No Detailed Affiliation Given.

  670:321.
- 177 Mod 2.providing add1 funds & incorporating 830302 proposed o "Thermal-Hydraulic Transients Behavior of Coolant in ated Reactor Coop."
  AN.D.C. Maryland: Univ. of. MORTON.K.V. Technical tance Contracts Branch. FIN 0-1043. NRC-G-04-82-013.
  /30. 1p. 19670:322.
- 1 Notification of grant execution: "Structural Mechanics in Tachnology 7 Post-Conference Seminar on Inclastic 5 & Life Prediction in High Temp Environ: " awarded to aer Polytechnic Inst.

  IT.D. Technical Assistance Contracts Branch. FIN 0-1050.

  1-93-006. B3/07/05. BATSON,W. Office of Nuclear Regulatory b. Director. WALKER,T. NRC No Detailed Affiliation Given.
- B5 Grant: "Structural Mechanics in Reactor Technology 7 conference Seminar on Inclastic Analysis & Life tition in High Temp Environ," awarded to Remsselaer chhic Inst. HORTON, K. V. ICE, J. M. Remsselaer Polytechnic Inst. HORTON, K. V. Cal Assistance Contracts Branch. FIN G-1050. 04-83-006. B3/07/05. 2pp. 19670:319.

- Notification of contract execution.Mod 5 to "Fire Protection Review & Evaluation V." Contractor:Gage-Babcock c. .A. Technical Assistance Contracts Branch. FIN 8-8015. 1-137. 83/06/20. VOLLMER.R.H. Division of Engineering. .R. NRC No Detailed Affiliation Given. 19. 19670:309.
- 98 Mod 5, revising statement of work & obligating funds for addles of "Fire Protection Program:Review & Evaluation V."
  M. Gage-Babcock Associates: Inc. GUSTAVE,R.P. Division of cts. FIN B-8015. NRC-03-81-139. 83/06/20. 3pp.
- Notification of contract execution Mod 3 to "Licensing ce/Geotechnical & Hydrological Evaluations." or: Harding-Lawson Assoc.

  A. Technical Assistance Contracts Branch.
  0-033-05. 83/07/05. DAVES.U. Office of Nuclear Material Safeguards.Director. GARCIA.P. NRC No Detailed ion Given. ip. 19670:307.
- 2 Mod 3.extending period of performance to 830930 at no addit "Licensing Assistance/Geotechnical & Hydrological ions."

  6.K.H. Harding-Lawson Associates. GUSTAVE.R.P. Division of ts. NRC-02-80-033-05. 83/07/05. ip. 19670:308.
- Notification of contract execution Mod 3 to "Hydrological ng (Coastal) Case Review 1." Contractor: US Army. A. Technical Assistance Contracts Branch. NRC-03-81-110. VOLLMER.R.H. Division of Engineering. JACKOMSKI.R. NRC iled Affiliation Given. 1g. 19670: 290.
- O Mod 3.extending period performance to 830930, revising ng requirements & changing project ofc. to "Hydrologic ring (Coastal) Case Review I."

  T.E. Army, Dept. of. GUSTAVE.R.P. Division of Contracts.
  81-110. 83/07/03. 4pp. 19670:291.

- Notification of contract execution Hod 5 to "Maint of Data onputers & Peripheral Equipment." Contractor: ultants, Inc.
  Administrative Contracts Branch. FIN 8-1663.
  -311. 83/07/13. BASSETT. H.R. Office of Resource to Director. JOHNSON, C.R. NRC No Detailed Affiliation p. 17672:261.

- -8307200388 Mod 5.correcting administrative error, to "Maint of Data General Computers & Peripheral Equipment." \* Data Consultants, Inc. SMITH.P.A. Division of Contracts. FIN B-1663. NRC-25-82-311. 83/07/13. 1p. 17672:262.
- 8307220057 Nutification of contract execution: "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Scottsboro, AL Public Library.

  AL Public Library.

  MURPHY,L.G. Administrative Contracts Branch. NRC-10-83-366.

  83/05/11. FELTON.J.M. Division of Rules and Records. SOUDER, J. NRC No Detailed Affiliation Given. 1p. 19691:348.
- -8307220075 Contract: "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Scottsboro, AL. Public Library, MCCUTCHEN.P. Scottsboro, AL. REBELLO, J. E. Purchasing Section, NRC-10-83-366, 83/05/11, 9pp. 19691:349.
- 8307250026 Notification of contract execution Mod 8 to "Deplogic Study of Low Level Radwaste Burial Site at West Valley, NY." Contractor: State Univ of NY.
  SILVIS: R. M. Technical Assistance Contracts Branch. FIN 8-6008.
  NRC-04-77-169. 83/07/14. 8AT80N. W. Office of Nuclear Regulatory Research. Director. HELD.E. NRC No Detailed Affiliation Given.
  1p. 19723: 307. 24X Fiche: 50-201. 83/07/14. 8307250026.
- --8307250030 Requests ack of Mod 8, deabligating funds, to "Geologic Study of Low Level Radwasse Burial Site at West Valley, NY."
  Signed by univ on 830425,
  GUSTAVE, R.P. Technical Assistance Contracts Branch. FIN 8-6008,
  NRC-04-77-169, 83/04/12, THOMPSON, J. New York, State Univ. of,
  (Albany). 1p. 19723;308, 24X Fiche; 50-201, 83/07/14, 8307250026.
- 8307290100 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of MI. SILVIB.R.M. Technical Assistance Contracts Branch. FIN 8-8451. NRC-30-83-644. 83/07/14. PAPPAG.H. Region 3. Office of Director. DESTMANN NRC No Detailed Affiliation Given. ip. 19720: 330.
- --8307250104 Mod 2, correcting B&R number, to "Radiation Monitoring Program Requirements." \* Michigan, State of. GUSTAVE,R.P. Division of Contracts. FIN 8-8451. NRC-30-83-644. 83/07/14. ip. 19720:331.
- 8307250111 Notification of contract statution. Mod 1 to "Radiation Monitoring Program Requirements." Contractor: State of CA. SILV18. R.M. Technical Assistance Contracts Branch. FIN B-8553. NRC-32-83-684. B3/07/14. ALEXANDER I. Region 5, Office of Director. HAMADA: Q. NRC No Datailed Affiliation Given. 1p. 19785: 345.
- --B307250131 Mod 1, providing CYB3 funding, to "Radiation Monitoring Program Requirements"

  \* California, State of, GUSTAVE, R. P. Division of Contracts. FIN B-8553. NRC-32-83-684. 83/07/14. 1p. 19725: 346.
- 8307250115 Notification of contract execution, Mod 5 to "Studies of Oas Liquid Flow Pattern." Contractor: Univ of Houston.
  SILVIS.R.M. Technical Assistance Contracts Branch. FIN B-6273.
  NRC-04-78-213. 63/07/14. BATSON.W. Office of Nuclear Regulatory Research, Director. ZUBER, N. NRC No Detailed Affiliation Given.
  1p. 19725:343.
- --8307250119 Requests ack of Mod 5.deobligating funds.to "Studies of Gas Liquid Flow Pattern." Signed by univ on 830209. OUSTAVE.R.P. Technical Assistance Contracts Branch. FIN 8-6273. NRC-04-78-213. 83/01/03. SIFUENTES.L. Houston, Univ. of. 1p. 19725:344.
- 8307250143 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor: State of CO. SILVIS.R. M. Technical Assistance Contracts Branch. FIN B-8501. NRC-31-83-668. 83/07/14. MEYERS.D.M. Region 4, Defice of Director, NICHDLAS.J.B. NRC No Detailed Affiliation Given. 1p. 19725: 348.
- --8307250153 Hod 1, providing CY83 funding & changing 8&R number, to "Radiation Monitoring Program Requirements."

  \* Colorado, State of, GUSTAVE,R.P. Division of Contracts. FIN B-8501. NRC-31-83-668. 83/07/14. 1p. 19725:349.
- 8307250165 Notification of contract execution. Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of MD. SILVIS.R. M. Technical Assistance Contracts Branch. FIN B-8454. NRC-30-83-643. 83/07/14. PAPPAS.H. Region 9. Office of Director. GESTMANN.M.J. NRC No Detailed Affiliation Given. 1p. 19725:357.
- --B307250171 Mod 2:correcting B&R number, to "Radiation Monitoring Program Requirements."

  \* Missouri, State of. GUSTAVE.R.P. Division of Contracts. FIN B-8454. NRC-30-83-643. 83/07/14. ip. 19725:358.

- 8307250168 Notification of contract execution. Mod 2 to "Reanalysis of Existing Data From Survey re TMI." Contractor: Natl Inst of Mental Health.
  SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-8621.
  NRC-03-82-130. 83/07/12. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. REGAN. W. H. NRC No Detailed Affiliation Given. ip. 19725: 355. 24X Fiche: 30-289,83/07/12.8307250168.
- --8307250176 Mod 2, extending period of performance to 830430, to "Reanalysis of Existing Data From Survey re TMI." # Health & Human Services, Dept. of. GUSTAVE, R.P. Division of Contracts. FIN 8-8251. NRC-03-82-130. 83/07/12. ip. 19725: 356. 24X Fiche: 50-289, 83/07/12, 8307250168.
- 8307250226 Corrected notification of contract execution. Mod 9 to "Memphis Area Regional Seismic Network." Contractor: Memphis
- "Memphis Area Regional Selsmic Newwork. Contracts Branch. FIN 8-6276. State Univ.
  SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-6276. NRC-04-78-200. 83/05/27. BATSON.W. Office of Nuclear Regulatory Research, Director. MURPHY.A. NRC No Detailed Affiliation Given. 19725:394.
- 8307250241 Notification of contract execution, Mod i to "Radiation Monitoring Program Requirements." Contractor: Dept of Health & Human Svcs.

  SILVIB,R. M. Technical Assistance Contracts Branch. FIN 8-8531. NRC-32-83-692. 83/07/14. ALEXANDER: I. Region 5. Office of Director. HAMADA: O. NRC ~ No Detailed Affiliation Given. 1p. 19721: 065.
- --8307250258 Mpd 1.providing incremental funding to "Radiation Monitoring Program Requirements." \* Health & Human Services, Dept. of, GUSTAVE.R.P. Divis Contracts. FIN 8-8551. NRC-32-83-682. 83/07/14. [p. 15 Division of
- B307250242 Notification of contract execution.Mod 4 to "Expert Consultation & Witness Svc for South Texas Project Hearings." Contractor: W Hubacek. PERLMAN. J. Administrative Contracts Branch. FIN B-8506. NRC-31-82-731. 83/07/14. COLLINS, J. T., CROSSMAN. W. Region 4, Office of Director. 1p. 19721:063. 24% Fiche: 50-498, 83/07/14, 8307250242.
- --B307250250 Mod 4, extending period of performance to B31231 & adding add1 funds to "Expert Consultation & Witness Svc for Bouth Texas Project Hearings."

  HUBACEK, H. G. Hubacek, W. G. SMITH, P. A. Division of Contracts.
  FIN B-B506. NRC-31-82-731. B3/07/14. 1p. 19721:064. 24X
  Fiche: 50-498, 83/07/14, 8307250242.
- 8307250503 Notification of contract execution, Mod i to "FSARs."

  Contractor: Info Handling Svcs.

  SMITH, P. A. Division of Contracts. NRC-10-83-341. 83/07/12.

  BESAN, W. Division of Technical Information & Document Contral.

  SKOCZLAS, J. NRC No Detailed Affiliation Given. Ip. 19720:355.
- --8307250509 Mod 1.increasing total contract amount & designating new project officer, to "FSARs."

  \* Information Handling Services. SMITH.P.A. Division of Contracts. NRC-10-83-341. 83/07/12. ip. 19720:356.
- 8307250508 Notification of contract execution: "Survey of Commercial Non-Nuclear Security Programs," awarded to SAS of Texas,
- Ltd. REBELLO,J.E. Administrative Contracts Branch. NRC-02-83-045. 83/07/12. BROWN.R.S. Division of Safeguards. KUNZE,D. NRC Np Datailed Affiliation Given. 1p. 19720:343.
- --8307250520 Contract: "Burvey of Commercial Non-Nuclear Security Programs: " awarded to 8AS of Texas, Ltd. IBHIMOTO W.Y. SAE of Texas, Ltd. REBELLO, J. E. Administrativ Contracts Branch. NRC-02-83-045. 83/07/12. 8pp. 19720:344. Өрр.
- 8307250540 Notification of contract execution. Mod 4 to "Assessment of Waste Retrieval Alternatives." Contractor: Engineers Intl. Inc.
  FLEENOR, C. Technical Assistance Contracts Branch. FIN B-7327-3.
  NRC-02-82-031. 83/07/14. DAVIS. J. Office of Nuclear Material Safety & Safeguards, Director. CHASE, L. NRC No Detailed Affiliation Given. 1p. 19716:012.
- --B307250550 Mod 4, incorporating microfiche requirements, obligating funds, extending delivery schedule & changing mailing address, to "Assessment of Maste Retrieval Alternatives."

  SINOH. M. M. Engineers International, Inc. GUBTAVE, R.P. Division of Contracts. FIN B-7327-3. NRC-02-82-031. B3/07/14. 4pp.

- B307250623 Notification of contract execution.Mod 2 to "Info Mgt Bys for NRC Operation Ctr." Contractor Phoenix Assoc OILDENHORN.A. Administrative Contracts Branch. FIN B-8709. NRC-05-83-218. B3/07/18. MUIR.A.P. Director's Office, Office of Inspection and Enforcement. HIMES.J. NRC No Detailed Affiliation Oiven. Ip. 19717:161.
- --8307250629 Mod 2. adding add1 training, extending period of performance to 831130 & increasing contract amount, to "Info Mgt Sys for NRC Operation Ctr."
  FEMSTERSTOCK J. Phoenix Associates, Inc. HAGAN, T.F. Technical Assistance Contracts Branch. FIN B-8709. NRC-05-83-218.
  83/07/18. 29pp. 19717:200.
- --B307250640 Notifies of proposal to provide training & hands-on experience for NRC sys manager to perform facility mgt activities & manage info mgt sys. Requests period of performance be extended to B30130.
  FENSTERSTOCK.J. Phoenix Associates, Inc. FIN B-8709. NRC-05-83-218. 83/06/08. GILDENHORN.A. Division of Contracts. 7pp. 19717: 191.
- --8307280647 Clarifies info in 830606 proposal to provide training & hands-on experience for NRC sys manager for info mgt sys.
  Lists three training methods & labor hours by managemen cists three training methods & labor hours by manpower categories. FENSTERBTOCK, J. Phoenix Associates, Inc. FIN B-8709. NRC-05-83-218. 83/06/16. HAGAN, T. Division of Contracts. 2pp. 19717: 198.
- B307250627 Notification of contract execution Mod 1 to "Autoprinter 'F' Microfiche Printer." Contractor: Dybell/Ware & Assoc. INC.
  SMITH,P.A. Administrative Contracts Branch, NRC-10-83-340.
  83/07/18. BESAW,W. Division of Technical Information & Document
  Control. SKUCZLAS,J. NRC - No Datailed Affiliation Given. 1p.
  19718:142.
- --8307290630 Mod I changing place of delivery, to "Autoprinter 'F' Microfiche Printer."

  WARE, J. T. Dybell/Ware & Associates, Inc. SMITH, P. H. Division of Contracts. NRC-10-83-340. 83/07/18. 1p. 19718:143.
- 8307250635 Notification of contract execution, Mod 2 to "Beginning Oregy Shorthand." Contractor: Montgomery County, MD Public Schools. Schööls. BMITH.P.A. Division of Contracts. NRC-10-79-384. 8 SPRINGER.M. Office of Administration. VAN SANTEN.L. Detailed Affiliation Given. 1p. 19716:351. 83/07/14. L. NRC - No
- --8307250645 Mod 2.deobligating total amount remaining under contract.to "Beginning Gregg Shorthand." PASCOE.S. Mortgomery County, MD. SMITH,P A Division of Contracts. NRC-10-79-384. 83/07/14. lp. 19716.332.
- B307250637 Notification of contract execution: "Advise ACRS
  Subcommittee on External Phenomena on Estimates of Frequency
  of Occurrence of Large Floods at SEP Plant Sites," awarded
  to Colorado State Univ.
  HOYLE, A. Administrative Contracts Branch. FIN B-1137.
  NRC-11-83-705. B3/07/18. FRALEY, R.F. ACRS Advisory Committee on
  Reactor Safeguards. SAVIO,R. NRC No Detailed Affiliation Given.
  1p. 19716:353.
- ---B307290643 Contract: "Advise ACRS Subcommittee on External Phenomena Estimates of Frequency of Occurrence of Large Floods at SEP Flant Sites," awarded to Colorado State Univ BHEN.H.W. Colorado State Univ. REBELLO, J. E. Administrative Contracts Branch. FIN II-1597. NRC-11-83+705. 83/07/18. App.
- B307250667 Notification of contract execution: "Integral Sys Test Program Once Through Integral Sys & Multiloop Integral Sys Test Components," awarded to B&H.

  EDGEWORTH,P., WDLLETT,S. Technical Assistance Contracts Branch. FIN B-8909. NRC-04-83-168. B3707708. BATSUN,W. Office of Nuclear Regulatory Research, Director. YOUNG,M. NRC No Detailed Affiliation Given. 1p. 19720:194.
- --8307250473 Contract: "Integral Sys Test Program Once Through Integral Bys & Multiloop Integral Sys Tost Components," awarded to B&W. 日本M. \*\* Babcock を Wilcox Co. \* Technical Assistance Contracts Branch. FIN 8-8909、 NRC-04-83-148。 83/07/08、 47pp. 19720:199.
- 8307250493 Notification of contract execution.Mud 2 to "Electrostatic Copying & Related Svcs." Contractor:Literature Research Co. PERLMAN.J. Administrative Contracts Branch NRC-10-83-318. 83/07/19. DESAW.W.J., BAGGETT.M. Division of Technical Information & Document Control. 1p. 19720:192.

- --8307250687 Mod 2, adding add1 funds, to "Electrostatic Copying & Related Sves " \* Literature Research Corp. SMITH,P.A. Division of Contracts. NRC-10-83-318. 83/07/19. ip. 19720.193
- B307250AB5 Notification of contract execution: "Incident Response Communication Svt." awarded to Boise Interagency Fire Ctr. HAGEY, H. Technical Assistance Contracts Branch. NRC-10-83-342. B3/07/19 CORLEY, J.H. Division of Facilities 5 Operations. MELVILLE, T. COHEN.S. NRC No Detailed Affiliation Given. 1p. 19719:304.
- ~-8307250691 Ltr Contract NRC-10-83-342. "Incident Response Communication Sycs," awarded to Boise Interagency Fire Ctr
  MATIA,M.J. Technical Assistance Contracts Branch. NRC-10-83-342.
  83704/23. ASTLEY,R. Boise, ID. 9p. 19719-305.
- 8307250690 Notification of contract execution: "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Greenfield, MA Community College Library.

  HDPPER,A. Purchasing Section NRC-10-83-365. 83/07/18.

  FELTON,J.M. Division of Rules and Records. SDUDER,J. NRC No Detailed Affiliation Given. 1p. 19720:182.
- --8307250693 Contract: "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Greenfield, MA Community College Library.

  CARTER, C. E. Greenfield, MA. REDELLO, J. E. Division of Contracts.

  NRC-10-83-365
- B307270485 Notification of contract execution.Mod 3 to "LA Offshore Radiological Licenses Burvey." Contractor.State of CA. HOPPER.A. Administrative Contracts Branch. FIN 8-8703. NRC-05-82-252. B2/09/23. BLAMA.J.L. Program Support Branch. KARAGIANNIB.H. NRC - No Detailed Affiliation Given. 1p. 19788:334.
- --8307270488 Mod 3.extending period of performance to 830930.to "LA Offshore Radiological Licensee Survey." \* Louisiana, State of REDELLO,J.E. Division of Contracts. FIN B-8703. NRC-05-82-252. 82/09/23. jp. 19788:335.
- 8307290030 Notification of contract execution.Mod 2 to "Bloaccumulation Factor for P-32 in Edible Fish Tissue." Contractor: GA Tech Research Inst. FLYNN.M.J. Technical Assistance Contracts Branch. FIN B-7478. NRC-04-B1-187. 83704717. BATSON.W. Office of Nuclear Regulatory Research. Director. HAYES.P. NRC - No Detailed Affiliation Given. 1p. 19826:357.
- --8307290038 Mod 2, extending period of performance to 830930, to "Bloaccumulation Factor for P-32 in Edible Fish Tissue." FREESION.D. Georgia Institute of Technology. GUSTAVE, R.F. Technical Assistance Contracts Branch. FIN A-7478. DRC-04-81-187. 83/06/17. 2pp. 19826:358
- B307290156 Notification of contract execution.Mod 7 to "Technical Assistance on Resistance Ductibility of 2-Way Slabs Under Bioarial Tension, Bending & Shear." Contractor: SRI Intl. SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-1156. NBC-03-77-161. B3/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. SIHWEIL.I. NRC No Detailed Affiliation Given. 1p. 19826:360.
- --8307270158 Mod 7, deubligating unliquidated balance remaining as result of fixed fee decrease, to "Technical Assistance on Resistance Ductibility of 2-Way Slabs Under Bioaxial Tension, Bending & Shear."
  FLOYD, S. SRI International. GUSTAVE, R.P. Division of Contracts.
  FIN B-1196. NRC-03-77-161. 83/07/19. 1p. 19826:361.
- B307290161 Notification of grant execution. Mod 3 to "Study of Effects of Orid Spacers & Blockage on Mist Cooling During LOCA Reflood of PWR." Grantee:Research Foundation of State Univ of New York at Stony Brook.
  MCDERHOTT.D. Technical Assistance Contracts Branch FIN G-1001.
  NRC-G-04-B1-014. B3/07/19. BATEON.W. Office of Nuclear Regulatory Research. Director. YOUNG.M. NRC No Detailed Affiliation Given. Ip. 19857:013
- --8307270144 Mod 3, increasing funding to "Study of Effects of Grid Spacers & Blockage on Mist Cooling During LOCA Reflood of PWR." TENBEAU, P. N. New York, State Univ. of, Stony Brook. MORTON, K. V. Technical Assistance Contracts Branch. FIN G-1001. NRC-G-04-B1-014. 63/07/19. 1p. 19857:014.
- B307290321 Notification of contract execution.Mad 2 to "Evaluation of Response of Neutron Dosimeters & Survey Instruments to Moderate CF-252 Source." Contractor:NBS.
  B1LVIS.R M. Technical Assistance Contracts Branch FIN B-10650.
  NRC-01-B0-015. B3/07/20. BATSON.W Office of Nuclear Regulatory Research. Director. DENNIS.N. NRC No Detailed Affiliation Given. Lp. 19898:152.

- --8307290326 Mod 2, deobligating unliquidated balance remaining in contract to "Evaluation of Response of Neutron Dosimeters & Survey Instruments to Moderated Cf-252 Source."

  SHREWE, D. B. Commerce, Dept. of, National Bureau of Standards.

  GUSTAVE, R. B. Division of Contracts. FIN B-10650. NRC-01-80-015, 83/07/20. 1p. 19888:153.
- 8307290357 Notification of contract execution Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs)."
  Contractor: Brooks Hemorial Library.
  TOWNSEND.B. Administrative Contracts Branch. NRC~10-92-421.
  B3/07/21. FELTON.J.M. Division of Rules and Records. SOUDER.J.
  NRC ~ No Detailed Affiliation Given. 1p. 17858:100.
- --8307270366 Mod 1.extending period of performance to 840718 & increasing funding to "Maint & Operation of Local Public Document Rooms (LPDRs)."

  BRYANT.J. Brattleboro, VT. REBELLO.J.E. Division of Contracts.

  NRC-10-82-421. 83/07/21. 1p. 19858:101.
- 8307290420 Corrected notification of contract execution: "BWR Nuclear Engineering Courses," Awarded to OE.

  MCDERMOIT, D. Technical Assistance Contracts Branch. FIN B-8710.

  NRC-05-83-219. 83/05/18. BLAHA.J.L. Director's Office, Office of Inspection and Enforcement. HAVENS, D. H. NRC No Detailed Affiliation Given. 1p. 19857: 355.
- 8307290454 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of WI.
  SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-8453.
  NRC-30-83-647. 83/07/19. PAPPAS.M. Region 3, Office of Director.
  UESTHANN.M.J. NRC No Datailed Affiliation Given. 1p. 19857: 353.
- ---8307290473 Mod 2.changing B&R number in Block 14. "Accounting & Appropriation Data." to 93193002, to "Radiation Monitoring Program Requirements."

  \*\*Wisconsin. State of. GUSTAVE,R.P. Division of Contracts. FIN B-8453. NRC-30-83-647. 83/07/19. 1p. 19857:354.
- 8307270480 Notification of contract execution Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of OH. SILVIS.R.M. Technical Assistance Contracts Branch. FIN 8-8450, NRC-30-83-646. 83/07/17. PAPPASH. Region 3, Office of Director. OESTMAN.M.J. NRC ~ No Detailed Affiliation Given. ip, 19857:345.
- --8307290489 Mod 2.changing B&R number in Block 14,
  "Accounting & Appropriation Data," to 93193002, to "Radiation
  Monitoring & Program Raquirements."
  " Ohio, State of, GUSTAVE.R.P. Division of Contracts. FIN
  B-8450. NRC-30-83-646. 83/07/19, ip. 19857:346.
- 8307270494 Notification of contract execution, Mod 7 to "Licensme Parformance Evaluation." Contractor: Teknekron Research, Inc. SILVIS.R.M. Technical Assistance Contracts Branch. FIN B-1228. NRC-05-78-302. 83/07/14. DLAHA, J.L. Director's Office, Office of Inspection and Enforcement. 1p. 19857:343.
- --B307290505 Mod 7, incorporating final overhead rates, to "Licensee Performance Evaluation."
  HEINRICKS,R.S. Teknekron, Inc. OUSTAVE,R.P. Division of Contracts. FIN B-1228. NRC-05-78-302. 83/07/14. ip. 17857:344
- 8307290509 Notification of contract execution, Mod 29 to "Downcomer Effects Experimental Program." Contractor: CREARE, Inc. WOLLETT. 5. Technical Assistance Contracts Branch. FIN A-4070, NRC-04-75-162. 83/07/12. BATSON, W. Office of Nuclear Regulatory Research. Director. REYES, J. NRC - No Detailed Affiliation Given. 1p. 19857: 226.
- --8307290513 Mod 29.providing add1 funding for within-scope changes, to "Downcomer Effects Experimental Program."

  \* Creare, Inc. GUSTAVE, R.P. Division of Contracts, FIN A-4070, NRC-04-73-142. 83/07/12. Ip. 19857:227.
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8306090382 FOIA request for documents released under FOIA Request 82-515 & NRC response & all encls. KRONZEK.A.L. FOI Services. 2553. 83/01/10. FELTON, J. M. Division of Rules and Records. 1p. 18815:170.
- 83072000i0 Add1 response to FOIA request for repts re inventory differences at NFS.App A documents partially withheld (ref FOIA Exemptions 1:3 & 4). Forwards nonexempt portions of documents. Review of remaining 13 documents in progress. FELTON.J.M. Division of Rules and Records. 83/04/28. BARLETT.D.L. Philadelphia Inquirer. App. 19671:001.

- --8307200014 Forwards detailed rept on current & planned projects designed to improve facility accountability sys & associated inventory difference results. Safeguards info deleted (ref 10CFR2.790).
  TAYLOR, C. W. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). NFE 79-081. 79/10/23. BURNETT, R. F. Division of Safeguards. 15pp. 19671:008.
- --8307200019 Forwards matl balances for inventory period 790512-0618.
  Safeguards info deleted (ref locFR2: 790).
  HENSLEY,K. D. Nuclear Fuel Services: Inc. (subs. of Getty Di) Co.).
  NPE 79-1271. 79/07/04. KENNA,W.B. Region 2, Atlanta, Safeguards
  Branch. 5pp. 19671:023.
- ---B307200025 Forwards math balances for inventory period 790309-0507 for highly enriched U & Pu. Safeguards info deleted (ref 10cFR2.790).

  HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Oetty Dil Co.).

  NFE 79-1268. 77/06/26. KENNA.W.B. Region 2. Atlanta, Safeguards
  Branch. 4pp. 19671:028.
- ---8307200029 Forwards matl balances for inventory period 790109-0309 for highly enriched U & Pu. Safeguards info deleted
  - 10/20029 Forwards mail balances for info deleted (ref 10CFR2.790).

    HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).

    NFE 79-1209. 79/04/09. KENNA.W.D. Region 2, Atlanta, Safeguards Branch. 6pp. 19671:032.
- ---8307200032 Forwards matl balances for inventory period 781110-790109 for highly enriched U & Pu. Safeguards info deleted (ref 10CFR2. 790).

  HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  79702/09. KENNA, H. B. Region 2, Atlanta, Safeguards Branch. 5pp. 19671:038.
- --8307200034 Forwards mat1 balances for inventory period 790618-0814.
  Safeguards info deleted (ref 10CFR2.790).
  HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  NPE 79-133, 79/09/24, KENNA.W.B. Region 2, Atlanta, Safeguards
  Branch. 5pp. 19671:043.
- --8307200039 Forwards matl balances for inventory period 790814-1004.
  Safeguards info deleted (ref 10CFR2.790).
  HENSLEY,K.D. Nuclear Fuel Services: Inc. (subs. of Getty Dil Co.).
  NPE 79-1385. 79/12/03. KENNA,W.B. Region 2. Atlanta, Safeguards
  Branch. 5pp. 19671:048.
- --B307200042 Forwards matl balances for inventory period 791004-1212.
  Safeguards info deleted (ref lOCFR2.790).
  HENBLEY.K.D. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.).
  NFE 80-1018. 80/10731. KENNA.W.B. Region 2. Atlanta, Safeguards
  Branch. Spp. 19671:053.
- --8307200045 Forwards matl balances for inventory period 791212-800325.

  Safeguards info deleted (ref 10CFR2.790).

  HENSLEY, K. D. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.).

  NFE 80-1137. 80/05/08. KENNA, W. B. Region 2, Atlanta, Safeguards

  Branch. 3pp. 19671:061.
- -8307200049 Forwards matl balance sheets for inventory period 791212-800325 inadvertently omitted from correspondence. Safeguards info deleted (ref 100FR2.790).
  HENBLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
  NPE 80-1141. 80705712. KENNA,W.B. Region 2, Atlanta, Safeguards Branch. 3pp. 17471:044.
- --8307200051 Forwards mati balances for high enriched U for physical inventory period 800325-0527. Safeguards info deleted (ref 10CFR2. 790). HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.
  - tref (ourse, 790). HENSLEY, K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). NFE BO-1232. BO/07/09. KENNA, W.B. Region 2. Atlanta, Safeguards Branch. 4pp. 19471:047.
- --8307200053 Forwards matl balances for inventory period May-Aug 1980.
  Safeguards info deleted (ref 10CFR2.790).
  HENSLEY, N.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
  NPE 80-1398. 80/09/24. KENNA, W. B. Region 2, Atlanta, Safeguards
  Branch. 5pp. 19671:071.
- --8307200056 Forwards matl balances for inventory period 800801-0926.

  Safeguards info deleted (ref 10CFR2.790).

  HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.).

  NFE 80-1487. 80/11/10. KENNA,W.B. Region 2, Atlanta, Safuguards
  Branch. Spp. 19671:076.
- -8307200058 Forwards mat) balances for inventory period Sept-Nov 1980, Safeguards info deleted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). NFE 80-1598. BO/12/23. KENNA,W.B. Region 2. Atlanta, Office of the Director (81/03/01). Spp. 19671:081.

- --B307200059 Forwards mat1 balances for B01120-B10121 operating period. Safeguards info deleted (ref 10CFR2.790)
  HENSLEY,K.D. Nuclear Fuel Borvices, Inc. (subs. of Getty Dil Co.).
  NFE 81-1139 81/02/24, LEWIS.R.C. Division of Resident & Reactor Project Inspection 6pp. 19671:084
- -8307200062 Forwards mat) balances for 810121-0325 operating period Safeguards info deloted (ref 10CFR2.790). HENSLEY.K.D. Nuclear Fuel Services: Inc. (subs. of Getty Oi) Co.) NFE 81-1306, 81/05/01, LENIS.R.C. Division of Resident & Reactor Project Inspection. 7pp. 19671:092.
- --B307200069 Forwards mat1 balance for 810527-0729 operating period.
  Revised sheet for 810325-0527 period for Mat1 Balance Areas
  5 & 6 contained in 810709 mat1 balance rept. Safeguards info
  deleted (ref 10CFR2.790).
  HENGLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Cil Co.).
  NFE 81-1665. 81/09/10. LEWIG.R.C. Division of Resident &
  Reactor Project Inspection. 6pp. 19671-098.
- --8307200072 Forwards metl balances for 810325-0527 operating period.
  Safoguerds info deleted (ref 10CFR2.790).
  MENSLEY:N.D. Nuclear Fuel Services: Inc. (subs. of Getty Oil Co.).
  NFE 81-1509. B1/07/07. LEWIS.R.C. Division of Resident &
  Reactor Project Inspection. 7pp. 19671:105.
- --B307200075 Forwards mat1 balances for Jul-Sept 1981 operating period. Safeguards info deleted (ref 10CFR2.790). HENSLEY, K.D. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.). NFE Bi-1837. Bj/11/11. LEHIS.R.C. Division of Resident & Reactor Project Inspection. 7pp. 19671:112.
- --B307200077 Forwards matl balances for Sept-Dec 1981 operating period.

  Safeguards info deleted (ref 10CFR2.790).

  HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).

  NFE 82-1037. B2/01/13. D'REILLY, J. P. Region 2, Atlanta, Office of the Director (81/03/01). 7pp. 19671:119.
- --8307200080 Forwards matl balances for Dec 1981 Feb 1982 operating period. Bafeguards info deleted (ref 10CFR2 790). HENSLEY,K.D. Nuclear Fuel Servicus. Inc. (subs. of Qetty Oil Co.). NFE 02-1142. 82/03/05. D'REILLY,J.P. Region 2. Office of 19671: 125
- --8307200083 Forwards mot1 balances for Feb-Apr 1982 operating period. Safeguards info deleted (ref 10CFR2.790)
  HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.)
  NFE 82-1277, 82705707. G'REILLY, J. P. Region 2. Office of Director. Opp. 19671:132.
- --8307200086 Forwards mat1 balances for Apr-June 1982 operating period Safeguards info deleted (ref 10CFR2.790). HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs of Getty Gil Co.) NFE 82-1418. 82/07/13. O'REILLY, J. P. Region 2, Office of Director. 7pp. 19671:140.
- -8307200071 Forwards Region II proposed license conditions to be imposed on NFS if startup approved & Div of Sys Integration comments. Addl insp effort may result in more recommendations.

  STELLD,V. Office of Inspection & Enforcement, Office of the Director. 79/12/07. BURNETT,R.F. Division of Safeguards. 19671: 147.
- --8307200096 Forwards Region II recommendations for license conditions to be imposed on NFS if startup approved Specific safety recommendations having impart on safeguards sys included Safeguards info deleted. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/21. BURNETT, R. F. Division of Safeguards 11pp. 19671:148
- B307200519 FOIA request for "USAEC Rept Safety Reactor Operating Experience 73-8 (Aug 1973)." PEDRO J. NUS Corp. CD-LIS-91(4. 83/04/19. Division of Rules and Records. 1p. 19472:177.
- 8307266523 Responds to FDIA request for "Safety Reactor Operating Experience 75-8 (Aug 1973). " Forwards document Document also available in PDR FELTON.J.M. Division of Rules and Records. 83/05/06. PEDRO.J. NUS Corp. 1p. 19672:178.
- ---8307200526 RDE 73-8 "Operating Experience Reactor Safety, Steam Generator Problems at PWRs." \* Atomic Energy Commission. 73/08/31 9pp 19672:179
- B307210054 Add1 response to FOIA request for documents re Harry Diamond Lab.from 1965 to present.Forwards requested documents.Info partially withheld (ref FOIA Exemption 6). FELTON.J.M. Division of Rules and Records B3/03/07. SIMPSDN.C. Affiliation Unknown. 2pp. 19783:315.

- 513069B Forwards request from Harry Diamond Labs to amend Byproduct atl License 19-17250-05. ARAS.D.N. Army, Dept. of. 99531 79/04/04. Radioisotopes itensing Branch (Pre 790501). lp. 19784:301.
- 7210063 "Radioactive Hatl Co-60 Sources " Neutron Products, Inc. 83/03/07. 308pp. 19783:319.
- 7210069 Voided Amend 2 to Matl/Byproduct License 19-17250-04 for arry Diamond Labs. Radioisotopes Licensing Branch (Pre 790501). 78/09/29. 1p. 9784:267.
- 7210072 Voided Amend 1 to Matl/Byproduct License 19-17250-04 for arry Diamond Labs. JINN P.R. Radicisotopes Licensing Branch (Pre 790501). 78/06/07. App. 19784:268.
- /210075 Forwards Harry Diamond Labs application for renewal/amend matl Byproduct License 19-17250-04. Amend removes Diamond denace radiation facility & Washington, DC site from list addresses at which byproduct matls used.
  RAGS, D.N. Army, Dept. of. 94530, 78/01/16. Radioisotopes censing Branch (Pre 790301). 2pp. 19785:027.
- 210080 Voided Amend 2 to Matl/Byproduct License 19-17250-05 for mry Diamond Labs. MBS.F.C. Radioisotopes Licensing Branch (Pre 790501). 78/09/29. p. 19785:055.

- 210083 Voided Amend 1 to Matl/Byproduct License 19-17250-05 for rry Dlamend Labs. MBS.F.C. Radioisotopes Licensing Branch (Pre 790901). 78/05/15. p. 19785:056.
- 210092 Voided Matl/Byproduct License 19-17250-05 for Harry Diamond
- bs. SSIN.N.S. Radioisotopes Licensing Branch (Pre 790501). /11/14. 3pp. 19785:057.
- 210102 Voided Amend 3 to Matl/Byproduct License 19-17250-05 for rry Blamond Laba. INN.P.R. Licensing Management Branch. 79/03/10. 3pp. 785:040.
- 210106 IE insp rept for License 19-17250-05 on 781128 & 29. RMAN.P.C. Region I. Philadelphia. Office of the Director. /11/29. 18pp. 19785:063.
- 210111 Ack receipt of application for renewal of Matl/Byproduct cense 19-17250-05. License will not expire until final tion taken by NRC. KEY.J.W. Licensing Management Branch. 12912. 82/11/03. RAS.D. Army, Dept. of Headquarters Materiel Development & Idiness Command. 1p. 19785:081.
- 210113 Forwards application for renewal of Mati/Byproduct License 17280-05.authorizing possession & use of Co-60 in Gamma Habbon facility. HAS.D.N. Army, Dept. of. 12912. 82/10/19. Licensing Lagement Branch. ip. 19783:082.
- :10118 Application for renewal of Mati/Byproduct License 17250-05.authoriring possession & use of Co-60 in Oamma lation facility. KE.A.R. Army, Dept. of. 12912. 82/10/19. 3pp. 19785:083.
- 10304 Voided Amend 1 to Matl/Dyproduct License (9-17250-03 for ry Diamond Labs. BIN.N. Radioisotopes Licensing Branch (Pre 790501). 0380. 08/29. 3pp. 19784:304.
- 10307 Voided Mati/Byproduct License 19-17250-03 for Harry Diamond BIN.N. Radioisotopes Licensing Branch (Pre 790501). 76/11/23. 19784:307.
- 10313 Voided Amend 3 to Matl/Byproduct License 19-17250-01 for y Diamond Labs. NN.P.R. Licensing Management Branch. 80/07/02, 1p. 34:346.
- 10321 Voided Amend 2 to Matl/Egproduct License 19-17250-01 for ry Diamond Labs. 18, F. C. Radioisotopes Licensing Dranch (Pre 790501). 78/09/29, 19784: 347.

- --B307210323 Voided Amend 1 to Matl/Byproduct License 19-17250-01 for Harry Diamond Labs. BASSIN N. Radioisotopes Licensing Branch (Pre 790301). 0380. 77/08/11. 3pp. 19784:351.
- --8307210325 Voided Matl/Byproduct License 19-17250-01 for Harry Diamond Labs. BABSIN N. Radioisotopes Licensing Branch (Pre 790501). 76/11/23. 3pp. 19784:354.
- --8307210330 Insp Repts 70-0378/81-01,30-12435/81-01,30-12436/81-01 & 30-12436/81-01 on 810616. No noncompliance noted.

  Region 1, Philadelphia, Office of the Director. 30-12435/81-01. 81/06/23. 8pp. 19784:358.
- --8307210341 Discusses Insp Repts 70-0378/78-01.30-12438/78-01. 30-12475/78-01.30-12435/78-01.30-12436/78-01 & 30-12840/78-01 on 780208. No noncompliance noted. MCCLINTOCK. R. D. Region 1. Philadelphia. Office of the Director. 79/02/27. RAMBDEN, J. Army. Dept. of. 2pp. 19785:006.
- --8307210347 IE Insp Repts 70-0378/78-02,30-12435/78-02,30-12436/78-02 & 30-12436/78-02 on 781128 & 29. No noncompliance issued. MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 30-12435/78-02. 78/12/07. 7pp. 19785:008.
- --8307210358 IE Insp Repts 70-0378/78-01,30-12435/78-01,30-12436/78-01, 30-12438/78-01,30-12840/78-01 & 30-12475/78-01 on 780208.No noncompliance noted. CONTELLO, C., MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 30-12435/78-01, 78/02/15, 9pp. 19785;015.
- --B307210378 Atk receipt of 770622 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-10736/77-01. 30-12438/77-01. 30-12438/77-01. 30-12438/77-01. NELSON.P.R. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 7130. 77/07/08. LOWERY.A. Army, Dept. of. ip.
- --8307220054 Responds to NRC 770606 ltr re violations noted in Insp Rept 77-01. Corrective actions: entrances to high radiation area will be controlled by securing area except when access required.

  LOWREY, A. Army, Dept. of. DRXDO-ASD, 77/06/22. NELSON, P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 200.
- --8307220063 Discusses IE Insp Repts 30-10736/77-01,30-12438/77-01, 30-12478/77-01,30-12438/77-01 & 30-12436/77-01 & forwards notice of violation.

  NELSON, P. R. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 77/06/06. LOHREY, A. Army, Dept. of, 2pp. 19785.024.
- --8307220073 Notice of violation from insp on 770525-26. Noncompliance noted: failure to control access to all entrances to high radiation area inside calibr facility by employment of any of described methods.

  \* NRC No Detailed Affiliation Given. 77/06/06. 1p. 19785:026.
- --8307220083 IE Insp Repts 30-10736/77-01,30-12438/77-01,30-12475/77-01, 30-12435/77-01 & 30-12436/77-01 on 770525-26. Noncompliance noted: entrance to calibr facility barricaded. COSTELLO, J., MCCLINTOCK,R. D. Region 1, Philadelphia, Office of the Director. 30-12438/77-01, 77/06/01, 9pp. 19785;086.
- --8307220102 Forwards results of closeout survey conducted at Harry Diamond Labs in Washington.DC. Results are for wipe tests taken at pool irradiator, sealed source storage facilities & labs. No containment detected.

  HGCLINTOCK.R.D. Office of Inspection & Enforcement. Office of the Director. 9190. 77/09/19. CDMBS.F. Radioisotopes Licensing Branch (Pre 790501). 23pp. 19785:104.
- -8907220108 Requests additinfore instrument calibr procedures, radiation survey program & personnel exposures per 820312 application for renewal of License 19-17250-01.
  PATTERSON.J. H. Licensing Managament Branch. 12247. 82/10/07.
  Army, Dept. of. 2pp. 19785:127.
- -83072201R5 IE insp rept of License 19-17250-05 for Harry Diamond Labs on 810616. No noncompilance noted. FRIEDMAN. L. F. Region 1, Philadelphia, Office of the Director. 81/06/23. 9pp. 19785:221.
- --8307260087 Diamond Ordnance Radiation Facility decommissioning program final rept.

  HARRIS.J.M. Rockwell International Corp. 80/07/07. 65pp. 19786:087.

- '220044 Add1 response to FOIA request for documents re IE Insp Rept h-358/81-13.Forwards J McCarten file. Portions of file & ictage addressing concerns raised at Commission meeting re-iminal investigation withheld (ref FOIA Exemptions 5 & 7).

  LITON.J.M. Division of Rules and Records. 83/05/18. DEVINE.T., ISENTHAL.J. Government Accountability Project. 2pp. 19713:357.

  IX Fiche: 50-358, 83/05/18, 8307220044.
- 10722006i J McCarten file on facility containing handwritten notes & various documents.

  \* NRC No Detailed Affiliation Given. 83/05/18. 405pp. 19714:001. 24% Fiche: 50-358.83/05/18.8307220044.
- '220071 Appeals denial of FOIA request for documents re iterrogatories & ABLB questions concerning facilities. 'ATT.S.L. Ohio Citizens for Responsible Energy. B3/04/04. RCKS-W.J. Office of the Executive Director for Operations. 3pp. 4592:350.
- '220079 Responds to appeal re denial of FOIA request for documents incerning interrogatories & ASLB questions re facilities. Inwards BJ Youngblood B30112 memo. Documents 2-6 withheld set FOIA Exemption 5).
  IRCKS, H. J. Office of the Executive Director for Operations. 1/05/12. HIATT, S. L. Ohio Citizens for Responsible Energy. 2pp. 1492:342.
- '220098 FDIA request for proposal submitted by Science Applications, ic under Request for Proposal RS-NMB-82-027.
  iNDS:H.S. Ebasco Services, Inc. (subs. of Enserch Corp.).
  1/04/15. FELTON, J. M. Division of Rules and Records. 1p.
  1698: 322.
- '2220106 Responds to FOIA request for proposal submitted by Science plications; Inc. under Request for Proposal R8-NMS-82-027.

  \*\*pressed in the proposal responsal proposal recument also available in PDR.

  \*\*ETON.J.M. Division of Rules and Records. 83/05/06, SANDS.H.S.

  \*\*esco Services, Inc. (subs. of Enserch Corp.). | 19. 19698:323.
- 107220114 Nonproprietary version of "Proposal for Licensing Technical Assistance."

  \* Science Applications, Inc. RS-NMS-82-027. 82/03/09. 67pp. 19498: 374
- '220119 Responds to appeal re denial of FOIA request for transcript 'Commission 830105 meeting re remand proceeding on CRBR. Example 10. The substitution 10. TILK, B. J. Uffice of the Secretary of the Commission. 83/05/19. IEENBERG.E.V. Oalloway & Oreanberg. 6pp. 19692:277. 24X. .che: 50-537,83/05/19,8307220119.
- '220126 Appeals denial of FDIA request for transcript of Commission 10105 meeting re exemption request for CRBR transcript.
  IEENBERG, E. V. Galloway & Greenberg, GREENBERG, E. V. Natural sources Defense Council. GREENBERG, E. V. Sierra Club. 83/03/21.
  ##fice of the Secretary of the Commission. 8pp. 17692: 283. 24X che: 50-537, 83/03/21, 8307220126.
- '250020 Add1 response to FOIA request for R2 categories of scuments. Forwards App A & B documents. Portions of App B scuments withheld (ref FOIA Exemptions 7 & 3).

  LITON.J.M. Division of Rules and Records. 83/05/05. SHOLLY, S. C. ion of Concerned Scientists. 4pp. 19725: 108. 24X .che: 50-000, 83/05/05, 8307250020.
- 108030682 Forwards rept on chronology of 820428 attempted sabotage. No individuals identified as being involved. Labor problems probably caused incidents.

  DIRCKS.W.J. Office of the Executive Director for Operations.
  82/06/08. PALLADIND.N.J. Commissioners. 73pp. 19725:223. 24X Fiche: 50-272,83/05/05,8307250020.
- 1072500R5 Sequence of events re mispositioned high-head safety injection common suction valve.

  \* Dequence Light Co. 81/06/05. 3pp. 19725:116. 24X Fiche: 50-000.83/05/05.8307250020.
- M07250027 House Resolution B2 directing House of Representatives Committee in Mines & Energy Mgt to conduct investigation into incidents that allegedly occurred at facility.

  \* Pennsylvania. Commonwealth of. B1/04/15. 1p. 19725:119. 24X Fiche: 50-000, 83/05/05, 8307250020.
- NOT250033 Notifies of Bill2 meeting in Harrisburg,PA to hear testimony re facility incident.Committee will attempt to limit subj matter to nuclear plant security requirements. TAYLOR,F.R. Pennsylvania, Commonwealth of. Bi/10/21.
  DIRCKS,W.J. Office of the Executive Director for Operations. 2pp. 19725:120. 24X Fiche: 50-000, 83/05/05, 8307250020.

- --B30725003B Requests that specific followup actions be taken re-current situation at facility. Actions include reviewing emergency notification procedure & listing plant sys that should be checked in future instances of suspected sabutage.

  DIRCKS.M.J. Office of the Executive Director for Operations.

  B2/05/04. HAYNES.R.C. Region 1. Office of Director. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. DEVIONO, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 19725-122. 24X Fiche: 50-000, B3/05/05, B307250020.
- --8307250044 Forwards FBI 820428,0502 % 05 teletypes.Ofc of Administration should take corrective action re delay in teletype distribution.

  CUMMINGS.J.J. Defice of Inspector & Auditor 82/05/06. PALLABING.N.J. Commissioners. 3pp. 19725-123. 24X Fiche: 50-000,83/05/05,8307250020.
- ---8307250049 Forwards info re util response to 810606 possible act of sabotage per PA House of Representatives Mines & Energy Mgt Committee Resolution 82 conveyed in 811021 & 1104 itms. DIRCKS,N.J. Office of the Executive Director for Operations. 81/12/10. TAYLOR.F.R. Pennsylvania. Commonwealth of.. 29p. 19725:126. 24X Fiche: 50-000, 83/05/05, 8307250020
- --8307250054 "Special Rept to PA House of Representatives Response to Apparent Act of Sabotage." \* NRC - No Detailed Affiliation Given. 83/05/05. App. 19725:134. 24X Fiche: 50-000, 83/05/05, 8307250020
- --B307250060 IE Investigation Rept 50-334/B1-16 on 810606-18, 30, 0701, 02, 09 & 10. Noncompliance noted: failure to maintain operable high pressure ECCS during power operation & failure to properly administer approved operator training program. DEVLIN. J. W., IECKMAN, D. A., REKITO, W. A., Region 1, Philadelphia, Office of the Director, B1/12/07. 24pp. 19725-137 24X Fiche: 50-000, 83/05/05, 8307250020.
- --B307250067 Requests summary rept re event including followup actions by licensee, NRC & other govt agencies by B20510. Rept should also indicate corrective actions for any problems encountered during response.

  PALLADINO, N. J. Commissioners. B2/04/30 DIRCKS, W. J. Office of the Executive Director for Ogerations. ip. 19725: 219. 24X Fiche: 50-000, B3/05/05, B307250020.
- 8307250527 FOIA request for all correspondence between Nuclear Assurance Corp. NRC & DOT since June 1982, documents re Chalk River Lab & proposed &/or approved routes for shipment of irradiated fuel. PUNTENNEY, J. Safe Energy Coalition. 83/02/14. Office of Administration. 1p. 19716:017.
- 8307250531 Add1 response to FOIA request for all correspondence between Nuclear Assurance Corp.NRC & DOT since June 1982 & documents or Chalk River Lab.Forwards App A documents. Documents 21~27 withheld (ref FOIA Exemption 3).
  FELTON.J.M. Division of Rules and Records 83/05/11. PUNTENNEY, J. Bafe Energy Coalition. 3pp. 19716:018.
- --8307250533 "Spent Fuel Route Survey,Port of Entry Champlain,NY to Savannah River,BC." Bafeguards info deleted. \* Office of Nuclear Material Safety & Safeguards,Director. 82/10/06. 21pp. 19716.031.
- --B30728083B Notifies that spent fuel shipments from AECL facility at Chaik River to DOE facility will be made under Export License ISNM-B1005, Amends 1 & 2. Schedule & port of entry encl. Safeguards info deleted (ref 10CFR73 21).

  DANESE, F. L. Nuclear Assurance Corp. FLD/B3/145/EIS. B2/09/29. GODY, A. Region 1, Office of Director. 2pg. 19716: 053.
- 8307250542 Approves 820914 request for revised route for transport of spent reactor foel. 8HERR,T.S. Material Transfer Safeguards Licensing Branch. 82/10/06. DANESE:F. L. Nuclear Assurance Corp. 2pp. 19716:055.
- 8307280546 FDIA request for three categories of documents re NRC consultation w/EPA re promulgation of stds for remedial actions at inactive U processing sites.

  DVNN.K. Beers & Dickson. 83/03/22 Office of Administration.

  3pp. 19720:242.
- B307250551 Partial response to F01A request for three categories of documents re NRC consultation w/EPA re promulgation of stds for remedial actions at inactive U processing sites. Forwards documents listed in App A. FELTON, J. M. Office of Administration. B3/05/06 DUNN, X. Beers & Dickson. 2pp. 19720; 245.

- ~-B307250558 Comments on EPA proposed groundwater protection strategy.

  Info focuses on possible interactions between proposed
  groundwater protection & regulation of radwaste disposal
  (high level, low level or U recovery) & in situ minum.

  MARTIN.J.B. Division of Waste Management. B1/02/18. SMITH.R.O.
  Office of Standards Development, Director. 2pp. 19720:247.
- --8307250564 Responds to request for review & comments on proposed disposal & cleanup stds for UMTRAP. Concurs w/disposal stds, release limit & stds for groundwater protection. MARTIN J B. Division of Waste Management. B1/07/01.
  ROSENBAUM, D. M. Environmental Protection Agency. 4pp. 19720: 249.
- --8307250572 Summary of 811221 meeting w/EPA in Washington.DC re promulgation of EPA stds concerning mill tailings & EPA comments on DES re decommissioning Edgemont milling site. 5CARANO.R.A. Uranium Recovery Licensing Branch. 82/01/13. MARTIN.J.B. Division of Waste Management. 3pp. 19720:266.
- ---B307250574 Discusses status of EPA std development under U Mill Tailings Control Act re revised stds for inactive U mill tailings sites. HAMILL.K Uranium Recovery Licensing Branch. 82/01/25. SCARANG.R. Uranium Recovery Licensing Branch. 2pp. 19720:269.
- --8307250579 Forwards excerpts from transcript of NRC 820222 hearings before Senate Committee on Environ & Public Horks re EPA radiological std setting activities. W/o encl. DAVIS.J.G. Office of Nuclear Material Safety & Safeguards. Director. 82/03/04. BENNEIT, K. Environmental Protection Agency. 2pp. 19720:271.
- --8307250585 Notifies that encl memo will be used as concurrence copy for files.closing out impact of EPA stds on NRC rules.Records show that memo ticketed as NASS Bill50 closed out on 82010å. BUNTNG.J.O. Licensing Process & Integration Branch. 82/03/10. BRDWN.R.S. Program Support Branch. 21pp. 19720:274.
- --8307250593 Forwards summaries from Div of Waste Mgt meetings w/DDE & EPA re high level waste form & packaging, repository siting & design & performance assessment.

  MARTIN.J.B. Division of Waste Management. 82/07/14. DAVIS.J.Q. Office of Nuclear Material Safety & Safeguards, Director. 18pp. 19720-298.
- --B307250601 Notifies that meetings will be scheduled in Jul w/DDE & EPA officials.Requests summaries re areas of interface problems & issues & actions needed from EPA priorities & action schedules by 920709.

  DAVIS.J.G. NRC No Detailed Affiliation Given. 82/07/01.

  BURNETT.R.F., CUNNINGHAM.R.E., MARTIN,J.B. NRC No Detailed Affiliation Given. 1p. 19720:316.
- --8307250606 Forwards EPA proposed final std on inactive mill tailings sites & previous NRC comments on draft std. W/o encl. SCARANO.R.A. Uranium Recovery Licensing Branch. 82/07/16. DAVIS.J. Q. Office of Nuclear Material Safety & Safeguards.Director. 1p. 19720:317.
- --B307250613 Responds to 821022 request for comments on second draft of "Potential Health & Environ Hazards of U Mine Wastes." Rept should include discussion of existing regulatory authorities & environ controls over mine wastes.

  MARTIN.J.B. Office of Nuclear Material Safety & Safegoards, Director. B2/11/19. SUDBLOM.G.L. Environmental Protection Agency. 1p. 19720:318.
- --8307250419 Bubmits suggestions for development of rule to establish criteria & schedules associated w/environ qualification of Class IE electrical equipment (SECY 81-486) PALLADING.N. Commissioners. CDMNP-81-4. 81/09/30. GILINEKY.V., BRADFORD.J. AHEARNE, J. Commissioners. 1p. 19720:319.
- B307260001 FDIA request for all records re NRC insps & evaluations of util const activities in soils work leading to Spessard memo.

  GARDE, B.P... Government Accountability Project. B3/03/22, TOMS, N. Office of Administration. 1p. 19787: 321. 24% Fiche: 30-329, B3/03/22, B307260001.
- 8307260002 Responds to FOIA request for records re IE insps & evaluations of util const activities in soils work leading to Spessard memo. Forwards documents listed in App A. FELTON.J.M. Division of Rules and Records. 83/05/18. GARDE, B. Gavernment Accountability Project. 2pp. 19787: 323 24X Fichs: 50-329, 83/05/18, 8307260002.
- --8307260004 "Insp Evaluation," re IE. Insp Repts 50-329/82-11 & 50-330/82-11 on 820519-0702. LANDGMAN, R. B. NRC - No Detailed Affiliation Given. B2/09/0; 2pp. 19787:325. 24X Fichs:50-329,83/05/18.8307260002.

- --8307260006 "Insp Evaluation." re IE Insp Repts 50-329/82-17 & 50-330/82-17 on 820809-13.
  RING.M., ROBINSON.D. NRC ~ No Detailed Affiliation Given. 82/08/20. 2pp. 19787:327. 24X Fiche: 50-329,83/05/18,8307260002.
- --8307260009 "Insp Evaluation," re IE Insp Repts 50-329/82-19 & 50-330/82-19 on 820920-24. ROBINSON.D., JACK.J.N. NRC - No Detailed Affiliation Given. 82/09/27. 2pp. 19787: 329. 24X Fiche: 50-329, 83/05/18, 8307260002.
- ---8307260011 Notifies of 820330 mesting w/util re underpinning activity. Principle points to be discussed include practicality of requirements & transition between various phases of project. WILLIAMS, C. , LITTLE, H. S. NRC No Detailed Affiliation Given. 82/03/24. NORELIUS, C.E. Region 3, Office of Director. 5pp. 19787: 331. 24X Fiche: 50-329, 83/05/18, 8307260002.
- --8307260014 Requests list of actions for licensee to correct deficiencies noted in underpinning, piping & electrical areas. Info needed for meeting preparation.
  NORELIUS.C.E. Region 3, Office of Director. 82/05/07.
  LITTLE, W.S. Region 3, Office of Director. 1p. 19787; 336. 24X Fiche: 50-327, 83/05/18, 8307260002.
- --8307260019 Discusses participation in 820521 ACRS briefing on facility QA program. Statement should be drafted by 820519.
  NORELIUG.C.E. Region 3, Office of Director. 82/05/14.
  LITTLE,W.S. NRC No Detailed Affiliation Given. lp. 19787: 337.
  24X Fiche: 50-329,83/05/18,8307260002.
- --8307260021 Forwards comments on ASLB orders & applicant response reconstractivities.

  NORELIUS, C. E. Division of Engineering. 82/05/18. ADENBAM.E. Licensing Branch 4. 4pp. 19787:338. 24X Fiche: 30-329,83/05/18,8307260002.
- 8307260104 FDIA request for documents re recent experiences w/illegal export of sensitive items through use of bogus destinations & invoices & Commissioner Gilinsky travel schedules & itineraries & speeches during travels for past 2 yrs.

  KAMENARYP.D. Washington Legal Foundation. B3/04/01. Division of Rules and Records. 2pp. 19744:098.
- 8307260111 Responds to FOIA request for documents re recent experiences w/illegal export of sensitive items through use of bogus invoices & Commissioner Gilinsky travel schedules & itineraries for past 2 yrs. Forwards App A documents. FELTON. J. M. Division of Rules and Records. 83/05/11. KAMENAR, P. D. Washington Legal Foundation. 4pp. 19744:100.
- --8210290407 Speech entitled, "Streamlining Nuclear Regulation," presented at AIF 820524 meeting in Kansas City, MD. OILINSKY, V. Commissioners. 82/05/24. 8pp. 19744:177,
- --8307260123 Speech entitled "First Step in Solving Nuclear Waste Problem: Providing Adequate Spent Fuel Storage," presented at Waste Mgt '83 Symposium in Tucson. AZ on 830228. QILINSKY, V. Commissioners, 83/02/28. 13pp. 19744: 104.
- ---8307260130 Speech entitled "Nuclear Safety:Dealing W/Conflicts of Interest," presented at East-West Ctr.Honolulu.HI on 830121. GILINBKY.V. Commissioners. 83/01/21. 17pp. 19744:117.
- --8307260149 Discusses four repts re recent attempts to circumvent US export control laws. Supporting documentation enci. QILINSKY, V. Commissioners. 83/04/13. RUDD.E. House of Rep. 24pp. 19744: 153.
- --B307260i61 Forwards New York Times article entitled "For Brazil, Embarrassing Tale of Intrigue." SCHECTER.H. Office of International Programs, Director. 81/06/24. GOLDBHITH.R. Commissioners. 2pp. 19744:185.
- --8307260167 Forwards Commissioner Gilinsky separate views re proposed amend to 10CFR110 (SECY-81-633/SECY-82-35)re nuclear exports for FR publication. Related info encl. MANNING.W. J. Commissioners. 83/03/21. CHILK,S. J. Office of the Secretary of the Commission. 27pp. 19744:187.
- 8307260599 FOIA request for SECY 82-464.
  BUCKLES.R. NUS Corp. 83/04/06. Division of Rules and Records.
  1p. 19788:044.
- B307260600 Responds to FOIA request for SECY 82-464 Forwards document. Info partially withheld (ref FOIA Exemption 5). FELTON, J.M. Division of Rules and Records. 83/05/18. BUCKLES, R. NUS Corp. 2pp. 19788:045.

- --8307260601 SECY-82-464
  Discusses litigation rept for wk of 821115 Info deleted SLAGOIE.E.L. Office of the General Counsel. 82/11/22. 2pp.
- 8307290442 Responds to FOIA request for SECYs 82-306 & 82-499. Forwards SECY 82-306. Documents also available in PDR. Ltr dtd 830428 responded to SECY 82-499. FELTON, J. M. Division of Rules and Records. 83/05/18. DIBBLE, C. B. LeBoeuf, Lamb, Leiby & MacRae. 1p. 19858: 358.
- --B208040324 SECY-82-306
  Recommends that Commission reconsider decision to remove
  Apps B through H from IOCFR140.
  DIRCKS.W.J. Office of the Executive Director for Operations.
  B2/07/20. 4pp. 19858:360.
- 8307290452 Responds to FOIA request for original license application submitted by Gamma Corp & corresponding licenses issued by NRC. NRC has no documents responsive to request. Contact w/DOE recommended.
  FELTON. J. M. Division of Rules and Records. 83/05/19. SULLIVAN. J. W. Affiliation Unknown. 1p. 19858: 293.
- 8307290457 FOIA request for original Gamma Corp research reactor license & corresponding licenses issued by NRC. SULLIVAN.J.W. Affiliation Unknown. 83/04/25. FELTON.J.M. Division of Rules and Records. 1p. 19858:294.
- 8307290461 FOIA request for NRC 810227 1tr to GE Date of 1tr referenced in NUREG-0390, Vol 6. PEDRO, J. NUS Corp. CD-LIS-9130. 83/04/26. Division of Rules and Records. 1p. 17859: 042.
- 8307290467 Responds to FDIA request for NRC 810227 ltr to GE. Forwards document. Document also available in PDR. FELTON, J. M. Division of Rules and Records. 83/05/18. PEDRD, J. NUS Corp. 1p. 19859:043.
- --8103300508 Forwards summary of evaluation of GE topical rept NEDG-21985 "Functional Capability Criteria for Essential Mark II Piping." Rept acceptable.
  TEDEBGO.R.L. Assistant Director for Licensing. 81/02/27.
  SHERWOOD, G. G. General Electric Co. 2ρp. 19839: 044.
- --8307290478 Topical rept evaluation of NEDC-21985, "Functional Capability Criteria for Essential Mark II Piping." Highest loading conditions re various ASME Code svc stress levels should be specified in functional capability assessment.

  \* Mechanical Engineering Branch. 80/05/31, 14pp. 19859:046.

# GEN TEC 15 GENERIC TECHNICAL ISSUES

- B307010044 Forwards BAW-1791, "B&W Owners Group Probabilistic Evaluation of Pressurized Thermal Shock: Phase I Rept."
  Findings of PRA study & related evaluations documented. NRC proposed screening limits valid & conservative.
  GOBBURN: T. H. Babcock & Hilcox Operating Plants Cuners Group.
  GOBBURN: T. H. Sacramento Municipal Utility District. 83/06/30 BCHROEDER; F. Division of Safety Technology. 1p. 19173:108.
- --8307010051 BAW-1791
  "B&W Duners Group Probabilistic Evaluation of Pressurised Thermal Shock: Phase I Rept." W/ten oversize drawings. Apenture cards are available in PDR.
  \* Babcock & Wilcox Co. 77-1142462-00. 83/06/30. 172pp. 19173:110.
- 8307050016 Informs that intake structure crane fully complies w/guideline 7 of NUREG-0612, "Crane Design," based on Franklin Research Ctr & Dresser Industries studies. UKRIG, R.E. Florida Power & Light Co. L-83-374. 83/06/28. CLARK, R.A. Operating Reactors Branch 3. 1p. 19193:085. 24X Fiche: 50-335,83/06/28,8307050016.
- 8307050333 Forwards draft technical evaluation rept. "Control of Heavy Loads at Nuclear Power Plants, LaBalle Units 1 & 2 (Phase II)." based on response to Bection 5.1 of NUREG-0612. SCHMENCER, A. Licensing Branch 2. 83/06/21. FARRAR, D. L. Commonwealth Edison Co. 2pp. 19262:007. 24X Fiche: 50-373, 83/06/21, 8307050333.
- B307070103 Submits supporting info on lifting devices to be used in transporting activated reactor components to licensed disposal site. Design of proposed lifting device adequate to withstand dynamic loads imposed by overhead handling sys. BINCLAIR.J.B. Vermont Yankee Nuclear Power Corp. EVYB3-67. B3/07/05. VASSALLO.D.B. Operating Reactors Branch 2. 2pp. 19294:115. 24X Fiche: 50-271.83/07/05.8307070103.

- 830707017B Submits partial response to 821203 request re Comeric Item 8-24 & NUREO-0737, Item II. E. 4 2 for proposed Tech Specs incorporating seal leakage test of containment younge & vent valves Rev to Itemse will be submitted by 830031 CROUSE.R.P. Toledo Edison Co. 963. 83706/30. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19269-335 24% Fiche: 30-346,83/06/30,8307070178
- 8307070232 Forwards synopsis of issues associated w/NUREG-0612 recontrol of heavy loads as discussed in 830617 telcon.
  Responses to open issues must be provided within 30 days of litr date.

  VARGA: S. A. Operating Reactors Branch 1. 83/06/21 | O[ESLER, C. N. Misconstin Public Service Corp. 13pp. 19362:227. 24X Fiche: 50-305, 83/06/21, 8307070232.
- 8307080008 Forwards Rev 3 to polar crane functional description for use in evaluating refurbishment of polar crane.

  KANDA, B. K. General Public Utilities GPU Service Corp.

  4410-83-L-0120 B3/06/30 BARBETI.L.H. TMI Program Office. 2pp.
  19351:244. 24X Fiche:50-320,83/06/30,8307080008
- 8307080646 Forwards "Control of Heavy Loads, St Lucie Plant, Unit 2 (Phase I), "technical evaluation rept KNIOHTON, G. W. Licensing Branch 3. TAC 47015 83/06/17. UHRIO, R. E. Florida Power & Light Co. 2pp. 19364:180 24X Fiche: 50-389, 83/06/17, 8307080666.
- 8307110093 Responds to B30931 ltr transmitting draft technical avaluation rept re control of heavy loads. Comparison of Mestinghouse spec for manipulator cranes w/ANSI 830-2 released devices meet both specs.

  TUCKER. H. B. Duke Power Co. 83/06/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19375:245. 24X Fiche: 50-413.83/06/28.8307110093.
- 8307110270 Forwards MCAP-10230: "Evaluation of Acceptability of Reactor Vessel Head Lift Rig:Reactor Vessel Internals Lift Rig:Load Cell ½ Load Cell Linkage to Requirements of NUREG-0612" & responses to NRC recommendations.
  ALEXICH.M.P. Indiana & Michigan Electric Co. AEP:NRC 05140.
  83/07/09. DENTON.H.R. Office of Nuclear Reactor Regulation.
  Director. 2pp. 19378:332. 24X Fiche:50-315,83/07/05.8307110270.
- --8307110295 WCAP-10230

  "Evaluation of Acceptability of Reactor Vessel Head Lift
  Rig.Reactor Vessel Internals Lift Rig.Load Cell & Load Cell
  Linkage to Requirements of NUREG-0612."

  9ANDNER: H. H. MARSHALL, J. R. Westinghouse Electric Corp.
  AEP: NRC: 05148, 83/04/30. 150pp. 19378:334. 24x
  Fiche: 50-315,83/07/05,8307110290.
- 8307120146 Forwards synopsis of issues associated w/NUREO-0612, "Control of Heavy Loads," to resolve open Items & draft final technical evaluation rept. Response should be provided within 60 days.

  VASSALLO,D.B. Operating Reactors Branch 2. 83/06/23 LIU.E. Iowa Electric Light & Power Co. 13pp. 19435-134. 24X

  Fiche: 50-331,83/06/23,8307120146
- --8307120149 TER-C5506-352 DRFT

  "Control of Heavy Loads (C-10), Duane Arnold Energy Ctr," draft technical evaluation rept.

  VOSBURY, F. W. Franklin Institute/Franklin Research Center.

  NRC-03-81-130. TAC 07988. 83/04/08 CLEMENSON, F. NRC No. Detailed Affiliation Given. 32pp. 19435:147. 24X

  Fiche: 50-331, 83/06/23, 8307120146.
- B307120469 Requests meeting to discuss future submittal of Tech Specs & supporting safety analysis to resolve pressurized thermal shock issues for Cyclo 9 licensing Update meeting requested first wk in Aug.
  UHRIGAR E. Florida Power & Light Co. L-83-373. 83/07/06.
  EISENHUT, D. G. Division of Licensing. Jap. 19424 191. 24X
  Fiche: 30-250, 83/07/06, 8307120469.
- 830713024B Discusses evaluation of lift rigs for reactor coolant pump motors & equipment hatches per NUREG-0612. Evaluation complete. Rigs will be constructed by Westinghouse.

  BABKIN, K. P. Southern California Edison Co. 83/07/06.

  CRUTCHF[EL]D, D. Operating Reactors Branch 5. 1p 19474: 361. 24X Fiche: 50-206.83/07/06.830713024B.
- G307130303 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re Phase I of response to NUREG-0612. "Control of Heavy Loads at Nuclear Plants." Phase I acceptable.
  CRUTCHFIELD.D. Operating Reactors Branch 5. L.305-83-07-016. 83/07/11. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19505:001. 24X Fiche: 50-237.83/07/11.8307130303.

- --8307130202 Safety evaluation accepting util Phase I response to NUREG-0512. "Control of Meavy Loads at Nuclear Plants."
  - 307130303 Sarety evaluation of teath to the teath of the
- --8305100146 TER-C5506-350/351 Ri
  "Control of Heavy Loads Comm Ed Dresden Nuclear Power
  Station Units 2 & 3." revised technical evaluation rept.
  BOMBERGER.C Franklin Institute/Franklin Research Center.
  TRC-03-81-130 TAC 46736. 83/06/08. SINGH.A. NRC No Detailed
  Affiliation Given 33pp 66826:099. 24X Fiche: 50-237,83/07/11,
- 8307140320 Notification of 83070A meeting w/Steam Generator Duners Group in Betnesda. MD to discuss findings from NRC generic steam generator program for resolution of Unresolved Safety Issues A-3. A-4 & A-5. IFPOLITO. I A Operating Reactors Assessment Branch. 83/07/01. MIRAGLIA.F J Assistant Director for Safety Assessment. 1p. 19809-132
- G3071501B2 Requests response to three unresolved items in Section 3.1 of NUREG-0512. "Control of Heavy Loads at Nuclear Power Plants " TER-C5505-377 b guidelines for NUREG-0512 of NUREG-0512. "Control of Heavy Loads at Nuclear Fower Plants " TER-05506-377 b guidelines for NUREG-0612 compliance forwarded. CRUTCHFIELD.D Operating Reactors Branch 5. L505-83-07-028. 83/07/14 VANCHALLE.D.J. Consumers Power Co. 3pp. 19531: 24X Fiche 50-255.83/07/14.8307150182 19531:013.
- GBO715037: Forwards for review & comments. "Control of Heavy Loads (C-10).Point Beach Units 1 & 2." updated draft technical evaluation rept CLARA, R.A. Operating Reactors Branch 3 83/06/30. FAY.C.W. Histonish Electric Power Co. 2pp. 19540-103 24% Fiche 50-266.63/06/30.8307150395
- --8397070582 TER-C5506-382/383 ER
  "Control of Heavy Loads (C-10) Point Beach Nuclear Plants
  Units i & D." draft final technical evaluation rept.
  BDM9ER3ER.C Frantin Institute/Franklin Research Center.
  NRC-03-31-130 TAC 08074 83/06/17 SINOH, A NRC No Details
  Affiliation Given 56pp 19540-105. 24X Fiche, 50-266, 83/06/30, 8307150375 No Detailed
- 8007180025 Forwards SER re NUREG-0612. "Control of Heavy Loads" & technical evaluation rept Phase I acceptable. VASSALLO.0 B Operating Reactors Branch 2 83/05/27. FARRAR.D.L. Consolve-lith Edison Co. 2pp 19567.301 24% Fiche: 50-254,83/06/27,8307160025
- --8307180030 Safety evaluation of util 801222 responses to NUREG-0512, "Control of Heavy Loads " Phase I acceptable
   NRC NO Detailed Affiliation Given 83/05/27, 2pp. 19567 303 24% Fichs: 50-254.83/05/27.8307180025
- --8306060275 TER-C5506-386/387
  TControl of Heavy Loads (C-10). Quad Cities Station Units 1 & 2." technical evaluation rept
  83M8EMSER,C. SARGENT.I H. Franklin Institute/Franklin Research
  Center NRC-03-81-130 TAC 08077 83706/01 SINOM.A. CHAN.T.
  NRC = No Detailed Affiliation Given 31pp 19367-305. 24X
  Fithe 50-254.83706/27.8307180026
- 8307180100 Submits final resolution of open items identified in draft technical evaluation rept dtd 830222 demanstrating conformance to NVMES-0612. "Control of Heavy Loads at Nuclear Fouer Plants." Phase 1 STEMART W. L. Virginia Electric & Power Co. 323 83/07/12. OENTON. If R. Office of Nuclear Reactor Regulation. Director. 4pp. 19557 005 24x Fiche 50-338.83/07/12.8307180100
- B307190000 Forwards HR Denton B30711 memo resolving JH Conran differing prof opinion ne potential safety significance of lack of progress in resolving Unresolved Bafety Issue A-17. "Sys interaction" BAWSIN.6 J. Hearing Branch 3. ISSUANCES OL. B3/07/14. BRENNER.L. MORRIS.9 A. CAFPENTER.J. L. Atonic Safety and Licensing Board Panel. 1192 12035 035 24% Fiche 50-322.B3/07/14.8307190002.
- 83071900in Forwards responses to Franklin Research Ctr 820212 draft yept on handling of heavy loads & response to 801222 request for add info re lifting devices Mods & procedure applicatements will be completed by 841231 HARRIWGTON: W D. Boston Editon Co. 60-181. 82/07/13. EISENHUT, D. Division of Licensing 49pp. 19633-084 24X Fiche. 50-293.
- 8307190127 Decoms nound of interrogatories me pressurized thermal shout Related correspondence L6468 M Lewis: M 83/07/15 Office of the Esecutive Legal Director Dep 19635 051 24x Fiche 50-352,83/07/15,8307190127.

- B307190345 Comments on ACRS ECCS Subcommittee B30524-25 meetings. Significant progress made in pressurized thermal shock (PTB) issue.Computer input decks partially completed for 18 plants subj to PTS analysis.

  ZUDANS.Z. Franklin Institute/Franklin Research Center. ZUDANS.Z. ACRS Advisory Committee on Reactor Safeguards. B3/05/31.

  BDEHNERT.P.A. ACRS Advisory Committee on Reactor Safeguards. 4pp.
- B307200026 Comments on ACRB Hetal Components Subcommittee B30615 meeting Plant operators should be prepared to cope w/potential pressurized thermal shock or other unexpected conditions. Diagnostic training should be provided.
  BINFORD.F.T. Dak Ridge National Laboratory. BINFORD.F.T. ACR Advisory Committee on Reactor Safeguards. B3/06/16. IONE.E.G. Advisory Committee on Reactor Bafeguards. 3pp. 19670:354. ACRE :
- 8307200043 Comments on Pressurized Thermal Shock (PTS) Task Action Plan A-49. Guidance to plant mgt & improvement in instrumentation & control sys offer best method to prevent PTS.
  BINFORD, F. T. Oak Ridge National Laboratory. BINFORD, F. T. ACRS Advisory Committee on Reactor Safeguards. 83/05/31. IGNE, E. G. ACRB Advisory Committee on Reactor Safeguards. 4pp. 19670:338.
- 8307200073 Responds to Generic Ltr 8i-07 dtd 810701 re control of heavy loads. Original submittal did not distinguish "load" from "heavy load." Page 4 of Attachment 1 to 810701 submittal should be replaced w/encl. W/o encl. BDRDINE.T. C. Consumers Power Co. GL-81-07. 83/07/15. CRUTCHFIELD.D. Deperating Reactors Branch 5. 1p. 19447:115. 24X Fiche: 50-155. 83/07/15. 8307200073.
- 8307200142 Forwards response to Phase II of NURE9-0612, "Control of Heavy Loads at Nuclear Power Plants." Items discussed include step plugs, vessel cavity plugs, dryer separator pool step plugs. Fueling slot plugs & auxiliary hoist.

  SORENSEN, O. C. Washington Public Power Supply System. GO2-63-614.
  83/07/13. SCHMENCER.A. Licensing Branch 2. 9pp. 19651:011. 24 Fiche: 50-397.83/07/13.8307200142.
- 8307200179 Comments on listed documents on Unresolved Safety Issue A-1, "Water Hammer," including for comment issues of NUREG-0927 & NUREG-0993 re evaluation of water hammer occurrence & value impact analysis of water hammer, respectively, BRADBURY, R. B. Stone & Webster Engineering Corp. B3/07/15, KNIEL, K. Division of Bafety Technology, 3pp. 19651:166.
- 8307200344 Summary of 830601 meeting w/licensee & C-E in Bethesda, MD re resolution of Unresolved Safety Issue A-47, "Safety Implications of Control Sys." BZUKIEWHICZ, A. Generic Issues Branch. 83/06/14. KNIEL, K. Generic Issues Branch. 4pp. 19670:007. 24X Fiche: 50-317, 83/06/14, 8307200344. & C-E in Bethesda, MD re
- --8305250564 Confirms proposed recommendations for improving NRC task action plan for Unresolved Safety Issue A-47. "Safety Implications of Control Sys." Approach would minimize adverse impact on engineering resources Meeting requested. PDINDEXTER.C.H. Baltimore Gas & Electric Co. B3/04/14. DIRCKS,W.J. Defice of the Executive Director for Operations. App. 19470:011. 24X Fiche: 30-317, 93/04/14, 8307200344.
- --8305250555 Responds to 830414 proposal re participation in activities concerning Unresolved Safety Issue A-47, "Safety Implications of Control Bys." Proposal meritorious Meeting to discuss proposal planned for 830523 in Bethesda MD. DIRKKS,M. J. Office of the Executive Director for Operations. 83/05/16. POINDEXTER.C.H. Baltimore Gas & Electric Co. 88pp. 19670:015. 24X Fiche: 50-317.83/06/14.8307200344.
- 8307200475 Comments favorably on Task Action Plan A-47 re pressurized thermal shock (PTS). Projected App K changes, w/potential for reduction of flux seen by reactor vessel walls, represents best opportunity for ultimate resolution of PTS.

  ZUDANS, Z. Franklin Institute/Franklin Research Center. ZUDANS, Z. ACRS Advisory Committee on Reactor Safeguards. 83/06/03. IONE, E. G. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19672:175.
- 8307200506 Comments on ACRS Metal Components Subcommittee 820930 maeting re pressurized thermal shock (Task Action Plan Item A-49). Procedure for screening PWRs acceptable. CATTON. I. ACRS Advisory Committee on Reactor Safeguards. 83/06/06. IGNE, E. ACRS Advisory Committee on Reactor Safeguards. 2pp. 19672: 279.
- 8307220034 Submits comments on proposed Task Action Plan A-49 re pressurized thermal shock.Recommends procedures contained in App E to SECY-82-465 be included in Reg Guide 1.99 earlier App E to SEC-82-460 be included in key dulum i. // collisted than 1986.
  GALL, M.R. GALL, W.R. ACRS - Advisory Committee on Reactor Safeguards. 83/06/03. IGNE.E.C. ACRS - Advisory Committee on Reactor Safeguards. 1p. 19712:092.

- 8307220174 Forwards page inadvertently omitted from 830715 submittal of rev to response on control of heavy loads (Generic Ltr 31-07). Page 4 of Attachment I to 810701 submittal should be replaced w/encl.
  BORDINE, T. C. Consumers Power Co. GL-81-07. 83/07/18.
  GRUTCHFIELD. D. Operating Reactors Branch 5. 2pp 19684:033. 24X Fiche: 50-155,83/07/18,8307220174.
- B307220376 Forwards Teledyne Rept 5310-9, "Responses to NRC Request for Info:Mark I Torus Program Plant-Unique Rept." In response to 22 questions from 830414 ltr.

  HARRINGTON, H. D. Boston Edison Co. 83-191. 83/07/19. VABSALLO, D. B. Operating Reactors Branch 2. 1p. 19686:188. 24X

  Fithe: 50-293,83/07/19,8307220376.
- --8307220378 5310-9
  "Responses to NRC Request for Info:Mark I Torus Program
  Plant-Unique Rept." W/two oversize drawings. Aperture cards
  are available in PDR.
  # Teledyne Engineering Services. 83/07/13. 25pp. 19686:189.
  24X Fiche: 50-293.83/07/19.8307220376.
- 8307250114 Summary of 830706 meeting w/Steam Generator Duners Group in Bethesda, MD re recommendations for new generic steam generator requirements, based on integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5. MIRAQLIA, F. J. Assistant Director for Safety Assessment. 83/07/13. EISENHUT, D. G. Division of Licensing. 20pp. 19737:200.
- 8307250120 Responds to NRC 830620 request for participation in NRC research program addressing Unresolved Safety Issue A-47, "8afety Implications of Control Sys." Participation declined due to lack of resources.

  EURY, L. N. Carolina Power & Light Co. LAP-83-192. 83/07/19, EISEN.NUT. D. G. Division of Licensing. 2pp. 19706:072. 24X Fiche: 50-261, 83/07/19, 8307250120.
- 8307250528 Requests that design info used by Ebasco in performing sys interaction methodology studies be provided directly to BNL & LLL. Effort important to resolution of Unresolved Safety Issue A-17.

  VARGA. 8. Operating Reactors Branch 1. 83/06/29. BAYNE, J. P. Power Authority of the State of New York. 3pp. 19739: 272. 24X Fiche: 50-286, 83/06/29, 8307250528.
- 8307260300 Forwards 6-month response to NUREQ-0612, "Control of Heavy Loads at Nuclear Power Plants." Procedures for overhead handling sys include precautions & guidelines to be observed while operating sys.

  CURTIB.N.W. Pennsylvania Power & Light Co. PLA-1752, 83/07/22.

  8GHHENGER, A. Licensing Branch 2. 17pp. 19726:092, 24X

  Fiche: 50-388, 83/07/22, 8307260300.
- 8307260320 Forwards B&W info re non-nuclear instrumentation/integrated control sys failures for generic pressurized thermal shock study. B&W-1743, Table B revised to reflect Failure 4 description.

  CODK: J. H. Consumers Power Co. 23860. 83/07/18. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 4pp. 19726:302. 24X Fiche: 50-329, 83/07/18. 8307240320.
- 8307260516 Forwards memo describing actions taken to resolve JH Conran differing prof opinion re sys interaction (Unresolved Bafety Issue A-17) & safety classification.
  DENTON, H.R. Office of Nuclear Reactor Regulation, Director.
  83/07/11. CUNRAN.J.H. Reliability & Risk Assessment Branch. 2pp.
  19782:241. 24X Fiche: 50-000,83/07/11,8307260516.
- --B307260525 Forwards NT Russell B30622 memo providing independent assessment & recommendations to resolve JH Conran differing prof opinion re sys interaction (Unresolved Safety Issue A-17) & safety classification. Recommendations adopted. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. B3/07/11. SPEIS, T.P. Division of Bafety Technology. 4pp. 19782: 243. 24X Fiche: 50-000, 83/07/11, 8307260516.
- --B307110505 Informs that independent assessment of issues raised in JR Conran differing prof opinion conducted, per B30415 request lasues A & B essentially same fundamental issue -- mgt of unresolved Bafety Issue A-17.

  RUSSELL, M. T. Systematic Evaluation Program Branch. B3/06/22.

  DENTON, H. R. Défice of Nuclear Reactor Regulation, Director. 7pp. 19782:247. 24X Fiche: 50-000, 83/07/11, 8307260516.
- ---8306080379 Submits statement of differing prof opinion re-certain aspects of existing policy & practice in areas of sys-interaction & safety classification, Excerpt from statement of mgt views to Shoreham board encl.
  GONRAN.J.H. Reliability & Risk Assessment Branch. 83/03/31.
  GOFFMAN,F.D. Reliability & Risk Assessment Branch. 55pp. 19782: 254. 24X Fiche: 50-000, 83/07/11, 8307260516.

- ---8307260540 Forwards transcript of presentation to American Stds Assoc ad hoc committee on nuclear research re NRC statistics. RUBINSTEIN.D. Applied Statistics Branch 81/02/04. ABRAMSON, L., BASSETT.H., ABELL, T., NRC - NO Detailed Affiliation Given. 8pp. 19782 317. 24K Fiche: 50-000.83/07/11,8307260516.
- --B307260545 Draft "Random Thoughts on Uncertainties Risk Analysis & Nuclear Regulation."
  RUBINSTEIN.D. NRC No Detailed Affiliation Given. 81/10/26
  12pp 19782-325. 24X Fiche.50-000.83/07/11.8307260516.
- --8304140030 Forwards JH Conran 830331 memo & attachments re differing prof opinion. Memo forwarded to ASLB hearing Contention 7B.

  Differing prof opinion should be expedited per Manual Chapter 4125. W/o encl.

  SPEIS.T.P. Division of Safety Technology. 83/04/05 DENION, H.R. Office of Nuclear Reactor Regulation. Director. 1p. 19783:014. 24X Fiche: 50-000.03/07/11.8307260516.
- --8304200084 Concurs w/k suppls F Coffman comments on JH Conran 8303211 differing prof opinion re Unresolved Safety Issue A-17. New A-17 program plan adequate basis for proceeding w/sys interaction issue.

  SPEIS T. P. Division of Safety Technology. ROMSOME, F. H. Assistant Director for Technology Review. THADANI.A. Reliability & Risk Assessment Branch. B3/04/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19783:015. 24% Fiche: 50-000,83/07/11,8307260516.
- ---8305050085 Comments on UH Conran 830331 differing prof opinion (DPG) re sys interaction program.topic of Unresolved Safety Issue A-17.

  COFFMAN, F. D. Reliability & Risk Assessment Branch. 83/04/13. THADANI.A. C. Reliability & Risk Assessment Branch. 4pp. 19783:019. 24X Fiche: 50-000: 83/07/11; 8307260316.
- --8305060655 Comments on JH Conran differing prof opinion on Issue C,
  "Iqsufficient Priority Given to Resolution of Known Safety
  Classification Problems." Add1 action needed to resolve
  issue generically.
  MATTSON.R.J. Division of Systems Integration (post Bi1005).
  VOLLMER.R.H. Division of Engineering. 83/04/13 DENTON,H.R.
  Office of Nuclear Reactor Regulation, Director. 3pp. 19783:023.
  24X Fiche: 50-000.83/07/11.8307260516.
- --8307260563 Designates WT Russell responsible manager for independently assessing issues raised by JH Conran differing prof opinion.
  Assessment should be completed by 830504.
  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
  83/04/15. RUSSELL.H.T. Systematic Evaluation Program Branch. ip.
  19783: 026. 24X Fichs: 50-000, 83/07/11, 8307260516.
- --8304270374 Requests written comments on manager views expressed in 830413 & 14 memos re 830331 differing prof opinion by 830425 Relevant documents also requested RUBSELL.W.T. Systematic Evaluation Program Branch. 83/04/18. CONRAN.J.H. Reactor Risk Branch. 1p. 19783:027. 24X Fiche: 50-000,83/07/11,8307240314.
- --8306080303 Recommends board notification be issued re JH Conran written statement of differing prof opinion on sys interaction issue.

  FUNCHES, J. L. Planning & Program Analysis Staff. 83/04/21.

  EIBENHUT, D. G. Division of Licensing. 1p. 19783:028. 24X

  Fiche: 50-000,83/07/11,8307260516.
- \*\*\*\*B307260572 Forwards JM Conran differing prof opinion re sys interaction issue & related info. Cognitant boards will be notified through board notification procedure. W/o ercl.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

  B3704/26. COTTER.D.P. Abomic Safety and Licensing Board Panel.

  ROBENTHAL.A.S. Atomic Safety and Cicensing Appeal Panel. 1919783: 029. 24X Fiche: 50-000. B3/07/11. B307260516.
- --8305050338 Forwards relevant documents per B30418 request re differing prof opinion of JH Contan re Unresolved Safety Issue A-17 & NUREB/CR-1321.
  COFFMAN,F. D. Reliability & Risk Assessment Branch. 83/04/28.
  RUSBELL,W. T. Systematic Evaluation Program Branch. 2pp.
  19783:030. 24X Fithe: 50-000, 83/07/11, 8307260516.
- --B305260333 Comments on status of differing prof opinion NRR decided to provide Boards, via usual notification process, of J Comman & NRR views.

  RUSSELL, W. T. Standardization & Special Projects Branch. 83/05/05.

  CORRAN, J. H. Reliability & Risk Assessment Branch. 1p. 19783: 032. 24X Fithe: 50-000, 83/07/11, 8307240516.
- --8304290048 Requests that Commission & recipients of Board Notifications 83-17 & 83-44 be provided w/Suffolk County 830323 testimony on Contention 78.

  LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips.

  LETSCHE, K. J. Buffolk County, NY. 83/04/21. RAWSON, R. J. Hearing Branch 4. 2pp. 19783: 295. 24X Fiche 50-000, 83/07/11, 8307260516.

- --8304080357 Forwards comments on mgt views & positions on sysinteraction per differing prof opinion in response to 830418 & 0505 memos Eicerpts from Suffolk County 830509 submittal & proposed request for addl info re Byron/Braidwood entl. CONRAN, J. H. Reliability & Risk Assessment Branch. 83/05/25. RUSSELL.W.T. Systematic Evaluation Program Branch. 74pp. 19783-033 24X Fiche: 50-000. 83/07/11. 8307260516.
- --B305020373 Comments on prediction intervals per J Ahearne B21102 memo. Prediction intervals do not provide panacea to risk analysis problems, yet merit exploration as tool in limited arsenal of rist assessment methodologies. Related info encl RUBINSTEIN, D. Reliability & Risk Assessment Branch. 83/03/09. BUSLIM.A. Reliability & Risk Assessment Branch. 39pp. 19783:203. 24x Fiche 50-000,83/07/11.8307260516.
- --8306080387 Discusses 630421 itr based on belief that Board Notification 63-44 constituted violation of 100782 780 re expants communications NRC does not consider board notification to be in violation RAISON.R J. Office of the General Counsel. 63/05/11.

  LETSCHE.R J. Kirtpatrick. Lockhart. Hill, Christopher & Phillips. 19783 297. 24X Fiche: 50-000.83/07/11.8307260516.
- --B306080370 Responds to B30421 request for explanation of two sentences contained in Board Notification B3-44 re Unresolved Issue A-17 re sys interactions.
  EIEEPROUT.D.C. Division of Licensing. B3/05/06. LETSCHE.K.J.
  Kirkpatrick. Lockhart. Hill. Christopher & Phillips. 3pp.
  19783-301 24X Fiche: 50-000. B3/07/11. B307260516
- --8306080374 States reason for declining to concur w/Congressman Downey
  ltr re achedules & resource allocation to Unresolved Issue
  A-17 Significant differences exist between personal views
  & views of Reliability & Risk Assessment Branch.
  CONRAN. J. H. Reliability & Risk Assessment Branch.
  83/04/28.
  COFFMAN.F.D. Reliability & Risk Assessment Branch.
  19783 304 24% Fiche 50-000, 83/07/11, 8307260516.
- --8307190481 Forwards documents containing history of resources assigned to Unresolved Safety Issue A-17.including organizational & personnel changes.per 830616 ltr Historical summary of program planning also encl
  DIRCHS.W J Office of the Executive Director for Operations.
  83/05/10 DUNNEY.T.J. House of Rep. Spp. 19783:305. 24X
  Fiche.50-000.83/07/11.8307260516.
- --B3072605B1 Discusses Board Notification 83-44 re differing prof opinion concerning safety interaction (Unresolved Safety Issue A-17) All boards & Commission considered concerns raised in 830207 affidavit resolved COMRAN.J. MRC No Detailed Affiliation Given 83/04/20 COFFMAN.F. NRC No Detailed Affiliation Given 1p. 19783.294. 24X Fiche 50-000.83/07/11.8307260516
- --830526033? Requests 30-working day extension to 830707 to complete independent assessment of issues raised in JH Conran differing prof opinion Delay due to JH Conran request for addlitine to prepare written response RUSSELL W T. Standardization & Special Projects Branch. 83/05/23. DENION H R Office of Nuclear Reactor Regulation. Director. 1p. 19783-310 24X Fiche: 50-000.83/07/tl.8307260516.
- --B307260594 Approves request for 30-day extension to complete evaluation of JH Conram differing prof opinion.

  DEMIGN.H R Office of Nuclear Reactor Regulation, Director.

  BJ/05/27 RUSSELL.M.T. Systematic Evaluation Program Branch. 1p. 19783 311: 24X Fiche: 50-000, 83/07/11, 6307260516.
- B307260525 Responds to unresolved items in EG Adensam 830610 ltr recontrol of heavy loads. Visual aids will be provided to assist crane operator in ensuring that designated safe load paths followed Listed lifting devices under evaluation. TUCKER.H B Dute Power Co. B3/07/15 DENTON.H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E.G. Licensing Branch 4. 2pp 19731 289. 24% Fiche 50-359.83/07/15.8307260526.
- 6307270023 Forwards comments received re technical findings & resolution positions for Unresolved Safety Issue A-43 reconstainment emergency sump performance Revs to NUREG-0897 recommended Technical/safety issues & resolutions requested. SERMIZ.A.W. Generic Issues Branch. 83/07/12. DALGMREN.D. Sandia Laboratories 2pp. 19811-209.
- --8307270328 Forwards comments on NUREG-0897, "Containment Emergency Gump Performance" & NUREG-0869, "Unresolved Safety Issue A-43 Resolution Positions" "HART.G H. Owans-Corning Fiberglas Corp 83/06/23, SERKIZ.A.W. Division of Safety Technology, 11pp 19811 211
- --B30727G033 Connents on draft NUREG-0897 & NUREG-0869 (Reg Guide 1.B2 rev) PADMANABHAN.H Alden Research Laboratory 83/06/13 SERKIZ.A.W. Generic Issues Branch 7pp 19811 222

- --8306280504 Forwards rev to Table A-3 in NUREQ-0869. Rev corrects discrepancies noticed in values of variables for vertical outlets. Corrections also applicable to NUREQ-0897. PADMANABHAN Alden Research Laboratory. 83/06/22. 8ERKIZ.A. Generic Issues Branch. 4pp. 17811:231.
- B307270243 Approves request for withholding Rept 83-155, "Fracture Mechanics Analysis of Indian Point 3 Nuclear Generating Station Steam Generator Girth Held Cracks Under Pressurized Thermal Shock Conditions," (ref 10CFR2.790), VARGA.S.A. Operating Reactors Branch 1, 83/06/27, 8AYNE, J.P. Power Authority of the State of New York, 4pp. 19811:167, 24X Fiche:50-286,83/06/27,8307270243.
- B307270340 Forwards responses to draft SER open items & rev to B30701 response to Open Item 151.

  MCDUFFIE, M.A. Carolina Power & Light Co. LAP-83-306. B3/07/15.
  DENTON, M.R. Office of Nuclear Reactor Regulation, Director. 346pp. 19768:001. 24X Fiche: 50-400, 83/07/15. B307270340.
- 8307280080 Discusses G Hacker concerns about Figure 3.6 in NUREO-0897 re containment emergency sump performance. Figure 3.6 replacement corrected copy encl. Concern re uncertainties in Harry data needs attention.

  SWIFT, W L. Creere: Inc. 83/06/13. STROM.P. Sandia Laboratories.
  3pp. 19826:011.
- 8307280289 Forwards comments on draft NUREO-0927, "Evaluation of Water Hammer Experience in Nuclear Power Plants." Water hammer design considerations should apply to entire feed sys.

  RAHE.E.P. Westinghouse Electric Corp. NS-EPR-2798. 83/07/20.

  KNIEC.K. Division of Safety Technology. 3pp. 19796: 322.
- 8307290174 Provides status of program re pressurized thermal shock.
  Issue would be resolved if NRC screening criteria
  conservative & if critical weld will not reach criteria
  prior to OL expiration.
  UTLEY, E. Carolina Power & Light Co. LAP-83-283. 83/07/26.
  DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp.
  19821:158. 24X Fiche: 50-261.83/07/26.8307290174.
- B307290466 Forwards safety evaluation of util responses to 801222 generic ltr re control of heavy loads. Phase I of issue resolved. Technical evaluation rept encl. CLARK. R.A. Operating Reactors Branch 3. 83/07/18. WITHERS, B. D. Portland General Electric Co. 2pp. 19859: 060. 24x Fiche: 50-344, 83/07/18, 8307290466.
- --8307290475 Safety evaluation of util responses to generic issue, "Control of Heavy Loads Near Spent Fuel." First response (Phase I) acceptable.

  # Operating Reactors Branch 5. 83/07/18. 2pp. 19859:062. 24x
  Fiche 50-344.83/07/18.8307290466.
- --8306140436 TER-C5506-378

  "Control of Heavy Loads, Portland GE Co, Trojan Nuclear
  Plant: "technical evaluation rept.
  BUMBERGER.C. Franklin Institute/Franklin Research Center.
  NRC-03-81-130. TAC 07716. 83/06/10. SINGH.A. NRC No Detailed
  Affiliation Given. 27pp. 19859:064. 24X Fiche:50-344.63/07/18,
  8307290466.

## ILE INSPECTION AND ENFORCEMENT

- B305120177 EN-B3-033: informs of issuance of proposed imposition of civil penalty in amount of \$1.000 for license failure to ensure only authorized & qualified pensonnel permitted to remove source holder containing 10 mCi Cs-137 sealed source. FLACK.E. AXELRAD.J. Director's Office. Office of Inspection and Enforcement. B3/05/10. Ip. 18422:001.
- 8306100097 EN-83-040: on 830630, notice of violation & proposed imposition of civil penalty to be issued in amount of \$40.000 re failure to satisfy primary containment integrity limiting condition for operation.

  BARBER. G. AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/06/08, ip. 18802:225. 24x Fiche: 50-277, 83/06/08, 8306100099.
- 8306270401 IE Info Notice 83-46. "Common Mode Valve Failures Degrade Surry Recirculation Spray Subsystem." Svc list encl.
  JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/11. Consolidated Edison Co. of New York, Inc. 154pp. 19363-293. 24X Fiche: 50-000, 83/07/11, 8306270401.
- 8306270404 IE Info Notice 83-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list enci.

  JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133. 24X Fiche: 50-000, B3/07/12, B306270404.

- 8306270406 IE Info Notice 83-48, "Gaseous Effluent Releases of Radioactive 1-125 & I-131 in Excess of NRC Limits." Svc list
  - encl.
    TAYLOR,J.M. Division of GA: Safeguards & Inspection Programs (Post B30103). 83/07/14. Consolidated Edison Co. of New York: Inc. 114pp. 19715:270. 24X Fiche: 50-000.83/07/14:8306270406.
- 8304280432 EN-83-005A: on 83012B, notice of violation & proposed imposition of civil penalty in amount of \$100,000 issued.
  Violation based on failure to implement adequate GA program for safety-related equipment.
  KLINGLER.G., AXELRAD.J. Director's Office, Office of Inspection and Enforcement. 83/06/27, 1p. 19020:327. 24X Fiche:50-456,83/06/27,8306280432.
- 8307010011 PNU-I-83-071: on 830627, licenses began shutting down to Inspect for unidentified RCS leakage. Licenses identified two pacting leaks on 830628. Outage astimated to last 3-4 days. JOHNSON, J., HUDSON, S., ELSASSER, T. Region I. Defice of Director. 83/06/28. 1p. 19169:087. 24X Fiche: 50-293, 83/06/28, 8307010011.
- 8307010049 PNO-I-83-068: on 830624, while performing exams per IE Bulletin 83-02 & NUREO-0313, stress corrosion cracking found in recirculation & RHR piping sys. Crack welded. Facility in cold shutdown while evaluation continues.
  ENMETER, S., DURR, J. Region I, Office of Director. IEB-83-02.
  83/06/24. ip. 19168:309. 24% Fiche: 50-278, 83/06/24, 8307010049.
- 8307010079 PNO-I-83-069: on B30624, high reactor water level acram resulted from loss of offsite power. Gaused by extensive damage to primary & secondary windings of startup transformer C phase. Evaluation underway.
  RHDADS. G., MCCABE. E. Region 1, Dffice of Director. 83/06/27. ip. 19169: 217. 24x Piche: 50-387, 83/06/27, 8307010079.
- 8307010188 PND-I-83-070; on 830605-09, aerial survey of central Long Island revealed spot that appeared to be contaminated w/Co-60 near Moriches, Long Island. Area identified as private property.

  CAMPBELLIM. Region 1. Office of Director. 83/06/27. 2pp.
- 8307010164 PND-I-83-070A: during 830605-09 aerial survey, Co-60 contamination discovered on residential property, BNL performed onsite measurement on 830624. Highest radiation found near picnic table. Well water not contaminated. GAMPBELL.M. Region 1, Office of Director. 83/06/28. 1p. 19170:085.
- 8307050112 PND-I-83-072: on 830629, leaking shipment of radioimmunoassay (RIA) kits received T-3 reagent w/less than 10 uCi I-125 in 420 milliter bottle found nearly empty. No detectable radioactivity found.

  DAVIS.J. KINNEMAN.J., JDYNER.J. Region 1, Office of Director.
  83/06/29. ip. 19299:109.
- 8307050114 EN-83-015A: on 830630, order imposing civil penalty in amount of \$40,000 issued, based on licensee failure to ensure complete GA sys turnover. Licensee may pay civil penalty within 30 days or request hearing.

  KLINOLER.O., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/06/30. 1p. 19199:362. 24X Fiche: 50-482, 83/06/30, 8307030114.
- 8307050201 PNS-I-83-017: on 830628,8&W craft worker discovered 20 severed cables in unfinished control bldg between control bldg & intake structure. Cause under investigation.
  MCKEOWN. GDDY. MARTIN. T. Region 1. Office of Director. 83/06/29.
  1p. 19199: 220. 24X Fiche: 50~423,83/06/29,8307050201.
- 8307060007 PND-V-83-026: on 830627, util notified Region V of intention to decommission facility. Decision based on restart costs. Licensee expected to apply for "possession only" license. Facility shut down since Jul 1976.

  KIRBCH.D.F., MDRRILL, P.J. Region 5, Office of Director. 83/06/27. 1p. 19251: 014. 24% Fiche: 50-133, 83/06/27, 8307060007.
- B307060027 PNB-I-B3-015A; updates B30616 marijuana cigarette discovery reported on B30617. Seven contract security personnel terminated because of accusations or admissions of usage. DUNLOF.J. GDDY.A. Region i. Office of Director. 83/06/30. ip. 19251:349. 24X Fiche: 50-245, 83/06/30, 8307060027.
- B307060052 PNO-V-B3-027: on B30627. State of MA notified that shipment of low level waste received from Palisades power plant b/one drum leaking due to hole caused by corrosion. Util banned from using site & burial permit suspended, effective B30621. THOMAS.R.D. Region 5, Office of Director. B3/07/01. ip. 19251:330.

- 8307060055 Corrected PNS-V-83-008: on 830620. QC inspector discovered three nonsafety-related cables cut near termination & two maters smashed Possibly caused by termination of employees. CANTER, H., YDUNG, T. Region 5. Office of Director. 83/06/22, 1p. 19250: 285. 24X Fiche: 50-312, 83/06/22, 8307060055.
- 8307060096 PND-V-83-025: on 830623.Co-60 contamination found in soil sample taken near controlled area of Allied Consulting. Inc Agreement State licenses in Yakima. WA. Mgt conference between state & licenses scheduled for 830627.
  HORNOR, J. M. Region 5, Office of Director. 83/06/27. 1p. 19251: 277.
- 8307060122 PND-IV-83-021: through-wall crack discovered in heat-affected area of weld connecting reactor water cleanup sys to RHR sys. 9E will perform 100% ultrasonic test insp of reactor water cleanup sys welds.
  WEBTERMAN.T.F., MADBEN.G.L. Region 4, Office of Director. 83/06/30. 1p. 19252:223. 24% Fiche: 50-298, 83/06/30, 8307060122.
- 8307040149 PNO-I-83-073: on 830429; following discovery of RHR logic relay, spurious signal generated resulting in closure of recirculation pump discharge valves, causing recirculation pump trip. Reactor manually scrammed. Logic relay repaired. RAYMOND. M. J., HUDSON. S., KISTER, H., Region 1, Diffice of Director. 83/04/30. 2pp. 19249; 228. 24X Fiche: 50-271, 83/04/30, 8307040149.
- 8307040225 PND-III-83-054; on 830627, 50 mCi Cs-I37 seed used in short-term treatment of cervical cancer discovered missing. Seed last seen on 830514 when removed from patient, inventoried & placed in storage safe. Search conducted.

  SRENIAHSKI, D. MILLER, J. Region 3, Office of Director. 83/06/27, ip. 19239: 342.
- B307060310 PNO-III-83-055: Region III authorized resumption of safety-related welding on HVAC sys at const sits. Zack Co welding procedures & observations of welding performance demonstrations reviewed.

  GARDMER.R. HARRISON.J. Region 3, Office of Director. B3/06/29.

  1p. 19238: 331. 24X Fiche: 50-329, 83/06/29, 8307060310.
- 8307060334 PNO-111-83-056: on 830629, security personnel found several rolled cigarette butts believed to be marijuana. Visitors denied access to site & alleged controlled substances turned over to police for analysis. Util awaiting results. CREED. J., MILLER, J. Region 3, Office of Director. 83/06/30. 1p. 19234:141. R4X Fiche: 50-295, 83/06/30, 8307060334.
- 8307040340 PND-III-83-057: on 830429. Bechtel fired lead welding engineer for allegedly instructing rod room attendant to falsify number of weld rod withdrawal slips. No safety significance resulted from incident.

  LANDBHAN.R.: HARRIBON.J. Region 3. Office of Director. 83/06/30. 1p. 19236: 254. 24X Fiche: 50-329, 83/06/30, 8307060340
- 8307080020 PND-III-83-058: on 830701, bomb threat received from unknown female stating that bomb would go off in 10 minutes.
  Licensee security force put on alert status. No explosion occurred. State police not notified due to lack of time.
  MADEDA, T., CREED, J. Region 3, Office of Director. 83/07/01. 1p. 19351:216. 24X Fiche: 50-295.83/07/01,8307080020.
- 8307110140 PND-V-83-025A: HA state inspectors continuing investigation re offsite contamination associated w/decontamination work by Allied Consulting: Inc.Of 12 soil samples, nine found w/ less than detectable limit of 0.1 pCi/gm. HDRNOR: J. H. Region 5, Office of Director. 83/07/01. ip. 19375:031.
- 8307110183 PND-II-83-051: on 830705. Region II notified of Am-241 discovered in reclaimed gold obtained on 830330 by Richmond, VA gold refiner. High dose rates could result from attempts to reclaim smoke detector foil mfg scrap. POTTER, J. P., COLLING, D. M. Region 2, Office of Director. 83/07/05. ip. 19380: 219.
- 8307110252 PND-II-B3-053: on 830705, workers removed concrete block shielding to perform maint on valve, leaving unguarded accuss path to reactor containment, Suard observed sleeping at torus post. Security evaluated incidents during 830706 & 07 insps. CLARK, K. M., OILLILAND, J. T. Region 2, Office of Director. 83/07/08. 2pp. 19374:270. 24X Fiche: 50-259, 83/07/08, 8307110252.
- 8307110274 PND-I-83-075: on 830705, reactor tripped from 95% power when MBIV closed. Caused by steam line isolation spike due to increase in condensate demineralizer resin. Water sample sent to Peach Bottom for analysis. RCIC being reevaluated. RHOADB. 0. / MCCABE.E. Region i. Office of Director. 83/07/06. 2pp. 19379:158. 24X Fiche: 50-387.83/07/06.8307110274.

- 8307110307 PNO-II-83-052: during insps per IE Bulletin 83-02, cracks identified in 33 of 91 pipe welds in recirculation sys & 14 of 32 pipe welds in RHR sys. Caused by intergranular stress corrosion cracking. Evaluation ongoing. CANTRELL, F. S., VERRELLI, D. M. Region 2, Office of Director. IEB-83-02, 83/07/08, 19, 19378: 329. 24x Fiche: 50-259, 83/07/08, 8307110307.
- 8307110473 PNO-I-83-074: on 830704 & 05.unit voluntarily shut down for add1 NDE of recirculation & RHR piping welds. Add1 erams being made by NDE tram from separate vendor organization. Subsequent licensee actions being discussed.
  TRIPP.L.: KEIMIO.R. Region 1. Office of Director. 83/07/05. 1p. 19380: 184. 24X Fiche: 50-277, 83/07/05, 8307110473.
- 8307120074 PNO-IV-B3-023: on B30708, reactor shut down following indications that tube leak in steam generator A increased. Preparations for steam generator tube insp made. Outage of 2 wits expected.

  JOHNSON W. D., CALLAN, L. J. Region 4, Office of Director. B3/07/08. ip. 19423: 147. 24X Fiche: 50-313. B3/07/08. 8307120074.
- 8307130007 PNG-TMI-B3-004: on 830708, leakage occurred from letdown sys flow instrument when, w/one reactor coolant pump in operation, util switched to other pump so that one pump was running in other RCS loop, Caused by loose fittings.
  WIESE, J., KEIMIO, R. Region 1, Dffice of Director. B3/07/08. 1p. 19465:357. 24X Fiche: 50-289, 83/07/08, 8307130007.
- B307140311 EN-B3-029A: on B30713, order imposing civil monetary penalty in amount of \$4,000 issued to licensee for failure to conduct adequate survey, resulting in worker receiving 4.27 reas exposure.

  FLACK, E., AXELRAD, J. Director's Office. Office of Inspection and Enforcement. 83/07/13. 1p. 19323:308.
- B3071B0159 PNO-III-B3-060: on B30713, licenses abandones efforts to retrieve 3 Ci Aa-241 & 2 Ci Cs-137 sources from well north of Beverely, OH, Cement cap will be placed inside well & plague describing abandoned sources will be affixed to cap. BRENIAMSKI, D. J. MILLER, J.R. Region 3, Office of Director, B3/07/14. 1p. 19556: 251.
- B30719000B PNO-IV-B3-024: two weeping leaks reported on reactor side of first isolation valve on core spray loop A. Visual examinations of the confidence of
- B307190039 PNO-III-B3-059: licensee authorized to resume remaining simple simple statical safety-related const. GA site managers replaced, insp procedures revised & personnel retrained.

  MILLIAMS.C., LITTLE.N., BSESSARD.R., Region 3, Office of Director B3/07/11. 1p. 19635:149. 24X Fiche: 50-346, 83/07/11. 8307190039.
- 8307190321 EN-83-023A: notice of violation & proposed imposition of civil penalty in amount of \$40,000 issued to licensee. Action based on licensee approval of preoperational test results even though one test acceptance criteria not satisfied. KLINGLER, C., AXELRAD, J. Director's Office. Office of Inspection and Enforcement. 83/07/15. ip. 19632:109. 24X Fiche: 50-322, 83/07/15.
- B307200155 PNO-III-B3-061: on B30714.Region III notified that Dow Chreical Co terminating contract wouth to supply process steam to facility. Buft sessing court judgment that all contract obligations canceled filed. HARRISON J., MARNICK.R. Region 3, Office of Director. B3/07/15, ip. 19651:246. 24X Fiche: 50-329, B3/07/15, B307200155.
- 8307200256 PNO-111-83-054A: on 830714, licensee abandoned search for 50 mCi Cs-137 seed removed from patient on 830514 following cervical cancer treatment. Seed missing since 830627. Employee may not have inventoried or stored seed following removal. SRENIAKSKI. D., MILLER. J. Region 3. Office of Director. 83/07/14. 1p. 17648: 060.
- 8307210124 PNO-T-83-074A: on 830704, unit taken diffline & into cold thutdown for add! NDE of RHR & recirculation sus piping welds. Bignificant indications found in RHR suction piping weld 10-0-5, 20-inch diameter pipe to allow weld. TRIPP.L., XEIMIG.R. Region 1, Office of Director. 83/07/15. ip. 19668: 361. 24X Fichs: 50-277, 83/07/15, 8307210124.
- B307220179 PNO-I-83-076: on B30715, during ultrasonic examt required by IE Bulletin 83-02. pipe creck identified in and cap to pipe weld of 22-inch diameter distribution header on circulation loop A. Caused by intergranular stress corrossion. LAZARUS, W. J. x XIBTER. H. B. Region I. Office of Director. IEB-83-02. 83/07/18. ip. 19684:012. 24X Fiche: 50-333, 83/07/18, 8307220179.

- B307220401 PND-III-83-062: on B30718, reactor tripped from 93% power due to loss of forced circulating water pumps. Pumps tripped due to lesk in seal injection sys. Caused by failed gasket on flow indicator. Reactor in cold shutdown.

  ACKIM, I., SHAFER, W. Region 3, Office of Director. 83/07/18, ip. 19485:001. 24% Fiche: 50-409, 83/07/18, 8307220401.
- 8307220531 PNO-III-83-063: on 830714, during monthly surveillance testing of ECC8 actuation circuitry one of two reactor water level switches failed to respond. Caused by improperly connected wires in terminal panel. Panels will be sealed. MADISON.A., SHAFER, W. Region 3, Office of Director. 83/07/18, 1p. 19465: 008. 24X Fiche: 30-373, 83/07/18, 8307220531.
- 8307250457 Updated PNO-II-B3-051A: on 830707, gold nuggets measured. Dose rates of 0.1 & 0.5 millirads per h rather than 30 & 150 millirads as reported earlier. Am-241 content estimated to be 0.5 & 0.9 uci.
  POTTER.J. P., CDLLINS, D. M. Region 2, Office of Director. 83/07/08. ip. 19701: 323.
- 8307260364 EN-83-045: on 830722, notice of violation & proposed imposition of civil penalties will be issued in amount of \$140,000. Action based on submittal of matl false statement & violation re operator requalification program. RUSAND.R., AXELRAD, J. Director's Office. Office of Inspection and Enforcement. 83/07/22. 1p. 19733:005. 24X Fiche: 50-289, 83/07/22, 83/07260364.
- 8307260492 PNO-II-83-055: on 830720, during maint on demister in shutdown ventilation sys, hydrogen flashback occurred at entrance to furnace in Bldg 300 complex. No internal personnel contamination or release to environ detected. CORYELL, Q.P., BARR, K.P. Region 2, Office of Director. 83/07/21. 2pp. 19734:010.
- 8307260541 PNO-III-83-064: on B30719, i/8-inch diameter hole found in metal bellows in primary containment drywell-to-torus vacuum breaker. Causad by welding strike during Mark I torus mods. Unit placed in cold shutdown.

  MADISON.A., SHAFER.M. Region 3, Office of Director. 83/07/20. 1p. 19732: 027. 24X Fiche: 50-237. 83/07/20, 8307260541.
- B307260574 PND-III-83-062A: on B30716, 15,000 gallons radioactively contaminated water leaked from seal injection sys into reactor containment subbasement. Caused by gasket failure, due to overpressurization. Mater pumped out.

  JACKIM-I., SHAFER.W. Region 3, Office of Director. 83/07/20. 1p. 19732: 090. 24X Fiche: 30-409, 83/07/20, 8307260374.
- B307280305 PNO-V-83-029: on B30718, during preparation for repairs on reactor coolant pumps 1A & 1B, three boits which hold diffusor clamp ring discovered missing & all bolts loose & 15% of impeller vanes missing.
  FIORELLI, G., YOUNG, T. Region 5, Office of Director. 83/07/19, 19789; 210. 24% Fiche: 50-528, 83/07/19, 8307280306.
- 8307280308 PNO-II-B3-056: on B30722, operator found insulation smoldering on stram-driven feedwater pump in turbine bidg. Caused by presence of oil. Insulation removed & burning extinguished by workers on scene. Unit reduced to 50% power.
  PEEBLES.T. A., BROWNLEE, V. L. Region 2, Office of Director. 83/07/22, 2pp. 19789: 211. 24% Fiche: 50-366, 83/07/22, 8307280308.
- 8307280333 PND-1-83-077: on 830720, two amployees discharged for cheating on GC certification exam taken by one employee. Other employee, certified GC inspector & personal friend of new employee, provided questions & answers on exam. CONNER.E., KEIMIQ.R. Region 1, Office of Director, 83/07/21, 19790:094. 24x Fiche: 50-219, 83/07/21, 8307280333.
- 8307280377 EN-83-028A: on 83042B. Commission notified of intent to issue notice of violation & proposed imposition of civil penalty in amount of \$10,000. Notice issued 830726 re unauthorized entry into protected area. ROSANO.R., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/07/26. ip. 19796:103. 24X Fiche: 50-275,83/07/26,8307280377.
- 8307280381 PNO-TMI-B3-006: on B30727. util informed TMI Program Ofc that R Parts & Bechtel reached settlement on R Parks Dept of Labor complaint. Neither party will make further public comment other than simultaneous press announcements. BARRETT.L. TMI Program Office. 83/07/27. 1p. 19796: 099. 24X Fiche: 50-320, 83/07/27, 8307280381.
- 8307280458 PND-I-83-078: on 830722, startup commenced following first refueling outage on 830121. Zero power physics testing will be conducted for 2-3 days. Corrective actions per 830506 order re ATMS events verified.

  8307722. 1p. 19797: 244. 24X Fiche: 30-311, 83/07/22, 8307280458.

- B307290312 PNA-B2-004A; on B20510, State of WA informed NRC of completed cleanup of contaminated area from B20507 spill. Caused by clarifier tank rupture. Similar tank in use at Rear Creek Mill in WY. Region IV notified.
  BOLLING, L. A. KENDIG, J. NRC No Detailed Affiliation Given.
  B3/05/ii. 2pp. 19858; 159.
- MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS
- B307050421 Forwards summary of nonreactor event rept (NRER) database for Jul-DEc 1982.Rept suppls AEOD B20111 rept on NRER database.

  HELTEMES,C.J. Director's Dffice. 83/06/14. DAVIS,J.G. Office of Nuclear Material Safety & Safeguards,Director. DEVOUNG,R.C. Director's Office, Office of Inspection and Enforcement. KERR,G.W. Office of State Programs, Director. 1p. 19243:086.
- --8307050427 "Summary of Nonreactor Event Rept Database for Period Jul-Dec 1982." BLACK, K. Director's Office. AEOD/N2093. B3/06/14. JSpp. 19263:087.
- 8307060147 Informs that encl memo advising that licensees should be cited for failure to meet license application commitments, sent to regional ofcs, in response to 830314 memo re HE Book 821124 memo. W/o encl.

  AXELRAD, J. A. Enforcement Staff. 83/06/30. Division of Fuel Cycle & Material Safety. 1p. 19249:204.
- 8307060194 Concurs w/RE Cunningham position that licensees should be cited for failure to meet license application commitments, even if commitments more restrictive than min reg guide requirements. License amend request needed for exemption.

  AXELRAD. J. A. Enforcement Staff. 83/06/30. BOOK. H. E. Region 5. Office of Director. 1p. 19249: 293.
- B307090344 Reiterates Tube-Line Corp opinion that add1 written notification by NRC to utils using carbon & stainless steel matls for nuclear applications unnecessary & will serve no useful purpose.

  HALLMAN,R.M. Cahill, Gordon & Reindel, HALLMAN,R.M. Tube-Line Corp. B3/07/05. DEYOUNG.R.C. Director's Diffice, Office of Inspection and Enforcement. App. 19390:315.
- --8307080348 Forwards four heat treat charts from Monninghoff confirming matls have been heat treated at 1,050 C & water quenched.
  Ltrs also being forwarded to end users.
  BHARKEY.J.J. Tube-Line Corp. 83/06/09. COLLINS.J. Region 4,
  Office of Director. 6pp. 19350:321.
- 8307110883 Forwards comments on 830128 draft overall project rept for FIN A-0427. Rept satisfactory & schedule for final rept publication acceptable. W/o encl.
  BEARD.J.T. Operating Reactors Assessment Branch. FIN A-0429. 83/06/27. LU.S. Lawrence Livermore Laboratory. ip. 19434:096.
- 8307140146 Forwards draft info notice. "Potential for Tampering W/Personnel Dosimetry Devices."

  O'REILLY, J.P. Region 2. Office of Director. 83/06/16. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 19514:229.
- 8307180391 Delegates & assigns certain operator reactor licensing functions to Region I. Region should consult w/Operator Licensing Branch on licensing functions having policy implications.
  DIRCKS.W.J. Office of the Executive Director for Operations.
  B3707701. MURLEY.T.E. Region 1. Office of Director. 2pp.
  19641:292.
- B307200377 Informs that B30505 recommendation for changes to STS Burveillance Requirement 4.8.1.1.2 re diesel fuel impurity level tests should be pursued per NRR Ofc Ltr 40 rather than Ofc Ltr 3B. Actions requested in B30505 memo completed. BISENHUT.D.O. Division of Licensing. B3/07/05. MATTSON, R. J. Division of Systems Integration (post 811005).
- 8307250497 Responds to 830613 ltr expressing concern re NRC issuance of civil penalties & effects on ultimate cost of electricity to consumers. Civil penalties increase compliance \( \omega \) requirements.

  DEYQUNO, R. C. Director's Office, Office of Inspection and Efforcement.

  83/07/11, CODK, L. G. L. G. Cook Associates, Inc. ip. 19725: 107.
- 8307240101 Responds to 830705 itr re issuance of bulletin on mati supplied by Tube-Line Corp. Due to substantial safety questions raised by company products NRC cannot rely on voluntary licensee compliance.

  DEYGUNG, R. Director's Office. Office of Inspection and Enforcement. 83/07/20. HALLMAN.R.M. Cahill, Gordon & Reindel. HALLMAN.R.M. Tube-Line Corp. 2pp. 19727:293.

- ---8307260113 Expresses displeasure w/draft written notification given to NRC incenses re Tube-Line Corp mati supplied for nuclear applications
  HALLMAN R M Cahill Gordon & Reindel HALLMAN R M Tube-Line Corp. 83/07/05. DEYGUNG R. Director's Office. Office of Inspection and Enforcement App. 19727.295
- 9307280086 Requests all correspondence be addressed to RT Laily in lieu of DC glabs.

  KERNDOLE.C Middle South Services, Inc. 83/07/22. HOUSTON, D. Licensing Branch 2. 1p. 19791:205.
- NUREG REPORTS AND RELATED CORRESPONDENCE
- B30510010B Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREG-0472. "Defisite Dose Calculation Manual" also encl. BTEMART. W. L. Virginia Electric & Power Co. 179. B3/05/04. DENTONIA. R. Office of Nuclear Reactor Regulation. Director. VARGA. S. Deparating Reactors Branch | 3pp. 19527:026. 24% Fiche: 50-280. B3/05/04, B30510010B.
- --8305100ili Proposed revs to radiological effluent Tech Specs in accordance w/Rev 3 to NUREG-0472.

  + Virginia Electric & Power Co. 83/05/04. 87pp. 19527:029. 24X Fiche: 50-280.83/05/04.8305100108.
- 8304090249 Forwards draft SER (NUREQ-0989), for review Detailed agenda to resolve SER open items requested Draft responses requested prior to recommended util & NRC meeting.

  NOVAK,T.M. Assistant Director for Licensing. 83/06/01. CAHILL,W.J. Gulf States Utilities Co. 483pp. 18799:201. 24X

  Fiche: 50-458,83/06/01,8306090249.
- 8306100004 Forwards BEIR rept. "Effect on Population of Exposure to Low Levels of Ionizing Radiation." in response to 830411 request for info re health impact estimate. W/o encl. SNYDER,B. J. TN1 Program Office. 83/06/06. HURBI. J. Affiliation Unknown. 3pp. 18815: 324. 24X Ficha: 50-320, 83/06/06, 8306100004.
- 8306100021 Forwards safety evaluation re NUREO-0737. Item II. B. 2, "Design Review of Plant Shielding." Item resolved VASSALLO. D. B. Operating Reactors Branch 2. 83705/25. BAYNE, J. P. Power Authority of the State of New York. Spp. 18815: 309. 24X Fiche: 50-333, 83/05/25, 8306100021.
- 8304270375 Generic Ltr 83-24 to all BWR applicants for OL & holders of OLs for Grand Gulf, LaSalle & Susquehanna re IMI Task Action Plan Item I.G.i. "Special Low Power Testing & Training & Recommendations for BWRs." Svc list encl. EISENNUT. D. G. Division of Licensing. GL-83-24. 83/05/29. Long Island Lighting Co. 26pp. 19384:115. 24X Fiche: 50-000, 83/06/29, 8306270395.
- B307010007 Informs that during 1982, there were no challenges to primary coolant sys safety & relief valves, per NUREG-0737. Item II.K. 3.3.

  DALTROFF, S. L. Philadelphia Electric Co. 83/06/27. EIGENHUT, D. G. Division of Licensing. 1p. 19169: 205. 24X Fiche 50-277, B3/06/27, 8307010009.
- 8307010014 Forwards IE Insp Rept 50-322/83-15 on 830516-19. No noncompliance noted.

  MARTIN T. T. Division of Engineering & Technical Programs. 83/06/15. POLLOCK M.S. Long Island Lighting Co. 2pp. 19124:320. 24X Fiche:50-322,83/06/15,8307010014.
- --B307010021 IE Insp Rept 50-322/83-15 on B30516-19 No noncompliance noted Major areas inspected licensee action on previous insp findings, preoperational test program including test program status & implementation & test procedure review.
  NICHOLAS.H.H., BETTENHAUSEN.L. Region 1, Office of Director.
  83/06/15. 11pp. 19124:322. 24X Fiche:50-322,83/06/15,8307010014.
- 8307010019 Requests that SER.Section 7.5.4 be amended to reflect current NRC requirements & util commitments for proposed plant computer-based safety parameter display sys.per NUREG-0896 & NUREG-0737. Suppl 1.

  DRUMMOND. F. J. Louisiane Power & Light Co. W3183-0204. 83/06/27. KKIGHTON. G. W. Licensing Branch 3. 1p. 19169:107. 24X Fiche: 50-382.83/06/27.8307010019.
- 8307010038 Forwards IE Insp Rept 50-309/83-08 on 830503-05. No noncompilance noted.

  STAROBTECKI,R. Division of Project & Resident Programs. 83/06/17. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 17169:017. 24X Fiche:50-309.83/06/17.8307010038.

- --8307010047 IE Insp Rept 50-309/83-08 an 830503-05 No noncompliance noted Major areas inspected: licensee actions taken to comply w/NURE9-0737. Item II. B. 2: "Design Review of Plant Shielding."
  - Shielding. L. KELLY,E. Region 1. Office of Director. GALLO,R.M. Division of Project & Resident Programs. 83/06/13. 7pp. 19169-019. 24X Fiche 50-309,83/06/17,8307010038.
- 8307010049 PNO-I--83-068: on 830624, while performing exams per IE Bulletin 83-02 & NUREG-0313, stress corrosion cracking found in recirculation & RHR piping sys Crack welded. Facility in cold shutdown while evaluation continues.

  EBNETER: S. , DURR: J. Region 1, Office of Director. IEB-83-02.
  83/06/24 ip. 19168: 309. 24x Fiche: 50-278, 83/06/24, 8307010049.
- 8307010104 Application to amend License DPR-22, changing Tech Specs to comply w/NUREG-0737, Items II. F 1. 1 ~ II. F. 1. 6 re accident monitoring instrumentation, per Generic Ltr 83-02.

  MUSOLF, D. Northern States Power Co. GL-83-02. 83/06/24. Office of Nuclear Reactor Regulation, Director. 3pp. 19168; 211. 24X Fiche: 30-263.83/06/24.8307010104.
- --8307010123 Proposed Tech Spec changes, restricting employee overtime, requiring safety/relief valve fatiures & challenges to be reported & adding limiting condition for operation & surveillance requirements for RCIC sys suction transfer.

  \* Northern States Power Co. QL-82-12. 83/06/24. 44pp. 19168:214. 24% Fiche: 50-263.83/06/24.8307010104.
- B307010143 Submits info identifying electrical equipment important to safety per IOCFR50. 49(g). Also submits schedules for qualification or replacement of remaining electrical equipment.

  FIEDLER.F.B. General Public Utilities GPU Service Corp. IEB-79-018. 83/06/23. CRUTCHFIELD.D. Operating Reactors Branch 5. 13pp. 19169.259. 24X Fiche: 50-219.83/06/23.8307010143.
- 8307050016 Informs that intake structure crane fully complies w/Guideline 7 of NUREG-0612, "Crane Design," based on Franklin Research Ctr & Dresser Industries studies. UHRIG.R.E. Florida Power & Light Co. L-83-374. 83/06/28. CLARK.R.A. Operating Reactors Branch 3. 1p. 19193:085. 24X Fiche: 90-335.83/06/28.8307050016.
- 8307050023 Forwards response to Generic Ltr 82-33, Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability."

  BAYNE, J. P. Power Authority of the State of New York. JPN-83-60. 83706/30. VASSALLD. D. B. Operating Reactors Branch 2. 2pp. 19220: 310. 24x Fiche: 50-333, 83706/30, 8307050023.
- --8307050029 Rev O to "Technical Guidelines for Emergency Operating Procedures" LISEND, R., CHILDS, W. N. Power Authority of the State of New York, GL-82-33, 83/06/15, 52pp. 19220; 320, 24X Fiche: 50-333,83/06/30,8307050023.
- --8307050034 Rev 3 to AP 2.2 "Procedure for Emergency Operating Procedures." W/five oversize drawings. Aperture cards are available in POR.

  \* Power Authority of the State of New York. QL-82-33. 83/06/03. 53pp. 19221:010. 24X Fiche: 50-333. 83/06/30.8307050023.
- 8307050064 Advises that environ qualification oragram for safetyrelated electrical equipment will be completed prior to fuel load. Util in compliance w/LOCFR50.49 & committed to remain so even though design grandfathered. SCHKIDT.H.C Texas Utilities Services, Inc. TXX-3997. 83/06/28. YQUNQBLOOD.N.J. Licensing Branch 1. 3pp. 19192:149. 24X Fiche: 50-445.83/06/28,8307050064.
- 8307030136 Forwards procedures for post-accident sample analysis & core damage evaluation, per NUREG-0892 (SER), Item II. 8. 8 Section 9. 3. 2. 4. GE interim dissolved gas analysis w/o krypton tracer expected by end of June 1983.
  BOUCHEY, G. D. Washington Public Power Supply System. GO2-83-557, 83706/23. SCHEMENCER, A. Licensting Branch 2. 2pp. 19199:080. 24X Fiche: 50-397.83/06/23.6307030136.
- 8307050189 Forwards "Integrated Plant Bafety Assessment Rept," for Sections 4.9,4,10.2 & 4,16.1 re effects on pipe break on components inside containment & jet impingement criteria outside containment Requests Tech Spec amend within 90 days.
  SHEA.J. Operating Reactors Branch 5. LEOS-83-06-064. 83/06/29.
  J. G. Northeast Nuclear Energy Co. (subs. of Northeast). 8pp. 19199:197 24% Fiche: 50-245, 83/06/29, 8307050189.

- 8307050211 Responds to Nov 1781 SER, subsequent suppl & correspondence & Generic Ltr 82-33, Suppl 1 to NUREO-0737 requirements for emergency response capabilities. Human factors study & status rept re historical parthquake data encl.

  VAN BRUNTLE. Arizone Public Service Co. GL-82-33. 83/06/30. KNIOHTON, G. Licensing Branch 3. 5pp. 17194:183. 24X

  Fiche: 50-528, 83/06/30, 8307050211.
- B307050224 Responds to approval request for info collection re NUREG-0737 concerning clarification of TMI action plan requirements & related orders. Request approved through B50930 under GMB Number 3150-0065. BCURRY.N. Office of Management & Budget. GMB 3150-0045. BCUTT.S. Document Management Branch. 2pp. 19261:029.
- B307050226 Responds to Generic Ltrs 92-28 & 82-33 & NUREG-0737. Item 11. F. 2 re detection on imadequate core cooling. Reactor vessel level instrumentation sys will be installed before fuel load, for operator training & familiarization. MILLS.L.M. Tennessee Valley Authority. GL-82-33. B3/06/29. ADEN9AM.E. Licensing Branch 4. 2pp. 19198:393. 24X Fiche: 50-390,83/06/29,8307050226.
- 8307080263 Discusses evaluation of emergency plan against requirements of App E to 10CFR50.Plan acceptable.Forwards Suppl 1 to SER (NUREO-0882).W/o encl.
  THOMAS.C.O. Standardization & Special Projects Branch. 83/06/14.
  ADCOCK.B. Defense. Dept. of. Defense Nuclear Agency. 2pp. 19261:021. 24% Fiche: 50-170:83/06/14.8307050263.
- 8307050270 Forwards marked-up FSAR pages for incorporation into amend to show conformance w/SRP (NUREQ-0B00).
  80UCHEY, G. D. Washington Public Power Supply System. G03-83-481.
  83/06/16. KNIGHTON.G.W. Licensing Branch 3. 11pp. 19199; 282. 24X
  Fiche: 50-508.83/06/16,8307050270.
- B30705028B Responds to B30512 ltr informing NRC that License Condition 2.C(21)(i)(iv) re containment high-range radiation monitors; satisfied per NUREO-0737. Item II.F. I. In-situ calibr of containment high-range monitors verified.
  CLARK, R. A. Operating Reactors Branch 3. B3/06/15. STEMART, W. L. Virginia Electric & Power Co. 2pp. 19263:219. 24X Fiche: 50-339.83/06/15.830705028B.
- B307050333 Forwards draft technical evaluation rept. "Control of Heavy Loads at Nuclear Power Plants, LaSalle Units 1 & 2 (Phase II)." based on response to Section 5.1 of NUREQ-0612. SCHWENCER.A. Licensing Branch 2. B3/06/21. FARRAR.D.L. Commonwealth Edison Co. 2pp. 19262:007. 24x Fiche: 50-373, 83/06/21. B307050333.
- --8306240037 "Control of Heavy Loads at Nuclear Power Plants, LaBalle Units 1 & 2 (Phase II)," draft technical evaluation rept. JEMSEN, S. A., STICKLEY, T. H. EG&O, Inc. FIN A~6457. 83/05/31. NRC No Detailed Affiliation Given. 21pp. 19262:009, 24X Fiche: 50~373, 83/06/21, 8307050333.
- 8307050432 Forwards SER on review of 801215,820514 & Q615 submittals re TMI Action Plan Items II.F. 1.4, "Containment Pressure Monitor," II.F. 1.5, "Containment Water Level Monitor," & II.F. 1.6 "Containment Hydrogen Monitor," CLARK, R. A. Operating Reactors Branch 3, 83/06/17, GARRITY, J. H. Maine Yankee Atomic Power Co. 8pp. 19262:346. 24X Fichs: 50-309,83/06/17,8307050432.
- B307050450 Forwards safety evaluation re NUREC-0737.TMI Items II.F. 1.4, "Containment Pressure Monitor." II.F. 1.5, "Containment Water Level Monitor." & II.F. 1.6, "Containment Hydrogen Monitor." Items resolved.

  VARGA:S.A. Operating Reactors Branch 1. B3/06/14, BAYNE, J.P. Power Authority of the State of New York. Spp. 19262:281, 24X Fiche: 30-286, B3/06/14, B307050450.
- B307030465 NUREC/CR-2883 V01
  STUDY OF THE VALUE AND IMPACT OF ALTERNATIVE DECAY HEAT
  REMOVAL CONCEPTS FOR LIGHT WATER REACTORS.
  BERRY, D. L., SANDERS, Q. A. Sandia Laboratories, FIN A-1226.
  SANDB2-1796. B3/06/30. Division of Risk Analysis. 100pp
  19264; 016.
- 8307050471 NUREG-0938
  INFORMATION FOR ESTABLISHING BIOASSAY MEASUREMENTS AND EVALUATIONS OF TRITIUM EXPOSURE.
  BRODSKY.A. Division of Facility Operations. 83/06/30, 34pp.
  Available at NRC. 3.75. 19263:341.
- 8307050479 NUREG-0974
  DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF
  LIMERICK GENERATING STATION, UNITS 1 AND 2. Docket Nos. 30-352
  And 30-353 (Philadelphia Electric Company)
  \* Division of Licensing 83/06/30. 33ipp. 19261:035. 24X
  Fiche: 50-352:83/06/30.8307050479.

- 8307050483 NUREG-0485 V05 ND5 SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As OF May 31,1983 (Buff Book) \* Division of Data Automation & Management Information. \* of Nuclear Reactor Regulation, Director. 83/06/30 67pp. 19264:200.
  - ion. \* Office 67pp.
- 8307050490 NUREG-0994 307030490 NUREG-0994
  ENVIRONNENTAL IMPACT APPRAISAL RELATED TO SPECIAL NUCLEAR
  MATERIALS LICENSE ND. SNM-696. Docket No. 74-734.
  (GA Technologies, Inc.)
  \* Division of Fuel Cycle & Material Safety. G3/06/30, 69pp
  19264: 122.
- 8307050522 Notifies of CRGR Meeting 41 on 830706 in Mashington BC to review final rulemaking re fitness for duty for personnel w/unescorted access to protected areas & NUREG-0847, "SRP for Review & Evaluation of Emergency Plans for Research..."

  97ELLG.V. Committee to Review Generic Requirements. 83/06/24. MATTSON,R.J. Division of Systems Integration (post 81005). JCRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). GUNNINGHAM,R.E. Division of Fuel Cycle & Material Safety. 87pp. 19262:172.
- 8307060021 Discusses review of results of Rev 15 to emergency plan submitted by 821217 ltr per App E of 100FR50. Section 50. 47 & Reg Guide 1. 101, Rev 2 which endorses NUREG-0654. Deficiencies still exist in emergency plan. NURDERHAUG.L. R. Region 3. Office of Director. 83/06/20. RODRIGUEZ.R. J. Sacramento Municipal Utility District. 5pp. 19251:042. 24X Fiche:50-312.83/06/20.8307060021.
- 83070&0034 Requests determination of NRC ofc responsible for review of Tech Spec Section 6.0 re administrative controls per 878 (NNREG-0452), by 830715. Jul meeting w/reviewers requested to effect tentative agreement by 830815.

  BCHNELL, D.F. Union Electric Go. ULNRC-641. 83/06/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19251:148. 24x Fiche: 50-483, 83/06/30, 8307060034.
- 8307060045 Responds to SER Suppl 2 (NUREG-0892) & TMI Action Item II.K.3.28 re surveillance requirements to ensure operability of back-up air supply sys. Requirement on calibr of bottle gauges contested & not included in Tech Spacs.

  BOUCHEY. O. D. Washington Public Power Supply System. GO2-83-552.

  83706/22. SCHMENCER. A. Licensing Branch 2 2pp. 19250: 338 Fiche: 50-397, 83/06/22, 8307060045.
- B3070&0078 Submits schedule changes for NUREQ-0737, Item II.B.3.

  "Post-Accident Sampling Capability." Post-accident sampling sys will not be fully operational by B30701. Clarifications of util B21217 responses encl.

  BROEHL.D. J. Portland General Electric Co. B3/06/28. EISENHUT.D.G. Division of Licensing. 5pp. 19238: 241. 24X Fiche: 50-344, 83/06/28, B307060078.
- 8307060081 Suppls 810121 ltr re implementation of NUREG-0619 "BWR Feedwater Nozzle & Control Rod Drive Return Line (CRDRL) Nozzle Cracking." Feedwater low flow controller installed on both units. Detailed rept scheduled for 830930.

  DALTROFF. S. L. Philadelphia Electric Co. GL-81-ii. 83/06/30. EISENHUT. D. G. Division of Licensing. 2pp. 19291:394. 24X Fiche: 50-277, 83/06/30, 8307060081.
- 8307060090 Responds to Suppl 1 to SER & Generic Ltr 82-33, Suppl 1 to NUREG-0737 re emergency classification sys. Enci Section 5.0 will be incorporated in Amend 49 to GL application. DEVINCENTIS.J. Yankee Atomic Electric Co. GL-82-33. 83/06/27. KNIGHTON.G.W. Licensing Branch 3. 18pp. 19251:149. 24X Fiche: 50-443.83/06/27.8307060090.
- 8307060095 Responds to Containment Sys Branch draft SER Open Item 68. Add1 failure alarm located within control room unnecessary. Continuous indication will be functioning within 30 minutes of safety injection initiation per TMI Item II.F. 1. MCDUFFIE.M.A. Carolina Power & Light Co. LAP 83-250. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 19252:008. 24X Fiche: 50-400.83/07/01.8307060095.
- B307060111 Forwards responses to draft Chemical Engineering Branch SER Open Items 146 & 147 re schematics of sample lines & panels (per TMI Item II.B.3) re post-accident sampling sys.

  MCDUFFIE, M.A. Caroline Power & Light Co. LAP-83-253. B3/06/30.

  DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp 19252:214. 24X Fiche: 50-400.83/06/30.8307060111.
- 8307060139 Forwards add1 info on mild environ, per NUREG-0737, Items II, F. 1.4 re containment pressure monitor, III, 5 re containment water level monitor & II, F. 1.6 re containment hydrogen monitor, in response to 830601 telecopy itr.
  FIEDLER.P. B. General Public Utilities GPU Service Corp. 83/06/30.
  CRUTCHFIELD. D. Operating Reactors Branch 5. 5pp. 19250:195. 24X Fiche: 50-219, 83/06/30, 8307060139.

- 8307040177 Forwards response to 830511 request for add1 info re NUREO-0737. Item II X. 3.28, "Qualification of Automatic Depressurization Sys (ABS) Accumulators." Current sys provides Sufficient capacity to meet FSAR requirements MCGAUGHV.R.W. Iowa Electric Light & Power Co. NG-83-2223. 83706/30 DENTON,H R. Office of Nuclear Reactor Regulation, Director 12pp. 19249: 234. 24X Fiche: 50-331.83/06/30.8307060177.
- B30704017B Forwards "Procedures Generation Package." in response to Generic Ltr 82-33. Suppl 1 to NUREG-0737 re emergency response capability.
  SCHUYLER, J. O. Pacific Gas & Electric Co.: GL-82-33. 83/07/01. EIGENHUT, D. G. Division of Licensing. 1p. 19249:244. 24X Fiche: 50-275, 83/07/01, 8307040178.
- --8307060180 "Procedures Generation Package." SEXTON, J. A. Pacific Gas & Electric Co. GL-82-33: 837 37pp. 19249: 247. 24% Fiche: 50-275, 83707/01, 8307060178 83/06/24
- 8307060184 Forwards SER accepting corrective actions proposed in 830316 5 0422 submittals for resolving leakage detection systissues raised in integrated plant safety assessment rept (NUREO-0821), Section 4.13.
  CRUTCHFIELD. D. Operating Reactors Branch 5. LS05-83-06-062.
  83706/28. MAIER. J. E. Rochester Gas & Electric Corp. 3pp. 19236:056. 24X Fiche: 50-244.83/06/28.8307040184.
- --8307060187 SER accepting licensee actions proposed in 830316 & 0422 submittals to resolve leakage detection sys issues raised in integrated plant safety assessment rept (NUREG-0821), Section 4.13.

  \* Office of Nuclear Reactor Regulation, Director, 83/06/28. 3pg Office of Nuclear Reactor Regulation, Director. 83/06/28.
   19236: 059. 24% Fiche: 50-244, 83/06/28, 8307060184.
- 8307060218 Informs that NUTECH analysis indicated that low-flow control mod & reactor water cleanup sys crosstie mod detailed in NUREG-0619, not required at facility. Vendor rept will be submitted by 830816.
  MILLS,L.M Tennessee Valley Authority. 83/07/01. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19248:361. 24X Fiche: 50-259,83/07/01,8307060218.
- 8307060227 Notifies that submittal of generic program w/B&H Owners Oraup, in support of revised manual reactor coolant pump trip criteria per NUREO-0737. Item II. K. 3. 5. delayed until 830930. WESTAFER, G. R. Fiorida Power Corp. 3F-0783-02. 83/07/01. EISENHUT, D. 0. Division of Licensing. 1p. 19249: 034 24X Fiche: 50-302.83/07/01.8307060227.
- 8307060234 Forwards responses to Procedures & Sys Review Branch draft SER Open Items 194.193 & 217. Responses cover NSSS review of low-power testing, power ascension & emergency operating procedures per NUREG-0737.
  MCDUFFIE,M.A. Carolina Power & Light Co. LAP-83-234 83/07/01.
  DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 19239: 356 24X Fiche: 50-400.83/07/01.8307060234.
- 8307060257 Forwards "Detailed Control Room Design Review Program Plan for SNUPPS." in response to Generic Ltt 82-33, Suppl 1 to NUREO-0737. "Requirements for Emergency Response Capability." PETRICK, N.A. Standardized Nuclear Unit Power Plant System. QL-82-33. 83/06/30. DENTON. H.R. Office of Nuclear Reactor Regulation, Director. 1p. 19238:263. 247 Fiche.50~000,83/06/30, 8307060257.
- --8307060264 "Detailed Control Room Design Review Program Plan for NVM0665-SNUPPS." \* Standardized Nuclear Unit Power Plant System OL-82-33. 83/06/30. 17pp. 19238:264. 24X Fiche:50-000:83/06/30:8307060257.
- 8307060258 Comments on DES (NUREG-0972) re plant operation Requesting public comments after decision supporting issuance of OL made inappropriate.

  LOTCHIN.P. Affiliation Unknown. 83/07/01. Division of Licensing. 3pp. 19239:303. 24X Fiche:50-400.83/07/01.8307060258.
- 8307060263 Forwards safety evaluation of SEP Topic III-1 re integrated plant SAR (MUREO-0821). Section 4.7. "Classification of Structures. Sys & Components." Info supplied B30124 acceptable to resolve open items in Section 4.7. CRUTCHFIELD. D. Operating Reactors Branch 5. LS05-83-06-061. B3/06/28. MAIER, J.E. Rochester Gas & Electric Corp. 9pp. 19239: 294. 24x Fiche: 50-244.83/06/28.8307060263
- B307060265 Forwards "St Lucie Units 1 % 2.Turkey Point Units 3 % 4 Detailed Control Room Design Reviews Program Plan." per util 830415 commitment re Suppl 1 to NUREG-0737.
  UHRIG.R.E. Florida Power & Light Co. L-83-383. 83/06/30. EISENHUT.D. G. Divisjon of Licensing. 1p. 19239:184. 24X Fiche:30-389.83/06/30.8307060265.

- 8307060269 Advises that 820426 response to restart SER (NUREO-0916) item 17 re early operation of loose parts monitoring sys reviewed & installation & operation of sys should assure continued safe operation of plant Item 17 resolved. CRUTCHFIELD.D Operating Reactors Branch 5. LSU5-83-07-001. 83/07/01. MAIER, J. E. Rochester Gas & Electric Corp 2pp. 1929: 182. 24x Fiche: 50-244,83/07/01,8307060269.
- 8307060270 Requests mod to NRC 830330 order confirming licensee commitments on post-TMI-related issues, allowing extension for implementation of NUREG-0737, Item II 8.3, "Post-Accident Sampling," to 830901.

  GUCWA, L. T. Georgia Power Co. NED-83-374, 83/06/28, STOLZ, J. F. Operating Reactors Branch 4, 2pp. 19239; 166, 24X Fiche: 50-321, 83/06/28, 8307060270.
- 8307060275 Responds to 830602 ltr re violations & proposed imposition of civil penalties noted in IE Insp Repts 50-269/83-11. 50-270/83-11 & 50-287/83-11. Corrective action: procedures per THI Item I. C. 6 reviewed. TUCKER. H. B. Duke Power Co. 83/07/01. Director's Office of Inspection and Enforcement. 21pp. 19238:352. 24x Fiche: 50-269,83/07/01,8307060275.
- 8307060277 Forwards revised rept providing add1 info in response to SER Confirmatory Issue 21 re suppression pool temp limits. Rept addresses plant-specific info, analyses & assumptions to meet requirements & criteria given in NUREG-0783. EDELMAN.M.R. Cleveland Electric Illuminating Co. PY-CEI/NRR-005783/06/29. YOUNGBLOOD, B. J. Licensing Branch i. 15pp. 19234: 191. 24X Fiche: 50-440,83/06/29,8307060277.
- B30706036B Forwards responses to NRC findings of Power Sys site audit conducted on 830406-07.per SER.NUREO-0837.

  VAN BRUNT, E. E. Aftiona Public Service Co. ANPP 24226-HFQ/.
  B3/07/01. KNIGHTON.G. Licensing Branch 3. 11pp. 19236: 22B. 24X
  Fithe: 50-528,83/07/01,8307060368.
- B307060413 Forwards review & evaluation of emergency plan against App E to 10CPR50 requirements & Rev 1 to Reg Guide 2.6. Plan acceptable & should be implemented within 120 days. THOMAS.C.O. Standardization & Special Projects Branch. 83/06/24. KERR.W.F. Michigan. Univ. of. 4pp. 19299-351. 24X Fiche: 50-002.83/06/24,8307060413.
- B307060481 Advises that onsite & offsite emergency preparedness adequate & plans upgraded per NUREG-0737. Item III.A.2.1. Item complete.

  STOLZ.J.F. Operating Reactors Branch 4. B3/06/17. CRDUBE.R.P. Toledo Edison Co. 2pp. 17279: 124. 24X Fiche: 50-346.83/06/17. 8307060481.
- 9307070006 Forwards revised Vols 1-3 to "Environ Equipment Qualification Rept for Safety-Related Equipment." Rev provides response to concerns raised in Suppl 3 to SER (NUREG-0872).
  BUCKEY, 6. D. Washington Public Power Supply System. IEB-79-01B. 83/06/30. SCHWENCER, A. Licensing Branch 2. 3pp. 17295:138. 24X Fiche: 50-397, 83/06/30. 83070700066.
- --8307070013 Revised Vols 1-3 to "Environ Equipment Qualification Rept for Safety-Related Equipment." \* Washington Public Power Supply System. IEB-77-018. 83/07/31. 1220pp. 19275:141. 24X Fiche: 50-397,83/06/30,8307070006.
- 8307070021 Advises that installation & calibr of SA-11 monitors complete & monitors fully operational per TMI Item II.F.i.l. Integration of instruments into other plant operating & smergency procedures & operator training incomplete. FAY.C. W. Hisconsin Electric Power Co. 83/06/29 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19293;232. 24x Fische; 50-266,83/06/29,8307070021.
- B307070054 Forwards comments on DES re operation of facilities (NUREO-0972). Opinions & calculations presented do not necessarily reflect Pennsylvania State Univ position. LOCHSTET.W.A. Pennsylvania State Univ. B3/06/30. Division of Licensing. 5pp. 19293: 261. 24X Fiche: 50-400. B3/06/30, B307070054.
- 8307070083 Forwards comments on DES, NUREQ-0972 Marked-up DES pages correcting typographical errors & containing minor comments encl.

  HURFORD, N. J. Carolina Power & Light Co. LAP-83-290. 83/07/05.

  EISENHUT, D. G. Division of Licensing. 20pp. 19293:138. 24x

  Fiche: 50-400,83/07/05,8307070083.
- B307070103 Submits supporting info on lifting devices to be used in transporting activated reactor components to licensed disposal site. Design of proposed lifting device adequate to withstand dynamic loads imposed by overhead handling sys. BINCLAIR. J. B. Vermont Yankee Nuclear Power Corp. EVY83-67. B3/07/05. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 19274:115. 24% Fiche: 50-271.83/07/05.8307070103.

- 8307070110 Comments on NRC policy statement on safety goals re evaluation plan & proposed rule 10CFR50 re policy statement on severe accidents & related views on nuclear reactor regulation. W/respect to value of PRA studies. BIALIK,E. I. New York, State of. 4BFR(4014, B3/06/30, Docketing & Services Branch. 1p. 19294:092.
- 8307070110 Comments on NRC policy statement on safety goals research on plan & proposed rule 10CFR50 responsed to statement on severe accidents & related views on nuclear reactor regulation w/respect to value of PRA studies.

  BIALIK.E. I. New York, State of, 48FR10772 023, 83/06/30, Docketing & Services Branch, 1p. 19294:092.
- 8307070114 Comments on proposed rule 10CFR50 re policy statement on severe accidents & related views on nuclear reactor regulation. Opposes use of PRA studies.
  BIALIK.E.I. New York, State of, 48FR16014 006. 83/06/30. Docketing & Services Branch. ip. 17293:345.
- B307070115 Forwards "Pressurizer Safety & Relief Line Evaluation Summary Rept," per TMI Item II.D.1 containing results of second iteration of thermal hydraulic evaluation & structural analysis on piping & supports. CAREY. J. J. Duquesne Light Co. B3/06/24. VARGA. S. A. Operating Reactors Branch I. 2pp. 19267:265. 24X Fiche: 50-334, 83/06/24, 8307070115.
- --B307070119 "Pressurizer Safety & Relief Line Evaluation Summary Rept."
  NO.C.K. Westinghouse Electric Corp. SMITH.L.C., CHANG.K.C.
  Duquesne Light Ca. B3/06/30. 71pp. 19267:267. 24X
  Fiche: 50-334, 83/06/24, 8307070115.
- 8307070128 Forwards response to 830511 request for add1 info re NUREG-0737. Item II. K. 3. 28, "Qualification of Automatic Depressorization Sys (ADS) Accumulator Sys." Accumulator leakage is of negligible concern.
  ZIMMERMAN.S.R. Carolina Power & Light Co. LAP-83-282, 83/07/05, VASSALLO.D.B. Operating Reactors Branch 2, 18pp. 19294:138, 24x Fiche: 50-324,83/07/05,8307070128.
- 8307070143 Comments on proposed rule re NRC policy statement on safety goal development program Opposes rule. FREY.D.G. Sassafras Audubon Society. 48FR10772 024. 83/07/03. Office of the Secretary of the Commission. 1p. 19274:160.
- B307070176 Forwards plant-unique analysis rept, Vols 1-7, demonstrating primary containment sys design adequacy & restoration of original design safety margins per NUREO-0661. RYBAK, B. Commonwealth Edison Co. 6846N. B3/06/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19290:001. 24X Fiche: 50-000, B3/06/27, B307070176.
- 8307070178 Submits partial response to 821203 request re Generic Item 8-24 & NUREG-0737, Item II. E. 4. 2 for proposed Tech Specs incorporating seal leakage test of containment purge & vent valves. Rev to license will be submitted by 830831. CROUSE. R.P. Toledo Edison Co. 963. 83/06/30. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19269:335. 24X Fiche: 50-346,83/06/30,8307070178.
- 8307070232 Forwards synopsis of issues associated w/NUREG-0612 recontrol of heavy loads, as discussed in 830617 telcon.
  Responses to open issues must be provided within 30 days of ltr date.
  VARGA.S.A. Operating Reactors Branch 1. 83/06/21. OIESLER.C.W. Wisconsin Public Service Corp. 13pp. 19362:227. 24X Fiche: 50-305.83/06/21.8307070232.
- 8307070515 Forwards evaluation of emergency plan per requirements of App E to 10CFR50 & Rev 1 to Reg Guide 2.6. Plan acceptable. Implementation should be accomplished within 120 days.

  THOMAS.C.O. Standardization & Special Projects Branch. B3/06/24. CLARK.L. Massachusetts Institute of Technology. 3pp. 19300:339. 24X Fiche: 50-020, 83/06/24, 8307070515.
- 8307080030 Forwards response to NRC 830511 itr requesting add1 info re TMI Item II.K.3.28, "Qualification of Automatic Depressurization Sys (ADS)." Designated allowable leakage criteria for ADS is zero.

  MUGDLF, D. Northern States Power Co. 83/06/28. Office of Nuclear Reactor Regulation, Director. 6pp. 19351:316. 24X
  Fiche: 50-263,83/06/28.8307080030.
- B307080169 Generic Ltr B3-28 to all licensees of operating reactors, applicants for OL & holders of CPs re required actions based on generic implications of Salem ATWS events. Svc list encl. EIEENHUT.D. G. Division of Licensing. GL-B3-28. 83/07/08. Consolidated Edison Co. of New York, Inc. 38pp. 19669:269. 24X Fiche: 50-000, 83/07/08, 8307080169.

- 9 Forwards backfit cost figures for add1 seven utils per 1 B3020B request Cost figures for 20 utils tted 830411. LDTTE.J Regulatory Reform Task Force. B3/06/22. ND.N. Commissioners 2pp. 19360:313. 24X 9-000.83/06/22.8307080259.
- 321 Forwards backfit cost info for facility.per NRC 830208 at Category 1 imposed by NRC regulations/orders, pry 2 imposed by NRC bulletins & NUREG-0737 rements & Category 3 initiated by util.

  J.D. Consumers Power Co. 83/04/14 TOURTELLOTTE, J. story Reform Task Force. 5pp. 17363:315, 24X; 50-000.83/06/22,8307080259.
- 3 Forwards safety evaluation re util responses to NUREG-0737, I.F. 1.4, "Containment Pressure Monitor," II.F. 1.5, ment Water Level Monitor," & II.F. 1.6, "Containment 1 Monitor." Items resolved.

  A. Operating Reactors Branch 1, 83/06/09, DOLAN, J. & Michigan Electric Co. 9pp. 19363: 304, 24X 0-315,83/06/09,8307080288.
- 7 Interim deficiency rept. Item M-87, re-design control process ate-to-assure design output documents contain a erection & insa criteria. Initially reported on deportability per IOCFR30. 55(e) not yet determined. B. J. Cincinnati Gas & Electric Co. 10CFR 050. 55E. 83/06/30. V. J. G. Region 3, Office of Director. 2pp. 19350:147. 24X 3-358.83/06/30.8307080327.
- 3 Forwards program description & schedule for resolving 737, Item II.K.3.5, "Automatic Trip of Reactor Coolant Program completion scheduled for end of 1983. Results jais & training dates will be communicated by 831231. W.9. Northeast Nuclear Energy Co. (subs. of Northeast 29). COUNSIL.W.9. Northeast Utilities A03074. B3/07/01. F.D.0. Division of Licensing. 7pp. 19350:306. 24X >-336.83/07/01.8307080353.
- ) Forwards response to 830610 request for add1 info relogy used to perform safety analyses supporting Cycle ion. Analyses performed based on C-E Owners Group 4-199 in response to NURSO-0737.1 tem II. K. 2.17.
  N. Q. Northeast Nuclear Energy Cn. (subs. of Northeast 18). COUNSIL.N.Q. Northeast Utilities. A03323. 83/07/01.
  A. Operating Reactors Branch 3. 9pp. 19349:315. 24X 3-336.83/07/01.8307080400.
- Forwards "Program Plan For Control Room Human Factors Review in Creek Nuclear Generating Station," per emergency : capabilities.
  P. B. General Public Utilities GPU Service Corp. 63/07/01.
  FT.D.O. Division of Licensing. 2pp. 17347:288. 24X
  3-219:83/07/01:8307080424.
- 126 "Program Plan for Control Room Human Factors Review at Creek Nuclear Genorating Station." aral Public Utilities GPU Service Corp. 83/06/30. 96pp. 290. 24X Fiche: 50-219, 83/07/01, 8307080424.
- Forwards safety evaluation of util B21203 response to ed plant safety assessment rept (NUREO-0024), Section ventilation sys.Loss-of-ventilation tests by procedural & design mods acceptable.

  Operating Reactors Branch 5. L909-B3-07-002. B3/07/05. W.Q. Northeast Nuclear Energy Co. (subs. of Northeast s). 2pp. 19346:152. 24X Fiche: 50-245, B3/07/05, B3070B0434.
- 39 Bafety evaluation accepting util 821203 response to ated plant safety assessment rept (NUREO-0824), Section re ventilation sys, based on listed procedural & re mods.
  ice of Nuclear Reactor Regulation, Director. 83/07/05. 5pp.: 154. 24x Fiche: 50-245, 83/07/05, 8307080434.
- Forwards response to Reg Guide 1.97. Rev 2 "Instrumentation to Hater Cooled Nuclear Power Plants to Assess Plant ns During & Following Accident," per NUREG-0737, re emergency response capability.

  1. Louisiana Power & Light Co. 83/07/06. DENTON, H.R. f Nuclear Reactor Regulation, Director. 47pp. 19347:158.
- Comments on NRC policy statement on evaluation plan for oal development program.

  Yakima Indian Nation. 48FR10772 025, 83/06/30, CHILK.8.J. f the Secretary of the Commission. 2pp. 19347:205, 24X -522,83/06/30,8307080445.

- ---8307080452 Comments on DES for Stagit/Hanford Nuclear Plant E1S flawed in scope & content & fails to recognize existence of Yakima Indian Nation. Not significant adverse impact addressed. Comment may not be used in proceedings.

  JIM.R. Yakima Indian Nation. 48FR10772 025. 83/06/30. BLACK.R. NRC No Detailed Affiliation Given ip. 19347 221. 24X Ficha 50-522,83/06/30,8307080445
- 8307080456 Memorandum & order denying State of NM 830526 objections to ASLB 830511 memorandum & order granting summary disposition of State of NH Contentions 9 & 13.

  HOYT.H.F. Atomic Safety and Licensing Board Panel ISSUANCES OL. 83707706 New Hampshire. State of. 9pp. 19347:228. 24X

  Fiche: 50-443: 63/07/06: 8307080456.
- B3070B0300 Forwards FR notice of availability of DES (NUREG-0974). SCHWENCER.A. Licensing Branch 2. 83/06/24, CHERRY.M. Cherry. M.M./Cherry. Flynn & Kanter. 4pp. 19365:051. 24x Fiche: 30-352, 83/06/24,8307080500.
- --8307080510 Notice of availability of DES (NURE9-0974). SCHWENCER.A. Litensing Branch 2. 83/06/24. 3pp Fiche: 30-382,83/06/24,8307090500. 19365: 055. 24X
- --B3070B0322 Forwards notice of availability of DES (NUREO-0974). Request for comments being sent to appropriate agencies FES will be prepared after receipt of comments.

  BCHWENCER.A. Licensing Branch 2. 83/05/24. WILSON.K.
  Environmental Protection Agency. 1p. 19365:058. 24X
  Fiche: 50-382.83/04/24.8307080500.
- --8307080525 Advises that DES issued. Notice of availability encl. W/o DEG. BCHWENCER:A. Licensing Branch 2. 83/06/24. BAUER,E.G. Philadelphia Electric Co. 4pp. 19365:059. 24X Fiche:50-352,83/06/24,8307080500.
- --B307080527 Forwards DEB (NUREO-0974) for review & comments Comments are due within 45 days after FR publication.W/o encl. SCHNERGER.A. Licensing Branch 2. 83706/24. HDDD.J M. Commerce, Dept. of, Natl. Oceanographic & Admospheric Administration. 3pp 19365:063. 24X Fiche:50-352,83706/24,8307080500.
- 8307080543 Forwards Equipment Gualification Branch request for addl into re NUREO-0737. Item II. D. 1 re review of NEDE-24988-P. For specific safety/relist valves employed at plant, applicability of generic test results must be justified. BCHMENCER.A. Licensing Branch 2. 83/06/27. BAUER, E. G. Philadelphia Electric Co. 4pp. 19365:043. 24X Fiche: 50-352,83/06/27,8307080543.
- B307080590 NUREO/CR-3236 REPORT ON TRACE OAB MEASUREMENT DY LASER IDNIZATION WITH APPLICATION TO ELECTRICAL INSULATOR AGING STUDIES. BMITH.A.V. Sandia Laboratories. FIN A-1051. SANDB3-0635. 83/06/30. Division of Engineering Technology. 19pp. 15 19365: 301.
- 8397080892 NUREQ/CR-3304
  MECHANISTIC MODELING AND CORRELATIONS FOR POOL ENTRAINMENT PHENOMENON.
  KATAGKA, I., ISHII, M. Argonne National Laboratory. FIN A-2 ANL-83-37. 83/04/30. Division of Accident Evaluation. 19365: 323.
- 8307080996 NUREG/CR-3007
  INVESTIGATION INTO THE FEASIBILITY OF ALTERNATIVE PLUTONIUM
  SHIPPING FORMS
  MISHIMA.J., LINDSEY.C.Q. Battelle Memorial Institute, Pacific
  Northwest Laboratory, FIN 8-2424, PNL-4307, 83/06/30, Div.
  of Risk Analysis. 166pp. Available at NRC, 96.00 19365:135. Division
- 8307080602 NUREG/CR-3338

  FLOW REGIME TRANSITION CRITERIA CONSISTENT WITH TWO-FLUID MODEL FOR VERTICAL TWO-FMASE FLOW.
  MISHIMA.W. JEHILM. Argonne National Laboratory FIN A-2026.
  ANL-83-42 83/06/30. Division of Accident Evaluation. 3891 19365-073
- B307080605 Requests enci comments & responses re NUREG-0933, "Prioritization of Generic Safety Issues" be placed in PDR SPEIS, T.P. Division of Bafety Technology B3/06/21. Pr Document Branch. 1p. 19364:242.
- --8307080609 Comments on draft NUREQ-0933, "Prioritization of Generic Safety Issues." NRR has taken important first step in resolving large number of safety & licensing matters. Conservative estimates unnecessary for ranking. REULAND. D. Electric Power Research Institute. 83/04/19. MINNERS.W. Office of Nuclear Reactor Regulation. Director. 15pp. 19364:243.

G337080h4v Forwards "Control of Heavy Loads Et Lucie Flant.Unit 2 (Phase II. 1 technical evaluation rept MMIGHTON 9 H Libersing Branch 3 TAC 47015 63/06/17 UHRIO.R.E. Flants Filen b Light Ch. 2pp 19354 180 24X Fische 50-589-83/06/17,8397089445

9307090130 MM969/CR-2970 VO2 MATERIALS SCIENCE & TECHNOLOGY DIVISION LIGHT-WATER-REACTOR SEFETY RESEARCH PROGRAM Quarterly Progress Report. REACTOR EFFECT HOSEMACH PROGRAM
Appil-June 1982
SHACK, M. J., REST. J., HASEMER. T. F. Argonne National Laboratory, FIN
A-2016 ANT-82-42 VCL 2 83/05/30 Division of Accident
Evaluation 115pp 19365-145

830711000" Responds to NAC request for add1 info re SER Confirmatory Issue 7. "Component Supports " Results of evaluation in Phase II indicate that I75 supports & 1c anchors acceptable BCUCHEV. G D. Washington Public Power Supply System. GO2-83-584. 83706/33. SCHMERGER.A. Licensing Branch 2. Ilpp. 19374; 214, 24 Fiche 50-397.63706/33.8307110007.

E30711G012 Forwards response to RER Section 7 7 2. Question 222.03 re qualification of control sys Response closes open item in Section 7 7 2 6 unil be incorporated into upcoming FBAR amend VAN BRIVATIE E Arisona Public Service Co ANPP-24225-WFQ/. B3/07/01 WHIGHTON 6 Licensing Brench 3 6pp. 19374:205. 24X Fiche 30-528-83/07/01.8397110012.

E307110053 Responds to 830531 Itr transmitting draft technical evaluation rept re-control of heavy loads. Comparison of Westinghouse spec for manipulator cranes u/ANSI 830-2 releaved devices meet both specs 100KER. H 9 Duse Power Co. 83/06/28 DENTON, H R. Office of Nuclear Reactor Regulation, Director. ADENSAM. E. G. Licensing Branch 4 Zpp 19375-245 24x Fiche. 50-413. 83/06/28. 8307110053.

G307110055 Submits updated schedule for completion of responses to NUREG-0737 Suppl I on emergency response capability resafety parameter display sys Update based on reevaluation of fuel loaf schedule.

GRUMHOND: F.J. Louisiana Power & Light Co. H3P63-2215, 83/07/05 KNIGHTCN: G.H. Litensing Branch 3. 2pp. 19375:243 24x Fiche 50-362,83/07/05.8307110055.

8:307110075 Forwards two copies of Suppl 2 to SER (NUREG-0830, Suppl 2). 

B307110382 NURRO/CR-2843 V03 N4
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM GUARTERLY
REPORT, ULLY-SEPTEMBER 1982
THOMPEGN-9 L Sandia Laboratories. FIN A-1205. SAND82-1788.
B3/06/20 Division of Accident Evaluation Bipp. 19388:099.

8307110087 NUREG/CR-2915

SO/FIDORAY NUMBER CR. 2915
INITIAL QUIDANCE OF DIGRAPH-MATRIX ANALYSIS FOR SYSTEMS
INTERACTION STUDIES
ALESSO, H P. SACMS, I J., SMITH, C.F.
FIN A-0403 UCID-19457, 83/03/31 Division of Safety Technology,
5800 Available at NRC \$4.75 19288-013.

B3071100B9 NUREC/BR-00B9 NRC CLASSIFICATION GUIDE FOR SAFEGUARDS INFORMATION • Division of Security 63/05/31, 22pp 19388 0

B307110097 Forwards safety evaluation re BWR Dwners Group response to THI Item II x 3 18. "Mod of Automatic Depressurization Sys " Elimination of high dryvell pressure permissive & bypass after sustained low water level acceptable VASSALLID D Operating Reactors Branch 2 B3/06/03. MUSQLF, D. M. Fiche 53-263, 83/06/03, 8307110399

@307110124 NUREGICR-0313

RADIATION DOSE ESTIMATES AND HAZARD EVALUATIONS FOR AIRBORNE
RADIAMUCLIDES Annual Progress Report. July 1.1981-June 30. 1982
WE WHINKEY, J A Inhalation Toxicology Research Institute,
MEWHINKEY, J A Lovelace Bloned & Environmental Research Institute,
FIN A-1031 LMF-105 83/06/30 Division of Health, Siting &
Waste Management 67pp Available at NRC \$4.50 19387:305.

B-307110135 NUREG/CR-2913
THO-PHASE JET LOADS.
WEIGAND-3 © . THOMPSON,S L . TOMASKO,D Sandia Laboratories. FIN
A-1205 SANDB2-1935 83/03/31 Division of Engineering
Technology 294pp 19387-012

B307110143 Forwards list of post-accident sampling sys items identified during functional testing requiring resolution.per
NUREG-0737. Item II.B.3. Other aspects of sys acceptable.
BROEHL, D. J. Portland General Electric Co. B3/07/01. EISENHUT, D. Q. RODEHL, D. J. Portland General Electric G Division of Licensing. 3pp. 19375:028. 8307110143. 24X Fiche: 50-344, 83/07/01,

8307110228 Forwards revised emergency response capability implementation plan schedule & submittals to reflect new submittal dates of 830101 for control room review program plan & 850701 for summary rept per Supp 1 to NUREQ-0737. WULLER, G. E. Illinois Power Co. U-0647. 83/07/05. 8CHWENCER, A. Licensing Branch 2. 5pp. 19376:107. 24X Fiche: 50-461, 83/07/05, 8307110228.

B307110232 Forwards response to request for add1 info re NUREO-0737, Items II.F. 1.4.II.F. 1.5 & II.F. 1.6.re containment pressure, water level & hydrogen monitors to complete post-implementation review.

BASKIN.K.P. Southern California Edison Co. 83/07/07. CRUTCHFIELD.D. Operating Reactors Branch S. 13pp. 19380:018. 2-Fiche: 50-206, 83/07/07, 8307110232. 19380: 018. 24X

8307110287 Submits proposed schedule for completing Tech Spec review & issuance. Issuance of Tech Spec Bections 1-5 expected prior to fuel load date of 840402.

SCHNELL, D. F. Union Electric Co. ULNRC-642. 83/06/30. DENTON, H. F. Office of Nuclear Reactor Regulation, Director. 2pp. 19374: 268. 24X Fiche: 50-483,83/06/30,8307110257.

8307110275 NUREG-0540 VO5 NO3 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE March 1-31.1983. s-orives. \* Division of Technical Information & Document Control. 03/06/30, 600pp. 19388:259.

8307110270 Forwards WCAP-10230. "Evaluation of Acceptability of Reactor Vessel Head Lift Rig.Reactor Vessel Internals Lift Rig.Load Cell & Load Cell Linkage to Requirements of NUREG-0612" & responses to NRC recommendations.
ALEXICH.H.P. Indiana & Michigan Electric Co. AEP.NRC:05140.
83/07/05. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19378:332. 24X Fiche:50-315,83/07/05,8307110270.

--8307110295 WCAP-10230

"Evaluation of Acceptability of Reactor Vessel Head Lift Rig.Reactor Vessel Internals Lift Rig.Load Cell & Load Cell Linkage to Requirements of NUREO-0612."

SANDNER.H.H. Westinghouse Electric Corp. AEP:NRC:05140. B3/04/30. 150pp. 19378:334. 24X Fiche:50-315.83/07/05, 8307110290.

B30711030B NUREG/CR-2843 V04
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM GUARTERLY
REPORT, OCTOBER - DECEMBER 1982.
THOMPSON, S. L. Sandia Laboratories, FIN A-1205. SAND
B3/04/30. Division of Accident Evaluation. 75pp. SAND82-1788

6307110313 NUREG-0983
SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE GPERATING LICENSE FOR THE RESEARCH REACTOR AT THE UNIVERSITY OF TEXAS, Docket No. 30-192. (University of Texas.et al.)

\*\*Division of Licensing. 83/06/30. 100pp. Available at NRC. \$4.75. 19385:239. 24X Fiche: 50-192, 83/06/30. 8307110313.

8307:10314 Forwards description of defect in control rod drive return line, proposed mod for capping reactor notice, operating history of return line & implementation schedule for all NUREO-0619 mods. BANNEL JP. Power Authority of the State of New York. JPN-83-64. 83/07/07. VASSALLO, D. B. Operating Reactors Branch 2. 11pp. 19381: 264. 24x Fiche: 50-333, 83/07/07, 8307110314.

8307110350 Outlines low power test program per SER (NUREG-0797) Open Item I.G. Lubich includes loss of offsite power test, comparable facility test data utilization & training on validated simulator, Program will be incorporated in FSAR, SCHMIDT, H.C. Texas Utilities Services, Inc. TXX-3995, 83/07/07, DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director, 2pp. 19381:306. 24X Fiche: 50-445, 83/07/07, 8307110350.

8307120009 NUREO/CR-3142 VO2
THE DEVELOPMENT OF A PLAN FOR THE ASSESSMENT OF DEGRADED NUCLEAR PIPINO BY EXPERIMENTATION AND TEARING INSTABILITY FRACTURE HECHANICS ANALYSIS. Appendices.
KANNINEN, M. F., WILKOWSKI, G. M., PAN, J. Battelle Memorial Institute, Columbus Laboratories. FIN 8-7027. 83/06/30. Division of Engineering Technology. 366pp. Available at NRC. \$\$8.00.

8307120012 NUREG/CR-3142 VOI
THE DEVELUPMENT OF A PLAN FOR THE ASSESSMENT OF DEGRADED
NUCLEAR PIPING BY EXPERIMENTATION AND TEARING INSTABILITY
FRACTURE MECHANICS ANALYSIS. Main Report.
KANNINEN. M.F., WILKOMSKI. G. M., PAN. J. Batteile Memorial Institute,
Columbus Laboratories. FIN B-7027. 83/06/30. Division of
Engineering Technology. 80pp. Available at NRC. \$4.50. 19436:210.

8307120014 Advises that return piping for reactor water cleanup sys on both units remouted via feedwater piping to feedwater norzles.per Section 4.2 of NUREO-0619. Fracture mechanic analysis per Generic Ltr 81-11 expected by 830729.

BECKHAM. J. T. Georgia Power Co. NED-83-373. 83706/30 STOLZ, J. F. Operating Reactors Branch 4. 2pp. 19423:153. 24X

Fiche: 50-321.83/06/30,8307120014.

B307120016 NUREG/CR-3160
PARAMETERS AND VARIABLES APPEARING IN RADIOLOGICAL.
ASSESSMENT CODES.
MILLS, M., VOGT, D., MANN, B. Teknekron Research, Inc. FIN 8-6985.
B3/06/30. Division of Waste Management. 63pp. Available at NRC.
\$5, 50. 19436:044.

8307120018 NUREO/CR-3250
ATMOSPHERIC TRANSPORT AND DIFFUSION MECHANISMS IN COASTAL
CIRCULATION SYSTEMS.
KALEEL,R.J., SHEARER,D.L., MACRAE,B.L. TRC Environmental
Consultants, Inc. FIN B-2384. PNL-4700. 83/06/30. Division of
Health, Siting & Maste Management. 40pp. Available at NRC. \$3.75.
19436:001.

8307120021 NUREG/CR-2000 VO2 N5 LICEMBEE EVENT REPORT (LER) COMPILATION: For Month of May 1983. \* Dak Ridge National Laboratory. FIN A-9135. GRNL/NSIC-200. 83/04/30. Director's Office. 73pp. 19435:274.

B307120026 NUREG/CR-2881
EXPERIMENT OPERATIONS PLAN FOR MT-4 EXPERIMENT IN THE NRU
REACTOR.
RUBBCHER, G. E., WILSON, C. L., PARCHEN, L. J.
Battelle Memorial
Institute, Pacific Northwest Laboratory. FIN B-2277. PNL-4293.
B3/06/30. Division of Accident Evaluation. 34pp. Available at
NRC. \$4.50. 19437:299.

B307120029 Discusses continued problems in making control room ventilation sys operational per TMI Action Plan Item III. D. 3. 4. Unly one area radiation monitor necessary, per TMI Action Plan Item III. A. 1. 2.

BROEHL, D. J. Portland General Electric Co. 83/07/08. EISENHUT, D. 6. Division of Licensing. 2pp. 19423. 142. 24X Fiche: 30-344, 83/07/08, 8307120029.

8307120036 NUREG-0881 SO2
8AFETY EVALUATION REPORT RELATED TO THE OPERATION OF WOLF
CREEK GENERATING STATION, UNIT NO. 1. Docket No. 50-482.
(Kansas Gas And Electric Company at al.)
# Division of Licensing. 83/06/30. 41pp. Available at NRC.
\$4.00. 19437:354. 24X Fiche: 50-482,83/06/30,8307120036.

B307120041 Requests util choose one of two acceptable alternatives in BMR Owners Group study re NUREQ-0737 Item II.K. 3.18.
"Automatic Depressurization Sys Logic Mods." Schedule for implementing mods should be provided within 45 days.
VABBALLO.D. B. Operating Reactors Branch 2. 83706/03. BAYNE, J.P. Power Authority of the State of New York. 3pp. 19435:350. 24X
Fiche: 50-333,83/06/03,8307120041.

8307120112 Forwards response to BWR Dwners Group study of alternatives to NUREG-0737, Item II.K.3.18, "Automatic Depressurization Bys Logic Mod." Two of seven alternatives acceptable. Implementation schedule should be provided within 45 days. VASBALLO.D.B. Operating Reactors Branch 2. 83/06/03. LIU.L. Iowa Electric Light & Power Co. 9pp. 19435:179. 24X Fiche: 50-331,83/06/03,8307120112.

8307120117 Ack receipt of 830420 ltr providing response to NRC request for approved design in implementing TMT Action Plan Item II.K.3.13, "HPC1/RCIC Initiation Level." Requirements met. Item closed.

VASSALLO.D.B. Operating Reactors Branch 2. 83/06/17. LIU.L. Iowa Electric Light & Power Co. 2pp. 19435:197. 24X Fiche: 50-331,83/06/17,8307120117.

8307120146 Forwards synopsis of issues associated w/NUREG-0612, "Control of Heavy Loads," to resolve open items & draft final technical evaluation rept. Response should be provided within 60 days.

VA83ALLO,D.B. Operating Reactors Branch 2. 83/06/23. LIU,L. Iowa Electric Light & Power Co. 13pp. 17435:134. 24X

Fiche: 50-331,83/06/23,8307120146.

--8307120149 IER-C5506-352 DRFT

"Control of Heavy Loads (C-10), Duane Arnold Energy Ctr."

draft technical evaluation rept.

VOSDUBY, F. W. Franklin Institute/Franklin Research Center

NRC-03-81-130. TAC 07988 83/04/08. CLEMENSON.F. NRC - No
Detailed Affiliation Given 32pp. 19435:147. 24X

Fiche 50-331,83/06/23,8307120146.

8307120152 Forwards response to BWR Owners Group study of alternatives to NUREG-0737, Item II.K. 3.18, "Automatic Depressurization Bys Logic Mod." Two of seven alternatives acceptable implementation schedule should be provided within 45 days VASSALLO.D.B. Operating Reactors Branch 2 83/06/03 FARRAR, D.L. Commonwealth Edison Co. 9pp 19435:179 24X Fiche.50-254,83/06/03,8307120192.

8307120185 Comments on proposed rule re safety goal development program evaluation plan. Safety goal criteria appear to envision future regulatory regime in both generic & plant-specific safety decision on cost-benefits CURRAN.D. SHOLLY, S. S. Union of Concerned Scientists. 48FR10772 011. 83/07/08. NRC - No Detailed Affiliation Given. 17pp. 19423:337.

B307120194 Comments on proposed rule 100FR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation. Severe accident criteria apply only if safety goals established & assessed.

CURRAN, D. SHOLLY, S. S. Union of Cuncerned Scientists. 48FR16014
011. B3/07/08. NRC - No Detailed Affiliation Given. 17pp. 19423:317.

8307120245 Furwards Core Damage Assessment Procedure Station 9918.1, "Estimation of Extent of Cure Damage." Encl changes to NUREO-0737, Item II IB.3 re post-accident analytical accuracies will be incorporated into FSAR rev. CODK, J. M. Consumers Power Co. 23228 83/07/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp 19422:308. 24X Fiche:50-329,83/07/01.8307120245.

8307120266 Forwards IE Insp Repts 50-315/83-08 & 50-316/83-09 on 830427-29 & 0503-06 & notice of violation.

PAPERIELLD.C.J. Region 3, Office of Director. 83/06/28. DDLAN, J.E. American Electric Power Service Corp. DDLAN, J.E. (Indiana & Michigan Electric Co. 2pp. 19424-136 24X Fiche 50-315-83/06/28, 8307120266.

--8307120280 IE (nsp Repts 50-315/83-08 & 50-316/83-09 on B30427-29 & 0503-06. Noncompliance noted: failure to perform evaluation when whole body vivo count data indicated exposure to greater than 40 h control measure HUETER, L.J., GREGER, L.R. Region 3, Office of Director, 50-316/83-09, 83/06/23, 13pp. 19424:139, 24X Fiche 50-315,83/06/28,8307120266

8307120278 Forwards Rev O to "Enrico Fermi Atomic Power Plant, Unit 2: Evaluation of Safety Relief Valvo Piping & Torus - Attachment Piping for Effects of Site-Specific Earthquake," in response to SER.NUREG-0798.

TAUBER.H. Detroit Edison Co. EF2-63, 927. 83/07/08.

YOUNDBLOOD.B.J. Licensing Branch 1 1p 19424:006. 24X

Fiche: 50-341,83/07/08,8307120278

--8307120282 EF2-63927 ROO
Rev O to "Enrico Fermi Atomic Power Plant, Unit 2 Evaluation of Safety Relief Valve Piping & Torus-Attached Piping for Effects of Site-Specific Earthquake"

\* Detroit Edison Co. 83/06/30, 27pp 17424-007. 24X Fiche: 50-341,83/07/08,8307120278.

8307120294 Informs that review of 811231 shielding design concluding that NUREG-0737, Item II. B. 2 requirements met erronedus. Reexam in process.

MANGAN, C. V. Naggra Mohawk Power Corp. 63/07/01 VASSALLO, D. B. Operating Reactors Branch 2. lp. 19424, 070 24x Fiche 30~220, 83/07/01, 8307120294.

8307120307 Forwards "WPPSS 2 Purge & Vent Valves Seismic & Hydrodynamic Analysia," per SER Outstanding Issue 26. BDUCHEY, G D. Washington Public Power Supply System GD2-83-550. B3/06/22. SCHMENCER, A. Licensing Branch 2 2pp 19427:163. 24X Fiche: 50-397,83/06/22,8307120309.

---8307120313 "MPPSS 2 Purge & Vent Valves Seismic & Hydrodynamic Analysis." \* Mashington Public Pawer Supply System. 83/06/30. \$59pp. 19427 165. 24% Fiche: 50-397: 83/06/22: 8307120309.

- 8307120312 Forwards "Seabrook Station Control Room Design Review," per NUREG-0737, Item I.D. 1 & Suppl I to NUREG-0737 (Generic Ltr 82-33) re emergency response & SER (NUREG-0896) Outstanding Item 19, Section 18.

  BEVINCENTIS, J. Vanize Atomic Electric Co. GL-82-33. 83/07/07. RNIGHTON, G.W. Licensing Branch 3. 140pp. 19430: 268. 24X
- B307120386 Forwards procedures generation package for emergency operating procedures in response to NUREG-0737, Suppl I (Oeneric i.tr 82-33), STEMART. H. L. Virginia Electric & Power Co. GL-82-33, 83/07/01, BENTON, H.R. Oeffice of Nuclear Reactor Regulation, Oirector, 15pp 19426: 209. 24X Fiche: 50-000, 83/07/01, 8307120386.
- 8307120388 Discusses control room design review summary reptiger requirements of Suppl 1 to NUREG-0737. Rept will provide results of efforts to identify human engineering discrepancies to resolve emergency response capabilities. HANGAN, C. V. Niagara Mohaw Power Corp. 83/07/07. VASSALLO, D. B. Diche: 50-220, 83/07/07, 8307120388.
- 8307120396 Forwards listing of docketed sources of documentation per NUREG-0802 criteria & comparison of plant w/Kuasheng.Grand Gulf & Perry per NUREG-0763 to resulve SER Dutstanding Issue
  - 9. WULLER: G. E. Illinois Power Co. U-0648. 83/07/08. SCHWENCER, A. Licensing Branch 2. 20pp. 19430:198. 24% Fiche: 50-461, 83/07/08, 8307120396.
- 8307120502 Forwards IE Insp Rept 50-483/83-10 on 830524-27.No noncompliance noted. PAPERIELLO,C.J. Region 3, Office of Director. 83/06/22. BCHNELL.D.F. Union Electric Co. 2pp. 19433:253. 24X Fiche: 50-483,83/06/22,8307120502.
- --8307120506 IE Insp Rept 50-483/83-10 on 830524-27. No noncompliance noted Major areas inspected radiation protection program, including organization, training radiation protection procedures, facilities & equipment & previous insp findings. LOVENDALE.P.C., OREGER.L.R. Region 4. Office of Director. 83/06/22, 7pp. 19433:255. 24X Fiche: 30-483,83/06/22,8307120502.
- P3071205t1 Forwards IE Insp Rept 50-312/83-17 on 830430-0608. No noncompliance nuted.
  STERNBERG, D. M. Region 5, Office of Director. 83/06/20.
  RODRIOUEZ, R. Satramento Municipal Utility District. 2pp. 19433: 227. 24x Fiche: 50-312,83/06/20.8307120511.
- -8307120919 IE Insp Rept 50-312/83-17 on 830430-0608.No noncompliance noted. Major areas inspected: maint & surveillance operations, TML modifications of LERS; plant operations; followup on enforcement (tens & regional requests & media contacts. CANTER, H. L., O'GRIEN, J., YOUNG, T. Region 9, Office of Director. 83/06/17, ISpp. 19433:229. 24X Fiche: 50-312,83/06/20,8307120511.
- 307120512 Forwards IE Insp Repts 50-275/83-17 & 50-323/83-15 on 830301-28 No nancompliance noted.
  B18H0P.T.W. Region 5, Office of Director. 83/06/24. SCHUYLER.J.O. Pacific Gas & Electric Co. 2pp. 19433:218 24%
  Fiche: 50-275.83/06/24,8307120512.
- -B307120522 IE Insp Repts 50-275/83-19 % 50-323/83-15 on B30501-28.No nencompliance noted Major areas inspected: plant operations, surveillance testing, maint TMI Item II. B. 2. emergency preparedness, preparedne
- 07120514 Forwards IE Insp Rept 50-285/83-13 on 830501-31.No noncompliance noted. SEIDLE,W.C. Region 4, Office of Director. 83/06/14. JONES, H.C. Omaha Public Power District. 2pp. 19433:202. 24X Fiche:50-285,83/06/14,8307120514.
- B307120523 IE Insp Rept 50-285/83-13 on B30501-31 No noncompliance noted Major areas inspected operational safety verification; startup testing, surveillance testing, maint activities & followup on violations & NUMEC-0737 items.
  YANDELL, L.A., JOHNSON, H. D. Region 4, Office of Director. B3/06/14. I2pp. 19433:204. 24X Fiche: 50-285, 83/06/14, 8307120514.
- O7120524 Forwards response to Generic Ltr 82-33 (Suppl 1 to MUREG-0737) re detailed control room design review based on mergency response capability, Response supersedes Section C. typ C to Suppl 1 to SER (NUREG-0517).

  ICHROEDER, C. W. Commonwealth Edison Co. GL-82-33. 83/07/06.

  IENTON.H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 7433: 264. 24X Fiche: 50-374, 83/07/06, 8307120524.

- 8307120538 Forwards IE Insp Rept 50-263/83-09 on 830516-20 & notice of violation PAPERIELLO, C. J. Region 3, Office of Director. 83/06/28. CARSON, C.E. Northern States Power Co. 2pp. 19434:011. 24X Fiche: 50-263, 83/06/28, 8307120538.
- --8307120547 IE Insp Rept 50-263/83-07 on 830516-20. Noncompliance noted: failure to rept unusual event within 15 minutes.per 10CFR50.App E.Section IV. D. 3. PATTERSON.J. P., OLOERSEN.W. B., AXELSON.W. L. Region 3. Office of 01Pector. 83/06/27, 13pp. 17434: 014. 24X Fiche: 50-263.83/06/28, 8307120538.
- B307120575 Forwards response to B30511 request for add1 info re NUREG-0737, Item II. K. 3. 28, "Qualification of Automatic Depressurization Sys (ADS) Accumulators." ADS valves & equipment capable of performing function described in FSAR. MILLS, L. M. Tennessee Valley Authority. B3/07/08. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 3pp. 19433:193. 24X Fiche: 50-259, 83/07/08, 8307120575.
- 8307130011 Forwards evaluation of 830411 % O616 responses to integrated plant SAR (IPSAR) Section 4.25.3, "Flooding Due to Failure of Tanks." Issue resolved.
  CRUTCHFIELD, D. Operating Reactors Branch 5. LSO5-83-07-014.
  83/07/08. MAIER.J. E. Rochester Gas & Electric Curp. 5pp.
  19474:204. 24X Fiche: 50-244:83/07/08,8307130011.
- B307130950 Forwards Suppl 2 to SER (NUREG-0830). H/a encl. YOUN08L00D.B.J. Licensing Branch 1. B3/07/04. SCHNELL.D.F. Union Electric Co. 3pp. 19511:297. 24X Fiche: 50-483, 83/07/06.8307130050.
- 8307130067 Response to W Eddleman 830502 contentions re applicant onsite emergency plan. Contentions 150, 153, 154, 155, 156, 158, 159 & 160 should be denied. Contentions 151, 152 & 157 should be deferred. Certificate of Svc encl.

  BARTH.C.A. Hearing Branch 1. ISSUANCES DL. 83/07/11. Atomic Safety and Licensing Board Panel. 10pp. 19474:217. 24X Fiche: 50-400, 83/07/11, 8307130067.
- B307130226 Requests extension until B30930 to complete response to questions from B20602 & 03 meetings re development of final radiological effluent Tech Specs submittal using meeting summary & draft Rev 3 to NUREG-0472 as guidance. FAY.C. W. Wisconsin Electric Power Co. B3/07/06. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK, R.A. Operating Reactors Branch 3. 2pp. 19473:288, 24x Fiche:50-266,83/07/06.8307130226.
- 8307130248 Discusses evaluation of lift rips for reactor coolant pump motors & equipment hatches per NUREG-0612. Evaluation complete. Rips will be constructed by Hestinghouse.

  BASKIN.F. Southern California Edison Co. 83/07/06.

  CRUTCHFIELD. D. Operating Reactors Branch 5. Ip. 19474:361. 24X fiche:50-206,83/07/06.8307130248.
- B307130249 Forwards Directive 3.1.10(DF), "Control Room Access & Control," in response to SER Section 13.5.
  TUCKER, H. B. Duke Power Co. B3706/29, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 4pp. 19307:328. 24X Fiche: 50-413, B3706/29, B307130249.
- 8307130265 Forwards mod of 810113 order as revised by 830119 order. Order continues exemption & extends completion date for installation of plant mod required by App A of NUREG-0661 to 830928.

  CRUTCHFIELD, D. Operating Reactors Branch 5. LSD5-83-07-017. 83/07/11. FARRAR, D. L. Commonwealth Edison Co. 3pp. 19508:248. 24X Fiche: 50-237, 83/07/11, 8307130265.
- ---B307130269 Mod of B30113 order extending completion date to B3092B Por installation of plant mod required by App A to NUREG-0661. PURPLE,R.A. Division of Licensing B3/07/11. Commonwealth Edison Co. Spp. 1950B:251. 24X Fiche:50-237,83/07/11.8307130265.
- B30713026B Forwards revised marked-up Tech Specs discussed at 830203 meeting Requests confirmatory issues & license conditions listed in BERs (NUREG-0830 & OBB1) be removed from SER & responsibility transferred to NRC for review. PETRICK, N. A. Standardized Nuclear Unit Power Plant Bystem. SLNRC 83-0036. 83/07/08. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 436pp. 19506:237. 24X Fiche: 50-000,83/07/08, B30713026B.
- B307130273 Informs of completion of analysis using TACD2 fuel performance code for LDCA limit for 177 fuel assembly raised loop plants. Rev to BAN-10105 dependent on NRC acceptance of other topical repts & resolution of NURG-0630 issue. TAYLOR, J. H. Babcock & Wilcox Co., 83/07/06. STOL7, J.F. Operating Reactors Branch 4. 2pp. 19308:286.

- 8307130282 Forwards evaluation re response to integrated plant SAR Bection 4.20, "Containment Isolation Sys." Design mod acceptable.

  BHEAJ.J. Operating Reactors Branch 5. LS05-83-07-011. 83/07/07. COUNSIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 19308:209. 24X Fiche: 30-245,83/07/07,8307130282.
- --8307130289 Evaluation concluding info & proposed corrective action re integrated plan SAR Section 4.20, "Containment Isolation Bys" acceptable. # Operating Reactors Branch 5, 83/07/07, 3pp. 19508:211, 24X Fiche: 50-245,83/07/07,8307130282.
- 8307130303 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re Phase I of response to NUREG-0612, "Control of Heavy Loads at Nuclear Plants." Phase I "Control or meavy Loads at Muciner Cience. The acceptable. CRUTCHFIELD, D. Operating Reactors Branch 5. Lt 83/07/11. FARRAR, D. L. Commonwealth Edison Co. 24X Fiche: 50-237, 83/07/11, 8307130303. L505-83-07-016 19505:001
- --8307130308 Bafety evaluation accepting uti) Phase I response to NUREO-0612, "Control of Heavy Loads at Nuclear Plants," acceptable.

  \* Office of Nuclear Reactor Regulation, Director. 83/07/11, 2pp. 19505:003. 24X Fiche: 50-237, 83/07/11, 8307130303.
- --B306100146 TER-C5506-350/351 RI
  "Control of Heavy Loads, Comm Ed Dresden Nuclear Power
  Station, Units 2 & 3," revised technical evaluation rept.
  BMMBERGER, C. Franklin Institute/Franklin Research Center.
  NRC-03-01-130, TAC 46736, B3/06/08, SINGH, A. NRC No Detaile
  Affiliation Given. 33pp. 19505:005, 24X Fiche: 50-237,83/07/11,
- B307130304 Responds to B30505 notice of violation & proposed imposition of civil penalties re B30222 & 25 ATMS events Magnitude of civil penalty disputed Events were isolated occurrences.

  SELGVER,R.E. Public Service Electric & Gas Co. of New Jersey.
  EA-B3-024, B3/07/06. DEYCUNG,R.C. Director's Office, Office of Inspection and Enforcement. 44pp. 19474:106. 24X
  Fiche: 50-272, B3/07/06, B307130306.
- 8307130497 Forwards NUREO-0969, "Rept of NRC Evaluation Team on Quality of Const at Zimmer Nuclear Power Station" for proprietary
- SNIEZEK. J. H. Director's Office: Office of Inspection and Enforcement. 83/04/18. BDROMANN.E. A. Cincinnati Gas & Electric Co. 398pp. 19510:047. 24X Fiche: 50-398,83/04/18.8307130437.
- B307140130 Forwards safety evaluation of BMR Dwners Group response to NUREG-0737, Item II. K. 3. 18, "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO, D. B. Operating Reactors Branch 2. 83/06/03, PILANT, J. M. Nebraska Public Power District. 2pp. 19328:347. 24X Fiche: 50-298,83/06/03,8307140130.
- B307140138 Forwards safety evaluation of BWR Dwners Group response to NUREO-0737, Item II. K. 3. 18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VABSALLO. D. B. Deperating Reactors Branch 2. 83/06/03. UTLEY, E. Carolina Power & Light Co. 2pp. 19528.338. 24X Fiche: 50-324, 83/06/03, 8307140138.
- B307140144 Forwards safety evaluation of BWR Dwners Group response to NUREO-0737. Item II. K. 3. 19, "Mod of Automatic Depressurization Sys Logic,..." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO, D. B. Deenating Reactors Branch 2. B3/06/03. RHODE, B. K. Niagara Mohawk Power Corp. 2pp. 19540:001. 24X Fiche: 50-220, 83/06/03, 8307140144.
- B30714014B Ack receipt of util B11231, B20416, 0525, 1227, B3030B & 032B submittals on TMI Action Plan Items II.F. 1.4, II.F. 1.5 & II.F. 1.6 re containment monitors. Items resolved. Safety II.F.1.6 re containment montreal actions evaluation encl.

  CLARK, R. A. Operating Reactors Branch 3, 83/06/27, COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). Bpp 19529: 351. 24X Fiche: 50-336, 83/06/27, 8307140148.
- 8307140130 Forwards safety evaluation of BMR Owners Group response to NUREO-0737, Item 11.K. 3.18, "Mod of Automatic Depressurization Sys Logic..." Two acceptable options include elimination of high drywell pressure permissive. VASBALLO, D. B. Operating Reactors Branch 2. 83/06/03. PARRIS, H. O. Tennessee Valley Authority. 2pp. 19529: 334. 24X Fiche: 50-259, 83/06/03, 8307140150.

- 8307140153 Forwards safety evaluation concluding requirements of TMI Items II F. 1.4. "Containment Pressure Monitor." II F. 1.5. "Containment Water Level Monitor" & II.F. 1.6. "Containment Hydrogen Monitor." met. Items resolved. VASSALLO.D.B. Operating Reactors Branch 2. 83/06/16. PARRIS.H.O. Tennessee Valley Authority. 7pp. 19540 04t. 24X Fiche. 50-259, 83/06/16, 8307140153.
- 8307140160 Forwards safety evaluation of BWR Owners Group response to NUREO-0737. Item II. R. 3. 18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO.D.B. Operating Reactors Branch 2. 83/06/03. SINCLAIR.J.B. Vermont Yankee Nuclear Power Corp. 2pp 19340:032 24X Fiche: 50-271.83/06/03.8307140160.
- B307140275 Advises that abbreviated operator training program for mitigating core damage satisfies intent of NUREG-0737. Item II B 4. Training uill be given to managers & technicians in health physics, plant chemistry & instrumentation. MILLS.L.M. Tennessee Valley Authority. B3/07/08. ADENBAM.E. Licensing Branch 4. 2pp. 19522:325. 24X Fiche: 50-327.83/07/08, B307140275.
- B307140296 Forwards request for add1 info re B3040B response to Generic Ltr B2-33 (NUREG-0737, Suppl 1) re emergency response capability requirements. Response requested within 30 days. CRUTCHFIELD.D. Operating Reactors Branch 5. LSU5-83-07-022. B3/07/12. LINDER,F. Dairyland Power Cooperative. 4pp. 19523:311. 24X Fiche: 50-409, B3/07/12, B307140296.
- B307140374 Responds to Mar 1983 SER (NUREO-0857) request for add1 info re emergency plan.External ltrs of agreement encl. Info adequately responds to request VAN BRUNT.E.E. Arizona Public Service Co. ANPP-24271-ACR/. B3/07/12. KNIGHTDN, O. Licensing Branch 3. 19pp. 19523:335. 24X Fiche: 30-328.B3/07/12,B307140374.
- B307140374 Ack receipt of B30615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~335/B3-12.

  DANCE,H.C. Division of Project & Resident Programs. B3/06/27. UHR10,R.E. Florida Power & Light Co. 1p. 19520: 166. 24X Fiche: 50~335, B3/06/27, B307140374.
- --8307140411 IE Insp Repts 50-335/83-12 & 50-389/83-32 on 830411-15. Noncompliance noted: failure to post specified documents per 10CFR19.11. TOCKRY-11.

  MRAYJ.R. Region 2: Office of Director. BARR, K.P. Division of Engineering & Radiological Safety Programs. 50-389/83-32.
  83/05/11. 9pp. 19520:172. 24X Fiche.50-335/83/06/27/8307140394.
- 8307140414 Forwards IE Insp Rept 50-302/83-04 on 830214-18 & notice 10/140414 rapmaros 12 insp. 159- - 5 desident Programs. B3/03/23. LEWIS,R.C. Division of Project & Resident Programs. B3/03/23. HANCOCK.J.A. Florida Power Corp. 2pp. 19521:118. 24X Fiche: 50-302, B3/03/23, B307140414.
- --8307140421 IE Insp Rept 50-302/83-04 on 830214-18 Noncompliance noted: failure of licensed personnel to read abnormal & emergency procedures.

  BELISLE.O.A. DEBBAGE, A. G. SKINNER, P. H. Region 2. Office of Director. B3/03/18. 13pp. 19321:121. 24X Fiche. 50-302, 83/03/23, 8307140414.
- B307140466 Forwards Commission 830701 order on issue of late filed contentions & NUREO-0794, "Protection of Unclassified Bafeguards Info." W/o NUREG.
  BARTH/C.A. Hearing Branch 1. 83/07/12. FLYNN, S. Carolina Power & Light Co. lp. 19521:134. 24X Fiche: 50-400,83/07/12.8307140466.
- 8307140518 Forwards Suppl 2 to SER (NUREQ-0881). W/o encl. YOUNGBLOOD, B. J. Licensing Branch 1. 83/06/27. KDESTER, G. L. Kansas Oas & Electric Co. 3pp. 19527 347. 24X Fiche: 50-482, 83/06/27, 8307140518
- B307130045 Forwards Amend 2 to License NPF-16. Suppl 4 to SER (NUREG-0843) & notice of issuance & availability. Amend authorizes operation at power levels up to 100% of full rated power. W/O SER.
  KNIGHTON, G. W. Licensing Branch 3. B3/06/10. UHRIG.R.E. Flow Power & Light Co. 2pp. 19562:313. 24X Fiche. 50-389,83/06/10. B307150045.
- B307130091 Forwards schedule for completion of Suppl 1 to NUREG-0737 requirements for emergency response capability Date of safety parameter display sys delayed 60 days. All other activities consistent w/orginal plan. CROUSE.R.P. Toledo Edison Co. 948. 83/07/11. EISERHUT, D. 0. Division of Licensing. 2pp. 19536:111. 24X Fiche: 30-346-83/07/11. 8307150091.

B307150131 NUREC/CR-28B3 VD2
STUDY OF THE VALUE AND IMPACT OF ALTERNATIVE DECAY HEAT
REMOVAL CONCEPTS FOR LIGHT WATER REACTORS
SERRY,D L , SANDERS,G A. Sandia Laboratories, FIN A-1226.
SANDB2-1776. 83/06/30. Division of Risk Analysis 547pp

8307150136 NUREO/CR-3311
NEUTRON SPECTRAL CHARACTERIZATION CALCULATIONS FOR THE
FOURTH NUCLEAR REGULATORY COMMISSION HEAVY SECTION STEEL
TECHNOLOGY IT-CT IRRADIATION EXPERIMENTS.
BALDHIN.C.A. Dak Ridge National Laboratory FIN B-0415.
ORNL/TH-8782. 83706/30. Division of Engineering Technology
36pp. 19362:244.

8307150137 NUREG/CR-3356
GEOTECHNICAL GUALITY CONTROL LOH-LEVEL RADIOACTIVE WASTE
AND URANIUM MILL TAILINGS DISPOSAL FACTLITIES.
JOHNSON, W. S. SPIGOLON, S. J. LUTTON, R. J. Army, Dept. of,
Headquarters Materiel Development & Readiness Command. FIN B-7326.
83/06/30. Division of Waste Hanagement. 166pp. 19942:188.

8307150137 NUREG-0787 SQ5
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF
MATERFORD STEAM ELECTRIC STATION.UNIT 3. Docket No. 50-382.
(Louisiana Power and Light Company)
\* Division of Licensing. 83706/30. 120pp. 19596:131. 24X
Fiche: 50-382.83706/30.8307150139.

8307150141 NUREG-0830 502
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CALLARAY PLANT, UNIT NO. 1. Docket No. 50-483. (Union Electric Company)

\*\*Division of Licensing.\*\* 83/06/30. 65pp. 19562:155. 24X Fiche: 50-483, 83/06/30. 8307150141.

8307150147 NUREC/CR-3061
SURVIVABILITY OF ANCIENT MAN-MADE EARTHEN MOUNDS:
IMPLICATIONS FOR URANIUM MILL TAILINGS IMPOUNDMENTS.
LINDSEY.C.G., KING.S.E., MISHIMA.J. Battelle Memorial Institute,
Pacific Northwest Laboratory. FIN B-2370. PNL-4541. 83/06/30.
Division of Health, Siting & Waste Management. 40pp. 19562: 205.

8307150149 NUREG/CR-3357
IDENTIFICATION OF SEISMICALLY RISK SENSITIVE SYSTEMS AND COMPONENTS IN NUCLEAR POWER PLANTS Feasibility Study.
AZARK.M. BOCCIO.J., FARAHZAD.P. Broakhaven National Laboratory.
FIN A-3397 BNL-NUREG-51683. B3/06/30. Division of Engineering. 120pp. 19596:001.

8307150155 NUREG/BR-0025 VO9 N6 INFORMATION REPORT ON STATE LEGISLATION. LANDAU, d., KERR.G.W. Office of State Programs, Director. 83/07/31. 10pp. 19974:346.

8307150162 Forwards mod of BID113 order, revised by B11125 & 820114 orders. Order continues exemption & extends completion date for installation/mod of support to torus piping of Mark I containment to not later 90 days after Fuel Cycle 10. VASSALLG.D.D. Operating Reactors Branch 2. 83/06/17. SINCLAIR.J.B. Vermont Yankee Nuclear Power Corp. 2pp. 19342:356. 24x Fiche: 50-271.83/06/17.8307150162.

--8307150169 Mod of 810113.1125 & 820114 orders extending completion date to not later than 90 days after start of Fuel Cycle 10 for installation of support to torus piping of Mark I containment required by App A of NUREG-064.
PURPLE,R.A. Division of Licensing. 83/06/17. Vermont Yankee Nuclear Power Corp. 3pp. 19542.338. 24X Fiche: 50-271.83/06/17, 8307130162

8307150165 Forwards evaluation of BWR Owners Group generic response to NUREO-0737, Item II. K. 3. 18 "Automatic Depressurization Sys Logic Mods." Two acceptable options include elimination of high drywell pressure permissive.

VASSALLO.D. B. Operating Reactors Branch 2. 83/06/03

HARRINGTON. H. D. Boston Edison Co. 2pp. 19562:304. 24X

Fiche: 50-293, 83/06/03, 8307150165.

8307150176 Comments on NRC policy statement on safety goals & proposed evaluation plan. Supports efforts, however, apposes use of PRAs due to uncertainty of PRA methodology.

SEELY,S. New England Coalition on Nuclear Pollution. 48FR10772 029. 83/07/08. Diffice of the Secretary of the Commission. 2pp.

B307150178 NUREG/CR-2884
DECONTAMINATION AS A PRECURSOR TO DECOMMISSONING STATUS
REPT: Task 2 - Process Evaluation
DIVINE, J.R., WOODBUFF, E. M., MCPARTLAND, S. A. Battelle Memorial
Institute, Pacific Northwest Laboratory, FIN B-2303, PNL-4343,
83/05/31. Division of Engineering Technology, 63pp. 19596:287.

8307150182 Requests response to three unresolved items in Section 3.1 of NUREG-0612. "Control of Heavy Loads at Nuclear Pawer Plants." TER-C5506-379 & guidelines for NUREG-0612 compliance forwarded. CRUTCHFIELD.D. Operating Reactors Branch 5. L505-83-07-028. 83/07/14. VANDEWALLE,D.J. Consumers Power Co. 3pp. 19531:013. 24X Fiche: 50-255,83/07/14,8307150182.

B307150216 Rev to B20910 application for amend to Licenses DPR-31 & DPR-41.revising proposed radiological effluent Tech Specs in response to NRC comments. List of exemptions from NUREG-0472 requirements encl.

UHR19.R.E. Florida Power & Light Co. L-B3-402. B3/07/11.

EISENHUT, D.G. Division of Licensing. 3pp. 19530:274. 24X Fiche: 50-250, 83/07/11, 6307150216.

8307150235 Comments on NRC policy statement on safety goals & avaluation plan. Opposes policy. LEWIS.M. I. Lewis M. 48FR10772 030. 83/07/11. Office of the Secretary of the Commission. 1p. 19530:209.

8307150277 Comments on proposed rule re NRC safety goal development program & evaluation plan. Opposes rule. DOUGHTV.J. Searcast Anti-Pollution League. 83/07/06. Office of the Secretary of the Commission. 7pp. 19530:091.

8307150297 Comments on proposed rule re NRC policy statement on safety goals for operation of nuclear power plants. Policy statement & EPA guidelines should be consistent.

DIXON.O.W. South Carolina Electric & Gas Co. 48FR10772 028.
83/07/08. CHILK.S.J. Office of the Secretary of the Commission.

8307190307 Forwards IE Insp Repts 50-387/83-15 & 50-388/83-07 on 830608-27. No noncompliance noted. 8TAROSTECKI.R. Division of Project & Resident Programs. 83/07/01. KENYON.O.D. Pennsylvania Power & Light Co. 2pp. 19532: 312. 24X Fiche: 50-387, 83/07/01, 8307150307.

--8307150313 IE Insp Repts 50-387/83-15 & 50-388/83-07 on 830608-27. No noncompliance noted. Major areas inspected; preoperational test review, operational varification, maint observation, surveillance observation & preoperational test witnessing. RHOADB.C., MCCANN.J., NICHOLAS.H. Region 1, Office of Director. 30-388/83-07. 83/06/30. 14pp. 19532:314. 24X Fiche: 50-387,83/07/01,8307150307.

8307150310 Forwards "Control Room Design Review Program Plan for WPPBB Nuclear Project 3," per Generic Ltr 82~33 (NUREO-0737, Suppl 1) re emergency response capability, NUREO-0700 & NUREO-0801. BOUCHEY, G.D. Washington Public Power Supply System. GD3-83-0541. B3/07/12. KNIGHTON.O.W. Licensing Branch 3. 1p. 17538:121. 24X Fiche: 50-508, 83/07/12, 8307150310.

--8307150318 Procedure WMM-025 "Control Room Design Review Program Plan for WPPSS Nuclear Project 3." \* Washington Public Power Supply System. GL-82-33. 83/07/12. 117pp. 19538:122. 24X Fiche:50-508,83/07/12,8307190310.

B307150333 Advises that Reg Guide 1.97.Rev 3.supersedes Rev 2 referenced in Generic Ltr B2-33 (NUREG-0737, Suppl 1) re emergency response capability.
WESTAFER.O.R. Florida Power Corp. 3F-0783-10. B3/07/12. STGLZ.J.R. Operating Reactors Branch 4. 1p. 1933B:334. 24) Fiche: 50-302, 83/07/12, 8307150333.

B307150342 Forwards SER Suppl 5, NUREQ-0787, W/o encl.
TURK, S. E. Hearing Branch 1. B3/07/12, KOHL, C. N., JOHNSON, W. R.,
WILBER, H. A. Atomic Safety and Licensing Appeal Panel. 1p.
19538; 327. 24X Fiche: 50-382, 83/07/12, 8307150342.

8307150356 NUREG/CR-28B3 VO3
STUDY OF THE VALUE AND IMPACT OF ALTERNATIVE DECAY HEAT
REMOVAL CONCEPTS FOR LIGHT WATER REACTORS,
BERRY, D. L. SANDERS, G. A. Sandia Laboratories. FIN A-1226.
SANDEZ-1796. 83/06/30. Division of Risk Analysis. 108pp.
19574: 200.

B307190359 NUREG/CR-2284

EROBION OF STEEL STRUCTURES BY HIGH TEMPERATURE MELTS.
POWERS.D.A., ARELLANO,F.E. Sandia Laboratories. FIN A-1247.

8AND81-1755. B3/06/30. Division of Accident Evaluation. 199pp.

8307150365 NUREG/CR-3246
THE EFFECT OF SOME OPERATIONS AND CONTROL ROOM IMPROVEMENTS
ON THE SAFETY OF THE ARKANSAS NUCLEAR ONE, UNIT ONE, NUCLEAR
PUMER PLANT.
BELL, B. J. Battelle Memorial Institute, Columbus Laboratories.
KOLS, G. J. Sandia Laboratories. FIN A-1241. SANDB3-0710. 83/06/30.
Division of Risk Analysis. 41pp. 19596;316. 24X
Fiche: 50-313,83/06/30,8307150365.

- 8307150371 NUREG/CR-2751 VO4
  HEAVY-SECTION STEEL TECHNOLOGY PROGRAM GUARTERLY PROGRESS
  REPORT FOR OCTOBER-DECEMBER 1982.
  WHITMAN.G.D., PUGH.C.E., BRYANT.R.H. Oak Ridge National Laboratory.
  FIN 8-0119. ORNL/TM-8349/V4. 83/06/30. Division of Engineering Technology. 184pp. 19539:163.
- 8307150375 Forwards for review & comments, "Control of Heavy Loads (C-10), Point Beach Units 1 & 2," updated draft technical evaluation rept.

  CLARK.R. A. Operating Reactors Branch 3. 83/06/30. FAY, C. W. Hisconsin Electric Power Co. 2pp. 19540:103 24X
  Fiche: 50-266,83/06/30,8307150395.
- --8307070382 TER-C8806-382/383 DR
  "Control of Heavy Loads (C-IO),Point Beach Nuclear Plants
  Units 1 & 2," draft final technical evaluation rept.
  BOMBERGER,C., AHMED,N. Franklin Institute/Franklin Research
  Center. NRC-03-81-130. TAC 07727. 83/06/17. SINGH.A., CHAN,T.
  NRC No Detailed Affiliation Given. 56pp. 19340:105. 24X
  Fiche: 50-266,83/06/30,8307150395.
- B307150411 Forwards request for add1 info to complete NRC review of util submittal addressing NUREG-0737. Item II.D. 1, "Parformance Tasting of Relief & Safety Valves." Response requested within 3D days.
  KNIOHTON, G.W. Licensing Branch 3. B3/06/27. DIETCH.R. Southern California Edison Co. 10pp. 19540:166. 24X Fiche: 50-361.83/06/27. B307150411.
- B307180026 Forwards BER re NUREO-0612, "Control of Heavy Loads" & technical evaluation rept Phase I acceptable, VABBALLO, D. B. Operating Reactors Branch 2, B3/06/27, FARRAR, D. L. Commonwealth Edison Co. 2pp. 19567:301, 24X Fiche:50-254,83/06/27,B307180026,
- --8307180030 Safety evaluation of util 801222 responses to NUREG-0612. "Control of Heavy Loads." Phase I acceptable \* NRC No Datailed Affiliation Given. 83/06/27. 2pp. 19567: 303. 24% Fiche: 50-254,83/06/27.8307180026.
- --830A060295 TER-C550A-386/387
  "Control of Heavy Loads (C-10), Quad Cities Station Units 1 & 2;" technical evaluation rept.
  BOMBERGER.C. Franklin Institute/Franklin Research Center.
  NRC-03-81-130. TAC 08078. 83/06/01. SINGH.A. NRC ~ No Detailed Affiliation Given. 31pp. 66817:300. 24x Fiche:50-254,83/06/27.
- B3071B0044 Forwards IE Insp Repts 50-266/83-08 % 50-301/83-08 on B30509-11 & 0609 & notice of violation.

  PAPERIELLU.C.J. Region 3, Office of Director. B3/07/01.

  BURBIEIN, 5. Wisconsin Electric Power Co. 2pp. 19560:234. 24)

  Fiche: 50-266/83/07/01/83071B0044.
- --8307180047 IE Insp Repts 50-266/83-08 & 50-301/83-08 on 830509-11 & 0609. Noncompliance noted: failure to collect air samples on 830331 during reactor vessel head removal & cavity flood operations & to install SA-11 main steam line monitors. LOVENDALE.P.C., OREGER, L.R. Region 3, Office of Director. 50-301/83-08. 83/06/30. 8pp. 19360:238. 24X Fiche: 50-266,83/07/01,8307180044.
- B307190081 Part 21 rept clarifying position re equipment failures during C-E qualification testing of Target Rock solenoid activated valves per T Lee B30620 request Valve design conforms to NUREG-0588. Retrofit program supported PATTARINI, D. M. Target Rock Corp. E-16673. B3/07/11. DEYGUNG, R. C. Director's Dfice, Office of Inspection and Enforcement. 1p. 19560:007. 24X Fiche: 50-528, B3/07/11, B307180081.
- 830718007B Forwards clarification to 830415 integrated implementation schedule for completing NUREG-0737. Suppl 1 items remembered for capabilities, per Generic Ltr 82-33. Items not dependent on fuel cycle identified.

  HUKILL, M. D. General Public Utilities OPU Service Corp.

  3211-83-197. 83/07/12. EISENUNT. D. G. Division of Licensing. 2pp.
  19557:001. 24X Fiche: 50-289, 83/07/12. 8307180098.
- 8307180100 Submits final resolution of open items identified in draft technical evaluation rept dtd 830222 demonstrating conformance to NUREC-0612, "Control of Heavy Loads at NUCLEAR Power Plants," Phase I.

  BTEWART, W. L. Virginia Electric & Power Co. 323. 83/07/12, DENTON, N. R. Dffice of Nuclear Reactor Regulation, Director, CLARK, R. A. Operating Reactors Branch 3. 4pp. 19557:005. 24X Fiche: 50-338.83/07/12,8307180100.

- 8307180108 Forwards rev to 830623 response to NRC 830202 request for add1 info re NUREG-0737. Items II. F 1.4. "Containment Pressure Monitor" & II. F. 1.5. "Containment Water Level Monitor." to correct inaccuracies in original data BAYNE, J P Power Authority of the State of New York 83/07/12. VASSALLO.D. B. Operating Reactors Branch 2 Spp. 19557:022. 24X Fiche: 50-333.83/07/12.8307180100
- B307180115 NUREG-0750 V16 NO2 NUCLEAR REGULATORY COMMISSION ISSUANCES August 1982 Pages 401-863. \* Commissioners. B2/08/31. 462pp. 19564:082.
- 8307180124 NUREG-0837 VO2 NO3ER

  NRC TLD DIRECT RADIATION MONITORING NETWORK Progress Report,
  July September 1982.
  COSTELLO.F. THOMPSON.T., COHEN.L. Region 1. Office of Director
  83/07/05. 3pp. 19641:136
- B307180139 NUREB/CR-2957
  MEABUREMENT DF GAMMA RAY DOSE FRUM A MODERATED CF-252
  SOURCE.
  MCDUNALD.J.C. Battelle Memorial Institute, Pacific Northwest
  Laboratory. GRIFFITH.R.V. Lawrence Livermore Laboratory. PLATD.P.
  Michigan, Univ. of. FIN B-2460-2 PNL-4590. 83/06/30. Division
  of Facility Operations. 22pp 19567:278
- 8307180143 NUREG/CR-2599
  EXPERIMENT OPERATIONS PLAN FOR THE MT-3 EXPERIMENT IN THE
  NRU REACTOR.
  RUSSCHER, G. E., WILBON, C. L., PARCHEN, L. J. Battelle Memorial
  Institute, Pacific Northwest Laboratory, FIN B-2277, PNL-4190,
  83/06/30 Division of Accident Evaluation, 40pp. 19567: 239.
- 8307190148 NUREG/CR-2595
  A GENERAL APPROACH TO ASBURE COMPLIANCE WITH ALARA
  GUIDELINES ON DIRECT RADIATION FROM A NUCLEAR POWER PLANT.
  January 1977 January 1982.
  HARDING, W. SILVER, C. Drezel Univ. 83/06/30. Safeguards Branch
  1350n. 19567, Oci.
- 8307180165 NUREG/CR-2963
  PLANNING GUIDANCE FOR NUCLEAR POWER PLANT DECONTAMINATION.
  MUNSON.L.F., DIVINE.J.R., MARTIN.J.B. Battelle Memorial Institute.
  Pacific Northwest Laboratory FIN B-2342, 83/06/30. Division of Engineering, 104pp. 19567:136.
- 8307190016 Forwards responses to Franklin Research Ctr 820212 draft rept on handling of heavy loads & response to 801222 request for addl info re lifting devices Mods & procedure emplacements will be completed by 841231. HARRINGION, W. D. Boston Edison Co. 83-181. 83/07/13. £ISENHUT, D & Division of Licensing. 49pp 19433.084 24X Fiche 50-293, 83/07/13.8307190016.
- 8307190100 Advises of completion of Mark I containment mod program per 820118 order Plant mods & structural reassessments meet NUREO-0661 acceptance criteria.
  MCGAUGHY.R.W. Iowa Electric Light & Power Co. NC-83-2357.
  83/07/12 DENTON.H. Office of Nuclear Reactor Regulation. Director. ip. 17634:255. 24% Fiche:50-331,83/07/12,8307190100
- 8307190105 Comments on changes to Tech Specs (NUREG-0926) proposed by util on 830629. Requirement for notic gas activity monitor w/alarm to be continuously operable at either offgas post-treatment or radwaste ventilation point recommended CDBB.A.B. Mississippi, State of 83/07/14. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19634-248. 24X Fichs: 30-416.83/07/14.8307190106
- 8307190135 Supplemental application for amend to License DPR-3B, proposing Tech Spec changes to support full-rated power during Cycle B & revising BAM-1774, "Cycle B Reload Rept." to reflect implementation of NUREO-0630 in LOCA analysis. TUCKER.H.B. Duke Power Co. B3/07/13 DENTON.H.R. Office of Nuclear Reaction Regulation, Director STCL2.J F Operating Reactors Branch 4. 3pp. 19636:075. 24X Fiche: 90-269.83/07/13.8307190135.
- --B307190139 BAK-1774 ERR
  Revised pages to "Oconee Unit 1 Cycle 8 Reload Rept" Util description of work scope for justification of use of FLECSET encl
  \* Babcock & Wilcox Co. B3/07/13 7pp. 19636:09B 24X Fiche: 50-269, 83/07/13, 8307190135.
- 8307190156 Discusses status of facility licensing actions. Considerable amount of time devoted to Suppl 1 to NUREG-0737 during last reporting period.

  WAGNER, P. C. Region 4, Office of Director 83/07/11. MADSEN. G L. Region 4, Office of Director. 2pp 19636:296. 247

  Fiche: 50-267.83/07/11.8307190156

- B307190190 Forwards "Emergency Procedure Generation Package." per requirements of Suppl 1 to NUREG-0737. VAN BRUNT, E. E. Arilona Public Service Co. GL-82-33. 83/07/15. KNIGHTON G. Licensing Branch 3. 2pp 19630-192. 24X Fiche: 50-528, 83/07/15, 8307190190.
- B307190209 Forwards detailed control room design review per requirements of Generic Ltr 82-33. "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability." Reg Guide SHIELDS, S.W. Public Service Co. of Indiana. Inc. SVP-0108-83. 83/07/15. EISENHUT, D.O. Division of Licensing. 113pp. 19628:322.
- 8307190219 Forwards "Seismic & Dynamic Qualification of Pressurizer Relief Sys." in response to NUREG-0737. Item II.D. 1.
  "Reliability Engineering." Action atom considered closed.
  BROEHL.D. J. Portland General Electric Co. 83/07/12. EISENHUT.D.G. 8307190219.
  2pp. 19627:001. 24X Fiche: 50-344.83/07/12.
- --8307190224 PGE-1039
  "Selsaic & Dynamic Gualification of Pressurizer Relief
  Sys."
  TUDD.A.J. Portland General Electric Co. 83/07/31. 191pp.
  19627-004. 24X Fiche: 50-344, 83/07/12, 8307190219.
- 8307190235 Forwards "Bounding Analytical Assessment of NUREQ-0630 Models on tOCA & Operating kW/Ft Limits." in response to 820713 ltr.
  HUKILL.H.D. General Public Utilities GPU Service Corp.
  5211-93-194. 83/07/14. NOVAK.T.H. Assistant Director for Licensing. 2pp. 19630:083. 24X Fiche: 50-289.83/07/14.8307190235.
- --B307190238 "Bounding Analytical Assessment of NUREG-0630 Models on LGCA & Operating tW/Ft Limits." • General Public Utilities - GPU Service Corp. 83/07/14. 18pp. 19630-085. 24X Fiche: 50-289, 83/07/14. 8307190235.
- 8307190270 Response to ASLB B30615 order, recommending that period of discovery not commence until all future issuances reintegrated plant safety assessment rept (NUREO-0821) available.

  VDIGT, H. H. Rochester Gas & Electric Corp. VDIGT, H. H. LeBoeuf, Lamb, Leiby & MacRae. ISSUANCES OL. B3/07/15. 3pp. 19628:304. 24% Fiche: 50-244, 83/07/15. 8307190270.
- 8307190376 Forwards generic safety evaluation supporting continued operation of PNRs w/Dresser primary safety valves until CLARK, R. A. Operating Reactors Branch 3. 33/05/03. LUNDVALE, A. E. Baltimore Gas & Electric Co. 2pp. 19656:052. 24x Fiche: 50-317, 83/05/03. 8307190376.
- --BJ07190383 Safety evaluation supporting continued operation of PWRs W/Dresser primary safety valves, until final resolution of NUREG-0737, Item II. D. E. A. Office of Nuclear Reactor Regulation. Director 83/04/18, 13pp. 19656: 054. 24x Fiche: 50-317, 83/05/03, 8307190376.
- 8307190386 Forwards safety evaluation supporting continued operation of PMRs w/Dresser primary safety valves Facility operation at present valve settings acceptable. NUREG-0737, Item II. D. I STOLZ, J. F. Operating Reactors Branch 4. 83/04/27 GRIFFIN. J. M. Arkansas Power & Light Co. 2pp. 19643:345. 24x Fiche: 50~313,83/04/27,8307190386.
- B307190388 Forwards proof & review STS for Westinghouse PWRs, (NUREO-0492,Rev 5) Listed info requested by B30902 THOMAS.C. O. Standardiration & Special Projects Branch. 83/07/08. IFPOLITG.T. A. Operating Reactors Assessment Branch. LIAW.B.D. Branch. BENARDYA.V. Chemical Engineering Branch. BENARDYA.V. Chemical Engineering
- 9307190397 "TMI Action Plan Tracking Sys." Apr 1983. KING.M. Office of Resource Management. Director. 83/04/30. 160pp.
- B307190446 NUREG-0894 S02

  SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION, UNITS 1 AND 2 Dockets No. 50-443 And 30-444 (Public Service Company of New Hampshire et al.)

  Blivision of Licensing. B3/06/30. 18pp Available at NRC 43. 25. 19569 285. 24X Fiche: 50-444, 83/06/30, 8307190446.
- B307190437 NUREG/CR-J363 V02
  MEASUREMENTS OF AXIALLY VARYING NONEGUILIBRIUM IN POST-CRITICAL-HEAT-FLUX BOILING IN A VERTICAL TUBE. (Appendix E). EVANS, D. G., WEBB.S. W., GHEN, J. C. Lehigh Univ. FIN B-5794. TS-B31-II. B3/06/30. Division of Accident Evaluation. 332pp. Available at NRC. \$7.50. 1956B:001.

- 8307170464 NUREG/CR-3363 VOI MEASUREMENTS DE AXIALLY VARYINO NUNEGUILIBRIUM IN POSI-CRITICAL-HEAT-FLUX BOILING IN A VERTICAL TUBE. (Main Report And Appendices A-D). EVANS. D. G. . HEBB. S. H. . CHEN. J. C. Lebigh Univ. FIN B-6794. TS-831-I. 83/06/30. Division of Accident Evaluation. 194pp. Available at NRC. \$6.00. 19568:336.
- 8307200073 Responds to Generic Ltr 81-07 dtd 810701 re control of heavy load. Original submittal did not distinguish "load" from "heavy load. Pege 4 of Attachment 1 to 810701 submittal should be replaced w/encl. W/o encl. BORDINE.T. C. Consumers Power Co. 9L-81-07. 83/07/13. CRUICHFIELD.D. Operating Reactors Branch 5. (p. 19447:115. 24X Fiche: 30-155, 83/07/15, 8307200073.
- 8307200135 Confirms current use of C-E Owners Group generic emergency procedure guidelines described in 830415 response to Suppl 1 to NUREG-0737, "Emergency Response Capability," LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/07/15. CLARK, R. A. Operating Reactors Branch 3. ip. 19651:020. 24X Fiche: 50-317, 83/07/15, 8307200135.
- 8307200142 Forwards response to Phase II of NUREG-0412, "Control of Heavy Loads at Nuclear Power Plants." Items discussed include step plugs, vessel cavity plugs, dryer separator pool step plugs, fueling slot plugs & auxiliary hoist. SQRENSEN. G. C. Washington Public Power Supply System. GD2-83-614. 82/07/13. SCHMENCER, A. Licensing Branch 2. 9pp. 19651:011. 24 Fiche: 50-397, 83/07/13, 8307200142.
- 8307200179 Comments on listed documents on Unresolved Safety Issue A-1, "Mater Hammer," including for comment issues of NUREG-0927 & NUREG-0923 re evaluation of water hammer occurrence & value impact analysis of water hammer, respectively.

  BRADBURY, R. B. Stone & Webster Engineering Corp. 83/07/15. KNIEL, K. Division of Safety Technology. 3pp. 19351:164.
- B307200187 NUREO-0968 V01 ERR

  SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE
  CLINCH RIVER BREEDER PLANT. ERRATA. DDCKET ND. 50-537. (US
  DEPARTMENT OF ENERGY, TENNESSEE VALLEY AUTHORITY AND PROJECT
  MANAGEMENT CORPORATION).

  GPFice of Nuclear Reactor Regulation, Director. 83/07/11. 2pp.
  19647: 308. 24x Fiche: 50-537, 83/07/11, 8307200187.
- 830720029B Responds to MRC 830603 ltr re safety evaluation of seven alternatives proposed by BWR Owners Group to modify present II. X3.18 Mods will be implemented during refueling outage. DALTROFF, S. L. Philadelphia Electric Co. 83/07/15. 8TOLZ.S.F. Operating Reactors Branch 4. 2pp. 17648:134. 24X
- 8307200316 Summarizes B30615 telcon w/applicant re accuracies in required post-accident analytical chemistry procedures per NUREG-0737. Item II. B. 3. Acceptable gamma spectrum analysis will be submitted in early Jul 1983.
  BILLER, M. A. Licensing Branch 4. B3/07/II. Licensing Branch 4. 4pp. 19656:343. 24% Fiche: 50-329, 83/07/II.8307200316.
- 8307200473 Comments on 830513 response to Generic Ltr 82-33 (NUREO-0737 Suppl 1) on detailed control room design & safety parameter display sys recview. Schedule for program plan or documentation describing processes & activities requested. RNIGHTON, G.W. Licensing Branch 3. 0L-82-33. B3/07/08. DIETCH, R. Southern California Edison Co. HOLCOMBE.J.C. San Diego Gas & Electric Co. 2pp. 19671:361. 24X Fiche: 50-361, 83/07/08, 8307200473.
- 8307200474 Comments on 830527 session of ACRS Joint Metal Components/
  Reactor Fuels Subcommittee B30526-27 meetings re bolting
  problems. Corrections should be made to underestimate of
  strain-to-failure at high temp in described in NUREG-0630.
  50LCMON.A.A. Purdue Univ. SOLCMON.A.A. ACRS Advisory
  on Reactor Safeguards. 93/06/01. SHEMMAN.P. ACRS Advisory
  Committee on Reactor Safeguards. 2pp. 19672:173.
- 8307200485 Forwards safety evaluation of 830321 submittal re NUREG-0737, Items II.F. 1.4, II.F. 1.5 & II.F. 1.6, "Addi Accident Monitoring Instrumentation," Items resolved W/o encl.

  VASSALLO, D. B. Operating Reactors Branch 2. 83/06/27. LIV, L. Iowa Fiche: 50-331, 83/06/27, 8307200485.
- 8307200503 Forwards SER Suppl 5, NUREG-07B7, H/o encl.
  KNIGHTON, G. H. Licensing Branch 3. 83/07/08. MAURIN, L. V. Louisiana
  B307200503. 2pp. 19672: 302. 24% Fiche: 50-382, 83/07/08,

0524 Forwards order modifying 810113 to 820119 orders reallation of plant mods in compliance w/acceptance erial of NURED-0661. Completion date extension to Spring outage, requested in 830615 itr.; granted.
ALLO, D. B. Operating Reactors Branch 2 B3/06/30. FARRAR, D. L. anwealth Edison Co. 2pp 19671:344. 24X Fiche: 50-254, 83/06/30, 200524.

200531 Order modifying Bi0113 & B20119 orders re installation of ant mods in compliance w/NUREG-0661 requirements. mpletion date extended to Spring 1984 refueling outage. RPLEs R. A. Division of Licensing. B3706/30. Commonwealth ison Co. 4pp. 19671:346. 24X Fiche: 50-254.83/06/30.8307200524.

0007 Forwards IE Insp Rept 50-247/83-14 on 830523-27. No ompliance noted.

DSTECKI.R. Division of Project & Resident Programs. B3/07/05.

DLE. J. D. Consolidated Edison Co. of New York. Inc. 2pp.

7:221. 24X Fiche: 30-247, 83/07/05, 8307210007.

210014 IE Insp Rept 50-247/83-14 on 830323-27. No noncompliance ted. Major areas inspected: Licensee actions taken to comply requirements described in NUREG-0737, Item II 8.2 resign of plant shielding & vital area assessment.

JNACK.W.H. EAPEN.P.K. KISTER.H.B. Region 1. Office of sector. 83/06/30. 8pp. 19669:223. 24X Fiche: 50-247, 83/07/05, 17210007.

)138 Forwards proposed rev to Generic Licensing Topical Rept I (P)-A, "Edgress Nuclear Safety-Related Extra-Safety & coring (X-SAM) Cranss." Changes describe how X-SAM is implemented per NVREG-0554, Approval requested. (.C. W. Edgres, Inc. 83/07/18. THOMAS, C. Standardization & lai Projects Branch. 2pp. 19866:110.

1145 Forwards safety evaluation of util 821101 analysis >st-accident sampling sys per NUREO-0737; Item II. 8, 3. .ution of three remaining criteria requested within 90

HFIELD, D. Operating Reactors Branch 5. LEO5-B3-07-031.

\*/IB. COUNSIL. N. C. Connecticut Vankee Atomic Power Co. 7pp. st 120. 24% Fiche: 50-213, 63/07/18, 8307210145.

#205 Informs that post-accident sampling sys operational duries approved & installed at plant by 830701 per TMI in I tem II.8.3 Due to recent sys malfunctions matives investigated to improve reliability. #RT.W.L. Virginia Electric & Power Co. 399. 83/07/18. M.H.R. Office of Nuclear Reactor Regulation, Director. HUT.D.Q. Division of Licensing. 1p. 19655:111, 24X:50-280,83/07/18.8307210205.

209 Forwards conceptual design overall schedule for engineering, rement & installation & NRC checklist for compliance w/ -0737/ltem II.F. 2. Approval of conceptual design & NRC list requested by B30902.
FER. G. R. Florida Power Corp. 3F~0783-15. B3/07/19.
N.H. R. Office of Nuclear Reactor Regulation, Director. 43pp.: 0649. 24X Fiche: 50-302, B3/07/18, B307210209.

235 NUREG/CR-2924
AND ESCA STUDIES OF POSSIDLE SODIUM URANATE PRECURSORS
LATED TO AEROSOL CHARACTERIZATION FROM A SIMULATED

ELLI, M. A., MILLER, G. D. CRAVEN, S. M. Mound Facility/Monsanto tch Corp. FIN A-1171. MLM-2983. 82/10/31. Division of ent Evaluation. 18pp. 19688: 297.

257 NUREO/CR-2932 VO2
MENT GUALIFICATION RESEARCH TEST OF ELECTRIC CABLE WITH
RY SPLICES AND INSULATION REWORK TEST NO. 2, REPORT NO.

.E.E., FURGAL, D. T. Sandia Laboratories. FIN A-1355.
1-2027. 82/11/30. Division of Engineering Technology. 65pp.

260 NUREG/CR-2810
TIONB IN ZIRCALOY-4 CLADDING DEFORMATION IN REPLICATE
BIMULATION TESTS.
ST.A. W. CROMLEY, J. L., CHAPMAN, R. H. Oak Ridge National
story. FIN 8-0120, ORNL/TH-8413, 82/10/31. Division of
ent Evaluation, 54pp. 19688:167.

262 NUREG-0748 VO3 NO5 FING REACTORS LICENSING ACTIONS BUMMARY. Data As Of May 33. (Orange Book) nagement Information Branch. 83/04/30, 324pp. 19688:323.

265 NUREO/CR-2335
FB OF THE SEMISCALE MOD-2A NATURAL CIRCULATION
IMENTS.
3.G.O., BODALK. EQ&Q, Inc. FIN A-603B. EQG-2200, 82/10/31.
sion of Accident Evaluation. 74pp. 17688; 073.

8307210268 NUREG/CR-2824 VOI
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM
GUARTERLY PROGRESS REPORT FOR PERIOD ENDING MARCH 31, 1982
DODD.C V. DEEDS.W.E., MCCLUNG, R.H. Gak Ridge National Laboratory.
FIN 8-0417. ORNL/TM-8418/VI. 82/10/31. Diffice of Nurlear
Regulatory Research, Director. 9pp. 19672:304.

8307220110 Responds to 830304 FR notice soliciting comments on issues to be included in environ assessment supporting nomination of DOE Hanford site as potentially acceptable repository site. NUREG-0960 analysis should considered in regt. BROWNING.R.E. Division of Waste Management. 00458. 83/05/02. BENNETT.W.J. Energy, Dept. of. 2pp. 19679.035

8307220128 Forwards SER re util 811116 response to Generic Ltr 81-21, "Natural Circulation Cooldown," Mods recommended by Westinghouse study demonstrate sufficient condensate supply consistent w/procedures. Response acceptable. VAROA, B.A. Operating Reactors Branch 1. GL-81-21. 83/07/05. 8AYNE, J.P. Power Authority of the State of New York. 2pp. 19692: 294. 24X Fiche: 50-286, 83/07/05, 8307220128.

8307220139 Forwards NRC FR notices of availability of NRC draft analysis of DOE site characterization rept for Basalt Waste Isolation Project (NUREO-0740). BROWNING.R.E. Division of Waste Management. 00412 83/04/18. MORGAN.R.L. Energy, Dept. of. lp. 17699.053.

8307220174 Forwards gags inadvertently omitted from 830715 submittal of rev to response on control of heavy loads (Generic Ltr 81-07). Page 4 of Attachment i to 810701 submittal should be replaced w/encl.
BURDINE.T.C. Consumers Power Co. GL-81-07. 83/07/18.
CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 19684:033. 24x Fiche: 50-155, 83/07/18, 8307320174.

8307220222 "LACBUR Annual Rept 1982." W/830217 ltr. LINDER.F. Dairyland Power Cooperative. LAC-8883 83/02/17. KEPPLER.J. G. Region J. Office of Director 11pp 19674:005. 24X Fiche: 50-409.83/02/17.8307220222.

B307220356 Forwards "Nuclear Environ Qualification Test Program on Foxboro N-E10 Series Pressure Transmitters," Vols 1-III.
Results should be reviewed per qualification requirements of NUREG-0988 & 10CFR0.49.
FAY.C.W. Wisconsin Electric Power Ca. B3/07/15. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. NOONAN, V.S. Equipment Qualification Branch. 2pp. 19676:120. 24X Fiche: 50-266, B3/07/15, B307220356.

8307220495 Discusses status of proposed mods to automatic depressurization sys.per NUREC-0737. Item II. K. 3. 18 Option 4 we timer installation described in GE BWR Duners Group response, selected for implementation, Mods Listed RYBAK. B. Commonwealth Edison Co. 4948N. 83707/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19685. t81. 24X Fiche: 50-000, 83/07/18. 8307220495.

8307220901 Supple response to Generic Ltr 82-33 re emergency response capability, clarifying position re schedule for implementation of guidance in Reg Guide 1.97. Rev 2 Schedule ulil be developed or NUREG-0737. Suppl 1.

BECKHAM. J. T. Georgia Power Co. GL-82-33. 83/07/18. SYGLZ, J. F. Operating Reactors Branch 4 1p. 19485:149. 24x

Fiche: 50-321, 83/07/18, 8307220501.

B307220508 Forwards Rev i to "Equipment Qualification Radiation Dose Map Development," per NRC B30617 request UHRIG.R.E. Florida Fower & Light Co. L-83-409, 83/07/15. CLARK.R.A. Operating Reactors Branch 3. 2pp. 19685:104, 24X Fiche: 50-335,83/07/15,8307220508.

--8307220514 Rev 1 to "Equipment Qualification Radiation Bose Map Development." \* Florida Power & Light Co. 83/06/24. 16pp. 19685:106. 24X Fiche: 90-335,83/07/15,8307220508.

8307220364 Submits evaluation of SPING-4 as indine sampler per NUREO-0737. Item II.F. 1.2.B. 2. Methodology & details of determination re use of SPING-4 found in Technical Rept LAC-TR-116.
SHAFER.F. W. Dairyland Power Cooperative. LAC-9173. 83/06/30. PAUL.R. Region 3. Office of Director. 2pp. 17685:360. 24X Fiche:50-407.83/06/30.8307220364.

8307220626 NUREG-0998 U.S. NUCLEAR REGULATORY COMMISSION 1982 ANNUAL REPORT. DICKBON.J.H. Office of Resource Management, Director. 83/07/3]. 224pp. 19697:293.

8307250059 Forwards Human Factors Engineering Branch audit rept of Control room design review from 830404-08 per Generic Ltr 82-33 Responses to unsatisfied conditions should be provided 60 days prior to espected literaling date YOUNGBLOOD, B. J. Licensing Branch 1 GL-82-33 83/07/08, GARY, R. J. Texas Utilities Generating Co. 34pp. 19723-309 24X Fiche 50-445,83/07/08,8307250059

8307250075 Responds to 830622 request for comments on first draft of NRR safety goal evaluation work plan. Div of Licensing should be invalved w/subtasks dealing w/possible effects of safety goals on regulatory requirements
EISENHUT, D.G. Division of Licensing. 83/07/14. SPEIS, T.P. Division of Safety Technology. 1p. 19724-085

8307250079 NUREC-0797 S03

SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Not 30-445 And 50-446. (Teras Utilities Generating Company, et al.)

4 Office of Nuclear Reactor Regulation, Director. 83/03/31. 62p Available at URC \$5.00. 19739:058 24x Fiche:50-445,83/03/31. 8307250079

B307230000 NUREG/CR-3068
CONCEPTUAL DESIGN OF ALTERNATIVE CORE MELT MITIGATION
SYSTEMS FOR A FMR HITH AN ICE-CONDENSER CONTAINMENT
REILLY,H J. COX.N D. POLKINGHORNE.S EGG. Inc FIN A-6351
EGG-2233 83/01/31 Division of Accident Evaluation. 29pp.

8307250075 NUREG/CR-2814 VO2 NUCLEAR FEACTOR SAFETY April 1 - June 30,1782. STEVENSON 9. Los Alamos Scientific Laboratory FIN A-7014-2. LA-9556-PR 83/01/31 Division of Accident Evaluation. 34pp 19721:127

B307250096 Forwards Suppl 2 to SER (NUREG-0896) re application for OL. M/o encl. AMIGHTON, G W. Licensing Branch 3 63/07/12. HARRISON, R. J. Public Service Co. of New Hampshire 4pp 19738-055. 24X Fiche 50-443,63/07/13,8307250098.

8307250103 Application for amend to License DFR-49, proposing Tech Spec Change RTS-154 re RCIC automatic reset & automatic suction switchover from condensate storage tank to suppression pool, ger NUREG-0737, Items II. K. 3 13b & II. K. 3 22.

MCGAUGHY, R. W. Iowa Electric Light & Power Co. NG-83-2294, 837/07/20 DENTON, B. Office of Nuclear Reactor Regulation, Director, 5pp. 1970b, 051. 24X Fiche 50-331, 83/07/20, 8307250108.

8307250107 NUREO/CR-2849
COMPARISON OF COMPARE AND BEACON SUBCOMPARTMENT ANALYSES OF BATTELLE-FRANKFURT CONTAINMENT TESTS.
IDAR.E.S. LIME.J.F., CIDD.R.C. Los Alamos Scientific Laboratory.
FIN A-7111. LA-9461-MS. 83/01/31 Division of Systems
Integration (post Bi1005). 70pp. 19739:154.

9307250117 Advises that mods to relief & safety valve discharge piping will be implemented during next refueling outage scheduled for early 1985.per 830121 itr re NUREG-0737. Item II D. 1. "Performance Testing of Reactor Relief & Safety Valves." TUCKER.H B. Dute Power Co. 83707/19. DENION.H.R. Office of Nuclear Reactor Regulation. Director. 1p. 19706-071. 24X Fiche 50-269.83/07/19.8307250117.

B307250159 NUREO/CR-2397

FUEL INVENTORY AND AFTERMENT POWER STUDIES OF URANIUM-FUELED PRESSURIZED MATER REACTOR FUEL ASSEMBLIES USING THE SAS2 AND ORIGEN-S MODULES OF SCALE WITH AN ENDF/B-V UPDATED CROSS SECTION LIBRARY.
RYMAN.J C , HERMANN,D H., WEBSTER,C.C Oak Ridge National Laboratory FIN A-9047. ORNL/CSD-90 82/16/31. Division of Engineering Technology. 144pp. 19736-280

B307250215 Application for amend to License DPR-49, consisting of Change RTS-153, revising Tech Specs re annual reporting of safety/ relief valve challenges malfunctions & procedures per TM/ Action Item II k 3.3.

MCGAUGHY, R. W. Toua Electric Light & Power Co. NG-83-2292.
B3/07/20 DENTON-H Diffice of Nuclear Reactor Regulation, Director. Jpp. 19708:032 24X Fiche: 50-331, 83/07/20, 8307250215.

--B307250227 Proposed Tech Specs revising Section 6 II.1 & Table 6 II-1 re annual reporting of safety/relief valve challenges, malfunctions & procedures.

\* Iowa Electric Light & Power Co. B3/07/20, 4pp. 19706:035. 24X Fiche: 50-331. B3/07/20, B307250215

8307250219 Advises that util emergency operating instruction being revised to manually energize permanent hydrogen mitigation sys.dus to delay in completion of Westinghouse Owners Group emergency response guidelines.
MILLS.L.M. Tennessee Valley Authority. 83/07/19. ADENSAM.E. Licensing Branch 4. 2pp. 19706:030. 24X Fiche:50-327.83/07/19.8307250219.

8307230231 Responds to Generic Ltr 82-33 (NUREG-0737, Buppl 1) resemengency response capabilities. Operations support ctr approved by Region I. Add1 time required for safety parameter display sys completion.
FIEDLER.P. B. General Public Utilities - GPU Service Corp. GL-82-33. 83/07/18. EISENHUT, D. G. Division of Licensing. 3pp. 19705: 360. 24X Fiche: 50-219, 83/07/18, 8307250231.

B307250233 Suppl 1 to B30217 proposed Amend B3 to License DPR-54 re NUREQ-0737 items & fire protection. RDDRIGUEZ/R.J. Sacramento Municipal Utility District. RJR 83-23B. B3/07/12. EISENHUT, D. Q. Division of Licensing. 1p. 19706:045. 24X Fiche: 90-312,83/07/12,8307250233.

--8307250240 Proposed Tech Specs re nuclear svc bus extensions & fire protection.

\* Sacramento Municipal Utility District. B3/07/12. 7pp. 19706:046. 24X Fiche:50-312.83/07/12.8307250233.

8307250235 Forwards safety evaluation of util 800111,820107 & 0427 responses to NUREG-0737. Item II. B. 2. 2, "Plant Shielding Mods for Vital Area Access." Quidance & criteria met. VARGA.8 A. Operating Reactors Branch 1. 83/04/30. UHRIO, R. E. Florida Power & Light Co. 4pp. 19725:350. 24X Fiche: 50-250,83/04/30,8307250235.

8307250294 NUREG/CR-2634
ACOUSTICALLY MEASURED PENETRATION PROFILES FOR A MOLTEN
METALLIC FDOL INTO RIVER-STONE CONCRETE.
SUTHERLAND, H. J. , HAGEN, S. Sandia Laboratories. FIN A-1218.
SANDB2-0676. 83/01/31. Division of Accident Evaluation. D4pp.
19724:048.

8307250323 NURE9-1011
DRAFT ENVIRONMENTAL STATEMENT RELATED TO STEAM GENERATOR
REPAIR AT THE POINT BEACH NUCLEAR PLANT UNIT NO. 1.
DOCKET NO. 50-266. (Misconsin Electric Power Company)
COLDUNAT. G. Division of Licensing. 83/07/31. 43pp. 19725:284.
24X Fiche: 50-266.83/07/31.8307250323.

8307250332 NUREG-0580 V12 NO6 REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of June 30.1983 (Blue Book) \* Management Information Branch. 83/07/31. 65pp. 19737:221.

B307250450 Submits info obtained to date & expected completion dates of work re-adequacy of PORV block valves per TMI Item II.D. 1. Varification of Anchor/Darling assumptions will be submitted by B31001.
BASKIN.K.P. Southern California Edison Co. B3/07/13.
CRUICHFIELD.D. Deprating Reactors Branch 5. 4pp. 19702:064. 24X Fiche:50-206, B3/07/13, B307250450.

8307250511 NUREC/CR-2967
INFLUENCE OF SCANNING VARIABLES ON ULTRASONIC RESPONSE.
COOK.K.V., LATIMER, P.S., MCCLUNG, R. N. Oak Ridge National Laboratory.
FIN 8-0103. ORNL/TM-6819. 83/01/31. Division of Engineering
Technology. 20pp. 19721:214.

8307250530 NUREG/CR-2475
HYDROGEN COMBUSTION CHARACTERISTICS RELATED TO REACTOR
ACCIDENTS.
BERLAD.A.L., SIDULKIN, M., YANG, C.H. Brookhaven National Laboratory.
FIN A-3315. BNL-NUREG-51492. 83/07/31. Division of Eystems
Integration (post B11005). 43pp. Available at NRC. \$3.75.

8307250544 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-51 & NPF-6 & proposed NBHC & opportunity for hearing re hydrogen/oxygen concentration limitations in radwaste gas sys.

STOLZ, J. F. Derating Reactors Branch 4, 83/07/13. CLARK, R. A. Operating Reactors Branch 3, 2pp. 19715:350. 24X

Fiche: 50-313, 83/07/13, 8307250844.

B307250555 NUREG-0750 V16 NO3 NUCLEAR REGULATORY COMMISSION ISSUANCES September 1982.Pp 865-1.218. \* Commissioners. 82/09/30. 363pp. 19781:235.

B307250591 NUREG-OD40 VO7 NO2 LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT. Guarterly Report.April 1983 - June 1983 (White Book) \* Region 4, Office of Director. B3/07/31. 275pp. 19716:057.

- 8307250663 Forwards draft safety evaluation concluding that util meets Criteria 1 & 3-9 in Item II.B.3 of NUREG-0737. "Post-Accident Sampling Sys." Add info requested within 60 days on Griteria 2:10 & 11 to complete evaluation. CLARK.R.A. Operating Reactors Branch 3. STOLZ.J.F. Operating Reactors Branch 4. 83702714. ORIFFIN.J.M. Arkansas Power & Light Ca. 19pp. 19718.291. 24X Fiche:50-313.83/07/14.8307250663.
- B307260015 Forwards estimated completion dates for emergency response capability upgrade items & revised dates for Reg Guide 1.97 position & Justification repts in response to NUREO-0737, Suppl 1 & Generic Ltr B2-33.
  RODRIGUEZ.R.J. Sacramenta Municipal Utility District. RJR B3-559.
  B3/07/20. STOLZ.J.F. Operating Reactors Branch 4. 3pp. 19727:174.
  24X Fiche: 50-312.83/07/20.8307260015.
- 8307240018 Submits supplemental response to NUREO-0737. Suppl 1 (Generic Ltr 82-33). Description of parameter selection criteria to be submitted by 831231. Human factors & safety parameter display sys verification to be performed w/verification program.

  8WARTZ.E.D. Commonwealth Edison Co. GL-82-33. 83/07/20. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19727:177. 24X Fiche: 50-000,83/07/20.8307260018.
- 8307260034 Reviews Chapters 8, "Climatology, Meteorology & Air Quality" & 13, "Site Issues & Plans," of site characterization rept for Basalt Waste Isolation Project, Rept may be supplemented w/NUREGYCR-2636 info re snow & ice.
  MILLER, M. J. Earth Sciences Branch. 00126. 82/12/02.
  KORNASIEWICZ, R. High Level Waste Technical Development Branch. 2pp. 19786-311.
- 8307260044 Forwards DOE site characterization rept for Basalt Waste Isolation Project Comments on draft site characterization analysis (DBCA), designated NUREG-0960, requested within 14 days of delivery in Jan 1983. W/o encl.
  BROWNING, R. E. Division of Waste Management. 00405. 82/12/02. CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. 2pp.
- 8307260057 Forwards DDE site characterization rept for Basalt Waste Isolation Project. Comments on draft site characterization analysis, designated NUREO-0760, requested within 14 days of delivery in Jan 1983. Wo encl.

  BROWNING.R.E. Division of Waste Management. 00129. 82/12/02. ARBEMAULT,F. Division of Health, Siting & Waste Management. 2pp. 19786:315.
- 8307260143 Advises of completed actions re NUREC-0737. Items II.F. 1.6 & III. D. 3.4 concerning containment hydrogen monitors & control room habitability.respectively.pur 830308 & 14 ltrs. Final action to be completed by 840630.

  JONES.W. C. Omaha Public Power District. LIC-83-174, 83/07/22, CLARK, R. A. Operating Reactors Branch 3. 2pp. 19727: 286. 24X Fiche: 50-283,83/07/22,8307260143.
- 8307260178 Provides add1 info re NUREQ-0737, Item II. K. 2.10 re anticipatory reactor trip sys, in support of request for exemption from NRC 830314 order Request applies only to loss of main feedwater.

  RODRIGUEZ, R. J. Sacramento Municipal Utility District. RJR 83-549.
  83/07/20. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17727:100. 24X Fiche: 50-312, 83/07/20, 8307260178.
- 8307260300 Forwards 6-month response to NUREC-0612. "Control of Heavy Loads at Nuclear Power Plants." Procedures for overhead handling sys include precautions & guidelines to be observed while operating sys.
  CURTIS:N.W. Pennsylvania Power & Light Co. PLA-1732. 83/07/22. 83HMRDGER.A. Licensing Branch 2. 17pp. 19726;092. 24X Fiche: 90-388,83/07/22,8307260300.
- B307260340 Updates B30415 response to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re emergency response capability. Summary repts recontrol room design review, post-accident monitoring & emergency operating procedures will be submitted by 841230. DIXON,O.W. South Carolina Electric & Qas Co. GL-82-33. 83/07/21. DENTON,H.R. Diffice of Nuclear Reactor Regulation, Director. 2pp. 19726:330. 24X Fiche: 50-395.83/07/21.8307260340.
- B307260402 Advises that design gas concentration of two compressed gas bottles in callbr gas subsystem modified from 4% hydrogen & 7% oxygen to 19.9% & 20.9% respectively, per B30609 ltr re NUREO-0737, Item II.F. i.6. HARRINGTON, M. D. Boston Edison Co. 83-193. 83/07/22. VASSALLO, D. B. Operating Reactors Branch 2. ip. 19733:118, 24% Fiche: 50-293, 83/07/22, 8307260402.
- 8307260445 Proposes mod to commitment made in NUREG-0821 per SEP Topic III-5.8 to protect main steam safety & relief valves from effects of block wall failures. Mod would ensure structural integrity.

  MAIER. J. E. Rochester Gas & Electric Corp. 83/07/20. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 19794:207. 24X Fiche: 50-244, 83/07/20, 8307240445.

- B307260453 Notifies that gas turbine preventative maint program will be revised to require calibr of control circuit timers during each refueling outage.per SEP Topic VIII-2. "Onsite Emergency Power Bys."

  COUNSIL.W. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W. 9. Northeast Utilities. R10840. B3/07/20. CRUTCHFIELD.D. Deperating Reactors Branch 5. 1p. 19734:049. 24X Fiche: 50-245.83/07/20.8307260493.
- B307240476 Documents understanding that either Rev 2 or Rev 3 to Reg Quide 1.97 acceptable to NRC for addressing guidelines of NUREO-0737. Buppl 1 (Generic Ltr B2-33) re emergency response capability. QARRITY, J.H. Maine Yankee Atomic Power Co. MN-83-151. B3/07/21. CLARK.R.A. Operating Reactors Branch 3. 1p. 19734:143. 24X Fiche: 50-309, B3/07/21, B307240476.
- 8307260498 Application to amend License DPR-62, revising Tech Specs re supression chamber water level monitoring instrumentation per NUREG-0737, Item II. F. I. 5. HOME, P. M. Carolina Power & Light Co. LAP-83-217. 83/07/22. VASSALLO, D. B. Operating Reactors Branch 2. 3pp, 19731:327. 24X Fiche: 50-324,83/07/22,8307260498.
- --8307260504 Tech Bpec Tables 3.3.5.3-1 & 4.3.5.3-1 re post-accident monitoring instrumentation & post-accident monitoring instrumentation surveillance requirements respectively.

  \* Carolina Power & Light Co. 83/07/22. 2pp. 19731:332. 24X Fiche: 50-324, 83/07/22, 8307260498.
- 8307260526 Responds to unresolved items in EO Adensem 830610 ltr recontrol of heavy loads. Visual aids will be provided to assist crane operator in ensuring that designated sefe load paths followed. Listed lifting devices under evaluation. TUCKER. H. B. Duke Power Co. 83/07/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19731: 289. 24X Fiche: 50-369. 83/07/15. 8307260526.
- 8307270022 Forwards request for add1 info needed for E080 to review util 881203 response to NUREO-0737, Item II. D. i re relief & safety valve testing, Jul 1983 meeting proposed to receive & discuss response since item is to be resolved by 830830.
  8TOLZ.J.F. Operating Reactors Branch 4. 83/07705. HUKILL, H. D. Oeneral Public Utilities OPU Service Corp. 8pp. 19811: 234. 24X Fiche: 50-289, 83/07/05, 8307270022.
- 8307270023 Forwards comments received re technical findings & resolution positions for Unresolved Bafety Issue A-43 recontainment emergency sump performance. Revs to NUREO-0897 recommended. Technical/safety issues & resolutions requested. BERKIZ.A.W. Generic Issues Branch. 83/07/12. DALGHREN.D. Sandia Laboratories. 2pp. 19811:209.
- --8307270028 Forwards comments on NUREQ-0897, "Containment Emergency Bump Performance" & NUREQ-0869, "Unresolved Safety Issue A-43 Resolution Positions." HART, G.H. Guens-Corning Fiberglas Corp. 83/06/23. BERKIX, A. W. Division of Safety Technology. 11pp. 17811:211.
- --B307270033 Comments on draft NUREO-0897 & NUREO-0869 (Reg Guide 1.82 rev).
  PADMANABHAN, M. Alden Research Laboratory. 83/06/13. SERKIZ, A. W. Generic Issues Branch. 7pp. 19811: 222.
- --B306280604 Forwards rev to Table A-3 in NUREQ-0869. Rev corrects discrepancies noticed in values of variables for vertical autilets. Corrections also applicable to NUREQ-0897. PADMANABHAN Aiden Research Laboratory. B3/06/22. SERKII, A. Generic Issues Branch. 4pp. 19811:231.
- 8307270027 Forwards DES (NUREG-1011) re steam generator repair & notice of availability.Comments due within 45 days following FR publication. W/o DES.
  CLARK, R.A. Operating Reactors Branch 3. 83/07/15. Wisconsin, Univ. of
- --B307270030 Notice of availability of DES (NUREG-1011) re steam generator repair.
  CLARK,R. A. Operating Reactors Branch 3. 83/07/15. 7pp. 19811: 202. 24X Fiche: 50-266.83/07/15,8307270027.
- 8307270170 Forwards revised 830330 order re commitments to implement NUREO-0737 items.extending completion date for Item 11.8.3, "Post-Accident Sampling," to 830701.
  STOLZ, J.F. Operating Reactors Branch 4. 83/07/01. BECKHAM, J.T. Georgia Power Co. 3pp. 19811:146. 24X Fiche: 50-321, 83/07/01, 8307270170.

- --8307270174 Mod of order confirming licenses conmitments on post-TMIrelated invasivelenting completion date for Item II.B. 3. Fost-A.C.Ident Sampling: to 830701 EISEMOCR. 0.0 Devision of Licensing 83/07/01 Georgia Power Co. Cup. 19811 149 .84x Fichs 10-321/83/07/01/8307270170.
- 830737018: Firwards Suppl 1 to SER for GESSAR-JI (NUREC-0979).W/o encl. THOMAS.( G. Standardstation A Special Projects Branch. 83/07/20. SHERHOODS G.G. General Electric Go. Spp. 19811.155. 24X Fiche 51-447.\$ 1-07/20. 8307270188.
- B307876307 Forwards "Environ Qualification of Safety-Related Electrical Equipment for Harsh Environ." Vols 1-3.in response to 10FEG-0588 NRC site verification visit expected in late .ul or Aug Response to 10FEG-049 will be provided TAUBER. Detroit Edison Co. FEZ 63.95715. 83/07/19. VGUNGSL330.8 J. Licensing Branch 1. ip 19770:148. 24X Fishe 50-741.93/07/19.8307270207.
- --830727G015 "Environ Qualification of Safety-Related Electrical Equipment for Harsh Environ." Vols I-G. including program description 1 action plans sommany sheets & justification for interim operation. In response to NUREG-0588 Eletroit Edison Co. 83/07/31 1915pp 19770 149 24X Fiche 50-341.83/07/19.830727020
- 836727022' Porwards final NUREO/CR-3224 which will be offered into system to the following system of the system of
- 830727024% Enrwards DES (AMREC-1011) & re repair of steam generators & notice of skallability DES not encl CLARK.R P. Operating Reactors Branch 3. 83/07/15 FAY.C.W. Wisconsin Electric Power Co. 3pp 19812 013 24X Fiche 50-266.83/07/15.8307270245
- B307270PAB Requests copy of NUREG/CR-2983. "Selected Hydrologic & Geathemical Insues in Site Characterization for Nuclear Waste Disposal Flood Basalts at Hanford Reservation." FREI. H. H. Energy, Dept. of. 60321 B3/03/14. BROWNING.R.E. Division of Waste Management 1p. 19809: 216
- 8307270261 Informs that 811123 Evaluation of design plan for emergency response facilities based on NUREG-0814 not applicable per 18 suance : f Suppl 1 to NUREG-0737 CLARK A Departing Reactors Branch 3 83/07/11 JUNES. W. C. Onaha Fublic Power District 2pp. 19811. 186. 24X Fiche 53-285. 83/07/11. 8307270261
- 8307270267 Informs that B11203 evaluation of design plan for emergency response faculities based on NUREG-0814 not applicable per Issuance of Suppl 1 to NUREG-0737 CLARK, R.A. Operating Reactors Branch 2 83/07/11, WITHERS, B. D. Portland General Electric Co. 2pp. 19811:132. 247 Fiche. 30-344, 83/07/11, 8307270267
- 8307270281 Forwards SER re analysis of effect of NUREG-0630 on facility ECCS analysis Administratively imposed temporary restrictions on facility operating limits identified in 830610 Itr appropriate & necessary pending NRC appropriat STOLZ, J.F. Operating Reactors Branch 4 63/07/13. GRIFFIN.J.M. Artansas Power & Light Co. 2pp. 19802 358 24X Fiche: 53-313,83/07/13,8307270281
- 9307270294 Requests identification of specific valves which will be locked open as discussed in 830120 response to NUREC-0727. Item II E t.1. "Autiliary Feedwater Sys Evaluation." Response requested by 830812 STOLZ.J F Operating Reactors Branch 4 83/07/15. CROUSE.R.P. Toledo Edison Co. 2pp. 19812-045 24X Fiche: 50-346,83/07/15,8307270234
- 8307270299 Forwards safety evaluation supporting plant shielding design to corrective actions per TMT Item II 8.2.2. Requirements net Item closed CRUTCHFIELD. D. Operating Reactors Branch S. LSD5-83-07-047. 83/07/26 CDUISIL N.G. Comments of Vanlee Atomic Power Co. Spp. 19769-026 P4x Fiche. 50-213. 83/07/26. 8307270299

- 8307270319 NUREG/CR-3133
  THE SENSITIVITY OF ADULT, EMBRYUNIC AND LARVAL CRAYFISH
  PROCAMBARUS CLARKII TO COPPER.
  RICE, D. M. HARRISON, F.L. Lawrence Livermore Laboratory. FIN A-0119
  UCRL-93948. 83/07/31. Division of Health. Siting & Waste
  Management. 29pp. Available at NRC. \$3.75. 19811:341.
- 8307270333 Forwards DES (NUREG-1011) re steam generator repair: notice of availability & request for comments by interested persons. Notice of availability only encl. CLARK.R.A. Decreting Reactors Branch 3. 83/07/15. PERRIN.8. Environmental Protection Agency. 2pp. 19812:008 24X Fiche: 50-266, 83/07/15, 8307270333.
- 8307270335 Advises that high drywell pressure permissive will be eliminated & manual inhibst switch added by 890430, per NUREG-0737, Item II.K.3.18. "Mod of Automatic Depressorization Sys Logic."

  BAYNE, J.P. Power Authority of the State of New York. JPN-83-70. 83/07/25. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 19767:239. 24X Fiche: 50-330,83/07/25,8307270335.
- 8307270340 Forwards responses to draft SER open items & rev to 830701 response to Open Item 151.

  MCDUFFIE,M.A. Carolina Power & Light Co. IE8-79-21, 83/07/15.

  DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 346pp.

  19768:001. 24X Fiche:50-400:83/07/15.8307270340.
- B307270348 Advises that proposal to separate in-containment high-range radiation monitors by approx 30 ft & to maintain conduit separation acceptable. Design meets criteria of NUREO-0737. Item II.F.i.3.

  STOLZ.J.F. Operating Reactors Branch 4, 83/07/13. HUKILL.H.D. General Public Utilities GPU Service Corp. Spp. 19802:345. 24X Fiche: 50-289.83/07/13.8307270348.
- B307270350 Forwards corrected order confirming commitments on post-TMI-related issues in Item III. D. 3. 4. "Control Room Habitability."

  VARGA.S.A. Operating Reactors Branch 1. B3/06/21. UTLEY, E. E. Carolina Power & Light Co. 2pp. 19788:356. 24X

  Fichs: 50-261,83/06/21,830/270350.
- --8307270356 Corrected order confirming licenses commitments on post-TMIrelated issues per Item III.D.3.4. "Control Room Habitability." EISENHUT, D. 0. Division of Licensing. 83/06/21, Carolina Power & Light Co. 1p. 19788: 358, 24X Fiche: 50-261,83/06/21,8307270350.
- 8307270357 Forwards draft SER re NUREG-0737, Item II.B. 3, "Post-Accident Sampling Sys." Five of ii criteria met Meeting proposed to discuss compliance w/six criteria.

  STOLZ.J.F. Operating Reactors Branch 4. 83/07/13. HUKILL, H. D. General Public Utilities GPU Service Corp. 13pp. 17802:332. 24X Fiche: 50-289, 83/07/13, 8307270359.
- 8307270360 NUREO/CR-2938
  TAILINGS TREATMENT TECHNIQUES FOR URANIUM MILL WASTE:
  A Review Of Existing Information.
  SHERWOOD, D. R., SERNE, R. J. Battelle Momorial Institute, Pacific
  Northwest Laboratory, FIN B-2370, PNL-4453, 83/07/31. Division
  of Health, Sting & Waste Management. 82pp. Available at NRC.
  \$4, 30, 19802:244.
- 9307270366 NUREO-0485 V05 NO6 SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As Of June 30,1983 (Buff Book) \* Office of Resource Management, Director. \* Office of Nuclear Reactor Regulation, Director. 83/07/31. 74pp. 19811:266.
- 8307270443 Forwards SER re NUREG-0737, Action Item III. D. 3.4, "Gontrol Room Habitability," Design acceptable. VARGA.8.A. Operating Reactors Branch I. 83/07/07. GIEBLER, C. W. Wisconsin Public Service Corp. Spp. 19802: 238. 24X Fiche: 50-305, 83/07/07, 8307270443.
- 8307270452 Forwards rept on safety parameter display sys safety analysis, per 830415 commitment & response to Generic Ltr 82-33. Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability,"

  BOUCHEY, G. D. Washington Public Power Supply System. GL-82-33. B3/07/01. BCHWENCER, A. Licensing Branch 2. 40pp. 19767:138. 24X Fiche: 50-397, 83/07/01, 8307270452.
- B307270455 Informs that evaluation of design plan for emergency response facilities using NUREO-0814, per NRC B11120 ltr, not applicable to facility in view of issuance of Suppl I to NUREO-0737, per B21217 submitted!
  CRUTCHFIELD, D. Operating Reactors Branch 5. L805-83-07-050. 83/07/26. LINDER, F. Dairyland Power Cooperative. 2pp. 19767:178. 24X Fiche: 50-409, 83/07/26, B307270455.

- 8307280020 Forwards comments on FES re decommissioning of Rare Earths Facility, West Chicago, IL (NUREG-0904). FES deficient & unresponsive to EPA DEB concerns. Rept does not substantiate that onsite waste disposal will be accomplished acceptably. ALBERICO.P.A. Environmental Protection Agency. 22548. 83/07/15. DAVIS, J. O. Office of Nuclear Material Safety & Safeguards. Director. 5pp. 19826:022.
- 8307280080 Discusses G Hecker concerns about Figure 3.6 in NUREG-0897 re containment emergency sump performance. Figure 3.6 replacement corrected copy encl. Concern re uncertainties in Merry data needs attention.

  8WIFT, W. L. Creare, Inc. 83/06/13. STROM, P. Sandia Laboratories.

  5pp. 19826:011.
- 8307280098 Forwards add1 info to util 830418 response to NUREQ-0737, Suppl 1 re safety parameter display sys.detailed control room design review & Reg Guide 1.97.
  UHRIO,R.E. Florida Power & Light Co. L-83-421. 83/07/25.
  VARGA.S.A. Operating Reactors Branch 1. 4pp. 19791:179. 24X Fiche: 50-250, 83/07/25, 8307280098.
- 8307280231 Forwards NUREQ-0960, "Draft Site Characterization Analysis," ltr of transmittal to RL Morgan & FR notice of availability. W/o encis.

  M/o encis.

  DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 00374. 83/03/31. 8PELLMAN, J. Washington, State of. 4pp. 19826:088.
- 8307280286 Responds to unresolved IE Insp Rept Items 277/82-23-01 & 278/62-22-01 re TMI Item II. B. 2, "Design Review of Plant Shielding."

  DALTROFF.S.L. Philadelphia Electric Co. 83/05/13. STAROSTECKI.R. Region I: Office of Director. 33pp. 19790:176. 24X Fiche: 50-277, 83/05/13, 8307280286.
- 8307280289 Forwards comments on draft NUREG-0927. "Evaluation of Water Hammer Experience in Nuclear Power Plants." Water hammer design considerations should apply to entire feed sys. RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2798. 83/07/20. KNIEL.K. Division of Safety Technology. 3pp. 19796:322.
- 8307280350 Forwards response to NRC 830628 & 0707 requests for addition of NUREQ-0737, item II.B. 2, "Plant Shielding."
  RIDRIGUEZ.R. J. Sacramento Municipal Utility District. RJR 83-553.
  837077/14. MARTIN.J.B. Region 5, Office of Director, Opp.
  19790:111. 24X Fichs: 50-312,83/07/14,8307280350.
- 8307280367 Forwards responses to 830504 acceptance review questions re safety-related structures, sus & components, GA program, fracture prevention of containment pressures boundary & inadequate core cooling.

  HOOLEVER, E. J. Duquesne Light Co. 2NRC-3-044. 83/07/14.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 11pp. 19796; 107. 24X Fiche: 50-412, 83/07/14; 8307280367.
- 8307290024 Forwards GA Program Insp Rept 97900802/83-01 on 830411-15 & notices of nonconformance & violation. POTAPOVS.U. Region 4. Office of Director. 83/07/08. PIRAING.D. Kaman Co. Spp. 19821:090.
- --8307270040 GA Program Insp Rept 99900802/83-01 on 830411-15.
  Noncompliance noted:design requirements not incorporated into mod procedures & emergency operating procedures manual, Bection 6 incorrectly identified.
  PARKER.L.B. Region 4. Office of Director. BARNEB, I. Division of Vendor & Technical Programs. 83/07/01, 7pp. 19821:095.
- B307290090 Requests review of util B30317 submittal, NRC B30603 ltr & clarification re whether NRC request concerning TMI Item II, K, 3, 18, "Automatic Depressurization Sys Logic Mods," appropriate.

  ZIMMERHAN, B, R. Carolina Power & Light Co. LAP-B3-323, 83/07/26. VASBALLO, D. B. Operating Reactors Branch 2. 2pp. 19822; 149, 24X Fichs: 50-324,83/07/26,8307290090.
- 8307290148 Forwards final response to NUREO-0737, Item II.D. 1, "Performance Testing of PMR Relief & Safety Valves." KAMMER.D. S. Tennessee Valley Authority. 83/07/22. ADENSAM.E. Licensing Branch 4. 8pp. 19821:053. 24X Fiche: 50-390,83/07/22,8307290148.
- 8307290190 Forwards FR notice of consideration of issuance of amend to License DPR-76 & proposed NBHC determination & opportunity for hearing re Tech Spec changes on installation of two new inverters & associated buses. NBHC determination withheld.

  BUCKLEY, B. Licensing Brench 3. 83/07/15. SCHUYLER, J. O. Pacific Gas & Electric Co. 4pp. 19857:037. 24X Fiche: 50-275, 83/07/15.

- --8307290192 Notice of consideration of issuance of amend to License DPR-76 & proposed NBMC determination & opportunity for hearing re Tech Spec changes on installation of two new inverters & associated buses to satisfy NUREG-0737. KNIGHTON, O.W. Licensing Branch 3. 83/07/12. 8pp. 19857:041. 24X Fiche: 50-275,83/07/15,8307290190.
- 8307270193 Forwards discussion of implementation of NURE9-0737, Item II. K. 3.18, "Automatic Depressorization Sys Logic Mods." per 830603 request. High drywell pressure permissive will be sliminated & manual inhibit switch added. PILANT.J. M. Nebraska Public Power District. LGA8300013. 83/07/22. VASSALLO.D. D. Operating Reactors Branch 2. 2pp. 19821:146. 24X Fiche: 50-298,83/07/22,8307270193.
- B307290204 Forwards safety evaluation resolving NUREG-0737. Items II.F. 1.4. "Containment Pressure Monitor." II.F. 1.5. "Containment Hater Level Monitor" & II.F. 1.6. "Containment Hydrogen Monitor." VASBALLD, D.B. Operating Reactors Branch 2. B3/07/18. RMODE, G. K. Niagara Mohawk Power Corp. 2pp. 19857:049. 24X Fichs: 50-220, 83/07/18, 8307290204.
- B307270206 Forwards response to 830603 request for add1 info re NUREO-0737. Item II.K.3 18. "Automatic Depressurization Bys Logic Mod." Proposed changes can be accomplished w/no loss of plant safety factor. Existing sys adequate. KAMMER.D.S. Tennessee Valley Authority. B3/07/22. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 19821: 144. 24X Fiche: 50-259, 83/07/22, 8307270206.
- B307270461 FDIA request for NRC Bi0227 ltr to GE. Date of ltr referenced in NUREG-0390, Vol 6. PEDRO J. NUS Corp. CD-LIS-9130. B3/04/26. Division of Rules and Records. 1p. 19859:042.
- 8307290466 Forwards safety evaluation of util responses to 801222 generic ltr re control of heavy loads. Phase I of issue resolved. Technical evaluation rept entl. CLARK, R. A. Operating Reactors Branch 3. 83/07/18. WITHERS, B. D. Portland General Electric Co. 2pp. 19839:060. 24X Fiche: 50-344,83/07/18,8307290466.
- --8307290475 Safety evaluation of util responses to generic issue, "Control of Heavy Loads Near Spent Fuel." First response (Phase I) acceptable.

  4 Operating Reactors Branch 5. 83/07/18. 2pp. 19859:062. 24X Fiche: 50-344,83/07/18,8307290466.
- --8306140436 TER-C5506-398
  "Control of Heavy Loads, Portland GE Co, Trojan Nuclear
  Plant:" technical evaluation rept.
  BOMBERGER, C. Franklin Institute/Franklin Research Center.
  NRC-03-81-130. TAC 07716. B3/06/10. SINGH.A. NRC No Detailed
  Affiliation Given. 29pp. 19859:064. 24X Fiche: 50-344.83/07/18.
  B307290466.
- B30729054B Forwards safety evaluation re demonstration of purge & vent valve operability (B-24). Operability of 8-inch pressure relief valve not yet demonstrated. Long-term option of blocking 42-inch purge/vent valves acceptable. CLARK.R. A. Operating Reactors Branch 3. 83/07/19. GARRITY.J. H. Maine Yankee Atmic Power Co. 2pp. 19857:075. 24X Fiche: 50-309. B3/07/19. 8307290548.
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8306240435 Responds to NRC request re disposition of three unresolved areas based on FEMA testimony at ASLB 820917 hearing in Forth Worth.TX.

  KRIMM.R.W. Faderal Emergency Management Agency. 83/03/22.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 19830:252. 24X Fiche: 50-445.83/03/22,8306240435.
- B306270401 IE Info Notice B3-46, "Common Mode Valve Feilures Degrade Burry Recirculation Spray Bubsystem." Svc list encl. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post B30103), B3707711. Consolidated Edison Co. of New York, Inc. 134pp. 17363:273. 24x Fiche: 50-000,83/07/11,8306270401.
- B306270404 IE Info Notice B3-47, "Failure of Hydraulic Snubbers as Result of Contaminated Hydraulic Fluid." Svc list encl. JORDANIE.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/07/12. Consolidated Edison Co. of New York, Inc. 141pp. 19563:133. 24X Fiche: 50-000.83/07/12.8306270404.

- 8306270406 IE Info Notice 83-48, "Oaseous Effluent Releases of Radioactive I-125 & I-131 in Excess of NRC Limits." Syc list enc 1. TAYLOR: J. M.
  - enci. TAYLOR.J.M. Division of QA, Safeguards & Inspection Programs (Post 830103). 83/07/14. Consolidated Edison Co. of New York, Inc. 114pp. 19713:270. 24x Fiche: 30-000,83/07/14.8306270406.
- 8307050222 Responds to approval request for info collection re 100FR20 toncerning stds for protection against radiation. Request approved through 860131 Under DMB Number 3150-0014.per Paperwork Reduction Act.
  SCURRY.N. OFfice of Management & Budget. DMB 3150-0014. 83/06/17. BCOTT; S. Document Management Branch. 2pp. 19261:027.
- 8307050224 Responds to approval request for info collection re NUREG-0737 concerning clarification of TMI action plan requirements & related orders. Request approved through 850930 under OMB Number 3150-0065. SCURRY, N. Office of Management & Budget. OMB 3150-0065. 83/06/17. SCURTY, S. Document Management Branch. 2pp. 19261:029.
- B307030230 Responds to approval request for info collection re NRC Form 371 concerning list of college courses & certificate of scholastic achievement. Request approved through 860630 under DHB Number 3150-0054, per Paperwork Reduction Act. BCURRY.N. Office of Management & Budget. BMB 3150-0054. B3/06/17. BCOTT. S. Document Management Branch. 2pp. 19261:031.
- BG07050234 Responds to approval request for info collection re generic clearance of draft IE bulletin. "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Request approved through B50430 under DMB Number 3150-0012. SCURRY,N. Office of Management & Budget. CMB 3150-0012. B3/06/17. BCOTT,S. Bocument Management Branch. 2pp. 19261:033.
- B307060376 Forwards draft findings based on review of encl FEMA draft its & evaluation of emergency response plan for Rancho Seco Nuclear Generating Station & on IE Insp Rept 50-312/83-09. Corrective actions requested within 4 months. MARTIN, J. B. Region 5, Diffice of Director. B3/06/15, RODRIGUEZ, R. J. Sacramento Municipal Utility District. 4pp. 19236:258. 24X Fiche: 50-312, 83/06/15, B307060376.
- --8307060384 Evaluation of emergency response plan for Rancho Seco Nuclear Generating Station Major deficiencies identified. \* Federal Emergency Management Agency. 82/06/23. 72pp. 19236: 262. 24X Fiche: 50-312, 83/06/15, 8307060376.
- B3070B0747 Forwards requests for OMB review & supporting statement re revs to 10CFR40,70 & 73 providing advance notification & assurances of protection for certain types of nuclear matl shipments. NDRRY,P.G. Defice of Administration. 83/07/01. SCURRY,N. Office of Management & Budget. 1p. 19385:330.
- 8307080739 Forwards request for OMB review & supporting statement for final rule to 10CFR3D. "Requirements for Licensee Actions re Bisposition of Spent Fuel Upon Expiration of Reactor Operating Licenses."
  NDRRY, P. G. Office of Administration. 83/07/01. SCURRY, N. Office of Management & Budget. ip. 19385:338.

- B307120311 Forwards INPD, "Evaluation of Mains Yankee Atomic Power Plant for 1983," from site evaluation conducted during B30116-23.

  BRUNNER,E. J. Division of Project & Resident Programs. 83/07/08. TAYLOR,J.M. Division of Reactor Programs (Pre 830103). CASE,E.G. Office of Nuclear Reactor Regulation, Director. ip. 19427:108. Fiche: 50-309, B3/07/08. 8307120311.
- --8307120314 "Evaluation of Maine Yankee Atomic Power Plant for 1983." \* Institute of Nuclear Power Operations. 83/05/31. 39pp. 19429:109. 24X Fiche: 50-309, 83/07/09, 8307120311.
- NOTIGORIT Advises that interim findings re offsite radiological response plans will be sent to FEMA headquarters. Related correspondence.

  CABSIDY, B. P. Federal Emergency Management Agency. B3/07/06.

  LAURENSON, J. A., ANDERSON, G. C., PAXTON, H. C. Atomic Safety and Licensing Board Panel. 1p. 19508:051. 24X Fiche: 50-482,83/07/06,8307/30217.
- 307140225 Forwards FEMA Region IV rept of observation results from B21208-D9 emergency exercise & Georgia Emergency Myt Agency response. Encourages tontinued work w/offsite agencies as necessary to resolve open issues.

  O'REILLY, J. P. Region 2. Office of Director. B3/03/25, KELLY, R. J. Georgia Power Co. 25pp. 19523: 126. 24x Fiche: 50-321, B3/03/25, B3/07140225.

- 8307140420 Forwards FEMA evaluation rept of 830120-21 emergency exercise per IE Insp Repts 50-335/83-04 & 50-387/83-12. DANCE,H.C. Division of Project & Resident Programs. 83/03/30. URRIG.R.E. Florida Power & Light Co. 1p. 19520:213. 24X Fiche: 50-335,83/03/30,8307140420.
- --8307140424 "St Lucie Nuclear Power Plant Full-Brale Local Exercise Conducted on 830120," final evaluation rept.

  \* Federal Emergency Management Agency. 83/03/08. 36pp. 19520:214. 24X Fiche: 50-335, 83/03/30, 8307140420.
- 8307150167 Forwards memo supplementing 830322 findings on adequacy of remedial actions taken by util resulting from 820914 order. Order required applicant to demonstrate that six deficient areas in offsite emergency planning & preparedness remediad. KRIMM.R.W. Federal Emergency Management Agency. 83706/17. UDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 19530:246. 24X Fiche: 30-155, 83/06/17, 8307150167.
- B307180202 Forwards request for QMB review & supporting statement re final rule 10CFR50.62 concerning reduction of risk from ATWS events for light-water-cooled nuclear power plants. NORRY,P. G. Diffice of Administration. B3/07/08. SCURRY,N. Offic of Management & Budget. ip. 19567:339. SCURRY, N. Office
- 8307190173 Forwards evaluation rept of radiological emergency exercise conducted on 830323, Deficiencies cited in four areas that will require schedule of corrective actions. Extension until and of June to furnish schedule granted.

  KRIMM.R.W. Federal Emergency Management Agency. 83/06/13.

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 930103). 3pp. 19634:172. 24X Fiche: 50-387,83/06/13,8307190173.
- --8307190177 Evaluation of PA:Columbia & Luzerne Counties & participating municipalities emergency preparedness plan for Susquehanna Steam Electric Station.

  Faderal Emergency Management Agency. 83/03/23. 66pp. 19634: 175. 24X Fichs: 50-387, 83/06/13, 8307190173.
- 8307170237 Discusses status of B30404 proposed stipulation of contentions. No agreement reached amongst counsel at B30427 conference call FEMA cannot commit resources to preparing testimony for B30B30 prefiling.
  CASSIDY.B.P. Federal Emergency Management Agency. 83/07/11. SIMPSON. J.M. Simpson. J.M. 2pp. 19630:081. 24x Fiche: 30-482.83/07/11,8307170237.
- B307190248 Discusses status of B30406 proposed stipulation of contentions. No agreement reached amongst counsel at B30427 conference cail. FEMA cannot commit resources to preparing testimony for B30830 prefiling.
  CASSIDY. B. P. Federal Emergency Management Agency. 83/07/11 SILBERG, J. E. Shaw. Pittman, Potts & Trowbridge. 2pp. 1966 24X Fiche: 50-482, 83/07/11, 8307170248. 83/07/11. 19629:279.
- 830720010B Forwards FEMA B30617 comments on intervenor comments relicensee response to deficiencies identified in ASLB 820914 emergency preparedness order FEMA original position that licensee comments adequate unchanged.

  OUDDARD.R.J. Hearing Branch 3. 83/07/15. BLOCH.P.B., SHON,F.J., PARIS,O.H. Atomic Bafety and Licensing Board Panel. 18pp. 19646: 030. 24X Fiche: 30-155,83/07/15,8307200108.
- 8307200210 Confirms discussions at 830713 prehearing conference re providing Town of Southhampton & other emergency planning parties \( \omega \)/correspondence between NRC & FEMA on FEMA review of bil interim offsite emergency response plan.

  LATHAM, S. Tuomey, Latham & Shea. ISSUANCES OL-3. 83/07/14. BORDENICK, B.M. Hearing Branch 3. PERRY, S. Federal Emergency Management Agency. 2pp. 19448:028. 24X Fiche: 50-322, 83/07/14, 8307200210.
- 8307200335 Responds to approval request for info collection re questionnaire to NRC licensees. Request approved through 831031 under DMB Number 3150-0097, per Paperwork Reduction ACC. SCURRY,N. Office of Management & Dudget. DMB 3150-0099. 83/07/09. SCOTY.S. Document Management Branch. 2pp. 17670:001.
- 8307260603 Responds to approval request for info collection re 10CFRSO.71(A) concerning domestic licensing of production & utilization facilities. Request approved through 850430 under OMB Number 3150-00011.per Paperwork Reduction Act. SCURRY.N. Office of Management & Budget OMB 3150-0011. 83/07/06. SCOTT, S. Document Management Branch. 2pp. 19787:347.
- 8307260606 Forwards request for OMB review & supporting statement for info collection re reactor operator & senior operator licensing & requalification exams.

  NORRY, P. O. Office of Administration. 83/07/20. SCURRY, N. Office of Management & Budget. ip. 19787:361.

#### R PROPOSED RULE

- 8303180682 Forwards response to 830215 ltr re impact of decentralization on safety of nuclear facilities Positive effect on plant safety expected.

  DIRCKS,W. J. Office of the Executive Director for Operations.

  B3/03/09. FRALEY.R.F. ACRS Advisory Committee on Reactor Safeguards. 7pp. 19434:038.
- 830A090500 Forwards comments on & resolution of proposed 10CFR20 rewrite re controlled areas & site boundaries.

  ANDERSON, F. D. Standardization & Special Projects Branch. 83/05/31.
  CLEVELAND, R. S. Research & Standards Coordination Branch. 5pp. 188(2) 064.
- B304290596 Comments on NRC policy statement on regionalization.Opposes statement. MEAVER.J. D. Nebraska Public Power District. 48FR12419 062. B3703/23. HALE.C.J. Region 4. Office of Director. Upp. 19434:036.
- 8307010050 Advises recipients of comments on proposed rules 10CFR50 & 51.re requirements for licenses actions on disposition of spent fuel upon expiration of reactor OLs, that Comment 3 miscoded, Number 3 will not be used again.

  3 Docketing & Services Branch. 4BFR22730. 83/06/30. Docketing & Services Branch. 1p. 19168:310.
- B307050035 Comments on proposed rule 10CFR40 re stds for disposal of U mill tailings Opposes rule.
  ANDRUS,N.J. Federal American Partners. 48FR23649 009. 83/06/27.
  Docketing & Services Branch. 21pp. 19220:286.
- 8307050117 Package of 10 comments on proposed rule 10CFR93 re-criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity.

  8TEWART, W. L. Virginia Electric & Power Co. FOLLOCK, M. S. Long Island Lighting Co. VANDEWALLE, D. J. Consumers Power Co. 48FR19382. 83/06/30. Docketing & Services Branch. 31pp. 19220; 102.
- 8307050268 "Environ Impact Assessment for Amend to 10CFR35 Group Licensing for Certain Medical Uses, Addition of Radiopharm TC-97m Labeled Albumin Colloid." MACDONALD.C.E. Division of Fuel Cycle & Material Safety. 83/06/21 5pp. 19261:023.
- B307050367 Forwards J Scinto B3060B itr expressing Executive Legal Director (ELD) interpretation of regulation in handling repts of changes per 10CFR50. 54(p). Past practice in handling licensee requests consistent w/ELD interpretation THOMAG. C. D. Standardization & Special Projects Branch. B3/06/13. CORKLE.G.W. Power Reactor Safeguards Licensing Branch. BROWN.W. B. Fuel Facility Safeguards Licensing Branch. 19 19263:263.
- --8307050374 Responds to 830415 memo re evaluation of licensee 10CFR50.54(p) repts.NRC must advise licensees of specified type of info withheld from public disclosure.
  BCINTO.J.F. Office of the Executive Legal Director. 83/06/08.
  MIRRGLIA.F.J. Assistant Director for Safety Assessment. 1p. 19263: 264.
- --B307050378 Requests views re NRC obligations concerning evaluation of licensee rept of changes to security & safeguards contingency plans per 100FR30. 34(p) repts.
  MIRROLIA.F. J. Assistant Director for Safety Assessment. 83/04/15.
  SCINTO.J. Office of the Executive Legal Director. 2pp.
- B307060195 Consolidated Group 4 comments in response to Commission request for comments re implications of Nuclear Waste Policy Act of 1982 on waste confidence decision. Discussion justified & supported W/Gertificate of Syc. AKELRAD.M., BAUSER,M.A. Lowenstein, Newman, Reis, Axelrad & Toll. B3/07/01. 21pp. 19249: 206.
- B307070101 Comments on implications of Nuclear Waste Policy Act of 1982 for draft Commission B30316 waste confidence decision & on lack of support for Commission finding that spent fuel can be stored w/o significant environ effects.
  FINAMORE, B. A. Natural Resources Defense Council. JORDAN. W. B. Hunton & Williams. B3/06/30. Commissioners. 13pp. 19294:102
- B307070107 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity. Elimination of 2-yr limit would more accurately follow congressional intent.

  MUSGLE, D. Northern States Power Co. 48FR19382 030. 83/06/28.

  Docketing & Services Branch. 2pp. 19294: 119.

- 8307070108 Forwards ANS comments on NRC draft decision & proposed rule re-storage & disposal of nuclear waste.

  CURRIN.E C Pacific Legal Foundation CURRIN.E C American Nuclear Society 83706/30 CHILK.S J. Office of the Secretary of the Commission. MILLER.M.E. Atomic Safety and Licenting Board Panel.

  1p 19295-001
- --8307070117 Comments on NRC draft decision & proposed rule re storage & disposal of high level nuclear waste.NRC should expedite final decision & findings of confidence.Certificate of Svc encl.

  CURRIN.E C. Pacific Legal Foundation. CURRIN.E.C. American Nuclear Society 81/12/21 17pp 19295 002.
- 8307070110 Comments on NRC policy statement on safety goals re evaluation plan & proposed rule 10CFR50 re policy statement on severe accidents & related views on nuclear reactor regulation w/respect to value of PRA studies. BIALIK, E. I. New York, State of 48FR10772 023 83/06/30. Docketing & Services Branch. 1p. 19294 092.
- B307070112 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent fuel storage capability Util will need to develop comprehensive spent fuel mpt plan to determine if storage problem exists. HODK, K. A. Bechtel Corp. 48FR193B2 031. 83/06/30. Docketing & Services Branch. 2pp. 19294:121.
- 8307070114 Comments on proposed rule 10CFR50 re policy statement on severe accidents & related views on nuclear reactor regulation. Opposes use of PRA studies BIALIK,E.I. New York, State of. 48FR16014 006. 83/06/30. Docketing & Services Branch. lp. 19293:345.
- B307070118 Comments on proposed rules 10CFR50 & 51 re requirements for licensee actions concerning disposition of spent fuel upon expiration of OLs Supports rules PATTERSON.J.D. Middle South Services, Inc. 48FR22730 007 B3/07/01. Docketing & Services Branch 2pp 19294:123.
- 8307070120 Package of three comments on proposed rule 10CFR53 recriteria & procedures for determining adequacy of available spent nuclear fuel storage capacity.

  GUERON.H.M. Consolidated Edison Co. of New York, Inc. BRADBURY.R.B. Stone & Webster Engineering Corp. BDUCHEY.G.D. Washington Public Power Supply System. 49FR19382. B3/07/01 Docketing & Services Branch. 6pp. 19294:095.
- B307070126 Comments on proposed rules 10CFR50 % 51 re requirements for licensee actions on disposition of spent fuel upon expiration of DLs. Supports rule. CROUSE, R.P. Toledo Edison Co. 48FR22730 003. B3/06/29. Docketing & Services Branch. ip. 19294:101.
- B307070129 Package of two comments supporting proposed rule 10CFR50 re NRC policy statement on severe accidents 5 related views on nuclear reactor regulation. GRIFFITH. U.D. Energy, Dept. of. FARRAR.D. Commonwealth Edison Co. 48FR16014. B3/07/05. CHILK.S.J. Office of the Secretary of the Commission. 7pp. 19274:176.
- B307070131 Comments on proposed rules 10CFR50 & 51 re requirements for licensee actions on disposition of spent fuel upon expiration of reactor OL Opposes rule. FREY.D.G. Sassafras Auduban Society, 48FR22730 012. B3/07/03 Office of the Secretary of the Commission. ip. 19294:156.
- 8307070133 Response to Commission request for comments on draft waste confidence decision. Decision should be finalized based on cited rationale & Nuclear Waste Policy Act of 1982 Certificate of Svc encl.

  DAVIS,L. D. Energy, Dept. of. 83/07/01. 35pp. 19294-183.
- B307070138 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation. Opposes rule. FREY.D.G. Sassafras Audubon Society. 48FR14014 008. B3/07/03. Office of the Secretary of the Commission. 1p. 19274:158.
- 8307070140 Package of two comments on proposed rules 10CFR50 & 51 re requirements for licensee actions on disposition of spent fuel upon expiration of OLs.
  REYNOLDS:N S. KNOTTS.J. B. Debevoise & Liberman. 48FR22730.
  B3/07/05. CHILK:S.J. Office of the Secretary of the Commission.
  None 19294.227
- B307070136 Package of two comments re proposed guspension of selected portions of 10CR40.App A re U & thorium mili tailings mgt at active processing sites.

  SUNDIN.R.E. Wyoming, State of. LIND-HONE.K.E. Ebasco Services, Inc. (subs. of Enserch Corp.). 48FR23649. 83/07/01. NRC No Detailed Affiliation Given. 9pp. 19294:341.

- 8307070157 Package of two comments opposing proposed rules 10CFR50 & 51 re requirements for licensee actions on disposition of spent fuel upon expiration of GLs.

  BERICK.D Environmental Policy Institute SINDERGRAND.C.

  Hisconsin, State of 48FR22730. 83/07/05 Docketing & Services
  Branch lipp 19789-344.
- 8307070163 Comments on proposed rules 10CFR50 & 51 re requirements for licensee actions re disposition of spent fuel upon expiration of DLs Supports rule.

  BAUSERM A. Louenstein, Neumann Reis, Axelrad & Toll. 48FR22730 007.
- B307070187 Package of two comments opposing proposed rules 10CFR50 & 51 re requirements for licensee actions concerning disposition of spent fuel upon expiration of OLs. FRISCOLD C Coalition for Nuclear Power Plant Postponement. JORDAPLW 5 Harmon & Weiss. 46FR22730. B3/07/06. Docketing & Services Branch. 11pp. 19274:080
- 8307070248 Notice of substitution of LD Davis for OF Brown as DOE counsel re iOCFR50 & iOCFR51.

  DAVIS.L D Energy, Dept. of. 83/07/01. 10pp. 19267:211.
- B3070B0342 Comments on proposed rule 10CFR50 re NRC policy statements on severe accidents & related views on nuclear reactor regulation.

  JIM.R. Yakama Indian Nation. 4BFR16014 009. 83/06/30. CHILK.S.J. Office of the Secretary of the Commission. 2pp. 19350:327. 24X Fiche:50-522.83/06/30,8307080342.
- --8307080350 Comments on DES for Skagit/Hanford Nuclear Plant.EIS flawed in scope b content & fails to recognize existence of Yakima Indian Nation. No significant adverse impact addressed. Comment may not be used in proceeding.

  JIM.R. Yakima Indian Nation. 48FR16014 009. 82/08/30. BLACK.R. NRC No Detailed Affiliation Civen. 1p. 19350:343. 24X
  Fiche 50-522,83/06/30.8307080342
- 8307080435 Comments on proposed rules 10CFR50 & 51 re requirements for licenser actions on disposition of spent fuel upon expiration of DLs.

  JUM.R. Yakima Indian Nation. 48FR22730 013. 83/06/30. CHILK.S.J. Office of the Secretary of the Commission. RATHBURN.D., MATTSON.R.J. NRC No Detailed Affiliation Given. 2pp. 19347: 001. 24X
- --B307080440 Comments on DES for Skagit/Hanford Nuclear Plant. EIS flawed in stope & content & fails to recognize existence of Yakima Indian Nation. No significant adverse impact addressed. Comment may not be used in proceedings.

  JIM.R Yakima Indian Nation. 4BFR22730 013. B3/06/30. BLACK.R. NRC No Detailed Affiliation Given. 1p. 19347:017. 24X Fiche: 50-522.83/06/30.8307080435
- B3070B0499 Comments on proposed rules 10CFR50 & 51 re Commission response to 830516 draft decision on storage & disposal of nuclear waste Commission finding of confidence should be withdrawn.

  BIALIK, E. I. New York, State of. 48FR22730 003. 83/06/27. Off of the Secretary of the Commission. 4pp. 19346:350.
- B307110387 Forwards A Rosenthal comments on proposed rule changes to iOCFR2 requiring parties to file single responsive brief regardless of number of appellant briefs filed HOYLE, J Office of the Secretary of the Commission. 48FR27876 001. 83/07/07. STUCKY, S. NRC No Detailed Affiliation Given. 1p. 19380-327.
- --8307i10393 Comments on proposed rule 10CFR2 requiring parties to file single responsive brief regardless of number of appellant briefs filed ROSENHAL.A. Atomic Safety and Licensing Appeal Panel. 48FR29876 001. 83/06/30. PALLADIND.N., GILINSKY,V., ROBERTS, T.M. Commissioners. 2pp. 19380:328
- 8307110420 Comments on proposed rule IOCFR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation. Supports decision to require applicant to perform PRA.

  DORSEY, J. A. Dorsey, J. A. 48FR16014 010. 83/07/05. Docketing & Services Branch ip. 19382:275.
- 307110454 Comments on proposed rules IOCFR50 & 51 on requirements for licensee actions re disposition of spent fuel upon expiration of OLs. NRC approval of storage plan should be considered application for amend to OL. MCGRANERY, J. P. Scientists & Engineers for Secure Energy. 48FR22730 O17 83/07/05. CHILK.S. J. Office of the Secretary of the Commission. 4pp. 19380:108.

- 8307110461 Package of three comments opposing proposed rules 10CFR50 & 51 re requirement for licensee actions concerning dispositions of spent fuel upon expiration of U.s. SALVESEN.D. Hisconsin's Environmental Decade. SEELY.S. New England Coalition on Nuclear Pollution. PILALIS.L.E. Affiliation Unknown. 48FR22730. 83/07/07. Docketing & Services Branch. 3pp. 19380:103.
- B307110465 Comments on proposed rule re NRC policy statement on regionalization. Supports rule.
  LEWIS.N. D. Washington, State of. 48FR12619 063. B3/03/31.
  DIRCKS.W. J. Office of the Executive Director for Operations. 1p.
- 8307120194 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation. Severe accident criteria apply only if safety goals established & assessed.

  CURRAN.D., SHOLLY, S. S. Union of Concerned Scientists. 48FR16014
  011. 83/07/08. NRC No Detailed Affiliation Given. 17pp. 19423:317.
- 8307120318 Marked-up transcript of NRC policy statement on regionalization from 830406 meeting in Rosemont IL.Pp 1-111. KEPPLER.J., NURLEY.T., BLACKWOOD, E. Region 3, Office of Director. 48FR12619. 83/04/06. 114pp. 19429:173.
- 8307120323 Protests timing of B30405 meeting to discuss NRC decentralization of certain regulatory functions from headquarter ofcs to regional ofcs. Meeting conflicts w/Comanche Peak licensing hearing.

  ELLIS.J. Citizens Association for Sound Energy. 48FR12619 066. 83/03/03. DIRKCKS.W.J. Defice of the Executive Director for Operations. 1p. 19429:288.
- 8307120362 Forwards six comments on NRC policy statement on regionalization. Transcript of public meeting on decentralization also encl. W/o encls.
  BLACKWOOD, E. NRC No Detailed Affiliation Given. 4BFR12619.
  83/07/07. CHILK, S. J. Office of the Secretary of the Commission. ip. 19429:095.
- 8307120417 Package of two comments on NRC policy statement on regionalization. Opposes rule.
  EBERSOLE, J. C. ACRE Advisory Committee on Reactor Safeguards.
  GAGE.K. Nuclear Information & Resource Service. 4BFR12619.
  83/07/08. PALLADING, N. J. Commissioners. 6pp. 19425: 082.
- B307120419 Comments on NRC policy statement on regionalization. Supports policy statement.

  MORRISBETT.E. Montana College of Mineral Science & Technology.

  48FR12619 061. B3/03/31. DIRCKS,W.J. Office of the Executive Director for Operations. 1p. 19430:141.
- 8307140544 Forwards draft FR notice amending 10CFR55 reflecting delegation of licensing authority for operator licensing function to regional administrator of Region I, for signature.

  DENTON.H.R. Office of Nuclear Reactor Regulation: Director. 83/06/30. DIRCKS,N.J. Office of the Executive Director for Operations. 8pp. 19326:133.
- 8307130168 Comments on proposed rule 10CFR50 re policy statement on severe accidents & related views on nuclear reactor regulation. Opposes rule: Failure to ack that risk of severe accidents not known represents significant weakness.

  SEELY.8. New England Coalition on Nuclear Pollution. 48FR16014 012. B3/07/08. Office of the Secretary of the Commission. 2pp. 19530:086.
- B307150179 Comments on proposed rule 10CFR50 rs NRC policy statement on severe accidents & related views on nuclear reactor regulation. Supports rule.

  SHERWOOD, O. 9. General Electric Co. 48FR16014 018, B3/07/11, Docketing & Services Branch. 2pp. 19531:011.
- B307150183 Comments on proposed rule 10CFR90 re policy statement on severe accidents. Opposes rule. LEWIS.M. I. Lewis, M. 48FR16014 013. 83/07/11. Office of the Secretary of the Commission. 1p. 17531:051.
- B307150256 Forwards comments from 61 members of NRR Div of Licensing on proposed rule re NRC policy statement on regionalization.
  BLACKHOOD, E. B. Regional Operations & Generic Requirements.
  B3707/13. CHILK, S. J. Office of the Secretary of the Commission. 1p. 19538:353.

- --8306290994 Forwards summary of comments on decentralization of project mgt function of operating reactors explaining concerns w/ presently constituted plan & how regionalization should proceed if results beneficial.

  WAMBACH.T.V. Operating Reactors Branch 5. 48FR12619 067.
  83/03/11. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 26pp. 19339:003.
- --B304200163 Forwards comments from lead project managers re quality & quantity of reviews conducted by regions.

  LAINAS.G.C. Assistant Director for Operating Reactors. 48FR12619 067. B3703/24. EISENHUT.D.G. Division of Licensing. 15pp. 15pp.
- --8307050061 Responds to B30412 memo re decentralization of operating reactors project mgt function. Opposes decentralization due to assurance of coordination & communication problems which will lead to wide variations in safety levels.
  WIGGINTON.D. Operating Reactors Branch 1. 48FR12619 067.
  B3/05/12. BEVAN.R. NRC No Detailed Affiliation Given. 15pp. 19339: 044.
- --8306290600 Advises that decision to decentralize NRC should be examined to determine whether program constitutes major Federal action under NEPA which would require issuance of EIS. NORRIS.J.A. Operating Reactors Branch 1. 48FR12619 067. 63/04/12. PURPLE.R.A. Division of Licensing. 1p. 19539:059.
- --8306290603 Recommends regional technical staff consist of project manager, electrical & mechanical engineers & regional & resident inspectors as part of plan to decentralize operating reactors project mgt function.
  HORKINS.J. B. Licensing Branch 4. 48FR12619 067. 83/04/26. PURPLE,R.A. NRC No Detailed Affiliation Given. 1p. 19539:060.
- --B306290605 Suggests communication problem re decentralization would be more effectively served if Commissioners order project managers to spend at least 2 days of any 2-month period at assigned plant site.
  BURMELL,S.B. Licensing Branch 1. 48FR12619 067. B3/04/22.
  PURPLE,R.A. NRC No Detailed Affiliation Given. 4pp. 19539:061.
- B307150257 Package of two comments supporting proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation.
  BRADBURY,R.B. Stone & Webster Engineering Corp. ELWARD.T.W. Consumers Power Co. 48FR16014. B3/07/11. Docketing & Services Branch. 4pp. 19338:342.
- B307150272 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents. Opposes rule. HIATT.B.L. Affiliation Unknown. 48FR16014 014. 83/07/01. Docketing & Services Branch. 3pp. 19538:100.
- 8307150276 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation. Supports rule. BCHMITZ.R.P. Bechtel Corp. 48FR16014 019. 83/07/08. Docketing & Services Branch. 2pp. 19538: 113.
- 8307150277 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on nuclear regulation. NRC should postpone final statement pending resolution of backfitting issue.

  HELFRICH.R.E. Yankee Atomic Electric Co. 48FR16014 020. 83/07/12.

  Docketing & Services Branch. 2pp. 19538:115.
- 8307130280 Comments on proposed rules 10CFR90 & 51 re spant fuel storage.Opposes rules. HIATT/8 L. Affilation Unknown. 48FR22730 018. 83/07/01. Docketing & Services Branch. 1p. 19531:107.
- 8307150295 Comments on proposed rule 10CFR35 re group licensing for certain medical uses. Opposes rule. FARNER, S.A. LIXI, lnc. 49FR13189 013. 83/07/08. WALKER, W. Assistant Director for Material Safety & Licensing. 4pp. 19532: 208.
- 8307150276 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity. Preventing public input in spent fuel matters will cause taxpayers financial burden.

  HIATT, S. L. Affiliation Unknown. 48FR19382 032. 83/07/01.

  Docketing & Services Branch. 1p. 19532:205.
- 8307150301 Comments on proposed rule 10CFR50 re policy statement on severe accidents & related views on nuclear reactor regulation. Policy statement should resolve PRA weaknesses. LEAVER.D.E. Wood-Leaver & Associates, Inc. 48FR16014 016. 83/07/08. Office of the Secretary of the Commission. 5pp.

- 8307180113 Cumments on proposed rule 10CFR53. "Criteria & Procedures for Determining Adequacy of Available Spent Fuel Storage Capacity" BALE.L.F. Mississippi Power & Light Co. 48FR19382 033 83/07/11. Docketing & Services Branch 2pp. 19556: 269
- 8307180131 Comments on proposed rules 10CFR50 & 51. "Requirements for Licensee Actions re Disposition of Spent Fuel Upon Expiration of Reactor OL." Supports rule. DALE.L.F. Mississippi Power & Light Co. 49FR22730 019. 83/07/08 Docketing & Services Branch. 2pp. 19556-270
- 8307180150 Comments on proposed rule IOCFR20 re performance testing program for dosimetry svcs Opposes rule TODD, H. E. Siemans Gammasonics 45FR2043 080. 63/07/07. PALLADINO.N. Commissioners. 1p 1956-255.
- B307190124 Comments on proposed rule 10CFR20 re amend incorporating entire personnel dosimetry accreditation program Supports rule
  BAIETTI.A. ICN Pharmaceuticals Inc. ICN-CtR Development. 45FR20493
  OB1. B3/07/13 PALLADING
- B307190146 Comments on proposed rule 10CFRSO re NRC policy statement on severe accidents & related views on nuclear reactor regulation Supports rule. MILLS.L.M. Tennessee Valley Authority 48FR16014 021. B3/07/11. Docketing & Services Branch 3pp. 17636:189.
- B307190154 Forwards 830623 revised comments on proposed rule 100FR20 re repts of theft or loss of licensed mat1.
  VAUGHAN.C.M. General Electric Co. 48FR20721 005. 83/07/12.
  Docketing & Services Branch. 1p. 19628: 255.
- B307250015 Forwards draft final rule re changes to 10CFR50, modifying & codifying existing LER sys ready for FR publication.
  Related public announcement & ltrs for transmittal to Congressional committees also encl.
  HELTEMES,C. J. Director's Office. 63/07/14 FELTON, J. M. Division of Rules and Records. 55pp. 19721:004.
- --B307230021 Forwards notice of final rulemaking re-changes to existing LER sys to be published in FR.All licensess of nuclear power plants will be required to submit written repts of any significant events. W/o encl. HELTEMES.C. J. Director's Office. 83/07/14. SYNAR.M. House of Rep., Government Derations. OTTINGER.R. L. House of Rep., Energy & Commerce. SIMPSON.A. House of Rep., Environment & Public Works. 4pp. 19721:059.
- B307250412 Comments on proposed rule 10CFR50 re proposed Commission policy statement on severe accidents & related views on nuclear reactor regulation. Supports rule RAHE, E.P. Westinghouse Electric Corp. 48FR16014 022. B3/07/15. CHILK, S. J. Docketing & Services Branch. 2pp. 19701:341.
- 8307250416 Package of two comments supporting proposed rule 10CFR50 re proposed Commission policy statement on severe accidents. EDELMAN.M. Atomic Industrial Forum. SCHERER.A.E. Combustion Engineering, Inc. 45FR16014. 83/07/21. Docketing & Services Branch. 7pp. 19702:170.
- 8307250588 Requests FR publication of Final Rule 10CFR55 re transfer of licensing authority pertaining to operator licensing to Region I administrator. THDMP60N.H.L. Division of Human Factors Safety. 83/07/08. FELTDN,J.M. Division of Rules and Records. 1p 19718:080.
- --8307250599 "Partial Regionalization of Operator Licensing Function to Include Region I." DIRCKS.N.J. Office of the Executive Director for Operations. 83/07/01. 7pp. 19718:081.
- --8307250616 Forwards FR notice re amend to 10CFR55 assigning authority & responsibility for licensing of nuclear power plant operators & senior operators in Region I to Regional Administrator Public announcement also encl. H/O encl. DENTON.H.R. Office of Nuclear Reactor Regulation. Director 83/07/08. OTTINGER.R.L. House of Rep., Energy & Commerce. 1p. 19718: 088.
- --8307290622 Forwards FR notice re amend to 10CFR55 assigning authority & responsibility for licensing of nuclear power plant operators & senior operators in Region I to Regional Administrator-Public announcement also enci. Wo enci. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 83/07/08 UDALL.M.K. House of Rep., Interior & Insular Affairs. ip. 19718:089.

- --B307250534 Forwards FR notice re amend to IOCFR55 assigning authority & responsibility for licensing of nuclear power plant operators & senior operators in Region I to Regional Administrator. Public announcement also encl. W/o encl. DENTON H R Office of Nuclear Reactor Regulation, Director. B3/07/08 SIMPSON A. Senate, Environment & Public Works. 1p. 19718-090
- 8307240311 Comments on proposed rule 10CFR20 modifying reporting of loss or theft of radioactive matis Supports rule, Final rulemaking should clarify which licensee responsible for reporting BROWN, R H Mallinckrodt, Inc. 48FR20721 007. 83/07/21. Docketing & Services Branch 2pp. 19726-293
- 8307270273 Forwards FR notice of final rulemaking 100FR50.73 re modifying & codifying existing LER sys.
  HELTEMES.C J Director's Office 83/07/18 GTTINGER.R.L. House of Rep., Energy & Commerce. SIMPBON.A. House of Rep., Environment & Public Works UDALL.M.K. House of Rep., Interior & Insular Affairs.
  4pp 19814 131.
- PROJ PROJECTS -- PREDOCKET LICENSING
- 8307050395 Forwards FR notice of withdrawal of application for CP REGAN, W. M. Site Analysis Branch ISSUANCES A. B3/06/15. FALLIN.J.F. Pacific Gas & Electric Co. Ip. 19263:291.
- --B307050357 Notice of withdrawal of application for CP.
  REGAN.W H. Site Analysis Branch. 83706/15. 1p. 19263:292.
- 8307090128 Trip rept of 830526 visit to BNHL to provide technical support to DDE for Nest Valley Demonstration Project.
  CLARK.A F. Advanced Fuel & Spent Fuel Licensing Branch.
  High Level Naste Licensing Management Branch. 83/06/20.
  Advanced Fuel & Spent Fuel Licensing Branch. BELL.M. J. High Level Maste Licensing Management Branch. 4pp. 19366:296.
- B307110632 Trip rept of B30613-14 visit to West Valley site to tour burial ground area & discuss site hydrology issues w/USGS & B30615 visit to NY State Geological Survey in Albany.NY regeology of West Valley area.
  HURT,R.D. Advanced Fuel & Spent Fuel Licensing Branch. 83/06/28.
  RDUSE.L C. Advanced Fuel & Spent Fuel Licensing Branch. 2pp. 19391:334. 24X Fiche: 50-201.83/06/28.8307110632.
- 8307120397 Forwards proprietary version of "MAPWR Pretendering Module 6 Reactor Sys." Hodule provides MAPWR design detail & reflects licensing control document commitments Rept withheld Gref 10CFR2 790). RAHE, E.P. Westinghouse Electric Corp. NS-EPR-2786. 83/06/30. EISENMUT, D.G. Division of Licensing. 2pp. 19430:265.
- --830712039? Application for withholding "WAPWR Pretendering Module 6 Reactor Sys." from public disclosure (ref 10CFR2.790). WESSMAN.R. A. Hestinghouse Electric Corp. AW83-35. 83/06/30. EISENHUT.D.G Division of Licensing.
- 8307140513 Notification 83-48 of 830711 mgt meeting w/DQE in King of Prussia-PA to discuss status of Hest Valley Demonstration Project & DOE/NRC interfaces Proposed agenda encl. ROTH, J. Region 1, Office of Director. 83/06/30. Region 1, Office of Director. 83/06/30. Region 1, Uffice of Director. 20p 19527 343. 24x Fiche 50-201.83/06/30.8307140513.
- 8307200495 Forwards "Analysis of Terminal Waste Form Selection for West Valley Demonstration Project."

  COFFMAN.F E Energy, Dept. of 22498 83/06/14 NRC No Detailed Affiliation Given. ip. 19672:001. 24x

  Fiche: 90-201.83/06/14.8307200495
- B307280114 Forwards proprietary slides presented at B30628 meeting w/NRC in Bethesda MD re Westinghouse advanced PWR Pretendering Modules 3 & 4. Slides withheld (ref. 10CFR2. 790). RAME, E.P. Hestinghouse Electric Corp. NS-EPR-2795 B3/07/12. EISENHUI.D G. Division of Licensing. 1p. 19795:307.
- --B307280120 Requests withholding per 10CFR2.790 of encl presentation mat1 from B30628 meeting w/NRC re Westinghouse advanced PWR Pretendering Modules 3 & 4.

  WIESEMANN.R.A. Westinghouse Electric Corp. AW-83-56. B3/07/12.

  EISENHUT.D.G. Division of Licensing. lp. 19795:308.
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8307050018 Part 21 evaluation rept re mismarling of ten 1,000 mCi Am-241 sources as 1,000 uCi. GC insp procedure changed, requiring that markings be recorded on insp form HOADLEY.S D Monsanto Co 83/06/20. Region 3, Office of Director 5pp 19220:058

- 8307050096 Final Deficiency Rept U-55 ra Robertshaw thermostatic flow control valves Castellated not & cutter pin installed & valve body O-ring eliminated, proventing valve stem from disengating. Also reported per Part 21.

  8CHNELL.D.F. Union Electric Co. 10CFR 050.55E. 83/06/24.

  KEPPLER.J.G. Region 3, Office of Director. 1p. 19199:337. 24X

  Fiche: 50-483.63/06/24.8307050096.
- 8307050219 Final deficiency rept re improperly torqued bolt on instrument mounts. Initially reported on 830222, Bolts will be replaced & torqued per designer specs. Corrective action due in approx 2 months. Also reported per Part 21.

  KDESTER. G. L. Kanass Gas & Electric Co. 100FR 050, 35E. 83/06/24.

  SEIDLE. M. C. Region 4, Office of Director. 4pp. 19198: 329. 24X Fiche: 50-482, 83/06/24, 8307050219.
- 8307060016 Final Deficiency Rept Item 95 re Comsip. Inc post-LUCA containment gas monitoring sys. Initially reported on 830524. Item not reportable per 10CFR50. 55s since sys not in use at facility. Also reported per Part 21. WELLS.D.A. Detroit Edison Co. PT21 83-921-000. 83/06/24. KEPPLER.J.G. Region 3. Office of Director. 1p. 19251:035. 24X Fiche: 30-341.83/06/24,8307060016.
- 8307070001 Part 21 rept re lack of automatic restart capabilities of P-47 chillers after loss of affsite power. Initially reported on 830429. Evaluation continuing.

  BARKER, N.R. Gilbert/Commonwealth Cos. 83/06/30. DEYQUNG, R.C. Director's Office, Office of Inspection and Enforcement. ip. 19293: 158 24X Fiche: 50-440, 83/06/30, 83070700001.
- B307070282 Part 21 rept re RCIC pump turbine which could operate w/o adequate room cooling. Initially reported on B30429. Automatic cooling water provided to pump room cooling unit when RCIC turbine starts.

  BARKER.N.R. Gilbert/Commonwealth Cos. B3/06/30. DEYDUNG.R.C. Director's Office. Office of Inspection and Enforcement. 1p. 19294:091. 24X Fiche: 50-440, 83/06/30. B307070282.
- B307080476 Final deficiency rept re triaxial cable mfg by Rockbestos used in electrical penetrations supplied by Westinghouse. Initially reported on B11026. Cable RSS-6-108 will be used as replacement. Also repurted per Part 21.

  OPREA, G. W. Houston Lighting & Power Co. 10CFR 050. 55E. B3/06/30. CULLINS. J. T. Region 4, Office of Director. 3pp. 19346: 325. 24X Fiche: 50-498, B3/06/30. B307080476.
- B307110231 Final Deficiency Rept U-56 & Part 21 rept re metal bellows flexible hose assembly w/60 degree instead of 90 degree fitting at discharge of reactor coolant pump B motor. Initially reported on B30602. All assemblies inspected. SCHNELL.D.F. Union Electric Co. 10CFR 050.55E. B3/07/01. KEPPLER.J.G. Region 3. Office of Director. 2pp. 19380:031. 24X Fiche: 50-483,83/07/01,8307110231.
- B307110244 Part 21 rept re deficiency in Bechtel design of ac & dc control circuits for facilities. Design changes to affected mator controller & power circuit breaker compartments initiated. Also reported per 100FR30. 35(e) by SNUPPS.

  MEYERS.B.L. Bechtel Corp. P721 83-923-000. B3/06/30. KEPPLER, J. O. Region 3. Office of Director. SEVFRIT. K. Region 4. Office of Director. Spy. 19374: 337. 24X Fiche: 50-000, 93/06/30. B307110244.
- 8307110390 Final deficiency rept re-potential problems w/loop power supply card heat sinks of Westinghouse 7300 process protection sys (SD-40). Initially reported on 830602 Concurs w/Hestinghouse hardware changes. Also reportable per Part 21. COUNSIL.W.G. Northeast Nuclear Energy CD. (Subs. of Northeast Utilities.) COUNSIL.W.G. Northeast Utilities. 10CFR 050. 35E. B3/07/01 MURLEY. T. E. Region 1, Office of Director. 3pp. 19380: 284. 24X Fiche: 50-423, 83/07/01. 8307110370.
- 8307120167 Sixth interim deficiency rept re RCS support & restraint bolt torques. Initially reported on 810824. EPRI funding received for NDE & corrosion research re high strength fasteners. Also reportable per Part 21.

  MILLS, L. M. Tennessee Valley Authority. 10CFR 050. 55E. 83/06/29.

  D'REILLY, J. P. Region 2, Office of Director. 2pp. 19423:160. 24X Fiche: 50-438, 83/06/29, 8307120167.
- B307120179 Final deficiency rept re steam generator water level ref column error. Initially reported on 790706. Sensing lines will be thermally insulated & low-low water level setpoint will be adjusted. Also reportable under Part 21.
  MILLS, L. M. Tennessee Valley Authority. 10CFR 050. 58E. 83/06/30. 0'REILLY, J. P. Region 2. Office of Director. 3pp. 19424:001. 24x Fiche: 30-390.83/06/30.8307120179.
- B307120207 Interim deficiency rept re Items 93 & 72 concerning shop welding in Bergen-Patenson seismic I pipe hangers & undersize skewed fillet welds. Initially reported on B20813 & 1105. Final rept by B31003. Also reported per Part 21. PARSUNS.R. M. Carolina Power & Light Co. 100FR 050. 55E, 83/07/01. 0/REILLY.J.P. Region 2. Office of Director. 5pp. 19423:284. 24X Fiche: 30-400.83/07/01.8307120207.

- 8307120433 Final deficiency rept for Unit 1 % interim deficiency rept for Unit 2 re incorrect wipe setting on normally closed contacts converted from normally open contacts on HFA relays. Also reportable under Part 21 for Unit 1. MCGAUGHY. J. P. Mississippi Power & Light Co. 10CFR 050. 35E. 83/07/01. 0/REILLYJ. J. P. Region & Light Co. 10CFR 050. 4pp. 19425: 240. 24X Fiche: 50-416.83/07/01: 8307120433.
- 8307120452 Final deficiency rept for Unit 1 % interim deficiency rept for Unit 2 re PRD-82/14 concerning sheared bolts on diesel generator rear crankcase cover Initially reported on 820322 Unit 1 bolts adequate. Also reported per Part 21.

  MCCAUGHY, J. P. Mississippi Power & Light Co. 10CFR 050. 55E.
  83/07/05. D'REILLY, J. P. Region 2. Office of Director. 6pp. 19425: 349. 24X Fiche: 50-416, 83/07/05. 8307120452.
- B307120499 Interim deficiency rapt re emergency diesel generator starting air valve assembly mfg by Transamerica Belaval. Initially reported on B20618. Capscrew design revised. Next rapt by const restart. Also reportable per Part 21. DE LORENZO,R. A. Washington Public Power Supply System. 10CFR 050. 58E. B3/06/29. STERNBERG, D.M. Region 5. Defice of Director. 2pp. 19425:021. 24X Fiche: 50-460. B3/06/29. B307120499.
- 8307120527 Final deficiency Rept DER 83-33 re GE Model AKR-50 breakers w/EC-1 trips which may have generic defect. Initially reported on 830429. Bechtel will correct defects prior to fuel load. Also reportable per Part 21.
  VAN BRUNTI, E.E. Arizona Public Service Co. 10CFR 050. 55E. 83/06/24. STERNBERG, D.M. Region 5. Office of Director. 11pp. 19433:295. 24X Fiche: 50-530. 83/06/24. 8307120529.
- 8307140259 Provides addl info re Part 21 rept dtd 830627 on throttling of HPI valves. Valves provided to ather 177 fuel assembly plants not mfg by Walworth Co & not specified for throttling conditions associated w/small break LDCA scenarios.

  TAYLOR. J. H. Babcock & Wilcox Co. 83/07/08. DEYQUING.R.C. Director's Office, Office of Inspection and Enforcement. 2pp. 17523:002.
- 8307150111 Part 21 rept re 8-inch uninsulated section of red conductor on 3-conductor 12 gauge wire supplied to facility during 1980. Info obtained 830616. Cause under investigation. ROBERTS, L. B. Brand-Rex Cs. 83/06/20. COLLING, J. Region 4, Office of Director. 2pp. 19536:213. 24X Fiche: 50-312,83/06/20.8307150111
- 8307130119 Part 21 rept re deviation in installation of ASCO 302A1264C transfer switches. Evaluation in progress. Next rept will be submitted within 60 days of 1tr date.

  MANNA.F. J. Automatic Switch Co. 83706/27. Region 4. Office of Director. 1p. 19536: 227. 24X Fiche: 50-247, 83/06/27, 8307150117.
- 8307150207 Sixth interim deficiency rept re containment spray miniflow valve design error initially reported on 820305.Engineering Change Notice 3420 under review for closure.Next rept will be provided by 830928. Also reportable per Part 21.
  MILLS.L.M. Tennessee Valley Authority. 10CFR 050.55E. 83/07/06.
  O'REILLY.J.P. Region 2, Office of Director. 1p. 17530:234. 24X fiche: 50-390.83/07/06,8307150207.
- 8307150208 Final Significant Deficiency Rept SD-39 re potential problems w/temp channel test (NTC) card relays Initially reported on 830602.Relay replaced prior to operation. Also reported per Part 21 by Westinghouse.

  COUNSIL, W. G., SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. O. Northeast Utilities. 10CFR 050.595. 83/07/06. WURLEY IT. E. Region 1, Office of Director. 4pp 19530: 221. 24X Fiche: 50-423,83/07/06.8307150208.
- B307150237 Part 21 rept re capacitors on Model 68 temp monitor modules w/blown seals. Hold placed on modules returned for mod. FIALA, D. US Riley Corp. B3/06/10. ANDERSON, G. General Electric Co. 2pp. 19530: 205.
- 8307150239 Final Delficiency Rept PRD-82-38 re Nelson stud failures on embedded plates. Initially reported on 821221. Condition not reportable per Part 21 for Unit 2. Failure unique to Type 86 plate. Welds will be redesigned. MCOAUGHY.J.P. Mississippi Power & Light Co. PRD-82-38. 83/07/05. URBILLLY.J.P. Region 2. Office of Director. 6pp. 19531:097. 24X Fiche: 50-416.83/07/05.8307150239.
- B307150263 Part 21 rept re indeterminate wold quality due to surface irregularities that may mask defects. Initially reported on 830622. Piping subassemblies containing welded angular branch connections w/pad reinforcement reviewed.

  MOERKE. M. H. BORNES, R. P. Southwest Fabricating % Welding Co. (subs. of IU International Corp.). 83/06/24. PDTAPDVS.U. Region 4. Office of Director. 5pp. 19538:080. 24x Fiche: 50-461.83/06/24.8307150263.

- B307150273 Part 21 rept me potential defect in component cooling water sys Initially reported on B30523 Loss of pressure integrity of equipment could result in loss of function of component cooling water systreducing degree of protection DERIENZO.P.P. Gibbs & Hill, Inc. (subs. of Dravo Corp.). B3/06/28. P307150273
- 8307150358 Part 21 Evaluation Rept 83-01 re section modulus error in ADLPIPE program Initially reported on 830128. Error did not affect safety-related nuclear power plant piping sys. Deviation not reportable per Part 21 VERDERBER. J. J. Burns & Roo Co. BRGG-83-002 63/04/26. CCULLING. J.P. Region 4, Office of Director 3pp 19539:090 24X Fiche: 50-397, 83/04/26. 8307150338.
- --8307190362 "Evaluation of ADLPIPE Error in Tee Element re Defect & Noncompliance Evaluation Rept 83-01. MPPSS Nuclear Power Plant 2."
  CHU, A. STUDNICKA, Z., MICHEJDA, O. Burns & Roe Co. 83/03/28
  17pp 19539:093. 24X Ficha:50-397,83/04/24,8307190358.
- B307150369 Final/interim Deficiency Rept PRD-B2/(4 for Units 1/2, respectively re sheared bolts on rear crankcase cover of Delaval diesel generators. Unit 1 bolts not defective. Unit 2 rept due on B50130. Also reportable per Part 21. MCGAUGHY. J. P. Mississippi Power & Light Co. 10CFR 050. 55E. B3/07/05. D'REILLY. J. P. Region 2. Office of Director. App. 19539: 084. 24X Fiche: 50-416. B3/07/05. B307150369.
- B307190380 Final deficiency rept re Item 136 on pipe hanger frame base metal reduction. Initially reported on B30606. Frame C-1-195 will be refabricated w/certified matl ½ will be welded onsite. Also reported per Part 21.

  PARSONS.R.M. Carolina Power & Light Co. 100FR 050.55E 83/07/05.

  O'REILLY.J.P. Region 2, Office of Director. 3pp. 19539:156 24X

  Fiche: 50-400.83/07/05.8307190380.
- 8307180081 Part 21 rept clarifying position re equipment failures during C-E qualification testing of Target Rock solenoid activated valves per T Lee 830620 request Valve design conforms to NUREG-0388 Retrofit program supported. PATTARINI.D.M. Target Rock Corp. E-16673. 83/07/11. DEYGUNG.R.C. Director's Office, Office of Inspection and Enforcement. 1p. 19560:007. 24X Fiche: 50-528.83/07/11.8307180081.
- B307180144 Interim deficiency rept re problem w/top cover gaskets on NAMCO Model EA180 series switches. Problem traced to over-impregnated & insufficiently heat cured top cover gaskets Also reported per Part 21 DE LORENZO, R. A. Washington Public Power Supply System. IOCFR 050. 55E 83/07/01. STERNBERG.D.M. Region 5. Office of Director. 3pp. 19557:046. 24X Fiche: 50-460. 83/07/01. 8307180144.
- B307210122 Interim Part 21 rept re 8-inch uninsulated section of red conductor, 3-conductor, 12-gauge wire shipped during 1980 to facility, Info obtained 830616 Condition under evaluation. RODERTS, L. B. Brand-Rex Co. PT21 83-924-000. 83/07/01. Director's Office, Office of Inspection and Enforcement 2pp. 19668:195. 24X Fiche: 50-312, 83/07/01, 8307210122.
- B307210221 Forwards B30621 Part 21 rept rs valve seat defects.
  GALLO.R M. Region 1. Office of Director. B3/07/05. KISTER.H. 8
  Region 1. Office of Director. 1p. 19865.290. 24X
  Fichs.50-000.83/07/05.8307210221.
- ---B307210229 Part 21 rept re valve seat defect Initially reported on B30620 Risk of seat cracking could occur under torque. Bechtel analysis underway. BARCLAY, J. F. Yarway Corp. P121 83-924-000 83/06/21. GALLO,R. Region 1, Office of Director 11pp. 19666: 291 24X Fiche 50-000,83/07/05,8307210221.
- B307220080 Second interim deficiency rept re Johnson Machine Works welds on auxiliary feedwater pump room doors. Initially reported on 830210. Doors returned to vendor for rework. Next rept expected by 840117. Also reported per Part 21 MILLS.L.M. Tennessee Valley Authority. 100FR 050 53E. 83/07/12. 837821LLY, J.P. Region 2. Office of Director. 3p. 19674:074. 24X Fiche: 50-438.83/07/12.8307220080.
- B307220145 Interim deficiency rept Item 127 re weld deficiencies on ITE Gould Class 1E 480-voit motor control ctrs. Initially reported on 830408. Extension of submittal of rept on reportability requested to B30831. Also reported per Part 21. PARSONS. R M. Carolina Power & Light Co. 100FR 050 55E 83/07/13. O'REILLV.J.P. Region 2. Office of Director 1p 17684 075 24X Fiche 50-400.83/07/13.8307220145.

- B307220169 Eighth interim deficiency rept re failure of Chattanooga Bolt & Screw nuts & Challenge Enterprises bolts to meet ASTM specs. Initially reported on B10924 Results of bolting matl analysis under review Also reportable per Part 21.
  MILLSIC. M Tennessee Valley Authority. 10CFR 050 55E. B3/07/14.
  O'REILLY, J. P. Region 2. Office of Director. 2pp. 19684:082 24X Fichs 50-438,83/07/14,8307220169.
- B307220265 Final deficiency rept re detachment of ILSCO Corp Number 14 stranded wire from screw clamp detectors initially reported on 830524. Deficiency not reportable per 10CFR50.55(s) for Unit 2. Item reportable per Part 21 for Unit 1. CWRISS.N.W. Pennsylvania Power & Light Co. 10CFR 050.55E. B3/07/13 MURLEY.T. Region 1. Office of Director. 3pp. 19683:226. 24X Fiche: 50-387.83/07/13.8307220265.
- 8307220446 Part 21 rept re possible discrepancy in variable springs in turnbucile & top plate assemblies bolt interface. No recorded failures or complaints registered against subj products. Encl list of springs identified for Comm Ed only.

  LITKA.T.J. Elican Metal Products Cd. 83/07/15. KEPPLER.J. Q. Region 3, Office of Director. 26pp. 19686:096. 24X Fiche: 50-000.83/07/15, 8307220446.
- 8307220483 Second interim deficiency rept re inadequacies in Bechtel design verification of max circuit lengths of low voltage power & control cables. Initially reported on 821215. Also reportable under Part 21. Next rept by 831031.
  CURTIS.N.W. Pennsylvania Power & Light Co. 100FR 050. 55E. 83707715. MURLEY.T. Region 1, Office of Director. 4pp. 19485: 185. 24X Fiche: 50-387, 83707715, 8307220483.
- 8307250335 Part 2) rept re putential defect in high pressure fuel injection line of DSR or DSRV standby diesel generator. Removal of random sample of lines to be internally borescope inspected recommended. BOYER.R. E. Transamerica Delaval. Inc. B3/07/20. Director's Office, Office of Inspection and Enforcement. 2pp 19703:011. 24: Fiche: 50-000.83/07/20.8307250335.
- B307250404 Fourth interim deficiency rept. Item &i re defective valve iprings on diesel engines mfg by Transamerica Delaval. Intitially reported on 810828 Final rept will be submitted by 840104. Also reportable under Part 21.

  PARSONS.R.M. Carolina Power & Light Co. 10CFR 050. 55E. 83/07/14. 8/REILLY.J.P. Region 2, Office of Director. 4pp. 19703: 209. 24X Fiche: 30-400.83/07/14.8307250404.
- B30725040B Second interim deficiency rept or snubber interference from rear brackets and by ITT Grinnell. Initially reported on B30126. Review of ITT Grinnell test results underway. Also reportable under Part 21. Next rept by 840125.

  MILLS, L. M. Tennessee Valley Authority. 100FR 050.58E. 83/07/15. D'RETLLY, J.P. Region 2. Office of Director. 2pp. 19704:013. 24X Fiche: 50-438,83/07/15,8307250408.
- 8307230461 Part 21 rept re defect in component of DSR-48 standby diesel generator. Improved design jacket water pump assembly retrofitted to all facility engines in Nov 1982. Assembly proven successful during several hours tested.

  80YER.R.E. Transamerica Delaval, Inc. 83/07/20. Director's Office. Office of Inspection and Enforcement. 2pp. 19701:321. 24X Fiche: 50-322,83/07/20,8307250461.
- 8307250464 Tenth interim deficiency rept re failure of main steam lines due to main feedwater overfill. Initially reported on 800319. Final analysis % verification of main steam line piping overfilt event not complete. Also reportable under Part 21. MILLS.L.M. Tennesses Valley Authority. 100FR 050.55E. 83/07/14. 0'REILLY.J.P. Region 2. Office of Director. 2pp. 19701:166. Z4X Fiche: 30-438, 83/07/14, 8307250464.
- B3072A0419 First interim deficiency rept re makeup/high pressure injection pump vibration. Initially reported on B30622, B&W requested to advise of corrective actions. Next rept expected by B31202. Also reported per Part 21.

  MILLS.L. M. Tennessee Valley Authority. 83/07/20. O'REILLY, J. P. Region 2. Office of Director. 2pp. 19733. 177. 24X fiche: 50-438, 93/07/20, 8307260419.
- 8307260485 Interim rept re welding deficiencies in main steam/feedwater support frames. Initially reported on 830715, Support frames evaluated item considered not reportable under (OCFRSO, 55(e) t Part 2)
  - \*\*Yeart 21
    \*\*YEANOI.N.J. Carolina Power & Light Co. 10CFR 050.55E. 83/07/15.
    \*\*TEILLY, J.P. Region 2, Office of Director. 1p. 19734:168. 24X::he:50-400.83/07/15.8307260485.
- PAOS20 Suppl to 930628 Final Deficiency Repts 81-73 & 81-69 reset generator room exhaust fan mod Initially reported on 310831. Deficiency also reportable per Part 21. MILLS. L.M. Tunnessee Valley Authority. 10CFR 050.55E. 83/07/21. D'REILLY. J. P. Region 2. Office of Director. 1p. 19731:288. 24: Fiche 50-390.83/07/21.8307260520.

- 8307280328 Part 2: rept ro insufficient clearance on QE 250-volt do control ctrs. Initially reported on 830721. Corrective measures will be determined upon QE insp completion. Separate rept per 100FR50. 55(e) forthcoming.

  MENYON. B. D. Pennsylvania Power & Light Co. 100FR 050, 55E. 83/07/25. MURLEY. T. E. Region I, Office of Director. 2pp. 19789:243. 24% Fiche: 50-387, 83/07/25, 8307280328.
- 8307280413 Revised final Deficiency Rept DER 83-33 re GE AKR-50 breaker w/EC-1 trips which may have generic defect. Initially reported on 820429. Defects will be corrected prior to fuel load. Also reportable per Part 21. VAN BRUNT, E. E. Artirona Public Service Co. 10CFR 080. 55E. 83/06/24. STERNBERG. D. M. Region 3. Office of Director. Spp. 19802:107. 24X Fiche: 50-530, 83/06/24, 8307280413.
- 8307270043 Part 21 rept re speed settings on nameplate for EGB-13C actuator. Caused by binding nameplate for spare actuator. Actuator will be tested w/nameplate installed & aligned. Purchase order of 811020 encl.
  ZMIEO: A. Hoodward Covernor Co. 83/06/29. CCLLINS. J. T. Region 4, Office of Director. 10pp. 17821:024. 24X Fiche:30-312,83/06/29, 8307270043.

## GA999 GUALITY ASSURANCE INSPECTIONS

- 8307060002 Informs of insp completion at Ebasco on Louisiana Power & Light Co deficiency rept re failure of Bergen-Paterson to perform pipe support stress analysis. No nonconformances noted. Details in GA Insp Rept 79700503/83-01.
  PDTAPOVS. U. Division of Vendor & Technical Programs. 83/06/30.
  GAGLIARDO, J. E. Division of Resident, Reactor Project & Engineering Programs. 1p. 19250:362.
- 8307040005 Confirms QA program insp at Tempe.AZ plant on 830725-29, per 830415 telcon.
  POTAPOVS.U. Region 4. Office of Director. 83/07/01. MURPHY.J. Tobar. Inc. 1p. 19251:013.
- 8307060018 Ack receipt of 830616 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900522/83-01.
  POTAPOVS,U. Region 4, Office of Director. 83/07/01. STATTON, C. D. Bechtel Corp. 1p. 19251:036.
- --8307060023 Responds to NRC 830523 itr re monconformance noted in GA Program Insp Rept 97700522/83-01 Corrective actions: responsibility of engineering personnel to identify Part 21 applicability on PMAM recomphasized within dept. STATTON.C. D. Bechtel Corp. 83/06/16. POTAPOVS, U. Region 4. Office of Director. 4pp. 19251:037.
- 8307060026 Confirms QA program insp at Forest Hills Test Facility on 830725-29, per 830622 telcon.
  POTAPOVS.U. Region 4. Office of Director. 83/06/29. SLEMBER, R. J. Westinghouse Electric Corp. ip. 19238: 262.
- 8307060053 Confirms GA program insp at Lynchburg, VA plant on 830712-14, per 830621 telcon. POTAPOVS, U. Region 4, Office of Director. 93/06/29. QUILDERT, D. E. Babcock & Wilcox Co. 1p. 19250:343.
- 8307060058 Confirms QA program insp at Lynchburg, VA plant on 830712-14, per 830621 telcon.
  POTAPOVS, U. Region 4. Office of Director. 83/06/24. GUILBERT, D. E. Babcock & Wilcox Co. 1p. 19250: 349.
- 8307040087 Atk receipt of 830429 & 0325 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp. Rept 99700501/83-01.
  PDTAFDVS.U. Region 4. Diffice of Director. 83/06/29. WAHLIH.W. Bechtel Corp. 1p. 17249:036.
- --B307060093 Responds to NRC B30330 ltr re nonconformance noted in QA Program Insp Rept 9990301/83-01. Corrective actions: meetings held w/Zack Co quality personnel to preclude recurrence of deficiencies for Bechtel procured matls. WAHL, H. W. Bechtel Corp. 83/05/25. PUTAPOVS, U. Region 4, Office of Director. 1p. 19249:057.
- 8307060096 Forwards QA Program Insp Rest 99900817/83-01 on 830411-15 to notices of violation & nonconformance. PDTAPOVS.U. Region 4. Office of Director. 83/06/06. LEUSINK.H.H. Litton Industries Inc. 3pp. 19251:167.
- --8307060100 Natice of violation from insp on 830411-15. \* Region 4, Office of Director. 83/06/06. 2pp. 19251:170.
- --8307060104 Notice of nonconformance from insp on 830411-15. \* Region 4, Office of Director. 83/06/06. 2pp. 19231:172.

- \*\*B3070&0112 QA Program Insp Rept 99900817/83-01 on 830411-15
  Nancompliance noted procurement documents issued after
  780106 for safety-related components not specified as Part
  21 & established measures did not assure drawing approval.
  FOSTER.W.E. BARNES.I. Region 4, Office of Director. B3/06/03.
  12pp 19291:174.
- 307060097 Confirms QA program insp on 830711-15 at Advanced Energy Sys Div,Large,PA,per 830622 telcon. PDTAPDVS.U. Region 4, Office of Director. 83/07/01. ARNOLD,H. Westinghouse Electric Corp. 1p. 19232:011.
- 307060103 Ack receipt of 830518 ltr informing NRC of results of investigation of forging supplier.CE Larson & Sons.Chicago.
  1L. Investigation performed per GA Program Insp Rept 9790034/83-01.
  PDTAPOUS.U. Region 4. Office of Director. 83/06/24. BRUNSON.B.C.
  Dresser Industries. Inc. 1p. 19252:210.
- -8307060109 Responds to GA Program Insp Rept 99900054/83-01 Investigation of CE Larson & Sons, supplier of forgings for use on ASME Section III valves, for failure to audit each matl supplier revealed item not reportable per Part 21. BRUNSON, B. G. Dresser Industries, Inc. 83/05/18. COLLINS Region 4, Office of Director. 2pp. 19252:211.
- 3307060188 Forwards QA Program Insp Rept 99900509/83-01 on 830502-06 & notice of nonconformance. POTAPOVS.U. Region 4. Office of Director. 83/06/09. KELLY.R.B. Stone & Webster Engineering Corp. 2pp. 19249:347.
- --8307060189 Notice of nonconformance from insp on 830502-06. \* Region 4, Office of Director. 83/06/09. 1p. 19249:349
- --8307060192 GA Program Insp Rept 97900509/83-01 on 830502-06.
  Noncompliance noted:superseded engineering design criteria
  neither destroyed nor marked superseded
  BREAUX.D.G., HALE.C.J. Region 4, Office of Director. 83/06/07.
  10pp. 17249:330.
- 8307060210 Forwards QA Program Insp Rept 99900505/83-01 on 830314-18 & notice of nonconformance POTAPOVS.U. Region 4, Office of Director. B3/06/01. TENZER.B.E. Ebasco Services. Inc. (subs. of Enserch Corp.). Jpp. 19239:219.
- --8307060215 Notice of nonconformance from insp on 830314-18. \* Region 4, Office of Director. 83/06/01. 1p. 19239:222.
- --B307060221 QA Program Insp Rept 99900505/83-01 on 830314-18.

  Noncompliance noted reviewed & approved vendor-submitted drawings that specified flanges did not conform to applicable spec or code. HARRELL,P.H., SEARS,P.M., HALE,C.J. Region 4, Office of Director. B3/05/26. 23pp. 19239: 223.
- B307060231 Discusses GA Program Insp Rept 99900365/B3-01 on B30321-24 & O414. Allegations re termination of GC staff in Florence, KY & unqualified welders in Longview, TX substantiated. POTAFOVS, U. Region 4. Office of Director. B3/06/30. JOHNSON, E. H. Director's Office, Office of Inspection and Enforcement. 1p. 19239:353.
- 8307060274 Ack receipt of 830617 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900370/83-01 POTAPOVS, U. Region 4, Office of Director. 83/07/01. KULD, B. Garrett Corp. 1p. 19239; 144.
- --8307060281 Responds to NRC 830420 ltr.re nonconformances noted in GA Program Insp Rept 99900370/83-01. Corrective actions: training implemented to increase awareness of 10CFR21 reporting requirements. VORIS.D.D. Garrett Corp. 83/06/17. POTAPOVS.U. Region 4. Office of Director. 1p. 19239: 165.
- 8307060283 Ack receipt of 830216 % 0510 ltrs intorming NRC of steps taken to correct nonconformance noted in GA Pr gram Insp Rept 99900378/81-01. POTAPDUS.U. Region 4, Office of Director. 83/06/27. GHANSON,N.E. Acme-Cleveland Go. 1pp. 19234:189.
- ...-8307060289 Responds to NRU 830216 ltr re nonconformance noted in GA Program Insp Rapt 99900378/81-01 Corrective actions sampling plan implemented effective 830809. SWAMSON.N.E. Acme-Cleveland Co. 83/05/10. POTAFOVE, U. Region 4, Office of Director. 1p. 19234 190.
- 8307060326 Forwards QA Program Insp Rept 99900300/83-61 on 830404-08 & notice of monconformance.
  POTAPUVS.U. Region 4. Office of Director. 83/06/09. MORIARITY.J.M. Colt Industries. Inc. 3pp 19234:213.

- --8307060330 Natice of nonconformances from insp on B30404~08. \* Region 4, Office of Director. 83/06/09. 2pp. 19234:216.
- -8307060336 GA Program insp Rept 99900300/83-01 on 830404-08.

  Noncompliance noted source insp personnel had not used four designated techniques to assure that equipment conformed to specified requirements. FOSTER, W. E. , BARNEB, I. Region 4, Office of Director. 83/06/06. 13pp. 19234: 218.
- 8307060337 Forwards OA Program Insp Rept 99900816/83-01 on 830314-18 & notice of nonconformance. POTAPOVS,U. Region 4: Office of Director. 83/06/02. REILLY,W. West Jansey Manufacturing Co. 2pp. 19234:038.
- -8307060341 Notice of nonconformance from insp on B30314-18 Region 4, Office of Director. 83/06/02. 3pp. 19234 19234: 040.
- --8307060347 QA Program Inap Rept 97900816/83-01 on 830314-18.

  Noncompliance noted: failure to demonstrate that only vendors on approved vendor list used for nuclear work prior to Sept 1782.

  ELLERGHAM.L.E., BARNES, I. Region 4, Office of Director. 83/05/25.

  8pp. 19234: 043.
- 8307060345 Forwards GA Program Insp Rept 99900209/83-01 on 830421-22. No noncompliance noted. POTAPOVS, U. Region 4: Office of Director. 83/06/03. NOREEN, H. Bergen-Paterson Pipe Support Corp. 2pp. 19236: 338.
- --8307060350 GA Program Insp Rept 97900207/83-01 on B30421-22. No noncompliance noted. Major areas inspected: review of stress analysis & structural testing of preloaded pipe clamps & exam of procedures & representative records. BEARS.F. Region 4, Office of Director. B3/06/03. Spp. 19236:340.
- B307040333 Forwards OA Program (nsp Rept 99700285/B3-01 on 830420-21. No noncompliance noted. PDTAPOVS, V. Region 4. Office of Director. 83/06/06. SEHELL, D. M. ITT Grinnell (subs. of ITT). 2pp. 19234:163.
- --8307060360 QA Program Insp Rept 99900285/83-01 on 830420-21 No noncompliance noted Major areas inspected review of stress analyses & structural testing of preloaded pipe clamps. SEARS.P., HALE.C.J. Region 4, Office of Director. 83/06/02. Spp. 19234:165.
- 8307060338 Forwards GA Program Insp Rept 99900918/83-01 on 830328-31 & natices of deviation & nonconformance. POTAPOVS, U. Region 4. Office of Director. 83/06/02. RICHARDS, D. H. Louis P. Canuso, Inc. 2pp. 19236:239.
- --8307040365 Notice of deviation from insp on 830328-31.
  \* Region 4. Office of Director. 83/06/02. 2pp. 19236:241.
- -8307060374 Notice of nonconformance from insp on 830328-31. \* Region 4, Office of Director. 83/06/02. 2pp. 19236:243.
- --8307060382 GA Program Insp Rept 99700818/83-01 on 830328-31.
  Noncompliance noted copies of 100FR21. Section 206 of Energy
  Reorganization Act of 1974 & procedures adopted per
  regulations & notice describing regulations not posted.
  ELLERSHAW.L.E., BARNES.I. Region 4, Office of Director. 83/05/25.
  3pp. 19236: 245.
- 8307060370 Informs that GA Program Insp Rept 99700505/83-01 item re error in charging pump & bypass valve control circuitry 80/0603/0 interms that the rights valve control circuitty error in charging pump & bypass valve control circuitty closed.
  POTAPOVB.U. Division of Vendor & Technical Programs. VITS 82-205.
  83/06/30. LEWIS.R.C. Division of Project & Resident Programs. IP 19236:227.
- 8307120201 Forwards OA Program Insp Rept 99900349/83-01 on 830310-13 & notice of nonconformance.
  POTAPOVS.U. Region 4, Office of Director. 83/06/13. ALLEN.W.Y. Corner & Lada Co., Inc. 3pp. 19423:272.
- --8307120204 Notice of nonconformance from insp on 930510-13. \* Region 4, Office of Director. 83/06/13. ip. 19423:295.
- --8307120207 GA Program Insp Rept 99700349/83-01 on 830510-13.
  Noncompliance noted: followup audits to confirm corrected
  deficiencies not performed within 30-day period.
  OLLERRE. BARNES. I. Region 4. Office of Director. 83/06/10.
  11pp. 19423:276.

- #5 Tis 2 Increment JA Program (Teb Rept 59950001/83-01 on 830404-08 & control on continue and a control of 83700.13 PRYGR.C W. March & B. Huston (1997) 1997 (1997
- 取り 3s 3v8 Not ce of minioreformance fects insp on 850494-08. カ 月和1フィギー じをわしゃ of Cireitah - 83205/13 - 1p - 19423,274.
- Relification was integran inso Prot RATICCO1/RE-01 on RE0404-0B.

  Substitution of itself six steam generator tube sleeves found
  on store Your Work, each or fold tead & one lot of guide tube
  objectives of the protocological and protocologica
- Materia (Alter Funder de 184 Program Insp. Rept. 99700707/83-01 on 830425-27. Nu monte (Mail 14), et notes Risepo C. Region 4 Difference CF Difference B3/C5/17. KARR.B.R. Naukin Commissio Ci. Ann. 19423-243
- 等アロジャン 30A Prospram inso Pest 99900707/60-01 on B30425~27. No Section is noted Major areas inspected Pert 21 rept re newforcests electrical splice in olderal insolated newforcests at BARGEO I Peptin 4. Office of Director. B3/06/13. おお (\*\*443) 345
- GXC132 G23 FARWards GA Progress Insp Rept 97900326/63-01 on 830404-08 & Fishers 4 Faurophedomance & Violation Allerical District BayCov13 District Co. Begins 4 Caffice 14 District BayCov13 District Co. Caffic Co. Caffic
- 機能性はApplication of violation form inspice 83464-08 \* 程度100 年 日本fice of Director 83765/13 ip 19423:219
- Bagrang Al Natice of Circinative from insp on GG0404-08 • Megram 4 | Newline of Circinative GJ/GE/13 | 2pp | 19423 220
- 後週の計算では19 Aprivends GA Program Insp Rept サアロジセロア/83-01 on 830328-0401. あられまいの向けにはては hotted から発展がある Appion 4 Office of Director 63/05/07 PATTERSON.R. M. Sengant & Sundy Inc. 第2日 19424-034
- © NITIZINGA GA Program Insp Peut 99730507/82-01 on 930328-0401 No Namiomotiance noted Pagor areas inspected Region III request may review by telephic design of Pain stem line & review of GAMBURATA G. HANGE OF BEICH OF CAMBURATA G. HANGE OF BEICH OF Director 83/05/07
- 정당(기교업은 전고에서 이 3A Progres Insp Rept 99900922/83-01 on 830503-04 May non-complience mated 하고 APUVS 가 한말같고 4. CPFits OF Director 82/06/17 THOMAS.B J International Maytronics, Ing. Top 19424-059
- できるいた。ACLARS GA MAINGRAM Insp Rept 59930922/03-D1 on 830503-04 No Maintanableatic matter Major areas inspected preparation of SA Maintal for GA program to control safetymrelated testing を issues as a SMICLIPS M B Region 4. Office of Director をよった as 19424 Col
- 線が成了を含むませる GA Program Insp Fept 99903751/B3-O1 on B30419-22. 機能 できたいを見ませると ested PCであれるの グー Pegison 4. Caption SF Cirentor B3/06/17 とDUTHAN.F. G. P等にな Jos. Reniem Inc. Rap. 19424 105
- 田原、下)記されて、AAA およのますを利用され Peat 99923751783-01 on 830419-22, No のおいのみのとまましま つませる Major Areas Inspected Following Insp of は神経にある Major Areas Area Color Insp. Of Director Major Major Major Areas Area Color Insp. GA Major Major Major Areas Are
- game Planumers GA Program Insp Rept 99900387/83-01 on 830425-29 か Tistice is manifertormance 所作機能機能 Regist 4. Effice of Director 83/06/17 BONIFACIO, A B
- ##360 7/2032에 Nustrice of managrational of From Insp on 830425-29 # ##3150 4. 기계기가 이번 이번 Director 82/06/17 ip 19430 003

- ~~B307120334 OA Program Insp Rept 99900307/F3-01 on 830425-29.
  Noncompliance noted corrective actions not submitted by B30225 for seven corrective action requests re survey of identified deficiencies at Seal Master Corp OLLER, R.E., BARNES, I. Region 4, Office of Director. B3/06/14 14pp. 19430-004.
- 8307120376 Advises that Section 4 of oncl (AA Program Insp Rept 99900507/83-01 re improperly tightened jam nots on bolted expansion connections considered closed for Sargent & Lundy W/o encl POTAPOVS.U. Division of Vendor & Tochnical Programs 83/07/07 DANIELEON.D.H. Division of Engineering ip 19489 006.
- 8307120437 Discusses QA Program Insp Rept 99900581783-01 re Brown & Root anchor bolt problem Problem reported as Part 21 deficiency & being processed by Bechtel POTAFDVS.U. Division of Vendor & Technical Programs VITS 81-152, 83707707. MILLS,W.R. Director's Office, Diffice of Inspection and Enforcement. 1p. 19425:277.
- B307120453 Forwards QA Program Insp Rept 99900521/83-01 on B30328-0401 & 0411-15 t notice of nonconformance. POTAPOVS, U. Region 4, Office of Director B3/06/17. HINKLEMAN.L 0. Bechtel Corp. 2pp. 19426:008
- --8307120457 Notice of nonconformance from 1889 DD G30328-0401 & 0411-15 \*\* Region 4. Office of Director 63/06/17 ip 17426:010.
- --8307120462 QA Program Insp Rept 99900021/EG-01 on EG0328-0401 t 0411-15. Noncompliance noted: two spects re use of Class R equipment in IE sys issued a/o evidence of design review notice COSTELLO, J. R. HALE, C. J. Region 4. Office of Director. 83/06/14 28pp. 19426:011.
- 8307120536 Advises that Brown & Root Part Pl deficiencies evaluated in GA Program Insp Rept 99900521/83-01. considered resolved. Programs. 83/07/01. MILLS, M.R. Division of Wendor & Technical Programs. 83/07/01. MILLS, M.R. Division of GA. Safeguards & Inspection Programs (Post B30103). 1p. 19433:332.
- 8307150116 Confirms GA program inap at Eden Prairie, MN plant on 830801-05, per 830629 telcon. PDTAPQVS, U. Region 4. Office of Director ECJ/07/08. ANDERGON, G. D. Rossmount, Inc. 1p. 17536. 221
- 8307150125 Ack receipt of 830516 & 0620 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 9990769/83-01.
  POTAPQUS,U. Region 4, Office of Director 83/07/00 ME96,L.R Pacific Air Products Co. 1p. 19395:242.
- --8307150129 Responds to NRC B30403 ltr re nonconformance noted in QA Program Insp Rept 99900769/83-01 Corrective actions: all the reviewed & evaluation of problem will be reported.

  DODSON, J.P. Pacific Air Products Co. 83/06/20 POTAPOVS. U. Region 4. Office of Director. 2pp. 19935-243
- 8307150247 Ack receipt of 830620 itr informing NRC of steps taken to carrect nanconformance noted in GA Program Imap Rept 99900300/83-01. Next rev to GA manual scheduled for 830619. POTAPOVS.U. Region 4. Office of Director 83/07/08 MCRIARTY.J.M. Colt Industries, Inc. 19. 19938-237
- --8307150249 Responds to NRC 830609 itr re nonconformance noted in GA Program Insp Rept 97900300/83-01. Corrective actions: 11871 439 signed.

  MORIARTY, J.M. Colt Industries, Inc 83/06/20. POTAPOVS, U. Region 4, Office of Director. 6pp. 19538:230
- 8307130251 Confirms QA program insp at Burlington.MA on 830719-22.per 830617 telcon POTAPOVS.V Region 4. Office of Director. 83/07/08. KULCSAR.E. Associated Testing Lab. Inc. 1p. 17532 328.
- 8307150260 Discusses GA Program Insp Rept 99990001/83-06 on 830518 & notice of violation.
  MARTIN.T. I Division of Engineering & Technical Programs. 83/07/13.
  SCHONLAU. J Imperial Inspection, Inc. 2pp. 19538:072.
- ~-8307150269 Notice of violation from insp on 930518 Noncompliance noted:
  pociet dosimeters not checked for correct radiation response
  since placed into svc.an interval of more than 1 yr
  Region 1, Office of Director. 83/07/13, 1p 19538:074.

- . Pt of 830120 & 0301 ltrs informing NRC of steps Conconformance noted in QA Program Insp Color B.3 ltem B.3 will be reviewed in greater insp.
  The 4. Office of Director 83/07/08. ETHERIDGE, M. R. Cering, Inc. 1p. 1931:117
- s to NRC 830207 itr requesting addl info re tem 8.2 noted in GA Program Insp Rept viron & seismic qualification not said of rewrap of detectors Combustion Engineering. Inc 83/03/01. ton 4, Office of Director. 2pp. 19331:118.
- e ipt of 830120 ltm in response to QA Program O 1/82-03. Requests conclusions of evaluation equalification.
  ion 4, Office of Director. 83/02/07.
  Combustion Engineering, Inc. 1p. 19531:120.
- Gambustion Engineering, Inc. 1p. 19531: 120.
- GA Program Insp Rept 99900919/83-01 on 830418-22
   Formance,
   4. Office of Director. 83/06/24. DAVIS, A. G.
   Quy Corp. 2pp. 19555:247.
- © f nonconformance from insp on 830418-22. ★ ce of Director. 83/06/24. 2pp 19555:249.
- Tam Insp Rept 79700719/83-01 on 830418-22.
  ted: GA procedures inappropriate, documented abls to indicate performance of internal GA udit documentation unavailable.
  LIPS.H.S. Region 4, Office of Director. 83/06/21.
- GA Program Insp Rept 99900070/83-01 on 830404-08
   f Grance.
   4. Office of Director. B3/06/29. MILLER, J. W.
   Engineering Corp. 2pp. 19995:176.
- □ ₱ nonconformance from insp on 830404-08.

  1 □ e of Director. 83/06/29. 2pp. 19555:178.
- ram Insp Rept 99900070/83-01 on 830404-08. ted:failure to perform required weld stress tify incomplete weld fusion & penetration
- NHES.I. Region 4. Office of Director. 83/06/25
- GA Program Insp Rept 99900923/83-01 on 830509-12 &
   D. 4. Office of Director. 83/07/01. MATTESON, 9.
   Systems. 2pp. 19855:163.
- □ # violation from insp on 830509-12.
  i ∈ e of Director. 83/07/01. 1p. 19555:165.
- r dem Insp Rept 97700923/83-01 on 830509-12. ted:required customer/purchaser procedures adopted & required Part 21 documents not
- \_ IPS, H.S. Region 4, Office of Director. 83/06/27.
- a∧ Program Insp Rept 99900745/83-01 on 830404-07 & mance.

  ¬ 4, Office of Director 83/06/21. XAVIER,M.A. 1 9355:210.
- ⊋ € nonconformance from insp on 830404-07. i c e of Director. 83/06/21. 2pp. 1955:213.
- nam Insp Rept 99900745/83-01 on 830404-07.
  bed:documentary evidence not available that
  ags held prior to Nov 1982 & semiannual
  ted during Sept & Mar.
  dES.I. Region 4. Office of Director. 83/06/08.
- 3€30718 mgt meeting in Assonet,MA re implementation 3€30617 telcon. 4. Office of Director. 83/07/14. RANDALL,M.W. on Services. 1p. 19668: 230.
- , to of 830628 ltr informing NRC of steps taken to ,nce noted in GA Program Insp Rept
- , 4, Office of Director 83/07/14, REILLY, W. ; & uring Co. 1p. 19665; 179.

- --9307210206 Responds to NRC 830602 ltr re nonconformance noted in GA Program Insp Rept 99700816/83-01 Corrective actions: GA program manual revised & GA & ofc personnel retrained. REILLY W. West Jersey Manufacturing Co. 83/06/28, POTAPOVS, U. Region 4. Office of Director. 11pp. 19665: 180.
- --8307210224 Forwards Chicago Tube & Iron 830317 ltr re Purchase Order NO0566 for four pieces FS blind flange for files. REILLY W. West Jersey Manufacturing Co. 83/03/22. ELLERSHAW, L. Region 4. Office of Director. 14pp. 19665.191.
- 8307220394 Forwards list detailing status of commitments for corrective actions made prior to transition of engineering work on project.
  RICE, M.M. Brown & Root Corp. (subs. of Halliburton Corp.).
  82/02/08. SEYFRIT, K. Region 4, Office of Director. 2pp.
  19673:235. 24X Fiche: 50-498, 82/02/08, 8307220394.
- 8307240191 Ack receipt of 830103 & 0303 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99700795/82-01.
  PDTAPOVS.U. Region 4, Office of Director. 83/07/21. LOTT, J. E. E. L. Manufacturing Peebles, Inc. 1p. 19727:265.
- --8307260158 Responds to NRC 830209 ltr re nonconformance noted in GA Program Insp Rept 99900795/82-01. Corrective actions: written procedure established to evaluate deviations, personnel briefed re procedure & purchase orders modified.
  PLANK.R.A. E.L. Manufacturing Peebles, Inc. 83/03/03. PDTAPOVS.U. Region 4, Office of Director. 3pp. 19727:266.
- ---B307260164 Ack receipt of 830103 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900795/82-01. Add1 response requested re items in notices of nonconformance & violation.
  PGTAPOVS.U. Region 4, Office of Director. B3/02/09. LGTT, J. E. E. L. Manufacturing Peebles, Inc. 1p. 19727:269.
- --B307260169 Responds to NRC 821208 ltr re nonconformance noted in QA Program Insp Rept 97900795/82-01. Corrective actions: operation sheets completed in requested order & newly purchased matls clearly marked. PLANK.R.A. E.L. Manufacturing Peebles, inc. 83/01/03, POTAPOVS,U. Region 4, Office of Director. 9pp. 19727;270.
- 8307260219 Ack receipt of 830527 ltr informing NRC of steps taken to correct noncomformance noted in QA Program Insp Rept 99900017/83-01.
  PGTAPDVS.U. Region 4. Office of Director. 83/07/22. ANDERSON.K. Dravo Corp. 1p. 19728:337.
- ~-8307260228 Responds to NRC B30421 ltr re nonconformance noted in QA Program Insp Rept 99700017/83-01. Corrective actions: insp & GA personnel cautioned to ensure that nonconformance or reject repts completed & mall returned to vendor. ANDERSON, K. B. Dravo Corp. 83/05/27. POTAPDVS, U. Region 4, Office of Director. 21pp. 19728:338.
- 8307260229 Provides info re changes to QA program from PSAR description, for review & acceptance.
  GERRETS.T.F. Louisiana Power & Light Co. W3KB3-0781. B3/06/09.
  COLLING.J.T. Region 4, Defice of Director. Spp. 19726:346. 24)
  Fiche: 50-382,83/06/09.8307260229.
- ~-8307260236 Advises that GA program described in Topical Rept CENPD-210-A.Rev 3 being implemented satisfactorily. Conclusions of ltr valid for 3 yrs. SEYFRIT.K.V. Region 4. Dallas. Office of the Director (81/03/01). 81/06/02. ETHERIDGE.M.R. Combustion Engineering. Inc. 3pp. 19726:359. 24X Fiche: 90-382,83/06/09,8307260229.
- B307260313 Confirms QA program insp 4t Westmont, IL. plant on B30815-19, per 830627 tolcon.
  PQTAPOVS,U. Region 4, Office of Director. B3/07/18. SESHAQIRI.M.L. CLOW Corp. 1p. 19726:010.
- 8307290026 Forwards QA Program Insp Rept 99700802/83-01 on 830411-15 & notices of nonconformance & violation.
  PUTAPOVS.U. Region 4. Office of Director. 83/07/08. PIRAIND.D. Kaman Co. 3pp. 19821:090.
- --8307290032 Notice of violation from insp on 830411-15.
  \* Region 4, Office of Director. 83/07/08. 1p. 19821:093.
- --8307270035 Notice of nonconformance from inso on 830411-15. \* Region 4, Office of Director. 83/07/08. ip. 19821:094.

- ---B307290040 GA Program Insp Rept 99900802/B3-01 on B30411-15.
  Noncompliance noted design requirements not incorporated into mod procedures & emergency operating procedures manual.
  Section 6 incorrectly identified
  PARKER, L B. Region 4, Office of Director BARNES, I Division of Vendor & Technical Programs. B3/07/01 9pp 19821:095.
- 8307290060 Forwards OA Program Insp Rept 99900266/83-01 on 830516-19. No noncompliance noted. POTAPDVS.U. Region 4. Office of Director. 83/07/08. EMPEY.D. Rockwell International Corp. 2pp. 19820 361.
- --B307290065 QA Program Insp Rept 99900266/83-01 on B30516-19. No noncompliance noted. Major areas inspected: followup on Part 21 repts, previous insp items, control of special processes, Insp & testing & audits.
  SUTTON.J.W., BARNES, I. Pegian 4, Office of Director. B3/07/07. Ppp. 19821.001.
- 8307290081 Forwards QA Program Insp Rept 99900785/83-01 on 830328-0401 & 23-29 & notice of nonconformance. POTAPOVS, U. Region 4. Office of Director. 83/07/11. DEZUTEL.C. Z. Zact Co. 3pp. 19822:182.
- --8307290087 Notice of nonconformance from insp on 830328-0401 & 25-29 • Region 4, Office of Director. 83/07/11. 2pp. 19822:185.
- ---8307290095 GA Program Insp Rept 99900785/83-01 on B30328-0401 & 25-29. Noncompliance noted: corrected matls certification not requested for 3.000 lb 14 gage ASTM A-240 Type 304-28 stainless steel.

  PARKER.L.B., BARNES.I. Region 4, Office of Director. B3/07/07. 14pp. 19822:187.
- 8307270114 Forwards QA Program Insp Rept 97900057/83-01 on 830411-15 & notice of nonconformance.
  POTAPOVS-U. Region 4. Office of Director. 83/07/08. MIEHAUS.P. William Powell Co. 2pp. 17822:076.
- --8307290120 Notice of nonconformance from insp on 830411-15.

  \* Region 4. Office of Director, 83/07/08. 2pp. 19822:078
- --B307270129 GA Program Insp Rept 99700057/83-01 on B30411-15.
  Noncompliance noted; documentation checklist missing from one package (ABO478-C) & wall section check not noted on 50 weld repair records out of 165 records contained in packages.
  CONNAY, J. T., BARNES, I. Region 4, Office of Director. B3/06/08
- 8307290133 Forwards QA Program Insp Rept 99900925/83-01 on 830523 & 25-27 & notices of honconformance & violation. POTAPDVS/U. Region 4: Diffice of Director. B3/07/11. SMITH.C.B. ANCO Engineers, Inc. 3pp. 19822:006.
- --8307290139 Notice of violation from insp on 830523 & 25-27. \* Region 4. Office of Director. 83/06/11. lp. 19822:009.
- --8307290144 Notice of nonconformance from insp on 830523 & 25-27.

  \* Region 4, Office of Director. 83/06/11. 2pp. 19822:010.
- --B307290147 OA Program Insp Rept 99900925/B3-01 on B30523 & 25-27.
  Noncompliance noted: failure to post all required documents, detailed GA program implementing procedures not developed for App B criteria & GA audits not conducted.
  MUBBARD, G. T., PHILLIPS, H. S. Region 4, Office of Director.
  B3/07/07. 13pp. 19822:012.

## REGGD REGULATORY GUIDES

- B307120105 "For Comment" issue of draft Reg Quide MS 144-4, "Fracture Toughness Criteria for Ferritic Steel Shipping Cask Containment Vessels W/Max Wall Thickness of 4 Inches (O.1 m)." MEIDENHAMER, O. Office of Nuclear Regulatory Research, Director. B3/06/30. 11pp. 19508:294.
- 8307130163 Comments on draft Reg Guide IC 127-5. "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Fower Generating Stations." Option A limiting QA guidance to IEEE 5td 467-1980.recommended.

  MGODLAN.D.R. Taxas Utilities Services. Inc. TXX-4003. 83/07/11. Doctating & Services Branch. 19. 19535:236.
- 8307180174 Comments on draft Reg Guide IC 127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Generating Stations." Endorses Option A re limiting GA guidance to IEEE Std 447-1780.

  MITTL/R.L. Public Service Electric & Gas Co. of New Jersey. 83/06/24. Docketing & Services Branch. 1p. 19531:010.

- 8307150190 Comments on draft Reg Guide IC 127-5. "Critoria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Generating Stations" Option A preferred DALELL F Missispip Fower & Light Co. AECM-83/0374 83/07/08 Docketing & Services Branch. 1p. 19531.052.
- 8307180119 For comment issue of draft Reg Guide QP 713-4: "Applications of Bioassay for Tritium."

  \* Office of Nuclear Regulatory Research: Director: 83/06/30: 16pp. 19641:215.
- B307190207 Comments on Rev 1 to Reg Ouide 1 82.Task MS 203-4. "Sumps for Emergency Core Cooling & Containment Spray Bys " Inconsistencies cited VIVIRITIO.M.A. Gibbs & Hill, Inc. (subs. of Dravo Corp.). 83/07/11. Docketing & Services Branch. 2pp. 19628:320.
- 8307260274 Comments on proposed Reg Guide 8.31, Task CH 941-4, re inforelevant to ensuring occupational radiation exposures at U mills will be ALARA. Suggests control of chemical hazards be brisfly addressed.
  MILLS, L.M. Tennessee Valley Authority. 83/07/19. Docketing & Services Branch. 2pp. 19726: 126.
- 9307260293 Comments on proposed Rev 1 to Reg Guide 1 82, Fask MB 203-4, re sumps for emergency core cooling & containment spray sys.

  Note should be added stating App A considered for info purposes only, subj to ECCB pump design.

  BUDZIK, D. M. Consumers Power Co. DMB 32-83. 83/07/15. Docketing & Services Branch. App 19784, 131.
- 8307260476 Documents understanding that either Rev 2 or Rev 3 to Reg Guide 1.97 acceptable to NRC for addressing guidelines of NUREQ-0737. Suppl 1 (Generic Ltr 82-33) re emergency response capability.

  GARRITY. J. H. Maine Yankee Atomic Power Co. MN-83-151. 83/07/21. CLARK.R. A. Operating Reactors Branch 3. 1p. 19734:163. 24X Fiche: 50-307.83/07/21.830/260476.
- 8307270023 Forwards comments received re technical findings & resolution positions for Unresolved Safety Issue A-42 re containment emergency sump performance. Revs to NUREG-0897 recommended. Technical/safety issues & resolutions requested. SERKIZ.A.W. Generic Issues Branch. 83/07/12. DALGHREN.B. Sandia Laboratories. 2pp. 19811:209.
- --8307270033 Comments on draft NUREO-0897 & NUREO-0869 (Reg Guide 1.82 rev). PADMANABHAN, M. Alden Research Laboratory. 63/06/13. SERKTZ, A. W Generic Issues Branch. 7pp. 19811:222.
- --8306280504 Forwards rev to Table A-3 in NUREG-0869 Rev corrects discrepancies noticed in values of variables for vertical autiets. Corrections also applicable to NUREG-0897 PADMANBHAN Alden Research Laboratory. 83/06/22. BERKIZ.A. Generic Issues Branch. 4pp. 1981:231.
- 8307270385 Comments on Rev 1 to draft Reg Quide 1 82.Task M6 203~4, "Sumps for Emergency Core Cooling & Containment Spray Sys." SALDARINI, J. C. Ebasco Services, Inc. (subs. of Enserch Corp.). 83/07/21. Docketing & Services Branch. 2pp. 197267:317.
- B30728009B Forwards add1 info to util 830415 response to NUREG-0737, Suppl 1 re safety parameter display sys, detailed control room design review & Reg Guide 1.97.
  UHRIO,R.E. Florida Power & Light Co. L-83-421 93/07/25
  VAROA.S.A. Operating Reactors Branch 1. App. 19794: 179. 24X
  Fiche: 50-250, 83/07/25, 8307280098.

## RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- B307050314 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC-Licensed Fuel Cycle Facilities," progress repts for Apr & May 1983. W/830610 ltr. SIMAN-TOV.M. Union Carbide Corp. FIN B-0495. 83/06/20. BERNSTEIN.S. Transportation & Materials Risk Branch. 5pp. 19263:242.
- 8307110560 "Accident Aerosol Characterization," informal monthly progress rept for May 1983 Grant Pacific Northwest CHCZARSKI,P.C. Battelle Memorial Institute, Pacific Northwest Laboratory, FIN B-2287, 83/06/22 BERNSTEIN,S. Transportation & Materials Risk Branch, 7pp. 19371:325
- B307120047 ANL/LWR/NRC B3-6
  Draft "DHR During Total Loss of Feedwater Event for C-2
  Bys 80 Plant "
  KOMORIYA.H., ABRAMSON.P.B. Argonne National Laboratory, 83/07/31.
  Division of Systems Integration (post 811005). [11pp 17438: 231.

- 8307130358 Draft NUREO/CR-XXXX. "Cost/Benefit Analysis of Adding Feed & Bleed Capability to C-E PWRs."

  @ALLUP.D.R. Sandia Laboratories. GAHAN.E., CHERDACK.R. Burns & Roe Ca. SANDR3-XXX. 83/06/30. NRC No Detailed Affiliation Given. 46pp. 19509: 327.
- 8307140478 "LWR Pressure Vessel Surveillance Dosimetry Improvement Program," bimonthly status repts for Feb-Mar & Apr-May 1783. PRESTON.C.C.: MCELROY.W.N. Hanford Engineering Development Laboratory. 8372445. 83/04/28. SERPAN.C.Z. Materials Engineering Branch. 8pp. 17540:010.
- 8307130390 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities," monthly progress rept for May 1983. MARTIN.R.A. Los Alamos Beientific Laboratory. FIN A-7029. 83/06/21. BERNSTEIN,B. Transportation & Materials Risk Branch. 12pp. 19540:305.
- phased out.

  BERNSTEIN.S. Transportation & Materials Risk Branch. FIN A-7029.

  83/07/06. MARTIN.R.A. Los Alamos Scientific Laboratory. ip.
  19340:317.
- 8307260043 "Invastigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities," Itr rept for June 1983. MARTIN.R.A. Los Alamos Scientific Laboratory. FIN A-7029. G-6-018 (RA73). 83/07/19. BERRHTEIN,8. Transportation & Materials Risk Branch. 6pp. 19786: 222.

#### REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8305230578 Disagrees w/current enforcement policy allowing assessment of monetary penalties for Severity Level IV or V violations, per 821221 ltr re regulatory reform.
  BRITTAIN,P.G. Teras Utilities Generating Co. 83/03/18.
  TOURTELLOTTE,J. Regulatory Reform Task Force. 2pp. 18541:312. 24 Fiche: 50-445,83/03/18,8305230578. 18541: 312. 24X
- B307050522 Notifies of CROR Meeting 41 on 830706 in Washington.DC to raview final rulemaking re fitness for duty for personnel w/unescorted access to protected areas & NOREG-0849, "SRP for Review & Evaluation of Emergency Plans for Research..."

  BTELLD.V. Committee to Review Generic Requirements. 83/06/24, MATTSON.R.J. Division of Bystems Integration (post 81005).

  JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). CUNNINGHAM.R.E. Division of Fuel Cycle & Material Bafety. 87pp. 19262:172.
- --8307050527 Discusses proposed IE bulletin re nonconforming matls supplied by Tube-Line Corp for CROR review. Requests CROR review be scheduled.

  DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83706/13. STELLO, V. Committee to Review Generic Requirements. 2pp. 17262:260.
- ---8307050530 Requests that NRC refrain from any final decision to take administrative action until pending NRC repts issued to Tube-Line.Company voluntarily suspended any sales of matls for nuclear applications until further notice.

  HALLMAN.R.M. Cahill, Gordon & Reindel. 83/06/10. CULLINS, J.T. NRC No Detailed Affiliation Given. 3pp. 19262:272.
- --B307050534 Responds to 830610 ltr to J Collins on behalf of Tube-Line Corp. NRC has independent obligation to fully & properly carry out statutory responsibilities.
  BROWN, M. L. Region 4. Defice of Director. 83/06/17. HALLMAN, R. M. Cahill, Gordon & Reindel. 1p. 19262:275.
- 8307070039 Summary of CROR Mesting 40 on 830601 re proposed final amends to 10CFR30.44 concerning hydrogen control in BNR Mark 111 & PMR ice condenser containments. Requirements listed. 8TELLO.V. Regional Operations & Generic Requirements. 83/06/24. DIRCKS.W.J. Office of the Executive Director for Operations. 13 19293: 211.
- 8307080259 Forwards backfit cost figures for add1 seven utils per original 830208 request Cost figures for 20 utils transmitted 830411.
  TOURTELLOTTEJ. Regulatory Reform Task Force. 83/06/22.
  PALLADINO, N., GILINSKY, V., AHEARNE, J., Commissioners. 2pp. 19363:313. 24% Fiche: 50-000, 83/06/22, 8307080259.
- --8307080321 Forwards backfit cost info for facility, per NRC 830208 request Category 1 imposed by NRC regulations/orders. Category 2 imposed by NRC bulletins & NUREO-0737 requirements & Category 3 initiated by util. SELBY.J.D. Consumers Power Co. 83/04/14, TOURTELLOTTE.J. Regulatory Reform Task Force, 5pp. 19363:315. 24% Fiche: 50-000,83/04/22,8307080259.

- --8307080331 Informs of inability to respond to NRC 830208 request re impact of regulatory backfit cost since util has no operating plant to use as baseline for comparison. Support expressed for backfit evaluation effort.

  HALL,D.P. 111inois Power Co. 0982-L. 83/04/08 TOURTELLOTTE, J. Regulatory Reform Task Force. 1p. 19363: 320. 24X Fiche: 50-000, 83/06/22, 8307080259.
- --8307080337 Forwards backfit & regulatory impact cost analysis for facility, per NRC 830208 request Analysis formerly confidential atty work product, released to intervenors & now to have forces. to task force
  BAYNE, J. P. Power Authority of the State of New York. JPB-106-83.
  83/06/01. TOURTELLOTTE, J. Regulatory Reform Task Force. 1p.
  19363: 321. 24X Fiche: 50-000: 83/06/22: 8307080259.
- -8307080341 "Determining Portion of Regulatory Burden on Indian Point 3 Capital & D&M Expenditures 1976 1986:10-Yr Cost Projection Also Included." \* Power Authority of the State of New York. 83/04/30. 3App. 19363:322. 24X Fiche:30-000.83/06/22.8307080259.
- -8307080352 Forwards backfit cost tabulations for facilities per NRC 3070BUSDA FORMATON SCALE | BOOKER FOR STATE | BOOKE 83/05/04. TOURTELLOTTE, J. 364:003. 24X
- --8307080358 Forwards backfit cost estimates for facilities, per NRC 830315 ltm.Costs do not reflect extending scheduled outages due to backfits & mods.

  PARRIS, H. O. Tennessee Valley Authority. 83/05/02.

  TOURTELLOTTE, J. Regulatory Reform Task Force. 5pp. 19364:009. 24X Fiche: 50-000, 83/06/22, 8307080259.
- --8307080366 Forwards summary of backfitting costs for facility, per NRC request.

  EDWARDS, D. W. Yankee Atomic Electric Co. SP8-83-3. 83/05/11.

  TOURTELLOTTE, J. Regulatory Reform Task Force. 2pp. 19364: 014, 24X Fiche: 50-000, 83/06/22, 8307080259.
- B307090111 Notification of B30714 meeting w/OE & Licensing Review Groups 1 & 2 in Bethesda, MD to discuss methodology for determining BWR reactor protection sys setpoints & allowable values.

  STEFANO, J. J. Licensing Branch 1. B3/06/28. YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 19384:107.
- B30711029B Notifies of CRGR Meeting 42 on B30712 in Bethesda.MD to review proposed IE bulletin, "Apparently Fraudulent Products Bold by Ray Miller,Inc" & final amends to 10CFR90 re ATWB events. STELLD,V. Committee to Review Generic Requirements. 83/07/OB. MATTSON.R.J. Office of Nuclear Reactor Regulation, Director. JORDAN.E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM.R.E. Division of Safeguards 2pp. 19381:039.
- --8307i10312 Forwards proposed Commission paper recommending issuance of final amend & related amend to 10CFR50 re ATMS events. Info fairly presents ATMB problem & reasonable course of action by Commission recommended.

  MINIQUE.R.B. Diffice of Nuclear Regulatory Research, Director. 83707/05. DIRCKS.W.J. Diffice of the Executive Director for Operations. 184pp. 19381:041.
- --8307110329 Forwards proposed IE bulletin, "Apparently Fraudulent Products Sold by Ray Miller.Inc" & IE Info Notice 83-01, "Ray Miller.Inc." for review. DEYDUNG.R.C. Director's Office, Office of Inspection and Enforcement. 83/06/30. STELLO.V. Regional Operations & Generic Requirements. 24pp. 19381:227.
- B307190399 Forwards summary of CROR activities for B20425-B30630. Summary will be included in weekly rapt for week ending 830701. 830701. SCHNINK,M. Committee to Review Generic Requirements. B3/07/05. Committee to Review Generic Requirements. 6pp. 19654:038.

- 8307200131 Discusses procedures for feedback & closure on CRGR reviews. CRGR minutes will be provided to ofc directly involved in issue, ofc involved will concur w/CRGR comments & proceed w/action.by memo to CRGR.within 5 working days.
  DIRCKS.W.J. Office of the Executive Director for Operations.
  83/07/18 DAVIS.J.G. Office of Nuclear Material Safety & Safeguards. Director. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. DEYOUNG.R.C. Director's Office of Inspection and Enforcement. 3pp. 19651.248.
- B307200186 Staff requirements memo re 830707 discussion of administrative proposals of Regulatory Reform Task Force on backfit rule in Washington.DC. CHILK, S. J. Defice of the Secretary of the Commission. MB30707A. 83/07/OB. DIRCKS, W. J. Office of the Executive Director for Operations. TQURTELLOTTE, J. Regulatory Reform Task Force. 1p. 17670-313.
- 8307250114 Summary of 830706 meeting w/Steam Generator Duners Group in Bethesda.MD re recommendations for new generic steam generator requirements.based on integrated program for resolution of Unresolved Safety Issues A-3,A-4 & A-5.
  HIRACLIA.F. J. Assistant Director for Safety Assessment. 83/07/15 83/07/13.
- 8307250367 Submits summary status of issues being addressed by Licensing Review Group II.per 830502 request. Four issues require further action prior to NRC closeout. Post-accident sampling requires procedural upgrading.
  HÖLTZSCHER.D.L. Licensing Review Group II. HOLTZSCHER.D.L. Illinois Power Co. U-0652. 83/07/15. STEFAND. J. J. Licensing Branch 1. 12pp. 19705:203. 24X Fiche: 50-000.83/07/15.8307250367.
- B307250665 Forwards transcript of Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals B30706 meeting in Hashington.DC.

   Office of the Secretary of the Commission. B3/07/19. PALLADINO.N.J., GILINSKY.V., ROBERTS.T. Commissioners. ip. 19719:028.
- --8307250568 Transcript of Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals 830706 meeting in Washington, DC. Pp 1-164. # NRC No Detailed Affiliation Given. 83/07/06. 183pp. 19719-029.

#### POSITION PAPERS BEFORE THE COMMISSION SECY

#### 8307030502 SECY-83-243

307050502 SECY-83-243
Requests Commission approval of draft final rule 10CFR50.73
re LER sys. Recommends Commission approve publication of
final rule to be effective 840101.
DIRCKS-W J. Office of the Executive Director for Operations.
83/06/21. 122pp. 19262:036.

#### 8307070489 SECY-83-232

307070489 SECY-83-232 Requests approval of final rev to 10CFR71 re NRC regulations on packaging & transport of radioactive matl more compatible w/IAEA stos & DOT revised regulations. DIRCKS.N.J. Office of the Executive Director for Operations. 83/06/13. 218pp. 19715:043.

#### 8307110103 SECY-83-248

30710103 SECY-83-248
Advises Commission of proposed generic actions resulting
from ATMS events on 830222 & 25.5alem Generic Implications
Task Force identified weaknesses in overall licensee mgt &
reactor trip sys reliability.
DIRCKS, M. J. Office of the Erecutive Director for Operations.
83/06/22. 20pp. 19386:239. 24X Fiche: 50-272,83/06/22,8307110103.

8307250039 Forwards omitted page to holders of SECY-B3-232. "Rev of 10CFR71.Packaging of Radioactive Matl for Transport & Transportation of Radioactive Matl Under Certain Conditions."

• Office of the Secretary of the Commission, 83/07/01. Office the Secretary of the Commission, 2pp. 19723:359. Office of

#### 8307250545 SECY-83-247

JOYANDAN BELT-83-267
Informs of status of pipe cracking at operating BWRs, Insps
per IE Bulletin 82-03. Rev i showed that cracking existed in
five of first seven plants examined, prompting issuance of
IE Bulletin 83-02 in Mar 1983.
DIRCKS, W. J. Office of the Executive Director for Operations.
IEB-82-03. 83/07/01. 5pp. 19737:193.

#### 8307250578 SECY-83-267A

Bulmits more recent results of pipe cracking at BWRs to update Table 1 of BECY-83-267.
DIRCKS-M.J. Office of the Executive Director for Operations.
83/07/11. 4pp. 19716:347. 24X Fiche:50-000,83/07/11,8307250578.

- 8307260600 Responds to FOIA request for SECY 82-464. Forwards document. Info partially withheld (ref FOIA Exemption 5). FELTON.J.M. Division of Rules and Records. 83/05/18. BUCKLES.R. NUS Corp. 2pp. 19788:045.
- --B307260601 SECY-B2-464
  Discusses litigation rept for wk of B21115 Info deleted,
  BLAGGIE.E.L. Office of the General Counsel. 82/11/22, 2pp.
- 8307290442 Responds to FOIA request for SECYs 82-306 & 82-499. Forwards SECY 82-306. Documents also available in PDR. Ltr dtd 830428 responded to SECY 82-499. FELTON.J.M. Division of Rules and Records. 83/05/18. DIBBLE.C.B. LyBosuf, Lamb, Leiby & MacRae. 1p. 19858:358.
- --8208040324 SECY-82-304

  Recommends that Commission reconsider decision to remove

  Apps B through H from 10CFR140.

  DIRCKS, H. J. Office of the Executive Director for Operations.

  82/07/20. 4pp. 19858:360.

#### STATE PROG STATE PROGRAMS

- 8307030383 Responds to NRC 830525 ltr re review & evaluation of State of AZ radiation control program. Concurs w/finding of two Category I indicators.

  TEDFORD, C. F. Arizona, State of. 83/06/14. MARTIN, J. B. Region 5, Office of Director. 4pp. 19263: 257.
- 8307060092 PNO-V-83-027: on 830627, Btate of WA notified that shipment of low level waste received from Palisades power plant w/one drum leaking due to hole caused by corrosion. Util banned from using site & burial permit suspended. effective 830621. THOMS.R.D. Region 5, Office of Director. 83/07/01. ip. 19251:330.
- 8307040086 PNO-V-83-025: on B30623.Co-40 contamination found in soil sample taken near controlled area of Allied Consulting.Inc Agreement State licensee in Yakima.WA. Mgt conference between state & licensee scheduled for B30627.
  HORNOR.J.H. Ragion 5. Office of Director. B3/06/27. ip. 19251:277.
- B307090099 Submits corrections to B30518 memo re NRC guidelines for groundwater monitoring at in situ U mines.

  OGLE.K.M. Wyoming, State of. 00343. B3/06/08. BEACH.Q. Wyoming. State of. 2pp. 19366:323.
- 8307110081 Requests comments on paper re required staff level presented at 830607 meeting in Bethesde, MD concerning storage of commercial low level waste. Policy to be utilized by NRC restorage proposed.

  JACKBON: K. Low Level Waste Licensing Branch. 83/06/24. BALDMON; S., 8CHEIDER; K., YOUNG, F. Dffice of State Programs, Director. 7pp. 19386:290.
- 8307110160 PNO-V-83-025A: WA state inspectors continuing investigation re offsits contamination associated w/decontamination work by Allied Consulting. Inc. Of 12 soil samples, nine found w/less than detectable limit of 0.1 pCi/gm.
  HORNOR. J. W. Region 5. Office of Director. 83/07/01. 1p. 19375:031.
- 8307110413 Confirms 830510 discussions re review & evaluation of NY Dept of Environ Conservation radiation control program.
  Significant problems identified w/Category I, "Technical Quality of Licensing Actions & Status of Insp."
  MURLEY.T.E. Region i, Office of Director. 83/06/28. WILLIAMS.H.G. New York, State of. 10pp. 19382:001.
- 8307140375 Forwards performance appraisal of State of SC activities under NRC/Btate of BC Environ Monitoring Contract 03-80-273. Contract renewed for 1983, based on good performance & excellent cooperation.

  OLSHINSKI, J. A. Division of Engineering & Radiological Safety Programs. NRC-05-80-273. 83/02/22, SHEALY, H. O. South Carolina, State of. ip. 19523; 330.
- --8307140380 Performance appraisal of State activities under NRC/State of SC Environ Monitoring Contract 05-80-273. Appraisal included: review of repts.correspondence & evaluation of judgement in problem situations. Blabe lab inspected.

  WORKMAN, E. H., MONTOOMERY. D. M. Region 2, Office of Director. NRC-05-80-273. 83/02/15. 4pp. 19523:331.

- 8307140389 Forwards performance appraisal of State of AL activities performed under NRC/State of AL Environ Monitoring Contract 05-80-255. Contract renewed for 1963, based on cooperation received. OLSHINSKI, J. A.
  - J.A. Division of Engineering & Radiological Safety NRC-05-80-255. 83/04/07. GDDWIN.A. Alabama, State of. 19514:012
- --8307140399 Performance appraisal of State activities under NRC/State of AL Environ Monitoring Contract 05-80-235. Appraisal included: review of repts & correspondence & evaluation of judgement in problem situations. Btate lab inspected. WORKMAN.E., MONTGOMERY, D. M. Region 2. Office of Director. NRC-05-80-235. 83/04/04. 4pp. 19314:014.
- 8307140487 Notification of contract execution, Mod 1 to "Radioactive Matls Transportation Surveillance Program." Contractor: State of MD.
  SMITH, P.A. Division of Contracts. FIN B-1327. NRC-06-80-679.
  B3/07/01. KERR, G. W. Office of State Programs. Director. JANINEK, M.
  NRC No Detailed Affiliation Given. 1p. 19527:341.
- --B307140493 Mod 1.deobligated remaining unliquidated balance, to
  "Radioactive Matls Transportation Surveillance Program."
  EICHBAUM.H.M. Maryland, State of. SMITH.P.A. Division of
  Contracts. FIN B-1327. NRC-06-B0-679. B3/07/01. Ip. 19527:342.
- 8307150155 NUREG/BR-0025 VO9 NA INFORMATION REPORT ON STATE LEGISLATION. LANDAU.M., KERR.G.W. Office of State Programs, Director. B3/07/31. 10pp. 19574:346.
- 8307150364 Notification of contract execution Mod 1 to "State Legislative Reporting Svcs." Contractor: Public Affairs Info, Inc. Inc.
  PERLMAN, J. Administrative Contracts Branch. FIN B-1992.
  NRC-06-83-266. 83/07/01. KERR, O. W. Diffice of State Programs.
  Director. LANDAU, H. NRC - No Detailed Affiliation Given. 1p.
  19540:343.
- --8307150367 Mod 1, adding quarterly payments, to "State Legislative Reporting Bycs."

  \* Public Affairs Information, Inc. SMITH.P.A. Division of Contracts. FIN B-1392. NRC-06-83-266. B3/07/01. 2pp.
- 8307180172 Confirms discussion between NRC & NY State Dept of Labor following NRC review of Dept of Labor radiation control program. Review of encl comments on program & plans to improve agreement matis program requested. MVRLEY, T. E. Region 1. Office of Director. 83/07/01. ROBERTS, L. New York, State of. 8pp. 17555:076.
- B307250100 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of MI. BILVIS.R.M. Technical Assistance Contracts Branch. FIN B-8451. NRC-30-83-644. B3/07/14. PAPPAB.H. Region 3. Office of Director. DESTMANN NRC No Detailed Affiliation Given. 1p. 19720: 330.
- ---8307250104 Mod 2, correcting B&R number, to "Radiation Monitoring Division of Contracts. FIN p. 19720; 331.
- B307250111 Notification of contract execution.Mod 1 to "Radiation Monitoring Program Requirements." Contractor:State of CA. BILVIS.R.M. Technical Assistance Contracts Branch. FIN B-8553. NRC-32-83-684, B3/07/14. ALEXANDERII. Region 5, Office of Director, HAMADA.G. NRC No Detailed Affiliation Given. 1p.
- --8307250131 Mod 1.providing CY83 funding.to "Radiation Monitoring Program Requirements "
  \* California, State of. GUSTAVE,R.P. Division of Contracts. FIN B-8553. NRC-32-83-684. 83/07/14. 1p. 19725:346.
- 8307250143 Notification of contract execution. Mod 1 to "Radiation Monitoring Program Requirements." Contractor: State of CO. SILV18:R.M. Technical Assistance Contracts Branch. FIN B-8501. NRC-91-83-66B. 83/07/14. MEYERS.D.M. Region 4. Office of Director. NICHOLAS.J.B. NRC No Detailed Affiliation Given. 1p. 19725: 348.
- --8307250153 Mod 1,providing CY83 funding & changing B&R number, to "Radiation Monitoring Program Requirements."

  + Colorado, State of. GUSTAVE, R.P. Division of Contracts. FIN B-8501. NRC-31-83-668. B3/07/14. lp. 19723:349.
- B307250165 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of MD. BILVI5.R.M. Technical Assistance Contracts Branch. FIN B-B454. NRC-30-B3-643. B3/07/14. PAPPAS,H. Region 3. Office of Director. DESTMANN.M.J. NRC No Detailed Affiliation Given. 19. 19725:357.

- -830725017; Mod 2.correcting B&R number, to "Radiation Monitoring Program Requirements," \* Missouri, State of. GUSTAVE,R P. Division of Contracts. FIN B-8454. NRC-30-83-643. 83/07/14. 1p 19725-358
- 8307290312 PNA-82-004A; on 820510. State of WA informed NRC of completed cleanup of contaminated area from 820507 spill. Caused by clarifier tank rupture. Similar tank in use at Bear Creek Mill in WY. Region IV notified.

  BDLLING. L. A. KENDIG. J. NRC No Detailed Affiliation Given.
  83/05/11. 2pp. 19838:159.
- B307290494 Notification of contract erecution Mod 2 to "Radiation Monitoring Program Requirements." Contractor: State of WI. BILVIS, R.M. Technical Assistance Contracts Branch. FIN 8-8453 NRC-30-89-647. B3/07/19. PAPPAS.H. Region 3. Office of Director. DESTMANN, M. J. NRC No Detailed Affiliation Given. 1p. 19897: 393.
- --8307290473 Med 2.changing B&R number in Block 14, "Accounting & Appropriation Data," to 93193002, to "Radiation Monitoring Program Requirements."

  \* Misconsin, State of. GUSTAVE, R. P. Division of Contracts. FIN 8-8483 NRC-30-83-647. 83/07/19. 1p. 19897:354.
- 8307290480 Notification of contract execution Mod 2 to "Radiation Monitoring Program Requirements." Contractor:State of CH. SILVIS.R.M. Technical Assistance Contracts Branch. FIN B-8450. NRC-80-83-646. 83/07/19. PAPPAS.H. Region 3. Office of Director. DESTMAN.M.J. NRC No Detailed Affiliation Given. 1p. 19857:345.
- --B3072904B9 Mod 2.changing B&R number in Block 14.
  "Accounting & Appropriation Data." to 93193002.to "Radiation Monitoring & Program Requirements."
  \* Ohio, State of, OUSTAVE.R.P. Division of Contracts. FIN B-8450. NRC-30-83-646. 83/07/19. tp 19857:346.
- VENDOR REPORTS AND RELATED CORRESPONDENCE TOPREP
- 8306030043 Forwards safety evaluation to Mostinghouse topical rept.
  "Rod Bank Worth Measurements Utilizing Bank Exchange." Rept
  acceptable for referencing in licensing submittals
  Evaluation withheld.
  THOMAS.C.O. Standardization & Special Projects Branch. 83/05/23.
  RAHE, E. P. Westinghouse Electric Corp. 1p. 18735:001.
- 8307010044 Forwards BAN-1791, "B&W Duners Group Probabilistic Evaluation of Pressurized Thermal Bhock:Phase I Rept "Findings of PRA Study & related evaluations documented.NRC proposed screening limits valid & conservative.

  COGBURN.T.H. Babcock & Wilcox Operating Plants Duners Group.

  COGBURN.T.H. Sacramento Municipal Utility District 83/06/30.

  BCHROEDER.F. Division of Safety Technology 1p. 19173:108.
- --8307010051 BAW-1791 197010UD1 BAM-1771
  "BBW Dumers Group Probabilistic Evaluation of Pressurized
  Thermal Shock:Phase I Rept." W/ten oversize drawings.
  Aperture cards are available in PDR.
  ### Babcock & Wilcox Co. 77-1142462-00. B3/06/30 172pp. 19173: 110.
- B307010144 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Section 3.10 resulting from New LOCA analysis.

  MUSDLF.D. Northern States Power Co B3/06/24. Office of Nuclear Reactor Regulation, Director. 1p. 19173:277. 24X
  Fiche: 50-282,83/06/24,8397010144.
- 807010157 XN-NF-83-38
  "Prairie Island Units 1 & 2 Limiting Break LCICA-ECCS
  Analysis Using EXEM/PWR."
  TAMVILI,T., KAYSER,W.V., CHANDLER,J.C. Exxon Nuclear Co
  (subs. of Exxon Carp.). 83/05/27. 56pp. 19173:291. 2Fiche:50-282.83/06/24.8307010144.
- 8307010172 Forwards "Depressurization & DHR, Response to NRC Questions." Recommends NRC base cost/benefit analysis in existing Sys 80 plants on possible design change. SCHERER, A. E. Cambustion Engineering, Inc. LD-83-058. 83/06/29. ETSEMHUT, D. G. Division of Licensing. 59pp. 19171:127. 24X Fiche: 50-470,83/06/29,8307010172.
- --- 9307010184 CEN-239 "Depressurization & DHR, Response to NRC Questions."

  Executive summary included.

  \* Combustion Engineering, Inc. 83/06/30. 433pp. 19171:186. 24X
  Fiche: 30-470.83/06/29.8307010172.
- 8307010188 Forwards responses to NRC request for addl info on scram discharge piping integrity. DENTE, T. J. General Electric Co. BHROG-8325. 83/06/29. EISENHUT, D. G. Division of Licensing. 19pp. 19124.220.

- B307050007 Forwards proprietary Rev O to "Exion Nuclear Corp Solution to NRC Sample Problems ~ PWR Assemblies Mechanical Response to Beismic & LUCA Events." Affidavit encl. Withheld (ref 10CFR2.790).
  CDPELAND.R.A. Exxon Nuclear Co... Inc. (subs. of Exxon Corp.).
  RAC: 025.83. B3706/23. THOMAS.C.D. Standardization & Special Projects Branch. 4pp. 19192: 045.
- 8307050157 Forwards proprietary versions of Apps A.B.C & D to Vol II to "QESTR-LOCA & SAFER Models for Evaluation of LOCA." Encis uithheld (ref 10CFR2.790).

  GUIRX.J.F. General Electric Co. MFN-121-83. 83/06/28. THOMAS.C.O. Standardization & Special Projects Branch. 7pp. 19197: 279.
- 8307040003 Forwards proprietary "Performance Evaluation of Oyster Creek Core Spray Sparger," comprising formal response to 821012 request for addl assessment of existing core spray sgs. Rept withheld. FIEDLER.P.B. General Public Utilities - GPU Service Corp. 83/06/30. EISENHUT.D.G. Division of Licensing. 2pp. 19237:170. 24X Fiche: 50-219.83/06/30.8307060009.
- 8307060317 Forwards BAW-1784. "BEW Dwners Group Bolting Task Force Summary Rept of NRC/BEW Gwners Meeting on Reactor Vessel Internals Bolting." Test results support continued operation w/original lower core barrel bolts. RODRIGUEZ, R.J. Sacramento Municipal Utility District. RJR 83-526. 83/06/24. EISENHUT, D.C. Division of Licensing. 3pp. 19237: 243. 24X Fiche: 50-312, 83/06/24, 8307060317.
- 8307060385 Forwards "Seismic Qualification of Nuclear Plant Mechanical & Electrical Equipment," Quanterly Rept B.
  CAMPBELL.W.E. Mechanical/Structural Engineering Branch.
  NRC+07-81-185. \$3706/24. MURRIS.B. Electrical Engineering Branch.
  NOONAN.V. Equipment Qualification Branch BOSNAK.R.J. Mechanical
  Engineering Branch. ip. 19300:001.
- ---B307060388 SHRI-6582

  "Seismic Qualification of Nuclear Plant Electrical & Mechanical Equipment," Quanterly Rept B. KANA, D. D. POMERENING, D. J. Southwest Research Institute. NRC-04-81-185. 83706/14. Office of Nuclear Regulatory Research, Director. 28pp. 17300:002.
- 8307070079 Confirms understanding reached during 830224 joint TVA/Westinghouse demo licensing meeting re licensing submittals for GUAD+ demonstration assemblies for NRC review of Cycle 6 reload.

  RAME, E. P. Westinghouse Electric Corp. NS-EPR-2784, 83/06/27, EISENHUT, D. 0. Division of Licensing. 1p. 19293:137, 24X Fiche: 50-260, 83/06/27, 8307070079.
- 8307070195 Forwards request for add1 info re impact on plant safety after extended operation at reduced power, followed by return to full power in same cycle Request should be forwarded to affected utils.

  RAHELE.P. Westinghouse Electric Corp. NS-EPR-2785. 83/06/27.

  RERLINGER.C. Core Performance Branch. App. 19294:255.
- 8307080304 Forwards proprietary & nonproprietary versions of "Dropped Rod Methodology for Negative Flux Rate Trip Plants" & 830624 application for withholding proprietary info Proprietary rept withheld (ref 100FR2.790). RAMEREP. Westinghouse Electric Corp. NS-EPR-2788. 83/06/24. THOMAS.C.O. Standardization & Special Projects Branch. 2pp. 19362:136.
- --B3070B0309 Requests withholding of proprietary version of "Dropped Rod Methodolngy for Negative Flux Rate Trip Plants," per 100FR2 790, Affidavit enci. HIESEMANN.R.A. Westinghouse Electric Corp. AW-83-49. 83/06/24. TMDMAS.C.D. Standardization & Special Projects Branch. 8pp. 19342 138
- --8307080314 WCAP-10298-A

  Nonproprietary version of "Dropped Rod Methodology for

  Negative Flux Rate Trip Plants."

  MORITA-T., GSSORNE, M. P., LOFTUS, P. A. Westinghouse Electric Corp.

  83/06/30, 80pp. 19362: 146.
- 8307080316 Forwards comproprietary & proprietary versions of "BASH: Integrated Core & RCS Refined Code for Analysis of PNR LOCA." for review & approval. Application for withholding encl. Proprietary version withheld (ref 10CFR2.790). RAHELE.P. Westinghouse Electric Corp. SED-THTA-226. B3/06/20. THOMAS. CO. Standardization & Special Projects Branch. 3pp. 19346:160.
- -8307080322 Application for withholding punpristary "BASH: Integrated Core & RCS Reflood Gode for Analysis of PWR LOCA." (ref. 10CFR2.790). WESEMMANN.R.A. Westinghouse Electric Corp. AW-83-47. 83/06/20. THOMAS.C.D. Standardization & Special Projects Branch. 7pp. 19346:163.

- --8307080325 WCAP-10337 Nonpreprietary "BASH: Integrated Core & RCS Reflood Code for Analysis of PMR LOCA." KABADI, J. N., ROD, S. R., SHANAWANY, M. E. Westinghouse Electric Corp. 83/06/20, 134pp. 19346:170.
- 8307090091 Nutification of 830706 meeting w/Westinghouse Owners Group in Bethesda, MD to discuss TMI Action Item II. K. 3.30, "Small Break LOCA Model" & future application of maxi-convolution to LOCA analyses.

  GUTTMANN, J. Reactor Systems Branch. 83/06/29. SHERON, B. W. Reactor Systems Branch. 2pp. 17366: 329.
- B307090111 Notification of B30714 meeting w/QE & Licensing Review Oroups 1 & 2 in Bethesda.MD to discuss methodology for determining BWR reactor protection sys setpoints & allowable values.

  STEFANO.J.J. Licensing Branch 1. 83/06/28. YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 19384:107.
- 8307110038 Forwards Rev 1 to QC Instruction QCI 10.01, "Const Implementation Overview Assessment."

  BARANOM.S.W. Stone & Webster, Inc. 14509. 83/06/28. KEPPLER, J. Q. Region 3, Office of Director. 1p. 19375: 298. 24X

  Fiche: 50-329, 83/06/28, 8307110038.
- --8307110040 Rev 1 to GC Instruction GCI 10.01, "Const Implementation Overview Assessment," \* Stone & Webster, Inc. 83/06/27. 6pp. 19375:299, 24X Fiche:30-329,83/06/28,8307110038.
- 8307110224 Forwards requested info to determine fee for review of NEDE-24284-P/NEDO-24284, "Assessment of Fuel Rod Bowing in GE BURS."

  IHOMAS.C.O. Standardization & Special Projects Branch. FIN A-3371. TAC 43379. 83/06/24. BERKOW, H. N. Management Analysis Branch. 2pp 17985:351.
- B307110270 Forwards WCAP-10230. "Evaluation of Acceptability of Reactor Vessel Head Lift Rig, Reactor Vessel Internals Lift Rig, Load Cell & Load Cell Linkage to Requirements of NUREG-0612" & responses to NRC recommendations.
  ALEXICH.M.P. Indiana & Michigan Electric Co. AEP:NRC:05140. 83/07/05. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19378:332. 24X Fiche:50-315.83/07/05.8307110270.
- --B307110295 MCAP-10230

  "Evaluation of Acceptability of Reactor Vessel Head Lift Rig. Reactor Vessel Internals Lift Rig. Load Cell & Load Cell Linkage to Requirements of NURGE-0612."

  SANDMER.H. H. Westinghouse Electric Corp. AEP: NRC: 05140. B3/04/30. 150pp. 19378: 334. 24X Fiche: 50-315, B3/07/05, B307110290.
- B307110305 Forwards comments on mgt review committee B30423 meeting re bulk hanger organization. Mods ready for implementation. BARANOW.8.W. Stone & Webster, Inc. B3/06/30. KEPPLER, J. O. Region G. Office of Director. 2pp. 19378:330. 24X Fiche: 50-327, 83/06/30, B307110305.
- B30712022B Forwards application for amend to License NPF-3, revising Tech Specs re Cycle 4 reload. "Davis-Besse Nuclear Power Station Unit 1, Cycle 4 Reload Rept" also encl. CROUSES.R.P. Toledo Edison Co. 965. 83/07/05. STOLZ, J. F. Operating Reactors Branch 4. 1p. 19425:132. 24x Fiche: 50-346, 83/07/05, 830712022B.
- --8307120246 BAH-1783
  "Davis-Besse Nuclear Power Station Unit 1, Cycle 4 Reload Rept."
  \* Babcock & Wilcox Co. 83/05/31. 69pp. 19425; 140. 24X
  Fiche: 50-346, 83/07/05, 8307120228.
- 8307120366 Final Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response. Initially reported on 821026. Deficiency not reportable per 10CFR50, 55(e).

  Bechtel independent analysis of calculations encl.

  VAN BRUNTIE.E. Arizona Public Service Co. ANPP-24173-BSK/.
  83/06/27. STERNEERG.D.M. Region 5. Office of Director. 32pp. 19429:048. 24% Fiche: 50-528, 83/06/27, 8307120366.
- --8307120377 Rev 1 to "Engineering Evaluation for Design of Condensate Water Storage Tank & Refueling Water Tank Palo Verde Nuclear Generating Station." for Deficiency Evaluation Repts 82-56 & 82-63.

  LIMAYE, G. S. Bechtel Corp. DER 82-56. 83/05/31. 28pp. 19429:052. 24X Fiche: 50-528, 83/06/27, 8307120366.

- B307120397 Forwards proprietary version of "WAPWR Pretendering Module 6 Reactor Sys." Module provides WAPWR design detail & reflects licensing control document commitments. Rept withheld (ref 10CFR2.790). RAME.E.P. Westinghouse Electric Corp. NS-EPR-2786. B3/06/30. EIBENHUT.D.9. Division of Licensing. 2pp. 19430-265.
- --8307120399 Application for withholding "WAPWR Pretendering Module 6 Reactor Sys," from public disclosure (ref 10CFR2.790). WIEBEMAN.R.A. Westinghouse Electric Corp. AW83-50 83/06/30. EIBENHUT.D.G. Division of Licensing. 1p. 19430:267.
- 8307120403 Forwards suppl to Abnormal Transient Operating Guidelines 76-1123278-00.per 830521 ltr. Suppl provides additional operator guidance & basis for actions during ATMS & small break LOCA evants.

  HHITNEY, D. D. Babcock & Wilcox Operating Plants Owners Group.

  HHITNEY, D. D. Sacramento Municipal Utility District. OBC 83-11.

  83/07/02. EISENHUT, D. D. Division of Licensing. 26pp. 19430:229.

  24X Fiche: 50-287, 83/07/02, 8307120403.
- B307130120 Notification of B30707 & OB meetings w/C-E.C-E Owners Group, ANL.Bandia Natl Labs & B&R in Windsor Locks.CT to discuss participant rapts on C-E plant PORV study, LIANG.C. Reactor Systems Branch. B3/06/28. SHERDN.B.W. Reactor Systems Branch. B3/06/28.
- 8307130273 Informs of completion of analysis using TACO2 fuel performance code for LOCA limit for 177 fuel assembly raised loop plants. Rev to BAW-10105 dependent on NRC acceptance of other topical repts & resolution of NUREO-0630 issue.
  TAYLOR.J.H. Babcock & Wilcox Co. 83/07/06. 8TOLZ.J.F. Operating Reactors Branch 4. 2pp. 19508:286.
- 8307130278 Forwards "Final Rept on Evaluation of Spot-Welded Matls Used in Support Bus for Electrical Conduit & Cable Trays at Diablo Canyon Power Plant," supplementing Bechtel rept transmitted by PO&E 830225 ltr.

  SCHUYLER, J. O. Pacific Gas & Electric Co. 83/07/01. EISENHUT, D. O. Division of Licensing. Ip. 19474:006. 24X Fiche: 50-275, 83/07/01, 8307130278.
- --8307130281 "Final Rept on Evaluation of Spot-Welded Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Canyon Power Plant."

  Bechtel Corp. B3/07/01. 19pp. 19474:007. 24X Fiche: 50-275, 83/07/01, 8307130278.
- --8307130286 0072C/0109
  "Outline for Sampling, Preparation & Testing of Spot-Welded Superstrut Members for Diable Canyon Power Plant."

  Bechtel Corp. 83/06/02. 12pp. 19474:026. 24x
  Fiche: 50-275, 83/07/01, 8307130278.
- --B307130298 Forwards "Investigation of Matls Used in Support Bys for Electrical Conduit & Cable Trays at Diablo Canyon."

  Superstrut spot-welded members meet design requirements & may be installed.

  CRANE.P.A. Pacific Oas & Electric Co. 83/02/25. ENGELKEN,R.H., MORRILL.P.O. Region 5, Office of Director. 1p. 19474:056. 24X Fiche: 50-275,83/07/01,8307130278.
- --8307130302 "Investigation of Matls Used in Support Sys for Electrical Conduit & Cable Trays at Diablo Canyon."

  \* Bechtel Corp. 83/02/25. 33pp. 19474:057. 24X
  Ficha: 50-275, 83/07/01, 8307130278.
- 8307140130 Forwards safety evaluation of BWR Owners Group response to NUREO-0737, Item II.K. 3.18. "Mod of Automatic Depressurization Sys Logic..." Two acceptable options include elimination of high drywall pressure parmissive. VASBALLO.D.B. Operating Reactors Branch 2. 83/06/03. PILANT, J. M. Nebraska Public Power District. 2pp. 19828: 347. 24X Fiche: 50-298, 83/06/03, 8307140130.
- 8307140138 Forwards safety evaluation of BWR Owners Oroup response to NUREG-0737, Item II.K. 3.18, "Mod of Automatic Depressurization Bys Logic..." Two acceptable options include elimination of high drywell pressure permissive. VABSALLO.D.B. Operating Reactors Branch 2. 83/06/03, UTLEY, E. Carolina Power & Light Co. 2pp. 19528: 338. 24X Fiche: 50-324, 83/06/03, 8307140138.
- B307140144 Forwards safety evaluation of BWR Duners Group response to NUREG-0737. Item II.K. 3.18, "Mod of Automatic Depressurization Sys Logic..." Two acceptable options include elimination of high drywell pressure permissive. VABBALLO.D.B. Operating Reactors Branch 2. 83/06/03. RHODE.B.K. Nisgara Mohawk Power Corp. 2pp. 17540:001. 24% Fiche: 50-220, 83/06/03, 8307140144.

- 8307140190 Forwards safety evaluation of BHR Owners Group response to NUREO-0737.1tom II K. 3 18. "Mod of Automatic Depressurization Sys Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO.D. B. Operating Reactors Branch 2. 83706703 PARRIS, H. 0. Tennessee Valley Authority. 2pp. 17927: 334. 24X Fiche: 50-259, 83706703, 8307140150
- 8307140160 Forwards safety evaluation of BWR Owners Group response to NUREO-0737, Item II.K.3.18, "Mod of Automatic Depressurization 89s Logic...." Two acceptable options include elimination of high drywell pressure permissive. VASBALLO.D.D. Operating Reactors Branch 2. 83/06/03. SINCLAIR.J.B. Vermont Yankee Nuclear Power Corp. 2pp 19540:032. 24X Fiche: 50-271,83/06/03,8307140160.
- 8307140215 Forwards 830525 meeting summary re status of formation of util Ofc of QA & completion of action items in Ofc of Engineering Design & Const 1982 action plan for quality improvement. Viewgraphs encl.
  LEWIS,R.C. Division of Project & Resident Programs. 83/06/17. PARRIS,H.G. Tennessee Valley Authority. 36pp. 19521:333
- 8307140216 Confirms 830706 teleon re cancellation of 830707 mgt meeting at Region II to discuss security organization. Meeting will be rescheduled in near future.

  LEHIS,R.C. Division of Project & Resident Programs. 83/07/06.

  PARRIS, H.G. Tennessee Valley Authority. 1p. 19323:125.
- 8307140263 Advises that 830609 request for delay in submitting Rev 7 to TVA-TR75-1A. "QA Program Description for Design.Const & Operation of TVA Nuclear Power Plants," until 830815 acceptable.
  LEWIS.R.C. Division of Project & Resident Programs. 83/06/28.
  MILLS.L.M. Tennessee Valley Authority. ip. 19322:362.
- 8307140270 Evaluates util approach to interpretation of reporting requirements & definition of operability,per 830218 request. D'REILLY,J.P. Region 2, Office of Director, 83/03/04. STAMPLEY,N.L. Mississippi Power & Light Co. 2pp. 19322:329.
- B307140286 Forwards Updating Status Memo 18 applicable to GA Program Manual ETR-1001. TENZER,D. E. Ebasco Services, Inc. (subs. of Enserch Corp.). B3/07/07. HAASS/N.P. Division of Engineering. 2pp. 19528:121.
- 8307140503 Summary of 830601 meeting w/Westinghouse Owners Ordup in Bethesda, MD re proposed generic design mod to incorporate automatic shunt trip feature in reactor trip breakers.
  Final design will be submitted by and of June 1983.
  IPPOLITO, T. A. Operating Reactors Assessment Branch. 83/06/22.
  MIRAOLIA, F. J. Assistant Director for Safety Assessment. 39pp.
- 8307150075 Forwards NEDO-10678, "Seismic Qualification of Class 1 Electrical Equipment," in response to R Martin 830609 request. BRADLEY,E.J. Philadelphia Electric Co. 83/07/12. BCHWENCER,A. Division of Licensing. 2pp. 19535:287. 24X Fiche: 50-352,83/07/12,8307150075.
- --8307130081 NEDD-10678
  "Beismic Qualification of Class I Electric Equipment."
  TEBT.L.D. General Electric Co. 72NED81. 72/11/30. 77pp
  19535:289. 24X Fiche: 50-392,83/07/12,8307150075.
- 8307180165 Forwards evaluation of BWR Owners Group generic response to NUREO-0737, Item 11. K. 3. 18 "Automatic Depressurization Sys Logic Mods." Two acceptable options include elimination of high drywell pressure permissive. VASSALLO. D. B. Uperating Reactors Branch 2. 83/06/03. HARRINOTON. W. D. Boston Edison Co. 2pp. 19562: 304. 24X Fiche: 50-293, 83/06/03, 8307150165.
- B307150196 Forwards nonproprietary & proprietary versions of "Relaxation of Constant Axial Diffset Control & FQ Surveillance Tech Specs." Proprietary version withheld (ref 100FR2.790).

  RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2789. B3/04/27. THOMAS. C.D. Standardization & Special Projects Branch. 3pp. 19530:100.
- --8307150200 Forwards application for withholding proprietary version of "Relaxation of Constant Axial Offset Control & FQ Survevillance Tech Specs," per 100FR2, 790.
  WIESEMANN,R.A. Westinghouse Electric Corp. AW-83-51. 83/06/27. THOMAS,C.O. Standardization & Special Projects Branch. 9pp. 19530: 103.

- --8307150202 WCAP-10217-A
  "Relatation of Constant Axial Offset Control & FQ
  Surveillance Tech Spec."
  MILLER.R.W., POCORZELSKI.N., VESTOVICH.J.A. Westinghouse Electric
  Corp. 83/06/30. 100pp. 19530:116.
- B307150244 Forwards proprietary "Gadolinia-Bearing Lead Test Assemblies Design Rept." Info includes design testing & analysis for five lead test assemblies w/i2 gadolina-bearing fuel rods to be loaded in Cycle 8. Rept withheld (ref 10CFR2. 790). TAYLOR.J. H. Babcot & Wilcox Co. 83/07/12. SUERMANN.J. Office of Nuclear Reactor Regulation, Director. Bpp. 19532:234. 24% Fiche: 50-269.83/07/12.8307150244.
- 8307150348 Forwards Rev 1.Suppl 1 to proprietary XN-NF-82-20(P) "Exxon Nuclear Co Evaluation Model EXEM/PRR ECCS Model Updates: Revised FLECHT Bases Reflood Carryover & Heat Transfer Correlations." Rept Withheld (ref 10CFR2.790). COPELAND.R.A. Exxon Nuclear Co. Inc. (subs. of Exxon Corp.). RAC:30:83. 83/07/08. THOMAS.C.D. Standardization & Special Projects Branch. 2pp. 19531:103.
- B307180312 Forwards Core Performance Branch topical rept evaluation of MCAP-9863(P) & MCAP-9864(NP), "Rod Bank Horth Measurements Utilizing Bank Exchange." Root acceptable. Publication of accepted versions of rept requested. THOMAS.C. O. Standardization & Special Projects Branch. B3/06/27. RAHE, E. P. Westinghouse Electric Corp. 2pp. 19363:332.
- --8303220392 Topical rept evaluation of MCAP-9863. "Rod Bank Worth Measurements Utilizing Bank Exchange." Rept acceptable. « Core Performance Branch. TAC 43488. 83/03/31. 3pp. 19365:394.
- ### 8307180317 Draft "Study of Controlled Depressurization of Primary System PMRs."

  ## Burns & Ros Co. 63/06/30. 145pp. 17565:192.
- 8307180396 Notification of 830713 meeting w/BWR Regulatory Response Group in Bothesda. MD to discuss recent experience to cracks detected in large-diameter BWR piping & basis & rationale for allowing continued operation. IPPOLITO. T. A. Operating Reactors Assessment Branch. 83/07/08. MERAOLIA, F. Assistant Director for Safety Assessment. 1p.
- 8307180406 Submits schedule for issuance of proof & review Tech Specs over next 6 months for C-E,QE & Westinghouse plants.
  THOMAS,C.O. Standardization & Special Projects Branch. 83/07/11.
  BALLARD,R.L. Environmental Engineering Branch. BOSNAK,R.J.
  Mochanical Engineering Branch. HULMAN,L.G. Accident Evaluation Branch. 2pp. 17366:358.
- 8307180421 Forwards request for addl info on Rev 1 to CEN-203-P,
  "Response to NRC Action Plan Item II.K.3.30, Justification of
  Small Break LOCA Methods." Response should be submitted by
  833701.
  THOMAS.C.O. Standardization & Special Projects Branch. 63/07/08.
  WELLE,R.W. Combustion Engineering, Inc. 8pp. 17566:327.
- B307190049 Notification of B30721 meeting w/GE & GE Owners Group in Bethesda, MD to discuss post-accident sampling sys requirements, including dissolved gas analysis & core damage estimate procedure.

  NGRRIS.J. A. Operating Reactors Branch 1, 83/07/07, VARGA, S, Operating Reactors Branch 1, 2pp. 19656:252.
- 8307190253 Forwards "Analysis of Capsule D from Connecticut Yankee Reactor Vessel Radiation Surveillance Program," per 10CFR50 App H. confirming past predictions of low rate of embrittlement as function of radiation fluence.

  COUNSIL. W. G., SEARS, C. F. Connecticut Yankee Atomic Power Co. B10820, B3/07/06, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19628:168. 24X Fiche: 50-213, 83/07/06, 8307190253.
  - 8307190257 HCAP-10236
    "Analysis of Capsule D From Connecticut Yankee Reactor
    Vessel Radiation Surveillance Program."
    YANICHKA, B. E., ANDERSON, S. L., SHOGAN, R. P. Westinghouse Electric
    Corp. 83/01/31, 85pp. 19628:170. 24X Fiche: 50~213,83/07/06,
    8307190253.
- 8307200095 Application for amend to License DPR-33, changing Tech Specs for Reload 5, Cycle 6 operation. Change reflects mods performed during refueling outage. Approval needed by 830929. MILLS, L. M. Tennessee Vailey Authority. TVA BFNP TS 190. 83/07/13. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19647:176. 24X Fiche: 50-259, 83/07/13, 8307200095.

- --B307200105 22AB559 ROD
  Rev O to "Supplemental Reload Licensing Submittal for
  Browns Ferry, Unit 1, Reload 5."
  ELLIOTT, P. E., HILF, C. L., CHARNLEY, J. S. General Electric Co.
  B3/05/31. 30pp. 19647:247. 24X Fiche: 50-259, 83/07/13, 8307200095.
- B30721013B Forwards proposed rev to Generic Licensing Topical Rept EDR-1 (P)-A, "Ederers Nuclear Bafety-Related Extra-Safety & Monitoring (X-SAM) Cranes." Changes describe how X-SAM cranes implemented per NUREG-0554. Approval requested. CLARK.C. W. Ederer, Inc. B3/07/19. THOMAS.C. Standardization & Special Projects Branch. 2pp. 19666: 110.
- 8307210300 Forwards proprietary "Independent Evaluation of Proposed Mods to Westinghouse D4.D5 & DE Steam Generators." Rept withheld (ref 10CFR2.790).
  BUTTERFIELD.L. Steam Generator Owners Group. 1101R. 83/07/18.
  EISENHUT,D.Q. Division of Licensing. 3pp. 19664:114. 24X
  Fiche: 50-000.83/07/18,8307210300.
- B307220133 Notification of rescheduled B30720 meeting w/QE & QE Dwners Group in BethesdarMD to discuss post-accident sampling sys requirements. NORRES.J.A. Operating Reactors Branch 1. B3/07/21. Operating Reactors Branch 1. 2pp. 19692:355.
- B307220316 TVA-TR75-1 RO6
  Rev 6 to "QA Program Description."
  \* Tennesses Valley Authority. B3/07/22. 183pp. 19674:278,
- 8307250088 Approves 821018 request for withholding Rev 1 to Westinghouse WCAP-10145 from public disclosure (ref 10CFR2.790). VARGA.S. A. Operating Reactors Branch 1. 83/06/27. BAYNE, J.P. Power Authority of the State of New York. 4pp. 19720: 337. 24X Fiche: 50-286: 83/06/27, 8307250088.
- 8307250320 VEP-NOS-6
  "Surry Unit 2. Cycle 6 Core Performance Rept." W/undated ltr.
  HENDRIKSON.E.S. Virginia Electric & Power Co. 405. B3/07/31.
  DENTON.M.R. Office of Nuclear Reactor Regulation, Director.
  VAROA.S.A. Operating Reactors Branch 1. 50pp. 19705:215. 24X
  Fiche: 50-281,83/07/31,8307250320.
- 8307250397 Forwards proprietary version of NEDE-30130, "Steady-State Nuclear Methods." Rept documents OE improved nuclear methods based on extensive measurements taken at different plants over several cycles. Rept withheld (ref 100FR2.790).
  CHARNLEY, J. S. General Electric Co. MFN-139-83. B3/07/21.
  MIRAGLIA, F.J. Assistant Director for Safety Assessment. App. 19705:225.
- B307250451 VEP-NDB-4
  "North Anna Unit 2, Cycle 3 Startup Physics Test Rept."
  W/B30719 ltr.
  STEMART. W.L., MANN, B. D., RUFTY, B. J. Virginia Electric & Power Co.
  410. 83/06/30. DENTON. H. R. Office of Nuclear Reactor Regulation,
  Director. CLARM. R. A. Operating Reactors Branch 3, 64pp.
  19702:094. 24% Fiche: 50-339,83/06/30,8307250451.
- 8307250534 Summary of 830629 meeting w/Mark III BWR Owners Group in Bethesda: MD re hydrogen control research program. Need & technical basis for reduced hydrogen source term in BWR discussed. Viewgraphs encl.
  HOUSTON: M. D. Licensing Branch 2. 83/07/15. 8CHWENCER: A. Licensing Branch 2. 120pp. 19739: 287. 24X Fiche: 50-416, 83/07/15, 8307250534.
- 8307260227 Provides info re changes to QA program from PBAR description: for review & acceptance.

  GERRETS: T.F. Louisiana Power & Light Co. M3K83-0781. 83/06/09. CDLLINS.J.T. Region 4. Office of Director. 9pp. 19726:346. 24X Fiche: 50~382,83/06/09.8307260229.
- --8307260247 Topical rept evaluation of ETR-1001.Rev O, "Ebasco Nuclear QA Program," Rept acceptable. \* QA Branch. B3/06/09. 2pp. 19726:357. 24X Fiche:50-382,83/06/09.8307260229.
- --B307260256 Advises that QA program described in Topical Rept CENPD-210-A.Rev 3 being implemented satisfactorily. Conclusions of ltr valid for 3 yrs. SEYRITIK.V. Region 4, Dallas, Office of the Director (81/03/01). B1/06/02. ETHERIDGE, M. R. Combustion Engineering, Inc. 3pp. 19726.359. 24X Fiche: 50-382, 83/06/09, 8307260229.
- 8307260270 Forwards NEDD-24056, Rev 1, "LOCA Analysis for Browns Ferry, Unit 1," to support 830713 amend request LOCA rept revised to reflect addition of new fuel type & to differentiate between most limiting assumed breaks.
  KAMMER.D. S. Tennessee Valley Authority. 83/07/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 19726:141. 24X Fiche: 50-259.83/07/21, 8307260270.

- --8307260279 NEDD-24096 R01
  Rev 1 to "LOCA Analysis for Browns Ferry Unit 1."
  W General Electric Co. 83/05/31. 47pp. 19726:143. 24X
  Ficha: 50-299, 83/07/21, 8307260270.
- 8307260437 Forwards proposed Rev 6 to "QA Program for Nuclear Fuel Design & Fabrication." Rev updates organizational titles & reflects improvements in program.

  VDLMER,C.J. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  83/07/14. ANKRUM,G.T. Director's Office, Office of Inspection and Enforcement. ip. 19731:212.
- --B307260440 XN-NF-1A RO6
  Rev 6 to "GA Program for Nuclear Fuel Design & Fabrication."
  MCCULLUGH, R. W., VOLMER, C. J., PERRY, S. K. Exxon Nuclear Co., Inc.
  (subs. of Exxon Corp.). 83/07/18. 65pp. 19731:213.
- 8307260497 Application for amend to License DPR-49, proposing Tech Spec Change RTS-152 re reduced flow rate requirements for RHR svc water sys, Proprietary NEDE-30051 & NEDC-22082-P encl. Repts withheld (ref 100FR2.790).

  MCGAUGHY, R.W. Iowa Electric Light & Power Co. NG-83-1931.
  83/07/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 11pp. 19731:299. 24X Fiche:50-331.83/07/20.8307260497.
- 8307270295 Forwards supplemental info requested at 830429 meeting w/NRC re fatigue crack growth uncertainties & loads considered & minor revs to NRC comments on Fracture mechanics evaluations.

  RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2793. 83/07/11.

  JOHNBON, N. V. Assistant Director for Matls. Chem & Environ Technology (Post 830201). 20pp. 19768:359.
- B307270422 Forwards proprietary & nonproprietary versions of "Fuel & Poison Rod Bowing," in response to B30215 request. Affidavit to withhold proprietary info per 10CFR2.790 encl. SCHERER, A. E. Combustion Engineering, Inc. LD-83-065. B3/07/22. THOMAS, C. O. Standardization & Special Projects Branch. 5pp. 19769:033.
- --8307270425 CENPD-225-NP-A "Fuel & Poison Rod Bowing." \* Combustion Engineering, Inc. 83/06/30. 468pp. 19767:040.
- 8307270439 Suppl to 821229 application to amend License DPR-59, allowing plant operation w/single recirculation loop out of svc for unrestricted duration at power levels not exceeding 50%. Errata & addenda to NED0-24281 encl.
  BAYNE.J.P. Power Authority of the State of New York. JPN-83-71.
  63/07/25. VASSALLO,D. B. Operating Reactors Branch 2. 2pp.
  19767:180. 24% Fiche: 50-333,83/07/25,8307270439.
- --8307270440 NEDD-24281 ERR Errata & addenda to NEDD-24281, "Single Loop Operation." + Oeneral Electric Co. BONED285. B0/12/31. 4pp. 19767:182. 24X Fiche: 50-333:B3/07/25,B307270439.
- 8307280055 Forwards Endorsement 107 to NELIA Policy NF-111 & Endorsement 46 to MAELU Policy MF-85.
  BOTHMAN, J. McDermott, Inc. 83/07/20. DINITZ, I. Division of Engineering. 3pp. 19791:196.
- 8307280114 Forwards proprietary slides presented at 830628 meeting w/NRC in Bathesda, MD re Westinghouse advanced PWR Pretendering Modules 3 & 4. Slides withheld (ref 10CFR2.790). RAHE, E.P. Westinghouse Electric Corp. NS-EPR-2795. 83/07/12. EISENHUT, D. G. Division of Licensing. 1p. 19795:307.
- --8307280120 Requests withholding per 10CFR2.790 of encl presentation mat1 from 830628 meeting w/NRC re Westinghouse advanced PWR Pretendering Modules 3 & 4.
  WIESEMANN, R. A. Westinghouse Electric Corp. AW-83-56. 83/07/12.
  EISENHUT, D. G. Division of Licensing. 1p. 19795:308.
- 8307280364 Forwards proprietary Rav O to XN-NF-711(P), "Extension of XNB Correlation to PWR Fuel Assembly Designs W/Spacer Pitch Greater Than 22 Inches." Withholding of proprietary rept requested per 10CFR2.790. Affidavit encl.

  ZIMMERMAN, S. R. Carolina Power & Light Co. LAP-83-345, 83/07/25. EISENHUT, D. G. Division of Licensing. 7pp. 19797: 245. 24X Fiche: 50-261,83/07/25,8307280364.
- 8307290455 Forwards summary of 830714 meeting w/BWR Cuners, GE, KMC & Bechtel re instrument setpoint methodology, Addl info needed to resolve concerns.

  STEFANCI, J. Licensing Branch 1, 83/07/22. BOYD.R. KMC, Inc. 6pp. 19857:347.
- 8307290467 Responds to FDIA request for NRC 810227 ltr to GE. Forwards document. Document also evailable in PDR. FELTON.J.M. Division of Rules and Records. 83/05/18. PEDRO.J. NUS Corp. ip. 19859:043.

- --8307290478 Topical rept evaluation of NEDD-21985. "Functional Capability Criteria for Essential Mark II Piping." Highest loading conditions re various ASME Code svc atress levels should be specified in functional capability assessment. # Mechanical Engineering Branch. 80/03/31. 14pp. 19839:046
- 8307290520 Notification of 830728 meeting w/BWR-Hydrogen Control Gwners Group in Bethesda.MD to discuss probability of large-scale hydrogen generation in Mark III BWRs.hydrogen control requirements & distributive ignition sys capability. HOUSTON.D. Licensing Branch 2. 83/07/18. SCHWENCER.A. Licensing Branch 2. 9pp. 19857:165.

#### WASTE MGT NUCLEAR WASTE MANAGEMENT

- 8305130263 Confirms comments re DES for Basalt Waste Isolation Project environ assessment in response to 830318 memo. OLMSTEAD.W.J. Regulations Division. 83/04/01. BELL.M.J. High Level Waste Licensing Management Branch. 2pp. 19713:323.
- 8307050275 Summary of 830617 meeting w/Electric Util Companies
  Nuclear Transportation Group in Baltimore MD re
  implementation of Natl Waste Policy Act Attendance list &
  viewgraphs encl.
  MACDDNALD, C.E. Division of Fuel Cycle & Material Safety. 83/06/21.
  Division of Fuel Cycle & Material Safety. 23pp. 19263: i04.
- 8307030278 Responds to B30523 request that IE be on distribution for documentation re implementation of Nuclear Waste Policy Act & development of imps & monitoring procedures for const & operation of high level waste storage facilities.

  BROWNING.R.E. Division of Waste Management. 83706/06. TAYLOR. J. M. Director's Office, Office of Inspection and Enforcement. 2pp. 19263:102.
- B307090280 Trip rept of attendance at Southern States Energy Board Compact Negotiators 830315-16 meetings w/EGS6 & DOE in Atlanta, GA re data sys for tracking low level waste. JACKSON.K. Low Level Waste Licensing Branch.
- 8307050296 Informs of review of seismic study rept for Bouth Salt Lake City prepared by Sergent, Hauskins & Beckwith. Rept adequately addresses risks from earthquakes re bldg on Bouth Balt Lake City site. No technical questions on rept. MARTIN, D. E. Low Level Wasto Licensing Branch. 83/06/20. MORLEY, J. A. Energy, Dept. of. 1p. 19263:226.
- 8307050301 Addresses three areas for consideration before reaching final agreement on DOE program for designating vicinity properties for remedial action under UMTRAP.
  HIGGINBOTHAM.L. Low Level Waste Licensing Branch. 83/06/17.
  BAUBLITZ.J.E. Energy, Dept. of. 4pp. 19263:229.
- B307050305 Forwards procedural agreement covering consultations between DDE & NRC on high level waste site characterization activities under Nuclear Maste Policy Act of 1982 Signature requested if agreement satisfactory.

  DAVIG. J. G. Office of Nuclear Material Safety & Bafeguards, Director. 83/06/17. MORGAN, R. L. Energy, Dept. of. 4pp. 19263:233.
- B307050308 Forwards draft summary of B30608 meeting in Bethesda.MD resite development activities, for review.
  BRUHNING.R.E. Division of Waste Management. 83/06/17. AVANT.R.V. Texas, State of. 5pp. 19263:237.
- 8307030388 Forwards 15 radiological assessment repts for properties in Edgement, 9D where residual radioactive math detected, W/o encl.
  MARTIN D. E. Uranium Recovery Licensing Branch. 83/06/16.
  GEIDT, J. R. Environmental Protection Agency. 1p. 19263:258.
- 8307050397 Forwards 15 radiological engineering assessment repts prepared by ARIX Corp for State of SD. Repts identify addi properties in Edgemont, SD w/presence of residual radioactive matls. H/o encl. MARTIN. D. E. Uranium Recovery Licensing Branch. 83/06/15. 8AUBLITZ. J. Energy, Dept. of. 1p. 1923:316.
- B307050405 Forwards 15 radiological assessment repts for properties in Edgemont, 8D where residual radioactive matl detected. W/o encl. MARTIN D.E. Uranium Recovery Licensing Branch. B3/04/16. BRICH, R. South Dakota, State of. 1p. 19263:315.
- B307050414 Forwards organization charts for UMTRA project ofc. technical assistance contractor & remedial action contractor. Meeting will be set up for project ofc & TAC personnel to present & receive NRC comments within 2 wks.
  ARTHUR.W.J. Energy, Dept. of. 83/06/13. MARTIN.D.E. Low Level Waste Licensing Branch. 6pp. 19262:354.

- 8307060485 Forwards "Implementation Plan for EIS Concerning Remedial Actions at U Mill Tailings Site near Grand Junction CD." MORLEY, J.A. Energy, Dept. of 83/06/23. MARTIN.D. Low Level Waste Licensing Branch. 2pp. 19299:132.
- --8307060489 "Implementation Plan for EIS Concerning Remedial Actions at U Mill Tailings Site near Grand Junction CD." \* Energy, Dept. of. 83/06/30. 65pp. 19297:134.
- 8307080580 Trip rept of attendance at DOE 830419-20 workshop in Niagara Falls.NY re in situ surface gamma radiometric maasurements w/portable instruments.
  FLORY.C.A. Low Levs! Waste Licensing Branch. 83/04/28, HIGOINBOTHAM.L. Low Level Waste Licensing Branch. 2pp. 19364:291.
- 8307080674 Trip rept of 830502-04 visit to Fort Mitchell, KY to attend ninth annual EPA research symposium on land disposal, incineration & treatment of hazardous wastes. PENNIFILL.R.A. Low Level Waste Licensing Branch. 83/06/22. MARTIN, D.E. Low Level Waste Licensing Branch. 17pp. 19364:106.
- 8307090103 Trip rept of participation in B30530-0603 course on containment hydrogeology at Univ of Materico. Instructors stressed physical & chemical processes of containment transport.

  LOGSDON.M. High Level Waste Technical Development Branch. 83/06/16.

  JUSTUS.P.S. High Level Waste Technical Development Branch. 17pp.
- 8307090106 Act receipt of comments on draft environ assessments. Most concerns addressed in revised assessments. Requests for more detailed info more appropriate as part of licensing actions. MCRLEY.J.A. Energy, Dept. of. 83/06/21. MARTIN.D. Low Level Waste Licensing Branch. 1p. 19366:334.
- 8307090109 Forwards revised radiological assessment rept for Property PNL-159. W/o encl.

  JACKSON,P. (I. Battelle Hemorial Institute, Pacific Northwest Laboratory, 83/06/22, FLORY,C.A. Low Level Waste Licensing Branch. 1p. 19366:333.
- 8307090113 Proposes development of MOU w/DOE re NRC/DOE interaction on sites identified in U Mill Tailings Radiation Control Act as needing remedial actions.

  CUNNINGHAM.R.E. Division of Fuel Cycle & Material Safety. 83/06/24.

  BROWNING.R. Division of Waste Management. 1p. 19366:332.
- B3071100B1 Requests comments on paper of required staff level presented at B30607 meeting in Bethesda MD concerning storage of commercial low level waste Policy to be utilized by NRC restorage proposed, JACKSON-K. Low Level Waste Licensing Branch. B3/06/24. SALOMON,S., SCHEIDER,K., YOUNG,F. Office of State Programs, Director. 7pp. 19386:290.
- 8307110111 Informs that NRC supported radiological survey of approx 970 Edgemont, SD properties & will provide survey repts in next few months for 184 properties in which contamination identified.

  COFFMAN.F.E. Energy, Dept. of, NE-24, 83/06/24. ROMATCHSKI, R.O. Energy, Dept. of, 2pp. 19386:133.
- B307110157 Apologizes for inactivity of Radwaste Subcommittee. Requests review & comments on encl preliminary Environ Effects Committee, Energy Div, ASCE, set of goals & activities. HAHKINS, E.F. Low Level Waste Licensing Branch. B3/06/24. BEER, L. American Society of Civil Engineers. 3pp. 19385:358.
- 8307130375 Forwards description of properties in vicinity of Grand Junction site contaminated w/residual radioactive mat1 slated for remedial action. BAUBLITZ. J. E. Energy, Dept. of. 83/06/29. HIGGINBOTHAM Low Level Waste Licensing Branch. 2pp. 19509: 325.
- 307180313 Forwards comments on EPA proposed environ stds for mgt & disposal of spent nuclear fuel & high level & transurenic wastes. Definition of high level radwastes should be made compatible w/Nuclear Waste Policy Act of 1982. DAVIS, J. G. Office of Nuclear Haterial Safety & Safeguards, Director. 83/05/10. Environmental Protection Agency. 9pp. 19366:096.
- B307180329 Forwards list of applicable EPA FR cites for proposed environ stds for mgt of spent nuclear fuel & high level & transurante wastes.

  BROWNING.R.E. Division of Waste Management: 83/06/20.
  Environmental Protection Agency. 2pp. 19586:001.

- 8307180331 Forwards list of UMTRA project ofc & technical assistance contractors responsible for coordinating design development & remedial action activities.

  MORLEY, J. A. Energy, Dept. of. 83/07/06. MARTIN.D. NRC No Detailed Affiliation Given. BERVEN.B. Dak Ridge National Laboratory. BAILEY, E. Texas, State of. 3pp. 17366:324.
- 8307180375 Forwards DES for Grand Junction inactive U Mill Tailings Site for review & comment. Comments requested by 830727. W/o encl. MORLEY, J. A. Energy, Dept. of. 83/06/27. MARTIN.D. Low Level Waste Licensing Branch. ip. 19641:278.
- 8307190055 Forwards comments on land value rept for Salt Lake City site, per 830620 telcon w/J Themelis Rationals for limiting rept to only 22.5 acres questioned. MARTIN.D.E. Uranjum Recovery Licensing Branch. 00380. 83/06/24. MORLEY, J. Energy, Dept. of. 2pp. 19656:250.
- 8307190447 Agrees w/decision to include six properties in Grand Junction.CD for remedial action under provisions of U Hill Tailings Radiation Control Act of 1978 (Public Law 95-604).
  HIGGINBOTHAM.L. Low Level Haste Licensing Branch. 83/06/29. BAUBLITZ.J.E. Energy, Dept. of. ip. 19651:361.
- 8307190451 Forwards 18 radiological assessment repts for properties in Edgemont, SD where presence of residual radiological matl detected. Repts incorporate comments agreed on during 830023 meeting, W/o sncl.

  MARTIN, D. E. Low Level Waste Licensing Branch. 83/06/24.

  BAUBLITZ, J. Energy, Dept. of. 2pp. 17656:032.
- B307190472 Forwards comments re land value rept discussed on B30620 w/NRC & Jacobs Engineering, Several documents referenced throughout rept should be included in rept conclusion. MARTIN.D.E. Uranium Recovery Licensing Brench. B3/06/24. MORLEY, J. Energy, Dept. of. 2pp. 17656:163.
- 8307200182 Trip rept of attendance at 830524-27 third nat1 symposium & exposition on aquifer restoration & groundwater monitoring in Columbus. OH re aquifer cleanup, groundwater monitoring & contaminant containment.

  SHAFFNER. J. A. Low Level Haste Licensing Branch. 83/06/30. Low Level Waste Licensing Branch. 4pp. 19670:314.
- 8307200224 Advises that three of 18 properties in Edgement. SD, reported in radiological engineering assessment repts, not eligible for remedial action due to absence of residual radioactive matl in excess of EPA stds.

  FLORY. G. Low Level Waste Licensing Branch. 83/06/30.

  HIGGINBOTHAM, L. Low Level Waste Licensing Branch. 1p. 19670:253.
- 8307210021 Advises that review of radiological assessment repts for 28 properties in Edgemont SD revealed that 10 properties not eligible for remedial action. Mine properties contained residual radioactive math not exceeding EPA stds. FLORY, C. Low Level Waste Licensing Branch. 807/06/30. HIGGINBOTHAM, L. Low Level Waste Licensing Branch. 2pp. 19672:361.
- 8307220010 Forwards Draft 2 of site characterization analysis, including executive summary & Chapters 1-11. Comments requested by 821228. Conclusions & recommendations will be available by 821227.

  WRIGHT, R. J. High Level Waste Technical Development Branch. 00146. 82/12/21. BELL, M. J. High Level Waste Licensing Management Branch. BUNTING, J. O. Licensing Process & Integration Branch. MILLER, H. J. High Level Waste Technical Development Branch. 138pp. 17678:157.
- 8307220026 Forwards "Radiolysis of Groundwater From High Level Waste Stored in Copper Canisters." Findings on hydrogen nucleation in backfills containing clay are of great importance. Rept should be sent to E Moore. W/a encl. MCNEIL.M.B. Health Effects Branch. 00092. 83/02/18. WRIGHT.R. High Level Waste Technical Development Branch. 2pp. 19712:272.
- 8307220029 Advises that 830124 request for "Basalt Maste Isolation Project Site Characterisation Rept" forwarded to DOE.
  MILLER.H.J. High Level Waste Technical Development Branch. 00091, 83/02/14. MAKINO, M. JGC Corp. 1p. 19712:274.
- 8307220033 Requests site characterization rept for Hanford Reservation suggesting site as candidate for high level raduaste repository.

  MAKING.M. JGC Corp. 00093, 83/01/26. MILLER, H. J. High Level Waste Technical Development Branch. 1p. 19712: 275.

- 8307220036 Forwards executive summary of "Basalt Waste Isolation Project Site Characterization Rept." Summary does not accurately reflect site uncertainties reflected in rept test.

  WRIGHT.R.J. High Level Waste Technical Development Branch. 00090.
  82/12/07. SALTZMAN, J. D. NRC No Detailed Affiliation Given. 1p. 19712:276.
- 830722003B Forwards FR notice re receipt of site characterization rept for candidate high level waste repository on Hanford Reservation. Notice should be distributed to WH std distribution code.
  8TILL.N. Division of Waste Management. 00089. 82/12/01.
  LARKINS.P. Policy & Publications Management Branch. 2pp. 19712:277.
- 8307220041 Summarizes Baselt Waste Isolation Project (BWIP) status. BWIP is leading site in DDE high level waste repository site characterization program.
  WRIGHT.R. J. High Level Waste Technical Development Branch. 00088.
  82/11/22. UNDERWOOD.L. Office of Resource Management, Director.
  2pp. 19712:279.
- 8307220045 Forwards press release of NRC receipt of Basalt Wasts Isolation Project site characterization rept. 8TILL.N. Licensing Process & Integration Branch. 00085. 82/11/19. NRC - No Detailed Affiliation Given. 4pp. 19712:281.
- 8307220051 Requests distribution of Basalt Waste Isolation Project site characterization rept per listed plans.
  WRIGHT.R.J. High Level Waste Technical Development Branch. 00086
  82/11/19. STILL,N. NRC No Detailed Affiliation Given. 2pp. 19712:285.
- 8307220053 Forwards draft public announcement of receipt of DDE SER for Hanford Reservation. INGRAM.F. Office of Public Affairs. 00084. 82/11/17. MARTIN.J. Office of Nuclear Material Safety & Safeguards.Director. 4pp. 19712:289.
- B307220062 Advises of general agreement w/P Justus. Issues should be raised through Basalt Waste Isolation Project effort.
  MILLER-H. NRC No Detailed Affiliation Given. 00053. B2/03/16.
  WRIGHT-B. NRC No Detailed Affiliation Given. 1p. 19712: 294.
- B307220067 Expresses concern re publication of any NRC paper on any aspect of issue NRC will use or consider using in licansing any facility. Rept should not be published in prof journal as results & conclusions of NRC research.

  JUSTUS.P. S. NRC No Detailed Affiliation Given. 00052. B2/03/14. MILLER. H. NRC No Detailed Affiliation Given. ip. 19712: 295.
- 8307220077 Forwards data review forms for boreholes from Basalt Waste Isolation Project, per 830215 request. Data to be used in computer simulations of groundwater flow for hypothetical repository in basalt.
  LOGEDON M. J. High Level Waste Technical Development Branch. FIN A-1266. 00163. 83/02/25. DAVIS, P. Sandía Laboratories. 14pp. 19713-296.
- 8307220084 Notification of 830307-08 meetings w/Golder Assoc.Geotrans & Williams & Assoc in Silver Spring.MD to discuss status of NRC two-dimensional groundwater modeling of Hanford site. LOGBDON.M. High Level Haste Technical Development Branch. 00313. 83703/02. MILLER.H.J. High Level Waste Technical Development Branch. 3pp. 19712;310.
- 8307220089 Requests review of DOE draft environ assessment for Basalt Maste Isolation Project. Comments on issues to be addressed in environ assessment needed by 830325.
  BELL,M.J. High Level Waste Licensing Management Branch. 00337.
  B3/03/18. CDMELLA:P.A. Division of Health, Siting & Waste Management. 2pp. 19712:313.
- --8307220094 Requests review of DDE draft environ assessment for Basalt Maste Isolation Project. Comments on issues to be addressed in environ assessment needed by 830325.

  BELL. M. J. High Level Haste Licensing Management Branch. 00350.

  83/03/18. CUNNINGHAM.R.E. Division of Fuel Cycle & Material Safety. 2pp. 19712:315.
- --8307220099 Requests review of DOE draft environ assessment for Basalt Waste Isolation Project.Comments on issues to be addressed in anviron assessment needed by 830325.

  BELL.M.J. High Level Waste Licensing Management Branch. 00348.
  83/03/18. BUNTING.J.O. Licensing Process & Integration Branch. 2pp. 19712:317.
- --8307220107 Requests review of DDE draft environ assessment for Basalt Waste Isolation Project.Comments on issues to be addressed in environ assessment needed by 830325. BELL.M.J. High Level Waste Licensing Management Branch. 00349. 83/03/18. OLMSTEAD.W.J. Regulations Division. 2pp. 19712:319.

- --8307220112 Requests review of DOE draft environ assessment for Basalt Waste Isolation Project. Comments on issues to be addressed in environ assessment needed by 830325.
  BELL-M. J. High Level Waste Licensing Management Branch. 00344.
  83/03/18. MILLER.M. J. High Level Waste Technical Development Branch. 2pp. 19712:321.
- --8307220117 DDE/EA-0210
  "Braft Environ Assessment for Characterization of Hanford Site per Nuclear Waste Policy Act of 1982 (Public Law 97-425). Hanford Site, Richland, Benton County, WA." \* Energy, Dept. of. 83/02/28. 184pp. 19712: 323.
- 8307220096 Summarizes 830316 telcon re RRL-2 drillhole rept. Basalt Waste isolation Project interpretation is that fracture zone within dense interior of umtanum unit in RRL-2 connected w/flow bottom.

  OREEVEG. J. T., JUSTUS, P. S. High Level Waste Technical Development Branch. 00425, 83/04/29. High Level Waste Technical Development Branch. 3pp. 19699:030.
- 8307220103 Summarizes B30317 telcon as followup to 830316 telcon re mud & core loss at RRL-2.Basalt Waste Isolation Project mgt believes mud lost in flow taps not within dense interior. GREEVES.J.T., JUSTUS.P.B. High Level Waste Technical Development Branch. 00424. 83704/29. High Level Waste Technical Development Branch. 2pp. 19699:033.
- 8307220110 Responds to 830304 FR notice soliciting comments on issues to be included in environ assessment supporting nomination of DDE Hanford site as potentially acceptable repository site. NUREG-0960 analysis should considered in rept.

  BROWNING.R.E. Division of Waste Management. 00458. 83/05/02. BENNETT.W.J. Energy, Dept. of. 2pp. 19699:035.
- B307220ii6 Comments on DDE B3040i FR notice of intent to prepare EIS on disposal of radioactive defense wastes stored at Hanford near Richland, MA. Principal concern relates to extent action will comply w/NRC regulations on radwaste disposal.
  BROWNING.R.E. Division of Waste Management. 00438. 83/05/04.
  BCHREIBER, J. J. Energy, Dept. of. 2pp. 19699:037.
- 8307220121 Confirms 830323 meeting of assistants to discuss NRC analysis of DDE Hanford site characterization rept. BATES.A. Office of the Secretary of the Commission. 00328. 83703/21. QARMER.D., AUSTIN.J., DROGGITIS.S. NRC No Detailed Affiliation Given. ip. 19713:146.
- 8307220122 Forwards "Nonisothermal Flow Modeling of Hanford Site."
  Rept demonstrates application of tools developed for NRC for simulation of post-closure coupled groundwater flow & heat transport near hypothetical repository, Myo encl.
  WRIGHT,R. J. High Level Waste Technical Development Branch. 00450.
  83/05/13. DLSON,O.L. Energy, Dept. of. 1p. 17479:039.
- 8307220124 Forwards branch comments on portions of Chapters 1,2 & 3 of DDE draft environ assessment for Basalt Waste Isolation Project.
  MILLER: H. J. High Level Waste Technical Development Branch. 00334.
  83/03/23. BELL, M. J. High Level Waste Licensing Management Branch. 34pp. 19713:147.
- 8307220127 Ack receipt of 830427 ltr w/status of 26 site characterization rept refs. Identity requested of refs DDE will supply when rept released. MRIOHTR. J. High Level Waste Technical Development Branch. 00473. 83/06/01. OLSON.O.L. Energy, Dept. of. 1p. 19699:040.
- 8307220131 Forwards Sierra Club statements re environ assessment of Hanford site as high level radwaste repository.

  HOVIS, J. B. Hovis, Cockrill, Weaver & Bjur. HOVIS, J. B. Sierra Club 00368. 83/04/28. WRIGHT, R. J. High Level Waste Technical Development Branch. 17pp. 19713:183.
- 8307220132 Lists items to be discussed at DDE/NRC meeting. Items include waste package development, siting guidelines, DDE project decision schedule & DDE mission plan.

  \* NRC No Detailed Affiliation Given. 00470. 83/05/05. NRC No Detailed Affiliation Given. 1p. 17679:041.
- 8307220136 Summary of 830613-16 meetings w/DDE in Richland WA re site characterization (saue clarification NRC must have access to test data as data developed, to test plans in formative stage & to evaluate QA documentation.
  WRIGHT.R.J. NRC No Detailed Affiliation Given. 00083. B3/06/16. NRC No Detailed Affiliation Given. 11pp. 17679:042.

- 8307220137 Forwards "Nonisothermal Flow Modeling of Hanford Site."
  Rept details Basalt Waste Isolation Project modeling
  results evaluates future modeling needs & recommends actions to strengthen program.

  BELL.M.J. High Lavel Waste Licensing Management Branch. 00384.

  83/03/31.

  BROWNING.R.E. Division of Waste Management. 1p.
- --8307220140 "Nonisothermal Flow Modeling of Hanford Site, GORDON, M. , WEBER, M. Division of Waste Management. OC 83/03/31. 114pp. 19713:201.
- B307220139 Forwards NRC FR notices of availability of NRC dreft analysis of DDE site characterization rept for Basalt Waste Isolation Project (NUREO-0760).
  BROWNING.R. E. Division of Waste Management. 00412. B3/04/18, MORGAN.R. L. Energy, Dept. of. 1p. 17699:053.
- 8307220144 Forwards comments from Basalt Waste Isolation Project geology & geologic stability workshop on 830411-15 in Richland, WA.

  GALSTERR, W. Army, Dept. of, Corps of Engineers. 00474. 83/06/06.

  NRC No Detailed Affiliation Given. Bpp. 19713:315.
- 8307220146 Forwards digest of all correspondence & interfaces done by NRC Div of Waste Mgt w/Yakima Indian Nation.per telcon.W/o BROWNING, R. E. Division of Waste Management. 00488. 83/04/18. HANRAHAN, E. Energy, Dept. of. 1p. 19679:054.

- 8307220152 Summarizes 830316 telcon re questions on RRL-2 drillhole rept. NRC mud loss reported within dense interior of untanum formation.

  OREEVES, J. T., JUSTUS, P.S.

  Branch. 00426. 83/04/29.

  Branch. 1p. 19699:055.
- 8307220154 Forwards first group of documents for Project WM-10 file for Basalt Waste Isolation Project on Hanford Reservation. Bocuments include all correspondence dtd prior to 821112. W/o documents. STILL.N Division of Haste Management. 00370. 83/04/04. ROBERTS, D. Richland, WA. 1p. 19713:325.
- 8307220157 Forwards comments on figures in site characterization rept, 30722013/ Forwards Commence on Figure 2. Chapter 3. WRIOHT, R. J. NRC - No Detailed Affiliation Given. 83/06/27. LARUE, J. Energy, Dept. of. 3pp. 19679:056.
- B307220163 Agenda for NRC 830609-11 visit w/DDE, Golder Assoc, Univ of Idaho, Rockwell, ONI & Sandia to Basalt Waste Isolation Project in Richland, MA. Viewgraphs encl. A NRC No Detailed Affiliation Given. 00391. 83/06/11. NRC No Detailed Affiliation Given. 164pp. 17697:059.
- 8307220164 Trip rept of 880323 discussions w/USGS & Golder Assoc in Tacoma & Seattle, MA re interpretation of Rockwell Hanford Operations principal borehole rapt for RRL-2 & plans for exploratory shaft, head measurements & large-scale tests.

  LOGSDON, M. High Level Waste Technical Development Branch. 00422.

  83/04/29, JUSTUS, P. S. High Level Waste Technical Development Branch. 4pp. 19713: 329.
- 8307220169 Requests info on interpretation of RRL-2 drilling results, including basis for assuming 3.773-3.783-ft interval of RRL-2 is dense basalt iones of mud loss in RRL-2 & amount & rates of mud loss estimated for exploratory shaft. WRIGHT, R. J. High Level Waste Technical Development Branch. 00392. 83704705. QLSON, D. L. Energy, Dept. of. 19. 19699:223.
- 8307220171 Notification of 830524-25 meetings between branch hydrogeology teams; Quider Assoc & Williams & Assoc in Silver Bering: MD to prepare for next hydrogeology workshop on LOGEDON, M. J. High Level Waste Technical Development Branch. 83/03/18. MILLER: H. J. High Level Waste Tachnical Development Branch. site. M.J. High Level Waste Technical Development Branch. | MILLER,H.J. High Level Waste Technical Development | 3pp. 19713:333.
- B307220173 Forwards QA chapter from NRC draft site characterization analysis of Basalt Haste Isolation Project site characterization rept. Issue will be discussed at 830512 meeting in Garmantown, MD. LONGO, T.P. Energy, Dept. of. 8-10. 83/04/28. OREEVES, J., RHODERICK, J. NRC No Detailed Affiliation Given. 7pp. 19699:224.
- 8307220177 Forwards info on Borehole RRL-2 w/missing core. Lower core loss explainable in terms of fractured ground. Upper core loss less understandable since 10 ft of core ground up or otherwise lost.

  HRIGHT.R. J. High Level Waste Technical Development Branch. 00456.
  83/05/24, KINO.J. AMAX Environmental Services, Inc. (subs. of AMAX, Inc.). 19. 19713:336.

- B3072201B1 Summary of B30322 bristing w/DOE in Washington, DC on results of NRC analysis of DOE sits characterization rept for potential high level waste repository sits at Hanford & NRC/DOE interaction w/sits characterization plan. BROWNING, R.E. Division of Waste Management. 00427. B3/05/02. Division of Waste Management. 1p. 19699:231.
- B307220185 Confirms USOS review committee availability for B30607-10 briefing at Richland, WA site. Briefing should be split into parts, including field trip, presentation of geologic a hydrologic data & discussions on specific topics. DINNIDDE, G. A. Interior, Dept. of. 00462. B3/05/26. DLBON, D. L. Energy, Dept. of. 5pp. 19713:337.
- 8307220189 Summary of 830527 mgt meeting w/DOE in Silver Spring, MD re Basalt Waste Isolation Project, including strategy of draft site cherecterization rept issue definition & resolution & the strategy of draft & procedural agreement, WRIGHT, R. J. High Level Waste Technical Development Branch. 00476. 83706/10. MILLER, H. J. High Level Waste Tachnical Development Branch. 2pp. 19699:232.
- 8307220191 Trip rept of 830411~15 DOE/NRC workshop on geology & geologic stability in Hanford, MA.
  WRIGHT, R. J. High Level Waste Technical Development Branch. O 83/06/02. MILLER, H. J. High Level Waste Technical Development Branch. 4pp. 19713:342.
- B307220196 Forwards marked-up Sections 4-6 & App A to NRC "Draft Technical Position on Hydrogeologic Testing Strategy for Basalt Waste Isolation Project Site."

  MRIGHT.R.J. High Level Waste Technical Development Branch. 00511.
  B3/07/07. OLSON.O.L. Energy, Dapt. of. 26pp. 19679:234.
- B307220198 Forwards, for consideration, proposed draft agenda for B30711 meeting on hydrologic test plans.
  WRICHT, R. J. High Level Waste Technical Development Branch. 00219.
  B3/06/27. OLSON, O. L. Energy, Dept. of. 2pp. 19713:346.
- B307220205 Trip rept of B30607-10 meetings w/Rockwell Hanford Operations, DDE & UBGB in Richland. WA re tests performed on Borehole RRL2 & hydraulic property testing program. VERMA-T.R. High Level Waste Tachnical Development Branch, ODE B3706/20. MILLER, H. J. High Level Waste Tachnical Development Branch, 9pp. 19713:348.
- B307220212 Announces intent to prepare EIS to provide environ input to decision on proposed selection & implementation of disposal strategy for certain radioactive defense wastes at Hanford sits. Notice published in B30401 FR. Press release encl. SCHREIBER, J. U. Energy, Dept. of. 00393. 83/04/05. NRC No Detailed Affiliation Given. Spp. 19499: 240.
- 8307220223 Responds to 830318 ltr stating that 26 of 189 site characterization rept refs requested in 821124 ltr not received w/830218 ltr. Encl describes current status of 26 documents.

  OLSON, D. L. Energy, Dept. of. 00417. 83/04/27. WRIGHT,R. J. High Layel Waste Technical Development Branch. 3pp. 19699:269.
- 8307220227 Transmits Basalt Waste Isolation Project info re exploratory shaft const & sealing.

  DLSON.D.L. Energy: Dept. of. 00423. 83/04/27. WRIGHT.R.J. High Level Waste Technical Development Branch. 104pp. 17697:272.
- 8307220230 Summarizes all hydrologic test data & hydraulic property values available from testing completed at Boreholes DC-4/5.

  OLSON.O.L. Energy, Dept. of. 00433. 83/05/11. WRIGHT,R.J. High Level Waste Technical Development Branch. 2pp. 19700:014.
- B307200232 Clarifies portion of Besalt Waste Isolation Project site characterization rept re Phase I & II testing, Followen testing will occur only at selected repository sites. OLSON, O. L. Energy, Dept. of. O0404. B3/05/11. WRIGHT, R. J. High Level Waste Technical Development Branch. 2pp. 19700:016.
- 8307220236 Forwards info re interpretation of RRL-2 drilling results OLSON.O.L. Energy, Dept. of. 00447. B3/05/20. WRIGHT.R.J. Hig Level Haste Technical Development Branch. 10pp. 19700:018.
- ---BG07220240 SD-BWI-TI-107

  "Preliminary Results of Hydrologic Testing Umtanum Basalt Entablature at Borehole RRL-2 (3,762 3,805 ft)."

  STRAIT, S. R., SPANE, F. A., LEDOERWOOD, R. K. Rockwell International Corp. 00447
- 8307220239 Discusses public availability of NRC & DDE documents referenced in DDE site characterization rept. SCATTOLINILL B. Public Document Branch. 00087. B2/11/18. MAUSSHARDT, D. B. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 19712: 287.

- 8307220244 Forwards Basalt Waste Isolation Project 830519 briefing to RL Morgan & MJ Lawrence testimony at EPA 830512 hearing re DOE efforts to provide facilities for storage & disposal of commercial radwaste, CORRHAM, E. J. Energy, Dept. of, 00445, 83/05/20, DAVIB, J. Q. Office of Nuclear Material Safety & Safeguards, Director. 10pp. 19700:065.
- --8307220248 Testimony of MJ Lawrence at EPA 830512 hearing re DOE efforts to provide facilities for storage & disposal of commercial radwaste.

  LAWRENCE, M. J. Energy, Dept. of. 00445. 83/05/12. 12pp. 19700:075.
- 8307220245 Summary of 830404 meeting re branch performance assessment strategy & resource allocations for coming yr. GORDON.M.J. High Level Waste Licensing Management Branch. 00404. 83/04/05. KNAPP.M.R. High Level Waste Licensing Management Branch. 2pp. 19713:326.
- 8307220249 Notifies of 830427 briefing on 830411-15 geology & geologic stability workshop held in Hanford.WA.
  WRIGHT,R.J. High Level Waste Technical Development Branch. 00406.
  83/04/26. High Level Waste Technical Development Branch. 1p. 19713:388.
- 8307220253 Forwards site characterization rapt Refs 81, "Lower Columbia River Environ Survey in Oregon" & 163, "West Canadian Research Publications of Geology & Related Sciences Series." W/o encl.

  OLSON,O.L. Energy, Dept. of. 00459. 83/05/26, WRICHT.R.J. High Level Maste Technical Development Branch. 1p. 19700:087.
- B307220255 Forwards response to NRC request for documents & geologic data discussed at B30411-15 meetings in Richland, WA. W/o enci. OLSON, O. L. Energy, Dept. of. 00280. 83/06/21. WRIGHT, R. J. High Level Waste Technical Development Branch. 2pp. 19700:088.
- 8307220579 Advises that five site issue analyses delayed due to late arrival of DOE testing plan draft apps & site issue analysis now in CRESS Code. Operating plan Commitments 31121C & 311221D satisfied.

  WRIGHT.R. J. High Level Waste Technical Development Branch. 00133. 82/12/06. BROWNING.R.E. Division of Waste Management. 1p. 19700:070.
- 8307220580 Forwards draft Apps D.P.G & R & draft site issue analyses re waste package site selection process & environ factors of site characterization analysis. GPS plan Commitments 311221G & 311221D completed.

  BELL:M.J. High Level Waste Technical Development Branch. 00132. BZ/12/03. MARTIN.J.B. Division of Waste Management. 372pp. 19700:091.
- 8307220693 "NRC Issues From D8CA Having Significant Impact on Basalt Haste Isolation Project." WRIGHT:R. Division of Haste Management. 00485. 83/05/25. 213pp. 19697:080.
- 8307250036 Forwards preliminary Draft 3 of Basalt Waste Isolation Project draft site characterization analysis. Sections under ray noted. Distribution & review by other branches tentatively scheduled for 830201. after changes made. WRIGHT.R. J. High Level Waste Technical Development Branch. 83/01/28. High Level Waste Technical Development Branch. 784pp 19721: 235.
- 8307250658 Trip rept of attendance at American Geophysical Union 830602 spring seminar in Baltimore.MD re flow through fractured rocks. Fundamental principles describing flow through fractures not sattled by technical experts.

  ORNSTEIN.P. M. High Level Waste Licensing Management Branch.
  B3/07/07. KNAPP.M.R. High Level Waste Licensing Management Branch.
  3pp. 19718:054.
- 8307260012 Forwards data requested on B21115 re Well DC-1, consisting of summary record of water level measurements made in deep piezometers on & near Hanford Reservation.

  MEYER, W. Interior, Dept. of, Geological Survey. 00112. B2/11/16.
  LOGBDON.M. NRC No Detailed Affiliation Given. 16pp. 19786:266.
- B307240016 Comments on site characterization rept deficiencies re compliance of waste package to NRC criteria. More details on future objectives of waste package performance needed before adequaty can be evaluated.

  DAVIB.M.S. BCHWEITZER, D. G. Brockhaven National Laboratory. 00124 B2/12/01. WICK.E. A. High Level Waste Licensing Management Branch. 50p. 19786: 282.

- 8307260022 Forwards itr rept on Basalt Waste Isolation Project, concerning problem re water migration into emplacement hole, evaporation & heat transfer condition of canister Problem should be modeled in detail to determine canister temps.

  BASTRE.C. Brookhaven National Laboratory. 00135. B2/12/07. MICK.E.A. High Level Waste Licensing Management Branch. 3pp. 19786: 287.
- B307260025 Submits informal guidelines for review & analysis of Basalt Waste Isolation Project site characterization rept. WRIGHT.R. J. High Level Waste Technical Development Branch. 00130. 82/12/03. High Level Waste Technical Development Branch. 1p. 19786:290.
- 8307260027 Confirms discussions w/R Walton requesting 1-day meeting w/Savannah River Lab personnel on 830720 or 21 to familiarize NRC w/current long-term program for high level defense waste.

  COOK.F.R. High Level Waste Licensing Management Branch. 83/07/11.

  OBRIEL, C. K. Energy, Dept. of. 1p. 19786:261.
- 8307260029 Comments on Basait Waste Isolation Project canister corrosion research plans. More detail would permit evaluation of aspects of ultimate DDE submission re mfg technology & corrosion properties. Revised research plan encl.
  MCNEIL/M.D. Waste Management Branch. 00127. B2/12/02. CODM, F.R. High Level Waste Licensing Management Branch. 20pp. 19786: 271.
- 8307240034 Reviews Chapters 8, "Climatology, Meteorology & Air Quality" & 13, "Site Issues & Plans," of site characterization rept for Bawalt Waste Isolation Project. Rept may be supplemented w/NURGO/CR-2636 info re snow & ice.

  MILLER, H. J. Earth Sciences Branch. 00126. 82/12/02.

  KORNABIEWICZ, R. High Level Waste Technical Development Branch. 2pg. 19786:311
- 8307260039 Forwards FR notice of availability of "Draft NRC Review Plan: GA Programs for Site Characterization of High Level Nuclear Waste Repositories."
  MILLER,H. J. High Level Waste Tachnical Development Branch.
  83/07/12. FELTON, J. M. Division of Rules and Records. 1p.
  19786: 228.
- --B307260046 Notice of availability of "Draft NRC Review Plan: GA Programs for Bite Characterization of High Level Nuclear Waste Repositories." MILLER.H.J. High Level Waste Technical Development Branch. 83/07/12. 3pp. 19786: 229.
- --8307260051 "Draft NRC Review Plan: GA Programs for Site Characterization of High Level Nuclear Waste Repositories."

  \* High Level Waste Technical Development Branch. 83/07/31. 27pp.
- 8307260044 Forwards DDE site characterization rept for Basalt Waske Isolation Project Comments on draft site characterization analysis (DSCA), designated NNREO-0760, requested within 14 days of delivery in Jan 1983. W/o eccl.
  BROWNING, R. E. Division of Waste Management. 00405. 82/12/02. CUNNINGHAM.R. Division of Fuel Cycle & Material Safety. 2pp. 19784-313.
- B307260097 Forwards DDE site characterization rept for Basalt Waste Isolation Project.Comments on draft site characterization analysis, designated NUREG-0960, requested within 14 days of delivery in Jan 1983. W/o encl.
  BROWNING.R.E. Division of Waste Hanagement. 00129. 82/12/02.
  ARSENAULT.F. Division of Health, Siting & Waste Management. 2pp. 19786:315.
- B30726005B Forwards FR notice of availability & "Borehole & Shaft Sealing of High Level Nuclear Waste Repositories: " NRC draft technical position.

  MILLER, H. J. High Level Waste Technical Development Branch.
  B3/06/30. FELTON, J. M. Division of Rules and Records. ip.
  19788:049.
- --8307260064 Notice of availability of "Borehole & Shaft Sealing of High Level Nuclear Waste Repositories:" NRC draft technical position. MILLER, H. J. High Level Waste Technical Development Branch. 83/06/30. 2pp. 19788:050.
- --8307260596 "Borehole & Shaft Sealing of High Level Nuclear Waste Repositories," NRC draft technical position. \* High Level Waste Technical Development Branch, 83/07/31, 32pp. 19788:052.
- B307260074 Forwards site characterization rept for Hanford site. Briefing schedule will be decided in future telcon.W/o enci. MILLER.H.J. High Level Waste Technical Development Branch. 00125. 82/12/01. TANO.R.C. ACRS - Advisory Committee on Reactor Bafeguards. 1p. 19786:318.

- 8307260078 Forwards Chapter 3 of Basalt Waste Isolation Project site characterization analysis for review re geotechnical accuracy. Redraft scheduled for B21206.
  BOYLE, R.R. High Level Waste Licensing Management Branch. 00123.
  B2/11/30 PRESTHOLT, F. T. High Level Waste Technical Development Branch. 14pp. 19786:319.
- 8307260103 Advises that early meeting re site characterization rept (ECR) would be useful, since Div of Waste Mgt position will have far-reaching effects Wo R MacDougall comments on B21113 draft SCR analysis.
  BUNTING. J. O. Licensing Process & Integration Branch. 00121. B2/11/30. BROWNING.R.E. Division of Waste Management. 1p. 19786: 333.
- 8307260109 Outlines scheme for NRC questions re DOE site characterization rept for Basalt Waste Isolation Project.W/o form for written questions.

  WRIGHTIR. J. High Level Waste Technical Development Branch. 82/11/30 High Level Waste Technical Development Branch. 2pp.
- B30726011B Forwards 28 radiological assessment repts for properties in Edgemont.SD. Concentrations of residual radioactive matls exceeded EPA stds for Ra-226 in soil of 18 properties. Categoric listing of repts encl.H/o repts. MARTIN.D.E. Low Level Waste Licensing Branch. 83/07/05. BRICH.R. South Dakota. State of. 2pp. 19786:264.
- 9307260120 Outlines instructions for site characterization analysis product submittal GRESS work request & control sheet & product summary sheet encl. ULECK, R. B. , WRIGHT, R. High Level Waste Technical Development Branch. O0120. 82/11/30. High Level Waste Technical Development Branch. 4pp. 19786: 336.
- 8307260127 Forwards 28 radiological assessment repts for properties in Edgemont.SD. Concentrations of residual radioactive matls exceeded EPA std for Re-226 in soil of 18 properties.W/o repts.

  MARTIN.D.E. Low Level Waste Licensing Branch. 83/07/05. GIEDT.J. Environmental Protection Agency. 2pp. 19786:262.
- 8307260132 Forwards marginal comments on 821118 draft site characterization analysis of Basalt Waste Isolation site screening process. Analysis conclusions do not reflect intent of 10CFR60. Recommendations listed.
  MACDOUGALL.R. Licensing Process & Integration Branch. 00118. 82/11/24. BOYLE.R.G. NRC No Detailed Affiliation Given. 15pp. 19788:340.
- 8307260141 Reviews GA chapter of site characterization rept for Basalt Maste Isolation Project, Input needed from each group re GA application to each program by 821130. GREEVES, J. High Level Waste Technical Development Branch. 00119, 82/11/24. Division of Waste Management. 1p. 19786:335.
- 8307260146 Confirms 821108 conversation re meteorologist/climatologist participation in site characterization rept review beginning 821115. Ltr rept requested by 821201. WRIGHT, R. J. High Level Waste Technical Development Branch. 00117. 82/11/23. BERATAN, L. Earth Sciences Branch. 2pp. 19786: 356.
- B307260159 Confirms conversation re J Kimball participation in Basalt Waste Isolation Project site characterization rept (BCR) review, scheduled for B21115 meeting. Deliverables, due on B21127, should consist of notes in SCR & NRC issue analysis. WRIGHT,R. J. High Level Waste Technical Development Branch. 00116. B2/11/23. JACKSON.R. E. Earth Sciences Branch. 2pp. 19786:358.
- B307260163 Requests TJ Schmitt assistance in reviewing site characterization rept (SCR) & supporting documents. Draft comments due B21203.

  OREEVES J. T. High Level Waste Technical Development Branch. 00115.
  B2/11/23. BERATAN, L. L. Division of Health, Siting & Wasta Hanagement. 2pp. 19786:360.
- 8307260171 Forwards notes of 82[117 hydrogeology meeting w/technical assistance contractors.Colder & Assoc & Williams & Assoc in Silver Spring.MD re site characterization rept distribution, revised site issue analysis & revised Chapter 4 mockup.
  LOGSDON.M. J. High Level Waste Technical Development Branch. 00147 82/11/23. JUSTUS.P.S. High Level Waste Technical Development Branch. 4pp. 19786:362.
- 8307260185 Forwards Baselt Waste Isolation Project bibliography from site characterization rept, excluding RHO documents. Revised bibliography will note availability of publications & estimated time of receipt after ordering M/o enci. PRESTMOLT, P.T. High Level Haste Technical Development Branch. 00114. B2/11/23. BOYLE, R.; COOK, R. High Level Waste Licensing Management Branch. JUSTUS, P. High Level Waste Technical Development Branch. ip. 19787:004.

- B307260192 Comments on draft site characterization analysis of Basalt Waste Isolation Project site selection process, concentrating on issues to be addressed due to elements included per 10CFR60, 1(ia).

  MACDDUOALLIR. Licensing Process & Integration Branch. 00113, B2/11/18. BOYLE, R. Q. NRC No Detailed Affiliation Given. 4pp. 19787:005.
- B307260199 Forwards drafts of listed draft site characterization analysis apps. W/o encl.

  WRIGHT.R.J. High Level Waste Technical Development Branch. 00147.
  B2/12/21. BELL.M.J. High Level Waste Licensing Management Branch.
  BUNTING.J.O. Licensing Process & Integration Branch. MILLER.H.J.
  High Level Waste Technical Development Branch. 1p. 19787:009.
- 8307260204 Responds to 821217 Itr.communiting on Chapter G, "Site Selection Process" & Chapter 9, "Institutional & Environ Factors," of site characterization analysis. Comments received on drafts encl. Drafts should be ready by 821222.
  BOYLE:R. High Level Waste Licensing Management Branch. 00144.
  82/12/17. MACDOUGALL.R. D. Licensing Process & Integration Branch. 20p. 19787:010.
- --8307260R09 Forwards std outline for chapters of draft site characterization analysis.

  WRIGHT, R.J. High Level Waste Technical Development Branch. 00144. 82/12/15. High Level Waste Technical Development Branch. 97pp. 19787:012.
- 8307260215 Comments on Draft 1 of site characterization analysis re siting & environ. MACDOUGALL,R. Licensing Process & Integration Branch. 00143. 82/12/17. BOYLE,R. NRC — No Detailed Affiliation Given. 5pp. 19787:109.
- 8307240222 Informs that 821215 request to revise draft site characterization analysis (SCA) Chapter B re waste package impractical. Encl proposed outline unsatisfactory. Items 1 & 2 redundant of SCA.

  COOK, F. R. High Level Waste Licensing Management Brench. 00140. 82/12/15. WRIGHT, R. J. High Level Waste Technical Development Branch. 3pp. 19787:114.
- 8307260226 Comments on Draft 1 of site characterization analysis on Basalt Waste Isolation Project rept. Checklist of 10CFR60. 11 requirements, to assist in preparation of Draft 2. encl. BUNTING, J. D. Licensing Process & Integration Branch. 00142. 82/12/15. BELLIM, J. BOYLE, R. High Level Waste Licensing Management Branch. HILLER, H. J. High Level Waste Technical Development Branch. 5pp. 19787:117.
- 8307260231 Forwards std outline for draft site characterization analysis technical chapters. Each chapter in Draft 2 should conform w/std outline.except listed chapters. WRIGHT.R.J. High Level Waste Technical Development Branch. 00141. 19787:122.
- B307260237 Forwards first draft set of chapters for Basalt Waste Isolation Project i site characterization analysis (SGA). Draft SCA subj to future revs. W/o encl. HRIOHT.R. J. High Level Waste Technical Devalopment Brench. 00138. 82/12/10. BROWNING.R.E. Division of Waste Management. ip. 19787:124.
- 8307260244 Designates E Zurfluch as research member of geologic stability team for review of Hanford site characterization rept.

  WRIGHT, R. J. High Level Waste Technical Development Branch. 00139.
  82/12/10. BERATAN, L. Earth Sciences Branch. 1p. 19787:125.
- 8307260250 Forwards Draft 1 of site characterization analysis, consisting of Chapters 1 through 11. Executive summary, Director's opinion & Chapter 12 will be incorporated in Draft 3 & apps in Draft 4. Draft 2 due by 821220.

  MRIGHT.R.U. High Level Waste Technical Development Branch. 00137.
  82/12/09. BELL.M.J. High Level Waste Licensing Management Branch. BUNTING.J.O. Licensing Process & Integration Branch. MILLER.H.J. High Level Waste Technical Development Branch. 99pp. 19787:126.
- 9307240255 Forwards draft of Basalt Waste Isolation Project site characterization rept App W. "Release Rate." for review & technical comments. Inconsistencies in apps unacceptable. OREEVES.U. T. High Level Waste Technical Davelopment Branch. 00136 82/12/08. High Level Waste Technical Davelopment Branch. 26pp.
- 8307260261 Reviews Chapter 18 rs GA of sits characterization rept for Basalt Wasta Isolation Project, Working meeting w/DDE & operating contractor personnel re review plan acceptance criteria vs Chapter 18 & identified deficiencies advisable. HAABS, W. P. Guality Assurance Branch. 00134. 82/12/07. MILLER, H. J. High Level Waste Tschnical Development Branch. Spp. 19787:251.

- 8307260265 Reviews Basalt Waste Isolation Project site characterization rept Chapter 6 re solubility constraints on transurants release to environ.

  MCNEILM B. Waste Management Branch. 00154. 83/01/10. CDDK, R. High Level Waste Licensing Management Branch. 2pp. 19787:256.
- B307260272 Discusses review of Basalt Waste Isolation Project GA technical procedures. "Draft NRC Review Plan of GA Programs for High Level Waste Repository Bite Investigations" encl. Comments on listed technical procedures requested. GREEVEB, J. T. High Level Waste Technical Development Branch. OD: B3701/10. High Level Waste Technical Development Branch. 4pp. 00153 83/01/10. 19787: 258.
- --8307260431 "Draft NRC Review Plan of GA Programs for High Level Waste Repository Bite Investigations." + NRC No Detailed Affiliation Given. 00153. 83/01/10. 23pp. 19787:262.
- 8307260276 Comments on Draft 2 of Basalt Waste Isolation Project site characterization analysis (SCA).per 830103 request Proposed wording for SCA conclusions encl.
  COOM,F.R. High Level Waste Licensing Management Branch. 00152.
  83/01/05. WRIGHT.R.J. High Level Waste Technical Development Branch. 3pp. 19787:285.
- 8307240283 Comments on Draft 2 of Basalt Waste Isolation Project site characterization analysis. Conceptual design does not include barrier reliability design criteria in multi-barrier engineered sys. Proposed wording for SGA conclusions encl. CODM, F.R. High Level Waste Licensing Management Branch. 00150. 82/12/28. WRIGHT.R. J. High Level Waste Tachnical Development Branch. 3pp. 19783:312.
- 8307240289 Forwards analysis of site characterization rept treatment of groundwater hydrology, emphasizing past efforts & future plans for performance assessment of geologic medium. GORDON.M.J. High Level Waste Licensing Management Branch. GOI48. 82/12/22. KNAPP.M.R. High Level Waste Licensing Management Branch: 17pp. 19787: 288.
- B307260295 Forwards comments on Basalt Waste Isolation Project site characterization rept, restricted to technical aspects of Chapter 4 re geoengineering & Chapter 10 re design. Simple elastic analysis inapplicable to rock mass behavior.

  SCHMITT.T.J. Earth Sciences Branch. 00145. 82/12/21.

  NATARAJA.M.S. High Level Waste Technical Development Branch. 5pp. 19787:305.
- 8307270066 Designates responsibility for placing in LPDR each listed ref of draft site characterization rept not presently obtainable in LPDR. Response requested by 830516. List of refs encl. WRIGHT,R.J. High Level Waste Technical Development Branch. 00451. 83/05/06. BOYLE,R., CODK.R., GREEVES,J. High Level Waste Technical Development Branch. 15pp. 17811:032.
- 8307270133 Forwards radiological assessment repts for 18 Edgemont vicinity properties designated for remedial action, W/o encis. COFFMAN, F.E. Energy, Dept. of. NE-24. 83/07/13. ROMATONSKI, R. G. Energy, Dept. of. 2pp. 1981: 134.
- 8307270142 Provides response to NRC 830126 questions on Basalt Waste Isolation Project sits characterization rept (SCR-9). Dialogue to determine most defensible means of extrapolating short-term matts initiated. snor-term matis initiated. CLSON.O.L. Energy, Dept. of. 00241. B3/02/17. WRIGHT,R.J. High Level Waste Technical Development Branch. 4pp. 19807:316.
- 830727014B Responds to NRC 830111 request for clarification of Basalt Waste Isolation Project (BWIP) site characterization rept Organization chart of BWIP mgt encl. OLSON.O.L. Energy, Dept. of. 0023B. 83/02/01. WRIGHT,R J. High Level Waste Technical Development Branch. App. 19807:320.
- 8307270152 Responds to NRC 821228 request for clarification of Basalt Waste Isolation Project site characterization rept (SCR~6) re-borehole drilling. OLSON.O.L. Energy. Dapt. of. 00234. 83/01/21. WRIGHT.R.J. High Lavel Waste Technical Development Branch. 2pp. 19807:326.
- 8307270159 Responds to NRC 821214 request for clarification of Dasalt Heste Isolation Project site characterization rept (SCR-3) re high temp kd measurement.

  OL80N,0.L. Energy, Dept. of. 00232. 83/01/18. WRIGHT,R.J. High Level Waste Technical Development Branch. 2pp. 19807:328. 2pp.

- 8307270166 Responds to NRC 821222 request for clarification of Basalt Waste Isolation Project site characterization rept (SCR-5) re results in Table 4-11. "Summary of In Situ Stress Data by Hydro Frac Method."

  OLSON, O. L. Energy, Dept. of. 00233. 83/01/18. WRIGHT, R. J. High Level Waste Technical Development Branch 1p. 19807:330.
- 8307270184 Responds to NRC 821203 questions on Basalt Waste Isolation Project site characterization rept (SCR-1) re model utilized in performance assessment. OLSON.O.L. Energy, Dept. of 00226. 82/12/22. WRIGHT.R.J. High Level Waste Technical Development Branch. 2pp. 19807:331.
- B307270190 Summary of 830613 meeting w/Marshall-Wythe Law School in Silver Spring.MD re regulator policies for V recovery. KALMAN.K. Low Level Waste Licensing Branch. 83/07/01. HIGGINBOTHAM.L. Low Level Waste Licensing Branch. 2pp. 19811:13
- 8307270194 Responds to NRC 821207 questions on Basalt Waste Isolation Project site characterization rept (SCR-2) re two-dimensional modeling using PORFLO. OLSON.O.L. Energy, Dept. of. 00227. 82/12/22. WRIGHT, R. J. High Level Waste Technical Development Branch. 3pp. 17807:333.
- 8307270198 Forwards "Dorehole Assessment Needs Plan." per DQE request. W/O encl. 1 BARTLETT.J.W. The Analytic Sciences Corp. 00223. 82/12/10. WRIGHT.R.J. High Level Waste Technical Development Branch. 1p. 19807:336.
- B307270202 Requests hydraulic test data reported in Basalt Waste Isolation Project site characterization rept,Figure 5-26.
  Data may be available at upcoming hydrology workshop in State of MA & should include hydrogeologic info.
  GORDON,M.J. High Level Waste Technical Development Branch. OO514.
  B3/07/07. WRIGHT,R.J. High Level Waste Licensing Management Branch.
  ip. 19811:159.
- B307270204 Forwards Basalt Waste Isolation Project site characterization rept refs requested in NRC B21124 ltr.W/o encis. OLSON.O.L. Energy, Dept. of. 00221. B2/12/08. WRIGHT.R.J. High Level Waste Technical Development Branch. 2pp 19807:337.
- B30727020B Forwards site characterization rept refs requested in NRC B21124 ltr.W/o ancls.
  OLSON, O.L. Energy, Dept. of. 00216 B2/11/30. WRIGHT, R.J. High Level Waste Technical Development Branch 2pp. 19807:339.
- 8307270214 Forwards "Highlights & Preliminary Results of Near Surface Test Facility Overcoring Stress Measurement Study" & "Geomechanics Logging Data for Candidate Repository Horizons in Borehole...," per 821005 & 66 requests W/o encls. CL80N.O.L. Energy, Dept. of. 00214. 82/11/23. WRIGHT.R.J. High Level Waste Technical Development Branch. 1p. 19807.34t.
- B30727021B Forwards description of 189 site characteristic rept refs requested in 821124 ltr. Documents will be sent under separate cover. OLSON,O C. Energy, Dept. of. 00243. B3/02/18. HRIGHT.R.J. High Level Waste Technical Development Branch. 19pp. 19807:342.
- B307270222 Trip regt of attendance at Second Natl Meeting on Low Level Radwaste w/Southern States Energy Board.Natl Governors Assoc & DDE. Summary of post-1986 waste options workshop included. JACKSON.K.C. Low Level Waste Licensing Branch. B3/07/06. HIGOINBOTHAM.L. Low Level Waste Licensing Branch. 3pp. 19811:160.
- 8307270223 Forwards response to 830113 request for addl info on 1072/0223 Forwards response to 830113 request for add1 info on Basalt Waste Isolation Project exploratory shaft const & sealing program. Info confirms mat1 discussed at 821004-05 workshop on repository design.

  ANTIONEN, J. H. Energy, Dept of. 00244. B3/02/23 MILLER, H. J. High Lavel Waste Technical Development Branch. 4pp. 19807:361.
- --B307270230 "GA Level 11 Const Spec for Shaft Drilling & Rig Svcs, Basalt Waste Isolation Project Exploratory Shaft Project B-314." \* Kaiser Engineers. \* Parsons, Brinkerhoff, Guada & Douglas, Inc. 00244. 83/02/03. 22pp. 19808:003.
- --8307270234 "Basalt Waste Isolation Project ES-1 Sealing Considerations." \* Daw Chemical Co. 00244. 83/02/09. 220pp. 19808:025.
- --B307270240 NM79-137 8072/0240 NM79-137
  "Preliminary Evaluation of Rock Mass Disturbance Resulting From Shaft, Tunnel or Borehole Excavation."
  KELSALL,P.C., CASE,J.B., CHABANNES,C.R. Battolle Memorial Institute. 00244. B2/07/31. 331pp. 19808:245.

- B307270248 Requests copy of NUREO/CR-2783, "Selected Hydrologic & Geochemical Issues in Site Characterization for Nuclear Maste Disgosal; Flood Basalts at Hanford Reservation," FREI.M. H. Energy Dept. of. 00321. 83/03/14. BROWNING, R. E. Division of Maste Management. Ip. 17809: 216.
- B307270253 Forwards response to NRC 830217 request for clarification of Basalt Waste Isolation Project site characterization rept (SCR-13).

  OLSON, O. L. Energy, Dept. of. 00378. 83/04/01. WRIGHT,R. J. High Level Waste Technical Development Branch. 22pp. 19809:217.
- 8307270257 Responds to NRC 830128 request for clarification of Basalt Waste Isolation Project site characterization rept (8CR-10) regroundwater composition.

  OLSON, O. L. Energy, Dept. of. 00376, 83/03/29, WRIGHT, R. J. High Level Waste Technical Development Branch. 2pp. 19809:239.
- B307270262 Responds to NRC B30214 request for clarification of Basalt Waste Isolation Project site characterization rept (SCR-12) re water sample analyses.

  OLSON, O. E. Energy, Dept. of, 00318, B3/03/22, WRIGHT, R. J. High Level Waste Technical Development Branch. 2pp. 19809: 241.
- B307270265 Responds to NRC questions on core & drilling fluid losses, per B30316 request.
  GLSON.O. L. Energy, Dept. of. 00325. B3/03/18. WRIGHT,R.J. High Level Waste Technical Development Branch. 4pp. 19809: 243.
- 8307270270 Forwards Figures 3-4.3-29.3-52 & 4-16 from site characterization rept.per 830307 request.W/o encl. OLSON.O.L. Energy, Dept. of. 00324. 83/03/21. WRIGHT,R.J. High Level Waste Technical Development Branch. 1p. 19809:247.
- 8307270274 Forwards "Draft Environ Assessment for Characterization of Hanford Site Pursuant to Nuclear Waste Policy Act of 1982 (PL 97-425)." Public meeting will be held on 830325 to notify site residents.

  OLSDN.G.L. Energy, Dept. of. 00319. 83/03/15. MILLER,H.J. High Lavel Waste Technical Development Branch. ip. 19809:248.
- 8307270284 Forwards shift rapt of operations & summary geologic logs for Borehole RRL-6, inadvertently omitted from 830318 transmittal W/o encl.
- GLEON.O.L. Energy Dept. of. 00395. 83/04/04. WRIGHT.R Level Waste Technical Development Branch. 1p. 19810:073. WRIGHT R. J. High
- 830727029: Forwards Rev 1 to Basalt Waste Isolation Project GA program & Rev 2 to Morrison-Knudsen Co.Inc GA program for project, per 830113 request for info re exploratory shaft const & sealing program OLSON, O.L. Ene
- sealing program. OLSON,O.L. Energy, Dept. of. 00373. 83/04/01. WRIGHT,R.J. High Level Haste Technical Development Branch. 22pp. 19810:074.
- --8307270296 Rev 1 to GA program plan for Basalt Waste Isolation Project. NICOL.M., HAMMOND,R.D., DEJU,R.A. Rockwell International Corp. 00373. 83/03/31. 57pp. 19810:076.
- --8307270300 GA program for Basalt Waste Isolation Project Hanford site. MULCHAM. R. D., LARVIE,F , SHALL,W. D. Morrison-Knudsen Co., Inc. 82/12/16. 82pp. 19810:155.
- 830/270309 Forwards Chapter 4 of DSCA re geology & apps.per agreement ROYATOGUE, B. Waller Commission of the Commissio
- 8307270307 Requests clarification of Basalt Waste Isolation Project Site characterization rept to LATA/Intra document. HRIGHT.R.J. High Level Waste Technical Development Branch. 00340. 83/03/17. SQUIRES.D. Rnergy, Dept. of. Ip. 19810:238.
- 8307270309 Requests clarification of Basalt Waste Isolation Project site characterization rept to format guide for PORFLO & input used in modeling effort.

  MRIGHT,R.J. High Level Waste Technical Development Branch. 00240. 83/02/17. SQUIRES, D. Energy, Dept. of. 2pp. 17810: 239.
- 8307270314 Requests clarification of Basalt Waste Isolation Project site characterization rept re water sample analyses. HRIGHT, R. J. High Level Waste Technical Development Branch. 00239. 83/02/14. SQUIRES, D. Energy, Dept. of. 1p. 19810:241.
- B307270315 Requests clarification of Basalt Waste Isolation Project site characterization rept re apparent inconsistencies in data provided in Table 5-53, Table II & Table 2. 
  MRIGHT,R. J. High Level Waste Technical Development Branch. 00237. 
  B3/01/28. SGUIRES, D. Energy, Dept. of. Ip. 19810:242.

- 8307270321 Submits questions on Basalt Waste Isolation Project site characterization rept re NWTS-34, "Program Plan for Development & Testing of NWTS Waste Package Matls." WRIGHT.R.J. High Level Waste Technical Development Branch. 00235. 83/01/26. SQUIRES.D. Energy, Dapt. of. 1p. 19810:243.
- 8307270336 Requests clarification of Basalt Waste Isolation Project site characterization rept re studies cited in Table 12-13 on backfill installation. WRIOHT.R.J. High Level Waste Technical Development Branch. 00228 82
- 8307270341 Requests clarification of Basalt Waste Isolation Project site characterization rept re results provided in Table 4-11 on Hydro Fracture method.

  WRIGHT,R.J. High Level Waste Technical Development Branch. 00225, 82/12/22. SQUIRES, D. Energy, Dept. of. 1p. 19810:246.
- B307270347 Requests clarification of Baselt Haste Isolation Project site characterization nept re presquilibration process used in high temp Kd measurement.

  HRIGHT,R.J. High Level Waste Technical Development Branch. ODR
- B307270353 Confirms telephone request Documents transmitted on 821206 not received.

  WRIGHT, R. J. High Level Waste Technical Development Branch. 00222, 82/12/07. SQUIRES, D. Energy, Dept. of. ip. 17810:248.
- 8307270387 Requests clarification of Basalt Waste Isolation Project site characterization rept re PORFLO Code & model. WRIGHT.R.J. High Level Waste Technical Development Branch. 00220. 82/12/07. SQUIRES.D. Energy, Dept. of. 1p. 17810:247.
- 8307270362 Expresses appreciation for assistance in providing ACRB w/Basalt Wasto Isolation Project site characterization rept. WRIOHT.R. J. High Level Waste Technical Development Branch. 00236. 83/01/28. SQUIRES.D. Energy. Dept. of. 1p. 19810:250.
- 8307270368 Provides status of documents discussed in Wright 830318 ltr. BTKLL:N. Division of Waste Management. 00401. 83/03/25. Division of Waste Management. 2pp. 19810: 256.
- 8307270371 Ack receipt of 830218 ltr forwarding portion of 189 refs requested on 821124 Encl [dentifies 26 documents not received. WRIGHT/R. J. High Level Waste Technical Development Branch. 0033:
  - . High Level Waste Technical Development Branch. 00331. OLSON.O.L. Energy, Dept. of. 19pp. 19810:258.
- 8307270397 Comments on Rev O to SD-BMI-TP-007, "Test Plan for Exploratory Shaft Phase I & Phase II." Plan requires substantial upgrading to provide reasonable assurance that testing meets stated objectives.

  ROBERTBON, J. B. Division of Waste Management. 00242, 83/02/17. OLSDN, O. L. Energy, Dept. of, 15pp. 17810:273.
- 8307270403 Forwards ltr from R Jim to NRC requesting info on site characterization activities at Basalt Waste Isolation Project & NRC 630110 response. W/o encl. WRIGHT.R.J. High Level Waste Technical Development Branch. 00231. 83/01/14. OLSON.O.L. Energy, Dept. of. 1p. 17810:308.
- 8307270408 Forwards add1 info considered necessary in area of exploratory shaft const & sealing above mat1 included in 821112 site characterization rapt.

  High Level Maste Technical Development Branch. 00230. 83/01/13. ANTIONEN.J.H. Energy, Dept. of. 7pp. 19810;309.
- --8307270410 "Const Manager/Const Contractor for Basalt Waste Isolation Project:" review of DOE RFP, ROBERDS, H. J. Golder Associates, NRC-02-81-037, 82/10/06, HARTUNG, L. High Level Waste Technical Development Branch, 7pp, 19810:316.
- --8307270412 Draft rept in response to request for review of document, "Const Manager/Const Contractor for Basalt Waste Isolation Project."
  RAJARAM, V. Engineers International, Inc. NRC-02-82-030.
  82/12/09. SEAMANS, T. High Level Waste Technical Development Branch. 5pp. 17810:326.
- --8307270418 Forwards trip rept of 821004-07 Visit to Richland, WA re Basalt Waste Isolation Project design workshop. RAJARAM.V. Engineers International, Inc. 82/10/20. BEAMANS.T. High Level Waste Technical Development Branch. 5pp. 19810:331.
- ---8307270420 Review of 821004-07 workshop on repository design in Richland, MA: per Task 6.Project 18. OATES, R. H. Golder Associates. NRC-02-81-037. 82/10/25. HARTUNG: L. High Level Waste Technical Development Branch, 9;

- 8307270423 Forwards list of non-NRC addressees sent Basalt Waste Isolation Project site characterization rept.M/o encl. MRIOHT.R.J. High Level Waste Technical Development Branch. 00217. 82/12/03. SQUIRES.D.J. Energy, Dapt. of. 1p. 19810:345.
- 8307270426 Submits questions on Basalt Waste Isolation Project site characterization rept. WRIOHT.R.J. High Level Waste Technical Development Branch. 00218. 82/12/03. SGUIRES.D. Energy, Dept. of. 1p. 19810:346.
- 8307270442 Requests DDE assistance in obtaining certain critical documents essential to site characterization rept review. MRIOHTR. J. High Level Waste Technical Development Branch. 00215. 82/11/24. DLSDN,O.L. Energy, Dept. of. 3pp. 19810:348.
- 8307270444 Discusses site characterization rept Section 17, 2, 1 re adding the sting.
  WRIGHT.R.J. High Level Waste Technical Development Branch. 00387, 83/03/30, SQUIRES, D. Energy, Dept. of. 1p. 17810; 351.
- 8307270446 Forwards DDE statement & Yakima Indian Nation comments re 830325 public hearing on proposed nomination of Basalt Waste Isolation Project for site characterization. W/o comments.
  WRIGHT.R.J. High Level Waste Technical Development Branch. 00389.
  83/04/01. BROWNING.R.E. Division of Waste Management. BELL.M.J. High Level Waste Licensing Management Branch. BUNTING.J. O. Licensing Process & Integration Branch. 11pp. 19810:352.
- 8307270448 Requests summary of all hydraulic test data, including hydraulic heads, for Boreholes DC-4/5 for clarification of Basalt Waste Isolation Project site characterization rept. HRIGHT.R.J. High Level Waste Technical Development Branch. 0038683/04/01. SGUIRES.D. Energy, Dept. of. ip. 17811:001.
- B307270456 Requests advice on NRC initial plans for tribal liaison re NRC review of DDE plans & activities to characterize site for possible high level waste repository on Hanford Reservation near Richland WA.
  MARTIN, J. B. Division of Waste Management. 00301. 82/11/24.
  SPEAKS. Interior. Dept. of, Bureau of Indian Affairs. 3pp. 19807:136.
- 8307270459 Forwards add1 set of matls sent on 821116 but not received re NRC review of DDE site characterization rept for candidate site for high level radwaste repository on Hanford Reservation. W/o encl.
  BUNTING J. D. Licensing Process & Integration Branch. 00303.
  82/12/17. MENINICK. J. Yakima Indian Nation. 2pp. 19807:139.
- 8307270460 Responds to 821123 ltr ra Hanford Reservation questions on DDE efforts to investigate other basalt deposits. NRC has not concluded that basalt under Hanford is better than basalts lying elsewhere in same formation.

  BUNTING J.O. Licensing Process & Integration Branch. 00304.

  83/01/10. JIM.R. Yakima Indian Nation. 6pp. 19807:141.
- 8307270463 Ack receipt of 830316 ltr re Bureau of Indian Affairs work identifying Indian tribes affected by Nuclear Waste Policy Act of 1982 & appropriate contacts.

  BROWNING.R.E. Division of Waste Management. 00416. 83/03/29. MILLS,S. Interior. Dept. of, Bureau of Indian Affairs. 1p. 19807:153.
- 8307270467 Discusses Yakima Indian Nation interaction w/NRC re Basalt Waste Isolation Project. Meeting being arranged to obtain Nation views on appropriate changes to 10CFR60 re NRC/Nation interactions & proposal to participate in reviews. DAVISI.J. G. Office of Nuclear Material Safety & Safeguards, Director. 00464. 83/04/14. MENINICK, J. Yakima Indian Nation. 2pp. 17807; 154.
- 8307270470 Statement of R Jim at 830415 task force advisory meeting. Expresses concern about DDE failure to consult Yakima Indian Nation about guidelines. JIM.R. Yakima Indian Nation. 00446. 83/04/15. 13pp. 19807:156.
- 8307270472 Forwards NRC response to 830304 FR notice re issues to be included in environ assessment supporting nomination of Basalt Waste Isolation Project site as potentially acceptable repository site. W/o encl. BUNTING. J. O. Licensing Process & Integration Branch. 00440. 83/05/12. JIM,R. Yakima Indian Nation. 1p. 19807;169.
- 8307270474 Responds to 830322 ltr requesting assistance in delineating areas of technical expertise useful in independently participating & consulting w/DDE on Basalt Waste Isolation Project.
  HILLER.H.J. High Level Waste Technical Development Branch. 00463.
  B3/03/27. SAMPSON.M.R. Yakima Indian Nation. 3pp. 19807:170.

- 8307270475 Forwards NRC comments on issues to be addressed in DDE planned DES on disposal of certain defense radwastes stored at Hanford site. W/o encl.
  BUNTING.J.O. Licensing Process & Integration Branch. 00447
  B3/09/27. JIM.R. Yakima Indian Nation. 1p. 19807-173.
- 8307270476 Forwards EIA for renewal of SNM disposal license at Hanford low level waste disposal facility & Amend 3. Amend 3 amended & reissued license. W/o encl. HAWKINS.E.F. Low Level Waste Licensing Branch. 83/04/03. HOVI5.J.B. Hovis. Cockrill. Weaver & Bjur. 1p. 19807:174.
- B307270479 Requests coordination of technical & tribal matters w/Environ Svts Staff for identification of interested Indian tribes re DOE potentially acceptable sites for nuclear waste repositories.

  MILLS,S. L. Interior, Dept. of, Bureau of Indian Affairs. 00377
  B3/03/16. BROWNING,R.E. Division of Waste Management. 4pp. 19807:175.
- B307270480 Forwards Tribal Council Resolution T-45-83 to insure Yakima Indian Nation participation as affected tribe under 100FR60. MENINICK.J. Yakima Indian Nation. 00305. B3/02/16. Defice of Nuclear Material Safety & Safeguards.Director. 4pp. 19807:179.
- 8307270481 Concurs w/list of six native American groups w/interest in Hanford site.Columbia River Inter-Tribal Fish Commission represents Yakima. Harm Springs, Nez. Perce & Umatilla Tribes. BDWLER.W.G. Interior, Dept. of Bureau of Indian Affairs. 00302. 82/12/09. MARTIN, J. B. Division of Haste Management. 3pp. 19807:183.
- 8307270482 Presents questions from 821116 meeting to DOE Basalt Waste Isolation Project & Hanford Reservation site. JIM.R. Yakima Indian Nation. 00300. 82/11/23. BUNTING, J. NRC -No Detailed Affiliation Olven. 2pp. 19807:186.
- 8307270483 Forwards comments on DDE/RL-82-3, "Site Characterization Rept for Basalt Waste Isolation Project." Rept fails mission. Many conclusions drawn not justifiable w/limited existing data. RUBERTSON.J. B. Interior, Dept. of, Geological Survey. 00429. 83/05/06. DLSON.Q.L. Energy, Dept. of. 62pp. 19807:188.
- 8307280025 Submits list of individuals named to negotiating team to negotiate consultation & cooperation agreement between State of MA & DDE.
  MOGS, D. W., GOULD, S. E. Washington, State of. 00513. 83/04/30.
  FREMLING, A. G. Energy, Dept. of. 1p. 19826:169.
- B307280031 Extends gratitude for useful briefings presented to task farce on B21115. LEMIS.N.D. Washington, State of. 00277. 82/11/17. MILLER.H. High Level Waste Technical Development Branch. (p. 19826:170.
- 8307280036 Confirms High Level Nuclear Waste Mgt Task Force 821220 meeting.
  LEWIS N. D. Washington, State of. 00276 82/11/17. BOYLE, B. J. , STEVENS, D. Washington, State of. GIBS, A. J. Washington, State of. Dept. of Social & Health Services. 1p. 19826:171.
- 8307280042 Forwards DDE B21206 agenda & draft work plan discussed at 821115 task force meeting. Short-term strategy to resolve Basalt Maste Isolation Project site characterization rept less controversial issues will be developed. ERLANDSON, B. G. Washington, State of. 00281. 82/12/01. MACDOUGALL.R. NRC ~ No Detailed Affiliation Given. 24pp. 19804-172
- 8307280049 Summarizes 821i15 task force meeting in Dlympia, MA regovernor rept, work plan & licensing program for Basalt Waste Isolation Project.
  LEHIS, N.D. Washington, State of. 00282. 82/12/06. BOYLE, B.J., STEVENS, D. Washington, State of. 01885, A.J. Washington, State of. Dept. of Social & Health Services. 3pp. 19826: 196.
- 8307280056 Confirms High Level Nuclear Haste Mgt Task Force 821220 meeting re Las Vegas NWTS meeting.advisory groups to task force future meeting schedules & interim work strategy.
  LEWIS, N.D. Hashington, State of, 00283, 82/12/10, BDYLE, B.J., BTEVENS, D. Washington, State of, GIBSS, A.J. Washington, State of, Dept. of Social & Health Services, 1p. 17826:179.
- 8307280058 Informs of High Level Nuclear Waste Mgt Task Force B20114 & 28 meetings & scheduled meetings on third Friday of each month thereafter until June 1982.

  LEWIB.N.D. Washington, State of. 00284. 82/12/22 BGYLE, B.J., STEVENS, D. Washington, State of. GIBBS, A.J. Washington, State of. Dept. of Social & Health Services. 2pp. 19826:200.

- 8307280067 Notifies of High Level Nuclear Waste Mgt Task Force 830128 meeting to discuss long-range work plan & analysis of Basalt Waste Isolation Project site characterization rept LEWIS.N D Washington, State of, 00286 83/01/20. BOYLE.B.J., STEVENS.D Washington, State of GIBBS.A J Washington, State of, Dept of Social & Mealth Services. Ip 19826 202
- B307280077 Concurs w/NRC response to inquiries re Golder Assoc & potential conflict of interest Issue of state contract for review of Basait Waste Isolation Project site characterization rept will be discussed at B30128 meeting, LEWIS.N D. Washington, State of, 00287, 83/01/24, MILLER,H.J. High Level Waste Licensing Management Branch. 1p. 19826:203.
- 8307280090 Submits reminder of High Level Nuclear Waste Mgt Task Force SUZEBUOYO SUBMITES TEMINDET OF HIGH LEVEL RUCLEEF WASTE NOT 1834 FULLE BROADED meeting. ERCANDSON, D. O. Washington, State of. 00290. 83/02/14. BOYLE, B. J., STEVENS, D., GIBBS, A. J. Washington, State of. 1p. 19826:207.
- 8307280097 Summary of High Level Nuclear Waste Mgt Task Force 830114 & 28 meetings re state role & consultant committee recommendations.

  LEMIS, N D Hashington, State of, 00291, 83/02/17, 80YLE, B. J., STEVENS.D Hashington, State of, 01888, A. J. Mashington, State of, Dept. of Social & Health Services. 5pp. 19826:208.
- B3072B0103 Notifies of rescheduling of High Level Nuclear Waste Mgt
  Task Force Mar meeting for 830316.
  LEMIS,N D Hashington, State of, 00292, 83/02/24, 80YLE,B.J.,
  STEVENS.D Washington, State of, GIBBS.A.J. Washington, State of,
  Dept. of Social & Health Services. Ip. 19826:213.
- B307280107 Concurs w/approach for B30325 public hearings re Basalt
  Haste Isolation Project environ assessment before
  exploratory shaft drilling restarts.
  LEWIS.N.D. Hashington. State of. 00306. B3/02/28. BDYLE.B.J.,
  STEVENS.D. Hashington. State of. G18BS.A.J. Hashington. State of,
  Dept. of Social & Health Services. 1p. 19826:214.
- 8307280113 Designates D Provost,R Lasmanis,N Kirner & J Hudson as State Agency Horting Group members. LEHIS,N.D. Mashington, State of 83/03/09. PROVOST,D., LASMANIS,R. Washington, State of. KIRNER,N. Washington, State of, Dept. of Social & Health Services. 1p. 19826:215.
- B307280119 Summary of High Level Nuclear Waste Mgt Task Force 830218 meeting re long-range work plan.

  LEMIS:N D. Hashington: State of: 00379: 83/03/15. BDYLE:B.J.: STEVENS.D. Hashington: State of: GIBBS.A.J. Washington: State of: Dept. of Social & Health Services. 5pp. 17826:216.
- B3072B0124 Requests meeting w/High Level Nuclear Waste Mgt Task Force members & NRC on B30324 to discuss preparation of site characterisation assessment for Basalt Waste Isolation Project
  Project
  ERLANDSON, B. G. Washington, State of 00317, 83/03/17, RUSSELL, K.
  NRC - No Detailed Affiliation Given. 2pp. 19826: 821.
- 8307280130 Comments on cooperative & coordinated relationships of NRC, DDE & state for safe mgt of radwastes as set forth in Subpart C of 10CFR60 regulation re geologic disposal. SPELLMAN, J. Washington, State of. 00323. 83/03/18. DIRCKS, M. J. Office of the Executive Director for Operations. 1p. 19826:223.
- 307280137 Summary of High Level Nuclear Waste Mgt Task Force 830316 meeting re advisory council structure & reporting requirements.

  LEMIS.N.D. Washington, State of 00398, 83/04/11, BOYLE.B.J., STEVENS.D. Washington, State of, GIBBS.A.J. Washington, State of, Dept. of Social & Health Services, 4pp. 19826:224. 8307280137 Summar
- 8307280145 Notifies of intent to submit comments on Baselt Waste Isolation Project site characterization rept to NRC & DOE by
- Diffice of Nuclear Material Safety & Safeguards, Director LEWIS, N.D. DAVIS, J. G.
- B307280151 Advises that correspondence re Hanford site characterization rept should be shared w/State of OR DOE. Hanford Repository Review Committee will schedule briefing.
  ATIVENIV Gregon, State of. 00418. B3/04/26. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17826: 227.
- B307280158 Summary of High Level Nuclear Waste Mgt Task Force 830415 masting re negotiation of consultant agreement, Nevada test site visit & PDR in Olympia. WA.
  LEHIS.N.D. Washington. State of. 00430. 83/04/29. 80YLE, B. J., STEVENS, D. Washington. State of. 01885.A. J. Washington. State of, Dept. of Social & Health Services. 4pp. 19826:230.

- 83072B0162 Forwards draft of proposed transmittal ltr to DDE re Golder rept & submits agenda for 830520 task force maeting. W/o ancl.
- enci. LEWIS.N.D. Washington, State of. 00442. B3/05/17. BOYLE.B.J., STEVENS.D. Washington, State of. 01885, A.J. Washington, State of, Dept. of Social & Health Services. 2pp. 19826:234.
- 8307280171 Extends gratitude for cooperation & assistance in providing info to Washington State High Level Nuclear Waste Mgt Task Force. R MacDougall & K. Russell cited for outstanding work. Responsibilities of task force transferred to Ecology Dept. LEWIS.N. D. Washington, State of. 00467. 83/05/31. BUNTING, J. D. NRC No Detailed Affiliation Given. ip. 19826:236.
- 8307280192 Forwards legislation enabling transfer of High Level Nuclear Waste Mgt Task Force responsibilities to Dept of Ecology, Gratitude for cooperation & assistance extended W/o encl. LEMIS.N.D. Washington State of, 00469, 83/05/31. MILLER.H.J. High Level Waste Technical Development Brench. 1p. 19826:237.
- 8307280197 Ack receipt of ltr re Commission response to FR notice on issues to be included in environ assessment supporting Basalt Waste Isolation Project.Legislation transferring task force responsibility to Dept of Ecology encl. LEWIS, N. D. Washington, State of. 00466. B3/05/31. BUNTING, J. C. NRC No Detailed Affiliation Given. 11pp. 17826:238.
- B307280203 Lists established meeting dates for remainder of yr & forwards AH Schilling article re high level radwaste. QDULD, S.E. Washington, State of. 00486. B3/06/20. Washing State of. 7pp. 19826:249.
- 8307280207 Notifies that 830722 meeting rescheduled for 830812 in Lacey, MA. KN Lee article, "Federalist Strategy for Nuclear Maste Mgt," encl.
  ODULD;8.E. Washington, State of. 00310. 83/06/27. Washington State of. 7pp. 17826: 236.
- 9307280216 Distribution list for Daswalt Waste Isolation Project site characterization rept. \* Energy, Dept. of. 82/11/05. 3pp. 19826:077.
- 8307280221 Informs of review process efforts & forwards FR notice of receipt of site characterization rept from DOE & procedural portion of 10CFR60 re Hanford waste site. W/o encis. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director, 00278. 82/11/22. LOHRY, M. House of Rep. 3pp. 19826:080,
- 8307280226 Forwards FR notice of receipt of DDE site characteritation rept for Basalt Waste Isolation Project.W/o encl. BUNTING.J.O. Licensing Process & Integration Brench. 00279, 82/11/23. GUESS, S. Washington, State of. 4pp. 17824:083.
- 8307280231 Forwards NUREO-0960, "Draft Site Characterization Analysis," ltr of transmittal to RL Morgan & FR notice of availability. W/o encls. DAVIS, J. G. Office of Nuclear Material Bafety & Bafeguards, Director. Office of Nuclear Material Bafety & Bafeguards.Director. 03/31. SPELLMAN.J. Washington, State of. 4pp. 1982A OBS
- 830728D235 Ack receipt of 830318 ltr re systematic exchange of info between states & DDE at each step of site characterization process. J Davis designated as leader for 10CFR60 implementation activities. DIRCKB, W.J. Office of the Executive Director for Operations. 00487. B3/04/18. SPELLMAN, J. Washington, State of. 2pp. 19826:092.
- 8307280240 Forwards response to 830304 FR notice re issues to be included in environ assessment supporting nomination of Basalt Waste Isolation Project as potentially acceptable repository, W/o encl.
  BUNITING, J. D. Licensing Process & Integration Branch. 00441.
  83/05/12. LEMIS, N. D. Washington, State of. 1p. 17826:074.
- 8307280245 Forwards comments on issues to be addressed in DOE draft EIS re disposal of certain defense radwastes stored at Hanford site.W/o encl. BUNIING.J.O. Licensing Process & Integration Branch. 00448. 83/05/27. LEWIS,N.D. Washington, State of. ip. 17826:075.
- B307280249 Responds to B30426 ltr re potential site for high level radwaste disposal at Hanford NRC wil) brief state officials on NRC role in characterization of site.

  BROWNING.R.E. Division of Waste Management. 00475. 83/06/13. GODARD, D. H. Oregon, State of. 1p. 19826:096.
- 8307280235 Trip rept of DOE 821021-22 briefing re status of site characterization activities for Hanford site. RUSSELL, C.F. Licensing Process & Integration Branch. 00444. 82/11/23. Licensing Process & Integration Branch. 4pp.

- 8307280260 Forwards D Kunihiro memo transmitting updated list of available changes in ofc for Washington legislators & host county administrators. Addl info forthcoming.
  YOUNG, F. Assistant Director for State & Licensee Relations. 00285. 83/01/12. MACDOUGALL, R. D. Licensing Process & Integration Branch. 8pp. 19826:101.
- 8307280273 Trip rept of 821114-17 briefing re NRC review of DDE characterization of Hanford site Viewgraphs encl.
  RUSSELL.C.F. Licensing Process & Integration Branch. 00443.
  B3/02/09. Licensing Process & Integration Branch. 34pp.
  19826:109.
- 9307280279 Informs of B Erlandson 830228 telcon request for briefing re-changes to 100FR60 & NRC program activities. State Participation Steering Group will meet on 830314 & briefing scheduled tentatively for either 830329 or 24.
  BUNTINO, J. Licensing Process & Integration Branch. 00341.
  83703714. BROWNING, B. Division of Haste Management. 1p.
  19826:143.
- 8307280285 Trip rept of 830419-21 trip to State of MA re 10CFR60. Bubpart C & state participation in reviews of Hanford site. Visugraphs encl. RUSSELL.C.F. Licensing Process & Integration Branch. 00453. 83705/27. Licensing Process & Integration Branch. 25pp. 19826: 144.
- 8307270331 Forwards list of items for discussion during 830720 generic licensing presentation for U mill tailings remedial action (UMTRA) sites. Discussion items will be used to draft itr of understanding reconcurrence points for UMTRA project. ARTHUR, U.J. Energy, Dept. of. 83/07/15. MARTIN, D. NRC No Detailed Affiliation Given. 14pp. 19859:103.
- 8307270347 Forwards procedural agreement between DDE & NRC re high level waste site characterization activities under Nuclear Maste Pollicy Act of 1982. DAVIB.J.O. Office of Nuclear Material Safety & Safeguards,Director. 83/04/29. MOROAN,R.L. Energy, Dept. of. 1p. 17859:105.
- --8307290349 Memorandum of understanding between NRC & DOE re guiding principles for interface during site investigation & site characterization activities.
  DAVIB.J. G. Office of Nuclear Material Safety & Safeguards. Director. MORGAN.R. L. Energy, Dept. of. 83/06/27.
- 8307290351 Forwards supplemental math re-updated listings for WASCLA.

  DEMIN, SANDAT & SCAL & draft operating manual & summary of
  macroscopic absorption cross sections.

  TUITE,P.T. Waste Management Group, Inc. 83/02/09. RDLES.G. NRC No Detailed Affiliation Given. 1p. 19858:104.
- 8307290400 Forwards draft of Bections 1-4 of RADMAN topical rept (nonproprietary) & Apps B & C (proprietary) to complete evaluation rept. H/o encis. TUITE:P.T. Haste Management Group, Inc. 83/05/31. RDLES.O. Low Level Haste Licensing Branch. 1p. 19857:396.
- 8307290945 Forwards rept of meeting re responses to comments on topical mept, "RADMAN.Computer Code to Classify & Document Packaged Low Level Waste in Accordance W/10CFR61 Regulations." W/a encl.
- enci.

  JOHNSON, T. C. Low Level Waste Licensing Branch. B3/04/27.

  LOHAUS, P. H. Low Level Waste Licensing Branch. Ip. 19857:091.
- XPORTLIC EXPORT AND IMPORT LICENSES
- 8307050468 Discusses NBS 830525 application for license to import Pu-239,Pu-240 & U-233,as deposits on metal backing from Belgium License should be issued.
  MODRE,R.N. Office of International Programs, Director. 83/06/15.
  Office of International Programs, Director. 19. 19262:171.
- 8307050518 Submits Ofc of Intl Programs findings re Exxon Nuclear Co application to import 23,000 kg U.enriched to 3.4% U-235, from West Germany.License should be issued. MODRE, R.N. Défice of International Programs, Director. 83/06/27. Office of International Programs, Director. 1p. 19262:034.
- B307050521 License for Sandvik Special Metals Corp to export 10 Zircaloy-4 guide thimble tubes to Japan. ZIMMEMAN. J. V. Assistant Director for Export/Import & International Bafeguards. SSM-31014. B3/06/28. 1p. 19262:035.
- B3D7D3D323 License for Exxon Nuclear, Inc. to import 23,000 kg U.enriched to 3.4% U-235, from West Germany.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Bafeguards. 83/06/25. ip. 19262:033.

- B307030525 Amend 1 to Exxon Nuclear Co.Inc export license, increasing quantity of U-235 to 1.513 kg. for export to West Germany.
  ZIMMERMAN. J. V. Assistant Director for Export/Import & International Safeguards B3/06/27. tp. 19262 032.
- 8307050529 Informs that Amend ! to License XSNM-2001 may be issued No matl changed circumstances since issuance of Amend ! to License XSNM-1713.

  MODRE,R.N. Assistant Director for Export/Import & International Safeguards. 83706/27. Assistant Director for Export/Import & International Safeguards. 1p. 17262:031.
- B307050533 Cancels B20920 application for license to export nuclear matis to Israelper telcon.

  JAMRISKA, D. J. Isotope Products Laboratories 83/06/15. HEMBY, E. Assistant Director for Export/Import & International Safeguards. 1p. 19262:030.
- 8307080536 Withdraws & cancels 810824 application for export license. EISENMANN.L.L. Leico Industries, Inc. 10072. 83706721. HEMBY.E. Assistant Director for Export/Import & International Safeguards. 1 17262:027.
- B307070220 License for Ledoux & Co to import 19.9 kg U.enriched to 5% U-235, from France. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. B3/06/15. ip. 19344:349.
- B307070224 Litense.for NBS to import 1.0 g Pu-239.Pu-240.Pu-241 & U-233 from Beigium.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Bafeguards. B3/06/15. ip. 19344:350.
- 8307070356 Requests early issuance of Export Licenses XSNM-2014,2015, 2022 & 2031 due to scheduled shipment dates. Further delay would jeopardize intended shipments & eventually result in reactor shutdown due to lack of reload fuels.

  DKADA, S. Mitsul & Co. (USA). Inc. (subs. of Mitsul & Co., Ltd.).

  B3/06/15. ZIMMERMAN, J. Director's Office, Office of Inspection and Enforcement. 4pp. 19300:235.
- 8307070361 Application to amend license to export changing intermediate consignee to either Transnucleaire.S.A. or Transnuklear. QmbH & supplier to either Union Carbide Corp or Goodyear Atomic Corp.

  Hannett,B.A. Transnuclear. Inc. TNP-429. 83/06/16. MOORE.N. Qefice of International Programs, Director. ip. 19300:239.
- 8307070364 Application to amend license to export, extending expiration date to 851231.

  HERBCH,M.M. Hestinghouse Electric Corp. MMH~384. 63/06/17.

  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. 1p. 19300:197.
- 8307070367 Application to amend license to export adding Medizinische Muchachule Mannover as ultimate consignee. Also requests BNM limits be increased to 1.970 kg U contained in 390 g U-235. MOWRY, W. R. GA Technologies, Inc. / General Atomic Co. IEL-4089. B3/06/13. ZIMMERMAN, J. Assistant Director for Export/Import & International Safeguards. 1p. 19300: 240.
- 8307070371 License for Sandvik Special Metals Corp to export 10 pieces Zircaloy-4 guide thimble tubes to Japan. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. 83/06/28. jp. 19300-165.
- B307070372 Application to amend license to export U to France, deleting COGEMA & replacing w/Transnuklear GmbH as ultimate consignees.

  MARCHAL, J. European Communities, Commission of. 83/06/17.

  GRIFFIN, J. A. Energy, Dept. of. 1p. 19300: 241.
- B307070377 License for Sandvik Special Metals Corp to export 340 pieces Zircaloy-4 guide thimble tubes to Japan. ZIMMERMAN J.V. Assistant Director for Export/Import & International Safeguards. B3/06/28. 1p. 19300:166.
- 8307070379 Requests Executive Branch position re GA Technologies, Inc application for license to export specially designed parts & components to Thailand. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. 83/06/22. STOIBER.C.R. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs 1p. 19300:242.
- 8307070381 License for Mitsubishi Intl Corp to export one full jet noizle to Japan. ZIMMERMAN.J.V. Assistant Director for Export/Import & International Bafeguards. 83/06/28. 1p. 19300:167.

- 8397070387 License for Ediau Intl Co to export 8.600 kg depleted U, contained in 12.600 kg U herafluoride to South Korea.
  IMMERMAN.J. V. Assistant Director for Export/Import & International Safeguards 83/06/16. lp. 19300-168
- 8307070388 Requests Executive Branch position re GA Technologies.Inc application for license to export SMM.as reload fuel, to Thailand
- STAIRSING THE STAIRS ASSISTANT DIRECTOR FOR Export/Import & International Safeguards 83/06/22. STOIRER.C.R. State, Dept. of, Bureau of Oceans & Intl Environ. & Scientific Affairs. Ip. 19300;332.
- 8307070389 Amend ; to Eston Nuclear Co.Inc export license, increasing quantity to 2.030 kg U-235 contained in 66.530 kg U.for export to Belgium 21mmEMPAN.J V Assistant Director for Export/Import & Internationa
- igium
  V Assistant Director for Export/Import & International
  63/06/17. ip. 19300:169.
- G307070332 Requests Executive Branch position re NUS Corp application for license to export 25,000 kg depleted U.in form of U herafluoride to Taiwan. Zihnerman. J. V. Assistant Director for Esport/Import & International Safeguards 83/06/21. STOIDER.C.R. State. Dept. of. Bureau of Cleans & Intl. Environ. & Scientific Affairs. 1p. 19300:333
- 0307070394 Amend 1 to Transnuclear, Inc export license, adding Reaktor Brennelement Union GmbH as ultimate consignee. ZIMMERKAN, J V Assistant Director for Export/Import & International Safeguards 03/06/15. Ip. 19300:170
- 6307070403 Forwards applications for export licenses for minor nuclear export of low enriched U.Ltr of assurance required.W/o encl. IMMERNAN.J V Assistant Director for Export/Import & International Safequards 63/06/15 RAYMOND.J.J. Energy, Dept. of. ip.
- --B307070468 Application for license to export 2,002 g U-235, contained in 10.060 g U.to Thailand.

  MUNRY.W R. GA Technologies, Inc./General Atomic Co. IEL-4090.

  B3/06/13 ip 19300:172.
- B307070407 License for GE to export miscellaneous specially designed fuel hardware to West Germany.
  ZIMMERHAN, J.V. Assistant Director for Export/Import & International Safeguards. BDM-047-B3. B3/06/22 ip. 19300:335.
- B307070413 Application for license to espart spare fueling machine parts to Argentina.
   Circle Seal Controls. P19920. B3/06/02 4pp. 19300:173.
- 8307070414 Forwards application for export license for minor nuclear suport adding uitimate consignee & increasing quantity of matt by 1.970 kg U. Ltr of assurance required W/a encl. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/06/22. RAYMOND, J. J. Energy, Dept. of. 1p.
- B307070417 Application for license to export 3.632 kg U.as natural & enriched U hexafluoride to Japan.
  OKADA.5 Mitsul & Co. (USA), Inc. (subs. of Mitsul & Co., Ltd.).
  MBKTR-14 B3/06/21, Ip. 17300:177.
- 8307070418 License for Rhone-Paulenc, Inc to export 5.275.44 kg thorium, contained in rare earth oxides & monazite, to France.
  ZIPPERMAN.J V. Assistant Director for Export/Import & International Safeguards 83/06/22. 2pp. 19300.357.
- 8307070421 License for Westinghouse to export three first stage potting assemblies for low voltage penetrations to Spain.
  IIMERMAN.J.V. Assistant Director for Export/Import & International Safeguards 83/06/22. 1p. 19300:359.
- 8307070424 License for NBS to import 1 g U.enriched to 99% U-235, from
- 8307070429 License for Exxon Nuclear Co.Inc to import 28,600 kg U. enriched to 3 3% U-235.from France.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/06/17. 1p. 19300:361.

- 8307070433 Submits Ofc of Intl Programs findings re Exxon Nuclear Co application to import 28,600 kg U, suriched to 3.5% U-235, from France-License should be issued. MODRE, R.N. Office of International Programs, Director. 83/06/17, Office of International Programs, Director. 1p. 17300:362.
- 8307070450 Application for license to export two irradiated Zircaloy II pressure tube sections, to Canada. FOSTER.C.M. Ediow International Go. AECL-2. 83/06/17. ip.
- B307070452 Application for license to export three first-stage potting assemblies to Spain.

  SCHNAUTZ, C. E. Westinghouse Electric Corp. ZE 20609-P. 83/06/20. ip. 19300:193.
- 8307070456 Application for license to export two miniature fission chambers to Canada.

  TERMILLIGER, L. Westinghouse Electric Corp. 83/06/15, 1p, 19300:194.
- 8307070458 License for Edlow Intl Co to export 0.74 mg Pu-242; contained in NBS 5 g solution of 5 molar nitric acid; to Japan. ZIMMERNAN,J.V. Assistant Director for Export/Import & International Safeguards. 83/06/23. 2pp. 19300:193.
- 8307070462 License for GE to export 300 pieces zirconium tubing to Hest Germany. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafaguards. 83/06/28. 1p. 19300: 228.
- 8307070465 License for Westinghouse to export two fission counter tubes/Model ML8073, to Japan.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/06/28. ip. 19300: 929.
- B307070520 Application for license to export 310 30B cylinders, containing U hexafluoride heels, to France or Netherlands. W/B30617 ltr. KIEL.0, R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). B3/06/17. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 2pp. 19300:344.
- 8307070525 Advises that Westinghouse 830621 application for license to export three low voltage penetration assemblies to Spain granted w/o normal 15-day waiting period. ZIMHERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/06/22. Assistant Director for Export/Import & International Safeguards. ip. 19300:304.
- B307070528 Requests expaditious issuance of license to export highly enriched U to France.

  HANNETT, B. A. Transnuclear, Inc. TNP-430, B3/06/23, ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards.

  1p. 19300:305.
- B307070590 License for Sandvik Special Metals Corp to export 790 pieces of Zircaloy-4 guide thimble tubes to Japan.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/04/28. 1p. 19300:336.
- 8307070531 Application for Amend 1 to export license authorizing shipment of 61.2 short tons of rare earth & monazits.

  Request due to oversight in failing to renew license application before expiration date of 830601.

  CLARK, E. Rhons-Poulene, Inc. 83/06/21. HEMBY, E. Office of International Programs, Director. 1p. 19300:306.
- 8307070534 Informs that Amend i to License XBNM-1929 may be issued. No metl changed circumstances since issuance of license.
  MOORE,R.N. Assistant Director for Export/Import & International Safeguards. 83/06/17. Assistant Director for Export/Import & International Safeguards. ip. 19300:307.
- 8307070537 Submits Ofc of Intl Programs findings re Braunkohle Transport & Storage, Inc application to import 500, 000 kg U, enriched to 4% U-235, from various countries. License should be issued.

  MOIRE, R.N. Assistant Director for Export/Import & International Safeguards. 83/06/24. Assistant Director for Export/Import & International Safeguards. 1p. 19300:308.
- 8307070540 Submits Dfc of Inti Program findings re NBS application to import 0.001 g U-235, enriched to 97% as fissionable deposits bonded to metal backings. License should be issued.

  MOGRE, R. N. Assistant Director for Export/Import & International Safeguards. 8JO6/15. Assistant Director for Export/Import & International Safeguards. 1p. 19300:309.

- 8307070546 Advises that license to export 61.2 short tons of rare earth oxides & monarite to France issued to Rhone-Poulenc w/o normal 15-day waiting period.

  ZIMMERHAN, J. Assistant Director for Export/Import & International Safeguards. 83/06/22. Assistant Director for Export/Import & International Safeguards. 1p. 19300:164.
- 8307110512 Amend 5 to Westinghouse export license, extending expiration date to 851231.

  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/06/29. ip. 19384:195.
- 8307110521 Application to amend license to export 5.06 kg U-235, contained in 70.2 kg U.Requests application be processed on amergency basis.

  GARRETT.J.A. Separative Work Unit Corp. 83/06/28. MODRE, N. Office of International Programs, Director. 1p. 19384:191.
- 8307110535 License for Teledyne Isotopes to export 2.9 kg depleted U, in form of calibr plates contained in woodcase as part of TLD systo Peoples Republic of China.
  ZIMRRMAN.J.V. Assistant Director for Export/Import & International Bafeguards. 83/06/28. ip. 19494:133.
- B307110541 Forwards LEICO Industries, Inc B30621 ltr.withdrawing license application for export of 25 lb unirradiated thorium metal trimmings to Israel.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. B3/06/28. ST018ER, C.R. State, Dept. of, Sureau of Oceans & Intl. Environ. & Scientific Affairs. ip. 17434:134.
- 8307110544 Forwards Transnuclear, Inc application for amend to export license, adding addl intermediate consignee. Ltr of assurance required. M/o encl.

  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Refeguerds. 83/06/27. RAYMOND, J. J. Energy, Dept. of. ip. 19434:136. enci. V. Assistant Director for Export/Import & International 83/06/27. RAYMOND.J.J. Energy, Dept. of. 1p.
- B307110345 Forwards application for export license for minor nuclear export.Ltr of assurance required.W/o encl.

  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Bafeguards. B3/06/29. RAYMOND.J.J. Energy, Dept. of. ip. 19391:178.
- 8307110547 Ltr of assurance re export of 0.77 kg U-235, contained in
  - SHIRAKAWA.T. Japan. Govt. of. 83/06/24. RAYMOND.J.F. Energy. Dept. of. 1p. 19434:137.
- 8307110549 Amends 820428 ltr of assurance re export of 1.30 kg U-235, contained in 30 kg U, to Belgium.
  MARCHAL, J. European Communities, Commission of. 83/06/23.
  QRIFFIN. J. A. Energy, Dept. of. 1p. 19391:321.
- 8307110550 Forwards application for export license for minor nuclear export. Ltr of assurance required, W/o ancl.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafaguards. 83/06/28. RAYMOND. J. J. Energy, Dept. of. 1p. Bafeguards. 19391: 180.
- B307110361 Amends B00B11 itr of assurance re export of Triga fuel to West Germany increasing quantity to 978 g U-235, contained in 4,925 g U & authorizing Medizinische Hochschule Hannover/ West Germany as addi consignee. MARCHAL, J. European Communities, Commission of. 83/06/23. GRIFFIN, J. A. Energy, Dept. of. 1p. 19434:095.
- B307120890 Informs that License XSNM-2015 may be issued No matl changed circumstances since issuance of License XSNM-2030.

  MODRE: R. N. Assistant Director for Export/Import & International Safeguards. 83/06/30. Assistant Director for Export/Import & International Safeguards. 1p. 19508:313.
- 8307130062 License for QE to export 0.77 kg U-235, contained in 44 kg U.
- to Japan. ZIMMERMAN, J. V. V. Assistant Director for Export/Import & International BDW-051-03. 03/06/30. ip. 19526:001.
- B307130064 License for Mitsui & Co (USA), Inc to export 207 kg U-235, contained in 6.834 kg U as U hexafluoride, to Japan.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafaguards, MBK-H2-R6(B), 83/06/30. 2pp. 19511:292.
- 8307130121 Ltr of assurance re export of 824 kg U-238, contained in 28,910 kg U-to Japan.

  BHIRAKAHA: T. Japan. Govt. of. 83/06/29. RAYMOND, J. F. Energy. Dept. of. 19. 19311:137.

- B3071301B1 Forwards application for license to export Cf-252 sealed source, contained in Monsanto Model 2755, to Israel. CROSBIE K.L. IRT Corp. TUBE PS-800. B3/06/27. MODRE, R.N. Assistant Director for Export/Import & International Safeguards. ip 19511:138.
- --8307130102 Application for license to export Cf-252 sealed source, contained in Monsanto Model 2753, to Israel.
  CROSBIE.K.L. IRT Corp. TUBE PS-800. B3/06/23. ip. 19511:139.
- B307130337 Ltr of assurance re export of 2,135 kg U-235, contained in 80,420 kg U-to Japan.

  SHIRAKAWA, T. Japan, Govt. of. 83/06/27. RAYMOND, J. F. Energy. Dept. of. 1p. 19508:351.
- B307130340 Ltr of assurance re export of 412 kg U-235, contained in 15,545 kg U, to Japan. SHIRAKANA T. Japan. Govt. of. 83/06/29. RAYM⊡ND, J. F. Energy, Dapt. of. 1p. 19308:344.
- B307130341 Lirense for Westinghouse to export two fission chambers: Model WX-33073; to Canada. ZIMMERMAN.J. Assistant Director for Export/Import & International Bafeguards. B3/07/07. 1p. 19508:343.
- 8307130342 License for Edlow Intl Co to export two pieces Zircaloy-II pressure tubes to Canada.
  ZIMMERMAN.J. Assistant Director for Export/Import & International Safeguards. 83/07/07. 1p. 19508:342.
- 8307130344 Amend 1 to export license, extending expiration date to 840701 % increasing quantity of mat1 to 70.2 kg U, containing 5.06 kg U-235.
  ZIMMERMAN, J. Assistant Director for Export/Import & International Bafeguards. 83/07/05. ip. 17508:341.
- B307130345 Application for license to export 348 kg U-235, contained in 11.231 kg U.to Japan. \* Mitsui & Co. (USA), Inc. (subs. of Mitsui & Co., Ltd.). MBK-FI-R9. B3/07/01. Assistant Director for Export/Import & International Safeguards. 2pp. 19508:339.
- B3071B0001 Amend 1 to Westinghouse export license, extending expiration date to 851201 & increasing quantity of matl to 1.30 kg U-235, contained in 30 kg U. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. ILS-148. B3/06/30. 1p. 19367:361.
- B3071B0004 Amend 1 to Transnutlear Inc export license authorizing shipment of Australian origin matl per 10CFR110, 50(b)(4).
  ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. RBU-411, 83/07/01. 1p. 17567:340.
- 8307180292 Forwards application for export license for minor nuclear export.Ltr of assurance required.W/o encl. ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/07/08. RAYMOND.J.J. Energy, Dept. of. Ip. Safeguards. 19566: 162.
- B307180305 License for Transnuclear, Inc to export 2,002 mCi Cf-252, in cermet wire, to France. Prior US approval must be obtained before reexport of matl can be made to listed countries. ZIMMERMAN, J. Assistant Director for Export/Import & International Bafeguards. 83/07/11. 2pp. 19366:116.
- B307180333 Application for license to export direction tubing & bar stock to Norway.
  WILBON.8.D. General Electric Co. BDW-072-B3. 83/06/30. 1p.
- B3071B0336 Application for license to export 9.572 kg U-238 contained in one irradiated flux measurement capsule, to Belgium. HENRY,L. 9. New York, State Univ. of, Stony Brook. 83/07/06. 2pp. 19565:339.
- B307180338 Amend 2 to Transnuclear, Inc export license, adding Transnuclear GmbH as addi intermediate consignee. ZIMMERMAN.J. Assistant Director for Export/Import & International Bafeguards. B3/07/11. 2pp. 19641:302.
- B3071B0345 Application for license to export 107,502.50 kg thorium & 10,886 33 kg U.contained in 3,000 short tons monarite, to 10,886 33 kg U.contained in 3,000 short tons mona: France. \* Rhone-Poulene, Inc. 83/06/24. lp. 19641:299.

- G307185374 Elecutive Branch position ne Safety Light Corp application to eastern 360,000 Ci tritium over 3-yr period to Argentina.
  Braill-India, Iraq, Israel, Libya, Pakistan, South Africa or
- Signia Batte. Dept of Bureau of Oceans & Intl. Environ. & ECUMBILD B State. Bept of SHEALJ.R Diffice of International Programs. Director. 1p. 19641-297
- E307160382 Application to amend license to export increasing value of export 6 extending expiration date to June 1985. GPEINGR, H F E656. Inc. 83/06/23. 2pp 19641:300.
- 6307190033 License for Mitsu: & Co (USA) Inc to export 611 kg U-235, contained in 21,294 kg U.as U herafluoride, to Japan Zimmerman, J v Assistant Director for Export/Import & International Safejuers: MSA-M2-R6(A) 83/05/30 2pp 19655:260.
- G307193034 Informs that License XSPM-2014 may be issued No matl changed circumstances since issuance of License XSPM-2030. MXOFE.B #: Assistant Director for Esport/Import & International Gafaguards G3706/30 Assistant Director for Esport/Import & International Safaguards. 1p 19656-259.
- G307190035 Amend 2 to GA Technologies, Inc export license, adding Medizinisthe Mochschule Hannover as another ultimate consignes & increasing quantity of matl to 0 978 kg U-235, contained in 4 925 kg U ZIMMERMAN, J V Assistant Director for Export/Import & International Safegueris IEL-1194, 83706/30. Ip 19656:258
- 9307190116 Advises that two amends to export license filed by franshuclear inc complicated by clarical error contained in 030517 ltm Ltms dtd 830128.0617 & 21 should be disregarded. MARCHAL, J. European Communities, Commission of, 83/07/06. RAYMOND, J. Energy, Dept. of 2pp. 19636:005
- B307190280 Forwards application for license to export 70 kg enriched U to Yawan % end use statement M/o enci.
  CHIEN.F.F. Coordination Council for North American Affairs.
  B3/02/23 DEAN.D American Institute in Taiwan. 1p. 19656:195.
- 8307190082 Ltr of assurance re esport of 70.2 ig enriched U to Taiwan.

  MU.A K Coordination Council for North American Affairs.

  MYLE, J B American Institute in Taiwan. 2pp. 19636:193.
- 8307190457 License for Safety Light Corp to export 360,000 Ci tritium to all countries except Kampuchea Cuba, Vietnam & North Zimmerman, J. V. Assistant Princeton Co. 7
- Elmmerman J V Assistant Director for Esport/Import & International Safequards 83/07/13 Zpp 19656:158
- B307190445 Forwards application for license to export tie plates for repair of in-use fuel assemblies to Sweden.

  KIEL, G. R. Exact Nuclear Co., Inc. (subs. of Exact Corp.). 83/07/13.

  Zicherman, J. V. Assistant Director for Export/Import & International Safeguards. Ip. 19656:160.
- --8307190447 Application for license to export tie plates for repair of in-use fuel assemblies to Sweden.

  # Execu Nuclear Co., Inc. (subs. of Execu Corp.). 83/07/13. 1p.
- 8307200234 Forwards application from GE to export zirconium tubing to Norway License not issued because Criterion 3 of Section 110 42(0) unsatisfied H/o encl. ZIPMERMAN, J V Assistant Director for Export/Import & International Bafaguards 83/07/12, SIDIBER.C.R State, Dept. of, Bureau of Oceans & Intl Environ & Scientific Affairs. 1p. 19656-360.
- BD07730291 Requests reason why application for export license has not been approved.

  HANNETT: D. Transbuclear. Inc. TNP-430 B3/07/06. ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards.
- 8307200294 Application to amend license to export low enriched U to France.authorizing Transmutlear GmbH as third intermediate consigner MARCHAL J European Communities, Commission of 83/06/21.

  ORIFFIN. J A Energy, Dept. of 19656: 355
- 8307200295 License for Mitsubishi Intl Corp to export 824 kg U-235. centained in 28.910 kg U to Japan. ZIMMERMAN.J V Assistant Director for Export/Import & International Safaşuards MSA-5482-11. 83/07/08. 2pp 19656:351.

- 83072003D4 Advises that Ofc of Intl Nuclear Nonproliferation Policy, in conjuction w/State Dept.has regular communication w/ Australian authorities re approval of export licenses. W/o encl. HART.T.A. Energy, Dept. of. 83/05/29. ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 1p. 19656: 347.
- 8307200319 License for Mitsubishi Intl Corp to export 412 kg U-235.contained in 15.545 kg U. to Japan. ZIMMERMAN.J. V. Assistant Director for Export/Import & International Safeguards. HBA-5482-10. 83/07/08. 2pp. 19656:335.
- B307210246 Application for license to export 937 kg U dioxide powder to Japan.
  WILSON B. D. General Electric Co. BDW-074-B3. B3/06/30. 1p. 19688:317.
- 8307210270 License for CERAC, Inc to export 2.636 kg therium, contained in 3.0 kg therium exide in powder form, to Ciecheslovakia.

  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/07/12. 2pp. 19672:357.
- 8307210277 Executive Branch position re Mitsubishi Intl Corpapplication to export 2,135 kg U-235, contained in 80,420 kg U, to Japan. License should be granted.
  DEVING. J. B. State. Dept. of. 83/07/08. BHEA, J. R. Diffice of International Programs, Director. 2pp. 19672:335.
- B307210317 Responds to B30622 ltr requesting amend to export license adding add1 intermediate & ultimate consignoe. Request denied. License expired on B30301. No objection to retransfer of matl covered by license to Canada. ZIMMERMAN. J. V. Assistant Director for Export/Import & International Bafeguards. B3707/13. MENTER, L. Bandvik Special Metals Corp. ip.
- B307210320 Ack receipt of B30706 ltr re export license application.
  Since application includes high enriched U.NRC procedures
  require that NRC obtain views & comments of Executive Branch
  prior to NRC decision.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International
  B36epuards. B3/07/13. HANNET, B. A. Transnuclear, Inc. 1p.
- B307210359 License for State Univ of NY at Buffalo to export 9,872 mg U-238, contained in stainless stael irradiated flux measurement capsule, to Belgium. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. B3/07/12. ip. 19672:323.
- 8307210366 Notifies the State Univ of NY at Buffelo 830706 application for license to export stainless steel irradiated flux measurement capsule to Belgium acceptable. License issued IV and the state of the state
- B307210379 Application for license to export 11.345 kg U dioxide as powder to Japan. HILSON, B. D. General Electric Co. BDW-073-B3. B3/06/30. 1p. 19672:316.
- 8307210385 Application for license to export 15.20 kg U, as U metal, to France.
  \* Energy, Dept. of. 83-54, 83/07/01, 2pp. 19472:320.
- 8307210389 Application for license to export 14.1 kg U.enriched to less than 20% in U-235 to Algeria.

  MOMRY, M. R. GA Technologies, Inc. / General Atomic Co. IEL-4076.
  B3/07/01. ZIMMERMAN, J. Assistant Director for Export/Import & International Safeguards. 3pp. 19678: 317.
- 8307220016 Forwards application for license to export 2.8 kg U-235, contained in 14.1 kg U. to Algeria.
  MOWRY, W. R. GA Technologies, Inc. /General Atomic Co. IEL-4097.
  International Safeguards. 1p. 19692: 133.
- --8307220031 Application for license to export 2.8 kg U-235, contained in 14.1 kg U.to Algeria.
  MUHRY, W. R. GA Technologies, Inc./General Atomic Co. IEL-4097.
  83/07/01. 1p. 19692:134.
- B307220165 Application for license to export spare parts. D-rings, poppets & nuts to Canada. Circle Seal Controls. P27630. 83/07/05. ip. 17672:353.

- B3072205B3 Informs that License XSNM-203B may be issued. No matl changed circumstances since issuence of License XSNM-2015.
  MODRE,R. N. Assistant Director for Export/Import & International Bafeguards. 83/07/0B. Assistant Director for Export/Import & International Safeguards. 1p. 19712:091.
- B30722063B Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. B3/07/14. RAYMOND, J. J. Energy, Dept. of. 1p. 19697:044.
- 8307220640 Forwards application for export license for minor nuclear export. Ltr of assurance required. H/o encl.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. B3/07/14. RAYMOND, J. J. Energy, Dept. of. 1p. 17697: 041.
- 8307220642 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/07/14. RAYMOND, J. J. Energy, Dept. of. 1p. 19697:039.
- 8307250071 Requests Executive Branch position re GA Technologies, Inc applications for licenses to export TRIGA Mark I Research Reactor & 14.1 kg enriched U to Algeria. W/o encl. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. 83/07/14. BTOIBER, C.R. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 1p. 19729; 361.
- 8307250086 License for Brunswick Corp.Circle Beal Controls to export miscellaneous specially designed spare parts for Circle Beal Valves to Canada. PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 83/07/15. ip. 19720:335.
- 8307250087 License for Exxon Nuclear Co to export 40 tie plate assemblies & associated hardware to Sweden.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards. 83/07/14. 1p. 19720:336.
- 8307250093 Application for license to export spare parts, poppets, O-rings & springs for PIN P170-526 valve to Canada.

  \* Circle Seal Controls. P28302. 83/07/03. 1p. 19720:332.
- 8307250097 Advises that license for Exxon Nuclear Co.Inc to export tie plate assemblies & associated hardware to Sweden issued w/o normal 15-day waiting period.

  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/07/14. Assistant Director for Export/Import & International Safeguards. ip. 19720:329.
- 8307250102 Advises that license for Circle Seal Controls to export specially designed valve parts to Canada issued w/o normal 15-day waiting period.

  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Safeguards. 83/07/15. Assistant Director for Export/Import & International Safeguards. 1p. 19725:342.
- 8307250531 Addl response to FOIA request for all correspondence between Nuclear Assurance Corp.NRC & DDT since June 1982 & documents as Chalk River Lab. Forwards App A documents. Documents 21-27 withheld (ref FOIA Examption 3). FELTON, J. M. Division of Rules and Records. 83/05/11. PUNTENNEY, J. Safs Energy Coalition. 3pp. 19716:018.
- --8307250538 Notifies that spent fuel shipments from AECL facility at Chalk River to DDE facility will be made under Export License ISNM-B1005. Amends 1 & 2. Schedule & port of entry encl. Safeguards info deleted (ref 10CFR73.21). DANEBE,F. L. Nuclear Assurance Corp. FLD/83/145/ETS. 82/09/29. GDDY,A. Region 1, Office of Director. 2pp. 19716:053.
- 8307250646 Ltr of assurance re export of 180 kg U-295, contained in 3,600 kg U) to France & the Netherlands. MARCHAL.J. European Communities, Commission of. 83/07/12. RAYMONDIJ. Energy, Dept. of. 1p. 19716:338.
- 8307250648 Ltr of assurance rs export of 816 kg U-235, contained in 26,865 kg U, to Japan. 8HIRAKANA, T. Japan. Govt. of. 83/07/19. RAYMOND, J. F. Energy, Dept. of. 1p. 19716:359.

į

- 830725065) Forwards application for license to export 400 fuel pellets, containing 0.051 kg U-235, to Belgium.
  CONLEY.D. T. Babcock & Wilcox Co. 83/07/15. MODRE, N. Assistant Director for Export/Import & International Safeguards. 1p. 19716:360.
- --8307250656 Application for license to export 400 pellets containing 0.051 kg U-235 to Belgium. CONLEY.D.T. Babcock & Wilcox Co. 83/06/14. lp. 19716:361.
- 8307250655 Requests that B30228 application to export 14,000 kg U to Japan be issued by 830805. NAKAMURA:N. Marubeni America Corp. (subs. of Marubeni Corp.). B3/07/15. ZIMMERIMAN.JV. Assistant Director for Export/Import & International Safeguards. 2pp. 19718:052.
- 8307270073 Forwards applications for export licenses for minor nuclear export. Ltr of assurance required.
  ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards, 83/07/20. STOIBER, C. R. Energy, Dept. of. 1p. 19811-070
- ---8307270079 Application for license to export 1 mg Cf-252 neutron source in special form MRC-Model 2765 capsule to India. HQADLEY.B. Monsanto Research Corp. 063-82AD(40). 83/07/20. 1p. 19811:071.
- --8307270086 Application for license to export 1 mg Cf-252 neutron source in special form MRC-Model 2765 capsule to India. HQADLEY, S. D. Moonsanto Research Corp. 228-82AO(40). 83/97/20. ip. 17811:072.
- 8307270073 Forwards application for export license for minor nuclear export. Ltr of assurance required.
  ZIMMERMAN.J.V. Assistant Director for Export/Import & International Bafeguards. 83/07/20. RAYMOND.J.J. Energy, Dept. of. 1p. 1981:067.
- --8307270099 Forwards application to export 400 fuel pellets
  (92% U-238 & 8% gadolinium) to Belgium.
  CONLEY.D.T. Babcock & Wilcox Co. 83/07/15. MOORE.N. Assistant
  Director for Export/Import & International Safeguards. 1p.
  19811:068.
- --B307270104 Application for license to export 400 pellets of 8% gadolinium & 72% unirradiated U to Belgium.
  CONLEY, D. T. Babcock & Wilcox Co. 83/06/14. 1p. 19811: 067.
- 8307270308 Discusses position re Exxon Nuclear Co, Inc. application to import 52,000 kg U, enriched to 3.83% U-235, from France.
  License should be issued.
  MOORE,R.N. Office of International Programs, Director. 83/07/14.
  Office of International Programs, Director. ip. 19812:042.
- 8307280105 Application for license to export i mg Cf-252 neutron source.in special form MRC-Model 2765 capsule to India. HOADLEY.S. Monsanto Research Corp. 063-82A0(40). B3/07/15. ip. 19812:352.
- 8307280198 Forwards application to export 150.000 kg U.contained in natural U ors concentrates, to Canada.
  MUYER.R.E. Pathfinder Mines Corp. B3/07/11. WRIGHT.B.L. Assistant Director for Export/Import & International Safeguards. 1p. 19826-064
- --8307280207 Application for license to export 150,000 kg natural U.contained in natural U ore concentrates, to Canada. MOYER,R. Pathfinder Mines Corp. 83/07/11. 1p. 19826:067.
- B307280466 Application for license to export 1 mg Cf~252 neutron source in special form MRC-Model 2765 capsule to India. HOADLEY, B. D. Honsanto Research Corp. 228-82AO(40). 83/07/15. ip. 19826:042.
- B307280467 Application for license to export 500 mCi Cf-252 to Japan. BAITO.T. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 64-7788-83. 83/07/14. ip. 19826:043.
- 8307290316 License for Mitsul & Co.Inc to export 816 kg U-235.contained in 26.865 kg U. to Japan. PETER80N.M.R. Assistant Director for Export/Import & International Safeguards. MBK-F3-R8. 83/07/21. 2pp. 19858:157.

ot category column in this index gives the docket and the symbol for the category of information to docket; for example, 50-320 P. The docket subject are defined in Appendix A.

ategories for nondocketed items are also entered jumn by symbol; for example, ACRS. These catedined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

ACCESSION NUMBER	SUBJEC CATEOO	RY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEOD	ŧγ	AUTHOR	ACCESSION NUMBER	SUBJEC	ŔY
8305100326							AXELRAD, J.			
	50~289	G	ALLARD, D. J.	8307170075*	40-672			8305120177	I&E	_
8307040208	50-269	Q	ALLEN, C. L.	9307120176*	50-537	T	AXELRAD, J.	6306100079	50-277	s
8307050071	30-287	G	AMICO: P. J.	B30729010B*	50-247	G	AXELRAD, J.	B306280432	50-456	8
8307140441	50-289	Q	AMSTUTZ, S.	B307220219	50-155	R	AXELRAD: J.	8307050114	50-492	Q .
8307110641	50-352	Œ	ANANDAPPA, A.	9307080496	50-237	8	AXELRADI J.	B307140311	1&E	
8307250072	50-352	E	ANDERSEN, N. W.	8307050050	50-331	8	AXELRAD, J.	0307190321	50-322	g.
8307270483	50~352	Æ	ANDERSON, C.	8307210026*	50-322	ā	AXELRAD, J.	8307260364	50-267	8
8307120047	RES		ANDERSON, C. J.	8307010161*	50-352	ā	AXELRAD, J.	8307280377	50-275	8
8307070184*	50-237	P	ANDERSON, C. J.	8307280283#	50-333	Ğ	AXELRAD, J. A.	8307060147	MIEC	-
B307070211*	50~237	þ	ANDERSON, C. J.	9307280342*	50-354	G	AXELRAD, J. A.	8307060194	DBIM	
8307070218*	50-237	P	ANDERSON, F. D.	8304090500	PR		AXELRAD, J. A.	8307130002	50-358	A
8307180147*	50-237	þ	ANDERSON, H. M.	8307220639	71-9151		AXELRAD, J. A.	8307130041	50-482	ä
8307180152*	50-237	Ë	ANDERSON, J. W.	8307110168#	50~537	-	AXELRAD, J. A.	8307130174	50-456	ŭ
8307180158*	50-237	þ	ANDERSON, J. W.			Ţ	AXELRAD, J. A.	8307130247	50-324	ä
8307050377		F	ANDERSON, K.	8307110168*	50-537	T	AXELRAD, J. A.	8307290318		
6307030377	90-369	r	Punerenuty.	8307060411*	50-400	Q	AXELINADI G. A.	830/240316	50~277	a
8307130104	50-369	þ	ANDERBON, K. D.	930726022B*	GA999		AXELRAD, H.	8307060195	PR	_
8307130112#	50-349	P	ANDERSON, M.	8307190152	50~331	R	AXELSON, W. L.	8307060303*	50-255	a
8307130354	50~328	P	ANDERSON, M.	192022701	50-331	R	AXELSON, H. L.	8307120547*	50-243	G
8307130383#	50-328	Р	ANDERSON, M. A.	8307060123	50-331	S	AXELSON, W. L.	8307220553*	50-454	Q
8307190416	50-375	Н	ANDERSON, P. L.	8307210191#	50-443	T	AXELSON, W. L.	8307280274*	50-275	Q
8307270011	50-413	D	ANDERSON, S. L.	8307190257*	50-213	Р	AXELEON, W. L.	8307280329#	50-373	q
8307270290	50-328	P	ANDRUS, N. J.	8307050035	PR		AZARM, M.	8307150149	NUREO	
8307270297*	50~328	P	ANDRUS, N. J.	8307150452	40-4492		AZZAZY, 6. E.	B307260028*	50-237	P
8307280099	50-413	D	ANG, H. P.	8307140103*	50~389	Œ.	BACHMANN, R. G.	B307130095	50-508	Ö
B306170403	50-142	Ť	ANG, W. P.	8307140117=	50-389	œ.	BAER, R. E.	8307120505*	50-458	ā
8307140141+	50-250	G.	ANG, W. P.	8307220494*	50-389	æ	BAGGETT, C.	8307130091	50-400	D
8307120168*	50-537	r	ANTTONEN, J. H.	9307270223	HABTE MO		BAIETTI.A.	8307190124	PR	v
8307090100*							BAILEY. Q. P.			_
	50-331	P	APICELLA.F.L.	8307150394	50-331	P	BAILEY, R. J.	8307120048*	20-385	F
8307120009	NUREG		ARAND, J. J.	8307110408	50-373	8		8307110469*	50-220	Q
8307120012	NUREG		ARCHITZEL, R. E.	8307150093*	50-317	a	BAILEY, R. J.	8307280284*	50-309	Q
B307280156*	50-374	G	ARCHITZEL, R. E.	8307280315*	50-317	Q:	BAIR, O. Q.	8307180149	50-344	R
B307280395*	50-341	G	ARELLAND, F. E.	8307150359	NUREO		BAIRD, J. B.	8307040019*	50-285	a
8307070582*	50-244	P	ARNOLD, R. C.	8307120342	50-320	P	BAIRD, J. S.	8307260531#	50-276	G
8307280020	40~2061		ARNOLD, R. C.	8307120347*	50-320	P	BAKER, N. D.	9307050328*	CONTRACT	ı
8307140064*	50-261	Q	ARTHUR, W. J.	8307030414	WASTE MG	T	BALDWIN, C. A.	8307130136	NUREO	
8307140089*	50-261	G	ARTHUR: W. J.	8307290331	WASTE MG	7	BALL, D. H.	8307280029	40-6500	
B307140321*	50-261	G	ASHE, F.	B307290393	50-375	8	BALL, T. W.	8307110158*	50~537	т
8307220006*	50-261	ē	ASHE, F.	8307290401*	50-395	ĕ	BALLINGER, P. L.	8307220184	50-298	Ŕ
8307180080	50-277	ē	ATA, H.	8307110189	50-237	ē	BALLINGER, P. L.	8307260441	50-278	8
B307210045	50-277	R	ATA, H.	8307110409	50-249	8	BANDINI, E.	8307070045	50-382	ĸ
8307220300	50-277	R	ATCHLEY, J. H.	8307110416	50-373	8	BANKS, H. R.	8307060191	50-261	0
93071100B7	NUREO	IV.	ATIYEH, V.	8307280151	WASTE MG		BANON, H.	8307180307*	50-155	P
8306020348*	50-284	p	AULUCK, R.	830705025B			BARAN, R.	8307220188	50-217	F
B307260455			AULUCK, R.		50-397	Ą	BARANGW, G. W.			
	50~16	R		8307190459	50-397	A	BARANON, S. W.	8307080453	50-329	Ą
8307060351	50-315	P	AUSTIN, O.	8307180198	50~295	R	EMMINUM S. W.	8307110038	50-329	A
8307070089	50-315	В	AUSTIN, M. A.	8307110515	70-135		BARANDH, S. W. BARANDH, S. W.	8307110305	50-329	Ą
8307110290	50-315	P	AUBTIN, M. A.	8307140143	70-135			8307250253	50-329	Ą
8307120400	50~315	P	AUSTIN, M. A.	B307150112*	70-364		BARANDH, S. W.	9307250261+	50-327	Α
8307120445	50-316	þ	AUSTIN, T. L.	8306280607*	50-445	1	BARANDH, S. W.	9307260547	50-329	Α
8307200130	50-315	Q	AUTIO, H. A.	8307010024	50-29	8	BARBER, O.	9906100099	50~277	8
8307280341	50-315	P	AUTIO, H. A.	8307010037	50-29	8	BARBIERI, N. J.	8307200310	50-352	D
8307290162	50-315	K	AUTIO, H. A.	8307010114	50-29	8	BARBOUR: D. A.	8307250354*	40-472	
8307150144	50~277	G	AUTIO, H. A.	8307010127	50-29	g	BARCLAY, J. F.	8307210229*	50-482	В
8307150171*	50-277	ā	AUTIO, H. A.	8307150130	50-29	8	BARKER, H. A.	8307190142*	50-546	ĩ
B307170091*	40-672	-	AUTIO, H. A.	8307150319	50-29	S	BARKER, N. R.	8307070001	50-440	Ē
	, .								- 1-10	<b>-</b>

AUTHÓR TO THE STATE OF THE STAT	ACCESSION WINDER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCEBBIO NUMBER	N BUBVECT CATEGORY
BARYER, N. B BARYERST, P BARYERS, I BARYERS, I BARYERS, I	8307060112+ 8307060336+ 8307060347+	50-440 S 50-362 F GA999 GA999 GA799	BATTERSON, S. BATTERSON, S. BAUBLITZ, J. E BAUER, E. G. BAUER, T. L.	8307220012 8307220039	50-307 R 50-29 R WASTE MOT 70-2988 50-192 F	BELKNAP, L. BELL, R. J. BELL, C. R. BELL, D. D. BELL, J.	830705008 830715036 830712017 830712003 8307110392	9* 70-25 5 50-313 p 6* 50-537
BYNES I BYNES I BYNES I SYNES I		QA999 GA999 GA999 QA999 QA999	BAUNACK, W. H. BAUSCH, H. P. BAUSER, D. B. BAUSER, D. B. BAUSER, D. B.	8307210014* 8307060025* 8307060198 8307060198 8307250350*	50-247 G 50-528 S 50-400 G 50-400 G 50-400 G	BELL, J. BELL, L. W. BELL, M. J. BELL, M. J. BELL, M. J.	8307250413 830712015 8307220089 8307220094 8307220099	3* 50-320 9 3* 50-337 T WASTE HOT
Barneti. I Barneti. I Barneti. I Barneti. I Barneti. I	8307180197+ 8307180215+ 8307290040+ 8307290043+	ga999 ga999 ga999 ga999 ga999	BAUSER, D. B. BAUSER, D. B. BAUSER, D. B. BAUSER, M. A. BAUSER, M. A.	8307250350* 8307280185 8307280185 8307060195 8307070163	50-400 G 50-400 G 50-400 G PR PR	BELL, M. J. BELL, M. J. BELL, M. J. BELL, M. J. BELL, N.	8307220107 8307220112 8307220137 8307220580 8307200126	TOM STEAM * TOM STEAM * TOM STEAM TOM STEAM
BARNES, P BARNES, P BARNES, P BARNES, P BARNES, R	9307290129+ 9307050135 9307060044 9307110331	9A777 9A777 50-304	BAXTER, J. A. BAXTER, T. A.	8307050123 8307050123 8307260360 8307260360 8307050271	50~289 Q 50~289 Q 50~400 Q 50~400 Q 50~289 Q	BELL, N. BELL, N. BELL, N. BELL, N. BEMIB, P.	83072001314 83072001384 83072001388 8307260298 83072201414	* 50-460 q * 50-460 q * 50-460 q
BARR K BARR K P BARR K P BARR K P BARR K P	9307250413+ 5 9307140053+ 5 9307140066+ 5 8307140089+ 5	0-591 0 60-524 0 60-350 0 60-350 0	BAXTER, T. A.	83070\$0271 8307080375 8307080375 8307080383* 8307130231	50-289	Bemig, P. Bemig, P. Bemig, P. Bemig, P. Berodoll, T. E.	8307220207# 8307220317# 8307220344# 8307220574#	50-324 q 50-324 q 50-400 q 50-324 q
BARRIK P BARRIK P BARRIK P BARRIK P BARRIK P	8307140368# 5: 8307140411# 5: 8307220006# 5: 8307220220# 5:	0-261 0 0-327 0 0-335 0 0-261 0 0-338 0	BAXTER, T. A.	8307130231 8307140443 8307140443 8307150201 8307150201	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	BERGDOLL, T. E. BERGER, H. BERGER, H. BERGOREN, J. S. BERGMAN, K. H.	8907050321* 8307190458* 8307200529 8307200529 8307110276*	CONTRACT CONTRACT ACRE ACRE 50-461 Q
BARRETT, L. H.	8307280381 50 8307180410 50 8307180412 50 8307180413 50	0-143 0-320 8 0-320 R 0-320 R 0-320 R	BAXTER, T. A.		50-312 G 50-312 G 50-483 G 50-483 G 50-289 G	BERCQUIST, S. H. BERICK, D. BERLAD, A. L. BERLIN, K. BERLIN, K.	8307200212# 8307120377# 8307070159 830705030 8307050244	CONTRACT  50~52B B  PR  NUREQ  50~529 Q
BARRETT, L. H.	8307270024 50 8307270032 50 8307270039 50 8307290327 50	-320 Q -320 P -320 P -320 P -320 R	BAXTER, T. A.	8307170283 8307170283 8307210203	50-289	BERLIN, K. BERLIN, K. BERLIN, K. BERLIN, K.	8307050251* 8307050251* 8307170076 8307170076 8307170081*	50-529 0 50-529 0 50-529 0 50-529 0 50-529 0
BARRON S. E BARTHIC A BARTHIC A BARTHIC A BARTHIC A	8307010179* 50- 8307080501 50- 8307120077 50- 8307130047 50-	-341 @ -322 A -358 0 -400 0	BAXTER, T. A.	8307250337 8307250337 8307280163 8307280163	50-400 G 50-400 G 50-400 G 50-400 G	BERLIN, K. BERLIN, K. BERLIN, K. BERLIN, K. BERLIN, K.	83071 90081 * 83072 1 0041 * 8307240243 8307240251 8307240367	50-529 0 50-529 0 50-529 0 50-529 0
BARTHE C. A. BARTHE C. A. BARTHE C. A. BARTLETT, J. S. BARTLETT, J. S. BARKLEY, K. P.	8307140466 50- 8307250247 50- 8307250167 50- 8307270198 WAS	400 G 400 G 400 G 400 G TE NGT	BAYNE, J. P.	B307010110 5 6307050023 5 8307080337# 5 8307110223 5	0-333 p 0-333 F 0-286 p 0-333 F	BERLIN, K.  BERLIN, K.  BERLIN, K.  BERLIN, K.  BERLIN, K.	8307260367 8307260403 8307260403 8307260407*	50-529 0 50-529 0 50-529 0 50-529 0 50-529 0
Baskin, K. P Baskin, K. P Baskin, K. P Baskin, K. P Baskin, K. P	8307060064 50-: 8307060091 50-: 8307060128 50-: 8307060155 50-: 8307070065 50-:	761 P 762 P 761 P	BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	8307110229* 84 8307110309 56 8307110314 56 8307110429 56	0-333 p 0-333 p 0-334 p	BERNABEI, L. BERNABEI, L. BERNABEI, L. BERNHOFT, S. L. BERNHOFT, S. L.	8307260407* 8307260161 8307260161 8307260161 8307110277	50-529 0 50-329 0 50-329 0 50-329 0 50-305 8
BASKIN, K.P. BASKIN, K.P. BASKIN, K.P. BASKIN, K.P.	8307080392 50-3 8307080392 50-3 8307110232 50-2 8307130192 50-3 8307130248 50-2	61 R 61 R	BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	8307180108 50 8307210011 50 8307250194 50 8307250238 50	)-333 K 1-333 b 1-334 K 1-333 K	BERRY, D. L. BERRY, D. L. BERRY, D. L. BERRY, D. L.	8307150131	50-305 g REB NUREQ NUREQ
Baskin, K P Baskin, K P Baskin, K P Baskin, K P	8307180096 50-36 8307180105 50-36 8307180121 50-36 8307180236 50-36 8307180284 50-36	61 P 62 P 61 P	BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	8307250248* 50 8307250278* 50 8307250278* 50 8307260468 50 8307270335 50	-333 K -333 G -286 G	BERRY, Z. E. BERRY, Z. E. BERRY, Z. E. BETTENHAUSEN, L. BETTENHAUSEN, L.	8307120424 8307150266 8307220478 8307010012#	NUREO 50-251 S 50-250 S 50-250 B 50-272 G
Backin, K. P. Backin, K. P. Backin, K. P. Backin, K. P. Cackin, K. P.	8307200202 50-36 8307210064 50-36 8307250450 50-20 8307260135 50-20 8307270029 50-20	1 P 6 P 6 F	Bazin, J. P. Bazin, J. P. Beachum, S. B. Beale, K. E.	8307270439 50- 8307140115 CDN 8307190453 CDN 8307180311* 50-	-333 P NTRACT NTRACT -155 P	BETTENHAUSEN, L. BETTENHAUSEN, L. BETTENHAUSEN, L. BEYER, B. R. BHATTI, M. H.	8307110266# 8307210212# 8307210226#	50-322
Partin M Partin M Par	8307270162 50-36: 8307210304+ F0IA 8307210323+ FDIA 8307210323+ FDIA		BEATTY, E. J. BEAULIEU, R. A. BECHHOEFER, C. BECHHOEFER, C.	8307110583 HIS 8307220262 50- 8307050094* 50- 8307190256 50-	244	BIALIK, E. I. BIALIK, E. I. BIBB, H. E.	8307260024* 5 8307070110 N 8307070114 N	70-346 F 70-237 P FUREO FUREO
A881m. n s A880. l f A880. l f A880. l f A880. l f	8307210092* FDIA 8307010142 50-317 8307210285 50-317 8307210287 50-317	5 5	BECKER, R. A. BECKHAM, J. T. BECKHAM, J. T. BECKHAM, J. T.	8307120148* 50-1 930712014 50-1 930712014 50-1	329 G 329 R 337 T 321 P	BICKER, B. D. BIDINGER, G. H. BIDINGER, G. H. BIELAWRKI. A. D.	8307110162 5 8307200392 5 8307110162 7	0~335
nteran, w H. Ater. A. Ater. J. W. Ater. J. M. Ater. R. M.	8307140449* 50-354 8307220121 HASYE 1 70-143 8307140330* 70-111	q Met	BECKHAN, J. T.  BECKHAN, D. A.  BELANGER, J. L.  BELISLE, G. A.	B307220501 50-3 B307270035 50-3 B307250060* 50-3 B307120439* 50-3	321 F 321 K 34 G 73 G	BIGGS, J, M. BILANIN, A. J. BINFORD, E. T.	8307190126 50 8307190126 50 8307280297* 50 8307190074* 50	0-454
	8307210012 50-336		BELISLE, Q. A. BELISLE, Q. A.	8307140236# 50~2 8307140421# 50~3 9307220209# 50~3	80 0 02 0	BINFORD, F. T. BINFORD, F. T. BINFORD, F. T. BINGHAM, W. Q.	8307200043 AC 8307200043 AC	:R8 :R8 :R8 :R8 -827 8

AUTHOR	ACCESS ION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESBION NUMBER	SUBJECT CATEGORY
BIRGEL, S. H. BIRKEL, R. A. BIRKENHEIER, J. BIRKENHEIER, J. BIRKENHEIER, J.	8307080551* 8307820436 8307820436 8307140471 8307140471	CONTRACT 50-269 P 50-322 0 50-322 G 50-529 G	BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8307150173 8307150324 8307150378 8307150378 8307190179	50-458 S 50-458 S 50-458 S 50-458 S 50-458 B	BRADBURY, R. B. BRADFORD, W. H. BRADFORD, W. H. BRADLEY, E. J. BRADLEY, E. J.	8307200179 8307140184* 8307220549* 8307010093 8307010185	0EN TEC 18 50-344 G 50-348 G 50-352 A 50-352 K
BISCHOFF, C. A. BISCHOFF, C. A. BISCHOFF, C. A. BISCHOFF, C. A. BISCHOFF, C. A.	8307190157 8307190227 8307190227 8307190232* 8307190232*	50-529	BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8307250447 8307250464 8307260003 8307260056 8307260414	50-458 8 50-458 8 50-458 A 50-458 8 50-458 8	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307060245 8307070037 8307070167 8307070286 8307080296	50-352 A 50-352 A 50-352 A 50-352 A
BISHOP, T. E. BISHOP, T. W. BISHOP, T. W. BISHOP, T. W. BISSETT, T. A.	8307200240* 8307120512 8307120540 8307150215 8307130313*	CDNTRACT 30-273 G 50-361 G 30-206 G 50-454 A	BORDENICK, B. M.	8307140439 8307140442 8307140446 8307180134 8307200089	20-322 0 20-323 0 20-323 0	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307080300 8307080454 8307080505 8307110459 8307110491	50-352 A 50-277 J 50-352 A 50-352 A
BLACK, D. BLACK, K. BLACK, R. BLACK, R. BLACKMON, T. G.	8307120592 8307050427* 8307190258* 8307190258* 8307040194	50-414 S MISC 50-329 T 50-329 T 50-237 F	Bordenick, B. M. Bordenick, B. M. Bordenick, B. M. Bordenick, B. M. Bordenick, B. M.	8307200102 8307250140 8307250255 8307250270 8307250279*	20-355 0 20-355 0 20-355 0 20-355 0	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307120330 8307120534 8307130271 8307150067 8307150069	50-352 E 50-352 E 50-352 E
BLACKWOOD, E. BLACKWOOD, E. BLACKWOOD, E. B. BLAKE, E. L. BLAKE, E. L.	8307120318 8307120362 8307130256 8307150327 8307150327	PR PR PR 50-287 G 50-287 G	BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M. BORDINE, T. C. BORDINE, T. C.	8307240049 8307280039 8307290008 8307050076 8307050105	50-922 0 50-922 0 50-922 0 50-155 S	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307150075 8307150074 8307150132 8307180054 8307190082	50-352 A 50-352 F. 50-352 E 50-352 C
BLAKE, E. L. BLAKE, E. L. BLAKE, E. L. BLAKE, E. L. BLAKE, E. L.	8307190077 8307190077 8307190268 8307200215 8307200215	50-289 0 50-289 0 50-382 G 50-289 G	BORDINE, T. C.	8307080443 8307110249 8307180302 8307200073 8307220174	50-155 S 50-155 Q 50-155 P 50-155 P 50-155 P	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307190118 8307190121 8307190197 8307220238 8307260147	50-352 A 50-352 A 50-352 A 50-277 K 50-352 A
BLAKE, E. L. BLAKE, E. L. BLAKE, J. BLAKE, J. J. BLAKE, J. J.	8307270130 8307270130 8307220474* 8307140041* 8307140088*	50~287 0 50~287 0 50~387 G 50~257 G 50~250 G	BORDINE, T. C. BORNES, R. P. BOSNAK, K. P. BOTHMAN, J. BOUCHARD, Q. H.	8307220184 8307150243 8307070144 8307280055 8307050148	50-155 F 50-461 S 50-361 P TOPREP 50-213 8	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307260350 8307260372 8307280063 8307280242 8307280257	50-352 A 50-352 K 50-352 A 50-352 A
BLAKE, J. J. BLAKE, J. J. BLAKE, J. J. BLAKE, J. J. BLANCHARD, T.	8307140103* 8307140117* 8307220022* 8307220400* 8307060259	50-387	BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, G. D. BOUCHEY, G. D.	8307050001 8307050004 8307050022 8307050085 8307050136	30-397 A 50-397 E 50-397 A 50-397 Q 50-397 E	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8307280274 8307280330 8307280338 8307280420 8307290080	50-352 A 50-352 A 50-352 A 50-352 A
BLAZEY, D. R. BLAZEY, D. R. BLAZEY, D. R. BLOCH, P. B. DLOCH, P. B.	8307060190 8307150329 8307150335* 8307080201 8307080461	50-289	BOUCHEY, G. D.	8307050176 8307050270 8307060945 8307060255 8307070006	50-397 E 50-508 A 50-397 E 50-508 A 50-397 A	BRADLEY, E. J. Bradley, E. J. Branlett, L. S. Branagan, E. F. Branagan, E. F.	8307290317 8307290329* 8307220305 8307110270* 8307110302*	70-2988 70-2988 50-368 R 50-413 G
BLOCK P.B. BLOCK P.B. BLOCK P.B. BLOCK P.B. BLOCK P.B.	8307080446 8307110048 8307140430 8307250351 8307280140	50-445 G 50-445 G 50-440 G 50-445 G 50-445 G	BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, Q. D. BOUCHEY, Q. D. BOUCHEY, Q. D.	8307070120 8307080324 8307110007 8307110321* 8307120309	PR 50-508 A 50-397 E 50-397 F 50-397 E	BRANAGAN, E. F. Drand, D. A. Brandenburg, B. Brandenburg, B. Brandenburg, B. Brandt, C. T.	B307120197* B307060199* B307120563 B307180060 B307190233*	50-537 T 50-275 P 50-247 G 50-247 G 50-445 G
BLODM, J. G. BLUMBERG, N. BOCCIO, J. BOEGLI, J. S. BOGART, D.	8307200201 8307210224* 8307150149 8307110270* 8307150088	50-454 G 50-412 G NUREG 50-413 G 50-302 R	BOUCHEY, O. D. BOUCHEY, Q. D. BOUCHEY, Q. D. BOUCHEY, Q. D. BOUCHEY, Q. D.	B307120539 B307120545 B307150227 B307150310 B307170213	50-397 F 50-397 H 50-397 A 50-508 F 50-397 A	BRANDT, C. T. BRANNIN, J. P. BRANNIN, J. P. BRANNIN, J. P. BRANNIN, J. P. BRANT, K. T.	9307250357* 9307110245 8307110402 8307120426 9307110427	50-445 Q 50-389 8 50-389 8 50-389 8 50-317 8
DOLLING, L. A. BOMBERGER, C. BOMBERGER, C. BOMBERGER, C. BOMBERGER, C.	8307270312 8306060275* 8306100146* 8306140436* 8307070582*	1&E 50-254 P 50-237 P 50-344 P 50-266 P	BOUCHEY, G. D. BOUCHEY, G. D. BOUCHEY, G. D. BOUKNIGHT, R. J. BOUKNIGHT, R. J.	8307200458 8307250135 8307270452 8307110210 8307110262	70-2750 50-508 A 50-397 F 50-395 8 50-395 9	Bray, T. C. Breaux, D. Q. Brenizer, J. S. Brenizer, J. S. Brenner, L.	8307070161 8307060192* 8307120204 8307230521* 8306030332	50-297   GA979   50-62   50-62   50-352
BONNEB, Q. BOOK, H. E. BOOK, H. E. BOOK, H. E. BOOK, H. E.	8307150376* 8307060236 8307060243* 8307060401 8307060407*	CONTRACT 50-224 G 50-224 G 27-48 27-48	BOUKNIGHT, R. J. BOUKNIGHT, R. J. BOUKNIGHT, R. J. BOUKNIGHT, R. J. BOUKNIGHT, R. J.	83071200B1 830712045B 83072202B4 B30725013B 8307250496	50-375 S 50-375 S 50-375 S 50-375 S 50-375 S	BRENNER, L. BRENNER, L. BRENNER, L. BRENNER, L. BRENNER, L.	8307110319 8307110336 8307120426* 8307180260 8307220369	20-355 6 20-355 6 20-355 6 20-355 6
BOOK; H. E. BOOK; H. E. BOOK; H. E. BOOK; H. E. BOOK; H. E.	9307120076 9307120101* 9307180110 9307180117* 9307180244	70-1359 70-1359 70-1257 70-1257 70-115	BOUKNIGHT, R. J. BOUKNIGHT, R. J. BOUKNIGHT, R. J. BOUKNIGHT, R. J. BOUKNIGHT, R. J.	8307250515 8307260557 8307270175 8307270186 83072700253	50-395 8 50-395 8 50-395 8 50-395 9 50-373 P	BRENNER, L. BREY, H. L. BREY, H. L. BRIDEN, D. W. BRIGGS, L.	8307280144 8307260218 8307260338 8307180306* 8307280449*	50-352 0 50-267 F 50-267 F 50-346 F 50-293 0
BOOK; H. E. BOOK; H. E. BOOK; H. E. BOOK; H. E. BOOKER; J. E.	8307260452 8307260456* 8307260478 8307260482* 8307050127	27-48 27-48 70-1007 70-1007 50-458 6	BOWLER, W. Q. BOYD, D. C. BOYD, D. C. BOYER, L. E. BOYER, L. E.	8307270481 8307060138* 8307180127* 8307110586* 8307110587*	WASTE MOT 50-316 G 80-155 G 50-324 F 50-324 F	BRIGHT, G. D. BRIGHT, G. D. BRINGHAM, P. S. BRITTAIN, P. G. BRITTAIN, P. G.	8307140430 8307280225 8307210373* 8305230578 8306280607*	50-440 9 50-483 9 71-6550 50-445 A 50-445 I
BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8307050144 8307050206 8307050208 8307050216 8307050238	50~458	BOYER, R. E. BOYER, R. E. BOYER, V. S. BOYER, V. S. BOYER, V. S.	6307250335 6307250461 6307010190* 6307150292 6307290101	50-204 8 50-322 S 50-352 K 50-277 F 50-277 F	SRITTON, W. H. SROAT, L. B. BROSST, G. E. BROCK, B. L. BROCK, B. L.	8307110187* 8307200220 8307110443 8307180117* 8307260482*	70-1151   50-443   9 50-317   8 70-1257   70-1007
BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8307060017 8307080332 8307080336 8307080374 8307080415	50-458 A 50-458 S 50-458 B 50-458 B 50-458 S	BOYLE, R. BOYLE, R. R. BRACKEN, K. W. BRADBURY, R. B. BRADBURY, R. B.	8307260204 8307260078 8307280034 8307070120 8307150257	WABTE MOT Wabte Mot 71-7156 Pr Pr	BRODBKY, A. BROEHL, D. J. BROEHL, D. J. BROEHL, D. J. BROEHL, D. J.	8307050471 8307060039 8307060076 8307110003 8307110143	NUREO 50-344 F 50-344 P 50-344 P

AUTHOR	ACCESSION NUMBER	N SUBJECT Category	AUTHOR	ACCESSION			ACCESSION	لسا
BROEKL, D. J.	8307120029	7 50-344 P		NUMBER	CATEGOR	RY AUTHOR	NUMBER	#UT 00
BROEHL, D. J. BROEHL, D. J.	8307180049	7 50-344 F	BURGESS, B. L. Burgmeier	8307140344		G CARROW, H.	9307670000	50
BROEHL, D. J.	B307190219 B307210223		BURGHEIER, M. J.	9307220325 8307110263		S CARROW, H.	9307070022 9307070023	50-40
RROEHL, D. J.	B3072200B		BURGHEIER, M. J.	8307150115	50~220	S CARROW, H.	8307070071	30 AO
BROEK, D.	D70710000	**	BURIAN, R. J.	8307050326	71-5957	CARROW, H.	8307070092 9307070092	50 40 50 40
BROEK, D.	8307120009 8307120012		BURKE, A. R.	8307210118	I= FDIA		4307070092	40~
BROMBERO, B. J.	8307150427		BURNETT, P. T.	8307210201	* 50-395	CARROW, H. CARTEAUX, P.	8307130244	•0"
BROMBERG, B. J. BRONS, J. C.	8307150433	CONTRACT	BURNETT,R,F. BURNETT,R,F.	8307110557		CARTER, C. E.	8307220426 83072 <b>5</b> 0693	* 30-34
	8307150018	50-286 S	BURNETT R. F.	8307110574 8307110580		CARTER, S.	8307220229	01 001
BRONS, J. C.	8307150254		Blinkerr n e			CARUSO, R.	8307060428	30 32
BRONS, J. C. BRONSTEIN, D. S.	8307220251 8307260395	30-286 R	BURNETT, R. F. BURNETT, R. F.	8307110633		C CARUSO, R.	8307250592	90,74
BRONSTEIN, D. S.	8307260395		BURNETT, R. F.	8307110637 8307110645	70-135 70-1201	CARVER, A. M.	B307120267	50-32E
BROWN, C. Q.	8307250483		BURNETT, R. F.	8307180005	70-371	CARVER, A. M. CARVER, A. M.	8307220235	30.32€
BROWN, C. H.	9307180013		BURNETT, R. F.	8307250507	70-1100	CASE, J. B.	8307220420 8307270240	50-32E 50-32E
BROWN, C. O.	9307200513	* 50-263 G 70-1257	BURNETT, R. F.	B307290314	70-1100	CACCIAL		145
BROWN, G. D. BROWN, G. D.	9307210015	40-8681	BURSTEIN, C. H. Burstein, C. H.	8307180145	50-3B2	G CASELLI, A. E		71-496
BROWN, C. D.	9307260189 9307260318	70-1406 40-8550	BURSTEIN, C. H.	8307180145 8307180153:	50-382 50-382	CASSIDY, B. P	8307130217	CONTRA 30-48
		10-6030	BURSTEIN, C. H.	83071801534		G CASSIDY, B. P	· 8307190237	
brown, O. D. Brown, P.	8307240490 8307240531	40-8722	BURSTEIN, C. H.	8307180160	50-382		6307190248	30-488
BROWN, R. B.	8307070194	50-298 G 50-443 G	BURSTEIN, C. H.	9307190160*		G CASTLE, M. N.	8307140127*	80-27
BROWN, R. S. BROWN, R. L.	8307080429	50-443 H	BURSTEIN, C. H. Burstein, C. H.	8307270052	50-382	CATTON, I. CATTON, I.	0307200482	ACR#
	8307150341#	50-458 Q	BURSTEIN, C. H.	9307290052 9307290056*		CATTON, I.	8307200506 8307200548	ACRE
BROWN, R. W.	8307260311	PR				CAVANAUGH, W.	8307010119	ACRE 50-382
BROWN, W. B. BROWN, W. B.	8307110548 8307110598	70-143	BURSTEIN, C. H. BURSTEIN, C. H.	8307290056* 8307290067*		C CERNE, A. C.	8307110426*	
BROWN, W. D.	9307110598	70-2609 70-734	BURSTEIN, C. H.	6307270067#		CHABANNES, C.	R. 8307270240*	HASTE
BROWN, W. B.	8307110630	70-27	BURTON, J. W.	8307120544		G CHAMBERLAIN, S CHAMBERS, Q. 1	D. 8307120284#	GASOF :
BROWN, H. B.	8307110655	70-143	BURWELL, S. B.	8306270605*	PR	CHANDLER, J. C	8307220217 8307010157#	50~257
BROWN, W. B.	B307110695	70-143 70-734	BURWELL, S. B.	8307200228	50-445	•		50-202
Brohn, H. L. Brohning, R. E.	8307050534*	REVIEW CRP	BURNELL, S. B. BUSH, M. W.	8307290500	50-445	A CHANDLER . I		50-275
BROWNING, R. E.	8307050278 8307050308	WASTE MOT	BUTLER, S. D.	9307050179 8307140077*		T CHANDLER, L., J	B307070201	50-275
DECEMBERS		WASTE MOT	BUTLER, S. D.	8307140092*		G CHANDLER, L. J G CHANEY, H. D.	9307130225	50-275 50-275
Browning, R. E. Browning, R. E.	6307180329 6307220110	HASTE MOT	BUTLER, T. A.	8307120176*	_	oriente er a. D.	8307210202*	50~445
BROWNING, R. E.	8307220116	WASTE MGT WASTE MOT	BUTTERFIELD, L.	8307210300	50-537 1 50-400 4	CHARGE N. C.	8307070119#	50-334
Browning, R. E. Browning, R. E.	6307220139	WASTE MOT	BUTTERFIELD.L. Byrd,r.	B307210300	50-400 4		8307010059	30-320 ·
	8307220146	WASTE MOT	BYRD, R.	8307120102 8307220296	50-416 E	CHAPLIN, S. D.	9307110441 9307110448	50~32 <b>0</b> 50~320
BROWNING, R. E. BROWNING, R. E.	8307220181	WASTE MOT	BYRD, R.		50-416 S	CHAPLIN, S. D.	8307210282	20-350
BROWNING, R. E.	8307260044 8307260057	WASTE MOT	CAHILL, W. J.	8307290128 8307190265	50-416 9		8307220537	-a :
BROWNING, R. E.	6307270463	WASTE MOT WASTE MOT	CAIN, C. L.	B307210020*	90-45B к 40-8681	CHAPLIN, S. D.	8307220550	50~320 50~320
BROWNING, R. E.	B307280249	WASTE MOT	CALDWELL, R. A. Callan, L. J.	<b>9</b> 307240296*	50~298 Q	CHAPLIN, B. D. CHAPMAN, R. H.	8307220565	50~320
BROWNLEE, V. L.	8307140030#	50-267 G		B307120074	20-313 E	CHARNLEY, J. S.	8307210260 8307120446*	NUREO :
BROWNLEE, V. L. BROWNLEE, V. L.	8307140185*	50~267 G 50~424 G	CALLAN, L. J. CAMPBELL, M.	8307120247*	50~313 G	CHARNLEY, J. S.		
BROWNLEE, V. L.	8307140195* 8307140476*	50-369 Q	CAMPBELL, M.	8307010158 8307010164	I&E	CHARNLEY, J. S.	9307200105* 930725 <b>0</b> 397	50~259
BROWNLEE, V. L.	8307220441*	50-321 Q 50-369 Q	CAMPBELL, R. D.	8307180307*	I&E 50-155 P	CHASON, J.	8307120467	TOPREP :
BROWNLEE, V. L.	575		CAMPSELL, R. D.	8307220411*	50-329 A	CHAUDHARY, S. # CHEN, J. C.	# #307210078*	50-352
BRUNNER, E. J.	830728030B 8307120311	50-366 8 50-307 R	CAMPBELL, R. K.	B3042B0403#	50-445 r		8307190457	NUREO
BRUNNER, E. J. BRUND, Q. E.	8307140174	50-309 R 50-423 A	CAMPBELL, W. E.	8307060385	50-445 I	CHEN, J. C. CHERDACK, R.	9307190464	NUREO
BRUNSON, B. Q.	8307180169 8307060109*	50-275 H	CANTER, H. CANTER, H. L.	8307060055	20-315 8	CHEW, G. P.	8307130358 8307190067*	RES
	020100104*	GA999	CANTRELL, F. S.	8307120519# 8307110307	50-312 Q 50-259 S	CHEZIK, M. T.	8307210172	50-237 50-354
BRYANT, J. BRYANT, J.	8305270643+	50-269 e	CANTRELL, F. S.		00 14, 3	CHIANGI, N. J.	8307110440	50-400
BRYANT, J.	8307140030* 8307290346*	50~269 Q	CANTRELL, F. S.	8307140184* 8307220078*	50-364 G	CHIANGI, N. J.	8307250399	50-400
BRYANT, R. H.	9307150371	CONTRACT Nureo	CANTRELL F. S.	8307220516*	50-395 Q 50-416 Q	CHIANGI, N. J.	9307260495	50-400
BUCK. J.	8307200532	ACRS	CANTRELL, F. S. CANTRELL, F. S.	B307220547*	50~259 G	CHIEN, F. F. CHILDS, W. N.	8307190280	XPORTLIC
BUCK. J.	8307200532	ACRS		8307220549*	50-34B G	CHILK, B. J.	8307050029* 8307050048	50-333
BUCKLEB, J. A. BUCKLEB, R.	B307200099	50~463 J	CANTRELL, F. S. CANTWELL, P. F.	8307220563*	50-395 Q	CHILK, B. J.		
BUCKLEY, B.	8307260599 8307290190	FOIA	CAREY, Q.	8307050066 8307220234	50-304 \$	CHILK, S. J.	9307050055 9307050115	50-361 50-322
BUCKMAN, F. W.	8307290113	50-275 Р 50-329 д	CAREY, J. J.	8307070115	50-254 g 50-334 p	CHILK, S. J.	8307050130	50-70
BUCKMAN, F. W.			CAREY, J. J.	B307120475*	50-334 q	CHILK, S. J.	8307050139	50-445
BUDZIK, D. M.	8307290191 8307260293	50-329 A Regod	CAREY, J. J.	8307150118	50~334 P		8307050150	50-155
BUFE, J. L. BUFE, J. L.	8307120249	50-302 g	CAREY, J. J. CAREY, J. J.	8307180118	50-334 P	CHILK, S. J.	8307050186	50-419
BUFE, J. L.	8307220254 8307290184	50-302 g	CAREY, J. J.	83072200115 8307220308	50-334 F	CHILK, S. J.	8307060325 8307070250	50-247 50-155
	0307E70184	50-302 B	CAREY, J. J.	8307270192	50-334 R 50-334 P	CHILK, S. J.	8307070252	50-153
BUNTING, J. G.		WASTE MOT	CAREY, J. J.	8307280244		CHILK, S. J.	8307070553	50-289
BUNTING, J. D.		FOIA WASTE MOT	CAREY, J. J.	8307280244	50-334 р 50-334 р	CHILK, S. J.	B3070B0432	50-153
BUNTING, J. Q.	8307260226	WASTE NOT	CAREY, J. J.	B307280298	80-334 K	CHILK'S' T'	83070900B1	50-413
BUNTING, J. C.		WASTE MOT	CARLISLE, C.S. CARLISLE, C.S.		50-397 Q	CHILK, B. J.	8307090090	10CFR 10CFR
BUNTING, J. O.	9307270460	WASTE MOT	•		50-397 Q	CHILK, S. J.	8307110564#	50-329
BUNTING, J. D. Bunting, J. D.	B307270472	WASTE MOT	CARLISLE.C.S. CARLISLE.C.S.		50-397 g	CHILK, S. J.		
BUNTING, J. D.		WASTE MOT WASTE MOT	CARLISLE, C. S.		50~397 s 50~397 s	CHILK, S. J.	B307130408	50-266 50-10
BUNTINO, J. O.	AAA	WASTE MOT	CARLISLE, C. S. CARLSON, J. D.	B307280359	50-397 A	CHILK, S. J. CHILK, S. J.	8307120A05	*n-27°
BUNTING, J. O.				8307120522*	50-275 G	CHILK, S. J.	E3071300A9	50-289 50-289
BURDOIN, J. F.	8307120568*	Waste mgt 50-528	CARPENTER, J. H.	8307120426*	50-322 G			
BURGER, C. Burger, C. W.	B307140195*	50-369 G	CARR, A. V. CARR, A. V.	8307130178	50-413 G	CHILK, S. J. Chilk, S. J.		50-322 50-275
BURGER, F. J.		30-324 Q 50-271 R	CARR, A. V.		50-413 G 50-413 G	CHILK, S. J.	830/180291	50-2/-
	,	m- • 13	CARR, A. V.		50-413 G	CHILK, S. J. Chilk, S. J.		
			•				8307190159	50-309

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHILK, S. J.	8307190163 8307200186 8307210301 8307220055 8307220060*	50-289 Q 10CFR 50-70 G 10CFR	CLARK, R. A.	8307270030* 8307270037 8307270050* 8307270059 8307270245	50-264 P 50-244 F 50-267 U 50-282 S 50-266 P	COLOMBO, R. W. COLOMBO, R. W. COMBG, F. C. COMBS, F. C. COMBB, F. C.	8307190161 8307280393 8307210080* 8307210083* 8307210321*	50-312 S 50-312 B FOIA FOIA FOIA
CHILK, B. J. CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J.	8307220119 8307250347 8307250352* 8307250357 8307250678	50-537 A 50-289 G 50-289 G 50-341 G 50-247 T	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8307270255 8307270261 8307270267 8307270303 8307270333	50-335 P 50-285 F 50-344 F 50-317 P 50-246 P	CONLEY, D. T. CONLON, T. E.	8307250651 8307250656* 8307270099* 8307270104* 8304200529*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-369 G
CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J.	8307260096 8307270117 8307270122 8307270128 8307280118	50-322 G 50-247 G 50-307 G 50-287 G 50-322 T	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8307280108 8307280465 8307290001 8307290464 8307290466	50-317 P 50-335 P 50-282 P 50-266 P 50-344 P	CONLON: T. E.	8307140124* 8307140133* 8307140156* 8307140249* 8307140385*	50-416. Q 50-413 Q 50-250 Q 50-424 Q 50-400 Q
CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J.	8307280122* 8307280136 8307280141* 8307280468 8307280469*	50-322 T 50-358 T 50-358 T 50-322 T 50-322 T	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLAUSS, J. M. CLAY, E. L.	8307270498 8307270543 8307270548 8307050094* 8307010003	50-285 P 50-309 P 50-309 P 50-387 Q 70-1201	CONLON, T. E. CONLON, T. E. CONNER, E. CONNER, E. CONNER, E. L.	8307220247* 8307220341* 8307280264* 8307280333 8307010025*	50-438 Q 50-389 Q 50-440 Q 50-219 8 50-219 Q
CHILK.B.J. CHILK.B.J. CHIRAMAL.M. CHIRAMAL.M. CHƏMACKE.A.C.	8307270216 8307270244 8307270324 8307270330* 8307180077	10CFR 10CFR 50~337 8 50~337 8 50~454 8	CLAY, E. L. CLAYTON, F. L.	8307140283* 8305100008 8307010132 8307010182 8307070080	70-1201 50-348 8 50-364 P 50-348 P 50-348 P	CONNER, E. L. CONNER, T. B. CONNER, T. B. CONNER, T. B. CONNER, T. B.	8307210078* 8307060409 8307060409 8307190191 8307190191	50-352 G 50-352 G 50-352 G 50-410 G 50-410 G
CHOULES, N. C. CHOULES, N. C. CHOULES, N. C. CHR ISBOT IMOS, N. CHR ISTEL, B.	8307080026* 8307200204* 8307280196* 8307250481* 8307060084	50-243 0 50-454 0 50-282 0 50-254 0 50-249 5	CLAYTON F. L.	8307070104 8307080272 8307080308 8307080402 8307080479	50-348 P 50-348 P 50-348 P 50-348 % 50-348 F	CONNER, T. B. CONNER, T. B. CONRAN, J. CONRAN, J. H. CONRAN, J. H.	8307190199 8307190199 8307260381* 8306080369* 8306080379*	50-358
CHR ISTEL. B. CHR ISTEL. B. CHR ISTENBURY. E. CHR IST IANSON, W. CHR ISTMAN, J. N.	8307200174 8307200218 8307120053 8307120584* 8307110358	50-237 S 50-249 S 50-338 G 50-358 G 50-322 G	CLAYTON: F. L.	8307120286 8307120483 8307120576 8307130262 8307140427	50-348 B 50-348 P 50-348 B 50-348 P 50-348 Q	CONRAN, J. H. CONSTABLE, G. L. CONWAY, J. T. CONWAY, R. E. CONWAY, R. E.	8305080374* 8307150284* 8307290129* 8307220195 8307220324	50-322 A 50-382 Q GA979 50-424 B 50-424 B
CHRISTMAN, J. N. CHRISTMAN, J. N. CHRISTMAN, M. T. CHRISTMAN, W. T. CHRISTOFFER, G.	8307120554 8307120554 8307210164 8307210164 8307120439*	50-322 0 50-322 0 50-322 0 50-322 0 50-373 0	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	8307150095 8307150097 8307150103 8307180095 8307190108	50-348 P 50-348 P 50-348 S 50-348 R 50-348 R	COOK; F. R. COOK; F. R. COOK; F. R. COOK; F. R.	830707012B 8307260027 8307260222 8307260276 8307260283	PROJ WASTE MOT WASTE MOT WASTE MOT
CHRIBTOPHER, W. CHRIBTOPHER, W. CHU, A. CHUNG, H. M. CHUNG, J. W.	8307120078 8307260552 8307150362* 8307070133 8307250060*	50-296 S 50-296 S 50-397 S NUREG FOIA	CLAYTON: F. L.	8307190113 8307190144 8307200106 8307220303 8307220338	50-364 R 50-364 P 50-364 P 50-348 S 50-348 S	COOK, J. W. COOK, J. W. COOK, J. W. COOK, J. W.	8307120527 8307060011 8307060356* 8307070152 8307080436	50-333 R 50-329 8 50-329 9 50-329 E 50-329 6
CILIMBERG, R. L. CILIMBERG, R. L. CILIMBERG, R. L. CLARE, G. H. CLARK, A. R.	8307080292* 8307140226* 8307210149* 8307110149* 8307090128	50-341 Q 50-546 G 50-461 Q 50-537 T PROJ	CLAYTON: F. L. CLAYTON: F. L. CLAYTOR: T. N. CLEMENTS: 8. R. CLEMENTS: 8. R.	9307220530* 9307290170 9307090133 9307210152 9307260391	50-348 G 50-348 S NUREG 50-445 K 50-445 S	COOK, J. W. COOK, J. W. COOK, J. W. COOK, J. W.	8307110405 8307120245 8307140211 8307180171 8307180270	50-329 A 50-329 A 50-329 A 50-329 B 50-329 B
CLARK, C. W. CLARK, D. CLARK, E. CLARK, K. M. CLARK, L.	8307210138 8307110639 8307070531 8307110252 8307280441	TOPREP 50-259 G XPORTLIC 50-259 S 50-20 P	CLEMONB, P. COATB, R. M. COBB, A. B. COCHRAN, T. B. COCHRAN, T. B.	8307110366* 9307060171 8307170106 8307120557 8307120557	50-334	coak, J. W. cook, J. W. cook, J. W. cook, J. W.	8307220402 8307250123 8307250431 8307260236 8307260320	50-327 A 50-327 G 50-327 S 50-327 E 50-327 A
CLARK, P. R. CLARK, P. R. CLARK, P. R. CLARK, R. A. CLARK, R. A.	8307220374 8307220485 8307260176 8307050288 8307050272	50-287 P 50-287 P 50-287 P 50-337 P 50-368 F	COFFEY, E. C. COFFEY, J. A. COFFEY, J. A. COFFEY, J. A. COFFMAN, F. D.	8307050285* 8307120219 8307220266 8307220433 8305050085*	CONTRACT 50-259 S 50-259 B 50-259 R 50-322 A	COOK, J. W. COOK, J. W. COOK, J. W. COOK, K. V. COOK, R. J.	8307260451 8307280191 8307280272 8307250511 8307050017*	50-327 G 50-327 S 50-327 S NUREQ 50-327 R
CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8307050298 8307050342 8307050432 8307060160 8307060174*	50-339 P 50-282 P 50-309 P 50-338 G 50-338 G	COFFMAN, F. D. COFFMAN, F. E. COFFMAN, F. E. COFFMAN, F. E. COGBURN, T. H.	8305050338* 8307110111 8307200475 8307270133 8307010044	50-322 A Waste Mot 50-201 P Waste Mot Toprep	CODK, R. J. COOL, D. A. COOL, D. A. COOL, D. A. COONEY, M. J.	8307140344* 8307060493 8307060497* 8307180006 8307210045	50-329 G 40-6940 40-6940 70-2982 50-277 R
CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8307060284 8307060373 8307080599 8307110288 8307110616	50-336 P 50-309 P 50-335 P 50-335 P 50-245 P	COOBURN, T. H. COHALAN, P. F. COHEN, I. COHEN, L. COHEN, T.	8307010044 8307050067 8307010048* 8307180124 8307110539*	TOPREP 50-322 G 50-220 G NUREG 50-244 G	COONEY: M. J. COONEY: M. J. COONEY: M. J. COONEY: M. J. COONEY: M. J.	8307220300 8307220404 8307220424 8307220466 8307220469	50-277 R 50-277 S 50-277 S 50-277 S 50-277 S
CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8307140107 8307140148 8307140159 8307150395 8307150403	50-368 G 50-336 P 50-307 P 50-266 P 50-368 P	COHN, B. M. COLBURN, T. G. COLE, G. F. COLE, R. F. COLEY, J. L.	8307200198* 8307250323 8307210047 8307280144 8307140041*	CONTRACT 50-244 P 50-358 A 50-352 G 50-259 G	COOPER: W. E. COOPER: W. E. COOPER: W. E. COOPER: W. E. COOPER: W. E.	8307050093 8307050245 8307060233 8307130097 8307130207	50-275 R 50-275 R 50-275 P 50-275 P 50-275 R
CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8307180437 8307190001* 8307190272* 8307190289 8307190376	50-282 F 50-387 P 50-335 P 50-307 P 50-317 P	COLLINS, D. M. COLLINS, D. M. COLLINS, J. T. COLLINS, S. COLLINS, S.	8307110183 8307250457 8307190103 8307280290* 8307280311*	I&E I&E 50-267 J 50-309 Q 50-286 Q	COOPER, W. E.	8307190044 9307200081 8307220334 8307260506 8307260539	50-275 P 50-275 R 50-275 P 50-275 R 50-275 R
CLARK; R. A. CLARK; R. A. CLARK; R. A. CLARK; R. A. CLARK; R. A.	8307250048* 8307250103 8307250107* 8307250463 8307270027	50~344 P 50~344 P 50~344 P 50~313 P 50~266 P	COLLINS, T. R. COLOMBO, R. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W.	8307140368* 83072605\$3 8307120521 8307180010 8307190109	50-327 G 50-312 R 50-312 S 50-312 S 50-312 S	CODPER, W. E. COPELAND, R. A. COPELAND, R. A. COPELAND, V. G. COPELAND, V. G.	8307280272 8307050009 8307150348 8307190124 8307190124	50-275 P TOPREP TOPREP 50-454 Q 50-454 Q

AUTHOR	NOTEREDOA REMUM	SUBJECT CATEGORY	AUTHOR	ACCESSIO	N SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	GUBJECT CATECORY
COPELAND, V. G COPELEY, W. G. COPLEY, W. G. COPLEY, W. G. COPLEY, W. G. COPPLEY, W. H.	9307260344 8307260344 8307210265= 8307210271+	50-329 G 50-329 G	COYLE, L. M. COYLE, L. M. COYLE, L. M. CRAGIN, J. G. CRAGIN, J. G.	830720019 830706023 830711035 830719004 830722033	7 50-237 B 7 50-237 B 8 50-275 P	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8307140415 8307150182 8307210145 8307250153 8307250480	50-255
CORMIER, W. H. CORVELL, Q. P.	8307060412 8307060417+ 8307060419+ 8307110133 8307110138+	50-142 0 50-142 0 50-142 0 50-142 0 50-142 0	CRANE, P. A.	8307050199 8307120573 8307130298 8307150218 8307180070	50-133 Q 1* 50-275 P 50-275 Q	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8307260443 8307260449 8307270299 8307270306 8307270344	50-206 B 50-244 p 50-213 p 50-213 p 50-29 0
CORYELL, G. P. COSTELLO, F. COSTELLO, F. COSTELLO, F. COSTELLO, J.	8307140460# 8307260492 8307180124 8307250413# 8307280170#	70-1151 70-143 NUREG 50-320 40-672	CRANE, P. A. CRAVEN, S. M. CRAWFORD, R. D. CRAWFORD, R. D. CRAWFORD, V. A.	8307250139 8307210255 8307180087 8307180092 8307040151	NUREG * 50-277 P * 50-277 P	CRUTCHFIELD, D. GRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CUMMINGB, J. J.	8307270373 8307270398 8307270434 8307270455 83072500444	50-155 p 50-237 p 50-155 p 50-409 p
COSTELLO, J. R. COSTELLO, O. COTTER, S. P. COTTER, B. P. COTTER, B. P. COTTER, B. P.	8307120442* 8307210358* 8307110043 8307190325	FDIA GA999 70-378 50-412 G 50-322 G	CRAWFORD, V. A. CRAWFORD, V. A. CRAWFORD, V. A. CREED, J. CREED, J.	8307060151 8307060156 8307060154 8307060334 8307080020	50-529 Q 50-529 Q 50-529 Q 50-295 8 50-295 S	CUMMINB, J. E. CUNNINOHAM, Q. E. CUNNINGHAM, Q. E. CUNNINGHAM, G. H. CUNNINGHAM, K. A.	8307120247# 8307150445 8307280004 8307180301 8307110524	50-313 q 71-9079 71-5971 50-329 A 70-371
COUNSIL.W.O. COUNSIL.W.O. COUNSIL.W.O. COUNSIL.W.O.	8306200394 8306200394 8307010010 8307010010	50-289	CREED, J. R. CREED, J. R. CREED, J. R. CREED, J. R. CREED, J. R.	9307050262: 9307120439: 8307180112: 9307220187 9307280325:	50-373 Q 50-282 Q 50-373 R	CUNNINGHAM, R. E. CUOMO, M. M. CURRAN, D. CURRAN, D. CURRAN, D.	8307090113 9307180082 8307070214 8307070214 8307120185	WABTE HOT 50-322 0 50-443 0 50-443 0 NUREO
COUNSIL, H. G. COUNSIL, H. G. COUNSIL, H. G. COUNSIL, H. G.	8307010074 8307010133 8307010133 8307010148	50-245 F 50-245 F 50-423 B 50-423 S 50-423 S	CRLENJAK, R. V. CROCKER, H. W. CROCKER, H. W. CROCKER, H. W. CROCKER, H. W.	8307140476* 8307010048* 8307010080* 8307110539* 8307140391*	50-220 Q 50-245 Q 50-244 Q	CURRAN, D. CURRAN, D. CURRAN, D. CURRAN, D. CURRAN, D.	8307120174 8307200208 8307200208 8307260337 8307260337	PR 50-443 0 50-443 0 50-443 0 50-443 0
COUNSIL, W. O. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G.	8307040082 8307040082 8307040134 8307040134	50-423 B 50-245 P 50-245 P 50-336 K 50-336 K	Cronenberg, A. W. Crosbie, K. L. Crosby, R. C. Crosby, R. C. Crossman, W. A.	8307250080 8307130181 8307130182* 8307120468 8307120430*	NUREQ XPORTLIC XPORTLIC 50-309 8 50-382 G	CURRAN, D. CURRAN, D. CURRIN, E. C. CURRIN, E. C. CURRIN, E. C.	8307240538 8307240538 8307070108 8307070108 8307070117*	50-443 0 50-443 0 PR PR
CONNEIL'N C CONNEIL'N C CONNEIL'N C	8307040182 8307080319 8307080319 8307080353	50-423 G 50-423 G 50-423 A 50-423 A 50-336 P	Crossman, W. A. Crossman, W. A. Crossman, W. A. Crossman, W. A. Crossman, W. A.	8307120447* 8307120505* 8307120531* 8307150148* 8307150284*	50-382	CURRIN, E. C. CURTIS, N. H. CURTIS, N. H. CURTIS, N. H. CURTIS, N. H.	8307070117# 8307010055 8307010099 8307050084 8307080369	PR 50-387 P 50-387 8 50-387 0
COUNSIL, W. Q. COUNSIL, W. Q. COUNSIL, W. Q. COUNSIL, W. Q.	8307080400 8307080400 8307110019 8307110019	50-336 P 50-336 P 50-336 P 50-245 F 50-245 F	CROSSMAN, W. A. CROUSE, R. P.	8307150341* 8307150091 8307050226 8307070041 8307070126	50-458 G 50-346 F 50-346 P 50-346 P PR	CURTIB, N. W.	8307110431 8307110437 8307110466 8307140105 8307150180	50-387 P 50-387 P 50-387 P 50-387 P 70-2983
COUNSIL.H Q COUNSIL.H Q COUNSIL.H Q COUNSIL.H Q	8307110390 8307120432* 8307120432* 8307120588	50-423	CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P.	8307070178 8307110120 8307110123* 8307120228 8307120411	50-346 Р 50-346 Р 50-346 Р 50-346 Р 50-346 Р	CURTIB, N. W.	8307220265 8307220483 8307260076 8307260300	50-388 E 50-387 S 50-387 F 50-388 R
COUNSIL. H. G. COUNSIL. H. G. COUNSIL. H. G. COUNSIL. H. G.	8307140241 8307140271 8307140271 8307140400	50-423 S 50-423 S 50-423 A 50-423 A 50-213 Q	CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P.	8307120413* 8307180177 8307210167 8307210302 8307210309*	50-346 P 50-346 Q 50-346 P 50-346 P 50-346 P	CURTIS, N. W. CUBTODIO, D. B. CUTCHIN, J. M. CUTCHIN, J. M. CUTCHIN, J. M.	8307260336 8307260337* 8307210196 8307210305 8307250360	50-387 P 50-387 P 50-219 8 50-440 0 50-440 0
COUNSIL. H. Q. COUNSIL. H. Q. COUNSIL. H. Q.	8307150193 8307150208 8307150208 8307150240	20-245 P 50-245 P 50-423 S 50-423 S 50-423 S	CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P.	8307260321* 8307260530 8307260537* 8307280069 8307280201	50-346 q 50-346 p 50-346 q 50-346 p 50-346 K	CUTCHIN, J. M. DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F.	8307270246 8307270250 8307010026 8307010081 8307040101	50-440 0 50-416 P 50-416 F 50-416 I
COUNSIL. H @ COUNSIL. H @ COUNSIL. H @ COUNSIL. H @ COUNSIL. H @ COUNSIL. H @	8307190131 8307190131 8307190131 8307190253	50-213 p 50-213 p 50-213 p 50-213 p	CROW, W. T. CROW, W. T. CROW, W. T. CROW, W. T. CROW, W. T.	8307080474* 8307110067* 8307110070* 8307150349 8307170026*	40-6264 70-1201 70-1201 70-920 70-2945	DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F.	8307180113 8307180131 8307180131 8307180175 8307180247	PR PR 50~416 P 50~416 P
COUNSIL. W 0 COUNSIL. W 0 COUNSIL. W 0 COUNSIL. W 0 COUNSIL. W 0	8307250469 5 8307260197 5 8307260197 5 8307260346 5	60-336 P 60-423 A 60-423 A 60-245 P	CROWLEY, B. R. CROWLEY, J. L. CRUMP, Q. R. CRUTCHFIELD, D. CRUTCHFIELD, D.	8307220400* 8307210260 8307220346 8307050007 8307050012*	50-335 Q NUREQ 50-445 Q 50-155 P 50-155 P	DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F.	8307190073 8307210177 8307210195 8307220368 8307250225	50-416 P 50-416 P 50-416 P 50-416 E 50-416 P
COUNSIL. H. C. COUNSIL. H. C. COUNSIL. H. C. COUNSIL. H. C. COUNSIL. H. C.	8307260453 56 8307260453 56 8307260522 56 8307260522 56	0-245 P 0-245 P 0-245 P 0-245 P	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8307060175 8307060184 8307060263 8307060269 8307060294#	50-155 P 50-244 P 50-244 P 50-244 P 50-155 P	DALTROFF, S. L. DALTROFF, S. L. DALTROFF, S. L. DALTROFF, S. L.	U307140298	50-416 R 50-277 P 50-277 Q 50-277 P 50-277 P
CONTILLIC COX. D. L. COX. H. T. COX. H. T.	8307180240 50 8307010025* 50 8307190236 71 8307110294 50	0-312 8 0-219 q 1-501 0-261 s	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	9307080303 9307080306	50-217 Q 50-219 Q 50-255 F 50-247 P 50-255 P	DALTROFF, S. L.  DALTROFF, S. L.  DALTROFF, S. L.  DALTROFF, S. L.  PALTROFF, S. L.	8307150258* 8307200298 8307250474* 8307250480*	50-277 q 50-277 p 50-277 f 50-277 F 50-277 F
COX.H. T. COX, N. D. COYLE. C.	8307290106 50 8307290179 50 8307250080 MJ		CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8307080396* 8307130011 8307130265 8307130303	50-255 P 50-244 P 50-237 P 50-237 P 50-409 F	DALTROFF, S. L.  DALTROFF, S. L.  DANCE, H. C.  DANCE, H. C.  DANCE, H. C.	8307270043# 8307280286 8304200521# 8305270412	50-277 F 50-277 Q 50-369 Q 50-269 Q
					•••	DANCE, H. C.	0707010041	10-351 d 10-369 d

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT
DANCE, H. C.	8307140026 8307140065 8307140070 8307140083 8307140097	50-259 G 50-250 P 50-413 G 50-250 G 50-387 Q	DENTE: T. J. DENTON: H. R.	8307010188 8307060321 8307060429 8307140544 8307170310	TOPREP 50-287 H 50-286 H PR 50-287 P	DIECKAMP, H. DIEDERICH, G. J.	8307170148 8307050070 8307050088 8307050146 8307060054	50-289 P 50-373 8 50-373 8 50-373 8 50-373 8
DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C.	8307140129 8307140131 8307140147 8307140151 8307140177	50-413	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	B307200390 B307250344* B307250616* B307250622* B307250634*	50-447 D 50-289 G PR PR PR	DIEDERICH, G. J.	8307060331 8307060333 8307060342 8307110408 8307110416	50-373 S 50-373 S 50-373 S 50-373 S 50-373 S
DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C.	8307140191 8307140245 8307140253 8307140274 8307140274	50-250 G 50-424 G 50-424 V 50-389 G 50-302 F	DENTON, H. R.	8307260134 8307260516 8307260525* 8307260563*	50-250 8 50-322 A 50-322 A 50-322 A	DIEDERICH; G. J. DIEDERICH; G. J. DIEDERICH; G. J. DIEDERICH; G. J. DIEDERICH; G. J.	8307110468 8307180191 8307210001 8307210048 8307210065	50-373 8 50-373 8 50-373 6 50-373 9 50-373 8
DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C.	8307140300 8307140302 8307140308* 8307140319 8307140353	50-335 V 50-369 G 50-369 G 50-321 V 50-338 F	DENTON, H. R. DENTON, H. R. DENTON, H. R. DER JENZO, P. P. DERKS, P. S.	8307260594# 8307270047 8307290045 8307150273 8307220492	50-322 A 50-267 U 50-272 B 50-445 B 50-133 R	DIEDERICH, G. J.	B307210148 B307220173 B307220200 B307220201 B307220542	50-373 8 50-373 8 50-373 R 50-373 6 50-373 6
DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C.	8307140394 8307140405* 8307140420 8307150347 8307190041	50-335 G 50-335 G 50-335 F 50-335 G 50-338 G	DEBAI: R. H. DEBLANDES: K. D. DEBMAN: R. J. DEVINCENTIS: J. DEVINCENTIS: J.	8307130333* 8307040024 8307280227 8307040035 8307060035	50-454 A 50-336 S 40-8724 50-443 A 50-443 A	DIETZ, C. R. DIETZ, C. R. DIETZ, C. R. DIETZ, C. R. DIETZ, C. R.	8307110432 8307110510 8307120127 8307120291 8307130212	50-324 S 50-325 S 50-324 S 50-325 S 50-324 R
Dance, H. C. Dance, H. C. Dance, H. C. Dance, H. C. Dance, H. C.	8307210240 8307220015 8307220028 8307220214 8307220224	50-302 Q 50-335 Q 50-389 Q 50-338 Q 50-338 Q	DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	B307060090 B307060090 B307060129 B307060129 B307120312	50-443 E 50-443 E 50-443 E 50-443 E 50-443 E	DIETZ, C. R.	8307150024 8307150102 8307150242 8307220405 8307220566*	50-324 S 50-325 S 50-324 S 50-325 S 50-324 Q
DANCE; H. C. DANCE; H. C. DANCE; H. C. DANCE; H. C. DANCE; H. C.	8307220324 8307220335* 8307220381 8307220395* 8307220431	50-389 G 50-389 G 50-335 G 50-335 G 50-349 G	DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8307120312 8307140222 8307140222 8307150094 8307150096	50-443 E 50-443 B 50-443 B 50-443 B 50-443 B	DIETZ, C. R. DIETZ, C. R. DIETZ, C. R. DIETZ, C. R. DIGGS, R. M.	8307240397 8307240404 8307240496 8307270132 8307140118	50-325 8 50-324 5 50-324 8 50-324 8 50-349 P
DANCE, H. C. DANCEE, F. L. DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H.	8307220488 8307250538* 8307080014* 8307080292* 8307140080*	50-387 Q FOIA 50-454 Q 50-341 Q 50-483 Q	DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8307150285 8307150285 8307180318 8307180318 8307210191*	50-443 S 50-443 S 50-443 S 50-443 S 50-443 T	DIGGS: R. M. DIGGS: R. M. DIGGS: R. M. DIGGS: R. M. DIGNAN, T. G.	83071 80417 93071 90028 83071 90372 93071 90436 93071 20379	50-244 P 50-250 P 50-301 G 50-286 P 50-443 G
DANIELBON, D. H. DANIELBON, D. H. DAVIDBON, L. R. DAVIB, B. DAVIB, F. D.	8307140226# 8307210149# 8307210272# 8307030095 8307070212	50-546 Q 50-461 Q 50-413 Q 50-289 H 50-289 Q	DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8307220279 8307220279 8307220367 8307220372 8307220372	50-443 8 50-443 6 50-443 8 50-443 8 50-443 8	DIGNAN, T. G. DIGNAN, T. G. DIGNAN, T. G. DIGNAN, T. G. DIIANNI, D. C.	8307120379 8307120383 8307120444 8307120444 8307050283	50-443
DAVIB.J. DAVIB.J.G. DAVIB.J.G. DAVIB.J.G. DAVIB.J.G.	8307050112 8307050305 8307180313 8307250579* 8307250601*	ILE Wabte mot Waste mot Foia Foia	DEVINE, J. B. DEVINE, J. B. DEVINE, T. DEVINE, T. DEVINE, T.	8307180379 8307210277 8307050052 8307050052 8307150312	XPORTLIC XPORTLIC 50-358 G 50-358 G 50-358 G	DILLON, P. B. DINITZ, I. DINITZ, I. DINWIDDIE, G. A. DIRCKS, W. J.	8307220419* 8307050338 8307060273 8307220185 8208030682*	50-382 A 70-2957 50-141 J HASTE MGT 50-272 S
DAVIS, J. G. DAVIS, J. G. DAVIS, J. G. DAVIS, J. G. DAVIS, J. G.	8307270467 8307280221 8307280231 8307270347 8307270349*	HABTE MOT WABTE MOT WABTE MOT WABTE MOT WABTE MOT	DEVINE,T. DEVINE,T. DEVINE,T. DEVINE,T. DEVINE,T.	8307150312 8307150317* 8307150317* 8307150322 8307150322	90-358 0 50-358 0 50-358 0 50-358 0 50-358 0	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J.	8208040324# 8303180682 8305250555# 8307050502 8307070487	FDIA PR 50-317 P SECY SECY
DAVIS, L. D. DAVIS, L. D. DAVIS, M. S. DAVIS, P. R. DAVIS, P. R.	8307070133 8307070248 8307260016 8307170323 8307170323	PR PR Waste mot Acre Acre	DEVINE.T. DEVINE.T. DEVINE.T. DEVINE.T. DEVINE.T.	9307150324* 9307150324* 9307150327* 9307150327* 9307150331*	50-358	DIRCKS, H. J. DIRCKS, H. J. DIRCKS, H. J. DIRCKS, H. J. DIRCKS, H. J.	8307090096 8307110103 8307110555 8307110634 8307140121	50-331 P 30-272 S 50-329 A 50-389 P 50-272 H
DAVIS: P. R. DAVIS: T. L. DAWSON: D. M. DAWSON: D. M. DE LORENZO: R.	8307250080 8307200513 8307280038 8307290335 8307280279	NUREG 70-1257 70-1308 71-4 50-440 B	DEVINE,T. DEVINE,T. DEVINE,T. DEVINE,T. DEVINE,T.	8307150331* 8307150338* 8307150338* 8307220354 8307220355*	50-358	DIRCKS, N. J. BIRCKS, N. J. BIRCKS, N. J. BIRCKS, N. J. BIRCKS, W. J.	8307140499 8307140501 8307180391 8307190481* 8307200151	50-275 P 50-272 S MISC 50-322 A REVIEW GRP
DE LORENZO, R. A DE LORENZO, R. A.	8307180034 8307120241 8307120479 8307180144 8307280345	50-460 8 50-513 8 50-460 8 50-460 8 50-460 8	DEVINE, T. DEVLIN, J. W. DEWEY, L. S. DEWEY, L. B. DEWEY, L. S.	9307250282 8307250060* 9307210039 9307210041* 8307210276	50-358	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J.	8307220079 8307250038* 8307250263 8307250565	FOIA 50-272 P 50-334 S 50-289 G SECY
DEAGAZIO, A. W. DEAGAZIO, A. W. DEBBAGE, A. G. DEBBAGE, A. G. DEBBAGE, A. G.	8307080611 8307220617 8307140236* 8307140421* 8307220302*	50-346 P 50-346 P 50-280 G 50-302 G 50-416 G	DEWITT, R. B. DEWITT, R. B. DEWITT, R. B. DEYOUND, R. DEYOUNG, R. C.	8307060057 8307060059 8307060061 8307260101 9307050212	50-329 A 50-329 E 50-329 E MISC 50-482 G	DIRCKS, H. J. DIRCKS, H. J. DIRCKS, H. J. DIRCKS, H. J.	9307250578 9307250599+ 9307270017 9307270054 9307280235	50-257 P PR 50-320 H 50-247 U WASTE MGT
DEBONB, A. DEEDB, W. E. DEITRICH, L. W. DEJU, R. A. DELLA RATTA, A.	8307200493 8307210268 8307110158* 8307270296* 8307140281*	ACRS NUREO 50-597 T WASTE MOT 70-364	DEYDUNG, R. C. DEYDUNG, R. C. DEYDUNG, R. C. DEYOUNG, R. C. DEYOUNG, R. C.	9307050217* 9307050501 9307050505* 9307050527* 9307060399*	50-482 G 50-454 G 50-456 G REVIEW GRP 50-358 G	DISE, D. P. DITTO, S. J. DITTO, S. J. DITTO, S. J. DITTO, S. J.	8307210059 8307200038 8307200038 8307220032 8307220032	50-410 S ACRS ACRS ACRS ACRS
DELOATCH, V. DELWICHE, D. E. DEMPBEY, K. C. DENIBON, E. T. DENNIBON, B. F.	8307180325 8307140350* 8307110279* 8307130258 8307190313*	CONTRACT 50-220 P 50-413 Q 50-275 R CONTRACT	DEYDUNG, R. C. DEYDUNG, R. C. DEYDUNG, R. G. DICKERSON, M. H. DICKBON, J. H.	8307060403* 8307110329* 8307250497 8307150140* 8307220626	50-358 G REVIEW GRP MISC 50-267 G NUREG	DIVINE, J. R. DIVINE, J. R. DIXON, J. P. DIXON, O. W. DIXON, O. W.	8307150178 8307180165 8307270186 8307050209 8307060272	NUREG NUREG 50-375 8 50-375 P 50-375 P

AUTHOR	Accessic Number	CATE		AUTHOR	ACCESSIO NUMBER	CATE	JECT EGDRY	AUTHOR	ACCESSION NUMBER	N SUBJ CATE	ECT CORV
DIXON.O W DIYON.G W DIXON.O W DIXON.O W	8397110210 8397110262 8397110370 8397120091 8397120196	50-37 50-37 50-37	5 S 5 S	DRUMMOND, F. J.	830722041 830726011 830726012 830726022 830726023	2 50~38 4 50~38 6 50~38 5 50~38	32 A 32 S 32 S	EDELMAN, M. EDELMAN, M. R.	8307250416 8307050203 8307040045 8307040277 8307040278	5 PR 5 50-44 5 50-44	O A O 8 O F
D1xON O W D1xON O W D1xON O W D1xON O W	9307120269 9307120459 9307140213 9307140213 9307140250	50-373 50-373 50-373	s s	DRUMMOND, F. J.	830726039; 830726047( 830726048; 830726051; 830726051;	7 50-38 7 50-38 1 50-38	2 E 2 A	EDELMAN, M., R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R.	8307080451 8307110134 8307110314 8307180031 8307190038	* 50-440 50-440 50-440 50-440	0 0 8 0 8 0
DIXGN.O W DIXON.O W DIXON.O W DIXON.O W DIXON.O W	0307220055 6307220172 0307220252 0307220254 6307220274	50-375 50-375 50-395 50-395	R S S	DRUMMOND, F, J.	8307260560 8307260562 8307260565 8307280363 8307270104	50-38; 50-38; 50-38;	5 G 5 E	EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R.	8307190134 8307190176 8307190204 8307200289 8307210077	50-440 50-440 50-440 50-440 50-440	) s
BIXON D W DIXON D W DIXON D W DIXON D W	5307820283 8397920284 6307920380 8307220454 8307220473	50~395 50~395 50~395 • 50~395	5 P S O	DUBE, R. J. DUBE, R. J. DUBQIB, D. L. DUCK, J. R. DUCK, J. R.	8307110553 8307120203 8307150315 8307080031 8307130187	* 50-537 * 50-298 50-327	7 T 3 G 7 J	EDELMAN, M. R. EDOAR, O. L. EDOAR, O. L. EDOAR, O. L. EDOAR, O. L.	8307220434 8307110142 8307110142 8307180266 8307180266	50-440 50-537 50-537 50-537 50-537	, T
DIXON O H DIXON O H DIXON O H DIXON O H DIXON O H	9307220552 9307250138 8307250201 8307250496 9307250515	50~395 50~395 50~395 50~395	9 8 8 8	DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R. DUGGIN, G. E. DUGSTAD, D.	8307130257 8307200008 8307200146 8307290094 8307150065	50-255 50-327 50-259 50-327 50-282	, 1 1	EDGAR, G. L.	9307220350 9307220350 9307250369 9307260369 9307260369	50-537 50-537 50-537 50-537 50-537	0
DIXON.O W	8307260340 8307260394 8307260461 8307260465 8307260557	50-395 50-395 50-395 50-395 50-395	5 6 6	DUNAWAY, F. R. DUNLAP, J. M. DUNLAP, J. M. DUNLOP, J. DUNN, K.	8307200204: 8307110425: 8307140410: 8307040027 8307250544	50-286	G Q	EDGEWORTH, P. EDISON, G. E. EDISON, G. E. EDWARDS, D. W. EGLE, D. M.	8307250667 8307130292 8307270037 8307080366* 8307150172*	CONTRAC 50-483 50-482 50-29	CT A
DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8397270995 8397270918 8397270942 8397270985	50-395 50-395 50-395 50-395 50-395	P P F P	DUPONT, D. DUPONT, S. G. DUPREE, D. DURBIN, S. L. DURBIN, S. L.	8306170403 8307140422* 8307220474 8307050241 8307060405*	50-327 50-275	T G R C O	EICH, E. F. EICH, E. F. EICHBAUM, W. M. EICHENHOLZ, M. EICHENHOLZ, M.	8307220365 8307220429 8307140493* 8307140409* 8307280449*	50-247 50-247 CONTRAC 50-293	R R ST
DIXON, O W DOBSON, D E DODD, C V. CODDS, R T DODSON, J P	8307276092 8307270175 8307280356 8307216268 8307120537*	50-395 50-395 50-508 NUMEG 50-397	P S A G	DURBIN, S. L. DURBIN, S. L. DURBIN, S. L. DURBIN, S. L. DURRIN, S. L.	8307060415* 8307130072 8307150357 8307200122 8307010049	50-275 50-275 50-275 50-275 50-278	0 0 0 8	EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8208060366 8305110506 8306060070 8306080370*	50-293 50-387 50-275 50-29 50-322	Q P R P
DOERFLEIN.L T COMERTY.J F DOOLITILE.E L CORCSHOW, J DOROSHOW, J	6307150129* 8307110421* 8307290082 6307040494 8307060393	0A979 30-333 50-537 50-423 50-269	Q H A G	DURR, J. DURR, J. P.	8307060027* 8307010146* 8307060124* 8307210025* 8307210026*	50-244 50-271 50-271 50-293 50-423	0 0 0 0	EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8306160669* 8306270395 8306270395 8306270396 8306270397	50-331 50-322 50-322 50-275 50~3	P A A R
DORDSHOW, J DORSEY, J A DORSEY, J A DORSEY, J A DORSEY, J A	6307130228 6307270127 8307110420 8307180134 8307180134	50-289 50-289 PR 50-352 50-352	6 6 6	DUS; R. DUS; R. DUS; R. DUS; R. DUVALL; D. D. DYNNER; A. R.	8307210001 8307210065 8307210148 8307110377* 8307050046	50-373 50-373 50-373 50-373 50-322	9 8 8	EISENHUT, D. Q.	8306270398 8306270400 8306270407 8306270417 8306270419	50-275 50-275 50-275 50-275 50-275	R A P P
DORSEY, J A DORSEY, J A DORSEY, J A DORSEY, J A DORSEY, J A	8307290088 8307290088 8307290093* 8307290093* 8307290099*	50-352 50-352 50-352 50-352 50-352	6666	DYNNER, A. R. DYNNER, A. R. DYNNER, A. R. DYNNER, A. R. DYNNER, A. R.	8307050046 8307110296 8307110296 8307260302 8307260302	50-322 50-322 50-322 50-322	0 0 0	EIBENHUT, D. Q.	8307050349 8307050458* 8307060329 8307060482 8307070557*	50-275 50-272 50-3 50-522	F P D
DORSEY, H DORSEY, H DORSEY, M DORSEY, M DORSEY, M	8307290099 8307050284 8307050317 8307140115 8307140523	50-352 CONTRACT CONTRACT CONTRACT CONTRACT	0	DYNNER, A. R. DYNNER, A. R. EAPEN, P. K. EAPEN, P. K. EARLEY, A. F.	8307240347 8307240347 8307210014* 8307280283* 8307080184	50-322 50-322 50-322 50-247 50-333 50-322	0 0 0	EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8307080169 8307080427 8307080463 8307080655# 8307080684	50-321 50-3 50-2 50-346 50-278 50-354	P V F P.
DOUGHERTY, C U DOUGHERTY, U B DOUGHERTY, U B DOUGHTY, U DRUMMOND, F. U	8307120477 8307120477 8307120347* 8307270159* 8307150279	50-322 50-322 NUREO	R G G	EARLEY, A. F. EARLEY, A. F. EARLEY, A. F. EARLEY, A. F. EARLEY, A. F.	8307080184 8307080174 8307120573 8307120573 8307120576*	50-322 50-322 50-322 50-322 50-322	G G O O O O	EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8307110002 8307120128* 8307120145* 8307140134 8307140135*	50-254 50-254 50-254 50-382 50-324	A P F F F
DRUMMOND, F. J DRUMMOND, F. J DRUMMOND, F. J DRUMMOND, F. J DRUMMOND, F. J	B307050021 B307050170 B307050170 B307050406 B3070602460	50-382 50-382 50-382 70-2946	E S S	EARLEY, A. F. EARLEY, A. F. EARLEY, A. F. EARLEY, A. F. EBERSOLE, J.	8307120616* 8307260409 8307270140 8307270140 8307270995	50-322 50-322 50-322 50-322 50-29	0 0 0	EIGENHUT, D. G. EIGENHUT, D. G. EIGENHUT, D. G. EIGENHUT, D. G. EIGENHUT, D. G.	8307140149 8307140163 8307140509# 8307140515# 8307140516#	50-443 50-309 50-333 50-220	P A F P
DRUMMOND, F. J.	9307060251 9307060314 9307060332 9307080298	50~382 / 50~382 / 50~382 /		EBERSOLE, J. C. EBERSOLE, J. C. EBNETER, S. EBNETER, S. D. ECKHART, J. H.	8307050316 8307120417 8307010049 8307210226* 8307120551*	ACRS PR 50~278 50~412	0 0	EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8307150048* 8307150408 8307150414 8307150441	50-389 50-382 50-368 50-275	P P F P
DRUMMOND, F. J.	83071 20046 83071 20046 83071 20202 93071 20516	50-382 F 50-382 F 50-382 F 50-382 S	<del>.</del> 	EDDLEMAN, H. EDDLEMAN, H. EDDLEMAN, H. EDDLEMAN, H. EDDLEMAN, H. EDDLEMAN, H.	8307040159 8307040383 8307040384* 8307040391* 8307040402	50-400 50-400 50-400	G G G	EIBENHUT, D. G.	8307180008 9307180058* 9307190359 8307200233 8307200377	50-271 50-263 50-356 MISC	P Q F A
DRUMMOND, F (S DRUMMOND, F (S DRUMMOND, F (S DRUMMOND, F (S	8307150261 8307150289 8307150339	50-382 s 50-382 s 50-382 s 50-382 s 50-382 s		EDDLEMAN, H. EDDLEMAN, H. EDDLEMAN, H. EDDLEMAN, W. EDDLEMAN, W. EDELMAN, J. Q.	8307150188 8307260248 8307260281 8307260341	50-400 50-400 50-400	0 0 0 0 0 0	EISENHUT, D. G.	8307260559	100-06	F 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EISENHUT, D. G. EISENHUT, D. G. EISENMANN, L. L. EL-AGHRY, M. T. EL-AGHRY, M. T.	9307270356* 9307270462 9307050536 9307050071 9307290230	50-261 P 50-272 G XPORTLIC 50-327 R 50-259 S	FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W.	6307070113 8307110343* 6307110487* 8307120364 8307130220	50-266 P 50-266 P 50-266 P 50-266 P	FELTON, J. M.	8307290293 8307290442 8307290452 8307290467 8307290514	50-275 F FOIA FOIA FOIA 50-321 F
ELLERSHAW, L. E.	8307040347*	GA799	FAY, C. W.	8307130224	50-266 P	FELTON, J. M. FELTZ, D. E. FELTZ, D. E. FENSTERSTOCK, J. FENSTERSTOCK, J.	8307290539	50-349 F
ELLERSHAW, L. E.	8307040382*	GA999	FAY, C. W.	8307140240	50-266 P		8307260223	50-128 P
ELLIOT, B. J.	8307110293*	50-413 G	FAY, C. W.	8307150044	50-266 R		8307260500	50-128 P
ELLIOTT, P. E.	8307120446*	50-265 P	FAY, C. W.	8307190018	71-7010		8307250629*	CONTRACT
ELLIOTT, P. E.	8307200105*	50-259 P	FAY, C. W.	8307190174	50-301 S		8307250640*	CONTRACT
ELLIB, J.	8305200618	50-445 G	FAY, C. W.	8307220210	50-301 S	FENSTERSTOCK, J. FERRANTE, J. FEY, F. L. FIALA, D. FIEDLER, P. B.	B307250647*	CONTRACT
ELLIB, J.	8307120323	PR	FAY, C. W.	8307220354	50-266 P		B307080563*	CONTRACT
ELLIB, J.	8307200211	50-445 G	FAY, C. W.	8307250157	50-266 P		B3071B0327*	50-282 F
ELMB, A.	8307220367	50-213 R	FAY, C. W.	8307260335	50-266 F		B307150237	PT21
ELROD, S. A.	8307140154*	50-335 G	FAY, C. W.	830726043 <del>7</del>	50-266 K		B307010056*	50-219 Q
ELROD, S. A.	8307140418*	50-335 Q	FAY, C. W. FEIERABEND, C. D. FEIL, R. A. FEITKNECHT, C. FELTON, J. M.	8307270145	50-301 P	FIEDLER, P. B.	8307010143	50-219 P
ELSASSER, T.	8307010011	50-273 B		8307040328*	50-292 Q	FIEDLER, P. B.	8307040008	50-219 P
ELSASSER, T. C.	8307010167*	50-245 Q		8307120537*	50-397 Q	FIEDLER, P. B.	8307040139	50-219 P
ELSASSER, T. C.	8307110401*	50-146 Q		8307270182	50-334 R	FIEDLER, P. B.	8307080010	50-219 P
ELSASSER, T. C.	8307140106*	70-487		8210170028	50-331 F	FIEDLER, P. B.	8307080424	50-219 F
ELBABBER, T. C. ELBABBER, T. C. ELBABBER, T. C. ELBEN, M. J. ELHARD, T. W.	8307150352* 8307210075* 8307280200* 8307260456* 8307150257	50-213 G 70-371 50-179 G 27-48 PR	FELTON, J. M.	8304140014 8307110159 8307110173 8307110179 8307110194	50-285 F 50-338 F 50-321 F 50-280 F 50-346 F	FIEDLER, P. B.	8307200006 8307210169 8307210196 8307220168 8307250231	50-219 P 50-219 G 50-219 B 50-219 R 50-219 F
EMCH, R. L.	8307010084	50-155 P	FELTON, J. M.	8307110205	50-274 F	FIEDLER, P. B.	8307260202	50-219 P
EMCH, R. L.	8307050248	50-155 P		8307110317	50-397 F	FIEDLER, P. B.	8307260208*	50-219 P
EMCH, R. L.	8307110030	50-155 P		8307110325	50-307 F	FIEDLER, P. B.	8307280443*	50-219 G
EMCH, R. L.	8307180020	50-155 P		8307110339	50-266 F	FIELDB, H. C.	8307220454	50-395 S
EMCH, R. L.	8307250144	50-155 P		8307110357	50-250 F	FIELDS, J.	8307220459	CONTRACT
EMCH, R. L.	8307260499	50-155 P	FELTON, J. M.	8307110474	50-280 F	FIELDS, J. A.	8307200153	CONTRACT
ENGEL, W. P.	8307290361	71-6400	FELTON, J. M.	8307110559	50-409 F	FIELDS, J. A.	8307200159	CONTRACT
ENGELDER, T. C.	8307290143*	70-824	FELTON, J. M.	8307110570	50-324 F	FIELDS, J. A.	8307200188	CONTRACT
ENGL 16H, W. A.	8307270180*	50-438 Q	FELTON, J. M.	8307110595	50-289 F	FIELDS, J. A.	8307200204	CONTRACT
ENNIS, J.	8307080460*	70-143	FELTON, J. M.	8307110403	50-27 F	FIELDS, J. A.	8307200221	CONTRACT
EPLER, E. P.	8307220018	ACRS	FELTON, J. M.	8307110607	50-315 F	FILBURN, T. FILBURN, T. FILKINS, D. FINAMORE, B. A. FINDLEY, D. E.	8307010030	50~336 S
EPLER, E. P.	8307220018	ACRS	FELTON, J. M.	8307120023	30-286 F		8307050104	50~336 S
ERICKSON, P. B.	8307260524	50-213 P	FELTON, J. M.	8307120025	50-244 F		8307220377	50~244 S
ERLANDSON, B. G.	8307280042	WASTE MOT	FELTON, J. M.	8307120033	50-255 F		8307070101	PR
ERLANDSON, B. G.	8307280070	WASTE MOT	FELTON, J. M.	8307120039	50-317 F		8307050496*	CONTRACT
erlandgon, B. C. Ernst, M. D. Ernst, M. D. Eskridge, H. E. Etheridge, M. R.	8307280124 8307260573 8307260576* 8307200525 8307150286*	WASTE MOT 50-293	FELTON, J. M.	8307120042 8307120049 8307120051 8307120058 8307120062	50-382	FINKEL, A. FIORELLI, O. FIREBAUGH, L. FIREBAUGH, L. FIREBAUGH, L.	8307210226* 8307280304 8307280415* 8307280421* 8307280427*	50-412 Q 50-528 S 50-369 P 50-369 P 50-369 P
EURY, L. W. EVANB, C. A. EVANB, C. A. EVANB, C. D. EVANB, D. O.	8307250120 8307060040* 8307060291* 8307140428* 8307190457	50-261 P 50-285 Q 50-313 Q 70-143 NURÉO	FELTON, J. M.	8307120049 8307120080 8307120600 8307120612 8307180249	50-289 F 50-317 F 50-315 F 50-409 F 50-321 F	FISHER, F.D. FISHER, F.D. FITZGIBBONS, R. FITZGIBBONS, R. FITZGIBBONS, R.	8307270445 8307270447* 8307210217* 8307210217* 8307250365	70-398 70-398 50-454 G 50-454 C 50-454 C
EVANB, D. G.	8307190464	NUREQ	FELTON, J. M.	8307180300	50-344 F	FITZGIBBONG, R.	8307250365	50-454 G
EVANB, J.	8307180306*	50-346 F		8307180314	50-348 F	FLACK, E.	8305120177	1&E
EVANB, J. H.	8307190035*	71-5552		8307180323	50-282 F	FLACK, E.	8307140311	1&E
EVANB, P. A.	8307270180*	50-438 Q		8307180330	50-320 F	FLAHERTY, J. A.	8307010179*	50-322 A
EVERETT, R. J.	8307210020*	40-8681		8307180402	50-155 F	FLANAGAN, D. O.	8307070192	50-322 G
EVERETT, R. J. EVERBOLE, R. E. FAIROBENT, J. E. FALCONER, D. FALCONER, D.	8307260325*	40-8550	FELTON, J. M.	8307180405	50-307 F	FLEENOR, C.	8307070503	CONTRACT
	8307170035*	71-5552	FELTON, J. M.	8307200010	70-143	FLEENOR, C.	8307140481	CONTRACT
	8307110279*	50-413 0	FELTON, J. M.	8307200523	FOIA	FLEENOR, C.	8307250540	CONTRACT
	8308270643*	50-269 0	FELTON, J. M.	8307210054	70-378	FLIPPO, T. A.	8307150284*	50-382 G
	8307140030*	50-269 0	FELTON, J. M.	8307220044	50-358 G	FLORY, C.	8307200224	WASTE MOT
FANNING, G.	9307200287	50-295 B	FELTON, J. M.	8307220106	FOIA	FLORY, C.	8307210021	WASTE MGT
FARAHZAD, P.	8307150149	NUREQ	FELTON, J. M.	8307250020	50-334 P	FLORY, C. A.	8307080580	WASTE MGT
FARMER, B. W.	8307070175*	50-261 G	FELTON, J. M.	8307250084	50-369 F	FLOYD, S.	8307290158*	CONTRACT
FARNER, S. A.	8307150295	PR	FELTON, J. M.	8307250101	50-269 F	FLYNN, M.	8307050495	CONTRACT
FARRAR, D.	8307070129	PR	FELTON, J. M.	8307250118	50-346 F	FLYNN, M.	8307070488	CONTRACT
FARRAR, D. L.	8307050033*	50-373 G	FELTON, J. M.	8307250132	50-275 F	FLYNN, M. J. FLYNN, S. F. FLYNN, S. F. FLYNN, S. F. FLYNN, S. F. FLYNN, B. F.	8307290030	CONTRACT
FARRAR, D. L.	8307050117	PR	FELTON, J. M.	8307250487	50-220 F		8307140437	50-400 G
FARRAR, D. L.	8307080334*	50-374 G	FELTON, J. M.	8307250500	50-241 F		8307140458	50-400 G
FARRAR, D. L.	8307080338*	50-374 G	FELTON, J. M.	8307250514	50-62 F		8307210171	50-400 G
FARRAR, D. L.	8307110146*	50-454 G	FELTON, J. M.	8307250531	FDIA		8307250375	50-241 G
FARRAR, D. L.	8307110419* 8307110434* 8307180023* 8307180043* 8307190147*	50-373	FELTON, J. M.	8307250551 8307250620 8307250626 8307250632 8307250672	FOIA 50-413 F 50-237 F 50-263 F 50-277 F	FOBARTY, D. J. FOBARTY, D. J. FONG, B. E. FODTE, A. M. FORCHT, K. A.	8307250379 8307250383* 8307060313* 8307060407* 8307060183*	50-206 P 50-206 P 50-331 P 27-48 50-423 Q
FARRAR, D. L. FARRAR, D. L. FARRELL, E. V. FARRELL, R. E. FARRINGTON, J.	8307220476* 8307230435* 8307120144 8307140417* 8306280600*	50-237	FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8307250696 8307250717 8307260002 8307260111 8307260600	50-348 F 50-249 F 50-329 G FOIA FOIA	FORD, E. J. FORD, E. J. FORNEY, W. L. FOSTER, C. M. FOSTER, D. G.	8307140077* 8307140092* 8307200116* 8307070450 8307010166	50-327 Q 50-327 Q 50-454 G XPORTLIC 50-424 K
FABANO, A.	8307110396*	50-320 G	FELTON: J. M.	8307270041	50-277 F	FOSTER, D. O.	8307010174*	50-424 A
FABANO, A.	8307250413*	50-320 G	FELTON: J. M.	8307270177	50-399 F	FOSTER, D. O.	8307110453	50-424 S
FAUSKE, H. K.	8307110158*	50-537 T	FELTON: J. M.	8307270184	50-275 F	FOSTER, D. O.	8307110453	50-424 B
FAY, C. W.	8307050246	50-301 P	FELTON: J. M.	8307270465	50-244 F	FOSTER, D. O.	8307120358	50-424 S
FAY, C. W.	8307070021	50-266 P	FELTON: J. M.	8307270473	50-305 F	FOSTER, D. O.	8307120358	50-424 S

AUTHOR	ACCESSION NUMBER	CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
FOSTER, D. O. FOSTER, D. D. FOSTER, H. E. FOSTER, W. E. FRAHM, R.	8307120412 8307120513 8307040112 8307040334 8307050025	50-424 A 2 QA999 3 QA999 50-311 S	GALLO, R. M. GALLUP, D. R.	8307010047 8307110426 8307110629 8307210221 8307130358		GILDENHORN, A. J. GILINSKY, V. GILINSKY, V. GILINSKY, V. GILINSKY, V.	8307190411 8210290407* 8307050257* 8307260123* 8307240130*	CONTRACT FOIA 50-289
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8307050043 8307140001 8307140142 8307140196	50-272 S 50-272 S 50-272 S 50-311 S	GALM.D.T. GALSTER,R.W. GAMBLIN,L. GARDE,B. GARDE,B.	8307010131: 8307220144 8307220359: 8307220354 8307150175:	WASTE MQT • 50-266 P 50-454 G	GILINSKY, V. GILLILAND: J. T. GILMAN: A. R. GIRARD: E. GLASE: P. S.	8307240149* 8307110252 8307280129* 8307220022* 8307170260*	50-259 40-672
FRAMI, R. FRAMI, R. FRAMI, R. FRAMI, R. FRAMI, R.	8307140293 8307190123 8307210003 8307210009 8307210112	50-311 S 50-311 S 50-311 S 50-311 S 50-311 B	GARDE, B. P. GARDE, B. P. GARDNER, R. GARDNER, R. GARDNER, R. N. GARG, H. C.	8307220355 8307240001 8307040310 8307140344* 8307120168*	50-327 Q 50-327 S 50-327 Q	OLABB, P. B. OLABBMAN, M. A. OLEABON, J. P. GLEABON, J. P. OLEABON, J. P.	8307190260* 8307120610* 8307120346 8307280225 8307290094	50-329 7 50-315 F 50-247 0 30-483 0 50-247 0
FRANKIR. FRANKIR. FRANKIR. FRALEYIR.F. FRANCISJJ.M.	9307210134 9307220343 8307220345 9307220558 B307050361	50-311 S 50-272 S 50-311 S 50-311 S ACRS	GARNER, L. H. GARNER, L. W. GARNER, L. H. GARNER, L. H. GARRETT, J. A.	8307220207* 8307220209* 8307220317* 8307220576* 8307110521	50-324 G 50-324 G	GLEICK, P. H. Gloersen, W. B. Gloerson, W. B. Gloerson, W. Goddard, R. J.	8307060411* 8307280329* 8307120547* 8307220553* 8307220108	50-400 0 50-373 0 50-263 0 50-454 0 50-155 0
FREBORO, S. S. FREBORO, S. S. FREESTON, D. FREI, M. W. FRENCH, L. D.	8307220506 8307150213 8307260357 8307290038* 8307270248	WASTE HOT	GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H.	8305070466 8307010006 8307110277 8307110378 8307110450	50-307 R 50-307 S 50-307 8 50-307 P 50-307 Q	QODY QODY, A. QODY, A. T. QODY, A. T. QODY, A. T.	830 7050201 830 7060027 830 711 0355* 830 711 0372* 830 711 0425*	50-423 8 50-245 8 70-1703 50-97 0 50-286 0
FRENCH, L. D. FRENCH, L. D. FRESHLEY, M. D. FREY, D. G. FREY, D. G.	9307010037 8307010127 8307220275 8307120026 8307070131	50-29 S 50-29 S 50-29 S NUREG PR	GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H.	8307120082 8307120468 8307120496 8307120617 8307150233	50-309 B 50-309 S 50-309 P 50-309 Q 50-309 B	QDDY, A. T. QDDY, A. T. QDDY, A. T. QDDY, A. T. QDDY, A. T.	8307110469* 8307140086* 8307140242* 8307140241* 8307140410*	50-220 q 50-57 q 50-29 q 70-364
FREY, D. G. FREY, D. G. FRIEDMAN, L. F. FRISCO, D. C. FRISCO, D. C.	8307070138 6307070143 9307210035 8307220125* 8307050117	PR NUREG 50-546 C FOIA PR	GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H.	8307150330 8307210004 8307220451 8307260474 8307280317	50-309	GODY, A. T. GOLDBERG, J. H. GOLDBERG, J. H. GOLDBERG, J. H. GOLDBERG, J. H.	9307280284* 8307060118 8307060170 8307070134 8307210008	50-309 0 50-498 A 50-498 A 50-498 F
FRIZZLE, C. D. FRYE, J. H. FRYE, J. H. FRYE, J. H. FRYE, J. H.	8307070189 8307190128 8305160589 8307060193 8307060390	FR 50-309 P 50-358 G 50-142 G 50-142 G	GARRITY, J. H. GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J.	8307280436 8306280576 8307060153* 8307120272 8307150100	50-309 Q 50-445 I 50-445 Q 50-445 H 50-445 8	ODLDBERG, J. H. GOLDBERG, J. R. GOLDBERG, J. R. GOLDBERG, J. R. GOLDBERG, J. R.	830 7 2 5 0 4 6 8 3 0 7 0 6 0 2 0 1 8 3 0 7 0 6 0 2 0 6 8 3 0 7 1 4 0 4 4 9	50-498 K 50-498 A 50-289 0 50-289 0 50-289 0
FUNCHES, J. L. FUNK, D. J. FURGAL, D. T. FURSE, M. C. FURSE, M. C.	8307110331 8306080383* 8307180274* 8307210257 8307210236	50-358 G 50-322 A 50-275 H NUREG 50-454 G	GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J.	8307150294 8307150311* 8307260405 8307270172 8307280070	50-445 8 50-445 0 50-445 0 50-445 F 50-445 A	OOLDBERG, J. R. OOLDBERG, J. R. OOLDBERG, J. R. OOLDBERG, S. OOLDBERG, S. C.	8307 1 50306 8307 1 70003 8307 2 50327 8307 2 70025 8307 0 50032*	50-289 0 50-289 0 50-289 0 50-289 0 50-454 0
GAD, R. K. GAD, R. K. GAD, R. K. GAD, R. K. GAD, R. K.	8307210236 8307060162 8307060162 8307060165 8307060165	50-454 G 50-443 G 50-443 G 50-309 G 50-309 G	GATES, R. H. GAVULA, J. A. GAVULA, J. A. GAVULA, J. A. GAVULA, J. A.	8307270420# 8307070228# 8307070239# 8307150128# 8307180179#	WASTE MQT 50-237 P 50-237 P 50-293 P 50-297 P	OOLDBERG, B. C. OOLDBERG, B. C. OOLDEN, M. P. OOLDEN, M. P.	8307030020* 8307120072 8307260042 8307130240 8307280407	50-454 Q 50-454 Q 50-454 Q 50-272 J 50-272 J
GAD, R. K. GAD, R. K. GAD, R. K. GAD, R. K.	8307120379 8307120379 8307120383 8307120444 8307120444	50-443 Q 50-443 G 50-443 G 50-443 G 50-443 Q	GAVULA, J. A. GEARB, G. GEARB, G. GERDEMAN, F. W. GERDEMAN, F. W.	8307180186* 8307140542 8307180423 8307130365 8307180390	50-237 P 50-277 Q 50-277 Q 40-8498 40-8498	GOLDFEIN, M. R.	8307190111 8307190111 8307290102 8307290102 8307290103*	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0
GAD, R. K. GAD, R. K. GAD, B. K. GAGE, K. GAHAN, E.	8307210185 8307210185 8307250376 8307250376 8307120417	50-443 T 50-443 T 50-443 T 50-443 T PR	GERNER, L. GERRETS, T. F. GERSTNER, M. C. GERUSKY, T. M. OIBBONS, T. D.	8307120068* 8307260229 8307220379 8307050185 8307140124*	50-254 F 50-382 A 50-461 A 50-289 G	GOLDFEIN, M. R. GOODMAN, L. B. GOODMAN, L. B. GOODMAN, L. B. GOODMIN, D. C.	8307290105* 8307110127 8307200264 8307220225 8307220083	50-454 Q 50-409 S 50-409 R
GAUIC, Z. GAUIC, Z. GALL, W. R. GALL, W. R. GALLD, J.	8307130358 8307080233 83072200213 8307220034 8307220034	RES 50-295 S 50-295 S ACRS ACRS	GIBSON, J. GIBSON, R. L. GIBSON, R. L. GIBSON, R. L. GIDG, R. G.	8307220042 8307050250 8307070196 8307110291 8307250109	50-416	GORDON, C. Z. GORDON, G. M. GORDON, M. GORDON, M. J. GORDON, M. J.	83070 10048* 83071 40350* 8307220140* 8307220245	50-220 g 50-220 p Waste Mot Waste Mot
GALLO, J. GALLO, J. GALLO, J. GALLO, J.	8307070207 8307070207 8307120591 8307120591 8307210211	50-454 G 50-454 Q 50-155 G 50-155 G 50-454 Q	GIESLER, C. W. GIESLER, C. W. GIESLER, C. W. GIESLER, C. W. GIESLER, C. W.	8307060107 8307070002 8307110239 8307110277	50-305 Q 50-305 P 50-305 F 50-305 B	ODRDON, M. J. CORHAM, E. J. CORHAM, J. E. GOULD, B. E. COULD, B. E.	9307220244 9307220244 9307220261 9307290025	Waste Mot Waste Mot Waste Mot 30-259 S Naste Mot
GALLO, J. GALLO, J. GALLO, J. GALLO, J. GALLO, J.	8307210211 8307210217+ 8307210217+ 8307210236 8307210236	50-454 G 50-434 G 50-454 G 50-454 G 50-454 G	GIESLER.C.H. GIESLER.C.H. GIESLER.C.H. GIESLER.C.H.	8307120263 8307170083 8307250286 8307250296	50-305 R 50-305 K 50-305 G 50-305 G	GOULD, S. E.  GRAESSER, K. L.  GRAESSER, K. L.  GRAESSER, K. L.  GRAESSER, K. L.	8307050066 8307050118 8307060233	WASTE MOT WASTE MOT 30-304 8 30-304 8 30-295 8
GALLO, J. GALLO, J. GALLO, J. GALLO, J. GALLO, J. GALLO, J.	8307250326 9307250365 8307250365 8307260310	50-155 G 50-155 G 50-454 G 50-454 G 50-454 G	GIESLER.C.W. GIESLER.C.W. GILBERT.E.R. GILBERT.E.R. GILBERT.L.D.	8307250488 8307270502* 8307120009 8307120012	50-305 R 50-305 P 50-305 F 4UREQ 4UREQ	Graebber, K. L. Graebber, K. L. Graebber, K. L. Graebber, K. L. Graebber, K. L.	8307200183 8307200183 8307200199 8307200213	30-304 8 30-295 R 10-295 8 10-295 8
PALLO, J. GALLO, J. GALLO, R. GALLO, R.	8307290105* 8307290105* 8307140409*	50-454 G 50-454 G 50-454 G 50-293 G 50-293 Q	GILCHRIST, J.E. OILDENHORN, A. J.	B307200167 4 B307250623 0 B305120547 0 B307070480 0	00-498 G NO-8064 ONTRACT CONTRACT ONTRACT ONTRACT	ORAMM, R. A.  ORAMT, J.  ORAMT, J. M.  ORAMT, J. M.  ORAMT, J. B.  ORAMT, W. B.	8307210224* 5 8307210224* 5 8307210224* 5 8307210078* 5	0-295 8 0-410 0 0-443 0 0-412 0 0-352 0 0-294 0 0-263 0

# PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RAVEB.R.H. RAVEB.R.H. RAVES.R.H. RAVES.R.H.	8307010067 8307050148 8307120262 8307220367 8307010146*	50-213 P 50-213 S 50-213 R 50-213 R 50-213 R	QUINN, P. R. QUINN, P. R. QUINN, P. R. QUMBLE, F. W. QUMBLE, F. W.	8307210072* 8307210102* 8307210313* 8307150018 8307150254	FOIA FOIA 50-286 S 50-286 S	HAMILTON, J. W. HAMMOND, R. D. HAMPTON, J. W. HANCHETT, J. Q. HANNETT, B. A.	8307120226* 8307270276* 8307250625* 8307050081 8307070361	GAT99 WASTE MGT 50-413 F 70-25 XPORTLIC
IRAY, E. H. IRAY, E. H. IRAY, H. IRAYBON, W. M. IREEN, H.	8307210036* 8307210133* 8307210226* 8307120101* 8307150021	50-423	QUSTAFSON, R. N. QUSTAVE, R. S. QUSTAVE, R. S. QUSTAVE, R. P. QUSTAVE, R. P.	8307120584* 8307200170* 8307290326* 8307050496* 8307070490*	50-358 Q CONTRACT CONTRACT CONTRACT CONTRACT	HANNETT, B. A. HANNETT, B. A. HANSEN, L. J. HANSEN, L. J. HANSLER, G. M.	8307070528 8307200291 8307150042* 8307290340 8307260502	XPORTLIC XPORTLIC 71-6679 71-9132 50-352 D
IREEN, H. J.	8307120078	50-296 8	GUSTAVE, R. P.	9307070506*	CONTRACT	Hanson, J. E.	8307120168*	50-537 T
IREEN, H. J.	8307120086	50-327 8	GUSTAVE, R. P.	9307080551*	CONTRACT	Hardin, A. K.	8307220207*	50-324 Q
IREEN, H. J.	8307120071	50-260 8	GUSTAVE, R. P.	9307080575*	CONTRACT	Hardin, A. K.	8307220207*	50-324 Q
IREEN, H. J.	8307120267	50-328 8	GUSTAVE, R. P.	9307180328*	CONTRACT	Harding, M. R.	8307120086	50-327 S
IREEN, H. J.	8307120416	50-328 8	GUSTAVE, R. P.	9307170112*	CONTRACT	Harding, M. R.	8307120267	50-328 S
REEN, H. J. REEN, H. J. REEN, H. J. REEN, H. J.	8307120418 8307120420 8307120422 8307120470 8307120501	50-260 8 50-327 8 50-327 8 50-259 8 50-259 8	OUSTAVE, R. P. GUSTAVE, R. P. GUSTAVE, R. P. GUSTAVE, R. P. GUSTAVE, R. P.	9307200157* 9307200162* 9307200198* 9307200212* 9307200240*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Harding, M. R. Harding, M. R. Harding, M. R. Harding, M. R. Harding, M. R.	8307120416 8307120420 8307120422 8307120587 8307220235	50-328 9 50-327 9 50-327 9 50-328 9 50-328 8
REEN, H. J.	8307120544	50-257 8	QUBTAVE, R. P.	8307250030*	50-201 P	Harding, M. R.	8307220420	50-328 8
REEN, H. J.	8307120589	50-328 6		8307250104*	CONTRACT	Harding, M. R.	8307270076	50-327 8
REEN, H. J.	8307220111	50-257 8		8307250117*	CONTRACT	Harding, R.	8307180205*	50-266 0
REEN, H. J.	8307220217	50-257 8		8307250131*	CONTRACT	Harding, V. R.	8307180183*	50-266 0
REEN, H. J.	8307220229	50-260 8		8307250153*	CONTRACT	Harding, V. R.	8307180176*	50-482 0
REEN: H. J. PREEN: H. J. PREEN: H. J. PREEN: H. J. PREEN: H. J.	8307220235 8307220246 8307220261 8307220268 8307220420	50-328 8 50-294 8 50-257 8 50-260 8 50-328 8	QUBTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P.	8307250171* 8307250176* 8307250258* 8307250350* 8307270038*	CONTRACT 50-289 P CONTRACT CONTRACT CONTRACT	HARDING, V. R.	8307180229* 8307190242* 8307190255* 8307190263* 8307190271*	50-264 0 50-312 0 50-483 0 50-320 0 50-382 0
DREEN, H. J.	6307220435	50-259 8	QUBTAVE, R. P.	8307290158#	CONTRACT	HARDING, V. R.	8307190278*	50-289 0
DREEN, H. J.	8307220440	50-259 8	QUSTAVE, R. P.	8307290473#	CONTRACT		8307190288*	50-400 0
DREEN, H. J.	8307220527	50-259 8	QUSTAVE, R. P.	8307290489#	CONTRACT		8307190299*	50-261 0
OREEN, H. J.	8307220544	50-259 8	QUBTAVE, R. P.	8307290305#	CONTRACT		8307210251*	50-277 0
DREEN, H. J.	8307250487	50-274 8	QUSTAVE, R. P.	8307290313#	CONTRACT		8307270477*	50-440 0
OREEN: H. J.	8307240552	50-294 8	GUTTMANN, J.	8307070091	TOPREP	HARDING, W.	8307180148	NUREQ
OREEN: H. J.	8307240564	50-260 8	HAABI M. N.	8307170112*	CONTRACT	HARLOW, E. V.	8307070228*	50-237 P
OREEN: H. J.	8307290039	50-327 8	HAABBI W. P.	8307260261	WASTE MOT	HARLOW, E. V.	8307070239*	50-237 P
OREEN: H. J.	8307290083	50-296 8	HACKNEY, C, A.	8307260531*	50-278 G	HARRAN, G.	8307220104	50-245 R
OREEN: H. J.	8307290094	50-327 8	HAELBIG, R. T.	8307150042*	71-6679	HARRELL, E. W.	8307110375	50-339 8
GREEN, M. C. GREENBERG, E. V. GREENBERG, E. V. GREENBERG, E. V. GREENMAN, E. Q.	8307130213* 8307220126 8307220126 8307220126 8307110627	50-413	Hagan, T. Hagan, T. F. Hagan, T. F. Hagan, T. F. Hagan, T. F.	8307050321* 8305120551* 8307070484* 8307170418* 8307250629*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HARRELL, E. W. HARRELL, E. W. HARRELL, E. W. HARRELL, E. W. HARRELL, E. W.	8307110435 8307120094 8307120254 8307120259 8307120491	50-338 8 50-337 8 50-339 8 50-339 8
QREENMAN, E. G.	8307280043*	50-322 Q	Hagen, B.	9307250274	NUREG	HARRELL, E. W.	8307120504	50-338 8
GREENSPUN, J. S.	8307200275*	ADVCM	Hagey, H.	9307250685	CONTRACT	HARRELL, E. W.	8307120562	50-338 8
OREEVES, J.	8307260141	WASTE MGT	Haireton, W. G.	9305100010*	50-348 8	HARRELL, E. W.	8307220048	50-338 5
OREEVES, J. T.	8307220096	WASTE MGT	Haireton, W. G.	9307120286	50-348 8	HARRELL, E. W.	8307220118	50-339 8
OREEVES, J. T.	8307220103	WASTE MGT	Haireton, W. G.	9307120570*	50-348 8	HARRELL, E. W.	8307220123	50-339 8
QREEVES, J. T.	8307220152	WASTE MOT	HAIRSTON, H. G.	8307120374*	50-348 8	HARRELL, E. W.	8307290058	50-339 8
QREEVES, J. T.	8307260163	WASTE MOT	HAIRSTON, H. G.	8307150106*	50-348 8	HARRELL, E. W.	8307290073	50-339 8
QREEVES, J. T.	8307260255	WASTE MOT	HAIRSTON, H. G.	8307150107*	50-348 8	HARRELL, E. W.	8307290171	50-338 5
QREEVES, J. T.	8307260272	WASTE MOT	HAIRSTON, H. G.	8307170108	50-348 R	HARRELL, E. W.	8307290187	50-339 8
QREOER, L. R.	8307080263*	50-274 Q	HAIRSTON, H. G.	8307170113	50-364 R	HARRELL, E. W.	8307290189	50-338 8
OREGER, L. R.	8307120280*	50-315 G	HAIRSTON, W. G.	8307220311*	50-348 8	HARRELL, P. H.	8307060221#	GA999
GREGER, L. R.	8307120506*	50-483 G	HAIRSTON, W. G.	8307220315*	50-348 8	HARRINGTON	8307220206	50-293 B
GREGER, L. R.	8307180047*	50-266 G	HAIRSTON, W. G.	8307220320*	50-348 6	HARRINGTON, D. B.	8307120351	50-293 P
GREGER, L. R.	8307180133*	50-263 G	HAIRSTON, W. G.	8307220323*	50-348 8	HARRINGTON, W.	8307060037#	50-293 G
GREGER, L. R.	8307280293*	50-10 G	HAIRSTON, W. G.	8307220338	50-348 8	HARRINGTON, W.	8307060048#	50-293 G
OREGO, R. J. OREINER, H. F. ORIFFIN, J. M. ORIFFIN, J. H. ORIFFING, E. P.	8307280319*	70-820	HAIRSTON, U. C.	8307290170	90-348 8	HARRINGTON, W. D.	8307010082	50-293 G
	8307180382	XPORTLIC	Hale, C. J.	8307060192*	0A979	HARRINGTON, W. D.	8307010134	50-293 S
	8307050072	50-313 P	Hale, C. J.	8307060221*	0A999	HARRINGTON, W. D.	8307050252	50-293 G
	8307170078	50-348 P	Hale, C. J.	8307060360*	0A999	HARRINGTON, W. D.	8307110354	50-293 P
	8307260455	50-14 R	Hale, C. J.	8307120284*	0A999	HARRINGTON, W. D.	8307110476	50-293 S
ORIFFITH, J. D.	8307070129	PR	HALE, C, J.	8307120462*	GA999	HARR INGTON, W. D.	8307110506	50-273 8
ORIFFITH, R. V.	8307180139	NUREG	HALL, B, L.	8307060299*	50-321 G	HARR INGTON, W. D.	8307120229	50-273 F
GROCE, R. H.	8307220012	50-309 R	HALL, B, L.	8307170060*	50-338 G	HARR INGTON, W. D.	8307120423	50-273 8
GROSSMAN, H.	8307050178	50-440 G	HALL, D, P.	8307060020	50-461 A	HARR INGTON, W. D.	8307120507	50-273 5
GROSSMAN, H.	8307120555	50-440 G	HALL, D, P.	8307060073	50-461 A	HARR INGTON, W. D.	8307120518	50-273 8
QROTENHUIS, M. OROVELURA, K. OUCHA, L. T. OUCHA, L. T. GUCHA, L. T.	8307270441 8307120467 8307060270 8307060352* 8307110176*	50-305 P 70-25 50-321 P 50-321 G 50-321 F	HALL, D. P.	8307080270* 8307080331* 8307110031 8307110322 8307180009	30-461	HARR INGTON, W. D. HARR INGTON, W. D. HARR INGTON, W. D. HARR INGTON, W. D. MARR INGTON, W. D.	8307130080 8307130082* 8307150022 8307150068 8307150123	50-273 P 50-273 P 50-273 P 50-273 P
QUCHA, L. T.	8307120357	50-366 8	HALL, D. P.	8307180036	50-461 S	HARR I NOTON; W. D.	8307150127	50-293 8
QUCHA, L. T.	8307140058	50-366 9	HALL, D. P.	8307180086	50-461 H		8307150245	50-293 8
QUCHA, L. T.	8307140472*	. 50-321 9	HALL, D. P.	8307280045	50-461 R		8307150262	50-293 8
QUERON, H. M.	8307070120	PR	HALLHAN, R. M.	8307050530*	Review GRP		8307190016	50-293 P
QUILD, R.	8307170239	50-413 6	HALLHAN, R. M.	8307080344	Misc		8307190040	50-293 R
QUILL, P. F. QUILL, P. F. QUINN, F. K. QUINN, F. K. QUINN, F. K.	8307220272 8307220511 8307080629 8307200462 8307280135	50-270 B 50-287 B 70-143 70-143 70-143	HALLMAN, R. M. HALLMAN, R. M. HALLMAN, R. M. HAMILL, K. HAMILTON, B.	8307080344 8307260113* 8307260113* 8307250574* 8307280429*	MISC FOIA	HARRINGTON: W. D. HARRINGTON: W. D. HARRINGTON: W. D. HARRINGTON: W. D. HARRINGTON: W. D.	8307210140* 8307220197 8307220331 8307220376 8307220430	50-293 G 50-293 R 50-293 S 50-293 P 50-293 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		ACCESS10	4				
HARRINGTON, W. D HARRINGTON, W. D	8307220519	50-293 8	AUTHOR	NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEOC	
HARRINGTON, W. D HARRINGTON, W. D	6307260166	50-293 K	HENSLEY, K. D.	8307200051 8307200053		HOEDEMAN, K. A.	8307060285*		
HARRINGTON, W. D	- 8307260402 - 8307260571	50~293 p 50-293 p	HENSLEY. K. D.	8307200056 8307200056	* 70-143	HOEDEMAN, K. A. HOEDEMAN, K. A.	8307060293* 8307060313*	50-331	ŕ
HARRINGTON, W. D.		50-273 g	HENSILEY, K. D.	8307200059		HOFFMAN, D. P. HOLDEN, C.	6307220219 8307280290#	50-155	Ŗ
HARRINGTON, W. D. HARRIS, J. M.	83072600B9*	50-293 R	HENSLEY, K. D. HENSLEY, K. D.	8307200D62 8307200069		HOLDER, E. T.			*
HARRISON, F.	8307140249* 8307130212	50-424 0	HENGLEY, K. D. HENGLEY, K. D.	8307200072	* 70~143	HOLDREN, J. P. HOLLEY, M. J.	8307120501 8307060411*	50-259 50-400	6
HARRIGON, F. L.	8307270319	30-324 R NUREO	HENSLEY, K. D.	8307200075 8307200077		HOLLEY, W. L. HOLLOWAY, C. J.	8307280297 <b>*</b> 8307120259*	50-275 50-267	e e
HARRISON, J. HARRISON, J.	8307040310 8307040340	50-327 g	HENGLEY, K. D. HENGLEY, K. D.	B307200080	* 70-143	HOLLOWAY, C. J.	8307190444*	50-387	P
HARRISON, J. HARRISON, J. J.	8307200155 8307050053	50-329 S	HENSLEY, K. D. HERLEKAR, A. S.	8307200083 8307200086	70-143	HOLLOWAY, C. J. HOLMEB-RAY, J.	8307190491# 8307200412#	50-437 50-466°	A
HARRISON, J. J.		50-329 A	HERLEKAR, A. S.	83070702281 83070702391	50-237 p	HOLONICH, J. J.	8307140476* 8307290037	50-321 50-462	g
HARRISON, J. J. HARRISON, J. J.	8307110010 8307110311	50-329 A 50-329 A	HERMAN, A. A.	8307130204	50~289 G	HOLTZ, J. L.	8307220308	50-334	a
HARRISON, J. J. HARRISON, J. J.	8307140044* 8307140344*	50-329 g 50-329 g	HERMANN, O. W. HERMANN, R. A.	8307250159 8307190046	NUREG	HOLTZSCHER, D. L. HOLTZSCHER, D. L.	8307250367 8307250367	50-440 50-440	¥
HART, G. H.	8307210125	50-329 A	HERMANN, R. A. HERMANN, R. A.	8307190047 8307190409	50-220 p	HOLZ, H. B. HOLZMAN, M. M.	8307120176* 8307060138*	50-537	T
HART, H. C. HART, T. A.	830727002B* 8307170264	GEN TEC 15 70-687	HERNAN, R.	9307180393	•	HOLZMER, M. M.	B307080450*	50-316 50-155	Q
HARTICAN, N. F.	9307200304 8307110304	XPORTLIC 40-2061	HERRIN, M. G.	8307170241* 8307060355	# T 11 T	HOOD, D. S. HOOK, K. A.	8307130335 8307070112	50-329	A
HARTMAN, P. L.	8307200204*	50-454 Q	HERRIN, M. Q. HERRIN, M. Q.	8307040355 8307070207	50~454 Q 50~454 Q	HOPCRAFT.C.P. HOPCRAFT.C.P.	8307070467	PR 71-9162	
HARVEY, R. C. HABSELL, D. F.	8307130043 8307130234	40-8743 50-247 Q	HERRIN, M. Q.		90-454 g	HOPCRAFT, C. P.	9307150372 9307200466	71-9163 71 <b>-2</b> 10	
HAUGHEY, M. HAUGHEY, M.	8307060425 8307200543*	50-410 A	HERSCH, M. M. HESSON, G. M.	8307070207 8307070364	50-454 G XPORTLIC	HOPEWELL, R. W HOPKINS, H. R.	8307130333*	50~454	A
HAUZE, G. L.	0307130317#	50-410 D 50-454 A	HEVERLY, L. HIATT, S. L.	8307120026 8307200205*	NUREO 50-361 P	HOPKINS, J. B. HOPKINS, J. B.	8307140528* 8306270603*	CONTRACT PR	
HAVIAN, E. HAVIAN, E.	8307240253 8307260253	50-275 G	HIATT, S. L.	8307070144	50-440 g	HOPKINS, J. B.	8307200231 8307250124		A
Hawkins, E. F. Hawkins, E. F.	8307110157 8307270476	50-275 G WASTE MGT	HIATT, S. L. HIATT, S. L.	8307070154* 9307070202	50-440 G 50-412 G	HOPPER, A.	8307250690	CONTRACT	-,
HAWKINS, F. C.	8307080026#	Haste Mgt 50-243 g	HIATT. S. L. HIATT. S. L.	8307070225 8307110310	50-440 Q 50-440 Q	HOPPER, A. HORIN, W. A.	8307270485 8307190228	CONTRACT	0
HAWKINS, F. C. HAWKINS, F. C.	8307080450*	50-155 Q		B307150272	PR	HORIN, W. A. HORIN, W. A.	8307170228 8307250356	50-445	9
HANKINS, F. C. HANKINS, F. C.	8307140417* 8307280196*	50-255 Q 50-282 Q	HIATT, S. L. HIATT, S. L.	8307150280 8307150296	PR PR	HORIN, W. A.	8307250356		
HAYES, D. W.	8307280442* 8307110276*	50-440 g 50-461 g	HIATT, S. L. HIATT, S. L.	8307190114 8307190186	50-440 Q	HORIN, W. A. HORIN, W. A.	8307270110 8307270110	50-445	ŗ
HAYES, D. W. HAYNES, J. Q.	83071800074	50-454 a	HIATT, S. L.	8307190222	50-440 g 50-440 g	HORNOR, J. W. HORNOR, J. W.	8307060086 8307110160	I&E	Ť
HAYNES, J. C. HAYS, J. K.	9307050010 9307120008	50~361 q 50~206 q	HIATT, S. L. HIATT, S. L.	8307210179 8307220071	50-440 G	HOBEY, C. M.	8307140053*	186	_
HEAD, C. F.	9307110368* 9307180101	50-250 F 50-366 P	HIBBITTS, H. W. Hibbitts, H. W.	8307110164# 8307110164#	F01A 50~537 T	HOSEY, C. M. HOSEY, C. M.	8307140208*	50-250	q q
HEATHERLY, T. L.	8307140069»	50-390 Q	HICKEY, J. W.	8307210111#	50-537 T FOIA	HOSSLER, D. E. HOTTEL, R. E.	8307220220* 8307060200	50-289 (	a H
HEDGES, V. D. HEDGES, V. D.	8307110169* 8307110168*	50-537 T 50-537 T	HIGGIN, J. C. HIGGINEDTHAM, L.	8307280290* 8307050301	50-309 G	Hou, s.			7
HEHL, C. HEHL, C. W.	9307140195*	50-36 <del>9</del> G	HIGGINBOTHAM, L. HIGGINB, J.	8307190447	WASTE MOT WASTE MOT	HOUSTON, D. HOUSTON, M. D.	8307290520	50-537 1 TOPREP	ſ
HEIDEL, C. M.	00000	-	HIGGINS, J. C.	8307280315* 8307250442*	50-317 g 50-322 g	HOUSTON, R. W. HOVIS, J. B.	8307180191	30-416 £ 30-373 £	
HEIDER, L. H. HEIDER, L. H.	B307220039	50-341 K 50-27 R 71-502	HILDEBRANCH, J. HILF, C. L.	B307210049	50-287 P	HOVIS, J. B.		WASTE MOT	
HEIDER, L. M. HEIDER, L. M.	B3072604B0 :	50-271 K	HILL, D. HILL, D.	8307200105# 8307150454#	50-259 P CONTRACT	HOWARD, G. L. HOWARD, G. L.	B307070184#	HASTE HOT 50-237 P	
HEIDER, L. H.		50-29 р 	HILLIR. F.	8307190418* 8307120446*	CONTRACT 50-265 P	HOWE, P. W.	8307180147* 8307190042	50-237 P 50-324 Q	
HEINRICH, B. C. HEINRICKS, R. S	8307220450	50-29 P 50-249 H	HILL: W. M. HIND: J. A.	830715014B*	50-498 Q	HOWE, P. W.	9307260084	10-324 F	
HELFRICH, R. E.	8307250057	ONTRACT 50-309 P	HIND, J. A. HIND, J. A.	#307050249 #307060116*	50-10 g 50-341 g	HOWE, P. W. HOWE, P. W.		10~324 ¥ 30~324 ₽	
HELFRICH, R F	0000000	PR	HIND, J. A.	8307060181 8307250371	50-237 G 50-266 Q	HOYLE, A. HOYLE, J.	8307250637	ONTRACT	
HELGESON, K. A. HELGESON, K. A.	8307050281 7	R '0~920	HIND, J. A.	8307260316	50-346 g	HOYT, H. F.		0-443 Q	
HELGEBON, K. A. Helgebon, K. A.	8307190011 7	0~850 0~850	HIND, J. A. HIND, J. A.	8307260488*	50-331 Q	HOYT, H. F. HOYT, H. F.		0-443 ¢	
HELTEMES, C. J.		0-820	MIND, J. A. HINDS, J. M.	8307280454#	50-10 G	HOYT, H. F. HOYT, H. F.	8307130250 5	0-443 č	
Heltemes, C. J. Heltemes, C. J.	8307130129# 50	ISC 0-272 s	HINRICHE, O.			HOYT, H. F.		0-443 g 0-443 g	
HELTEMES, C. J. HELTEMES, C. J.	B307250015 ps	0-250 s	Hinrichs, Q. Hinrichs, Q.	8307180151	50-247 g	HOYT, H. F. HOYT, H. F.		0-443 g	
HELTEMES C. J.	9307250021* PR	1	Hinrichs, Q. Hinrichs, Q.	8307220280	50-247 g 50-247 g	HOYT, H. F. Hubacek, W. Q.	8307290150 5	0~443 0 0~443 0	7
HENDRIXSON, E. S. HENISCHEL, H. F.	9307270273 PR 9307250320 50	)-281 P	HIRSCH, D.		50-247 s	HUBBARD, O. T.		0-498 A 4999	
HENRY, G. D. HENRY, G. D.	8307140517# CO 8307120418 50	NTRACT	Hirech, D. Hirech, D.	8307040363	50~142 T 50~142 G	HUBBARD, C. T. HUDSON, C.		1999	,
	8307260564 50	-240 g	HIRSCH, D. HOADLEY, S.	8307120555	50-142 g 30-142 g	HUDSON, 8. HUDSON, 8.	8307010011 50	7-263 F	
HENRY, L. G. HENGLEY, K. D.		ORTLIC -143	HOADLEY, S.		(PORTLIC	HUDBON, S. D.		)-271 S )-220 Q	
HENSLEY, K. D. HENSLEY, K. D.	8307200025* 70	-143 -143 -143	HOADLEY, S. D. HOADLEY, S. D.	830705001B 7	PORTLIC 0-572	HUDSPETH, J. B. HUDSPETH, J. B.		-348 F	
	ADA	-143 -143	HOADLEY, S. D. HOCH, J. B.	8307280466 X	PORTLIC PORTLIC	HUETER, L. J. HUETER, L. J.	8307060108 50	-346 F -331 q	
INCISCLESSIN, D.		-143	HOCH, J. B.	9307120327# 5	0-275 R	HUGHES, P. Q.		-315 G	
HENSLEY, K. D.	B307200042* 70-	-143 -143	HODODON, A. P. HODODON, A. P.	8307130196 5	0-275 R 0-352 g	HUGHES, P. G. HUGHES, W. R.	8307270184 50	-302 8	
		-143 -143	HODODON, A. P. HOEDEMAN, K. A.	8307150300 5 8307250152 5	0-352 g 0-352 g	HUKILL, H. D. HUKILL, H. D.	8307120377# 50 8307050145 50	-528 B -289 P	
			The state of the s		0-331 P	HUKILL, H. D.	8307050154# 50·	-287 P -287 B	

	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR'	
-	8307120052* 8307120227* 8307150323 8307180098 8307190149	50-289 F 50-289 G 50-289 P 50-289 F 50-289 F	JOHANSEN, E. JOHNSON, A. R. JOHNSON, B. JOHNSON, B. D. JOHNSON, B. D. JOHNSON, B. D.	8307260400 8307120293* 8307260309 8307050140 8307060158	50-344 GA999 50-454 50-255	- J G 5	JUNGE, M. A. JUNGE, M. A. JUNGE, M. A. JUSTUS, P. S. JUSTUS, P. S.	8307110427 8307180193 8307210287 8307220047 8307220094	50-317 50-318 50-317 WASTE MG WASTE MG	
	8307170226 8307170231# 8307170235 8307210049	50-287 P 50-287 P 50-287 P 50-287 P	JOHNBON: B. D. JOHNBON: B. D. JOHNBON: B. D. JOHNBON: B. D. JOHNBON: C. R.	8307080481 8307190012 8307190205 8307200251 8307280433	50-255 50-255	5 8 9 0	JUSTUS, P. S. JUSTUS, P. S. KABADI, J. N. KAKU, M. KALEEL, R. J.	8307220103 8307220152 8307080325* 8306170403 8307120018	WASTE MG WASTE MG TOPREP 50-142 NUREG	
	8307220182 8307260509 8307270031 8307270316 8307120176*	50-289 R 50-289 P 50-289 F 50-289 K 50-537 T	JOHNSON, F. R. JOHNSON, G. E.	8307220359* 8307110256 8307110264* 8307110273* 8307110289*	50-266 50-413 50-413 50-413	P G G O	Kalivianakis, n. Kalivianakis, n. Kalivianakis, n. Kalivianakis, n. Kalman, o.	8307110061 8307130219 8307220234 8307220258 8307110396*	50-254 50-254 50-254 50-265 50-320	5 R S S G
	8307120197* 8307120414* 8307120430* 8307120531* 830719008	50-537 T 50-298 0 50-382 0 50-498 0 50-298 S	JOHNSON: G. E. JOHNSON: Q. E. JOHNSON: H. V. JOHNSON: J.	8307110297* 83071280032 8307150137 8307010011 8307140407*	50-413 50-413 NUREG 50-293	- G G G	KALMAN, G. KALMAN, K. KALMAN, K. KALMAN, K. KALMON, K. J.	8307250413* 8307210001 8307210148 8307270190 8307040331	50-320 50-373 50-373 WASTE MG 50-373	9 5 5 7
	8307260286* 8307060227 8307140133* 8307080284* 8307120584*	50-298	ЈОНИВОМ, Ј. ЈОНИВОМ, М. К. ЈОНИВОМ, Р. Н. ЈОНИВОМ, Р. Н.	8307280449* 8307250092* 8307060416* 8307120570*	50-293 50-369 50-528	9 F 9 9	KAMENAR, P. D. RAMENIC, M. KAMMER, D. S. KAMMER, D. S. KAMMER, D. S.	8307240104 8307130325* 8307240207 8307240270 8307260297	FOIA 50-454 50-327 50-259 50-390	A P P A
	8307050117 8307070083 8307200150 8307060200 8307110632	PR 50-400 D 50-325 G 50-289 H 50-201 P	JOHNSON, R. G. JOHNSON, R. G. JOHNSON, W. D. JOHNSON, W. D.	8307260475 8307260479 8307290545 8307060019* 8307060040*	50-263 WASTE MOT 50-285 50-285	J	KAMMER, D. S. KAMMER, D. S. KAMMER, D. S. KAMMER, D. S. KAMMER, D. S.	8307270036 8307270176 8307280370 8307290109 8307290148	50-327 50-436 50-276 50-257 50-370	ዖ G P P
	8307250109 8305270643* 8307120193* 8307060632* 8307220053	NUREG 50-269 G 50-537 T 50-286 H WASTE MOT	ЈОНИВОМ, W. D. ЈОНИВОМ, W. D. ЈОНИВОМ, W. D. ЈОНИВОМ, W. D.	8307060291* 8307120013* 8307120074 8307120247* 8307120497*	50-482 50-313 50-313 50-285	9 8 9 9	KAMMER, D. S. KAMMER, D. S. KANA, D. D. KANE, J. KANE, J.	B307270151 B307270206 B307060368* B307220417* B307250376*	50-390 50-259 TOPREP 50-382 50-329	A P G
	8307140503 8307140520 8307180396 8307220544 8306150383	TOPREP REVIEW GRP TOPREP 50-259 S 50-322 G	JOHNSON, W. D. JOHNSON, W. D. JOHNSON, W. P. JOHNSON, W. P.	8307120478* 8307120523* 8307150079* 8307060203 8307150142	50-285 50-285 50-443 50-443 50-412	о о о к о	KANGA: B. K. KANGA: B. K. KANGA: B. K. KANGA: B. K. KANGA: B. K.	8307010057 8307010117 8307070147 8307080008 8307080225	50-320 50-320 50-320 50-320 50-320	S G P P R
	8306150383 8307050266 8307080592 8307080602 8307250520*	50-322 0 50-322 0 NUREQ NUREG CONTRACT	JOHNSRUD, J. H. JOHNSTON, H. V. JONES, C. JONES, C. R. JONES, C. R.	8307050097 8302040562* 8307120482 8307260221 8307260230	50-387 50-285 50-298 50-298	Р G Р Р	KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K.	8307110441 8307110448 8307120004 8307150159 8307180166	50-320 50-320 50-320 50-320 50-320	6 8 P P
	8307110260* 8307250029 8307250537 8307110276* 8307260009*	50-413 0 50-413 A 50-413 E 50-461 Q 50-327 Q	JONES, C. R. JONES, D. W. JONES, V. H. JONES, V. H. JONES, V. H.	8307260410 8307140377* 8307200195* 8307200197* 8307220385	50-298 70-1201 50-280 50-280 50-280 50-285	R R R R	KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K.	8307180178 8307180332* 8307190017 8307190119 8307200164	50-320 50-320 71-6771 50-320 50-320	8 F P
	8307220401 8307240574 8307050028 8307060328* 8307050260	50-409 S 50-409 B 50-409 Q 50-282 G WASTE MGT	JONES, W. C. JONES, W. C. JONES, W. C. JONES, W. C. JONES, W. C.	8307040078 8307040078 8307080423 8307120454* 8307120445*	50-285 50-285 50-285 50-285 50-285	7 G G G G	KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K.	6307210282 8307220527 8307220537 8307220550 8307220556	50-320 50-320 50-320 50-320	5 5 5 5
	8307110081 8307120467 8307270222 8307090109 8307120224*	HABTE MOT  70-25 HABTE MOT HASTE MOT 70-1143	JONES, W. C. JONES, W. C. JONES, W. C. JONES, W. C. JONES, W. C.	8307170125 8307170158 8307220416 8307250428*	50-285 50-285 50-285 50-285 50-285	J R G	KANGA; B. K. KANGA; B. K. KANGA; B. K. KANGA; B. K. KANGA; B. K.	8307220545 8307250331 8307250454 8307240474 8307260357	50-320 50-320 50-320 50-320 50-320	명 P P P
	8307190307 8307280229* 8307280458 8307050533 8307110503*	CONTRACT  50-272	JONES, W. C. JONES, W. C. JORDAN, D. B. JORDAN, D. B.	8307260143 8307260179 8307270338 8307070050 8307070098	50-285 50-265 50-458 50-438	P G A A	KANGA, B. K. KANNINEN, M. F. KANNINEN, M. F. KARRA, M. KARRA, J. E.	8307280447 8307120017 8307120017 8307280024 8307110168*	50-320 NVREG NUREG 50-261 50-537	а 0 1
	8307180107* 8307140073* 8307140291* 8307210201* 8307220037*	50-282	JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, H. JORDAN, H.	8306270401 8306270404 8307260254 8307130328* \$307130331*	50-3 50-3 50-329 50-454 50-454	G G A A	KASSNER, Q. KASSNER, T. F. KATAUKA, I. KAUFMAN, P. H. KAUFMAN, P. H.	8307110423 8307070133 8307080592 8307060397 8307130074*	50-304 NUREG NUREG 50-275 50-275	5 0
	8307220493* 8307280165 8307180067* 8307130317* 8307150192*	50-390	JORDAN; W. B. JORDAN; W. H. JORDAN; W. S. JORDAN; W. S. JORDAN; W. S.	8307070101 8307080461 8307070189 8307260337 8307260337	PR 50-445 : PR 50-443 50-443	G .	KAUFMAN, P. H. KAYE, J. A. KAYSER, W. V. KAZA, R. N. KEATING, D. E.	8307150361* 8307180212* 8307010157* 8307190165* 8307080292*	50-275 50-322 50-282 50-335 50-341	G R P Q
	B306240037* B307210106* B307080342 B307080350* B307080435	50-373 P FOIA 50-522 D 50-522 D 50-522 D	JORDAN: N. S. JORDAN: N. S. JORDAN: N. S. JORDAN: N. S. JOYNER: J.	8307260355 8307260355 8307260538 8307260538 8307050112	50-443 50-443 50-443 1&E	0	KEATING, D. E. KEATING, D. E. KEIMIG, R. KEIMIG, R. KEIMIG, R.	8307140226* 8307210147* 8307110473 8307130007 8307210124	50-546 50-461 50-277 50-289 50-277	0 0 8 8
	8307080440* 8307080445 8307080452* 8307270470 8307270482 8307120550	30-522 D 30-522 D 30-522 D WASTE MOT WASTE MGT 30-298 B	JULIAN. G. JULIAN. G. JULIAN. G. JULIAN. G. A. JUNGE, M. A. JUNGE, M. A.	8307140141# B307140154* 8307220267* 8307140418* 8307010124 8307010142	50-250 50-335 50-336 50-335 50-316 50-317	0 0 0 5 5	KEIMIG.R. KEIMIG.R.R. KEISER.H.W. KEISER.H.W. KEISER.H.W.	8307280333 8307010005* 8307010031 8307010054 8307010069	50-219 50-410 50-387 50-387 50-387	6 9 5

AUSHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	N BUBJECT CATEGOR
#E15EP; H W #E15EP; H W #E15EP; H W #E15EP; H W	8307120255 8307120273 8307120435 8307120442 8307125443	50-387 S 50-387 S 50-387 S 50-387 S 50-387 S	KIMBRELL, M. Kimbrell, M. Kimler, D. Kin, J. W.	8307130328: 8307130331: 8307110041 8307150128:	50~454 A 50~254 8 50~293 P	KOESTER, O. L. KOESTER, O. L. KOESTER, G. L. KOESTER, G. L.	8307190110 8307220487 8307250315 8307250323	0 50-482 7* 50-482 5 50-482
FCISCO, H W MRLHER, H W MRINER, H W MRINER, H W MRINER, H W	8307180230 8307180264 8307220299 8307220312	50-387 S 50-397 S 50-397 S 50-397 S	KINCAID, R. H. KING, M. KING, S. E. KING, T. L. KING, T. L.	8307290118# 8307190397 8307150147 8307120168# 8307120188#	NUREQ NUREQ 50-537 T	KOESTER, G. L. KOESTER, G. L. KOESTER, G. L. KOESTER, G. L.	8307250380 8307250453 8307260382 8307290178	50-482 50-482 50-482
MEISER H W	8307220319 8307220459 8307280281	50-387 S 50-387 S 50-387 S	KING, T. L. KING, T. L.	8307120211+ 8307120220+	50-537 T 50-537 T 50-537 T	KOESTER, Q. L. KOHN, R. KOLB, Q. J.	9307270352 9306170403	50-405
MELLEY, G MELLEY, G MELLEY, G	8307010046 8307016060 8307050138* 8307260090	50-333 S 50-333 S 50-445 Q	KING, T. L. KING, T. L. KINNEMAN, J. KINNEMAN, J.	83071202324 8307130215* 8307050112 8307280170*	50-537 T 50-537 T 1&E 40-672	KOLB, L. E. KOLB, L. E. KOLB, L. E. KOLB, L. E.	8307150365 8307120194 8307120256 8307220254 8307250201	50-313 50-395 50-395 50-395 50-395
METTERY OF T METTERY OF T METTERY OF T METTERY OF T	8307030104 8307030104 8307180089 8307190262	50-336 S 50-336 S 59-413 G 50-490 G	KINNEY, W. W. KINNEY, W. W. KINTNER, L. L. KIPP, T. R. KIRK, W. F.	9307110401* 9307280200* 9307290496 9307220411* 9307200460	50~166 Q 50~199 Q 50~358 A 50~329 A 70~371	KOMORIYA, H. KOMORIYA, H. KONKLIN, J. E. KONKLIN, J. E. KOOF, A. R.	8307120047 8307130074 8307110430* 8307180137* 8307270182*	RE8 50-470 50-546 50-483
MESTA' C MESTA' E MESTEA' M MESTEA' M D	8307220358 8307180197* 8307220271 8307010047* 8307220072	50-413	KIRK.W.F. KIRSCH.D.F. KIRSCH.D.F. KIRSCH.D.F. KISH.J.N.	9307220635 9307060007 9307120522* 9307120551* 9307280176*	70-371 50-133 8 50-275 G 50-361 G 50-262 G	KOSLA: B. M. KOST: E. O. KOST: E. G. KOVACK: T. J.	8307110070* 8307070181* 8307180138* 8307120068*	70-1201
HERTTA'S W E HERTA'S W E HERTA'S W E HERTA'S	9307260531+ 8307060291+ 8307060040+ 8307260286+ 8307220251	50-298	KISH.J.N. KISTER.H. KISTER.H. KISTER.H.	8307280442* 8307060149 8307220160 8307280458	50-440 Q 50-271 S 50-244 Q 50-311 S	KRAFT, D. C.  KRAUBE, D. F.  KRAUBE, D. F.  KRECHTING, J. E.  KRECHTING, J. E.	8307120553 8307050019 8307050090 8307050134	50-315 8 50-215 8 50-275 8
RELLY: R B RELLY: W J RELLY: W J RETERRET: P C	8307260547 8307130092 8307220496 8307270245± 8307280352+	50-329 A 50-275 B 50-275 R HASTE MGT 50-277 P	KISTER, H. B. Kister, H. B. Kister, H. B. Kister, H. B. Kister, H. B.	8307010005* 8307010036* 8307110421* 83071404315* 8307140403*	50-410 Q 50-410 Q 50-333 Q 50-220 Q	KRICH, R. M. KRIMM, R. W. KRIMM, R. W. KRIMM, R. W.	8307180154 8307120044* 8306240435* 8307150167 8307170173	50-275 R 50-255 F 50-445 F 50-155 F
AEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8307120216 8307120484 8307120508+ 8307120015 8307250316	50-352 s 50-352 A 50-352 g 50-352 s	KISTER, H. B. KISTER, H. B. KIGTER, H. B. KLEIN, T. J. KLEINSORGE, H. P.	8307210014* 8307220179 8307290487 8307110762	50-244 Q 50-247 Q 50-333 S 50-311 Q 40-8584	KRONZEK, A. L. KRUEGER, J. E. KRUG, E. P. KRUG, H. KRUSE, L. M.	8306070382 8307120333* 8307140291* 8307220037*	50-387 F FDIA 50-352 A 50-389 Q
PEMPER, J B AND S L, NEWMER, J B AND S L, SEWEEN S C BENDER, J B AND S C AND S	9307260406 8307260472 8307280298 83072804634	50-352 A 50-352 A 50-352 Q 50-352 Q	KLINE, J. R. KLINE, J. R. KLINGLER, Q. KLINGLER, Q.	8307140088* 8307140430 8307280225 8306280432 8307050114	50-250 q 50-440 g 50-483 g 50-454 g	KUCZYNSKI, L. A. KUCZYNSKI, L. A. KUCZYNSKI, L. A. KUCZYNSKI, L. A.	9307040204 9307010031 9307010054	50-387 B
RENNEEV. D M KENNEDY, M F RENNEDY, R P	#30713 <u>0</u> 094	18E 50-255 R 50-470 A	KLINGLER, G. KNICELEY, J. R. KNICELEY, J. R.	8307190321 8307050262*	50-482 q 50-322 q 50-10 q	KUCZYNSKI, L. A. KUCZYNSKI, L. A. KUCZYNSKI, L. A.	8307220176 8307220319 8307220459 8307280281	50-387 R 50-387 8 50-387 8 50-387 8
KENNEDY, R. P. MENNY, T. J. MENDYER, J. MENYON, B. D.	9307220411* 9307290118* 8307280311*	50-329 A 50-329 A 50-286 G 50-298 Q	KNIGHTON, G. W. KNIGHTON, G. W. KNIGHTON, G. W. KNIGHTON, G. W.	8307050359 8307050365 8307070226	50-282 Q 50-275 P 50-275 P 50-528 A 50-528 A	KUHRTZ, S. O. KULCHAK, R. D. KULP, C. J. KUNCHO, A. KUNCHO, A.	9307250443# 8307270300# 8307070036 8307170247#	40-86 HASTE HOT 50-412 A 50-443 0
KENYON, 8 D KENYON, 8 D KENYON, 8 D KENYON, 8 D	8307040069 8307010023+ 8307120464+ 8307120472+	50~397 g 50~397 g 50~397 g 50~397 g	KNIOHTON, G. H. KNIOHTON, G. W. KNIOHTON, G. W. KNIOHTON, G. W. KNIOHTON, G. W.	8307080637 8307080646 8307140152	50-528 A 50-528 E 50-389 P 50-335 F	KUNCL, L. G. KUNCL, L. G. KUNKLE, G. L. KUPPERMAN, D. G.	8307190247* 8307180054 8307280073 8307180222*	50-443 Q 50-298 P 50-298 K 50-322 R
KENYON B. D KEPPLER: J G KEPPLER: J G KEPPLER J G	8303540549 83045540549 8304580358	50~387 R 50~387 S PR 50~237 Q 50~329 H	KNIGHTON, Q. H. KNIGHTON, Q. H. KNIGHTON, Q. H. KNIGHTON, Q. H	8307150050* 5 8307150411 5 8307200473 5	10-387 р 0-387 р 0-341 р 0-341 г	LABARGE, F. Lacey, W. S. Lacey, W. S.	8307010133 8307180395	NUREQ 40-279 50-334 B
KEPPLER, J. G KEPPLER, J. G PEPPLER, J. G MEPPLER, J. G	8307050184 5 8307050099 5 8307080278 5	0-329 н 0-341 g 0-358 g	KNIGHTON, G. U. KNIGHTON, G. U. KNIGHTON, G. U	8307220115 50	0-443 A 0-382 E 0-508 E	LACEY, W. S. LACEY, W. S. LACEY, W. S.	8307110446 8307180170 8307220277	50-334 8 50-334 8 50-334 8
PEPPLER J G PEPPLER, J G PEPPLER, J G PEPPLER, J G MEPPLER, J G	8307110532 5. 8307190073 50 8307250478 50	0-295 S 0-461 A 0-246 G 0-254 G	KNIGHTON, G. W. KNOP, R. C. KNOP, R. C. KNOP, R. C. KNOP, R. C.	8307290192# 50 8307110268 50 8307110424 50	0-443 E 0-275 P 0-461 G	LADUM, R. H. LAFLAMME, B. J. LAFLAMME, B. J. LAGIENSKI, J. S.	8307280173 8307110279 8307120082	50-334 8 70-148 50-309 8 50-309 8
PERPEER, J. G PERPEER, J. G PERPECOLE, C MERR, G. W NERR, W	8307280322 50 8307280446 50 8307280068 HI 8307150155	0-331 g 0-461 A 0-10 g SEC REG	KNOP, R. C. KNOP, R. C. KNORR, J. E. KNOTTS, J. B.	8307180007# 50 8307180132 50 8307280392 50	-454 G -454 G -483 G -483 G -266 F	LAGIEWSKI, J. S. LAGRANGE, R. G. LAINAS, G. C. LAINAS, G. C. LAINAS, G. C.	8307120144 5 8307190281* 5 8304200163* p	70-317 B 70-443 T 7R 10-302 P
KESEL D T MEDEL D T METILACH N METILACH N	8307200257 50 9307110345 50 8307150014 50	-220 S -220 S -220 S	KNOTTS, J. B. KNUBEL, J. KO, J. D. KOENIG, E. C.	830723036* 50-	-219 p -423 g	LAINAS, G. C. LANDAU, M. LANDERS, D. F. LANDERS, D. F.	8307040487 5 8307070444 5 8307150155 N 8307010091 5	0-366 P 0-272 8 UREQ 0-322 R
etilagh, h Etilagh, h Etilagh, h Etilagh, h Evserling, li p	8307110147# 70- 8307180415 70- 8307180416 70- 6307190026# 70-	~120) -2950 -2983 -2983 -2945	KDESTER, O. L. KOESTER, O. L. KOESTER, O. L. KOESTER, O. L.	8307050080 50- 8307050087 50- 83070500113 50-	-315 S -482 A -482 S -482 S	LANDERS, D. F. LANDERS, D. F. LANDGRAF, L. C	9307290140 50	0-322 A 0-322 A
EVERTLING W M IDLER D R IEL G R IEL G R	TPO	18 331 g RTLIC	KOESTER, O. L. KOESTER, O. L. KOESTER, O. L. KOESTER, O. L.	8307060077 50- 8307120476* 50- 8307120515	482 S 482 V	LANDSMAN, R. B. LANDSMAN, R. B. LANDSMAN, R. B.	8307060340 50 8307140344# 50 8307250470 50	0-341 K 0-329 8 0-329 0 0-329 A
		RILIC	KDESTER, Q. L. KDESTER, Q. L.	8307150241 50- 8307150243 50- 9307180278* 50-	482 5 492 5	LANE, R. E. LANE, R. E. LANKEBURY, R. D. LANPHER, L. C.	8307200193 50 8307200199 50 8307140422* 50	0-327 Q 0-275 S 0-275 S 374 Q 275 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHÜR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHÜR	ACCESSION NUMBER	SUBJECT
LANPHER; L. C. LANPHER; L. C. LARIZZA; Ø. F. LARSON; C. E. LARSON; C. E.	8307220357 8307220357 8307280366 8307080343 8307280353*	50-322 0 50-322 0 50-244 8 50-263 R 50-263 9	LEVINE, J. M. LEWIS, M. LEWIS, M. I. LEWIS, M. I. LEWIS, N. D.	8307050078 8307190127 8307150183 8307150235 8307110465	90-368 B 90-352 G PR NUREG PR	LEWIS, S. H. LIANG, C. LICITRA, E. A. LICITRA, E. A. LICKUS, R. M.	8307060495 8307130120 8307050498 8307220109 8307280274*	50-358 G TOPREP 50-528 F 50-400 F 50-275 G
LARVIE, F. LATHAM, K. L. LATHAM, K. L. LATHAM, S. LATHAM, B. B.	8307270300* 8307060167 8307150298 8307200210 8307050180	WASTE MOT 50-322	LEWIB, N. D. LEWIS, N. D. LEWIS, N. D. LEWIS, N. D. LEWIS, N. D.	8307280031 8307280034 8307280049 8307280056 8307280058	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	LIDEN, E. A. LIDEN, E. A. LIDEN, E. A. LIDEN, E. A. LIDEN, E. A.	8307070057 8307130255 8307130274 8307200004 8307200067	50-272 F 50-311 S 50-272 S 50-272 F 50-272 P
LATHAM: S. B. LATHAM: S. B. LATHAM: S. B. LATIMER: P. S. LAUDE: L.	8307050180 8307070203 8307270159* 8307250511 8307250370*	50-322	LEWIS, N. D. LEWIS, N. D. LEWIS, N. D. LEWIS, N. D. LEWIS, N. D.	8307280067 8307280077 8307280097 8307280103 8307280109	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	LIDEN, E. A. LIDEN, E. A. LIDEN, E. A. LIDEN, E. A. LIDEN, E. A.	8307210037 8307210104 8307250427 8307250449 8307270402	50-311 P 50-272 P 50-272 P 50-272 F 50-272 P
LAUER, R. J. LAUER, R. J. LAUER, R. J. LAUER, R. J. LAURENBON, J. A.	8307190252 8307190252 8307220351 8307220351 8307110315	50-329 T 50-329 T 50-329 T 50-329 T 50-322 G	Lewis, N. D. Lewis, N. D. Lewis, N. D. Lewis, N. D. Lewis, N. D.	8307280113 8307280119 8307280139 8307280145 8307280158	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	LIDEN, E. A. LIDEN, E. A. LIEBERMAN, J. LIHOU, H. LIMAYE, G. S.	8307270416* 8307270180 8307130236 8307220258 8307120377*	50-272 G 50-272 P 50-358 G 50-245 S 50-528 S
LAURENSON, J. A. LAURENSON, J. A. LAURENT, N. N. LAWRENCE, M. J. LAZARUS, W. J.	8307140468 8307220366 8307220327 8307220248* 8307010047*	50-142	LEWIS, N. D. LEWIS, N. D. LEWIS, N. D. LEWIS, R. C.	8307280162 8307280171 8307280172 8307280177 8307050158	WASTE MGT WASTE MGT WASTE MGT WASTE MGT SO-416 G	LIME, J. F. LIMOGES, C. LIN, D. L. LIND-HOWE, K. E. LINDER, F.	8307250109 8307220275 8307220200 8307070156 8307110127	NUREQ 50-247 S 50-373 R PR 50-409 S
LAZARUS, W. J. LAZO, L. LAZO, L. LAZO, R. M. LAZO, R. M.	8307220179 8307220043 8307220046 8307120572 8307280184	50-333 8 50-412 A 50-412 A 50-529 G 70-25	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307050175* 8307040287 8307140054 8307140062 8307140068	50-414 G 50-321 G 50-348 G 50-259 G 50-280 F	LINDER, F. LINDER, F. LINDER, F. LINDER, F. LINDER, F.	B307110563* B307120624* B307200264 B307210253* B307220222	50-409 F 50-409 F 50-409 S 50-409 R
LEAHY, M. LEAVER, D. E. LEDDICK, R. B. LEDGERWOOD, R. K. LEE, J.	8307220240 8307150301 6307150203* 8307220240* 6307050071	50-249 8 PR 50-508 0 WASTE MGT 50-287 G	Lewis.r.C. Lewis.r.C. Lewis.r.C. Lewis.r.C. Lewis.r.C.	8307140093 8307140112 8307140169 8307140189 8307140215	50-416 F 50-387 G 50-364 G 50-369 G TOPREP	LINDER, F. LINDSEY, C. G. LINDSEY, C. G. LINENBERGER, G. LINVILLE, J. C.	8307220225 8307080596 8307150147 830705016B 8307110421*	30-409 R NUREO NUREO 30-344 G 30-333 Q
LEE, J. LEE, J. LEE, J. LEE, J. LEE, J. C.	8307140453 8307210252 8307210254* 8307290138 8307220035	50-287 0 50-287 H 50-287 H 50-287 0 ACR8	Lewib, R. C. Lewib, R. C. Lewib, R. C. Lewib, R. C. Lewib, R. C.	8307140216 8307140218 8307140223 8307140227 8307140227	TOPREP 50-347 P 50-280 G 50-389 G 50-250 G	LIPINSKI, D. R. LIPINSKI, W. C. LIPINSKI, W. C. LIPINSKI, W. C.	8307010167* 8307200342 8307200342 8307200347 8307200347	50-245 G ACRS ACRS ACRS
LEE, O. R. LEECH: P. LEMPOES: T. E. LEMPOES: T. E. LEMPOES: T. E.	8307120408 8307170395 8307010033 8307010154 8307110263	50-247	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307140231* 8307140237 8307140244 8307140252 8307140254	50-280	LISENO.R. LITKA.T.J. LITTLE.B.H. LITTLE.W. LITTLE.W.S.	83070500R9* 8307220446 8307280375* 8307190039 8307080283	50-333 F 50-10 S 50-341 Q 50-546 B 50-461 Q
LEMPOES, T. E.	8307110365 8307150014 8307150080 8307150115 8307220325	20-550 8 20-550 8 20-550 8 20-550 8	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307140257 8307140263 8307140266 8307140269 8307140273	50-369 F TOPREP 50-416 G 50-259 V 50-395 G	LITTLE, W. S. LITTLE, W. S. LITTLE, W. S. LITTLE, W. S. LITTLE, W. S.	8307080286 8307080289* 8307080329 8307080448 8307110139	50-341 0 50-341 0 50-374 0 50-440 0 50-454 0
LEMPOES, T. E. LEMPOES, T. E. LEMPOES, T. E. LENAHAN, J. J. LENTINE, F. Q.	8307250438* 8307260155 8307280389* 8307140156* 8307010103	50-220	Lewib, R. C. Lewib, R. C. Lewib, R. C. Lewib, R. C. Lewib, R. C.	8307140285* 8307140292 8307140336 8307140340 8307140355*	50~387 0 50~321 G 50~247 G 50~327 G 50~327 G	LITTLE, W. S. LITTLE, W. S. LITTLE, W. S. LITTLE, W. S. LITTLE, W. S.	9307110352 9307110360 9307140071 9307140075 9307140175	50-483 Q 50-483 Q 50-454 Q 50-483 Q 50-373 Q
LENTINE, F. G. LENTINE, F. G. LENTINE, F. G. LESSOR, L. C. LESSY, R. P.	8307120281 8307120391 8307280375 8307260357 8307070016	50-454 A 50-295 P 50-295 P 50-298 S 50-443 G	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307140359 8307140360 8307140367 8307140376 8307140392	50-321 P 50-259 Q 50-416 P 50-321 P 50-261 Q	LITTLE, W. S. LITTLE, W. S. LITTLE, W. S. LITTLE, W. S. LITTLE, W. S.	8307140221 8307210139 8307210147 8307220463 8307260011*	50-546
LEBBY: R. P. LEBBY: R. P. LETSCHE: K. J. LETSCHE: K. J. LETSCHE: K. J.	8307170150 8307170276 8304270048* 8304270048* 8307050266	50-443	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307140393 8307140402 8307140408* 8307140414 8307140467	50-335	LITTLE, N. S. LITTLE, N. S. LITTLE, N. S. LOCKSTET, N. A. LOCKE, R. F.	8307280142 8307280247 8307280253* 8307070054 8307270147	50-374 G 50-440 G 50-440 G 50-275 G
LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J.	8307120350 8307120350 8307120350 8307120350 8307120350	50-322 6 50-322 6 50-325 6 50-325 6	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307140473* 8307220001 8307220003* 8307220059 8307220048*	50-321	LODGE, J. L. LODGE, T. J. LODGE, T. J. LODGE, T. J.	8307260274 8307260274 8307150325 8307150325 8307200214	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G
LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J.	8307120367* 8307120367* 8307270154 8307270154 8307270154	50-322	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307220204 8307220273* 8307220274 8307220333 8307220340*	50-324	LODGE, T. J. LOTTUB, P. A. LOGIDDICE, J. M. LOGEDON, M. LOGEDON, M.	8307200214 8307080314* 8307200185* 8307090103 8307220084	CONTRACT WASTE MOT WASTE MOT
LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J. LETSCHE, K. J. LEVI, R. P.	8307270154 8307270154 8307270159* 8307270159* 8307150172	50-322	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307220445 8307220464 8307220468* 8307220528 8307220532*	50-259 0	LOOSDON, M. LOOSDON, M. J. LOOSDON, M. J. LOOSDON, M. J. LOIS, L.	8307220164 8307220077 8307220171 8307260171 8307110037	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 50-261 G
LEVIN.H.A. LEVIN.H.A. LEVIN.H.A. LEVINE.D.L.	8307210225 8307210233* 8307210271 8307210276* 8307170035*	50~327 R 50~329 R 50~329 R 50~329 R 71~5552	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	8307220338 8307220548 8307220557* 8307220562 8307220569*	50-395 G 50-395 G 50-324 G	LOMONACO, L. LOMONACO, L. M. LONERGAN, T. LONG, J. K. LONGENECKER, J.	8307120032* 8307120027* 8307260531* 8307120176* 8307070086	9 50-286 F 9 50-298 Q

AUTHOR	ACCESSIO RABRUM	CATEGORY	AUTHOR	ACCESSI NUMBER			ACCESSIO NUMBER	N SUBJECT
LONGENECHER. )	830707010		MACDONALD, C. E.	83072505		MARCHAL, J.		
LONGENECHER. J	83071203		MACDONALD, C. E.	83072505		MARCHALI J.	830707037: 830711054:	
LENGEST, A # LENGO, T. P	830721026		MACDONALD, C. E.	83072505	73* 71-5026	MARCHAL, J.	830711056	
LOOMIS G D	830722017 830721028		MACDONALD C E.	83072505		MARCHAL, J.	#30719011a	XPORTLIC
	PTO/EIGE:	3 MYKEY	MACDONALD, C. E.	830725057	76 71-6272	MARCHAL, J.	<b>B3072002</b> 94	XPORTLIC
LOTCHIN, P	930706025		MACDONALD, C. E.	830725057	77 71-210	MARCHAL, J.	B307250648	Vhena
LOTITO, E LOVENDALE, P.C.	830720014		MACDONALD, C. E.	830725058	}i 71-6272	MARQULIES, M. B.	E307140461	
LOVENDALE, P.C.	930712050 930719004		MACDONALD.C.E. MACDONALD.C.E.	630725056		MARQULIES, M. D.	B307250393	50-261
LOWREY. A	830722005		MACDONALD, C. E.	830725059 830725060		MARQULIES, M. B. MARK, R.	B307250492	30-261
LOY, C						i ionat a i	E307190225	* 50~443
LUCK, H D	830719014 830725036		MACDONALD, C. E. MACDONALD, C. E.	830725060		MARK, R.	8307190225	* 50-443
LUCKS, A S	830714034		MACDONALD, C. E.	830725040 830729037		MARGUARDT, W. G.	<b>8304280593</b>	* 50-445 '
LUCKS A 5	830714035		MACDONALD, C. E.	830727038		MARBCHALL, C. W. MARBCHALL, C. W.	8307120009	*************
LUCKS, A. S.	B30714035	4* 50-329 G	HACDONALD, C. E.	830729038		MARSHALL, J. R.	9307120012 9307060051	
LUCKS. A S	8307140356	8+ 50-329 @	MACDONALD, C. E.					50-313 1
LUCKS. A S.	930714036	14 50-329 Q	MACDONALD, C. E.	830727041 830727042		MARSHALL, J. A.	B307060250	\$0~36B F
LUCKS, A. S	8307140365	5+ 50-329 G	MACDONALD, J. A.	830721019		MARSHALL, J. R. T MARSHALL, J. R.	8307080413	50-313
LUCKS. A. S	8307140370 8307140370		MACDOUGALL, R.	830724013		MARSHALL, J. R.	8307110295 8307120191	
	420717037	3+ 50-329 <u>0</u>	HACDOUGALL, R.	0307260192	2 Waste Mot	MARSHALL, J. R.	Ø307120269	50-368 6 50-313
LUCKS.AS LUKSDEN.RE	8307140378		MACDQUQALL, R.	830726021	WASTE MOT	MADOLIAL 4 n		
LUNDINE . S.	8307050191 830727005		MACOREGOR, N.	8307220373		MARSHALL, J. R. MARSHALL, J. R.	B307120304	20-313 b
LUNDVALL, A E	B307060292	3* 50-247 U ? 50-317 G	MACRAE, B. L.	9307120018	NUREG	MARSHALL, J. R.	8307150271 8307150383	50~313 8
LUNDVALL, A E	8307110129		MADEDA, T. MADEDA, T. J.	B307080020		8 MARSHALL, J. R.	8307180079	50-313 B
LUNDVALL, A E	0203100014			8307120439	?* 50~373	q MARSHALL, J. R.	8307190065	50-313 p
LUNDVALL, A E	9307120264 8307150110		HADEDA, T. J.	8307280325	* 70-36	MARSHALL, J. R.	00071001##	
LUNDVALL, A E	8307200133	50-317 F	MADISON, A. MADISON, A.	8307220531	50-373	S MARSHALL, J. R.	8307190155 8307190181	50-313 p
LUNDVALL: A. E. LUNDVALL: A. E.	6307210013	50-317 K	HADISON, A. L.	8307260541 830718 <b>0</b> 177		MARSHALL, J. R.	8307210159	50-313 P
CONDINGE, M. E.	9307210198	50-317 P	MADSEN, Q. L.	8307050119		G MARSHALL, J.R. G MARSHALL, J.R.	8307210299	30-313 p
LUNDVALL.A E.	8307250091	71-9111	Manage a .			G MARSHALL, J. R.	8307220278	50-313 R
LUNDVALL, A. E. LUNDVALL, A. E.	8307280199	50-317 P	MADSEN, Q. L. MADSEN, Q. L.	8307050132		9 MARSHALLIJ.R,	8307220305	50-0/0 -
LUNDVALL A E	B307280352		MADSEN, G. L.	8307060122 8307060132	44 270 6	MARBHALL, J. R.	8307220310	Я 85C-05 4 E1E-05
LUTTON, R J.	8307280430 8307150137	50-317 P NUREQ	MADSEN, Q. L.	8307060145			9307220517*	50-313 g
1 3/33/ALL 14 Th		HANGE W	MADSEN, Q. L.	8307060241	30-3B2 G		8307220540	50-313 g
LYNCH, H D LYNCH, H D	8307130297 8307130301	50-341 A	MADSEN, Q. L.	8307120255			8307250482	20-313 K
LYNCH, M. D.	8307260487	50-341 A 50-341 A	MADSEN, G. L.	8307120235	50-267 G		8307240075	50-346 g
LYNCH, H. D.	8307290493	50-341 A 50-341 A	MADSEN, G. L.	8307120405	50~278 G		8307260094	50-313 0
EYNCH, N. P.	8307260268	50-546 G	MADSEN, G. L. MADSEN, Q. L.	B307120425	50-382 g		8307260190 8307260322	50-313 R
MACANN, J.	83072803494		THE BETT G. L.	8307120440	50-382 G	MARBHALL, J. R.	6307260322	8 84C-05 9 94C-05
MACDONALD, C. E	9307050248	50-397 g PR	MADSEN, Q. L.	8307120486	50-458 g	MARRILLI		40-380 P
MACDONALD, C E MACDONALD, C E	8307050275	WASTE HOT	MADSEN, G. L.	8307120520	50-49B Q		8307260584	8 8AE-07
MACDONALD.C E	8307080623	71-607B	MADSEN, Q. L. MADSEN, Q. L.	8307150122	30-498 G		8307210117	50-445 A
	8307080657	71-6406	MADSEN, Q. L.	8307150133 8307150185	50-267 Q	MARGHALL, M. H.	9307070198 8307070198	50-329 Q
MACDONALD C. E.	8307060569*	71-6406	M4==== .		20-115 G	MARSHALL, R, K.	8307120024	50-329 Q NUREQ
MACDONALD, C.E. MACDONALD, C.E.	8307080672	71-9180	MADSEN, Q. L. MADSEN, Q. L.	8307150281	50-392 g	MARTIN, D. E.		***************************************
MACDONALD C E	8307080676* 8307110071	71-9180	MADSEN, Q. L.	9307150303	50~29B G	MARTIN, D. E.	8307050296 8307050388	WABTE MOT
MACDONALD, C E	8307110085	71-9089 71-5874	MADSEN, Q. L.	8307150304 8307150334	50-445 Q	MARTIN, D. E.	8307050399	WASTE MOT WASTE MOT
MACDONALD, C E		** 5074	MADSEN, C. L.	8307180273	50-458 G 50-267 P	MARTIN, D. E.	8307050405	WASTE MOT
HACDONALD, C. E	8307110092 8307120028	71-9180	MADSEN, Q. L.			MARTIN, D. E.	8307190055	WARTE MOT
MACDONALD.C E	8307120030	71-9505 71-9088	MADSEN, G. L.	8307210192 8307220285	50-445 G	MARTIN, D. E.	8307190451	
MACDONALD, C. E MACDONALD, C. E	8397120034	71-6286	MADSEN, G. L.	8307260280	50~498 Q 50~298 G	MARTIN, D. E.	8307190472	TOM STRAW
MUCODINACD, C. E.	8307130017	71-5641	MADSEN, C. L.	8307260433	50~298 P	MARTIN, D. E.	8307260118	WASTE HOT
MACDONALD, C. E	8307130022+		MADSEN, Q. L.	8307260514	50-298 G	MARTIN, D. E. MARTIN, J.	8307260127	WASTE MOT
MACDONALD, C E	930713002B	71-5641 71-6708	MADSEN, G. L.	8307260531*	** ***	,	8307050151#	50-397 E
MACDONALD, C. E. MACDONALD, C. E.	8307130029	71-9044	MADSEN, G. L.	8307290137	50-298 g 50-267 g	MARTIN, J.	8307050156*	50-397 E
MACDONALD, C. E.	8307130030	71-300	MAIDRAND, R. A. MAIER, J. E.	9307210191*	50-267 G 50-443 T	MARTIN, J.	8307050160*	50-397 E 50-397 E
	8307130034	71~9033	MAIER, J. E.	8307120031*	50-244 F	MARTIN, J. MARTIN, J.	8307050165*	50-397 E
MACDONALD, C.E.	8307130034	71-500		8307120490	50-244 p	MARTIN, J.	8307050167#	50-397 E
MACDONALD, C. E.	8307130037	71-9151	MAIER, J. E.	8307150379	50-244 g		8307050173#	50-397 E
MACDONALD. C.E.	8307130039 8307130042	71-499	MAIER, J. E. MAIER, J. E.	8307190169*	50-244 g	MARTIN, J. B. MARTIN, J. B.	8307040374	50~312 F
MACDONALD.C.E	8307130045+	71-5971 71-499	HAIER, J. E.	8307220262	50-244 g	MARTIN, J. B.	8307060408	50-528 G
MACDONALD, C E			KAIER, J. E.	9307220377 8307240445	50-244 g	MARTIN, J. B.	8307140455* 8307150252	50-142 0
MACDONALD, C E	8307130052 8307130053	71-9080	MAIER, J. E.		50-244 p	MARTIN, J. B.	8307180165	50-397 A Nureo
MACDONALD, C.E.	8307130066	71-9176	MAIER, J. E.	8307270448*	50-244 p	MADTIN ( n		HUNES
MACDONALD, C E	8307130311	71-5957 71 <b>-</b> 9135	MATER, J. E.	8307280337 8307280346	50-244 Q	MARTIN, J. B. MARTIN, J. B.	B307250558*	FOIA
	8307130315	71-494	MAIYA, P. S.	8307090133	50-244 g	MARTIN, J. B.	8307250564* 8307250593*	FOIA
MACDONALD, C E	8307190392	74	MAKINO, M.	8307220033	NUREO WASTE MOT	MARTIN, J. B.	8307250613#	FOIA
MACDONALD, C. E. MACDONALD, C. E.	8307190401	71~5957 71~9163	MANGAN, C. V.			MARTIN, J. B.	8307270456	FOIA HASTE MOT
MACDONALD, C. E	8307190404	71-9163	MANGAN, C. V.	8307010102 8307070038	50-220 G	MARTIN, L. H.		
MACDONALD, C E	8307190415 8307190420#	71-9010	MANGAN, C. V.	8307070099	50-220 p 50-220 p	MARTIN, R. A.	9307130261* 9307130370	50~400 G
		71-9010	MANGAN, C. V. MANGAN, C. V.	8307120198	20~550 K 20~550 b	MARTIN, R. A.	日30プタんのハ4つ	RES RES
MACDONALD, C. E. MACDONALD, C. E.	8307190428	71-9089		8307120294	50-220 P	MARTIN, R. E. MARTIN, R. E.	8307070549	50-352 A
MACDONALD, C E	8307190434	71-9070	MANGAN, C. V.	8307120388			8307070556	50-352 A
MACDONALD, c #	8307190468 8307220105	71-9163	MANGAN, C. V.	8307140309	50-220 F	MARTIN, R. E.	8307150373	
MACDONALD, C E	9307250023	71-9070 71-9108	MANGAN, C. V. MANGAN, C. V.	B307140348	50-220 p	MARTIN, R. E.		50-352 A
MACDONALD, C. E.		- 1140	MANGAN, C. V.	8307220150	71-6346	MARTIN, R. E. MARTIN, R. E.	8307150389	50-352 E 50-352 A
MACCONALD, C.E.		71-6771		8307250495*	50-550 ₽	MARTIN, T.	8307200449	50-352 E
MACDONALD, C. E.	8307250553	71-6550	MANN, B. MANN, B. D.	8307120016	NUREG			50-423 B
MACDONALD, C.E.	B307250559	71-5552 71-9098	MANNA, F. J.	8307250451	50-339 P	MARTIN, T. J.	8307150199	50_25A 0
······································		71-5552	MANNING, W .	8307150119 8307260167*	50-247 g	MARTIN, T. T. MARTIN, T. T.	B307010007	50-354 8 50-272 G
			MANNO, S. F.	8307190151	FOIA	MARTIN, T. T.	8307010014	20~355 G
				1	50-410 g	MARTIN, T. T.	8307010035	50~322 G
						• •		20-550 6

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	,	AUTHOR	ACCESSION NUMBER	SUBJECT
MARTIN, T. T. HARTIN, T. T. MARTIN, T. T. HARTIN, T. T. HARTIN, T. T. KARTIN, T. T.	8307010072 8307010125 8307010128 8307010129 8307010139	50-245	MAYBERRY, G. B. MAYES, R. MAYES, R. MAYWEATHER, L. MCALPINE, E. J.	8307290290 8307280421* 8307280429* 8307220465 8307010003	71-9006 50-369 50-369 50-361 70-1201	P P R	MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8307120526 8307120592 8307140230 8307150092 8307150113	50-416 8 50-416 8 50-416 0 50-416 5 50-416 8
MARTINIT.T. MARTINIT.T. MARTINIT.T. MARTINIT.T. MARTINIT.T. MARTINIT.T.	8307010152 8307060022 8307060030 8307060117 8307060338	50-352 G 50-244 G 50-293 Q 50-271 G 70-1100	MCALPINE, E. J. MCALPINE, E. J. MCALPINE, E. J. MCALPINE, E. J. MCALPINE, E. J.	8307140199* 8307140283* 8307140327* 8307140330* 8307140377*	70-143 70-1201 70-1151 70-1113 70-1201		MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8307150144 8307150239 8307150274 8307150369 8307220296	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S
HARTIN, T. T.	8307110251 8307110257 8307110280 8307110351 8307110362	50-307	MCALPINE, E. J. MCBREARTY, R. MCBREARTY, R. A. MCBREARTY, R. A. MCBREARTY, R. A.	8307140460* 8307280449* 8307010146* 8307040124* 8307140315*	70-1151 50-293 50-271 50-271 50-220	9 9 9	MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8307220482 8307220500* 8307220505* 8307250164 8307250173	50-416 S 50-416 Q 50-416 Q 50-416 S 50-416 S
MARTINIT.T. HARTINIT.T. MARTINIT.T. HARTINIT.T. HARTINIT.T. HARTINIT.T.	8307110369 8307110386 8307110410 8307110463 8307110498	50-97 Q 50-247 Q 50-286 Q 50-220 Q 50-271 Q	MCBRIDE, M. H. MCGABE, E. MCGABE, E. MCGABE, E. MCGABE, E. C.	8307110388* 8307010079 8307110274 8307280127 8307110620	50-247 50-387 50-387 50-322 50-322	9 8 5 A A	MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8307 250289 8307 250473 8307 260464 8307 270128 8307 270238	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8
HARTIN, T. T.	8307110536 8307120214 8307120253 8307120456 8307140079	50-244 G 50-287 G 70-371 50-387 G 50-57 G	MCCABE, E. C. MCCABE, E. C. MCCABE, E. C. MCCABE, E. C. MCCABE, E. C.	8307140469* 8307150313* 8307250442* 8307260346* 8307280349*	50-354 50-387 50-322 50-387 50-387	G G G	MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W.	8307010181 8307040177 8307040249 8307080386* 8307180039	50-331 K 50-331 P 50-331 P 50-331 Q 50-331 Q
MARTIN, T. T. MARTIN, T. T. HARTIN, T. T. HARTIN, T. T. HARTIN, T. T. HARTIN, T. T.	8307140232 8307140238 8307140277 8307140384 8307140404	50-311 G 50-27 G 70-364 50-286 G 50-333 G	MCCANN, J. MCCARTEN, J. B. MCCABKILL, R. E. MCCLESKEY, K. E. MCCLESKEY, K. E.	8307150313* 8307040197 8306280580* 8307120381 8307120381	50-387 50-358 50-445 50-322 50-322	e 1 0 0	MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W. MCGAUGHY, R. W.	8307170100 8307250108 8307250215 8307260140 8307260471*	50-331 P 50-331 P 50-331 P 50-331 P 50-331 G
MARTINIT, T. MARTINIT. T. HARTINIT. T. HARTINIT. T. MARTINIT. T. HARTINIT. T.	8307150255 8307150260 8307190087 8307190206 8307210018	50-277	MCCLESKEY, K. E. MCCLINTDCK, R. O. MCCLINTDCK, R. O. MCCLINTDCK, R. O. MCCLINTDCK, R. O.	8307260411 8307210341* 8307210347* 8307210358* 8307220083*	50-322 70-378 70-378 70-378 FOIA	9	MCGAUGHY, R. W. MCGOWAN, J. J. MCGRANERY, J. P. MCGUIRE, D. R. MCGUIRE, D. R.	8307260497 8307080243 8307110454 8307050181# 8307060299#	50-331 P 50-237 8 PR 50-414 0 50-321 0
MARTIN, T. T. MARTIN, T. T. HARTIN, T. T, HARTIN, T. T. MARTIN, T. T. MARTIN, T. T.	8307210023 8307210033 8307210121 8307210130 8307210204	50-322 Q 50-423 Q 50-443 Q 50-271 F 50-389 Q	MCCLINTOCK, R. O. MCCLUNG, R. W. MCCLUNG, R. W. MCCOLLOM, K. A. MCCONNELL, T.	8307220102* 8307210248 8307250511 8307080441 8307250092*	FOIA NUREG NUREG 50-445 50-369	G F	MCQUIRE, D. R. MCQUIRE, D. R. MCQUIRE, D. R. MCQUIRE, D. R. MCQUIRE, D. R.	8307080460* 8307140165* 8307140312 8307150355* 8307180094*	70-143 50-327 0 50-349 F 50-335 0 50-261 0
MARTIN, T. T.	8307210213 8307220038 8307220373 8307250040* 8307250114	50-412 G 50-277 F 50-271 G FOIA 70-2319	MCCRAY, B. L. MCCREDA, B. MCCRORY, B. L. MCCRORY, B. L. MCCULLUGH, R. W.	B307050129* B307240531* B30705013B* B307150079* B307240440*	50-267 50-298 50-445 50-285 TOPREP	G G G	MCGUIRE, D. R. MCGURREN, H. J. MCGURREN, H. J. MCGURREN, H. J. MCGURREN, H. J.	8307190060* 8307130234 8307180019 8307180022 8307210051	50-338 G 50-247 Q 50-338 G 50-275 Q 50-247 Q
MARTIN,T.T. MARTIN,T.T. MARTIN,T.T. HARTIN,T.T. MARTIN,T.T. MARTIN,T.T.	8307250349 8307250440 8307280123 8307280164 8307280269	40-672 40-86 40-672 40-672 50-309 <b>G</b>	MCCUTCHEN, P. MCDERMOTT, D. MCDERMOTT, D. MCDERMOTT, D. MCDERMOTT, D.	8307220075# 8307200172 8307200181 8307290161 8307290420	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		MCINNES, I. D. MCINNES, I. D. MCINNES, I. D. MCINNES, I. D. MCINNES, I. D.	8307070184* 8307070211* 8307070218* 8307180147* 8307180152*	50-237 P 50-237 P 50-237 P 50-237 P 50-237 P
MARTIN, T. T. MARTIN, T. T. MARTIN, T. T. MARTIN, T. T. MASON, C. C.	8307280278 8307280312 8307280334 8307280343 8307220474	50-333	MCDIARMID, R. C. MCDUNALD, D. G. MCDUNALD, J. C. MCDUFFIE, M. A. MCDUFFIE, M. A.	8307210216 8307150434 8307180139 8307010053 8307060095	50-416 50-250 NUREG 50-400 50-400	M P E E	MCINNES, I.D. MCINTOSH, M.D. MCKENZIE, B. MCKEGHN MCKEGHN, L.M.	8307180158* 8307290544* 8307070208 8307050201 8307110425*	50-237 P 50-369 F 50-170 0 50-423 S 50-296 G
MASSEY, J. V. MASSEY, J. V. MASSIE, H. H. MASTERSON, B. MASTERSON, V. V.	8307070181* 8307180138* 8307190067* 8307210048 8307220193	50-237 P 50-237 P 50-237 P 50-373 S 50-373 S	MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A.	8307060111 8307060114 8307060121 8307060144 8307060163	50-400 50-400 50-400 50-400 50-400	E E E E	MCKEDHN, L. M. MCKINNEY, C. J. MCKINNEY, C. J. MCKINNEY, C. J. MCLEAREN, T.	8307140410* 8307110370 8307220252 8307220274 8307150054	50-333 0 50-395 S 50-395 S 50-395 S CONTRACT
MABTERSON, V. V. MATAKAS, R. A. MATERS, B. R. MATHIS, J. L. MATTHEWS, B. A.	8307220201 8307250060* 8307120239 8307220473* 8307050231	50-373 B FOIA 50-341 A 50-390 Q 50-241 G	MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A.	8307040234 8307040302 8307070085 8307070125 8307080315	50-400 50-400 50-400 50-400 50-400	원 문 문	MCLEAREN, T. MCLESKEY, K. E. MCNAMARA, A. E. MCNEIL, M. B. MCNEIL, M. B.	8307150413 8307180213 8307220178 8307220024 8307260029	CONTRACT 50-322 G 50-244 R WASTE MOT WASTE MOT
MATTHEWS, B. A. MATTHEWS, B. A. MATTHEWS, C. R. MATTHEWS, D. E. MATTHEWS, D. E.	8307050236* 8307150346 8306280588* 8307150016* 8307180436*	50-261	MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A. MCDUFFIE, M. A.	8307080390 8307140323 8307150225 8307210146 8307270057	50-400 50-400 50-400 50-400 50-400	E F E K	MCNEIL, M. B. MCNEILL, C. A. MCNEILL, C. A. MCNEILL, C. A. MCNEILL, C. A.	8307260265 8307010017 8307010046 8307010060 8307010111	WARTE MOT 50-333 S 50-333 S 50-333 S
MATTHEWS, T.P. MATTIA: M.J. MATTIA: M.J. MATTIA: M.J. MATTIA: M.J.	8307190158 8307140119* 8307140328* 8307190458* 8307250491*	50-285 R CONTRACT CONTRACT CONTRACT CONTRACT	MCDUFFIE, M. A. MCDUFFIE, M. A. MCELROY, W. N. MCFARLAND, D. M. MCFARLAND, D. M.	8307270340 8307280361 8307140478 8307260024* 8307260028*	50-400 50-400 RES 50-237 50-237	E E P	MCNEILL, C. A. MCNEILL, C. A. MCNEILL, W. M. MCPARTLAND, S. A. MEDLUCK, R. L.	8307110400* 8307120527 8307120221* 8307150178 8307180394	50-933 G 50-333 R GA979 NUREG 40-8452
MATTSON, R. J. MAUR IN. L. V. MAVEAL, W. T. MAXWELL, D. MAXWELL, G.	8305040455* 8307260422 8307240455 8307110115 8307220141*	50-322 A 50-382 V 50-16 R 50-237 S 50-400 Q	MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8307050166* 8307120102 8307120109 8307120275 8307120433	30-416 50-416 50-416 50-416 50-416	G 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	MEDBKER, L. MELSTAD, K. MENDES, T. MENDEZ, R. MENDEZ, R.	8307060406* 8307060220 8307190015* 8307140074* 8307280395*	50-400 G 50-346 8 70-820 50-454 G 50-341 G
MAXWELL, Q.F. MAXWELL, Q.F. MAY, E. L. MAY, E. L. MAY, E. L.	8307220344* 8307280442* 8307010114 8307150130 8307220327	50-400 0 50-440 0 50-29 5 50-29 8	MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8307120452 8307120459 8307120473 8307120509 8307120525	50-416 50-416 50-416 50-416 50-416	5 5 5 5	MENDONCA, M. M. MENINICK, J. MENSCER, D. V. MENTA, H. S. MERLINO, R. J.	8307120522* 8307270480 8307170142* 8307140299* 8307210191*	50-275 Q WASTE MOT 50-546 I 50-277 P 50-443 T

AUTHOR	ACLESSION REMUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGOR
MERRILL. D. N MERRINGATHER. N MENHINGEY. J. A MEYER. O. C	8307210191 8307280264 8307110124 8307110124 8307200382	* 50-440 Q NUREG NUREG	MILLS, L. M. MILLS, L. M. HILLS, L. M. HILLS, L. M. MILLS, L. M.	6307120598 8307140045 8307140045 8307140275 8307140345	50-326 P 50-438 R 50-327 V	MOONEY, J. A.	9307080508 8307080514 8307200079 83072101444 8307210208	50-329 50-329 50-329
MEYERS, B. L. MEYERS, B. L. MEYERS, D. O MICHEJDA, O. MIGHT, A	8307260012 8307110244 8307220207 8307150362 8307220008	50-482 S • 50-324 Q	MILLS, L. M. HILLS, L. M. HILLS, L. M. HILLS, L. M. MILLS, L. M.	8307140351 8307150166 8307150207 8307150236 8307150267		MOONEY, J. A. MOONKA, A. K. MOORE, D. E. MOORE, D. E. MOORE, Q. C.	8307280434 8307190067* 8307140165* 8307150355* 8307120249	50-329 50-237 50-327
MICHT, A MIXICS, J. MILLER, D. MILLER, D. B	8307220097 8307190097: 8307180139 8307200513 8307140256	50-315 R 40-672 NUREG 70-1257 50-329 A	MILLS: L. M. MILLS: L. M. MILLS: L. M. MILLS: L. M. MILLS: L. M.	8307190087 8307190146 8307190166 8307200095 8307220080	50-328 P PR 50-327 P 50-257 P 50-438 8	MOORE, J. E. MOORE, J. E. MOORE, R. N. MOORE, R. N. MOORE, R. N.	8307130234 8307270221 8307050468 8307050516 8307050527	50-247 50-247 XPORTLIC XPORTLIC XPORTLIC
MILLER.O.D. MILLER.O.E. MILLER.O.E. MILLER.H MILLER.H	8307210255 8307010168 8307010171 8307220062 8307220029	NUREO 50-326 R 50-326 B Waste Mot Waste Mot	Mille, L. M. Mille, L. M. Mille, L. M. Mille, L. M. Mille, L. M.	8307220155 8307220169 8307220211 8307220302 8307220304	50-259 G 50-438 S 50-259 G 50-438 S	MOORE, R. N. MOORE, R. N. MOORE, R. N. MOORE, R. N. MOORE, R. N.	8307070433 8307070534 8307070537 8307070540 8307120890	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MILLER.H J.	8307220124 8307240034 8307240039 8307240046+ 8307240058	WASTE HOT	MILLS, L. M. MILLS, L. M. HILLS, L. M. MILLS, L. M. MILLS, L. M.	8307220321 8307220422 8307220437 8307220526* 8307220533*	50-438 8 50-439 8 50-438 8 50-438 0	MODRE, R. N. MODRE, R. N. MODRE, R. N. MODRE, S. N. MODRE, T. S.	8307170034 8307220583 8307270308 8307110258 8307070235	XPORTLIC XPORTLIC XPORTLIC 50~400 p
MILLER, H.J. MILLER, H.J. MILLER, H.J. MILLER, H.J. MILLER, J. MILLER, J.	8307260064* 8307260074 8307270408 8307270474 8307060225	WASTE MOT WASTE MOT WASTE MOT WASTE MOT INE	MILLS, L. M. MILLS, L. M. MILLS, L. M. MILLS, L. M. MILLS, L. M.	8307220554 8307250127 8307250219 8307250230 8307250272	50-370 8 50-257 0 50-327 F 50-438 8 50-390 8	MODB, D. W. Morgan, C. Morgan, C. Morgan, C. Morgan, C.	8307280025 8307120035 8307120035 8307120365 8307120365	50-275 0 HASTE MOT 50-247 0 50-247 0
MILLER.J. R. MILLER.J. R. MILLER.J. R. MILLER.J. R. MILLER.J. R. MILLER.J. R.	8307050334 830720255 830705085 8307050278 8307120434	50-295 S IAE 50-150 G 50-254 Q 50-373 G	HILEB.L.M. HILLS.L.M. HILLB.L.H. HILLS.L.M. HILLS.L.M.	8307250395 8307250405 8307250408 8307250464 8307250633*	50-390 8 50-390 8 50-438 8 50-438 8 50-259 F	MORGAN, H. E. MORGAN, H. E. MORGAN, R. L. MORIARTY, J. M. MORITA, T.	9307250394 9307250490 9307250349* 8307250249*	50-247 0 50-342 8 50-341 8 WARTE MOT GAPP9
HILLER, J.R. HILLER, J.R. HILLER, J.R. HILLER, J.R. HILLER, L.K. HILLER, L.K.	8307180109 8307180159 8307280321 8307280452 8307150072	50-282 G F&E 70-36 50-150 G 50-272 R	Hills, L. M. Hills, L. M. Mills, L. M. Hills, L. M. Mills, L. M.	9307260032 9307260274 9307260419 9307260434 9307260503	50-259 P REGOD 50-438 8 50-390 8	MORLEY, J. A. MORRILL, P. J.	8307080314# 8307060485 8307070106 8307180331 8307180375	MASTE MOT WASTE MOT WASTE MOT WASTE MOT
HILLER.H. HILLER.H. HILLER.H. HILLER.H.A. HILLER.H.A.	8307150105 8307010080* 8307050020* 8307140391* 8307200316	50-311 R 50-245 G 50-454 G 50-286 G 50-329 A	Mills, L. M. Mills, L. M. Mills, L. M. Mills, L. M. Mills, L. M.	8307260320 8307260335 8307270034 8307270135 8307270172	50-390 8 50-438 8 50-390 8 50-438 8	MORRILL, P. J. MORRIS, B. MORRIS, B. MORRIS, G.	8307040007 8307120533 8307120148* 8307120174* 8307040411*	50-133 8 50-275 P 50-537 T 50-537 T 50-400 0
MILLER, M E MILLER, M I MILLER, M I MILLER, M I MILLER, M I	8307200318 8307150321 8307060355 8307060355 8307190122	50-329 A 50-537 G 50-454 O 50-454 G 50-454 G	MILLS, L. M. MILLS, M. MILLS, M. E. MILLS, S. L. MINADEO, R.	8307270176 8307120016 8307210218 8307270479 8307130328*	50-390 8 NUREG 50-508 A WASTE MGT	MORRIS, P. A.  MORRIS, P. A.  MORRIS, W. J.  MORRISON, Q. M.  MORRISSETT, E.	8307120426# 8307280144 8307220020 8307150233 8307120417	50-322 0 50-352 0 71-37 50-309 8 PR
MILLER, M. I. MILLER, M. S. MILLER, M. S. MILLER, M. S. MILLER, M. S.	9307170122 B307280153 8307140444 B307140444	50-454	MINECK, D. L. MINECK, D. L. MINECK, D. L. MINECK, D. L. MINECK, D. L.	8307050050 8307050120 8307050135 8307050214 8307060123	50-331 8 50-331 8 50-331 8 50-331 8	MORTON, K. L.  MORTON, K. V.  MORTON, K. V.  MORTON, K. V.  MORTON, K. V.	8307220278 8307140517* 8307200177* 8307200185* 8307290164*	50-313 R CONTRACT CONTRACT CONTRACT CONTRACT
MILLER, R. O. HILLER, R. W. HILLER, W. H. HILLER, W. H. HILLER, W. H.	8307140448* 8307250285 8307150202* 8307150202* 8307140385*	50-322 Q 50-400 Q TOPREP 50-369 Q 50-400 Q	Mineck, D. L. Mineck, D. L. Mineck, D. L. Mineck, D. L. Mineck, D. L.	8307190152 8307200161 8307210067 8307210151 8307220281	50-331 8 50-331 R 50-331 G 50-331 S 50-331 S	MOSLAK, T. MOSLAK, T. MOSLAK, T. MOTL, G. P. MOTL, G. P.	8307270273 8307110396* 8307250413* 8307060359	71-6272 50-320 q 50-320 q 71-496
HILLER, W. J. HILLER, W. O. HILLER, W. O. HILLER, W. O.	8307190440	50-389 Q 50-331 S 50-312 P 50-331 P 50-387 P	MINOQUE, R. B. MINOR, E. E. HINTZER, I. MIRAGLIA, F. J. HIRAGLIA, F. J.	8307110312# 8307210257 8307060411# 8307050378#	FEVIEW GRP NUREG 50-400 G PR	MOHRY, W. R. MOHRY, W. R. MOHRY, W. R. MOHRY, W. R. MOHRY, W. R.	8307270375* 8307070367 8307070404 8307070408*	71-496 71-496 XPDRTLIC XPORTLIC XPORTLIC 50-89 F
MILLER, W O MILLER, W O MILLER, W P MILLER, L. M. MILLER, L. M.	8307190489 8307200409 8307180246± 8307050226	50-317 F 50-4437 A 50-466 A 70-115 50-390 A	Hiraqlia, F. J. Hisak, A. Hishima, J. Hishima, J. Hishima, K.	8307250114 8307130219 8307080576 8307130147	50-456 E REVIEW GRP 50-254 R. NUREG NUREG NUREG	MOHRY, W. R. MOHRY, W. R. MOHRY, W. R. MOHRY, W. R. MOHRY, M. R. MOYA, H. E.	8307190275 8307210389 8307220016 9307220031*	71-5787 KPORTLIC KPORTLIC KPORTLIC
MICLES C. M. MICLES C. M. MICLES C. M. MICLES C. M. MICLES E M	8307070003 8307070122 8307110054 8307110508	50-259 p 50-328 p 50-259 p 50-390 F 50-390 8	HITCHELL, J. A. HITTL, R. L.	8307110279# 8307130087 8307130287 8307130174	50-413 G 50-354 K 50-354 A REOGD	MOYER, R. MOYER, R. E. MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J.	8307280207* X 8307280198 X 8307010027 8	(PORTLIC (PORTLIC 10-245 8 10-245 8
MILLE, L. M.	8307120167 8307120179 8307120180 8307120210 5	10-370 g 10-438 g 0-390 g 0-390 g 0-438 g	MIZUNO, O. S. MOERKE, N. H. MOLHOLT, B. MONTOOMERY, B. S. MONTODMERY, D. M.	8307120156 8307150263 8307050071 8307120559	00-354 V 00-537 T 00-461 S 00-289 Q 00-317 Q tata Prog	MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J.	9307010030 5 9307010122 5 9307010122 5 9307040024 5 9307040024	0-336 8 0-336 8 0-245 8 0-245 8 0-336 8
TILLS, L. H. TILLS, L. H. TILLS, L. H.	8307120481 5 8307120549 5 8307120575 5	0-340 8 0-340 8 0-259 P 0-370 8	HONTGOMERY, D. M. HONTGOMERY, D. M. HONTGOMERY, J. L. HONTGOBS, R. W. HONTGOS, R. W. HONTGOS, R. W.	8307140399# 8 8307140428# 7 8307060019# 5 8307120050# 5	tate Prog 0-143 0-285 G 0-255 F 0-546 G	MROCZKA, E. J.  MROCZKA, E. J.	9307060259 9307060259 9307060343 9307060381 9307060381	0-334 8 0-334 8 0-245 8 0-334 8 0-336 8

ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	′
NUMBER 8307110281 8307120409 8307120409 8307180144 8307180164	CATEGORY 	NAIDU, K. R. NAKAMURA, N. NARBUT, P. P. NARDI, A. J. NARDOCI, P. B.	8307280375* 8307250655 8307120368* 8307180025 8307120115	50-341 G XPORTLIC 50-528 G 71-5450 50-369 S	ı	NORDERHAUG, L. R. NOREL [US. C. E. NOREL IUS. C. E. NOREL IUS. C. E. NOREL IUS. C. E.	8307280528* 8307050259 8307180017 8307180195 8307190145	50-142 50-373 50-373 50-373 50-454	G G G G
8307170138 8307170138 8307170173 8307170173 8307210012	50-245	NARDOCI, P. B. NARDOCI, P. B. NARDOCI, P. B. NARDOCI, P. B. NARDOCI, P. B.	8307120200 8307120583 8307120597 8307150108 8307150212	50-370 S 50-369 S 50-369 S 50-369 S 50-369 S		NOREL IUS; C. E. NOREL IUS; C. E. NOREL IUS; C. E. NOREL IUS; C. E. NOREL IUS; C. E.	B307240014* B307240019* B307240021* B307240205 B307280084	50-329 50-329 50-329 50-483 50-10	@ @ @ @
8307210012 8307210342 8307220042 8307220042 8307220104	50-334 S 50-336 S 50-336 R 50-336 R 50-245 R	NARDDC1, P. B. NARDDC1, P. B. NARDDC1, P. B. NARDDC1, P. B. NARDDC1, P. B.	8307150234 8307150253 8307150259 8307150305 8307150340	50-369 S 50-369 S 50-370 S 50-370 S 50-369 S	 	NORRIE, H. R. NORRIE, J. A. NORRIE, J. A. NORRIE, J. A. NORRY, P. C.	0307130059 9306270600* 9307170049 0307220153 0307000747	50-261 PR TOPREP TOPREP ORG	R
8307220104 8307220408 8307220408 8307200030 8307200030	50-245 R 50-336 S 50-336 S ACRS	NAR DOC 1, P. B. NAR DOC 1, P. B. NAR DOC 1, P. B. NAR DOC 1, P. B. NAR DOC 1, P. B.	8307220221 8307220257 8307220409 8307250202 8307250202	50-370 8 50-370 8 50-369 5 50-369 8 50-370 9	  -  -	NORRY, P. G. NORRY, P. G. NORRY, P. G. NORTON, B. NORTON, B.	8307080757 8307180202 8307260604 8306170403 8307200203	ORO ORO ORO 50-142 50-275	T Q
8307190015* 8307180165 8307120318 8307110413 8307150008	70-820 NUREG PR State Prog 50-289 P	NARDOCI, P. B. NARDOCI, P. B. NARDOCI, P. B. NARDOCI, P. B. NARROW, L.	8307260370 8307260335 8307260567# 8307260569* 8307210226*	50-370 8 50-369 8 50-369 9 50-369 9 50-412 9	i i i	NORTON, B. NORTON, B. NORTON, B. NORTON, B. NORTON, B.	8307200203 8307200311 8307200311 6307260275 8307260275	50-275 50-275 50-275 50-275 50-275	0000
8307150059 8307180172 8307280291 8307280431 8307280453	50-277	NASH, K. L. NEAL, T. P. NEELY, B. B. NELBON, G. B. NELBON, J. E.	B307280071* B307280023 B307270180* B307240528* B307190313*	50-346 P 71-5805 50-438 G 50-142 G CONTRACT	9	NORTON, J. F. NORTON, J. F. NORHOOD: D. H. NOVACHEK, F. J. NOVAK, T. M.	8307140182* 8307210154* 8307120091 8307190010 8306090249	50-373 50-374 50-260 50-267 50-458	0 8 8
8307130313* 8307150431 8307150009 8307180434 8307220057	50-454 A 71-9071 Contract Contract Contract	NELSON, P. R. NELSON, P. R. NERSES, V. NERSES, V. NESSITT, C. D.	8307210378* 8307220063* 8307080667 8307110573* 8307070080	FOIA FOIA 50~389 F 50~341 F 50~348 F	•	NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M.	8306270415 8307050348 8307050456 8307070431 8307130346	50-454 50-413 50-387 50-382 50-327	Q E P A E
8307010078* 8307110389* 8307170078 8307210056* 8307220397*	50-271 G 50-271 G 50-271 R 50-271 G 50-271 G	NEUMAN: R. W. NEUMANN: M. R. NEUMANN: M. R. NEYLAN: A. J. NEYLAN: A. J.	9307120591 9307180254 9307220009 9307080495 9307200307		3 A R	NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M.	8307130359 8307140111 8307150448 8307190423 8307200537	90-546 50-395 50-443 90-330 50-395	P E P
8307220484 8307290336 8307120259* 8307120447* 8307120305*	50-271	NEYLAN, A. J. NG. C. K. NICHOLAS, H. NICHOLAS, H. H. NICHOLAS, J. B.	8307280262 8307070119* 8307150313* 8307010021* 8307120447*	50-334   50-387   50-322	R P G G	NYKIRK, J. W. NYKIRK, J. W. O'BRIEN, J. O'GONNOR, P. W. O'NEILL, B.	8307120064* 8307270279* 8307120517* 8307070126 8307110376*	50-304 50-295 50-312 50-546 50-320	F G A G
8307210202* 8307270141* 8307050015 8307060115 8307060220	50-445 0 50-267 0 50-346 8 50-346 8 50-346 8	NICHOLS: F. A. NICHOLS: H. H. NICHOLSON: N. A. NICOL: M. NIMITZ: R. L.	6307090133 6307210212* 8307180107* 8307270296* 8307110287*	50-282 WASTE MOT	a a	O'NETLL: J. A. O'NETLL: J. A. O'NETLL: J. A. O'NETLL: J. A.	8307250413* 8307210127 8307130253* 8307130253* 8307060173	50-320 50-346 50-400 50-400 50-400	9 5 9
8307110482 8307120237* 8307120413* 8307180035 8307180181	50-346 8 50-346 P 50-346 P 50-346 R 50-346 R	NIMITZ, R. L. NIX, H. C. NIX, H. C. NIX, H. G. NIX, H. G.	8307140235* 8305230439 8307070069 8307120098 8307120579	50-344 50-321 50-366	Q 5 9 9 8	O'NETLL, J. H. O'NETLL, J. H. O'NETLL, J. H. O'NETLL, J. H. O'NETLL, J. H.	8307060173 8307130241* 8307130241* 8307140440 8307140440	50-400 50-400 50-400 50-400 50-400	0 0 0 0
8307180304* 8307210127 8307220092 8307220228 8307220125*	50-346 F 50-346 B 50-346 R 50-346 B 50-346 F	NIX; H. C. NIX; H. G. NIX; H. G. NIX; H. G. NIX; H. G.	8307120586 8307150064 8307150071 8307150074 8307150120	50-366 50-366 50-366	5 8 9 9	O'NETLL; J. H. O'NETLL; J. K. O'RETLL; J. P. O'RETLLY; J. P. O'RETLLY; J. P.	8307250346 8307250346 8306140100 8307140040 8307140049	50-400 50-400 50-324 50-414 50-261	G G F P
8307270034 8304030241 8307010104 8307010144 8307010149*	50-322 F 71-9151 50-243 P 50-282 P 50-282 P	NIX+H. G. NIX. H. G. NIX. H. C. NIX. H. C. NIX+H. G.	8307150121 8307150385 8307180251* 8307170006 8307250076	50-366 50-321 50-321	8 5 F R 5	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	8307140081 8307140136 8307140146 8307140168 8307140207	50-261 50-389 MISC 50-389 50-261	GI P P
8307050092 8307050098* 8307060229 8307060252 8307070107	50-282 P 50-282 P 50-304 S 50-363 S PR	NIX, H. C. MIX, H. C. MIX, H. C. MIX, H. C. MIX, H. C.	8307250166 8307250191 8307250214 8307250269 8307250293	50-366 50-321 50-321 50-366 50-321	8 8 8 8	O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	8307140212 8307140224 8307140225 8307140248 8307140251	50-280 50-370 50-321 50-324 50-261	G F V P
8307080030 8307080198 8307150065 8307220461 8307220561	50-243 P 50-282 K 50-282 R 50-243 F 50-282 F	NIX, H. C. NIX, H. C. NIX, H. C. NIX, H. C. NIXON, W. A.	8307250343 8307250348 8307270523* 8307270530* 8307150026	50-366 50-366 50-321 50-321 40-6500	8 F F	O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P.	8307140270 8307140276 8307140316* 8307140339 8307200094*	TOPREP 50-335 50-261 50-250 70-143	F G F
8307270283 8307010178 8307220209* 8307220317* 8307220574*	50-324 G	NOLAND, J. D. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R.	8307060204 8307060021 8307110384 8307110391* 8307120106	50-546 50-312 70-1257 70-1257 70-734	G F	O'REILLY, J.P. D'REILLY, J.P. O'REILLY, J.P. G'REILLY, J.P. D'REILLY, J.P.	8307220270 8307220301* 8307220491 8307220507* 8307220522	50-416 50-416 50-438	Q Q Q
8307140268* 8307190182 8307210300 8307080473* 8307280156*	50-522 D 50-522 D •, 50-440 G	NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R.	8307120384 8307120528 8307260053 8307260442 8307260521	70-734 70-2950 50-206 50-142 50-142	G G	G'ROURKE, A. P. D'TOGLE, J. D'TOGLE, J. D. G'TOGLE, J. D. G'TOGLE, J. D.	8307180071 8307220555 830701155 8307050152 83070501624	50-247 50-247 50-247 50-247 50-247	9 B

<b>A</b> 17 * 417 #4	#10E501	CATEGORY	AUTHOR	ACCESSIO NUMBER	N SUBJECT CATEGORY	AUTHOR	ACCE9810N NUMBER	SUBJECT CATEOGRY
E TOOLS U C GITOOLS U C GITOOLS U C GITOOLS U C GITOOLS U C	800 70 60 8 830 73 60 3 8 70 71 80 8 8 71 2 5 5 8 70 71 5 60	95 50-247 0 05 59-247 0 35+ 50-247 0 57+ 50-247 0	PAINTER. B. F. PALLADINO, N. PALLADINO, N. J. PALLADINO, N. J. PALLADINO, N. J.	630713006 830725041 830706043 830714000 830717005	9* FDIA 9 50-289 U 4 50-247 U	PASTVA, M. J. PATTARINT, D. M. PATTERSON, J. D. PATTERSON, J. P. PATTERSON, J. P.	8307260404 8307180081 8307070118 8307120547* 8307280325*	50-324 50-528 PR
COTODLE 2 D D TODLE 3 D COTODLE 3 D DOTODLE 3 D D TODLE 3 D	93071951 93072252 93072252 93072302 93072303	03	PALLADINO, N. J. PALLADINO, N. J. PALLADINO, N. J. PALLADINO, N. J. PALLADINO, N. J.	8307190196 8307200245 8307200245 8307200248 8307200259	COMMISSION COMMISSION	PATTERSON, J. W. PATTERSON, W. F. PATTERSON, W. F. PAUL, E. PAUL, R. A.	8307220108# 8307130283 8307200112 8307050117 8307060108	FOIA 50-443 50-443 PR 50-331
CITODLE JE COESAARCENIR S COESAARCENIR S COESAARCENIR H COOST JE	83072234 \$\$170895 \$3070865 \$30713064 \$3671\$0	74 71-4909 38 71-4498 49 71-9132	PALLADINO, N. J. PALLADINO, N. J. PALMER, R. A. PALMER, R. A. PALMER, R. A.	930720320 6400725068 6400705068 6400705068 64007068	* 50-272 8 * 50-315 8 * 50-315 8	PAUL/R.A. PAULK.G.L. PAXTON,G.J. PAYNE, M.T. PAYNE, M.T.	8307280293* 6307220347* 8307110169* 8307050195 8307050195	50-10 9 50-259 9 50-338 F 50-400 9 50-400 6
Destmann, M., Obstmann, M., Omford J. C Offord J. C Offord J. C	6307;2000 8307;900; 8307;5043 8307;904; 8307;9009	8+ 30-454 Q 4+ CONTRACT 8+ CONTRACT	PALMER, R. A.	8307080007 8307110200 8307110209 8307180140 8307220410	* 50-316 8 * 50-316 8 50-315 8	PAYNE, M. T. PAYNE, M. T. PAYNE, M. T. PAZARADI, S. PEACOCK, B.	8307050198 8307050205# 8307050205# 8307060025# 8307070053	50~400 0 50~400 0 50~400 0 50~528 8
omada. 5 Dimada. 5 Dilen. 7 Cilen. 7 Dimeteat. 6	83070707035 830707041 830712020 830712033 830513024	7 XPORTLIC 9• GA999 4• GA999	PAN. J. PAN. J. PANCIERA. V. PANDEY. P. PANDEY. P.	9307120009 \$307120012 9307210275 9307180179 9307180186	50-237 P	PEACOCK, B. PEDRO, J. PEDRO, J. PEELES, T. A. PELKE, P. R.	8307070139 8307200519 8307290461 8307280308 8307110430*	50-413 A FOIA FOIA 50-366 B
Clean a f Clean L n Clean L n Clean Bari J a Clean Bari J a Clean Bari J a	830719001 830231003 830713030 830714337 830714038	3 30-454 A 5 30-454 V 5 State Prog 9 State Prog	PANG, J. F. PAGLING, R. J. PAGLING, R. J. PAPAY, L. T. PAPERIELLO, C. J.	8307260482* 8307010161* 8307280342* 8307150222* 8307060102	50-352 Q	PELLETIER, J.P. PELLETIER, J.P. PELLETIER, J.P. PELLETIER, J.P. PENNIFILL, R.A.	B307010022 B3070100B5 B307010105 B307150354 B307080474	30-271 8 30-271 8 30-271 8 50-271 8 50-271 8 WASTE HOT
SLEON DE OLEON DE OLEON DE OLEON DE OLEON DE	9367250024 836725022 836722622 836722622 836722623	S 50-237 P WASTE MOT WASTE MOT WASTE MOT	PAPER IELLO, C. J.	8307040294 8307080015 8307080254 8307120004 8307120244	50~255	PERCH, R. L. PERCH, R. L. PERCH, R. L. PERKING, O. R. PERKING, T. J.	8307050286 8307070058 8307140167 8307060185* 8307170243	50-388 A 50-387 P 50-458 A 50-423 Q
CLSON C L CLSON C L CLSON C L CLSON C L	9307220232 8307220234 8307220253 9307220255	MASTE MOT WASTE MOT WASTE MOT WASTE MOT	PAPERIELLO, C. J.	8307120271* 8307120502 8307120538 8307120542* 8307180014	50-315 Q 50-483 Q 50-263 Q 50-263 Q 50-454 Q	PERKINS, T. J. PERLIS, R. O. PERLIS, R. O. PERLIS, R. O. PERLIS, R. O.	8307250499* 8307070040 8307070063* 8307130283	50-220 F 50-483 0 50-483 0 50-443 0
OTROW OF OTROW OF DIROW OF DIROW OF	\$307270148 8307270152 \$307270159 \$307270166 8307270164	HASTE MOT HASTE MOT HASTE MOT HASTE MOT WASTE MOT	PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J.	8307180044 8307180045* 8307180102 8307180127 8307180130*	50-266 q 50-266 q 50-262 q 50-263 q 50-263 q	FERLIS:R.O. PERLIS:R.O. PERLMAN.J. PERLMAN.J. PERLMAN.J.	8307190150 8307220414 8307250381 8307050324 8307150364	50-443 0 50-412 0 50-483 0 CONTRACT
OLSON, O. L. OLSON, O. L. OLSON, O. L. OLSON, O. L.	8307270194 8307270204 8307270208 8307270214 8307270218	Waste Mgt Hasie Mgt Hasie Mgy Wasie Mgt	PAPERIELLO, C. J.	8307220425 8307220544 8307260533 8307280266 8307280287	50-237 F 50-454 Q 50-346 Q 50-295 Q 50-10 Q	PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J.	8307150420 8307150420 8307170335 8307170430 8307200380	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DESONO DE DESONO	8307270253 8307270257 8307270252 8307270270 8307270274	HABTE MGT HABTE MGT HABTE MGT HABTE MGT HABTE MGT	PAPERTELLO, C. J. PAPERTELLO, C. J. PARCHEN, L. J. PARCHEN, L. J. PARTILLO, J.	8307280323 8307280347 8307120024 8307180143 8307220408	50-373 Q 50-10 F NUREQ NUREQ 50-336 B	PERLMAN, J. PEROTTI, D. J. PERRY, S. K. PETERS, R.	8307250242 8307250683 8307120177* 8307260440* 8307010017	50-498 A CONTRACT 50-537 T TOPREP 50-333 S
CLECH.C.L. CLECH.C.L. CPREA.C.W CPREA.C.W	8307270284 8307270291 9307040268 8307080474	WASTE MOT WASTE MOT HASTE MOT 50-498 S	PARIS.O.H. PARK.J.Y. PARKER.L.B. PARKER.L.B. PARKER.H.E.	8307050168 8307090133 8307290040* 8307290095* 8307180129*	50-546 G NUREG GAPPP GAPPP 50-155 G	PETERBON, B. H. PETERBON, D. A. PETERBON, M. R. PETERBON, M. R. PETRICK, N. A.	8307150124 8307250086 8307290314	71-9029 50-255 R XPORTLIC XPORTLIC 50-482 F
CPREA. G W CPREA. G W CPRALS. B L CRALS. D L	8307220242+ 8307250465 83071800664+ 8307180065+	50-466 A 50-478 Q 50-478 S 50-373 Q 50-373 Q	Parker, W. G. Parks, C. V. Parris, H. G. Parsons, R. M. Parsons, R. M.	8304280580* 8307230159 8307080358* 8307110338 8307120207	50~445 I NUREG 50~257 P 50~400 S 50~400 B	PETRICK, N. A.  PETRONE, C. D.  PETRONE, C. D.  PETRONIE, A. D.  PETTENOILL, H. J.	8307130268 8307250040# 8307250442# 8307130317#	50-482 E FDIA 50-322 G 50-454 A 80-2259
CROSTEIN P M CROSTEIN P M CROSTER J CSTER J	830722041: 8307250458 8307250458 8307260430 8307140007:	30-373 G 30-389 G WASTE MOT TOPREP 50-10 J	PARSONS, R. M.	8307120316 8307120395 8307150380 8307170005 8307220143*	50-400 B 50-400 B 50-400 B 50-400 S	PETTY, J. C. PETTY, J. C. PETTY, J. C. PETTY, J. C. PEVENSTEIN, J. E.	8307120613 8307120613 8307290033 8307290034	50-270 8 50-269 8 60-269 8
Cubas, r p Chic Iarsa I. p c Pace. p l Paceanashan Pachanashan	8307240553 8307110560 8307220329 8306280404.	50-247 U 50-312 R RES 50-250 R GEN TEC IS	PARSONS, R. M. PARSONS, R. M. PARSONS, R. M. PARSONS, R. M. PARSONS, T. D.	8307220145 8307220148* 8307220336* 8307250404	50-400 8 50-400 G 50-400 G 90-400 S	PHILLIPS, H. S.	8307120236* G 8307120293* G 8307180161* G 8307180192* G	ONTRACT A999 A999 A999 A999
Pagang, F g Page. R g Page. R g Page. R g	83071403954 83070804474 83070804744 8307116063	SEN TEC 18 50-259 F 40-6264 40-6264 70-1201	PASCIAK, N. J. PASCIAK, M. J. PASCOE, S. PASTVA, N. J. PASTVA, N. J.	8307110265# 8307110503# 8307250645# 8307120129	50-309 G 50-271 G CONTRACT 50-324 S	PHILLIPS M.P. PICKARD, R.C. PICKENS, T.A. PIEMONTESE, A.P. PIEMONTESE, A.P.	8307280274* 5 8307070039 5 8307150128* 5 8307120256 5	A999 0-295
Add R G Add R G Add R G Add R G	8307130030 8307140024 8307350517 8307120338	70-2950 70-371 70-2945 70-820 50-261 0	PASTVA, M. J. PASTVA, M. J. PASTVA, M. J. PASTVA, M. J. PASTVA, M. J.	8307150024 8307150102 8307150242 8307220405	50-325 S 50-324 S 50-325 S 50-324 S 50-325 S 50-325 S	PIEMONTEBE, A. P. PIEMONTEBE, A. P. PIEMONTEBE, A. P. PIERINGER, P. PIERINGER, P. PIERINGER, P. PIERINGER, P. A.	8307120442 50 8307120442 50 8307120443 50 8307180264 50 8307110456 50	0-387 8 0-387 8 0-387 8 0-387 8 0-317 8 0-317 8 0-317 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PILALIS, L. E. PILANT, J. M. PILANT, J. M. PILANT, J. M. PILANT, J. M.	8307110461 8307010126 9307050187 8307120244 8307120404	PR 50-298 P 50-298 P 50-298 P 50-298 P	POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	9307120536 9307150116 9307150125 9307150247 9307150251	GA999 GA999 GA999 GA999 GA999	RAHSON, R. J. RAHSON, R. J. RAHSON, R. J. RAHSON, R. J. RAHSON, R. J.	8307060375 8307130254 8307190002 8307200087 8307200093*	50-454 G 50-454 G 50-322 G 50-454 G 50-454 G
PILANT, J. M.	B307120404 B307120407 B3071204B0 B307260361 B307270193	50-278 P 50-278 K 50-278 P 50-278 P 50-278 P	POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307150282 8307150309* 8307180155 9307180184 8307180185	GA999 GA999 GA999 GA999 GA999	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	9307060062 9307060067 9307060076 9307060090 9307060214	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S
Pinkerton, B. Pirtle, G. L. Pirtle, G. L. Plaine, H. E. Planchon, H. P.	8307130331* 8307050262* 8307180112* 8307200274 8307110149*	50-454 A 50-10 G 50-282 G ADVCM 50-537 T	POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307180209 8307210101 8307210190 8307240151 8307240144*	GA999 GA999 GA999 GA999 GA999	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	8307060311 8307060387 8307060423 8307130081 8307130096	50-362 8 50-362 8 50-361 8 50-361 8
PLANK, R. A. PLANK, R. A. PLATO, P. PLATO, P. PLOSKI, T.	8307260158* 8307260169* 8307180137 8307190097* 8307060303*	GA999 GA999 Nureg 40-672 50-255 G	POTAPOVS; U. POTAPOVS; U. POTAPOVS; U. POTAPOVS; U. POTAPOVS; U.	8307260219 8307260313 8307290026 8307290060 8307290081	GA999 GA999 GA999 GA999 GA999	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	8307130235 8307130244 8307130275 8307180050 8307180051*	50-361 8 50-361 8 50-361 8 50-361 8 50-361 8
PLOSKI.T. PLOTKIN,S. PLUMLEE,Q.L. PLUMMER,D.E. POOORZELSKI,N.	8307280327* 8306170403 8307150140* 8307270367* 8307150202*	50-373 G 50-142 T 50-267 G 71-6400 TOPREP	POTAPDVS, U. POTAPOVB, U. POTTER, J. P. POTTER, J. P. POULK, R. M.	8307290114 8307290133 8307110183 8307250457 8307110432	GA999 GA999 I&E I&E 50-324 S	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	8307180053* 8307180093 8307180135 8307180144 8307220290	50-361 8 50-361 8 50-361 8 50-361 8 50-206 8
POINDEXTER, C. H. POLK, P. J. POLKINGHORNE, B. POLLOCK, M. B. POLLOCK, M. B.	8305250564* 8307220138 8307250080 8307050117 8307140335*	50-317 P 50-286 P NUREQ PR 50-322 Q	POULK, R. M. POWERS, D. A. PRATT, R. A. PRATT, R. A. PRATT, R. A.	8307110510 8307150359 8307120606* 8307120606* 8307150290	50-325 S NUREO 50-322 G 50-322 G 50-322 G	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	B307220465 B307220506 B307250278 B307250426 B307250433	50~361 R 50~206 R 50~362 S 50~362 S 50~262 S
POMERÉNING. D. J. POMEROY, P. W. POMEROY, P. W. POPE, J. R. POPE, M. A.	8307060388* 8307200033 8307200033 8307060204 8307060171	TOPREP ACRS ACRS 50-546 G 50-261 G	PRESTHOLT, P. T. PRESTON, C. C. PREVATTE, R. PREVATTE, R. L. PRICE, W. C.	8307260185 8307140478 8307220141* 8307220344* 8307050261	WASTE MGT RES 50-400 G 50-400 G 50-322 G	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	8307250459 8307250462 8307250472 8307250474 8307250476*	50~362 8 50~361 5 50~361 8 50~361 8 50~361 8
POPE, R. R. POPELAR, C. H. POPELAR, C. H. POPPE, L. K. POPPE, L. K.	8307070051 8307120009 8307120012 8307080404 8307150442	50-546 A Nureg Nureg 71-9096 71-5026	PRICHARD, R. P. PRICHARD, R. P. PRICHARD, R. P. PRILLS, L. PROCTOR, S. D.	8306240429 8307190030 8307210367 8307190217* 8307150195	71-6495 71-5552 71-6550 50-397 A 50-329 G	RAY, H. B. RAY, H. B. RAY, H. B. RAY, J. A. RAY, J. J.	8307250479* 8307250490 8307250491 8307010130 8306240426*	50-361 S 50-361 S 50-361 S 50-27 F 50-447 O
POPPE, L. K. POPPE, L. K. POPPE, L. K. POPPE, L. K. POPPE, L. K.	8307190027 8307190266 8307200364 8307280125 8307290381	71-2601 71-9111 71-9111 71-6601 71-231	PROCTOR, S. D. PROCTOR, S. D. PROCTOR, S. D. PUGH, C. E. PULIDO, M.	8307150195 8307180077 8307220347 8307150371 8306170403	50-329 G 50-329 G 50-329 G NUREG 50-142 T	RAYBURN, C. R. RAYBURN, C. R. RAYMOND, R. L. RAYMOND, W. J. RAYNOR, J.	8307070180 8307120043* 8307250499* 8307060149 8307110456	50-317 F 50-317 F 50-220 F 50-271 S 50-317 S
POPPELL, F. B. PORTER, R. J. PORTER, R. J. PORTER, R. J. PORTER, R. J.	8307220268 8307010087 8307010160 8307180187 8307180207	50-260 6 50-318 8 50-317 8 50-317 8 50-317 8	PULLANI, S. V. PUNTENNEY, J. PURPLE, R. A. PURPLE, R. A. PURPLE, R. A.	8307010012* 8307250527 8307060427* 8307130269* 8307140425*	50-272	RAYNOR, J. W.	8307010083 8307010160 8307180187 8307180193 8307180207	50-317 S 50-317 S 50-318 S 50-317 S
PORTER, R. J. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307210285 8307040002 8307040005 8307040018 8307040024	50-317	PURPLE, R. A. PURPLE, R. A. PURPLE, R. A. PURPLE, R. A. PURPLE, R. A.	8307150169* 8307190361* 8307200531* 8307210331* 8307210339*	50-271 P 50-263 F 50-254 P 50-333 F 50-346 P	RAYNDR, J. W. RAYNDR, W. READ, F. REAGAN, S. REAVIS, J.	8307180245 8307010087 8307070076 8307080648 9307190267	50-318 8 50-400 0 70-143 50-269 P
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307060033 8307060058 8307060087 8307060096 8307060097	GAP99 GAP99 GAP99 GAP99 GAP99	PURPLE, R. A. PURPLE, R. A. PURVIS, J. QUERIO, R. E. QUICK, D.	8307250484* 8307270042* 8307180310 8307180099 8307140195*	50-237 P 50-344 F 27-47 50-454 S 50-369 G	REAVIS, J. A. REAVIS, J. A. REBELLO, J. E. REBELLO, J. E. REBELLO, J. E.	8307190188* 8307190309* 8307150016* 8307180436* 8307220075*	50~369 R 50~369 R CONTRACT CONTRACT CONTRACT
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307040103 8307040188 8307040210 8307040231 8307040274	GA779 GA777 GA777 GA777 GA777	GUICK, D. R. GUICK, D. R. GUICK, D. R. GUIGG, P. S. GUIGG, P. S.	9307140059* 9307140077* 9307140092* 9307180064* 9307180065*	50-327 G 50-327 G	REBELLO, J. E.	#307250509 #307250520* #307250643* #307250693* #307270488*	CONTRACT CONTRACT CONTRACT CONTRACT
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307060283 8307060326 8307060337 8307060345 8307060353	GA777 GA777 GA777 GA777 GA777	GUIQO, P. S. GUINN, V. M. GUIRK, J. F. RADEMACHER, J. M. RAHE, E. P.	8307180064* 8307260349 8307050157 8307080480* 8307070079	50~498 K TOPREP	REBELLO, J. E. REBELOWSKI, T. A. REDANO, R. T. REDANO, R. T. REDNANZ, F. J.	8307150352* 8307050129* 8307150079* 8307190006	50-213 G 50-247 G 50-285 G 50-321 R
POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U.	8307040358 8307040370 8307120201 8307120212 8307120218	GA779 GA777 GA777 GA777 GA777	RAHE, E. P. RAHE, E. P. RAHE, E. P. RAHE, E. P. RAHE, E. P.	8307070155 8307080304 8307080314 8307120397 8307130196	TOPREP TOPREP TOPREP PROJ TOPREP	REED, C. REED, C. REED, C. REED, C. REED, C.	8307200216* 8307250448 8307260301 8307280102* 8307280457*	50-237 P 50-237 P 50-374 A 50-10 G 50-10 G
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307120223 8307120277 8307120270 8307120275 8307120278	QA799 QA797 QA797 GA999 50~389 Q	RAHE, E. P. RAHE, E. P. RAHE, E. P. RAHE, E. P. RAJARAM, V.	8307250412 8307270295 8307280114 8307280289 8307270412*		REED. J. REEVES. E. REEVES. E. REGAN. W. H. REGAN. W. H.	8307180263 8307150402 8307250567 8307050355 9307050357*	50-364 P 50-364 P PROJ
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	8307120321 8307120328 8307120376 8307120437 8307120453	50-373 G GA797 GA797 GA799 GA799	RAJARAM; V. RAMBAMATH S. RASKIN; D. B. RATHBUN; L. A. RAWSON; R. J.	8307270418# 8307140299* 8307190153 8305240240 8304080387*	50-277 P 50-275 G 50-254 P	REHM, T. A. REHM, T. A. REHM, T. A. REHM, T. A. REHM, T. A.	8307090092 8307090118 8307190403 8307190443 8307250513	COMMISSION COMMISSION COMMISSION

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REILLY, H. J. REILLY, W. REILLY, W. REIMERS, G. A. REIMERS, G. A.	8307250080 9307210206* 8307210224* 8307050135 8307210067	NUREG GA999 GA999 50-331 S 50-331 S	RIVENBARK, Q. RIVENBARK, Q. RIVENBARK, Q. RIVERIA, J. A. ROBERDS, H. W.	8307140541 8307180424 8307200357 8307270375* 8307120013*	50-366 F 50-321 P 50-366 P 71-496 50-482 G	ROTH: J. ROTHECHILD: M. U. ROTHECHILD: M. U. ROUSE: L. C. ROUSE: L. C.	8307210075* 8307130085 8307140526 8307130436 8307130445	70-371 50-508 G 50-445 A 70-1143 70-364
REIS, E. J. REIS, E. J. REKITO, W. A. REKITO, W. A. RENNELS, A. E.	8307080425 8307150314 8307110266+ 8307250060+ 8307070216	50-322	ROBERDS, H. J. ROBERTS, L. B. ROBERTS, L. B. ROBERTS, T. M. ROBERTS, T. M.	8307270410* 8307150111 8307210122 8307200367 8307200369*	WASTE MOT 50-312 8 50-312 8 COMMISSION COMMISSION	ROUBE, L. C. ROUBE, L. C. ROUBE, L. C. ROWE, C. ROWSOME, F. H.	8307140497 8307220076 8307220120 8307280170* 8304200084*	70-1193 70-1193 70-344 40-672 50-322 A
RENTSCHLER, R. R. RENTSCHLER, R. R. RENTSCHLER, R. R. RENTSCHLER, R. R. RENTSCHLER, R. R.	8307110565 8307110594 8307110605 8307110649 8307110691	70-2940 70-1257 70-344 70-27 70-398	ROBERTS, T. M. ROBERTS, T. M. ROBERTS, T. M. ROBERTS, W. B. ROBERTSON, J. B.	8307200372* 8307200374* 8307200379* 8307220359* 8307270399	COMMISSION COMMISSION COMMISSION 50-266 P WASTE MGT	ROY, F. L. ROY, F. L. ROZAK, S. RUBIN, M. RUBINSTEIN, D.	8307110064* 8307110077* 8307120007* 8307220419* 8306080373*	50-261 P 50-261 P 50-263 Q 50-382 A 50-322 A
RENTSCHLERIR.R. RENWICK, J. C. REPKA, D. A. REPKA, D. A. REPKA, D. A.	8307180069 8307110488 8307010068 8307050266 8307110039	70-143 50-373	Robertson, J. B. Robinson, D. Robinson, D. Robinson, D. Robinson, D.	8307270483 8307110340* 8307110347* 8307260006* 8307260009*	WASTE MOT 50-315 8 50-315 8 50-329 0 50-329 0	Rubinstein, D. Rubinstein, D. Ruff, A. B. Rufty, S. J. Ruiter, G. H.	8307260540* 8307260545* 8307220247* 8307250451 8307120263	50-322 A 50-322 A 50-438 G 50-337 P 50-305 R
REPKA, D. A. REPKA, D. A. REQUA, G. REQUA, G. REBNIKOFF, M.	8307110042 8307140470 8307110037 8307180430 8307050117	50-322 G 50-322 G 50-261 G 50-261 P PR	ROD, S. R. RODRIGUEZ, R. J.	8307080325* 8307010034 8307040049 8307040068 8307040152	TOPREP 50-312 P 50-312 S 50-312 S 50-312 S	RULAND, W. H. RUMBLE, E. T. RUMBLE, E. T. RUMBLE, E. T. RUMKLE, J.	8307220549* 8307120168* 8307120176* 8307130215* 8307130242	50-348 Q 50-537 Y 50-537 T 50-537 T 50-400 Q
REST. J. REURAND, B. REVELEY, H. T. REVELEY, H. T. REVELEY, H. T.	8307090133 8307080609* 8307050192 8307050192 8307140447	NUREG NUREG 50-322 G 50-322 G 50-322 G	RODRIGUEZ, R. J.	8307040317 8307070012 8307110235 8307120521 8307180010	50-312 P 50-312 P 50-312 P 50-312 8 50-312 S	RUNKLE, J. D. RUNNER, W. R. RUSSCHER, G. E. RUSSCHER, G. E. RUSSCHER, G. E.	8307260483 8307110479* 8307120026 8307180143 8307280255	50-400 Q 50-280 F NUREQ NUREQ WASTE MGT
REVELEY, W. T. REYES, L. A. REYES, L. A. REYNOLDS, J. R. REYNOLDS, J. R.	9307140447 8307140422* 8307200204* 8307050242 8307050242	50-322 G 50-374 Q 50-454 G 50-275 Q 50-275 G	RODRIGUEZ, R. J.	8307180012 8307170077 8307170107 8307170161 8307250233	50-312 P 50-312 R 50-312 S 50-312 S 50-312 P	RUSSELL, C. F. RUSSELL, C. F. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B.	8307280273 8307280285 8307010076 8307010083 8307010087	HASTE MGT WASTE MOT 50-317 B 50-317 B 50-318 B
REYNOLDS; J, R. REYNOLDS; J, R. REYNOLDS; J, R. REYNOLDS; J, R. REYNOLDS; J, H.	8307060437 8307060437 8307120571 8307120571 8307120373	50-275 Q 50-275 Q 50-275 G 50-275 Q 50-327 E	RODRIGUEZ, R. J.	8307260015 8307260178 8307260352 8307260457 8307270433	50-312 F 50-312 P 50-312 P 50-312 Q 50-312 K	RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B.	8307010142 8307010140 8307070180 8307110427 8307110443	50-317 8 50-317 8 50-317 F 50-317 8 50-317 6
REYNOLDS, N. S.	8305100420 8305100420 8307070140 8307080437 8307080437	50-508 0 50-508 0 PR 50-508 0 50-508 0	RODRIGUEZ, R. J.	8307280250 8307280350 8307280393 8307280432 8307280445	50-312 Q 50-312 P 50-312 S 50-312 S 50-312 F	RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B.	8307110436 8307120043* 8307120083* 8307120144 8307120479	50-317 8 50-317 F 50-317 F 50-317 8 50-317 8
REYNOLDS, N. S.	8307110236 8307110236 8307120585 8307120585 8307140464	50-50B	ROGERS, H. R. ROGERS, H. R. ROGERS, H. R. ROGERS, H. R. ROGERS, H. R.	8307120086 8307120416 8307120420 8307120422 8307120587	50-327 8 50-328 8 50-327 8 50-327 8 50-328 8	RUBBELL, L. B. RUBBELL, L. B. RUBBELL, L. B. RUBBELL, L. B. RUBBELL, L. B.	8307180187 8307180193 8307180207 8307180245 8307210285	50-317 \$ 50-316 \$ 50-317 6 50-317 8 50-317 8
REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, S. D. RHINELANDER, J.	8307140464 8307190228 8307190228 8307060029* 8307260305	50-508 0 50-445 0 50-445 0 50-244 0 40-2061	ROGERS, J. C. ROGERS, P. ROGERS, P. ROGERS, P. C. ROGERS, P. C.	8307210274* 8307240322 8307260554 8307120191 8307150271	50-413	RUSSELL, L. S. RUSSELL, L. S. RUSSELL, T. A. RUSSELL, V. RUSSELL, W. T.	8307210287 8307220509 8307250035 8307150056* 8304270394*	50-317 8 50-318 8 71-9151 CONTRACT 50-322 A
RHINELANDER, J. RHOADB, Q. RHOADB, Q. RHOADB, Q. RHOADB, Q.	8307260305 8307010079 8307110274 8307150313* 8307280349*	40-2061 50-387 8 50-387 8 50-387 9 50-387 9	ROGERS, P. C. ROGERS, P. J. ROGERS, W. H. ROHRER, M. V. ROHRER, M. V.	8307150383 8307210237 8307290530* 8307120109 8307120509	50-313 8 50-326 8 50-321 F 50-416 8 50-416 8	RUBBELL, W. T. RUBBELL, W. T. RUBBELL, W. T. RUBBELL, W. T. RUTHER, W. E.	8305260333* 8305260337* 8307110505* 8307250334* 8307090133	50-322 A 50-322 A 50-322 A 50-289 Q NUREQ
RHOADS, G. G. RHODE, G. K. RHODE, G. K. RICE, D. A. RICE, D. W.	8307280346* 8307070062 8307220407 8307010024 8307270319	50-387 G 50-410 G 50-410 A 50-29 S NUREG	ROHRER, M. V. ROHRER, M. V. ROHRER, M. V. ROHRER, M. V. ROHRER, M. V.	8307150113 8307250164 8307250193 8307250289 8307250473	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	RUTHERFORD, N. A. RUTLEDGE, C. RYAN, J. S. RYAN, K. M. RYAN, R. H,	8307140048 8307080538 8307170339* 8307150320 8307200157*	50-269 P 40-8585 CONTRACT 50-397 Q CONTRACT
RICE, W. M. RICHARD, M. E. RICHARDS, B. L. RICHARDS, B. L. RICHARDS, S. RICHARDSON, J. D.	8307220374 8307060224 8307140197* 8307140377* 8307210026*	50-478 A 50-322 G 70-143 70-1201 50-322 Q	ROHRER, M. V. ROHRER, M. V. ROMAN, T. W. ROMAN, T. W. ROMO, L. R.	8307260464 8307290238 8307150080 8307250499* 8307050188*	50-416 8 50-416 9 50-220 R 50-220 F 50-329 H	RYBAK: B. RYBAK: B. RYBAK: B. RYBAK: B. RYBAK: B.	8307070174 8307170062 8307170178 8307170187 8307210050	50-237 P 50-237 P 50-237 P 50-237 P 50-265 P
RIDDLE, D. H. RIDGWAY, D. A. RIDGWAY, D. A. RIDGWAY, D. A. RIDGWAY, D. A.	8307260324 8305120351* 8307140435 8307140435 8307140454	50-416 R CONTRACT 50-400 G 50-400 G	ROOD, H. ROONEY, V. L. ROOT, L. E. ROSAND, R. ROSAND, R.	8307110568 8307250541 8307190435* 8307260364 8307280377	50-361 P 50-271 P CONTRACT 50-289 S 50-295 S	RYBAK, B. RYBAK, B. RYBAK, B. RYBAK, B. RYBAK, B.	9307220306 8307220495 8307250304 8307250452 8307250020	50-249 P 50-237 P 50-237 P 50-237 S 50-237 F
RIDGWAY, D. A. RIDGWAY, D. A. RIDGWAY, D. A. RIDGWAY, D. A. RIDGWAY, D. A.	8307140454 8307180176 8307180200 8307180200 8307180218	50-400 Q 50-266 Q 50-266 Q 50-266 Q	ROSENTHAL, A. ROSS, W. J. ROSSBACH, L. W. ROSSI, C. E. ROSSOMONDO, C.	8307110373* 8307220022* 8307280311* 8307120168* 8307080532	PR 50-335	RYMAN, J. C. SABADOS, J. H. SACKG, I. J. SAITO, T. SALAH, S.	8307250159 8307140327* 8307110087 8307280467 8307290284	NUREO 70-1151 NUREO XPORTLIC 50-416 8
RILEY, J. L. RINALDI, F. RING, M. RING, M. A.	8307190239 8307190339 8307250402# 8307260006# 8307200204#	50-320	ROTELLA, T. S. ROTELLA, T. S. ROTH, J. ROTH, J. ROTH, J.	8307150205 8307250207 8307140106* 8307140513 8307200170	50-389 8 50-389 8 70-467 50-201 P 50-201 P	SALAH, S. SALDAR INI, J. C. SALTZMAN, J. SALTZMAN, J. SALVENDY, Q.	8307270287* 8307270385 8307080005 8307080679 8307220643	50-416 B REGQD 50-8 J 50-141 J AGRS

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SALVENDY, G. SALVESEN, D. SAMUELS, P. SAMUELS, P. SAMUELS, P.	8307220643 8307110461 8307050100 8307050110* 8307050116*	ACRS PR 50-247 H 50-247 H 50-247 H	SCHUYLER, J. O. SCHUYLER, J. O. SCHUYLER, J. O. SCHUYLER, J. O. SCHUYLER, J. O.	8307070026 8307110406* 8307120324 8307120582 8307130221	50-275 P 50-275 P 50-275 P 50-275 R 50-323 S 50-275 P	SEARS, C. F. SEARS, C. F. SEARS, C. F. SEARS, C. F. SEARS, C. F.	8307140271 8307150193 8307150193 8307150208 8307150240	50-423 A 50-245 P 50-245 P 50-423 S 50-423 S
SANCHEZ, R. A.	8307060267*	50-331 P	SCHUYLER, J. O.	8307130278	50-275 P	SEARS, C. F.	8307170253	50-213 P
SANDERB, G. A.	8307050465	NUREO	SCHUYLER, J. O.	8307180002	50-275 P	SEARS, J. R.	8307170277*	50-443 T
SANDERB, G. A.	8307150131	NUREO	SCHUYLER, J. O.	8307190115	50-133 P	SEARS, P.	8307060350*	GA999
SANDERB, G. A.	8307150356	NUREO	SCHUYLER, J. O.	8307190171	50-275 P	SEARS, P.	8307060360*	GA999
SANDERB, W. F.	8307140185*	50-424 Q	SCHUYLER, J. O.	8307220362	50-275 R	BEARS, P. M.	8307060221*	GA999
SANDNER, H. H. SANDS, H. S. SANSONE, R. C. SARGENT, I. H. SARSOUR, S.	8307110295* 8307220098 8307120333* 8304040295* 8307220092	50-315 P FDIA 50-352 A 50-254 P 50-346 R	SCHUYLER, J. O. SCHUYLER, J. O. SCHUYLER, J. O. SCHUYLER, J. O. SCHUYLER, J. O.	8307260379 8307270195* 8307270201* 8307280101 8307280296	50-275 P 50-275 F 50-275 F 50-275 F 50-275 R	SEELY, S. SEELY, S. SEIDLE, W. C. SEIDLE, W. C.	8307110461 8307150168 8307150176 8307040015 8307040033	PR PR NUREG 50-285 G 50-285 G
BABTRE, C. BATHER, A. BAUDERS, R. F. BCALETTI, D. C. BCARANO, R. A.	B307260022	WASTE MOT	SCHUYLER, J. D.	B307270175	50-275 P	SEIDLE, W. C.	8307040135	50-285 Q
	B307140044*	50-329 Q	SCHUYLER, J. D.	B307270221	50-275 P	SEIDLE, W. C.	8307040282	50-313 Q
	B307270173	50-280 S	SCHWALLIE, A. L.	B307110149#	50-537 T	SEIDLE, W. C.	8307120010	50-482 Q
	B307150374	50-447 A	SCHWAN, C. A.	B307110371#	70-1257	SEIDLE, W. C.	8307120240	50-313 Q
	B307250572*	FOIA	SCHWEITZER, D. G.	B307260016	WASTE MOT	SEIDLE, W. C.	8307120449	50-285 Q
SCARAND, R. A.  BCATTOL INI, L. B.  BCHAUFELBERGER  SCHECTER, H.  SCHEIBELHUT, C.	8307230404* 8307220237 8307240008 8307240141* 8307120584*	FOIA WASTE MOT 50-298 P FOIA 50-358 Q	SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A.	8307050293 8307050333 8307080447 8307080471 8307080500	50-373 P 50-373 P 50-416 F 50-387 P 50-352 D	SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C.	8307120460 8307120471 8307120487 8307120488 8307120514	50~285 @ 50~482 @ 50~285 @ 50~482 @ 50~285 @
Schemel, R.	8307120168*	50-537 T	SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A.	8307080510*	50-352 D	BEIDLE: W. C.	B307150073	90-285 @
Scherer, A. E.	8307010172	50-470 A		8307080522*	50-352 D	SEIDLE: W. C.	B307180261	90-482 @
Scherer, A. E.	8307250416	PR		8307080525*	50-352 D	SEIDLE: W. C.	B307220480	90-482 @
Scherer, A. E.	8307270352	50-470 E		8307080527*	50-352 D	SEIDLE: W. C.	B307220512	90-313 @
Scherer, A. E.	8307270422	TOPREP		8307080543	50-352 A	SEIDLE: W. C.	B307250410	90-285 @
SCHIERLING, H. SCHIERLING, H. SCHLAPPER, G. A. SCHLEICHER, R. J. SCHMIDT, H. C.	8307140155 8307150368 8307260566 8307220024* 8307050064	50-275 P 50-275 P 50-59 H 71-37 50-445 A	BCHWENCER, A. BCHWENCER, A. BCHWENCER, A. SCHWENCER, A. BCHWENCER, A.	8307110569 8307130006 8307140145 8307150044 8307150046*	50-373 P 50-352 A 50-354 A 50-416 P 50-416 P	SEIDLE, W. C. SEIKEN, S. J. SEIKEN, S. J. SELBY, J. D.	8307260435 8307060286 8307060286* 8307250307 8307080321*	50-285 Q 50-482 S 50-482 B 50-482 A 50-255 P
BCHMIDT, H. C.	8307110282	50-445 A	BCHWENCER, A. BCHWENCER, A. BCHWENCER, A. SCHWENCER, A. BCHWENCER, A.	8307150051*	50-416 P	BELDVER, R. E.	8307130306	50-272 Q
BCHMIDT, H. C.	8307110350	50-445 E		8307180367*	50-387 P	BELDVER, R. E.	8307270395	50-272 Q
BCHMIDT, H. C.	8307120631	50-445 A		8307180381*	50-387 P	BERBU, R. J.	8307110270*	50-413 Q
BCHMIDT, H. C.	8307250256	50-445 A		8307170410	50-373 F	BERINI, B. L.	8307270302	70-2946
BCHMIDT, H. C.	8307250370	50-445 A		8307170494	50-387 P	BERKIZ, A. W.	8307270023	GEN TEC IS
SCHMIDT, H. G. SCHMIDT, R. J. SCHMITENDORF, G. SCHMITT, H. H. SCHMITT, T. J.	8307260548 8307060185* 8307220192 8307180328* 8307260295	30-445 K 30-423 G 30-336 R CONTRACT WASTE MOT	BCHHENCER, A. BCHWENCER, A. BCHWENCER, A. BCHHENCER, A. BCHHENCER, A.	8307190495 8307200050* 8307200154 8307200383 8307200384	50-397	SERNE, R. J. SESTAK, F. SESTAK, F. SESTAK, F. SEXTON, J. A.	8307270360 8307050137* 8307050143* 8307050149* 8307060180*	NUREG 50-275 R 50-275 R 50-275 R 50-275 F
SCHMITZIR.P.	8307150276	PR	SCHWENGER: A. SCHWENGER: A. SCHWENGER: A. SCHWENGER: A. SCHWENGER: A. SCHWENGER: A.	8307200386	50-397 A	SEYFRIT, K. V.	8307260256*	50-382 A
SCHNAUTZIC.E.	8307070452	XPORTLIC		8307200480	50-354 D	SHACK, W. J.	8307090133	NUREG
SCHNEIDERIG.	8307140195*	50-369 G		8307200538	50-410 D	SHAFER, P. W.	8307080518	50-407 G
SCHNELLID.F.	8307050096	50-483 S		8307220587	50-458 A	SHAFER, P. W.	8307110563*	50-409 F
SCHNELLID.F.	8307060034	50-483 A		8307270049	50-461 A	SHAFER, P. W.	8307220564	50-409 P
SCHNELL, D. F.	8307110231	50-483 8	SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWINK, W.	8307270164	50-354 A	SHAFER, W.	8307220401	50-409 8
SCHNELL, D. F.	8307110257	50-483 A		8307270251	50-354 A	SHAFER, W.	8307220531	50-373 8
SCHNELL, D. F.	8307110301	50-483 8		8307270478	50-387 P	SHAFER, W.	8307260541	50-237 8
SCHNELL, D. F.	8307110354*	50-483 Q		8307280187	50-410 D	SHAFER, W.	8307260574	50-409 8
SCHNELL, D. F.	8307110364*	50-483 Q		8307190399	REVIEW GRP	SHAFER, W. D.	8307060131	50-316 0
SCHNELL, D. F. SCHNELL, D. F. SCHOPPMAN, M. SCHREIBER, J. J. SCHROCK, V. E.	8307240214* 8307280401* 8307250473 8307220212 8307200352	50-483 G 50-483 G 50-247 K Waste Mgt Acre	SCINTO, J. F. SCINTO, J. F. SCOTT, D. E. SCOTT, D. J. SCOTT, D. J.	8307050374* 8307180015 8307220516* 8307060084 8307060237	PR 50-445 Q 50-416 Q 50-247 8 50-237 8	BHAFER, W. D. BHAFER, W. D. BHAFER, W. D. SHAFER, W. D. BHAFER, W. D.	8307040134* 8307040315 8307040324* 8307080381 8307180011	50-314 G 50-282 G 50-331 G 50-263 G
SCHROCK, V. E.	8307200352	ACRE	SCOTT, D. J.	8307080243	50-237	SHAFER, W. D.	8307180125	50-155 Q
SCHROEDER, B. A.	8307150194	50-237 R	SCOTT, D. J.	8307080496		SHAFER, W. D.	8307210005	50-331 Q
SCHROEDER, B. A.	8307220231	50-237 E	SCOTT, D. J.	8307110115		SHAFER, W. D.	8307210247	50-407 Q
SCHROEDER, C. W.	8307050210	50-373 R	SCOTT, D. J.	8307110187		SHAFER, W. D.	8307250434	50-373 Q
SCHROEDER, C. W.	8307110114	50-373 P	SCOTT, D. J.	8307110359		SHAFFNER, J. A.	8307200160	27-48
SCHROEDER; C. W. SCHROEDER; C. W. SCHROEDER; C. W. SCHROEDER; C. W. SCHROEDER; C. W.	8307110371 8307120382 8307120431 8307120435 8307120524	50-373 B 50-373 A 50-373 P 50-265 P 50-374 E	SCOTT, D. J. SCOTT, D. J. SCOTT, D. J. SCOTT, D. J. SCOTT, D. J.	8307110409 8307150194 8307200168 8307200174 8307200191	50-249 8 50-237 R 50-237 8 50-237 8 50-237 8	SHAFFNER, J. A. SHAHEN, R. J. SHAMSIAD, M. SHAMSIAD, P. E. SHANAWANY, M. E.	8307200182 8307190254* 8307180152* 8307080325*	WASTE MGT 50-443 0 50-237 P 50-237 P TOPREP
SCHROEDER; C. W.	9307220375	50-373 P	SCOTT, D. J.	8307200218	50-247 8	SHANBAKY, M.	8307110364*	50-334 G
SCHROEDER; C. W.	9307220486	50-374 B	SCOTT, D. J.	8307200302	50-237 8	SHANBAKY, M.	8307110388*	50-247 G
SCHROEDER; C. W.	9307260314	50-373 E	SCOTT, D. J.	8307220231	50-237 8	SHANBAKY, M. M.	8307110287*	50-322 G
SCHUERMAN; L. E.	9307170023	70-2926	SCOTT, D. J.	8307220260	50-249 8	SHANBAKY, M. M.	8307140235*	50-311 G
SCHULTZ; W. H.	9307080301	50-295 Q	SCOTT, D. J.	8307240213	50-237 P	SHAPIRO, R.	8307120367*	50-322 G
BCHULZ, R. D.	8307010036*	50-410 G	SCOTT-WASILK, J.	8307280071*	50-346 P	SHAPIRO,R.	8307290159*	50-322 G
SCHUM, M. B.	8307120498*	50-482 G	SCULL, D. L.	8307070215	50-170 G	SHEAIJ.	8307080348*	MIBC
BCHUMACHER, M.	8307120007*	50-263 G	SCURRY, N.	8307050222	ORG	SHEAIJ.	8307050187	50-245 P
BCHUMACHER, M. C.	8307180018*	50-454 G	SCURRY, N.	8307050224	ORG	SHEAIJ.F.	8307120367*	50-322 G
BCHUMACHER, M. C.	8307180107*	50-282 G	SCURRY, N.	8307050230	ORG	SHEAIJ.J.	8307080434	50-245 P
SCHUYLER, J. O.	8307010163	30-275 P	SCURRY, N.	8307050234	ORG	SHEA, J. J.	8307130282	50-245 P
SCHUYLER, J. O.	8307010170	50-275 R	SCURRY, N.	8307200335	ORG	SHEA, J. J.	8307250524	50-245 P
SCHUYLER, J. O.	8307060088	50-275 P	SCURRY, N.	8307260603	ORG	SHEARER, D. L.	8307120018	Nureg
SCHUYLER, J. O.	8307060178	50-275 F	BEARS, C. F.	8307140241	50-423 5	SHEDLOSKY, J. T.	830710167*	50-245 Q
SCHUYLER, J. O.	8307060176	50-275 P	BEARS, C. F.	8307140271	50-423 A	SHELKRET, E. L.	8307150417*	Contract

AUTHOR	ACCESSION RAGRUM	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCE88ION NUMBER	SUBJECT CATEGORY
SHELLEY, W. J SHEN, H. W. SHEPHERD, R. E SHERMAN, C. I. SHERR, T. S	8307080548 8307250643* 8307250060* 8307060243* 8307250542	40-8027 CONTRACT FOIA 50-224 G FOIA	SILBERG, J. E.	8307190084 9307190203 8307190203 8307190208*	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	SMITH, C.N. SMITH, C.N. SMITH, C.N. SMITH, C.N. SMITH, C.N.	8307110628 8307110643 8307110647 8307110648 8307110654	70-687 70-1257 70-371 70-25 70-824
SHERWOOD, D. R. SHERWOOD, G. G. SHERWOOD, G. G SHERWOOD, G. G. SHERWOOD, G. G.	8307270360 8307010180 8307110470 8307150179 8307250377	NUREQ 50-447 A 50-447 A PR 50-447 K	SILBERG, J. E.	8307190240 8307190240 8307190284 8307190284 8307210241	50-482 G 50-482 G 50-412 G 50-412 G 50-482 G	SMITH, C. N.	8307110658 8307110662 8307110666 8307110671 8307110678	70-1100 70-135 70-27 70-1113 70-1143
SHERWOOD, C. G. SHERWOOD, C. G. SHICK, V. SHIELDS, S. W SHIELDS, S. W.	9307250382* 9307270131 9307190331 9307050174 9307060010	50-447 X 50-447 A 40-8331 50-546 S 50-546 Q	SILBERG, J. E. SILBERG, J. E. SILBERG, J. E. SILVER, C. SILVER, H.	8307210241 8307210248 8307270287 8307180148 8307140525	50-482	SMITH, C.N. SMITH, C.N. SMITH, G.C. SMITH, G.C. SMITH, G.C.	8307110702 8307110760 8307110355* 8307110372* 8307140086*	70-754 70-1201 70-1703 50-97 q 50-57 q
Shields, S. W Shields, S. W. Shields, S. H. Shields, S. H.	8307110305 8307190140 8307190172 8307190209 8307190210	50-546 B 50-546 I 50-546 G 50-546 F 50-546 Q	SILVER, H. SILVIS, R. M. SILVIS, R. M. SILVIS, R. M. SILVIS, R. M.	8307180294 8307080583 8307200166 8307250026 8307250100	50-289 P CONTRACT CONTRACT 50-201 P CONTRACT	SMITH, Q.C. SMITH, I.W. SMITH, I.W. SMITH, I.W. SMITH, I.W.	8307140242# 8307050148 8307060400 8307110324 8307150187	50-29 q 50-346 q 50-454 q 50-454 q 50-454 q
SHIELDS, S. W. SHIELDS, S. W. SHIELDS, S. W. SHIFFER, J. D SHIFFER, J. D	8307190261 8307220460 8307220490 8307220271 8307130092	50-546 S 50-546 S 50-546 S 50-275 S 50-275 S	SILVIS, R. M. SILVIS, R. M. SILVIS, R. M. SILVIS, R. M. SILVIS, R. M.	8307250111 8307250115 8307250143 8307250168 8307250168	CONTRACT CONTRACT CONTRACT CONTRACT 50-289 P	SMITH, I.W. SMITH, I.W. SMITH, I.W. SMITH, J.L. SMITH, J.L.	8307150293 8307220341 8307280232 8307010004 8307010043*	50-454 Q 50-454 Q 50-454 Q 50-322 A 50-322 Q
SHIRAKAWA, T. SHIRAKAWA, T. SHIRAKAWA, T. SHIRAKAWA, T. SHIRAKAWA, T.	8307110347 8307130121 8307130337 8307130340 8307250648	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	SILVIS, R. M. SILVIS, R. M. SILVIS, R. M. SILVIS, R. M. SILVIS, R. M.	8307250226 8307250241 8307290156 8307290321 8307290454	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SMITH: J. L. BMITH: J. L. SMITH: J. L. SMITH: J. L. SMITH: J. L.	8307010112 8307050031 8307050038 8307050091 8307050254	50-322 A 50-322 E 50-322 A 50-322 E
SHIVELY, C. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J.	8305270018 8307050077 8307050109 8307050159 8307060421	50-313 P 50-382 Q 50-287 Q 50-287 Q 50-443 Q	SILVIS, R. M. SILVIS, R. M. SIMAN-TOV, M. SIMON, A. C. SIMON, J. A.	8307290480 8307290494 8307050314 8307090034 8307140044*	CONTRACT CONTRACT RES 71-500 50-329 G	SMITH, J. L. SMITH, J. L. SMITH, J. L. SMITH, J. L. SMITH, J. L.	8307050274 8307070015 8307070046 8307070094 8307070121	50-322 E 50-322 A 50-322 A 50-322 Q
SHOEMAKER, C, J. SHOEMAKER, C, J. SHOEMAKER, C, J. SHOEMAKER, C, J. SHOEMAKER, C, J.	8307080464 8307080469 8307080475 8307080494 8307110050	50-275	SIMON, W. A. SIMONDS, G. E. SINCLAIR, J. B. SINCLAIR, J. B. SINCLAIR, J. B.	8307150238 8307110302* 8307070058 8307070103 8307260408	50-52B A 50-413 Q 50-271 F 50-271 P 50-271 P	SMITH.J.L. SMITH.J.L. SMITH.J.L. SMITH.J.L. GMITH.J.L.	8307080249 8307080398 8307140200 8307140356 8307200002	50-322 K 50-322 A 50-322 A 50-322 K
SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J.	8307120548 8307130070 8307140438 8307180269 8307180272*	50-266 G 50-454 G 50-409 G 50-275 H 50-275 H	Sinclair, M. Sinderbrand, C. Singh, A. Singh, M. M. Sinibi, J. M.	8307050111* 8307070159 8307110260* 8307250550* 8307200111	50-329 H PR 50-413 0 CONTRACT 50-245 J	SMITH, J. L.	8307200012 8307200141 8307230477 8307280075 8307280100	50-322 A 50-322 E 50-322 A 50-322 F 50-322 A
SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J.	8307200120 8307210250 8307210280 9307220360 8307220371	50-382 0 50-443 G 50-289 G 50-443 G 50-352 0	Sinke, G. J. Sinke, G. J. Sinke, G. J. Skinner, P. Skinner, P. H.	8307130086 8307200207 8307200217 8307140175* 8307140236*	40-8768 40-8768 40-8768 50-369 Q 50-280 Q	BMITH, J. L. BMITH, K. R. BMITH, L. C. BMITH, M. BMITH, M. P.	8307280300 8307040411* 8307070119* 8307220553* 8307270110	50-322 8 50-400 0 50-334 P 50-454 G 50-423 H
SHOEMAKER, C. J. SHOEMAKER, C. J. SHOGAN, R. P. SHOLLY, B. S. SHOLLY, S. S.	8307280154 8307290077 8307190257* 8307120185 8307120194	50-454 @ 50-382 @ 50-213 P NUREG PR	SKINNER, P. H. SKOLDS, J. L. SKOLDS, J. L. SKOVHOLT, D. J. SKOVHOLT, D. J.	8307140421* 8307220078* 8307220563* 8307140457* 8307140462*	50-302 Q 50-375 Q 50-375 Q 50-87 Q 50-89 Q	SMITH, P. A. SMITH, P. A. SMITH, P. A. SMITH, P. A. SMITH, P. A.	8307050284 8307050285* 8307050317 8307050328* 8307080557	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SHOTHELL, J. A. SHOTHELL, J. A. SHOTHELL, J. A. SHOTHELL, J. A. SHOTHELL, J. A.	8307050203 8307190212 8307190216* 8307190220* 8307260358	50-443 G 50-443 G 50-443 G 50-443 G 50-443 G	SLADE, M.L. SLAGGIE, E.L. SLAHINSKI, W.J. SLIGER, E.K. SLIGER, E.K.	8307200227 8307260601* 8307220101 8307110164* 8307110164*	50~244	BMITH, P. A. BMITH, P. A. SMITH, P. A. SMITH, P. A. SMITH, P. A.	8307080563* 8307140487 8307140493* 8307150056* 8307150367*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SHREVE, D. B. SHREVE, D. B. SHUNMUQAVEL, P. SHUNMUQAVEL, P. SHYHLOCK, M. B.	8307200170* 8307290326* 8307210261* 8307210261* 8307220267*	CONTRACT CONTRACT 50-329 G 50-329 G 50-338 G	SLOWLY: L. SMALL: W. D. SMITH: A. L. SMITH: A. L. SMITH: A. V.	8307180431* 8307270300* 8307180161* 8307180192* 8307080590	CONTRACT WASTE MGT GA999 GA999 NUREG	SMITH, P. A.	8307150376* 8307150417* 8307150422* 8307150430* 8307150435*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SIBULKIN, M. SIETI, J. D. SILAKOSKI, A. F. SILBERG, J. E. SILBERG, J. E.	8307250530 8307060293* 8307190104* 8307060238 8307060238	NUREQ 50-331 P 50-440 G 50-440 T 50-440 T	Smith, C. F. Smith, C. N. Smith, C. N. Smith, C. N. Smith, C. N.	8307110087 8307090094 8307090098 8307110551 8307110556	NUREG 70-143 70-36 70-27 70-1113	SMITH, P. A.	8307180429 8307180431* 8307190339* 8307190435* 8307200388*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SILBERG, J. E. SILBERG, J. E. SILBERG, J. E. SILBERG, J. E.	8307060339 8307060339 8307060344# 8307060344# 8307150287	50-440 G 50-440 G 50-440 G 50-440 G 50-412 G	SMITH, C. N. SMITH, C. N. SMITH, C. N. SMITH, C. N. SMITH, C. N.	8307110571 8307110576 8307110582 8307110584 8307110587	70-371 70-143 70-1257 70-1113 70-1308	SMITH, P. A.	8307250250* 8307250503 8307250507* 8307250627 8307250635	SO-498 A CONTRACT CONTRACT CONTRACT CONTRACT
SILBERG, J. E. SILBERG, J. E. SILBERG, J. E. SILBERG, J. E. SILBERG, J. E.	8307150287 8307150343 8307150343 8307150350 8307150350	50-412	Smith, C. N. Smith, C. N. Smith, C. N. Smith, C. N. Smith, C. N.	8307110570 8307110572 8307110574 8307110607 8307110613	70-1151 70-143 70-27 70-135 70-734	SMITH, P. A. SMITH, P. A. SMITH, P. H. SMITH, P. H. SMITH, R.	8307250645# 8307250687# 8307150454# 8307250630* 8307010080*	CUNTRACT CONTRACT CONTRACT CONTRACT CONTRACT 50-245 G
SILBERG, J. E. SILBERG, J. E. SILBERG, J. E. SILBERG, J. E.	8307180190 8307180204 8307180225 8307180225 8307190084	50-482 G 50-482 G 50-412 G 50-412 G 50-440 G	SMITH, C. N.	8307110617 8307110621 8307110623 8307110624 8307110625	70-143 50-27 C 70-398 70-1193 70-143	SMITH, R. H. SMITH, S. L. SMITH, T. W. SMITH, W. G. SMITH, W. G.	8307250040* 8307070090 8307010151 8307050019 8307050054	FOIA 50-322 0 50-284 8 50-315 8 50-315 8

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMITH, W. C.	8307050090	50-315 S	STAROSTECKI.R.	8307050347	50-307	STEWART, W. L.	8307120356	50-338 P
SMITH, W. C.	8307060372	50-315 S	STAROSTECKI.R.	8307110285		STEWART, W. L.	8307120386	50-280 F
SMITH, W. G.	8307060007	50-316 S	STAROSTECKI.R.	8307110385		STEWART, W. L.	8307120441	50-339 P
SMITH, W. G.	8307110193	50-316 S	STAROSTECKI.R.	8307110392		STEWART, W. L.	8307120561	50-338 P
SMITH, W. G.	8307110333	50-316 S	STAROSTECKI.R.	8307110394		STEWART, W. L.	8307140228*	50-280 G
SMITH, W. O.	8307180104	50-316 S	STAROSTECKI, R.	8307110397	50-166 @	STEWART, W. L.	8307180097	50-338 P
SMITH, W. O.	8307180140	50-315 S	STAROSTECKI, R.	8307110414	50-333 @	STEWART, W. L.	8307180100	50-338 P
SMITH, W. O.	8307200273#	50-315 Q	STAROSTECKI, R.	8307110422	50-443 @	STEWART, W. L.	8307180106	50-338 Q
SMITH, W. O.	830722008	50-316 R	STAROSTECKI, R.	8307120213	70-1143	STEWART, W. L.	8307200194	50-280 R
SMITH, W. O.	8307220097	50-315 R	STAROSTECKI, R.	8307120231	50-247 @	STEWART, W. L.	8307210205	50-280 P
SMITH, W. G.	83072203B4	50-315 S	STAROSTECKI, R.	8307120387	50-387 S	STEWART, W. L.	8307220192	50-338 R
SMITH, W. G.	8307220403	50-316 S	STAROSTECKI, R.	8307120429	50-245 Q	STEWART, W. L.	8307220385	50-280 R
SMYTH, C. W.	8307220182	50-287 R	STAROSTECKI, R.	8307120463	50-334 Q	STEWART, W. L.	8307250451	50-339 P
SNEIDER, C. S.	8307260259	50-443 G	STAROSTECKI, R.	8307120503	50-352 Q	STEWART, W. L.	8307270289	50-338 F
SNELL, W.	8307060303*	50-255 G	STAROSTECKI, R.	8307140099	70-667	STEWART, W. L.	8307270329	50-280 F
SNIDER, J. M. SNIEZEK, J. H. SNOW, A. C. SNOW, A. L. SNOW, B. A.	8307130325* 8307130437 8307130224* 8307130206* 8307220178	50-454 A 50-358 A 50-413 G 50-413 G 50-244 R	STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R.	8307140313 8307140327 8307140371 8307140404 8307140459	50-220	STEWART, W. L STICKLEY, T. H. STIEDE, W. L. STIEDE, W. L. STILL, N.	8307280418 8306240037* 8307010175 8307270454* 8307220038	50-280 P 50-273 P 50-237 K 50-454 Q WASTE MGT
SNYDER, A. M. SNYDER, B. J. SNYDER, B. J. SODA, K. SOLLEY, B. W.	8307250080 8306100004 8307290542 8307210265 8307120470	NUREG 50-320 H 50-320 P NUREG 50-259 S	STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R.	8307150089 8307150101 8307150107 8307150264 8307150307	50-317	STILLIN. STILLIN, STILLIN. STOHRIJ.P. STOHRIJ.P.	8307220045 8307220154 8307270368 8306140204 8307010061	WASTE MGT WASTE MGT WASTE MGT 50-414 F 70-1201
SOLLEY, S. W.	8307220435	50-259 5	STAROSTECKI, R.	8307150351	50-213	STOHRI J. P.	8307010140	70-1201
SOLLEY, S. W.	8307220440	50-259 8	STAROSTECKI, R.	8307180141		STOHRI J. P.	8307080455	70-143
SOLOMON, A. A.	8307200474	ACR8	STAROSTECKI, R.	8307180203		STOHRI J. P.	8307110181	70-1151
SOLOMON, A. A.	8307200474	ACR8	STAROSTECKI, R.	8307190164		STOHRI J. P.	8307140047	70-1151
SOMMER, S. J.	8307280415#	50-369 P	STAROSTECKI, R.	8307210007		STOHRI J. P.	8307140050	50-302 F
SOONO, A. L.	8307180420	70-143	STAROSTECKI, R.	9307210053	50-271 Q	STOHR, J. P.	8307140164	50-269 F
SORENSEN, G. C.	8307180059	50-508 A	STAROSTECKI, R.	9307210070	50-352 Q	STOHR, J. P.	8307140170	50-250 F
SORENSEN, G. C.	8307200142	50-397 A	STAROSTECKI, R.	9307210096	70-371	STOHR, J. P.	8307140188	50-395 F
SORENSEN, G. C.	8307260519	50-397 E	STAROSTECKI, R.	9307210123	50-273 Q	STOHR, J. P.	8307140193	70-143
SORENSEN, G. C.	8307260523	50-397 C	STAROSTECKI, R.	9307250403	50-320 Q	STOHR, J. P.	8307140194	50-324 F
SORENSEN, G. C.	8307290177	50-440 A	STAROSTECKI, R.	8307250436	50-220 G	STOHR, J. P.	8307140205	70-143
SORENSON, G. C.	8307220415	50-508 E	STAROSTECKI, R.	8307250437	50-322 G	STOHR, J. P.	8307140219	50-395 F
SPANE, F. A.	8307220240*	Waste Mot	STAROSTECKI, R.	8307270464*	50-272 G	STOHR, J. P.	8307140244	50-269 F
SPECTER, A.	8307270019*	50-320 H	STAROSTECKI, R.	8307280188	50-199 G	STOHR, J. P.	8307140247	70-143
SPEIS, T. P.	8211030148	50-447 A	STAROSTECKI, R.	8307280211	50-272 G	STOHR, J. P.	8307140261	70-143
SPEIS, T. P.	8304140030*	50-322 A	STAROSTECKI, R.	8307280276	50-307 0	STOHR, J. P.	8307140279	70-1201
SPEIS, T. P.	8304200084*	50-322 A	STAROSTECKI, R.	8307280304	50-286 Q	STOHR, J. P.	8307140324	70-1113
SPEIS, T. P.	8307080605	NUREQ	STAROSTECKI, R.	8307280307	50-317 Q	STOHR, J. P.	8307140325	70-1151
SPELLMAN, J.	8307280130	WASTE MOT	STAROSTECKI, R.	8307280318	70-820	STOHR, J. P.	8307140357	50-324 F
SPENCE, M. D.	8307220259	50-445 B	STAROSTECKI, R.	8307280332	50-387 Q	STOHR, J. P.	8307140364	70-1201
SPESBARD, R.	8307190039	50-546 E	STAROSTECKI, R.	8307280336	50-367 Q	STOHR, J. P.	8307140390	50-259 F
SPESSARD, R. L.	8307080009	50-454 G	STAROSTECKI, R.	8307280334	50-220 Q	STOHR, J. P.	8307140423	70-143
SPESSARD, R. L.	8307080012*	50-454 G	STAROSTECKI, R.	8307280438*	50-219 Q	STOHR, J. P.	8307140456	70-1151
SPESSARD, R. L.	8307110411	50-373 G	STAROSTECKI, R.	8307280444	50-273 Q	STOHR, J. P.	8307220282	70-27
SPESSARD, R. L.	8307110480	50-266 G	STAROSTECKI, R.	8307280461*	50-352 Q	STOHR, J. P.	8307290140	70-824
SPESSARD, R. L.	8307180062	50-373 G	BTATTON, C. D.	8307060023*	QA799	STOLZ, J. F.	8307040422	50-312 F
SPESSARD, R. L.	8307200207	50-237 G	STEAD, L. S.	8307290182	50-334 R	STOLZ, J. F.	8307040430	50-312 P
SPESSARD, R. L.	8307280384	50-341 G	STEFANO, J. J.	8307090111	TOPREP	BYOLZ, J. F.	8307040481	50-346 F
SPESSARD, R. L.	8307280388*	50-341 G	STEFANO, J. J.	8307290455	TOPREP	STOLZ, J. F.	8307070554	50-321 P
SPIGOLON, S. J.	8307150137	NUREG	STEFFEY, W. J.	8307060285*	50-331 P	STOLZ, J. F.	8307080236	50-312 P
SPITZBURG, D. B.	8307240325*	40-8550	STELLO, V.	8307050522	REVIEW GRP	STOLZ, J. F.	8307080553	50-321 P
SPRAUL, J. Q.	8307120193*	50-537 T	STELLO, V.	8307070059	REVIEW GRP	STOLZ, J. F.	8307080615*	50-346 P
SRENIAWSKI, D.	8307040225	1&E	STELLO, V.	8307110298	REVIEW GRP	STOLZ, J. F.	8307080620*	50-346 P
SRENIAWSKI, D.	8307200254	I&E	STELLO, V.	8307200091*	70-143	STOLZ, J. F.	8307080650	50-278 P
SRENIAWSKI, D. J.	8307180159	I&E	STEPTOE, P. P.	8307110150	50-327 G	STOLZ, J. F.	8307180268*	50-269 P
SRENIAWSKI, D. J.	8307220521	70-2204	STEPTOE, P. P.	8307110150	50-327	STOLZ, J. F.	8307190386	50-313 P
SRENIAWSKI, D. J.	8307220524*	70-2204	STEPTOE, P. P.	8307210259		STOLZ, J. F.	8307200358*	50-366 P
ST LAURENT, N. N.	8307220275	50-27 6	STEPTOE, P. P.	8307210259		STOLZ, J. F.	8307200360*	50-366 P
STADNICK, S.	8307040381	50-336 S	STEPTOE, P. P.	8307240413		STOLZ, J. F.	8307200465	50-302 P
STANGE, S. J.	8307110579*	50-287 F	STERNBERG, D. M.	8304170412		STOLZ, J. F.	8307200469*	50-302 P
STANGE, B. J.	8307120073*	50-287 F	STERNBERG, D. M.	8307120511	50-312	STOLZ, J. F.	8307210335	50-366 P
STANISH, P.	8307040240*	50-508 A	STERNBERG, D. M.	8307120532		STOLZ, J. F.	8307220585	50-312 P
STARK, R. M.	8307120211*	50-537 T	STERNBERG, D. M.	8307120541		STOLZ, J. F.	8307220590	50-346 P
STARKEY, R. B.	8307110294	50-241 S	STERNBERG, D. M.	8307120558		STOLZ, J. F.	8307220621*	50-346 P
STARKEY, R. B.	8307120337	50-241 Q	BTERNBERG, D. M.	8307120540		STOLZ, J. F.	8307250544	50-313 P
STARKEY, R. B.	8307130059	50-241 R	STERNBERG, D. M.	8307150198	50-50B Q	STOLZ; J. F.	8307250663	50-313 P
STARKEY, R. B.	8307220002*	50-241 G	STETKA, T. F.	8307210275*	50-302 Q	STOLZ; J. F.	8307250702	50-302 G
STARKEY, R. B.	8307220458*	50-241 G	STEVENS, G. P.	8307220373	50-443 G	STOLZ; J. F.	8307250706*	50-302 G
STARKEY, R. B.	8307220473	50-241 S	STEVENSON, M. G.	8307250095	NUREG	STOLZ; J. F.	8307270022	50-289 P
STARKEY, R. B.	8307250106	50-241 S	STEWART, W. L.	8305100108	50-280 P	STOLZ; J. F.	8307270044	50-289 V
STARKEY, R. B.	8307290179	50-261 8	STEWART, W. L.	8307010020	50-281 F	STOLZ, J. F.	8307270045	50-313 P
STAROSTECKI.R.	8307010002	50-410 0	STEWART, W. L.	8307010070	50-338 P	STOLZ, J. F.	8307270048	50-366 P
STAROSTECKI.R.	8307010016	50-219 0	STEWART, W. L.	8307050117	PR	STOLZ, J. F.	8307270170	50-321 P
STAROSTECKI.R.	8307010018	50-397 0	STEWART, W. L.	8307060042	50-338 Q	STOLZ, J. F.	8307270259	50-277 P
STAROSTECKI.R.	8307010029	50-410 0	STEWART, W. L.	8307060230	50-280 P	STOLZ, J. F.	8307270281	50-313 P
BTAROSTECKI, R.	8307010038	50-309 G	STEWART, W. L.	8307110184*	50-280 F	STOLZ, J. F.	8307270294	50-346 P.
STAROSTECKI, R.	8307010052	50-219 G		8307110477*	50-280 F	STOLZ, J. F.	8307270327	50-289 V
STAROSTECKI, R.	8307010087	50-271 G		8307120251	50-280 G	STOLZ, J. F.	8307270348	50-289 P
STAROSTECKI, R.	8307010094	50-334 G		8307120268	50-338 P	STOLZ, J. F.	8307270359	50-289 P
STAROSTECKI, R.	8307010155	50-245 G		8307120302	50-338 P	STOLZ, J. F.	8307290012	50-289 P

AUTHOR	ACCESSION NUMBER	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STRAIT. S. R. STRAWBRIDGE, L. STRAWBRIDGE, L. STRAWBRIDGE, L. STREETER, J. F. STREETER, J. F.	9307220240 9307110149 9307110158 93071101644 9307050024	50-537 50-537	T T G	TAYLOR. G. J. TAYLOR. J. H. TAYLOR. J. H. TAYLOR. J. H. TAYLOR. J. H. TAYLOR. J. M.	8307220172 8307130273 8307140259 8307150244 8306270406	50-395 R TOPREP PT21 50-267 P 50-3 G	THOMPSON, T. THONUS, L. THORGERSEN, J. C. THORGERSEN, J. C. THORGERSEN, J. C. THORGERSEN, J. C.	8307220228 8307110394* 8307110277 8307110284 8307120451*	50-346 8 50-320 0 50-305 8 50-305 8 50-316 P
STREETER, J. F. STREETER, J. F. STREETER, J. F. STREETER, J. F.	8307080023* 8307080446 8307140176 8307140181*	50-263 50-155 50-374 50-374	G G G G	TAYLOR, P. A. TEDEBCO, R. L. TEDFORD, C. F. TENBEAU, P. N TENZER, B. E. TERAD, D.	8307140073* 8103300508* 8307050383 8307290164* 8307140286	50-413 Q FOIA State Prog CONTRACT TOPREP	THORNBERRY, R. C. THORNBERRY, R. C. THORNBURGH, D. THORNBURGH, D. THULL, T. S.	8307220496 8307250156* 8307060395 8307070204 8307010027	50-275 R 50-275 F 50-412 0 50-412 C 50-245 S
STREETER, J.F. STREETER, J.F. STREETER, J.F. STREETER, J.F.	8307140415* 8307200200 8307200269 8307280190	50-255 50-454 50-315 50-282 50-263	9 9	TERRELL, C. W. TERHILLIGER, L. TEST, L. D. THADANI, A.	8307270072* 9307260374 8307070456 8307130081* 8304200084*	50-484 A 50~112 V XPORTLIC 50~352 A 50-322 A	THULL, T. S.	8307010122 8307060343 8307060343 8307110281 8307190138	50-245 B 50-245 B 50-245 B 50-245 B 50-245 B
STREETER, J. F. STREETER, J. F. STRUCKMEYER STRUCKMEYER, R. STRUMWASSER, M.	8307280437 8307280439* 8307110503* 8307250413*	50-440 50-440 50-271	G G G	THEOFANGUS, T. G. THIBAU, H. P. THOM, T. THOM, T. THOMAS, C. O.	8307120176* 8307220413* 8307220413 8307220433 8306030043	50-537 T 50-375 P 50-259 R 50-259 R TOPREP	THULL.T.S. TIEN,C.L. TIEN,C.L. TIFFANY,T.A. TIFFANY,T.A.	8307190193 8307250081 8307250081 8307210006 8307220451	50-245 8 ACRE ACRS 50-309 8 50-309 8
STUCKY, S. H. STUDNICKA, Z. STYLES, L. C. STYLES, L. C.	8307050254 8307150362* 8307210217* 8307220348	50-289 50-397 50-454 50-454	G S G G	THOMAS, C. O.	8307050263 8307050367 8307060413 8307070230 8307070515	50-170 F PR 50-2 F 50-59 F 50-20 F	TILLMAN, A. TIPPB, S. B. TIPPB, S. B. TIPPB, S. B. TIPPB, B. B.	8307050181* 6305230444* 6307120098 8307120579 8307120586	50-416 Q 50-366 S 50-366 S 50-321 S 50-321 S
SUERMANN J F. SUGARMAN R. J. SUGARMAN R. J. SUGARMAN R. J. SULLIVAN J. W.	8307180262 8307110272 8307220364 8307220364 8307270364	50-269 50-352 50-352 50-352 FOIA	P A G G	THOMAS, C. O. THOMAS, C. O. THOMAS, C. O. THOMAS, C. O.	B307070523 B307070527 B307080493 B307090088 B307110224	50-83 F 50-54 F 50-54 P 50-445 A TOPREP	TIPPB, S. B. TIPPB, S. D. TIPPB, S. B. TIPPS, S. B. TIPPB, S. B.	8307150064 8307150071 8307150094 8307150120 8307150121	50-366 B 50-366 B 50-366 B 50-366 B 50-321 B
SUMMERS, R. SUND, H. J. SUND, H. J. SUND, H. J.	8307280458 8307060267* 8307060285* 8307060293*	50-311 50-331 50-331 50-331	2 9 9 9	THOMAS, C. O.	8307130307 8307130310* 8307150160 8307150170 8307150438	50-407 P 50-407 P 50-470 A 50-470 A 50-225 P	TIPPE, S. B.	8307150385 8307250096 8307250166 8307250191 8307250214	50-366 8 50-366 8 50-366 5 50-321 8 50-321 8
SUNDAHL, J. A SUNDIN, R. E. SUTHERLAND, H. J. SUTPHIN, R. N.	8307070105 8307070156 8307250274 8307080450*	40-8714 PR NUREG 90-155	Q	THOMAS. C. O.	8307150439* 8307180312 8307180406 8307180421 8307180427	50-225 P TOPREP TOPREP TOPREP 50-294 F	TIPPS, S. B. TIPPS, S. B. TIPPS, S. B. TIPPS, S. B. TIPTON, A.	8307250269 8307250293 8307250343 8307250348 8307060451	50-366 8 50-321 8 50-366 8 50-366 8 50-329 T
SUTTON, J. W. SUTTON, J. W. SVENSSON, B. A. SVENSSON, B. A. SHAN, W. B.	8307180215* 8307270065* 830722008 8307220097	0A999 0A999 50-316 50-315	R R	THOMAS, C. O.	B307190388 B307200027 B307200035+ B307200374 B307200393	NUREQ 50-73 P 50-73 P 50-410 A 50-407 F	TOBIN, H. J. TOBIN, H. J. TODD, A. J. TODD, A. J. TODD, A. J.	\$307080460* \$307180094* \$307190221* \$307190224* \$307220087*	70-143 50-261 Q 50-344 P 50-344 F 50-344 K
SHANSON, D. SWANSON, E. R. SHANSON, N. E. SHANSON, N. E. SHARTZ, E. D.	8307120174* 8307040138* 8307060289* 8307130205	50-537 50-314 GA999 50-335	T Q P	THOMAS, C. O.	8307200511* 8307210336 8307210338* 8307210343 8307210344	50-57 P 50-54 P 50-54 P 50-27 F 50-62 F	TODD, J. J. TODD, W. E. TOMASKO, D. TOMLINSON, D. P. TOMLINSON, W. P.	8307120273 8307180150 8307110135 8307120414* 8307060191	50-387 8 PR NUREG 50-298 0 50-261 0
SWARTZ, E. D.	8307130309 8307200121 8307210188 8307240018	50-454 50-454 50-456 50-237 50-346	9 6 7 8	THOMAS, C. O.	8307210345 8307250586 8307250618 8307270157 8307270173	50-166 F 50-407 I 50-407 F 50-470 A 50-407 V	TONER, K. A. TONER, K. A. TOURIGNY, E. Q. TOURIGNY, E. Q. TOURIGNY, E. Q. TOURIELLOTTE, J.	9307120485 9307210032 8307150096 8307250549 8307080259	50-155 P 50-155 P 50-285 H 50-285 P 50-27 P
SWARTZ, L. L. SWARTZ, L. L. SWARTZ, L. L. SWETLAND, P. SWIFT, J. J.	8307110363 8307110363 8307150308 8307280290*	50-322 50-322 50-322 50-309	G G G	THOMAS, C. D.	8307270188 8307270235 8307270252 8307270273 8307280104	50-447 E 50-148 F 50-131 F 50-116 F 50-112 F	TOWNLEY, E. L. YOWNBEND, B. TRAINOR, A. TRAHM, T. R. TRAMM, T. R.	8307110612* 8307290357 8307060342 8306230264 8307050282	50-315 F CONTRACT 50-373 8 50-454 A 70-2973
SWIFT, J. J. SWIFT, W. L. SWIGER, M. A. SWIGER, M. A. SWIGER, M. A.	8307120136* 8307280080 8307150316 8307150316	50-537 GEN TEC 50-440 50-440	G G	THOMAS, C. O. THOMAS, C. O. THOMAS, C. O. THOMAS, D. C. THOMAS, Q. S.	8307280107 8307280168 8307280179* 8307070209 8307210191*	50-186 H 50-243 P 50-243 P 50-454 0 50-443 T	TRAMM.T.R. TRAMMELL.C.M. TRAMMELL.C.M. TRAVIS.W.H. TRAVIS.W.H.	6307250432 6307170485 6307250041 6307170032* 8307260216	50-454 S 50-344 H 50-344 P 71-5552 71-5552
SZCZECH.R.A. SZUKIEHWICZ,A. TAHVILI.T. TALBOTT,D.C.	8307110436 8307200344 8307010157* 8307070218*	50-320 50-289 50-317 50-282 50-237	P S P P	THOMAS, J. THOMAS, M. THOMAS, R. D. THOMAS, R. D. THOMAS, R. D.	8307010025* 8307220493* 8307060052 8307060407* 8307120101*	50-217 G 50-390 G 27-48 27-48 70-1359	TRIMBLE, D. C. TRIMBLE, D. C. TRIPP, L. YRIPP, L. TRIPP, L.	8307150093* 8307280315* 8307110473 8307210124 8307280227*	50-317 @ 50-317 @ 50-277 8 50-277 8 50-272 G
TANG WEE, D. TANG, J. C. TAPIA, J. I. TARAS, D. N. TARAS, D. N.	8307180158* 8307200302 8307110265* 8307120430* 7905150678*	50-237 50-237 50-309 50-382 FOIA	P 5 0 0	THOMAS, R. D. THOMAS, R. D. THOMAS, R. D. THOMASON, P. V. THOMASON, P. V.	8307180117* 8307260456* 8307260482* 8307120550 8307150213	70-1257 27-48 70-1007 50-298 5 50-298 8	TRIPP, L.E. TROSKOSKI, M.M. TROWBRIDGE, G.F. TROWBRIDGE, G.F. TROWBRIDGE, G.F.	8307010109* 8307010109* 8307060207 8307060207 8307060212*	50-334 Q 50-334 Q 50-261 Q 50-261 Q 50-261 Q
TARAS, D. N. TAUBER, H. TAUBER, H. TAUBER, H. TAUBER, H.	8307210075* 8307210113* 8307050107 8307050362 8307120278	FOIA FOIA 50-341 50-341	F F · E	THOMASON, P. V. THOMASON, P. V. THOMPSON, H. L. THOMPSON, R. H. THOMPSON, R. H.	8307220184 8307260441 8307250588 8307220254 8307250129	50-298 R 50-298 S PR 50-302 S 50-302 S	TROMBRIDGE, G.F. TROMBRIDGE, G.F. TROMBRIDGE, G.F. TROMBRIDGE, G.F. TROMBRIDGE, G.F.	8307060212* 8307190294 8307220352 8307220352 8307220353	50-261 0 50-261 0 50-261 0 50-261 0 50-261 0
TAUBER, H. TAUBER, H. TAYLOR, C. W. TAYLOR, F. R.	8307170330 8307210028 8307270207 8307200014* 8307250033*	70-2926 50-341 50-341 70-143 50-334	À A G	THOMPSON, R, H. THOMPSON, S, L. THOMPSON, S, L. THOMPSON, E, L. THOMPSON, E, T.	8307250185 8307110082 8307110135 8307110308 8307180124	50-302 8 NUREG NUREG NUREG NUREG	TROWBRIDGE, G. F.	8307220353 8307260264 8307260264 8307280155 8307280155	50-261 Q 50-289 0 50-289 Q 50-289 G 50-289 Q

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TUCKER, H. B.	8305270627* 8307010015 8307040275 8307070067 8307080362	50-269 Q 50-413 F 50-269 Q 50-269 K 50-267 P	UHRIO, R. E.	8307050014 8307050126 8307060070 8307060209 8307060216	50-335 P 50-389 P 50-250 P 50-250 P 50-250 P	VAN BRUNT, E.E VAN ECK, D.J. VAN VLIET, J. VANDEL, T.E. VANDEWALLE, D.J.	8307290183 8307080595* 8307180295 8307280442* 8307050117	50-528 A CONTRACT 50-289 F 50-440 Q PR
TUCKER, M. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B.	B307110053	50-413 A	UHRIG, R. E.	8307040223	50-335 P	VANELL, J. A.	8307270345*	50-285 G
	B307110226	50-269 P	UHRIG, R. E.	8307040253	50-335 P	VARELA, A. A.	8307210025*	50-293 G
	B307110383	50-413 E	UHRIG, R. E.	8307040245	50-389 P	VARELA, A. A.	8307210133*	50-443 G
	B307120093	50-270 8	UHRIG, R. E.	8307070077	50-335 P	VARQA, S. A.	8307050371	50-286 P
	B307120115	50-369 S	UHRIG, R. E.	8307070084	50-250 P	VARQA, S. A	8307050449	50-247 G
TUCKER, H. B.	8307120200 8307120289 8307120349 8307120371 8307120398	50-370	UHRIG,R.E. UHRIG,R.E. UHRIG,R.E. UHRIG,R.E. UHRIG,R.E.	8307110153 8307110241 8307110361* 8307120410 8307120467	50-251 P 50-389 E 50-250 F 50-389 P 50-250 P	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8307050450 8307050457 8307060389 8307070232 8307070238	50-284 P 50-272 F 50-284 P 50-305 P 50-305 Q
TUCKER, H. B.	8307120427	50-414 S	UHRIG, R. E.	8307140198	50-250 P	VARGA, S. A.	B307070442	50-334 F
	8307120583	50-369 S	UHRIG, R. E.	8307140217	50-335 Q	VARGA, S. A.	B307070495	50-286 G
	8307120597	50-369 S	UHRIG, R. E.	8307140282*	50-387 Q	VARGA, S. A.	B30708028B	50-315 P
	8307120604	50-267 S	UHRIG, R. E.	8307140398*	50-335 Q	VARGA, S. A.	B307120885	50-348 P
	8307120609	50-269 S	UHRIG, R. E.	8307140401*	50-335 Q	VARGA, S. A.	B307140116*	50-348 P
TUCKER, H. B.	8307120613	50-267 S	UHRIG, R. E.	8307150216	50-250 P	VARGA, S. A.	8307180271	50~305 Q
	8307130249	50-413 E	UHRIG, R. E.	8307150231	50-389 P	VARGA, S. A.	8307190022*	50~280 P
	8307130263	50-267 G	UHRIG, R. E.	8307190132	50-250 P	VARGA, S. A.	8307190031	50~250 P
	8307140067	50-267 G	UHRIG, R. E.	8307190141	50-335 Q	VARGA, S. A.	8307200381	50~261 P
	8307140140	50-413 G	UHRIG, R. E.	8307190160	50-335 P	VARGA, S. A.	8307220128	50~286 P
TUCKER, H. B.	8307140305*	50-369 G	UHRIG, R. E.	8307220330*	50-389 Q	VARGA, S. A.	8307220423	50-272 F
TUCKER, H. B.	8307140310*	50-369 G	UHRIG, R. E.	8307220332*	50-389 Q	VARGA, S. A,	8307250088	50-286 P
TUCKER, H. B.	8307150108	50-369 B	UHRIG, R. E.	8307220389*	50-335 Q	VARGA, S. A.	8307250126	50-247 P
TUCKER, H. B.	8307150212	50-369 B	UHRIG, R. E.	8307220392*	50-335 Q	VARGA, S. A.	8307250128*	50-247 P
TUCKER, H. B.	8307150234	50-369 B	UHRIG, R. E.	8307220503	50-335 P	VARGA, S. A.	8307250141*	50-247 P
TUCKER, H. B.	8307150253	50-369 6	UHRIG, R. E.	8307220508	50-335 P	VARGA, S. A.	8307250235	50-250 P
	8307150259	50-370 5	UHRIG, R. E.	8307220518	50-251 R	VARGA, S. A.	8307250237	50-313 P
	8307150305	50-370 6	UHRIG, R. E.	8307250173	50-250 P	VARGA, S. A.	8307250528	50-286 P
	8307150340	50-369 6	UHRIG, R. E.	8307260353	50-387 P	VARGA, S. A.	8307270243	50-286 P
	8307150391	71-6678	UHRIG, R. E.	8307260505	50-335 Q	VARGA, S. A.	8307270247	50-286 P
TUCKER, H. B.	8307180074	50-369 F	UHRIG,R.E.	B307270351	50-335 F	VARGA, S. A.	8307270275	50-284 G
	8307190085	50-413 E	UHRIG,R.E.	B307280051	50-389 P	VARGA, S. A.	8307270320	50-261 P
	8307190135	50-269 P	UHRIG,R.E.	B307280098	50-250 F	VARGA, S. A.	8307270343	50-295 P
	8307190184	50-369 R	UHRIG,R.E.	B3072B0237	50-389 F	VARGA, S. A.	8307270350	50-261 P
	8307190218	50-413 E	UHRIG,R.E.	B307280314	50-335 K	VARGA, S. A.	8307270443	50-305 P
TUCKER, H. B.	8307220007	50-413 Q	ULECK,R.B.	8307260120	WASTE MOT	VAROA, S. A.	8307280482	50-275 P
	8307220221	50-370 S	UNKLE,T.J.	8307010076	50-317 S	VAROA, S. A.	8307270023	50-247 P
	8307220257	50-370 S	UPRIGHT,C.M.	8307140236*	50-280 G	VAROA, S. A.	8307270334	50-364 P
	8307220269	50-414 S	UPRIGHT,C.M.	8307140421*	50-302 G	VASSALLO, D. B.	8306100021	50-333 P
	8307220272	50-270 S	UPRIGHT,C.M.	8307220502*	50-414 G	VASSALLO, D. B.	8307110060	90-278 P
TUCKER, H. B.	8307220470 8307220499 8307220504 8307220511 8307250087*	50-413 G 50-370 S 50-413 G 50-287 S 50-369 F	UPRIGHT, C, M. URBANIK, T. URBANIK, T. UTLEY, E. E. UTLEY, E. E.	8307220541* 8307190285* 8307190285* 8307140314 8307220298*	50-438 Q 50-443 T 50-443 T 50-261 Q 50-324 Q	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	8307(10072 83071(10099 8307(20038 8307(2004) 8307(2004)	50-271 P 50-263 P 50-333 P 50-271 P
TUCKER, H. B.	8307250110*	50-269 F	UTLEY, E. E.	8307250197	50-324 K	VASSALLO, D. B.	8307120112	50-331 P
	8307250117	50-269 P	UTLEY, E. E.	8307290174	50-261 P	VASSALLO, D. B.	8307120117	50-331 P
	8307250202	50-369 S	VAIL, H. W.	8307150021	50-260 B	VASSALLO, D. B.	8307120125	50-254 P
	8307250300	50-269 F	VAIL, H. W.	8307220529	50-259 S	VASSALLO, D. B.	8307120137	50-254 F
	8307250372	50-413 E	VALDES, S. A,	8307120172	50-389 S	VASSALLO, D. B.	8307120146	50-331 P
TUCKER, H. B.	8307250441 8307250455 8307250625* 8307250730* 8307260304	50-287 P 50-413 E 50-413 F 50-269 F 50-269 P	VALDES, S. A. VALDES, S. A. VALDES, S. A. VAN BRUNT, E. VAN BRUNT, E. E.	8307120177 8307150268 8307250182 8307150363 8305130239	50-387 6 50-387 5 50-387 8 50-528 E 50-529 8	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	8307120152 8307130018 8307130021* 8307140126 8307140130	50-254 P 50-325 P 50-325 P 50-324 P 50-298 P
TUCKER, H. B.	8307260384 8307260390 8307260412 8307260426 8307260462	50-370 8 50-370 8 50-269 P 50-413 8 50-367 8	VAN BRUNT, E. E.	8307050024 8307050133 8307050197 8307050211 8307040012	50-528 A 50-528 A 50-528 A 50-528 E 50-528 A	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	8307140137 8307140138 8307140144 8307140150 8307140153	50-324 P 50-324 P 50-220 P 50-259 P 50-259 P
TUCKER, H. B.	8307260495	50-369 S	VAN BRUNT, E. E.	8307060013	50-528 8	VASSALLO, D. B.	8307140160	50~271 P
	8307260526	50-369 P	VAN BRUNT, E. E.	8307060046	50-528 S	VASSALLO, D. B.	9307140504	50~333 P
	8307260535	50-369 S	VAN BRUNT, E. E.	8307060323	50-528 B	VASSALLO, D. B.	9307140506	50~220 P
	8307260538	50-369 S	VAN BRUNT, E. E.	8307060368	50-528 E	VASSALLO, D. B.	9307140512	50~293 P
	8307280409	50-369 P	VAN BRUNT, E. E.	8307060379	50-528 S	VASSALLO, D. B.	9307140514	50~254 P
TUCKER, H. B. TUCKER, H. B. TUCKER, M. K. TUITE, P. T. TUITE, P. T.	8307270033	50-269 8	VAN BRUNT, E. E.	8307110012	50-528 E	VASSALLO, D. B.	8307150153	50-263 P
	8307270084	50-269 8	VAN BRUNT, E. E.	8307120195	50-527 S	VASSALLO, D. B.	8307150158	50-293 P
	8307110723	40-1341	VAN BRUNT, E. E.	8307120294	50-529 S	VASSALLO, D. B.	8307150162	50-271 P
	8307270351	Waste mot	VAN BRUNT, E. E.	8307120366	50-528 S	VASSALLO, D. B.	8307150163	50-293 P
	8307270400	Waste mot	VAN BRUNT, E. E.	8307120529	50-530 S	VASSALLO, D. B.	8307180026	50-254 P
TULODIESKI, D. TULODIESKI, D. TURK, S. E. TURK, S. E. TURK, S. E.	8307210233*	50-329 R	VAN BRUNT, E. E.	8307120530	50-528 S	VASSALLO, D. B.	8307180035	50-271 G
	8307210276*	50-327 R	VAN BRUNT, E. E.	8307140374	50-528 E	VASSALLO, D. B.	8307180173	50-263 P
	8307070200	50-537 T	VAN BRUNT, E. E.	8307180221	50-528 S	VASSALLO, D. B.	8307200485	50-331 P
	8307120156	50-537 T	VAN BRUNT, E. E.	8307170170	50-528 F	VASSALLO, D. B.	8307200324	50-254 P
	8307130211	50-537 T	VAN BRUNT, E. E.	8307170223	50-528 K	VASSALLO, D. B.	8307210030	50-259 P
TURK, S. E.	8307150342	50-382	VAN BRUNT, E. E.	8307200117	50-52B F	VASSALLO, D. B.	8307210326	50-333 F
TURK, B. E.	8307270227		VAN BRUNT, E. E.	8307260291	50-52B Q	VASSALLO, D. B.	8307290204	50-220 P
TURK, B. E.	8307280178		VAN BRUNT, E. E.	8307280313	50-52B S	VASSALLO, D. B.	8307290210	50-220 P
UDALL, M. K.	8307060443*		VAN BRUNT, E. E.	8307280348	50-52B S	VASSALLO, D. B.	8307290217	50-220 P
UHRIG, R. E.	8307010078		VAN BRUNT, E. E.	8307280413	50-52B S	VASSALLO, D. B.	8307290305	50-333 F

AUTHOR	ACCESSION NUMBER	SUBJE CATEG		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VASSALLO, D. B VAUGHAN, C. H. VAUGHAN, C. H VAUGHN, T. S VENDER, J.	8307290382 8307070048 8307190154 8307250110* 8307120423	70~1111 PR * 50~269 50~293	3 F 8	WALLACH, G. HALLER, W. K. HALLING, G. E. HALLING, G. E. WALLING, G. E.	8307180186* 8307150033 8307120134 8307120166 8307220427	50-237 71-6679 50-389 50-335 50-389	P S S S	WESTAFER, G. R. WESTAFER, G. R. WESTAFER, G. R. WESTAFER, G. R. WESTAFER, G. R.	8307120370 8307120495 8307120552 8307150088 8307150333	50-302 ; 50-302 ; 50-302 ; 50-302 ;
VENDER, J. VENDER, J. VENDER, J. VENDER, J. VERDERBER, J. J. VERMA, T. R. VERRELLI, D.	8307120518 8307220430 8307220551 8307150358 8307220205	50-293 50-293 50-293 50-397 WASTE M	S S S HGT	WALLING, G. E. WALTERS, W. H. WALTON, G. A. WAMBACH, T. V. WAMBACH, T. V.	6307220535 8307150147 8307210226* 8306290594* 8307270378*	PR 50-155	8 G P	WESTAFER, O. R. WESTAFER, O. R. WESTAFER, O. R. WESTAFER, O. R. WESTAFER, O. R.	8307210209 8307220254 8307250129 8307250185 8307250471	50-302 p 50-302 g 50-302 g 50-302 p
VERRELLI, D. VERRELLI, D. VERRELLI, D. M. VERRELLI, D. M. VERRELLI, D. M.	8307140158 8307140347 8307180070 8307140035 8307140046	50-327 50-390 50-261 50-259 50-259	0 0 8 0	HAMBACH, T. V. WAMBACH, T. V. HARD, E. C. WARD, E. C. HARD, E. C.	8307270404* 8307270436* 6307180326* 8307250642* 8307250650*	50-237 50-155 50-282 50-263 50-263	P F F F	WESTAFER, Q. R. WESTAFER, Q. R. WESTERMAN, T. WESTERMAN, T. F. WESTERMAN, T. F.	8307250483 8307270184 8307120414* 8307050129* 8307050138*	50-302 8 50-302 8 50-278 0 50-267 0 50-445 0
VERRELLI, D. M.	8307140046 8307140060 8307140064 8307140072 8307140085	50-259 50-261 50-390 50-327 50-327	0 0 0 0	WARD, K. D. WARE, J. T. WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D.	8307080272* 8307250630* 8307010041 8307050002 8307050069	CONTRACT 50-267 50-267	ច ន R P	WESTERMAN, T. F.	8307060122 8307120259* 8307150079* 8307150140* 8307150315*	50-298 \$ 50-267 q 50-265 q 50-267 8 50-298 q
VERRELLI.D.M. VERRELLI.D.M. VERRELLI.D.M. VERRELLI.D.M. VERRELLI.D.M.	8307140120 8307140161 8307140214 8307140220 8307140258	50-416 50-324 50-327 50-327 50-327	9 6 7 7	WAREMBOURG, D.	8307050106 8307120087 8307140157 8307190010 8307060244	50-267 50-267 50-267	8 0 5 p	WESTERMAN, T. F. WESTERMAN, T. F. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J.	8307210202* 8307270141* 8307060376 8307060376 8307070255	50-445 q 50-267 q 50-358 0 50-358 0 50-352 0
VERRELLI, D. M.	8307140278 8307140381 8307210197 8307220130	50-250 50-250 50-400 50-395 50-400	F Q Q	WAREMBOURG, D. W. WARNER, D. L.	8307040254 8307190105* 8307250398 8307260494 8307150375	50-267 50-267	ე () 1	WETTERHAHN; M. J. WETTERHAHN; M. J. WETTERHAHN; M. J. WETTERHAHN; M. J. WETTERHAHN; M. J.	8307070255 8307130232 8307130232 8307210230 8307210230	50-352 0 50-352 0 50-352 0 50-352 0
VERRELLI, D. M.	8307220202 8307220242 8307220481 8307220498	50-400 50-324 50-438 50-390 50-416	0 0 0	WARNICK, R. F.	8307200155 8307050006 8307060349 8307080284* 8307120574	50-327 ( 50-327 ( 50-356 (	5 R Q Q	WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J.	9307280147 8307280147 8307280149 8307280149 8307280246	50-352 0 50-352 0 50-352 0 50-352 0
VERRELLI.D.M. VESTOVICH.J.A VIETTI.A. VIETTI.A. VIETTI.A.	8307220534 » 8307150202 » 8307190390 8307200530	50~348 16PREP 50~508 50~443	Q A A	WARNICK, R. F.	8307120580* 8307140032 8307140038* 8307140341*	50-329 ( 50-329 ( 50-329 (	G G G G	WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WHAN, Q. A. WHICHER, J. M.	8307280246 8307280254* 8307280254* 8307250310 8307050003	50-352 0 50-352 0 50-352 0 50-252 R 50-454 0
VIETTIA. VISSING G. VIVIRITO H. A. VOGLERAB. H. VOGT, D.	8307220030 8307110037 8307190207 8307140475	50-478 50-261 REGGD 50-352 NUREG	F G	WARNICK, R. F. WARNICK, R. F. WATERHOUSE, G. A. WAYNE, L. WEAVER, J. D.	8307210038 8307280339 8307220373 8306170403 8306270596	90-358 G 50-329 A 50-443 G 50-142 Y PR	A G	WHICHER, J. M. WHICHER, J. M. WHICHER, J. M. WHICHER, J. M. WHICHER, J. M.	8307050011 8307050020* 8307050020* 8307050020* 8307050032*	50-434 Q 50-434 Q 50-454 Q 50-454 Q
VOIGT-H.H. VOIGT,H.H. VOIGT,H.H. VOIGT,H.H.	8307140141* 8307070075 8307080302 8307080302	50-250 50-285 50-341 50-341	Q H G G	WEAVER, J. D. WEBB, B. J. WEBB, S. W. WEBB, S. W. WEBB, S. W.	8306290596 8307120026 8307190457 8307190464 8307220140*	PR NUREC NUREC NUREC WASTE MCT		WHICHER, J. M. WHICHER, J. M. WHICHER, J. M. WHICHER, J. M. WHICHER, J. M.	8307050032# 8307050032# 8307050227 8307050227 8307050227	50-454 0 50-454 0 50-454 0 50-454 0
VOLGT, H. H. VOLGT, H. H. VOLLMER, R. H. VOLMER, C. J.	8307170270 8307170273* 8307170273* 8307170273* 8305040455*	50~244 50~244 50~244 50~322 TOPREP	G G A	WEBSTER, C. C. WEEKS, E. D. WEIDENHAMER, G. WEIGAND, G. G. WEINKAM, E. J.	8307250157 8307220492 8307120105 8307110135 8307040431	NUREG 50-133 R REGGD NUREG 50-458 A		HHICHER, J. M. HHICHER, J. M. HHICHER, J. M. WHICHER, J. M. WHICHER, J. M.	8307080488 8307120578 8307120578 8307120578 8307120578	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0 50-454 0 50-454
VOLMER, C. J. VORDERBRUEGGEN VORIS, D. D. VOSBURY, F. H. VOSBURY, F. W.	8307260440* 8307120549* 8307060281* 8306140199*	TOPREP 50-528 GA999 50-286	G G	WEINKAM, E. J. WEINKAM, E. J. WEINTRAUB, A. A. WEINTRAUB, A. A. WEINTRAUB, S. A.	8307190463 8307220142 8307220641 8307280214 8307220479*	50-458 E 50-458 A 71-3828 71-9049 50-261 Q	ı	Whicher, J. M.* Whicher, J. M. Whicher, J. M. Whicher, J. M. Whicher, J. M.	8307220417 8307220417 8307220417 8307220417 8307220417	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0
VOTH, M. H. VOTH, M. H. VUMBACO, F. J. VUMBACO, F. J. HADE: P. B.	8307010013 8307010113 8307190095* 8307250354*	30-54 50-34 40~672 40-672	P F F	WEISS, D. WEISS, D. WEISS, E. R. WEISS, E. R. WEISS, E. R.	8307110326* 8307110300 8307250362	70-135 70-371 50-289 G 50-289 G 50-289 G		WHICHER, J. M. WHICHER, J. M. WHICHER, J. M. WHICHER, J. M. WHITE, O. S.	8307260288 8307260425 8307260425 8307260425 8307250657	50-454 0 50-454 0 50-454 0 50-454 0 50-412 0
HAGNER, A. G. WAGNER, C. W. WAGNER, D. WAGNER, M. E.	8307050181* 8307220516* 8307210242 8307250032	50-416 50-416 50-255 50-354	а е н А	WEISS, E. R. WEISS, E. R. WEISS, E. R. WEISS, E. R. WELLS, C. E.	8307270135 8307270135 8307270135	50-289 Q 50-289 Q 50-289 Q 50-289 Q 50-346 F		WHITE, Q. S. WHITE, Q. S. WHITE, J. R. WHITEWAY, B. J. WHITMAN, Q. D.	8307050063* 8307270278 8307110388* 8307050074* 8307050071	50-412 0 50-412 0 50-247 0 50-387 0 NUREO
WAGNER, M. E.	8307050172 8307200097 8307220370 8307270239	50-460 ( 50-289 ( 50-289 (	0 0 0 0	WELLS, D. A. WELLS, D. A. WELLS, D. A. WELLS, R. WELLS, R.	8307060064 8307060137 8307180178	50-341 S 50-341 S 50-341 B 50-320 S 50-320 S	·	WHITMAN, J. H. WHITMEY, D. D. WHITMEY, D. D. WHITMEY, O. WHITMEY, O. WHITMEY, O.	8307250297 8307120403 8307120403 8307150245 8307010064	40-6657 50-287 P 50-287 P 50-293 8 50-293 8
WAONER, P. C. WAHL, H. W. HALKER, H. HALKER, L. I. WALKER, R. D.	8307190154 8307040093* 8307190281* 8307130322*	50-289 G 50-267 P GA999 50-443 T 50-454 A	P T A	WENDERLICH, R. L. WENDLAWSKI, F. WESCOTT, H. M. WESLEY, D. A. WESLEY, D. A.	8307060243* 8307180137* 8307180307* 8307290118*	50-318 8 50-224 9 50-483 9 50-155 P 50-329 A		WHITNEY, G. O. WHITNEY, G. O. WHITNEY, G. G. WHITNEY, G. G. WHITNEY, G. G.	8307010134 8307110476 8307110506 8307120507 8307150022	50-293 8 50-293 8 50-293 8 50-293 8 50-293 8
HALKER, R. D. HALKER, R. D. HALKER, R. F. WALLACH, Q.	8307180179# 8307250481# 8307070205	50-373 Q 50-254 Q 50-254 Q 50-412 Q 50-237 p	3 3	WESTAFER, Q. R. WESTAFER, Q. R. WESTAFER, G. R. WESTAFER, G. R. WESTAFER, G. R.	8307060319 8307070031 8307080275	50-302 P 50-302 Q 50-302 P 50-302 K 50-302 P		WHITNEY, Q. Q.	8307150127 8307150262 8307170040 8307220197 8307220206	50-293 8 50-293 8 50-293 8 50-293 8

AUTHÜR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
WHITNEY, O. G. WHITNEY, O. G. WHITNEY, O. G. WIEBE, J. WIEBE, J.	8307220331 8307220519 8307280059 8307110396* 8307130007	50-273 8 50-273 8 50-273 9 50-273 9 50-320 0 50-287 9	HILSON, S. W. WINEGURA, K. WINELAND, S. WINGO, M. D. WINGO, M. D.	8307060025* 8307120467 8307120467 8307220246 8307250487	50-528 8 70-25 70-25 50-276 S 50-276 S	WRIGHT: R. J. WRIGHT: R. J. WRIGHT: R. J. WRIGHT: R. J. WRIGHT: R. J.	8307260146 8307260159 8307260199 8307260209* 8307260231	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT
WIEDEMAN, D. G.	B307050193	70~2974	Hindgura, H.	8307120447*	70-25	URIGHTAR.J.	6307260237	WASTE MOT
WIEDEMAN, D. G.	8307050197*	70~2974	Wise, R.	8307120447*	50-382 @	WRIGHTAR.J.	6307260244	WASTE MOT
WIEDEMAN, D. G.	8307210031	70~1353	Hise, R. E.	8307120131*	50-237 P	WRIGHTAR.J.	6307260250	WASTE MOT
WIESEMAN, R. A.	B307120399*	PROJ	Wise, R. E.	8307180138*	50-237 P	WRIGHTAR.J.	6307270066	WASTE MOT
WIESEMANN, R. A.	8307080309*	TOPREP	Wittenburg, K.	8307050088	50-373 S	WRIGHTAR.J.	6307270302	WASTE MOT
Wiesemann, R. A. Wiesemann, R. A. Wiesemann, R. A. Wiggins, E. Wiggins, E.	8307080322* 8307150200* 8307280120* 8307140481 8307140508	TOPREP TOPREP PROJ CONTRACT CONTRACT	WITTENBURG, K. WITTENBURG, K. WITTENBURG, K. C. WODECK, D. J. WOJCHOUSKI, A. V.	8307050146 8307060054 8307050070 8307180392 8307060252	50-373 S 50-373 S 50-373 S 40-8714 '	WRIGHT, R. J. WRIGHT, R. J. WRIGHT, R. J. WRIGHT, R. J. WRIGHT, R. J.	8307270307 8307270309 8307270314 8307270315 8307270321	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT
WIQQINTON, D.	8307030061*	PR	WOLFE, S. J.	8307050128	50-382 G	WRIGHT, R. J.	8307270336	TOM STEAM TOM STEAM TOM STEAM TOM STEAM TOM STEAM
WIQQINTON, D.	8307230076	50-315 F	WOLFE, S. J.	8307070204	50-382 G	WRIGHT, R. J.	8307270341	
WIQQINTON, D. L.	8307130437*	50-348 P	WOLFE, S. J.	8307150299	50-338 G	WRIGHT, R. J.	8307270347	
WIQLE, Q. L.	8307210373*	71-6550	WOLFF, M.	8307120303*	50-529 S	WRIGHT, R. J.	8307270353	
WILBORN, C.	8307270141*	50-267 G	WOLLETT, S.	8307080547	CONTRACT	WRIGHT, R. J.	8307270357	
WILKOWSKI, Q. M.	8307250390	50-327 Q	WOLLETT, 8.	8307190107	CONTRACT	WRIGHT,R.J.	8307270362	WASTE MGT
WILKINBON, B. W.	8307120467	70-25	WOLLETT, 8.	8307250667	CONTRACT	WRIGHT,R.J.	8307270371	WASTE MGT
WILKINBON, B. W.	8307110220*	50-274 F	WOLLETT, 8.	8307290509	CONTRACT	WRIGHT,R.J.	8307270403	WASTE MGT
WILKOWSKI, Q. M.	8307120009	NUREG	WOLTMER, E. F.	8307140281*	70-364	WRIGHT,R.J.	8307270423	WASTE MGT
WILKOWSKI, Q. M.	8307120012	NUREG	WONG, C. H.	8307260454	50-243 F	WRIGHT,R.J.	8307270424	WASTE MGT
WILLIAMS, B. C.	8307220387*	50-395 P	WOOD, B.	8307220161	50-387 H	WRIGHT,R.J.	8307270442	WASTE MOT
WILLIAMS, C.	8307190039	50-546 S	WOOD, E. G.	8307110269	50-309 S	WRIGHT,R.J.	8307270444	WASTE MOT
WILLIAMS, C.	8307260011*	50-329 Q	WOOD, E. C.	8307110444	50-309 S	WRIGHT,R.J.	8307270446	WASTE MGT
WILLIAMS, C. C.	8307140074*	50-454 Q	WOODHEAD, C. P.	8307010121	50-142 G	WRIGHT,R.J.	8307270448	WASTE MGT
WILLIAMS, C. C.	8307140182*	50-373 Q	WOODHEAD, G. P.	8307050153	50-142 G	WRIGHT,R.W.	8307220541*	50-438 Q
WILLIAMS, C. C.	8307210154*	50-374	HOODHEAD, C. P.	8307080468	50-440 G	WRIGHT, S. V.	8307270144	27-48
WILLIAMS, C. C.	8307280156*		HOODHEAD, C. P.	8307110047	50-341 G	WU, A. K.	8307190282	XPORTLIC
WILLIAMS, C. C.	8307280395*		HOODHEAD, C. P.	8307120054	50-142 G	WULLER, Q. E.	8307110228	50-461 F
WILLIAMS, D. L.	8307060328*		HOODHEAD, C. P.	8307120057	50-142 G	WULLER, G. E.	8307120396	50-461 E
WILLIAMS, J.	8307060060		HOODHEAD, C. P.	8307120061	50-142 G	WULLER, G. E.	8307150344	50-461 V
WILLIAMS, J. WILLIAMS, J. WILLIAMS, J. WILLIAMS, J. WILLIAMS, J.	8307060297 8307060327 8307080294 8307080327 8307080335	50-358 S 50-358 B 50-358 S 50-358 S	MGODHEAD, C. P. MGODHEAD, C. P. MGODHEAD, C. P. MGODHEAD, C. P. MGODLAN, D. R.	8307130227 8307140450 8307140452 8307270134 8307150163	50-341	WULLER, G. E. WULLER, G. E. WULLER, G. E. WURTZ, W. E. YAGGEE, F. L.	8307190230 8307260154 8307280134 8307140318 8307090133	50-461 F 50-461 E 70-2947 50-289 G NUREG
WILLIAMS, J.	8307080345	50-358	HOODRUFF, E. M.	B30715017B	NUREG	YANDELLILIA.	8307120497*	50-285 G
WILLIAMS, J.	8307080428		WOODB, J. T.	B307050118	50-304 S	YANDELLILIA.	8307120523*	50-285 G
WILLIAMS, J.	8307080482		WOODB, T. O.	B307060426*	50-528 G	YANQICIH.	8307250530	NUREO
WILLIAMS, J.	8307180253		WOODWARD, K. W.	B3072203B7*	50-395 P	YANIGHKAISE.	8307190257*	50-213 P
WILLIAMS, J.	8307210002		WOODWARD, K. W.	B307220413*	50-395 P	YARGERIK.	8307050015	50-344 S
Williamb, J.	8307210040	50-358 9	WOOLEVER	8307180279	50-412 K	YIN, I. T.	8307080014*	50-454 Q
Williamb, J.	8307210044*	50-358 0	WOOLEVER, E. J.	8307110292*	50-412 G	YIN, I. T.	8307140080*	50-483 Q
Williamb, J.	8307210096	50-358 8	WOOLEVER, E. J.	8307150275	50-412 E	YDUNG, F.	8307280260	WASTE MOT
Williamb, J.	8307210109	50-358 A	WOOLEVER, E. J.	8307180201	50-412 G	YDUNG, G. T.	8307140483*	CONTRACT
Williamb, J.	8307210116	50-358 9	WOOLEVER, E. J.	8307220287	50-412 B	YDUNG, M. A.	8307050143	50-244 G
Williams, J.	8307210186	50-358 8	HOOLEVER, E. J.	8307280360	50-412 C	YOUNG: M. A.	8307050172	50-460 G
Williams, J.	8307260550	50-358 8	HOOLEVER, E. J.	8307280367	50-412 A	YOUNG: M. A.	8307110051	50-454 G
Williams, J.	8307260556	50-358 8	HOOLEVER, E. J.	8307290100	50-412 C	YOUNG: M. A.	8307120066	50-454 G
Williams, J. W.	8307110245	50-387 8	HOOLEVER, E. J.	8307290103	50-412 K	YOUNG: M. A.	8307120072	50-454 G
Williams, J. W.	8307110402	50-387 8	HORKMAN, E.	8307140399*	State Prog	YOUNG: M. A.	8307130233	50-494 G
WILLIAMS, J. W. WILLIAMS, J. W. WILLIAMS, J. W. WILLIAMS, J. W. WILLIAMS, J. W.	9307120134 9307120166 9307120172 9307120177 9307120424	50-389 8 50-335 8 50-389 8 50-389 8 50-251 9	HORKMAN, E. H. HRAY, J. R. HRAY, J. R. HRAY, J. R. HRAY, R.	8307140380* 8307140053* 8307140411* 8307220220* 8307280297*	State Prog 50-259	YOUNG, M. A. YOUNG, M. A. YOUNG, M. A. YOUNG, M. A. YOUNG, M. A.	8307130280 8307140433 8307150302 8307190004 8307200109	50-454 G 50-454 G 50-454 G 50-244 G 50-454 G
WILLIAMS, J. W.	8307120428	50-389 S	HRIGHT, G. C.	8307180129*	50-155 G	YOUNG, T.	8307060055	50-312 \$
WILLIAMS, J. W.	8307150205	50-389 S	HRIGHT, N. A.	8307070020	50-327 G	YOUNG, T.	8307060416*	50-528 Q
WILLIAMS, J. W.	8307150266	50-250 S	HRIGHT, N. A.	8307080462	50-327 G	YOUNG, T.	8307120519*	50-312 Q
WILLIAMS, J. W.	8307150268	50-389 S	HRIGHT, N. A.	8307200104	50-327 G	YOUNG, T.	8307120549*	50-528 Q
WILLIAMS, J. W.	8307220329	50-250 R	HRIGHT, R.	8307220633	Waste Mot	YOUNG, T.	8307120564*	50-528 Q
Williams, J. W.	8307220427	50-389 8	HRIGHT: R.	8307260120	WASTE MOT	YOUNG, T.	8307120569*	50-528 Q
Williams, J. W.	8307220478	50-250 8	HRIGHT: R. J.	8307220010	YOM STRAW	YOUNG, T.	8307120570*	50-528 Q
Williams, J. W.	8307220535	50-389 B	WRIGHT: R. J.	8307220036	TOM STRAW	YOUNG, T.	8307280306	50-528 S
Williams, J. W.	8307250182	50-389 8	WRIGHT: R. J.	8307220041	TOM STRAW	YOUNGBLOOD, B. J.	8307050351	50-445 F
Williams, J. W.	8307250209	50-389 8	HRIGHT: R. J.	8307220051	TOM STRAW	YOUNGBLOOD, B. J.	8307110076	50-483 E
WILLIAMS, R. E.	8307250502	40-8829	HRIGHT, R. J.	8307220122	WASTE MOT	YOUNGBLOOD, B. J.	8307130050	50-483 E
WILBON, B. D.	8307180333	XPORTLIC	WRIGHT, R. J.	8307220127	WASTE MOT		8307130057	50-445 F
WILBON, B. D.	8307210246	XPORTLIC	WRIGHT, R. J.	8307220136	WASTE MOT		8307130294	50-445 A
WILBON, B. D.	8307210379	XPORTLIC	WRIGHT, R. J.	8307220137	WASTE MOT		8307130300	50-358 A
WILBON, C. L.	8307120026	NUREG	WRIGHT, R. J.	8307220168	WASTE MOT		8307130312	50-482 A
WILSON; C. L.	8307180143	NUREQ	WRIGHT, R. J.	8307220177	WASTE MOT	YOUNGBLOOD, B. J.	8307130316	50-445 F
WILSON; G.	8307040333	50-373 8	WRIGHT, R. J.	9307220189	WASTE MOT		8307140125	50-358 A
WILSON; J.	8307110479*	50-280 F	WRIGHT, R. J.	8307220191	WASTE MOT		8307140518	50-482 E
WILSON; J. L.	8307120225	50-280 8	WRIGHT, R. J.	8307220194	WASTE MOT		8307140519	50-423 A
WILSON; J. L.	8307120535	50-281 S	WRIGHT, R. J.	8307220198	WASTE MOT		8307140522	50-423 A
WILSON, J. L. WILSON, J. L. WILSON, J. L. WILSON, L. B. WILSON, R.	8307250467 8307250485 8307290173 8307060191 8307210281	50-280 S 50-281 S 50-280 S 50-261 Q 50-400 Q	WRIGHT, R. J. WRIGHT, R. J. WRIGHT, R. J. WRIGHT, R. J. WRIGHT, R. J.	8307220249 8307220579 8307250034 8307260025 8307260109	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	YOUNGBLOOD: B. J.	8307150156 8307200504 8307250059 8307290042 8307290047	50-423 D 50-445 V 50-445 F 50-456 C 50-454 A

#### PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJEC	
JNGBLOOD, B. J.	8307290430	50-454 A	ZIMMERMAN, J. V.	8307110535	XPORTLIC	ZIMMERMAN, S. R.	8307260363	50-400	··-·
UNGLING, E. J.	8307120601*	50-322 G	ZIMMERMAN, J. V.	8307110541	XPORTLIC	ZIMMERMAN, B. R.	8307270435	50-324	F
UNOLING, E. J.	8307200222	50-322 G	ZIMMERMAN, J. V.	0307110544	XPORTLIC	ZIMMERMAN, S. R.	8307280355		
NDT.C.P.	B307120287	50-344 B	ZIMHERMAN, J. V.	8307110545	XPORTLIC	ZIMMERMAN, B. R.		50-400	K
NDT.C.P.	8307180149	50-344 R	ZIMMERMAN, J. V.	8307110550	XPORTLIC	ZIMMERMAN, S. R.	9307280364 9307280411	50-261 50-261	P
BLQCKI, C. J.	8307190059*	COMMISSION	TTHUPPHUAN ( I)						
NOTELLI, W A.	8307210255		ZIMMERMAN, J. V.	8307130062	XPORTLIC	ZIMMERMAN, S. R.	8307290090	50-324	P
FF, D. W.		NUREG	ZIMMERMAN, J. V.	8307130064	XPORTLIC	ZIMMERMAN, S. R.	8307290169	50-261	Q
	8307010064*	70-1201	ZIMMERMAN, J. V.	8307180001	XPORTLIC	ZUDANG, Z.	8307190327	50-335	0
GARTH. J.	8307130322*	50-454 A	ZIMMERMAN, J. V.	8307180004	XPORTLIC	ZUDANG, Z.	B307190327	50-335	O
IGLER: J. Y.	#E160E14GE8	50~454 A	ZIMMERHAN, J. V.	8307180292	XPORTLIC	ZUDANS, Z.	8307170345	ACRS	-
OULSKY, H.	8307140281 a	70-364	ZIMMERMAN, J. V.	8307190033	XPORTL1C	ZUDANS, Z.	8307190345	ACRS	
1Α, Q. E.	8307150178	NUREG	ZIMMERMAN, J. V.	8307190036	XPORTLIC	ZUDANS, Z.	8307200022		0
MERMAN, J.	8307070546	XPORYL1C	ZIMMERMAN, J. V.	8307190439	XPORTLIC	ZUDANS, Z.	8307200022	50-373	Ď
MMERMAN, J.	B307130341	XPORTLIC	ZIMMERMAN, J. V.	8307200254	XPORTLIC	ZUDANS, Z.	0307200475	ACRS	U
MERMAN, J.	8307130342	XPORTLIC	ZIMMERMAN, J. V.	8307200294	XPORTLIC	ZUDANS, Z.	8307200475	ACRS	
AMERICAN (	00000.0000.0							nune	
MERMAN, J.	8307130344	XPORTL1C	ZIMMERMAN, J. V.	9307200319	XPORTLIC	ZUKOR, D.	8307290257	50~275	8
1MERMAN, J.	8307180305	XPORTLIC	ZIMMERMAN, J. V.	B307210270	XPORTLIC	ZUKOR, D.	8307270268*	50-275	8
MMERMAN, J.	8307180338	XPORTLIC	ZIMMERMAN, J. V.	8307210317	XPORTLIC	ZUKOR, D.	8307270272	50-304	ä
MERMAN, J. V.	8307050521	XPORTLIC	ZIMMERMANI J. V.	8307210320	XPORTLIC	ZUKOR, D.	8307270280*	50-304	8
MERMAN, J. V.	8307050523	XPORTLIC	ZIMMERMAN, J. V.	8307210359	XPORTLIC	ZUKOR: D.	8307290298	50-280	5
MERHAN, J. V.	8307050525	XPORTLIC	ZIMHERMAN, J. V.	8307210366	XPORTLIC .	ZUKOR, D.	8307290307*	50-280	8
IMERMAN, J. V.	8307070220	XPORTLIC	ZIMMERMAN, J. V.	8307220638	XPORTL IC	ZUKOR, D.	8307270377*	50-315	
HMERMAN, J. V.	8307070224	XPORTLIC	ZIMMERHAN, J. V.	8307220640	XPORTLIC	ZUKOR, D.	8307270414	50~280	8
MERMAN, J. V.	8307070371	XPORTLIC	ZIMMERMAN, J. V.	8307220642	XPORTLIC	ZUKOR, D.	8307270414		•
MERMAN, J. V.	8307070377	XPORTLIC	ZIMMERMAN, J. V.	8307250071	XPORTLIC	ZUKOR, D. J.	8307270434*	50-280 50-315	8
MERMAN, J. V.	8307070379	XPORTLIC	ZIMMERMAN, J. V.	8307250089	XPORTLIC	ZUPKO, J. M.	555757-4		
IMERMAN, J. V.	8307070381	XPORTLIC	ZIMMERMAN, J. V.				8307090025	50-311	5
MERMAN, J. V.	8307070387	XPORTLIC	ZIMMERMAN, J. V.	8307250097	XPORTLIC	ZUPKO: J. M.	930705003P	50-272	S
MERMAN, J. V.	8307070388	XPORTLIC	ZIMMERMAN, J. V.	8307250102	XPORTL IC	ZUPKO, J. M.	8307050043	50-272	8
MERMAN, J. V.	8307070389	XPORTLIC		8307270073	XPORTLIC	ZUPKO, J. M.	8307120238	50-311	8
		AFORTEIG	ZIMMERMAN, J. V.	8307270093 ·	XPORTLIC	ZUPKO, J. M.	B307120243	50-311	8
IMERMAN, J. V.	8307070392	XPORTL10	ZIMMERMAN, R. P.	B307140403*	50~244 G	ZUPKO, J. M.	B307120450	50~272	8
IMERMAN, J. V.	8307070394	XPORTLIC	ZIMMERMAN, S. R.	B307060075	50-201 F	ZUPKO, J. M.	8307140142	50-272	š
IMERMAN, J. V.	8307070403	XPORTLIC	ZIMMERMAN, S. R.	8307060171	50-261 G	ZUPKO, J. M.	8307140176	50-311	s
IMERMAN, J. V.	8307070407	XPORTLIC	ZIMMERMAN, S. R.	8307070128	50-324 P	ZUPKO, J. M.	8307140293	50~311	
IMERMAN, J. V.	8307070414	XPORTLIC	ZIMMERMAN, S. R.	8307070172	50-261 G	ZUPKO, J. M.	8307150072	50-272	8 R
MERHAN, J. V.	8307070418	XPORTLIC	ZIMMERMAN, 8. R.	8307110058	50-261 P	ZUPKO: J. M.	0007450465		_
MERHAN, J. V.	8307070421	XPORTLIC	ZIMMERMAN, S. R.	8307110578*	50-324 F	ZUPKO: U. FI.	8307150105	50-311	R
MERMAN, J. V.	8307070424	XPORTLIC	ZIMMERMAN, S. R.	8307140063		ZUPKO: J. M.	8307170123	50-311	8
MERMAN, J. Y.	8307070429	XPORTLIC	ZIMMERMAN, B. R.	8307140063	50-261 P	ZUPKO, J. M.	8307210003	50~311	6
MERMAN, J. V.	830707045B	XPORTLIC	ZIMMERMAN, B. R.	8307220322	50-400 K 50-261 P	ZUPKO, J. M.	8307210009	50-311	В
				030/820322	50-261 P	ZUPKO, J. M.	8307210112	11E-08	8
MERMAN, J. V. MERMAN, J. V.	8307070462 8307070465	XPORTLIC	ZIMMERMAN, S. R.	8307220578	50-261 P	ZUPKO, J. M.	8307210134	50-311	8
MERHAN, J. V.	8307070525	XPORTLIC	Z IMMERMAN, S. R.	8307250290	50-261 G	ZUPKO, J. M.	6307220343	50-272	8
MERMAN, J. V.		XPORTLIC	ZIMMERMAN, S. R.	8307230295	50-324 P	ZUPKQ, J. M.	8307220345	50-311	6
MERMAN, J. V.	8307070530	XPORTLIC	ZIMMERMAN, S. R.	B307250504*	90-261 F	ZUPKO, J. M.	8307220558	50-311	ŝ
PENIMAN Q. V.	8307110512	XPORTLIC	ZIMMERMAN, S. R.	8307250510*	50~261 F	ZUPKO, J. M.	8307280358	50-311	Š
i						ZUPKO: J. M.	8307280427	50-311	8
i						ZURAKOWEKI, P. R.	8307260482*	70-1007	**
						ZWIEG, A.	8307290043		8
i •									-

ot category column in this index gives the docket nd the symbol for the category of information t docket; for example, 50-320 P. The docket subject are defined in Appendix A.

ategories for nondocketed items are also entered umn by symbol; for example, ACRS. These catedefined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATIGN	ACCESSION NUMBER	SUBJECT CATEGOR	
	8305100326	50-289			#11E05270EB	50-348	s
	8307050071	50-289	ă		B307220315*	50-349	8
	6307060208	50-289	ō		#02E02270EB	50-34B	8
	8307140441	50-289	Ö		9307220323 <b>*</b>	50-348	8
	8307050328×	CONTRAC	Τ	•	8307220338	50-348	8
Co.	83070402B9*	9A999			8307220530*	50-348	Q
Development Co.	0307130205	50-335	P		8307220530*	50-346	ā
mingy, Inc.	8307280079#	50-346	P		8307250699*	50-348	F
n. Inc.	8307170331	40-8331	_	Alden Besses Laterates	8307290170	50-348	S
t. of	8307150435*	CONTRAC	Т	Alden Research Laboratory	#4040854068	GEN TEC	15
30.	9305100008	50-348	5 6	American Nuclear Society	8307270033* 8307070108	GEN TEC PR	IS
	8305100010* 8307010132	50-348 50-364	P B	West from Marians antitată	8307070117#	PR	
	8307010132	50-364 50-348	P	Amesbury, MA	8307070194	50-443	Q.
	8307010182	30-34B	P	thur and die in .	8307070174	50-443	Ğ
			•				-
	8307010187*	50-34B	P		8307080429	50-443	н
	8307010187#	50-348	P	4 <b>4 4</b>	8307080429	50-443	Н
	8307070080	50-34B	P	Anefco, Inc.	9307150431	71-9071	G
	8307070104	50-348	P	Applied Risk Technology Corp. Argonne National Laboratory	830729010B* 8307080592	50-247 NUREO	G
	8307070104	50-348	P	vedouus meriniai rappiatoi	8307080342	NURED	
	0307080272	50-348	P		9307080602	NUREO	
	8307080272	50-348	P		8307090133	NUREO	
	8307080308	50-348	þ		8307120047	RES	
	8307080308	50-348	P		8307130094	50-470	A
	8307080402	50-348	К		8307200030	ACRS	
	8307080405#	50-349	К		8307200342	ACRS	
	8307080479	50-348	<u>P</u>	Arizona Public Service Co.	8307200347	ACRS 50-527	s
	8307080479	50-348	P	Artiona Public Service Co.	B305130239 B307050026	50-528	Ä
	8307120284 8307120483	50-348 50-348	5 P		R307050026	50~528	Ä
					8307050026	50-528	Α
	8307120483 8307120576	50-348 50-348	P B		8307050133	50-528	Ä
	8307120574	50-348	8		8307050133	50-528	Ä
	8307120570#	50-348	8		8307050133	50-528	Ä
	8307120594*	50-348	ä		B307050199	50-528	A
	8307130262	50-348	p		B307050199	50-528	A
	9307130262	50-348	P		8307050199	50-528	Α
	8307140427	50-34B	à		8307050211	50-528	E
	8307150095	50-34B	P		8307050211	50-526	E
	8307150097	50-348	P		8307050211	50-528	E
	8307150097	50-348	Р		8307060012	50-52B	Ą
	8307150099#	50-348	P		8307060012	50-528	٨
	8307150099*	50-346	P		8307060013	50-528	S
	8307150103	50-348	В		8307060046	50-528	8
	0307150106*	50-348	В	•	8307060323	50-528	8
	8307150109*	50-348	8		8307 <b>0</b> 60368 8307 <b>0</b> 60368	50~528 50~528	E
	8307180095	50-348	R		8307060368	50-52B	Ē
	8307180095	50-349	R		8307040379	50-528	S
	8307180319*	50-348	F		8307060377	50-528	5
	8307190108	50-340	R				
	8307190113	50-364	R		8307060379	50-528	8
	8307190144	50~364	P		8307060426*	50-526	Œ
	8307200106	50-364	₽		8307110012	50-528 50-528	E
	8307200110*	50-364	P		8307110012 8307110012	50~528 50~528	£
•	8307220303	50-348	8		930/110015	20228	-

AUTHOR AFFIL IATION	ND1883D3A R3EMUN	SUBJECT CATEGOR	ŶΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8307120195 8307120296 8307120366 8307120366 8307120366	50-529 50-529 50-529 50-528 50-528	6 8 8 8	Atom Sciences, Inc. Atomic Industrial Forum Auduban Society Automatic Switch Co.	8307180328* 8307250416 8307250406* 8307210035 8307150119	CONTRACT PR 50-400 50-546 50-247	
	8307120529 8307120530 8307140374 8307150363 8307180221	50-530 50-528 50-528 50-528 50-528	8 8 8	Automation Industries, Inc. Babcock & Wilcox Co.	8307270290 8307010051* 8307010064* 8307110515 8307120246*	71-9006 TOPREP 70-1201 70-135 50-346	P
	8307180221 8307180221 8307190190 8307190190 8307190190	50-528 50-528 50-528 50-528 50-528	8 F F F		8307130273 8307140143 8307140259 8307150112* 8307150244	TOPREP 70-135 PT21 70-364 50-269	P
	8307190194# 8307190194# 8307190194# 8307190223 8307190223	50-528 50-528 50-528 50-528 50-528	F F K K		8307190013 8307190139* 8307250451 8307250454* 8307250473*	70-824 50-269 XPORTLIC XPORTLIC CONTRACT	
	8307190223 8307190227 8307190227 8307190232* 8307190232*	50-528 50-527 50-529 50-529 50-529	K G G	Babcock & Wilcox Operating Plants Owners Group		XPORTLIC XPORTLIC 70-824 TOPREP	
	8307200117 8307260291 8307260291 8307260291 8307260313	50-528 50-528 50-528 50-528 50-528	F Q Q B	Baltimore Gas & Electric Co.	8307120403 8305250564* 8307010076 8307010083 8307010087	50-317 50-317 50-317 50-318	P
Arizona, State of Arkansas Power & Light Co.	8307280348 8307280413 8307290183 8307050383 8305270018	50-528 50-530 50-528 State Pri 50-313	P		8307010124 8307010142 8307010160 8307060292 8307070180	50-317 50-317 50-317 50-317	8 9 8 G F
	8307050072 8307050072 8307050078 8307050079* 8307050079*	50-313 50-313 50-368 50-313 50-313	P B P		8307070180 8307110127 8307110427 8307110443 8307110456 8307120043*	50-318 50-317 50-317 50-317	F P 8 8 8 F
	8307040051 8307040250 8307080413 8307120191 8307120269	50-313 50-368 50-313 50-368 50-313	P F 9 \$ #		8307120083* 8307120144 8307120264 8307120479	50-317 50-317 50-317 50-317	F 8 R
	8307120304 8307150271 8307150383 8307180079 8307180079	50-313 50-313	P 8 F F		8307120559 8307120559 8307150110* 8307180187 8307180193	50-317 50-317 50-317 50-318	G G G G G
	8307190065 8307190098 8307190101* 8307190155 8307190181	50-368 50-368 50-313	የ የ የ የ		8307180245 8307200135 8307200149 8307210013	50-917 50-917 50-917 50-917	8 8 R K
	8307210159 8307210159 8307210299 8307220278 8307220305	50-313 50-313 50-313 50-368	P P P R R		8307210017* 8307210017* 8307210017* 8307210178 8307210285	50-317 ( 50-317 ( 50-317 ( 50-317 (	K K P 8
	8307220310 8307220310 8307220314* 8307220314* 8307220517*	50-313 50-313 50-313 50-313	P P P Q		8307210287 8307220509 8307230091 8307280199 8307280199	50-318 5 71-9111 50-317 5	8 \$ P
	8307220360 8307250482 8307250482 8307250486* 8307260075	50-313   50-313   50-313   50-368	8 K K	Battelle Memorial Instituta Battelle Memorial Institute, Columbus	8307280352# 8307280352# 8307280430 8307280430 8307270240#	50-317 ( 50-317 F 50-317 F WASTE MOT	G P P
*:	8307240094 8307240180 8307240322 8307260544 8307260554	50-313 50-368 50-368	Q R S F S	Laboratories	8307050326 8307050327* 8307120009 8307120012	71-5957 71-5957 NUREQ NUREQ	
Army, Dept. of	7905150698* 8307200240* 8307200310 8307210075* 8307210113*	FOIA CONTRACT 50-352 I FOIA FOIA	D	Battelle Memorial Institute, Pacific Northwest Laboratory	8307150365 8305260240 8307080576 8307090109	NUREO	P P
Army, Dept. of, Corps of Engineers Army, Dept. of, Headquarters Material	8307210118* 8307220054* 8307200157* 8307220144	FOIA FOIA CONTRACT WASTE MOT			8307110560 8307120018 8307120026	WABTE MOT RES NUREQ NUREQ	
Development & Readiness Command	8307150137	NUREC			8307150147 8307150178	NUREO NUREO	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8307180139 8307180143 8307180165	NUREG NUREG NUREG	Brown & Root Carp. (subs. of Halliburton	8307260016 8307260022 8307220394	WASTE MOT WASTE MOT 50-498 A
	8307260531* 8307270360	50-298 G Nureg	Corp. ) Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.)	830711037 <b>7*</b>	50-373 8
Bear Creek Uranium Co.	8307180394	40-8452 50-424 K	50.7 200.7	8307110377*	50-373 \$
Bechtel Corp.	8307010213* 8307040023* 8307040093* 8307070072*	97799 97979 9 12E-08	Burns & Ros Co.	8307110381* 8307130358 8307150358 8307150362*	50-373 S RES 50-397 S 50-397 S
	8307070112 8307110244 8307120303* 8307120377* 8307130281*	PR 50-482 S 50-529 S 50-528 S 50-275 P	Burstein, C. H.	B307180145 B307180145 B307180153* B307180160* B307290052	TOPREP 50-382 9 50-382 9 50-382 0 50-382 9
	8307130286* 8307130302* 8307150276 8307190258* 8307190258*	50-275 P 50-275 P PR 50-329 T 50-329 T	Businessmen for the Public Interest	8307290036* 8307290067* 8307050003 8307050003 8307050011	50-382
Heers & Dickson Bendix Corp.	8307190260* 8307190260* 8307210261* 8307250546 8307110726*	50-329 T 50-329 T 50-329 G FOIA 40-1341	CLOW Corp.	8307050011 8307080488 8307120578 8307120333*	50-454
Bellutt Surp.	8307110727*	40-1341	CONOCO:Inc. (Continental Dil Co.) Cahill, Gordon & Reindel	8307130043 8307050530*	40-8743 REVIEW GRP
Berlin, Roisman, Kessler & Cashdan	8307190076 8307190076 8307190081* 8307190081*	50-529 Q 50-529 Q 50-529 Q 50-529 Q	California, State of	8307080344 8307260113* 8307050075 8307050241 8307060397	M18C M18C 50-275 G 50-275 G 50-275 G
	8307260367 8307260403 8307260403	50-529		8307060397	50-275 0
	8307260407* 8307260407*	50-527 G 50-527 G		8307060405* 8307060405*	50-275 0 50-275 0
Boeing Computer Services, Inc. (subs. of		CONTRACT		8307060415* 8307060415*	50-275 G 50-275 G
Boston Edison Co.	8307150422* 8306280580* 8307010066 8307010082	CONTRACT 50-445 I 50-273 B 50-273 G		8307130072 8307130072 8307130074* 8307130074* 8307150357	50-275
	8307010134 8307050252 8307060037* 8307060048* 8307110356	50-293 5 50-293 0 50-293 0 50-293 0 50-293 P		8307150357 8307150361* 8307150361* 8307200122 8307250131*	50-275 0 50-275 0 50-275 0 50-275 0 CONTRACT
	8307110476 8307110504 8307120229 8307120351 8307120423	50-273 6 50-273 8 50-273 F 50-273 P 50-273 8	California: Univ. of, Berkeley California: Univ. of: Irvine	8307040411* 8307200352 8307250081 8307010168 8307010171	50-400 0 ACRS ACRS 50-326 R 50-326 S
	8307120507 8307120518 8307130080 8307130082* 8307150022	50-293 8 50-293 8 50-293 P 50-293 P 50-293 S	California, Univ. of, Los Angeles	8307210237 8307060412 8307060417* 8307060419* 8307110133	50-326 8 50-142 0 50-142 0 50-142 0 50-142 0
	8307150048 8307150070* 8307150123 8307150127 8307150245	50-273 F 50-273 P 50-273 P 50-273 S 50-273 S	Capital City Coach Carolina Environmental Study Group Carolina Power & Light Co.	8307110138* 8307190337* 8307190239 8307010053	50-142 0 CONTRACT 50-413 0 50-400 E 50-400 E
	8307150262 8307190016 8307190040 8307210140* 8307220197	50-293 8 50-293 P 50-293 R 50-293 G 50-293 R		8307050117 8307060075 8307060095 8307060095 8307060111	PR 50-201 F 50-400 E 50-400 E
	8307220206 8307220331 8307220376 8307220430 8307220519	50-293 8 50-293 8 50-293 P 50-293 8 50-293 8		8307060111 8307060114 8307060114 8307060121 8307060121	50-400 E 50-400 E 50-400 K 50-400 K
	8307220551 8307260166 8307260172* 8307260402 8307260571	50-273 B 50-273 K 50-273 K 50-273 F 50-273 F		8307060127* 8307060127* 8307060144 8307060144 8307060163	50-400 K 50-400 K 50-400 E 50-400 E 50-400 E
Brand-Rex Co.	8307280059 8307280399 8307280404* 8307150111 8307210122	50-293 8 50-293 R 50-293 R 50-312 S 50-312 B		8307060163 8307060173 8307060173 8307060191 8307060198	50-400 E 50-400 G 50-400 G 50-261 G 50-400 G
Brattleboro, VT Bronstein, D.S. Brookhaven National Laboratory	8307290366* 8307260395 8307150149 8307250530	CONTRACT 50-352 G NUREG NUREG		B307060198 B307060207 B307060212*	50-400 0 50-261 0 50-261 0

AUTHOR AFFILTATION	ACCESSION RUMBER	SUBJ CATE	GDRY	AUTHOR AFFILIATION	ACCE861DN NUMBER	SUBJE	
	8307040234 8307040234 8307040302 8307040302 8307070022	50-40 50-40 50-40 50-40 50-40	0 E		8307150380 8307150380 8307190005 8307190042 8307190283	50-400 50-400 50-400 50-324 50-400	9 8 9 8
	8307070022 8307070025 8307070025 9307070071 8307070071	50-40 50-40 50-40 50-40 50-40	9 9		8307190283 8307200150 8307210146 8307210171 8307210171	50-400 50-325 50-400 50-400 50-400	) G
	8307070083 8307070083 8307070085 8307070085 8307070092	50-400 50-400 50-400 50-400 50-400	) D D E D E		8307210203 8307220002* 8307220143* 8307220145 8307220145		Q Q
	8307070092 8307070125 8307070125 8307070128 8307070172	50-400 50-400 50-400 50-324 50-261	) E   P		8307220148* 8307220298* 9307220298* 9307220322 8307220336*	50-400 50-324 50-241 50-261 50-400	G G P
	8307070175* 8307080315 8307080315 8307080390 8307080390	50-261 50-400 50-400 50-400 50-400	) E		8307220352 8307220353 8307220405 8307220458* 8307220566*	50-261 50-261 50-325 50-261 50-324	9 8 0
	8307110058 8307110294 8307110338 8307110338 8307110432	50-261 50-261 50-400 50-400 50-324	9 9		8307220566* 8307220578 8307250120 8307250197 8307250211*	50~324 50~261 50~261 50~324 50~324	G P K K
	8307110440 8307110510 8307110578* 8307110586* 8307110586*	50-400 50-325 50-324 50-324	8 F		8307250290 8307250337 8307250337 8307250346 8307250346	50-261 50-400 50-400 50-400 50-400	9000
	8307110589* 8307110589* 8307120129 8307120207 8307120207	50-324 50-324 50-324 50-400 50-400	F 8 9 8		8307250350* 8307250350* 8307250375 8307250399 8307250404	50-400 50-400 50-261 50-400 50-400	0 0 8 8
	8307120291 8307120314 8307120337 8307120338* 8307120395	50-325 50-400 50-261 50-261 50-400	8 Q Q		8307250504* 8307250510* 8307260084 8307260084 8307260360	50-261 50-261 50-324 50-324 50-400	F F F 0
	8307120395 8307130059 8307130212 8307130212 8307130231	50-400 50-261 50-324 50-324 50-400	8 R R R		8307260360 8307260363 8307260363 8307260397 8307260404	50-400 50-400 50-400 50-325 50-324	O R R B
	8307130231 8307130241* 8307130241* 8307130244 8307130244	50-400 50-400 50-400 50-400 50-400	@ @ @		8307260460 8307260460 8307260485 8307260493 8307260496	50-324 50-324 50-400 50-261 50-324	Y # 8
	8307130253* 8307130253* 8307130261* 8307140063 8307140267	50-400 50-400 50-400 50-261 50-400	0 0 P K		9307260498 8307260504* 8307270057 8307270057 8307270060*	50-324 50-324 50-400 50-400 50-400	P K K K
	8307140267 8307140314 8307140323 8307140323 8307140435	50-400 50-261 50-400 50-400 50-400	E E C	*	8307270060* 8307270340 8307270340 8307270435 8307270435	50-400 50-400 50-400 50-324 50-324	K E E F
	8307140435 8307140437 8307140437 8307140440 8307140440	50-400 50-400 50-400 50-400 50-400	0		8307280143 8307280163 8307280185 8307280355 8307280355	50-400 50-400 50-400 50-400 50-400	9 9 K K
	8307140443 8307140443 8307140445* 8307140445* 8307140454	50-400 50-400 50-400 50-400 50-400	0 0 0		8307280361 8307280361 8307280364 8307280411 8307290090	50-400 50-400 50-261 50-261 50-324	E E P P
	8307140454 8307140458 8307140458 8307150024 8307150102	50-400 50-400 50-400 50-324 50-325	0 0 0 8		8307290106 8307290132 8307290169 8307290174 8307290179	50-261 50-324 50-261 50-261 50-261	8 8
	8307150201 8307150201 8307150225 8307150225 8307150242	50-400 50-400 50-400 50-400 50-324	9 F F 8	Center for Law in the Public Interest  Chapel Hill Anti-Nuclear Group Effort	8307050242 8307060437 8307120571 8307260253 8307070076	50-275 50-275 50-275 50-275 50-275	00000

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Chem-Nuclear Systems: Inc.	8307080404 8307080407*	71-9096 71-9096	- <b>-</b> -	Coalition for Nuclear Power Plant Postponement	6307050117	PR	
	8307150442 8307180310 8307190027	71-5026 27-47 71-6601		Coalition for Safe Power	8307070189 8307200124 8307200131* 8307200134*	PR 50~460 50~460 50~460	0
	8307190266 8307200364 8307200365* 8307280125 8307290381	71-9111 71-9111 71-9111 71-6601 71-231		Colorado State Univ. Colorado: State of Colt Industries. Inc.	8307200138* 8307260298 8307250643* 8307250153* 8307150249*	50-460 50-460 CONTRACT CONTRACT GAPPP	G O
Chemtron Corp. Gincinnati Gas & Electric Co.	8307280227 8307060060 8307060297 8307060327 8307060396	40-6724 50-358 50-358 50-358 50-358	5 9 9	Combustion Engineering, Inc.	8307010172 8307010184* 8307150286* 8307200525 8307250416	50-470 50-470 GA999 70-36 PR	Å
	8307080294 8307080327 8307080335 8307080345 8307080428	50-358 50-358 50-358 50-358 50-358	8 9 9	Commerce, Dept. of, National Bureau of Standards	8307270352 8307270422 8307270425* 8307200170*	50-470 TOPREP TOPREP CONTRACT	E
	8307080482 8307180 <b>25</b> 3	50-358 50-358	S A		*44550727056	CONTRACT	
	8307190199 8307210002 8307210040	50-358 50-358 50-358	8 8	Committee to Bridge the Gap	8306170403 8307060363 8307060367* 8307120555	50-142 50-142 50-142 50-142	T Q Q
	8307210044 <del>*</del> 8307210047	50-358 50-358	Ø A	Commonwealth Edison Co.	8306230264	50-454	Á
	8307210094 8307210109 8307210114 8307210184	50-358 50-358 50-358 50-358	8 6 8		8306230264 8306230264 8306230264 8306230264 8306230264	50-454 50-454 50-454 50-454 50-454	A A A
	8307260550 8307260556	50-358 50-358	\$ 8		8307010103	50-275	A Q
Circle Seal Controls	8307070413 8307220165 8307250093	XPORTLIC XPORTLIC	; ;		8307010195 8307010195 8307010195 8307010195	50-237 50-237 50-237 50-237	KKK
Citizens Association for Bound Energy	8305200418 8307120323	50-445 PR	0		B307010195	50-237	к
Gleveland Electric Illuminating Co.	8307200211 8307050202 8307060065	50-445 50-440 50-440	G A S		8307010195 8307010196* 8307010198* 8307010198*	50-237 50-237 50-237 50-237	K K K
	8307040238 8307040238 8307040277 8307040278	50-440 50-440 50-440 50-440	T T E E		8307010198* 8307010201* 8307010201* 8307050020*	50-237 50-237 50-237 50-454	K K G
	8307060298 8307060339 8307060339 8307060344* 8307060344*	50-440 50-440 50-440 50-440 50-440	E G G G		8307050032* 8307050032* 8307050033* 8307050064 8307050070	50-454 50-454 50-373 50-304 50-373	0 0000
	8307080451# 8307110134	50-440 50-440	0 8		8307050088	50-373	8
	8307110134 8307110316 8307110316	50-440 50-440 50-440	s 8 6		8307050117 8307050118 8307050144 8307050155 8307050210	PR 50-304 50-373 50-304 50-373	8 6 8
	8307110382 8307110382 8307150316	50-440 50-440	8 0		8307050210	50-373	R
	8307180031 8307190038 8307190038	50-440 50-440 50-440	5 6 8		8307050215* 8307050218* 8307050220* 8307050223*	50-373 50-373 50-373 50-373	R R R
	8307190084 8307190084	50-440 50-440	0		8307050225*	50-373	R
	8307190104* 8307190104*	50-440 50-440	0		8307050229* 8307050233*	50-373 50-373	R
	8307190136 8307190136	50-440 50-440	5 6		8307050235* 8307050239*	50-373 50-373	R
	8307170136 8307170174 8307170174 8307170203	50-440 50-440 50-440	s s c		8307050282 8307060044 8307060054 8307060186	70-2973 50-254 50-373 50-237	0 8 F
	8307170203 8307170204	50-440 50-440	e S		8307060186	50-237	F
	8307190204 8307190208* 8307190208*	50-440 50-440 50-440	8 0 0		8307040237 8307040333 8307040342 8307040355	50-237 50-373 50-373 50-454	5 8 6
	8307200289 8307210077 8307210077	50-440 50-440 50-440	S K K		8307070129 8307070176	PR 50-237	P
	8307210081* 8307210081*	50-440 50-440	K K		8307070176 8307070176 8307070207	50-237 50-237 50-454	P P G
	8307220231 8307220234 8307220434	50-237 50-254 50-440	8 8 8		8307080233 8307080243	50-295 50-237	8
Cleveland-Cliffs Iron Co.	8307220434 8307220434 8307180392	50-440 40-8714	9		9307080334* 9307080338*	50-374 50-374	ā

458

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE				UTHOR LIATION	ACCESSION NUMBER	CATEGO	
	8307080496 8307110096 8307110061 8307110114 8307110115	50-237 50-456 50-254 50-373 50-237	8 9				8307210188 8307210188 8307210211 8307210211 8307210217*	50-456 50-456 50-454 50-454 50-454	A 0 0
	8307110146* 8307110187 8307110357 8307110371 8307110371	50-454 50-237 50-237 50-373 50-373	8 8				8307210217* 8307210236 8307210236 8307210300 8307210300	50-454 50-454 50-454 50-400 50-400	9 9 8 4
	B307110408 B307110409 B307110416 B307110419* B307110423	50-373 50-249 50-373 50-373 50-304	9 G				8307220193 8307220200 8307220201 8307220234 8307220258	50-373 50-373 50-373 50-254 50-265	9 R 8 8
	8307110434* 8307110488 8307110531 8307120064* 8307120068*	50-373 50-373 50-254 50-304 50-254	Ω				8307220260 8307220306 8307220309* 8307220348 8307220348	50-249 50-249 50-249 50-454 50-454	В Р С С
	8307120281 8307120281 8307120382 8307120382	50-454 50-454 50-454 50-373 50-373	A A A				9307220375 9307220476* 9307220486 9307220495 9307220495	50-373 50-237 50-374 50-237 50-237	P G 8 P P
	8307120391 8307120431 8307120435 8307120438* 8307120524	50-295 50-373 50-265 50-265 50-374	р Р Р				8307220495 8307220542 8307250304 8307250365 8307250365	50-237 50-373 50-237 50-454 50-454	P 8 P 0 0
	8307130219 8307130309 8307130309 8307130317* 8307130317*	50-254 50-454 50-454 50-454 50-454	R A A A				8307250432 8307250432 8307250432 8307250435# 8307250435#	50-454 50-454 50-454 50-373 50-373	8 8 9 0
	8307130322* 8307130322* 8307130322* 8307130322*	50-454 50-454 50-454 50-454 50-454	A A A A				8307250448 8307250448 8307250452 8307250498 8307260018	50-237 50-237 50-237 50-254 50-237	4 8 8 8
	8307150194 8307180023* 8307180063* 8307180063* 8307180099	50-237 50-373 50-373 50-373 50-454	R Q Q S				8307260018 8307260018 8307260018 8307260020 8307260213	50-237 50-237 50-237 50-237 50-237	F F F P
	8307180191 8307180198 8307190062 8307190062 8307190062	50-373 50-295 50-237 50-237 50-237	8 P P				8307260301 8307260310 8307260310 8307260314 8307260314	50-374 50-454 50-454 50-373 50-373	A O O E E
	8307190111 8307190122 8307190126 8307190147* 8307190178	50-454 50-454 50-454 50-454 50-237	G G G P				8307260430 8307270454* 8307280102* 8307280102* 8307280102*	50-10 50-454 50-10 50-10 50-10	) 0 0
	8307190180* 8307190183* 8307190187 8307190187 8307190187	50-237 50-237 50-237 50-237 50-237	ት ት				8307280102* 8307280102* 8307280102* 8307280102* 8307280375	50-10 50-10 50-10 50-10 50-295	9 9 9 9
	8307190187 8307190187 8307190189* 8307190192* 8307190195*	50-237 50-237 50-237 50-237 50-237	9 9 9				8307280457* 8307270102 8307270102 8307270105* 8307270105*	50-10 50-454 50-454 50-454 50-454	0000
	8307190201* 8307200121 8307200121 8307200125* 8307200168	50-237 50-456 50-456 50-456 50-237	P C C S	c	omputer Systems Sup onnecticut Yankee A	oport Corp. Atomic Power Co.	8307270279* 8307270277* 8307170435* 8307010067 8307050148	50-275 50-275 CONTRACT 50-213 50-213	F F # 8
	8307200174 8307200183 8307200191 8307200199 8307200213	50-237 50-295 50-237 50-295 50-295	5 5 5 6				8307120262 8307140400 8307190131 8307190253 8307220367	50-213 50-213 50-213 50-213 50-213	R Q P P R
	8307200216* 8307200218 8307200287 8307200302 8307210001	50-237 50-249 50-295 50-237 50-373	0 9 8	c	onnar & Watterhahn		8307280326# 8307060396 8307060409 8307070255 8307130232	50-213 50-358 50-352 50-352 50-352	0000
	830721004B 8307210050 8307210052* 8307210045 8307210148	50-373 50-265 50-265 50-373 50-373	8 P 8				8307190191 8307190199 8307210230 8307280147 8307280147	50-410 50-358 50-352 50-352 50-352	00000

## **DOCKETED ITEMS**

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEODS	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	-
	8307280169 8307280246 8307280246 8307280254* 8307280254*	50-352 50-352 50-352 50-352 50-352	© © © ©		8307190252 8307190252 8307190258* 8307190258* 8307190240*	50-329 50-329 50-329	T T T T
Consolidated Edison Co. of New York, Inc.	8307010156 8307050152 8307050162* 8307050169* 8307060084	50-247 50-247 50-247 50-247 50-249	8 P P		8307190240* 8307200073 8307200079 8307200251 8307210032	50-155 50-329 50-255	T P A Q
	8307040295 8307040305 8307040331 8307070120 8307120235*	50-247 50-247 50-373 PR 50-247	G G S		8307210144* 8307210144* 8307210208 8307210208 8307210210*	50-329 50-329 50-329	A A A A
	8307120563 8307120567* 8307150061 8307180060 8307180060	50-247 50-247 50-247 50-247 50-247	9 9 9 9		8307210210* 8307210259 8307210259 8307210261* 8307210261*	50-329 50-329 50-329	A C G G
	8307180151 8307220203 8307220275 8307220280 8307220365	50-247 50-247 50-247 50-247 50-247	9 9 5 8 R		8307210266* 8307210266* 8307220174 8307220186 8307220217	50-329 50-155 50-155	G ወ P F R
Construction Technology Laboratories	8307220427 8307220555 8307250302* 8307210246* 8307210271*	50-247 50-247 50-247 50-329 50-329	н я к о о		8307220351 8307220351 8307220402 8307220402 8307250123	50-329 50-329 50-329	τ τ Α Α
Consumers Power Ca.	8307050076 8307050105 8307050117 8307050140 8307060011	50-155 50-155 PR 50-255 50-329	9 9 9		8307250295 8307250324 8307250431 8307250431 8307250236	50-155 50-329 50-329	P G S S €
	8307060011 8307060057 8307060057 8307060059 8307060059	50-329 50-329 50-329 50-329 50-329	S A A E E		8307240236 8307260293 8307260320 8307260320 8307260344	REGGD 50~329 50~329	E A Q
	8307040041 8307040041 8307040158 8307040354* 8307070152	50-329 50-329 50-255 50-329 50-329	E F O E		8307260451 8307260451 8307280023 8307280191 8307280191	50-329 71-5805 50-329	0 0 9 9
	8307070152 8307080321* 8307080436 8307080436 8307080443	50-329 50-255 50-329 50-329 50-155	E P S S S		8307280272 8307280272 8307280434 8307280434 8307280113	50-329 50-329 50-329	5 A A A
	8307080481 8307080508 8307080514 8307080514 8307110150	50-255 50-329 50-329 50-329 50-329	S A R R G		8307290113 8307290191 8307290191 8307290196* 8307290196*	50-329 50-329 50-329	A A A A
	8307110150 8307110154*	50-329 50-329	g 0	Continuum Dynamics, Inc. Controls for Environmental Pollution,	8307190074* 8307190015*	50-237 70-820	P
	8307110154* 8307110249 8307110405	50-329 50-155 50-329	G G A	Inc. Coordination Council for North American Affairs	8307190280 8307190282	DILTROGK DILTROGK	
	8307120040* 8307120044*	50-255 50-255	F F	Creare, Inc.	8307280080	GEN TEC I	ទេ
	8307120050* 8307120245 8307120245	50-255 50-329 50-329	F A A	Cygna Energy Services Dairyland Power Cooperative	8307270513* 8307120637* 8307080518 8307110127 8307110563*	CONTRACT 50-445 50-409 50-409 50-409	A Q B F
	8307120248* 8307120373 8307120485 8307120571	50-329 50-329 50-155 50-155	A E P G		8307120624* 8307200264 8307210253* 8307220222 8307220225	50-409 50-409 50-409 50-409 50-409	F 9 0 R
	B307140211 B307140256 B307150124 B307150195 B307150195	50-329 50-329 50-255 50-329 50-329	A A R G	Dallas Power & Light Co. Dames & Moore Data Consultants, Inc.	8307220564 8304280600* 8307080484* 8307150376* 8307200388*	50-409 50-445 40-6264 CONTRACT CONTRACT	ľ
	8307180171 8307180171 8307180171 8307180270	PR 50~327 50~327 50~327	5 5 8	Davis: Polk & Wardwell DeKalb Area Alliance for Responsible	8307140318 8307050020*	50-289 50-454	G G
	6307180270 8307180302	50-329 50-155	8 P	Energy	8307050032* 8307050227 8307120578	50-454 50-454 50-454	G
	8307180311* 8307180404* 8307190012 8307190205	50-155 50-155 50-255 50-255	F 5 8		8307220417 8307260258	50-454 50-454	G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATIO		ACCESSION NUMBER	BUBJI	
Debevoise & Liberman	9307260288 8307260288 8307260425 8307260425 8305100420	50-454 50-454 50-454 50-454	G G G G	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		8307130198 8307130198 8307130202 8307130202 8307130206	50-41; 50-41; 50-41; * 50-41;	3 9
	8307050117 8307070140 8307080437 8307110236 8307120585	50~508 50~445	G G			8307130206 8307130224 8307130224 8307130249 8307130263	* 50-413	9 Q
Del-Aware Unlimited, Inc.	8307140464 8307190228 8307210269 8307250354 8307290110	50-445 50-413 50-445 50-445	G G O G T			830714004B 8307140048 8307140067 8307140140 8307140140	50-269 50-269 50-269 50-413 50-413	. b
Delaware River Basin Commission Delaware, State of Detroit Edison Co	8307220364 8307260502 8307140127* 8307010173* 8307010175*	50-352   50-272   50-341   50-341	д Н К К			8307140305# 8307140310# 8307150108 8307150212 8307150234	50-349 50-349 50-349 50-349	G 8
	8307050107 8307060016 8307060064 8307060137 8307060362	50-341 5 50-341 5 50-341 6 50-341 F	F			8307150253 8307150259 8307150305 8307150340 8307150391	50-369 50-370 50-370 50-369 71-669	8
	8307120237 8307120278 8307120282* 8307190023	50-341 6 50-341 6 50-341 6 50-341 6 70-2926	A E			8307180076 8307190085 8307190085 8307190135 8307190137#	50-369 50-413 50-413 50-269 50-269	<b>年</b> 医
Ditta. S. J.	8307210028 8307240455 8307270207 8307270215#	70-2926 50-341 A 50-16 R 50-341 A 50-341 A	t N			8307190184 8307190184 8307190188* 8307190188* 8307190218	50-369 50-369 50-369 50-369 50-413	R R R E
Daherty, J.F. Domus Design Studios, Inc. Dan L. Warner, Inc. Darsey, J.A.	8307279082 8307190458* 8307150375 8307110420	ACRS 50-537 H CONTRACT 70-820 PR				8307190267 8307190309# 8307210269 8307210269 8307210272#	50-269 50-369 50-413 50-413 50-413	P R O G
	8307290088 8307290088 8307290093* 8307290093*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0				8307210272* 8307210274* 8307210274* 8307220007 8307220007	50-413 50-413 50-413 50-413 50-413	0 0 0
Dow Chemical Co. Dravo Corp. Dresser Industries, Inc. Dressel Univ.	8307290099* 8307270234* 8307260228* 8307060109*	50-332 G 50-352 G WASTE MOT GA999 GA999				8307220221 8307220287 8307220269 8307220272 8307220409	50-370 50-370 50-414 50-270 50-369	8 8 8
Dute Pawer Co.	8305270627* 8307010015 8307050250 8307050250	50-249 Q 50-413 F 50-413 Q 50-413 Q				8307220470 8307220470 8307220499 8307220504 8307220504	50-413 50-413 50-370 50-413 50-413	0 8 0
	8307060275 8307060275 8307070087 8307070087	50-269 K				8307220511 8307250087# 8307250092# 8307250110# 8307250117	50-287 50-369 50-369 50-269 50-269	6 6 6
	8307070196 8307070196 8307080362 8307110053	50-413 G 50-413 G 50-267 P 50-413 A				9307250117 9307250117 8307250202 9307250300 8307250372	50-269 50-269 50-369 50-269 50-413	P
	8307110226 8307110291 8307110291 8307110383	00-269 P 00-413 Q 00-413 G 00-413 E				8307250372 8307250441 8307250455 8307250455 8307250425*	50-413 50-287 50-413 50-413 50-413	E P E E F
	8307120115 5 8307120200 5 8307120289 5 8307120349 5	0-270 8 0-369 8 0-370 8 0-267 8 0-413 6				8307250425* 8307250439* 8307250730* 8307250744* 8307260304	50-413 50-259 50-269 50-269 50-269	F F F
	8307120371 5: 8307120371 5: 8307120398 5: 8307120427 5:	0-413 S 0-413 S 0-413 S 0-413 S 0-414 S				8307240384 8307240390 8307240412 8307240412 8307240412	50-370 50-370 50-269 50-269 50-269	68 88 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
	8307120597 50 8307120604 50 8307120609 50	0-369 8 0-369 9 0-287 8 0-269 8 0-269 8			4	8307260417* 8307260426 8307260462 8307260495 8307260526	50-249 50-413 50-369 50-369 50-369	P 8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8307260526 8307260535 8307260558 8307260558 8307260567*	50-349 50-369 50-369	- P S S S	Ederer, Inc. Edlow International Co.	8307050198 8307050205* 8307050205* 8307050205* 8307210138 8307070450	50-400 G 50-400 G 50-400 G TOPREP XPORTLIC
	8307240569* 8307280409 8307280415* 8307280421* 8307280429*	50-349 50-369 50-369	8 P P P	Elcen Metal Products Co. Electric Pawer Research Institute Energy Consultants, Inc. Energy, Dept of	8307220444 8307080609* 8307180212* 8307180222* 8306240429	50-10 S NURE9 50-322 R 50-322 R 71-4495
t∉ Light Co.	8307290033 8307290054 8307290544* 8307010136 8307070115	50~269 50~369 50~334	8 5 F 8 P		8307050414 8307060485 8307060489* 8307070127 8307070133	WASTE MOT WASTE MOT WASTE MOT PR PR
	8307070119* 8307110292* 8307110412 8307110446 8307120475*	50-334 50-412 50-334 50-334 50-334	P a s s		8307070248 8307070106 8307110161 8307110164* 8307110168*	PR WASTE MOT WASTE MOT 50-537 T 50-537 T
	8307150118 8307150275 8307150287 8307150343 8307150350	50-334 50-412 50-412 50-412 50-412	P S C Q		8307110723 8307130375 8307180331 8307180375 8307190030	40-1341 Wabte Mgt Waste Mgt Waste Mgt 71-3552
	8307180118 8307180170 8307180201 8307180206# 8307180225	50-334 50-334 50-412 50-412 50-412	P S C C C G		8307190032* 8307200304 8307200495 8307210367 8307210365	71-5552 XPORTLIC 50-201 P 71-4550 XPORTLIC
	8307180279 8307190284 8307200115 8307220277 8307220287	50-412 50-412 50-334 50-334 50-412	K C F S		8307220117* 8307220173 8307220212 8307220223 8307220227	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT
	8307220207 8307220443 8307220443 8307250025* 8307270192 8307270197*	50-334 50-334 50-334 50-334 50-334	R S S P		8307220230 8307220232 8307220236 8307220244 8307220249*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT
	6307280244 8307280248* 8307280277 8307280282*	50-334 50-334 50-334 50-334 50-334	Р Р Р К		8307220253 8307220255 8307220641 8307250363 8307270133	WASTE MOT WASTE MOT 71-5828 50-537 0 WASTE MOT
	8307280298 8307280303* 8307280340 8307280347 8307290100 8307290103	50-334 50-412 50-412 50-412 50-412	K C A C K		8307270142 8307270148 8307270152 8307270159 8307270166	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
/Ware & Associates, Inc.  U Pont de Nemours & Co., Inc.  [anufacturing Pesbles, Inc.	8307290182 8307250630* 8307090034 8307090038* 8307260158*	50-334 CONTRACT 71-500 71-500 GA999	R		8307270184 8307270194 8307270204 8307270208 8307270214	WASTE MOT WASTE MOT WASTE MOT WASTE MOT
Inc.	8307260169* 8306240037* 8307180382 8307210265 8307250080	GA999 50-373 XPORTLIC NUREG NUREG	p		8307270218 8307270223 8307270248 8307270253 8307270257	WASTE MOT WASTE MOT WASTE MOT WASTE MOT
Inc. Services, Inc. (subs. of Enserch )	8307190112* 8307070136 8307140286	CONTRACT PR TOPREP			8307270262 8307270265 8307270270 8307270274 8307270284	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
()	8307190165* 8307220078 8307220419* 8307270385 8307060159	50-335 FOIA 50-382 REGGD 50-400	P A Q		8307270291 8307280029 8307280034 8307280214	WASTE MGT 40-6500 71-9156 71-9049
nan, W.	8307060137 8307060383 8307060383 8307060386* 8307060386* 8307060371*	50-400 50-400 50-400 50-400 50-400 50-400	0 0 0		8307280214 8307280218 8307290273 8307290331 8307290349* 8307290341	WASTE MGT 71-5552 71-6272 WASTE MGT WASTE MGT 71-6400
	8307040391* 8307060402 8307060402 8307150188	50-400 50-400 50-400 50-400	6 0 0	Energy, Dept. of Ciinch River Breeder Reactor Plant	8307290367* 8307290870* 8307290374* 8307070086	71-6400 71-6400 71-6400 50-537 A
•	8307260248 8307260281	50-400 50-400	G G	Manage and I seems	8307070102	50-537 A
bein & Payne	8307260341 8307050195 8307050195 8307050198	50-400 50-400 50-400 50-400	0 0 0	Engineers International, Inc.	8307070105* 8307120345 8307070506* 8307250550*	50-537 A 50-537 A CONTRACT CONTRACT

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUD JE C
Environmental Coalition on Nuclear Powe Environmental Policy Institute Environmental Protection Agency	8307270412 8307270418	* WASTE MOT 50-412 G PR			50-335 50-335 50-230 50-230 50-339
Epler, E.P. Ertec, Inc. European Communities, Commission of	8307290020 8307220018 8307140483 8307070372 8307110549	40-2061 ACRS CONTRACT XPORTLIC XPGRTLIC		8307220332* 8307220389* 8307220392* 8307220427 8307220427	20-38-2 20-33-2 20-33-2 20-33-2 20-38-2 20-38-2
Extel Corp./Warner Associates,[nc.	9307110561 8307190116 8307200294 8307250646 8307050285	XPORTLIC XPORTLIC XPORTLIC XPORTLIC GCONTRACT		8307220503 8307220508 8307220514* 8307220518	50-335 50-335 50-335 50-25
Exton Corp.  Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	8307200167 8307010157+	40~8054 50-282 P		8307220523* 8307220535	50-38 <b>-</b>
	8307050009 8307070520 8307150348	TGPREP XPORTLIC TOPREP		8307250173 8307250182 8307250209 8307260353	20-38-5 20-38-5 20-38-5 20-32-0
	8307190445 8307190449* 8307200513 8307260437 8307260440*	70-1257 TOPREP		8307260505 8307270351 8307270351 8307280051 8307280078	50-33등 50-33등 50-33등 50-38등 50-250
FOI Services Federal American Partners	9306090382 9307050035	FOIA Pr		8307280237 8307280314	50-33 <b>5</b>
Federal Emergency Management Agency	8307150452 830624043 <b>5</b> * 8307060384*	40-4492 50-445 F 50-312 F	Florida Power Corp.	8307280316* 8307060227 8307060319	50-30⊉ 50-30₽
	8307130217 8307140424* 8307150167 8307190173 8307190177*	50-482 0 50-335 F 50-155 F 50-387 F 50-387 F		8307070031 8307070033# 8307080275 8307110447 8307120249	20-305 20-305 20-305 20-305
Florida Power & Light Co.	8307190237 8307190248 8307010078 8307050016 8307050126	50-482		8307120370 8307120495 8307120552 8307150088 8307150333	50-30⊋ 50-30⊋ 50-30⊋
	8307060070 8307060070 8307060209 8307060213* 8307060216	50~250 P 50~250 P 50~250 P 50~250 P 50~250 P	·	8307210209 8307220254 8307250129 8307250185 8307250471	50-30≥ 50-30≥ 50-30≥ 50-30≥
	8307060216 8307060223 8307060253 8307060265	50-250 P 50-335 P 50-335 P 50-389 P	Franklin Institute/Franklin Research Center	8307250483 8307270184 8306060275*	50-302 50-302 50-254
	8307070077 8307070084	50-335 Р 50-250 Р		8306140199*	50-237 50-28&
	8307110153 B307110241 8307110245 B307110361*	50-251 P 50-389 E 50-389 8 50-250 F		8306140436* 8307070470* 8307070582* 8307120149* 8307170327	50-344 CONTRAC T 50-266 50-331 50-335
	8307110368* 8307110402 8307120134 8307120166 8307120172	50-250 F 50-387 S 50-387 S 50-335 S 50-367 S	Friends of the Earth Futura Coatings, Inc.	8307190345 8307200022 8307200475 8307130077 8307280165	ACR8 50-373 ACR8 50-247 40-803.5
	8307120177 8307120410 8307120424 8307120428 8307120469	50-389 B 50-389 P 50-251 S 50-389 S 50-250 P	GA Technologies, Inc./General Atomic Co.		XPORTLIC XPORTLIC XPORTLIC 50-89 71-5787
	8307140198 8307140217 8307140282# 8307140398* 8307140401#	50-250 P 50-335 Q 50-389 Q 50-335 Q 50-335 Q	Gage-Babcock Associates, Inc. Gall, W.R.	8307210389 8307220014 8307220031# 8307200198#	XPORTLIC XPORTLIC XPORTLIC CONTRACT ACRS
	8307150205 8307150214 8307150214 8307150221* 8307150221*	50-389 8 50-250 P 50-250 P 50-250 P 50-250 P	Galloway & Greenberg Garrett Corg. General Electric Co.	8307220126 8307060281* 8307010180 8307010188	50-537 GA999 50-447 TOPREP TOPREP
	9307150231 9307150266 9307150268 9307190132 9307190132	50-389 P 50-250 S 50-389 S 50-250 P 50-250 P		B307070048 8307110470 8307120446# B307140299#	70-1113 50-447 50-265 50-277 50-352
	8307190133* 8307190133* 8307190134* 8307190134*	50-250 P 50-250 P 50-250 P 50-250 P		8307150179 8307150445 8307180333	PR 71-907 <b>9</b> XPORTLI <b>C</b> PR

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AVTHOR AFFILIATION		ACCESSION NUMBER	SUBJECT CATEGOR	łΥ
	6307200105* 6307200205* 6307210246 6307210379 8307250377	XPORTLIC XPORTLIC	k b			8307270031 8307270031 8307270316 8307270318* 8307280357	50-289 50-289 50-289 50-289 50-320	F K K P
	8307250382* 8307250397 8307250397 8307240279* 8307270440* 8307280004	TOPREP 50-259	K P	Georgia Institute of Techn Georgia Power Co.	nalogy	8307280443* 8307280447 8307290038* 8305230439 8305230444*	50-219 50-320 CONTRACT 50-366 50-366	0 0 5 9
Oeneral Electric Uranium Management Corp. General Physics Corp. General Public Utilities - OPU Service	8307290131 8307290355 8307280038 8307280081* 8307010056*	71-4 70-1308 50-322	F G			8307010166 8307010166 8307010174* 8307010183* 8307010183*	50-424 50-424 50-424 50-424 50-424	К К А К
Corp.	8307010059 8307010117 8307010143 8307050145 8307050154*	50-320 50-219 50-289	5 G P P			8307010189* 8307010189* 8307010191* 8307010191* 8307010194*	50-424 50-424 50-424 50-424 50-424	К К К К
	8307050161* 8307060008 8307060139 8307070149 8307080008	50-289 50-219 50-219 50-320	P P P P			B307010194* B307010197* B307010197* B307010204* B307010204*	50-424 50-424 50-424 50-424 50-424	K K K K
	8307080010 8307080225 8307080424 8307080426* 8307110436	50-320 50-219 50-219	P R F S			8307010205* 8307010205* 8307010207* 8307010207* 8307010210*	50~424 50~424 50~424 50~424 50~424	к к к к
	8307110441 8307110448 8307110599* 8307120004 8307120052*	50-320 50-289 50-320	8 8 F P			8307010210* 8307010214* 8307010214* 8307010215* 8307010215*	50-424 50-424 50-424 50-424 50-424	К К К К
	8307120073* 8307120227* 8307120342 8307120347* 8307120352*	50-287 50-320 50-320	F Q P P			8307010216* 8307010216* 8307010217* B307010217* B307010221*	50-424 50-424 50-424 50-424 50-424	К К К К
	8307150159 8307150323 8307150329 8307180098 8307180166	50-320 50-289 50-289 50-289 50-320	Р Р С F			B307010221* B307010222* B307010223* B307010223*	50-424 50-424 50-424 50-424 50-424	K K K K
	8307180178 8307180332* 8307190017 8307190119 8307190148	50-320 50-320 71-6771 50-320 50-287	8 F P P			8307010225* 8307010225* 8307010226* 8307010227*	50-424 50-424 50-424 50-424 50-424	K K K K
	8307170147 8307170226 8307170231* 8307170234* 8307170235		F P P P			8307010227* 8307010228* 8307010228* 8307010230* 8307010230*	50-424 50-424 50-424 50-424 50-424	KKKK
	8307190238* 8307200006 8307200007* 8307200164 8307210049	50-320	р Р Р Р			8307010231* 8307010233* 8307010233* 8307010233*	50-424 50-424 50-424 50-424 50-424	K K K K
	8307210169 8307210196 8307210282 8307220182 8307220188	50-219 50-219 50-320 50-289 50-219	Q 5 6 R R			8307010234* 8307010235* 8307010235* 8307010237* 8307010237*	50-424 50-424 50-424 50-424 90-424	***
	8307220374 8307220485 8307220527 8307220537 8307220550	50-287 50-287 50-320 50-320 50-320	P P S S	•	·	8307010238* 8307010239* 8307010239* 8307010241* 8307010241*	50~424 50~424 50~424 50~424 50~424	K K K K
	8307220556 8307220565 8307250231 8307250331 8307250336*	50-320 50-320 50-219 50-320 50-320	8 8 F P			8307010242* 8307010242* 8307010244* 8307010244* 8307060270	50-424 50-424 50-424 50-424 50-321	К Ж К Р
	8307250454 8307260176 8307260202 8307260208* 8307260211*	50-320 50-289 50-219 50-219 50-219	Р Р Р Р			8307060270 8307060352* 8307060352* 8307070069 8307110176*	50-321 50-321 50-321 50-321 50-321	P G P F
	8307260432 8307260474 8307260477* 8307260509	50-219 50-320 50-320 50-289	P P P			8307110453 8307120014 8307120098 6307120357 8307120358	50-424 50-321 50-366 50-366 50-424	8 2 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	CATE	JECT EGORY	AUTHOR Affiliation	ACCESSION		
	6307120412 5307120412 8307120513 8307120513 8307120579	50-42 50-42 50-42 50-42 50-32	24 A 24 A 24 A 24 A 21 S		NUMBER 8307190175 8307190265 8307250284 8307250447 8307250446	9 30-45 3 30-45 3 30-45 3 50-45	18 S 18 K 18 S
	8307120586 8307140058 8307140243 8307140243 8307140472	90-32	54 0 21 0 21 9 21 0	HMM Associates, Inc. Hampton, NH	8307240003 8307240056 8307260414 8307210200 8307170225	50-456 50-456 50-456	8 8 8 8 8 5 3 T
	9307150064 9307150071 9307150094 9307150120	50-36 50-36 50-36 50-36	66 S 66 S	Hanford Engineering Davelopment Laboratory	8307170225 8307170247 8307170247 8307140478	* 50-443 * 50-443	3 0
	8307150121 8307150385 8307180101 8307180251* 8307190006	50-32 50-36 50-36 50-32 50-32	6 S 6 P 1 F	Harding-Lawson Associates Harmon & Weiss	8307200212: 8307070189 8307070214 8307200208 8307250368*	PR 50-443 50-443	3 G
	8307220195 8307220195 8307220324 8307220324 8307220501	50-424 50-424 50-424 50-321	4 8 4 8 4 8 1 F		8307260337 8307260355 8307260355 8307260538 8307260538 8307260538	50-289 50-443 50-443 50-443 50-443 50-289	
	8307250166 8307250191 8307250214 8307250269 8307250293 8307250343	50-366 50-321 50-326 50-366 50-321 50-366	1	Hartsville Group  Health & Human Services, Dept. of.	9307050231 8307050236* 9307150346 9307250176* 8307250258*	50-261 50-261 50-261 50-289	0 0 0 P
	8307250348 8307270035 8307270038* 8307290523*	50-364 50-321 50-321 50-321	S K K K	House of Rep. House of Rep., Energy & Commerce House of Rep., Foreign Affairs House of Rep., Interior & Insular Affair Houston Lighting & Power Co.	8307270055* 8307140007* 8307190059* \$307050443* 8307060118	50-247 50-247 COMMISS 50-289 50-498	U U WO 1 E U A
Gatty/Petrotomics Co. Glbbs & Hill. Inc. (subs. of Drave Corp. Glbbsrt/Commonwealth Cos.	8307190207 8307070001	50-321 40-4659 50-445 REGOD 50-440	F 9 8		8307060118 8307060170 8307060170 8307060268 8307070134	50-498 50-498 50-498 50-498 50-498	A A B F
Godfrey & Sundahl Golder Associates Gould: Inc.	8307070001 8307070282 8307070105 8307270410* 8307270420*	50-440 50-440 40-8714 WASTE M	5 5 4 10T		8307070134 8307080476 8307080476 8307200417* 8307210008	50-498 50-498 50-498 50-464 50-498	F S A K
Covernment Accountability Project	8307130333* 8307050052 8307150175* 8307150312 8307150317*	50-454 50-356 ADVCM 50-358 50-358			8307210008 8307210010* 8307210010* 8307220292* 8307250465	50-498 50-498 50-498 50-498 50-498	8 6 K K
	8307150322 8307150324* 8307150327* 8307150331* 8307150338*	50-358 50-358 50-358 50-358 50-358	G G G	Hovis, Cockrill, Weaver & Bjur Hubacek, W.O. Hunton & Williams	B307250448 B307260349 B307260349 B30722013[ B307250250*	50-498 50-498 50-498 Waste Mg 50-498	A K K PT A
	8307220354 8307220354 8307220355* 8307220355* 8307220355*	50-454 50-454 50-454 50-454 50-327	0 0 0	TOTAL A WILLIAMS	8304150383 8307050192 8307070101 8307070192 8307080184	50-322 50-322 PR 50-322 50-322	0
Graterford Prisoners Oreenfield, MA Graundwater Alliance Gulf Nuclear, Inc.	8307280161 8307260395 8307250693# 8307050117 8307070467	50-329 50-352 CONTRACT PR 71-9162	e o		9307120381 9307120554 9307120573 9307120576* 9307120616*	50-322 50-322 50-322 50-322	00000
Gulf Oil Corp. Oulf States Utilities Co.	8307200466 8307200467* 8307150392 8307050127 8307050144	71-210 71-210 71-9163 50-458	<b>9</b> 8		8307140447 8307180213 8307210164 8307260409 8307260411	50-322	0000
	8307050204 8307050208 8307050216	50-458 50-458 50-458	s s s	Development IRT Corp.	8307270140 8307190124 8307130181	50-322 PR XPORYLIC	<b>Q</b>
	8307060017 8307060017 8307080332		5 A A S	ITT Orinnell (subs. of ITT) Illinois Power Co.	8307130182* 8307040240# 8307040020	XPDRTLIC 50-508 50-461	Ą
	8307080374 8307080415 8307150173 8307150326	50-458 50-458 50-458 50-458	8 8 8		8307040073 8307080270* 8307080331* 9307110031	50-461 50-461 50-461	A Q A Q
		50-458	S	. <b> </b>	9307110322 1307120396		e E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT Category	AUTHOR AFF IL TATTON	ACCESSION NUMBER	SUBJECT CATEGORY
<u></u>	8307150344 8307180009 8307180009 8307180036 8307180086	50-461 V 50-461 S 50-461 S 50-461 S 50-461 H		8307190152 8307200161 8307210067 8307210151 8307220281	50-331 R 50-331 G 50-331 S 50-331 S
	8307190230 8307220379 8307250367 8307260154 8307280065	30-461 F 50-461 A 50-440 A 50-461 E 50-461 R		8307250108 8307250113* 8307250215 8307250227* 8307260140	50-331 P 50-331 P 50-331 P 50-331 P 50-331 P
Illinois, State of Indiana & Michigan Electric Co.	8307280134 8307110304 8307120581 8307050019 8307050054	70-2947 40-2061 50-461 9 50-315 5 50-315 8	Iowa Geological Survey Iowa State Univ.	8307260491* 8307260497 8307260501* 8307080595* 8307010151	50-331 Q 50-331 P 50-331 P CONTRACT 50-284 R
	8307050062* 8307050068* 8307050090 8307060351 6307060372	50-315 S 50-315 S 50-315 S 50-315 P 50-315 S	Iowa, Univ. of Ishem, Lincoln & Boale	8307200 <b>5</b> 32 83070603 <b>5</b> 5 83070 <b>7</b> 0207 83071 <b>1</b> 0150 8307120591	ACR8 50-454 G 50-454 G 50-329 G 50-155 G
	8307070089 8307080007 8307110193 8307110200* 8307110209*	50-315 H 50-316 S 50-316 S 50-316 S 50-316 S		8307150195 8307180077 8307190111 8307190122 8307190122	50-327 G 50-329 G 50-454 G 50-454 G 50-454 G
	8307110290 8307110333 8307110340* 8307110347* 8307110612*	50-315 P 50-315 B 50-315 S 50-315 S 50-315 F		6307170252 8307200201 8307210211 8307210211 8307210217*	50-329 T 50-454 G 50-454 G 50-454 G 50-454 G
	8307120400 8307120400 8307120401* 8307120401* 8307120445	50-315 P 50-315 P 50-315 P 50-315 P 50-314 P		6307210236 9307210259 8307210259 8307220347 8307220347	50-454 0 50-327 0 50-327 0 50-329 0 50-329 G
	8307120607* 8307120607* 8307120610* 8307120610* 8307180104	50-315 F 50-315 F 50-315 F 50-315 F 50-316 S		8307220348 8307220349* 8307220349* 8307220351 8307220351	50-454 0 50-329 9 50-329 0 50-329 T 50-329 T
	8307180140 8307200273* 8307220008 8307220097 8307220384	50-315 S 50-315 G 50-316 R 50-315 R 50-315 S		6307250324 6307250365 6307250365 8307260310 0160627068	50-195
	8307220403 8307220410* 8307220426* 8307280341 8307280344*	50-316 8 50-316 8 50-316 8 50-315 P		8307240344 8307260413 8307260413 8307280153 8307290102	50-155 0 50-327 0 50-327 0 50-327 0 50-454 0
Indiana & Michigan Power Go. Indiana, State of Industrial Quality, Inc.	8307270162 8307270166* 8307200130 8307070037 8307200527	50-315 K 50-315 K 50-315 G 50-546 A ACRB	Isotope Products Laboratories J. Stawart Bland Consulting	8307290102 8307290105* 8307290105* 8307050533 8307210173*	50-454 C 50-454 C 50-454 G XPORTLIC 50-346 P
Informatics, Inc. Information Handling Services Inhalation Toxicology Research Institute Institute of Nuclear Power Operations Interior, Dept. of	8307180431* 8307250509* 8307110124 8307120314* 8307220185	CONTRACT CONTRACT NUREG 50-309 R WABTE MGT	JGC Corp. JRM Associates Jack R. Benjamin & Associates, Inc. Japan, Govt. of	8307220033 8307140268* 8307130291* 6307110547 8307130121	WASTE MOT 50-244 P 50-275 P XPORTLIC XPORTLIC
Interior, Dept. of, Bureau of Indian Affairs	8307270479	WASTE MOT		8307130337 8307130340 8307250648	XPORTLIC XPORTLIC XPORTLIC
Interior, Dapt. of, Fish & Wildlife Service	8307270481 8307070036	WASTE MOT 50-412 A	Joint Applicants-Clinch River Breeder Reactor	8307110149*	50-537 T
	8307070050 8307070098	50-438 A 50-438 A		8307110159* 8307110164*	50-537 T 50-537 T
Interior, Dept. of, Geological Survey	8307210172 8307240012 8307270483	50-354 G Waste Mot Waste Mot	Joint Applicants-Palo Verde	830711016B* 8307180246 8307060151 8307060156	50-537 T 50-537 G 50-529 G 50-529 G
interior, Dept. of, National Park Servic International Business Services, Inc.	8307050321*	50-546 A Contract		8307190157	50-529 0
Iowa Electric Light & Power Co.	8210190031* 8210190034* 8307010181 8307050050	50-331 F 50-331 F 50-331 K 50-331 S 50-331 S	Joint Intervenors-Diablo Canyon	8307050242 8307060437 8307060441# 8307120571	50-275 0 50-275 0 50-275 0 50-275 0
	8307030120 8307030135 8307050214 8307040123 8307040177	50-331	Joint Intervenors-Shearon Harris Joint Intervenors-Waterford	8307240253 8307240483 8307180145 8307180153* 8307180160*	50-275 G 50-400 G 50-382 G 50-382 G 50-382 G
	8307060247 8307080386* 8307180038 8307170100	50-331 P 50-331 G 50-331 G 50-331 P	Joy Manufacturing Co.	8307270052 8307270056* 8307270067* 8307130313*	50-382 0 50-382 0 50-382 0 50-454 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Justice, Dept of Kaiser Engineers Kansas Gas & Electric Co.	8307200275* 8307270230* 8307050080 8307050087 8307050113	ADVCM WASTE M 50-482 50-482 50-482		Limerick Ecology Action	8307180136 8307180136 8307180142# 8307180142# 8307290088	50-352 50-352 50-352 50-352 50-352	00000
	8307050219 8307060077 8307120476* 8307120515 8307150241	50-482 50-482 50-482 50-482 50-482	S V G S		8307290088 8307290093* 8307290093* 8307290099* 8307290099*	50-352 50-352 50-352 50-352 50-352	0000
	8307150243 8307180278* 8307190110 8307190240 8307210241	50-482 50-482 50-482 50-482 50-482	8 9 8 6	Literature Research Corp. Lodge: T.J Lone Tree Council Long Island Lighting Co.	8307250687# 8307150325 8307200214 8307050188# 8306150383	CONTRACT 50-440 50-440 50-329 50-322	7 G H G
	8307220487* 8307250315 8307250322 8307250380 8307250453	50-482 50-482 50-482 50-482 50-482	0 8 8 8		8307010004 8307010043# 8307010112 8307050031 8307050038	50-322 50-322 50-322 50-322	A A E A
Kansas, Univ. of Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp.)	8307260382 8307290178 8307290352 8307120553 8307260305	50-482 50-482 50-482 50-148 40-2061	\$ 9 0		8307050091 8307050117 8307050192 8307050256 8307050266	50-322 PR 50-322 50-322 50-322	A G E Q
Kerr-McGee Corp.  Keyboard Communications, Inc.	8307080548 8307130086 8307200209 8307200219 8307140119*	40-8027 40-8768 40-8768 40-8768 CONTRACT			8307050274 8307070015 8307070066 8307070090 8307070094	50-322 50-322 50-322 50-322	E A Q A
Keyserling, W M. Kirtpatrick, Lockhart, Hill, Christopher & Phillips	8307250535	ACRS 50-322 50-322	Λ G		8307070121 8307080184 8307080194 8307080269 8307080398	50-322 50-322 50-322 50-322 50-322	0 0 E A
	8307080209 8307110276 8307120350 8307120347# 8307140444	50~275 50~322 50~322 50~322 50~322	0 0 0		8307110358 8307120381 8307120554 8307120593 8307120596*	50-322 50-322 50-322 50-322 50-322	00000
	B307140448* B307140471 B307220357 B307260302 B307260347	50-322 50-322 50-322 50-322 50-322	0 0 0		8307120601* 8307120606* 8307120616* 8307140200 8307140335*	50-322 50-322 50-322 50-322 50-322	00000
Korea, Democratic Peoples Republic (North Korea) Kudiu Alliance	8307050195	50-322 50-322 50-423 50-400	G G		8307140356 8307140447 8307200002 8307200003* 8307200012	50-322 50-322 50-322 50-322 50-322	A Q K K A
LIXI, Inc. Lawrence Berkeley Laboratory	8307050195 8307050205* 8307050205* 8307150295 8307210373*	50-400 50-400 50-400 PR 71-4550	0 G		8307200141 8307200145* 8307200222 8307210164	50-322 50-322 50-322	EECO
Lawrence Livermore Laboratory  LeBosuf, Lamb, Leiby & MacRae	8306020348* 8307110087 8307180139 8307270319 8307010169	50-284 NUREO NUREO NUREG	P K		8307270034 8307270034 8307270140 8307280075 8307280100	50-322 50-322 50-322 50-322	A F O F A
and, and, and	8307070075 8307080302 8307080302 8307190270	50-341 50-265 50-341 50-244	6 6	Lus Alamos Scientific Laboratory	8307280300 8307150390 8307250095 8307250109	FES NUREO NUREO	8
League of Women Voters of Rockford, IL	8307050020* 8307050032* 8307050227 8307070209	50-454 50-454 50-454 50-454	6 6 0	Louisiana Power & Light Co.	8307260043 8307010017 8307010117 8307050021 8307050170	RES 50-382 50-382 50-382 50-382	E K S
	8307070209 8307110057 8307110057 8307120578 8307220417	50-454 50-454 50-454 50-454 50-454	0 0 0		8307050204 8307050406 8307060246* 8307060251	50-352 50-362 70-2946 50-382 50-382	s
	8307240258 8307240309 8307260309 8307260425	50-454 50-454 50-454 50-454	6 0 0		83070602314 8307060332 8307070045	50-382 50-382 50-382	AAK
Lehigh Univ. Leica Industries, Inc. Lewis, M.	8307260425 B307190457 B307190464 8307050536 8307150183	50-454 NUREG NUREG XPORTLIC PR	G .		8307080442 8307110055 8307120046* 8307120048*	50-362 50-362 50-362 50-362	A F F F F
Licensing Review Group	8307150235 8307190127 8307250347	NUREG 50-352 50-440	G A		8307120202 8307120516 8307120543 8307150261 8307150287	50-382 50-382 50-382 50-382	8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
	8307150339 8307150388 8307150388 8307220412 8307220419#	50-382 S 50-382 S 50-382 S 50-382 A 50-382 A		8307190220* 8307190225* 8307190225* 8307190241* 8307190241*	50-443 G 50-443 G 50-443 G 50-443 G 50-443 G
	8307260114 8307260126 8307260225 8307260229 8307260356	50-382		6307190247* 6307190247* 6307190254* 6307190254* 6307260259	50-443 G 50-443 G 50-443 G 50-443 G 50-443 G
	8307260392 8307260422 8307260470 8307260489 8307260511	50-382 S 50-382 V 50-382 E 50-382 A 50-382 E	Matthews, D E. McDermott, Inc. McGraw-Hill Publications Co.	B307260358 B307150016* B307180436* B307280055 B307080563*	50-443 G CONTRACT CONTRACT TOPREP CONTRACT
	8307240518 8307240540 8307260542 8307240548 8307280343	50-382 E 50-382 E 50-382 E 50-382 E 50-382 Q	Mechanics Research, Inc. Merrimac, MA Metropolitan Edison Co.	8307150042* 8307220373 8307050123 8307050271 8307150327	71-6679 50-443 G 50-289 G 50-289 G 50-289 G
Louisiana, State of Lovelace Biomed & Environmental Research Institute	8307270104 8307270488* 8307110124	50-382 S CONTRACT NUREG		8307190077 8307190274 8307200215 8307260264	50-289 G 50-289 G 50-289 G 50-289 G
Lowenstein, Newman, Reis, Axelrad & Toll	8307040195 8307070163	PR PR		8307280155 8307290130	50-287 G
Maine Yankee Atomic Power Co.	8307190153 8305090446 8307010006 8307060165 8307110269	50-275	Metrotec, Inc. Miami Valley Power Project	8307190313* 8307050052 8307150312 8307150317*	CONTRACT 50-358 G 50-358 G 50-358 G
	8307110299 8307110328* 8307110334* 8307110378 8307110444	90-309 B 50-309 F 50-309 F 50-309 P 50-309 S		8307150322 8307150324* 8307150327* 8307150331* 8307150338*	50~358 G 50~358 G 50~358 G 50~358 G 50~358 G
	8307110450 8307120082 8307120468 8307120496 8307120617	50-309 G 50-309 S 50-309 S 50-309 P 50-309 G	Michigan State Univ. Michigan, State of Michigan, Univ. of	8307250282 8307110220* 8307210242 8307250104* 8307180137	50-358 G 50-294 F 50-255 H CONTRACT NUREO
	8307120626* 8307150233 8307150330 8307180408* 8307180409*	50-307 G 50-307 S 50-309 G 50-309 F 50-309 F	Middle Sauth Bervices, Inc.	8307190097* 8307200257 8307220035 8307070118 8307280048	40-672 50-2 @ ACRS PR MISC
	8307170128 8307170130* 8307210006 8307220012 8307220451	50-309 P 50-309 P 50-309 S 50-309 R 50-309 S	Miranda Associates, Inc. Mississippi Power & Light Co.	8307150430* 8307010026 8307010081 8307050166* 8307060101	CGNTRACT 50-416 P 50-416 F 50-416 G 50-416 [
Mallinckrodt, Inc.	8307260476 8307280317 8307280320* 8307280436 8307260311	50~309 F 50~309 P 50~309 P 50~309 Q PR		8307040101 8307040113* 8307040113* 8307120102 8307120109	50-416 I 50-416 I 50-416 I 50-416 S 50-416 S
Hanagement Analysis Co.	8307060043* 8307140179* 8307140183* 8307270466*	50-443 A 50-423 A 50-423 A 50-272 Q 50-327 G		8307120275 8307120433 8307120452 8307120452 8307120459	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S
Mapleton Intervenors  Marsh & McLennan, Inc.	8307070198 8307070198 8307080031 8307130187 8307130840	50~327 0 50-327 J 50~250 J 50-272 J		8307120473 8307120509 8307120525 8307120526 8307120592	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S
	8307130257 8307200008 8307200099 8307200111 8307200146 8307280407	50-259 J 50-327 J 50-483 J 50-245 J 50-259 J 50-272 J		B307140230 B307150092 B307150092 B307150113 B307150144	50-416 G 50-416 S 50-416 S 50-416 S 50-416 S
Marubeni America Corp. (subs. of Maruben: Corp.) Maryland, State of Maryland, Univ. of		XPORTLIC CONTRACT CONTRACT		8307150190 8307150239 8307150239 8307150274 8307150369	REGGD 50-416 S 50-416 S 50-416 S 50-416 S
Massachusetts Institute of Technology Massachusetts Public Interest Research Group	8307280441 8307260573 8307260576*	50-20 P 50-293 G 50-293 G		8307150349 8307180113 8307180131 8307180175	50-416 B PR PR 50-416 P
Massachusetts, Commonwealth of,	8307050203 8307190212 8307190212 8307190216#	50-443		8307180247 8307190073 8307190079*	50-416 P 50-416 P 50-416 P
	8307190216* 8307190220*	50-443 G 50-443 Q		8307210177 8307210181* 8307210195	50-416 P 50-416 P 50-416 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJE CATEG	
	8307220294 8307220348 8307220482 8307220500*	50-416 50-416 50-416 50-416	8 9 0		8307180147* 8307180147* 8307180147* 8307180152* 8307180152*		, b
	8307250164 9307250193 8307250225 8307250289 8307250473	50-416 50-416 50-416 50-416 50-416	\$ 5 9 8		8307180152# 8307180158# 8307180158# 8307180158# 8307180179#	50-237 50-237 50-237 50-237 50-237	P P
Mississippi, State of Missouri, State op	8307260324 8307260464 8307290128 8307290238 8307190106	50-416 50-416 50-416 50-416 50-416	R 8 8 9	Natural Resources Defense Council	8307180179# 8307180186# 8307180186# 8307190067# 8307070101	50-237 50-237 50-237 50-237 PR	P
Mitsubishi International Corp. (subs. of Mitsubishi Corp.) Mitsubishi Corp.) Mitsui & Co. (USA), Inc. (subs. of Mitsu & Co., Ltd.)	i 8307070356 8307070417	CONTRACT XPORTLIC XPORTLIC XPORTLIC		Navy, Dept. of Nebraska Public Power District	8307120557 8307220124 8307220020 8307220024* 8304290594	50-537 50-537 71-37 71-37 PR	T A
Monsanto Co. Monsanto Research Corp.	9307130345 9307050018 9307270079* 9307270086* 9307280105 9307280466	XPORTLIC  70-572  XPORTLIC  XPORTLIC  XPORTLIC  XPORTLIC			8305270595 8307010126 8307050187 8307120244 8307120404	PR 50-298 50-298 50-298 50-298	P P P
Montana College of Mineral Science & Technology Montgomery County, MD	8307120419 8307070208 8307070208 8307070215	PR 50-170 50-170 50-170	G G		8307120404 8307120407 8307120480 8307120550 8307150213	50-278 50-278 50-278 50-278 50-278	P K P S
Morgan Associates Morgan, Lewis & Bockius	8307070215 8307250645* 8307120035 8307120565 8307110142	50-170 CONTRACT 50-247 50-247	G O T		8307180056 8307180057* 8307220184 8307260008 8307260221	50-278 50-278 50-278 50-278 50-278	P R P P
Marrison-Knudsen Co Inc.	8307180266 8307220350 8307260369 8307270300* 8307280149	50-537	6 0 0		8307260230 8307260357 8307260361 8307260410 8307260441	50-298 50-298 50-298 50-298 50-298	Р В Н В
Mound Facility/Monsanto Research Corp. NUS Corp.	8307210255 8307060359 8307060366* 830719096* 8307200519	NUREQ 71-496 71-496 50-352 FOIA	С	Neutron Products, Inc. New England Coalition on Nuclear Pollution	8307280073 8307280093* 8307290193 8307210063* 8307070214	50-298 50-298 50-298 FOIA 50-443	К К Р
·	8307220639 8307250035 8307250040* 8307250042* 8307250045* 8307250047*	71-9151 71-9151 71-9151 71-9151 71-9151			8307110461 8307150168 8307150176 8307200208 8307260337	PR PR NUREO 50-443 50-443	0 0
	8307250493 8307260599 8307260369 8307290375# 8307290461	71-9151 50-247   FOIA 71-496 71-496 FOIA	4	New Jersey, State of	8307240355 8307240355 8307240538 8307240538 8307250443*	50-443 50-443 50-443 50-443 40-86	0000
NUSAC, Inc. NUTECH Engineers, Inc.	8307200162# 8307050094# 8307060267# 8307060285# 8307060293#	CONTRACT 50-387 ( 50-331 F 50-331 F 50-331 F	•	New Mexico, Univ. of New York, State Univ. of, Stony Brook New York, State of	8307250444* 8307250310 8307180336 8307290164* 8307070110	40-84 50-252 XPORTLIC CONTRACT NURES	
	B307040304* B307040313* B307070181* 8307070181* 8307070181*	50-331 F 50-331 F 50-237 F 50-237 F 50-237 F	•	Newburyport, MA Niagara Mohawk Power Corp.	8307070114 8307080499 8307180082 8307200220 8307010033	NUREQ PR 50-322 50-443 50-220	0 0 0
	8307070184# 8307070184# 8307070184# 8307070211# 8307070211#	50-237 P 50-237 P 50-237 P 50-237 P 50-237 P	• •		8307010102 8307010154 8307070038 8307070062 8307070099	50-220 50-220 50-220 50-410 50-220	0 0 P 0 P
	8307070211* 8307070218* 8307070218* 8307070218* 8307070228*	50-237 P 50-237 P 50-237 P 50-237 P 50-237 P			8307110263 8307110365 8307120198 8307120205* 8307120294	50-220 50-220 50-220 50-220 50-220	8 8 K F
	3307070228* 3307070239* 3307070239* 3307150128*	50-237 P 50-237 P 50-237 P 50-293 P 50-237 P			8307120388 8307140309 8307140348 8307140350* 8307150014	50-220 50-220	F P P S
and the state of t	307180138*	50-237 P 50-237 P			8307150080 8307150115 8307190151 8307190191	50-220 50-410	R 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8307190243 8307190249* 8307210059 8307220150 8307220325	50-220 50-220 50-410 71-6346 50-220	R R S		B307060343 B3070603B1 B307080319 B307080353 B307080400	50-336 50-423 50-336	E A P P
	B307220407 B307250436* B307250495* B307250499* B307260155	50-410 50-220 50-220 50-220 50-220	A G F F		8307110019 8307110019 8307110281 8307110390 8307120409	50-245 50-245 50-423	F F 8 8
North Carolina State Univ. North Carolina, State of North Shore Committee Against Nuclear &	8307280389* 8307070161 8307130091 8307130213* 8307120350	50-220 50-297 50-400 50-413 50-322	G F D G		8307120432* 8307120588 8307140241 8307140271 8307150193	50-423 50~423 50-423	G S A P
Thermal Pollution  Northeast Nuclear Energy Co. (subs. of	8307120367* 8307290154 8307290159* 8306200396	50-322 50-322 50-322 50-423	0 0 0 8		8307150208 8307150240 8307180164 8307190131 8307190138	50-423 50-334 50-213	8 8 8 P 8
Northeast Utilities)	8307010010 8307010027 8307010030 8307010074	50-423 50-245 50-336 50-245	9 8 F		8307190193 8307210012 8307220042 8307220104 8307220408	50-334 50-336 50-245	\$ \$ R 8
,	8307010122 8307010133 8307010148 8307050104 8307060024	50-245 50-423 50-423 50-334 50-336	8 8 8 8		8307250469 8307260197 8307260346 8307260453 8307260522	50-423 50-245 50-245	₽ ል P P P
	8307060082 8307060136 8307060140* 8307060182 8307060183*	50-245 50-334 50-336 50-423 50-423	Р К С С С	Northern States Power Co.	8304030261 8307010104 8307010123* 8307010144 8307010144	50-263 50-282	P P P
	8307060185* 8307060289 8307060343 8307060381 8307080319	50-423 50-336 50-245 50-336 50-423	û 5 8 8 A		8307010149* 8307010149* 8307010153* 8307010153* 8307010178	50-282 50-282 50-282	P P P F
	8307080353 8307080400 8307110017 8307110019 8307110281	50-336 50-336 50-245 50-245 50-245	P P F F B		8307010178 8307010178 8307010178 8307050072 8307050072	50-263 50-263 50-282	F F P P
	8307110390 8307120409 8307120432* 8307120588 8307140271	50-423 50-245 50-245 50-423 50-423	8 9 8 A		8307030078* 8307030098* 8307030102* 8307030102* 8307060227	50-282 50-282 50-282	P P P S
	8307150193 8307150197* 8307150197* 8307150206	50-245 50-245 50-245 50-423	Р Р S		8307040252 8307070107 8307080030 8307080198 8307080204*	50-263 PR 50-263 50-282 50-282	SPKK
	8307150240 8307180164 8307190131 8307190138 8307190193	50-423 50-336 50-213 50-245 50-245	8 8 8 8		8307080343 8307150045 8307180324# 8307180327#	50-263 50-262 50-262 50-262	RRFF
	8307210012 8307210342 8307220042 8307220104 8307220408	50-336 50-336 50-336 50-245 50-336	8 8 R R		8307220441 8307220541 8307250442* 8307250642* 8307250642*	50-263 50-263 50-263 50-263	
	8307250469 8307260197 8307260346 8307260351* 8307260453	50-336 50-423 50-245 50-245 50-245	P P P		8307250642* 8307250650* 8307250650* 8307250650*	50-263 50-263 50-263 50-263	मनम
Northeast Utilities	8307260522 8306200376 8307010010 8307010027	50-245 50-423 50-423 50-245	6 6 8		8307260475 8307260475 8307260479 8307270283 8307280353*	50-263 50-263 50-263 50-282 50-263	3 3320
	8307010030 8307010074 8307010122 8307010133	50-336 50-245 50-245 50-423 50-423	8 8 8	Norton, Burke, Berry & French	8307200203 8307200203 8307200311 8307200311	50-275 50-275 50-275 50-275	0 000
	8307050104 8307060024 8307060082 8307060136	50-336 50-336 50-245 50-336	8 8 P K	Nuclear Assurance Corp.  Nuclear Fuel Services, Inc. (subs. of	8307250275 8307250238* 8307280423 8307080527	50-275 FOIA 71-9010 70-143	G
	8307060140* 8307060182 8307060259	50-336 50-423 50-336	K G S	Oetty Dil Co.)	8307200014* 8307200019*	70-143 70-143	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	DRY	AUTHDR AFFILIATION	ACCESSION NUMBER	CATEGO	RY
	8307200025* 8307200029* 8307200032* 8307200034* 8307200039*	70-143 70-143 70-143 70-143 70-143		Oregon. State of Owens-Corning Fiberglas Corp. Pacific Air Products Co. Pacific Oas & Electric Co.	8307260458* 8307280151 8307270028* 8307150129* 8307010143	50-243 WASTE M GEN TEC GA799 50-275	P OT
	8307200042* 8307200045* 8307200049* 8307200051* 8307200053*	70-143 70-143 70-143 70-143 70-143			6307010170 6307060068 6307060178 6307060178 6307060180*	50~275 50~275 50~275 50~275 50~275	R P F F
	8307200056* 8307200058* 8307200059* 8307200042* 8307200069*	70-143 70-143 70-143 70-143 70-143			8307060180* 8307060196 8307060199* 8307060202* 8307070026	50-275 50-275 50-275 50-275 50-275	4 4 4 4
	8307200072* 8307200075* 8307200077* 8307200080* 8307200083*	70-143 70-143 70-143 70-143 70-143			8307110406* 8307120324 8307120327* 8307120573 8307120582	50-275 50-275 50-275 50-133 50-323	P R Q B
Nuclear Information & Resource Service	8307200086* 8307200462 8307280135 8307280150* 8307120417	70-143 70-143 70-143 70-143 PR			8307130092 8307130221 8307130278 8307130278 8307130278*	50-275 50-275 50-275 50-275 50-275	8 P P P
Nuclear Metals, Inc.  Nuclear Packaging, Inc.	8307190091* 8307190095* 8307250354* 8307280129* 8307270340	40-672 40-672 40-472 40-672 71-9132			8307150218 8307150218 8307180002 8307180070 8307180070	50-275 50-275 50-275 50-275 50-275	0 0 P 0 0
Nuclear System G'Dwyer & Bernstein Dak Ridge National Laboratory	8305120551* 8307060632* 8307120021 8307150136 8307150371	CONTRACT 50-284 NUREO NUREO NUREO	т		8307190115 8307190171 8307200203 8307200203 8307200311	50-133 50-275 50-275 50-275 50-275	P G G G
	8307190035* 8307200026 8307200043 8307210260 8307210268	71-5552 ACRE ACRE NUREO NUREO			8307200311 8307220271 8307220362 8307220472 8307220476	50-275 50-275 50-275 50-275 50-133 50-275	9 R R
Office of Management & Budget	8307250159 8307250511 8307280223* 8307050222 8307050224	NUREQ NUREQ 71-5552 ORQ ORG			8307250137* 8307250136* 8307260275 8307260379 8307270147	50-275 50-275 50-275 50-275 50-275	FFOFO
Ohio Citizens for Responsible Energy	8307050230 8307050234 8307200335 8307260603 8307070144	ORG ORG ORG ORG 50-440	o		8307280101 8307280115* 8307280296 8307280301* 8307290195	50-275 50-275 50-275 50-275 50-275	F R R
	8307070144 8307070154± 8307070154± 8307070202 8307070225	50-440 50-440 50-440 50-412 50-440	0 0 0 0	Pacific Legal Foundation	8307290221 8307070108 8307070117* 8307110363 8307150308	50-275 PR PR 50-322 50-322	P G
	8307110310 8307190114 8307190186 8307190186 8307190222	50-440 50-440 50-440 50-440 50-440	G G G G	Palmetto Alliance Parents Concerned About Indian Point Parsons, Brinkerhoff, Guada & Douglas, Inc. Patal Engineers	8307170239 8307130077 8307270230* 8307110064*	50-413 50-247 WASTE MOT	r
Ohio, State of Oklahoma, Univ. of	8307190222 8307210179 8307220071 8307290489* 8307150192*	50-440 50-440 FDIA CONTRACT 50-112	ф С	Pathfinder Mines Corp. Pennsylvania Power & Light Co.	8307110077# 8307280198 8307280207# 8307010023#	SO-241 XPORTLIC XPORTLIC 50-387	P P G
Omaha Public Power District	8307260374 8304160022* 8307060078 8307080423 6307120454*	50-112 50-285 50-285 50-285 50-285	٧ ۴ و و		8307010023* 8307010031 8307010054 8307010055 8307010069	50-387 50-387 50-387 50-387	9 8 8
	8307120465* 8307120482 8307120489* 8307180182 8307190123	50-285 50-285 50-285 50-285 50-285	9 9 9		8307010099 8307010099 8307050084 8307060069 8307080368	50-387 50-387 50-387 50-387	8 0 8 0
	8307190158 6307220416 6307250428* 6307260031 6307260143	50-285 50-285 50-285 50-285 50-285	R G K F		8307080371* 8307090061* 8307110431 8307110439 8307110439	50-387 50-387 50-387 50-387	ե ե 1
Gregon State Univ.	8307260179 8307260182* 8307270338 8307270345* 8307260454	50-285 50-285 50-265 50-265 50-243	р 9 9 Р		8307110466 8307110466 8307120256 8307120273 8307120436 8307120442	50-387   50-387   50-387   50-387	P B B B B

AUTHOR AFF1L1ATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTH AFFILIA	ACCESSION NUMBER	SUBJECT	₹Y
	8307120443 8307120464* 8307120472* 8307140105 8307150180	50-387 50-387 50-387 50-387 70-2983 50-388	8 9 0		 8307130232 8307130232 8307130271 8307130271 8307130271	50-352 50-352 50-352 50-352 50-277	G G A A P
	8307180230 8307180264 8307220176 8307220265 8307220299	50-387 50-387 50-387 50-387 50-387	9 9 8 8 8 8		8307150067 8307150067 8307150069 8307150069 8307150075	50-352 50-352 50-352 50-352 50-352	E E E A
	8307220312 8307220319 8307220459 8307220483 8307260076	50-387 50-387 50-387 50-387 50-387	3 3 3 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		8307150075 8307150074 8307150074 8307150132 8307150132	50-352 50-352 50-352 50-352 50-352	A F E E
	8307260076 8307260300 8307260336 8307260339* 8307260342*	50-387 50-388 50-387 50-387 50-387	F R F P		8307150258* 8307150292 8307150292 8307180054 8307180054	50-277 50-277 50-277 50-352 50-352	0 F E E
Pennsylvania State Univ. Pennsylvania, Commonwealth of:	8307280281 8307280328 8307070054 8307050185 8307060190	50-387 50-387 50-400 50-289 50-289	0 0 8 8		8307180080 8307180084* 8307180085* 8307180087* 8307180091*	50-277 50-277 50-277 50-277 50-277	Р Р Р
	8307040398 8307070204 8307150329 8307150335* 8307150417*	50-412 50-412 50-287 50-289 CONTRACT	G G		8307190092* 8307190082 8307190082 8307190092* 8307190092*	50-277 50-352 50-352 50-352 50-352	P C C C
Philadelphia Electric Co.	8307250027* 8307250033* 8307010009 8307010009 8307010093	50-334 50-334 50-277 50-277 50-352	G G P P A		830719011B 830719011B 8307190121 8307190121 8307190197	50-352 50-352 50-352 50-352 50-352	A A A
	8307010093 8307010106 8307010106 8307010185 8307010185	50-352 50-277 50-277 50-352 50-352	A Q G K K		8307190197 8307200298 8307210045 8307210230 8307210230	50-352 50-277 50-277 50-352 50-352	A P R G
	8307010190* 8307010192* 8307010192* 8307010193* 8307010193*	50-352 50-352 50-352 50-352 50-352	К К К К		8307220238 8307220241* 8307220300 8307220404 8307220424	50-277 50-277 50-277 50-277 50-277	K R S
	8307060081 8307060245 8307060245 8307060407 8307060407	50-277 50-352 50-352 50-352 50-352	P E G G		8307220466 8307220469 8307250316 8307250316 8307250676*	50-277 50-277 50-352 50-352 50-277	S A A F
	8307070037 8307070037 8307070167 8307070167 8307070170*	50-352 50-352 50-352 50-352 50-352	A A A A		8307250676* 8307250680* 8307260147 8307260147 8307260350	50-277 50-277 50-352 50-352 50-352	F A A
	8307070170* 8307070255 8307070255 8307070286 8307070286	50-352 50-352 50-352 50-352 50-352	A G G A A		8307260350 8307260372 8307260372 8307260406 8307260406	50-352 50-352 50-352 50-352 50-352	A A A
	8307080294 8307080296 8307080300 8307080300 8307080352#	50-352 50-352 50-352 50-352 50-277	A A A A		8307260421 8307260472 8307260472 8307270043* 8307270043*	50-277 50-352 50-352 50-277 50-277	# A F F
	8307080454 8307080454 8307080505 8307080505 8307110459	50-277 50-277 50-352 50-352 50-352	J A A A		8307270046* 8307280063 8307280063 8307280147 8307280147	50-277 50-352 50-352 50-352 50-352	F K K G
	8307110459 8307110491 8307110491 8307120216 8307120216	50~352 50~352 50~352 50~352 50~352	A A A S		8307280169 8307280169 8307280242 8307280242 8307280246	50-352 50-352 50-352 50-352 50-352	G A
	8307120330 8307120330 8307120484 8307120484 8307120508*	50-352 50-352 50-352 50-352 50-352	A A A G		8307280244 8307280254* 8307280254* 8307280257 8307280284	50-352 50-352 50-352 50-352 50-277	9 A
	8307120508* 8307120534 8307120534 8307130015	50-352 50-352 50-352 50-352 50-352	9 6 8 8		8307280286 8307280288 8307280288 8307280294 8307280294	50-277 50-352 50-352 50-352 50-352	Q Q A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATE	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEO	
	8307280330 8307280330 8307280338 8307280338 8307280420	50-352 50-352 50-352 50-352 50-352	2 A 2 A		8307050069 8307050106 8307060244 8307060256 8307120087	50-267 50-267 50-267 50-267 50-267	P 8 P P 8
	8307280420 8307280463 8307290080 8307290080 8307290101	50-352 50-352 50-277	Q A A F		8307120408 8307140157 8307180276* 8307190010 8307190105*	50-267 50-267 50-267 50-267 50-267	C 8 4 5 0
Philadelphia, PA Phoenix Associates, Inc.	5307290317 8307290329; 8307050179 8307070484; 8307250629;	50-352 CONTRA CONTRA	S CT CT		8307250398 8307240218 8307260338 8307260343* 8307260494	50-267 50-267 50-267 50-267 50-267	9 4 4 5
Pismo Beach, CA Plateau Resources, Ltd.	8307250640* 8307250647* 8307180274* 8307130365 8307130367*		СT Н В	Public Service Co. of Indiana, Inc.	9307050174 9307060010 9307060204 9307060204 9307110306	50-546 50-546 50-546 50-546 50-546	8 9 9
Portland General Electric Co.	8307180390 8307040039 8307060078 8307110003 8307110143	40-869( 50-344 50-344 50-344 50-344	F P P		8307190140 8307190140 8307190142* 8307190172 8307190172	50-546 50-546 50-546 50-546 50-546	1 1 1 Q
	6307120029 8307120287 8307180049 8307180149 8307190219	50-344 50-344 50-344 50-344 50-344	P 8 R P		8307170209 8307170210 8307170210 8307170261 8307170261	50-546 50-546 50-546 50-546 50-546	5 Q 8 8
	8307190221* 8307190224* 8307210223 8307220085 8307220087*	50-344 50-344 50-344 50-344 50-344	4 k K K	Public Service Co. of New Hampshire	8307220460 8307220460 8307220490 8307060035 8307060090	50-546 50-546 50-546 50-443 50-443	8 8 8 A E
Power Authority of the State of New York	8307220091* 8307260400 8307010017 8307010046 8307010060	50-344 50-344 50-333 50-333 50-333	K J 8 8 8		8307060129 8307060162 8307060162 8307060203 8307060203	50-443 50-443 50-443 50-443 50-443	E 0 0
	8307010110 8307010111 8307050023 8307050029# 8307050034#	50-333 50-333 50-333 50-333 50-333	POFF		8307120312 8307120379 8307120379 8307120383 8307120383	50-443 50-443 50-443 50-443 50-443	E 0 0 0
	8307080337* 8307080341* 8307110223 8307110225 8307110227*	50-286 50-286 50-333 50-333	P F P		8307120444 8307120444 8307140222 8307150096 8307150096	50-443 50-443 50-443 50-443 50-443	9 8 8 8
	8307110233* 8307110309 8307110314 8307110400* 8307110429	50-333 50-333 50-333 50-333 50-286	P 55 P 67 P		8307150142 8307150142 8307150145* 8307150285 8307150285	50-443 50-443 50-443 50-443 50-443	8 K K 8
	8307110433* 8307110438* 8307120027* 8307120032* 8307120035	50-286 50-286 50-286 50-286 50-247	P P F G		8307180318 8307180318 8307210185 8307210185 8307210191#	50-443 50-443 50-443 50-443	8 8 T T
	8307120527 8307120565 8307130018 8307150254 8307180108	50-333 50-247 50-286 50-284 50-333	R Q S S P		8307210191* 8307220279 8307220279 8307220572 8307220572	50-443 50-443 50-443 50-443	T 8 8 8 8
	8307210011 8307220251 8307250194 8307250200* 8307250238	50-333 50-284 50-284 50-284 50-333	P R K K K	Bukli - Buris	8307250376 8307250378* 8307250378* 9307050025	50-443 50-443 50-443 50-311	T T 9
	8307250248* 8307250267 8307250278* 8307250468 8307270335	50-333 50-333 50-333 50-286 50-333	К О О Р		9307050036 9307050043 9307070057 9307070057 9307120238	50-272 50-272 50-272 50-272 50-311	8 F F 9
Project Management Corp.  Public Affairs Information, Inc.	8307270439 8307110142 8307220350 8307250363 8307260369	50-333 50-537 50-537 50-537 50-537	P T G G	S E E	3307120243 3307120450 3307130087 3307130255 3307130276	50-311 50-272 50-354 50-311 50-272	8 K 8
Public Service Co. of Colorado	8307150367# 8307130077 8307010041 8307050002 8307050008#	CONTRACT 50-247 50-267 50-267 50-267	e e r		3307130287 3307130306 3307130306 3307140001 3307140142	50-272 50-272 50-272	A Q Q S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8307140196 8307140293 8307150072 8307150105 8307150174	50-311 S 50-311 S 50-272 R 50-311 R REGGD	Runkle, J. D. SAS of Texas, Ltd.	8307120444 8307210185 8307250376 8307130242 8307250520*	50-443 G 50-443 T 50-449 T 50-400 G CONTRACT
	8307150199 8307190123 8307200004 8307200067 8307210003	50-354 8 50-311 5 50-272 F 50-272 P 50-311 8	SRI International Sacramento Municipal Utility District	8307290158* 8307010034 8307010044 8307060049 8307060068	CONTRACT 50-312 P TOPREP 50-312 S 50-312 S
	8307210009 8307210037 8307210104 8307210104 8307210112	50-311 8 50-311 P 50-272 P 50-272 P 50-311 8		8307040152 8307040317 8307070012 8307110235 8307110237*	50-312 B 50-312 P 50-312 P 50-312 P 50-312 P
	8307210134 8307220343 8307220345 8307220558 8307250427	50-311 8 50-272 8 50-311 8 50-311 8 50-272 P		8307120403 8307120521 8307180010 8307180012 8307180240	50-287 P 50-312 9 50-312 8 50-312 P 50-312 8
	8307250427 8307250449 8307250456 8307270195* 8307270195*	50-272 P 50-272 F 50-354 V 50-275 F 50-275 F		8307190099 8307190102* 8307190109 8307190161 8307190229	50-312 R 50-312 R 50-312 S 50-312 S 50-312 G
	8307270201* 8307270395 8307270395 8307270402 8307270402	50-275 F 50-272 Q 50-272 Q 50-272 P 50-272 P		8307250233 6307250240* 6307260015 8307260178 6307260352	50-312 P 50-312 P 50-312 F 50-312 P 50-312 P
	8307270406* 8307270416* 8307270416* 8307280358 8307280427	50-272 P 50-272 G 50-272 G 50-311 B 50-311 B		8307260459 8307260553 8307270433 8307270437* 8307280250	50-312 G 50-312 R 50-312 K 50-312 K 50-312 G
Puget Sound Power & Light Co.	8307290180 8307290185* 8307190182 8307190182 8307210303	50-272 P 50-272 P 50-522 D 50-522 D 50-522 D	Safe Energy Coalition	8307280350 8307280393 8307280492 8307280445 8307250527	50-312 P 50-312 S 50-312 S 50-312 F FOIA
Purdue Research Foundation Purdue Univ. R.E. Williams & Associates, Inc.	8307210303 8307140517* 8307200474 8307220643 8307250502	50-522 D CONTRACT ACRS ACRS 40-8827	San Diego Oas & Electric Co. Sandia Laboratories	8307080372 8307080465 8307080570 8307110082 8307110135	50-361 R NUREG NUREG NUREG NUREG
Reed, J. Q. Rensselaer Polytechnic Inst. Rhone-Poulene, Inc.	8307250506# 8307180263 8307200185# 8307070531 8307180345	40-8829 50-483 0 CONTRACT XPORTLIC XPORTLIC		8307110308 8307130358 8307150131 8307150356 8307150359	NUREG RES NUREG NUREG NUREG
Robert L. Cloud Associates, Inc. Rochester Gas & Electric Corp.	8307130258 8307120031* 8307120037* 8307120470 8307130379	50-275 R 50-244 F 50-244 F 50-244 P 50-244 S	Sargent & Lundy, Inc.	8307150365 8307210257 8307250294 8307070223* 8307070223*	50-313 P NUREQ NUREG 50-237 P 50-237 P
	9307190169* 9307190270 9307190273* 8307220178 8307220262	50-244 Q 50-244 G 50-244 G 50-244 R 50-244 S	Sassafras Audubon Society	8307180168* 8307180168* 8307260024* 8307260028*	50-237 P 50-237 P 50-237 P 50-237 P PR
	8307220377 8307260445 8307270468* 8307270471* 8307280337	50-244 9 50-244 P 50-244 F 50-244 F 50-244 G	Science Applications: Inc.	8307070138 8307070143 8307260268 8307260366 8209200358*	PR NUREQ 50-546 Q 50-546 Q 50-338 Q
Rockland County, NY	8307280344 8307050100 8307050100 8307050110* 8307050110*	50-244 B 50-247 H 50-247 H 50-247 H 50-247 H	Scientific Inspection Technology, Inc.	8210040180* 8307050496* 8307140206* 8307220114* 8307190236	50-219 Q CDNTRACT 50-322 A FOIA 71-501
Rockwell International Corp.	8307050116* 8307050116* 8307220240* 8307260087* 8307270276*	50-247 H 50-247 H Waste Mot Füia Waste Mot	Scientists & Engineers for Secure Energy Scottsboro, AL	8307190236 8307190244* 8307190246* 8307110454 8307220075*	71-501 71-501 71-501 Pr Contract
Rocky Mountain Energy Co. Rondout Associates	8307180254 8307180256* 8307220009 8307200033	40-8380 40-8380 40-8380 ACRS	Sezcoest Anti-Pollution League Benate Beparative Work Unit Corp. Shaw, Pittman, Potts & Trowbridge	8307150279 8307270019+ 8307110521 8307050123 8307050271	NUREQ 50-320 H XPORTLIC 50-289 Q 50-289 Q
Ropes & Gray	8307060162 8307060165 8307120379 8307120383 8307120383	50-443		8307050271 8307060178 8307060178 8307060207 8307060212*	50-207 G 50-400 G 50-400 G 50-261 G 50-261 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	JRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEO	ORY
	8307060238 8307060238 8307060339 8307060339 8307060344*	50-440 50-440 50-440 50-440 50-440	T T Q G	<b>************</b>	8307250350* 6307250350* 8307260264 8307260305 8307260360	50-400 50-400 50-287 40-206 50-400	0 0 6
	8307060344* 8307070092 8307070092 8307080375 8307130231	50-440 50-400 50-400 50-483 50-400	0 0 0 0		8307270287 8307270287 8307270477* 8307270477* 8307280155	50-440 50-440 50-440 50-440 50-267	0 0 0
	8307130231 8307130241* 8307130241* 8307130253* 8307130253*	50-400 50-400 50-400 50-400 50-400	0 0 0 0	Shoreham Opponents Coalition	8307280163 8307280185 8307290130 8307290142 8307050266	50-400 50-400 50-289 50-400 50-322	G G G G
	8307140435 8307140435 8307140440 8307140440 8307140443	50-400 50-400 50-400 50-400 50-400	G G G	Siemans Qammasonics	8307120350 8307120367* 8307290154 8307290159* 8307180150	50-922 50-922 50-922 50-922 PR	9
	8307140443 8307140454 8307140454 8307150201 8307150201	50-400 50-400 50-400 50-400 50-400	0 0 0	Simra Club Simkens Industries, Inc.	8307050117 8307120557 8307220124 8307220131 8307150056*	PR 50-537 50-537 WASTE M CONTRAC	
	8307150287 8307150316 8307150343 8307150350 8307180176	50-412 50-440 50-412 50-412 50-266	0 0 0	Sinclair, M. Sinnistippi Alliance for the Environment (SAFE)	8307050032*	50-327 50-454 50-454	9
	9307180176 8307180183* 8307180183* 8307180190 9307180196*	50-266 50-266 50-266 50-482 50-482	0 6 6 0	Small Business Administration	8307050227 8307120578 8307220417 8307260258 8307050321* 8307150454*	50-454 50-454 50-454 50-454 CONTRAC	Т
	8307180200 8307180204 8307180205* 8307180218 8307180225	50-266 50-482 50-266 50-266 50-412	0 0 0 0	Snell & Wilmer	8307190313# 8307190418# 8307190458# 8307060151 8307060156 8307190157	CONTRAC CONTRAC CONTRAC 50-529 50-529 50-529	т
	8307190077 8307190084 8307190203 8307190203	50-289 50-440 50-440 50-440 50-440	0		8307190157 8307190227 8307190227 8307190232* 8307190232*	50-529 50-529 50-529 50-529 50-529	00000
	8307190208* 8307190229 8307190240 8307190242*	50-440 50-312 50-482 50-312 50-483	9 9 9	Somervell County, TX South Carolina Electric & Qas Co.	8307220346 8307050209 8307060272 8307110210 8307110262	50~445 50~395 50~395 50~395 50~395	8 8 9
	8307190255* 8307190259 8307190263* 8307190268	50-483 50-320 50-320 50-382 50-382	0 0 0		8307110370 8307120081 8307120196 9307120260 8307120458	50-395 50-395 50-395 50-395	8 8 8 8
	8307190274 8307190278* 8307190283 8307190283 8307190284	50-289 50-289 50-400 50-400	0 0 0		8307140213 8307140250 8307150297 8307220065# 8307220172	50-395 50-395 NUREQ 50-395 50-395	Q Q Q R
	8307190288* 8307190288* 8307190294 8307190299*	50-261 50-261	0 0 0 0		8307220252 8307220256 8307220274 8307220283* 8307220284	50-395 50-395 50-395 50-395 50-395	8 8 8
	8307210203 8307210241 8307210248 8307210248	50-400 50-482 50-277 50-277	e 0 0 0		8307220380 8307220383* 8307220387* 8307220413*	50-395 50-395 50-395 50-395	P P P
	8307210248 8307210248 8307210248 8307210251*	50-277 50-277 50-277 50-277 50-277	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		8307220454 8307220473* 8307220552* 8307250138 8307250201 8307250496	50-375 50-375 50-375 50-375 50-375	8 9 9
· · · · · · · · · · · · · · · · · · ·	9307210251* 9307210251* 9307210251*	50-277 50-277 50-277	0 0 0 0		8307250515 8307260340 8307260394 8307260399# 8307260461	50-395 50-395 50-395 50-395	\$ F P
· · · · · · · · · · · · · · · · · · ·	3307220353 3307250337 3307250346	50-261 50-400 50-400	9 9 9		8307260463* 8307260465 8307260469*	50-375 50-375	P P P B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	JRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8307270006 8307270013* 8307270018 8307270020* 8307270062	50-395 50-395 50-395 50-395 50-395	P P P P		8307250426 8307250433 8307250450 8307250459 8307250462	50-362 50-206 50-206 50-362 50-361	8 P 8 8
	8307270182* 8307290085 8307290092 8307290175 8307290186	50-395 50-395 50-395 50-395 50-395	5 P F F		8307250472 8307250474 8307250474 8307250476* 8307250479*	50-361 50-361 50-361 50-361 50-361	99999
South Carolina, State of Bouth Mississippi Electric Power Association Bouthampton, NY	8307070053 8307070139 8307060110* 8307050180	50-413 50-413 50-416 50-322	A A I		8307250490 8307250491 8307260135 8307270029 8307270162	50-361 50-361 50-206 50-206 50-361	88 F F
	8307070203 8307120350 8307120367* 8307290154 8307290159*	50-322 50-322 50-322 50-322 50-322	0		8307010220* 8307110453 8307120358 8307150263	50-424 50-424 50-424 50-461	8 8 K
Southern California Edison Co.	8307050010 8307050010 8307040042 8307040044 8307040044	50-361 50-361 50-361 50-361 50-361	0 9 F F	Southwest Research Institute Spiegel & McDiarmid Stamiris, D. Standardised Nuclear Unit Power Plant	8307060388* 8307080551* 8307210216 8307280161 8307060257	TOPREP CONTRACT 50-414 50-329 50-482	M G F
	8307040047 8307040080 8307040080 8307040091 8307040091 8307040128	50-361 50-361 50-361 50-361 50-361 50-362	8 8 8 6 8		8307060257 8307060257 8307060264* 8307060264*	50-482 50-482 50-482 50-482 50-482	£ £ £ £
	8307060155 8307060155 8307060214 8307060311 8307060387	50-341 50-341 50-341 50-342 50-342	P 8 8 8		8307060280 8307060280 8307060280 8307060288* 8307130268 8307250309	50-482 50-482 50-482 50-482 50-482 50-482	5 5 5 5 E A
	8307060423 8307070065 8307070067* 8307070164 8307070166*	50-361 50-362 50-362 50-361	8 0 9 P	State, Dept. of State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs Steam Generator Owners Group	8307210277	XPORTLIC XPORTLIC	;
	8307080392 8307110232 8307120008 8307130081 8307130096	50-361 50-264 50-266 50-361 50-361	R P G 8	Stone & Webster Engineering Corp.	8307050134 8307050137* 8307050143* 8307050149* 8307070120 8307070120	50-275 50-275 50-275 50-275 PR	R R R
	8307130096 8307130192 8307130192 8307130235 8307130246	50-361 50-361 50-361 50-361 50-361	8 R R S	Stone & Webster, Inc.	8307180154 8307200179 8307250253 8307280425* 8307080453	50-275 GEN TEC 50-327 50-280 50-329	A P A
	8307130248 8307130275 8307130275 8307150222* 8307150222*	50-206 50-361 50-361 50-206 50-206	P 9 9 0 0		8307080453 8307110038 8307110038 8307110040* 8307110305 8307140349*	50-329 50-329 50-329 50-329 50-329 50-329	A A A A G
	8307150222* 8307180050 8307180050 8307180051* 8307180053*	50-206 50-261 50-261 50-261 50-261	9 9 9		8307140352* 8307140354* 8307140358* 8307140361* 8307140365*	50-329 50-329 50-329 50-329 50-329	9
	8307180093 8307180096 8307180096 8307180105	50-361 50-361 50-361 50-361	9 P P		8307140370* 8307140373* 8307140378* 8307250261* 8307250261*	50-327 50-327 50-327 50-327 50-327	G G A A
	8307180121 8307180126* 8307180135 8307180146	50-342 50-342 50-341 50-341	Р 9 8 8	Structural Mechanics Associates	8307260547 8307260547 8307180307* 8307180315* 8307220411*	50-329 50-329 50-155 50-155 50-329	A P P A
	8307180234 8307180284 8307180286* 8307200202	50-361 50-361 50-361 50-361	P 8 P P	Buffolk County, NY	8307270118* 8304270048* 8307050046 8307050067 8307050266	50-327 50-322 50-322 50-322 50-322	A A O O G
	8307220290 8307220445 8307220465 8307220506	50-206 50-361 50-361 50-206	S R R R		8307110276 8307120350 8307120367* 8307140444 8307140448*	50-322 50-322 50-322 50-322 50-322	0000
	8307250298 8307250379 8307250383* 8307250394	50-362 50-206 50-206 50-362	9 P 6		8307140471 8307220357	50-322 50-322	G G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	YROS	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	
Sugarman, R.J.	8307240302 8307260347 8307290154 8307290159* 8307110272	50~322 50~322 50~322 50~352	2 G 2 G		8307120219 8307120250 8307120250 8307120250 8307120267	50-259 50-390 50-390 50-390 50-328	8 8 8
Sunflower Alliance	8307220364 8307150325 8307200214 8307260294	50-352 50-440 50-440 50-440	)		8307120416 8307120418 8307120420	50-328 50-260 50-327	9 9
TERA Corp.	8307210225 8307210225 8307210233*	50-329 50-329 50-329	R		8307120422 8307120470 8307120481	50-327 50-259 50-390	8
	8307210233 <del>*</del> 8307210291 8307210291	50-329 50-329 50-329	R		8307120481 8307120501 8307120544 8307120567	50-390 50-259 50-259 50-390	9 8 8
TRC Environmental Consultants, Inc. Target Rock Corp. Technassociates, Inc.	8307120018 8307120018 8307180081 8307150454* 8307190418*	50-329 NUREG 50-528 CONTRAC	g CT		8307120575 8307120575 8307120575 8307120577 8307120577	50-259 50-259 50-259 50-390 50-390	9 9 8
Teknetron, Inc. Teledyne Engineering Services	8307120016 8307290505* 8307010091 8307010100* 8307010176	NUREQ CONTRAC 50-322 50-322 50-322	R R A		8307120589 8307120598 8307120598 8307140043 8307140045	50-328 50-370 50-370 50-328 50-438	8 8 9 8
	8307010179* 8307050093 8307050245 8307050253* 8307060233	50-322 50-275 50-275 50-275 50-275	A R R P		8307140275 8307140275 8307140345* 8307140351* 8307150021	50-327 50-327 50-327 50-327 50-260	V 0 0 8
	8307130097 8307130207 8307130214* 8307190044 8307200081	50-275 50-275 50-275 50-275 50-275	P R R P R		8307150166 8307150166 8307150207 8307150236 8307150236	50-438 50-438 50-390 50-390 50-390	8 8 8
	8307200084* 8307220334 8307220378* 8307260506 8307260527*	50-275 50-275 50-273 50-275 50-245	R P R P		8307150267 8307150267 8307190089 8307190074* 8307190146	50-438 50-438 50-328 50-328 PR	8 8 P P
	B307260539 B307260544* B307280292 B307280297* B307290160	50-275 50-275 50-275 50-275 50-322	R R P R		8307190166 8307200095 8307200100* 8307220080 8307220111	50-327 50-259 50-259 50-438 50-259	P P B S
Tennessee Valley Authority	8307270163* 8307010284 8307010284 8307050226 8307050226	50-322 50-370 50-370 50-370 50-370	R K K A		8307220155 8307220169 8307220169 8307220211 8307220211	50-259 50-438 50-438 50-259 50-259	G 5 6 0
	8307040071 8307040133* 8307040218 8307040218 8307040218	50-327 50-327 50-259 50-259 50-259	R P P		9307220211 9307220217 9307220229 9307220235 9307220246	50-259 50-259 50-260 50-328 50-276	0 8 8 8
	8307070003 8307070005* 8307070011* 8307070122 8307070122	50-328 50-328 50-328 50-259 50-259	Р Р Р		8307220261 8307220266 8307220268 8307220302 8307220304	50-259 50-259 50-260 50-438 50-438	8 8 9 8
	8307080358*	50-259 50-259 50-259 50-259 50-259	P P P		8307220304 8307220313 8307220316 8307220321 8307220420	50-438 50-259 TOPREP 50-438 50-328	8 R S
	8307080358* 8307080358* 8307110054 8307110054	50-328 50-259 50-328 50-390 50-390	P P F F		8307220422 8307220433 8307220435 8307220437 8307220437	50-439 50-259 50-259 50-438 50-438	8 8 8
	8307110168# 830711050B 8307110508	50-537 50-537 50-390 50-390 50-296	T 9 8		8307220440 8307220474 8307220526* 8307220529 8307220533*	50-259 50-327 50-438 50-259 50-259	8 R Q 8
	8307120091 8307120160 8307120160 8307120167	50-260 50-390 50-390	6 6 6 6		8307220533* 8307220533* 8307220544 8307220554 8307250127	50-259 50-259 50-259 50-259 50-259	0 8 8
	8307120179 8307120180 8307120180	50-390 50-390 50-390	8 8 8		8307250127 8307250127 8307250219 8307250230 8307250292	50-259 50-259 50-227 50-438 50-390	0 0 5 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8307250292 8307250395 8307250395 8307250405 8307250408	50-370 50-370 50-370 50-370 50-438	6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8307190233* 8307190233* 8307210117 8307210117	50-445 G 50-445 Q 50-445 A 50-445 A 50-445 K
	8307250464 8307250464 8307250487 8307250633* 8307250633*	50-438 50-438 50-296 50-257 50-257	8 8 F F		8307210161* 8307210161* 8307220259 8307250356 8307250359*	50-445 K 50-445 K 50-445 G 50-445 G 50-445 Q
	8307250633* 8307260032 8307260032 8307260032 8307260041*	50-259 50-259 50-259 50-259 50-259	F P P P		8307250357* 8307260391 8307260405 8307270172 8307270172	50-445 Q 50-445 S 50-445 Q 50-445 F 50-445 F
	8307260041* 8307260041* 8307260207 8307260270 8307260274	50-259 50-259 50-327 50-259 REGGD	P P P	Texas Utilities Services, Inc.	8307280070 8307290110 8307050064 8307110350 8307120631	50-445 A 50-445 T 50-445 A 50-445 E 50-445 A
	8307260297 8307260297 8307260419 8307260434 8307260434	50-370 50-370 50-438 50-370 50-370	A A S S S		8307150163 8307250254 8307250260* 8307250370 8307250370	REGGD 50-445 A 50-445 A 50-445 A
	9307260503 8307260520 9307260520 8307260552 8307260555	50-438 50-390 50-390 50-294 50-438	8 8 8 8	Texas, Univ. of, Austin, TX The Analytic Sciences Corp. Three Mile Island Alert	8307260548 8307260548 8307050092 8307270198 8307060393	50-445 K 50-445 K 50-192 F Waste Mot 50-289 G
	8307260555 8307260564 8307270036 8307270036 8307270040*	50-439 50-260 50-327 50-327 50-327	8 P P	Toleda Edison Co.	8307130228 8307290127 8307050015 8307060115 8307060220	50-287 0 50-287 0 50-346 8 50-346 8 50-346 8
	8307270040* 8307270176 8307270180* 8307280370 8307290034	50-327 50-438 50-438 50-294 50-390	р G Р В		8307050225 8307070041 8307070125 8307070178 8307110120	50-346 P 50-346 P PR 50-346 P 50-346 P
	8307290034 8307290034 8307290034 8307290039 8307290083	50-390 50-390 50-390 50-327 50-296	5 5 5 5		8307110123* 8307110126* 8307110197* 8307110482 8307120228	50-346 P 50-346 P 50-346 F 50-346 S 50-346 P
	8307270094 8307270109 8307270109 8307270109 8307270135	50-327 50-259 50-259 50-259 50-438	8 P P P		8307120237* 8307120411 8307120413* 8307120415* 8307150071	50-346 P 50-346 P 50-346 P 50-346 P 50-346 F
	8307290135 8307290148 8307290148 8307290151 8307290151	50-438 50-390 50-390 50-390 50-390	8 A A A		8307180035 8307180177 8307180181 8307180304* 8307180306*	50-346 R 50-346 Q 50-346 R 50-346 F 50-346 F
	8307290155* 8307290155* 8307290172 8307290172 8307290174	50-390 50-390 50-390 50-390 50-390	A 6 8 8		8307210129 8307210167 8307210302 8307210309* 8307210314*	50-346 P 50-346 P 50-346 P 50-346 P 50-346 P
	8307290176 8307290204 8307290206 8307290206 8307290230	50-370 50-259 50-259 50-259 50-259	\$ P P 8		8307220092 8307220228 8307250121* 8307250125* 8307240321*	50-346 R 50-346 B 50-346 F 50-346 F 50-346 Q
Tennessee, State of Texas A&M Univ., College Station, TX	8307080648 8307190285* 8307260223 8307260500 8307260566	70-143 50-443 50-128 50-128 50-59	T P P H		8307260530 8307260537* 8307280069 8307280071* 8307280201	50-346 P 50-346 Q 50-346 P 50-346 P 50-346 K
Texas Electric Service Co. Texas Municipal Power Agency Texas Power & Light Co. Texas Utilities Co. Texas Utilities Generating Co.	8304280593* 8304280588* 8304280403* 8304280407* 8305230578	50-445 50-445 50-445 50-445 50-445	I I A	Tarrey Pines Technology	8307280206# 8306270356 8307050228# 8307080485 8307150238	50-346 X 50-358 A 50-528 E 50-358 A 50-528 A
	8306280576 8307060153* 8307110282 8307120272 8307120585	50-445 50-445 50-445 50-445 50-445	1 Q A H O	Trane Co. Transamerica Delavel, Inc.	8307200307 8307280262 8307150290 8307120606* 8307250335	50-358 R 50-358 R 50-322 G 50-322 G 50-206 B
	8307150100 8307150294 8307150311* 8307190228 8307190228	50-445 50-445 50-445 50-445 50-445	6 G G	Transco, Inc. Transnuclear, Inc.	8307250335 8307250461 8307180067* 8307070361 8307070528	30-206 8 50-322 8 50-373 0 XPORTLIC XPORTLIC

### **CORPORATE SOURCE INDEX**

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
Tube-Line Corp.  Twomey, Latham & Shea	8307200291 8307080344 8307080348* 8307260113* 8307050180	XPORTLIC MISC MISC MISC 50-322 0		8307110169* 8307110169* 8307110184* 8307110375 8307110435	50-338 F 50-338 F 50-280 F 50-339 S 50-338 S
VS Ecology, Inc. (formerly Nuclear Engineering)	8307200210 8307150033 8307150035+ 8307150038+	50-322		8307110479* 8307120094 8307120225 8307120251 8307120254	50-280 F 50-337 S 50-280 S 50-280 G 50-337 S
US Gypsum Co.	8307150040* 8307270144 8307180064* 8307180065* 8307180066*	71-6679 27-48 50-373 Q 50-373 Q 50-373 Q		8307120268 8307120268 8307120299 8307120302 8307120302	50-338 P 50-338 P 50-338 P 50-338 P
US Riley Corp. Union Carbide Gorp.	8307150237 8307010013 8307010113 8307050314 8307190264	PT21 50-34 F 50-54 F RES 70-687		8307120308* 8307120308* 8307120356 8307120356 8307120361*	50-338 P 50-338 P 50-338 P 50-338 P 50-339 P
Union Electric Co.	8307050076 8307060034 8307080375 8307080383* 8307110231	50-483 S 50-483 A 50-483 G 50-483 G 50-483 B		8307120361* 8307120386 8307120386 8307120386 8307120372*	50-338 P 50-280 F 50-280 F 50-280 F 50-280 F
	8307110257 8307110301 8307110354* 8307110364* 8307120477	50-483 A 50-483 8 50-483 0 50-483 0 50-483 R		8307120441 8307120491 8307120504 8307120535 8307120541	50-339 P 50-339 S 50-338 S 50-281 S 50-339 P
Union Minerals Union of Concerned Scientists	8307190250 6307260214* 8307280401* 8307110762 6307110300 8307120185	50-483		8307120561 8307120562 8307120566* 8307120566* 8307130068	50-338 P 50-338 S 50-338 P 50-338 P 50-280 J
	8307120194 8307130077 8307250362 8307250366* 8307250368*	NUREC PR . 50-247 C 50-287 C 50-287 C		8307140228* 8307140264* 8307140244* 8307180097 8307180100	50-280 Q 50-280 P 50-280 P 50-338 P 50-338 P
United Nuclear Corp.	8307270135 8307050281 830709102 8307110524 8307110524	50-289 0 70-820 70-820 70-371 70-820		8307180104 8307200194 8307200195* 8307200197* 8307210205	50-338 0 50-280 R 50-280 R 50-280 R 50-280 P
Velsicol Chemical Corp.	8307200460 8307220147 8307220535 8307280319* 8307080480*	70-371 70-820 70-371 70-820 40-6264		8307220048 8307220118 8307220123 8307220192 8307220385	50-338 8 50-339 8 50-339 8 50-338 R 50-280 R
Vermont Yankee Nuclear Power Corp.	8307010022 8307010085 8307010098* 8307010105 8307070038	50-271 S 50-271 S 50-271 G 50-271 S 50-271 F		8307250320 8307250451 8307250467 8307250485 8307270287	50-281 P 50-339 P 50-280 8 50-281 8 50-338 F
	8307070103 8307110289* 8307150288 8307150354 8307170078	50-271 P 50-271 0 50-271 R 50-271 S 50-271 R		8307270327 8307280418 8307290058 8307290073 8307290171	50-280 F 50-280 P 50-337 S 50-339 S
	8307210056* 8307220397* 8307220484 8307250519 8307260408	50-271	Virginia, Univ. of, Charlottesville, VA	8307290173 8307290187 8307290189 8307120206 8307250521*	50-280 8 50-339 8 50-338 8 50-62 8 50-62 F
Virginia Electric & Power Co.	9307260490 6307260481* 9307290336 9305100108 9305100108	50-271 K 50-271 K 71-6348 50-280 P 50-280 P	Habash Valley Power Association, Inc. Mashington Legal Foundation Washington Public Power Supply System	8307190143* 8307260104 8305100420 8306170416* 8306170422*	50-546 I FOIA 50-508 G 50-397 G 50-397 G
	8305100111* 6305100111* 8307010020 8307010090 8307010090	50-280 P 50-280 P 50-281 F 50-238 P 50-338 P		8307050001 8307050004 8307050022 8307050085 8307050134	50-397 A 50-397 E 50-397 A 50-397 G 50-397 E
	8307050117 8307060042 8307060042 8307060230 8307060230	PR 50-338 G 50-338 G 50-280 P 50-280 P		8307050141* 8307050151* 8307050154* 8307050160* 8307050165*	50-397 E 50-397 E 50-397 E 50-397 E 50-397 E
	8307060235* 8307060235* 8307110165* 8307110165*	50-280 P 50-280 P 50-338 F 50-338 F		8307050167* 8307050173* 8307050196 8307050270 8307060045	50-397 E 50-397 E 50-397 E 50-508 A 50-397 E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	,
	8307060228 8307060232* 8307060237* 8307060255 8307070002	50-397 8 50-397 9 50-397 8 50-508 A 50-305 P	West Valley Agricultural Protection Council, Inc.	B307050244 B307050244 B307050247* B307050247* B307050251*	50-529 50-529 50-529	0 0000
	8307070006 8307070013* 8307070120 8307080324 8307080437	50-397 A 50-397 A PR 50-508 A 50-508 Q		8307050251* 8307190076 8307190076 8307190081* 8307190081*	50-529 ( 50-529 ( 50-529 ( 50-529 (	00000
	8307110007 8307110236 8307110277 8307110321* 8307120241	50-397 E 50-508 Q 50-305 S 50-397 F 50-513 S		8307210041* 8307240243 8307240243 8307240251 8307240251	50-529 ( 50-529 ( 50-529 ( 50-529 (	00000
	8307120309 8307120313* 8307120499 8307120499 8307120539	50-397 E 50-397 E 50-460 S 50-397 F		B307260367 B307260367 B307260403 B307260403 B307260407*	50-529 0 50-529 0 50-529 0 50-529 0	99999
	8307120545 8307140464 8307150203* 8307150227 8307150310	50-397 H 50-508 Q 50-508 Q 50-397 A 50-508 F	Westchester County, NY	8307260407* 8307180071 8307180071 8307180074*	50-247 0 50-247 0 50-247 0	00000
	8307180027 8307180027 8307180034 8307180034 8307180039	50-308 F 50-397 8 50-460 9 50-460 9 50-509 A	Westinghouse Electric Corp.	8307010131* 8307010217* 8307070079 8307070119* 8307070155	70-498 50-424 # 50-260 F	K P
	8307180083 8307180144 8307180144 8307190213 8307190215*	50-397 S 50-460 S 50-460 S 50-397 A		B307070364 B307070452 B307070456 B307080304 B307080309*	XPORTLIC XPORTLIC XPORTLIC TOPREP TOPREP	
	8307190217* 8307200142 8307200458 8307220415 8307250135	50-397 A 50-397 A 70-2950 50-508 E 50-508 A		8307080314* 8307080316 8307080322* 8307080325* 8307110187*	TOPREP TOPREP TOPREP TOPREP 70-1151	
	8307260519 8307260523 8307270452 8307280299 8307280345	50-397 E 50-397 C 50-397 F 50-460 B 50-460 S		8307110275* 8307120224* 8307120397 8307120379* 8307130325*	50-315 P 70-1143 PROJ PROJ 50-454 A	
Washington, State of	8307280356 8307280359 8307290177 8307060407* 8307110465	50~508 A 50~397 A 50~440 A 27~48 PR		8307150196 8307150200* 8307150202* 8307180025 8307190257*	TOPREP TOPREP TOPREP 71-5450 50-213 P	•
	8307180320 8307210218 8307280025 8307280031 8307280036	50~397 € 50~508 A WASTE MOT WASTE MOT WASTE MOT		8307250412 8307270295 8307280114 8307280120* 8307280289	PR TOPREP PROJ PROJ NUREG	
	8307280042 8307280047 8307280056 8307280058 8307280067	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	Whicher: J.M.	8307220417 8307260288 8307260288 8307260425 8307260425	50-454 G 50-454 G 50-454 G 50-454 G 50-454 G	9
	8307280077 8307280090 8307280097 8307280103 8307280107	HASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	Wilson, R. Wilt, D.D. Wisconsin Electric Power Co.	8307210281 9307260294 8307050246 8307070021 8307070113	50-400 G 50-440 G 50-301 P 50-264 P 50-246 P	) )
	8307280113 8307280119 8307280124 8307280130 8307280139	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8307070113 8307110343* 8307110348* 8307110487* 8307120364	50-266 P 50-266 F 50-266 F 50-266 Q	; 3
	8307280145 8307280158 8307280162 8307280171 8307280172	WASTE MGT WASTE MGT WASTE MGT WASTE MGT		8307120369* 8307130220 8307130220 8307130226 8307140260	50-266 P 50-266 P 50-266 P 50-266 P 50-266 P	,
Washington, Univ. of Seattle, WA Waste Management Group, Inc.	8307280197 8307280203 8307280209 8307180246* 8307290351	WASTE MOT WASTE MOT 70-115 WASTE MGT		8307150066 8307150066 8307180200 8307190018 8307190174	50-264 R 50-264 R 50-264 G 71-9010 50-301 S	? ?
West Branch Conservation Association Hest Chicago, IL West Jersey Manufacturing Co.	8307290400 8307130077 8307070216 8307210206* 8307210224*	WASTE MGT 50-247 G 40-2061 GA797 GA797		8307220210 8307220354 8307220354 8307250157	50-301 S 50-264 P 50-266 P 50-266 P	3

### CORPORATE SOURCE INDEX

AUTHOR AFFILTATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	DRY
			F				
	8307260335	50-266 50-266	K		8307080452*	50-522	D
	8307240439		ĸ		8307080452*	20-255	D
	8307270382*	50-246			8307270470	WASTE M	
	83072703B2 <del>+</del>	50-266	K		8307270460	WASTE M	
	8307290145	50-301	P		8307270482	WASTE M	OΥ
Wisconsin Public Service Corp	B307040107	50-305	(t		8307010024	50-29	8
Mileconatti Lonite Dei erra anib	8307110239	50-305	F	Yankee Atomic Electric Co.	8307010027	50-27	S
	8307110284	50-305	8			50-27	
	8307120263	50-305	R		8307010114		8
	9307190083	50-305	K		8307010127	50-27	8
	0007170000				8307010150	50-29	F
	8307190086*	50-305	K		8307050117	PR	
	8307250286	50-305	G .		8307060035	50-443	Α
	8307250276	50-305	G		8307060090	50-443	Ë
	8307250340	50-305	R		8307060129	50-443	Ē
	8307250488	50-305	P		8307080344*	50-29	P
					9307 (QC Q 100 ··	50 k)	r
	8307270502*	50-305	F		8307120312	50-443	E
	8307270506¥	50-305	F		9307140222	50-443	8
Wisconsin's Environmental Decade	8307110461	PR			8307150094	50-443	8
Wisconsin, State of	8307070159	₽₽				50-443	8
	B307270473*	CONTRACT	-		9307150096		
					830715O130	50-27	8
Wood-Leaver & Associates, Inc.	8307150301	PR			6307150277	PR	
Woodward Governor Co.	8307290043	50-312	8		8307150285	50~443	
Wule Laboratories	8307060025*	50-528	S			50-27	8 8
•	9307120451*	50-314	P		8307150319		
	8307130328*	50-454	Α		8307180318	50~443	8
					8307180318	50-443	8
	8307130328*	50-454	A		8307220039	50-29	R
	8307130330*	50-454	Ą	•	8307220279	30-27 30-443	
	8307130330*	50-454	A				B
	8307130331*	50-454	A		8307220279	50-443	8
	830722035 <b>7</b> *	50-266	P		8307220295	50-29	8
					8307220327	50-29	B
Hyoming Mineral Corp.	8307080538	40-8585				WD 440	
Wyoming, State of	8307070156	PR			8307220567	50-443	8
• =	8307090099	State Pr	.00		8307220 547	50-443	B
	6307180395	40-277			8307220 572	50-443	8
Yakima Indian Nation	8307080342	50-522	Ð		8307280416	50-27	P
					9307 <b>2804</b> 23*	50-27	P
	8307080350*	50-522	מ				_
	8307080435	50-522	D		8307280442	50-29	P
	8307080440*	50-522	D		8307280464*	50-29	P
	#307080440*	50-522	D	Yarway Corp.	830721O229*	50-482	8
	<b>ロマハブハロハ&amp;&amp;</b> 等	50-522	D.				

### REPORT NUMBER INDEX

subject category column in this index gives the docket ber and the symbol for the category of information in that docket; for example, 50-320 P. The docket subject gories are defined in Appendix A.

ect categories for nondocketed items are also entered its column by symbol; for example, ACRS. These cateas are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

EPORT IUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
09 H-01 R00 R00	9307130266* 9307130271* 9307200105* 9307120446* 9307060025*	50-275 P 50-275 P 50-259 P 50-265 P 50-528 S		IDW-40-199-A RO1 LBL-2168 NEDD-10678 NEDD-24096 RO1 NEDD-24281 ERR	8307040304* 8307210373* 8307150081* 8307260279* 8307270440*	50-331 P 71-4550 50-352 A 50-259 P	22520 72NEDB1 80NED2B5
V01 V02	9307120451* 9307130331* 9307130328* 9307130330* 9307220359*	50-316 P 50-454 A 50-454 A 50-454 A 50-266 P		NM79-137 NUREG-0040 V07 NO2 NUREG-00485 V05 NO5 NUREG-0485 V05 NO6 NUREG-0540 V05 NO3	8307270240* 8307250591 8307050483 8307270366 8307110275	WASTE MGT NUREG NUREG NUREG NUREG	00244
114 160	8307220378* 8307120333* 8307170074* 8307050314 8307110560	50-293 P 50-352 A 50-237 P RES RES		NUREG-0580 V12 NO6 NUREG-0748 V03 NO5 NUREG-0750 V16 NO2 NUREG-0750 V16 NO3 NUREG-0787 S05	8307250332 8307210262 8307180115 8307250555 8307150139	NUREO NUREO NUREO NUREO 50-382 E	
158 178 190 143 NRC 83-6	8307130358 8307140478 8307150390 8307260043 8307120047	RES RES RES RES	BAND83-XXXX B352445 G-6-01B (R673)	NUREG-0797 803 NUREG-0830 502 NUREG-0837 VOZ NOSER NUREG-0881 502 NUREG-0896 502	8307250079 8307150141 8307180124 8307120036 8307190446	50-445 E 50-483 E NUREQ 50-482 E 50-444 E	
NRC 69-7 DR1 EAR	8307130094 8307170139* 8307120246* 8307010051* 8307150042*	50-470 A 50-267 P 50-346 P TOPREP 71-6679		NUREG-0938 NUREG-0948 VOI ERR NUREG-0974 NUREG-0983 NUREG-0994	0307050471 0307200107 0307050479 0307110313 0307050490	NUREG 50-537 E 50-352 D 50-192 E 70-734	1
1 3 RO2 :5-NP-A :39-1 ROO	8307130325* 8307270180* 8307010184* 8307270425* 8307180138*	50-454 A 50-439 Q 50-470 A TOPREP 50-237 P		NUREG-0998 NUREG-1011 NUREG/8R-0025 VO9 N6 NUREG/8R-0069 NUREG/CR-2000 VO2 N5	8307220626 8307250323 8307150155 8307110087 8307120021	NUREG 30-266 P NUREG NUREG NUREG	ORNL/N810-200
139-2 R00 139-3 R00 139-4 R00 139-4 R00 139-7 R00	8307180147# 8307180152# 8307180158# 8307180179# 8307180186#	50-237 P 50-237 P 50-237 P 50-237 P 50-237 P		NUREO/CR-2284 NUREG/CR-2335 NUREG/CR-2397 NUREG/CR-2475 NUREG/CR-2475	8307150357 8307210265 8307250159 8307250530 8307180148	NUREO NUREO NUREG NUREG NUREG	SAND81-1755 EGG-2200 DRNL/CSD-90 BNL-NUREG-51492
41-1 R00  41-2 R00  41-3 R00  41-4 R00  41-6 R00	8307070181* 8307070184* 8307070211* 8307070218* 8307070228*	50-237 P 50-237 P 50-237 P	64, 305, 1100 64, 305, 1101 64, 305, 1102 64, 305, 1103 27, 0200, 2105	NUREQ/CR-2599 NUREG/CR-2634 NUREG/CR-2751 V04 NUREG/CR-2810 NUREG/CR-2814 V02	8307180143 8307250274 8307150371 8307210240 8307250095	NUREO NUREG NUREG NUREG NUREG	PNL-4190 SAND02-0676 ORNL/TM-8369/V4 ORNL/TM-8413 LA-9596-PR
41-7 R00 23 R00 V02 R06 210 7 R00	8307070239* 8307190067* 8307070105* 8307220117* 8307120282*		•	NUREO/CR-2824 VO1 NUREO/CR-2843 VO3 N4 NUREO/CR-2843 VO4 NUREO/CR-2849 NUREO/CR-2881	8307210268 8307110082 8307110308 8307250109 8307120026	NUREG NUREG NUREG NUREG NUREG	ORNL/TM-8418/V1 SAND82-1788 SAND82-1788 LA-9461-MS PNL-4293
-204 R00 R00 B 801	8307060406* 8307130322* 8307130317* 8307060411* 8307050228*	50-400 Q 50-454 A 50-454 A 50-400 Q 50-528 E		NUREO/CR-2883 VO1 NUREO/CR-2883 VO2 NUREO/CR-2883 VO3 NUREO/CR-2884 NUREO/CR-2913	8307050465 8307150131 8307150356 8307150178 8307110135	NUREG NUREG NUREG NUREG NUREG	SAND82-1796 SAND82-1796 SAND82-1796 PNL-4343 SAND82-1935
79-1 V01 R01 79-2 V02 R01 79-5 V05 R01 79-6 V06 R00	8307110727* 8307060267* 8307060285* 8307060293* 8307060313*	40-1341 50-331 P 50-331 P 50-331 P		NUREG/CR-2915 NUREG/CR-2926 NUREG/CR-2932 VO2 NUREG/CR-2938 NUREG/CR-2957	8307110087 8307210255 8307210257 8307270360 8307180139	NUREO NUREO NUREO NUREO NUREO	UCID-19457 MLM-2783 8AND81-2027 PNL-4453 PNL-4590

### REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATÉGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT	
NUREG/CR-2963	8307180165	NUREG					
NUREG/CR-2967	8307250511	NUREO	DRNL/TM-8519				
NUREG/CR-2970 VO2	8307090133	NUREG	ANL-82-42 VOL 2	SECY-82-464	8307260601#	FOIA	
NUREG/CR-3007	8307080596	NUREG	PNL-4507	SECY-83-232	8307070489	SECY	
NUREG/CR-3061	8307130147	NUREG	PNL-4541	8ECY-83-243	8307050502	SECY	
		,,,,,,	, we 4941	SECY-83-248	8307110103	50-272	5
NUREG/CR~3068	8307250080	NUREG	EGG-2233	SECY-83-267	8307250565	SECY	IEB-82-03
NUREG/CR-3133	8307270319	NUREG	UCRL-53948			SEC I	154-88-03
NUREG/CR-3142 V01	9307120012	NUREG	OURL-33140	BECY-83-267A	9307250578	50~259	
NUREG/CR-3142 VO2	8307120009	NUREG		SMA 13701.05R003 V03	8307290118*	50-329	7
NUREG/CR-3160	8307120016	NUREG		SMA 13701.05R003 VOB	8307220411+	50~327	7
		1101124		SMA 13703.01R003 R03	8307180307*	50-155	P
NUREO/CR-3234	8307080590	NUREQ	SAND83-0635	BWR1-6582	8307060388*	TOPREP	•
NURE0/CR-3246	8307150365		9AND83-0710		0307000300*	IUPREP	
NUREO/CR-3250	B307120018	NUREG	PNL-4700	TER-C5506-130	B306140199*	50-286	O 740 41-4-
NUREG/CR-3304	8307080592	NUREO	ANL-83-37	TER-C5506-350/351 R1	#901100140#	50-237	G TAC 46840
NUREQ/CR-3311	8307150136	NUREG	ORNL/TM-8782	TER-C5506-352 DRFT	8307120149#	50-237	P TAC 46736
	504,150105	HONLY	DXMC/111-8/82	TER-C5506-382/383 DR	B307070582*	50-266	P TAC 07988
NUREQ/CR-3313	8307110124	NUREG	LMF-105	TER-C5506-386/387	8306060295*		P TAG 07727
NUREG/CR-3338	9307080602	NUREG	ANL-83-42		6306060273*	50-254	P TAC 08077
NUREQ/CR-3356	8307150137	NUREG	WWF-83-45	TER-C5506-398	B304140436*		
NUREG/CR-3:357	8307150149		930 MUDEO #4400	TR-109			P TAG 07716
NUREG/CR-3363 VOI	8307190444		8NL-NUREG-51683 TS-831-I	TR-5633-3	8307180067#: 8307010100#		<u>Q</u>
	0007170404	WORLD	12-931-1	TR-5633-4			R
NUREG/CR-3363 VO2	8307190457	NUREG	TS-831-II	TVA-TR75-1 ROA	6307290163*		R
ORNL/ENG-TM-5/R1	8307170437			144 - 1410 - 1 400	8307220316	TOPREP	
PE-452	8307060260*	71-3352 50-508 A	22482	VEP-NOS-4	8000000 A F A		
PEI-TR-83-6-8A	8307110064*	50-261 P		VEP-NOS-4	8307250451		P 410
PE1-TR-83-4-8B	8307110084* 8307110077*	50-261 P		WAPD-LP(CE)-256	8307250320		P 405
121 (11 43 4 45	930/1100//*	30-581 h		WAPD-RS(CC) RO1	8307290367*	71-6400	NRF8304459
PGE-1039	B307190224*	50-344 P		148	8307290370*	71-6400	
PIR 1454-294	8307200205*			HONE-TOKIT-M	8307150202*	TOPREP	
GA-014 RB	8307290375*	50-361 P		WCAP-10230			
ROE 73-8	8307270375* 8307200526*		22558	11121	8307110295*	50-315	P AEP: NRC: 05149
583-12C		FOIA			B307190257*		P
	8307120637*	50-445 A			93070B0314*	TOPREP	
SAI~186-028-29	000000000				8307080325*	TOPREP	
SAI-186-028-24	920720035B*	50-338 0		XN-NF-IA ROS	8307260440*	TOPREP	
SAI-180-026-34 10-A9-E8-278-1A8		50-219 g		VM ME 00 00			
SD-8WI-TI-107	8307140206*	50-322 A		XN-NF-83-38	B307010157#	50~282	۶
30-841-11-10/	8307220240*	WASTE MOT	00447				

Items listed as enclosures are those indicated by an asterisk following the accession number in the Indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

ACCE8910N	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	Y
B306170422	8306170412	E1/40/E8	50-397	a
B306240037	8307050333	83/06/21	50~373	Ρ
8306240426	8307200390	83/07/08	50-447	0
B306240435	8306240435	83/03/22	50-445	F
8306280580	8304280576	83/06/15	50~445	I
B30628058B	8304280576	83/06/15	50-445	1
8306280593	8306280576	83/06/15	50-445	I
8304580400	8306280576 8306280576	83/06/15 83/06/15	50-445 50-445	I I
8306280603	8307270023	83/05/13		18
6306860004				
8306280607	8304280576	83/06/15	50-445	I
8306270594	8307150256	83/07/13	PR	
B306270600	B307150256	B3/07/13	PR	
8306270603	6307150256	83/07/13	PR	
8304290405	8307150254	83/07/13	PR	
8307010005	8307010002	B3/06/14	50-410	G.
8307010012	8307010007	83/06/14	50-272	q
8307010021	B307010014	83/06/15	50-322	G
8307010023	8307010018	83/04/28	50-387	G
8307010025	8307010016	83/06/17	50-219	G
8307010032	8307010029	83/04/15	50-410	Q
8307010036	8307010029	83/06/15	50-410	G
6307010043	8307010035	83/06/14	50-322	G
6307010047	8307010038	B3/06/17	30-309	G
8307010048	B307010040	83/06/16	50-220	G
B307010051	8307010044	83/04/30	TOPREP	
8307010056	8307010052	83/06/28	50-219	Q
8307010064	B307010061	83/06/17	70-1201	
8307010080	8307010072	83/06/15	50-245	G
8307010098	8307010089	83/06/27	50-271	Q
8307010100	B307010091	B3/06/30	50-322	R
8307010109	8307010096	83/06/14	50~334	G
8307010123	8307010104	83/04/24	50-263	Р
8307010131	8307010125	83/06/24	70-698	
8307010146	8307010139	83/06/14	50-271	o.
8307010149	B307010144	83/06/24	50-282	P
8307010153	8307010144	83/06/24	50-282	P
8307010157	8307010144	83/06/24	50-282	P
8307010161	8307010132	83/06/14	50~352	G
8307010167	8307010155	83/06/14	50-245	0
8307010173	8307010169	83/04/30	50-341	ĸ
8307010174	8307010166	83/06/55	50-424	Α
8307010175	8307010169	83/06/30	50-341	ĸ
8307010179	9307010176	83/06/29	20-355	A
8307010183	8307010166	83/06/22	50-424	K
8307010184	8307010172	83/04/29	50-470	A
8307010187	8307010182	83/06/28	50-346	P
8307010189	B307010166	83/04/22	50-424	ĸ
8307010190	0307010185	83/04/30	50-352	ĸ
8307010191	8307010166	83/06/22	50-424	K

	PRINCIPAL	DATE	BUBJECT	•
ENCLOSURE	DOCUMENT	188080	CATEGOR	v
CHCCCCCC				
7905150698	8307210054	83/03/07	FOIA	
B103300508	8307290467	83/05/18	FOIA	
920B030AB2	B307250020	83/05/05	50~272	5
				•
820B040324	8307290442	83/05/18	FOIA	_
8209200358	8307060160	83/06/50	50-338	Q.
8210040160	8307060309	83/06/RB	50-219	G.
8210170031	8210190028	82/10/01	50-331	F
8210170034	8210170028	82/10/01	50-331	F
8210290407	8307260111	B3/05/11	FOIA	
8302040562	8208060366	82/07/20	50-387	P
8303220392	8307180312	83/06/27	TOPREP	
8304140030	8307260514	83/07/11	20-355	Α
8304140613	8211030148	82/10/08	50-447	Α
8304200084	8307260516	83/07/11	50-322	Α
			PR	• • •
8304200143	8307150256	83/07/13	FR	
8304200521	8307140302	83/06/24	90-369	a
8304200525	8307140302	83/06/24	50-369	G.
8304200529	8307140302	83/05/24	50-349	ā
8304270394	8307260516	83/07/11	50-322	Α
8304270048	8307260516	83/07/11	50~322	Α
8305050085	8307260516	83/07/11	50~322	Α
		83/07/11	50-322	Ä
8305050338	8307260516			
8305060655	8307260516	B3/07/11	50-322	Α
8305100010	8305100008	03/05/02	50-348	5
8305100111	8305100108	83/05/04	50-280	P
0000140111	0000100100	DD, 00, 0 .		•
			454177447	_
8305120551	8305120547	83/05/09	CONTRACT	
8305230444	8305230439	83/05/09	50-366	S
B305250555	8307200344	83/06/14	50-317	P
	8307200344	83/06/14	50-317	P
8305250564				
8305260333	8307260516	83/07/11	20~325	Α
B305260339	8307260516	83/07/11	20-325	Α
8305270427	8305270612	83/04/25	50-269	ø
B305270630	8305270412	83/04/25	50-269	e
				Ğ
8305270636	8305270612	83/04/25	50-269	
8305270643	8305270612	83/04/25	50-269	Q
B4E02040EB	8307250528	83/06/2 <b>9</b>	50-286	P
8306040295	8307180026	83/06/27	50-254	P
		83/07/11	50-322	Ä
8306080369	6307260516			
8306080373	8307260516	B3/07/11	50~322	Α
8306080379	8307260516	83/07/11	50-322	Α
8304080383	8307260516	83/07/11	50-322	Α
8306080387	8307260516	63/07/11	50-322	Ą
0960804068	8307260516	83/07/11	50~322	Α
83060B0374	8307260516	B3/07/11	50-322	Α
8306100146	8307130303	83/07/11	50-237	ρ
2200140140	220,100000		70 207	-
	MARTINE 4 ***	MB (84 (45	EA 00:	_
8306140199	8307070495	83/04/10	50-286	G
8306140436	8307290466	83/07/18	50-344	P
8304140022	8306160016	83/06/05	50-285	F
8306160669	8307090096	83/06/27	50-331	Þ
8306170416	8304170412	83/06/13	50-397	Q

ACCESS10	N NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	8UBJEC1 CATEGOR	٦Y
9307010192 8307010193	8307010185 8307010185	83/04/30 83/04/30	50-352 50-352	K	8307050215 8307050215	9307050210 9307050212	83/06/24	50-373	R
8307010194 8307010196	8307010166 8307010195	83/06/22 83/06/29	50-424 50-237	K K	6307050218	8307050210	83/06/30 83/06/24	50-492 50-373	Q Ft
8307010197	8307010166	83/04/25	50-424	ĸ	8307050220 8307050223	8307050210 8307050210	83/06/24 83/06/24	50-373 50-373	R
8307010198 8307010201	8307010195 8307010195	83/06/29 83/06/29	50-237 50-237	K	8307050225 8307050228	8307050210 8307050211	83/06/24	50-373	R
8307010204 8307010203	8307010166 9307010166	83/04/55	50-424	К	8307050229	8307050210	83/06/30 83/06/24	50-528 50-373	E
8307010209	8307010166	83\09\55 83\07\55	50-424 50-424	K	8307050233 8307050235	8307050210 8307050210	83/06/24 83/06/24	50-373 50-373	R
9307010210 9307010213	8307010166 8307010166	83/06/22	50-424	К	8307050234	9307050231	83/06/27	50-261	G
8307010214	8307010166	83/06/22	50-424 50-424	K	8307050239 8307050247	8307050210 8307050244	83/06/24 83/06/29	50-373 50-529	R
8307010215 8307010216	9307010166 9307010166	83\09\55 83\09\55	50-424 50-424	K	8307050251 8307050253	B307050244 B307050245	83/06/29 83/06/30	50-529 50-275	Q R
8307010217 8307010219	8307010166 8307010166	83/06/22	50-424	ĸ	B307050257	8307050254	83/07/01	50~289	Q
8307010220	8307010166	83/04/22	50-424 50-424	K	8307050262 8307050285	8307050249 8307050284	83/05/23 83/05/06	50-10 CONTRACT	a
8307010221 8307010222	8307010166 8307010166	83/04/55 83/04/55	50-424 50-424	K	8307050321 8307050327	8307050317 8307050326	83/04/23 83/06/13	CONTRACT	
8307010223	0307010166	83/06/22	50-424	к	8307050328	8307050324	93/06/20	CONTRACT	
8307010225 8307010226	8307010146 8307010164	83/07/55	50-424 50-424	ĸ	8307050345 8307050357	8307050342	83/06/17	20-282	P
8307010227 8307010228	8307010166 8307010166	83/06/22 83/06/22	50-424	K	8307050374	8307050355 8307050367	83/06/15 83/06/13	PROJ PR	
B307010230	8307010166	83/05/22	50~424 50~424	K	8307050376	8307050371	83/04/10	50-286	P
8307010231	6307010166	83/06/22	50-424	K	8307050378 8307050427	8307050367 8307050421	83/06/13 83/06/14	PR MISC	
8307010233 8307010234	8307010166 8307010166	83/06/22 83/06/22	50-424 50-424	K	8307050453 8307050458	8307050449 8307050457	83/06/17 83/06/17	50-247 50-272	Q F
8307010235	<b>83</b> 07010166	83/06/22	50-424	K	8307050463	8307050457	83/06/17	50-272	F
8307010237 8307010238	8307010166 8307010166	83/06/22 83/06/22	50-424 50-424	K	830705049& 8307050505	9307050495 9307050501	83/06/03 83/06/27	CONTRACT	
8307010239 8307010241	8307010166 8307010166	83/06/55	50-424 50-424	K	8307050527	8307050522	83/06/24	SO-456 Review G	Q qq
8307010242	B307010166	83/06/22	50-424	ĸ	B307050530 B307050534	8307050522 8307050522	83/06/24 83/06/24		RP RP
8307010244 8307050008	9307010166 9307050002	83/06/21	50~424 50~267	K R	8307060019	8307060015	83/07/07	50-285	Œ
B307050012 B307050017	8307050007 8307050006	83/06/29	50-155	Р	8307060023 8307060025	8307060018 8307060013	83/07/01 83/06/17	GA979 50~528	8
8307050020	6307050011	83/06/58 83/06/58	50-329 50-454	R	8307060029 8307060037	8307040022 8307040030	83/06/20 83/06/30	50-244 50-293	G G
8307050029 8307050032	8307050023 8307050011	B3/04/30	50-333	F	8307040040	8307060033	83/06/30	50-285	G.
8307050033	8307050024	83/06/29 83/06/28	50-454 50-373	0	8307060043 9307060048	8307060035 8307060030	83/06/21 83/06/30	50-443 50-293	A Q
8307050034 8307050061	8307050023 8307150256	83/05/30 83/07/13	50-333 PR	F	8307060093 8307060100	9307060097 9307060096	83/06/06	GA999 GA999	_
8307050062	B307050054	83/06/22	50-315	8	8307060104	8307060096	83/06/04	QA777	
8307050063 8307050048	B307050057 B307050054	83/06/27 83/06/22	50-412 50-315	G S	8307060104 8307060109	8307060079 8307060103	83/06/29	50-341	G
8307050079 8307050089	9307050072 9307050081	83/06/28	50-313 70-25	ř	8307060110	8307060101	83/06/24 83/06/30	0A999 50-416	1
8307050094	8307050084	83/06/30	50-387	G	8307060112	0307060096	83/06/06	GA999	
8307050078 8307050102	8307050092	83/07/01	50~282	P	8307060113 8307060114	8307060101 8307060099	83/06/30 83/06/29	50-416 50-341	I G
8307050110	8307050092 8307050100	83/07/01 83/06/27	50-282 50-247	P H	8307060124 8307060127	8307060117 8307060121	83/06/20 83/06/30	50-271 50-400	Ä
8307050111	8307050101	83/06/27	50-329	H	8307060133	8307060071	83/06/29	50-327	R
8307050116 8307050121	B307050100 B307050119	83/06/27 83/06/16	50-247 50-247	H	9307040134 9307040139	8307060131 8307060131	83/06/20	50-316 50-316	G
8307050129 8307050137	8307050119 8307050134	83/06/16 83/06/30	50-267 50-275	Q R	8307060140	B307060136	83/06/20 83/06/30	50-334	Q K
0307050138	8307050132	83/06/15	50-445	Ġ	8307060141 8307060153	8307060135 8307060145	83/05/04 83/06/30	50-285 50-445	G G
6307050141 6307050143	8307050136 8307050134	83/06/23 83/06/30	50-397 50-275	E R	8307060174	8307040140	83/06/20	50-338	G
B307050149 B307050151	B307050134	83/06/30	50-275	R	B307060176 B307060180	8307040140 8307040178	83/04/20 83/07/01	50-338 50-275	Q F
8307050151	8307050136 8307050145	83/06/23 83/06/24	50-397 50-289	Þ	8307060183 8307060185	8307060182 8307060182	83/06/30 83/06/30	50~423 50~423	G G
8307050156 8307050160	9307050134 9307050134	83/06/23 83/06/23	50-397 50-397	Ē	8307060187	8307040184	83/04/2B	50-244	P
B307050161	B307050145	83/06/24	50-289	E P	830706018 <del>7</del> 9307060192	9307040198 9307040198	83/06/09 83/06/09	QA999 QA999	
B307050162 B307050165	8307050152 8307050136	83/05/03 83/06/23	50-247 50-397	P E	8307060199 8307060202	8307060196 8307060196	83/07/01 83/07/01	50-275 50-275	P P
8307050166 8307050167	8307050158	83/06/29	50-416	Q	8307060212	8307060207	83/06/30	50-261	
8307050169	8307050136 8307050152	83/05/03 83/05/03	50-397 50-247	E	8307060213 8307060215	8307060209 8307060210	83/06/30 83/06/01	50-250 GA999	P
8307050173 8307050175	8307050136 8307050158	83/06/23 83/06/29	50-397 50-416	E Q	8307060221 8307060232	8307060210 8307060228	83/06/01 83/06/24	GA999 50-397	_
8307050181	B307050158	83/06/29	50-416	G.	8907040235	8307040228	83/06/30	50-397 50-280	8 P
8307050188 8307050197	8307050184 8307050193	83/06/28 83/06/28	50-329 70-2974	H	9307060237	8307060228	83/06/24	50~397	8
8307050205 8307050213	8307050198 8307050210	83/06/27 83/06/24	50-400	Q	9307060243 8307060246	8307060236 8307060241	83/06/17 83/06/30	50-224 50-382	G G
HIVIVIUEIS	CHANGORIO	43/00/24	50-373	R	8307060260	8307060255	83/06/15	50-508	A

ACCESSION	1 NUMBER					ACCESSION				
ENGLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT		EA	CLOSURE	PRINCIPAL DOCUMENT	DATE 199UED	SUBJECT CATEGORY	,
8307060264	8307060257	83/06/30	50-482	F		307070484	9307070480	83/06/24	CONTRACT	
8307040267	8307060249	QE\40\E8	50-331	P	83	107070490	8307070488	83/06/27	CONTRACT	_
8307040281 8307040285	8307060274 8307060249	83/07/01 83/06/30	0A999 50-331	P			8307070495 8307070503	83/06/10 83/06/08	50-286 CONTRACT	Œ
8307060288	8307040280	83/06/30	50-482	S			8307070554	83/06/24		P
8307060289	0307040203	83/06/29	0A999	_			B307150395	83/06/30		P
8307060291 8307060293	8307060282 8307060249	83/06/29 83/06/29	50-313 50-331	Q. P			8307080009 8307080009	83/06/22 83/06/22		Q G
8307060294	B307040175	83/06/29	50-155	₽	63	307080019	83070B0015	83/07/05	50-409	Œ
8307040299	0307060207	83/05/17	50-321	æ	83	307080023	8307080021	83/06/24	50-263	a
8307040303 8307040308	8307040294 8307040249	83/04/20	50-255	Q: P		107090026 107080204	9307080021 9307080198	B3/06/24		G .
8307060313	8307060249	83/06/30 83/06/30	50-331 50-331	P			8307080236	83/06/30 83/06/24		K
8307060318	8307040309	83/06/28	50-217	Q.		107080263	8307080254 8307080278	83/06/13		Q.
8307060322	8307060309	83/06/28	50-217	G.				B3/06/23		Q
8307040324 8307040328	8307060315 8307060315	83/06/50 83/06/50	50~292 50-282	Q:			8307080286 8307080283	83/06/24 83/07/05		Q Q
8307060330	8307060326	83/06/09	QA999	-	83	107080292	8307080286	83/06/24		ũ
8307060336 8307060341	8307060326 8307060337	83/06/09 83/06/02	0A999 0A999				8307080304 8307080306	83/06/24 83/07/07	TOPREP 50-249	P
										,
8307060344 8307060347	8307040339 8307040337	83/07/01 83/06/02	50-440 QA999	<b>Q</b>			8307080304 8307080259	83/06/24 83/06/22	TOPREP 50-255	P
8307060350	6307060337	83/04/03	0A979				8307080314	83/06/20	TOPREP	г
8307060352	0307060346	83/06/30	50-321	G.			8307080316	83/06/20	TOPREP	
8307060356	8307060349	83/06/30	50-329	G		-	8307080259	83/06/22	50-461	A
8307060360 8307060365	8307040353 8307040358	83/06/05 83/06/02	0A999 0A <del>999</del>				8307080329 8307080259	83/06/22		G.
8307060366	6307040359	83/04/20	71-494		63	307080336	6307080327	83/04/30	50-374	G
8307060369 8307060374	8307040343 8307040358	83/06/02	50~142 0A999	G			8307080259 8307080344	83/06/22 83/07/05	50~284 MISC	þ
							·	•		_
9307060380 9307060382	8307060373 8307060358	83/06/21 83/06/02	50~309 0A999	P			8307080342 8307080259	83/06/30 83/06/22		Ð
B307060384	8307060376	83/06/15	50-312	F	83	307080358	8307080259	83/06/22	50-259	P
8307060386 8307060388	83070603 <b>8</b> 3 8307060385	83/06/30 83/06/24	50-400 TOPREP	Ģ			8307080257 8307080368	83/06/30 83/06/30		P Q
·				_						
8307060391 8307060392	8307060383 8307060389	83/06/30 83/06/13	50-400 50-286	P			8307080375 8307080381	83/07/05 83/06/29		Q G
8307060399	8307060396	83/07/01	50-358	Ġ.	83	307080396	8307080387	B3/07/07	50-255	P
8307040403 8307040405	8307060396 8307060397	83/07/01 83/07/01	50-358 50-275	9			83070803B7 8307080402	83/07/07 83/07/01		P K
8307060406	8307060383						8307080404	83/06/28	71-9094	
8307060406	8307060401	83/06/30 83/06/30	50-400 27-48	Ģ			83070B0404	B3/07/01		F
8307060411	6307040363	83/06/30	50-400	0			8307080434	83/07/05		P
8307060415 8307060416	8307060397 8307060408	83/07/01 83/06/30	50-275 50-528	Ģ.			8307080435 8307080446	83/06/22		D G
8307040417	8307060412	83/06/30	50-142	G	85	307080451	B3070B044B	83/07/05	50-440	G
8307060419	8307040412	83/06/30	50-142	Ğ	83	307080452	8307080445	63/06/30	50~522	Ď
8307060420 8307060426	0307060408 0307060408	83/06/30 83/06/30	50~528 50~528	Gi Gi			8307080455 8307080468	83/07/01 83/07/06	70-143 50-440	G.
8307060427	8307060408	B3/06/15	50-312	F			8307080467	83/06/09	40-4244	•
8307060433	9307060430	83/06/24	50-312	P	83	307080480	83070B0457	83/06/09	40-6264	
8307060441	8307060437	05\40\60	50-275	Ģ			6307080467	83/04/09	40~4264	_
8307060443 8307060489	8307060439 8307060485	93/06/24 83/06/23	50~269 WASTE MG	U IT			8307080500 6307080500	83/06/24 83/06/24		D D
8307060497	8307040493	83/06/23	40-6940	•			8307080500	83/06/24		D
8307040432	8307040429	83/06/21	50-284	н		307080527	8307080500	83/06/24	50-352	D
8307070005	8307070003	83/07/01	50-328	p.		907080551 907080563	6307080547 8307080557	83/06/27 83/06/27	CONTRACT	
8307070011	8307070003 8307070006	83/07/01	50-328 50-397	Ä		307080595	B3070805B3	83/06/27	CONTRACT	
8307070033	8307070031	83/06/22	50-302	Þ	83	307080609	8307080605	83/06/21	NUREO	
8307070063	8307070060	83/06/30	90-483	•			8307080611	83/06/16		P
8307070067 8307070072	8307070063 830 <b>7</b> 070069	83/07/05 83/06/16	50-362 50-321	Ca P			8307080611 8307080611	83/06/16 83/06/16		₽ P
8307070105	8307070102	83/07/06	50-537	Á	83	307080455	8307080650	83/06/24	50~278	P
8307070117	8307070108	83/04/30	PR		8:	307080663	8307080650	B3/Q6/24	50-278	P
8307070119	B307070115	83/06/24	50-334	P		307080669 307080676	8307080657 8307080672	83/06/23 83/06/27	71-6404 71-9180	
9307070124 9307070154	8307070122 8307070144	83/06/24 83/06/29	50-259 50~440	P			8307090034	B3/06/07	71-500	
8307070166	8307070164	83/07/05	146-06	₽			830707005B	83/06/29		P P
0307070170	8307070167	83/07/01	50-352	A			8307090094	83/06/27	70-34 I	r
9307070175	8307070172	83/06/30	50-261	œ.			8307110038	83/05/28 83/07/01	50-329 50-261	A P
9307070181 9307070184	8307070176 8307070176	83/04/27 83/04/27	50-237 50-237	₽ P			8307110058 8307110063	B3/06/29	70-1201	•
8307070211	8307070174	83/04/27	50-237	Þ	183	307110070	8307110063	83/06/29	70-1201	
9307070218	8307070176	83/06/27	50-237	P			8307110058	63/07/01		P
9307070223 9307070228	6307070174 6307070174	83/06/27 83/06/27	50-237 50-237	P P	83	307110123 307110126	8307110120 8307110120	83/07/01 63/07/01	50-346 50-346	P P
8307070239	8307070176	83/06/27	50-237	P	<b>3</b> 3	307110138	8307110133	83/06/23	30-142	G
8307070242 8307070408	8307070238 8307070404	83/04/08	50-305	G.		307110146 307110147	8307110139 8307110140	83/07/06 83/06/29	50-454 70-2950	g
930/4/9408	2307070404	83/06/13	XPORTLIC		<b>a.</b>					

ACCESS	ION NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT		SUBJE		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUDJE CATEG	
830711014 830711015 830711015 830711014	830711015 830711014	0 83/07/08 2 83/07/08	5 50-329 50-537	7 G	8307110578 8307110588 8307110589 8307110599	9307110570 9307110570 9307110570	83/06/24 83/06/24 83/06/24 83/06/24	50-324 50-324 50-324 50-289	F
8307110165 8307110166	930711015	9 83/06/24	4 50-338	} F	8307110612	8307110407	B3/06/24	50-315	F
8307110169 8307110176	830711015	9 83/06/24	50-338	F	8307110726 8307110727 8307120007	8307110723	83/06/06 83/06/06	40-134 40-134	1
8307110184 8307110187	8307110179 8307110181	83/06/24 B3/05/25	50-2B0	F	8307120011 8307120013	8307120010	83/06/27 83/06/14 83/06/14	50-263 50-482 50-482	G.
8307110197 8307110200	8307110193	93/06/29	50-316		9307120027 9307120031	8307120023 8307120025	83/06/24 83/06/24	50-286 50-244	F
8307110209 8307110220	8307110205				8307120032 8307120037		83/06/24 83/06/24	50-286	F
9307110229 9307110233		93/07/07	50-333	P	9307120040	8307120033	83/06/24	50~244 50~255	F
8307110237 8307110255	8307110235	83/06/29	50-312	P	8307120043 8307120044	8307120039 8307120033	83/06/24 83/06/24	50-317 50-255	F
8307110260	8307110256	B3/07/0B	50-413	Q Ç	8307120046 8307120049	8307120042 8307120042	83/06/24 83/06/24	50-382 50-382	F
8307110264 8307110265	8307110256 8307110251			G G	8307120050	8307120049	93/06/24	50-255	F
8307110266 8307110270	8307110259 8307110256	83/06/22	50-220	a	B307120052 B307120064	8307120051 8307120058	83/06/24 83/06/24	50-289 50-304	F
8307110273	8307110256	83/07/08	50-413 50-413	G	8307120068 8307120073	8307120062 8307120069	83/06/24 83/06/24	50-254	F
8307110276 B307110279	8307110268 8307110256		50-461 50-413	g C	8307120083	8307120080	83/06/24	50-289 50-317	F
9307110287 8307110289	8307110280 8307110254	83/06/24	50-322	Q	8307120101 8307120128	8307120096 8307120125	83/07/08 83/06/24	70-1359 50-254	) P
8307110292 8307110293	8307110256 8307110256	83/07/08 83/07/01 83/07/08	50-413 50-412 50-413	G G	9307120145 9307120149 9307120169	8307120137 8307120146 8307120156	83/06/23 83/06/23 83/07/08	50-254 50-331	F
8307110295	8307110290	83/07/05	50-315	P				50-537	Ŧ
8307110297 8307110302	8307110254 8307110254	83/07/08 83/07/08	50-413	Ģ	8307120174 8307120188	8307120156 8307120156	83/07/08 83/07/08	50-537 50-537	T
8307110312 8307110321	8307110298 8307110317	83/07/08 83/04/24	50-413 REVIEW 50-397	GRP F	8307120193 8307120197 8307120203	9307120156 9307120156 9307120156	83/07/08 83/07/08 83/07/08	50-537 50-537	Ţ
8307110328 8307110329	8307110325 8307110298	83/06/24 83/07/08	50-309 REVIEW	F	8307120204	8307120201	83/04/13	50~537 GA779	Ť
8307110334 8307110340	B307110325 B307110333	93/06/24 83/06/29	50-309	F	8307120205 8307120209	8307120198 8307120201	03/07/01 03/06/13	50-220 GA999	K
8307110343 8307110347	8307110339	83/06/24	50-315 50-266	F	9307120211 9307120215	8307120154 8307120212	83/07/08 83/06/13	7E8-08	۲
8307 (1034B	8307110333 8307110339	83/06/29 83/06/24	50-315 50-266	5 F	8307120220	8307120156	83/07/08	50~537	۲
8307110354 8307110355	8307110352 8307110351	83/07/06 83/06/22	50-483 70-1703	G	9307120221 9307120224	8307120212 8307120213	83/06/13 83/06/30	0A999 70-1143	
8307110361 8307110364	8307110357	83/06/24	50-250	F	8307120226 8307120227	8307120218 8307120214	83/06/17 83/07/06	0A999 50-289	Œ
B307110366	9307110360 9307110362	83/07/06	50-483 50-334	G G	B307120230	8307120223	83/06/13	GA999	
8307110368 8307110372	8307110357 8307110349	83/06/24 83/06/22	50-250 50-97	F G	8307120232 8307120233	8307120156 8307120223	83/07/08 83/06/13	50-537 GA999	T
8307110377 8307110381	8307110371 8307110371	83/07/07	50-373	8	8307120235 8307120234	8307120231 8307120223	83/07/01 83/06/13	50-247 GA999	G
8307110388 8307110389	8307110386	83/07/07 83/06/24	50-373 50-247	S G	8307120237 8307120242	9307120228	83/07/05	50-346	þ
B307110391	8307110385 8307110384	93/07/01 93/07/01	50-271 70-1257	Q	8307120246	8307120240 8307120228	83/06/15 83/07/05	50-313 50-346	Q. P
8307110393 8307110396	8307110387 8307110392	83/07/07 83/06/23	PR		8307120247 8307120248	8307120240 8307120245	83/04/15 83/07/01	50-313 50-329	Ġ A
8307110400 8307110401	8307110394	83/07/01	50-333	G G	9307120259 9307120271	8307120255	03/05/23	50-247	G
8307110406	8307110397 8307110002	83/06/23 83/07/11	50-166 50-275	Q P	8307120280	8307120246 8307120266	83/07/58 83/07/58	50~315 50-315	G G
8307110417 8307110418	8307110414 8307110410	93/06/22	50-333	Q.	8307120282 8307120284	8307120278 8307120279	83/07/08 83/06/09	50-341 GA999	Ē
8307110419 8307110421	8307110411 8307110414	83/07/06	50-286 50-373	G G	8307120293 8307120300	8307120290	83/06/17	0A999	
8307110425	8307110410	83/04/22 83/06/22	50-333 50-284	Q Q	9307120303	8307120295 8307120296	83/06/17 83/06/30	QA999 30-529	8
8307110426 9307110430	8307110422 9307110424	83/06/22	50-443	<b>Q</b>	8307120308 8307120313	8307120302 8307120309	83/07/01 83/06/22	50-338 50-397	P
8307110433 8307110434	8307110429	83/06/27 83/07/06	50-546 50-286	G P	8307120314	8307120311	83/07/08	50-309	R
8307110438	8307110411 8307110429	83/07/0 <u>6</u> 83/07/06	50-373 50-284	Q P	8307120327 8307120329	8307120324 8307120328	83/06/24 83/06/17	50-275 QA979	R
8307110469	8307110463	83/06/24	20-550	ā	8307120333 8307120334	8307120330 8307120328	83/07/07 83/06/17	50-352 GA997	A
8307110479 8307110487	8307110474 - 8307110480	83/06/24 83/07/06	50~280 50~244	F	8307120339	8307120337			_
8307110503 8307110505	8307110498 8307260516	83/06/24	50-266 50-271	Q G	8307120347	8307120342	83/07/08 83/07/07	50-261 50-320	Q P
8307110518	8307110515	83/07/11 83/05/26	50-322 70-135	A	8307120352 8307120361	8307120342 8307120356	83/07/07 83/07/06	50-320 50-338	P
8307110526 8307110539	8307110524 8307110536	83/05/02 83/05/02	70-371 50-244	G	8307120367 6307120369	8307120350 8307120364	83/07/07 83/07/05	50-322 50-266	Ö P
8307110563 8307110564	8307110559 8307110555	83/06/24 83/06/27	50-409 50-329	F	8307120377 8307120392	8307120366 8307120386	83/06/27	50-528	B
8307110573	8307110568	83/06/28	50-361	A P	8307120399	8307120397	83/07/01 83/06/30	50-280 PROJ	F
					8307120401	8307120400	83/07/08	50-315	P

ACCESSION	NUMBER				ACCESSIO	NUMBER			
	PRINCIPAL	DATE	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE GBUSBI	SUBJECT CATEGOR	Y
ENCLOSURE	DOCUMENT	19SUED	CATEGORY	·-	8307130290	8307130280	83/07/11	50-454	G.
8307120413 8307120414	8307120411 8307120405	83/07/08 83/06/17		P Or	9307130291	0307130270	83/07/01	50-275	P P
8307120415	8307120411	83/07/08	50-346	P	8307130298 9307130302	8307130278 8307130278	83/07/01 83/07/01	50-275 50-275	P
8307120426 8307120430	8307120381 8307120425	83/07/08 83/06/06		Q Q	8307130304	8307130300	83/07/06	50-358	Α
8307120432	8307120429	83/07/05	50-245	G	8307130308	8307130303	83/07/11	50-237	P P
8307120438	8307120435	B3/07/05	50~265	P	9307130310 9307130313	8307130307 8307130307	83/07/07 83/07/07	50-407 50-454	Ā
8307120439 8307120446	B307120434 B307120435	83/07/07 83/07/0 <b>5</b>		Q P	8307130317	8307130309	83/07/0 <b>7</b> 83/07/04	50-454 50-445	A F
8307120447	6307120440	83/05/23		G	8307130319	8307130316			
8307120451	8307120445	83/07/08		P	8307130322 8307130325	B307130309 B307130309	83/07/07 83/07/07	50~454 50~454	A
8307120454 8307120457	8307120449 8307120453	83/07/01 83/06/17	50-285 GA999	a	6307130328	8307130309	83/07/07	50-454 50-454	A A
8307120462	B307120453	B3/06/17	0A999	a	9307130330 9307130331	8307130309 8307130309	83/07/07 83/07/07	50-454	Ä
8307120464	8307120456	83/07/01			8307130333	8307130309	83/07/07	50-454	Α
8307120465 8307120472	8307120460 8307120456	83/07/01 83/07/01	50-285 50-387	Q G	8307130367	8307130365	83/06/20	40-84 <b>98</b> 50-328	P
8307120475	8307120463	83/07/08	50-334	G	8307130383 8307140007	8307130354 8307140004	83/07/01 83/06/28	50-247	U
8307120476 8307120487	8307120471 8307120482	83/07/01 83/07/01	50-482 50-285	G G	8307140009	8307240134	83/07/20	50-250	8
	8307120487	83/05/18	50-285	G	B307140030	8307140026	83/06/22	50-269 50-329	Q Ø
8307120492 8307120494	8307120488	83/06/15	50-482	œ.	8307140038 8307140041	8307140032 8307140035	83/07/01 83/06/16	50~259	Q
8307120497 8307120498	8307120487 8307120488	83/05/18 83/06/15	50-285 50-482	G G	8307140044	8307140032	93/07/01 93/06/23	50-327 50-257	G G
8307120505	8307120486	83/05/16	50-458	Œ	8307140053	8307140046			
8307120506	B307120502	83/06/22	50-483	G	9307140066 9307140069	8307140060 8307140064	93/06/13 83/06/24	50-261 50-390	G G
8307120508	8307120503 8307120511	83/07/04 83/06/20	50-352 50-312	G.	8307140073	07001170EB	83/06/23 83/07/01	50~413 50~454	Q G
8307120519 8307120522	8307120512	83/06/24	50-275	ğ	8307140074 8307140077	8307140071 8307140072	B3/06/24	50-327	ã
8307120523	8307120514	83/06/14	50-285	G	8307140080	8307140075	83/06/30	50-493	0
8307120531	8307120520	83/06/09 83/06/29	50-498 50-397	Q G	8307140086	8307140079	83/06/29	50-57	() ()
8307120537 8307120542	9307120532 9307120538	83/06/28	50-263	Ġ.	8307140988 8307140089	6307140083 9307140081	83/06/24 83/06/24	50-250 50-261	Ğ.
8307120547 8307120549	8307120538 8307120541	83/06/28 83/06/27	50-263 50-528	G G	8307140092		83/06/24	50-327	G
			50-361	g.	B307140103		83/04/24	50-389	Q
8307120551 8307120564	8307120540 8307120560	83/06/27 83/06/23	50-528	G	6307140104 9307140114		83/06/27 83/07/06	70-687 50~348	P
8307120566	8307120561 8307120563	83/07/01 83/07/07	50-338 50-247	P	B307140117	8307140112	93/02/25 82/12/01	50-389 CONTRAC	T G
8307120567 8307120568	8307120558	83/04/50	50~528	Q	B307140115				
8307120570	8307120560	83/06/23	50-528	a	9307140124 8307140127		83/06/21 83/07/01	50-416 50-272	G. H
8307120580	8307120574	83/06/28	50-358 50-358	a a	9307140133	8307140129	83/06/23	50-413 50-324	Q P
8307120584 8307120590	8307120574 8307120576	83/06/22	50-34B	ន	8307140135 8307140141		83/06/21 83/06/24	50-250	Ġ
8307120574	8307120576	83/06/22	50-348	8	8307140154		83/06/14	50-335	Q.
8307120596	8307120593	83/07/07	50-322 50-322	G	8307140154	B307140151	83/06/17	50-250 50-327	Q Q
8307120601 8307120606	8307120593 8307120593	83/07/07 83/07/07	50-322	0	830714016 830714017		83/07/11 83/06/30	50-423	Α
8307120607	8307120600 8307120600	83/06/24 83/06/24	50-315 50-315	F	830714018		83/07/01	50-374	a
8307120610			50-322	D	B30714018			50-373 50-423	Q A
8307120616 8307120624	8307120573 8307120612	83/07/07 83/06/24	50-409	F	930714019 930714018		83/02/03 83/02/03	50-364	Q
8307120626	8307120617 8307120631	83/07/06 83/06/10	50-309 50-445	Q: A	830714018	5 8307140177		50-424 50-369	G G
8307120637 8307130021	8307130018	83/06/58	50-325	P	830714019				
8307130022	8307130017	83/06/29	71-5641		830714019 830714020		83/07/11	70-143 50-322	A
B307130025	8307130018	83/06/28 83/07/07	50-325 71-500	f	830714020	8307140191	83/04/20	50-250 50-546	G G
8307130036 8307130045	8307130030 8307130039	83/06/29	71-499		930714022 830714022			50-280	a
8307130074	8307130072	93/07/08	50-275	G	830714023	1 8307140223	83/05/28	50-280	G
8307130082		83/07/07 83/06/28	50-293 50-349	P P	830714023	3 8307140232	83/06/28	50-311 50-280	e G
8307130112 8307130118		83/06/28	50-369	Р	830714023 830714023	5 0307140238	83/06/28	50-311	G
8307130127		83/07/21 83/06/27	50-272 XPORTLI	s c	830714023	6 8307140223	93/06/28	50-280	
8307130182			50-419	G	830714024				9
8307130202 8307130204		63/07/08	50-413	G	830714024 830714024	4 830510010	83/05/04	50-280	P
8307130213	8307130198	83/07/08	50-413 50-275	Q R	830714026 830714028	B30714026		50-266 70-364	
8307130214 8307130215			50-537	T					
8307130224	9307130198		50-413	0	830714026 830714026	3 930714027	9 83/06/28	70-120	1
8307130241	8307130231	83/07/08		G G	830714026 830714026	8 830714027	4 83/06/30		
8307130253 8307130260	8307130254	83/07/12	50-454	Q Q	830714020 830714020				
8307130261	8307130231	83/07/08	50-400		83071402	79 830714029	83/07/01		
8307130269			50-237 50-275	P P	83071403	5 830714030	2 83/06/24		
8307130281 8307130284	8307130280	B3/07/11	50-454	Q	83071403 83071403	0 830714030	5 83/09/54	50-36	⇒ G
8307130286	B307130278			P	83071403	15 830714031	3 83/04/27	7 50~22	
8307130289	, 500/100E0E	. 55,0,,0,							

	SION NUMBER					ACC	EGBION NUMBER			
ENCLOSURE	PRINCIPA			UBJECT			PRINCIP	AL DATE	Olin u	
				ATEGORY	Y 	ENCLOS	JRE DOCUME	NT IBBUED		
830714031 830714031	17 83071403				0	8307150	050 8307150	045 83/06/1	0 50-389	
830714032 830714032			/05 50-		ā	#307150 #307150	036 8307130			
830714033	0 83071403			1113		8307150 8307150			1 50-293	) p
830714033 830714034					G	B307150				-
830714034	4 830714033	7 83/06			Q G	8307150	081 83071500	75 83/07/1	2 50-352	
830714034 830714034					G G	8307150 8307150	099 83071500	97 83/07/08		
8307140356		83/07/			P	8307150			50-348	8
8307140351 8307140351		0 83/06/	27 50~	327 (	Œ	#307150 #307150		03 83/07/07 01 83/07/11		8
8307140354 8307140355	930714033	7 83/06/	30 50~	127 (	0 3	8307150 8307150	112 83071501	07 83/07/11	70-364	Q.
8307140356					3	8307150				P
8307140361	830714033	7 83/06/	30 50-3	129 0		9307150			50-267	Q
8307140363 8307140365	9307140333			127 G	ì	#3071501 #3071501		13 <b>83/06/2</b> 4	50-267 50-443	Œ
8307140368		83/06/				93071501 93071501	48 830715012	2 83/06/30	50~498	K G
8307140370 8307140373						93:071501			50-271	P
8307140377 8307140378	8307140364	83/06/2	23 70~1	201		83071501	75 830715017	2 83/06/30	50-277 ADVCM	G
8307140380		93/06/3 93/02/2		29 G • Prog		93071501 93071501	97 830715019		50-112 50-245	G P
8307140385	8307140381	83/06/2		•		83071502		6 83/06/27	TOPREP	r
8307140391 8307140395	8307140386 8307140390	83/06/2 83/02/0	9 50-26	36 Q		93071502 93071502			TOPREP	
8307140396 8307140398	8307140371 8307140394	83/06/2	7 50-24	14 Q		830 7 1 502; 830 7 1 502;	21 830715021	6 83/07/11	50-50B 50-250	P
B307140399	8307140389	83/04/0		_		83071502		93/07/11 7 83/07/08	50~204 0 <b>4</b> 799	Q
8307140401 8307140403	8307140393 8307140371	83/06/2	9 50-33			890715025		93/07/13	50~277	G.
8307140405 8307140407	8307140394	83/06/5	7 50-33			830715026 830715026	3 830715028	83/07/13	9A999	
B307140408	8307140394	83/06/2				830715026 830715026	4 6307150261	83/06/30	50-362 50-362	9
8307140409	8307140393 8307140404	83/06/29	7 50-33 0 50-29			830715030			9A999	
8307140410 8307140411	8307140404 8307140394	83/06/26	50-33	3 Q		830715031	1 8307150304	83/07/11	QA999 50~445	Q.
8307140413	8307140393	83/06/29	50-33			830715031 830715031	5 8307150303	B3/04/04	50-387 50-298	a
8307140415 8307140416	8307140412 8307140414	93/04/30				830715031	7 0307150312	83/07/12	50-358	Q Q
8307140417 8307140418	8307140412	83/06/30	50-25			9307 1 50311 9307 1 5032		83/07/12	50~508	F
8307140421	8307140393 8307140414	83/04/29 83/03/23				9307 1 5032; 9307 1 5033;	7 8307150322	83/07/12 83/07/12	50-358 50-358	0
8307140422 8307140424	8307140176	83/07/01		-		830715033	0307150322 0307150329	83/07/12 83/07/06	50-358 50-289	0
8307140425	8307140420 8307140419	83/03/30 83/07/12	50-331	F		83071 50332		83/07/12	50-358	0
8307140426 8307140428	8307140423 8307140423	83/04/01	70-143	ı -		83071 50341 83071 50352	8307150351	83/06/24 83/07/01	50-458	G
8307140432	8307140419		70-143			83071 50355 83071 50341	8307150949	83/07/12	50-335	G G
8307140445 8307140448	8307140440 8307140444	83/07/12 83/07/11	50-409 50-400	Q		83071 50362		93/07/08	50-275	0
8307140455 8307140457	8307140452 9307140450	83/07/12	50-322 50-142	G G		83071 50367 83071 50376	8307150364	83/04/26 83/07/01	50-397 CONTRACT	8
		83/07/12	50-89	č		8307 1 50393 8307 1 50405	8307150374 8307150390	83/06/23 83/06/21	CONTRACT RES	
B307140462	8307140456 8307140450	83/06/24 83/07/12	70-1151 30-89				8307150403	83/06/22		P
8307140465	8307140459 8307140459	83/06/28 83/06/28	50-354	Q Q		83071 50417 83071 50422	8307150413 8307150420		CONTRACT	
	8307140459	83/06/28	50-354 50-354	Q Q		8307150430 8307150435	8307150427 8307150433	H3/06/09	CONTRACT CONTRACT	
	8307140467 8307140467	83/06/27	50-321	0		83071 50437	8307150432		TOARTAGO 50~348 p	,
0307140474	8307140467	83/06/27 83/06/27	50-321 50-321	g Q		83071 50439 83071 50454	9307150438		50-225 P	
8307140483		83/06/27 83/06/16	50-321 CONTRAC	0		83071 <b>B0</b> 007	8307150453 8307180003	83/06/12	CONTRACT	
	9907140497	B3/07/01	CONTRAC			83071 80013 83071 80018	8307180011 8307180016	93/06/27	30-454 g	ì
8307140509 E	307140501	83/07/05 83/06/24	50-272 50-333	s		8307180023	8307180017		50-454 Q	'
	1007110000	B3/06/24 B3/06/24	50-220	P P		8307180030 8307180045	8307180026 8307180044	83/06/27	90-979 Q 90-954 p	
8307140517 B		3706/16	50-273	P		8307180047 8307180051	8307180044	83/07/01	10-266 G 10-266 G	
8307150016 8	30/140523	93/04/16	CONTRACT	•		9307190053	8307180050	83/07/08	0-361 8	
agg1120033 B	307150033	33/07/01 33/06/30	71-6579			8307180057	8307180050 8307180056		0-361 s	
	000	33/06/30	71-6679			93071 80058 93071 80063	8307180055 8307180062	83/06/27 5	0-271 G	
8307150042 B	307150033 8	13/04/30 13/04/30	71-6679 71-6679			8307180044	8307180062		0-373 g 0-373 g	
8307150048 B	307150045 B	3/07/01	50-416 50-389	P		8307180065 8307180066	8307180062 8307180062	83/07/11	0-373 g	
er and the St	307150044 B		50-416	P P		8307180067 8307180074	B3071800Ap	83/07/11 5/	9-973 q 9-973 q	
						8307180084	8307180071 8307180080	83/07/11 5	0~247 G	
									)-277 p	

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGOR	Y
8307180095	8307180080	83/07/08	50-277	_ Р	8307190091	8307190087	83/07/13	40-672	
8307180087	8307180080	83/07/08	50-277	þ	8307190092	8307190082	83/07/15	50-352	C
8307180091 8307180092	8307180080 8307180080	83/07/08 83/07/08		P P	8307190094 8307190095	8307190089 8307190087	83/07/13 83/07/13	50-328 40-672	P
8307180094	8307180090	83/07/13		à		8307190082	83/07/15	50-352	C
8307180107	6307180102	83/07/01	50-202	G G	8307190097	8307190087	83/07/13	40-672	
8307180112	8307180107	83/07/14		œ.	8307170101 8307170102	8307190098 8307190099	83/07/12 83/07/07	50-348 50-312	P R
8307180117 8307180124	8307180110 8307180121	83/06/28 83/07/14	70-1257 50-362	Þ	8307190104	8307190084	93/07/15	50-440	G
8307180129	8307180125	83/06/29	50-155	<b>G</b>	8307190105	8307190103	83/07/07	50-267	J
8307180130	8307180127	83/07/01	50~263	G	8307190112	B307190107	83/07/01	CONTRACT	
8307180133 8307180137	8307180127 8307180132	83/07/01 83/06/30	50-263 50-483	q q	8307190130 8307190133	8307190128 8307190132	83/07/14 83/07/15	50-309 50-250	P P
8307180136	8307070176	83/06/27	50-237	P	8307190134	8307190132 8307190135	83/07/15	50-250	p p
8307180142	8307180134	83/07/11	50-352	G	8307190137		83/07/13	50~269	
8307180147	9307070176	83/06/27		P	8307190139 8307190142	8307190135 8307190140	83/07/13 83/07/14	50-269 50-546	P I
8307180152 8307180153	8307070176 8307180145	83/06/27 83/07/15	50-237 50-382	P 0	8307190143	8307190140	B3/07/14	50-546	I
8307180157	8307180155	83/06/24 83/06/27	QA777 \$0-237	Р	8307190147 8307190165	8307190145 8307190160	83/07/13 83/07/15	50-454 50-335	g P
8307180158	8307070176								
8307180140 8307180141	8307180145 8307180155	83/07/15 83/04/24	50-382 0A999	C	8307190169 8307190177	8307190164 8307190173	83/07/15 83/06/13	50-244 50-387	G F
8307180169	8307070176	83/06/27	50-237	P	8307190180	8307190178	83/07/12	50-237	P P
8307180179 8307180180	830707017 <i>6</i> 8307180173	83/06/27 83/06/16	50-237 50-263	P P	8307190183 8307190188	8307190178 8307190184	83/07/12 83/07/15	50-237 50-369	Ŕ
					8307190189	8307190178	83/07/12	50-237	P
8307180183 8307180186	9307180174 9307070176	83/07/13 83/06/27	50-266 50-237	G P	8307190192	8307190178	93/07/12	50-237	P
8307180188	8307180184	83/06/29	GA797		8307190194 8307190195	8307190190 8307190178	83/07/15 83/07/12	50-528 50-237	F P
8307180189 8307180192	8307180185 8307180185	B3/07/01 B3/07/01	QA777 QA777		8307190201	8307170178	83/07/12	50-237	P
•				^	8307190208	8307190203	83/07/14	50-440	Q
8307180196 8307180197	8307180190 8307180184	83/07/13 83/06/29	50-482 0A999	0	8307190215	8307190213	83/07/08	50-397	Α
8307180177 8307180205	8307180195 8307180200	83/07/01 83/07/13	50-373 50-266	G G	8307170216 8307170217	8307190212 8307190213	83/07/15 83/07/08	50-443 50-397	Q A
8307180206	8307180201	83/07/14	50-412	č	8307190220	6307190212	83/07/15	50-443	<b>@</b>
8307180210	8307180209	83/06/21	QA999		8307190221	8307190219	83/07/12	50-344	P
8307180212	8307180203	83/07/13	50-322	R	8307190224 8307190225	8307190219 8307190212	83/07/12 83/07/15	50~344 50~443	P
9307190215 9307190222	8307180207 8307180203	83/04/21 83/07/13	94777 50-322	R	8307190231	6307190226	B3/07/11	50~269	P
8307180229	8307180218	83/07/13	50-266	Q	8307190232	8307190227	93/07/15	50-529	G
9307180246	8307180244	83/07/13	70-115		8307190233	8307190228	83/07/15	50-445 50-289	C P
8307180251 8307180256	830718024 <i>9</i> 8307180254	83/06/24 83/06/17	50-321 40-8380	F	8307190234 8307190238	8307170224 8307170235	83/07/11 83/07/14	50~287	P
8307180268	8307180262	83/06/27	50-269	P	B307190241	8307190212 8307190229	83/07/15 83/07/13	50~443 50~312	0
8307180272	0307180269	83/07/14	50-275	н	8307190242				•
8307180274	8307180269	83/07/14	50-275	H	8307170244 8307170246	9307190234 9307190236	83/05/03 83/05/03	71~501 71~501	
8307180276 8307180278	8307180273 8307180261	83/07/11 83/07/13	50-267 50-482	P G	8307170247	8307190212	83/07/15	50-443	Q.
8307180286	8307180284	83/07/14	50~341 50-346	8 F	8307190249 8307190254	8307190243 8307190212	83/06/23 83/07/15	50-220 50-443	R
8307180304	9307180300	83/06/24				8307190250	83/07/13	50-483	G
9307180306 9307190307	8307180300 8307180302	83/06/24 83/07/12	50-346 50-155	F P	<b>8307190255</b> 83071 <b>9025</b> 7	8307190253	83/07/06	50-213	Ρ
B307180311	8307180302	83/07/12	50-155	P	8307170258 8307170260	8307190252 8307190252	83/07/15 83/07/15	50-329 50-329	Ť
8307180315 8307180319	8307180302 8307180314	83/07/12 83/06/24	50-155 50-348	P F	8307170263	8307170259	83/07/13	50-320	Ġ
		83/06/24	50-282	F	8307190271	8307190268	83/07/13	50-382	Q
8307180326 8307180327	8307180323 8307180323	83/06/24	50-282	F	8307190272	8307170269	83/06/21	50-335 50-244	P
8307180328 8307180332	8307180325 8307180330	83/07/02 83/06/24	TOARTMOD:	F	8307190273 8307190278	8307190270 8307190274	83/07/15 83/07/13	50-289	ō
<b>030</b> 71 <b>0</b> 0332	8307270478	83/07/18	50-387	P	8307190279	9307190276	83/07/15	50-443	٢
8307180381	8307270478	83/07/18	50-387	P	8307190281	8307190276	83/07/15	50-443	Ţ
8307180404	8307160402	83/06/24	50-155	Ē.	<b>8307190285</b> 83071 <b>9028</b> 8	0307190276 0307190283	83/07/15 83/07/13	50-443 50-400	T G
8307180408 8307180409	8307180405 8307180405	83/06/24 83/06/24	50-309 50-309	F ' F	B307170299	8307190294	83/07/13	50-261 50-369	0
8307180431	8307180429	83/07/05	CONTRACT		8307190309	B307190184	83/07/15		
8307180436	8307180434	83/06/30	CONTRACT	_	9307190313 9307190339	8307190307 8307190335	83/06/10 83/07/07	CONTRAC	
8307190001 8307190015	8307180446 8307190011	83/04/15 83/07/01	50-387 70-820	P	8307190361	8307190359	83/06/16	50-263	F
B307190022	8307190020	83/07/12	50-280	P	8307190370 8307190383	8307190359 8307190376	83/06/16 83/05/03	50-263 50-317	F
8307190026	8307190024	83/06/30	70-2945						
8307190032	B307190030	83/06/29	71-5552 71-5552		8307190404 8307190418	8307190401 8307190411	83/06/29 83/06/29	71-9163 CONTRAC	T
8307190035 8307190059	8307190030 8307190057	83/06/29 83/06/28	COMMISSI	DN	8307190420	B307190415	83/07/12 83/07/14	71-9010 CONTRAC	
8307190060	8307190041	83/07/15 83/07/12	50-338 50-237	G P	8307190435 8307190444	8307190430 8307190440	83/07/14	50-3B7	`Р
9307170067	8307190062				8307190449	8307190445	83/07/13	XPORTLI	С
8307190070 8307190074	8305270407 8307190062	83/07/14 83/07/12	50-275 50-237	P P	8307190458	8307190453	83/07/07	CONTRAC	T
8307190079	8307190073	93/07/11	50-414	P	8307190481 8307190491	8307260516 8307190489	83/07/11 83/07/08	50-322 50-437	A
8307190081 8307190086	8307190076 8307190083	83/07/15 83/07/15	50-529 50-305	g K	8307200003	6307200002	83/06/30	20-355	K

	SELON NOTER				ACCESSION NUMBER		
ENCLOSUR	PRINCIPA E DOCUMEN		D CATE		PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	BUDJE CATEQI	
83072000 83072000 83072000 83072000 83072000	14 83072000 19 93072000 25 83072000	10 83/04/ 10 83/04/ 10 83/04/	28 70-14: 28 70-14: 28 70-14:	3	8307210036 8307210033 83/07/05 8307210041 8307210037 83/07/19 8307210044 8307210039 83/07/19 8307210052 8307210050 83/07/15 8307210056 8307210053 83/07/14	50-423 50-529 50-358 50-265 50-271	G
83072000: 83072000: 83072000: 83072000:	34 63072000 35 83072000 39 83072000 42 83072000	10 83/04/2 27 83/07/2 10 83/04/2 10 83/04/2	28 70-143 11 50-73 28 70-143	P	8307210061 B307210051 B3/07/13 8307210063 B307210054 B3/03/07 B307210069 B307210054 B3/03/07 8307210073 B307210054 B3/03/07 8307210073 B307210070 B3/07/05	50-247 FOIA FOIA FOIA 50-352	Q Q
930720004 930720004 930720005 930720005 930720005	930720001 90 830727047 91 830720001 93 830720001	0 83/04/2 8 83/07/1 0 83/04/2 0 83/04/2	29 70-143 28 50-387 29 70-143 28 70-143	P	8307210075 8307210054 83/03/07 8307210078 8307210070 83/07/05 8307210080 8307210054 83/03/07 8307210081 8307210077 83/03/07 8307210083 8307210054 83/03/07	FDIA 50-352 FOIA 50-440 FDIA	ĸ
830720005 830720005 830720004 830720004	8 830720001 9 830720001 2 830720001 9 830720001	0 83/04/2 0 83/04/2 0 83/04/2 0 83/04/2	8 70-143 9 70-143 9 70-143 9 70-143		8307210089 8307210086 83/07/07 8307210092 8307210084 83/03/07 8307210095 8307210086 83/07/07 8307210102 8307210084 83/03/07 8307210104 8307210054 83/03/07	70-371 FOIA 70-371 FOIA FOIA	
830720007: 830720007: 830720008: 830720008:	830720001 7 830720001 830720001 830720001	0 83/04/2 0 83/04/2 0 83/04/2 0 83/04/2	9 70-143 9 70-143 9 70-143 9 70-143		8307210111 8307210054 83/03/07 8307210118 8307210054 83/03/07 8307210118 8307210054 83/03/07 8307210124 8307210121 83/07/07 8307210133 8307210121 83/07/07	FOIA FOIA FOIA 50-443 50-443	<b>Q</b>
8307200086 8307200091 8307200096 8307200096	8307200010 8307200010 8307200010 8307200010	93/04/20 93/04/20 93/07/10 93/04/20	70-143 70-143 50-454 70-143	R O	\$307210140 \$307210123 \$3/07/14 \$307210144 \$307210125 \$3/07/15 \$307210149 \$307210139 \$3/07/08 \$307210154 \$307210147 \$3/07/06 \$307210161 \$307210152 \$3/07/18	50~293 50~329 50~461 50~374 50~445	G G G K
8307200103 8307200110 8307200116 8307200125	8307200093 8307200104 8307200109 8307200121	83/07/13 83/07/13 83/07/16 83/07/15	50-259 50-364 50-454 50-456	P P Q C	8307210173 8307210167 83/07/14 8307210181 8307210177 83/07/19 8307210191 8307210185 83/07/15 8307210200 8307210185 83/07/15 8307210201 8307210197 83/07/01	50-346 50-416 50-443 50-443 50-395	Р Р Т О
8307200134 8307200138 8307200145 8307200157	8307200126	83/07/13 83/07/13 83/06/27	50-460 50-460 50-322 CONTRACT		8307210210 8307210208 83/07/15 8307210212 8307210204 83/07/07	50-445 GA999 50-329 50-388 50-412	Q A Q
8307200170 8307200177 8307200185 8307200195	8307200166 8307200172 8307200181 9307200194	83/06/27	CONTRACT CONTRACT CONTRACT 50-280	r R	8307210217 8307210211 83/07/19 8307210219 8307210213 83/07/06 8307210224 8307210190 83/07/14 8307210226 8307210213 83/07/14	50-454 50-412 GAY79 50-412	G G
8307200198 8307200204 8307200205 8307200212	8307200188 8307200200 8307200202 8307200204	83/06/20 83/07/05 83/07/18 83/07/05	30-280 CONTRACT 50-454 50-361 CONTRACT 50-237	O P	8307210253 8307210249 83/07/13 8307210252 83/07/15 8307210254 8307210252 83/07/20	50-329 50-277 50-409 50-289	R Q H
8307200240 8307200273 8307200275 8307200356	8307200221 8307200269 8307200274 8307200357	83/07/05 83/07/14 83/06/24 83/06/29	CONTRACT 50-315 ADVCM 50-366	a a P P	8307210272 8307210259 83/07/18 8307210249 83/07/15 8307210274 8307210249 83/07/15 8307210275 8307210249 83/07/15 8307210275 8307210275	00-329 00-329 00-413 00-413	0
8307200361 8307200365 8307200369 8307200372 8307200372	8307200357 8307200364 8307200367 8307200367	83/06/29 83/06/29 83/06/14 83/06/14		P  N  N	8307210307 8307210034 83/03/07 F 8307210309 8307210034 83/03/07 F 8307210313 8307210302 83/07/13 5	0-329 F DIA DIA 0-346 F DIA	R
8307200368 8307200412 8307200417 8307200467 8307200469	8307200367 8307200380 8307200409 8307200409	83/06/14 83/07/13 83/07/11 83/07/11	COMMISSIO CONTRACT 30-466		8307210323 8307210054 83/03/07 FI 8307210325 8307210054 83/03/07 FI 8307210330 8307210054 83/03/07 FI	0-346 P DIA DIA DIA D-378	•
8307200471 8307200510 8307200511 8307200513	8307200465 8307200465 8307200505 8307200505	83/07/12 83/07/12 83/07/11 83/07/11	50-302   50-302   50-57	P P P	8307210331 8307210326 83/07/01 50 8307210338 8307210336 83/07/12 50 8307210337 8307210335 83/07/08 51 8307210341 8307210054 83/03/07/08 51 8307210347 8307210054 83/03/07/08	0-333 F 0-34 P 0-366 P 0-378	•
8307200526 B307200531 B307200543 B307210010 B307210014 B307210017	8307200523 8307200524 8307200538 8307210007	83/05/06 83/06/30 83/07/13 83/07/19	50-57 FOIA 50-254 50-410 50-498 H		8307210358 8307210054 83/03/07 70 8307210373 8307210347 83/07/01 71 8307220002 8307220001 83/03/07 F0 8307220003 8307220001 83/07/13 50	)-378 -4350 )IA  -261 G  -261 G	
8307210020 8307210025	8307210013 8307210015 8307210018 8307210023	83/07/18 83/06/10 83/07/06 83/07/06	50-317 x 40-8681 50-293 G 50-322 G		8307220004 8307220001 83/07/13 50 8307220005 8307220001 83/07/13 50 8307220006 8307220001 83/07/13 50 8307220028 8307220015 83/07/13 50 8307220024 8307220015 83/06/28 50	-241 Q -241 Q -241 Q -241 Q -335 Q	

MACHICISHIES	ACCESSION						ACCESSION				
BEDT/920031   S07200018   S0720018   S0720		PRINCIPAL			,	ENG.		PRINCIPAL			,
BADYZEONES											-
Biolife					Q.						
BGD7220015 GD7220016 GD7210016 GD721017 GD721016 GD722017	B307220054			FOIA							
BO072800078   BO07280079   BO07280079   BO07280078   BO					Q				83/07/13		
BO072800078   BO07280079   BO07280079   BO07280078   BO	BARRECTARA	B307210054	83/03/07	FOTA		830	07220476	8307220463	83/07/19	50-237	a
Security	8307220065	8307220059	日3/07/14	50-395		830	7220479	8307220445	83/07/15		
Sacrigacions   Sacr											
S007220076					_	930	07220494	8307220488	83/06/58	50-389	a
8007220058	8307220075	8307220057	83/05/11	CONTRACT							
S0072200095					a						
BADYZEO104   BADYZEO104   BADYZEO104   BADYZEO104   BADYZEO105   BADYZEO104   BADYZEO106   BAD	8307220087	8307220085	83/07/20	50-344		830	07220507	8307220491	83/07/11	50-416	
Section	8307220071	8307220085	83/07/20	50-344	×						
Secretarion											
Section					•	830	07220516	8307220491	83/07/11	50-416	_
BO77220151					Т						
September   Sept					_			0207220621	02/07/10	70~2204	
B307220137   B307220038   B3707/119   B0-400   B307220039   B3077/119   B0-400   B307220039   B307220039   B3077/119   B0-300   B307220039   B307220039   B3077/119   B0-300   B307220039   B3077/119   B0-300   B307220039   B3077/119   B0-300   B307220039   B3077/119   B0-300					ī			8307220522	83/07/12	50-438	
19-07-201-04   19-07-201-05   19-07-05   1	8307220117	8307220089	83/03/18	WASTE MG	r						
Bary					Q						
B307220214   B307220213   B307711   B30-400   B30722037   B30722038   B30772038   B30722038   B30722038   B30722038   B30722038   B30722038   B30722038   B307722038   B30722038   B307722038   B30722038   B307722038   B307713   B0-388   B307722038   B307722038   B307713   B0-388   B307722038   B3077220	B3A7320134	930799019B	B3/07/05	50-286	P	83	07220534				
Section   Sect	8307220135	8307220130	83/07/15	50-400	G						
Section   Sect						83	07220539	8307220520	83/07/13	50-348	Q
BEST/220076   BEST/2200776   BEST/22007776   BEST/2200776   BEST/2200776   BEST/2200776   BEST/2200776   BEST/2200776   BEST/22007776   BEST/22007777777777777777777777777777777777						83	07220540	8307220528	83/07/15	50-259	Q
Ba07/220270   Ba07/220204	9307220148	8307220130	83/07/15	50-400	G G	83	07220541				
BO072202140   BO07220214   BO07220214   BO0722024   BO07220214   BO0	8307220207					93 93	07220543				
B307220241   B307220248   B3077100   50-438   0   B307220353   B307220340   B30720340   B307220340   B30722	8307220220		83/06/28	50-338	Q.	83	07220549				
B307/220244	<b>83</b> 07220240	8307220236	83/05/20	WASTE MG	T						
Ba07220047											
Ba07220224   Ba07220224   Ba07220270   Ba072202020   Ba07220200   Ba072202020   Ba072202020   Ba072202						63	07220559	8307220548	83/07/13		
B307220276   B307220270   B307220270   B307220270   B307220270   B307220270   B307220270   B307220270   B307220270   B307220270   B307220281   B30	B307220267	B307220224									
B307280276   B307280277   B30728027	830/5505/3					92	94800070	B3079205A2	B3/07/13	50-324	Ġ
Biologacia   Bio						83	107220571	0307220542	83/07/13	50-324	G
Sany	8307220292	9307220285	83/07/18	50-498							
B307220307   B307220394   B3/07/19   S0-324   C   B307250025   B307250020   B3/05/03   S0-334   C   B307250039   B3/05/03   S0-334   C   B307250039   B3/05/03   S0-334   C   B307250039   B3/05/03   S0-334   C   B307250031   B307250030   B3/05/03   S0-334   C   B307250031   B307250031   B3/05/03   S0-334   C   B307250031   B3/05/03   S0-334   C   B307250031   B3/05/03   S0-334   C   B307250031   B3/05/03   S0-334   C   B307250031   B3/05/03   S0-324   C   B307250031   B3/05/03   S0-272   P   B307250031   B3/05/03   S0-273   P   B307250031   B30									B3/07/14	PR	
Sa07220309   Sa07220309   Sa07710   So - 348   Sa07250020   Sa072500	B307770307	Apencethra	83/07/13	50-324	G						
B307220314   B307220303   B3106/10   B3106	8307220309	8307220306	83/07/18	50-249	P						
Sacration   Sacr						83	307250033	8307250020	83/05/05		
B307220317   B307220324   B3/07/13   S0-324   S3/07/15   S0-348   S3/07/20320   B3/07/20320   B3/07/15   S0-348   S3/07/20320   B3/07/20320   B3/07/15   S0-348   S3/07/20320   B3/07/20320   B3/07/10   B3/07/20320   B3/07/20320   B3/07/10   B3/07/20320				50-348	ន	63	307250038	8307230050			,
B307220329   B307220303   B3/07/15   50-348   B307220328   B3/07/15   50-348   B307220329   B3/07220328   B3/07/15   50-349   B307220330   B3/07220326   B3/07/15   50-349   B307220331   B307220326   B3/07/15   50-349   B307220331   B3/07220326   B3/07/15   50-349   B3/07/20326   B3/07/20326   B3/07/15   S0-349   B3/07/20326   B3/07/15   B3/07/15   B3/07/20326   B3/07/20326   B3/07/20326   B3/07/20326   B3/07/15   B3/07/15   B3/07/20326   B3/07/20326   B3/07/20326   B3/07/15   B3/07/15   B3/07/2040   B3/07/2040   B3/07/2040   B3/07/2040   B3/07/2040   B3/07/2040   B3/07/2040   B	8307220317	8307220294									
Signotation						83	307250044	8307250020	B3/05/05		P
B307220332   B307220326   B3/07/15   S0-389   G   B307250041   B307250020   B3/05/05   S0-344   P   B307220336   B307220338   B3/07/15   S0-389   G   B307250049   B307250020   B3/05/05   S0-334   P   B307220337   B307220326   B3/07/15   S0-389   G   B307250049   B307250020   B3/05/05   S0-344   P   B307220337   B307220326   B3/07/15   S0-389   G   B307250040   B307250020   B3/05/05   S0-334   P   B307220339   B3/07/12   S0-400   G   B307250040   B307250020   B3/05/05   S0-334   P   B307250041   B307250032   B3/05/05   S0-345   P   B307250044   B307250084   B3/07/19   S0-349   P   B307250044   B307250084   B3/07/19   S0-349   P   B307250049   B307250084   B3/07/19   S0-344   P   B307250034   B3/07/19   S0-344   P   B30725034   B3/07/19   S0-344   P   B30725034   B3/07/19   S0-344   P   B30725034   B3/07/19   S0-344   P   B30725034   B3/07/19	8307220330	8307220326	83/07/15	50-389	œ						
BB07220335   BB07220326   BB 70712   BB 70720336   BB 70720326   BB 70		8307220326			_				83/07/08	50-344	p
B307220337   B307220326   B3/07/15   B0-389   B307250054   B307250020   B3/05/05   S0-334   B307250034   B3072500329   B3/05/05   S0-334   B307250034   B307250032   B3/05/05   S0-334   B307250034   B307250032   B3/05/05   S0-334   B307250034   B307715   B307250034   B307714   B307220403   B307220402   B307220402   B30721034   B307250						83	307250049	8307250020	83/05/05	50-334	5
S307220340   S307220325   S3707/12   S0-400   S307250060   S307250020   S3707/12   S0-400   S307250060   S3072719   S0-369   F S307250060   S307250060   S307714   S0-369   F S307250060   S307250060   S3072714   S0-369   F S307250060   S307250060   S3072714   S0-360   F S307250060   S307250060   S3072714   S0-360   F S307250060   S307250060   S307714   S0-360   F S307250060   S307250060   S307714   S0-360   F S307250060   S3072714   S0-360   F S307250060   S3072714   S0-360   F S307250060   S307714   S0-360   F S307250060   S307711   S0-360   F S307250060   S307710   S0-360   F S307250060   S307250060   S307710   S0-360   F S307250060   S307710   S0-360   S307710   S0-360   F S307250060   S30771	8307220337	8307220326	83/07/15	50-387	G					50-334	8
B307220341   B307220326   B3/07/15   50-387   Q   B307250047   B307250084   B3/07/17   50-369   F										50-334	Q
Sagorazo341   Sagorazo325   Sagor7/12   So-400   G											
B307220344   B307220347   B307220347   B3072118   B307230104   B307230107   B3072		8307220333	83/07/12	50-400	G	80	307250087 307250082			70-369	F
B307220395   B307220354   B3/07/19   50-454   0   B307250110   B307250101   B3/07/19   50-269   F	8307220344					8:	307250104	8307250100	83/07/14		
B307220378   B307220380   B3/07/15   B307230112   B307250103   B3/07/10   B3/07/1						8:	307250107				
B3072203P3   B3072203B0   B3/07/15	8307220339	8307220356	83/07/15							50-344	
## B307220387 ## B307220381 ## B307220381 ## B307230181 ##	8307220378	8307220376	83/07/19			es	307250113	8307250108	83/07/20	50-331	
B3072203B7   B3072203B1   B3/07/15   S0-335   G   B307250118   B3/07/19   S0-346   F		8307220380	83/07/15	50-395	P	8:	307250119 307250121				
B307220392   B307220381   B3/07/15   50-335   0   B307250128   B307250126   B3/07/06   50-247   P		83072203B1	83/07/15	50-335	G					50-346	F
8307220391 8307220393 83/07/15 50-231 9 8307250131 83/07/14 50-271 9 8307250131 8307250132 83/07/19 50-275 F 8307220400 8307250410 8		8307220381				8:	307250128	8307250126	83/07/05	50-247	Þ
B307220410         B307220403         B307220403         B3072114         B307220410         B30722041				50-271	Q	8:	307250131				P
8307220410 8307220403 83/07/14 50-316 5 8307250126 83/07/14 60078807 P 8307250126 83/07/14 CONTRACT 8307220413 8307220412 83/07/15 50-382 A 8307250178 8307250168 83/07/12 50-289 P	6307220398	8307220381	83/07/15								F
8307220410 8307220403 83/07/14 50-316 8 8307250153 8307250143 83/07/14 CONTRACT 8307220411 8307220402 83/07/15 50-327 A 8307250154 8307250132 83/07/17 50-327 B 8307220413 8307220412 83/07/15 50-382 A 8307250171 8307250168 83/07/12 50-389 P 8307250174 8307250168 83/07/12 50-289 P		100				R	307250141	8307250126			
B307220413 B307220380 B3/07/15 50-395 P B307250171 B307250174 B307250175 B3/07/14 CONTRACT B307220417 B307250176 B3/07/19 50-382 A B307250176 B307250168 B3/07/12 50-289 P						8	307250153	8307250143			
630/5301/9 930/53010 aniiii	B307220413	8307220380	B3/07/15	50-395		8	307250171	B307250145	83/07/14	CONTRAC	Ŧ
						е	307250176	8307250168	83/07/12	JU-K07	•

	ON NUMBER					ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT
8307250200 8307250211 8307250227 8307250240	9307250194 9307250197 8307250215	83/07/20 83/06/20 83/07/20	50-324 50-331	K P	8307250643 8307250645 8307250647	8307250637 8307250635 8307250623	93/07/18 83/07/14 83/07/18	CONTRACT CONTRACT CONTRACT CONTRACT
8307250248 8307250250	8307250238	83/07/20	50-333	K	8307250650 8307250656		83/07/19 83/07/15	50-263 F XPORTLIC
8307250258 8307250260	8307250241 8307250256	83/07/14 83/07/14 83/07/19		г <mark>А</mark>	8307250668 8307250673	8307250667	83/07/19 83/07/08	REVIEW GRP CONTRACT
8307250261 8307250278 8307250279	8307250267	83/07/14 83/07/21	50~329 50-333	A Q	8307230674 8307230680 6307230681	8307250472 8307250472 8307250478	83/07/19 83/07/19 83/07/19	50-277 F 50-277 F 50-247 T
8307250302 8307250334		83/07/22 83/07/22 83/07/21	50-322 50-247 50-289	ě K	8307250697 8307250691	8307250683 8307250685	83/07/19 83/07/19	CONTRACT
8307250336 8307250344	8307250331 8307250327	93/07/20 93/07/21	50-320 50-289	P	8307250693 6307250499 8307250706	8307250690 8307250696 8307250702	83/07/18 83/07/19 83/07/13	CONTRACT 50-348 F 50-302 G
8307250350 8307250352 8307250354	8307250346 8307250327	83/07/20 83/07/21	50-400 50-287	G	8307230730 8307250744	8307250717 8307250717	83/07/19 83/07/19	50-269 F 50-269 F
8307250359 8307250356	8307250349 8307250354 8307250362	83/07/19 83/07/21	40-672 50-445	G	9307250004 9307250005	8307260002 8307260002	83/05/18 83/05/18	50-327 Q 50-327 Q
8307250348	9307250362	93/07/21 93/07/21	50-289 50-289	G G	8307250009	8307260002	83/05/18	50~329 0
8307250378 8307250382	8307250376 8307250377	83/07/18 83/07/18	50-443 50-447	Ť	8307250011 8307260014	8307260002 8307260002	83/05/18 83/05/18	50-327 Q 50-327 Q
8307250383 8307250396	8307250379 8307250390	83/07/20 83/07/22	50-206 50-329	e G	8307260019 8307260021 8307260024	8307240002 8307240002 8307240020	83/05/18 83/05/18 83/07/19	50-327 0 50-327 0 50-237 P
8307250402 8307250406	9307250390 9307250403	83/07/22 83/07/08	50-329 50-320	o G	9307260028	8307260020	83/07/19	50-237 P
8307250413 8307250428	8307250403 8307250410	93/07/08 93/06/06	50-320 50-285	Q Q	8307260041 8307260046	8307260032 8307260039	83/07/18 83/07/12	90~259 P Waste mot
8307250435 8307250438	9307250434	B3/07/19	50-373	Œ	8307240051 8307240064	8307260039 8307260059	83/07/12 83/06/30	Waste Mot Waste Mot
8307250439 8307250442	9307250436 9307250437	93/07/20 93/07/08	50-220 50-322	G G	9307260089 9307260113	0307210054 0307260101	83/03/07 83/07/20	FDIA
8307250443 8307250444	8307250437 8307250440 8307250440	83/07/08 83/07/19 83/07/19	50-322 40-86 40-86	Œ	6307240123 6307240130 6307240149	8307260111 8307260111 8307260111	83/05/11 83/05/11 83/05/11	MISC FOIA FOIA FOIA
8307250476 8307250479	8307250474 9307250474	83/07/12 83/07/12	50-361 50-361	8	8307260158 8307260161	8307240151	B3/07/21	0.A979
8307250491 8307250484	8307250478 8307250480	83/06/21 83/07/21	50-254 50-237	Gŧ P	8307240164 8307240167	8307260111 8307260151 8307260111	93/05/11 83/07/21	FOIA 0A779
8307250486 8307250495	8307250482 8307250489	83/07/15 83/07/19	50-313	K _	B307240149	8307260151	83/05/11 83/07/21	FOIA Gappp
8307250499 8307250504	8307250489 8307250500	83/07/19 83/07/19	50-220 50-220	F	9307240172 9307240192	8307260166 8307260179	83/07/19 83/06/10	50-293 K 50-285 P
8307250506 8307250509 8307250510	8307250502 8307250503 8307250500	83/06/13 83/07/12	50-261 40-8829 CONTRACT	F	8307240208 8307240209 8307240211	8307260202 8307260204 8307260202	83/07/18 82/12/17 83/07/18	50-219 P WASTE MOT 50-219 P
8307250520 9307250521	8307250508 8307250514	83/07/19 83/07/12 83/07/19	50-261 CONTRACT	F 	8307260214 8307260228	8307260205 8307260219	83/07/21 83/07/22	50~483 G GA979
8307250533 8307250538	8307250531 8307250531	83/05/11 83/05/11	50-62 FOIA FOIA	F	8307260247 8307260256 8307260279	8307260229 8307260229 8307260270	83/06/09 83/06/09 83/07/21	50~382 A 50-382 A 50-259 P
9307250550 930725055B	8307250540 8307250551	83/07/14 83/05/06	CONTRACT FOIA		8307260286 83072603 <b>2</b> 1	8307240280 8307240314	83/07/21	50-298 q
8307250562 8307250564 8307250570	8307250557 8307250551 8307250559	83/07/13 83/05/06 83/07/18	71-5552 FOIA 71-9098		8307240325 8307240339 8307240342	8307260318 8307260336 8307260336	83/07/20 83/06/03 83/07/22 83/07/22	50-346 0 40-8550 50-387 P 50-387 P
8307250572 8307250573	9307250551 930725056 <i>9</i>	83/03/06 93/07/14	FOIA 71-5026		8307260343	8307260338	83/07/13	50-267 F
8307230574 8307230575	8307250551 8307250553	83/05/06 83/07/14	FDIA 71-6550		8307260351 8307260379	8307260346 8307260394	83/07/15 83/07/22	50-245 P 50-395 P
9307250579	8307250551	83/05/06	FOIA		8307260407 8307260417	8307260403 8307260412	83/07/22 83/07/19	50-527 Q 50-267 P
8307250582 8307250585	8307250577 8307250551	83/07/14 83/05/06	71-210 FOIA		8307260431	8307260272	B3/01/10	WASTE MOT
8307250593 8307250599	8307250551 8307250588	83/05/06 83/07/08	FOIA PR		8307260440 8307260444 8307260450	8307260437 8307260442	83/07/14 83/07/20	TOPREP 50-142 0
8307250601 8307250605	8307250551	83/05/06 83/07/18	FOIA 71-9096		8307260456	8307260449 8307260452	83/07/25 83/07/19	50-244 P 27-48
8307250606 8307250609	8307250551 8307250603	83/05/05 83/07/14	FOIA 71-6400		8307260458 8307260463	8307260454 8307260461	83/07/19 83/07/22	50-243 P 50-395 P
8307250613 8307250616	8307250551 8307250588	83/05/06 83/07/08	FOIA PR		8307260469 8307260477 8307260481	8307260465 8307260474 8307260480	83/07/22 83/07/22 83/07/20	50-395 P 50-320 P 50-271 K
8307250619 8307250622	8307250551 8307250588	83/05/06 83/07/08	FOIA PR		8307240482 8307240487	9307240478	83/07/19	70-1007
8307250625 8307250629 8307250630	8307250420 8307250423 8307250427	83/07/19 83/07/18 83/07/18	50-413 E CONTRACT CONTRACT	r	8307260488 8307260491 8307260491	8307260484 8307260484 8307260484 8307260497	83/07/20 83/07/20 83/07/20	50-331 G 50-331 G 50-331 G
8307250633 8307250634	8307250626 8307250588	83/07/19	50~259 8	-	B307260504	8307260497	83/07/20 83/07/22	50-331 P 50-324 P
8307250637 8307250640	8307250598 8307250626 8307250623	93/07/08 93/07/19	PR 50-259 F	7	8307260525 8307260527	8307260516 8307260522	83/07/11 83/07/20	50-324 P 50-322 A 50-245 P
8307250642	6307250632	83/07/18 83/07/19	CONTRACT F E65-08	•	9307240528 9307240531	8307260521 8307260514	83/07/08 83/06/24	50-245 P 50-142 Q 50-278 Q

ACCESS10A					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8307260537 8307260540 8307260544	8307260533 8307260516 8307260539	83/07/21 83/07/11 83/07/22	50-346 50-322 50-275	Q A R	8307280081 8307280093 8307280102	8307280075 8307280073 8307280084	83/07/20 83/07/22 83/07/22	50-322 50-278 50-10	F K
8307260545 8307260563	8307260516 8307260516	83/07/11 83/07/11		A	8307280115 8307280120	8307280101 8307280114	83/07/15 83/07/12	50-275 PROJ	F
8307260567 8307260569	8307260558 8307260558	83/07/14 83/07/14		6 8	8307280122 8307280129	8307280118 8307280123	83/07/20 83/07/15	50-322 40-672	T
8307260572	8307260516	B3/07/11	50~322	A	8307280141 8307280150	8307280136 8307280135	83/07/19 83/07/13	50-35B 70-143	T
8307260576 8307260581	8307260573 8307260516	93/07/20 93/07/1i		G A	8307280156	8307280142	83/07/14	50-374	G
8307260594 8307260596	8307260516 8307260058	83/07/11	50-322 WASTE MOT	A	8307280160 8307280166	9307280136 9307280136	83/07/19 83/07/19	50-35B 50-35B	T T
B307260601	8307260400	83/05/18 83/05/18	FOIA		8307280170	8307280164	83/07/11	40-672	
8307270013 8307270019	8307270004 8307270017	83/07/22 83/07/13		Р Н	8307280172 8307280179	8307280136 8307280168	93/07/19 93/07/20	50-358 50-243	P
8307270020	8307270018	B3/07/22		P	8307280194 8307280196	8307280188 8307280190	83/07/11 83/07/08	50-199 50-282	g Q
8307270028 8307270030	8307270023 8307270027	83/07/12 83/07/15	GEN TEC 1 50-266	6 R	8307280200	8307280188	83/07/11	50~199	ā
B307270033	8307270023	83/07/12	GEN TEC I	6	830728020 <i>6</i> 8307280207	8307280201 8307280198	93/07/22 83/07/11	50-344 XPORTLIC	K
B30727003B	6307270035	83/07/22		K _		8307280218	83/07/06	71-5552	
9307270040 9307270042	9307270036 9307270037	83/07/21 83/07/08		P F	8307280223 8307280229	8307280211	83/07/20	50-272	G
B307270043	B307270041	83/07/19	50-277	F	8307280248 8307280253	9307280244 9307280247	83/07/14 83/07/15	50-334 50-440	P G
8307270046 8307270050	8307270041 8307270047	83/07/19 83/06/22		F U	8307280254	8307280246	83/07/25	50-352	Ğ
8307270055	8307270034	B3/07/15		U	8307280264 8307280274	8307280247 8307280266	83/07/15 83/07/12	50-440 50-295	a a
8307270060 8307270072	8307270057 8307270059	83/07/22 83/07/11	50-400 50-282	K B	8307280275	8307280269	83/07/13	50~307	ũ
8307270079 8307270086	8307270073 8307270073	83/07/20 83/07/20	XPORTLIC XPORTLIC		830728028 <b>0</b> 8307280282	8307280274 8307280277	83/07/13 83/07/14	50-309 50-334	Q P
8307270099	8307270093	83/07/20	XPORTLIC		8307280283	8307280278	83/07/13	50-333	a
B307270104	8307270093	83/07/20	XPORTL10	_	8307280284 8307280290	8307280249 8307280276	83/07/13 83/07/13	50-309 50-309	0
8307270179 8307270180	8307270170 8307270176	83/07/01 83/07/22	50-321 50-438	P Q	8307280293	8307280287	83/07/14	50-10	G
8307270182	8307270177	83/07/19	50-375	F	8307280295	8307280291	83/07/20	50-333	9
B307270195	8307270186 8307270192	83/07/19 83/07/15	50-275 50-334	F P	8307280297 8307280301	8307280292 8307280296	83/07/22 83/07/22	50-275 50-275	P R
8307270197 8307270201	8307270192	83/07/19	50-275	F	8307280303	8307280298 8307280307	83/07/22 83/07/14	50-334 50-317	GI K
8307270215 8307270230	8307270207 8307270223	83/07/19 83/02/23	50-341 WASTE MO	Α T	8307280310 8307280311	8307280304	B3/07/24	50-284	ā
8307270234	8307270223	83/02/23	WASTE MG	T	8307280315	8307280307	83/07/14	50-317	Q.
B307270240	8307270223	83/02/23	WASTE MO	Т	830728 <b>0</b> 314 8307280319	8307280314 8307280318	83/07/22 83/07/20	50-335 70-820	ĸ
8307270282 8307270284	8307270275 8307270281	83/06/13 83/07/13	50-286 50-313	G P	8307280320	8307280317	83/07/20 83/07/24	50-309 70-36	P
8307270296	8307270291	83/04/01	WASTE MO	т	8307280325	8307280321 8307280312	63/07/19	50-213	G
8307270297	8307270270	83/07/15 83/04/01	50-328 WASTE MG	P T	8307280324 8307280329	8307280323	83/07/15	50~373	6
8307270300 8307270301	8307270271 8307270270	83/07/15	50-328	P	8307280335 8307280340	8307280332 8307280336	83/07/12 83/07/12	50-397 50-397	Q Q
8307270312 8307270313	8307270306 8307270303	83/07/26 83/07/08	50-213 50-317	P P	8307280342	8307280334	B3/07/13	50-354	Q
8307270318	8307270316	83/07/18	50-289	ĸ	8307280344	8307280341 8307280336	83/07/25 83/07/12	50-315 50~387	P 0
B307270345	8307270338	83/07/15 83/06/21	50-265 50-261	Q P	8307280344 8307280349	8307280332	83/07/12	50-387	G
8307270356 8307270378	8307270350 8307270373	93/07/22	50-155	P	8307280352 8307280353	8307280343 8307280351	B3/07/21 B3/07/26	50-317 50-263	Q Q
0307270362	8307260439	83/07/18	50-266	к	8307280388	8307280384	83/07/13	50-341	Q
8307270404	830727039B 8307270402	83/07/20 83/07/22	50-237 50-272	P P	8307280389	8307280354	83/07/19	50-220	g G
8307270406 8307270410	8307270408	83/01/13	WABTE HO	т	8307280395 8307280401	8307280384 8307280392	83/07/13 83/07/22	50-341 50-483	G.
8307270412 8307270416	8307270408 8307270395	83/01/13 83/07/22	WASTE MG	T Q	8307280404	8307280399	83/07/19	50-293	R
8307270419	8307270408	83/01/13	WASTE MO	т	9307280415	8307280409 8307280409	83/07/22 83/07/22	50-369 50-369	P
8307270420	8307270408	03/01/13	WASTE MG	т	8307280421 8307280423	8307280416	83/07/19	50-27	P
8307270425 8307270436	8307270422 8307270434	83/07/22 83/07/19	TOPREP 50-155	p	8307280425 8307280429	8307280418 8307280409	83/07/26 83/07/22	50-280 50-369	P
8307270437	8307270433	83/07/22	50-312	К	B307280427	6307260431	83/07/20	50-219	0
8307270440	8307270439 8307270445	83/07/25 83/07/18	50-333 70-39 <b>9</b>	P	8307280438	8307280431	83/07/20 83/07/25	50-219 50-440	G G
B307270447 B307270453	8306270415	93/07/22	50-454	g a	8307280439 8307280442	8307280437 8307280437	83/07/25	50-440	G
8307270454 8307270464	8306270415 8307270462	93/07/22 93/07/20	50-454 50-272	G G	8307280443	8307280431	B3/07/20	50-219	a
B307270466	8307270462	83/07/20	50-272	Q	9307280449 9307280450	8307280444 8307280446	83/07/14 83/07/25	50~293 50~10	9
8307270468	8307270465	83/07/19	50-244	F .	8307280454	8307280446	83/07/25	50-10	a
8307270471 8307270477	8307270465 8307270287	83/07/19 83/07/13	50~244 50~440	r . G	8307280457 8307280459	8307280446 8307280453	83/07/25 83/07/18	50~10 50-35⊉	9
8307270488		82/09/23	CONTRACT	·	8307280451	8307280453	83/07/18	50-352	a
8307270502	B307270473	B3/07/19	50-305 50-305	F	8307280463	8307280453	83/07/18	50-352 50-29	Q P
8307270506 8307280043	8307280039	83/07/19 83/07/27	50-322	© .	8307280464 8307280469	8307280462 830728046B	83/07/20	50-322	Т
B307280071	8307280069	83/07/22 83/07/22	50-346 50-346	P P	8307290014	8307270012	83/07/08	50-289	P
8307280079	8307280069	03101188	22 444	•					

ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 195VED	SUBJEC	
8307290032	8307290026	83/07/08	QA999	
8307290035	8307290026	83/07/08	0A999	
8307290038	8307270030	83/06/17	CONTRAC	т
9307290040	8307290026	83/07/08	QA999	
9307290056	8307290052	83/07/22	50-382	G
8307290065	8307270060	83/07/0B	0A999	
8307290067	8307270052	83/07/22	50-382	G
8307290072	B307290047	83/07/21	50~454	Ă
8307290087	8307270081	83/07/11	0A999	•••
8307290093	8307290088	83/07/21	50~352	G
8307290095	8307270081	83/07/11	0A999	
B307290099	8307290088	83/07/21	50-352	G
8307290105	8307270102	83/07/26	50-454	ŏ
8307290108	8307290094	93/07/27	50-247	ē
8307290118	8307290113	83/07/22	50-329	Ā
8307290120	8307290114	83/07/08	QA999	
8307290129	8307290114	83/07/08	0A999	
8307290139	8307290133	83/07/11	0A999	
8307290141	8307290137	83/06/16	50-267	Q.
8307290143	8307290140	83/07/08	70-824	
8307290144	8307290133	83/07/11	0A999	
8307290147	8307290133	83/07/11	QA777	
6307290155	8307290151	83/07/27	50-390	A
8307290158	8307290156	83/07/19	CONTRACT	
8307290159	8307290154	B3/07/26	50-322	G:
B307290163	8307270160	83/07/26	50~322	R
B307290164	8307290161	83/07/19	CONTRACT	**
8307290166	B307290162	83/07/22	50-315	к
8307290185	8307270180	83/07/22	50~272	P
8307270192	8307290190	83/07/15	50-275	P

ACCEPCION NUMBER

ACCESSI	3N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE LESUED	SUBJECT CATEGORY
8307290194	8307290191	83/07/22	50-329 A
8307290268	8307290257	83/06/15	
8307290280	8307290272	83/06/13	50~275 g 50~304 g
8307290287	8307290284	83/06/17	50-304 B
8307290299	8307290293	83/07/19	50-416 S
8307290307	8307290298	83/06/13	50-280 s
8307270326	8307290321	83/07/20	50-280 S CONTRACT
8307290329	8307290317	83/06/01	70-2988
8307290330	8307290324	83/06/13	
8307290349	8307270347	83/04/29	
		037047 24	WASTE MGT
8307290346	8307290357	83/07/21	CONTRACT
8307290367	8307290361	B3/07/08	CONTRACT 71-6400
8307290370	8307290361	83/07/0B	71-6400
B307290374	8307290361	83/07/08	
8307290375	8307290369	83/07/12	71~6400 71-496
		03/0//12	/1-496
8307290377	8307290320	83/07/11	50~315 B
8307270387	8307290382	B3/07/18	
8307270401	8307290393	83/06/14	
8307290422	B307290411	83/07/22	50~395 8 71~5450
8307290434	8307290414	83/04/15	
		04,04,15	50-280 S
8307290437	B307290430	83/07/20	50-454 A
8307290469	8307270464	83/07/15	50~454 A 50-266 p
8307290473	B307290454	83/07/19	CONTRACT
8307290475	8307290466	83/07/18	50-344 P
8307290478	8307290467	83/05/1B	FOIA
			1 014
8307290489	8307290480	B3/07/19	CONTRACT
8307290505	8307290494	83/07/14	CONTRACT
8307270513	8307290509	B3/07/12	CONTRACT
8307290523	8307290514	83/07/19	50-321 F
8307290530	8307290514	63/07/19	50-321 F
			Aer L
8307290544	8307290539	83/07/19	50-369 F
8307290550	8307290548	83/07/19	50-309 P

#### APPENDIX A

#### DEFINITIONS OF DOCKET 50 CATEGORIES

### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- Transmittal and acknowledgement letters. 3.
- 4. Certificates of service to the PSAR

### UTILITY ENVIRONMENTAL REPORT (ER). AMENDMENTS AND CORRESPONDENCE C.

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A. D. M. P or R.

- Environmental Report (ER) submitted by the utility. 1.
- Amendments and supplements to the ER. 2.
- 3. Transmittal and acknowledgement letters.
- Information on scheduling of submittal or review of ER. 4.
- NRC questions, requests for additional information, and applicant responses. 5.
- Federal register notices citing the availability of items 1 and 2. 6.
- Correspondence relating to the review of ER. 7.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the

### NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), D. SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A. C. M. P or R.

- Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of tiens 1 and 2.
- 9. Site visits to obtain information for DES or FLS.
- Meeting announcements or reports of meetings where the primary subject of discussion is the 10.

## NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A. P or W. depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

#### H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

## K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

### L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

### O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

## Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

### S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LERs) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

### U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

### X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

### Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- License applications, licenses, amendments and proposed amendments to possess power reactor spent
  fuel and other radioactive materials associated with spent storage in an independent spent fuel
  storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate
- All related correspondence and reports to the above.

#### APPENDIX B

#### **DEFINITIONS OF NONDOCKETED CATEGORIES**

### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. · ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

### ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

- Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any,

### DISCLOSURE -- Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FO1A.

### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. 1&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission,
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

### ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- Correspondence between NRC's Office of Standards Development and other government
  agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority
  to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- Requests from the nuclear industry, organizations and other parties for written interpretations
  of the PR.

### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

l. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned à docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - 1. Application submitted by the utility.
  - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual.
  - 4. Early site review information.
  - 5. Backup technical documents submitted in support of the application.
  - 6. Early site visits.
- B. Utility PSAR and Amendments
  - 1. PSARs submitted by the utility.
  - 2. Amendments and changes to the PSAR.
  - 3. Transmittal letters.
  - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
  - 1. Submittals and related material pertaining to the antitrust review.

### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

### PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Fart 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3, Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

### REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

#### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

### STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

#### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import of export licenses,
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1. REPORT NUMBE NUREG-0540 Vol. 5, No.				
4. TITLE AND SUBTITLE (Add Volume No., if appropriate)		2. (Leeve blank)				
Title List of Documents Made Publicly Availabl	е					
July 1-31, 1983	•	3. RECIPIENT'S ACCESSION NO.				
7. AUTHOR(S)		5. DATE REPORT C	OMPLETED			
		MONTH	YEAR			
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include		DATE REPORT IS				
Division of Technical Information and Document	: Control	September 1983				
Office of Administration U.S. Nuclear Regulatory Commission		6. (Leave blank)	1200			
Washington, DC 20555						
washington, bo Looso	<del> </del>	8. (Leave blank)				
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include	Zıp Codel	10. PROJECT/TASK/	WORK UNIT NO.			
Same as 9, above.		11. FIN NO.				
13. TYPE OF REPORT	PERIOD COVERE	D (Inclusive dates)				
Monthly		31, 1983				
Hotterry	· ·					
15. SUPPLEMENTARY NOTES		14. (Leave plank)				
16. ABSTRACT (200 words or less)						
This document is a monthly publication contain received and generated by the U.S. NRC. This material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	information r plants and received an The follow Report Numb	includes (1) dother uses ond generated b ing indexes ar	docketed of radio- oy NRC re included:			
17. KEY WORDS AND DOCUMENT ANALYSIS	17a. DESCRIPTORS					
17b. IDENTIFIERS/OPEN-ENDED TERMS		A TOWNS OF THE PARTY OF THE PAR				
18. AVAILABILITY STATEMENT		CLASS (This report)	21 NO OF PAGES			
Unlimited		CLASS (This page) Ssified	22 PRICE			
Official Court	<u>Unclas</u>	sified	s			